NUREG-0540 Vol. 4, No. 8

Title List of Documents Made Publicly Available

Dens-Joj

August 1-31, 1982

y 3. N 00 . TI

Office of Administration U.S. Nuclear Regulatory Commission



PENINA TO GOY DITTE CITER

Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

Title List of Documents Made Publicly Available

August 1-31, 1982

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface	V
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xvii
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	2
Domestic Licensing of Production and Utilization Facilities — Docket 50	11
Domestic Licensing of Special Nuclear Material — Docket 70	417
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	424
Licensing of Independent Spent Fuel Storage — Docket 72	428
Nondocketed Items	
10 CFR — Commission Meeting Records	429
ACRS — Advisory Committee on Reactor Safeguards	429
COMMISSION — NRC Commissioners	430
CONTRACT — NRC Contracts and Modifications	430
FOIA — Freedom of Information Act Requests and Releases	434
GEN TECH IS — Generic Technical Issues	439
I&E — Inspection and Enforcement	439
MISC — Public Document Room Miscellaneous	440
NUREG — NUREG Reports and Related Correspondence	440
ORG — Correspondence with Other Organizations	443
PR — Proposed Rule	444
PRM — Petition for Rulemaking	446
PROJ — Projects - Predocket Licensing	446
PT 21 — Noncompliance Reports and Related Correspondence	446
QA999 — Quality Assurance Inspections	447
REGGD — Regulatory Guides	450
RES — Research and Technical Assistance Reports	451
REVIEW GROUP — NRC Research Review Groups	452
SECY — Position Papers Before the Commission	454
STATE PROG — State Programs	454
TOPREP — Vendor Reports and Related Correspondence	455
WASTE MGT — Nuclear Waste Management	457
XPORTLIC — Export and Import Licenses	460
Personal Author Index	463
Corporate Source Index	495
	531
Report Number Index	533
Cross Reference of Enclosures to Principal Documents	A-1
Appendix B — Definitions of Nondocketed Categories	A-1 B-1
Appendix D — Definitions of Mondocketed Categories	D-I

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

(1) P. Operating license stage documents & correspondence

2
3
8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.

4 MILLS, L.M. 3 Tennessee Valley Authority. 6 82/03/04. 7 VASSALLO, D.B. Operating Reactors Branch 2. 8 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.

- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 10. This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

1&E - Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG — NUREG Reports and Related Correspondence

ORG — Correspondence with Other Organizations

PR — Proposed Rule

PRM - Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 — Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD — Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM — Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence


WASH — Regulatory Publications—Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC -- Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Rad	waste Disposal Sites Docket 27		40-8452	Bear Creek Uranium Co., Casper, WY	8
27-039	Sheffield, IL, U.S. Ecology, Inc.	1	40-8502	Wyoming Mineral Corp., Lakewood, CO	9
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8546	National Aeronautics & Space Administration, Hampton, VA	9
27-048	Richland, WA, U.S. Ecology, Inc.	1	40-8584	Minerals Exploration Co., Los Angeles, CA	9
Domestic Licen	sing of Source Material — Docket 40		40-8585	Wyoming Mineral Corp., Lakewood, CO	9
40-0086	W. R. Grace & Co., Pompton Plains, NJ	2	40-8602	Silver King Mines, Inc., Casper, WY	9
40-0299	Union Carbide Corp., Grand Junction, CO	5			9
40-0460	Washington Public Power Supply System, Richland, WA	5	40-8674 40-8681	Plateau Resources, Ltd., Grand Junction, CO Bnergy Fuels Nuclear, Inc., Denver, CO	9
40-0501	Aluminium Co. of America	5	40-8684	Western Nuclear, Inc., Lakewood, CO	9
40-0672	Nuclear Metals, Inc., Concord, MA	6	40-8697	Rocky Mountain Energy Co., Denver, CO	9
40-1162	Western Nuclear Corp., Jeffrey City, WY	6	40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	9
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	6	40-8724	Chemetron Corp., Chicago, IL	9
40-2259	Pathfinder Mines Corp., Riverton, WY	7	40-8743	Conoco, Inc., Denver, CO	9
40-3453	Atlas Mineral, Inc., Denver, CO	7	40-8745	Ogle Petroleum, Inc., Casper, WY	10
40-4492	Federal-American Partners, Riverton, WY	7	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	10
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	7	40-8781	Teton Exploration Drilling Co., Inc.	
40-6940	Kawecki Berylco Industries, Inc., Boyertown, PA	7		Casper, WY	10 10
40-7138	Yankee Atomic Electric Co.,		40-8783	Uranerz USA, Inc., Casper, WY	
	Westborough, MA	7	40-8786	Uranium Resources, Inc., Richardson, TX	10
40-7604	Vistron Corp., Lima, OH	7	40-8791	Custom Machine, Inc., Cleveland, OH	10
40-8027	Kerr-McGee Nuclear Corp., Okiahoma City, OK	7	40-8793	Conoco, Inc., Denver, CO	10
10.0041	•	8	40-8794	Molycorp, Inc., Los Angeles, CA	10
40-8064	Exxon Minerals Co. USA, Houston, TX		40-8801	Radiation Management Corp., Northbrook, IL	10
40-8084	Rio Algom Corp., Moab, UT	8	40-8823	EM Chemicals, Hawthorne, NY	11
40-8102	Exxon Co. USA, Houston, TX	8	Domestic Licen Docket 50	sing of Production and Utilization Facilities	
40-8135	Minnesota Mining & Manufacturing, St. Paul, MN	8	50-2	Univ. of Michigan Research Reactor	11
40-8211	Chamberlain Manufacturing Corp., Waterloo, IA	8	50-3	Indian Point Station, Unit 1	11
40-8348	Minerals Exploration Co., Los Angeles, CA	8	50-5	Pennsylvania State Univ. Research Reactor	12

Docket	Name	Page	Docket	Name	Page
50-10	Dresden Nuclear Power Station, Unit 1	12	50-157	Cornell Univ. Research Reactor	25
50-13	Babcock & Wilcox Co. Critical Facility	13	50-160	Georgia Institute of Technology	
50-16	Enrico Fermi Atomic Power Plant, Unit 1	14		Research Reactor	25
50-20	Massachusetts Institute of Technology		50-163	General Atomic Company	25
	Research Reactor	14	50-166	Univ. of Maryland Research Reactor	25
50-27	Washington State Univ. Research Reactor	14	50-170	National Naval Medical Center	25
50-29	Yankee-Rowe Nuclear Power Station	14	50-171	Peach Bottom Atomic Power Station, Unit 1	26
50-54	Union Carbide Research Reactor	17	50-182	Purdue Univ. Research Reactor	26
50-57	State Univ. of New York Research Reactor	17	50-184	National Bureau of Standards Reactor	26
50-59	Texas A&M Univ. Research Reactor	17	50-186	Univ. of Missouri Research Reactor	26
50-70	General Electric Test Reactor	17	50-187	Space Radiation Research Reactor	26
50-73	General Electric Nuclear Test Reactor	17	50-188	Kansas State Univ. Research Reactor	27
50-77	Catholic Univ. of America Research Reactor	17	50-193	Rhode Island & Providence Plantations AEC	27
50-83	Univ. of Florida Training Reactor	17	50-199	Manhattan College Research Reactor	27
50-87	Westinghouse Critical Experiment	17	50-201	West Valley Reprocessing Plant	27
50-89	General Atomic Co.	18	50-206	San Onofre Nuclear Station, Unit 1	27
50-97	Cornell Univ. Zero Power Reactor	18	50-208	Columbia Univ. Research Reactor	31
50-99	Babcock & Wilcox Test Reactor	18	50-213	Haddam Neck Plant	31
50-112	Univ. of Oklahoma Research Reactor	18	50-219	Oyster Creek Nuclear Power Plant	33
50-113	Univ. of Arizona Research Reactor	18	50-220	Nine Mile Point Nuclear Station, Unit 1	36
50-116	Iowa State Univ. Research Reactor	18	50-223	Univ. of Lowell Research Reactor	38
50-123	Univ. of Missouri Research Reactor	18	50-225	RPI Critical Experiment	38
50-128	Texas A&M Univ. Research Reactor	18	50-228	Aerotest Radiography & Research Reactor	38
50-133	Humboldt Bay Power Plant, Unit 3	18	50-237	Dresden Nuclear Power Station, Unit 2	39
50-134			50-241	Mississippi State Univ. Research Reactor	42
	Research Reactor	19	50-243	Oregon State Univ. Research Reactor	42
50-139		19	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	42
50-142		20	50-245	Millstone Nuclear Power Station, Unit 1	45
50-146		21	50-246	Advanced Critical Reactor, Experiment	47
50-147	Rockwell International Corp. Critical Facility	21	50-247	Indian Point Station, Unit 2	47
50-148	Univ. of Kansas Research Reactor	21	50-249	Dresden Nuclear Power Station, Unit 3	51
50-150	Ohio State Univ. Research Reactor	21	50-250	Turkey Point Plant, Unit 3	
50-155		21	50-251	Turkey Point Plant, Unit 4	54
50-156		25			56
	The state of the s		50-252	Univ. of New Mexico Research Reactor	59

Docket		Name	Page	Docket	Name	Page
50-	254	Quad-Cities Station, Unit 1	59	50-296	Browns Ferry Nuclear Power Station, Unit 3	132
50-	255	Palisades Nuclear Plant	62	50-297	North Carolina State Univ. PULSTAR Reactor	136
50-	259	Browns Ferry Nuclear Power Station, Unit 1	65	50-298	Cooper Nuclear Station	136
50-	260	Browns Ferry Nuclear Power Station, Unit 2	70	50-301	Point Beach Nuclear Plant, Unit 2	138
50-	261	H.B. Robinson Plant, Unit 2	74	50-302	Crystal River Nuclear Plant, Unit 3	141
50-	262	Brigham Young Univ. Research Reactor	77	50-304	Zion Nuclear Power Station, Unit 2	143
50-	263	Monticelio Nuclear Generating Plant	77	50-305	Kewaunce Nuclear Power Plant	145
50-	264	Dow Chemical Co.	79	50-306	Prairie Island Nuclear Station, Unit 2	147
50-	265	Quad-Cities Station, Unit 2	79	50-309	Maine Yankee Atomic Power Plant	150
50-:	266	Point Beach Nuclear Plant, Unit 1	82	50-311	Salem Nuclear Generating Station, Unit 2	153
50-	267	Fort St. Vrain Nuclear Generating Station	85	50-312	Rancho Seco Nuclear Generating Station	156
50-:	268	Midwest Fuel Recovery Plant	87	50-313	Arkansas Nuclear One, Unit 1	159
50-	269	Oconee Nuclear Station, Unit 1	87	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	163
50-2	270	Oconee Nuclear Station, Unit 2	90	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	166
50-	271	Vermont Yankee Nuclear Power Station	93	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	168
50-	272	Salem Nuclear Generating Station, Unit 1	94	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	173
50-2	274	U.S. Geological Survey Research Reactor	97	50-320	Three Mile Island Nuclear Station, Unit 2	176
50-2	275	Diablo Canyon Nuclear Power Plant, Unit 1	97	50-321	Edwin I. Hatch Nuclear Plant, Unit 1	179
50-2	276	Georgia Tech Research Reactor	101	50-322	Shoreham Nuclear Power Station	182
50-	277	Peach Bottom Atomic Power Station, Unit 2	101	50-323	Diablo Canyon Nuclear Power Plant, Unit 2	187
50-2	278	Peach Bottom Atomic Power Station, Unit 3	103	50-324	Brunswick Steam Electric Plant, Unit 2	189
50-	280	Surry Power Station, Unit 1	104	50-325	Brunswick Steam Electric Plant, Unit 1	192
50-2	281	Surry Power Station, Unit 2	108	50-326	Univ. of California at Irvine Research Reactor	196
50-2	282	Prairie Island Nuclear Station, Unit 1	110	50-327	Sequoyah Nuclear Plant, Unit 1	196
50-:	284	Idaho State Univ. Research Reactor	113	50-328	Sequoyah Nuclear Plant, Unit 2	200
50-2	285	Fort Calhoun Station, Unit 1	113	50-329	Midland Plant, Unit 1	203
50-	286	Indian Point Station, Unit 3	116	50-330	Midland Plant, Unit 2	207
50-2	287	Oconee Nuclear Station, Unit 3	119	50-331	Duane Arnold Energy Center	210
50-2	288	Reed College Research Reactor	122	50-332	Barnwell Reprocessing Plant	213
50-2	28 9	Three Mile Island Nuclear Station, Unit 1	122	50-333	James A. Fitzpatrick Nuclear Power Plant	213
50-2	293	Pilgrim Nuclear Power Station, Unit 1	127	50-334	Beaver Valley Power Station, Unit 1	215
50-2	294	Michigan State Univ. Research Reactor	129	50-335	St. Lucie Plant, Unit 1	220
50-2	295	Zion Nuclear Power Station, Unit 1	129	50-336	Millstone Nuclear Power Station, Unit 2	222

Docket		Name	Page	Docket	Name	Page
5	50-338	North Anna Power Station, Unit 1	225	50-401	Shearon Harris Nuclear Power Plant, Unit 2	309
5	50-339	North Anna Power Station, Unit 2	228	50-402	Shearon Harris Nuclear Power Plant, Unit 3	311
5	50-341	Enrico Fermi Atomic Power Plant, Unit 2	231	50-403	Shearon Harris Nuclear Power Plant, Unit 4	311
5	50-344	Trojan Nuclear Plant	233	50-404	North Anna Power Station, Unit 3	311
5	50-34 6	Davis-Besse Nuclear Power Station, Unit 1	235	50-406	Tuskegee Institute Research Reactor	311
5	50-348	Joseph M. Farley Nuclear Plant, Unit 1	239	50-407	Univ. of Utah Research Reactor	311
5	50-352	Limerick Generating Station, Unit 1	242	50-409	La Crosse Boiling Water Reactor	312
5	50-353	Limerick Generating Station, Unit 2	247	50-410	Nine Mile Point Nuclear Station, Unit 2	315
5	50-354	Hope Creek Nuclear Station, Unit 1	250	50-412	Beaver Valley Power Station, Unit 2	316
.5	50-355	Hope Creek Nuclear Station, Unit 2	251	50-413	Catawba Nuclear Station, Unit 1	316
5	50-356	Univ. of Illinois LOPRA Research Reactor	252	50-414	Catawba Nuclear Station, Unit 2	320
	50-358	William H. Zimmer Nuclear Station, Unit 1	252	50-416	Grand Gulf Nuclear Station, Unit 1	323
	50-361	San Onofre Nuclear Station, Unit 2	255	50-417	Grand Gulf Nuclear Station, Unit 2	328
3	50-362	San Onofre Nuclear Station, Unit 3	260	50-423	Millstone Nuclear Power Station, Unit 3	330
5	50-363	Forked River Nuclear Station, Unit 1	262	50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	331
5	50-364	Joseph M. Farley Nuclear Plant, Unit 2	262	50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	332
	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	264	STN-50-437	Floating Nuclear Plant	332
5	50-367	Bailly Generating Station	267	50-438	Bellefonte Nuclear Plant, Unit 1	333
5	50-368	Arkansas Nuclear One, Unit 2	267	50-439	Bellefonte Nuclear Plant, Unit 2	337
3	50-369	William B. McGuire Nuclear Station, Unit 1	270	50-440	Perry Nuclear Power Plant, Unit 1	340
3	50-370	William B. McGuire Nuclear Station, Unit 2	274	50-441	Perry Nuclear Power Plant, Unit 2	344
5	50-373	LaSaile County Station, Unit i	276	50-443	Seabrook Nuclear Station, Unit 1	347
5	50-374	LaSalle County Station, Unit 2	281	50-444	Seabrook Nuclear Station, Unit 2	349
5	50-375	Nuclear Examination Reactor	283	50-445	Comanche Peak Steam Biectric Station, Unit 1	351
5	50-382	Waterford Generating Station, Unit 3	283	50 -44 6	Comanche Peak Steam Blectric Station, Unit 2	354
5	50-387	Susquehanna Steam Electric Station, Unit 1	287	STN-50-447	GESSAR-238	356
5	50-388	Susquehanna Steam Electric Station, Unit 2	291	STN-50-454	Byron Station, Unit !	356
5	50-389	St. Lucie Plant, Unit 2	293	STN-50-455	Byron Station, Unit 2	360
5	50-390	Watts Bar Nuclear Plant, Unit 1	296	STN-50-456	Braidwood Station, Unit 1	364
5	50-391	Watts Bar Nuclear Plant, Unit 2	299	STN-50-457	Braidwood Station, Unit 2	365
5	50-395	Virgil C. Summer Nuclear Station, Unit 1	302	50-458	River Bend Station, Unit 1	367
5	50-397	WPPSS Nuclear Project, Unit 2	305	50-459	River Bend Station, Unit 2	369
5	50- 4 00	Shearon Harris Nuclear Power Plant, Unit 1	307	50-460	WPPSS Nuclear Project, Unit 1	369

Docket	Name	Page	Docket	Name	Page
50-461	Clinton Power Station, Unit 1	371	STN-50-528	Palo Verde Nuclear Station, Unit 1	396
50-462	Clinton Power Station, Unit 2	372	STN-50-529	Palo Verde Nuclear Station, Unit 2	399
50-466	Allens Creek Nuclear Station, Unit 1	373	STN-50-530	Palo Verde Nuclear Station, Unit 3	401
STN-50-470	CESSAR System 80	374	STN-50-531	GESSAR-251	403
STN-50-480	RESAR-41	374	STN-50-532	BRAUNSAR	403
STN-50-481	B-SAR-241	374	STN-50-535	GASSAR-6	403
STN-50-482	Wolf Creek Generating Station	374	50-537	Clinch River Breeder Reactor	403
STN-50-483	Callaway Plant, Unit 1	375	50-538	Memphis State Univ. Research Reactor	410
STN-50-485	Sterling Power Nuclear Project, Unit 1	377	STN-50-545	RESAR-3S	410
STN-50-486	Callaway Plant, Unit 2	378	STN-50-546	Marble Hill Nuclear Station, Unit 1	410
STN-50-488	Perkins Nuclear Station, Unit 1	378	STN-50-547	Marble Hill Nuclear Station, Unit 2	411
STN-50-489	Perkins Nuclear Station, Unit 2	378	50-549	Greene County Nuclear Power Plant	412
STN-50-490	Perkins Nuclear Station, Unit 3	379	STN-50-550	GESSAR-238-BOP, Interface	412
STN-50-491	Cherokee Nuclear Station, Unit 1	379	STN-50-553	Phipps Bend Nuclear Station, Unit 1	412
STN-50-492	Cherokee Nuclear Station, Unit 2	380	STN-50-554	Phipps Bend Nuclear Station, Unit 2	413
STN-50-493	Cherokee Nuclear Station, Unit 3	380	STN-50-556	Black Fox Station, Unit 1	413
STN-50-495	SWESSAR-P1	381	STN-50-557	Black Fox Station, Unit 2	414
STN-50-498	South Texas Project, Unit 1	381	STN-50-560	BOPSSAR	414
STN-50-499	South Texas Project, Unit 2	383	STN-50-561	B-SAR-205	414
50-500	Davis-Besse Nuclear Power Station, Unit 2	385	50-564	Nuclear Fuels Recovery & Recycle Center	414
50-501	Davis-Besse Nuclear Power Station, Unit 3	385	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	414
STN-50-502	Haven Nuclear Plant, Unit 1	385	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	415
STN-50-508	WPPSS Nuclear Project, Unit 3	386	STN-50-572	RESAR-414 Westinghouse Electric Corp.	416
STN-50-509	WPPSS Nuclear Project, Unit 5	388	STN-50-584	Gibbsar, Gibbs & Hill	416
50-513	WPPSS Nuclear Project, Unit 4	389	STN-50-591	Essar, Ebasco Services	416
50-514	Pebble Springs Nuclear Plant, Unit 1	390	STN-50-597	New Haven, Unit 2	416
50-515	Pebble Springs Nuclear Plant, Unit 2	390	STN-50-599	Carroll Facility I	416
STN-50-518	Hartsville Nuclear Plant, Unit 1	391	STN-50-600	Carroll Pacility II	417
STN-50-519	Hartsville Nuclear Plant, Unit 2	392	Domestic Licen	sing of Special Nuclear Material — Docket 70	
STN-50-520	Hartsville Nuclear Plant, Unit 3	392	70-0025	Rockwell International Corp., Canoga Park, CA	417
STN-50-521	Hartsville Nuclear Plant, Unit 4	393		Awade a mul are	711
50-522	Skagit Nuclear Power Project, Unit 1	394	70-0027	Babcock & Wilcox Co., Lynchburg, VA	417
50-523	Skagit Nuclear Power Project, Unit 2	395	70-0033	Texas Instruments, Inc., Attleboro, MA	418

Docket	Nøme	Page	Docket	Name	Page
50-338	North Anna Power Station, Unit 1	225	50-401	Shearon Harris Nuclear Power Plant, Unit 2	309
50-339	North Anna Power Station, Unit 2	228	50-402	Shearon Harris Nuclear Power Plant, Unit 3	311
50-341	Enrico Fermi Atomic Power Plant, Unit 2	231	50-403	Shearon Harris Nuclear Power Plant, Unit 4	311
50-344	Trojan Nuclear Plant	233	50-404	North Anna Power Station, Unit 3	311
50-346	Davis-Besse Nuclear Power Station, Unit 1	235	50-406	Tuskegee Institute Research Reactor	311
50-348	Joseph M. Farley Nuclear Plant, Unit 1	239	50-407	Univ. of Utah Research Reactor	311
50-352	Limerick Generating Station, Unit 1	242	50-409	La Crosse Boiling Water Reactor	312
50-353	Limerick Generating Station, Unit 2	247	50-410	Nine Mile Point Nuclear Station, Unit 2	315
50-354	Hope Creek Nuclear Station, Unit 1	250	50-412	Beaver Valley Power Station, Unit 2	316
50-355	Hope Creek Nuclear Station, Unit 2	251	50-413	Catawba Nuclear Station, Unit 1	316
50-356	Univ. of Illinois LOPRA Research Reactor	252	50-414	Catawba Nuclear Station, Unit 2	320
50-358	William H. Zimmer Nuclear Station, Unit 1	252	50-416	Grand Gulf Nuclear Station, Unit 1	323
50-361	San Onofre Nuclear Station, Unit 2	255	50-417	Grand Gulf Nuclear Station, Unit 2	328
50-362	San Onofre Nuclear Station, Unit 3	260	50-423	Millstone Nuclear Power Station, Unit 3	330
50-363	Forked River Nuclear Station, Unit 1	262	50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	331
50-364	Joseph M. Farley Nuclear Plant, Unit 2	262	50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	332
50-366	Edwin I. Hatch Nuclear Plant, Unit 2	264	STN-50-437	Floating Nuclear Plant	332
50-367	Bailly Generating Station	267	50-438	Beliefonte Nuclear Plant, Unit 1	333
50-368	Arkansas Nuclear One, Unit 2	267	50-439	Bellefonte Nuclear Plant, Unit 2	337
50-369	William B. McGuire Nuclear Station, Unit 1	270	50-440	Perry Nuclear Power Plant, Unit 1	340
50-370	William B. McGuire Nuclear Station, Unit 2	274	50-441	Perry Nuclear Power Plant, Unit 2	344
50-373	LaSalle County Station, Unit 1	276	50-443	Seabrook Nuclear Station, Unit 1	347
50-374	LaSalle County Station, Unit 2	281	50-444	Seabrook Nuclear Station, Unit 2	349
50-375	Nuclear Examination Reactor	283	50-445	Comanche Peak Steam Blectric Station, Unit 1	351
50-382	Waterford Generating Station, Unit 3	283	50-446	Comanche Peak Steam Electric Station, Unit 2	354
50-387	Susquehanna Steam Electric Station, Unit 1	287	STN-50-447	GESSAR-238	356
50-388	Susquehanna Steam Electric Station, Unit 2	291	STN-50-454	Byron Station, Unit 1	356
50-389	St. Lucie Plant, Unit 2	293	STN-50-455	Byron Station, Unit 2	360
50-390	Watts Bar Nuclear Plant, Unit 1	296	STN-50-456	Braidwood Station, Unit 1	364
50-391	Watts Bar Nuclear Plant, Unit 2	299	STN-50-457	Braidwood Station, Unit 2	365
50-395	Virgil C. Summer Nuclear Station, Unit 1	302	50-458	River Bend Station, Unit I	367
50-397	WPPSS Nuclear Project, Unit 2	305	50-459	River Bend Station, Unit 2	369
50-400	Shearon Harris Nuclear Power Plant, Unit 1	307	50-460	WPPSS Nuclear Project, Unit 1	369

Docket	Name	Page	Docket	Name	Page
50-461	Clinton Power Station, Unit 1	371	STN-50-528	Palo Verde Nuclear Station, Unit 1	396
50-462	Clinton Power Station, Unit 2	372	STN-50-529	Palo Verde Nuclear Station, Unit 2	399
50-466	Allens Creek Nuclear Station, Unit 1	373	STN-50-530	Palo Verde Nuclear Station, Unit 3	401
STN-50-470	CESSAR System 80	374	STN-50-531	GESSAR-251	403
STN-50-480	RESAR-41	374	STN-50-532	BRAUNSAR	403
STN-50-481	B-SAR-241	374	STN-50-535	GASSAR-6	403
STN-50-482	Wolf Creek Generating Station	374	50-537	Clinch River Breeder Reactor	403
STN-50-483	Callaway Plant, Unit 1	375	50-538	Memphis State Univ. Research Reactor	410
STN-50-485	Sterling Power Nuclear Project, Unit 1	377	STN-50-545	RESAR-3S	410
STN-50-486	Callaway Plant, Unit 2	378	STN-50-546	Marble Hill Nuclear Station, Unit 1	410
STN-50-488	Perkins Nuclear Station, Unit 1	378	STN-50-547	Marble Hill Nuclear Station, Unit 2	411
STN-50-489	Perkins Nuclear Station, Unit 2	378	50-549	Greene County Nuclear Power Plant	412
STN-50-490	Perkins Nuclear Station, Unit 3	379	STN-50-550	GESSAR-238-BOP, Interface	412
STN-50-491	Cherokee Nuclear Station, Unit 1	379	STN-50-553	Phipps Bend Nuclear Station, Unit 1	412
STN-50-492	Cherokee Nuclear Station, Unit 2	380	STN-50-554	Phipps Bend Nuclear Station, Unit 2	413
STN-50-493	Cherokee Nuclear Station, Unit 3	380	STN-50-556	Black Fox Station, Unit 1	413
STN-50-495	SWESSAR-PI	381	STN-50-557	Black Fox Station, Unit 2	414
STN-50-498	South Texas Project, Unit 1	381	STN-50-560	BOPSSAR	414
STN-50-499	South Texas Project, Unit 2	383	STN-50-561	B-SAR-205	414
50-500	Davis-Besse Nuclear Power Station, Unit 2	385	50-564	Nuclear Fuels Recovery & Recycle Center	414
50-501	Davis-Besse Nuclear Power Station, Unit 3	385	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	414
STN-50-502	Haven Nuclear Plant, Unit 1	385	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	415
STN-50-508	WPPSS Nuclear Project, Unit 3	386	STN-50-572	RESAR-414 Westinghouse Electric Corp.	416
STN-50-509	WPPSS Nuclear Project, Unit 5	388	STN-50-584	Gibbsar, Gibbs & Hill	416
50-513	WPPSS Nuclear Project, Unit 4	389	STN-50-591	Essar, Ebasco Services	416
50-514	Pebble Springs Nuclear Plant, Unit 1	390	STN-50-597	New Haven, Unit 2	416
50-515	Pebble Springs Nuclear Plant, Unit 2	390	STN-50-599	Carroll Facility I	416
STN-50-518	Hartsville Nuclear Plant, Unit 1	391	STN-50-600	Carroll Facility II	417
STN-50-519	Hartsville Nuclear Plant, Unit 2	392	Domestic Licen	sing of Special Nuclear Material — Docket 70	
STN-50-520	Hartsville Nuclear Plant, Unit 3	392	70-0025	Rockwell International Corp., Canoga Park, CA	417
STN-50-521	Hartsville Nuclear Plant, Unit 4	393		Contribut stri Ou	411
50-522	Skagit Nuclear Power Project, Unit 1	394	70-0027	Babcock & Wilcox Co., Lynchburg, VA	417
50-523	Skagit Nuclear Power Project, Unit 2	395	70-0033	Texas Instruments, Inc., Attleboro, MA	418

Docket	Name	Page	Docket	Name	Page
70-0036	Combustion Engineering, Inc., Windsor, CT	418	70-1173	Mercyhurst College, Brie, PA	422
70-0113	Pennsylvania State Univ., University Park, PA	418	70-1193	Kerr-McGee Nuclear Corp.,	400
70-0135	Babcock & Wilcox Co., Apollo, PA	418	4	Oklahoma City, OK	422
70-0143	Nuclear Fuel Services, Inc., Brwin, TN	418	70-1201	Babcock & Wilcox Co., Lynchburg, VA	422
70-0184	Westinghouse Electric Corp., Horseheads, NY	419	70-1230	Slippery Rock State College, Slippery Rock, PA	422
70-0190	Catholic Univ. of America, Washington, DC	419	70-1257	Exxon Nuclear Co., Inc., Richland, WA	422
70-0261	Schlumberger Technology Corp.,		70-1308	General Electric Co., San Jose, CA	423
70-0273	Ridgefield, CT National Carbon Co., Fostoria, OH	419 419	70-1314	National Aeronautics & Space Administration, Hampton, VA	423
70-0303	Carnegie-Mellon Univ., Pittsburgh, PA	419	70-1810	Westinghouse Electric Corp., Pittsburgh, PA	423
70-0356	Nuclear Research Corp., Dover, NJ	419	70-2174	Southeast Missouri Hospital,	
70-0359	Pittsburgh, Univ. of, Pittsburgh, PA	420		Cape Girardeau, MO	423
70-0364	Babcock & Wilcox Co., Apollo, PA	420	70-2623	Duke Power Co., Charlotte, NC	423
70-0371	UNC Naval Products, Inc., Uncasville, CT	420	70-2625	Newton Memorial Hospital, Newton, NJ	423
70-0398	Commerce, Dept. of, Washington, DC	420	70-2884	Long Island Lighting Co., Hicksville, NY	423
70-0533	St. Peter's College, Jersey City, NJ	420	70-2909	Westinghouse Electric Corp., Prattville, AL	423
70-0600	Seattle Univ., Seattle, WA	420	70-2936	Mississippi Power & Light Co., Jackson, MS	423
70-0624	Gulf Research & Development Co.,	740	70-2937	Pennsylvania Power & Light, Allentown, PA	423
70-0024	Pittsburgh, PA	420	70-2955	Edlow International Co., Washington, DC	423
70-0625	Howard Univ., Washington, DC	420		dioactive Material for Transport and Transports e Material Under Certain Conditions — Docket 7	
70-0629	Washington & Jefferson College, Washington, PA	420	71-0062	Industrial Nuclear Co.	424
70-0687	Union Carbide Corp., Tuxedo, NY	420	71-0370	Amersham Corp.	424
70-0734	General Atomic Co., San Diego, CA	420	71-0478	X-Scan Inspection Co.	424
70-0754	General Electric Co., Pleasanton, CA	421	71-0480	Mercury Metals, Inc.	424
70-0820	United Nuclear Corp., Wood River Junction, RI	421	71-5097	Model: 44, Energy, Dept. of	424
70-0824	Babcock & Wilcox Co., Lynchburg, VA	421	71-5149	Model: 814A, Babcock & Wilcox Co.	424
70-0925	Kerr-McGee Nuclear Corp.,	740-	71-5768	Model: BB-250-2, Combustion Engineering Co., Inc.	424
10-0340	Oklahoma City, OK	421	71-5796	Model: 181375, 181361, Advanced Medical	727
70-0938	Massachusetts Institute of Technology, Cambridge, MA	421		Systems, Inc.	424
70-0968	Gannon College, Eric, PA	421	71-5805	Model: Vandenburgh, Chem-Nuclear Systems, Inc.	424
70-1068	Florida, Univ. of, Gainesville, PL	421	71-5874	Model: WAPD-40, Energy, Dept. of	424
70-1113	General Electric Co., Wilmington, NC	421	71-5908	Model: DOT-6M Type B,	
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	422		Babcock & Wilcox Co.	424

Docket		Name	Page	Docket	Name	Page
7	1-5926	Model: GE-100, General Electric Co.	424	71-9094	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	427
71	1-5939	Model: GE-1500, General Electric Co.	424	# # 000	•	,
71	1-5957	Model: BMI-1, Battelle Columbus Laboratory	424	71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	427
71	1-6088	Model: D-38, Oak Ridge National Lab	424	71-9098	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	427
7	1-6115	Model: R1010-0032, Energy, Dept. of	425		•	
71	1-6574	Model: HN-200, Hittman Nuclear & Development Corp.	425	71-9111	Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	427
<u> </u>			120	71-9128	Model: C-8, Gamma Industries	427
71	1-6601	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	425	71-9132	Model: T-3, Energy, Dept. of	427
71	1-6678	Model: LP-30, Energy, Dept, of	425	71-9135	Model: Century S & SA, Century Univ. S & SA, Gamma Industries	427
7	1-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	425			
71	1-6717	Model: 6717-B. Gamma Industries	426	71-9139	Model: 589, General Electric Co.	427
	1-9006	Model: 500-SU, Automation Industries, Inc.	426	71-9145	Model: NUPAC 50-1.5L, -2.5L, -3.OL & -4.OL, No Users	427
71	1-9032	Model: 650, Technical Operations, Inc.	426	71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	428
71	1-9033	Model: 660 & 660B, Technical Operations, Inc.	426	7 4 - 4 7 9		
7:	1-9036	Model: C-1, Source Production &		71-9158	Model: GPU 80, General Public Utilities	428
		Equipment Co.	426	71-9159	Model: NUPAC Series A, Nuclear Packing, Inc.	428
71	1-9053	Model: 683, Technical Operations, Inc.	426		Nuclear Packing, Inc.	440
71	1-9056	Model: Spec 2-T, Source Production &		71-9161	Model: R, Gulf Nuclear, Inc.	428
,	1-9020	Equipment Co.	426	71-9162	Model: GNM-20, Gulf Nuclear, Inc.	428
71	1-9074	Model: AP-100, ANEFCO, Inc.	426	71-9163	Model: GNG-20, Gulf Nuclear, Inc.	428
71	1-9079	Model: HN-100, Series 2 & 2A, Hittman		71-9166	Model: 864 Type B, Technical Operations, Inc.	428
		Nuclear & Development Corp.	426	71-9186	Model: S-6213, Energy, Dept. of	428
71	1-9080	Model: 9080, Hittman Nuclear & Development Corp.	427	, - , 100		
7	1-9086	Model: HN-100, Series 1, Hittman Nuclear				
		& Development Corp.	427	Licensing of In	dependent Spent Fuel Storage — Docket 72	
71	1-9089	Model: HN-1008, Hittman Nuclear		-		
		& Development Corn	427	72,0001	Morris Operations, General Ricciric Co.	428

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket	27				
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Minnesota Mining & Manufacturing,		
Richland, WA, U.S. Ecology, Inc.	27-048	1	St. Paul, MN	40-8135	8
Sheffield, IL, U.S. Ecology, Inc.	27-039	1	Molycorp, Inc., Los Angeles, CA	40-8794	10
Domestic Licensing of Source Material - Doc	eket 40		National Aeronautics & Space Administration, Hampton, VA	40-8546	9
Aluminium Co. of America	40-0501	5	Nuclear Metals, Inc., Concord, MA	40-0672	6
Atlas Mineral, Inc., Denver, CO	40-3453	7	Ogle Petroleum, Inc., Casper, WY	40-8745	10
Bear Creek Uranium Co., Casper, WY	40-8452	8	Pathfinder Mines Corp., Riverton, WY	40-2259	7
Chamberlain Manufacturing Corp., Waterloo, IA	40-8211	8	Pathfinder Mines Corp., Shirley Basin, WY	40-6622	7
Chemetron Corp., Chicago, IL	40-8724	9	Plateau Resources, Ltd., Grand Junction, CO	40-8674	9
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	9	Radiation Management Corp., Northbrook, IL	40-8801	10
Conoco, Inc., Denver, CO	40-8743	9	Rio Algom Corp., Moab, UT	40-8084	8
Conoco, Inc., Denver, CO	40-8793	10	Rocky Mountain Energy Co., Denver, CO	40-8697	9
Custom Machine, Inc., Cleveland, OH	40-8791	10	Silver King Mines, Inc., Casper, WY	40-8602	9
BM Chemicals, Hawthorne, NY	40-8823	11	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	10
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	9	Union Carbide Corp., Grand Junction, CO	40-0299	5
Exxon Co. USA, Houston, TX	40-8102	8	Uranerz USA, Inc., Casper, WY	40-8783	10
Exxon Minerals Co. USA, Houston, TX	40-8064	8	Uranium Resources, Inc., Richardson, TX	40-8786	10
Federal-American Partners, Riverton, WY	40-4492	7	Vistron Corp., Lima, OH	40-7604	7
Kawecki Berylco Industries, Inc., Boyertown, PA	40-6940	7	W. R. Grace & Co., Pompton Plains, NJ	40-0086	2
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	6	Washington Public Power Supply System, Richland, WA	40-0460	5
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	7	Western Nuclear Corp., Jeffrey City, WY	40-1162	6
Кеп-McGee Nuclear Corp.,			Western Nuclear, Inc., Lakewood, CO	40-8684	9
Oklahoma City, OK	40-8768	10	Wyoming Mineral Corp., Lakewood, CO	40-8502	9
Minerals Exploration Co., Los Angeles, CA	40-8348	8	Wyoming Mineral Corp., Lakewood, CO	40-8585	9
Minerals Exploration Co., Los Angeles, CA	40-8584	9	Yankee Atomic Electric Co., Westborough, MA	40-7138	7

Name	Docket	Page	Name	Docket	Page
Domestic Licensing of Production and Utiliza Docket 50	tion Facilities —		Callaway Plant, Unit I	STN-50-483	375
Advanced Critical Reactor Experiment	50-246	47	Callaway Plant, Unit 2	STN-50-486	378
Aerotest Radiography & Research Reactor	50-228	38	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	168
Allens Creek Nuclear Station, Unit 1	50-466	373	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	173
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	331	Carroll Facility I	STN-50-599	416
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	332	Carroll Facility II	STN-50-600	417
Arkansas Nuclear One, Unit 1	50-313	159	Catawba Nuclear Station, Unit 1	50-413	316
Arkansas Nuclear One, Unit 2	50-368	267	Catawba Nuclear Station, Unit 2	50-414	320
B-SAR-205	STN-50-561	414	Catholic Univ. of America Research Reactor	50-77	17
B-SAR-24!	STN-50-481	374	CESSAR System 80	STN-50-470	374
Babcock & Wilcox Co. Critical Facility	50-13	13	Cherokee Nuclear Station, Unit 1	STN-50-491	379
Babcock & Wilcox Test Reactor	50-99	18	Cherokee Nuclear Station, Unit 2	STN-50-492	380
Bailly Generating Station	50-367	267	Cherokee Nuclear Station, Unit 3	STN-50-493	380
Barnwell Reprocessing Plant	50-332	213	Clinch River Breeder Reactor	50-537	403
Beaver Valley Power Station, Unit 1	50-334	215	Clinton Power Station, Unit 1	50-461	371
Beaver Valley Power Station, Unit 2	50-412	316	Clinton Power Station, Unit 2	50-462	372
Bellefonte Nuclear Plant, Unit 1	50-438	333	Columbia Univ. Research Reactor	50-208	31
Bellefonte Nuclear Plant, Unit 2	50-439	337	Comanche Peak Steam Blectric Station, Unit 1	50-445	351
Big Rock Point Nuclear Plant	50-155	21	Comanche Peak Steam Electric Station, Unit 2	50-446	354
Black Fox Station, Unit 1	STN-50-556	413	Cooper Nuclear Station	50-298	136
Black Fox Station, Unit 2	STN-50-557	414	Cornell Univ. Research Reactor	50-157	25
BOPSSAR	STN-50-560	414	Cornell Univ. Zero Power Reactor	50-97	18
Braidwood Station, Unit 1	STN-50-456	364	Crystal River Nuclear Plant, Unit 3	50-302	141
Braidwood Station, Unit 2	STN-50-457	365	Davis-Besse Nuclear Power Station, Unit 1	50-346	235
BRAUNSAR	STN-50-532	403	Davis-Besse Nuclear Power Station, Unit 2	50-500	385
Brigham Young Univ. Research Reactor	50-262	77	Davis-Besse Nuclear Power Station, Unit 3	50-501	385
Browns Ferry Nuclear Power Station, Unit 1	50-259	65	Diablo Canyon Nuclear Power Plant, Unit 1	50-275	97
Browns Ferry Nuclear Power Station, Unit 2	50-260	70	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	187
Browns Ferry Nuclear Power Station, Unit 3	50-296	132	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	163
Brunswick Steam Electric Plant, Unit 1	50-325	192	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	166
Brunswick Steam Electric Plant, Unit 2	50-324	189	Dow Chemical Co.	50-264	79
Byron Station, Unit 1	STN-50-454	356	Dresden Nuclear Power Station, Unit 1	50-10	12
Byron Station, Unit 2	STN-50-455	360	Dresden Nuclear Power Station, Unit 2	50-237	39

Name	Docket	Page	Name	Docket	Page
Dresden Nuclear Power Station, Unit 3	50-249	51	Hope Creek Nuclear Station, Unit 2	50-355	251
Duane Arnold Energy Center	50-331	210	Humboldt Bay Power Plant, Unit 3	50-133	18
Edwin I. Hatch Nuclear Plant, Unit 1	50-321	179	Idaho State Univ. Research Reactor	50-284	113
Edwin I. Hatch Nuclear Plant, Unit 2	50-366	264	Indian Point Station, Unit 1	50-3	11
Enrico Fermi Atomic Power Plant, Unit 1	50-16	14	Indian Point Station, Unit 2	50-247	47
Enrico Fermi Atomic Power Plant, Unit 2	50-341	231	Indian Point Station, Unit 3	50-286	116
Essar, Ebasco Services	STN-50-591	416	Iowa State Univ. Research Reactor	50-116	18
Floating Nuclear Plant	STN-50-437	332	James A. Fitzpatrick Nuclear Power Plant	50-333	213
Forked River Nuclear Station, Unit 1	50-363	262	Joseph M. Farley Nuclear Plant, Unit 1	50-348	239
Fort Calhoun Station, Unit 1	50-285	113	Joseph M. Farley Nuclear Plant, Unit 2	50-364	262
Fort St. Vrain Nuclear Generating Station	50-267	85	Kansas State Univ. Research Reactor	50-188	27
GASSAR-6	STN-50-535	403	Kewaunee Nuclear Power Plant	50-305	145
General Atomic Co.	50-89	18	La Crosse Boiling Water Reactor	50-409	312
General Atomic Company	50-163	25	LaSalle County Station, Unit 1	50-373	276
General Electric Nuclear Test Reactor	50-73	17	LaSalle County Station, Unit 2	50-374	281
General Electric Test Reactor	50-70	17	Limerick Generating Station, Unit 1	50-352	242
Georgia Institute of Technology Research Reactor	50-160	25	Limerick Generating Station, Unit 2	50-353	247
Georgia Tech Research Reactor	50-276	101	Maine Yankee Atomic Power Plant	50-309	150
GESSAR-238	STN-50-447	356	Manhattan College Research Reactor	50-199	27
GESSAR-238-BOP, Interface	STN-50-550	412	Marble Hill Nuclear Station, Unit 1	STN-50-546	410
GESSAR-251	STN-50-531	403	Marble Hill Nuclear Station, Unit 2	STN-50-547	411
Gibbsar, Gibbs & Hill	STN-50-584	416	Massachusetts Institute of Technology Research Reactor	50-20	14
Grand Gulf Nuclear Station, Unit 1	50-416	323	Memphis State Univ. Research Reactor	50-538	410
Grand Gulf Nuclear Station, Unit 2	50-417	328	Michigan State Univ. Research Reactor	50-294	129
Greene County Nuclear Power Plant	50-549	412	Midland Plant, Unit 1	50-329	203
H.B. Robinson Plant, Unit 2	50-261	74	Midland Plant, Unit 2	50-330	207
Haddam Neck Plant	50-213	31	Midwest Fuel Recovery Plant	50-268	87
Hartsville Nuclear Plant, Unit i	STN-50-518	391	Millstone Nuclear Power Station, Unit 1	50-245	45
Hartsville Nuclear Plant, Unit 2	STN-50-519	392	Millstone Nuclear Power Station, Unit 2	50-336	222
Hartsville Nuclear Plant, Unit 3	STN-50-520	392	Millstone Nuclear Power Station, Unit 3	50-423	330
Hartsville Nuclear Plant, Unit 4	STN-50-521	393	Mississippi State Univ. Research Reactor	50-241	42
Haven Nuclear Plant, Unit 1	STN-50-502	385	Monticello Nuclear Generating Plant	50-263	77
Hope Creek Nuclear Station, Unit 1	50-354	250	National Bureau of Standards Reactor	50-184	26

Name	Docket	Page	Name	Docket	Page
National Naval Medical Center	50-170	25	Pilgrim Nuclear Power Station, Unit 1	50-293	127
New Haven, Unit 2	STN-50-597	416	Point Beach Nuclear Plant, Unit 1	50-266	82
Nine Mile Point Nuclear Station, Unit 1	50-220	36	Point Beach Nuclear Plant, Unit 2	50-301	138
Nine Mile Point Nuclear Station, Unit 2	50-410	315	Prairie Island Nuclear Station, Unit 1	50-282	110
North Anna Power Station, Unit 1	50-338	225	Prairie Island Nuclear Station, Unit 2	50-306	147
North Anna Power Station, Unit 2	50-339	228	Purdue Univ. Research Reactor	50-182	26
North Anna Power Station, Unit 3	50-404	311	Quad-Cities Station, Unit 1	50-254	59
North Carolina State Univ. PULSTAR Reactor	50-297	136	Quad-Cities Station, Unit 2	50-265	79
Nuclear Examination Reactor	50-375	283	Rancho Seco Nuclear Generating Station	50-312	156
Nuclear Fuels Recovery & Recycle Center	50-564	414	Reed College Research Reactor	50-288	122
Oconee Nuclear Station, Unit 1	50-269	87	RESAR-3S	STN-50-545	410
Oconee Nuclear Station, Unit 2	50-270	90	RESAR-41	STN-50-480	374
Oconee Nuclear Station, Unit 3	50-287	119	RESAR-414 Westinghouse Electric Corp.	STN-50-572	416
Ohio State Univ. Research Reactor	50-150	21	Rhode Island & Providence Plantations AEC	50-193	27
Oregon State Univ. Research Reactor	50-243	42	River Bend Station, Unit 1	50-458	367
Oyster Creek Nuclear Power Plant	50-219	33	River Bend Station, Unit 2	50-459	369
Palisades Nuclear Plant	50-255	62	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	42
Palo Verde Nuclear Station, Unit 1	STN-50-528	396	Rockwell International Corp. Critical Facility	50-147	21
Palo Verde Nuclear Station, Unit 2	STN-50-529	399	RPI Critical Experiment	50-225	38
Palo Verde Nuclear Station, Unit 3	STN-50-530	401	Salem Nuclear Generating Station, Unit 1	50-272	94
Peach Bottom Atomic Power Station, Unit 1	50-171	26	Salem Nuclear Generating Station, Unit 2	50-311	153
Peach Bottom Atomic Power Station, Unit 2	50-277	101	San Onofre Nuclear Station, Unit 1	50-206	27
Peach Bottom Atomic Power Station, Unit 3	50-278	103	San Onofre Nuclear Station, Unit 2	50-361	255
Pebble Springs Nuclear Plant, Unit I	50-514	390	San Onofre Nuclear Station, Unit 3	50-362	260
Pebble Springs Nuclear Plant, Unit 2	50-515	390	Saxton Nuclear Experimental Facility	50-146	21
Pennsylvania State Univ. Research Reactor	50-5	12	Seabrook Nuclear Station, Unit 1	50-443	347
Perkins Nuclear Station, Unit 1	STN-50-488	378	Seabrook Nuclear Station, Unit 2	50-444	349
Perkins Nuclear Station, Unit 2	STN-50-489	378	Sequoyah Nuclear Plant, Unit 1	50-327	196
Perkins Nuclear Station, Unit 3	STN-50-490	379	Sequoyah Nuclear Plant, Unit 2	50-328	200
Perry Nuclear Power Plant, Unit 1	50-440	340	Shearon Harris Nuclear Power Plant, Unit 1	50-400	307
Perry Nuclear Power Plant, Unit 2	50-441	344	Shearon Harris Nuclear Power Plant, Unit 2	50-401	309
Phipps Bend Nuclear Station, Unit 1	STN-50-553	412	Shearon Harris Nuclear Power Plant, Unit 3	50-402	311
Phipps Bend Nuclear Station, Unit 2	STN-50-554	413	Shearon Harris Nuclear Power Plant, Unit 4	50-403	311

Name	Docket	Page	Name	Docket	Page
Shoreham Nuclear Power Station	50-322	182	Univ. of Michigan Research Reactor	50-2	11
Skagit Nuclear Power Project, Unit 1	50-522	394	Univ. of Missouri Research Reactor	50-186	26
Skagit Nuclear Power Project, Unit 2	50-523	395	Univ. of Missouri Research Reactor	50-123	18
South Texas Project, Unit l	STN-50-498	381	Univ. of New Mexico Research Reactor	50-252	59
South Texas Project, Unit 2	STN-50-499	383	Univ. of Oklahoma Research Reactor	50-112	18
Space Radiation Research Reactor	50-187	26	Univ. of Utah Research Reactor	50-407	311
St. Lucie Plant, Unit 1	50-335	220	Univ. of Washington Research Reactor	50-139	19
St. Lucie Plant, Unit 2	50-389	293	Univ. of Wisconsin Research Reactor	50-156	25
State Univ. of New York Research Reactor	50-57	17	Vermont Yankee Nuclear Power Station	50-271	93
Sterling Power Nuclear Project, Unit 1	STN-50-485	377	Virgil C. Summer Nuclear Station, Unit 1	50-395	302
Surry Power Station, Unit 1	50-280	104	Washington State Univ. Research Reactor	50-27	14
Surry Power Station, Unit 2	50-281	108	Waterford Generating Station, Unit 3	50-382	283
Susquehanna Steam Electric Station, Unit 1	50-387	287	Watts Bar Nuclear Plant, Unit 1	50-390	296
Susquehanna Steam Electric Station, Unit 2	50-388	291	Watts Bar Nuclear Plant, Unit 2	50-391	299
SWESSAR-PI	STN-50-495	381	West Valley Reprocessing Plant	50-201	27
Texas A&M Univ. Research Reactor	50-59	17	Westinghouse Critical Experiment	50-87	17
Texas A&M Univ. Research Reactor	50-128	18	William B. McGuire Station, Unit 1	50-369	270
Three Mile Island Nuclear Station, Unit 1	50-289	122	William B. McGuire Station, Unit 2	50-370	274
Three Mile Island Nuclear Station, Unit 2	50-320	176	William H. Zimmer Nuclear Station, Unit 1	50-358	252
Trojan Nuclear Plant	50-344	233	Wolf Creek Generating Station	STN-50-482	374
Turkey Point Plant, Unit 3	50-250	54	Worcester Polytechnic Institute		
Turkey Point Plant, Unit 4	50-251	56	Research Reactor	50-134	19
Tuskegee Institute Research Reactor	50-406	311	WPPSS Nuclear Project, Unit 1	50-460	369
U.S. Geological Survey Research Reactor	50-274	97	WPPSS Nuclear Project, Unit 2	50-397	305
UCLA Training Reactor	50-142	20	WPPSS Nuclear Project, Unit 3	STN-50-508	386
Union Carbide Research Reactor	50-54	17	WPPSS Nuclear Project, Unit 4	50-513	389
Univ. of Arizona Research Reactor	50-113	18	WPPSS Nuclear Project, Unit 5	STN-50-509	388
Univ. of California at Irvine Research Reactor	50-326	196	Yankee-Rowe Nuclear Power Station	50-29	14
Univ. of Florida Training Reactor	50-83	17	Yellow Creek Nuclear Plant, Unit i	STN-50-566	414
Univ. of Illinois LOPRA Research Reactor	50-356	252	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	415
Univ. of Kansas Research Reactor	50-148	21	Zion Nuclear Power Station, Unit 1	50-295	129
Univ. of Lowell Research Reactor	50-223	38	Zion Nuclear Power Station, Unit 2	50-304	143
Univ. of Maryland Research Reactor	50-166	25			

Name	Docket	Page	Name	Docket	Page
Domestic Licensing of Special Nuclear Materia	l - Docket 70		Pennsylvania State Univ., University Park, PA	70-0113	418
Babcock & Wilcox Co., Apollo, PA	70-0135	418	Pittsburgh, Univ. of, Pittsburgh, PA	70-0359	420
Babcock & Wilcox Co., Apollo, PA	70-0364	420	Rockwell International Corp., Canoga Park, CA	70-0025	417
Babcock & Wilcox Co., Lynchburg, VA	70-1201	422	Schlumberger Technology Corp., Ridgefield, CT	70-0261	419
Babcock & Wilcox Co., Lynchburg, VA	70-0824	421	Scattle Univ., Scattle, WA	70-0600	420
Babcock & Wilcox Co., Lynchburg, VA	70-0027	417	Slippery Rock State College, Slippery Rock, PA	70-1230	422
Carnegie-Mellon Univ., Pittsburgh, PA	70-0303	419	Southeast Missouri Hospital.	70-2174	423
Catholic Univ. of America, Washington, DC	70-0190	419	Cape Girardeau, MO	70-0511	420
Combustion Engineering, Inc., Windsor, CT	70-0036	418	St. Peter's College, Jersey City, NJ	70-0033	418
Commerce, Dept. of, Washington, DC	70-0398	420	Texas Instruments, Inc., Attleboro, MA	70-033	420
Duke Power Co., Charlotte, NC	70-2623	423	UNC Naval Products, Inc., Uncasville, CT		420
Edlow International Co., Washington, DC	70-2955	423	Union Carbide Corp., Tuxedo, NY	70-0687	421
Exxon Nuclear Co., Inc., Richland, WA	70-1257	422	United Nuclear Corp., Wood River Junction, RI	70-0820	421
पाorida, Univ. of, Gainesville, FL	70-1068	421	Washington & Jefferson College, Washington, PA	70-0629	420
Jannon College, Erie, PA	70-0968	421	Westinghouse Electric Corp., Horseheads, NY	70-0184	419
Jeneral Atomic Co., San Diego, CA	70-0734	420	Westinghouse Blectric Corp., Pittsburgh, PA	70-1151	422
General Electric Co., Pleasanton, CA	70-0754	421	Westinghouse Electric Corp., Pittsburgh, PA	70-1810	423
General Electric Co., San Jose, CA	70-1308	423	Westinghouse Electric Corp., Prattville, AL	70-2909	423
General Electric Co., Wilmington, NC	70-1113	421	Packaging of Radioactive Material for Transport of Radioactive Material Under Certain Conditi	and Transport	ntion
Gulf Research & Development Co., Pittsburgh, PA	70-0624	420	Amersham Corp.	71-0370	424
Howard Univ., Washington, DC	70-0625	420	Industrial Nuclear Co.	71-0062	424
Kerr-McGee Nuclear Corp., Oklahoma City, C		422	Mercury Metals, Inc.	71-0480	424
Kerr-McGee Nuclear Corp., Oklahoma City, C		421	Model: 181375, 181361, Advanced Medical	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Long Island Lighting Co., Hicksville, NY	70-2884	423	Systems, Inc.	71-5796	424
Massachusetts Institute of Technology,		•	Model: 44, Energy, Dept. of	71-5097	424
Cambridge, MA	70-0938	421	Model: 500-SU, Automation Industries, Inc.	71-9006	426
Mercyhurst College, Brie, PA	70-1173	422	Model: 589, General Electric Co.	71-9139	427
Mississippi Power & Light Co., Jackson, MS	70-2936	423	Model: 650, Technical Operations, Inc.	71-9032	426
National Aeronautics & Space Administration, Hampton, VA	70-1314	423	Model: 660 & 660B, Technical Operations, Inc.	71-9033	426
National Carbon Co., Fostoria, OH	70-0273	419	Model: 6717-B, Gamma Industries	71-6717	426
Newton Memorial Hospital, Newton, NJ	70-2625	423	Model: 683, Technical Operations, Inc.	71-9053	426
Nuclear Fuel Services, Inc., Brwin, TN	70-0143	418	Model: 814A, Babcock & Wilcox Co.	71-5149	424
Nuclear Research Corp., Dover, NJ	70-0356	419	Model: 864 Type B, Technical Operations, Inc.	71-9166	428
Pennsylvania Power & Light, Allentown, PA	70-2937	423	Model: 9080, Hittman Nuclear & Development Corp.	/1-9080	427

Name	Docket	Page	Name	Docket	Page
Model: AP-100, ANEFCO, Inc.	71-9074	426	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	71-9151	428
Model: BB-250-2, Combustion Engineering Co., Inc.	71-5768	424	Model: HN-100S, Hittman Nuclear	71-9089	427
Model: BMI-1, Battelle Columbus Laboratory	71-5957	424	& Development Corp.	/1-9089	447
Model: C-1, Source Production & Equipment Co.	71-9036	426	Model: HN-200, Hittman Nuclear & Development Corp.	71-6574	425
Model: C-8, Gamma Industries	71-9128	427	Model: LP-50, Energy, Dept. of	71-6678	425
Model: Century S & SA, Century Univ. S & SA,			Model: NFS-4, Nuclear Fuel Services, Inc.	71-6698	425
Gamma Industries	71-9135	427	Model: NUPAC 50-1.5L, -2.5L, -3.0L & -4.0L, No Users	71-9145	427
Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	71-9094	427	Model: NUPAC Series A, Nuclear Packing, Inc	. 71-9159	428
Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	427	Model: R, Gulf Nuclear, Inc.	71-9161	428
Model: CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	425	Model: R1010-0032, Energy, Dept. of	71-6115	425
Model: CNS 6-80-2, Chem-Nuclear Systems,			Model: S-6213, Energy, Dept. of	71-9186	428
Inc.	71-9111	427	Model: Spec 2-T, Source Production & Equipment Co.	71-9056	426
Model: D-38, Oak Ridge National Lab	71-6088	424	• •	,	427
Model: DOT-6M Type B, Babcock & Wilcox Co	. 71-5908	424	Model: T-3, Energy, Dept. of	71-9132	427
Model: GE-100, General Electric Co.	71-5926	424	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	71-9098	427
Model: GE-1500, General Electric Co.	71-5939	424	Model: Vandenburgh, Chem-Nuclear Systems,	71-5805	424
Model: GNG-20, Gulf Nuclear, Inc.	71-9163	428	Inc.		
Model: GNM-20, Gulf Nuclear, Inc.	71-9162	428	Model: WAPD-40, Energy, Dept. of	71-5874	424
Model: GPU 80, General Public Utilities	71-9158	428	X-Scan Inspection Co. Licensing of Independent Spent Fuel Storage —	71-0478 Docket 72	424
Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	71-9086	427	Morris Operations, General Electric Co.	72-0001	428
Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	: 71-9079	426			

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S. ECOLOGY, INC

- 8208030125 Forwards sampling & analysis data received from Phase i study Info distributed to committee members prior to 820610 meeting GAYNOR, R. K 82/06/07 UB Ecology, Inc. (Formerly Nuclear Engineering) 14200-285.
- --8208030127 Sampling & analysis data for Mar 1782 * UB Ecology, Inc (Formerly Nuclear Engineering) 82/06/07 3pp 14200 286
- 8208170227 Forwards "Trench 18 Monitoring Record, Jan-Mar 1982 " HIPBHER, W M UB Ecology, Inc (Formerly Nuclear Engineering) 82/06/11. E8810, T H Region 3, Office of Director 1p 14369 028
- --8209170234 "Trench iB Monitoring Record.Jan-Mar 1982"
 W US Ecology. Inc. (Formerly Nuclear Engineering) B2/06/11 ip 14369 029.
- B208030119 Porwards summery of B20610 technical update meeting to evaluate Phase 1 of tritium investigation QAYNOR, R. K. UB Ecology, Inc. (Formerly Nuclear Engineering) B2/07/07 UB Ecology, Inc. (Formerly Nuclear Engineering) 8pp 14197:353.
- B20B130242 Forwards summary of B20610 technical update meeting re site tritium migration investigation Sampling & analysis data & map of locations of well to be dug in Phase 2 encl QAYNOR, R K. UB Ecology, Inc. (Formerly Nuclear Engineering) B2/07/07. NRC No Detailed Affiliation Given 8pp 14333 157.
- 8208130158 Forwards quarterly monitoring data of piecometers & wells in vicinity of Trench 18 % Trench 18 sumps for Apr-June 1982 HIPSHER,W M US Ecology, Inc (Formerly Nuclear Engineering) 82/07/12. E881Q,T H. Region 3, Office of Director ip 14337 030
- --B208130161 Quarterly monitoring data of piezometers & wells in vicinity of Trench 18 & Trench 18 sumps for Apt-June 1982

 * UB Ecology, Inc (Formerly Nuclear Engineering), 82/07/12, 1p
- 8208040302 Bummary of 820610 meeting w/IL Dept of Nuclear Safety.lL Atty General Dfc,IL State Oeological Survey & US Ecology to discuss results of Phase I tritium migration studies & finalize plans for Phase II studies BIEFKEN.D L. Low Level Waste Licensing Branch 82/07/15
 HAHKINB.E F Low Level Waste Licensing Branch 28pp 14223 280
- 8208020224 Statement re status of settlement negotiations per ASLB 820714 order. Certificate of Svc encl WETTERHAHN, M. J. US Ecology. Inc (Formerly Nuclear Engineering) WETTERHAHN, M. J. Conner & Metterhahn 82/07/29 5pp 14152.028.
- B208030258 Order granting NRC 820728 motion to file status rept on negotiations 10 days after repts filed by other parties Motion consistent w/Commission regulations QUOMHOPE, A C. Atomic Barety and Licensing Board Panel 82/08/02 Office of the Executive Legal Director 2pp 14158 127
- 8208050502 Notice of CF Eason change of address Certificate of Svc encl. EABON, C.F US Ecology, Inc. (Formarly Nuclear Engineering) 82/08/02, 3pp 14214:161
- B208060107 Statement of progress in settlement negotiations Certificate of Svc 4ncl. CHABNOFF, B. A. Illinois, State of. B2/08/02 Bpp. (4238 184

8208170335 Statement concerning progress in ongoing settlement negotiations w/US Ecology & State of IL Portions of 15 points addressed in NRC/US Ecology site stabilization & closure conditions met Certificate of Suc enci

- DOCKET 27-047 BARNWELL, SC. CHEM-NUCLEAR SYSTEMS, INC
- 8208110125 Responds to questions raised at 820715 meeting re tender offer for common stock of Chem-Nuclear Bus. Inc GERSHOWITZ, H. Waste Management, Inc. 82/07/19 DAVIS, J.O. Office of Nuclear Material Safety & Bafeguards
- B2DB170385 Advises of developments re tender offer made for common stock of Chem-Nuclear Bys. Inc Haste High Inc will acquire up to 55% of common stock for cash w/balance of stock exchanged for Waste High Inc stock in merger REIS.H F Lowenstein.Newman.Reis.Axelrad & Toll B2/07/27 DAVIS.J. G Office of Nuclear Material Bafety & Safeguards, Director 2pg 14372.322
- 8208170381 Forwards 820729 1tr originally delivered by messenger re Chem-Nuclear Sys, Inc & Waste Mgt, Inc merger REIS:H F Lowenstein: Newman, Reis: Azelrad & Toll 82/07/29 DAVIS:J G Office of Nuclear Haterial Safety & Safeguards, Director 19 14272 014.
- --8208170383 Forwards pertinent provisions of agreement of merger between Chem-Nuclear Sys. Inc. & Waste Mgt. Inc Request for NRC consent to transfer of control will be filed soon REIS. H F Lowenstein. Newman, Reis. Axelrad & Toll 82/07/29 DAVIS. J. O Office of Nuclear Material Safety & Bafesyuards. Director 10pp 14372 015
- DOCKET 27-048 RICHLAND, WA, U 8 ECQLOOY, INC
- B208030365 Forwards Waste Packaging Insp Rept 15000046/82-09 on B20622 Noncompliance noted BDDK,H E Division of Radiological Safety & Bafeguards Program 82/07/29 GRELLA,A Division of Fuel Facilities, Materials & Bafeguards 1p 14158.113
- --B208030369 Waste Packaging Insp Rept 15000046/82-07 on 820622
 Noncompliance noted 55-gallon drum of low specific activity.
 NOS radioactive math had i to 1 1/2-inch diameter hole in
 lid of drum
 HATTE. J A . THOMAS R D . BOOK. H E Division of Radiological Safety
 & Esfeguards Program 82/07/29. US Ecology. Inc (Formerly
 Nuclear Engineering) 3pp 14158
- 8208050535 PNO-V-B2-032 on 920728, shipment containing 54 wooden boxes of low level waste received w/nine boxes not labelled as LSA matl & one box leaking Burial permit for TVA suspended, effective 820728
 THOMAS: B D Region 5, Office of Director 82/07/30 ip. 14213 301
- 8208100145 PNO-V-82-033 on 820805, shipment containing 42 drums of low specific activity low level waste received from Nuclear Matls of Concord, MA will d off one drum Licenses banned from site Shipment placed in trench for disposal THOMAS.R.D. Region 5, Office of Director. 82/08/05 ip 14298 052
- 8208100192 Forwards Waste Packaging Insp Rept 15000046/82-10 on 820707 Noncompliance noted BOOK, H E. Region 5, Office of Director 82/08/06 GRELLA, A Fuel Facilities & Materials Branch 1p. 14297; 218

- --8208100196 Waste Packaging Insp Rept 15000046/82-10 on 820707 Nancompliance noted incorrect placarding & failure to brace shipment WALTELJA: THOMAS, R.D., BOOK, H.E. Region S. Diffice of Director 82/08/06 US Ecology, Inc. (Formerly Nuclear Engineering) 13pp 14297 219
- 8208240407 Forwards IE Waste Packaging Insp Rept 15000046/82-11 on 820728 BOOK.H.E Division of Radiological Safety & Safeguards Program 82/08/17 QRELLA.A Fuel Facilities & Materials Branch 1p 14522 316
- --B208240410 IE Maste Packaging Insp Rept 15000046/B2-11 on 820728
 Nancompliance noted shipment received from TVA Browns Ferry
 Nuclear Plant was inspected & nine boxes identified w/o
 radioactive low-specific activity markings
 SIEWART,N J , THOMAS,R D , BOOK,H E Region 5, Office of Director,
 82/08/17 UB Ecology, Inc (Formerly Nuclear Engineering) 2pp
 14522 317.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0086 W R GRACE & CO . POMPTON PLAINS, NJ

- 8208250061 Responds to FOIA request for documents re NRC activities concerning Sheffield Brook & mati re radiation in Hayne, NJ Forwards documents listed in App A FELTON, J M Davision of Rules and Records 82/06/17 AKST, D Record. The Hackensack, NJ 10pp 14560 003
- ---8201140133 Summary of 811124 & 25 discussions w/MR Grace Chemical Core radiological survey plan for Pompton Plains site
 CROW.M T Uranium Fuel Licensing Branch 81/11/30 Uranium
 Fuel Licensing Branch 2pp 14361 216.
 - 8208250066 Issues License R-132.authorizing receipt, possession & title to unlimited rew source mati. Related info encl.
 JOHNSON, L. Atomic Energy Commission, 54/04/01, STONE, R. L. Rare Earths, Inc. 35pp. 14350-013
- -8208280067 Forwards renewed Source Matl License STA-422 HARMON,D F Atomic Energy Commission 68/02/26 GARING,P J W. R Grace & Cp 1g 14560 330
- --8208250072 Issues License R-132, authorizing receipt, possession & title to unlimited raw source math from producers & distributors licensed by AEC & through importation, for processing only.

 Related info encl Chergy Commission 56/07/25. STONE, R. L. Rare Earths, Inc. 7pp 14560 048.
 - 208250073 Renewed Source Matl License SUA-422 for UR Orace & Co. Davison Chemical Div.authorizing unlimited use of thorium for ore processing w Atomic Energy Commission 68/02/26 2pp 14560-331
 - 208250077 Forwards guidance in response to 560629 ltr re proposed receipt of 100 lb thorium bomb reduction residues
 JOHNSON L Atomic Energy Commission 56/07/25, MANDLE R H H.
 R Grace & Co ip 14560 055
- 1208250080 Issues Revision 1 to License R-132, authorizing use of 100 lb thorium bomb reduction residues for experimental processing at Curtis Bay.140
 DCHNSON,L. Atomic Energy Commission 56/08/13. MANDLE.R.M. Rare Earths: Inc. 1p. 14360-036.
- 2008250082 Forwards Revision 1 to Source Mat1 License R-(32, authorizing procurement of 100 lb thorium bomb reduction residues JOHNSON:L Atomic Energy Commission 56/08/20 MANDLE, R. H Rare Earths. Inc. ip 14560:057
- 8208250084 Insp Findings & Licensee Ack dtd 681204 of License 8TA-422. Noncompliance noted records of surveys or disposals not properly maintained properly maintained 68/12/04 (p. 14860.341
- 8208250086 Forwards Form AEC-59! listing items of compliance noted during 681204 insp M/o form Related info enc!
 KIRKHAN.R.W Atomic Energy Commission 68/12/06 BWEITZER.H. W
 R Grace & Co 18pp. 14560:342
- 8208250087 Requests transfer of License R-132 to Davison Chemical Co. DIV of WR Grace & Co.Baltimore, MD 8TONE, R. L. Rere Earths, Inc. 56/12/21. JOHNSON, L. Atomic Energy Commission 2pp. 14560 G60.

- --B20825009: Summarizes 6B1230 telcon w/P Garino re spill of natural thorium in unrefined ore near Mayne. NJ No hazard associated w/spill Hatl szempt from AEC regulation No further action planned Related info encl CLEVELAND. R B. Atomic Energy Commission 69/01/06 RGEDER. J R Atomic Energy Commission 2pp. 14561 008
- --B208250093 Confirms RL Stone 561221 ltr re liquidation of Rare Earths, Inc Request for transfer of License R-132 to Davison Chemical Co reinterated BARRETT.D P. W R Orace & Co. 57/01/14. JDHN80N, L Atomic Energy Commission 1p. 14560-062
- --8208250094 Notifies of discontinuation of monerite processing on 710407 Storage license requested OARINO.P J W. R Grace & Co 71/04/06 Atomic Energy Gemmission ip 14561 010.
- ---B208230102 Discusses 710408 telcon w/R Stone re discontinued production of licensed mati at facility No further action recommanded BTEARNB, C.F., Atomic Energy Commission. 71/04/21 NELBON, R.P. Atomic Energy Commission. 1p. 14561,011
- --B20B250105 Forwards application for renewal of Source Matl License R-196 BARRETT, D P W R Orace & Co 5B/03/10 JOHNSON, L Atomic Energy Commission ip. 14560.046
- --8208250106 Issues Amend 1 to Bource Matl License BTA-422 to authorize thorium storage only.

 LAYFIELD.L. Atomic Energy Commission 71/04/23 GARING, P. J. W. R. Grace & Co. ip. 14561 012
- --8208250110 Notifies of expiration of Source Matl License BTA-422 on 730228. MALARD, J. G. Atomic Energy Commission 72/12/27 W R Grace & Co 4pp 14561,013.
- ---8208250i12 Forwards application for renewal of storage License STA-422, Related info encl. MOBLEY, B L W R. Grace & Co. 73/12/14. ROUSE, L Atomic Energy Commission: Directorate of Licensing App 14561 017
- --9208250114 Application for renewal of Source Matl License R-176, * W R Grace & Co 58/04/11. 1p 14560.067.
- --B208250117 Discusses 731206 telcons w/J Metager & Mobley re Bource Matl License BTA-422 No problem w/leaving buriel matl on property BMITHIR Atomic Energy Commission 73/12/06 Atomic Energy Commission. 3pp. 14561 026
- ---8208250118 Issues Source Matl License R-196, authorizing possession of unlimited quantities of thorium-containing matl for processing at Pompton Plains, NJ & Curtis Bay, MD facilities.

 DELANEY, J C. Atomic Energy Commission 58/03/13 BARRETT, D, P, W R Orace & Co 1p 14560-068.
- --B208250119 Forwards application to renew Bource Matl License R-196.
 BARRETT, D. P. W. R. Grace & Co. 59/03/19. DELANEY, J. C. Atomic Energy Commission 1p. 14560:069.
- --B208290120 Forwards fee for renewal of Source Matl License STA-422, authorizing matl storage, per 731224 telcon.

 BUBLEY, B. L. W. R Orace & Co 74/01/03 MEISS, D Atomic Energy Commission. ip. 14561 027.
- --8208280122 Application for renewal of Bource Matl License BTA-422, authorizing continued Use of storage facilities MOBLEY, B. L. M. R. Grace & Co. 73/12/14 Rpp. 14561-030
- --B20B2B0124 Requests application fee for renewal of License BTA-422, in response to 731214 ltr. Related info encl.
 HILLER, W. O. Atomic Energy Commission, 74/01/03, SHAW, F. W. R. Orace & Co. 2pp. 148611032.
- --8208250125 Requests advice re importation of 5 1b normel U disxide from Caneda PRICE:A L. H. R. Grace & Co. 59/04/29. DELANYE, J.C. Atomic Energy Commission. 1p. 14560:072.

- --9208250130 Forwards rept re decontamination of facility Release for unrestricted use & termination of storage license requested H/o encl H08LEY.B L W R Grace & Co 74/07/26 SINGER.B Atomic Energy Commission ip 14561 135
- --9208250134 Discusses telcon w/Q Epstein re close-out survey of facility Further decontamination required prior to release for unrestricted use Related info encl BUCHANAN Atomic Energy Commission 74/09/04 SINGER, B , COLLINS, D Atomic Energy Commission, 13pp 14561 136
- --9209250136 Forwards compliance insp rept of Licenses R-194, R-132 & C-3623 Noncompliance noted excess radiation levels in restricted areas, failure to perform radiation surveys & improper storage of licensed matl W/o encl KIRKMAN, R W Atomic Energy Commission 60/01/26 Atomic Energy Commission 3pp 14360 089
- --8208250139 Requests renewal of License R-196 to receive & process therrium-containing matls at facility TORQUE.TO W R Grace & Co 60/02/11 DELANEY, J C Atomic Energy Commission ip 14360 092
- --8208250140 Ack receipt of 600211 application to renew License R-196 DELANEY, J. C. Atomic Energy Commission 60/02/15 TONGUE, T D W. R Orace & Co ip 14560 093
- --B208250142 Ack receipt of 600211 application to renew License R-196 DELANEY, J.C. Atomic Energy Commission 60/02/17 TONOUE, T.O. W R. Grace & Co. 1p. 14560-094
- --8208250146 Discusses 591125 insp No noncompliance noted re License C-3623 Noncompliance noted re License R-196.failure to conduct radiation surveys & improper radwaste disposal JOHNSON, L Atomic Energy Commission 60/03/14 BARRETT, D P W R Grace & Co 4pp 14560 095
- ~-8208250151 Discuses 600408 telcon w/DC Hubbard of Davison Chemical Co confirming AEC 600413 visit to investigate 600314 notice of violation PAOE: R O Atomic Energy Commission. 60/04/08 Atomic Energy Commission ip 14560 079
- --8208250133 Bummary of 600413 meeting w/DLR & Davison Chemical Co to discuss compliance status of Pompton Plains,NJ facility WRLTY,C O Atomic Energy Commission 60/03/24 Atomic Energy Commission 2pp 14560 100
- --9208250155 Forwards final rept re decontamination of facility. Release of facility for Unrestricted use & termination of storage license requested W/o encl.
 MOBLEY.B L. W R. Grace & Co. 74/09/id SINGER, B. Atomic Energy Commission ip 14561 148
- --8208250158 Ack receipt of 600411 ltr informing of corrective actions taken in response to violations noted in AEC 600314 ltr Application to release source matl to unrestricted areas not received
 JOHNSON.L. Atomic Energy Commission 60/06/06 BARRETT.D P. W. R. Grace & Co. ip. 14360 102
- --8208250159 Forwards RQ Insp Rept 40-0086/74-01.
 NELSON-P R Atomic Energy Commission. 74/10/22 THORNBURG, H D.
 Atomic Energy Commission. 1p. 14551:149
- --8208250166 RO Insp Rept 40-0086/74-01 on 740731-0920 re close-out survey of facility Final survey results showed agreement w/licensee results
 EPSTEINE: MCCLINTOCK, R. Atomic Energy Commission. 74/10/08.
 R22pp. 14561 150
- --8208250167 Forwards "Health Physics Manual" & "Procedures for Measurement of Redioactivity "
 TONGUE, T.O. W. R. Orace & Co. 60/06/29 JOHNSON, L. Atomic Energy Commission ip 14560-104
- --8208250174 Submits addl info for release of facility per 741029 telcon Burial area graded, dressed w/fill dirt & seeded Drainage measurements failed to disclose any radioactivity MOBLEY, B.L. M. R. Grace & Co. 74/10/30 BINGER, B. Atomic Energy Commission 1p 14561 172
- ---8208250182 Discusses close-out survey of facilities for release to unrestricted use New owner should be licensed to possess buried thorium or math should be transferred to authorized disposal site
 RGY. W. Atomic Energy Commission 74/11/07 NELBON, P.R. Atomic Energy Commission. 2pp 14561:174

- ~-8208250183 Reiterates 601109 request for info re complation of anforcement action for licensee WARNER, DE Atomic Energy Commission 61/01/13 JOHNBON, L. E. Atomic Energy Commission 19 14560-173
- --8208250187 Transcript re point of noncompliance noted during 1964 insp of facility concerning radwaste burial Reburial completed in accord w/exact requirement following citing QARIND.P J Affiliation Unknown, 74/12/16 Atomic Energy Commission 1p. 14561 176
- --8208250188 Advises re deferred reinspection scheduling of licensee pending receipt of info that anforcement action has been completed.

 WARNER-D E Atomic Energy Commission 61/05/15 ROGERS,L R Atomic Energy Commission. ip 14360-174
- --B208250193 Transcript re reburial of radwaste at facility during 1764-65
 BAUN, J. Affiliation Unknown 74/12/16 Atomic Energy Commission. 1p. 14561 177,
- --B20B250199 Recommends release of unrestricted property, based on licenses statements of compliance. Land records should indicate that math has been buried on property.

 LIEBERHANLY Office of the General Counsel 75/01/09

 BUCHANANC NRC No Detailed Affiliation Given ip. 14561-178
- --B20B250200 Compliance insp rept on 610629. No noncompliance noted Major areas inspected previous items of noncompliance re maint of records invantories receipts & transfers of refined source matl
 KLEVIN.P B. . KIRKMAN.R. Atomic Energy Commission 61/06/29 9pp. 14560-176
- --B208250201 Advises that property meets decontamination criteria for release of facilities for unrestricted use based on 740709 survey rept & 0916,1030 & 1217 ltrs.

 SINDER, B. Office of Nuclear Material Safety & Safeguards Director. 75/01/22 MOBLEY, B. L. W. R. Grace & Co. ip 14561 179.
- --B208250204 Responds to request for release of property formerly under License BTA-422 for unrestricted use, Property meets decontamination criteria & can be released for unrestricted used. Reduss te should be buried per 10CFR20 304 (1974) SINOER.B Office of Nuclear Material Bafety & Safeguards, Director 75/01/22 MOBLEY.B L W R Grace & Co 1p. 14361:180
- --B20B250208 Advises that next inspector should assure that new facility owner is licensed Related info encl
 MCCLINTOCK-R O NRC No Detailed Affiliation Oiven. 75/02/19
 NRC No Detailed Affiliation Given 12pp. 1456: 181
- --8209250222 Advises that preliminary evaluation of Pompton Plains sits indicates surface radiation up to 1 m/h Site does not meet criteria for release for unrestricted use JOYNER, J. H. Division of Engineering & Technical Inspection, 81/07/30 HIGGINBOTHAM, L. Radiological Bafety Branch. App. 14561:196
- --8208250226 Forwards Region 1 file for License BTA-422, including requested insp repts M/o encl.
 JDYNER, J. H. Technical Inspection Branch. 81/08/25 CROW, W.T. Uranium Fuel Licensing Branch 1p. 14561:202.
- --B208250231 Requests review of Pompton Plains, NJ site to determine legal responsibility for remedial action HIGGINBOTHAM, L. Radiological Safety Branch 81/09/18 CUNNINGHAM, G. Office of the Executive Legal Director 1p
- --820825020å Advises that request for legal interpretation of responsibility for remedial action at Pompton'Plains, NJ site has been initiated in response to 810730 memo HIQQINBUTHAM, L. Radiological Safety Branch. 81/09/18 NRC ~ Np Detailed Affiliation Given. ip 14561, 204.
- --B208250237 Requests authorization to burn 100 lb of burlap bags containing monatite sand GARINO.P J. H. R. Grace & Co 61/07/03 JOHNSON.L. Atomic Energy Commission 1p. 14860:198
- ---B208250242 Forwards Region 1 request for survey of Pompton Plaine, NJ site. Tentative completion date requested HIGOINBOTHAM.L. Radiological Safety Branch. 81/09/18. PAGE, B. Q Uranium Fuel Licensing Branch. 2pp 145511205.

- --8208250244 Suppls 600620 & 0713 lies replant operations & disposal of plant effluents Requests permission to continue operations w/present sys of controls & records pending const of sanitary sewer GARING.P J W R Orace & Co 61/07/06 JOHNSON, L Atomic Energy Commission 2pp 14560.199
- --8208250249 Advises that radiological survey of Pompton Plains site will be initiated in response to 610918 request PAGE.R O Uranium Fuel Licensing Branch 81/10/08 HIGGINBOTHAM.L Radiological Safety Branch 1p 14561 208
- --8208250251 Advises that no items of noncompliance noted during 610529 insp KLEVIN,F B Atomic Energy Commission 61/07/19, MANDLE:R H R Grace & Co Rpp 14560 201
- --8208250259 Requests preliminary site visit & development of radiological survey plan for Pompton Plains.NJ site MILDE,R.M. Uranium Fuel Licensing Branch FIN A-9093 81/10/08 GRESHAM.J.R. Office of Nuclear Material Safety & Bafeguards. Director 2pp. 14561 209
- ~-8208250261 Requests full rept on 610627 insp of facility.
 CUNNINGHAM, R.E. Atomic Energy Commission 61/07/28 DUBINSKI, L.
 Atomic Energy Commission 1p 14560:205
- ~~B208250266 Forwards summary licensing history of facility & file for License BTA-422, per request.

 KINNEMAN.J D Materials Radiological Protection Section 8:/10/27 FONNER.R Office of the Erecutive Legal Director 4pp 14561-211
- --B208250267 Submits application for new source math license for unlimited amount of math for use in rere earth operations in Pompton Plains. NJ. TONOUE, T.O. U. R. Orace & Co. 61/08/02 JOHNSON, L. Atomic Energy Commission 2pp 14560-206.
 - 208250273 Forwards excerpt from "clear" compliance insp rept of facility
 KIRKHAN-R.W Atomic Energy Commission 61/08/07 LOWENSTEIN, R
 Atomic Energy Commission 3pp 14560-208
- 8208250275 Confirms Bill25 discussion re preliminary visit to site during which 811207 Final comprehensive survey plan & tentative schedule will be provided.

 CROM.WIT Uranium Fuel Licensing Branch 81/11/27 HARDWICKE, J
- 8208250278 Requests complete rept of 610629 insp of facility to assist
 in license application processing
 DUSINSKIFL Atomic Energy Commission. 61/08/08 KIRKHAN, R. W.
 Atomic Energy Commission ip 14560 211
 - 9208250283 Ack receipt of 610719 "clear" notice of insp on 610629. Further enforcement action unnecessary. CUNNINOHAM.R E Atomic Energy Commission. 61/09/10 NUSSRAUMER.D. Atomic Energy Commission fp 14560 212.
- d208250265 Forwards licensing history of WR Grace & Co, Pompton Plains:NJ facility, CAMPBELL:M. Region I. Philadelphia, Office of the Director (81/03/01) 81/11/30 SLY:D Director's Office of Inspection and Enforcement 4pp, 14551.218
- 8208250288 Forwards "clear" follows insprept for facility KIRMAN.R M. Atomic Energy Commission. 61/08/17. LOMENSTEIN.R. Atomic Energy Commission. 19 14560 213.
- 3208250291 Forwards GA Program Insp Rept 99970001/81-21,in response to 811125 raquest.
 HAYNES, R Region 1. Philadelphia, Office of the Director (81/03/01). 81/11/30 STELLG.V. Regional Operation, & Generic Requirements 4pp. 14561-222
- 208250295 Forwards historical background & summary of WR Grace insprepts.

 CAMPBELL, M Region 1, Philadelphia, Office of the Director

 (81/03/01) 81/12/01 SLY, D. Region 1, Philadelphia, Office of the Director (81/03/01). 2pp 14561, 230.
- 208250297 Confirms results of Bil214 meeting re WR Grace site in Pompton Plains, NJ Characterization of potential radiological risk to public from creek holds priority THORNBURGO, H.D. Division of Safequerds & Radiological Safety Inspection. 81/12/16. MAUSSHARDT, D. Office of Nuclear Material Safety & Safeguards, Director. 1p. 14561, 236.

- --8208250306 Responds to request for background info re NRC desire to perform radiological survey of Fompton Plains, NJ site Status questioned because of burial problems identified when license was terminated PAGE, R G Uranium Fuel Licensing Branch 81/12/24 HARDWICKE, J W R Grace & Co 2pp 14561 257
- --8208250310 Forwards QA Program Insp Rept 97970001/81-21 More detailed surveys uill be performed in 1982 MARTIN,TT Technical Inspection Branch 81/12/30 FELDMAN,J Environmental Protection Agency ip 14961 259
- --B2082503i3 Submits analysis, findings & conclusions from radiological safety evaluation of facility Licensee complies w/AEC regulations HARMON, D.F., NUSSBAUMER, D.A. Atomic Energy Commission 61/10/04 Atomic Energy Commission 3pp 14560 227
- ~-B20B250315 Discusses B20218 telcon w/J Kinneman re preliminary site visit on B20226 to formulate plans for radiological survey Project assigned to R Hace CROM, H. T. NRC ~ No Detailed Affiliation Given, B2/02/19 FA0E, R G NRC ~ No Detailed Affiliation Given 2pp 14561.261
- --9209250317 Forwards Bource Matl License STA-422 Special request required for utilizing respirators in determination of airbonne radioactivity exposure Related info encl NUSBBAUMER, D. A. Attonic Energy Commission 61/11/22 MANDLE, R. W. R. Grace & Co. 2pp 14560 230
- --\$208250321 Bource Mat1 License SUA-442 for HR Grace & Co, Davison Chemical Div.authorizing use of unlimited thorium for processing NUSSBAUMER, D Atomic Energy Commission 61/11/22 1p
- --8208250325 Notifies of insp on 640701 restatus of compliance w/ 100FR30,40 & 20 Related info encl KIRKMAN.R W Atomic Energy Commission 64/06/24 MANDLE.R W R Orace & Co 2pp. 14560 235
- --B20B250327 Summary of 811214 meeting w/DDE to discuss WR Grace & Co facility in Pompton Plains,NJ DDE agreed to inform NRC re decision on remedial action List of attendees encl CAMPSELL.M A Region 1, Office of Director 82/03/24 KINNEMAN.J D. Region 1, Office of Director 3pp 14561-266
- --B20B250329 "Proposed Rediological Survey Plan, WR Grace Property Pompton Plains, NJ" * NRC - No Detailed Affiliation Given 82/03/15 Spp 14561 269.
- -- 0208250330 Responds to 640717 notice of noncompliance Corrective actions surface contamination surveys conducted & thorium sludge burial method modified Decontamination procedures encl MANDLE, R M W R Drace & Co 64/07/24 KIRKMAN, R W Atomic Energy Commission. 3pp. 14560 237
- --8208250332 Summary of 820226 meeting w/Oak Ridge Associated Univs.

 WR Grace & Co & Electro-Nucleonics Inc to provide first hand
 info re site geography & bristing concerning radiological
 survey Public notification recommended
 CAMPBELL.M Region 1. Office of Director 82/04/01 KINNEMAN, J
 Region 1. Office of Director. 2pp 14561 277
- --8208250334 Application for renewal of Source Matl License STA-422 for use of unlimited quantities of thorium for one processing SWEITZER, H J W R Grace & Co 67/11/03 3pp 14560 262
- --B208250337 Responds to 670310 inquiry relicenses Source Mati License BTA-422 issued on 641012, authorizing possession of unlimited quantity of thorium KIRKMAN,R W Atomic Energy Commission 67/03/20 Marcus & Levy, lp. 14560:235
- --B20B250338 Notice of violation from insp on 640701 Noncompliance noted surveys to determine concentrations of removable surface contamination in restricted & unrastricted areas conducted EPSYEIN.E Atomic Energy Commission 64/07/17, ip 14960.240
- ---B208250343 Notifies of expiration of License STA-422 on 641031.
 Application for license renewal should be filed if program continues.
 NUSBBAUMER, D. Atomic Energy Commission. 64/09/02. W R. Graca & Co. lp. 14560-243.

- -B208250344 Summary of S20325 meeting w/MR Grace & Co re plans for survey of Sheffield Brook area in Wayne, NJ Discussions re responsibility for remedial action premature, pending survey KINNEMAN, J D Region 1, Office of Director 82/04/27 MARTIN, T T Division of Engineering & Technical Programs 2pp
- --8208250347 Application for renewal of Source Matl License STA-422, authorising possession of unlimited quantities of thorium for processing w W R Grace & Co 64/09/21 1p 14560 244
- --8208250348 Summary of 820416 meeting w/Mayor of Wayne Township,NJ recontamination at WR Grace facility KINNEMAN,J D Region 1, Office of Director 82/04/28 JGYNER,J H Region 1, Office of Director 1p 14861 319
- -- 8208250352 Forwards application for renewal of Source Matl License STA-422 STONE, R L W R Grace & Co 64/09/18 Commission 1p 14560 245 Atomic Energy
- --B208250359 Forwards renewed Source Matl License STA-422 NUSSBAUHER, D. Atomic Energy Commission 64/10/12 BTONE, R. L. W. R. Grace & Co. 1p. 14560 247
- --8208250364 Concurs that present exemption inappropriate, in response to 660923 ltr re amend to 10CFR20, Section 20 203(f)
 QARINO, P J W R Grace & Co 66/10/07 NUSBBAUMER, D Atomic Energy Commission ip 14560 250
- --5208250365 Amends Source Matl License BTA-422 per 661007 application Licenses exempt from requirements of 10CFR20 Section 20 203 (e)(2), provided all entrances to plant are conspicuously HARMON,D F Atomic Energy Commission 66/11/04. OARING,P.J R R Orace & Co ip 14560 251
- --8208250366 Notifies of 661117 insp of facilities re compliance w/10CFR20 & provisions of 10CFR30,32,33,34,35,40 & 70 KIRKMAN,R.W Atomic Energy Commission 66/11/15 GARIND.P R Orace & Co ip 14560 252
- --8208250368 Submits evaluation of compliance insp.Licensee has corrected deficiencies No apparent health & safety irregularities found found GRANT,W B Atomic Energy Commission 66/11/30 Commission Ip. 14560-254 Atomic Engrau
- --8208250369 Advises that Source Matl License STA-422 expires on 671031 Application for license renewal should be filed if program continues NUSSBAUMER, D. Atomic Energy Commission 67/08/28, QARING, F ogram continues 9898AUMER, D. Atomic Energy Commission 67/08/28. GARING, P.J. R. Grate & Co. ip. 14560-254
- --8208250370 Application for renewal of Source Matl License 8TA-422, authorizing use of unlimited quantity of thorium for ore processing SWEITZER: H J W R Grace & Co 67/09/19 1p. 14560 257
- --B208250371 Requests filling of new application for Source Hatl License STA-422 W/o ref to previous application 30-days prior to license expiration HARMON, DF Atomic Energy Commission 67/10/06 SWEITZER, H. J W R Orace & Co ip 14360 259
- --B208250372 Requests that encl process description re breakup of monarite sands be treated as company confidential math & withheld from PDR SNEITZER, H J W R Grace & Co 47/11/03. HARMON, D F Atomic Energy Commission 2pp 14560-260.
- manual - Includes procedures for mer radioactivity GARINO.P J W R Grace & Co 68/0 Energy Commission 4pp 14560 266 68/02/13 HARMON,D F Atomic
- --8208250378 "Health Physics Manual " GARING.P J W R Grace & Co 67/10/10 56pp. 14560 270

- --8208250384 Responds to 600606 request re-status of application to cogrouped response to account request re-state or applicate release source mati to unrestricted areas Manual covering sampling procedures, methods of evaluation & time spent by employees at location prepared Related info encl TONOUE. TO UR Grace & Co 60/06/20 JOHNSON, L At Energy Commission 9pp 14561 335 JOHNSON, L Atomic
- --8208250392 Summary of 780905 meeting w/DDE in Germantown, MD re WR Grace site in Curtis Bay. MD Company will submit complete radiological survey of disposal area by 781001 Related info enc: KINNEMAN, J D Office of Nuclear Haterial Safety & Safeguards, Director 78/09/22 Office of Nuclear Haterial Safety & Safeguards, Director 13pp 14561 353
- 8208130227 Provides results of 820630 soil sample analysis of three EVOLUMENT PROVIDES TESUITS OF BZOCHO SOIL Sample analysis of low level hot spots mear railroad siding north of old Pompton Plains, NJ railroad station Th~121 concentrations indicate no immediate hatard. KINNEMAN, JD Division of Engineering & Technical Programs 82708/09 FITZPATRICK: P Pequannock: Township of, NJ, i 14333 142
- --820Bi30236 Requests results of soil temple analysis of three low level hot spots near railroad siding north of old Pompton Plains, NJ railroad station FITZPATRICK,F. Pequannock, Township of, NJ, 82/07/12. CAMPBELL,M Region 1, Office of Director is 14333 143
- 820B180003 Informs that rept re Dak Ridge Associated Univs surveys will be completed by late Aug or early Sept Final rept will not be available until Dec 1982 Aerial rediological survey indicates no hazard to nursing home KINNEMAN, J D Region i, Office of Director 82/08/11, HAVERMANN, B Willowbrook Mursing Home Wayne, NJ, 19 14378 289
- 8208200070 Forwards "Radiological Surveys of Sheffield Brook," preliminary rept. HOBLEY, B W R Grace & Co 82/08/16 JGYNER, J. H Division of Engineering & Technical Programs 2pp 14392 262
- --820820008; "Rediblogical Surveys of Sheffield Brook," proliminary rept FRAME.P W., BERGER, COLE.L W. Oak Ridge Associated Univ. 82/07/31 57pp 14392-244
- DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO
- 9208050045 Discusses 820621 telcon w/H Pettengill of NRC re status of Land Guelity Div schedule for review of Union Carbide tailings reclamation plan. Review completed & forwarded to Wuoming, State of 3pp.
 - FRANCIB, E Wyoming, State of. 82/06/23
- 8208040044 Forwards summary on reclamation performance bonding for Oas Hills mining operation Bonds require recalculation HONG, T Union Carbide Corp. 82/07/12 FLEMING, T NRC No Detailed Affiliation Given 3pp 14232 361.
- 8208040252 Grants 820707 request for extension until 820815 to answer 820614 requests in form of revisions to tailing & heap leach reclamation plan.

 ACKERMAN, W.C. Wyoming, State of 82/07/13 WONG, T. Union Carbide 5pp 14232:273
- DOCKET 40-0440 HABHINGTON PUBLIC POHER BUPPLY BYSTEM, RICHLAND, WA
- 8208200090 Forwards corporate organizational changes effective B20810. Changes will be reflected in future revisions to FSAR & operational QA program description.
 8DUCHEY.0 D Hashington Public Power Bupply System 82/08/16.
 NOVAK.T.H Assistant Director for Licensing 4pp 14393 241 24X Fichs 50-397.82/08/16.8208200090
- DOCKET 40-0501 ALUMINIUM CO OF AMERICA
- 8208230206 Forwards IE Insp Rept 40-0501/82-01 on 820629 No noncompliance noted
 MARTIN, T T Division of Engineering & Technical Programs. 82/08/06
 GEIGER, R Aluminum Co of America. 2pp. 14013-207

- --8208230214 IE Insp Rept 40-0501/82-01 on 820629 No noncompliance noted Major areas inspected formerly licensed site engaged in production of magnesium thorium casting alloys, including interviews w/site owners
 JOHANSEN, J M , KINNEHAN, J D Region 1. Defice of Director 82/07/28 App. 14513 211
- --8208230222 Source Mati License C-5023 for Aluminum Co of America authorizing use of 1.400 lb source matl for experimental use for production of magnesium thorium casting allow DELANEY, J G Atomic Energy Commission, Directorate of Licensing 60/01/11 ZANES, R H Aluminum Co of America 3pp 14513 214
- 8208230229 Forwards IE Insp Rept 40-0501/82-01 on 820629 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs 82/08/06 ORUSER, C Gruber Supply Corp 2pp 14513 334
- 8208230236 Forwards IE Insp Rept 40-0501/82-01 on 820629 No noncompliance noted MARTIN.TT Division of Engineering & Technical Programs 82/08/04 HURLEY, J CPC International Inc 2pp. 14508 341

DOCKET 40-0672 NUCLEAR METALS, INC , CONCORD, MA

- 8208060240 Requests add1 info re rept on Last Quarter 1981 skin dose to employes, per 820301 ltr. Info requested within 14 days Rept withheld (ref 100FR2 790) MARTIN, T T Division of Engineering & Technical Programs. 82/07/21 VWBACO, F. Nuclear Matals, Inc 2pp 14241 318
- 82083:0424 Advises that 820818 request for extension to respond to IE insp rept forwarded in NRC 820721 Itr granted Response to be submitted by 820727.

 KINNEMAN.J D. Division of Engineering & Technical Programs 82/08/26 TRIFFIN.W B Nuclear Metals, Inc. ip 14693-289
- --B20B310423 Requests 30-day extension to respond to B20721 ltr re rept on 19B1 last quarter skin dose to employee, contained in IE insp rept. VUHBACG.F.J Nuclear Metals, Inc. B2/07/29 MARTIN, T. T. Region 1. Office of pirector. 1p 14693 270

DOCKET 40-1162 WESTERN NUCLEAR CORP , JEFFREY CITY, HY

- 8207220663 Forwards annual technical evaluation, "Insp & Surveillance of Embankment Retention Sys." required per License Condition 16
 BDQDEN, 0 Western Nuclear, Inc. (aubs of Phelps Dodge Corp.)
 82/04/30 PETTENGILL, H. J. Uranium Recovery Licensing Branch 2pp.
 14024 022
- --8207220673 "Insp & Surveillance of Embankment Retention Sys." annual technical evaluation required per License Condition 16, for period Jul 1981-May 1982 H/16 oversize drawings Aperture cards are available in PDR Western Nuclear. Inc (subs of Phelps Dodge Corp) 82/06/29, 38pp 14024-024.
- 8208090025 Forwards "Split Rock Hill Hater Guality Rept," Jan-Mar 1982
 Rept includes groundwater, drinking water & surface water
 results
 BOODEN, 6 Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.)
 82/06/30 PETTENGILL, H. J. Uranium Recovery Licensing Branch 2pp
 14301-172
- ---8208090026 "Bplit Rock Mill Water Guality Rept," Jan-Mar 1982 Three oversize maps encl Aperture cards are available in PDR, a Mestern Nuclear, Inc. (subs of Phelps Dodge Corp.) 82/06/30 339pp 14301,174
- 8208170393 Responds to request for add1 info re 820319 & 0520 submittals of environ monitoring data. In future repts, concentrations of radionuclides in water will be reported in units of uci/ml.
 8088EN.O. Western Nuclear, Inc. (subs of Phelps Dodge Corp.), 82/07/16. PETTENGILL, H. J. Uranium Recovery Licensing Branch. 2pp. 14372.326
- B20B2404B: Informs that Wells 17,18,19 & 23 located on floodplain to north/northwest of permit boundary presently inaccessible for sampling period. Addendum to third quarter 1982 groundwater monitoring rest will be submitted BODEN. O Western Nuclear, Inc. (subs of Phelps Dodge Carp.). B2/07/16 PETTENGILL, H.J. Uranium Recovery Licensing Branch ip. 14544-163

- 8208040070 Advises that all important items addressed in land use survey for Split Rock Mill GARCIA.P J , PETTENGILL.H J Uranium Recovery Licensing Branch 82/07/20 Uranium Recovery Licensing Branch 1p 14228 284
- DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , OXLAHDMA CITY, OX
- 8208040630 Revision O to "Mealth Physics Manual for Decommissioning & Stabilization of Kerr-McGee Chemical Corp.West Chicago Rare Earths Facility "
 LEVING.A J. OSODOD.N L Kerr-McGee Corp 81/05/22 360pp 14226 001
- 8208020462 Comments re DEB on decommissioning Rare Earths facility
 Proposal has no impact on prime or important farmlands
 Consideration must be given to impact on adjoining
 residential & recreational tracts
 ECKES.J. J. Agriculture.Dept of 82/06/21 PAGE.R O Uranium Fuel
 Licensing Branch 1p 14180 078
- 8208230183 Forwards comments on DEB for decomissioning Rare Earths Facility NRC should be prepared to monitor site for more than 5 yrs EARLEY, DF Affiliation Unknown 92/06/21 Uranium Recovery Licensing Branch App 14517 335
- 8208020447 Clarifies A Rapkin 820629 ltr confirming 820629 telcon re DES (NUREO-0904) Comments on DES should be submitted before 820706 All timely comments to be addressed before FEB issuance Comments received by end of Jul considered timely GROW.W T Uranium Recovery Licensing Branch 82/07/02 RAPKIN, A Illinois, State of ip. 14181 044
- 8208050004 Comments on DES for decommissioning of Rare Earths Facility, West Chicago, IL Document only partially addresses waste problems & health hazards in West Chicago, IL area CAHILL.P. Environmental Protection Agency 82/07/06 PACE, R Q Uranium Fuel Licensing Branch 4pp 14272 360
- 8208130332 Requests copies of Arganne EIA studies re characterization of geohydrology & subsurface chemistry & site surface RAPKIN.A Illinois. State of BZ/07/15. NIXON.W A Uranium Recovery Licensing Branch ip. 14340 244
- 8208130327 Forwards comments re DEB for decommissioning of Kerr-McQee Rare Earths Inc facility in West Chicago. IL GUBTAFBON,P F. Illinois, State of 82/07/27 PAGE,R G Uranium Recovery Licensing Branch 2pp. 14340 230
- 8208240058 Forwards comments on DES (NUREG-0704) re decommissioning of Rare Earths Facility SHELLEY, W.J. Kerr-McQpp Corp. 82/07/27 PAGE, R.O. Licensing Policy & Programs Branch. 35pp. 14548 111
- 820B130391 Comments on DES re decommissioning Rare Earths Facility, West Chicago, IL DES does not clarify recommended action, RAPKIN.A., FAHNER,T.C Illinois, State of 82/07/29, PAGE.R Q Uranium Fuel Licensing Branch, 34pp 14354 270
- 820Bi90029 Summary of 820728 meeting w/Kerr-McGee re views on NEPA issues raised in EPA 820706 itr on decommissioning of Kerr-McGee Rare Earths facility No decisions or conclusions reached
 NIXON-W A Uranium Fuel Licensing Branch 82/07/30 Uranium Fuel Licensing Branch ip 14506-260
- 8207180028 FOIA request for all drafts or preliminary versions of NUREO-0704 re DES concerning decommissioning of facility RAPKIN.A. Illinois, 8tate of 82/08/05 Office of Administration 2pp 14567 354
- 8208090165 Order CLI-82-21 directing NMSS director or designee to act as presiding officer to adjudicate City of West Chicago contentions challenging Kerr-McGee request for Amend 5 to license for Rare Earths Facility HOYLE, J C Office of the Secretary of the Commission 82/08/06, Kerr-McGee Corp. 5pp 14271:355,
- 8208250212 Forwards questions & statements received at 820621 public meeting re Kerr-McGee Rare Earths Facility in West Chicago IL ** NRC No Detailed Affiliation Given. 82/08/09 NRC No Detailed Affiliation Given. 10pp. 14551.274
- 8208260001 Responds to FDIA request for draft or preliminary versions of NUREO-0904, DEB concerning decommissioning of facility Belected records in PDR Preliminary drafts withheld (ref. FOIA Exemption 5)
 FELTON-J M Division of Rules and Records, 82/08/16 RAPKIN, A Illinois, 8tate of 2pp 14567, 355.

- 820B300318 Dbjects to portions of NRC 820B05 Order CLI-82-21, including informal type of hearing grantsd findings of no public interest & lack of stds upon which findings based SPELMAN, H J Harold J Spelman & Associates SPELMAN, H J West Chicago, IL 82/08/23 HOYLE NRC No Detailed Affiliation Given 2ap 14579 140
- DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY
- 8208040079 Comments on licensee environ monitoring data & dose evaluations for First Quarter 1982, submitted per License Condition 54 Licensee in compliance w/40CFR190. Three minor errors in reporting corrected BOLLENBERGER, D. PETTENGILL, H. J. Uranium Recovery Licensing Branch, 82/07/20 Uranium Recovery Licensing Branch, 6pp. 14228 294
- DOCKET 40-3453 ATLAS MINERAL, INC , DENVER, CO
- B2070A01B7 Forwards IE Insp Rept 40-3453/82-01 on B20525-27 & notice of violation BROWN, Q D Division of Vendor & Tachnical Programs B2/06/23. WEAVER.R.R Atlas Minerals 2pp 13706,142.
- --8207060191 Notice of violation from insp on 820525-27 * Division of Vendor & Technical Programs 82/06/23, 2pp. 13706 144
- --8207060192 IE Insp Rept 40-3453/82-01 on 820325-27 Noncompliance noted, failure to prevent recurrence of 40-h control measure & failure to select proper respiratory protection.
 CAIN.C L. SHOPENN, M r. EVERETT.R J. Region 4, Office of B2/06/16, 11pp. 13706,146
- 8208060348 Discusses Atlas Minarals 820519 response to request for info re 40CFR190 data Background air monitoring site should be relocated QARCIA.P J , PETTENGILL.H J Uranium Recovery Licensing Branch 82/07/28. Uranium Recovery Licensing Branch 2pp. 14281 281.
- 8208110009 Advises that licensee 820819 response to Item I of NRC 820803 request for info re present location of background air monitoring station unacceptable. Proposed site for relocation of station requested by 820901 PETTENOILL. H. J. Uranium Recovery Licensing Branch 82/07/28 BLUBAUOH: R.E. Atlas Minerals. ip. 14330 272.
- 8208120193 Ack receipt of 820720 ltr informing NRC of steps taken to correct violations noted in IE insp rept
 BROWN.9 D Division of Vendor & Technical Programs 82/08/05
 BLUBAUGH.R C. Atlas Minerals ip 14323.266.
- --8208120196 Responds to NRC 820623 ltr re violations noted in IE insprept Corrective actions calibr of environ air samplers performed on 820228 & Kurz Intl. Inc notified that extended turn-around time is unecceptable.

 BLUBAUDH R E Atlas Minerals 82/07/20 BROWN, O. D Division of Vendor & Technical Programs. 3pp 14323.267
- DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY
- 8208040306 Forwards water quality data requested in 820625 telcon. WATTB.K Federal American Partners. 82/06/28. GILLEN.D. Division of Fuel Cycle & Material Safety 11pp 14223; 269.
- 8208040295 Ack receipt of 680610 ltr re Tailings Pond 1 & proposal for in-pit tailings disposal. DES will be issued re proposed use of tailings ponds as eveporation ponds & sagebrush pit for subsurface disposal ANDRUG: N.J. Federal American Partners. 82/07/19 ACKERMAN. H. C. Wyoming: State of 4pp 14223:308.
- DOCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY
- 8208270836 Forwards one oversize topographic map requested by License Condition 41 of License 8UA-442. Amend 7. Aperture card is available in PDR BHITH. J C. Pathfinder Mines Corp 82/07/20. Uranium Recovery Licensing Branch. 1p 14683.221

- DOCKET 40-6940 KAWECKI BERYLCO IND . INC . BOYERTOWN, PA
- 8208040168 Application for amend of License SMB-920, correcting Form NRC-2. Item 2 re name change of corporation COYLE: F T Cabot Corp. 82/06/18 CROW.H T. Uranium Fuel Licensing Branch. 43pp 14236-316
- DOCKET 40-7138 YANKEE ATOMIC ELECTRIC CO , WESTBORDUGH, MA
- 8208270010 Responds to FQIA request for documents detailing collective dose exposures in 1781 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J. M. Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp 14677-208, 24X Fiche 50-000, 82/07/13, 8208270010.
- --8208270629 Forwards whole body range rept for CY81, per 10CFR20. 407 MGDDY, D. E. Yankee Atomic Electric Co. 82/03/12. HALLER, N. M. Office of Henagement and Program Analysis 1p. 14680 050. 24X Fiche. 50-000, 82/07/13, 8208270010.
- --8208270638 Whole body range rept for CY81.
 TRIJO.J., ANTIO.H A. Yankee Atomic Electric Co. 82/03/08. 1p. 14680.051 24X Fiche. 30-000, 82/07/13, 8208270010
- DOCKET 40-7604 VIBTRON CORP. , LIMA, OH
- 8208270552 Forwards IE Insp Rept 40-7604/82-01 on 820712-16 & 26. No noncompliance noted. PAPERIELUG. J. Division of Emergency Preparedness & Operational Support. 82/08/11. SHOWER.R.C. Vistron Corp. 2pp. 14556:047
- ---8208270557 IE Insp Rept 40-7604/82-01 on B20712-16 & 26. No noncompliance noted, Major areas inspected, site radiological status for license termination, shipping papers to confirm offsite disposal of 0-238 & effluent piping diagrams, NICHOLBON, N. A., BCHUMACHERM, C. Division of Emergency Preparedness & Operational Support, 82/08/04, App. 14566:049.
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK
- 820B040423 Requests copy of License 8UB-1010 listed in 820417 FR & environ appraisal of subj license. CORYDON.L. Pechiney Ugine Kuhlmann Development, Inc. 82/07/15. Division of Fuel Cycle & Material Safety. ip 14220-171
- 8208040407 Requests suspension of Condition 3b of Amend 17 to License SUB-1010 re molybdenum limit, Strict adherence to spec would limit fertilizer application of nitrogen, Nitrogen concentration due to unusually heavy reins, SHELLEY, W.J. Kerr-McGee Corp. 82/07/21. PAGE, R.O. Uranium Fuel Licensing Branch. 2pp. 14224:333.
- 8208040669 Requests EIA for Sequoyah U hexafluoride facility as described in 820617 FR CLAPPER.T.H. Oklahoma, State of. 82/07/21. Division of Fuel Cycle & Material Safety. 1p 14224;362.
- 8208090291 Informs of issuance of Amend 18 to License SUB-1010, exempting first 3 million gallons of treated raffinate distributed as fertilizer from mollybdenum content requirements of Amend 17. Condition 3. b. PAGE.R. C. Uranium Fuel Licensing Branch 82/07/28 SHELLEY, H. J. Kerr-McGse Nuclear Corp. ip 14007.100.
- ---8208070275 Safety evaluation supporting limited exemption for molybdenum content of treated raffinate.
 NIXON.M.A., GROH.M.T. Uranium Fuel Licensing Branch. 82/07/28, 3pp. 14307;101.
- 9208240465 Informs that Div of Accounting & Finance will refund portion of amend fee for Amend i7 to License BUS-1010.
 MILLER.W.O. License Fee Management Brench. 82/09/11 SHELLEY, W. J. Kerr-McCee Nuclear Corp. 1p. 14544:145
- 8208270002 Requests withdrawal of 820522 & 0414 applications to dispose of solidified raffinate sludge in below prade pit. Applications should be resubmitted when decision re sludge process reached. PAGE.R. Q. Uranium Fuel Licensing Branch. 82/08/17, SHELLEY, W. J. Kerr-McGee Nuclear Corp. 1p. 14683.220.

DOCKET 40-8064 EXXON MINERALS CO USA, HOUSTON, TX

- 8208060005 Documents 820702 telcon Summary breakdown of tailings basin reclamation vol & costs, mill decommissioning cost & solution mine restoration costs encl Engineering studies focusing on cut-fill vol continuing SHANNON, J B Erron Corp 82/07/09. FLEMMING, T. E NRC No Detailed Affiliation Given Spp 14244 361
- 8208160429 Forwards IE Insp Rept 40-8102/82-01 on 820628-0702 & notice of violation for License 8UA-1044 BROWN, G. D. Division of Vendor & Technical Programs 82/07/28 BRANNON, J. B. Exon Corp. 2pp. 14348-184
- ---8208160441 Notice of violation from insp on 820630 Noncompliance noted three monitor wells exceeded criteria for sulfates by greater than 20% from 820103-0323

 * Division of Vendor & Technical Programs 82/07/28 ip
- --8208160449 IE Insp Rept 40-8102/82-01 on 820628-0702 No noncompliance noted Major areas inspected U milling operations & radiation safety program, including organization & administration, internal review & audit HHTTEN, J. E. SPITZBERO, D. B., EVERETY, R. J. Division of Vendor & Technical Programs 82/07/22 7pp 14348, 187
- 8208260311 Provides contract costs incurred & manhours expended in reviewing 810728 application for renewal of License 8UA-1064
 KALMAN.K., FLORY.C., LINEHAN.J. Uranium Recovery Licensing Branch. 82/08/03 MILLER.W.O. License Fee Management Branch. 3pp. 14355 044.

DOCKET 40-8084 RIG ALGOM CORP , MDAB, UT

8208040286 Explains process for recovering U-308 from product emanating from Allisd Chemical Hetropolis Plant Approval requested.

LAHYON-M D Rio Algom. Ltd 62/07/16 PETTENGILL.H Uranium Recovery Licensing Brench 13pp 14225 179

DOCKET 40-BIO2 EXXON CO. USA, HOUSTON, TX

- B20B230A32 Informs of 10CFR170.31 Category 2A few requirement for B20427 request for approval of Highland U Operations fabounkment surveillance program HEIBS.D License Few flanagement Branch B2/05/14. SHANNON, J B Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp 14528 123
- --8208230435 Forwards Highland U Operations tailings retention sysembantment surveillance program, incorporating applicable portions of Reg Quide 3 ff. 1 & self-imposed weekly insp. gursuant to License Condition 27 gursuant to License Corp 3 gursuant Condition 27 gursuant Corp 3 gursuant Condition 27 gursua
- \$208230497 Forwards general emergency plan documenting actions to be initiated by personnel in event of radiological incidents, fires, tailings dam failure to transportation accidents w/ yellowcake spiilage-gursuant to License Condition 25. SHANNON, J. B. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 82/03/26 PETTENGILL, H. J. Uranium Recovery Licensing Branch App. 14529-076
- --9208230440 Highland U Operations emergency action plan.

 Exzon Nuclear Co., Inc. (subs. of Exxon Corp.), 82/05/26. App. 14529:078
- 8208030159 Reviews license amend request for onsite burial of waste matte & equipment contaminated w/metural U. Supports request.
 SMITH.R.D. High Level Waste Licensing Management Branch 82/07/08 SCARAND.R.A Uranium Recovery Licensing Branch. 2pp 14200 303.
- 8208060005 Documents 820702 telcon Summary breakdown of teilings basin reclamation vol & costs.mill decommissioning cost & solution mine restoration costs encl. Engineering studies focusing on cut-fill vol continuing SHANNON, J. E. Exxon Corp. 82/07/09 FLEMMING, T. E. NRC No Detailed Affiliation Given. Sap. 14244; 361

- 8208170002 Amends Source Matl License SUA-1139, revising License Condition 27 to require implementation of embankment surveillance program SCARAND, R.A. Uranium Recovery Licensing Branch 82/07/27 Exxon Coff p p 14372,003
- --8208170241 Discusses proposed amend to Bource Matl License SUA-1139, revising License Condition 27 to require implementation of embankment surveillance program JONES,8 Z , PETTENDILL,H, J Uranium Recovery Licensing Branch, 82/07/27 Uranium Recovery Licensing Branch 2pp, 14372,004,
- 820B16042P Forwards IE Insp Rept 40-8102/82-01 on 820628-0702 & notice of violation for License SUA-1064.
 BROWN, Q D Division of Vendor & Technical Programs 82/07/28 SHANNON, J B Exxon Corp 2pp. 14348 184
- --B20B160449 IE Insp Rept 40-B102/82-01 on 020628-0702 No noncompliance noted Major areas inspected U milling operations & radiation safety program including organization & administration, internal review & audit (MITTEN.) E . SPITZBERO, D. B . EVERETT, R. J. Division of Vendor & Technical Programs 82/07/22 7pp 14348 187
- DOCKET 40-8135 MINNEBOTA HINING & MANUFACTURING, BT PAUL, MN
- 8208040673 Forwards application to renew License STB-1129 WISBINK,R G 3M Co , Minnesota Mining & Mfg Co. 82/07/14 Division of Fuel Cycle & Material Safety 1p. 14225-238
- --8206040477 Application for renewal of License 878-1129, authorizing use of 5.682 kg thorium WIBSINK.R 0 3M Co. Hinnesota Mining & Mfg Co. 82/07/14 50pp
- DOCKET 40-8211 CHAMBERLAIN MANUFACTURING CORP., WATERLOD, IA
- 8208040291 Responds to NRC 820630 ltr re License 9UB-1198 No radioactive matls ever used, so no matls or wastes to be disposed of & no need for closeout survey. HILCOX.G L Chamberlin Manufacturing Corp. 82/07/06. BAQGETT Procedures & Certification Branch 3pp 14224 357
- DOCKET 40-8348 MINERALS EXPLORATION CO , LOS ANGELES, CA
- 820Bii0082 Advises that License BUA-i223 amended by revising License Condition 4 to extend expiration date from 920731 to 830201 Extention necessary for NRC to make final decision on adequacy of groundwater restoration SCARANO.R.A. Uranium Recovery Licensing Branch 82/07/27. Union Oil Co. of California. 1p. 14327-356
- DOCKET 40-8452 BEAR CREEK URANIUM CD , CABPER, WY
- 8208230116 Memorializes 820706 telcon License SUA-1310 820630 renewal application is for mill activities only. Heap leach tests referenced in Amends 2 & 8 no longer being conducted HERSLOFF,L W. Rocky Mountain Energy Co 82/07/07 WEISS,D Uranium Recovery Licensing Branch ip 14317:354
- B2GBii0053 Forwards dam raise specs for Geotechnical Engineering Svcs tailings dam const control & expansion of tailings disposal area Specs should be incorporated into Nov 1781 tailings mgt plan as App B.

 MEOLOCK, R. L. Bear Creek Uranium Co. B2/07/08 BCARANO, R. A.

 Uranium Recovery Licensing Branch App. 14329, 209
- --8208110054 Revision 2 to "Tach Spec for Geotechnical Engineering Svcs Tailings Dam Const Control " * Rocky Mountain Energy Co. 62/06/30 9pp 14329 215
- ---B208110057 Revision C to "Tech Spec for Expanding Capacity of Bear Creek Tailings Disposel Area " One oversize drawing encl Aparture card is evailable in PDR. 4 Rocky Mountain Energy Co 82/06/30 17pp 14329 224.
- 8208260589 Notifies that preliminary review of 820630 renewal application acceptable. Addl info will be requested during renewal review process Current license valid under 100FR40.43(b), PETTENOILL. H. J. Uranium Recovery Licensing Branch 82/07/30. BAUMANN, W. Bear Creek Uranium Co. 1p. 14569-145.

- DOCKET 40-8502 WYOMING MINERAL CORP , LAKEWOOD, CO
- 820B170372 Confirms B20715 telcon re excessive levels of chloride & alkalinity in Coal Zone Well 95M-1 Pumping initiated in closest well completed in upper Irigaray sandstone until chloride level decreases CONROY.B W Myoming Mineral Corp 82/07/20 CHANCELLOR,R Hyoming, State of 2pp 14371 115
- 8208170388 Provides corrective actions re 820630 leak in evaporation pend RA Leak & loss patch repaired & pumping stopped CONROY, BW Wyoming Mineral Corp 82/07/20 SCARAND, RA Uranium Recovery Licensing Branch CHANCELLOR, R Wyoming, State of 2pp 14372 324
- 8208300353 Amends Bource Matl License SUA-1341 authorizing replacement of Monitor Well R6-65 w/Monitor Well R8-79 in monitor well network at Irigaray Mine & requiring continuation of monthly monitoring of all excursion monitor wells

 SCARANDOR Uranium Recovery Licensing Branch 82/08/19 Hyoming Mineral Corp 2pp. 14697 173
- DOCKET 40-8946 NATIONAL AERONAUTICS & SPACE ADMIN , HAMPTON, VA
- 8208030232 IE Insp Findings & Licenses Ack dtd 820713 of License SUB-1297 Insp findings no violations observed. FRANKLIN.L C Region 2, Office of Director. 82/07/13 ip.
- DOCKET 40-8584 MINERALS EXPLORATION CO , LOS ANGELES, CA
- 8208030121 Forwards support documentation concerning design const. testing & insp of tailings impoundment Cell C for Sweetwater U Mill. in response to 820517 request PETTENGILL, H. J. Uranium Recovery Licensing Branch 82/05/28. FERRITER, Colorado, State of 2p 14178,354
- --B208030122 Requests that Div of Waste Mgt provide assistance to Mine Safety & Health Administration re info on Sweetwater U Hill Tailings insp on 920519 LEAR.G Hydrologic & Geotechnical Engineering Branch, 62/05/13 SCARANO.R A Uranium Recovery Licensing Branch ip 14198:356,
- 8208120032 Ack receipt of 820701 ltr informing NRC of steps taken to correct violations noted in IE insp of License 8UA-1350 BROWN, 0 D Region 4, Office of Director, 82/08/05 DYKERS, L 0 Hinerals Exploration Co. (subs of Union Gil Co of California) 1 14324 233
- --8208120034 Responds to NRC 820611 ltr re violations noted in IE inap of License 8UA-1350 Corrective actions, repairs to product packaging equipment completed, including installation of butterfly shutoff valve
 SNYDER, H L Minerals Exploration Co (subs of Union Oil Co of California), 82/07/01 SEYFRIT, K V Region 4, Office of Director 5pp. 14324 234
- DOCKET 40-8585 WYOMING HINERAL CORP , LAKEHOOD, CO
- B20B260543 Bubmits results of review of semiannual affluent monitoring rept Release rates below those previously estimated in Section 5 of EIA GNUANDLIG N. Uranium Recovery Licensing Branch 82/07/27. Uranium Recovery Licensing Branch 2pp. 14572 333
- DOCKET 40-8602 BILVER KING MINES, INC . CASPER, WY
- 8208250536 Comments on 820422 "Review of Preoperational Radiological Environ Monitoring Rept for Jul-Dec 1981 for Monton Ranch " Air particulate concentrations considered typicalof background values, PANTELL, B E Uranium Recovery Licensing Branch 82/08/11 Uranium Recovery Licensing Branch 1p 14572,336.
- DOCKET 40-8674 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- B20B040438 Advises of issuance of Amend 4 to License BUA-1326, revising License Condition 26 re reclamation & decommissioning plan described in 810625 submittal SCARANO, R.A. Uranium Recovery Licensing Branch 82/05/18 GUPTA, U.K. Plateau Resources, Ltd 2pp. 14220-188.

- 8207200515 Forwards radiological safety training manual GERDEMAN, F W Plateau Resources, Ltd 92/06/30 GNUGNOLI, G. Uranium Recovery Licensing Branch 2pp 13976 223
- ---8207200520 Radiological safety training manual * Plateau Resources, Ltd 82/03/31 52pp 13996 225
- DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC . DENVER, CO
- 8207140402 Requests Region 4 assistance re const insp.scheduled by License Condition 26(a), of White Hesa Cell 3 tailings impoundment & Cell 4 dike

 8CAPANO.R A Uranium Recovery Licensing Branch 82/06/22.

 COLLINS.J T Region 4. Office of Director 2pp 13858 006
- 8208300350 Ack receipt of 820521 ltr requesting amend to Bource Matl License SUA-1358 reducing thickness of tailings reclamation cover at White Hesa Hill AddI info required by 820830 MARTIND & Uranium Recovery Licensing Branch 82/08/12 BAKER.C E Energy Fuels Nuclear. Inc 2pp 14697 151
- DOCKET 40-8484 WESTERN NUCLEAR, INC , LAKEWOOD, CO
- 8208030011 Discusses prelicensing guidance re vendor proposed pumping test program for planned R&D in situ solution mining operation License application not yet received PORLE, J A Uranium Recovery Licensing Branch 82/07/08 Uranium Recovery Licensing Branch 4pp 14208 342.
- DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO . DENVER, CO
- 8208050031 Forwards addendum to "Reno Creek Pattern 2 Restoration Rept." NEUMANN: H R Rocky Mountain Energy Co 82/07/16 SCARAND, R. Uranium Recovery Licensing Brench 2pp 14243 130
- --8208050035 Addendum to "Reno Creek Pattern 2 Restoration Rept "
 4 Rocky Mountain Energy Co 82/07/16 18pp 14243 132.
- DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO , CLEVELAND, GH
- B208240022 Discusses aquifer restoration of A & 8 fields at Collins Draw Bits to achieve baseline groundwater quality Restoration is inadequate to meet min requirements of quality & use OGLE.K M Cleveland-Cliffs Iron Co B2/07/17 Claveland-Cliffs Iron Co 5pp. 14548.163
- 8208300005 Forwards quarterly rept for Apr-June 1982 WODEK.D J Cleveland-Cliffs Iron Co 82/07/21. SCARANO.R A Uranium Recovery Licensing Branch 1p 14695 049
- ---9208300007 Guarterly rept for Apr-June 1982. One oversize figure encl Aperture card is available in PDR 4 Cleveland-Cliffs Iron Co 82/07/21 25pp 14695 050
- DOCKET 40-8724 CHEMETRON CORP , CHICAGO, IL
- 8208130400 Application for amend to License 8UB-1357, extending expiration date to 830731 PHILLIPS, B J Allegheny International. 82/07/14 PAGE, R O Uranium Fuel Licensing Branch 19. 14350, 360
- 8208190037 Advises of issuance of Amend 6 to License 808-1357, extending expiration date to 830731 PAGE:R.O Uranium Fuel Licensing Branch 82/07/30 PHILLIPS.B.J Chemtron Corp ip 14507 027
- --8208190040 Bafety evaluation supporting Amend 5 to License 508-1357. KOSLA.B.M Uranium Fuel Licensing Branch. 82/07/30 ip. 14507.028
- DOCKET 40-8743 CONOCO, INC , DENVER, CO
- 8207140406 Forwards public. State agency & Federal agency comments on DEB me operation of Sand Rock Mill Project in Campbell County, MY. Written comment responses required by 820720 W/o encl FLEMING.T.E Uranium Recovery Licensing Branch. 82/07/02. NELSON, U.D. Colorado State Univ. 3pp. 13859-201

- 8208090029 Forwards addl geohydrology data in response to NRC 811103 ltr & 821014 meeting Five oversize figures encl. Aperture cards are available in PDR BULLEO, D W CONOCO, Inc (Continental Dil Co.) 82/07/13 FLEMMING, T NRC No Detailed Affiliation Civen 11pp 14301 124 14301 124
- --8208070031 "Specs for Bentomite Slurry Cutoff Trench Proposed for Evaporation Pond " One oversize figure encl Aperture card is available in PDR (Continental Cil Co) 82/07/13 32pp, 14301 137 CONOCO, Inc
- 8208110064 Forwards for signature, Mod 1 to Task Order 10 of NRC Contract NRC-02-81-039, requiring work re CONOCO Band Rock U Mill project
 HAJAN TF Technical Assistance Contracts Branch FIN 8-7301
 82/07/14 Williams-Robinette & Associates, Inc. 4pp. 14329
- 4pp 14329-348

DOCKET 40-8745 COLE PETROLEUK, INC , CABPER, WY

- 8208040607 Forwards "Ore-Sand Aquifer Test in Ogle Petroleum,Inc Bison Basin Mining Unit 2," per License Condition 61 LAHSON.B.A Ogle Petroleum, Inc 82/06/25 SCARANO.R A Uranium Recovery Licensing Branch 2pp 14220 001
- --B20B040614 "Ore-Band Aquifer Test in Ogle Petroleum, Inc Bison Basin Mining Unit 2." Two oversize maps encl Aperture cards are available in PDR. PLAYION.2 J. HOFFMAN.O.L. Hydro-Engineering 82/06/30 168pp
- 8208040392 Submits annual land use survey conducted on 820709.per License Condition 70 No changes in land use observed LAMSON.8 Ogle Petroleum, Inc. 82/07/15 SCARANO.R A Uranium Recovery Licensing Branch 2pp. 14224 311.
- 8208310514 Informs that rept on annual land use survey submitted 820715 complete & acceptable. BRYCK, G. J. Uranium Recovery Licensing Branch 82/08/19 Ur Recovery Licensing Branch. ip. 14697 274 Uranium
- DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP. . OKLAHOMA CITY, DK
- 8208040634 Forwards application for amend to License SUA-1387, changing wording of License Conditions 43,47,49 & 50 re well & pand mampling. BHELLEY.W J. Kerr-McGee Nuclear Corp 82/05/28 SCARANG.R A. Uranium Recovery Licensing Branch. 1p 14224 013.
- --8208040640 Application for amend to License BUA-1387, changing wording of License Conditions 43,47,49 & 50 re well & pond sampling # Kerr-McGee Nuclear Corp. 82/05/28 3pp. 14224 014

DOCKET 40-8781 TETON EXPLORATION DRILLING CO , INC , CASPER, WY

- 8208040443 Informs that NRC is issuing DES on environ considerations re Levenberger Project Notice transmitted to FR for publication ROSB, F W. Uranium Recovery Licensing Branch. 82/06 Teton Exploration Drilling Co , Inc. 1p 14220.197 82/06/30 APPEL, R
- 8208040318 Advises that EPA scheduled 620709 FR publication of notice of availability of EIS, "Operation of Taton Solution Mining Project License, Converse County, NY," (NAREO-0925) HILSON, K. Environmental Protection Apancy, 82/07/07, SCARANO, R, NRC No Detailed Affiliation Given 1p, 14223, 321
- 8208040429 Ack receipt of info re issuance of source & byproduct matl license for Teton Exploration Drilling Co in Converse County, MY. No comments provided. DAVIS, V.W. Agriculture, Dept. of 82/07/15. GCARAND, R.A. Uranium Recovery Licensing Branch ip. 14220, 172.
- 8208040349 Advises that Forest Byc has no substantive comments on Taton Exploration Drilling, Inc. Teton Project DEB, since project not on t does not affect Netl Forest Bys lands.
 8CHE68LER, T. E. Agriculture, Dept of, Forest Service. 82/07/19
 8CARANG, R. A. Uranium Recovery Licensing Branch 1p. 14223.334.
- 8208240482 Comments on DES re issuance of source & bygroduct math license for Teton Exploration Drilling, Inc. on 820722 Clearance for project recommended, BABTRON, A F. Hydeming, 85 ate of 82/08/06, Uranium Recovery Licensing Branch. [p 14544·162.

- DOCKET 40-8783 URANERI USA, INC., CASPER, WY
- 820B310521 Documents review of Uraner: Ruth In Bitu Leach Project third quarterly rept submitted 820707 Rept complete & acceptable BRYCK, C J Uranium Recovery Licensing Branch 82/08/19 Uranium Recovery Licensing Branch 2pp 14697 269
- DOCKET 40-8786 URANIUM RESOURCES, INC . RICHARDSON, TX
- 8208030123 Issues Amend 3 to License BUA-1400 modifying License Conditions 33 & 40 re requirement for submittal showing airborne monitoring locations BCARAND, R A Uranium Recovery Licensing Branch 82/06/16 PELIZZA, H S Uranium Resources, Inc. 2pp 14178 357
- --8208030124 Informs that Amend 3 has been issued to License 5UA-1400 modifying License Conditions 33 & 40 re requirement for submittal showing airborne monitoring locations (HETSROOK,K B. Uranium Recovery Licensing Branch 82/06/14 Uranium Recovery Licensing Branch. 2pp 14198 359
- 8208040359 Advises of issuance of Amend 4 to License SUA-1400, deleting Condition 22 which required mechanical integrity tests of injection wells & revising License Condition 39 SCARANO, R A Uranium Recovery Licensing Branch 82/07// PELIZZA, H B Uranium Resources, Inc 2pp 14221 358
- --8208040362 Bafsty evaluation supporting Amend 4 to License SUA-1400, deleting License Condition 22 & revising Condition 39 WESTBROOK, K. B., LINEMAN, J. J. Uranium Recovery Licensing Branch 82/07/22 2pp, 14221.360
- 8208110080 Discusses problems of inaccurate fluid balance data presented in licenses 820521 quarterly rept Plans for rectifying problems requested by 820820 LINEHAN, J. Uranium Recovery Licensing Branch 82/07/23 PELIZZA
- DOCKET 40-8791 CUSTOM MACHINE, INC . CLEVELAND, OH
- 8208100107 Forwards IE Insp Findings & Licensee Ack dtd 820729 of License SUB-1397 SLANINSKI,W J Region 3, Office of Director 82/08/05 HODOSON,@ Custom Machine. ip 14298:188
- --8208100113 IE Insp Findings & Licensee Ack dtd 820729 of License 8UB-1397 Insp findings no noncompliance noted 8LAHINSKI, W. J. Region 3, Office of Director 82/07/29 1p. 14298 189.

DOCKET 40-8793 CONOCO, INC , DENVER, CO

- 8208040542 Summary of B20505 meeting w/CONOCO in Bilver Spring, MD to discuss status of overdue requested submittals & results of review of aquifer pump test YDUNG, Y A , LINEHAN, J J Uranium Recovery Licensing Branch 02006404 LINEHAN, J.J. Uranium Recovery Licensing Branch Uranium Recovery Licensing Branch . 6pp. 14220 351
- 8208240467 Requests withdrawal of Ruby Ranch R&D In Situ U Leach Project license application Vendor in process of phasing out mineral operations & will not continue w/development of project HEOGLAND,R.W CONDCO, Inc. (Continental Dil Co.), 82/07/20 LINEHAN,J J Uranium Recovery Licensing Branch 1p 14544 173
- DOCKET 40-8794 MOLYCORP , INC , LOS ANGELES: CA
- 8208120241 Forwards results of test well sample analysis performed by EPA Eastern Environ Radiation Facility. Concentrations of Ra-228 & Th-232 do not appear to exceed NRC limits Results to be further reviewed during upcoming insp JOYNER, J. H. Division of Engineering & Technical Programs, 82/08/09 SINGER, B. Procedures & Certification Branch, 6pp 14326-271 P2/08/09
- DOCKET 40-8801 RADIATION MANAGEMENT CORP , NORTHBROOK, IL
- 8208230016 Requests formal notification if Commission intends to take further action on findings of radiological survey at West Lake Landfill, CORCORAN, M.J. Bridgeton, MO. 82/06/21 CROW, W.T. Uranium Recovery Licensing Branch. 1p. 14518:003.

DOCKETED ITEMS

DOCKET 40-8823 EM CHEMICALS, HAWTHRONE, NY

- 8208130347 Forwards application for source matl license & license fee FIEMAN, B D EM Chemicals 82/07/12 Office of Nuclear Material Safety & Safeguards, Director ip 14340 251
- --8208130351 Application for license to import, store & ship 50 kg thorium fluoride, sealed in 100 g & 500 g metal containers FEIMAN, B D EM Chemicals 82/07/12 lp 14340 252

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

- F Security, medical, emergency & fire protection plans
- 8208310057 Releases public version of licensee response to NRC request for info re reactor emergency plan FELTON, J M Division of Rules and Records 82/08/11 Document Management Branch. ip. 14697, 244 24X Fiche 50-002, 82/08/11, 8208310057
- --B20B31005B Submits public version of licensed response to NRG request for info re reactor emergency plan Plan dtd 801124 mests review guidelines of NUREO-0849.

 BURNAR R Michigan: Univ of 82/07/29 BATEB, EF Division of Emergency Preparedness. 1p 14697 245 24X Fiche 50-002. 82/08/11,820B310057.
- Q Inspection reports. IE Bulletins & correspondence
- B20A2i0395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Davices for External Radiation " Svc list encl JURDANA, E.L. Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ of 112pp 14357.354, 24X Fiche, 50-000, 82/07/19, 8204210395
- DOCKET 50-3 INDIAN POINT STATION, UNIT 1
- F Becurity, medical, amergency & fire protection plans
- 8208030686 Releases public version of revised emergency plan implementing procedures. FELTON.J M Division of Rules and Records. 82/07/20 Document Management Branch ip 14301 074 24X Fiche 50-003,82/07/20, 8208030686
- --B208030730 Public version of Emergency Plan Implementing Procedures IP-1023, "Operational Support Ctr" & IP-1024, "Monthly Check of Indian Point Emergency Radios, Telephones & Outdoor Evacuation Alarm" FINCH, Q L. Consolidated Edison Co of New York, 82/06/18, 23pp 14301 078, 24X Fiche: 50-003, 82/07/20, 8208030486
- B20B020073 Advises that amended Page 3-14 from physical security plans per 820121 ltr, is withdrawn Approved page in effect on 820526 remains in effects in response to NRC 820518 ltr 0'TOOLE, J. D Consolidated Edison Co. of New York 82/07/27. VAROA: S A. Operating Reactors Branch I. is 14144.112 24X Fiche: 50-003, 82/07/27, 8208020073
- 8208270584 Releases public version of ravised emergency plan implementing procedures FELTON, J M. Division of Rules and Records. 82/08/12, Document Management Branch. 1p. 14683:227 24X Fiche 50-003,82/08/12, 82/08/20384
- ---9208270590 Forwards public version of revised emergency plan implementing procedures including Procedures IP-1016 recobtaining meteorological data & IP-1037 re obtaining offsite Ruster-Btokes monitor data.

 D'TOOLE, J D., LIEBLER, P H Consolidated Edison Co of New York. 82/07/01. Defice of Nuclear Reactor Regulation. Director. 1 14683:228. 24X Fichs: 50-003, 82/08/12, 8208270584.

- --8208270593 Public version of revised emergency plan implementing procedures, including Procedures IP-1016 re obtaining meteorological data & IP-1037 re obtaining offsite Rueter-Stokes monitor data * Consolidated Edison Co. of New York 82/07/01 51pp 14683 229 24X Fiche 50-003,82/08/12.8208270584
- H Ceneral correspondence
- B20B020270 Ack raceipt of NRC ltr in response to Westchester County, NY request for 120-day regulatory clock against facilities County appreciates NRC efforts to meet concerns by requesting interim findings from FEMA DELBELLO, A B Westchester County, NY. B2/07/13 PALLADINO, N. Commissioners 1p 14151 301 24X Fiche 50-003, 82/07/13, 820B020270
- I Financial information
- 8208030217 Forwards projection of util ability to pay \$20 million retrospective premium adjustment for Aug 1982-Jul 1983 O'TOOLE, J D Consolidated Edison Co of New York 82/07/29 BALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance), 2pp 14159 338 24X Fiche 50-003.82/07/29,8208030217
- P. Operating license stage documents & correspondence
- 8207080044 Generic 1tr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl.

 DIRCKS, M J Office of the Executive Director for Operations 82/07/02. Consolidated Edison Co of New York. 93pp 14194 001 24X Fiche: 50-000, 82/07/02, 8207080064
- B20Bii0050 Requests info re NY City water supply sys to aid R Codell testimony for hearing on risk re water contamination by release of radioactivity in event of severe accident, per 820709 discussion HANAUER, B, H Division of Bafety Technology 82/07/22 CONHAY, J New York, State of App 14330 218 RAX Fiche 50-003, 82/07/22, R20Bii0050.
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl.
 EISENNUT, D Q, Division of Licensing 82/09/09 Consolidated Edison Co of New York. 1p. 14396-332 24X Fiche 50-000,82/09/09,8208090194
- G Inspection reports, IE Bullstins & correspondence
- B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MBIV) Leakage." Svc list encl.

 JORDANS L. Division of Engineering & Quality Assurance B2/07/16

 Consolidated Edison Co. of New York B7pp 14356:274 24X

 Fiche.50-000.82/07/16.8204210393
- 8204210395 IE Info Notice 81-26,Part 3,8uppl 1, "Clarification of Placement of Personnial Monitoring Davices for External Radiation" 8vc list encl.

 JURDAN,E L. Division of Engineering & Quality Assurance 82/07/19

 Hichigan, Univ of. 112pp 14357-354 24X Fiche 86-000.82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure." Byc list encl.
 JORDAN,E L. Division of Engineering & Quality Assurance 82/07/20
 Consolidated Edison Co. of New York. 112pp 14380.252 24X
 Fiche: 50-000, 82/07/20, 8204210396.
- 8204210397 IE Info Notice 82-24, "Hater Leaking From U Hexafluoride Overpacks," Svc list encl. COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co of New York. 71pp. 14357.276, 24X Fiche 50-000,92/07/20,8204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures," Svc list encl.

 URDAN,E L. Division of Engineering & Quality Assurance. B2/07/22, Consolidated Edison Co. of New York. 112pp. 14194:321 24X Fiche-50-000,82/07/22,8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list and. URDANIE, L. Division of Engineering & Quality Assurance, 82/07/23, Consolidated Edison Co of New York, 122pg. 14380:115 24X Fiche 50-000, 82/07/23, 8204210401.

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (GRD) Quide Tube Support Pin Failures at Wastinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fithe 50-000.82/07/23.8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sheeves in RCS Piping at Certain Hestinghouse PWR Power Plants " Svc list encl JORDANSE L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl URPAN.E L Division of Engineering & Quality Assurence 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Ficha 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list and URDAN,E L Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- A Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing seld info Forwards documents listed in App A FELTON.J.H Division of Rules and Records. 82/07/13 UDELL,R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000.82/07/13.8208270010
- --B208270012 Forwards "Number of Personnel & Man Rem By Hork & Job Function for CYBI," per 10CFR20 407 D'TOOLE, J D Consolidated Edison Co. of New York B2/03/01 HAYNEG, R C Region I, Office of Director ip 14679 361, 243 Fiche 50-000,82/07/13,8208270010
- --8208270016 "Number of Personnel & Man Rem By Work & Job Function for CYB1" * Consolidated Edison Co of New York 82/03/01 1p 14679 362. 24% Fiche 50-000-82/07/13,8208270010
- --8208270098 "Annual Hhole Body Dose At Licensed Nuclear Power Facilities for CY81" • NRC - No Detailed Affiliation Given. 62/07/13 48pp 14479 216 24X Fiche 50-000.82/07/13.8206270010
- --B208270632 Forwards "Personnel Whole Body Exposures For CYBI," per 10CFR20 407 BRONS.J C. Power Authority of the State of New York 82/02/26 Office of Hamagement and Program Analysis ip 14679 345 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270637 "Personnel Whole Body Exposures for CY81 "
 * Consolidated Edison Co of New York 82/02/26 1p, 14679 346 24X Fiche, 50-000, 82/07/13, 8208270010
- DOCKET 50-5 PENNSYLVANIA STATE UNIV. RESEARCH REACTOR
 P. Operating license stage documents & correspondence
- 8208190112 Notifies of 820820 meeting to discuss subcritical experiments w/new core fuel elements containing U oxide pellets enriched to 7% U-235 LEVINE.8, H. Pennsylvania Btata Univ 82/08/12 BERNARD, H Standardization & Special Projects Branch ip 14383 145 24% Fiche 50-000, 82/08/12, 8208190112
- @ Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26.Part 3. Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for Esternal Radiation " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ. of 112pp. 14358.001. 24X Fichs 50-000,82/07/19,8204210395.
- DOCKET 50-10 DREBDEN NUCLEAR POWER STATION, UNIT 1
- F. Becurity, medical, emergency & fire protection plans
- 8208040353 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records. 82/07/13 Document Management Branch ip 14223:161 24X Fiche. 50-010,82/07/13, 8208040353

- ---B208040358 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-08. "Rad/Chem Director" Receipt form, procedure history & safety evaluation encl BCOTT, D J Commonwealth Edison Co B2/07/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 14223 162 24X Fiche 50-010, B2/07/19, 8208040353
- --8208040361 Public version of Revision 2 to Emergency flan Implementing Procedure EPIF 100-CB, "Rad/Chem Director " Revised index of station group director duties end;
 * Commonwealth Edison Co 82/06/30 5pp 14223 165 24X Fiche 50-010,82/07/13,8208040353
- B208040473 Releases public version of revised emergency plan implementing procedures
 FELTON.J M Division of Rules and Records 82/07/22 Document Management Branch ip 14220 294 24% Fiche 50-010,82/07/22, B208040473
- --8208040479 Forwards public version of Ravision 2 to Emergency Plan Implementing Procedure EPIP 100-C7, "Security Director" & Revision 0 to EPIP 500-7, "Operational Check of Notification Phone List "Receipt form encl SCOTT.D J Commonwealth Edison Co 82/07/10 DENTON, HR Office of Nuclear Reactor Regulation, Director Spp 14220 295 24X Fiche 50-010,82/07/22,8208040473
- --B208040483 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7, "Security Director" & Revision 0 to EPIP 500-9, "Operational Check of Notification Phone List "

 * Commonwealth Edison Co 62/07/07 App. 14220 300 24X
 Fiche 50-010,82/07/22,8208040473
- 8208270134 Forwards 1E lnsp Repts 50-010/82-11,50-237/82-15 & 30-249/82-16 on 820624,29,30 & 0709 & notice of significant test deficiency HIND.J A Division of Emergency Preparedness & Operational Support 82/08/03 REED.C Commonwealth Edison Co 3pp 14563 338 24% Fiche,50-010,82/08/03,8208270134
- --B208270142 IE Insp Repts 50-010/B2-11, 50-237/B2-15 & 50-249/B2-14 on B20624, 27, 30 & 0707 Significant test deficiency noted failure of seven prompt public notification sys sirens JANUSKA, A 0 , EMITH, M J , PATTERBON, J P Division of Emergency Preparedness & Operational Support 62/07/23 12pp 14563 341 24X Fiche 50-010, 82/08/03, 8208270134
- 8208250559 Releases gublic version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
 FELTON.J M Division of Rules and Records 82/08/12. Document Management Branch 1p 14559 354 24X Fiche 50-000,82/08/12,8208250559
- --8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 HOORE.R D Commonwealth Edison Co 82/07/19 DENTON, H R NRC No Detailed Affiliation Given in 14959 355 24X
 Fiche 50-000,82/08/12.8208230559
- --8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures "

 4 Commonwealth Edison Co 82/06/30. 7pp 14559 356 24X Fiche 50-000,82/08/12.8208250559
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP rs Commission approved charter for GROR 8vc list encl.
 DIRCKS, H J Gffice of the Executive Director for Operations 82/07/02 Consolidated Edison Co. of New York. 93pp 14194 001 24X Fiche 50-000,82/07/02.8207080064
- 8208030254 Comments on SEP in response to 820714 request Few deviations identified between design criteria used for Phase I/II plants vs current criteria.

 DELGEORGE, L. O. Commonwealth Edison Co. 82/07/29 GRUTCHFIELD, D. Operating Reactors Branch 5 Spp. 14158 227 24X Fiche 50-010, 82/07/29, 8208030254
- 8208110188 Forwards revised pages to CE-1-A, "Com Ed QA Program for Nuclear Cemerating Stations," Revision 21, Revised pages correct typographical & other minor errors.

 SMARTZ,E D Commonwealth Edison Co 82/08/06 HAABS,W P. Quality Assurance Branch. 1p 14314 079 24X Fiche 50-000,82/08/06,82/08/06.

- --B208110204 Revised pages to CE-1-A.Revision 21. "Comm Ed GA Program for Nuclear Generating Stations" + Commonwealth Edison Co 82/06/06 11pp 14314 080 24X Fichs 50-000,82/08/06.8208110188
- 820B090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes lOCFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT.D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24% Fiche 50-000,82/08/09,8208090194
- 6 Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN.E L. Division of Engineering & Guality Assurance
 Consolidated Edison Co of New York 87pp 14356 274
 Fichs 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/19 Hichigan Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19.
- 8208050373 Forwards IE Insp Repts 50-010/82-06.50-237/82-10 & 50-249/82-11 on 820507-0604 & notice of violation SPEESARD,R L. Division of Project & Resident Programs 82/07/15 REED.C Commonwealth Edison Co. 2pp 14207 191 24X Fiche 50-010,82/07/19.8208050393
- --B208050398 Notice of violation from insp on 820507-0604 * Division of Project & Resident Programs 82/07/19 2pp 14209 193 24% Fiche 50-010,82/07/19,8208050393
- --B20B050403 IE Insp Repts 50-010/B2-04,50-237/82-10 & 50-249/B2-11 on B20507-0604 Noncompliance noted failure to follow hose color tode
 TONOUE, T M , JORDAN, M J , MALKER, R D Division of Project & Resident Programs 82/07/11 9pp 14209 195 24X
 Fiche 50-010, 82/07/19, 8208050393
- 8204210376 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 62/07/20 Consolidated Edison Co of New York 112pp 14380.252 24% Fiche 50-000,82/07/20,8204210376
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L ! Division of Fuel Facilities, Materials & Safeguards, 82/07/20 Cansolidated Edison Co. of New York, 7ipp 14357 272 24X Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Bvc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/22 Cansolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Gvc list encl JORDAN,E L pivision of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380.113 24X Fiche.30-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Mestinghouse PWRs " Svc list encl WRDANLE L. Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co of New York, 127pp 14194,120 24X Fiche.50-000,82/07/23,8204210402
- 8208100289 Forwards IE Insp Repts 50-010/82-09, 50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25 No noncompliance noted. MILLER, J R. Division of Engineering & Technical Programs REED, C Commonwealth Edison Co 2pp. 14294-191 24X Fichs: 50-010, 82/07/23, 8208100289
- --0208100299 IE Insp Repts 50-010/82-09,50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25. No noncompliance noted Major areas inspected action on previous findings open items & hydrogen gas addition into reactor feedwater sys PAUL/R. A., OREOER, L. R. Division of Engineering & Technical Programs 82/07/22 7pp 14294:193. 24X Fiche 50-010,82/07/23, 8206190289.

- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list enci JORDAN,E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipg 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Dverexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/28, Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208270134 Forwards IE Insp Repts 50-010/82-11,50-237/82-15 & 50-249/82-16 on 820624,29,30 & 0709 & notice of significant test deficiency HIND, J A Division of Emergency Preparedness & Operational Support 82/08/03 REED, C Commonwealth Edison Co 3pp 14563 338 24X Fiche 50-010,62/08/03,8208270134
- --B208270142 IE Insp Repts 50-010/B2-11,50-237/B2-15 & 50-249/B2-16 on B20624.27,30 & 0707 Significant test deficiency noted failure of seven prompt public notification sys sirens JANUSKA,A G , GRANT,W B , NICHOLSDN.N A Division of Emergency Preparadness & Operational Support 82/07/23 12pp 14563 341 24X Fiche 50-010,82/08/03,8208270134
- 8204210407 IE Info Notice 82-27, "Fuel Ros Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8208200241 Advises of error in NRC 820719 ltr transmitting IE Insp Repts 50-010/82-04.50-237/82-10 & 50-249/82-11 Page 2 should be replaced w/encl page 8PESSARD.R L Division of Project & Resident Programs. 82/08/13 REED. C Commonwealth Edison Co 2pp 14399 031 24X Fiche 50-010, 82/08/13, 8208200241
- 8208310218 Forwards suppl to util 820526 response to IE Bulietin 81~03, "Flow Blockage of Cooling Water to Safety Sys Components by Combicule Sp (Asiatic Clam) & Hytilus Sp (Hussel) "
 SWARTZ,E D. Commonwealth Edison Co 82/08/23 KEPPLER.J O Region 3, Office of Director 7pp 14693 130 24X Fiche 50~010.82/08/23, 8208310218
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A. Critical Mass Energy Project 8pp 14679 208 24% Fiche 50-000, 82/07/13.8208270010
- ---8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CV61" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14677 216 24% Fiche 50-000, 82/07/13, 8208270010
- --B208270559 Forwards "Recorded Annual Whole Body External Exposure for CYB1," per 10CFR20 407(6) W/o Guad Cities, Zion LeSalie, Byron & Braidwood repts RAUSCH, T. J. Commonwealth Edison Co. B2/03/31 Office of Management and Program Analysis ip 146E0 075 24% Fiche 50-000, B2/07/13, B208270010
- --B208270567 "Recorded Annual Whole Dody External Esposure for CYB1 "
 * Commonwealth Edison Co B2/03/31 1p 14680 076 24X
 Fiche. 50-000, 82/07/13: 8208270010
- 8208170242 Forwards monthly operating repts for Jul 1782 SCOTT, D J Commonwealth Edison Co 82/08/01 Director's Office, Office of Inspection and Enforcement. ip 14369 228 24X Fiche 50-010, 82/08/01, 8208170242
- --8208170245 Monthly operating repts for Jul 1982 8CHROEDER, B. A. Commonwealth Edison Co. 82/08/01, 18pp 14369 229. 24X Fiche 50-D10, 82/08/01,8208170242
- packet 50-13 BAHCOCK & WILCOX CQ. CRITICAL FACILITY

 @ Inspection reports, IE Bulletine & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Syc list encl JORDAN, EL Division of Engineering & Quality Assurance. B2/07/19 Hichigan, Univ of 112pp. 1435B.001 24X Fichs. 50-000. 82/07/19, 8204210395

- DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1
- R Periodic operating reports & related correspondence
- 8208240143 Forwards annual rept for decommissioned License DPR-9 for yr ending 820630 ORIFFING E.P Detroit Edison Co. 82/07/29 STOLZ, J Operating Reactors Branch 4 ip 14519 338 24X Fiche 50-016/82/07/29, exceptions
- --B208240147 Annual rept for decommissioned License DPR-9 for yr ending B20630 HARRIBON, W Q . GRIFFING.E P , ALEXANDERBON, E Detroit Edison Co EF-128 82/08/09 10pp 14519 339 24X Fiche 50-016, B2/07/29, B208240143
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR
 F. Sacurity, medical, emergency & fire protection plans
- 8208230039 Forwards IE Insp Rept 50-020/82-01 on 820614-15.No noncompliance noted BTAROSTECKI.R Division of Project & Resident Programs 82/08/06 CLARK.L Meseachusetts Institute of Technology 2pp 14517 242 24X Fiche 50-020
- --8208230041 IE Insp Rept 50-020/82-01 on 820414-15 No noncompliance noted Major areas inspected licensee action on previous insp findings; facility operation, organization, audits % HIT reactor safeguards committee activities KINNEY, W. W., ROTH, J. OREENMAN, E. O. Division of Project & Resident Programs 82/08/05 7pp 14517-244 24X Fiche 50-020,82/08/06,8208230039
- 8208250127 Requests 30-day extension for implementation of Amends 19 & 21 to License R-37.per NRC 820611 ltr Amend 19 identifies physical security plan & Amend 21 authorizes change in storage of fresh fuel.

 CLARK-L. Hassachusetts Institute of Technology. 82/08/20 HILLER, JR Standerdization & Special Projects Branch 1p 14540.273 24X Ficha.50-020.82/08/20.8208250127.
- P Operating license stage documents & correspondence
- 8208230127 Requests 30~day extension for implementation of Amends 17 k 21 to License R-37.per NRC 820611 ltr Amend 19 identifies physical security plan & Amend 21 authorizes change in storage of fresh fuel CLARK.L Massachusetts Institute of Technology, 82/08/20. HILLER, JR Standardization & Special Projects Branch. ip 14540 273 24% Fiche 50-020.82/08/20.8208250127
- @ Inspection reports. IE Bullatins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Buppl i, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " 8vc list encl JORDAN, E L Division of Engineering & Guality Assurance 82/07/19 Hichigan, Univ of 112pp, 14358 001, 24X Fiche, 50-000, 82/07/19, 8204210395
- 8208230039 Forwards IE Imag Rept 50-020/82-01 on 820614-15 No noncompliance noted.
 BTAROSTECKI,R. Division of Project & Resident Programs 82/08/06 CLARK,L. Massachusetts Institute of Technology. 2pp. 14517;242 24X Fiche: 50-020,82/08/06,8208230039.
- --B20B230041 IE Insp Rept 50-020/B2-01 on B20614-15. No honcompliance noted Major areas inspected, licensee action on previous insp findings, facility operation organization, audits & MIT reactor sefeguards committee activities KINNEY.M W , ROTH.J., GREENMAN.E Ø Division of Project & Resident Programs. B2/08/05. 7pp. 14517:244 24X Fiche: 50-020, 82/08/06, B208230039.
- 8. Reportable occurrences, LERs & related correspondence
- 9208260293 RO: an B20809, slight increase found in levels of Plassian products in reactor primary sys Cause under investigation Criterion for operation wigosaible faulty core element par RB 50-20/79-4 will be observed.

 CLARK, L. Massachusetts Institute of Tachnology 82/08/17, MAYNES, R C. Region 1. Office of Director Spp. 14554-283 24X Fiche: 50-020, 82/08/17, 8208260293.

- DOCKET 50-27 HASHINGTON STATE UNIV RESEARCH REACTOR

 F Security, medical, emergency & fire protection plans
- 8208030143 Forwards IE Safeguards Insp Rept 50-027/82-01 on 820719-20 No noncompliance noted NORDERHAUG.L Division of Radiological Bafety & Bafeguards Program 82/07/28 HILGON.W E Washington Univ 4pp 14160 013 24X Fichs 50-027,82/07/28,8208030143
- --B20803015i IE Bafeguards Insp Rept 50-027/82-01 on 820717-20 No noncompliance noted Major areas inspected security plan, SNM protection, security organization & access controls Details withheld (ref 10CFR2 790) MCGUEEN, A D , SCHWAN, C A , 8CHWSTER, M D Division of Radiological Safety & 8afeguards Program 82/07/28 1p 14160 017 24X Fiche 50-027, 82/07/28 8208030143
- P Operating license stage documents & correspondence
- 8208260379 Forwards Amend 10 to License R-76, BER (NUREG-0911), EIA & notice of issuance & availability Amend renews OL for 20 yes, adds Tech Spec limit on max reactivity & incorporates new requirements on pool water quality BERNARD, H Standardization & Special Projects Branch 82/08/11 NILEON, W E Washington State Univ 2pp 14571 331 24X Fiche 50-027, 82/08/11, 8208260399
- --8208260404 Amend 10 to License R-76, renswing OL for 20 yrs, adding Tech Spec limit on max reactivity & incorporating new requirements on pool water quality BERNARD, H Standardiration & Special Projects Branch 82/08/ii 45pp 1457: 333 24% Fiche 50-027,82/08/ii.8208260399
- --8208260407 EIA supporting Amend 10 to License R-76 # NRC - No Detailed Affiliation Given 92/08/11 2pp 14572 016 24X Fiche 50-027,82/08/11,8208260399
- --8208260412 Notice of issuance & availability of Amend 10 to License R-76 BERNARD, H Standardization & Special Projects Branch, 82/08/11 2pp 14572 022 24% Fithe 50-027,82/08/11,8208260399
- Q Inspection reports, IE Bulletins & correspondence
- B20B030143 Forwards 1£ Safeguards Insp Rept 50-027/82-01 on 820719-20. No noncompliance noted NORDERHAUGI, Division of Radiological Safety & Safeguards Program 82/07/28 WILBON, W.E. Washington Univ 4pp 14160 013 24X Fichs 50-027, 82/07/28, 8208030143
- ---B20B030151 IE Bafaguards Insp Rept 50-027/82-01 on 820719-20 No noncompliance noted Major areas inspected security plan. SNM protection. security organization & access controls Details withheld (ref 10CFR2 790) MGUEEN, A D , SCHUSTER, M. D. Division of Radiological Bafety & Bafeguards Program 82/07/28 ip. 14160 017 24X Fiche 50-027,82/07/28 8208030143
- DOCKET 90-29 YANKEE-ROWE NUCLEAR POWER STATION

 F Becurity, medical, emergency & fire protection plans
- 8208040298 Releases public version of revised emergency plan implementing procedures FELTON.J.M. Division of Rules and Records 82/07/20 Document Management Branch ip 14231.060 24X Fiche 50-029,82/07/20.8208040298.
- ~-#208040304 Forwards public version of revised emergency plan implementing procedures, including Procedures OP-3301 re unusual event, UP-3302 re aiert & UP-3303 re aite area emergency Receipt form encl.

 MARKI, D. Yankee Atomic Electric Co. 82/07/13 Office of Nuclear Reactor Regulation, Director 1p 14231-061, 24X Fiche 30-029, 82/07/20, 8208040298
- --8208040309 Public version of revised emergency plan implementing procedures including Procedures OP-3301 re unusual event. OP-3302 re alent & GP-3703 re site area emergency Revised table of contents encl # Yankse Atomic Electric Co 82/07/09 50pp 14231 062 24X Fiche 50-029,82/07/20:8208040298

- 820Bi10119 Forwards exemption from requirement of 10CFR50 48 & App R re installation of fixed fire suppression sys in control room in response to util 820513 ltr CRUTCHFIELD.D Operating Reactors Branch 5 82/08/05 KAY. J A Yankee Atomic Electric Co 2pp 14314 317 24X Fiche 30-029, 82/08/05, 8208110119
- --8208110122 Exemption from requirement of 10CFR30 48 & App R reinstallation of fixed fire suppression sys in control room EIBENIUT.D 0 Division of Licensing 82/08/05 Yankee Atomic Electric Co 4pp 14314 321 24X Fiche 50-029,82/08/05,8208110119
- 8208310037 Releases public version of revised emergency plan implementing procedures table of contents FELTON. J M Division of Rules and Records 82/08/11 Document Hanagement Branch 1p 14697 202, 24X Fiche 50-029,82/08/11,8208310037
- --B20B310033 Forwards public version of Revision 12 to emergency plan implementing procedures table of contents Receipt form encl MARKT, D Yankes Atomic Electric Co 82/07/30 Office of Nuclear Reactor Regulation, Director 2pp 14697 203 24X Fiche 50-029,82/08/11.8208310039
- --B208310059 Public version of Revision 12 to emergency plan implementing procedures table of contents

 4 Yankes Atomic Electric Co B2/07/28 ip 14697 205 24X
 Fichs 30-029, B2/08/11, B208310039
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR 8vc list encl.

 DIRCKB.W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 OOI R4X Fiche 50-000, 82/07/02, 8207080064
- 8208020185 Forwards response to 820617 & 25 requests for add1 info re degraded grid voltage, Marked-up preliminary Tech Specs encl KAY, J A Yankee Atomic Electric Co 82/07/09 CRUTCHFIELD, D Operating Reactors Branch 5 Spp 14141 025 24X Fichs: 50-029, 82/07/09, 8208020185
- 820B040534 Notification of 820727-27 meetings w/util in Rowe & Framingham MA to perform onsite insp of soil conditions & to review licensee documentation on SEP Topics II-4 D, II-4 E & II-4 F CARUSOR Operating Reactors Branch 5 82/07/21 CRUTCHFIELD, D Operating Reactors Branch 5. 3pp. 14221 205 24X Fiche 50-029, 82/07/21, 8208040534
- 8208060184 Responds to NRC 820512 request for add1 info re spent fuel pool mods Personnel exposure dose rates, analysis methods & spent fuel pool surveillance results discussed KAY, J A Yankse Atomic Electric Co 82/07/28 CRUTCHFIELD, D Operating Reactors Branch 5, 3pp 14239 101 24X Fiche 30-029, 82/07/28, 8208060184
- 8208030165 Forwards Franklin Research Ctr request for addl info needed to complete review of util submittal on TMI Item II K 3 17 re rept on outages of ECGS CRUTCHFISLD, D Operating Reactors Branch 5, 82/07/27 KAY, J A Yankee Atomic Electric Co. 2pp. 14160 107 24X Fiche 50-027,82/07/29,8208030165
- --B208030169 "ECCS Repts (F-47) TMI Action Plan Requirements," request for addi info. VOSBURY:F Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-C5504-303 B2/06/22 CHUN,E NRC - No Detailed Affiliation Given 5pp 14160, iii 24X Fiche 50-029,82/07/29,8208030165
- 8208030193 Forwards Franklin Research Ctr environ qualification review of Fisher & Porter Model 13B-2495-JBN8 level transmitters Justification for adequacy of transmitters for interim or short-term operation requested within 30 days.
 CRUTCHFIELD.D Operating Resectors Branch 5. NRC-03-79-118.
 82/07/29. KAYJ A Yankse Atomic Electric Co 26pp 14160:126
 24X Fiche 50-029,82/07/29.8208030193.
- 8208050533 Forwards latest revision to proposed radiological ET9.per 820413-14 meeting w/NRC. Revision reflects requirements necessary to meet intent of std radiological ET8 for operating reactors KAY. J. A. Yankee Atomic Electric Co. 82/07/30. PANDEY.8 Franklin Institute/Franklin Research Center. 2pp 14213-321. 24X Fiche 50-027, 82/07/30. 8208050533.

- --8208050537 Preliminary radiological ETS re channel function test requirement on liquid & gaseous effluent monitors & deletion of channel calibr & functional test requirements for PVS flow rate measuring device * Yankee Atomic Electric Co 82/07/31 95pp 14213,323 24x Fiche 50-029,82/07/30,8208050533
- 9208170229 Forwards add1 info re TMI Item II D 1, "Bafety & Relief Valves " KAY, J A Yankse Atomic Electric Co 82/08/01 CRUTCHFIELD, D Operating Reactors Branch 5 24pp 14369 004 24X Fiche 50-029, 82/08/01.8208170229
- B20B260310 Forwards criteria contained in NUREG-0737 w/guidelines developed by NRC to assess acceptability of licensee mod & procedures for TMI Item II B 3. "Post-Accident Bampling " Schedule for response requested within 20 days CRUTCHFIELD.D Operating Reactors Branch 5 82/08/04 KAY, J A Yankee Atomic Electric Co 10pp 14576 121 24X Fiche 30-027,82/08/04,8208260310
- B20B090206 Bubmits response to NRC 820714 ltr re SEP Phase II Urges NRC to avoid prematurely launching another BEP phase before value of Phase II has been determined EDMARDS.D W Yankse Atomic Electric Co 82/08/05 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 14272 069 24x Fiche 50-029, 82/08/05.8208070206
- 8208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC, Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Stor list encl EISENHUT, D 0 Division of Licensing B2/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208250516 Informs that 820727 application, proposing Tech Spec changes to eliminate need for SER issuance & to reduce review for routine core refueling changes, requires Class III fee in lieu of Class II fee submitted. Adul fee requested DIGOS.R M. License Fee Management Branch 82/08/11 KAY, J A Yankee Atomic Electric Co 1p 14962 243 24X Fiche: 50-029, 82/08/11, 8208250516
- B208260336 Notification of B2090B-07 meetings w/util in Bethesda.MD to initiate integrated assessment of facility B0YLE.M L Bystematic Evaluation Program Branch B2/08/12 RUSSELL.M T Bystematic Evaluation Program Branch 2pp 14575-218 24X Fiche 50-027.82/08/12.6208260356
- 8208170332 Forwards final safety evaluation of SEP Topic VIII-4 re electrical penetrations of reactor containment. Changes in protection for medium & low voltage electrical penetrations, plant Tech Byecs & operating procedures recommended CARUSO.R Operating Reactors Branch 5 82/08/13 KAY, J A Yankee Atomic Electric Co 4pp. 14367 004 24X Fiche 50-029,82/08/13, 8208170332
- 8208190179 Forwards safety evaluation of TMI Action Plan Item II E 1.2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication." & technical evaluation rept Yech Specs should be revised to include monthly testing of pumps GRUYCHFIELD.D. Operating Reactors Branch 5 82/08/16 KAY, J. A Yankee Atomic Electric Co 5pp. 14500 177 24X Fiche 50-029, 82/08/16, 8208190199.
- --8206220204 "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication," technical swaluation rept KACUCHER, J.E. F. FERTNER, K. Franklin Institute/Franklin Research Center, NRC-03-79-118. TER-C5257-289, 82/06/18 KENDALL,R NRC-No Detailed Affiliation Olven 12pp 14500,182 24X Fiche, 80-029,82/08/16,8208190199
- 8208200017 Clarifies position concerning misunderstanding re 820712 request for info on status of unresolved safety issues at facility CRUTCHFIELD, D Operating Reactors Branch 5. 82/08/17. KAY, J A Yankes Atomic Electric Co 3pp 14392 197. 24X Fiche 50-029, 82/08/17, 8208200017
- B20B27068: Forwards licenses responses to questions re TMI Action Plan
 ** Items II F i. 4:II F i 5 & II F i 6 re containment monitors
 **CARUBOR Operating Reactors Branch 5 B270B/19 Operating
 **Reactors Branch 5 6pp. 14683 179 24X Fiche 50-029.82/08/19,
 **B20B2706B1.
- 8208240R92 Forwards evaluation of BEP Topic III-5 A, "Effects of Pipe Braak on Btructures, Bys & Components Inside Containment." Criteria acceptable CARUSO.R. Operating Reactors Branch 5 82/08/20 KAY, J A Yankee Atomic Electric Co. 12pp 14328-097 24X Fichs. 50-029, 82/08/20, 8208240892

- 8208240304 Confirms 820813 telcon re SEP Topics VI-2 D. "Mass & Energy Release for Possible Pipe Break Inside Containment" & VI-3. "Containment Pressure & Heat Removal Capability "Temp profiles & pressure acceptable CARUBG.R Departing Reactors Branch 5 82/08/20 KAY, J A Yankee Atomic Electric Co 2pp 14528 076 24X Fiche 50-029,82/08/20,8208240304
- G Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Bleam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24% Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list and JORDAN, E. L. Division of Engineering & Ouality Assurance 82/07/19, Michigan, Univ. of 112pp 14358 001 24X Fiche 30-000, 82/07/19, 8204210395
- 8204210396 IE info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl. JORDAN, E. Division of Engineering & duality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche.50-000, 82/07/20, 8204210396
- 8204210397 tE info Notice 82-24. "Water Leating From U Hexafluoride Overpacks " Evc list enci COBB.L.! Division of Fuel Facilities, Materials & Safeguards 82/07/20. Consolidated Edison Co of New York 7ipp 14357 276 24X Fi
- 8208040534 Notification of 820727-27 meetings w/util in Rowe & Framingham, MA to perform onsite insp of soil conditions & to review licenses documentation on SEP Topics II-4 D, II-4 E & II-4 F.

 CARUSO.R. Operating Reactors Branch 5 82/07/21 CRUTCHFIELD, D, Operating Reactors Branch 5 3pp 14221.203, 24X Fiche 50-029,82/07/21.8208040534
- 6204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Syc list enc! JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 1129p 14194.321, 24X Fiche: 50-000, 62/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Dreined & Open RCB " Svc list and JORDAN,E.L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380.115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29. "Control Rud Drive (CRD) Guide Tube Bupport Pin Failures at Hestinghouse PMRs " Svc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PWR Power Plants," Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 62/07/26 Consolidated Edison Co of New York 12ipp 14357-013 24X Fiche.50-000.82/07/26.8204210403
- 8204210405 IE Info Natice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl.
 JORDANIE L. Division of Engineering & Quality Assurance 82/07/28
 Consolidated Edison Co of New York. 122pp 14357 146 24X
 Fiche 30-000.82/07/28.8204210405
- 8208100137 Responds to IE Bulletin ER-02 re leakage in holted closures of RCPB insp conducted revealed flange leak in main coolant pump 3 Casket seating surfaces cleaned & lapped MCGDV.D E Yankee Atomic Electric Co. 82/07/30 HAYNES,R C. Ragion 1. Office of Director. 2pp. 14298.016 24X Fiche 50-029,82/07/30,8208100137
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance. 82/08/05 Consolidated Edison Co. of New York 117pp. 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8208240276 Ack receipt of 820701 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/82-07 MARTIN:T.T Division of Engineering & Technical Programs. 82/08/19, KAY.J A Yankee Atomic Electric Co ip 14527 178 24X Fiche:50-029,82/08/19,8208240276

- ---8208240280 Responds to NRC 820604 itr re violations noted in IE Insp Rept 50-029/82-07 Corrective actions plant mgt will re-emphasize need for comprehensive corrective action planning & procedures will be revised MODDY.D E Yankee Atomic Electric Co 82/07/01 HAYNES.R C Region 1, Office of Director 3pp 14527 179 24X Fiche 50-029.82/08/19.8208240276
- R Periodic operating reports & related correspondence
- 8208120232 Forwards monthly operating rept for June 1982, MODDY, D E Yankee Atomic Electric Co 82/07/09 Office of Resource Management, Director 2pp 14326 277 24X Fiche 50-029, 82/07/09,8208120232
- --8203120234 Monthly operating rept for June 1982 BOYLE.A E Yankee Atomic Electric Co 82/07/09 4pp 14326 279 24% Fiche 50-029, 82/07/09, 8203120232
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fichs 50-000, 82/07/13, 8208270010
- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CV61" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679:216 24X Fiche, 50-000, 82/07/13, 8208270010.
- --8208270547 Forwards "Yankee Rowe Personnel & Man Rem By Work & Duty Function Rept CYB1 " MODDY, D. E. Yankse Atomic Electric Co. 82/03/04 HAYNES, R C Region 1. Office of Director 1p 14680.030 24X Fiche 50-000.82/07/13.8208270010
- --B208270550 "Yankee Rowe Personnel & Han Rem By Work & Duty Function Rept.CY81 " ANTID.R.H., TRIGER.J.C Yankee Atomic Electric Co 82/02/16 ip 14680 031 24X Fiche.50-000,82/07/13,8208270010
- --8208270629 Forwards whole body range rept for CYBi, per 10CFR20 407 MODDY, D E Yankee Atomic Electric Co 82/03/12 HALLER, N H Office of Management and Program Analysis 1p 14680.050 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270638 Whole body range rept for CYB1
 TRIJO, J., ANTID, H.A. Yankee Atomic Electric Co. 82/03/08 ip
 14680 051 24X Fiche 50-000, 82/07/13, 8208270010.
- 8 Reportable occurrences, LERs & related correspondence
- 8208020292 Forwards LER 82-018/03L-0 AUTIO:H A. Yankem Atomic Electric Co 82/07/23 HAYNES:R C Region 1: Office of Director ip 14151 304 24X Fichm 50-029:82/07/23:8208020292
- --B208020301 tER B2-018/03L-0 on 820624, low main coolant flow relay phase C in sys B failed to drap out when de-energized Caused by abnormal friction between plunger & upper bushing Relays SC-1,1876-072 replaced FRENCH, L A Vankee Atomic Electric Co 82/07/23 Region I, Office of Director 1p. 14151 305, 24X Fiche 50-029,82/07/23, 8208020292.
- 8208090050 Forwards LER 82-020/03L-0, AUTID: H A Yankee Atomic Electric Co 82/07/29 HAYNES: R C. Region 1. Office of Director 10 14267:361 24X Fiche 50-029, 82/07/29, 8208090050
- --B20B090052 LER B2-020/03L-0 on B20629, during testing of nonreturn valve tripping sys, valve 3 failed to close on actuation of train A Caused by failure of main dump solenoid valve Valve replaced wimproved model. Remaining valves will be replaced FRENCH. L Yankee Atomic Electric Co B2/07/29 Region 1, Office of Director 1p 14269.362 24X Fiche 50-029, B2/07/29, B208090050
- 8208090118 Forwards LER 82-019/03L-0 AUTID.H.A Yantee Atomic Electric Co 82/07/29. HAYNES.R C. Region J. Office of Director ip 14269 353 24X Fiche 50-029,82/07/29,8208090118

- --9208090122 LER 82-019/03L-0 on 820629, voltage surges on 115-kV lines during thunderstorm resulted in loss of Z 126 line & loss of flow scram Caused by lightening strike on 115-kV line during storm Line restored to svc MAY-E L Yankee Atomic Electric Co 82/07/29 Region 1, Office of Director 19 14269 354 24X Fiche 50-029, 82/07/29, page 2014
- #208230032 Forwards LER 82-021/03L-0 AUTIO.H A Yankue Atomic Electric Co 82/08/11 HAYNES.R C Region 1. Office of Director ip 14517 262 24X Fiche 50-029.82/08/11.8208230032
- --BR08230045 LER 82-021/03L-0 on 820712, fire detection may ranes for charging pump cubicles & charcoal filters failed Caused by rain water which entered junction box through openings made to facilitate const activity Openings seeled MAY.E L Yankes Atomic Electric Co. 82/08/11 Region 1, Office of Director ip 14917 263 24X Ficha 80-029,82/08/11,8208230032
- 8208230072 Forwards LER 82~022/03L-0 AUTIO, H A. Yankee Atomic Electric Co 82/08/12 HAYNES, R C Region L. Office of Director. Ip 14917 209 24X Fiche 50-027:82/08/12.8208230072
- --B208230074 LER 82-022/03L-0 on 820713.8I MOV-1 motor operator contactor circuit control transformer primary winding grounded during normal operation Caused by nearby const activity resulting in rain entering EMCC-2 & BI-MOV-1 operator contactor RICE, D.A. Yanker Atomic Electric Co. 82/08/12. Region 1, 0ffice of Director. ip 14517-206-24X Fiche 50-029,82/08/12,8208230072
- DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR
- O Inspection reports, IE Bulletins & correspondence
- 8204210399 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Syc list encl UCRDAN, E.L. Division of Engineering & Guality Assurance 82/07/19, Hickigan, Univ of 112pp. 14358 001 24X Fiche, 50-000, 82/07/19, 8204210395.
- DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR
- O Inspection reports, IE Bulletins & correspondence
- B2Q4210395 IE Info Notice Bi-26,Part 3,Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" See list and!.

 JORDAN,E L Division of Engineering & Quality Assurance 82/07/19
 Hichigan, Univ. of 112pp. 14258 001 24X Fiche 50-000.62/07/19, B204210395
- DOCKET 50-59 TEXAS AM UNIV RESEARCH REACTOR
- G Inspection reports: IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN E L Division of Engineering & Quality Assurance, 82/07/19 Kichigan, Univ of 112pp 14358.001 24X Fiche: 50-000, 82/07/19, 8204210395
- POCKET 50-70 GENERAL ELECTRIC TEST REACTOR
- Adjudicatory correspondence
- 8208190121 Initial decision removing NRR 771024 show cause order, approving restart & designating proper geologic & seismic design bases.
 FERQUEON. O A. FOREMAN, H. Atomic Bafety and Licensing Board Panel 62/08/16 240pp 14381:303 24X Fiche 50-070,82/08/16,8208190121.
- 9208240232 Notice of ASLAB constitution CN Kohl, chairman & BF Eilperin & HA Hilber, members. SHOEKHARR, C. J. Atomic Bafety and Licensing Appeal Panel. 82/08/2019 14519 147. 24X Ficher 50-070, 82/08/20, 8208240232

- P. Operating license stage documents & correspondence
- 8208090194 Qeneric Ltr 82-14 to all reactor licensees, holders of CF & applicants re submittal of documents to NRC Summarizes iQCFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENNUT.D.O Division of Licensing 82/08/09 Consolidated Edison Co of New York | p | 14386 332 24X Fiche 50-000,62/08/09,8208090194
- DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnol Monitoring Devices for External Radiation" But list and I. JORDAM, E.L. Division of Engineering & Quality Assurance. 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fichs 50-000, 82/07/19, 8204210375
- DOCKET 50-77 CATHOLIC UNIV OF AMERICA RESEARCH REACTOR
- G Inspection reports. IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3. Buppl 1. "Clarification of Flacement of Personnel Monitoring Devices for External Radiation" But list end JORDAN: E.L. Division of Engineering & Quality Assurance 82/07/19, Michigan: Univ of. 112pp 14358:001. 24X Ficha 30-000.82/07/19, 8204210395
- DOCKET 50-83 UNIV. OF FLORIDA TRAINING REACTOR
- F Security, medical, emergency & fire protection plans
- 820B130294 Forwards IE Safeguards Insp Repts 50-083/82-01 & 70-1068/82-01 on 820629-0701 No noncompliance noted VERRELLI,D. Division of Project & Resident Programs 82/07/19 JACO88.4 M. Florida, Univ of, Osinesville 2pp. 14336 317 24) Fichs 50-083,82/07/19,8208130294
- --8208130299 IE Bafeguards Insp Repts 50-083/82-01 % 70-1068/82-01 on 820629-0701 No noncompliance hoted. Major areas inspected security plan & organization.access controls. records & repts & physical barriers Details withheld (ref 10CFR2 790) MODRE.D E . MCGUIRE.D R. Division of Engineering & Technical Programs 82/07/15 ip 14336 319 24X Fiche.50-083,82/07/19,8208130294
- G Inspection reports. IE Bulletins & correspondence
- 8208130294 Forwards IE Bafeguards Insp Repts 50-083/82-01 & 70-1068/82-01 on 820629-0701. No noncompliance nuted. VERRELLI, D. Division of Project & Resident Programs 82/07/19, JACOBS, A.M. Fierida, Univ of, Gainesville 2pp 14336:317 24) Fiche, 50-083, 82/07/19, 8208130294
- --B208130299 IS Bafequards Insp Repts 50-083/82-01 & 70-1068/82-01 on 820629-0701 No noncompliance noted. Major areas inspected security plan & organization, access controls, records & repts & physical barriers Details withheld (ref 10CFR2 790). MODRE, D.E., MCGUIRE, D.R. Division of Engineering & Technical Programs. 82/07/15 1p 14336.319 24% Fiche.50-083,82/07/19,8208130294.
- DOCKET BO-BY WESTINGHOUSE CRITICAL EXPERIMENT
- Q Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl.

 JORDAN E. L. Division of Engineering & Quality Assurance 82/07/19

 Michigan, Univ of. 112pp 14358 001 24X Fiche. 50-000, 82/07/19, 8204210395.

DOCKET 50-89 GENERAL ATOMIC CO

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of ECUALIVITY IE INTO NOTICE BINZE, PART J. SUPPL 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/19 Michigam. Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210399 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of

204210373 IE into Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnej Monitoring Devices for External Radiation " Svc list encl JOROAN, E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24% Fiche 50-000, 82/07/19, 8204210395

DOCKET 50-99 BARCOCK & WILCOX TEST REACTOR

J Insurance & indemnity information

8208090032 Unexecuted Amend 21 to Indemnity Agreement B-8 SALTZMAN.J. Assistant Director for State & Licensee Relations 82/07/26 1p. 14301 101 24% Fiche 50-099.82/07/26,6208090032

8208060217 Forwards Amend 21 to Indemnity Agreement B-8, in response to NRC 820720 1tr DLBEN, A.F. Babcock & Wilcor Co. 82/08/03 Division of Licensing Rpp. 14241 083 24X Fiche 50-099,82/08/03,8208060217 OLSEN, A F

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of

W Decommissioning Stage Documents & Correspondence

820B120004 Forwards order terminating License R-47 in accordance w/B10723 application & Amend 21 to Indemnity Agreement 8 EISENHUT. D Q Division of Licensing 82/07/20 OLSEN, A F Babtoc & Wilcox Co 2pp 14332 244 24X Fiche 50-099, 82/07/20, 820B120004

-8208120095 Order authorizing termination of License R-47, effective

EIGENHUT, D G. Division of Licensing 82/07/20 Babcock & Wilcox Co 2pp 14332 247 24X Fiche 50-099,82/07/20,8208120004

B208120097 Sefety evaluation supporting termination of License R-47

* Office of Nuclear Reactor Regulation. Director 82/07/20 3p
14332:249. 24X Fiche 50-099:82/07/20:8208120004

THEY 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR Operating license stage documents & correspondence

)8060197 Requests amend to License R-53 Amend authorizes increase in lumber of fuel elements from current license limitation of 12 to 20 elements or less increase in fuel elements allows reactor to operate in flux trap configuration TERRELL.C W Gklahoma. Univ of 82/07/31 MILLER.J R Standardization & Special Projects Branch 6pp 14239.009 24X Fiche 50-112,82/07/31,8208060197.

JCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR

> Inspection reports, IE Bulletins & correspondence

04210376 IE Info Notice Bi-26, Part 3, Suppl i, "Clarification of OMAZIOSPD 16 Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Tadiation." Syc list encl ORRON. E.L. Division of Engineering & Quelity Assurance 82/07/19 Hichigan. Univ. of. 112pp. 14358 001 24X Fiche. 50-000.82/07/19, 204210395

DOCKET 50-114 IOWA STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Syc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

H General correspondence

8208030235 Requests that DL Warner replace TJ Planje on distribution list re License R-79 Ltr dtd 820602, referred to in NRC 820712 ltr, cannot be found BOLON A E Hissouri, Univ of, Rolla 82/07/20 DERNARD, H Standardistion & Special Projects Branch ip 14207 337 24X Fichs 50-123, 82/07/20, 8208050256

--8208050260 Advises of death of TJ Planje in Jul 1980 DL Warner is now Dean of School of Mines & Metallurgy,
STOSBUILL, P. Missouri, Univ. of Rolla 82/07/20. BERNARD, H.
Standardization & Special Projects Branch Ip 14207 338 2.
Fiche 50-123, 82/07/20. 8208050835

DOCKET 50-128 TEXAS AMM UNIV RESEARCH REACTOR

Q Inspection reports: IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Syc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/19 Hichigan JORDAN, E L. Division of Engir Michigan, Univ of 112pp 8204210395

DOCKET 50-133 HUMBOLDT BAY POWER PLANT: UNIT 3

F Security, medical, emergency & fire protection plans

8208240290 Forwards IE Insp Rept 50-133/82-03 on 820720-23 No noncompliance noted in high rep of 153/52-03 bit 82/720-23 No noncompliance noted STERNSERO, D M Division of Resident, Reactor Project & Engineering Programs 82/08/03 CRANE, P A Pacific Gas & Electric Co. App 14544 128 24X Fishe 50-133/82/08/03/8208240290

--8208240295 IE Insp Rept 50-133/82-03 on 820720-23 No noncompliance noted Major areas inspected operations, organization & administration, procedures, procurement & fire prevention MILLETT, D J , YOUNG, T Division of Resident, Reactor Project & Engineering Programs 62/08/03 5pp. 14544-132 24X Fiche 50-133,82/08/03,8208240290

H General correspondence

8208020456 Respands to 820608 ltr re decommissioning facility Plant shut down in 1962 ASLB 820216 order established schedule for licenses to decide whether to decommission plant or resume operation Safety issues to be resolved prior to reopening DENTON. H R Office of Nuclear Reactor Regulation, Director 82/07/07 SIMMONS. O T Affiliation Unknown. 3pp 14180 167 24x Fichar 50-133, 82/07/07, 8208020456

~-8208020458 Demands facility be decommissioned BIHMONS,6 T Affiliation Unknown 82/06/08 Qff; Reactor Regulation, Diractor 2pp 14180 170 24X Fiche. 50-133, 82/07/07. 8208020456. Office of Nuclear

8208020134 Requests decommissioning of facility D'ABBACCI,T Affillation Upknown 82/07/25, DENTON.H Nuclear Reactor Regulation, Director 1p 14141 334, 2 Fiche 50-133,82/07/25,8208020134 Office of

8208300334 Responds to 820725 ltr to H Denton re need for decommissioning plant Since facility has been shut down since 760706, public health & safety are not compromised LAINAS. G C Assistant Director for Operating Reactors D'ABBRACCI.T Affiliation Unknown ip 14697:153 24X Fiche 50-133, 82/08/20, 8208300334. 82/08/20.

J Insurance & indemnity information

8208030523 Submits responses to questions re insurance coverage per 820624 ltr No addl studies analyzing risk & consequences of accident in cold shutdown conducted MANEATIB, G A Pacific Gas & Electric Co 82/07/28 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 14163 093 24X Fiche 50-133,82/07/28,8208030523

P Operating license stage documents & correspondence

- 8207080064 Generic ltr to all licensees of operating plants, applicants for GL & holders of CP re Commission approved charter for CRQR 89v list encl
 DIRCKS: N J Office of the Esscutive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 OOI
 24X Fiche 50-000:82/07/02.8207080064
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISEMHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York Ip 14356 332 24X Fiche 50-000.82/08/09, 8208090194

Q Inspection reports, IE Bulletins & correspondence

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list anc!
 JORDAN,E L Division of Engineering & Quality Assurance
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26.Part 3.Buppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Evc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19.8204210395
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Fressure" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396.
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " 8vc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357.276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Byo list enc! JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche: 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl.

 JORDAN, E L Division of Engineering & Guality Assurance 82/07/23

 Consolidated Edison Co of New York 122pp 14380 115, 24X

 Fiche 30-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Opide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E. L. Divisian of Engineering & Quality Assurance 82/07/23. Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23. 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PNR Power Plents " Svc list encl JURDAN, E L Division of Engineering & Quality Assurance. 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Hork in Fuel Storage Fool " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance B2/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche, 50-000, 82/07/28, 8204210405
- 8208240290 Forwards IE Insp Rept 50-133/82-03 on 820720-23 No noncompliance noted BTERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/08/03 CRANE,F A Facific Qas & Electric Co 4pp 14544 128, 24% Fiche 50-133,82/08/03,8208240290

- --8208240295 IE Insp Rept 50-133/82-03 on 820720-23 No noncompliance noted Major areas inspected operations organization & administration, procedures, procurement & fire prevention WILLETT, D J , YOUNG, T Division of Resident, Resctor Project & Engineering Programs 82/08/03 5pp 14544 132 24X Fiche 50-133,82/08/03,8208240290
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list entl JURDAN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fithe 50-000.82/08/05.8204210407
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000,82/07/13.8208270010
- ---8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYSI" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000.82/07/13,8208270010
- --8208270611 Forwards "Rept of Recorded Personnel Whole Body Exposures for CY81," per 10CFR20 407(a) CRANE,P A Pacific Gas & Electric Co 82/03/26 BASSETT, H B Office of Management and Program Analysis 1p 14680 056 24X Fiche. 50-000, 82/07/13, 8208270010
- --8208270616 "Rept of Recorded Personnel Whole Body Exposures for CVB1 "
 * Pacific Oas & Electric Co 82/03/26 ip 14680 057 24%
 Fiche 50-000,82/07/13,8208270010
- 8208120316 Forwards monthly operating rept for June 1982 HEEKS,E D Pacific Gas & Electric Co 82/07/19 Office of Resource Management. Director ip 14324 265 24X Fiche 50-103, 82/07/19, 8208120316
- --8208120318 Monthly operating rept for June 1982 DERMS, F B Pacific Gas & Electric Co 82/07/19 4pp 14324 264 24X Fichs 80-153.82/07/19.8208120316
- B Reportable occurrences. LERs & related correspondence
- 8208020241 Forwards LER 82-007/03L-0 CRANE.P A Facific Gas & Electric Co 82/07/23 ENGELKEN.R H Region 5. Office of Director 1p 14151 231 24X Fiche 80-133.82/07/23.8208020241
- --8208020247 LER 82-007/03L-0. on 820623, w/unit shutdown, screen wash pump I was started but no discharge pressure observed Cause by stuck open position on discharge cheet valve Pump repaired & returned to svc QETTY.8 C Pacific Oas & Electric Co 82/07/23 Region 5, Office of Director ip 14151 232 24X Fichs 50-133, 82/07/23, 8208020241
- DOCKET 50-134 HORCESTER POLYTECH INST RESEARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- B204210395 IE Info Notice B1-26, Part 5, Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Syc list encl JURDAN, E. Division of Engineering & Quality Assurance 82/07/19 Nichigan, Univ of 112pp 14398 001 24X Fiche 50-000, 82/07/19, 8204210395
- DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8208030504 Forwards IE Safeguards Insp Rept 50-137/82-02 on 820722 Nu noncompliance noted. NGRDERHAUG.L R. Division of Radiological Bafety & Bafeguards Program 82/07/27 CARLSON D A Washington Univ of App 14162 301 24X Fiche 50-139,82/07/29,8208030504

- --B208030498 IE Safeguards Insp Rept 50-139/62-02 on 820722 No nancompliance noted Major areas inspected security plan & procedures, protection of 6NM, access control alarm sys communications & security organization Details withheld SCHWAN, C A, MCQUEEN, A D, SCHWSTER, M D Division of Radiological Safety & Bafeguards Program 82/07/29 ip 14162-305 24X Fiche 50-139, 82/07/29, 8208030504
- @ Inspection reports. IE Bulletins & carrespondence
- 8208030504 Forwards 1E Safeguards Insp Rept 50-139/82-02 on 820722 No noncompliance noted NORDERHAUG.L R Division of Radiological Bafety & Safeguards Program 62/07/29 CARLSON,D A Washington Univ of 4pp 14162 301 24X Fichs 50-139,82/07/29,8208030504
- ---8208030498 IE Bafeguards Imsp Rept 50-139/82-02 on 820722 No noncompliance noted Major areas inspected security plan & procedures, protection of BNK, access control alarm sus communications & security organization Details withheld SCHMAN, C A . MCGUEEN. A D. SCHUBTER, M D. Division of Radiological Safety & Safeguards Program 82/07/27 ip 14162 305 24X Fiche 50-139,82/07/29.8208030504

DOCKET 50-142 UCLA TRAINING REACTOR

- F Security, medical, emergency & fire protection plans
- 8208190160 Forwards five pages of Amend B to physical security plan Pages withheld (ref 10CFR2 790)
 ABMBAUGH: C E California, Univ of, Los Angeles 82/08/10
 BERNARD.H Standardization & Special Projects Branch 1p
 14381 019. 24% Fiche 50-142.82/08/10.8208190160
- Q Adjudicatory correspondence
- 8208020289 Objects to City of Santa Monica proposed protective order & affidavit of nondisclosure & responds to Committee to Bridge the Sap 820712 mods to contention language CORMIER.W H California. Univ of Los Angeles 82/07/26, FRYE.J H , FARIS, O H , LUEBKE, E A Atomic Safety and Licensing Board Panel. 2pp 14151 302 24X Fiche 50-142, 82/07/26, 8268020289
- 8208090182 Advises that univ submitted emergency response plan to Commission on 820729 Plan nearly identical to Mar 1982 yersion Plan & transmittal ltr enci. Wo encl CORMER. W H California. Univ of Los Angeles 62/08/02 FRYE. J H , PARIS, O H , LUEDKE, E A Atomic Safety and Licensing Board Panel Ip 14272:036 24% Fiche 50-142.82/08/02,0208090182.
- 920B110139 Advises of change in circumstances affecting scope of discovery on Contention XX, UCLA recently completed transfer of reactor fuel, reducing U-235 inventory to less than 5 kg Transfer changes basis of 10CFR73 60 exemption request CORNIER, W H California, Univ of, Los Angeles 82/08/06 FRYE, J H., PARIB, O H., LUEBKE, E A. Atomic Bafety and Licensing Board Panel Ip 14314 307 24X Fiche 50-142, 82/08/06, 820B110139
- -8208110142 Advises of recent transfer of U-235, reducing inventory to lass then 5 kg. UCLA need not maintain self-protecting conditions for in-core fuel to remain exempt from updated safeguards requirements of 10CFR/3 60 WEOST.W.F. California, Univ. of. Los Angeles, 82/08/06 BERNARD, H. Bampdardiration & Special Projects Branch ip 14314 308 24X Fiche: 50-142, 82/08/06, 8208110139.
- 8206110176 Requests avoited listed persons of new emergency plan & B20430 amends Future timely svo & compliance u/filing deadlines requested.
 HIRSCH.D Committee to Bridge the Cap B2/08/06 CDRMIER.W H California. Univ of Los Angeles ip. 14314.172 24x
 Fiche 50-142,82/08/06,8208110178
- 8208110179 Comments on Cormier 820802 ltr re applicant proposed amends to emergency plan ASLB should not schedule addit discovery & motions for summary disposition until amends completed & plan reviewed by Committee to Bridge the Gap HIRSCH.D. Committee to Bridge the Gap 82/08/06. FRYE, J H, PARIS.O H, LUEBKE, E.A. Atomic Safety and Licensing Board Panel 2pp 14314 170 24X Fiche: 30-142,82/08/06.8208110179
- 8208110195 Dbjections to portions of ABLB 820726 prehearing conference order denying Committee to Bridge the Cap request that NRC be directed to furnish info to assess potential conflict of interest Declaration of Svc encl.

 HIRSCH.D. Committee to Bridge the Cap B2/08/06 Atomic Safety and Licensing Board Panel 7pp 14313 033 24X

 Fiche 50-142, 82/08/06, 8208110195

- 8208110212 Response to NRC & UCLA concerns re 820712 language mode to Contention VIII reflecting proposed application amends Basis for contention does not refer to 1982 amended application Declaration of Svc encl HMRGCH.D Committee to Bridge the Gap 82/08/06 16pp 14313 045 24X Fiche 50-142.82/08/06.8208110212
- B20Bi301B2 Response to Committee to Bridge the Qap B2072O request for production of documents re security-related Contention XX UCLA will provide outlined documents at B20B12 document exam session Certificate of Svr Bnc1 CORMIER W H California, Univ of, Los Angeles B2/0B/09 Committee to Bridge the Qap 11pp 1433B 318 24X Fiche 50-142. B2/0B/09. B20B130152
- 820B130204 Response to first set on interrogatories for Contention XX Certificate of Svc enci CORNIER,W H California, Univ of Los Angeles 82/08/09 Atomic Bafety and Licensing Board Panel 14pp 14339 080 24X Fiche 50-142, 82/08/09, 8208130204
- 8208170246 Memorandum scheduling 820825 conference call to discuss hearing schedule for emergency plan contentions not subj of motions for summary disposition, per 820725 prehearing conference order SER to be issued on 820816 FRYC. J H Atomic Bafety and Licensing Board Panel 82/08/13 2pp 14367 137 248 Fichs 50-142.82/08/13.8208170266
- 820B170325 Informs of ASLB decision to treat Committee to Bridge the Gap 820806 objections to 820726 prehearing conference order as motion for reconsideration. Responses due by 820823 FRYE, J H Atomic Bafety and Licensing Board Panel 82/08/13 WOODDHEAD, C P Hearing Branch i CORMIER, W H California, Univ of, Los Angeles ip. 14366 348, 24X Fiche 50-142,82/08/13,8208170325,
- 920B170330 Advises of intent to file motion for summary disposition of all contentions except Contention XII.pursuant to ABLB B20726 prehearing conference order Contention to be revised to reflect UGLA 820729 emergency plan WDODMEAD, C P Hearing Branch i B2/08/16. FRYE, J. H., PARIS, O H., LUEBKE, E A Atomic Safety and Licensing Board Panel ip 14367 003 24X Fiche 50-142.82/08/16.8208170330
- 8208180121 Hemorandum & order approving Committee to Bridge the Gap B20712 mode to Contentions VIII,I 2 a & V 3 Contentions based only on 1960 Harards Analysis Restatement of contentions pursuant to ASLB 820816 order enri LUEBKE,E A . PARIS,O H . FRYE,J Atomic Bafety and Licensing Board Panel 82/08/16 28pp 14377 127 24X Fichs 50-142.82/08/16, 8208180121
- 8208200301 Provides info per ASLB 820726 order re in camera hearing & motion for summary disposition Transcript of hearing should not be withheld from public disclosure Committee to move for summary disposition of Contentions XIII & XVII.
 HIRSCH.D Committee to Bridge the Gap 82/08/16 FRYE.J H.,
 PARIS.O H, LUERKE.E.A. Atomic Safety and Licensing Board Panel ip 14394 145, 24X Fiche 50-142,82/08/16,8208200301
- 8208240249 Advises that univ intends to move for summary disposition of all contentions admitted to proceeding, w/exception of Contentions XX & XXI Franscript of prehearing conference contains no security sensitive info CORMIER. W. H. California, Univ. of, Los Angeles 82/08/16 FRYE. J. H., PARIS, O. H. LUERKE. E. A. Atomic Bafaty and Licensing Doard Panel 3pp. 14520 073 24X Fiche. 50-142, 82/08/16, 8208240249
- 8208230052 Clarifies ASL8 820816 order ruling on mod to contentions Withdrawn document identified as 1960 hazards analysis submitted as SAR in 1980 application MODDHEAD, CP Hearing Branch 1 82/08/19 FRYE, J. H., LUEBKE, E.A., PARIB, O.H. Atomic Safety and Licensing Board Panel. Gpp. 14517 232 24X Fiche 50-142,82/08/19,8208230052
- 8208230078 Motion to amend Apr 1981 motion for summary disposition of Contention XX; to reflect recent reduction in inventory of SMM to less than 5 kg & change in application of 100FR73, Certificate of Svc enc!

 MODDHEAD, C P Hearing Branch 1 82/08/20. Atomic Sefety and Licensing Board Panel 5pp 14517 146, 24X Fiche 50-142,82/08/20,8208230078.
- 8208240337 Response to Committee to Bridge the Gap 820806 filing which ASLB is treating as motion for reconsideration of ASLB 820726 prehearing conference order Concurs w/ASLB decision to deny Gap request for add1 info Certificate of Syc encl. CORMIER.W H California. Univ of, Los Angelss. 82/08/20 Atomic 8afety and Licensing Board Panel 5pp 14520 316 24x Fichs. 50-142.82/08/20.8208240337

- B20B240356 Forwards latest amends to application, correcting two items in emergency response plan
 CORMIER, W.H. California, Univ. of, Los Angeles 82/08/20
 HIRSCH, D. Committee to Bridge the Gap. 4pp. 14521 053 24X
 Fiche 50-142, 82/08/20, 8208240356
- 8208250216 Forwards IE Insp Rept 30-142/82-02 & H Bernard photographs of exterior of Boslter Hall W/o encl HOODNEAD.C P Hearing Branch 1 82/08/23 HIRSCH, D Committee to Bridge the Gap 1p 14541 357 24X Fiche 50-142,82/08/23, 8208250216
- 8208250287 Response opposing Committee to Bridgo the Gap 820806 filing which ASLB treated as motion for reconsideration of ASLB 820726 prehearing conference order Interrogatories unlikely to lead to admissible evidence w/Certificate of 8vc WOODHEAD.C P Hearing Branch 1 82/08/23 Atomic Safety and Licensing Board Panel 32pp 14542 186 24X Fiche 50-142.82/08/23.8208250287
- B20827041B Forwards add1 questions re fuel self-protection calculations included as Exhibit A to Univ response to Committee to Bridge the Cap interrogatories on Contention XX.per 820819 agreement BAY.J H Affiliation Unknown 82/08/23 CORMIER.W H California. Univ of. Los Angeles 3pp. 14865 240 24X Fichs 50-142.82/08/23,820827041B
- 8208300273 Memorandum & order confirming 820825 telcon w/UCLA.
 Committee to Bridge the Gap, Banta Monica. CA & NRC rescape
 of Banta Monica interest in contentions, status of
 Contentions XXI & XXIII & use of technical terminology
 FRYE, J H Atomic Safety and Licensing Board Panel 82/08/26 3pp
 14979 235 24X Fichs 30-142,82/08/26,8208300273
- 8208300301 Order directing Secretary to place 820630 prehearing conference transcript. Pages 672-712 in PDR & LPDR FRYE.J H Atomic Safety and Licensing Board Panel 82/08/26 Office of the Secretary of the Commission ip 14673-218 24X Fiche 50-142, 82/08/26, 8208300301

P Operating license stage documents & correspondence

- 8208110139 Advises of change in circumstances affecting scope of discovery on Contention XX WCLA recently completed transfer of reactor fuel.reducing U-235 inventory to less than 5 kg Transfer changes basis of 10CFR73 60 exemption request CORMIER,W H California, Univ of, Los Angeles 82/08/06 FRYE,U H, PARTS,O H, LUERKE,E A Atomic Safety and Licensing Board Panel 1p 14314 307 24X Fiche 50-142,82/08/06,8208110139
- --8208110142 Advises of recent transfer of U-235, reducing inventory to less than 5 kg UCLA need not maintain self-protecting conditions for in-core fuel to remain exempt from updated safeguards requirements of 10CFR73 60

 WEGST,W F California, Univ of, Los Angeles 82/08/06

 BERNARD,H Standarditation & Special Projects Branch ip 14314 308 24% Fiche 50~142,82/08/06,8208110139

Q Inspection reports, IE Bulletins & correspondence

- 8204210395 lE Info Notice 81~26.Part 3. Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JURDAN.E L Division of Engineering & Guality Assurance 82/07/19 Michigan. Univ of 112pp 14358 001 24X Fichs 50~000.82/07/19, 8204210398
- 6208160100 Forwards IE Insp Rept 50~142/82-02 on 820628~30 & natice of violation STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 82/07/22 MEOST, W.F. California, Univ. of, Los Angeles 2pp. 14345 160 24X Fiche 50-142,82/07/22,8208160100
- --8208160102 Notice of violation from insp on 820628-30 YOUNO.T Division of Resident, Reactor Project & Engineering Programs 82/07/22 ip 14345 162 24X Fiche 50-142,82/07/22, 8208160100
- --B20B160105 IE Insp Rept 50-142/B2-02 on 92062B-30 Noncompliance noted addendum to prestant checkoff for B20111 not submitted to director of nuclear sergy lab for routine review MORRILL, P., BTEMART, P., YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 82/07/20 4pp 14345 163 24X Fichs 50-142.B2/07/22,B20B160100
- B20B240172 Ack receipt of B20B03 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-142/B2-02 BIBHUP.T W Division of Resident Reactor Project & Engineering Programs B2/08/16 WEOST, W F California, Univ of, Los Angeles 1p. 14517.327 24X Fiche 50-142.82/08/16.8208240172

- --8208240174 Respands to NRC 820722 ltr re violations noted in IE Insp Rept 50-142/82-02 Corrective actions N Ostrander designated as NEL acting director Action will allow for approval prior to implementation of changes WEOST, W.F. California, Univ. of, Los Angeles 82/08/03 YOUNO, T Division of Resident, Reactor Fraject & Engineering Programs 2pp 14955 171 24X Fiche 50-142,82/08/16,8208240172
- T Hearing transcripts on non-antitrust matters
- 8208300297 Transcript of ASLB 820630 prehearing conference in Los Angeles:CA Pp 672-712 Released per ASLB 820826 order * Atomic Safety and Licensing Board Panel 82/06/30 42pp 14599 238 24X Fiche 50-142.82/06/30.8208300297
- DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY

 R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said into Forwards documents listed in App A FELTON.J M Division of Rules and Records, 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000.82/07/13.8208270010
- --B20B27009B "Annuel Whole Body Dose At Licensed Nuclear Power Facilities for CYB1" AND Particle Affiliation Given B2/07/13 48pp 14479 216 24X Fiche 50-000, 82/07/13, 820B270010
- DOCKET 50-147 ROCKHELL INTL CORP CRITICAL FACILITY

 O Inspection reports. IE Bulletins & correspondence
- 8208240269 Ack receipt of 820809 ltr informing NRC of steps taken to correct violation noted in IE insprept STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/08/16 CRANDALLN E Northrop Research & Technical Center ip 14544 126 24% Fiche 50-147, 82/08/16, 8208240269
- --B208240273 Responds to NRC B20727 ltr re-violation noted in IE insprept Corrective actions future meetings scheduled so health physicist may attend & addi health physicists will be certified to comply w/Tech Specs
 CRANDALL, W E Northrop Research & Technical Center 82/08/09
 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 19 14544 127 24X Fiche 50-147, B2/08/16, B208240269

DOCKET 50-140 UNIV OF KANSAS RESEARCH REACTOR

- R Periodic operating reports & related correspondence
- 8208020362 Submits annual operating rept for Jul 1981-June 1982 MESLER.R B Kansas. Univ of 82/07/23 Division of Licensing 2pp 14150 130 24X Fiche 50-148.82/07/23.8208020362
- DOCKET 50-150 DHIO STATE UNIV RESEARCH REACTOR
- G Inspection reports. IE Bulletins & correspondence
- 8204210395 [E Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" 5vc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8208090197 Forwards response to NRC 820607 ltr re intrusion detection sys Present sys deemed adequate Response withheld (ref 10CFR73 21) VANDEWALLE,D J. Consumers Power Co 82/07/29 CRUTCHFIELD,D. Operating Reactors Branch 5 3pp 14272 014 24X Fiche 50-155,82/07/29,8208090197
- 8208190430 Releases public version of revised site emergency plan & implementing procedures
 FELTON, J M Division of Rules and Records 82/08/10 Document Management Branch 1p 14504 281 24% Fiche 50-135, 82/08/10, 8208190430

- --8208170433 Forwards public version of revised Vol 9 to site emergency plan & revised Vol 9A to site emergency plan implementing procedures.

 VANDEMALLE, D J Consumers Power Co 82/07/30 CRUYCHFIELD, D Operating Reactors Branch 5 ip 14504 284 24X Fiche 50-155, 82/08/10, 8208190430
- --8208170434 Public version of revised Vol 7 to site emergency plan • Consumers Power Co 81/11/17 250pp 14504 285 24X Fiche 50-155,82/08/10,8208190430
- --8208190435 Public version of Vol 9A to site emergency plan implementing procedures; including Procedures I re activation of emergency plan, 2 re facility actions during emergency & 3 re activation of technical support ctrs
 HARTMAN, C. J. Consumers Power Co. 81/11/24 300pp 14505-177
 24X Fiche 50-155,82/08/10,8208190430
- 8208170171 Requests submittal of current engineering drawings of facility layout & sys needed in support of two reactor sefeguards programs simed at reviewing effectiveness of NRC regulations & validating vital area designations CRUTCHFIELD.D. Operating Reactors Branch 5 82/08/11 VANDEMALLE,D Consumers Power Co 4pp 14364 318 24X Fiche: 50-155, 82/08/11, 8208170171
- Q Adjudicatory correspondence
- 8208030306 Reply opposing Christa-Maria 820714 motion requesting NRC 820625 testimony be subj of evidentiary hearings rather than first being pursued through deposition process. Certificate of Syc enci OALLOJ Consumers Power Co. GALLOJ Isham, Lincoln & Beals 82/07/29 Atomic Safety and Licensing Board Panel 9pp 14:57, 147. 24X Fiche. 50-155, 82/07/29, 8208030306
- B208030388 Proposed findings of fact & conclusions of law on Christa-Maria Contentions 9(4),9(5) & 9(7) Certificate of Svc encl
 BENMEL.H Christa-Maria BENMEL.H Antioch College of Law
 B2/07/29, 7pg 14154-265 24X Fiche 50-155,82/07/29,8208030388,
- B20B040227 Forwards proposed opinion on administrative controls contention & certain emergency planning subcontentions & proposed findings of fact & conclusions of law on same issues.

 COPELAND, V. O. Isham. Lincoln & Beale COPELAND, V. O. Consumers Power Co. 82/07/30 BLOCH, P. B., PARIS, D. H., SHON, F. J., Atomic Bafety and Licensing Board Panel in 14188 140 24% Fiche 50-155, B2/07/30, 8208040227
- --8208040232 Proposed opinion on administrative controls contention (O'Neill IIO(a)) & emergency planning subcontentions (Christa-Marie 9(4)) 9(5), 9(7) & gart of 9(2)) GALLOJ J. STEPTOE, P. COPELAND, V. O. Consumers Power Ca 62/07/30 15pp 14188 141 24X Fichs 50-155, 82/07/30, 8208040227
- --8208040243 Proposed findings of fact & conclusions of law on administrative controls contention, O'Neill IIO(a) & smargency planning subcontentions, Christa-Haria 9(4), 9(5), 9(7) & part of 9(2) OALLO.J. BTEPTOE.PP. COPELAND V G Consumers Power Co 82/07/30 17pp 14188 156 24X Fiche 50-155, 82/07/30, 8208040227
- 8208050090 Forwards proposed findings of fact & conclusions of law on O'Neill Contention II 0 (a) & Christa-Maria Contentions 9(4).9(5) & 9(7) GODDARD, R.J. Hearing Branch 3 82/07/30 BLOCH, P.B., 8HON, F.J., PARIS, G.H. Atomic Safety and Licensing Spard Panel 1p. 14238-134, 24X Fiche, 50-135, 82/07/30, 8208050090.
- ---8208060093 Proposed findings of fact & conclusions of law on O'Neill Contention II. 9 (a) he adequacy of administrative controls proposed to prevent cask drop over spent fuel pool, GODDARD, R. J. Hearing Branch 3 82/07/30 App 14238-135, 24% Fiche 50-155, 82/07/30, 8208060090
- --8208060096 Proposed findings of fact & conclusions of law on Christa-Maria Contentions 9(4),9(3) & 9(7) re emergency evacuation GODDARD.R.J Hearing Branch 3 82/07/30 6pp 14238-141 24X Fiche: 50-155,82/07/30:8208060090.
- 8208040025 Informs that licensee had promptly notified NRC, on 820519, before hearings of possible structural inadequacy of semi-gantry crane to support 24-ton fuel transfer cask Issue of cask drop properly lies within ABLB jurisdiction.
 900DARD.R.J. Hearing Branch 3. 82/08/03 BLOCH.P.B. SHON,F.J., PARIBJO H Atomic Safety and Litensing Board Panel 2pp.
 14189:155. 24X Fiche: 50-155, 82/08/03, 8208040025.

- 8208060111 Forwards util draft evaluation rept to INPO 1982 review, formalizing handwritten preliminary findings & recommendations made available to ASLB & parties on 820608 GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 82708/03 BLOCH, P.B., SHON, F.J., PARIB, O.H. Atomic Safety and Licensing Board Panal 38pp 14238 194 24X Fiche 50-155,82/08/03,8208060111
- 8208090264 Summarizes pertinent provisions of ASLB 820804 telcon respent fuel pool mod No schedule determined for further evidentiary hearings Unresolved issues involve structural concrete analysis & seismic stability of overhead crane OCDDARD. R S Hearing Branch 3 BACHMANN. R J Hearing Branch 1 82/08/06 BLOCH. P B . PARIS. O H . SHON. F J Atomic Safety and Licensing Board Panel 2pp 14270 319 24X Fiche 50-155.82/08/06.8208090264
- 8208110072 Memorandum & order denying J O'Neill 820706 motion that ASLB adopt terms of agreement between CPC & NRC re 60-ton spent fuel transfer cask as license condition 8LOCH-P B Atomic Safety and Licensing Board Panel 82/08/06 O'Neill, J 1p 14316 352 24X Fiche 50-155,82/08/06.8208110072
- 8208110093 Initial decision re emergency planning contentions on emergency planning pamphiet Pamphiet shall be modified as listed & promptly distributed BLOCH.P B . PARIS.O H . SHON.F J Atomic Safety and Licensing Board Panel 82/08/06 19pp 14316 315 24X Fiche 50-155,82/08/06.820810093
- 8208110194 Response in opposition to intervenors Christa Maria, et al 820714 motion to reppen hearing record re Contention II C on potential for dropping spent fuel transfer cask Intervenors had ample notice of design inadequacies GALLO. J Consumers Power Co GALLO. J Isham, Lincoln & Beals 82/08/06. Atomic Safety and Licensing Board Fannel Opp 14314 001 24X Fiche 50-155,82/08/06,8208110194
- --B208110199 Affidavit of FA Turski re potential deficiencies w/spent fuel transfer cask load-bearing pins & reactor bldg crans girder load-bearing bolts Event rept based upon Whiting Corp analyses of unreliability of pins & bolts TUREKI,F A Consumers Power Co 82/08/04 3pp 14314 007. 24x Fichs. 50-155, 82/08/06, 8208110194
- --820B110211 Affidavit of DE Demoor re Event Rept E-BRP-82-26 prepared by F Turski on safety concern w/spent fuel transfer cask Based upon Whiting Corp testimony, situation did not require reporting Rept retracted H/Certificate of Bvc DEMOOR, D. E. Consumers Power Co. 82/08/04, 28pp. 14314-010 24x Ficher 50-155, 82/08/04, 8208110174
- 8208130005 Confirms 820810 telcon agreement w/Judge Bloch delaying date for filing findings of fact on TMI issues until 820823 & reply until 820913 BACHMANN,R.O. Regulations Division 82/08/11 BLOCH,P.B., 8HON,F.J., PARIB
- 8208130133 Order extending Commission time to review Director's Decision DD-82-05 until 820913 CMILK 8 J Office of the Secretary of the Commission 82/08/11 Commissioners. 1p. 14336-017 RAX Fiche 50-155,82/08/12,8208130133
- 8208130145 Memorandum & order denying Christa-Maria, et al 820719 motion requesting reopening of record re cask drop contention BLOCH, P.B. Atomic Safety and Licensing Board Penel 82/08/12, Christa-Maria ip. 14337-148 24X Fiche 50-155,82/08/12,8208130145
- 8208170124 Proposed findings of fact re Christa-Maria Contention 8 k O'Neill Contention III-2 (Subparts 1,2 k 3) Certificate of Svc enc!

 8208/13 | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | Christa-Maria | SEMMEL, H. | Antioch College of Law |
 82/08/13 | Christa-Maria | Christa-Maria
- 8208170264 Forwards Chapter 5 & portions of App IV to probabilistic risk assessment re containment integrity Licensee 820720 ltr containing revisions to isolation fediure calculations encl.

 9ALIO, J. Isham, Lincoln & Beale GALLO, J. Consumers Power Co. 82/08/13, BLOCH, P. B., PARIB, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel 100pp. 14367 139, 24% Fiche 50-135, 82/08/13, 82/08170264.
- 8208200189 Memorandum correcting error on Page 13 of 820806 initial decision 8L0CH.P.B Atomic Safety and Licensing Board Panel 82/08/18 ig 14500:188 24X Fiche. 50-155.82/08/18.8208200189.

- M208240374 Forwards util reply to intervenor proposed findings on Christa-Maria Contentions 9(4),9(5) & part of 9(2) COPELAND,V G Isham, Lincoln & Beale COPELAND,V G Consumers Power Co 82/08/19 BLOCH,P , PARIS,O H , SHON,F J Atomic Safety and Licensing Board Panel 1p 14522 319 24X Fiche 50-155,82/08/19,8208240374
- -8208240377 Reply to intervenor proposed findings on Christa-Maria Contentions 9(4),9(5) & part of 9(2) GALLOLJ, COPELANDLY O Consumers Fower Co GALLO, J Isham, Lincoln & Beale 82/08/19 14pp 14522 320 24X Fiche 50-155,82/08/19,8208240374
- 1208270508 Proposed findings of fact & conclusions of law re EIA Certificate of Svc encl BEMMEL, B Christa-Maria BEMMEL, H Antioch College of Law 82/08/20 11pp 14564 095 24X Fiche 50-155,82/08/20,8208270508
- 3208250224 Forwards proposed findings of fact & conclusions of law on O'Neill Contention VIII re NEPA Issues & Christa-Maria Contention 8 & O'Neill Contention III E 2 re TMI Issues BACHMANN, R O Hearing Branch 1 82/08/23 BLCCH, P B , SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 1p 14542 004 24X Fiche 30-155,82/08/23,8208250224
- --B208250232 Proposed findings of fact & conclusions of law on O'Neill Contention VIII re NEPA issues BACHMANN,R G Hearing Branch 1 82/08/23 7pp 14542.005 24X Fiche 50-185.82/08/23.8208250224
- --8208250238 Proposed findings of fact & conclusions of law on Christa-Maria Contention 8 & O'Neill Contention III E 2 re TMI issues BACHMANN:R G Hearing Branch 1 82/08/23 10pp 14542.012. 24X Fiche 50-155.82/08/23.8208250224
- 3208270328 Forwards proposed partial initial decision & proposed findings of fact & conclusions of law on Christa-Maria Contention 8 & O'Neill Contention III E-2 COPELAND, V 9 Isham, Lincoln & Beale COPELAND, V 9 Consumers Power Co 82/08/23 BLOCK, P. PARIB, O H. SHON, F. J. Atomic Safety and Licensing Ocerd Panel ip 14567 019 24X Fiche 50-155, 82/08/23, 8208270328
- --B20B270333 Proposed partial initial decision on admitted issues re Christa-Maria Contention B & O'Neill Contention III E-2 Licensee demonstrated makeup line, pool water level monitor & motor-operated valves adequate QALLO, J , COPELAND, V 9 Consumers Power Co GALLO, J Isham, Lincoln & Beale B2/08/23 Atomic Safety and Licensing Board Panel 15pp 14367 020 24X Fichs 50-155, B2/08/23, B20827 0328
- --B20B270337 Proposed findings of fact & conclusions of law on admitted issues to Christa-Maria Contention 8 & D'Neill Contention III E-2.

 # Consumers Power Co. # Isham, Lincoln & Beale B2/08/23 10pp 14567-035 24K Fiche 50-155,82/08/23,8208270328
- 3208270514 Forwards util proposed findings of fact & conclusions of law on remaining NEPA issues
 THORNTON,P. Isham, Lincoln & Beals THORNTON,P Consumers Power
 Co 82/08/23 BLOCH,P., PARIS.O H , SHON,P J Atomic Safety and
 Licensing Board Panel 1p 14964 109, 24% Fiche 50-155,82/08/23,8208270514
- --82082705iB Proposed findings of fact & conclusions of law on remaining NEPA issues Certificate of Svc encl QALLO, J . THORNTON. P. Consumers Power Co GALLO, J Isham, Lincoln & Beale 82/08/23 18pp 14564.110 24X Fiche:50-155,82/08/23.8208270514
- B20B270414 Advises that parties agree to B20927 date for simultaneous filings of findings of fact & conclusions of law re O'Neill Contention II C on cask drop issues GALLO, J Consumers Power Co B2/09/25 BLQCH,P B , PARIS,O H , SHON,F J Atomic Safety and Licensing Board Panel 1p 14565 237 24% Fiche 50-155,82/09/25, B208270414
- J Insurance & indemnity information
- B20B060224 Forwards Endorsement 92 to NELIA Policy NF-117, FROUNFELKER R Consumers Power Co 82/08/02 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 2p 14241:067 24X Fiche 50~155.82/08/02.8208040224
- 8208270494 Forwards Endorsement 93 to NELIA Policy NF-117 FRDUNFELKER: R Consumers Power Co 82/08/20 SALTZMAN, J Antitrysk Economic analysis Branch (Utility Finance) 2pp 14864.078 24X Fiche 50-155.82/08/20.8208270494

- P Operating license stage documents & correspondence
- 8208260377 Approves 82020B request for route for transport of spent reactor fuel Sanitized version of info to be incorporated into shipment plan & approved route encl SHERR.T S Material Transfer Bafeguards Licensing Branch BORDINE.T C Consumers Power Co 10 14579 219 24X Fiche 50-155.82/02/24,8208260377
- B207080064 Generic 1tr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR BVc list encl
 DIRCKS.H J. Office of the Executive Director for Operations
 B2/07/02 Consolidated Edizon Co of New York 93pp 14194 001
 24% Fichs 50-000.B2/07/02.B207060064
- 8208020081 Requests clarification of NRC 820702 ltm.establishing applicability of statement re access limitations during LUCA.expressed in 820821 & 0604 ltm. Util concurs w/applicability of 820521 ltm re spent fuel pool VANDEWALLE.D J Consumers Power Co 82/07/28 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 14144 102 24X Fiche 50-155,82/07/28,8208020081
- 8208050534 Advises that interpretation of Tech Spec Section 3 7(c) re leak testing of calibr test connections (s acceptable.until issue is resolved as part of SEP Topic VI-4, "Containment Isolation Sys" GRUTCHFIELD,D Operating Reactors Branch 5 82/08/02 VANDEMALLE,D Consumers Power Co 4pp 14213 317 24X Fiche 50-155,82/08/02,8208050534
- B208060178 Forwards review of NRC & contractor evaluations of util response to BEP Topic VIII-2, "Onsite Emergency Power Bys & Diesel Generator."
 VINCENT, R A Consumers Power Co 82/08/03 CRUTCHFIELD, D Operating Reactors Branch 5 7pp 14839 046 24X
 Fiche 50-135, 82/08/03, 8208060178
- 820807008i Forwards evaluation of SEP Topic III-2 rs wind & tornado loadings Facility provides adequate tornado protection VINCENT.R A Consumers Power Co 82/08/03 CRUTCHFIELD,D Obserting Reactors Branch 5 30pp 14270 204 24X Fiche 50-155,82/08/03,8208070081
- 8208070208 Forwards preliminary comments on SEP Topics VI-2 D, "Mass & Energy Release for Possible Pipe Break Inside Containment" & VI-3. "Containment Pressure & Heat Removal Capability." per NRC 820610 draft evaluation
 VINCENT.R A Consumers Power Co 82/08/05 CRUTCHFIELD, D Obstating Reactors Branch 5 4pp 14271 120 24X
 Fiche 50-155,82/08/05.8208090208
- 8208090257 Discusses status of seismic analyses per BEP Topic III-6, "Beismic Design Considerations," Heeting to discuss unresolved questions proposed for wk of 820823 VINCENT.R A. Consumers Power Co. 82/08/05 CRUTCHFIELD, D. Operating Reactors Granch 5. 3pp. 14270-348 24X Fiche: 50-135, 82/08/03, 8208090257.
- 8208100320 Forwards comments on NRC draft safety evaluation of SEP Topic VI-10 A re testing of reactor trip sys & E6F, including response time Existing programs for instrument & control testing adequate VINCENT, R A Consumers Power Co 82/08/05 CRUTCHFIELD, D Operating Reactors Branch 5 16pp 14297 111 24X Fiche 50-155, 82/08/05, 8208100320
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements by 11st and EISENHUT.D 0 Division of Licensing 82/08/09 Consolidated Edison Co. of New York ip 14356 332 24X Fichs 50-000,82/08/09,8208090194
- B208170259 Forwards "Responses to BNL Questions on Release & Consequence Analysis Reported in Big Rock Foint Probabilistic Risk Assessment "Results of addl analyses rehydrogen generation & base mat penetration failure encl VANDEWALLE, D. J. Consumers Power Co. 82/08/10 CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 14367-045 24X Fiche: 50-155, 82/08/10, 8208170259
- --8208170261 "Responses to BNL Questions on Release & Consequence Analysis Reported in Dig Rock Point Probabilistic Risk Assessment " # Wood-Leaver & Associates, Inc. # Fauske & Associates, Inc. HLA-1-R-82-05 82/07/29 33pp 14367 047 24X Fiche 50-155,82/08/10,8208170259

- 8208170001 Forwards EG&O, ID final technical evaluation of SEP Topic V-(1 A re requirements for isolation of high & low pressure sys & NRC final safety evaluation Core spray sys local control station should be modified CRUTCHFIELD. D Operating Reactors Branch 5 92/08/12 VANDEMALLE, D. J Consumers Power Ca Jpp 14361 214 24X Fichs. 50-195, 82/08/12, 8208170001
- --B208170003 "SEP. Topic V-II A.Electrical Instrumentation & Control Features for Isolation of High & Low Pressure Bys. Big Rock Point Nuclear Station "

 MAYB. B E. FARMER, F. G. EG&O, Inc. EGO-EA-5931 82/07/31

 BCHOLL, R F. Division of Licensing 10pp 14361:217, 24X
 Fiche 50-159, 82/08/12, 820817001.
- 6208170198 Forwards safety evaluation of util responses to SEP Topic III-4.D, "Site Proximity Hissiles (Including Aircraft)" Potential site proximity missiles do not pose significant hazard to safe operation of plant GRUTCHFIELD.D Operating Reactors Branch 5 82/08/12 VANDEMALLE.D.J. J. Consumers Power Co 10pp 14366 258 24% Fiche 50-155.82/08/12,8208170198
- 8208170264 Forwards Chapter 5 & portions of App IV to probabilistic risk assessment re containment integrity Licenses 820720 itr containing revisions to isolation failure colculations sucl.

 QALLO, J. Isham, Lincoln & Beale GALLO, J. Consumers Power Co. 82/08/13 BLOCH, P. B. PARIS, O. H., SHON, F. J. Atomic Bafety and Licensing Board Panel 100pp 14367 139 24X Fiche 50-155, 82/08/13,8208170264
- 8208200278 Notification of 820831 meeting w/util in Bethesde.MD to discuss SEP seismic program EMCH.R Operating Reactors Branch 5 82/08/18 CRUTCHFIELD.D Operating Reactors Branch 5 4pp. 14399 001 24X Fiche:50-135,82/08/18
- 8208230006 Notification of 820824 meeting w/util in Bethesda.MD to discuss SEP seismic program for facility EMCH/R. Operating Reactors Branch 5 82/08/19 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 14517 227 24X Fiche:50-155.82/08/19.8208230006
- 8208230077 Summary of 820818 meeting w/util & NUS Corp in Gaithersburg, MD re spent fuel pool expansion Attendance list & agenda enci enci EMCH/R Operating Reactors Branch 5 82/08/19 CRUTCHFILED, D Operating Reactors Branch 5 2pp. 14514:361 24X Fiche:80-185.82/08/19,8208230077
- 8208240324 Requests relief from 10CFR50 App J.Type C testing requirements for containment pressure instrument lines at penetrations H-89, H-90, H-94, H-98 & H-99 Updated SER App J review which incorporates request for exemption requested BORDINE.T C. Consumers Power Co. 82/08/19. CRUTCHFIELD.D Operating Reactors Branch 5. 2pp 14520 288 24X Fiche.50-155, 82/08/19.8206240324.
- 8208240327 Requests extension until 930215 for response to NRC 820713 itr re facility unresplied safety issues Extension is in agreement w/current schedule for issuance of integrated assessment rept.

 VANDEWALLE, D. J. Consumers Power Co. 82/08/19 CRUTCHFIELD, D. Operating Reactors Branch S. 19 14520-224. 24X Fichs. 30-155, 82/08/19, 8208240327
- 8208240442 Forwards EGAQ final technical evaluation rapt & NRC safety evaluation on SEP Topic VI-7.A 3; "EGC8 Actuation Sys "Plant satisfies review criteria Review complete CRUTCHFIELD.D. Operating Reactors Branch 5 82/08/20 VANDEWALLE.D J. Consumers Power Co 3pp 14826 301 24X Fiche.80-135,82/08/20,8208240442
- --8208240445 "BEF Topic VI-7 A G.ECCS Actuation Bys.Big Rock Point," final technical evaluation rept VANDERBECK, R. EG&O, Inc Fik A-6425 EGG-EA-5961, 82/07/31 BCHOLL, R.F. Divisian of Licensing, 12pp 14526 304 24X Fiche 50-155,82/08/20.8208240442
- 8208250109 Notification of 820826 meeting w/util & Whiting Corp in Harvey. It to discuss methodology for seismic qualification of facility semi-gantry crans
 EMCH.R. Operating Resettors Branch 5 82/08/24, CRUTCHFIELD.D Operating Reactors Branch 5. App 14540 360 24X Fiche: 30-135, 82/08/24, 8208250109,

- @ Inspection reports. IE Bulletins & correspondence
- B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list anc!
 JORDAN EL Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000
- 8204210395 IE Info Notice 81-26. Part 3. Buppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Syx list entl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19, Michigan, Univ of 112pp 14358 001 24% Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Foilures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list and I JORDAN, E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche \$0-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list enc! CD8B.L.! Division of Fuel Facilities, Materials & Safeguards 62/07/20 Consolidated Edison Co of New York 7ipp 14337 276 24X Fichs 50-000,82/07/20,8204210397
- 8208050462 Forwards IE Insp Rept 50-185/82-11 on 820628-0701 No noncompliance noted MILLER, JR Division of Engineering & Technical Programs 82/07/21 DEWITY.R B Consumers Power Cp 2pp 14216, 325 24x Fiche 50-155, 82/07/21, 8208050462
- --8208050478 IE Insp Rept 50-155/82-11 on 820628-0701 No noncompliance noted Major areas inspected radiation protection ectivities, effluent control instrumentation, testing of air cleaning sys, reactor coolant water quality & license audits LOVENDALE, P. C., GREGER/L.R. Region 3, Office of Director 82/07/19 6pp 14216 327, 24X Fiche 50-155, 82/07/21, 8208050462
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Evc list encl URDAN.E.L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 9204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JURDAN, E.L. Davision of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Ficher 50-000, 82/07/23, 8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PURs " Svc list encl. JURDAN.E.L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120, 24X Fiche, 50-000, 82/07/23, 8204210402.
- 8204210403 IE Info Notice 82-90, "Loss of Thermal Sleeves in RCB Piping at Certain Hestinghouse PWR Power Plants" Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013, 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Eve list enci. JORDANIE L. Division of Engineering & Quality Assurance, 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000.82/07/28.8204210405
- 8208050366 Forwards revised Page 2 to 801223 response to IE Bulletin 80-24. "Frevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Eventi " VANDEWALLE, D J. Consumers Power Co 82/07/28 KEPPLER, J. 9 Region 3. Office of Director 2pp 14209 151 24X Fiche, 50-155, 82/07/28. 8208050366
- 8208100204 Ack receipt of 820801 & 0701 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/82-04. Ltrs unresponsive to NRC concerns Meeting requested to discuss corrective actions NRELIUS, C.E. Division of Engineering & Technical Programs 82/08/04. DEMITTER B. Consumers Power Co. 2pp. 14274-264 24X Fiche: 30-155, 82/08/04, 8208100204.
- --820B100212 Responds to NRC B20421 ltr re violations noted in IE Insp Rept 50-155/82-04 Corrective actions training session on posting high radiation areas conducted & all visitors & contractors will be instructed in radiation protection VANDEMALLE, D. J. Consumers Power Co. B2/06/01 KEPPLER, J. Q. Resion 3. Office of Director. App. 14294.266. 24X Fiche, 50-155, B2/08/04, B208100204

- --8208100217 Responds to NRC 820615 telcon re violations noted in IE Insp Rept 50-155/82-04 Corrective actions training progrem will be implemented for all radiation workers Basic course will start in Sept 1982 VANDEWALLE, D. J. Consumers Power Co. 82/07/01 KEPPLER, J. G. Region 3, Office of Director. 3pp. 14294 272 24X Fiche 50-155,82/08/04,8208100204
- 8204210407 IE Info Notice 82~27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN.C L Division of Engineering & Quality Assurance 62/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 820B180104 Forwards rationals for request for relief from internal visual insp of reactor cleanup pump internal welds & reactor circulation pump casing welds Relief request will be submitted as addenda to util 820B03 ltr
 VANDEWALLE, D J Consumers Power Co 82/08/ii CRUTCHFIELD. D Operating Reactors Branch S 18pp 14378 168 24X Fiche 50-155, 82/08/ii, 8208180104
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270029 Forwards "Big Rock Point Plant Annual Operating
 Rept-Occupational Exposure for CYB1 "
 BURDINE, T C Consumers Power Co 82/03/01 KEPPLER, J G Region
 3. Office of Director 1p 14680 004 24X Fichs 50-000,82/07/13,8208270010
- --8208270035 "Big Rock Point Plant Annual Operating Rept-Occupational Exposura for CY81" * Consumers Fourer Co \$2/03/01 9pp 14680 005 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whols Body Dose At Licensed Nuclear Power Facilities for CY81" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000.82/07/13.8208270010
- --8208270531 Forwards "Annual Exposure Rengt Rept,1981," per 10CFR20.407
 W/o License 21-08606-01 rept
 VANDEWALLE, D J Consumers Power Co 82/03/27 Office of
 Management and Program Analysis 1p 14480 064 24X
 Fiche 50-000,82/07/13,8208270010
- --8208270537 "Annual Exposure Range Rept, 1981 "
 # Consumers Power Co 82/03/29 ip. 14680 045 24X
 Fiche 50-000,82/07/13,8208270010
- S Reportable occurrences, LERs & related correspondence
- 8208090268 Forwards LER 82-022/03L-0 VANDEWALLE,D J Consumers Power Co 82/07/30 KEPPLER,J. 0 Region 3, Office of Director 1p 14270 316 24X Fiche 50-155,82/07/30. 8208090268
- --B208090273 LER 82-022/03L-0 on 820702 during post-implementation review of recent facility change, one pair of flanges in 8-inch fire sys piping did not meet facing requirements Caused by engineer error, to be corrected at outage # Consumers Fower Co 82/07/30 Region 3, Office of Director, ip 14270 318 24X Fiche 50-155,82/07/30,8208090268
- 8208130278 Forwards LER 82-021/03L-0 BORDINE T C Consumers Power Ca 82/08/05 KEPPLER, J Q Region 3, Office of Director ip 14333 061 24X Ficha 50-155, 82/08/05, 8208130278
- ---9208130279 LER 82-021/03L-0 on 820707.both open & closed position indication lights remained on when backup core spray valve MO7071 returned to normal closed position Caused by misalighed open position switch Switch adjusted.

 * Consumers Power Co 82/08/05 Region 3, Office of Director ip 14333 062 24% Fiche 80-155.82/08/05,8208130278
- 8208300282 Forwards LER 82-023/03L-0 BORDINE,T C Consumers Power Co 82/08/19 KEPPLER,J Q Region 3, Office of Director ip 14599 281, 24X Fiche 50-155,82/08/19, 8208300282

- --8208300288 LER 82-023/03L-0 on 820801, back-up core spray valve M07071 opening stroke found one-half of normal full stroke, but adequate for core cooling requirements Cause Unknown 81ip clutch in positioning mechanism adjusted.

 ** Consumers Power Co 82/08/19 Region 3, Office of Director.
 1p 14597 282 24X Fiche 50-155,82/08/19,8208300282
- DOCKET 50-154 UNIV OF WISCONSIN RESEARCH REACTOR

 R Periodic operating reports & related correspondence
- 8208030484 Forwards Annual Operations Rept for FY81-82 CASHMELL.R J Wisconsin. Univ of Madison 82/07/27 MILLEH.J R Standardization & Special Projects Branch ip 14154 068 24X Fiche 50-156.82/07/27.8208030484
- --8208030488 Annual Operating Rept for FY81-82 CASHMELL.R J Wisconsin, Univ of, Madison 82/07/27 14pp 14154:069 24X Ficha 50-156.82/07/27.8208030484,
- DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8204210379 IE Info Notice 81-26.Part S. Suppl i, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN,E.L Division of Engineering & Guality Assurance 82/07/19 Hichigan
- DOCKET 50-160 QEORGIA INST OF TECH RESEARCH REACTOR
 Q Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" 8vc list encl JORDAN, E L Division of Engineering & Guality Assurance 62/07/19 Hichigan, Univ of 112pp 14358:001 24X Fiche 50-000.82/07/19, 8204210395
- DOCKET 50-163 GENERAL ATOMIC COMPANY
- Q Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Inpo Notice 81-26.Part 3. Suppl 1. "Clarification of Placement of Personnel Honitoring Devices for External Radiation " Svc list encl JCRDAN.E L Division of Engineering & Quality Assurance 82/07/19 Hichigan. Univ. of 112pp 14358 001 24X Pichs 50-000.82/07/19, 8204210395
- DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR
- R Periodic operating reports & related correspondence
- 8208020138 Submits annual operating rept for Jul 1981-June 1982 BELCHER.R L Maryland Univ of 82/07/27 TEDESCO,R L NRC - No Dytailed Affiliation Olven Spp 14142 032 24X Fiche 50-166,82/07/27,8208020138
- DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER
- O Adjudicatory correspondence
- 8208060119 Bupplementary response to first set of interrogatories Related correspondence ENTHIBLE,E B Citizens for Nuclear Reactor Safety, Inc 82/08/02, Armed Forces Rediobiological Research Institute 29pp 14238 288 24X Fiche 50-170,82/08/02,8208060119
- 8208060132 Motion for leave to suppl responses to listed Armed Forces Radiobiology Research Inst interrogatories Expert witness unable to complete response due to illness Certificate of Svc encl Related correspondence ENTHISLE, B. B. MACKLIN.L. Citizens for Nuclear Reactor Safety, Inc. MACKLIN.L. Institute for Public Representation. 82/08/02 Atomic Bafety and Licensing Board Penel Spp 14241 277. 24% Fiche 50-170.82/08/02.8208060132

- 8208170281 Informs that no response to Citizens for Nuclear Reactor Bafety 820802 motion for leave to suppl further interrogatory responses will be submitted Motion involves discovery matter between Citizens & licenses BACHMANN.R 0 Hearing Branch 1 82/08/16 HOYT.H , SCHINK, D R , HILL, E Atomic 8afety and Licensing Board Panel 1p 14367 OBO 24X Fiche 50-170.82/08/16.8208170281
- 8208240194 Response opposing Citizens for Nuclear Reactor Safety 820802 supplementary response to licensee first set of interrogatories Draft order & Certificate of Svc encl BRITTIGAN: R L. Armed Forces Rediobiological Research Institute 82/08/17 10pp 14521,251 24X Fiche 50-170,82/08/17,8208240194

a Inspection reports, IE Bulletins & correspondence

- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc liet encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 182pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1
 P Operating license stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submitted of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Byo list and EIBENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York. Ip 14354 332 24X Ficher 50-000, 82/08/09, 820890194

Q Inspection reports. IE Bullatins & correspondence

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakags." Bvc list encl JORDAN.E.L. Division of Engineering & Guality Assurance, 62/07/16 Consolidated Edison Co. of New York 87pp 14356.274 24X Fiche 30-000,82/07/16,8204210393
- 820421039A IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN & L Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co. of New York 112pp 14381-001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Hater Leaking From U Hexafluoride Overpacks " Syc list encl COBP,L I Division of Fuel Facilities, Materials & Bafeguards. 82/07/20 Consolidated Edison Co. of New York 71pp 14357.274 24X Fiche 50-000.82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures," Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York, 112pp, 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-29, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCB," Bvc list encl.

 JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York 122pp. 14380,115 24X Fiche.50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Bupport Pin Failures at Westinghouse PWRs." Svc list encl. JORDAN.E.L. Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 127pp 14174-120, 24X Fiche: 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Byc list encl JORDAN.E.L. Division of Engineering & Quality Assurance. 82/07/26 Concelidated Edison Co of New York 121pp 14357 013, 24X Fiche. 50-000, 82/07/26, 8204210403.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Bhorage Pool," Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/28
 Consolidated Edison Co. of New York, 122pp. 14357 146 24X
 Fiche 50-000, 82/07/28, 8204210405.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement," 8vc list encl.
 JORDAN,E.L. Division of Engineering & Quality Assurance. 82/08/05
 Consolidated Edison Co. of New York. 117pp. 14388 201 24X
 Fiche. 50-000, 82/08/05, 8204210407

- DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 8208240401 Provides add1 info for Change 1 to Tech Specs re reactivity limits, as requested in 820524 Itr STANSBERRY, 6. R Purdue Univ 82/08/16 Standardization & Special Projects Branch 1p 14822 293 24X Fiche 50-182,82/08/16,8208240401
- @ Inspection reports, IE Bulletins & correspondence
- 8204210398 IE Info Notice 81-26, Part 3, Buppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/19 Hichigan
- BOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 8204210395 IE info Notice Bi-26.Part 3.Suppl 1. "Clarification of Placement of Personnel Monituring Devices for External Radiation " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Hichigan. Univ of. 112pp 14358 001 24X Fichs 50-000.82/07/19, 8204210395
- DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 8208310369 Forwards "Reactor Operations Annual Rept, Jul 1981-June 1982 " MCKIBBEN, J C Missouri, Univ of, Columbia 82/08/27 Division of Licensing ip 14693 291 24% Ficha 50-186,82/08/27,8208310369
- --8208310385 Std operating procedures * Missouri, Univ of: Columbia 81/10/31 275pp 14494 010 24X Fichs 50-186,82/08/27,8208310369
- R Periodic operating reports & related correspondence
- 9208310369 Forwards "Reactor Operations Annual Rept, Jul 1981-June 1982" MCKIBBEN, J C Missouri, Univ of, Columbia 82/08/27 Division of Licensing Ip. 14693 291. 24X Fiche 50-186, 82/08/27, 8208310369
- --8208310377 "Reactor Operations Annual Rept. Jul 1981-June 1982 "
 MCKIBBEN. J C , ALOER. D M Missouri, Univ of, Columbia 82/08/31
 52pp 14693, 292 24X Fiche 50-186, 82/08/27, 8208310369.
- ~-8208310385 Std operating procedures * Missouri, Univ of, Columbia 81/10/31 275pp 14694 010. 24X Fiche, 80-184, 82/08/27, 8208310369
- DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR
- d Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnal Monitoring Devices for External Radiation," See list encl
 JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/19
 Michigan: Univ. of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8208160108 Forwards IE Insp Rept 50-187/82-01 on 820628-30 & notice of violation STERNBERG,D M, Division of Resident, Reactor Project & Engineering Programs 82/07/27 CRANDALL,W E Northrop Research & Technical Genter, 2pp 14345 171, 24X Fiche 50-187,82/07/27,8208160108
- --8208160111 Notice of violation from insp on 820628-30 YOUNG, T Division of Resident, Reactor Project & Engineering Programs. 82/07/27 4pp 14345 173 24X Fiche 50-187,82/07/27, 8208160108.

--8208160115 IE Insp Rept 50-187/82-01 on 820628-30 Noncomptiance noted: absence of qualified health physicist at reactor safety subcommittee quarterly meeting HILLETT, D. J., YOUNO, T Division of Resident, Reactor Project & Engineering Programs 82/07/16 6pp 14345 177 24% Fiche 50-187,82/07/27,8208160108

OCCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

B204210395 IE Info Notice B1-26,Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list entl JORDAN,E L Division of Engineering & Guality Assurance B2/07/19 Hichigan, Univ of 112pp 14359 001 24% Fiche: 50-000.82/07/19, B204210395

DOCKET SO-193 RHODE (BLAND & PROVIDENCE PLANTATIONS AEC
G. Inspection reports, IE Sulletims & correspondence

8204210395 IE Info Notice 81-26, Part 3, Buppl 1. "Clarification of Placement of Personnal Monitoring Devices for External Radiation " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/19, Michigan, Univ of. 112pp 14358, 001 24X Fiche 30-000, 82/07/19, 8204210399

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

Q Inspection reports. IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Soy 11st encl UDRDAN, E.L. Division of Engineering & Guality Assurance 82/07/19. Michigan, Univ. of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

Q. Adjudicatory correspondance

820Bii0i47 Order extending time within which Commission may act to review ALAB-677 until 820917 CHILK, B. J. Office of the Secretary of the Commission 82/08/09, Commissioners 1p. 14314 293. 24X Fiche 50-201.82/08/09, 8208110149

B20B170337 Forwards NRC B2072B ltm acknowledging receipt of encl Sterre Club B20714 ltm re approx 3 dozen drums found in poor condition near site, per Note 2 of ASLB G11231 memorandum & order, Certificate of Syc encl. HOLF, J R Regulations Division G2/08/13, BRENNER, L. HARBOUR, J, MORRIS, P.A., Atomic Sefety and Licensing Board Panel 3pp 14366-342. 24X Ficher 50-201,82/08/13,8208170337

8208300104 Forwards NRC 820823 response to Signra Club request for reconsideration of Change 32, for info & per ABLB 811231 memorandum & order Certificate of Svc encl, WOLF, J.R Regulations Division. 82/08/25 BRENNER, L Atomic 84fety and Licensing Roard Panel 30pp. 14576 080. 24X fiche. 50-201, 82/08/25, 8208300104

P Operating license stage documents & correspondence

8208040401 Expresses concern re approx three dozen drums found near site in poor condition.Listed questions should be appended to Bierre Club 820326 petition re License Change 32 to License CSF-1.

FINALDI, L. Bierre Club 82/07/14. CUNNINGHAM, R. Division of Fuel Cycle & Material Safety. App 14224, 323. 24X Ficher 50-201.

82/07/14.8208040401.

8208170337 Forwards NRC 820728 ltm acknowledging receipt of encl Sierra Club 820714 ltm re approx 3 dozen drums found in poor condition near site, per Note 2 of ASLB 811231 memorandum & order Certificate of Svc encl. HOLF, J. Regulations Division. 82/08/13 BRENNER, L. HARBOUR, J. . HORRIS, P. A. Atomic Safety and Licensing Board Panel. 3pp. 14366-342. 24X Fichs 50-201,82/08/13,8208170337. DOCKET 50-206 BAN ONDERE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8208020376 Responds to 820721 telephone request for status of ingestion none planning by State of CA State has retained consultants to do planning Plan will be submitted to FEMA in late Sept 1982
KRIMM.R.W Federal Emergency Management Agency 82/07/28
ORIMES.B Division of Emergency Preparedness 19 14150 118. 24X Fiche 50-206. 82/07/28. 8208020376

8208190180 Discusses status of ingestion pathway planning in CA Final evaluation re capability of involved jurisdictions to implement ingestion pathway plans must avait still expected in late Aug/early Sept 1982
KRIMMAR W Federal Emergency Management Agency 82/08/05
GRIMERS BK Division of Emergency Preparedness 4pp 14386.353
24x Fiche 50-206.82/08/05.8208190180

8208170170 Requests current version of full-size engineering drawings of facility layout & sys to review effectiveness of NRC safeguards regulations & validate vital area designations Drawing list encl.
CRUTCHFIELD,D Operating Reactors Branch 5, 82/08/ii DIETCH.R.
Bouthern California Edison Co. 3pp. 14366 236 24X
Fiche: 50-206, 82/08/ii, 8208170170

8208270696 Responds to 820630 ltr re changes to facility physical security plan.Revision 5 NRC concurs w/changes except provisions in Section 1.3 1.4 re protected & vital areas CRUICHFIELD.D. Operating Reactors Branch 5 82/08/17 BASKIN.K.P. Southern California Edison Co 3pp 14683 051 24X Fiche 50-206,82/08/17,8208270696

8208230023 Forwards Revision 6 to Mar 1981 physical security plan Revision withheld (ref 10CFR73 21) BABKIN,K P Bouthern California Edison Co B2/08/18. EISENHUT, D Q. Division of Licensing ip 14517 227 24X Fiche 50-206, 82/08/18, R208230023

O Adjudicatory correspondence

8208050482 Supplemental requests for exemption from listed fire protection rule implementation schedule & request for reconsideration of exemption decision to allow safe shutdown measures implementation w/coordination of SEP PIOOTT, D.R. Bouthern California Edison Co. PIOOTT, D.R. Drrick. Herrington & Butcliffe 82/08/03 Commissioners 34pp. 14214 167 24X Fichs 50-206.82/08/03,8208050482

--B2080504B7 Affidavit of KP Baskin supporting supplemental request for exemption & reconsideration re fire protection rule implementation BASKIN:K P Southern California Edison Co. B2/08/02 10pp 14214-200 24% Fische-50-206.82/08/03,8208030482

8208170167 Ltr to CA residents who patitioned NRC to suspend or revoke QL for facility. Order confirming licensee coamitments on seismic upgrading encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/08/11 Affiliation Unknown 5pp. 14366 241 24X
Fiche: 50-206, 82/08/11, 8208170167

P Operating license stage documents & correspondence

8207140515 Advises that Class III fee owed for 820105 application for approval of Tech Spec changes to increase allowable phosphate discharge limit Review involves consideration of single environ issue HILLER, W O. License Fee Hanagement Branch 82/07/01. DIETCH, R. Bouthern California Edison Co. ip 13848.359 24% Fiche.50-204,82/07/01,8207140515

8207080064 Generic ltr to all licenses of operating plants, applicants for DL & holders of CP re Commission approved charter for CRGR 8vc list encl.
DIRCKS: N J Diffice of the Executive Director for Operations.
82/07/02 Consolidated Edison Co. of New York. 93pp. 14194:001.
24X Fiche.50-000,82/07/02,8207080064

8208020214 Forwards results of verification testing of electric distribution sys voltages conducted per NRC 820224 ltr. Results demonstrate adequacy of sys. Calculational procedures also verified.

BABKIN.K.P. Bouthern California Edison Co. 82/07/15
CRUTCHFIELD.D. Operating Reactors Branch 5. 15pp. 14141:044. Fiche: 50-204. 82/07/15, 8208020214.

- 8208050474 Forwards 32 oversize drawings re 8EP Topic IV-2, "Reactivity Control Sys." in response to NRC request Aperture cards are available in PDR
 KRIEGER.R H Bouthern California Edison Co 82/07/23
 CRUICHFIELD.D Operating Reactors Branch 5 2pp 14213 272 24X
 Fiche 30-206.82/07/23.8208050476
- 8208050253 Remits licensing application fee for Amend 103 to OL consisting of Proposed Change 100 to Tech Specs Application not fee exempt since review involves consideration of single nat ree exempt since review involves tonsideration or single environ issue
 BAEKIN-K P Southern California Edison Ca 82/07/27 NILLER, W O
 License Fee Hanagement Branch 2pp 14209 348 24X
 Ficha 30-206.82/07/27,8208050253

- 820B170186 Responds to 820706 request for info on status of unresolved safety issues Util requires until 821015 to provide status due to extensive & time consuming research KRIEQER, R W Southern California Edison Co 62/07/29 CRUTCHFIELD, D Operating Reactors Branch 5 | 19 14364 323 24X Fiche. 50-206, 82/07/29, 8208170186
- 8208060157 Forwards "Control of Heavy Loads," technical evaluation rept CRUTCHFIELD, D Operating Reactors Branch 5 82/08/03 DIETCH, R Southern California Edison Co 2pp 14239 243 24X Fiche 50-206, 82/08/03, 8208060137
- --8208060161 "Control of Heavy Loads," technical evaluation rept VITO, D.J. Franklin Institute/Franklin Research Center, TER-C5257-529 82/07/16 CLEMENSON, F NRC No Datailed Affiliation Given 36pp 14239 245 24K Fiche 50-206,82/08/03, 8208060157
- 8208060214 Informs that pump runout protection on low discharge pressure similar to protection installed on existing pump will be provided for new auxiliary feedwater sys pump BAGKIN, K P Gouthern California Edison Co 82/08/03 CRUICHFIELD, D Operating Reactors Branch 9 19 14241 085 Fiche: 50-206, 82/08/03, 8208060214
- 8208100148 Responds to 760421 request for exemptions from 10CFR50. App J, All exemptions re airlock testing denied Safety evaluation encl Proposed Tech Specs that include pertinent requirements of App J should be submitted within 60 days EISEMHUT.D O. Division of Licensing 82/08/03 DIETCH, R Bouthe California Edison Co 3pp 14298 045 24X Fiche.50-206,82/08/03,8208100148
- --B208100156 Safety evaluation denying util request for exemptions from 10CFR50.App J re airlock testing requirements # Office of Nuclear Reactor Regulation, Director, 62/08/03 2pp 14298 048 24% Fiche 30-206.82/08/03.8208100148
- 820B100077 Advises that util decision between replacing valves & AUSIOUD// Advises that Util decision between replacing valves redesigning alternative for safety injection sys mods has not yet been made Decision on redesign alternative expected by 820913 Procuprement of replacement valves continues KRIEGER.R H Southern California Edison Co 82/08/05 CRUTCHFIELD.D Operating Reactors Branch 5 ip 14296 156 Fiche: 50-206.82/08/05.8208100077
- 8208100088 Resubmits Amend 100 to License DPR-13, consisting of proposed Change 110 to Tech Specs reflecting reorganization of managerial responsibility to maintain organizational requirements of three unit station BASKIN, X P Southern California Edison Co 82/08/05 CRUICHFIELD. D Operating Reactors Branch 5 ip. 14297 237 24X Fichs 30-206, 82/08/05,8208100088
- --8208100093 Proposed Change 110 to Tech Bpecs reflecting reorganization of managerial responsibility to maintain organizational requirements of three unit station

 * Southern California Edison Co 82/08/05 13pp 14297, 238

 24X Fiche: 50-206-82/08/05-8208100088
- 8208100223 Advises that because of further review performance testing 208100223 Advises that because of further review, performance testing of power operated relief & safety valves per TMI Action Item II.D 1 will not be completed until Sept KRIEOER, R W. Southern California Edison Co. 82/08/06, CRUTCHFIELD, D. Depreting Reactors Branch 5 ip 14274 340 24X Fiche: 50-206, 82/08/06, 8208100223
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP tapplicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements to provides alternatives to requirements five list and: EISENHUT.D 0 Division of Licensing 82/08/09. Consolidated Edison Co. of New York 1p. 14356 332 24X Fiche 50-000,82/08/09, 8208090194.

- 8208120108 Forwards response to specific items of interest raised by 20812010B Forwards response to specific leams or interest NRC at 820804 meeting re scismic re-evaluation Summary of ground motion studies also encl BASKIN, K P Southern California Edison Co 82/08/09 CRUTCHFIELD.D Operating Reactors Branch 5 75pp 1431 Fiche 50-206, 82/08/09, 8208120108 14319 045 241
- --8208120iii "Supplemental Analysis of Dispersion of 1975 Oroville & 1979 Imperial Valley Aftershock Data."

 Woodward-Clyde Consultants, Inc 82/08/07 30pp 14319 120 24X Fiche 50-206.82/08/09.8208120108
- 8208200040 Advises that implementation schedule for NUREO-0737. Item III D 3 4. "Control Room Habitability." will be delayed pending completion of 8EP integrated assessment by Apr 1983 BASKIN.K P Southern California Edison Co 82/08/09 CRUTCHFIELD.D Operating Reactors Branch 9 1p 14392 251 24X Fichs 50-206.82/08/09.8208200040
- 8208170143 Forwards order confirming licenses commitments on seismic upgrading upgrading Reactors Branch 5 82/08/11 DIETCH,R Southern California Edison Co 2pp 14366.127 24X Fiche 50-206,82/08/11.8208170143,
- --8208170146 Order confirming licensee commitments on seismic upgrading EISENHUT, D o Division of Licensing 82/08/11 Southern California Edison Co App. 14366, 129 24X Fiche 50-206, 82/08/11, 2001.7048.
- 820B170251 Forwards Amend 61 to License DPR-13, safety evaluation & notice of issuance & availability Amend approves changes to App A Tech Bpacs, incorporating revised Section 6 ii. "Radiation Protection Program" CRUTCHFIELD.D Operating Reactors Brench 5 B2/08/11 DIETCH.R Southern California Edison Co. 2pp 14367 202 24X Fichs, 50-206, 62/08/11, 8208170251
- --8208170256 Amend 61 to License DFR-13, revising App A Tech Specs to incorporate revised Section 6 11. "Radiation Protection Frogram " Tech Spec changes encl CRUTCHFIELD, D Operating Reactors Branch 5 82/08/11. 7pp 14369 204 24X Fiche 50-206, 82/08/11,8208170251
- --B208170262 Bafety evaluation supporting Amend 61 to License DPR-13, * Office of Nuclear Reactor Regulation, Director B2/08/11 2p 14367 211 24X Fiche 50-206, B2/08/11, B208170251
- --8208170265 Notice of issuance & availability of Amend 61 to License DPR-I3 CRUTCHFIELD,D Operating Reactors Branch 5 82/08/11 2pp 14367 213 24X Fishe 50-206,82/08/11.8208170251
- 8208170345 Forwards HR Denton 820805 ltr & Div of Licensing order COSI/U345 Forwards in painton Bayes to maintain shutdown condition until completion of seismic mods & until NRC approval for restart obtained, per B20615 & 24 submittails DENYGN, HR Office of Nuclear Reactor Regulation, Director 82/08/11 NADER, R Center for Progressive Law, 2pp 143 24X Fiche 50-206, 82/08/11, 8208170345 14367 019
- --B208170348 Informs of issuance of enci Div of Licensing order confirming licensee commitment to maintain shutdown condition until completion of seismic mods & until NRC approval for restart obtained per 820615 & 24 submittals DENTON.H R Office of Nuclear Reactor Regulation, Director B2/08/06 NADER:R Center for Progressive Law 3pp 143.24X Fiche 50-206.82/08/11.8208170345 14367, 021
- outained EISENNUT, D Q Division of Licensing 82/08/11. Southern California Edison Co App 14367.024 24X Fiche 50-206,82/08/11, 8208170345
- 8208240237 Forwards application for Amend 108 to License DPR-13, proposing Tech Spec Change 113 to revise Table 4 1 2 re min equipment check & sampling frequency Amend fee encl DIETCH, R Southern California Edison Co 82/08/11. DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 14527 045 24X Fiche 50-206, 82/08/11, 8208240257
- --8208240259 Application for Amend 108 to License DPR-13, proposing Tech Spec Change 113 to revise Table 4 1,2 re min equipment check & sampling frequency. Description of proposed change & safety analysis encl
 DIETCH/R Southern California Edison Co COTTON/O D San Diego
 Oas & Electric Co 82/08/10. Spp. 14527 066, 24X
 Fiche 50-206/82/08/11,8208240257

- --B208240264 Proposed Tech Spec Table 4 1 2 re min equipment check & sampling frequency Certificate of Svc encl * Bouthern California Edison Co 82/08/10 3pp 14527 074 24X Fiche 50-204.82/08/11.8208240257
- 8208160101 Advises that response to NUREQ-0737. Action Item II B 3, "Post-Accident Gampling," will be provided by 821101 BABKIN.K P Bouthern California Edison Co 62/08/12 CRUTCHFIELD, D Operating Reactors Branch 5 2pp. 14345 153 24X Fiche 50-206.82/08/12.8208160101
- 8208170005 Informs that SEP Topic VI-6 re containment leak testing, considered complets Topic covered in NRC 820803 safety evaluation re extent of compliance w/App J to 10CFR50 & exemption requests PAULBON, W Operating Reactors Branch 5 82/08/12 DIETCH, R Southern California Edison Co 2pp 14361 212 24X Fiche 50-206, 82/08/12, 8208170005
- 8208270684 Forwards case study rept containing detailed description, findings, conclusions & recommendations re 800310 loss of sait water cooling event.
 MICHELBON, C Director's Office 82/08/12 DENTON, H R Office of Nuclear Reactor Regulation, Director DEYOUNG, R C Director's Office of Price of Inspection and Enforcement MINOGUE, R B Office of Nuclear Regulatory Research, Director Spp 14683'072 24X Fiche 30-204,82/08/12,8208270684
- --B20B2706BB Forwards case study rept containing detailed description, findings, conclusions & recommendations re 800310 loss of salt water cooling event MICHELSON, C Director's Office 82/08/12 WILKENSON, E P Institute of Nuclear Fower Operations. 2pp. 146B3 075 24X Fiche 50-206, 82/08/12, 82082706B4
- --8208270591 Forwards case study rept containing detailed description, findings, conclusions & recommendations re 800310 loss of salt water cooling svent.

 MICHELSON, C Director's Office 82/08/12, ROSSIN, D Nuclear Safety Analysis Canter 2pp 14683,077, 24X
 Fiche 50-204,82/08/12,8208270684.
- --8208270695 Forwards case study rept containing detailed description, findings, conclusions & recommendations re 800310 loss of salt water cooling event MICHELBON. C. Director's Office 82/08/12 RAY, H B Southern California Edison Co 2pp. 14683 079 24X Fiche 50-206,82/08/12,8208270684
- --8208270497 "San Onofre Unit 1 Loss of Balt Water Cooling Event on 800310 " GRNBTEIN: H L Director's Office 82/07/31 58pp. 14483 081 24% Fiche 50-204: 82/08/12:8208270484
- 820BiB01i3 Forwards "Beismic Safetų Margins re 84th Fercentile Instrumental Spectrum." Previous analyses will not be impacted by exceedences of up to 10% over specified ranges Response spectra of 0 67 g Housner will be used BABKIN.K P Southern California Edison Co 82/08/16 CRUTCHFIELD.D Operating Reactors Branch 5 48pp 14379 195 24x Fiche 50-206: 82/08/16, 8208180113.
- 8208260390 Forwards "San Onofre Unit i Loss of Salt Water Cooling Event on 800310." DIRCKS.W.J. Office of the Executive Director for Operations 82/08/16. PALLADIND.N., GILINSKY,V., AHEARNE.J Commissioners 14569'149 24X Fiche.50-206.82/08/16.8208260390
- --9208260403 "Ban Onofre Unit 1 Loss of Balt Water Cooling Event on 800310 " GRNSTEIN,H L Director's Office. 82/07/31 58pp 14569,150, 24% Fiche 50-204,82/08/16,8208260370
- 8208190114 Forwards add1 comments on draft review of operating experience submitted by NRC 820512 itr.Comments suppl 620714 submitted & complete response.

 BABKIN,K P Southern California Edison Co 62/08/17 CRUTCHFIELD,D. Operating Reactors Branch 5. 7pp 14383 129, 24X Fiche.30-206,82/08/17.8208190114.
- 8208190145 Forwards "Electric Raceway Bupports, Seismic Re-evaluation Criteria," providing description of seismic re-evaluation of cable tray & conduit support BABKIN, K P Bouthern California Edison Co 82/08/17, CRUTCHFIELD, D. Operating Reactors Branch 5 ip 14381.099. 24X Fiche. 80-206, 82/08/17, 8208190145.
- --8208190147 "Electric Raceway Supports, Seismic Ra-evaluation Criteria, "
 * Southern California Edison Co. 82/08/13. 21pp. 14381 100.
 24% Fiche: 50-206, 82/08/17, 8208190145

- 8208190203 Forwards "Soil Backfill Conditions" in response to BEP Topic III-6, "Spismic Design Considerations" Structures evaluated are not affected by in-situ soil conditions Fuel storage bldg evaluation will be provided by 821001

 BASKIN.K P Southern California Edison Co 82/08/17

 CRUICHFIELD, D Operating Reactors Branch 5 2pp 14387 351 24X

 Fiche 50-206.82/08/17.8208190205
- --8208190208 "Boil Backfill Conditions " * Southern California Edison Co 82/08/12 200pp 14387 353 24X Fiche 50-206,82/08/17,8208190205
- 8208200192 Confirms intentions re NRC 820726 re-evaluation guidelines for seismic criteria.per 820728-30 discussion Seismic anchor displacements due to OBE & machanical equipment internals will not be evaluated for seismic re-evaluation program.

 BASKIN.K P Southern California Edison Co 82/08/17 CRUTCHFIELD, D Operating Reactors Branch 5 ip 14500 137 24X Fiche 50-206.82/08/17.8208200192
- 8208250167 Provides add1 info to 820310 ltr re beto rediction assessment & environ qualification of electrical equipment Exposed cables are only equipment inside containment which do not have metal encis.

 BABKIN.K P Bouthern California Edison Co 82/08/23.
 CRUTCHFIELD, D Operating Reactors Branch 5 lp 14540 277 24X Fiche: 50-206: 82/08/23. 8208250167
- 8208310251 Forwards Amend 62 to License DPR-13, safety evaluation & FR notice of issuance & availability Amend approves changes to App A Tech Specs incorporating mods to testing interval for safety injection sys hydraulic valve testing CRUTCHFIELD, D Operating Reactors Branch 5 82/08/25 DIETCH, R Southern California Edison Co 2pp 14688 172 24X Fiche 50-206,82/08/25,8208310251
- --8208310254 Amend 62 to License DPR-13, revising App A Tech Specs to incorporate mode to testing interval for safety injection sys hydraulic valve testing Revised Tech Specs encl CRUTCHFIELD, D Operating Reactors Branch 5 82/08/25 4pp 14688 174 24% Fiche 50-206, 82/08/25, 8208310251
- --8208310257 Baf#ty evaluation supporting Amend 62 to License DPR-13
 * Office of Nuclear Reactor Regulation, Director 82/08/25 2pp
 14688 178 24X Fiche 50-206/82/08/25,8208310251
- --8208310262 Notice of issuance & availability of Amend 62 to License DPR-13 CRUTCHFIELD, D. Operating Reactor's Branch 5 82/08/25, 2pp 14688 180 24X Fiche 50-206,82/08/25,9208310251
- 8208300234 Responds to open items of 8EP Topic III-6, "Seismic Design Considerations" Eight oversize drawings encl Aperture cards are available in PDR BABKIN.K P Southern California Edison Co. 82/08/26 CRUTCHFIELD.D Operating Reactors Branch 5 95pp 14673 012, 24X Fiche 50-206.82/08/26.8208300234
- --8208300271 "FFTF Rept Drilled-In Expansion Bolts Under Static & Alternating Load "
 LIN.M S Dechtel Corp BR-5853-C-4. 75/01/16 90pp 14673:108
 24X Fichs 50-206.82/08/26.8208300234
- 8208310013 Notification of 820908 meeting w/util in Bathasda.MD to discuss approach to resolve safety injection sys valve issue PAULSUN, H A Operating Reactors Branch 5 82/08/26, CRUYCHFIELD, D. Operating Reactors Branch 5 3pp 14689, 287, 24X Fiche 50-206.82/08/26.8208310013
- 8208310233 Notification of B20909 meeting w/util in Bethesda,MD to discuss licensee structural analysis of steam generator urapper support & address concerns re-potential wear of steam generator tubes

 PAULSON.H A Operating Reactors Branch 5 82/08/26 CRUTCHFIELD.D. Operating Reactors Branch 5 3pp 14695 112 24X Fiche 50-206.82/08/26.8208310233
- G Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage." Syc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/07/16,
 Consolidated Edison Co of New York 87pp 14356 274, 24X
 Fiche 50-000,82/07/16,8204210393

- 8208160288 Submits addl response to NRC 800815 ltr re violations noted in IE Health Physics Appraisal Insp Rept 30-206/80-17 Corrective actions interim health physics facility made operational in Fab 1982 RAY. H B Southern California Edison Co 82/07/16 ENGELKEN, R H Repion 5, 04fice of Director 3pp 14346 268 24% Fiche 30-206, 82/07/16, 8208160288
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Syc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ. of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395
- B204210396 IE Info Notice B2-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list and Upon Upon Jordan, E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp. 14381,001 24X Fiche:50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl. CO88: L I. Division of Fuel Facilities, Haterials & Safeguards, 82/07/20, Consolidated Edison Co of New York 71pp 14357 27, 24X Fiche 50-000: 82/07/20: 8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures," Svc list encl URDAN.E. L. Division of Engineering & Quality Assurance 62/07/22 Consolidated Edison Co of New York, 112pp 14194 321 24X Fiche:50-000, 82/07/22, 8204210398,
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Bvc list enc! JGRDAN.E.L. Division of Engineering & Quality Assurance 82/07/23. Consolidated Edison Co. of New York 122pp 14380.115 24X Fiche.50-000,82/07/23.8204210401
- B204210402 IE Info Notice B2-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Mestinghouse PMRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co. of New York 127pp 14174-120 24X Fiche: 50-000, B2/07/23, B204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Hestinghouse PHR Power Plants " Svc list encl JCRDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 12ipp 14357 013, 24X Fiche: 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Hork in Fuel Storage Pool " Syc list encl. JORDAN,E L. Division of Engineering & Quality Assurence 82/07/28, Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche: 50-000, 82/07/28, 8204210405.
- 8208060214 Informs that pump runout protection on low discharge pressure similar to protection installed on existing pump will be provided for new auxiliary feedwater sus pump. BASKINK.P. Southern California Edison Cd 82/08/03. CRUTCHFIELD.D Operating Reactors Branch 3 ip 14241.085 24X Fiche: 50-204.82/08/03.8208060214.
- 104210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Nater-Jet Impingement." Bvc list encl JCRDAN,E L. Division of Engineering & Quality Assurance 82/08/05. Consolidated Edison Co of New York. 117pp 14388,201. 24X "iche: 50-000,82/08/05,8204210407
 - 3230368 Advises of delay until 821001 to comply w/Action Item 5 in E SUlletin 82-02. "Degradation of Threaded Fasteners in 2PB of PRR Plants."

 AVMES./ J. Bouthern California Edison Co. 82/08/05 ENGELKEN.R.H. tepion 5. Office of Director. ip 14512: 354. 24X (che. 30-204, 82/08/05, 8208230368.
 - 160113 EN-82-019A on B20811, order imposing civil penalties in sunt of 660,000 will be issued for violations re-positive :ess control to vital areas associated w/implementation physical security plan.

 SANO.R. LIEBERMAN.J. Director's Office, Office of Inspection and forcement. 82/08/11. ip. 14343:170 24X Fiche, 50-206, 82/08/11, 98(A0113)
 - (30042 Forwards notarized version of response to IE Bulletins 61-03 ii-03 rs flow blockage of cooling water to safety sys by sicula 8p & Mytilus 8p. respectively.

 NEB, J. 9. Bouthern California Edison Co. 82/08/12. ENGELKEN, R H. sion 5. Office of Director. 2pp. 14517-251. 24X he: 50-206, 82/08/12, 8208230042.

- --B208230047 Responds to IE Bulletins 81-01 & 91-03 re flow blockage of cooling water to safety sys by Corbicula Sp & Mytilus Sp. respectively HAYNES.J Q Bouthern Celifornia Edison Co 82/08/12 ENOSELKEN.R H Region 5. Office of Director 7pp 14517 253 24x Fiche 50-206.82/08/12.8208230042
- 8208230076 Resubmits 820209 & 810604 responses to IE Bullstins 81-01 & Bi-03 re mechanical snubbers, to include required affirmation HAYNES, J G Southern California Edison Co GR/OB/12 ENGELKEN, R H Region 5, Office of Director Rpp 14517 151 24X Fiche 50-206, 82/0B/12, 8208230076
- --8208230086 Bubmits add1 info to 810227 & 0421 responses to IE Bulletin 81-01 re mechanical snubbers, Summary of installed mechanical snubbers on safety-related sys encl HAYNEB, J O Southern California Edison Co 82/08/12 ENGELKEN, R H Region 5, Defice of Director 3pp 14517 153 24X Fichs 50-206,82/08/12,8208230076
- 8208240197 Ack receipt of \$20806 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-204/82-19
 800K,H E Division of Radiological Safety & Bafeguards Program 82/08/16 PAPA/L T Southern California Edison Co ip 14519 297 24X Fiche 50-206/82/08/18/8208240197
- --8208240203 Responds to NRC B20707 ltr re violations noted in IE Insp Rept 50-206/82-19 Corrective actions caution signs posted in high radiation area & Health Physics Procedure S0123 VII-7 4 re posting implemented on B20624 PAPAV.L T. Bouthern California Edison Co 82/08/06 ENDELKEN.R H Region 5, Office of Director 3pp 14519 298 24X Fiche 50-206,82/08/18,8208240197.
- R Periodic operating reports & related correspondence
- 820B120147 Forwards monthly operating rept for June 1982 RAY, H. B. Southern California Edison Co. 82/07/06, Management Information Branch 1p 14319; 231 24X Fiche 50-206, 82/07/06, 820B120147.
- --B20B120152 Monthly operating rept for June 1982 RAIDY,T Bouthern California Edison Co. B2/07/06 5pp 14319,232 24X Fiche 50-206,82/07/06,820B120147.
- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyxing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A. Critical Mass Energy Project. Spp 14679, 208 24X Fiche 30-000.82/07/13.8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" * NRC - No Detailed Affiliation Given, 82/07/13 48pp 14679,216 24% Fiche.50-000,62/07/13,8208270010.
- --8208270563 Rept of total man rem for 1981 * Southern California Edison Co 82/03/04 1p 14680,032 24X Ficha: 50-000,82/07/13,8208270010
- ---8208270592 "Forwards "Number of Personnel & Man Rem Exposure By Work & Job Function for GY81," per 10CFR20 407
 RAY.H B Southern California Edison Co. 82/03/08 Office of Management and Program Analysis ip 14680.039 24X
 Fichs 50-000.82/07/13.8208270010
- --8208270588 "Number of Personnel & Men Rem Exposure By Work & Job Function for CV81 " * Southern California Edison Co 82/03/08 2pp 14680,040 24X Fichs,50-000,82/07/13,8208270010.
- 8208170250 Forwards monthly operating rept for Jul 1982. RAY,H S. Southern California Edison Co. 82/08/11. Office of Resource Managament, Director. 1p. 14367 039. 24X Piche: 30-206. 82/08/11.8208170250
- --8208170314 Monthly operating rept for Jul 1982 SPEER, M. Gouthern California Edison Co 82/08/13 5pp. 14367:040 24X Fiche 30-206, 82/08/11, 8208170250.
- 8. Reportable occurrences. LERs & related correspondence
- 8208020324 Forwards updated LER 82-011/03X-1, Detailed event analysis submitted RAY:H.B. Bouthern California Edison Co. 82/07/21. ENGELKEN.R H Region 5, Office of Director. 20p. 14151:147 24X Fiche: 50-206:82/07/21:8208020324

DOCKETED ITEMS

- --8208020329 Updated LER 62-0ii/03X-i from 81i215 to 0218, surveillance tests not performed for containment.purge & exhaust isolation & power operated relief valve channels Caused by insufficient communication between depts RAY, H B Southern California Edison Co 82/07/21 Region 5, Office of Director 1p 14151 147 24X Fiche 50-206,82/07/21,8208020324
- 8208120180 Forwards LER 82-017/01X-1 Detailed event analysis encl RAY, H B Southern California Edison Co 82/08/02 ENGELKEN, R H Region 5. Office of Director 3pp 14327 013 24X Fiche 50-206, 82/08/02, 8208120180
- --B20B1201B2 LER B2-017/01X-1 on B20614, south waste gas decay tank depressurized from 25 psig to appox 0 psig during 24-h surveillance period Cause not stated Helium leak test performed by outside contractor RAY,H B Southern California Edison Co 82/0B/02 Region 5, Office of Director 1p 14327 016 24X Fiche 50-206, 82/08/02, 6208120180
- 8208180076 RD 82-013 installation of radiation monitors in release line of reheater pit sump & oily sump not completed due to delays in performing hydrostatic testing of sys piping Completion expected prior to end of outage RAY. H B Southern California Edison Co 82/09/06 ENGELKEN, R H. Region 5. Office of Director 2pp 14376 345 24X Ficha 50-206, 82/08/06, 8208180076
- 8208200231 Forwards LER 82-018/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co 82/08/06 ENGELKEN, R H Region 5. Office of Director 2pp 14399 338 24X Fiche 50-206.82/08/06.820820231
- --8208200242 LER 82-018/03L-0 on 820706, particulate filter tamples taken from main stack in May & Jul 1982 discarded before analysis for Sr-89 & Sr-90 conducted Caused by human error Procedure revised RAV.H B Southern California Edison Co 82/08/06. Region 5, Office of Director 1p 14399 340 24X Fiche 50-206,82/08/06, 8208200231
- 8208300057 Forwards LER 82-019/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co 82/08/17 ENGELKEN, R H. Region 5. Office of Director 2pp 14679 149 24X Fiche 50-206, 82/08/17. 8208300057
- --B20830005B LER 82-019/03L-0 on 820719, effective leakage from circulation loop outside containment found greater than Tech Spec limit Caused by leak in south refueling water pump casing drain valve & spray orifics bypase Valve. RAY, H B Southern California Edison Co 82/08/17 Region 5, 0ffice of Director ip. 14679 151 24X Fiche 50-206,82/08/17,8208300057
- 8208300087 Forwards LER 82-020/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/08/20 ENGELKEN.R.H Region 5. Office of Director 2pp 14596 145, 24X Fiche 50-206, 82/08/20. 8208300087
- --B20B3000B9 LER 82-020/03L-0 on Bi0702, 16, B20209 & 0729, Tech Spectesting period limits not adhered to Caused by operator misinterpretation of Tech Specs Operator retraining will be completed by B20930 & surveillance instructions revised. RAY, H B Sputhern California Edison Co 82/08/20, Region 5, Dffice of Director 1p 14596 147 24X Fiche 50-206, B2/0B/20, B208300087
- DOCKET 50-209 COLUMBIA UNIV RESEARCH REACTOR
- O Inspection reports, IE Bulletins & correspondence
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Sec list encl JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/19 Hichigan, Univ of 112pp 14358:001. 24X Fiche: 50-000, 82/07/17, 8204210375
- DOCKET 50-213 HADDAM NECK PLANT
- F. Security, medical, emergency & fire protection plans
- 8207210248 Forwards add1 info supporting 810319 exemption request from App R requirements COUNSILW 0, CAGNETTA, JP Connecticut Yankee Atomic Power Co. 82/07/16 EISENHUT, D 0 Division of Licensing 132pp. 13934:351, 24X Fichs 50-213.82/07/16,8207210248

- 8208050163 Forwards "Fire Protection App R Review, Haddam Neck Plant, Bupplemental Info" COUNSIL, W O, CAGNETTA, J P Connecticut Yankee Atomic Power Co 82/07/16 EIBENHUT, D O Division of Licensing 10pp 14211 247, 24X Fiche 50-213,82/07/16,8208050163
- --B208050167 "Fire Protection App R Review, Haddam Neck Plant, Supplemental Info." * Northeast Utilities 82/07/31 150pp 14211 25B 24X Fiche 50-213, 82/07/16, 8208050163
- 8208030013 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records. 82/07/20 Document Hanagement Branch 1p 14201:001 24X Fiche:50-000,82/07/20, 8208030013
- --8208030019 Public version of revised emergancy plan implementing procedures, including Procedures EPIP 4102 re alert, EPIP 4103 re site area emergancy & EPIP 4104 re general emergancy.

 * Connecticut Yankee Atomic Power Co * Northeast Nuclear Energy Co. (subs of Northeast Utilities) 82/07/20 718pp 14201 005 24% Fiche 50-000, 82/07/20, 8208030013
- 8208060247 Bubmits add1 clarifications of B20301 App R review for facilities, in response to NRC 820628 & 0707 requests.

 COUNSIL, W 0 Connecticut Yankee Atomic Power Co. COUNSIL, W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities)

 B2/07/30 CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 3 CRUTCHFIELD, D Fiche 50-000, 82/07/30, 8208060267
- 8208090312 Advises that fee sent w/B20120 application for exemption from safeguarding requirements of 10CFR73 21 will be refunded MILLER, W.O. License Fee Hanagement Branch 82/07/30 CDUNBIL, W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), Jp 14307 323 24X Fiche 50-000, 82/07/30, 8208090312
- 8208160434 Forwards revision to suitability, training & qualification plan Revision withheld (ref 10CFR2 790)
 ADDY, R. J. Connecticut Yankee Atomic Power Co. 82/08/04
 DENTON, R. Office of Nuclear Reactor Regulation, Director ip 14349 198 24X Fiche 50-213,82/08/04,8208160434
- 8208260447 Releases public version of revised emergency plan procedures FELTON, J M Division of Rules and Records 82/08/09 Document Management Branch ip 14579 045 24X Ficha 50-213,82/08/09, 8208260447
- --B208260451 Forwards public version of revised emergency plan procedures, including Procedures EPP 1 5-1 re emergency assessment, EPP 1 5-2 re notification & communication & 1.5-3 re notification of unusual event COUNSIL.W 0, Connecticut Vankes Atomic Power Co B2/07/29. EISENHUT, D. 0 Division of Licensing ip 14579-046 24X Fiche 50-213, B2/08/09, B208260447
- --8208260455 Public version of revised emergency plan procedures, including Procedures EPP 1.5-1 re emergency assessment, EPP 1.5-2 re notification & communication & 1.5-3 re notification of unusual event Revised index encl 4 Connecticut Yankes Atomic Power Co 82/07/31 200pp. 14579 047 24X Fichs 50-213, 82/08/09, 8206260447
- H General correspondence
- 8208250135 Notifies of recent changes in util organization reflected in GA program topical rept Revision 4A Details enci. COUNBIL.W 0 . CAQNETTA: J. P. Northeast Utilities Service Co. 82/08/17. HAASB, W P. Quality Assurance Branch. 7pp 14541:302 24X Fiche 50-000,82/08/17.8208250135
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for GROR Byc list smcl.
 DIRCKS M.J. Office of the Executive Director for Operations.
 82/07/02. Consolidated Edison Co. of New York 93pp 14194;001, 24X Fiche 50-000,82/07/02,8207080064
- 8208020076 Advises that facilities fully mest position of NUREO-0737, Item [II D 3 3, "Improved In-Plant Iodine Instrumentation Under Accident Conditions "No deviations requested, COUNSIL.H 0. Connecticut Yankee Atomic Power Co. COUNSIL.H.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) BZ/07/20 CRUTCHFIELD. Operating Restors Branch 5. ip 14144.106. 24X Fiche.50-000.82/07/20.8208020076

- 8208020225 Application to amend License DPR-61, revising Tech Specs to change definition of containment integrity & to update removal plan for remaining reactor vessel surveillance capsules
 CDUNSIL.W O Connecticut Yantee Atomic Power Co 82/07/23
 CRUTCHFIELD.D Deparating Reactors Branch 5 App 14152 033 24X
 Fiche 50-213.82/07/23.8208020225
- ~-8208020234 Proposed Tech Specs, changing definition of containment integrity & updating removal plan for remaining reactor yessel surveillance capsules * Connecticut Yankee Atomic Power Co 82/06/30 14pp 14152 037 24X Fiche 50-213,82/07/23,8208020225
- --B208020239 Proposed ETS, changing surveillance & reporting requirements of fish impingement * Connecticut Yankee Atomic Power Co 82/06/30 ip 14152 051 24X Fiche 50-213.82/07/23.8208020225
- E208020244 Notifies of proposed programmatic change to QA program topical rept Revision 4A. Exception to Paragraph 1 4 of ANBI N43 2 9-1974 re definition of QA records will be added to App F of topical rept COUNSIL. W O Northeast Utilities Service Co COUNSIL. W O Northeast Utilities Service Co COUNSIL. W O Northeast Utilities 82/07/26 HAASS, W P Quality Assurance Branch 2pp 14152-234 24X Fiche 50-000, 82/07/26, 8208020244
- 8208060230 Notifies of delay in submittal of head vent procedures until 820701 COUNSIL, W. Q., CAGNETTA: J. P. Northeast Nuclear Energy Co., (subs. of Northeast Utilities) COUNSIL, N. G. Connecticut Yankee Atomic Power Co. 82/07/30 CRUTCHFIELD.D. Operating Reactors Branch 5 CLARK, R. A. Operating Reactors Branch 3 2pp. 14241 332 24X Fiche 50-000. 82/07/30.8208060230
- 8208060231 Submits comments on SEP Phase II. to assist NRC in development of proposed program for Phase III COUNSIL W Q Connecticut Vankes Atomic Power Co COUNSIL W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/07/30 CRUTCHFIELD.D Operating Reactors Branch 5 Bpp 14241 323 24% Fichs 30-000,82/07/30.828060231
- 8208060277 Provides further response to NRC 801222 request for info re NVREO-0612. "Control of Heavy Loads at Nuclear Power Plants." Schedule for completion of remaining work expected by 820827 COUNSIL, N O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, N O Connecticut Yankee Atomic Power Co 82/07/30 EISENNUT, D O. Division of Licensing App. 14241 088 24X Fiche 50-000, 82/07/30, 8208040279
- 8208310426 Responds to FOIA request for documents re NFS-4 shipping casks Forwards Documents 2,5,8,9,11,12,13,29,31,33 & 48
 listed in App A Remaining documents available in PDR
 FELTON.J H Division of Rules and Records 82/07/30 KRONZEK, A L
 FOI Bervices 4pp 14705 134 24X Fiche 50-000,82/07/30,
 R20R31042A
- --8208310481 Informs of intent to ship SNM in form of three irradiated fuel assemblies from Haddam Nack-CT to BMI in Columbus, CH on 800422, 28 & 0502 COUNSIL, H Q , FEE, M, F Connecticut Yankee Atomic Power Co. 80/04/15 CRIER, B H Region 1, Philadelphia: Defice of the Director. 19 14705 256 24X Fiche 50-000,82/07/30,8208310426
- --8208310483 Informs that first spent fuel assembly shipped from facility to BMI in NAC-1 cask exceeded decay heat limit. No adverse effects un health k sefety observed, therefore no further action necessary COUNSIL. W O Connecticut Yankes Atomic Power Co. 80/05/21. ORIER, B H Region i. Philadelphia. Office of the Director 2pp 14705 274 24X Fiche. 50-000, 82/07/30, 8208310426.
- 8208050076 Forwards final evaluation of licenses response to SEP Topic III-4 A re tornado missiles Facility can be operated safely until issue of providing addl protection to 10 listed areas is resolved in integrated assessment CRUTCHFIELD.D Operating Reactors Branch 5 82/08/02 COUNBIL.W.Q. Connecticut Yankee Atomic Power Go 17pp 14213 210 24X Fichs.50-213.82/08/02.8208050076
- B20B110039 Discusses changes to Tech Specs re containment air recirculation sys filtration sys in ESF filter sys No Tech Spec need yet be proposed for primary auxiliary bldg filters & fuel storage bldg filters Multi-Plant Task C-04 closed. CRUTCHFIELD, D Operating Reactors Branch 5 BZ/08/05 COUNSIL, W Q Connecticut Yankee Atomic Power Co. 2pp. 14317.172 24X Fiche 50-213,82/08/05,820B110039

9. .

- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list ancl EISCHNUT, 0 Division of Licensing 82/08/09 Consolidated Edison Co of Neu York ip 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- B20B160117 Requests assurance that final radiological effluent Tuch Bpecs will be submitted no later than B21001 CRUTCHFIELD, D. Operating Reactors Branch 5 B2/08/11 COUNBIL.W Q Connecticut Yankee Atomic Power Go 2pp 14345 183 24X Fiche 50-213.82/08/11.2208160117
- B20B190297 Comments on draft technical & safety evaluations of SEP Topic VII-1 A. "Isolation of Apactor Protection Sys From Nonsafety Bys, Including Qualification of Isolation Devices " GOUNSIL.H O Connecticut Yankee Atomic Power Co B2/0B/11 CRUTCHFIELD, D Operating Reactors Branch 5 App 14500 076 24X Fiche 50-213, B2/0B/11, B20B190297
- 8208170158 Forwards "Control of Heavy Loads," draft technical evaluation rept Sefety evaluation will be issued following receipt of comments CRUTCHFIELD, Departing Reactors Branch 5 NRC-03-79-118 82/08/12 GOUNSIL,W Q. Connecticut Yankes Atomic Power Co 2pp 14364 345 24X Fiche 50-213,82/08/12,8208170158.
- --8208170163 "Control of Heavy Loads," fraft technical evaluation rept.
 HDFKIN.T , BARGENT, I H Franklin Institute/Franklin Research
 Center NRC-03-79-118. TER-05257-445 82/08/03 CLEMENBON.F.
 NRC NO Detailed Affillation Given 27pp 14364 347 24X
 Fiche 50-213,82/08/12.8208170158
- 8208170169 Forwards final evaluation of sys portion of SEP Topic VI-7 B, "ESF Switchover From Injection to Recirculation Mode Automatic ECGS Realignment." Manual switchover procedure does not meet SEP review criteria CRUTCHFIELD, D Operating Reactors Branch 5 82/08/12 CDUNSIL.W Q Connecticut Vankee Atomic Power Co 7pp 14364 333 24X Fiche 50-213,82/08/12,8208170169
- 8208240251 Forwards technical evaluation rept & draft safety evaluation re BEP Topic III-1, "Quality Group Classification of Components & Bys." for review Response requested within 30 days of itr receipt GRUTCHFIELD, D. Operating Reactors Branch 5 82/08/12 COUNSIL, W. G. Connecticut Yankes Atomic Power Co. Opp. 14523 001 24X Fiche 50-213, 82/08/12, 8208240251
- --8207260247 "Quality Group Classification of Components & Bys (BEP. III-1)CT Yankse Atomic Power Co. Haddam Neck Plant," technical sysluation rept TIKOO, B., GONZALEZ, A., BERKOHITZ, L. Franklin Institute/Franklin Research Center NRC-03-79-118 TEP-05257-435 B2/07/22 BOYLE, M. NRC No Detailed Affiliation Given, 180pp 14523,007 24X Fiche 50-213,82/08/12.8208240251
- 8208240384 Forwards add1 info re NUREO-0737. Item II K. 3 17. "ECCS Outages." in response to NRC 820622 request COUNSIL.W O , OPEKA, J F. Connecticut Yankee Atomic Power Co COUNSIL.W O Northeast Nuclear Energy Co (subs. of Northeast Utilities). 82/08/16 GRUTCHFIELD.D Operating Reactors Branch 5 CLARK.R A Operating Reactors Branch 3 23pp. 14524 045 24X Fichs: 50-000, 82/08/16, 8208240384
- 8208240404 Forwards comments on SEP Topic VI-4. "Containment Isolation Sys" Requests comments be incorporated into revised safety syaluation for SEP topic COUNSIL, W. O. WERNER, R. P. Connecticut Yankee Atomic Power Co. 82/08/18. CRUTCHFIELD. D. Operating Reactors Branch 5 20pp 14522 275. 24X Fiche 50-213,82/08/18.8208240404.
- 820825013B Forwards sefety evaluation of util 820407 sefety assessment rept for sys & radiological consequences of SEP Topic XV-17, "Steam Generator Tube Rupture " Assessment acceptable. CRUTCHFIELD,D. Operating Reactors Branch 5, 82/08/17 COUNSIL,W G. Connecticut Yankee Atomic Power Ca 17pp, 14540 330 24X Fiche 50-213,82/08/17,8208230138
- 8208300094 Advises that leased temporary modular structures on site do not violate Yech 8pec Section 5 2 No action required or requested COUNSIL.W 0. Connecticut Yankes Atomic Power Co 82/08/19 CRUICHFIELD, D Assistant Director for Operating Reactors, 2pp 14596.154 24X Fichs.50-213.82/08/19.8208300094
- 8208300075 Advises that SAR for SEP Topic III-5.A, "High Energy Pipe Break Inside Containment," will be submitted on or before 820917 CQUNSIL.W 0, CAONETTA.J P Connecticut Yankee Atomic Power Co 82/08/23 CRUTCHFIELD.D. Operating Reactors Branch 5 1p. 14578.306 24% Fiche: 30-213,82/08/23 8208300075.

- 8208300036 Forwards "Aerial Radiological Survey of Haddam Neck Plant & Burrounding Area " BORES.R J. Region 1. Office of Director, 82/08/25 COUNSIL.W G Connecticut Yankee Atomic Power Co. 1p. 14578-255 24X Fiche 50~213,82/08/25,8208300036
- --8208300038 "Aerial Radiological Survey of Haddam Neck Plant & Surrounding Area:" date of survey Oct 1981 HOBAUOH,J.L., HAGUIRK-T.C., TIPTON, M.J. EG&G, Inc., EGG-1183-1829 82/07/31 NRC No Detailed Affiliation Given 15pp Available at NTIS &6 00 14398 256 24X Fiche 30-213.82/08/25, 8208300036

G Inspection reports, IE Bulletins & correspondence

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN,E.L Division of Engineering & Quality Assurance 82/07/ Consolidated Edison Co of New York 87pp 14356 274 24X Fiche,50-000,82/07/16,8204210393 82/07/16 24X
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation," 8vc list encl.

 JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19

 Michigan, Univ of 112pp 14358 001 24X Fiche 80-000, 82/07/19, 8204210395.
- 8204210374 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure," Svr list encl. JURDAN E L Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York. 112pp 14381.001 24X Fiche. 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list snc1 CD8B.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20. Consolidated Edison Co of New York. 71pp 14357, 2: 24X Ficha 50-000, 82/07/20, 8204210397.
- 8204210378 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl. Valve Failures "Syc list encl.

 JORDAN: EL Division of Engineering & Quality Assurance 82/07/22

 Consolidated Edison Co of New York 112pp 14174 321 24X

 Fiche 50-000: 82/07/22: \$204210378.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/29 Consolidated Edison Co of New York. 122pp 14380, 115 24X Fiche: 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (GRD) guide Tube Support Pin Failures at Westinghouse PWRs." Syc list and JORDAN.E.L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York, 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl, JORDAN,E L Division of Engineering & Guality Assurance, 82/07/26, Consolidated Edison Co of New York 121pp 14357, 013, 24X Fiche: 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Governosure of Diver During Work in Fuel Storage Pool," Syc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp. 14357,146, 24X Fiche: 50-000, 82/07/28,8204210405
- 8208100142 Responds to IE Bulletin 82-02 re degradation of threaded fasteners in RCPB Action Item 1, procedures for threaded fastener practices, will be implemented prior to Action Item Taskers | Passess | Passes
- 8208140423 Responds to Action Items 3 & 5 of IE Bulletin 82-02 re degradation of threaded fasteners in RCPB. Occurrences of visible leakage from body to bonnet areas of valves noted No fastener corrosion observed COUNBIL. W. O. Connecticut Yankee Atomic Power Co. CQUNBIL. W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/07/30 HAYNES.R C. Region 1, Office of Director App. 14348:173 24X Fichs: 30-000.82/07/30.8208140423.

- 8208310426 Responds to FOIA request for documents re NF8-4 shipping casks Forwards Documents 2,5,8,9,11,12,13,29,31,33 & 48 listed in App A Remaining documents available in PDR FELTON, J M Division of Rules and Records 82/07/30 KRONZEK, A FOI Services 4pp 14705 134 24X Fiche 50-000,82/07/30. KRONZEK, A L 8208310426
- --8208310469 Forwards IE Investigation Repts 50-213/80-20 & 50-219/80-38 on 801006-810114 & notice of violation GARLSON, R T Enforcement & Investigation Staff 81/12/23 GOUNSIL. W O Connecticut Yankes Atomic Power Co 2pp 14705, 227 24X Fiche 50-000, 82/07/30, 8208310426
- --8208310472 Notice of violation from investigation on 801006-810114 CARLEBON.R T Enforcement & Investigation 816FF 81/12/23 1p 14705 229 24% Fichs 50-000.82/07/30.8208310426
- --8208310476 IE Investigation Repts 50-213/80-20 & 50-219/80-38 pm B01004-810114 Noncompliance noted on B00501.Model NFS-4. Beriel NAC-1E cask, loaded w/failed bundle H07.delivered carrier w/decay heat generation in excess of 2 5 kH BMITH.R H. ROTH.J. CARLSON.R T Enforcement & Investigation Staff 81/10/06 14pp 14705:230 24X Fiche:50-000,82/07/30, 8208310426.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffie Water-Jet Impingement," Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/08/05. Consolidated Edison Co. of New York 117pp 14388 201 24X Fiche 50-000.82/08/05.8204210407

R Periodic operating reports & related correspondance

- 8208120238 Forwards monthly operating rapt for June 1782 ORAVES.R.H. Connecticut Yankez Atomic Power Co. 82/07/13 of Hanagement and Program Analysis 1p 14326 035 24X Fiche: 50-213, 82/07/13, 8208120238 Office
- --8208120239 Monthly operating rept for June 1982 4 Connecticut Yankee Atomic Power Co B2/07/13 14326 036 24X Fiche 50-213,82/07/13,8208120238 12pp.
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A analyzing said into Foreeros accuments listed in App FELTON, J M Division of Rules and Records 82/07/10 Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010 82/07/13 UDELL, R A
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power COSE/20078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1."

 NRC - No Detailed Affiliation Given 82/07/13 48pp. 14679 216 24% Fiche 50-000 82/07/13.8208270010.
- --8208270271 Forwards annual occupational exposures by work & job COB2702/1 FORWARD ANNUAL OCCUPATIONS OF PROPERTY OF CO. 12/02/18 Function for CYBI GRAVES, R. H. Connecticut Yankse Atomic Power Cp. 82/02/18 Director's Office, Dffice of Inspection and Enforcement 1 14677-304 24X Fiche 50-000:82/07/13,8208270010
- ---BR08270276 Annual occupational exposures by work & job function for * Connecticut Yankes Atomic Power Co 82/02/18 1p. 14679-305 24X Fiche 50-000,82/07/13,8208270010
- --8208270531 Forwards "Personnel Exposure & Monitoring Rept 10CFR20 407 Rept for 1981" GRAVEB,R H Connecticut Yankee Atomic Power Co 82/03/31 HALLER,N,M Office of Hanagement and Program Analysis. 1p. 14680-070 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270554 "Personnel Exposure & Monitoring Rept 10CFR20.407 Rept For **Connecticut Yankee Atamic Pawer Co 82/03/31 4pp. 14480:071, 24X Fiche. 50-000, 82/07/13, 8208270010,

DOCKET 50-219 GYSTER CREEK NUCLEAR POWER PLANT

- F. Security, medical, emergency & fire protection plans
- 8208050390 Forwards IE Bafeguards Insp Rept 50-219/82-14 on 820517-21 No noncompliance hoted. Rept details withheld (ref 10CFR73 21) WARTINIT T. Division of Engineering & Technical Programs 82/07/P1, FIELDER, P. B. Qeneral Public Utilities - OPU Barvice Corp 2pp. 14209.188 24X Fiche. 50-219. 82/07/21, 8208050390

- --8208050400 iE Safeguards Rept 50-219/82-14 on 820517-21 No noncompliance noted Major areas inspected physical barriers, vital/protected areas:security sys power supply & lighting aids Details withheld (ref 10CFR73 2!)

 MADDEN.W. SHITH.G. 90DY.A T Division of Engineering & Technical Programs 82/07/19 ip 14209 190 24X Fiche 50-219,82/07/21.
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR 8vc list encl
 DIRCKB.H J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000,82/07/02.820780004
- 8208240247 Confirms 820720-22 visits to util headquarters & plant site to discuss SEP integrated assessment program Meetings involve review of licensee position on differences & discussion of factors re backfitting decisions CRUTCHFIELD.D Operating Reactors Branch 5 82/07/12 FIEDLER,P B Oeneral Public Utilities QPU Service Corp 2pp 14520 092 24X Ficha 50-219,82/07/12,6208240247
- 8208020384 Responds to util 811224 request for deferment of items previously committed to accomplish during 1982 Cycle 10 refueling/maint outage. Deferral of Items 3, 4, 5, 8, 9 & 10 acceptable EISEMHUT, D @ Division of Licensing 82/07/30 CLARK, P R General Public Utilities GPU Service Corp 11pp 14148 210 24X Fiche 50-219, 82/07/30, 8208020384
- B20B060R01 Requests exemption from final interim requirements rehydrogen control Installation of high point vents on isolation condensers should be deferred until Cycle if refueling outage after Aug 1982
 FIEDLER:P B General Public Utilities OPU Service Corp 82/08/02 Office of Nuclear Reactor Regulation, Director 2pp 14238 361, 24X Fiche 50-219,82/08/02,8208060201
- 8208060257 Bubmits addl info re SEP Topics III-5 B. III-6, III-10 A.V-5, VI-7 A 3, VI-7 C 1, VI-10 A.VII-1 A.VIII-2 & VIII-4, per B20518-20 commitment Info re Topics III-6, VI-4, VI-7 A 3, VII-1 A & VIII-2 will be provided later FIEDLER.P B General Public Utilities QPU Service Corp B2/0B/02 CRUICHFIELD.D Operating Reactors Branch 5 7pp 14241 297, 24X Fichs 50-219, 82/0B/02, 8208060257
- 8208190157 Forwards proprietary version of XN-NF-78-12, "Spray Cooling Heat Transfer Test Results, Phase-II Facility & Test Data ENG Bib BWR Fuel "Encl withhold (ref 10CFR2 790) Affidavit encl FIEDLER, P B General Public Utilities OPU Service Corp 82/08/06 CRUTCHFIELD.D Deparating Reactors Branch 5 4pp 14381 015 24X Fiche 30-219,82/08/06.8208190157
- B208070174 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENNUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fichs 30-000, B2/08/09, B208090174
- 8208170182 Advises of 820824 meeting w/util to discuss SEP integrated assessment program Discussion will include review of licensee position on difference factors pertinent to backfitting decisions at to close out resolved differences CRUTCHFIELD. D. Operating Reactors Branch 5. 82/08/13 FIEDLER, P. B. Gensral Public Utilities OPU Service Corp. 3pp. 14386-349 24X Fiche 50-219,82/08/13,8208170182
- 8208240230 Comments on value of SEP SEP should be terminated at end of Phase II. since major objectives & benefits will be reached, other NRC programs overlap SEP & resources needed for other programs
 FIEDLER.F B General Public Utilities OPU Service Corp 82/08/16
 CRUTCHFIELD.D. Decreting Reactors Branch 5 3pp 14517 147 24X
 FIChe 30-217, 82/08/16, 8208240230
- 8208270103 Forwards application to amend License DPR-16, consisting of Change Request II, increasing capacity of spent fuel storage facilities to allow storage of 2,600 fuel assemblies Class III amend fee enci FIEDLER.P 8 Ceneral Public Utilities OPU Bervice Corp 82/08/20 CRUTCHFIELD.D. Operating Reactors Branch 5 2pp 14563-319 24X Fiche.50-219,82/08/20,8208270103

- --8208270111 Application to amend License DPR-16.consisting of Change Request 11. increasing capacity of spent fuel storage facilities to allow storage of 2.600 fuel assemblies Certificate of Svc encl FIEDLER.P B General Public Utilities - OPU Service Corp 82/08/20 3pp 14583 320 24X Fiche 50-219,82/08/20.8208270103
- 8208270284 Forwards responses to list of deficiencies identified in NRC 820316 ltr re radiological effluent Tech Specs Schedule for submitting final radiological specs & offsite dose calculation manual will be provided later FIEDLER,P B Jersey Central Power & Light Co 82/08/20 CRUTCHFIELD,D Deprating Reactors Branch 5 16pp 14963 097 24x Fiche 50-219,82/08/20,8208270284
- 8208310413 Submits response to questions raised by M Masnik re Tech Spec Change Request 94 re intake water canal level FIEDLER.P B General Public Utilities - GPU Service Corp 82/08/20 LDMBARDD.J Operating Reactors Branch 5 2pp 14693 274 24X Fiche 50-219.82/08/20.8208310413
- B20B310440 Forwards Revision O to "Tech Spec for Water Quality," in response to BEP Topic V-12 A, "Water Purity of BWR Primary Coolant" NAOALY General Public Utilities GPU Service Corp B2/08/24 FELL.R Bystematic Evaluation Program Branch 2pp 14690 170 24x Fiche 50-217, B2/08/24, B20B310440
- --8208310447 Revision O to "Tech Spec for Water Quality "
 WATTERS,C R General Public Utilities QPU Service Corp
 82/07/01 26pp 14690 172 24X Fiche 50-219,82/08/24,8208310440
- 8208260174 Notification of 820702 meeting w/util in Bethesda.MD to discuss SEP integrated assessment program for facility LOMBARDD.J Operating Reactors Branch 5 82/08/25 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 14554
- Q Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (M6IV) Leakage " 8vc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York, 87pp 14356-274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list enci JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14398 OOI 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl URBAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks" 8vc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000.82/07/20,8204210397
- 8208050390 Forwards IE Sefeguards Insp Rept 30-219/82-14 on 820517-21 No noncompliance noted Rept details withheld (ref 10CFR73 21), MARTIN T. T. Division of Engineering & Technical Programs 82/07/21, FIELDER, P B General Public Utilities - GPU Service Corp 14209 188 24X Fichs 50-219,82/07/21,8208050390
- -8208050400 IE Bafeguards Rept 50-219/82-14 on 820517-21 No noncompliance noted Major areas inspected physical barriers, vital/protected areas, security sys power supply & lighting aids. Details withheld (ref 10CFR73 21)

 MADDEN.W. SMITH.G., ODDY.A.T. Division of Engineering & Technical Programs 82/07/19 1p. 14209-190 24X Fiche 50-219,82/07/21.
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fichs 50-000, 82/07/22, 8204210398
- | S208050275 Forwards | E | Insp. Rept. 50-219/82-17 on 820402-0705 & notice of violation | STAROBTECKI, R. | Division of Project & Resident Programs | S2/07/22 | FIEDLER, P | Starobtecki, P | Starobtecki, R | Division of Project & Resident Programs | S2/07/22 | FIEDLER, P | Starobtecki, R | St

- --8208050278 Notice of violation from insp on 820602-0705 STAROBTECKI,R Division of Project & Resident Programs 82/07/22 ip 14210 124 24X Fiche 50-219,82/07/22,8208050275
- --8208050285 IE Insp Rept 50-219/82-17 on 820602-0705 Noncompliance noted unmonitored release of radioactive liquid to discharge canel.contaminating new radwaste bldg svc air sys THOMAS. J. TRIPP, LE Division of Project & Resident Programs 82/07/20 11pp 14210 125 24X Fiche 50-219.82/07/22.8208050275
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rad Drive (CRD) Ouide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Piche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Lose of Thermal Bleeves in RCS Piping at Certain Westinghouse PWR Power Plants " 8vc list encl JGRDAN.E L. Division of Engineering & Quality Assurance. 82/07/26 Consolidated Edison Co of New York 12ipp. 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl, JORDAN,E L. Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche, 50-000, 82/07/28, 8204210405
- 8208100207 Ack receipt of 820707 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-06 MARTIN.T T Division of Engineering & Technical Programs 82/07/30 FIEDLER.P B General Public Utilities QPU Bervice Corp Rpp. 14294 255 24X Fiche 50-219.82/07/30.8208100207
- --8208100213 Responds to NRC 820520 itr reviolations noted in IE Insp Rept 50-217/82-06 Corrective actions reporting guidelines incorporated into local leak rate testing procedure FIEDLER,P B General Public Utilities - GPU Service Corp 82/07/07 HARTIN,T T Division of Engineering & Technical Programs. 7pp 14294 257 24X Fiche 50-219,82/07/30,8208100207
- 8208310426 Responds to FOIA request for documents re NFB-4 shipping casks Forwards Documents 2,5,8,9,11,12,13,29,31,33 & 48 listed in App A. Remaining documents available in PDR FELTON, J M Division of Rules and Records 82/07/30 KRONZEK, A. L. FOI Bervices, 4pp. 14705 134 24X Fiche 50-000,82/07/30,
- --8208310467 Forwards IE Investigation Repts 50-213/80-20 & 50-219/80-38 on 801006-810114 & notice of violation. CARLSON,R.T Enforcement & Investigation Staff 81/12/23. COUNSIL, M.O. Connecticut Yankee Atomic Power Co. 2pp 14705 227 24X Fiche 50-000,82/07/30,8208310426.
- ---B20B310474 IE Investigation Repts 50-213/80-20 & 50-219/80-38 on 801004-810114. Noncompliance noted on 800501, Model NFS-4, Barial NAC-IE cask loaded w/failed bundle HD7. delivered to carrier w/decay heat generation in excess of 2.5 kH. BMITH.R H , ROTH.J , GARLSON.R T Enforcement & Investigation 8taff 81/10/06 14pp 14705 230 24X Fiche 30-000.82/07/30, 8208310426
- --B20B3104B6 Discusses review of licensee mgt of NAC-1E spent fuel shipping container on 800723-0801 (IE Insp Rept 50-217/80-26), No noncompliance noted. Shipping & receiving survey records encl. PLUNLEE, K. E. Fecility Radiological Protection Section 81/09/17 SMITH.R. H. Region 1, Philadelphis, Office of the Director (81/03/01) 34pp. 14705.276, 24% Fiche 50-000,82/07/30,8208310426.
- 8208060247 Advises of intent to use ABME 8 & PV Code Section XI 1980 Edition through 1981 Winter Addenda IWA-5000 for inservice insp program, per 10CFR50, 55 a(g), FIEDLER, P 8 General Public Utilities GPU Service Corp. 82/08/02 Office of Nuclear Reactor Regulation, Director. 2pp 14241 310, 24X Fiches. 50-219, 82/08/22, 8208040247
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Syc list enci.
 JORDAN.E.L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co. of New York. 117pp 14388 201. 24X
 Fiche: 50-000, 82/08/03, 8204210407

- 8208190305 Forwards inservice insprept on 820302-0723 Rept describes exams performed on support components of feedwater; containment spray & core spray sys FIEDLER.P B General Public Utilities OPU Service Corp 82/08/12 HAYNES.R C Region i. Office of Director ip 14387 348 R4X Fiche 80-217, 82/08/12, 8208190305
- --8208190309 Inservice insp rept on 820302-0723, describing exams performed on support components of feedwater.containment spray & core spray sys
 TOM8.R B General Public Utilities QPU Service Corp 82/08/02,
 3pp 14387-349 24X Fiche 50-219.82/08/12,8208190305
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp 14679: 208 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVB!"

 * NRC No Detailed Affiliation Given 82/07/13 48pp 14679.216 24X Fiche: 50-000, 82/07/13, 8208270010
- --B208270280 Forwards "Personnel Whole Rody Exposures for CYB1,"
 per 10CFR20 407
 FIEDLER,P B Oeneral Public Utilities OPU Bervice Corp.
 82/02/18 Office of Management and Program Analysis ip
 14679-306 24X Fiche,50-000,82/07/13,8208270010
- --8208270288 "Personnel Whole Body Exposures for CY81."

 * General Public Utilities GPU Service Corp. 82/02/18 ip
 14679 307. 24X Fiche, 50-000, 82/07/13,8208270010
- 8208120037 Forwards inadvertently emitted page to monthly operating rept for Apr 1982
 FIEDLER, PB General Public Utilities GPU Service Corp 82/07/14,
 Management Information Branch 2pp 14324 004 24X
 Fiche 50-219,82/07/14,8208120037
- --8208120038 Inadvertently omitted unit shutfown & power reductions page to monthly operating rept for Apr 1982
 BARAN, R General Public Utilities QPU Service Corp 82/06/10 2pp. 14324 006 24% Fiche 80~219,82/07/14,8208120037
- B Reportable occurrences, LERs & related correspondence
- 8208050453 Forwards LER 82-016/03L-0 Detailed event analysis encl FIEDLER,P 8 General Public Utilities - GPU Service Corp. 82/07/14. HAYNES,R C Region 1. Office of Director 5pp. 14216-341. 24X Fiche. 50-219, 82/07/14,8208050453
- --B208050460 LER 82-016/03L-0. on 820611. during transfer of spent resin, avc air piping became cross contaminated w/water.resulting in three leaks to environ Caused by blocked vent lines on tank Affected sys isolated, FITZGERALD, M J. General Public Utilities GPU Bervice Corp. 82/07/14 Region 1, Office of Director ip. 14216, 346. 24X Fiche: 50-219, 82/07/14, 8208050453.
- 8208050126 Forwards LER 82-034/03L-0. Detailed event energe's encl. FIEDLER, F.B. General Public Utilities QPU Service Corp. 82/07/16 HAYNES, R.C. Region 1. Office of Director. 3pp 14213:115 24X Fiche. 50-219, 82/07/16, 8208050126.
- --8208080131 LER 82-034/03L-0: on 820616.300 gallons of contaminated water leaked to environs due to broken fitting. Caused by failure of threaded connection on 1-2 condensate transfer pump discharge Connection replaced HADER: C. General Public Utilities QPU Service Corp 82/07/16. Region 1. Director ip. 14213 iii 24X Fiche: 50-219, 82/07/16, 8208050126.
- 8208050346 Forwards LER 82-035/03L-0. Detailed event analysis encl. FIEDLER.P 8 General Public Utilities GPU Service Corp. 82/07/19. HAYNES.R C. Region 1. Office of Director 3pp. 14219:334. 24X Fiche 50-219.82/07/19.8208050346.
- --8208050338 L&R 82-035/03L-0.on 920515.off-gas isolation valve gld not indicate closure. Caused by piece of foreign matt lodged in redundant solanoid valve. Solenoid valve removed & replaced. 8DBEL.C.P. General Public Utilities - GPU Service Corp. 82/07/19. Region 1, Office of Director 1p. 14219:337 24X Fiche 50-219.82/07/19.8208030346

- 9208020390 LER 82-037/01P on 820719, opening of supply breakers for normally open valves during isolation condenser isolation test & calibr found to prevent automatic isolation Caused by procedural inadequacy
 FIEDLER.P B General Public Utilities CPU Service Corp 82/07/20
 HAYNEB.R C Region i, Office of Director 3pp 14150 070 24%
 Fiche 50-219, 82/07/20, 8208020390
- 8208050443 RO on 820611.new radwaste svc dir sys was contaminated w/radioactive water from resin transfer tank Caused by failure of check valve to isolate at cross-connection of two sys All plant floor & roof drain sys will be reviewed FIEDLER.P.B General Public Utilities GPU Service Corp 82/07/20 HAYNEB.R C Region I. Office of Director 2pp 14218 026 24% Fiche: 50-219, 82/07/20, 8208050443
- 8208050084 Forwards LER 82-041/01T-0 Detailed event analysis encl FIEDLER.P B General Public Utilities - GPU Service Corp 82/07/23 HAYNES,R C Region 1, Office of Director 3pp 14213 194 24X Fiche, 50-219, 82/07/23, 8208050
- ---B208050091 LER 82-041/01T-0 on 820707 & 08. stack gas sample pump B electrically tripped overload causing stack gas sampling to reduce to 0 std cubic ff per minute Caused by high ambient temp near motor controller Backup pump activated CHARTERINA, J. General Public Utilities 0PU Service Corp 82/07/23 Region 1. Office of Director ip 14213 177 24X Fiche 50-217,82/07/23,8208050084
- 8208050270 Forwards LER 82-040/01T-0 Detailed event analysis encl FIEDLER.P. B General Public Utilities ~ 0PU Service Corp 82/07/26 HAYNES.R.C Region 1, Office of Director 3pp 14210 112 24X Fiche 30-219, 82/07/26,8208050270
- --B208050274 LER 82-040/01T-0 on 820707, signal input disconnected to safety valve vibration monitor rendering acoustic monitoring channel inoperable. Cause undetermined Hire reconnected & alarm will be added to alarm circuit HARKLERDAD, R General Public Utilities GPU Service Corp 82/07/24 Region 1, Office of Director ip 14210 115 24X Fiche, 50-219, 82/07/26, 8208050270
- B208060030 Forwards incident reporting sys repts re effects of fire protection sys actuation on safety-related equipment & seismic qualification of safety-related sys for transmission to NEA HICHELBON, C Director's Office. B2/07/29 LAFLEUR, J D Office of International Programs, Director 21pp 14244.315 24X Fiche 50-000, B2/07/29, B208060030
- B20B160034 Forwards LER B2-03B/03L-0 Detailed event analysis encl FIEDLER.P B General Public Utilities - GPU Service Corp B2/0B/02 HAYNES.R C Region 1. Office of Director 3pp 14344 304 24X Fiche: 30-217. 82/08/02. B20B160034
- --8208160035 LER 82-038/03L-0 on 820630, monthly surveillance of safety & relief valve backup monitoring sys (thermocouples) not performed per Tech Spec Gaused by personnel error & finadequate inplementation of procedural controls FITZOERALD, M J General Public Utilities OPU Bervice Corp 82/08/02 Region 1, Office of Director 1p 14344 307 24X Ficher 50-219,82/08/02.8208160034,
- 820B160174 Forwards LER 82-039/03L-O Detailed event analysis encl FIEDLER,P. B. General Public Utilities - QPU Service Corp 82/08/02 HAYNES.R C Region I. Office of Director 3pp 14345.055 24X Fiche: 50-219,82/08/02,8208160174
- --8208160177 LER 82-039/O3L-0 on 920701, during surveillance testing, thermocouple for sefety valve NR28J found imperable. Caused undetermined Adjacent acoustic monitor setpoint reduced. Thermocouple will be removed during next outage SUBEL. C F. Ceneral Public Utilities GPU Service Corp Region 1, Dffice of Director 1p, 14345 038 24X Fiche, 50-219, 82/08/02, 8208160174
- B20Bi30255 Forwards LER B2-037/0iT-0. Datailed event analysis encl FIEDLER.P B. General Public Utilities - OPU Service Corp B2/08/03. HAYNES.R C Region 1. Office of Director 3pp 14333 007 24X Fiche 50-219, 82/08/03, 8208130255
- --B208i30238 LER 82-037/01T-0'on B20719, procedural error identified which removed capability to automatically isolate isolation condenser as required by Tech Space Caused by procedural inadequacy. Procedure will be revised RIGQLE, E I General Public Utilities -- GPU Service Corp 82/08/03 Region 1, Office of Director. ip 14333 010 24X Fiche. 50-219, 82/08/03, 8208130255

- 8208300055 LER 82-044/01P on \$20810. while in run mode, stack gas not continuously manitored when B sample pump tripped Caused by electrical overload trip of heater protector on motor controller FIEDLER.P B General Public Utilities GPU Service Corp 82/08/14 HAYNES,R C Region 1, Office of Director 2pp 14598 308 24% Fiche 50-219, 82/08/11, 8208300055
- B20B190254 PND-I-82-056 on 820B14, reactor shut down to clean HX & repair leaking electromatic relief valve following inservice testing which indicated fouling of containment spray/emergency svc water HX TRIPP.L. KEIMIOR Region i. Office of Director B2/08/16 1p 14388 170 24X Fiche 50-217,82/08/16,820B190254
- 8208260194 Forwards LER 82-042/03L-0 Detailed event analysis encl FIEDLER,P B General Public Utilities - GPU Service Corp 82/08/16 HAYNES,R C Region i. Office of Director App 14554 312 24X Fiche 50-219,82/08/16,8208260194
- --B208260199 LER B2-042/03L-0.on B20716, during surveillance testing, relay 16K118 & 15K14B timers failed, preventing automatic actuation of containment spray sys II Caused by instrument drift Relays replaced & tested.

 CUSTODIO, D. B. General Public Utilities GPU Service Corp B2/08/16 Region 1, Office of Director ip 14554 314 24X Fiche 50-219,82/08/16.8208260194
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8208020200 Informs that submittal of analyses for compliance w/Section III G of 10CFR50 App R will be delayed until 521001 Schedule for completion of fuse coordination study will also be submitted on 821001

 LEMPGES, T E Niagara Mohawk Power Corp 82/07/22 VASSALLO, D B, Operating Reactors Branch 2 ip 14141 004, 24X Fiche 50-220,82/07/22,8208020200
- 8208100327 Forwards IE Insp Rept 50-220/82-09 on 820615-18 & notice of violation
 HARTIN, T T Division of Engineering & Technical Programs 82/07/23 LEMP0ES T E, Niagara Mohawk Power Corp 3pp 14297 185 24X Fiche 50-220, 82/07/23, 8208100327
- --8208100329 Notice of violation from insp on 820615-18 # Division of Engineering & Technical Programs 82/07/23 ip 14297-188, 24X Fiche. 50-220, 82/07/23, 8208100327,
- --8208100333 IE Insp Rept 50-820/82-09 on 820615-18 Noncompliance noted failure to follow procedure re fire watch in screen & pump house where welding was being conducted RICHARDS,8 , PAGLING,R , BECKMAN,D Division of Engineering & Technical Programs 82/07/23 9pp 14297 189 24X Fiche: 50-220,82/07/23,8208100327,
- 8208270496 Requests exemption from Section IV F of App E to 10CFR50 to waive requirement to conduct small-scale exercise during ur subsequent to 810915 full-scale exercise Exemption requested due to work outage LEMPGES, T. E. Niagara Mohauk Power Corp 82/08/20 VASSALLD, D B Operating Reactors Branch 2, 2pp. 14565,059 24X Fiche 50-220,82/08/20,8208270496
- 8208270230 Forwards changes to security plan Changes withheld (ref 10CFR2 790) SUNBER.J.J. Niagare Mohawk Power Corp 82/08/23 VABSALLO, D B Operating Reactors Branch 2, ip 14563 126 24X Fiche 50-220, 82/08/23, 8208270230
- H General correspondence
- 8208050053 Responds to 820705 concerns re design defects. Preliminary review of control board layout revealed potential for cord entangling critical controls Program of design review will be implemented THOMPSON.M.L. Division of Human Factors Bafety 82/07/29 HJ001NS.R. Affiliation Unknown. 2pp 14317.305 24X Fiche 50-220.82/07/29.8208050053.
- I Financial information
- B20B130293 Forwards Annual Financial Rept 1781 % addl financial info. RUSHMORE, J. H. Niapara Mohawk Power Corp. B2/0B/09 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 1p. 14336 271 24X Fiche 50-220, B2/0B/09, B20B130293

- P Operating license stage documents & correspondence
- 8208240051 Submits action plan progress rept for Dec 1981-Mar 1982, including items discussed w/R Baer in Feb PERKINS.T J , LEMPGES.T E Niagara Mohawk Power Corp 82/05/14 HAYNES.R C Region 1, Office of Director 7pp 14520 007 24X Fiche 30~220, 82/05/14,8208240051
- 8208030688 Corrects Paragraph 2 of Amend 48 to License DPR-63, issued on 820609
 POLK:P J Operating Reactors Branch 2 82/07/01 DISE, D P
 Niagara Mohawk Power Corp 2pp 14196 319 24X
 Fiche 50-220, 82/07/01, 8208030688
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR 8vc list encl DIRCKS.W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 Q01 24% Fiche 50-000,82/07/02.8207080064
- B20B050047 Approves final welding procedures & authorizes welding of replacement safe end. Listed as license condition in Amend 47 to License DPR-63
 VABBALLO, D B Operating Reactors Branch 2 82/07/20 DISE, D P Niagara Hohauk Power Corp 2pp 14244 034 24X
 Fiche 50~220, 82/07/20, 6208050047
- 8208040574 Requests submittal of documents explaining util satisfaction of NUREO-0737, Item II B 3 criterion re post-accident sampling sys Guidelines encl VASSALLO, D B Operating Reactors Branch 2 82/07/26 DISE, D P Niagara Mohawk Power Curp 10pp 14225 346 24X Fiche 50-220,82/07/26,8208040574
- 8208040216 Concludes that commitments & exceptions to requirements of Reg Ouide 1 58.Revision 1 & Reg Ouide 1 146 re qualification of insp & audit personnel acceptable Review of 820301 response to Generic Ltr 81-01 complete VASSALLO, D B Operating Reactors Branch 2 82/07/28 DISE, D P Niagara Mohawk Power Corp 2pp 14232 278 24X Fiche 50~220,82/07/28,8208040216
- 8208130115 BOCIDECONUMIC IMPACTS OF NUCLEAR QENERATING STATIONS NINE MILE PLANT AND FITZPATRICK CASE STUDY Docket Nos 50-220, 50-410 & 50-333 (Niagera Mohawk Power Corporation And Power Authority Of The State of New York)
 BRANCH,K, MEALE,R Mountain West Research, Inc. * Social Impact Research, Inc. FIN B-1268 NUREG/CR-2749 VO6 82/07/31, Division of Health, Siting & Environment 287pp Available at NTIS \$8 00 14341 001 24% Fiche 50-000,82/07/31,8208130115
- 8208050470 Forwards add1 info re control of heavy loads in response to 801222 request Heavy loads handled w/reactor bldg crane main hoist & lifting devices Load lift points required by NUREO-0612 provided LEMPGES. TE Niagara Mohawk Power Corp. 82/08/01 EISENHUT.D.O Division of Licensing 35pp 14214 123 24X Fiche 50-220.82/08/01.8208050470
- 8208090047 Informs that interim dose assessment sys will not be operational by 820731 due to electrical problems w/computer hardware Problems should be corrected within 2 was LEMPGEB.TE Niagare Mohawk Power Corp 82/08/03 EIGENHUT.D.Q. Division of Licensing 1p 14270 034 24% Fiche 50-220.82/08/03.8208090047
- 820B130195 Confirms previous verbal communication w/NRC re replacement of all 28-inch recirculation sys piping Mathodology being developed Revised occupational dose estimate will be submitted w/next quarterly repair program status rept LEMPOES.T E Niagara Mohawk Power Corp 82/08/06 EIBENHUT.D 0 Division of Licensing. ilpp 14339 147 24X Fiche 50-220,82/08/04/08,8208150195
- 8208090174 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT.D 9 Division of Licensing 82/08/07 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000, 82/08/09, 8208070174
- 8208200042 Advises that equipment & procedures utilized for in-plant iddine measurements, are in place & consistent w/NUREG-0737, Item III D 3 3 technical guidance.

 MANOAN, C. V Niegara Mohawk Power Corp 82/08/16 VABSALLO, D 8 Operating Reactors Branch 2, 1p 14392 250 24% Fiche 30-220, 82/08/16, 8208200042

- 8208200049 Submits addI info supplementing 820806 ltr re preliminary plans for replacing all 28-inch recirculation sys piping ALARA program will be utilized for mitigating worker radiation doses during piping replacement MANOAN.C V Niagara Mohawk Power Corp 82/08/16 EISENHUT, D Q Division of Licensing 7pp 14392 187 24X Fiche 50-220,82/08/16,8208200049
- 8208250197 Informs that schedule for providing add1 info re NUREO-0737, Item II B 3 on post-accident sampling will be provided by 821203, per 820726 request MANGAN,C V Niagara Mohawk Power Corp 82/08/18 VABSALLO, D B Operating Reactors Branch 2 ip 14540 280 24X Fiche 50-820,82/08/18,8208250197
- 8208270399 Revises 820707 implementation schedule for operational dose assessment sys, due to delays in obtaining design info from equipment vendor Hardware & software operational by 830301 Inland pole & associated equipment operational by 830701, LEMPOES, T E Niagara Mohawk Power Corp 82/08/20 EISENHUT, D. G Division of Licensing 2pp 14565 116 24X Fiche 50-220,82/08/20,8208270399
- Q Inspection reports, IE Bulletins & correspondence
- 8208160032 Forwards waste handling procedures, fulfilling commitment to IE Bulletin 79-19
 OERBER.C A Niagara Mohawk Power Corp 81/04/17 BAER,R Region 1, Philadelphia, Office of the Director (81/03/01) 2pp 14345 010 24X Fiche 50-220,81/04/17,8208160032
- --820Bi60037 Waste Handling Procedure Ni-WHP-8, "Van Shipment Preparation Procedure" # Niagara Mohawk Power Corp 81/04/06 ilpp 14345 012 24X Fiche 50-220, 61/04/17, 6208160032
- --8208160039 Waste Handling Procedure N1-WHP-9, "Solidification Procedure " * Niagara Mohawk Power Corp 81/04/06 3pp 14345 023 24X Fiche 50-220.81/04/17.8208160032
- --820Bl60042 Waste Handling Procedure N1-WHP-11, "Process Control Procedure " * Niagara Mohawk Power Corp Bl/04/06 3pp 14345 026 24X Fiche 50-220.Bl/04/17.B20Bl60032
- --8208160045 Waste Handling Procedure Ni-WHP-12, "Bolid Dry Waste Collection & Compaction " * Niagara Mohawk Power Corp 81/04/02 9pp 14345 029 24X Fiche 50-220,81/04/17,8208160032
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 UGRDAN.E L Division of Engineering & Quality Assurance
 Consolidated Editor Co of New York 87pp 14356 274
 Fichs 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3. Suppl i, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JURDAN, E.L. Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ of 112pp 14359 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8208020370 Forwards IE Insp Rept 50-220/82-10 on 820621-25 & notice of violation Response to 820619 mislocation of cutting operation for safe-end replacement program requested MARTIN.T T Division of Engineering & Technical Programs B2/07/19 LEMPOES,T E Niagara Mohauk Power Corp 2pp, 14150:100 24X Fiche 50-220,82/07/19,8208020370
- --8208020374 Notice of violation from insp on 820621-25 # Division of Engineering & Technical Programs 82/07/19 ip 14150 102 24% Fiche 50-220 82/07/19 8208020370
- --8208020378 IE Insp Rept 50-220/82-10 on 820621-25 Nontempliance noted failure to obtain Site Operations Review Committee approval for safe-end replacement program procedures EAPEN.P K. CAPHTON.D.L. Division of Engineering & Technical Programs 82/07/13 6pp 14150 103 24X Fiche 50-220,82/07/19,8208020370
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 182pp 14381:001 24X Fichs 50-000:82/07/20.8204210396

- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluorida Overpacks " Svc list enc! COBB.L! Division of Fuel Facilities. Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- 8204210398 IE Info Notice 82-24, "RCIC & MPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fichs 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28. "Mydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Fiche 50-000. 82/07/23.8204210401
- 8204210402 IE Info Notice 82-29, "Control Rad Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JGRDAN E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche 50-000, 82/07/23, 8204210402
- B208100327 Forwards IE Insp Rept 50-220/82-09 on 820615-18 & notice of violation MARTIN,T T Division of Engineering & Technical Programs 82/07/23 LEMPGES,T E Nisgara Mohawk Power Corp 3pp 14297 185 24X Fiche 50-220,82/07/23,8208100327
- --8208100327 Notice of violation from insp on 820615-18

 B Division of Engineering & Technical Programs 82/07/23 ip 14297 188 24% Fiche-50-220, 82/07/23,8208100327
- --8208100333 IE Insp Rept 50-220/82-09 on 820615-18 Noncompliance noted. failure to follow procedure re fire watch in screen & pump house where welding was being conducted RICHARZE, 8. PADLINO, R. BECKMAN, D. Division of Engineering & Technical Programs 82/07/23 9pp 14297 189 24% Fiche 50-220,82/07/23,8208100327
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sieves in RCS Piping at Certain Westinghouse PMR Power Plants " Svc list encl JORDAN,E L Division of Engineering & Quality Assurence 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000,82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, E.C. Division of Engineering & Ovality Assurence 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208050436 Forwards add1 info re inservice insp program in response to NRC 820414 1tr LEMPOES TE Niagara Mohawk Power Corp 82/07/30 VASSALLO, D B Operating Reactors Branch 2 18pp 14218 030 24X Fiche: 50-220, 82/07/30, 8208050436
- 8204210407 JE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list and I JORDAN, E.L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche.50-000,82/08/05.8204210407
 - Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, U M Division of Rules and Records 82/07/13 UDELL,R.A Critical Mass Energy Project. Spp 14479 208, 24% Fiche 50-000,82/07/13.8208270010
- -8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBL." "NRC - No Detailed Affiliation Given. 82/07/13 48pp 14679.216 24X Fiche.50-000,82/07/13,8208270010.
- 8208270579 Forwards "Personnel Whole Body Exposures for CYBL." per 10CFR20 407 LEMPOES, T.E., Niegera Mohawk Power Corp. 82/05/06. Office of Resource Management: Director ip 14680.079 24X Fiche 50-000,82/07/13,8208270010
- 8208270583 "Personnel Whole Body Exposures for CYB1 " * Niagara Mohawk Power Corp 82/05/06 R3pp 14680,080 24X Fiche. 50-000, 82/07/13, 8208270010

- 8208160448 Forwards monthly operating rept for Jul 1982 MANDAN,C V Niagara Mohawk Power Corp 82/08/09 Director's Office, Office of Inspection and Enforcement 1p 14349 264 24) Fiche 50-220.82/08/09.8208160448
- --8208160455 Monthly operating rept for Jul 1982 ROMAN,T W. Niagara Mohawk Power Corp. 82/08/04 4pp. 14349 265 24X Fiche 50-220,82/08/09,8208160448
- S Reportable occurrences: LERs & related correspondence
- 8208200104 Forwards LER 82-011/03L-0 LEMPGES Y E Niagara Mohawk Power Corp 82/08/09 HAYNES, R C. Region 1. Office of Director 1p 14393 047 24X Fiche 50-220, 82/08/09, 8208200104
- --8208200112 LER B2-011/03L-0 on 820802.oil leak on fuel oil supply manifold discovered on dissel fare pump Caused by defective braze joint Leak repaired by manufacturer OALAZZO. S Niagara Mohawk Power Corp 82/08/05 Region 1. Office of Director 1p 14393 O48 24X Fiche 50-220,82/08/09,8208200104
- 8208180044 PNO-I-82-031A continuing nondestructive exams (ultrasonic & dye penetrant tests) of circumferential welds in 28-inch diameter reactor racirculation sys piping disclosed indications in 31 of 37 welds tested KISTER.H. BRUNNER.E Region 1. Office of Director 82/08/12 ip 14379 276 24X Fiche 50-220.82/08/12.8208180064
- 8208230299 Forwards updated LER 82-009/01X-1 LEMPGES.T E Niagara Mohauk Power Corp 92/08/12 HAYNES.R C Region 1. Defice of Director 1p 14809 341 24X Fiche 50-220, 82/08/12, 8208230299
- --B20B23D304 Updated LER B2-009/01X-1'on B20323,water observed leaking from insulation on recirculation piping discharges 11 & 15 from reactor vessel Caused by cracking in riser elbow welds Recirculation piping replaced OALAZZO.8 Niagara Mohawk Power Corp B2/08/11 Region 1, Office of Director 2pp 14509 342 24X Fichs 50-220,82/08/12,8208230279
- DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8208300234 Forwards IE Insp Rept 50-223/82-01 on 820616 & notice of violation STARGSTECKI, R Division of Project & Resident Programs 82/08/11 BEONIANL E Lowell, Univ. of 2pp 14479 165 24X Ficha 50-223,82/08/11.8208300236
- --8208300241 Notice of violation from insp on 820616 BTAROSTECK1.R, Division of Project & Regident Programs 82/08/11 2pp 14679 167 24X Fiche 50-223,82/08/11,8208300236
- --8208300250 IE Insp Rept 50-223/82-01 on 820616 Noncompliance noted failure to have procedures for opening raceipt & handling of hadd 0E-1500 shipping casts containing Co-60 matl KINNEY.N.W. ROTH.J., GREENMAN.E.G. Division of Project & Resident Programs 82/08/10 7pp 14679 169 24X Fiche 50-223,82/08/11, 8208300296
- DOCKET 50-225 RPI CRITICAL EXPERIMENT
- Q Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Syc list encl JORDAN, E L. Division of Engineering & Guality Assurance 82/07/19 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, B204210395
- DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

 R Periodic operating reports & related correspondence
- 820B030589 Forwards annual summary of changes, tests & experiments performed at Aerotest Radjography & Research Reactor for period ending 820630 HASKINB, J. J. Aerotest Derations 82/07/21. STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs ip 14160, 200 24X Fiche 50-228, 82/07/21, 820B030589

- --8208030598 Annual summary of changes, tests & experiments performed at Aerotest Radiography & Research Reactor for period ending 820430
 HASKINB, J J, NEWACHECK, R L. Aerotest Operations 82/07/21 4pp 14160 201 24% Fiche 50-228,82/07/21,8208030589
- DOCKET 50-237 DREBDEN NUCLEAR POWER STATION, UNIT 2

 F Security, medical, smergency & fire protection plans
- 8208040353 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/07/13 Documen Management Branch ip 14223 161 24X Fiche 50-010,82/07/13, 8208040353
- --8208040358 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIF 100-08, "Rad/Chem Director" Receipt form, procedure history & safety evaluation encl SCOTT.D J Commonwealth Edison Co 82/07/02 DENTON, H R Office of Nuclear Reactor Regulation Director 3pp 14223 162 24X Fiche 50-010, 82/07/13, 8208040353
- --8208040361 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C8, "Rad/Chem Director " Revised index of station group director duties encl.

 * Commonwealth Edison Co 88/06/30 5pp 14223 165 24X Fiche 50-010,82/07/13,8208040353
- 8208040473 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/07/22 Documen Management Branch ip 14220 R74 24X Fiche 50-010,62/07/22, 8208040473
- --8208040477 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-07. "Security Director" & Revision 0 to EPIP 500-9, "Operational Check of Notification Phone List " Receipt form encl SCOTT.D J Commonwealth Edison Co 82/07/10 DENTON, H R Diffice of Nuclear Reactor Regulation, Director, 5pp 14220, 275 24X Fiche 50-010, 82/07/22, 8208040473
- --8208040483 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7, "Security Director" & Revision 0 to EPIP 300-9, "Operational Check of Notification Phone List" * Commonwealth Edison Co 82/07/07 App 14220 300, 24X Fiche 30-010,82/07/22,8208040473
- 8208270134 Forwards IE Insp Repts 50-010/62-11.50-237/82-13 & 50-249/82-14 on 820624.29.30 & 0709 & notice of significant test deficiency HIND. J A Division of Emergency Preparedness & Operational Support 82/08/03 REED. C Gommonwealth Edison Co 3pp 14563 338 24X Fiche: 50-010, 82/08/03.8208270134
- --8208270142 IE Insp Repts 50-010/82-11, 50-237/82-15 & 50-249/82-16 on 820624, 29, 30 & 0709 Significant test deficiency noted failure of seven prompt public notification sys strens JANUSKA, A G , SMITH.M. J , PATTERSON, J P Division of Emergency Preparedness & Operational Busport 82/07/23 12pp 14563 341, 24X Ficher 50-010, 82/08/03, 8208270134
- 8208250557 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 FELTON, J M Division of Rules and Records 82/08/12 Document Management Branch 1p 14559 354 24X Fiche. 50-000, 82/08/12: 8208250557
- --8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 MODRER D. Commonwealth Edison Co 82/07/19 DENTON.H R NRC No Detailed Affiliation Given 1p 14559.355. 24X
 Fiche. 30-000,82/08/12.8208250559
- --8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."

 * Commonwealth Edison Co 82/06/30. 7pp 14559:356. 24X Fiche. 50-000, 82/08/12, 8208250559
- 8208230107 Forwards revised cable discrepancy lists re-fire protection safe shutdown analyses Lists indicate how each discrepancy noted in fire protection associated circuit analysis k mod repts will be resolved.

 RAUBCH, T. J. Commonwealth Edison Co 82/08/13 EIGENHUT, D Q. Division of Licensing. 2pp. 14515 001. 24X Fiche: 50-000, 82/08/13, 8208230107

- --8208230113 "Fire Protection Cable Discrepancy List Dresden Unit 2 "
 * Commonwealth Edison Co 82/08/03 125pp 14515 003 24X
 Fiche 50-000, 82/08/13, 8208230107
- --8208230119 "Fire Protection Cable Discrepancy List, Dresden Unit 3 "

 * Commonwealth Edison Co 82/08/04 150pp 14515 144, 24X
 Fiche 50-000, 82/08/13, 8208230107
- --8208230122 "Fire Protection Cable Discrepancy List.Guad Cities Unit 1 * Commonwealth Edison Co 82/08/06 250pp 14515 293. 24X Fichs 50-000, 82/08/13. 8208230107
- --8208230130 "Fire Protection Cable Discrepancy List. Guad Cities Unit 2 * Commonwealth Edison Co 82/08/02 250pp 14516 216 24X Fiche 50-000, 82/08/13, 8208230107

Q Adjudicatory correspondence

- 8208190125 Final initial decision ordering NRR issue license amend authorizing installation of 33 high donsity storage racks in each spent feel gool WOLFE, J.F., REMICK, F.J., LITTLE, L.W. Atomic Safety and Licensing Board Panel 82/08/17 29pp 14381 043 24X Fiche 50-237, 82/08/17, 8208190125
- 8208240267 Response to ASLB 820728 order Requests leave to withdraw application w/o prejudice Need for transshipment in near-term reduced due to approval of installation of high density spent fuel racks. Certificate of Svc encl STEPTOE: P Commonwealth Edison Co STEPTOE: P Isham, Lincoln & Beale 82/08/18. Atomic Safety and Licensing Board Panel opp 14527.120 24% Fiche 50-000,82/08/18.8208240267
- B20B240233 Notice of ASLAB constitution AS Rosenthal, chairman & TB Moore & RL Gotchy, members BHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel, 82/08/20 ip 14519 148 24X Fichs 50-237,82/08/20.8208240233.
- B208240265 Response to ASLB B2072B order NRC does not object to proceeding termination since licensee has moved to withdraw license application w/o prejudice.due to decision in Dresden high density storage rack case W/Certificate of Byc WRIGHT.N.A Hearing Brench 2 B2/0B/20 Atomic Safety and Licensing Board Panel 3pp 14527 126. 24X Fiche.50-000,82/0B/20,8208240265
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl DIRCKS, M J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York, 93pp 14194 001, 24X Fiche 50-000,82/07/02,8207080064
- 8208050037 Forwards request for add1 info re TMI Item II D I.

 "Performance Testing of BWR & PWR Safety/Rollef Valves "
 Applicability of generic results reported in NEDE-2478BP-P
 must be demonstrated for specific valves at facility

 VASSALLO,D B Operating Reactors Branch 2 82/07/27 DELGEORGE,L
 Commonwealth Edison Co. Spp 14244 047 24X Fiche 50-237, 82/07/27,
 82/80803057
- 8208180266 Forwards revised version of model Tech Specs for reactor protection sys/power monitoring sys design VASBALLO, 0 8 Operating Reactors Branch 2 82/07/28 pELGEORGE, L. Commonwealth Edison Co 3pp 14389 318 24X Fiche, 50-000, 82/07/28, 8208180266.
- --820BiB0271 Revised model Tech Specs re electric power monitoring of reactor protection sys design # Operating Reactors Branch 2, 82/07/28 ip 14389:321, 24X Fiche 50-000.82/07/28,820BiB0266
- 8208030254 Comments on SEP in response to 820714 request Few deviations identified between design criteria used for Phase I/II plants vs current criteria DELOEORGE, U. Commonwealth Edison Co. 82/07/27 CRUTCHFIELD, D. Operating Reactors Branch 5, 3pp. 14158, 227. 24% Fichs. 50-010, 82/07/29, 8208030254.
- 8208050268 Forwards comments on design codes, design criteria & loading combinations per SEP Topic III-7 8 Sargent & Lundy input to 820515 NCT Engineering rept encl.
 RAUSCHIT J Commonwealth Edison Co 82/08/02. O'CONNOR, PM.
 Operating Reactors Branch 5 15pp 14241 160. 24X
 Fiche 50-237, 82/08/02, 8208060268

- 8208110041 Forwards response to request to cross-ref info re environ qualification of safety-related equipment & TMI action plan equipment SHARTZ.E D Commonwealth Edison Co 82/08/02 EISENHUT, D O Division of Licansing 557pp 14315 001 24X Fiche 50-000, 82/08/02,8208110041
- 8208130046 Requests approval to delay implementation of commitments in response to Generic Ltr 82-05 re NUREO-0737.1tem II F 1 6, "Containment Hydrogen Monitor" Completion postponed until 840101 to accommodate schedule requirements SIVARTZ.E D Commonwealth Edison Co 82/08/05 EISENHUT, D 6 Division of Licensing 2pp 14335 353 24X Fiche 50-000, 82/08/05, 8208130046
- 820Bi101BB Forwards revised pages to CE-1-A. "Com Ed QA Program Pur Nuclear Generating Stations," Revision 21 Revised pages correct typographical & other ainor errors SWART2.ED Commonwealth Edison Co 82/08/06 HAASB, W. P. Quality Assurance Branch ip 14314 079 24X Fiche 50-000,82/08/04, 820Bi101BB
- --B208110204 Revised pages to CE-1-A.Revision 21. "Comm Ed GA Program For Nuclear Generating Stations " * Commonwealth Edison Co. 82/06/06 11pp 14314 080 24X Fiche 50-000.82/08/06.8208110188
- 8208240444 Requests appropriate action be taken re acceptable vent sys for isolation condenser per hydrogen rule & NUREG-0737 guidance (TMI Item II 8 1) or exemptions from applicable provisions of IGCFRSO 44 should be requested VAGSALLO, D B Operating Reactors Branch 2 82/08/06 DELGEORGE, L Commonwealth Edison Co 3pp 14544 170 24X Fiche 50-237,82/08/06,8208240444
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Ex list and EISENHUT, D @ Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- B20B170135 Responds to NRC B20721 request to provide notification if util intends to deviate from NUREG-0737. Item III D 3 3, "Improved in-Plant lodine Instrumentation Under Accident Conditions "Both facilities comply w/requirement BWARTZ.E D Commonwealth Edison Co 82/08/12 EISENHUT, D 0, Division of Licensing 2pp 14365 211 24X Fiche 50-000, 82/08/12, 82/08/70135
- 8208230332 Forwards aperture card print of listed electrical schematics of reactor protection sys.per NRC request Info maeded to perform probabilistic risk assessment M/o encl RAUBCH.T J Commonwealth Edison Co 82/08/13 O'CONNOR.P Operating Reactors Branch 5 ip 14508 276 24% Fiche 50-237.82/08/13.8208230352
- 8208230349 Forwards revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of previously submitted inservice insp & testing program for second 10 yrs Revision necessary to enable insp of LPCI/CCSH HX tube welds
 RAUSCHIT.J Commonwealth Edison Co. 82/08/16 EISENHUT, D. 0
 Division of Licensing 2pp 14512 357 24X Fiche 50-237.82/08/16.8208230349
 - 3208230357 Revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of inservice insp & testing program for second 10 years ** Commonwealth Edison Co 82/08/16 3pp 14512 357 24X Fiche. 50-237.82/08/16.8208230347
- '08240398 Forwards NRC responses to util 820406 comments on evaluation of SEP Topics VI-2 B & VI-3 Revised Table 4 to 820610 evaluation enci Evaluation final & will be used as basic input to integrated safety assessment O'CONNOR.P Operating Reactors Branch 5 82/08/19 DELOEURGE.L Commonwealth Edison Co Spp 14524 205 24X Fiche 50-237.82/08/19, 8208240398
- OB270250 Application for amend to License DPR-29, proposing Toch Specchanges to implement iOGFR50 59 veload licensing w/ODYN transient analyses & extended exposure MAPLHOR limits
 Bignificant changes discussed, Class III amend fee encl
 4AUSCH-T J Commonwealth Edison Co 62/08/19 DENTON,H R. Office of Nuclear Reactor Regulation, Director Spp 14564 001 24X
 Fiche: 50-000, 82/08/19, 8208270250
- 3208270273 Errata & Addenda Sheet 7, replacing Pages 4-11 & 4-14 to "LDOA Analysis Rept for Dresden Units 2 & 3 & Guad Cities 1 & 2 Nuclear Power Stations" # Oeneral Electric Co. NEOG-24246A ERR 07 82/07/31 5pp. 14364 026, 24X Fiche: 50-000, 82/08/19, 8208270250

- 8208230147 Forwards safety evaluation addressing open items in B20117 draft safety evaluation of SEP Topic III-5 B, "Pipe Break Outside Containment " Facility adequately protected from pipe break effects, subj to listed resolution O'CONNOR,P W Operating Reactors Branch 5 82/08/20 DELOEORGE, L Commonwealth Edison Co 17pp 14540 313 24% Fiche 50-237, 82/08/20,8208250147
- 820827046B Forwards final safety evaluation of util 820617 assessment of SEP Topic II i C re-potential hazards due to nearby transportation institutional, industrial & military facilities Facility adequately protected O'CONNER.P Operating Reactors Branch 5 82/08/20 DELGEORGE, L Commonwealth Edison Co 25pp 14565 298 24X Fiche 50-237, 82/08/20,820827046B
- 8208310230 Application for amend to Licenses DPR-19 & DPR-25 re installation & use of high density fuel storage racks RAUBCH T J Commonwealth Edison Co 82/08/26 EIBENHUT, D G, Division of Licensing 2pp 14695 115 24X Fiche 50-237, 82/08/26, B208310230
- Q Inspection reports: IE Bulletins & correspondence
- 8208050414 Forwards IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 on 810813-820503 No noncompliance noted KEPPLER, J G Region 3, Office of Director 82/07/12, REED, C Commonwealth Edison Co ip 14217 166 24% Fiche 50-000, 82/07/12, 8208050414
- --8208050441 IE Insp Repts 30-237/81-37.50-249/81-32.50-254/81-23.50-254/81-23.50-254/81-31. & 50-304/81-27 on 810813-820503. No noncompliance noted Major areas inspected allegations re Comm Ed operation of facilities & compliance w/10CFR21 HAYEB, D. W. PHILLIP. & A. HINDS, J. M. Division of Project & Resident Programs 82/07/09 154pp 14217 169 24% Fiche: 50-000, 82/07/12, 8208050414
- 6204210393 IE 1nfo Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Bvc list encl JORDAN.E.L Division of Engineering & Quality Assurance 52/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-24, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list onel JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14338 001 24X Fiche 50-000, 62/07/19, 8204210795
- 8208050393 Forwards IE Insp Repts 50-010/82-04, 50-237/82-10 & 50-249/82-11 on 820307-0604 & notice of violation SPESSARD, R L Division of Project & Resident Programs 82/07/19 REED, C Commonwealth Edison Co 2pp. 14209 191 24X Fiche 50-010.82/07/19.8208050393
- ~~8208050378 Notice of violation from insp on 820507-0404 * Division of Project & Resident Programs 82/07/19, 2pp. 14209 173 24X Fiche 50-010,82/07/19,8208050373
- --8208050403 IE Insp Repts 50-010/82-06,50-237/82-10 & 50-249/82-11 on 820807-0604 Noncompliance noted failure to follow hose color code
 TONGUE,T M , JORDAN M J , WALKER,R D Division of Project & Resident Programs 82/07/11 9pp 14209 195 24X
 Fiche 50-010,82707/19,8208050393
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure" Bvc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York, 112pp 14381.001, 24X Fiche 50-000, 82/07/20, 8204210396,
- 8204210397 IE Info Notice 82-24, "Nater Leaking From U Hexafluoride Overpacks" Svc list encl COBB.L I Division of Foel Facilities, Materials & Safeguards, 82/07/20. Consolidated Edison Co of New York 7ipp 14357, 276, 24X Fiche 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & NPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN.E. L Division of Empineering & Quality Assurance, 82/07/22 Consolidated Edison Co of New York 112pp, 14194-321 24X Fiche. 50-000, 82/07/22, 8204210398.
- B204210401 IE Info Notice B2-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Evc list encl.

 JORDAN,E L Division of Engineering & Quality Assurance B2/07/23

 Consolidated Edison Co of New York 122pp 14380:115 24X

 Fiche 50-000, 82/07/23, 8204210401

DOCKETED ITEMS

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tuba Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23,8204210402
- 8208100287 Forwards IE Insp Repts 50-010/82-09,50-237/82-13 & 50-2497/82-14 on 820616-17 & 21-25 No noncompliance noted MILLER, J R Division of Engineering & Technical Programs REED, C Commonwealth Edison Co 2pp 14294 191 24X Fiche 50-010, 82/07/23,8208100289
- --8208100277 IE Insp Repts 50-010/82-07.50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25 No noncompliance noted Major areas inspected action on previous findings.open items & hydrogen gas addition into reactor feedwater sys PAUL.R A. GREGER.L R Division of Engineering & Technical Programs 82/07/22 7pp 14274 173 24X Fiche 50-010.82/07/23, 8208100287
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RGS Piping at Certain Westinghouse PWR Power Plants" Syc list and JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24X Fiche 50-000. 82/07/26.8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl.
 JORDAN, E. L. Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208270134 Forwards IE Insp Repts 50-010/82-i1.50-237/82-i5 & 50-247/82-i6 on 820624:27.30 & 0707 & notice of significant test deficiency HIND, J A Division of Emergency Preparedness & Operational Support 82/08/03 REED, C Commonwealth Edison Co 3pp 14563 338 24X Fiche 50-010.82/08/03.8208270134
- --8208270142 IE Insp Repts 50-010/82-11.50-237/82-15 & 50-249/82-16 on 820624, 29.30 & 0707 Significant test deficiency noted failure of seven prompt public notification sys strens JANUSKA.A Q., GRANT.W B., NICHOLSON,N A. Division of Emergency Preparedness & Operational Support. 82/07/23 12pp. 14563,341 24X Fiche 50-010.82/08/03,8208270134
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl.

 JORDAN, E. Division of Engineering & Quality Assurance 82/08/05

 Consolidated Edison Co of New York 117pp 14388 201 24X

 Fiche 50-000, 82/08/05, 8204210407
- 8208200241 Advises of error in NRC 820719 ltr transmitting IE Insp Repts 50-010/82-06,50-237/82-10 & 50-249/82-11 Page 2 should be replaced w/encl page SPE88ARD, R L Division of Project & Resident Programs 82/08/1: REED. C Commonwealth Edison Co 2pp 14399,031 24X Fiche 50-010,82/08/13,8208200241
- 8208230349 Forwards revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of previously submitted inservice insp & testing program for second 10 yrs Revision necessary to enable insp of LPCI/CCSW HX tube welds RAUSCH, T. J Commonwealth Edison Co 82/08/16, EISENHUT, D O Division of Licensing 2pp 14512,357 24X Fiche 50-237,82/08/16,8208230349
- --8208230357 Revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of inservice (nep & testing program for second 10 years # Cammonwealth Edison Co 82/08/16 3pp 14512 359 24% Fiche, 50-237, 82/08/16 8208230347
- B20B3i0212 Forwards final response to IE Bulletin 80-06, "EBF Reset Controls " Testing of listed mods performed after installation & specifically demonstrated equipment will not reposition from emergency position winitial signal reset. BHARTZ.E D. Commonwealth Edison Co 82/08/20. KEPPLER.J Q. Regio. 3, Office of Director. Spp 14693 148 24X Fiche 50-237.82/08/20, 820B310212.
- 8208310218 Forwards suppl to util 820524 response to IE Bullatin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus Bp (Mussel)."

 SWARTZ.E D. Commonwealth Edison Co. 82/08/23 KEPPLER, J Q Region 3, Office of Director 7pp 14693.130 24X Fiche 50-010,82/08/23, 8208310218

- R Periodic operating reports & related correspondence
- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power glants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records. 82/07/13 UDELL.R A. Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000.82/07/13.8208270010
- --8208270098 "Annual Whole Body Doso At Licensed Nuclear Power Facilities for CYBL" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000,82/07/13,8208270010
- --8208270839 Forwards "Recorded Annual Whole Body External Exposure for CY81," per iOCFR20 407(b) W/o Guad Cities, Zion, LaSalla, Byron & Braidwood repts
 RAUBCH, T J Commonwealth Edison Co 82/03/31 Office of Management and Program Analysis Ip 14680 075 24X
 Fiche 50-000,82/07/13,8208270010
- --B208270567 "Recorded Annual Whole Body External Exposure for CY81" * Commonwealth Edison Co. B2/03/31. ip 14680 076 24X Fiche 50-000, B2/07/13, B208270010
- B20B170242 Forwards monthly operating repts for Jul 1982 SCOTT,D J Commonwealth Edison Co. 82/08/01 Director's Office, Office of Inspection and Enforcement lp 14369 228 24X Fiche 30-010.82/08/01,8208170242
- --B20B170245 Monthly apprating repts for Jul 1982 SCHROEDER.B A Commonwealth Edison Co 82/08/01 18pp 14369 229 24X Fiche 50-010,82/08/01.8208170242
- 8 Reportable occurrences, LERs & related correspondence
- 8208130095 Forwards updated LER 82-014/03X-1 SCOTT, D. J. Commonwealth Edison Co. 82/07/07 KEPPLER, J. G. Region 3, Office of Director 1p. 14335-001 24X Fiche 50-237, 82/07/07, 8208130055
- B20B130052 Forwards updated LER 61-055/03X-1 SCOTT.D J Commonwealth Edison Co B2/07/08 KEPPLER, J 0 Region 3, Office of Director tp 14335-340 24X Ficher 50-237, 82/07/08, 8208130052
- --820Bi30057 Updated LER 81-055/03X-1.on 8i0B30.small leak detected in floor drain dischargs line Caused by butt weld failure on line 2/3-2014 6-inch carbon steel pipe weakened by corrosive solutions Affected pipe section replaced ANANDAPPA.A Commonwealth Edison Ca 82/07/08 Region 3, Office of Director 2pp 14335-361 24X Fiche-50-237,82/07/08,8208130052
- 8208020184 Forwards LER 82-030/01T-0 8COTT.D J Commonwealth Edison Co 82/07/20 KEPPLER.J 9 Region 3. Office of Director 1p. 14141 037 24X Fiche 30-237,82/07/20, 8208020184
- --8208020186 LER 82-030/01T-0.on 820712.during MPCI motor operated valve operability test, steam supply isolation valve 2201-04 failed to close Caused by valve packing leak Valve repacked & motor replaced by valve packing leak Valve repacked & ANANDAPPA.A Commonwealth Edison Co 82/07/23 Region 3, Office of Director 3pp 1414, 038 24X Fiche 50-237,82/07/20, 8208020184.
- 8208090242 Forwards LER 82-026/03L-0 Detailed event analysis encl SCOTT,D J Commonwealth Edison Co 82/07/20. KEPPLER,J 9 Region 3. Office of Director 2pp 14271 088 24X Fiche 50-237.82/07/20, 8208090242
- --8208090245 LER 82-026/03L-0.on 820701.MU2-1501-50 failed to close & breaker tripped. Caused by stuck closed contact in reversing contactor causing short circuit & tripped breaker. Contactor replaced & valve successfully cycled COYLC.L Commonwealth Edison Co 82/07/20 Region 3. Office of Director. Ip 14271.090 24X Fiche.50-237.82/07/20.8208090242.

- 8208030338 Forwards LER 82-024/03L-0 SCOTT-D J Commonwealth Edison Co 82/07/21. KEPPLER, J 0 Region 3. Diffice of Director ip 14157 037 24% Fiche 50-237,82/07/21, 8208030336
- --8208030340 LER 82-024/03L-0 on 820427, dryweil to torus differential pressure drupped to 0 74 psid when HPCI steam supply isolation valve HD 2-2301-4 was automatically closed Caused by packing leak on valve Valve repacted ANANDAPPA, A Commonwealth Edison Co 82/07/23 Region 3, Office of Director 2pp 14157 038 24X Fiche 50-237,82/07/21.8208030338
- 820B090228 Forwards LER 82-025/03L-0 Detailed event analysis encl 8COTT, D J Commonwealth Edison Co 82/07/21 KEPPLER, J Q Region 3. Office of Director 2pp 14271 100 24X Fiche 50-237,82/07/21, B208080238
- --B208090230 LER 82-025/03L-0 on 920701.during testing.LPCI suction valve MG-2-1501-50 failed to open electrically Caused by dirty auxiliary contact in breaker Contact cleaned COVLE.L M Commonwealth Edison Co. 82/07/22 Region 3. Office of Director, 1p 14271 102 24X Fichs 50-237,82/07/21, 8208090228
- 8208130269 Forwards LER 82-028/03L-0 BCDTT, D. J Commonwealth Edison Co 82/08/05 KEPPLER, J G Region 3. Office of Director 1p 14333 072 24% Fiche 50-237,82/08/05, 8208130269
- --8208130272 LER 82-028/03L-0 on 820708, during normal operation w/isolation condenser valve operability test in progress, valve M02-1301-10 failed to close Gaused by bent auxiliary contact in motor control ctr. Contact repaired.

 CGYLE.L. Communumenth Edison Co. 82/08/05. Region 3, Office of Director 2pp 14333.073 24X Fiche 50-237,82/08/05.8208130269
- 8208200053 Forwards LER 82-027/03L-0 SCOTT.D J Commonwealth Edison Co B2/08/09 KEPPLER, J 0 Region 3. Office of Director 1p 14392 184 24X Fichs 50-237, 82/08/09, 8208200053
- --8208200063 LER 82-029/03L-O on 820712, HPCI min flow valve 2-2301-14 failed to reclose after opening Caused by control wire caught under torque switch Wire secured away from torque switch & recycled to verify operability MORRAN.W Commonwealth Edison Co 82/08/02 Region 3, Office of Director, 2pp 14392-185 24X Fiche 50-237,82/08/09, e208200033
- 8208230026 Forwards LER 82-037/03L-0 SCOTT.D J Commonwealth Edison Co 82/08/10 KEPPLER, J 0 Region 3. Office of Director ip 14517 285 24% Fichs, 50-237, 82/08/10, 8208230024
- --B20B230030 LER 04-037/03L-0 on 820724, average power range monitor gain adjustment factor for average power range monitors 4 & 6 exceeded 1 02 while in final hours of 12-h zenon soak period. Caused by changes in flux distribution & lag time SCHROEDER, 8. A Commonwealth Edison Co 82/08/10 Region 3, Office of Director 2pp 14517 286 24X Fiche 50-237, 82/08/10, 8208230026
- 8208230252 Forwards LER 82-036/03L-0 8COTT.D.J. Commonwealth Edison Co 82/08/10 KEPPLER, J 9 Region 3. Office of Director 1p 14508, 358 24X Fiche 50-237, 82/08/10.
- --B20B230259 LER B2-036/03L-0:on B20723, everage gower range monitor gain adjustment factor for ARPMs 2 & 3 exceeded Tech Spec Caused by changes in flux distribution & lag time for instrument mechanic to make gain adjustment BCHROEDER, B A. Commonwealth Edison Co B2/08/10 Region 3, Office of Director 2pp 1450B 359, 24X Fiche 50-237.82/08/10, B20B230252
- B20830012B Forwards LER 82-033/03L-0 SCOTT, D J. Commonwealth Edison Co. 82/08/20 KEPPLER, J. C. Region 3, Office of Director, 1p 14595-354 24% Fiche 50-237, 82/08/20, B20830012B
- --B208300134 LER 82-033/03L-0 on B20722; reactor water cleanup valve MD-2-1201-3 failed to close upon close signal Apparently caused by sticky limit switch contact that bypasses torque switch in close direction & lack of valve stam lubrication GARNIER-P. Commonwealth Edison Co. 82/08/20 Region 3, Office of Director 2pp 14595;355. 24X Fiche 50-237,82/08/20,8208300128

- 8208310092 Forwards LER 82-035/03L-0 SCOTT,D J Commonwealth Edison Co 82/08/25 KEPPLER,J G Region 3. Office of Director 1p 14689 300 24% Fiche 50-237,82/08/23, 8208310092
- --B20B310094 LER B2-035/03L-0 on B20724, offgas flow indicated high during normal startup Caused by cracked fillet weld in 2D1 feedwater heater emergency spill to normal heater drain line connection Held cracked due to srcessive line movement CHRISTEL, B Commonwealth Edison Co 82/08/23 Region 3, Office of Director 2pp 14689 301 24X Fiche 50-237,82/08/23,8208310092
- 8208310270 Forwards LER 82-034/03L-0 SCOTT.D J Commonwealth Edison Co 82/08/23 KEPPLER.J G Region 3. Office of Director 1p 14688 144 24X Fiche 80-237,82/08/23, 8208310270
- --8208310279 LER 82-034/03L-0 on 820726.pinhole leak discovered in 1-inch diameter HPCI drain pot drain line 2-2323-1-LX to main condenser Cause unknown Temporary patch installed & area decontaminated Deviation rept encl GARNIER:P J Commonwealth Edison Co 82/08/23 Region 3, Office of Director 2pp 14688 145 24X Fiche 50-237,82/08/23, 8208310270
- DOCKET 50-241 H1881881PPI STATE UNIV RESEARCH REACTOR

 Inspection reports, IE Bulletins & correspondence
- B20B16042B Forwards IE Insp Rept 50-241/82-01 on 820621-22 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/07/19 CARLEV.C T Mississippi State Univ 2pp 14349 258 24X Fiche 50-241/82/07/19,820816042B
- --B208160437 IE Insp Rept 50-241/82-01 on 820621-22 No noncompliance noted Hajor areas inspected, survey for residual contamination after disposal of contaminated reactor components

 ALBRIGHT: R H . BARR, K P Division of Engineering & Technical Programs B2/07/13 3pp 14347 260 24X Fichs 50-241,82/07/19, B208160428
- DOCKET 50-243 OREODN STATE UNIV RESEARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice Bi-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ. of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- DOCKET BO-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

 D NRC Draft/Final Environmental Statements, suppls & correspondence
- B20B110100 Requests review of existing FEB, dtd Dec 1973 to determine fearibility of license conversion Comments re significant changes to fecility or environs should be submitted within 30 days of receipt of ltr CRUTCHFIELD.D Deparating Reactors Branch 5 82/08/06 MAIER.J E Rochester das & Electric Corp 2pp 14317.178, 24X Fiche 50-244.82/08/06.8208110100
- F Security, medical, emergency & firs protection plans
- 8208020193 Releases public version of revised emergency plan implementing procedures.
 FELTON.J.H Division of Rules and Records 82/07/13, Document Hanegement Branch ip 14179 162, 24X Fiche 50-244,82/07/13, 8208020193
- --8208020194 Forwards public version of revised emergency plan implementing procedures, including Procedures 8C-213 rescountability of personnel.8C-233 research & rescus operation & 8C-322 remaining of smergency survey ctr HAIER. J. E. Rochester Cas & Electric Corp. 82/06/30, CRUTCHFIELD.D. Operating Reactors Branch 5 1p. 14179-163 24X fiche.50-244,82/07/13,8208020193
- --B20B020199 Public version of revised emergency plan implementing
 procedures, including Procedures SC-213 re accountability of
 personnel, SC-203 re search & rescue operation & SC-322 re
 manning of emergency survey ctr.
 BDDINE, J C. Rochester Qas & Electric Corp. 82/04/25, 16pp.
 14179 164 24X Fiche. 50-244, 82/07/13, 8208020193

- 8208030363 Forwards response to NRC 820507 ltr re request for exemption from 72-h requirement for achieving cold shutdown following fire in auxiliary bldg RHR pit zone Cold shutdown can be achieved & maintained within 72-h of plant shutdown MAIER. JE Rochester Gas & Electric Corp 82/07/28 CRUTCHFIELD, D Operating Reactors Granch 5 10pp 14158 103 24X Fiche 50-244, 82/07/28, 8208030363
- 8208030250 Forwards Amend 53 to License DPR-18, safety evaluation & notice of issuance & availability Amend approves provisions updating firs protection sys operability & surveillance requirements
 GRUTCHFIELD, D. Operating Reactors Branch 5 82/07/29 MAIER, J E Rochester Cas & Electric Corp. Rep. 14158 230 24X
 Fiche 50-244, 82/07/29, 8208030250
- --8208030253 Amend 53 to License DPR-18, approving provisions which update fire protection sys operability & surveillence requirements CRUTCHFIELD, D. Operating Reactors Branch 5 82/07/29 12pp. 14158 232 24K Fiche 50-244, 62/07/27, 6208030250
- --8208030259 Bafety evaluation supporting Amend 53 to License DPR-18
 * Office of Nuclear Reactor Regulation, Director 62/07/29 4pp
 14158,244, 24X Fiche 50-244,82/07/29,8208030250
- --820B030260 Notice of issuance & availability of Amend 53 to License DPR-18. CRUTCHFIELD, D Operating Reactors Branch 5 82/07/29 2pp 14158:248 24X Fiche 50-244,62/07/29.8208030250
- 8208060074 Releases public version of revised emergency plan implementing procedure. FELTON.J.H Division of Rules and Records 82/08/02, Document Management Branch 1p 14283.091 24X Fiche 50-244,82/08/02,820806074
- --B20B060079 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure 8C-452, "Bampling Bnow. Crass. Boil & Vegetation." MAIER, J.E. Rochester Cas & Electric Copp. 82/07/21 CRUTCHFIELD. D. Operating Reactors Branch 5 ip. 14283 092 24X Fiche 50-244,82/08/02:8208060074
- --B20B060081 Public version of Revision 1 to Emergency Plan Implementing Procedure 8C-452. "Bampling Snow.Grass.Boil & Vegetation " BODINE, J. C Rochester Gas & Electric Corp. B2/07/16. App 14283 093 24X Fiche 50-244, 82/08/02. B20B060074.

O. Adjudicatory correspondence

- 8208020213 Response to ASLB 820708 order re-status of hearing Discussion of matters re-discovery.prehearing conferences & hearings are premature & should be postponed pending issuance of documents. Gertificate of Svc encl VOIOT.H H Rochester Oas & Electric Corp. VOIOT.H H LeBoeuf, Lamb, Leiby & MacRae B2/07/30 Spp. 14141.115 24X Fiche 50-244.82/07/30.8208020213
- 8208020231 Response to ASLB 820708 order to submit status rapt. Immediate prehearing conference or conversion hearing not naeded due to uncertainty re completion of integrated safety assessment & conversion SER.W/Cartificate of SVc. YOUNG, M.A. Hearing Branch 4 82/07/30 7pp. 14152:337, 24X Fichel 50-244, 82/07/30, 8208020231.
- D. Advisory Committee on Reactor Safeguards reports & correspondence
- 8208230274 Discusses ACR9 267th meeting on 820708-10 rs SEP Phase II review Stated objectives achieved & NRC actions on SEP assessment acceptable.

 8HEWMON, P. ACR8 Advisory Committee on Reactor Bafeguards 82708/18, PALLADINO, N.J. Commissioners. 3pp. 14513 202, 24X Fiche 50-244, 82/08/18, 8208230274.
- P. Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CP re Commission approved charter for CRGR Byc IIst and DIRCKB.H J Office of the Executive Director for Operations. 82/07/02 Consolidated Edison Co of New York. 93pp. 14194:001. 24X Pithe 50-000,82/07/02,8207080064
- 8208030250 Forwards Amend 53 tp License DPR-18, sefety evaluation & notice of issuance & availability Amend approves provisions updating fire protection sus operability & surveillance requirements CRUTCHFIELD, D Operating Reactors Branch 5, 82/07/29, MAIER, J. E. Rochester Oas & Electric Corp. 2pp. 14158 230 24X Fiche: 50-244, 82/07/27, 8208030250.

- --8208030283 Amend 53 to License DPR-18, approving provisions which update fire protection sys operability & surveillance requirements. CRUTCHFIELD, D Operating Reactors Branch 5 82/07/29 12pp 14188 232 24X Fiche 50-244, 82/07/29, 8208030250
- --8208030259 Safety evaluation supporting Amend 53 to License DPR-18.

 Office of Nuclear Reactor Regulation Director. 82/07/29, 4pp.
 14158 244 24X Fitch 50-244,82/07/29,820830230.
- --8208030260 Notice of issuance & availability of Amend 53 to License DPR-18. CRUTCHFIELD.D. Operating Reactors Branch 5. 82/07/29 2pp. 14158 248 24X Fiche 50-244,82/07/29.8208030250.
- 8208030519 Comments on SEP.Phase II SEP-like program incorporating experience of SEP (minimal topics, acceptable alternative to SRP & integrated assessment) is of safety benefit MAIER, J & Rochester Qas & Electric Corp 82/07/30. CRUTCHFIELD, D. Operating Reactors Branch 5 App. 14163 244 24% Fiche 50-244, 82/07/30, 8208030517
- 8208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Bummarires 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl.
 EISENNUT. D G. Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14354:332 24X Fiche 50-000,82/08/09,8208090194.
- 8208170164 Forwards application for amend to License DPR-18.proposing Tech Spec change to permit operation at both current & reduced primary sys temp & pressure.

 MAIER.J.E Rochester Oas & Electric Corp. 82/08/07 DENTON, H
 Office of Nuclear Reactor Regulation, Director. 1p. 14365;012. 24X
 Fiche.50-244,82/08/07.8208170164.
- --8208170173 Application for amend to License DPR-18, proposing Tech Spec change to permit operation at reduced primary sys pressure & temp MAIERJ E. Rochester Oas & Electric Corp. 82/08/09 2pp. 14365:013. 24X Fiche.50-244.82/08/09.8208170164.
- --8208170181 Proposed Tech Specs 1 0 & 2 3 & Table 3 5-2 re definitions, limiting safety sys settings & protective instrumentation applicability & emergency cooling, respectively Safety evaluation encl.

 ** Rochester Oas & Electric Corp. 62/08/09. 17pp 14365:015. 24% Fiche:50-24%, 82/08/09, 8208170164.
- --B208170188 "Plant Transient Analysis for Deeration of RE Ginna Unit i Nuclear Power Plant at Reduced Pressure & Temp." NUTT.M.T., CODKE, G.C., MORGAN, J.N. Exxon Nuclear Co., Inc. (subsof Exxon Corp.) XN-M-82-65 ROL. 82/07/22, 97pp 14365:032. 24X Fiche. 50-244, 82/08/09, 8208170164.
- ---8208170206 "RE Ginna Nuclear Plant Cycle 12 8AR for Low Temp & Pressure."
 NIELBEN, L. A., COPELAND, R. A., KRAJICEK, J. E., Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-82-57. 82/07/20 44pp, 14365:130 24X Fiche: 50-244,82/08/09.8208170164.
- 8208170214 Forwards application for amend to License DPR-18, revising Tach Spacs to incorporate radiological effluent Tech Specs. Change supersedes 790214 proposal. HAIER, J. E. Rochester Que & Electric Corp. 82/08/12. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 19. 14361.234. 24X Fiche: 80-244, 82/08/12, 8208170214
- --8208170216 Application for amend to License DPR-18, revising Tech Baecs to incorporate radiological effluent Tech Space.

 MAIER, J. E. Rochaster Oas & Electric Corp. 82/08/13 2pp.
 14361 235. 24X Fiche 30-244.82/08/12.8208170214.
- ----8208170220 Proposed Tech Specs incorporating radiological effluent Tech Specs Bafety evaluation encl. • Rochester Ges & Electric Corp 82/08/12. 80pp 14361:237. 24X Fiche: 50-244, 82/08/12,8208170214.
- 8208240149 Requests that rept of relief & safety valve failures & challenges be included in next annual rept, per TMI Action Item II K J. 3. "Reporting Relief & Bafety Valve Failures & Challenges." Commitment resolves item. CRUTCHFIELD. D. Operating Reactors Branch 5 82/08/18 MAIER, J E. Rochaster Oas & Electric Corp. 2pp. 14519, 359. 24% Fiche: 50-244, 82/08/18, 8208240149.

- 8208240331 Forwards "Control of Heavy Loads (C-10), Rothester Gas & Electric Corp.RE Ginna Nuclear Power Plant, " draft technical evaluation rept per 820201 response to 801222 generic ltr. After 4-wk review period.conference call will be arranged CRUTCHFIELD.D Operating Reactore Branch 5 82/08/19 MAIER, J E Rochester Gas & Electric Corp. 2pp. 14528 044 24X fiche 50-244.82/08/19.8208240331
- --8208240344 "Control of Heavy Loads (C-10), Rochester Oas & Electric Corp. RE Ginna Nuclear Power Plant," draft technical evaluation rept
 HOFKIN.T Franklin Institute/Franklin Research Center
 TER-C5257-444 DRFT 82/08/10 CLEMENSON.F NRC No Detailed
 Affiliation Given 29pp 14528 046 24X Fiche 50-244, 82/08/19, 8208240331
- 8208300249 Notifies that response to 820617 request for status info re unresolved safety issues will be provided by late Sept 1982 for inclusion in safety evaluation No short-term safety implication associated w/response delay MAIER. J E Rochester Oas & Electric Corp 82/08/20 CRUICHFIELD. D Operating Reactors Branch 5 ip 14679 136 24X Fiche 50-244.82/08/20.8208300249
- 8208310335 Forwards response to open items noted in draft SEP Integrated Plant Safety Assessment Rept.NUREO-0821 Every sffort will be made to ensure task completion within schedule HAIER.J E Rochester Gas & Electric Corp 82/08/25 CRUTCHFIELD, D Operating Reactors Branch 5 7pp 14694 323 24X Fichs 50-244, 82/08/25, 8208310335
- 8208310327 Forwards Page 4 15-2 of Tech Specs re scheduling functional tests.inadvertently omitted from Amend 53 to License DPR-18, forwarded by NRC 820727 ltr
 CRUTCHFIELD.D Operating Reactors Branch 5 82/08/26 MAIER, J E Rochester Qas & Electric Corp 3pp 14692 145 24X
 Fiche 30-244, 82/08/26, 8208310329

Q Inspection reports, IE Bulletins & correspondence

- 8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leatage " Syc list Encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14354, 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210375 IE Info Notice 81-26,Part 3,Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/19 Michigan,
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure," Svc list encl
 JORDAN-E L Division of Engineering & Quality Assurance 82/07/20
 Consolidated Edison Co of New York 112pp 14381 001 24X
 Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacts" Syc list enc!
 COSB, L I Division of Fuel Facilities, Materials & Safeguarde 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- B204210398 IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Bvc list encl JORDAN: EL Division of Engineering & Quality Assurance B2/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance, B2/07/23 Consoliated Edison Co of New York 122pp 14380 115 24X Fiche 50-000,82/07/23.8204210401
- 8204210402 IE Info Notice 82-29, "Control Rad Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche: 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Wastinghouse PWR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403

- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Hori in Fuel Btorage Pool " Bvc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 144 24x Fishe 50-000.82/07/28.8204210405
- 8208020223 Ack receipt of 820716 ltr informing NRC of stops taken to correct violations noted in IE Insp Rept 50-244/82-10 STAROSTECKI, R Division of Project & Resident Programs 82/0//29 MAIER, J E Rochestor 0ss & Electric Corp 1p 14151 219 24x Fiche 50-244,82/07/29,8208020223
- --8208020228 Responds to NRC 820616 ltr re violations noted in IL Insp Rept 50-244/82-10 Corrective actions GC inspectors made aware of incident & instructed to discuss contents of all surveilliance repts when submitting repts for review MAIER. J E Rochaster Gas & Electric Corp 82/07/16 DRUNNER, E. J Division of Project & Resident Programs 2pp 14151 220 24x Fichs. 50-244, 82/07/29, 82080202223
- 820B120100 Forwards IE Insp Rept 50-244/82-13 on 820628-0701 No noncompliance noted MARTIN T T Division of Engineering & Technical Programs 82/07/29 MAIER, J E Rochester Oas & Electric Corp 2pp 14324 242 24X Fiche 50-244,82/07/29,8208120100
- --B208120104 IE Insp Rept 50-244/82-13 on B20628-0701 No noncompliance noted Major areas inspected followup on IE Circular 80-21, verification of core load, post-refueling startup testing & control rod worth measurements & predications PETRONE.C D , BETTENHAUSEN,L Division of Engineering & Technical Programs 82/07/20 7pp 14324 244 24X Fiche 50-244.82/07/29, 8208120100
- B20B09004B Forwards response to IE Bulletin B2-02. "Degradation of Threaded Fasteners in RCPB of PWR Plants" Rept identifies bolted closures experiencing leakage since plant startup Rept will follow 1983 outage for remaining items MAIER, J E Rochester Gas & Electric Corp 82/07/30 HAYNEB, R C Region 1, Office of Director 2pp 14270 032 24X Fiche 50-244, 82/07/30, 8208070048
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp. 14388 RO1 24X Fiche 50-000, 82/08/05, 9204210407
- 8208300044 Forwards IE Insp Rept 50-244/82-09 on 820903-06 & notice of violation MARTIN,T T Division of Engineering & Technical Programs 82/08/13 MAIER, J E Rockester Oas & Electric Corp 2pp 14598 211 24X Fichs 50-244, 82/08/13, 8208300044
- --B208300045 Notice of violation from insp on B20803-06
 ** Region i, Office of Director B2/08/13 ip 14598 313 24%
 Fiche 50-244,82/08/13,8208300044
- --B20B300047 IE Insp Rept 50-244/82-07 on B20503-06 Noncompliance noted failure to follow requirements of special work permit procedure MCGRIDE,M H , GREENMAN, E Q Division of Engineering & Technical Programs 82/08/11 10pp 14598 314 24X Fiche 50-244, 82/08/13, 820B300044
- 8208300048 Forwards IE Insp Rept 80-244/82-14 on 020701~31 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/08/16 MAIERJE Rochester Oas & Electric Corp 2pp 14378,324 24X Fiche 50-244,82/08/16,8208300048
- --8208300090 Notice of violation from insp on 820701-31.
 STAROSTECKI.R Division of Project & Resident Programs 82/09/16
 1p 14598 326 24X Fiche 80-244, 82/08/16, 8208300048
- --B20B300052 IE Insp Rept 50-244/82-14 on B20701-31 Noncompliance noted failure to perform auryeillance test within required frequency ZIMMERMAN.R.P. Region 1. Office of Director KIBTER.H B Division of Project & Resident Programs 82/08/13 Bpp 1459B 327 24X Fiche 50-244,82/08/16.820830004B
- R Periodic operating reports & related correspondence
- 8208120245 Forwards monthly operating rept for June 1982, SNOW, B. A. Rochester Cas & Electric Corp 82/07/09, Office of Management and Program Analysis ip 14326 341 24X Fiche 50-244,82/07/09,8208120245

- --B208120247 Monthly operating rept for June 1982 KNAMARA:A E Rochester Gas & Electric Corp 82/07/07 6pp 14326 342 24X Fichs 50~244.82/07/09.8208120245
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270546 Forwards "Btd Rept of Personnel Whole Body Exposure (REM) By Exposure Groups for 1981," per 10CFR20 407 MAIER.JE Rochester Gas & Electric Corp 82/03/31 Office of Management and Program Analysis 1p 14680 068 24X Fiche 80-000,82/07/13,8208270010
- --8208270549 "Btd Rept of Personnel Whole Body Exposure (REM) By Exposure Groups for 1981 " MAIER, J.E. Rochestor Gas & Electric Corp. 82/03/31 ip 14680 069 24X Fiche 50-000, 82/07/13, 8208270010
- B Reportable occurrences, LERs & related correspondence
- 8208020266 Forwards LER 82-014/03L-0.
 MAIER, J E Rochester Gas & Electric Corp 82/07/22 HAYNEB,R C
 Region 1, Office of Director 1p 14152 310 24X
 Fiche 50-244, 82/07/22, 8208020266
- --8208020274 LER 82-014/03L-0 on 820624, discharge check valve 8628 on containment spray pump failed to close at required differential pressure Caused by wear on pin & swing arm Parts will be replaced during next outage SPECTOR.S M Rochester Oas & Electric Corp 82/07/22 Region 1, Office of Director 1p 14152 311 24X Fiche 50-244,82/07/22,8208020266
- 8208020313 Forwards LER 82-015/03L-0 MAIER, J E Rochester Gas & Electric Corp 82/07/24 HAYNES, R C Region 1, Office of Director 1p 14151 128 24X Fiche 50-244, 82/07/24, 8208020313
- --B208020321 LER B2-015/03L-O on 820622.at steady-state 100% operation, periodic test identified faulty sealing of containment gas radiation monitor return line check valve Caused by dirt deposits from veins of monitor pump SPECTOR, S M Rachester Gas & Electric Corp 82/07/24 Region 1. Office of Director 1p 14151 127 24X Fiche 50-244,82/07/24,8208020313
- 8208060030 Forwards incident reporting sys repts re effects of fire protection sys actuation on safety-related equipment & seismic qualification of safety-related sys for transmission to NEA MICHELBON.C Director's Office 82/07/27 LAFLEUR.J.D. Office of International Programs. Director. 2ipp 14244-315 24X Fiche 50-000,82/07/29.8208060030
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

 F Becurity, medical, emergency & fire protection plans
- 8208050388 Forwards "Fire Protection App R Review, Millstone Unit 1." supplemental info, supporting 810319 request for exemption from App R requirements.

 GOUNBIL, W O. GAONETTA, J P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). GOUNBIL, W.O. Northeast Utilities 82/07/16 EISENHUT, D G. Division of Licensing 7pp 14209 001 24X Fithe 50-245. 82/07/16, 8208050388
- --8208050395 "Fire Pratection App R Review.Millstone Unit 1," supplemental info
 * Northeast Utilities 82/07/31 140pp 14209 008 24X Fiche 50-245,82/07/16.8208050388
- 9208030013 Releases public version of revised emergency plan implementing procedures.
 FELTON.J.M Division of Rules and Records 82/07/20 Document Management Branch ip 14201.001 24X Fiche.50-000.82/07/20, 8208030013.

- ---8208030019 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4102 re alert, EPIP 4103 re site area emergency & EPIP 4104 re general emergency * Connecticut Yankee Atomic Power Co * Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/07/20 718pp 14201 005 24X Fiche 50-000, 82/07/20, 8208030013
- 8208050082 Forwards IE Safeguards Insp Repts 50-245/82-11 & 50-336/82-11 on 820524-28 & notice of deviation Insp rept details & notice of deviation withheld (ref 10CFR73 21) MARTIN:T T Division of Engineering & Technical Programs 82/07/21 COUNBIL:H @ Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 14213 203 24X Fiche 50-245,82/07/21,8208050082
- --8208050085 IE Safeguards Insp Repts 50-245/82-11 % 50-334/82-11 on 820524-28 Deviation noted failure to meet commitment Details withheld (ref 10CFR73 21) COOAN,N J. GDDY,A T. Region i, Office of Director 82/07/19 ip 14213 205 24X Fiche 50-245,82/07/21,8208050082
- 8208060267 Submits addl clarifications of 820301 App R review for facilities in response to NRC 820625 & 0707 requests
 CDUNSIL W O Connecticut Vankee Atomic Power Co CDUNSIL W O
 Northeast Nuclear Energy Co (subs of Northeast Utilities).
 82/07/30 CLARK,R A Operating Reactors Syanch 3 CRUTCHFIELD,D
 Operating Reactors Byanch 5 10pp 14241 196 24X
 Fiche 50-000,82/07/30,8208060267
- 8208090312 Advises that fee sent w/820120 application for exemption from safeguarding requirements of 10CFR73 21 will be refunded MILLER, W O License Fee Management Branch 92/07/30 CDUNBIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) lp. 14307 323 24X Fiche 50-000, 82/07/30, 8208090312
- 8208160340 Forwards suitability, training & qualification plan Flan withheld (ref 10CFR2.790)
 ADDY:R J Northeast Utilities Service Co 82/08/04 DENTON, H. R. NRC NO Detailed Affiliation Given 1p 14348 067 24X
 Fiche 50-245
- 8208250494 Responds to 820A03 ltr re Revision 9 to modified amended security plan Revised Page 12-2 should be changed to incorporate commitment to maintain isolation zone CRUTCHFIELD.D Operating Reactors Branch 5 82/08/11 COUNSIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 14562.254 24X Fiche 50-245.82/08/11.8208250494
- 82083:0468 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 62/08/11 Document Management Branch 1p 14697.343 24X Fiche 50-245,82/08/11.
- ---820B310471 Forwards public version of revised emergancy plan implementing procedures including Procedures EPIP, 4105, "Bomb Threat" & EPIP Form 4105-1, "Bomb Threat Bearch Checklist Unit 1 Shift Supervisor/Designes"

 COUNSIL.W O Nortbeast Nuclear Energy Co. (subs of Northeast Utilities). 82/07/30 EIESNHUT,D G Division of Licensing 1p 14697 344 24X Fithe 50-245,82/08/11.820B310468
- --B208310473 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4105, "Bomb Threat" & EPIP Form 4105-1, "Bomb Threat Bearch Checklist Unit 1 Shift Supervisor Designee"

 * Northeast Nuclear Energy Co (subs. of Northeast Utilities), 82/07/20 22pp 14497 345 24X Fiche 50-245,82/08/11.8208310448
- H General correspondence
- 8208250135 Notifies of recent changes in util organization reflected in GA program topical rept Revision 4A Details encl COUNSIL.W G., CAONETTA-J P. Northeast Utilities Service Co 82/08/17 HAASB-M P. Guality Assurance Branch 7pp 14541,302. 24X Fiche 50-000.82/08/17,8208250135
- P Operating license stage documents & correspondence
- 8208020076 Advises that facilities fully meet position of NUREO-0737, Item III D 3 3, "Improved In-Plant Iodine Instrumentation Under Accident Conditions," No deviations requested COUNBIL.W 9, Connecticut Yankee Atomic Power Co COUNBIL.W 0, Northeast Nuclear Energy Co, (subs of Northeast Utilities) 82/07/20 CRUTCHFIELD D Derating Reactors Branch 3, 1p 14144 106 24X Fichs 50-000, 82/07/20, 8208020076.

- 8208020244 Notifies of proposed programmatic change to QA program topical rept. Revision 4A Exception to Paragragh 1 4 of ANSI N45. 2 9-1974 re definition of QA records will be added to App F of topical rept COUNSIL. W Q Northeast Utilities Service Co COUNSIL. W Q Northeast Utilities 82/07/26 FMASS. W P Quality Assurance Branch 2pp 14152 234 24X Fiche 30-000.82/07/26.8208020244.
- 8208050179 Comments on NRC draft evaluation of SEP Topic IX-5 reventilation sys, transmitted in NRC 820510 ltr Util considers NUREO-0737.ttem [I B.2 to be of no consequence & resolved COUNSIL.W. O Northeast Nuclear Energy Co (subs of Northeast Utilities). 82/07/29 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 14212:069. 24X Fiche 50-245,82/07/29,8208050179
- 8208060231 Bubmits comments on BEP Phase II, to assist NRC in development of proposed program for Phase III.
 COUNBIL, W O Connecticut Yankse Atomic Power Co COUNBIL, W O Northeast Nuclear Energy Co. (subs of Northeast Utilities)
 82/07/30 CRUTCHFIELD.D. Operating Reactors Branch 5 Spp
 14241 323 24X Fiche 50-000, 82/07/30, 8208060231
- 8208060279 Provides further response to NRC 801222 request for info re NVREO-0612, "Control of Heavy Loads at Nuclear Power Plants "Schedule for completion of remaining work expected by 820827.
 CDUNSIL.W O, Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL.W O. Connecticut Yankee Atomic Power Co 82/07/30 EISENHUT, D. G Division of Licensing. 6pp. 14241 088 24X Fiche: 30-000, 82/07/30, 8208060279
- 8208100001 Confirms validity of assumption that design of control rod drive sys practudes operation of more than one control rod, excluding reactor trip, in response to draft avaluation of SEP Topic IV-2. W/six sperture cards Aparture cards in PDR COUNSIL. M. 0. CAONETTAL J. P. Northeast Nuclear Energy Co (subs. of Northeast Utilities). 82/08/02. CRUTCHFIELD. D. Operating Reactors Branch 5 2pp. 14298-235. 24X Fiche. 50-245-82/08/02. 8208100001
- 8208050490 Forwards revised final evaluation of SEP Topic II-1 C rapotential hazards due to nearby transportation.
 Institutional, industrial & military facilities Facility meets current licensing criteria.
 SHEALJ Operating Resettra Branch 5 82/08/04 COUNSIL, W.O. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 7pp. 14237:281, 24X Fiche 50-245,62/08/04,6208050460
- 8208250545 Forwards draft technical evaluation rept "Control of Heavy Loads (C-10)," based on responses to Section 2 1 of 801222 generic ltr Comments requested within 30 days of receipt of ltr. CRUICHFIELD,D. Operating Reactors Branch 5. 82/08/04 CDUNSIL,W G. Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp. 14562.212 24% Fiche: 30-245,82/08/04.8208230545
- --8208250548 "Control of Heavy Loads (C-10)," draft technical avaluation rept
 HOFKIN.T. Franklin Institute/Franklin Research Center.
 NRC-03-79-118. TER-C5257-451 DRFT. B2/07/27 NRC No Detailed Affiliation Given 27pp. 14562.214. 24X Fiche 50-245,82/09/04,8208250848
- 8208160074 Forwards add1 info re individuals experience, college ed & current operator licenses, per NUREO-0737. Item I A.1.1, "Shift Technical Advisor." GOUNSIL.M.O., CAONETTAJ.P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL,M.O., Continue Counsil,M.O., Northeast Utilities 82/08/06, EIBENHUT.D.O. Division of Licensing. 3pp 14342 114 24X Fiche-50-245, 82/08/06, 8208160074
- B208170218 Forwards detailed technical description of evaluation & findings re combustible gas control Evaluation demonstrates that primary means of combustion gas control is nitrogen inerted containment.

 COUNSIL.M. 9. CAONETTA. J. P. Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL.M. 9. Northeast Utilities Bervice Co. B2/08/06. DIRCKB.W. J. Office of the Executive Director for Operations 350pp. 14499-073 24X Fiche. 50-245,82/08/06,82/08/0218
- 8208090194 Generiz Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl. EIBENHUT, D 9. Division of Licensing 82/08/09 Consulidated Edison Co of New York. Ip 14356:332 24X Fiche 50-000.82/08/09, 8208090194
- 8208190279 Submits no comment re draft evaluation of SEP Topic III-07 B. "Design Codes,Design Criteria & Load Combinations." Goincident setsmic & LOCA events inappropriate for inclusion in design basis of plant COUNSIL.# 0. Northeast Nuclear Energy Co (subs. of Northeast Utilities). 82/08/11. CRUICHFIELD,D. Operating Reactors Branch 5, ip. (4387:347. 24X Fiche;50-245,82/08/11,8208190279.

- 8208200072 Application to smend Licenses DPR-21 & DPR-45, incorporating revised radiological ETS in safety Tech Specs (Subs of Northeast COUNSIL, W 9 Northeast Nuclear Energy Co (Subs of Northeast Utilities) COUNSIL W 0 Northeast Utilities 82/08/12 CLARK.R A Operating Resolvers Branch 3 CRUTCHFIELD, D Operating Resolvers Branch 5 5pp 14392 010 24% Fiche 50-245,82/08/12,8208200072
- --8208200080 Proposed revisions to radiological ETB for incorporation into safety Tech Specs

 * Northeast Nuclear Energy Co (subs of Northeast Utilities)
 82/08/31 175pp 14392 015 24X Fiche 50-245.82/08/12,
 8208200072
- 8208240384 Forwards addl info re NUREO-0737. Item II K 3 17, "ECCS Outages." in response to NRC 820622 request COUNSIL,N 0 . OPEKA.J F Connecticut Yankes Atomic Power Co COUNSIL,W 0 . Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/08/16 CRUTCHFIELD.D Operating Reactors Branch 5 CLARK.R A Operating Reactors Branch 3 23pp 14524 045 24X Fichs 50-000, 82/08/16, 8208240384
- 8208200238 Notification of 820914 meeting w/Northeast Nuclear Energy Co in BethesdarMD to discuss licensee 820806 rept & supplemental into re-post-LOCA oxygen formation by water decomposition due to radiolysis SHEA-J J Operating Reactors Branch 5 82/08/19, CRUTCHFIELD, D, Operating Reactors Branch 5 3pp 14399 083 24X Fiche 50-245, 82/08/19, 8208200238
- 8208310306 Forwards offsits dose calculation manual, providing parameters & methodology for offsite dose & effluent monitor setpoint calculator COUNSIL.W O Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 82/08/20 CLARK, R.A. Operating Reactors Branch 3 ip 14688, 037 24% Fiche 50-245, 82/08/20, 8208310306
- --8208310310 Offsite dose calculation menual providing parameters & methodology for affsite dose & effluent monitor setpoint calculation
 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 82/08/31 86pp 14688.058 24X Fiche.50-245.82/08/20.8208310306
- Q Inspection reports. IE Bulletins & correspondence
- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN: E L Division of Engineering & Quality Assurance 82/07/16. Consolidated Edison Co of New York, 87pp 14356 274 24X Fithe, 50-000 82/07/16, 8204210373
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E.L. Division of Engineering & Quality Assurance 82/07/20. Consolidated Edison Co. of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210376.
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks " Byc list encl COBB.L I Division of Fuel Facilities. Haterials & Bafeguards, 82/07/20. Consolidated Edison Co. of New York 7ipp 14357.276 24X Fiche 50-000.82/07/20,8204210397
- 8208030082 Forwards IE Safeguards Insp Repts 50-245/82-11 & 50-336/82-11 on 820524-28 & notice of deviation Insp rept details & notice of deviation withheld (ref 10CFR73 21) MARTIN, T.T. Division of Engineering & Technical Programs 82/07/21 CDUNSIL, W.O., Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 2pp 14213 203 24X Fichs 50-245,82/07/21,8208050082
- --B2080800B5 IE Safeguards Insp Repts 50-245/82-11 & 50-336/82-11 on B20524-28 Deviation noted failurs to meet commitment Details withheld (ref 10CFR73 21) COGAN.N J. ODDY, A. T. Region 1, Office of Director B2/07/19, 1p 14213:205 24X Fiche 50-245.82/07/21.8208050082
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/22. Consolidates Edison Co of New, York 112pp 14194, 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydragen Explosion While Grinding in Vicinity of Drained & Open RCB " Evc list encl UDRDAN,E L. Division of Engineering & Guality Assurance, 82/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401

- B204210402 IE Info Notice B2-29, "Control Rod Drave (CRD) Ouide Tube Support Pin Failures at Westinghouse PHRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl. JORDAN.E L Division of Engineering & Quality Assurance 82/07/26. Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210403 IE Info Notice 82-31, "Oversxposure of Diver During Work in Fuel Storage Pool" Svc list encl JURDAN.E L. Division of Engineering & Quality Assurance 82/07/28, Consolidated Edison Co of New York 122pp 14357 146 24X Fichs. 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Saffle Water-Jet Impingement " Svc list enc!
 JORDAN,E L Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000.82/08/05.8204210407
- B208300065 Forwards IE Insp Repts 50-245/82-10 & 50-336/82-14 on 820621-25 & notice of violation MARTIN,T T Division of Engineering & Technical Programs B2/08/13 COUNSIL,W @ Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 14598 341 24X Fiche: 50-245,82/08/13,8208300065.
- --8208300068 IE Insp Repts 50-245/82-10 & 50-336/82-14 on 820621-25 Noncompliance noted failure to maintain procedures & engineering drawings. NAPUDA.O. BISSETT.P., MEYER.O. Division of Engineering & Technical Programs 82/08/12 20pp 14598 345 24X Fiche 50-245,82/08/13.8208300065
- R Pariodic operating reports & related correspondence
- 820B120090 Forwards monthly operating rept for June 1982 MROCZKA,E J Northeast Nuclear Energy Co. (subs of Northeast Utilities) MROCZKA,E J Northeast Utilities 82/07/12 Office of Resource Management, Director 1p 14327.139 24X Fiche 50-245,82/07/12.8208120090
- --8208120091 Monthly operating rept for June 1982 HARRAN, O Northeast Nuclear Energy Co (suds of Northeast Utilities) 82/07/07 App 14327 140 24X Fiche 50-245, 82/07/12.8208120090
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said infe Forwards documents listed in App A FELTON.J M. Division of Rules and Records 82/07/13 UDELL.R.A Critical Mass Energy Project 8pp 14679 208 24% Fiche 30-000.82/07/13.8208270010
- --B20B27009B "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYG1" # NRC - No Detailed Affiliation Given B2/07/13 48pp, 14679 216 24K Fiche 50-000, B2/07/13.B20B270010
- --8208270541 Forwards "Reporting of Recorded Personnel Whole Body Exposures for CY81." per 10CFR20 407
 MRCCZKA: E J Northeast Nuclear Energy Co. (subs of Northeast Utilities) 82/03/31 Office of Management and Program Analysis Ip 14680 046 24X Fiche.50-000,82/07/13,8208270010.
- --8208270543 "Reporting of Recorded Personnel Whole Body Exposures for CYBI " * Northeast Nuclear Energy Co (subs. of Northeast Utilities), 82/03/31 ip. 14680 067 24X Fiche 80-000, 82/07/13, 8208270010,
- S Reportable occurrences: LERs & related correspondence
- 8208260488 LER 81-004/01T-O on 810421, reactor manual scram & blowdown/ cooldown subsequent to main turbine & condenser failure resulted in reactor coolant temp decrease Cooldown rate exceeded due to necessity for manual reactor blowdown.

 * Northeast Nuclear Energy Co. (subs of Northeast Utilities).
 81/03/05, Region 1, fhiladelphia, Office of the Director (81/03/01) 3pp. 14595.047 24X Fiche-50-245.81/05/05,8208260488

- DOCKET 50-246 ADVANCED CRITICAL REACTOR EXPERIMENT
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR 89x list encl.

 DIRCKS-W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fichs 50-000
- O Inspection reports: IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26,Part 3, Suppl 1, "Clarification of Placement of Personnal Monitoring Devices for External Radiation" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24% Fiche 50-000,82/07/19, 8204210395

DOCKET 50-247 INDIAN FOINT STATION, UNIT 2

F Security, medical, emergency & fire protection plans

- 8208030088 Requests FEMA findings on adequacy of offsite preparedness around facilities to determine whether to invoke provisions of NRC regulations requiring licenses to demonstrate removal of identified significant deficiencies GRIMES, B.K. Division of Emergency Preparedness 82/06/16 KRIMH, R.M. Federal Emergency Management Agency 4pp 14200 291 24X Fiche, 50-247, 82/07/06, 8208030080
- 8207300500 Responds to 820602 ltr concerning emergency response plans for facilities & requesting initiation of 120-day regulatory clock against facilities FEMA will provide findings on adequacy of plant offsite preparedness
 DEYGUNG-R C Director's Office. Office of Inspection and Enforcement 82/07/07 DEL BELLO. A B Westchester County, NY 4pp 14172 063. 24X Fiche 50-247.02/07/07.0207300508
- --8206060006 Expresses concerns re facility emergency response plans & requests initiation of 120-day regulatory clock against facilities Critiques on emergency drill encl.

 DELBELLO.A B Westchester County.NY 82/06/02 PALLADINO.N Commissioners. 57pp 14172 066 24x Fiche 50-247.82/07/07. 8207300508.
- 8208030686 Releases public version of revised emergancy plan implementing procedures. FELTON.J H Division of Rules and Records. B2/07/20 Document Management Branch ip 14301 074 24X Fiche:50-003,82/07/20,
- --8208030728 Forwards public version of revisions to Emergency Plan
 Implementing Procedures IP-1023, "Operational Support Ctr" &
 IP-1024, "Monthly Check of Indin Point Emergency Radios,
 Telephones & Outdoor Evacuation Alarm,"
 O'TODLE-J.D. Consolidated Edison Co. of New York 82/07/09
 HAYNES.R C. Region 1, Office of Director 3pp, 14301 075, 24X
 Fiche 50-003,82/07/20,8208030686
- --8208030730 Public version of Emergency Plan Implementing Procedures IP-1023, "Operational Bupport Ctr" & IP-1024, "Honthly Check of Indian Point Emergency Radios, Telephones & Gutdoor Evacuation Alarm" FINCH, G.L. Consolidated Edison Co. of New York, 82/06/18 23pp 14301.078 24X Fiche 50-003,82/07/20,8208030686
- 8208020073 Advises that amended Page 3-14 from physical security plan, per 820121 itr, is withdrawn Approved page in effect on 820526 remains in effect in response to NRC 820518 itr. O'TOOLE, J D Consolidated Edison Co of New York 82/07/27. VAROA, 8 A Operating Reactors Branch I lp 14144-112, 24x Fiche 50-003, 82/07/27, 8208020073
- B208050050 Forwards FEMA 820802 ltr & interim findings rapt on adequacy of radiological emergency response preparedness of state & local govts near plant.

 HABSELL, D.F. Hearing Branch : 82/08/02 CARTER, L.J., BHON, F.J., PARIS, D.H. Atomic Safety and Licensing Board Panel, 36pp 14213 231 24X Fiche: 50-247, 82/08/02, 82080 50050
- 8208100030 Notifies that NRC will determine whether reactor should be shut down if significant deficiencies identified in FEMA 820802 ltr are not corrected within 120 days. Written statement describing plans requested within 30 days. HAYNES.R.C Region 1. Office of Director 82/08/03 0/100LE, J B Consolidated Edison Co of New York. 2pp 14296 275 24X Fiche 50-247,82/08/03,8208100030

- --8208100035 Forwards interim findings rept on adequacy of radiological emergency response preparedness of state & local govts at Indian Point Power Station Plans & preparedness inadequate THOMAS, L. M. Federal Emergency Management Agency 82/08/02 DIRCKS, W. Office of the Executive Director for Operations 2pp 14296 277. 24X Fiche 50-247, 82/08/03,8208100030
- --8208100039 Interim findings on adequacy of radiological emergency response preparation of state & local govts at Indian Point Nuclear Power Station PETRONE.F.P Federal Emergency Management Agency 82/07/30 33pp. 14296 279 24X Fiche 50-247.82/08/03.8208100030
- 8208230413 Forwards minutes of 820701 meeting w/BNL re NRC review of util compliance w/106FR30.App R & summary of 820713 site visit re investigation of methods for reducing rist of core melt due to fires.

 VAROA.S A Operating Reactors Branch 1 82/08/06 D'TGOLE, J D Consolidated Edison Co of New York 24pp 14529 001 24X Fiche; 30-247.82/08/06.8208230413
- 8208260349 Forwards minutes of 820701 neeting re review of compliance w/fire protection requirements of 100FR50 48 Firm schedule of answers to specific issues requested within 20 days of receipt of itr
 EISENHUF, D 0 Division of Licensing 82/09/10 G/TOOLE, J D Consolidated Edison Co. of New York 51pp 14375 220 24X Fiche: 50-247, 82/08/10, 8208260349
- 6208270584 Releases public version of revised emergency plan implementing procedures FELTON, J. H. Division of Rules and Records 62/08/12 Bocument Management Branch. Ip 14683 227 24X Fiche 50-003, 82/08/12, 820827084
- --B208270570 Forwards public varsion of revised emergency plan implementing procedures including Procedures IP-1016 repotatining mateorological data & IP-1037 repotatining offsite Ruster-Biokes monitor data
 O'TOGLE, J D : LIEBLER, O H. Consolidated Edison Co of New York
 B2007/01, Office of Nuclear Reactor Regulation, Director. ip
 14683 228 24X Fiche 50-003,82/08/12,8208270584
- --8208270593 Public version of revised emergency plan implementing procedures including Procedures IP-1016 re obtaining meteorological data & IP-1037 re obtaining offsite Rueter-Btokes monitor data & Consolidated Edison Co. of New York 82/07/01 51pp 14683.227. 24% Fiche-50-003,82/08/12,8208270584

G Adjudicatory correspondence

- 8208110236 Response to UCS/NY PIRO 820521 request for admissions Affiliavits & Centificate of Svc encl. MCOURREN.H. U Hearing Branch I 82/06/11 Union of Concerned Scientists, 25pp. 14330,315 24X Fiche 50-247.82/06/11,8208110236
- 8208270458 Expresses appreciation for opportunity to address ASLB DIAMANT.L. Affiliation Unknown 82/07/07. CARTER.L. Atomic Safety and Licensing Board Panel 1p 14565 272 24X Fiche: 30-247, 82/07/07, 8208270459
- 8208030348 Response to final set of interrogetories & document requests re Commission Question 1.Certificate of Svc encl Related correspondence.
 POSMER.P. Parents Concerned About Indian Point 82/07/23 Consolidated Edison Co. of New York 8pp. 14157.214 24X Fiche: 50-247.82/07/23.8208030348
- 8208030335 Attempts to clear confusion of ASLB 820714 & 16 telcons to Come Ed, Convergation on 820714 was substantive Discussions re-wertes of motions or issues should be entertained only w/all parties participating. W/Certificate of Svc SOHINKI, S M Consolidate's Edison Co of New York, 82/07/27 CARTER, L.J., Atomic Safety and Licensing Board Panel. 7pp. 14156 351 24X Fiche. 50-247, 82/07/27, 8208030335.
- 8208160223 Memorandum & Order CLI-82-15 denying PASNY request for directed certification of charges that ASL8 exceeded or misapplied jurisdiction in admitting UGS & other intervenor contentions Add1 Commissioner views and CHILK-8 J Office of the Secretary of the Commission 82/07/27. 30pp 14346-290. 24X Fichs. 50-247, 82/07/27, 8208160223.
- 8208020275 Urges Order CLI-82-15 be rescinded Interests of nearby restients must be considered.
 MESSINGER.R.L., FRIEDLANDER.M., GREITZER.C. New York.NY, 82/07/28, PALLADIMO.N.J., AMEARNE.J., GILINSKY.V. Commissioners ip 14152:262. 24X Fiche 50-247.82/07/28,8208020275

j

- 8208020281 Expresses outrage on behalf of Alliance to Close Indian Point at order CLI-82-15 narrowing scope of hearing POBNER, P Affiliation Unknown 82/07/28 PALLADINO, N J , AMEARNE, J F , ROBERTS, T M Commissioners ip 14151.311 24X Figbs 50-247, 82/07/28.6208020281
- 8208050050 Forwards FEMA 820802 ltr & interim findings rept on adequacy of radiological emergency response preparedness of state & local govts near plant HASEELL, D.F. Hearing Branch 1 82/08/02 CARTER, L.J., SHON, F.J., PARIS, O.H. Atomic Safety and Licensing Board Panel. 35pp 14213 231 24X Fiche 50-247, 82/08/02, 8208050050
- 8208040100 Requests immediate suspension of plant OLs until determination made that adequate emergency plans suist that are capable of protecting public MEISB, E.R., SHOLLY, B.C. Union of Concerned Scientists WEISB, E.R., Harmon & Neiss 82/08/04 PALLADINO, N.J., GILINSKY, V., AHEARNE, J., Commissioners 3pp. 14238,173 24X Fiche 50-247,82/08/04,82080-04100
- 8208100093 Forwards Region 1 820803 ltrs to licenses re emergency preparedness HASEELL.D F Hearing Branch 1 82/08/05 CARTER,L J., SHON,F J., PARTE,O H Atomic Safety and Licensing Board Panel. 5pp 14296-234 24X Fiche: 50-247,82/08/05,8208100053
- B20Bii0079 Hemorandum & certification seeking further Commission guidance on witness testimony on consequences & probabilities & evidence on status & degree of conformance w/NRC/FEMA guidalines, CARTER, L J PARIS, O H . SHON, F J Atomic Safety and Licensing Board Panel B2/08/09 App 14316, 344 24X Fiche: 50-247, 82/08/09, 82/08/10079
- B20B1100B5 Errata to 820B09 memorandum & certification, correcting typographical errors CARTER, L. J. Atomic 8#fety and Licensing Board Panel 82/08/09 ip. 14316 343 24X Fichs 50-247, 82/08/09, 820B1100B5
- 8208170274 Bolicits support for each Croton-Harmon Board of Ed 820706 resolution demending NRC institute 120-day clock to develop acceptable evacuation plan GERADI.K.A Affiliation Unknown 82/08/10 PARIS.O H Atomic Safety and Licensing Board Panel 2pp 14367 226 24X Fiche 50-247.82/08/10.8208170274
- 8208160440 Supports UCS/NY PIRO motion for order to show cause requesting shutdown Cancellation of testimony & tardiness of objections to 820423 order unsupported FLEISHER, Z 8 West Branch Conservation Association 82/08/11 PALLADINO, N Commissioners ip 14348 255 24X Fichs 50-247, 82/08/11, 8208160440.
- 8208170120 Forwards Town of Cortlandt 820810 Resolutions 250-82 & 251-82 committing to cooperate in formulating evacuation plans & to demand documents re evacuation plans from utils 80YLE.H L. Cortlandt. Town of, NY 82/08/12 Docketing & Services Branch 3pp 14365 206 24X Fichs:50-247,82/08/12,8208170120
- 8208170284 Opposes congressional investigation re conduct of ongoing adjudicatory proceeding Investigation could irreparably impair legal validity of subsequent agency decisions, Memo detailing concerns encl DUFFY. J. F. Pawer Authority of the State of New York 82/08/13 OFFINGER, R. L. House of Rep. Energy & Commerce 7pp 14369:195 24X Fichs 50-247,82/08/13,8208:70284
- 8208170285 Response supporting ASLE 820807 memorandum & order on two questions to Commission re-probabilities & consequences, Certificate of Svc encl BRANDENBURG, B. Consolidated Edison Co. of New York, MORGAN, C. Power Authority of the State of New York MORGAN, C. Morgan Associates. 82/08/13 Commissioners 12pp 14347-183. 24x Fiche: 50-247, 82/08/13, 8208170285
- 8208190119 Lists corrections to licensee 820813 response to ASLB 820809 memorandum & certification COLARULLI, P. F. Consolidated COLARULLI, P. F. Consolidated Edison Co. of New York COLARULLI, P. F. Power Authority of the Btate of New York 82/08/17 STUCKY, S. W. Docketing & Services Branch 19 14381, 294, 24X Fiche 50-247, 82/08/17, 8208190119,
- --8208190123 Corrected copy of response to ASLB 820809 memorandum & certification Commission should reaffirm 820727 decision w/o further opinion.

 8RANDENBURG.B Consolidated Edison Co. of New York MORGAN.C. Fowar Authority of the State of New York MORGAN.C Morgan Associates 82/08/17 8pp. 14381 295 24X Fiche. 90-247, 82/08/17, 8208190119

- 8208200120 Forwards documents in response to Interrogatory 7 filed on
- 20820120 remards occuments in response to invertogetory / filed on 820119 W/o enci MCORE.J E Hearing Branch 1 82/08/19 WEISS,E.R. Harmon & Weiss WEISS,E.R. Union of Concerned Scientists WEISS,E.R. Public Interest Research Group, New York 1p 14500 086 24X Fiche 50-247,82/08/19,8208200120
- 8208240367 Submits informal Commission response to ASLB 820809 memorandum & certification of questions re intent to issue 820727 memorandum & order.CLI-82-15 Formal response expected during wk of 820830 CHILK.S J Office of the Secretary of the Commission 82/08/23 CARTER.L J. SHON.F J. PARIS.D H Atomic Rafety and Licensing Board Panel 3pp 14520 168 24X Fiche 30-247, 82/08/23,8208240367

- 8208030080 Responds to Rockland County Legislature Resolution 320 prohibiting use of county employees funds for federally mandated radiological response plans for facilities FEMA will provide findings on adequacy of offsite preparedness DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/07/06 GRANT.J T Rockland County, NY 2pp. 14200 289 24X Fiche 50-247.82/07/06.8208030080
- --B208030085 Requests FEMA findings on adequacy of offsite preparedness around facilities to determine whether to invoke provisions of NRC regulations requiring licenses to demonstrate removal of identified significant deficiencies ORIMES, B K Division of Emergency Preparedness 82/06/16 KRIMM.R M Federal Emergency Managament Agency 4pp 14: 24% Fiche, 50-247, 82/07/06, 8208030080 14200-291
- 8208020290 Ack receipt of NRC ltr in response to Hestchester County, NY request for 120-day regulatory clock against facilities. County appreciates NRC efforts to meet concerns by requesting interim findings from FEMA DELBELLO, A B Westchester County, NY 82/07/13, PALLADINO, N Commissioners. Ip 14151 301 24X Fiche 50-003,82/07/13, B208020290
- 8208180044 Informs of concerns & objections to proposed NRC plans for evacuation of residents from areas surrounding facilities in event of accident EL80N.9 Oray Panthers 82/07/22 Commissioners 2pp. 14376 300. 24X Fiche 50-247.82/07/22.8208180044

I Financial information

- 8208030217 Forwards projection of util ability to pay \$20 million retrospective premium adjustment for Aug 1782-Jul 1783 O'TOOLE, J D Consolidated Edison Co of New York 82/07/27 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 2pp 14157,338 24X Fiche 50-003,82/07/27,8208030217.
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR. Bvc list encl
 DIRCKB.W J. Diffice of the Executive Director for Operations.
 82/07/02. Consolidated Edison Co of New York. 73pp 14194.001.
 24X Fichs: 50-000.82/07/02.8207080064
- 8208200291 Forwards advance notification of shipment of nuclear waste from facilities to Dernwell.SC O'TOOLE.J D Consolidated Edison Co of New York 82/07/14, HAYNES.R C Region 1. Office of Director 3pp. 14398 323 24X Fiche. 50-247. 82/07/14.8208200291
- 8208040511 Notification of 820727 meeting w/util in Bethesda, MD to discuss scheduling of open items
 THONA.J.D. Openating Reactors Branch 1 82/07/21. VARQA.B.A.
 Openating Reactors Branch 1 2pp. 14220 335. 24X
 Fiche 30-247, 82/07/21.8288040511
- 8208110030 Requests info re NY City water supply sys to aid R Codell testimony for hearing on risk re water contamination by release of radioactivity in event of severe accident, per 820709 discussion. HANAUER, 8. H Division of Safety Technology. 82/07/22. CONHAY, J. New York, State of. 4pp 14330 218. 24X Fiche 50-003, 82/07/22. B208110050.
- 8208020426 Notification of 820727 meeting w/Bandie Natl Lab & Pickard Lowe & Garrick in Albuquerque, NM to obtain info re open technical (saues raised during meeting in June 1982 HANNON, J. Operating Reactors Branch 1. 82/07/26. VARQA, 8. A. Operating Reactors Branch 1. 82/07/26. VARQA, 8. A. Fiche 50-247, 82/07/26, 8208020426.

- 8208160012 Responds to NRC 820630 request for schedule for responding to encl info request Final design details re implementation of NNREO-0737, item II B 3. "Post-Accident Bampling," will be provided for gast-implementation review by 833301 O'TDOLE. J D Consolidated Edison Co of New York 82/08/06, VARGA, 8 A Operating Reactors Branch 1 ip 14344 335 24X Fiche 80-247, 82/08/06, 8208160012
- 8208090194 Opneric Ltr 82-14 to all reactor licensess, holders of CP & applicants re submitted of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT. D G. Division of Licensing 82/08/09 Consolidated Edison Co of New York ip. 14356:332 24X Fiche 50-000.82/08/09, 8208090194
- 8208160407 Forwards replacement pages to 810622 ltr re control of heavy loads 0'YOOLE.J D Consolidated Edison Co of New York 82/08/10 VAROA: S A Operating Reactors Branch 1 8pp. 14349 007 24X Fiche 50-247,82/08/10,8208160407
- 8208230232 Forwards application for amend to License DPR-26 & proposed Tech Specs to incorporate various requirements re steam generator exams
 G'TOOLE, J D Commonwealth Edison Co 82/08/18, VARGA, 8 A
 Operating Reactors Branch 1 ip 14514 276 24X
 Fiche 50-247, 82/08/18, 8208230232,
- --- 8208230238 Application to amend License DPR-25, incorporating requirements re steam generator exams D'TOOLE.J D Commonwealth Edison CO 82/08/18, 2pp, 14514:277 24X Fiche. 50-247.82/08/18.8208230232
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svr list encl
 Leakage " Svr list encl
 JORDAN E L Division of Engineering & Quality Assurance. 82/07/16
 Consolidated Edison Co of New York 87pp 14356; 274. 24X
 Fichs 30-900.82/07/16.8204210393
- 8204210379 IE Info Notice 81-26.Part 3.Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDANAE L. Division of Engineering & Quality Assurance. 82/07/19 Hichigan, Univ of 112pp, 14358 001, 24% Fiche 50-000.82/07/19, 20048000 JORDAN, E.L. Division Michigan, Univ of 8204210393
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressurs," Byo list encl JORDAN/E L. Division of Engineering & Guality Assurance. 82/07/20 Consolidated Edison Co. of New York, 112pp. 14381:001 24X Fichs:50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards, 82/07/20 Comsolidated Edison Co of New York, 71pp, 14387-2; 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26.**RCIC & HPCI Turbine Exhaust Check Valve Failures ** 8vc list encl JORDAN,E L. Division of Engineering & Quality Assurance. 82/07/22 Consolidated Edison Co of New York 112pp. 14194 321. 24X Fiche 50-000, 82/07/22, 8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCB." Svc list encl.

 ORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/23, Consolidated Edison Co. of New York 122pp. 14380 115, 24X Fiche 30-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PMRs." Svc list encl. URDAN.E.L Division of Engineering & Guality Assurance. 82/07/23 Consolidated Edison Co. of New York 127pp, 14194.120, 24X Fiche 50-000, 82/07/23, 8204210402.
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Hestinghouse PHR Power Plants." Svc list sncl. JORDANIE L. Division of Engineering & Quality Assurance. 82/07/26, Consolidated Edison Co of New York, 12ipp. 14357 013 24X Fiche 50-000. 82/07/26, 8204210403

- 8204210405 IE Info Notice 82-31, "Overesposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/28 Consolidates Edison Co of New York 122pp 14357 146 24X Fiche. 50-000.82/07/28,8204210405
- 8208130294 Forwards response to Action Item 3A of 1E Bulletin B2-02, "Degradation of Threaded Festners in RCPB of PMR Plants " Response to remainder of Items 3A & 3B will be submitted by 820830 0'TDOLE, J D Consolidated Edison Co of New York 82/08/02 HAVNES, R C Region 1. Office of Director 4pp 14337.088 24% Fiche 30-247.82/08/02.8208130296
- 8204210407 IE Info Notice 82-27, "Fuel Rad Degradation Resulting From Baffle Mater-Jet Impingement " Svc list encl 1 GROWN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche: 50-000.82/08/05,8204210407
- 8208120230 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/82-09 STAROSTECKI.R. Division of Project & Resident Programs 82/08/05 0'TOOLE, J D Consolidated Edison Co of New York ip 14326 283 24X Fichs 50-247.82/08/05.8208120230
- --B20B12Q237 Forwards response to NRC B20616 ltr re violations noted in IE Insp Rept 30-247/82-09 Corrective actions temporary procedure change for heatup from cold shutdown issued per station administrative orders & Tech Spacs
 O'TOGLE: J D. Contolidated Edison Co of New York, B2/07/16
 STAROBIECKI, R Division of Project & Resident Programs 4pp 14326 284 24% Ficha 50-247,82/08/05,8208120230
- 8208189077 Forwards "Fourth Refueling Outage Inservice Insp Exam Summary for Oct 1980-May 1981 " Summary includes areas subj to examinate results & squipment used Datafled data will be available onsite O'IDOLE, J. Consolidated Edison Co of New York 82/08/12 9818F, B H Region 1, Office of Director. 1p 14376 330 24X Fiche 50-247, 82/08/12, 8208180077
- --8208180084 "Fourth Refueling Outage Inservice Insp Exam Summery for Out 1980-May 1981 " * Consolidated Edison Co of New York 81/08/31 14pp 14374 331 24X Fiche 50-247.82/08/12.8208180077
- 8208230282 Forwards response to IE Bullatin 80-11, "Masonry Hall Design " Response covers final re-evaluation rept & justifications, O'TOOLE, J D Consolidated Edison Co of New York 82/08/16 VAROA: B A Operating Reactors Branch 1 4pp 14510.001. 24X Fiche 30-247, 82/08/16, 8208230282
- --9208230285 "Final Re-Evaluation Rept in Response to IE Bulletin 80-11."

 * Computerh Engineering Services, Inc. R547 01 82/06/30 100pp.
 [4510 005 24X Fiche 50-247.82/08/16,8208230282
- --8208230287 "Justification for Various Aspects of Re-Evaluation Criteria in Response to NRC 811222 Request for Addl Info re JE Bulletin 80-11 " Regimenting Services, Inc 82/08/31 48pp. 14510:114 24X Fiche 50-247, 82/08/16, 8208230282
- 3208300041 Forwards IE Insp Rept 50-247/82-14 on 820701-31 & notice of violation STAROSTECKIR Division of Project & Resident Programs B2/08/16 D'TOOLE, J D. Consolidated Edison Co. of New York 2pp 14598 277 24X Fichs 50-247, 82/08/16, 8208300041.
- -8208300042 Notice of violation from insp on 820701-31 8TAROSTECKI,R Division of Project & Resident Programs 62/08/16 1p 14598-279 24X Fichs 50-247, 82/08/16, 8208300041
- --8208300046 IE Insp Rept 50-247/82-14 on 820701-31 Noncompilance noted. Failure to chain & pediock recirculating bupass valve on Charping Pump 23 REBELOWERI, T., KOLTAY, P., KISTER, H. Division of Project & Resident Programs. 82/08/13 17pp 14598 280 24% Fiche 50-247, 82/08/16, 8208300041.
- 2 Periodic operating reports & related correspondence
- 8208:10049 "Core Helt Natis Interactions Evaluations," annual progress rept for Apr 1980-May 1981.

 SHANSON, D. O., CATTON, I. Applied Science Associates, Inc. NRC-03-09-104, ABAI-81-001, 81/03/31 Division of Systems Integration (post 81:009) 217pp 14330 001 24% ciche:50-247-81/03/31,8208:10049.

- 8208270010 Responds to FOIA request for documents detailing collectiva dose exposures in 1981 for operating nuclear power plants & analysing said info Ferwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14579 208 24X Fiche 50-000.82/07/13.8208270010
- --8208270012 Forwards "Number of Personnel & Man Rem By Work & Job Function for CY81," per 10GFR20 407
 O'TODLE J D Consolidated Edison Co of New York 82/03/01
 HAYNES R C Region 1. Office of Director 1p 14679, 361 24x
 Fiche, 30-000, 82/07/13, 8208270010.
- --8208270016 "Number of Personnel & Man Rem By Work & Job Function for GYB1" # Consolidated Edison Co of New York. 82/03/01 lp 146/9 362 24X Fiche 50-000.82/07/13.8208270010
- --0208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBI" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 214 24X Fiche. 50-000, 82/07/13, 8208270010
- --B20B270432 Forwards "Personnel Whole Body Exposures For CYB1." per 10CFR20 407

 BRONS.J C Power Authority of the State of New York B2/02/R4.

 Office of Hanagement and Program Analysis 1p 14679-348. PAX Fichs 50-000, 82/07/13, 8208270010
- --8208270637 "Personnel Whole Bady Exposures for CY81 "
 + Consolidated Edison Co. of New York 82/02/26 ip. 14677 346 24X Fiche 50-000,82/07/13,8208270010
- 8208240248 Forwards monthly operating rept for Jul 1982 D'TOOLE, J.D. Consolidated Edison Co. of New York 82/08/16 MCDDNALD,W G. Distribution Services Branch 1p. 14544; 137. 24% Ficha 50-247, 82/08/16, 8208240248
- --8208240252 Monthly operating rept for Jul 1982 EICH, E.F. Consolidated Edison Co. of Naw York 82/08/05 5pp. 14544 138, 24X Fiche, 50-247, 82/08/16, 8208240248
- B Reportable occurrences: LERs & related correspondence
- 8208050217 Forwards LER 82-026/03L-0 Q'TOQLE, J D Consolidated Edison Co of New York 82/07/16. HAYNES, R C Region 1, Office of Director 1p 14209-261 24X Fishe 50-247, 82/07/16, 8208050217
- --8208050220 LER 82-026/03L-0 on 820618, during normal operation essential svc water sys being supplied by svc water pumps 21, 22 & 23 declared inoperable Caused by low pump head values. Pumps repaired, replaced & tested, FITZPATRICK, B Tennessee Valley Authority 82/07/18 Region 1, 0PPice of Director 1p. 14209 262 24% Fiche 50-247, 82/07/16, 8208050217.
- 8208020229 Forwards LER 82-027/03L-0 0'TGOLE.J D Consolidated Edison Co of New York 82/07/21. HAYNES: R C Region 1. Defice of Director. 1p. 14192 296 R4X Fiche 50-247,82/07/21.8208020229.
- --8208020232 LER 82-027/03L-0 on 820621, during normal operation, boron injection tank level indicator read low Gaused by solidiffication of boric acid in instrument guise line Line cleared & instrument returned to normal operation fitzPATRICK. B Consolidated Edison Co. of New York. 82/07/21. Region 1. Office of Director. 2pp 14152 237 24X Fiche 50-247,82/07/21,8208020225.
- 8208050191 Releases sanitized version of overaxposure rept 100FR2D 405 * Administration Branch 82/07/23 Document Management Branch 1p 14242:061 24X Fiche 50-247,82/07/23,8208050191.
- --B208050247 Senitized version of overexposure rept re 820601 event in which limit for whole body exposure per 10CFR20 101(b)(1) exceeded for one employee of contractor performing activities Ltr supple 820602 & 820609 repts, TOOLE, J. Consolidated Edison Co. of New York. 82/07/01 FMAYNES, R. C. Region 1, Office of Director 7pp. 14242:062, 24X Fiche: 50-247, 82/07/23, 8208050171
- E208060327 Forwards incident reporting sys repts re spill of contaminated water & contamination of personnel in auxiliary bidg & failure of control rod guide tube support pins for transmittal to NEA MICHELBON.C Director's Office B2/07/29. LAFLEUR, J. D Office of International Programs, Director. 17pp. 14281:234. 24x Fiche 50-000, 82/07/29, 8208060327

- 8208160004 Forwards LER 82-029/03L-0 O'TOOLE.J Consolidated Edison Co of New York 82/07/30 HAYNES.R C Region 1. Office of Director 1p 14344 313 24X Fiche 50-247.82/07/30.8208160004
- --8208160005 LER 82-029/03L-0 on 820702, containment isolation valve in primary make-up water sys would not fully close when tested Valve will be secured in closed position until repaired Cause & corrective actions will be reported after repair FITZPATRICK, B Gonsolidated Edison Co of New York 82/07/30 Region 1. Diffice of Director 2pp 14344 314 24X Fichs 50-247,82/07/30,8208160004
- 8208230341 Forwards LER 82-030/03L-0 D*TQQLE.J D Consolidated Edison Co of New York 82/08/09 HAYNES.R C Region L. Office of Director 1p 14508 271 24X Fiche 50-247. 82/08/09, 8208230341
- --9208230347 LER 82-030/03L-0 on 820710, during normal operation, bypass valve 267A in chemical & vol control sys found leaking Caused by damaged diaphragm New valve bonnet assembly & diaphragm installed FITZPATRICK,B Consolidated Edison Co of New York 82/08/09 Region 1, Office of Director ip 14508 272 24X Fichs 50-247,82/08/09.8208230341
- 8208260132 RO 82-32 on 820817, steam generator 22 blowdown outer isolation valve CV1215A closed Caused by failure of 1315A solenoid valve Jumper installed in instrument air sys to establish blowdown Also reportable per Part 21 JACKBON, C W Consolidated Edison Co of New York 82/08/18, HAYNES, R C Region 1, Office ad Director 2pp 14556 331 24X Fiche 50-247, 82/08/18, 8208260132
- 8208310178 Forwards LER 82-028/03L-0 0/T00LE,J D. Consolidated Edison Co of New York 82/08/19 HAYNES:R C Region 1. Office of Director 1p 14689 009 24X Fiche 50-247, 82/08/19, 820831017B
- --8208310186 LER 82-028/03L-0 on B20720, operator observed low air flow condition to Ri1/Ri2 containment gas & particulate monitors. Caused by moisture on electrical leads Source of moisture corrected & motor leads dried & reconnected FITZPATRICK, B Consolidated Edison Co. of New York 82/08/19. Region 1. Office of Director 1p 14689 004 24X Fiche 50-247, B2/08/19, 8208310178
- T Hearing transcripts on non-antitrust matters
- 8208040357 Transcript of Commission 820722 public meeting/affirmation session in Washington DC re SECY-82-270A on alternative Commission decision in Indian Point special proceeding + Commissioners 82/07/22 10pp 14223 170 24X Fiche 30-247, 82/07/22, 8208040357.
- U Congressional/Executive Correspondence
- 6208100350 Responds to 820608 ltr to Chairman Palladino requesting that facilities be shut down pending NRC review of results of hearings Protective measures imposed by NRC cited Results of current hearings to be reported to Commissioners Sept 1982. DIRCKS, H.J. Office of the Executive Director for Operations 82/07/09 GILMAN.B A House of Rep. 5pp. 14308 347. 24X Fiche 50-247, 82/07/09, 8208100350
- --8206060022 Urges shutdown of facilities until adequate emergency plan can be formulated & ASLB findings studied Constituent concern re plant safety & inadequate evacuation plan cited. GILMAN,B A House of Rep 82/06/09 PALLADINO,N Commissioners. 4pp. 14308,351 24X Fiche: 50-247,82/07/09,8208100350.
- DOCKET 50-249 DREBDEN NUCLEAR POWER STATION, UNIT 3

 F Becurity, medical, emergency & fire protection plans
- B20B040353 Releases public version of revised emergency plan implementing procedure. FELTON.J.M Division of Rules and Records. 82/07/13. Document Management Branch ip 14223-161 24X Ficha 50-010,82/07/13, 8208040353.
- --8208040358 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-CB, "Rad/Chem Director," Receipt form, procedure history & safety evaluation and SCOTT,D,J, Commonwealth Edison Co 62/07/02 DENIBN,H.R. Office of Nuclear Reactor Regulation, Director 3pp 14223 162 24X Fiche 50-010,82/07/13,8208040353

- --8208040361 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-CB, "Rad/Chem Director " Revised index of station group director duties encl * Commonwealth Edison Co 82/06/30 Spp. 14223 165, 24X Fichs 50-010,82/07/13,8208040353
- 8208040473 Releases public version of revised emergency planimplementing procedures FELTON.J M Division of Rules and Records 82/07/22, Document Management Branch 1p 14220 294 24X Fiche: 50-010, 82/07/22, 8208040473
- --8208040479 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7, "Becurity Director" & Revision 0 to EPIP 300-9; "Operational Check of Notification Phone List " Receipt form and 1 SCOTT.D J Commonwealth Edison Co 82/07/10 DENTON, HR Diffice of Nuclear Reactor Regulation, Director 5pp. 14220 295 24X Fiche 50-010, 82/07/22, 8208040473
- --8208040483 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7, "Security Director" & Revision 0 to EPIP 500-9, "Operational Check of Notification Phone List "

 * Commonwealth Edison Co. 82/07/07 App. 14220:300 24X Fiche 50-010,82/07/22,8208040473
- 8208270134 Forwards IE Insp Repts 50-010/82-11:50-237/82-15 & 50-249/82-16 on 820524:29.30 & 0709 & notice of significant test deficiency
 HIND.J A Division of Emergency Preparedness & Operational Support. 82/08/03 REED, C Commonwealth Edison Co 3pp 14363:338 24X Fiche:50-010:82/08/03:8208270184
- --8208270142 IE Insp Repts 50-010/82-11.50-237/82-15 & 50-249/82-16 on 820624,29,30 & 0709 Significant test deficiency nated failure of seven prompt public notification sys sfrans JANUSKA,A O., AXELSON,W L Division of Emergency Preparadness & Operational Support 82/07/23 12pp 14563:341 24X Fichs 50-010,82/08/03,8208270134.
- 8208290559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures "
 FELTON. J. M Division of Rules and Records. 82/08/12, Document Management Branch 1p. 14559: 354. 24X Fiche: 50-000,82/08/12,
- --8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 MODRE, R D Commonwealth Edison Co. 82/07/19. DENTGN.H.R. NRC No Detailed Affiliation Given 1p 14559:355. 24X Fichs: 50-000;82/08/12,8208250559
- --8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."

 * Commonwealth Edison Co 82/06/30. 7pp 14559:356 24% Fichs 50-000,82/08/12.8208250559.
- B208230107 Forwards revised cable discrepancy lists refire protection safe shutdown analyses Lists indicate how each discrepancy noted in fire protection associated circuit analysis & mod repts will be resolved RAUBCH, T. J. Commonwealth Edison Co B2/08/13 EISENHUT, D Q. Division of Licensing 2pp 14515:001 24X Fiche: 50-000, 82/08/13, 8208230107.
- --8208230119 "Fire Protection Cable Discrepancy List, Dresden Unit S." * Commonwealth Edison Co B2/08/04, 150pp. 14515:144 24X Fiche: 50-000,82/08/13,8208230107
- Q Adjudicatory correspondence
- 8208190125 Final initial decision ordering NRR issue license amend authorizing installation of 33 high density storage racks in each spent fuel pool MOLFE, J.F., REMICK, F.J., LITTLE, L.W. Atomic Safety and Licensing Soard Panel 82/08/17, 29pp 14381.043 24X Fiche 50-237, 82/08/17,8208190125.
- 8208240267 Response to ASLE 820728 order. Requests leave to withdraw application w/o prejudice Need for transahipment in nearterm reduced due to approval of installation of high density spent fuel racks. Certificate of Svc encl. STEPTOE.P. Commonwealth Edison Co. STEPTOE.P. Isham, Lincoln & Reale. 82/08/18. Atomic Safety and Licensing Board Panel. App. 14527, 120. 24% Fishe 50-000, 82/08/18, 8208240267.

- 8208240233 Notice of ASLAB constitution AS Rosenthal.chairman & TS Moore & RL Qotchy.members SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 82/08/20 p 14517 148 24X Fichs 50-237.82/08/20.8208240233
- 8208240265 Response to ASLB 820728 order NRC does not object to proceeding termination since licensee has moved to withdraw licensee application w/o prejudice, due to decision in Dresden high density storage rack case H/Certificate of Svc WRIGHT, N A Hearing Branch 2 82/08/20 Atomic Safety and Licensing Board Panel. 3pp. 14527 126 24X Fiche 50-000, 82/08/20, 8208240265
- P. Operating license stage documents & correspondence
- B2070B0064 Generic Itr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Bvc list encl
 DIRCKS,W J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edition Co of New York 93pp 14194 001
 24x Fiche-50-000, B2/07/02, B2070B0064
- 8208050115 Forwards "Dresden Unit 3 Reactor Containment Bldg Integrated Leak Rate Test," conducted during 820423-25, per requirement of 100FR50. App J. Section V. B 3 SCOTT, D J. Commonwealth Edison Co 82/07/09 DENTON, H Defice of Nuclear Reactor Regulation, Director 1p 14213 125 24X Fiche: 50-249, 82/07/09.8208050115
- --8208050118 "Dreaden Unit 3 Reactor Containment Bldg Integrated Leak Rate Test," conducted during 820423-25 * Commonwealth Edison Co 82/04/25 53pp 14213 126 24X Fiche 50-249,82/07/09,8208050115
- 8208050057 Forwards request for add1 info re TMI Item II.D 1,
 "Performance Testing of BWR & PWR Rafety/Relief Valves "
 Applicability of generic results reported in NEDE-24988-P
 must be demonstrated for specific valves at facility
 VASSALD, D.B. Operating Reactors Branch 2 82/07/27 DELOEDRGE, L
 Commonwealth Edison Co. Spp. 14244 047 24X Fiche 50-237, 82/07/27,
 8208050057
- 8208180266 Forwards revised version of model Tech Spets for reactor protection sys/power monitoring sys design VASBALLO, D B Gerating Reactors Branch 2 82/07/28 DELOEDROF, L Commonwealth Edison Co 3pp 14387-318 24X Fiche 50-000, 82/07/28, 8208180266
- --8208180271 Rayised model Tech Specs re electric power monitoring of reactor protection sys design * Operating Reactors Branch 2 82/07/28 ip 14389 321 24X Fiche 50-000,82/07/28,8208180266
- 8208110041 Forwards response to request to cross-ref info re environ qualification of safety-related equipment & THI action plan equipment SHARTZ.E D Commonwealth Edison Co. 82/08/02 EISENHUT, D Q Division of Licensing 557pp 14315 001 24x Fiche 50-000, 82/08/02,8208110041.
 - 08130046 Requests approval to delay implementation of commitments in response to Generic Ltr 82-05 re NUREQ-0737. Item II F. 16. "Containment Hydrogen Monitor " Completion postponed until 840101 to accommodate schedule requirements. EMARTY.E D. Commonwealth Edison Co 82/08/05 EISENHUT, D Q Division of Licensing. 2pp 14935 353 24X Fiche 50-000.82/08/05, 8208130046
- 1208110188 Forwards revised pages to CE-1-A. "Com Ed GA Program for Nuclear Cenerating Stations." Revision 21 Revised pages correct typographical & other minor errors SWARTZ.E D. Commonwealth Edison CO 82/08/06 HAASS.W P Quality Assurance Branch. 1p 14314-079 24% Fiche 50-000,82/08/06.
- --B208110204 Revised pages to CE-1-A.Revision 21, "Comm Ed GA Program for Nuclear Generating Stations" "Commonwealth Edison Co B2/06/06 11pp 14314 080 24X Ficha 50-000, 82/08/06, 8208110188.
- 8208240444 Requests appropriate action be taken re acceptable vent sysfor isolation condensar per hydrogen rule & NUREG-0737 guidence (TMI Item II B.I) or exemptions from applicable provisions of IOCRESO 44 should be requested VASSALLO.D B Operating Reactors Branch 2, 82/08/06 DELOEOROE.L Commonwealth Edison Co. 3pp 14544 170 24X Ficher 50-237, 82/08/06, 8208240444

- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chepter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D & Division of Licensing B2/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09, G208090194
- 8208170085 Forwards "Dresden Unit 3 Cycle 8 Startup Testing Summary "
 RAUSCH-T J Commonwealth Edison Co 82/08/10 VASSALLO,D B
 Operating Reactors Branch 2 1p 14358 135 24X
 Fiche, 30-249, 82/08/10, 82/08170085
- --8208170088 "Dresden Unit 3 Cycle 8 Startup Testing Summary " * Commonwealth Edison Co 82/08/10 10pp 14358 136 24X Fichs 50-249, 82/08/10, 8208170085
- 8208170135 Responds to NRC 820721 request to provide notification if util intends to deviate from NUREO-0737. Item III D 3 3, "Improved In-Flant Codine Instrumentation Under Accident Conditions" Both facilities comply w/requirement BNARTZ.E D Commonwealth Edison Co. 82/08/12 EISENHUT, D Q Division of Licensing 2pp 14365 211 24X Fiche 50-000,82/08/12,8208170135
- 8208230349 Forwards revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of previously submitted inservice insp & testing program for second 10 yrs Revision necessary to enable insp of LPCI/CCSW HX tube welds
 RAUSCH: T J Commonwealth Edison Co 82/08/16 EISENHUT. D 0 Division of Licensing 2pp 14512.357 24X Fiche 50-237.82/08/16, 8208230349
- --8208230359 Revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of inservice insp & testing program for second 10 years * Commonwealth Edison Co 82/08/14 3pp 14512,359 24X Fiche 50-237,82/08/145/8208230349
- 8208270290 Application for amend to License DPR-29 proposing Tech Spet changes to implement 10CFR50 59 reload licensing w/ODYN transient analyses & extended exposure MAPLHGR limits Significant changes discussed Class III amend fee encl RAUSCH: T J Commonwealth Edison Ca 82/08/19 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 14364 001 24X Fiche 50-000, 82/08/19, 8208270250
- --8208270273 Errata & Addenda Sheet 7. replacing Pages 4-11 & 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Guad Cities 1 & 2 Nuclear Power Stations" ** 4 Reneral Electric Co. NEDD-24246A ERR 07 82/07/31 5pp 14564 026 24x Fiche 50-000,82/08/19,8208270250
- 8208270276 Informs that analysis to determine appropriate equipment qualification temp profiles will be submitted in Sept 1782, not Jul 1982, as previously indicated RAUSCH.T.J. Commonwealth Edison Co. 82/08/23 VASSALLO, D.B. Division of Licensing ip 14564·177 24X Fiche 50-000, 82/08/23, 82082702946
- 8208310230 Application for amend to Licenses DPR-17 & DPR-25 reinstallation & use of high density fuel storage racks RAUSCH.T J Commonwealth Edison Co 82/08/26 EISENNUT, D C Division of Licensing 2pp 14695 115 24X Fiche 50-237.82/08/26, 820831030
- O Inspection reports: IE Bulletins & correspondence
- 8208050414 Forwards IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 on 810813-620503 No poncampilance noted KEPPLERJ O Region 3, Office of Director 82/07/12 REED, C Commonwealth Edison Co 1p 14217-166 24X Fiche 50-000, 82/07/12, 8208050414.
- --B20805044i IE Insp Repts 50-237/81-39.50-249/81-32.50-254/81-23.
 50-245/81-23.50-275/81-31 & 50-304/81-29 on B10813-820503
 No noncompliance noted Major areas inspected allegations re Comm Ed operation of facilities & compliance w/10CFR21
 HAYES.D W. PHILLIP.O A., HINDS.J M. Division of Project & Resident Programs 82/07/09 154pp 14217 169 24X
 Fichs 50-000,82/07/12.8208050414
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Lakage " Svc list encl JORDAN E L Division of Engineering & Quality Assurance Consolidated Edison Co. of New York B7pp, 14356, 274, 24X Fiche 50-000, 82/07/16, 8204210393

- 8204210395 IC Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Syr list encl JORDAN, E L Division of Englneering & Quality Assurance 82/07/19 (Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8208050393 Forwards IE Insp Repts 50-010/82-06, 50-237/82-10 & 50-247/82-11 on 820907-0604 & notice of violation. SPE6SARD, R L Division of Project & Resident Programs 82/REED, C Commonwealth Edison Co 2pp 14207 191 24X Fishe 50-010, 82/07/19, 8208050393 82/07/19
- ---8208030378 Notice of violation from insp on 820507-0604 * Division of Project & Resident Programs 82/07/19 14209 193 24X Flchs 50-010.82/07/19.8208050393 2p p
- --B203050403 IE Insp Repts 50-010/82-04.50-237/82-10 & 50-249/82-11 an 820507-0604 Noncompliance noted failure to follow hose color code 0000UE,T M , JORDAN,M J , WALKER,R D Division Resident Programs 82/07/11 9pp 14209 195 Division of Project & Resident Programs 82/07/11 9; Fiche 50-010,82/07/19,8208050393
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000.82/07/20.8204210396
- B204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks" Svc list enci CBBILL I. Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York. 71pp 1435/.2 24X Fichs 50-000.82/07/20.8204210397
- 820421039B IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Byc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210398
- B204210401 IE Info Notice 02-28, "Hydrogen Explosion While Orinding In Vicinity of Drained & Open RCB " Svc list encl JORDANE L Division of Engineering & Quality Assurance B2/07/29 Consolidated Edison Co. of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tubo Support Pin Failures at Mestinghouse PWRs " Svc list encl JCRDAN.5 L Division of Englneering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8208100287 Forwards IC Insp Repts 50-010/82-07, 50-237/82-13 & 50-247/82-14 on 820616-17 & 21-25 No noncompliance noted MILLER, J R Division of Engineering & Technical Programs. 8207/23 REED. C Commonwealth Edison Co 2pp 14274-171 R4X Fiche 50-010, 82/07/23, 8208100289
- -8208100299 IE Insp Repts 50-010/82-09,50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25 No noncompilance noted Major areas inspected action on previous findings,open items & hydrogen pass addition into reactor feedwater sys PAULAR A. QREGERIL R. Division of Engineering & Technical Programs 82/07/22 7pp 14294 193 24X Fiche 50-010,82/07/23,8208100289
- 9204210403 IE Info Notice 82-30, "Loss of Thermal Sizeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDANIE L Division of Engineering & Quality Assurance, B2/07/26. Consolidated Edison Co of New York 121pp 14357 019 24X Fichs 50-000, 32/07/26, 8204210403
- 8204210405 IE Info Notice 82-31. "Gverexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357.146 24X Fiche 50-000.82/07/28.8204210405
- 8208100252 Forwards IE Insp Rept 50-249/82-08 on 820420-0521 & notice 208100252 Forwards 12 1939 Nept to account and account of violation
 NORELIUS.C E Division of Engineering & Technical Programs
 82/07/29 REED.C Commonwealth Edison Co 2pp 14297.001 24X
 Fiche 50-249.82/07/29.8208100252
- -8208100257 Natice of violation from insp on 820420-0521 NORELIUS,C E Division of Engineering & Technical Programs 82/07/29 2pp 14297 003 24% Fiche 50-249,82/07/29,8208100252

- --8208100265 IE Insp Rept 50-249/62-08 on 820420-0521 Noncompliance noted failure to perform calculations per 10CFR App J during initial phase of containment integrated leak tost & failure JACKIH. I N , MAURA, F , ROBINSON. D Region 3. Office of Director 82/06/28 6pp 14297 005 24X Ficher 50-249, 82/07/29, 8208160252
- 8208270134 Forwards IE Insp Repts 50-010/82-11.50-237/82-15 & 50-249/82-16 on 820624.29.30 & 0709 & notice of significant test deficiency HIND, J A Division of Emergency Preparedness & Operational Support 82/08/03 REED, C Commonwealth Edison Co 3pp 14563 338 24X Fiche 50-010, 82/08/03, 8208270134
- --B208270142 IE Insp Repts 50-010/82-11.50-237/82-15 & 50-249/82-16 on B20624.29.30 & 0709 Significant test deficiency noted failure of seven prompt public notification sys sirens JANUSKA.A O . GRANT.H B . NICHOLSON.N A Division of Emergency Preparedness & Operational Support B2/07/23 12pp 14563 341 24X Flohe 50-010.82/08/03.8208270134
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Daffle Water-Jet Impingement " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fichs 50-000, 82/08/05, 8204210407
- 8208200241 Advises of error in NRC 820719 ltr transmitting IE Insp Repts 90-010/82-06.50-237/82-10 % 50-247/82-11 Page 2 should be replaced w/encl page 8PE85ARD,R L Division of Project & Resident Programs 82/08/13 REED.C. Commonwealth Edison Co 2pp 14379 031 24x Fiche 80-010,82/08/13.8208200241
- 8208230349 Forwards revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of previously submitted inservice insp & testing program for second 10 yrs Revision necessary to enable insp of LFCI/CCBW HX tubo welds.

 RAUSCHIT J. Commonwealth Edison Co 82/08/14 EISENHUT, D G Division of Licensing 2pg 14512 357 24X Fiche 50-237, 82/08/16, 8208230349
- --8208230357 Revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of inservice insp & testing program for second 10 years * Commonwealth Edison Co 82/08/16 3pp 14512 359 24% Fichs 50-237,82/08/16,8208230349
- 8208310212 Forwards final response to IE Bulletin 80-04, "ESF Reset Controls " Testing of listed mods performed after installation & specifically demonstrated equipment will not reposition from emergency position w/initial signal reset SHARTZ.E D Commonwealth Edison Co 82/08/20 KEPPLER, J 9 Regio J. Office of Director 5pp 14693 148 24% Fiche 50-237, 82/08/20.
- 8208310218 Forwards suppl to util 820526 response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Bys Components by Corbicula 8p (Asiatic Clam) & Myttius 8p (Mussel) "
 SHARTZ.E D Commonwealth Edison Co 82/08/23 KEPPLER, J Q Region 3, Office of Director 7pp 14693 130 24X Flohe 50-010,82/08/23, 8208310218
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL.R A. Critical Hass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- --- 8208270098 "Annual Whole Dody Dose At Licensed Nuclear Power Facilitles for CY81 "
 * NRC - No Detailed Affiliation Given 14679, 216 24X Fich+ 50-000, 82/07/13, 8208270010
- --B20B270559 Forwards "Recorded Annual Whole Body External Exposure for CYBI," per 10CFR20, 407(b) W/o Quad Cities, Zion. LaSalie, Byron & Braidwood repts
 RAUSCH.T J Commonwealth Edison Co B2/03/31 Office of Management and Program Analysis Ip 14680 075 24%
 Fiche 50-000, 82/07/13, 8208270010
- ---BR08270557 "Recorded Annual Whole Body External Exposure for CYB1 "
 * Commonwealth Edison Co B2/03/31 ip 14680,076 24X # Commonwealth Edison Co 82/00 Fiche 50-000.82/07/13.8208270010
- B208170242 Forwards monthly operating repts for Jul 1982 SCOTT.D J Commonwealth Edison Co 82/08/01 Direc Office of Inspection and Enforcement 1p 14369 228 Fiche 50-010.82/08/01.8208170242 Director's Office,

DOCKETED ITEMS

- --8208170245 Monthly operating repts for Jul 1982 BCHROEDER, B A Commonwealth Edison Co 82/08/01 18pp 14369 229 24X Fiche 50-010,82/08/01,8208170242
- S Reportable occurrences, LERs & related correspondence
- 8208310222 Forwards LER 82-018/03X-1 BCOTT.D.J Commonwealth Edison Co 82/07/12 KEPPLER, J G Region 3- Office of Director is 14493 123 24X Fiche 50-249.82/07/12, 8208310222
- --8208310228 LER 82-D18/03X-i on 820414, during refueling outage, quarterly valve timing par Procedure DDS 1600-instrogen inerting stop valve 3-1601-55 closure time exceeded Tech Specs Caused by hardening of internal seals Valve actuator replaced WHALEN.R Commonwealth Edison Co 82/07/30 Region 3, Dffice of Director 2pp 14693 126 24X Fichs 50-249,82/07/12,
- 8208020246 Forwards LER 82-029/01T-0 SCOTT-D J. Commonwealth Edison Co 82/07/22 KEPPLER, J. 0 Region 3: Office of Director 1p 14150 053 24% Fichs 50-249,82/07/22, 8208020246
- --8208020254 LER 82-029/01T-0 on 820752, while testing scram discharge vol level acram switches for proper tripping upon water loading.

 820 & 800 Magnetrol switches did not trip Cause not determined. Visual insp revealed no abnormalities

 WHALEN, R Commonwealth Edison Co 82/07/22 Region 3, Office of Director 4pp 14150.054 24X Fiche 50-249,82/07/22,8208020246
- 8208230273 Forwards updated LER 82-025/03X-1 SCOTT.D J. Commonwealth Edison Co 82/07/27 KEPPLER.J Q Region 3. Office of Director. 1p. 14513 205 24X Fiche 30-249, 82/07/27, 8208230273.
- ---8208230279 Updated LER 82-025/03X-1 on 820605, while performing plant insp. water discovered dripping from insulation in vicinity of isolation valve Gaused by cracked fillet weld on 1-inch drain line off MO3-3206A isolation valve Held reworked CRREFEL.8. Commonwealth Edison Co. 82/07/16 Region 3, Office of Director Spp 14513 206 24X Fiche 50-249, 82/07/27.
- 8208060030 Forwards incident reporting sys repts re effects of fire protection sys actuation on safety-related equipment & seismic qualification of safety-related sys for transmission to NEA MICHELBON, C. Director's Office 82/07/29 LAFLEUR, J.D. Diffice of International Programs. Director 21pp. 14244 315 24X Fiche 50-000, 82/07/29, 8208060030
- 8208130322 Forwards LER 82-028/03L-0 SCDTT-D J Commonwarth Edison Co 82/08/05 KEPPLER, J. 0, Region 3. Office of Director ip 14/3/6/326 24% Fiche 50-249.82/08/05, 8208130322
- --B208130324 LER 62-028/03L-0 on B20708,LPCI & core spray pressure switch 1554 F tripped above Tech Spec limit, Caused by linkage sticking due to poor past work practices Linkage freed & switch tested Work practices improved, CDYLE, L. Commonwealth Edison Co 82/08/05, Region 3, Office of Director. 2pp 14336,327, 24% Fiche 50-249,82/08/05,8208130322,
- 8208230029 Forwards LER 82-032/03L-0 8COTT.D J Commonwealth Edison Co 82/08/06 KEPPLER, J. O Regio 3. Office of Director 1p 14517 264 24K Fiche 50-249, 82/08/06, 8208230029
- --B208230033 LER B2-032/03L-0 on B2071B, during attempt to open 3-1601-23 valve, valve cycled from open to close w/o operator action Caused by laskage of air from weep hole of Versa valve, due to hardening of Orring seal Versa valve replaced TANO HEE, D Commonwealth Edison Co. 82/08/06 Region 3, Office of Director 2pp. 14517 265 24% Fiche 50-249,82/08/06,
- 9208230272 Forwards LER 82-031/03L-0 SCDTT.D. J Commonwealth Edison Co 82/08/06 KEPPLER, J. O. Regio 3, Office of Director. 1p. 14509-338 24X Fiche 50-249,82/08/06. 8208230292.
- -8208230297 LER 82-031/03L-0.on 820718, several spurious trips of main steam line high flow isolation switch occurred Caused by disconnection of mechanical linkage between torque tube mechanism & electrical switch Linkage replaced. PEDIGO, 8 Commonwealth Edison Co 82/08/06, Region 3, Office of Director 1p. 14509-339, 24x Fiche: 50-249,82/08/06, 8208230292

- 8208230390 Forwards LER 82-030/03L-0 SCOTT.D J Commonwealth Edison Co 82/08/06 KEPPLER, J G Region 3. Office of Director 1p 14513 007 24X Fiche 50-249,82/08/06, 8208230390
- --8208230401 LER 82-030/03L-0 on 820716, transient in-core probe bail valve 3A failed to reclose after opening Cause will be resolved during next outage Valve will be replaced & supplemental LER submitted when cause determined MDRGAN,W Commonwealth Edison Co 82/08/06 Region 3, Office of Director 2pp 14513 008 24X Fiche 50-249, 82/08/06, 8208230370
- 8208310048 Forwards LER 82-033/03L-0 SCOTT, D J Commonwealth Edison Co 82/08/17 KEPPLER, J Q Region 3. Office of Director 1p 14674 355 24X Fiche 50-249, 82/08/17, 8208310048
- --8208310052 LER 82-033/03L-0 on 820727, sporadic Group I isolation signals occurred on one channel & relay 595-1018 dropped in & out Caused by faulty main steamline temp switch 261-188 Contacts sumpered until next shutdown Insp planned 8HRDEDER, B. Commonwealth Edison Co 92/08/17 Region 3, Office of Director 2pp 14694 356 24X Fiche 50-249,82/08/17,8208310048

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

- F Security, medical, smergency & fire protection plans
- 8208030404 Forwards IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16. No noncompliance noted DANCE, H. C. Division of Project & Resident Programs 82/07/29 UHR10, R.E. Florida Power & Light Co 2pp 14154 008 24X Fiche 50-250, 82/07/29, 8208030404
- --8208030417 IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization & personnel Details withheld (ref loCFR73, 21) STANSBERRY, W W , MCGUIRE, D, R Division of Engineering & Technical Programs \$2/07/29 ip 14154 010 24X Fiche 50-250,82/07/29, 8208030404.
- BROBO90061 Forwards Revision 5 to security plan & discussion on Section B 4 (d) referenced in SA Varga B20517 Itr Encls withheld (ref 10CFR73 21)
 URRIO,R E Florida Power & Light Co B2/07/30 EISENHUT,D Q Division of Licensing 19 14270 357 24X Fiche 50-250,B2/07/30,B208090061
- 8208110240 Releases public version of emergency plan implementing procedure FELTON. J M Division of Rules and Records 82/08/05 Document Management Branch 1p 14331 030 24% Fiche 50-250,82/08/05,8208110240
- --8208110242 Forwards public version of Emergancy Plan Implamenting Procedure 20126, "Offsite Dose Calculations," per 820727 telcon UHRIO, R E Florida Power & Light Co 82/07/28 O'REILLY, J P Region 2, Office of Director 1p 14331,032 24X Fiche 50-230,82/08/05.8208110240
- --8208110244 Public version of Emergency Plan Implementing Procedure 20126. "Offsite Dase Calculations" HAY8.J C: NILLIAMS.J H Florida Power & Light Co 82/05/17 28pp. 14331.033 24X Fiche 50-250.82/08/05.8208110240
- 8208230007 Forwards corrected discussion of Section 8 4(d) of physical security plan referenced in 8 Verge 820517 ltr.Discussion withheld (ref 10GFR73.21) UHR10:R E Florida Power & Light Co 82/08/16 EISENHUT.D 0 Division of Licensing. 1p 14517 273 24X Fiche 50-250,82/08/16.8208230007

H. General correspondence

8207300503 Responds to H20618 ltr re steam generator tube degradation at plant Encl safety evaluation & Amend 80 provides basis for approval to operate Unit 4 until Oct 1982 Special actions based on Ginna event under consideration W/o encl DIRCKS,W J Office of the Executive Director for Operations 82/07/09. FABSELL,D.B House of Rep 7pp 14172 001. 24X Fichs. 50-250, 82/07/09, 8207300503.

- --8204200036 Expresses constituent concern re steam generator tube degradation problem at plant Basis of NRC decision allowing util to operate Unit 4 until Oct 1982 & hearing of event at Ginna on plant requested FARCELL, D.B. House of Rep. 82/06/18 PALLADING, N. Commissioners 2pp 14172 007 24X Fiche 50-250, 82/07/09, 2007300503
- P. Operating license stage documents & correspondence
- B207080064 Quaeric ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Bvc list encl
 DIRCKB,W J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24x Fiche 50-000,82/07/02.8207080064
- B208030050 Consents to provide FERC w/access to documentation provided by util & required by FERC & PSC of FL to retain, as backup to util record retention sys Util could establish symbiotic relationship to alleviate recordseeping burden HAASS W P Quality Assurance Branch B2/07/13 UHRIO.R E Florida Power & Light Co 2pp 14208 330 24% Fiche 50-000.82/07/13, 8208030050
- 82081j02i3 Forwards evaluation of proposed Tech Specs re organizational changes, per 8202i6 ltr Proposel to eliminate Figure 6 2-1 & composition of FL Power & Light Nuclear Raview Board unacceptable VARGA. 6 A Operating Reactors Branch 1 82/07/20 UHRIG, R E Florida Power & Light Co 4pp 14328 360 24X Fiche 50-230, 82/07/20, 82081i02i3
- B208100130 Informs that info requested in 820630 itr re NUREG-0737, Item II B 3. "Post-Accident Sampling Sys." will be transmitted on or before 821115 UHRIGRE Florida Power & Light Co 82/08/02 VARGA. B A Operating Reactors Branch i ip 14298,179 24X Fiche 50-250.82/08/02.8208100130
- B20B100075 Advises that radiological effluent Tech Bpec & offsite dose calculation manual will be submitted by B20910
 UNRIGHT E Florida Power & Light Co 82/08/09 EISENHUT, D 0
 Division of Licensing 1p 14296 174 24X Fiche 50-250, 82/08/05, 8228100075
- E208130037 Application for amend to Licenses DPR-31 & DPR-41. revising Tech Bpec Tables 3 5-2 re undergency buses, 3.5-4 re undervoltage relay setpoints & 4 i-1 re 4 i6-kV & 480-volt load ctr test requirements UHRIGAR E florida Power & Light Ca 82/08/04 EISENHUT, D 0 Division of Licensing 2pp 14335 075 24% Fiche 50-250, 82/08/06, 8208130039
- --B20Bi30042 Tech Bpec Tables 3 5-2 re emergency buses, 3 5-4 re undervoltage relay setpoints & 4 i-1 re 4 i6-kV & 480-volt load ctr test requirements e Florida Power & Light Co B2/08/06 5pp 14335 077 24X Fiche 30-230, 82/08/06, 820Bi30039
- B20B090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 1GCFR Chapter I requirements & provides alternatives to requirements Svc list enc1 EIBCHNUT.D O Division of Licensing B2/08/09 Consolidated Edison Co of New York ip 14936 332 24X Fiche 50-000,62/08/09,620B090194
- 9208170102 Forwards add1 info re schedular commitments for items in draft technical evaluation rept on control of heavy loads. URRIGER E Florida Power & Light Co 82/08/10 VARGA.8. A. Operating Reactors Branch 1 15pp 14366,003 24% Fiche 50-250: 82/08/10: 8208170102
- B208170116 Advises that response to Question 1 of NRC 820316 request for add1 info re containment purps & vent valve operability will be submitted by 821001 Util awaiting analysis from valve manufacturer, due in early 8ept 1982 UHRIGAR E Florida Power & Light Co. 82/08/10 VARGAR A Operating Reactors Branch 1, ip. 14358 187. 24X Fiche 50-250.62/08/10.6208170116
- 8208170123 Proposes mod to turbine runback sys, deleting flux rate input Bys prone to spurious runbacks due to single failure of electrical component Encl safety evaluation discusses consequences of single dropped rod control cluster assembly UHRIGIR.E Florida Power & Light Co. 82/08/10 EISENHUT.D Q Olvision of Licensing 4pp 14365.177 24X Fiche-50-250,82/08/10,8208170123

- 8208200133 Advises that final heat tracing components necessary for completion of containment hydrogen monitor.per NUREG-0737. Item II F 1 6.received from manufacturer on B20801 Estimated completion of installation reschaduled until 820730 UHRIO.R E Florida Power & Light Co B2/08/12 VARGA, 5 A Operating Reactors Branch I ip 14500 087 24% Fiche 50-250.82/08/12.8208200133
- 8208200295 Application for amend of Licenses DPR-31 & DPR-41.changing Tech Specs 6 5 2 3.6 5 2 4.6 5 2 5.6 5 2 6 & Figure 6 2-1 to update offsite organization URITOR E Florida Power & Light Co 82/08/12 EISENHUT.D 9 Division of Licensing 2pp 14394 354 24X Fiche 50-250.82/08/12, 8208200395
- --8208200299 Proposed changes to Tech Specs & 5 2.3, & 5.2 4, & 5.2 5, & 5 2 & K Figure & 2-1 to update offsite organization e Florida Power & Light Co 82/08/12 4pp 14394.356 24X Fiche 50-250.62/08/12.8208200295
- 8208190152 Advises that NUREQ-0737, Item II 0 i B, "PHR Relief & Bafety Valve Testing" is satisfied by submittal of "PORV Block Valve Info Package" & listed info UHRIO.R E Florida Power & Light Co 82/08/13 EISENHUT.D 0 Division of Licensing 2pp 14382 188 24X Fiche 50-250,82/08/13,8208180832
- Q Inspection reports, IE Bulletins & correspondence
- 8208030200 Ferwards IE Insp Repts 50-250/82-23 & 50-251/82-23 on 820415-17 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/04 UHRIO, R E Florida Power & Light Co. 2pp. 14158 278 24X Fiche 50-250, 82/07/04,8208030200
- --8209030224 IE Insp Repts 50-250/62-23 & 50-251/82-23 on 680615-17 No noncompilance noted Major areas inspected, seismic analysis for as-built safety-related piping (IE Bulletin 79-14) & pipe support baseplate design (IE Bulletin 79-02) ANG, W P . ECONDMOS, N Division of Engineering & Technical Programs 82/07/01 4pp 14:58 280 24X Fiche 50-250,62/07/06,6208030200
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN.E L. Division of Engineering & Quality Assurance 82/07/16,
 Consolidated Edison Co. of New York 87pp 14356-274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JURPAN.E L Division of Engineering & Quality Assurance 82/07/19 Mithigan. Univ of 112pp 14358 001 24X Fiche 80-000.82/07/19,8204210395
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list ancl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381:001 24X Fiche: 50-000, 82/07/20, 8204210396
- 8204210397 IE info Notice B2-24, "Water Leaking From U Hexafluoride Overpacks " Svc list and COMPLE I. Division of Fuel Facilities, Materials & Safeguards, 82/07/20 Consolidated Edison Co of New York, 7ipp. 14357, 276 24K Fiche 50-000, 82/07/20, 8204210397
- 8208210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Syc list encl. JORDAN, E. t. Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co. of New York 112pp 14194 321 24X Fiche 30-000, 82/07/22, 8204210398
- 8204210401 IE info Notice 82-28. "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl. JARDAN,E L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Esison Co. of New York 122pp 14380 115. 24X Fichs. 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drivs (CRD) guide Tube Support Fin Failures at Westinghouse PWRs " Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/23, Consolidated Edison Co.
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Bvc list encl. URDANIE L. Division of Engineering & Quality Assurance 62/07/26. Consolidated Editon Co. of New York 12ipp 14357 013. 24X Fiche: 50-000.82/07/26.8204210403

DOCKETED ITEMS

- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Hork in Fuel Storage Pool " Svc list and! Guality Assurance R2/07/28 JORDAN.E L Division of Engineering & Guality Assurance R2/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche: 50-000, 82/07/28, 8204210405
- 8208160317 Forwards 18 Insp Repts 50-250/82-25 & 50-251/82-25 on 820713-16 No noncompliants noted DANCE: H C Division of Project & Resident Programs 82/07/28 UHRIG, R E Florids Power & Light Co 2pp 14348 146 24X Fiche 50-250, 82/07/28, 8208160317
- --8208160416 IE Insa Repts 50-250/82-25 & 50-251/82-25 on 820713-16 No contouria it insp. Repts 50-250/82-25 & 50-251/82-25 on 820713-16 No moncompliance noted Major areas inspected radiological shviron monitoring mgt & administrative controls, QC of analytical measurements & monitoring stations CUNNINGHAM.A L. MONTOUMER, D.M. Division of Project & Resident Programs 82/07/28 5pp 14348 148 24% Fiche 50-250.82/07/28, 30001403.7 Frograms 82/07/28 8208160317
- 8208030404 Forwards IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16 No noncompliance noted DANGE.H C Division of Project & Resident Programs B2/0 WHRIO.R E Florids Power & Light Co 2pp 14154 008 2 Fiche 50-250.82/07/29.8208030404 82/07/29
- ~-8208030417 IE Bafeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16 No noncompliance noted Major areas inspected sacurity plan & implementing procedures, security organization & personnel. Datails withheld (ref 100FR73 21) STANSBERRY, W.W., MCOUIRE, D.R. Davision of Engineering & Technica Programs 82/07/29 ip 14154-010 24X Fiche 50-250.82/07/29, 8208030404
- 8208160267 Forwards info in response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PHR Plants "Control rod drive flanges have omega swal weld design No injection sealant mati used UHR10.R E. Florida Power & Light Co 82/08/02. O'REILLY.J P Region 2. Office of Director. 3pp. 14347 035 24X Fiche 30-230.82/08/02.8208160267
- 820Bi60354 Ack receipt of B2061B, 25 & 0715 ltrs informing NRC of steps taken to correct violations noted in IE Imap Repts 50-250/82-21 & 50-251/82-21 DANCE H C Division of Project & Resident Programs 82/08/03 UHRIO.R E Florida Power & Light Co ip 14347 084 24X Fiche 50-250.82/08/03,820Bi60354
- --8208160365 Forwards add] response to NRC 820514 ltr re violations noted in IE insp Repts 50-250/82-21 & 50-251/82-21 Corrective actions processel for method of tracking plant work order will be incorporated into applicable plant procedures UHRIG.R E Florida Power & Light Co 82/07/15 O'REILLY, J P Region 2, Office of Director 2pp 14349 085 24X Fiche: 50-250,82/08/03,8208160354
- -8208i60376 Forwards response to NRC ltr re violations noted in IE Insp Repts 30-280/82-21 & 50-281/82-21 Corrective actions: recorder switches for listed circuits returned to proper positions Response to Item 8 expected by 820714 UNRIO, R.E. Florida Power & Light Co. 82/06/18 0'REILLY, J.P. Region 2, Office of Director 3pp. 14347 087 24x Fiche 50-250,82/08/03,8208160354
- --8208160382 Forwards IE Insp Repts 50-250/82-21 & 50-251/82-21 on 820403-25 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/05/14 URIO.R E Floride Power & Light Co. 2pp 14349 090 24X Fichs 50-250,82/08/03,8208160354.
- --8208160386 Notice of violation from insp on 820403-25
 * Division of Project & Resident Programs 82/05/14 2pp
 14347:092 24X Fiche 50-250,82/08/03,8208160354
- --8208160394 IE Insp Repts 50-250/82-21 & 50-251/82-21 on 820403-RB Noncompliance noted failurs to follow procedure, failure to meet requirements of GA manual & failure to maintain updated stacedures. VOGT.R.J.: HARDIN, A K Division of Project & Resident Programs B2/05/12 App 14949 094. 24% Fiche 50-250,82/08/09,8208160354
- 9204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Bafele Water-Jet Ispingement " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/05 Consolidate Edison Co. of New York 117pp 14388, 201 24X Fiche 50-000, 82/08/05, 8204210407.

- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants to analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fichs 50-000, 92/07/13, 8208270010
- --8208270066 Forwards "Man Rem Rept.1981 "
 UHRIG.R E Florida Power & Light Co 82/03/02 G
 Region & Office of Director ip 14680 OI6 24X
 ficha 50-000.62/07/13/200270010 O'REILLY, J P
- ~~8208270072 "Man Rem Rept. 1981 " # Florida Power & Light Co 82/03/02 ip 14680 017 24x Fiche 50-000,82/07/13,8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB!" e NRC No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000,82/07/13,8208270010
- --8208270540 Forwards personnel monitoring rapts for 1981, per 10CFR20 407 W/a 8t Lucie rept UNRIO, R E Florida Power & Light Co 82/03/04 DPflici Management and Program Analysis ip 14680 028 24X Fiche 50-000, 82/07/13, 8208270010 Defice of
- ~~B208270545 Personnel monitoring repts for 1981
 * Florida Power & Light Co 82/03/04 ip 14680 029 24X
 Ficha 50-000,82/07/13,8208270010
- B20B120174 Forwards monthly operating repts for June 1982 & corrected Turkey Point 4 operating rept for May 1982 UILLIAMS, J W Florida Power & Light Co 82/07/15 Office of Resource Management, Director 19 14328, 001 24X Fiche 50-000, 82/07/15, 8208120174
- --8208120181 Monthly operating repts for June 1982 PACE.P Florida Power & Light Co 82/07/15 12pp 24% Fiche 50-000,82/07/15,8208120174 14326 002
- --8208120184 Corrected monthly operating rept for May 1782 PACE,P Florida Power & Light Co 82/07/15 ip 14: Fishe 50-600, 82/07/15, 8208120174
- S Reportable occurrences, LERs & related correspondence
- 8208200115 Forwards LER 82-011/03L-0 HILLIAMS: J W Florida Power & Light Co 82/0 Region 2: Office of Director 1p 14393 318 Fiche 50-250:82/08/12.8808200115 82/08/12 D'REILLY, J P.
- --B20B200125 LER B2-011/03L-0 on B20713, quarterly surveillance test of seismograph completed 3 days after last allowable Tech Epec date Caused by comst equipment blocking access to seismograph Test successfully completed on B20716 PACE; PL Florida Power & Light Co B2/0B/12 Region 2. Office of Director 2pp 14393.319 24x Fiche 50-250, B2/0B/12, B20B200115 Region 2. Office
- DOCKET 80-281 TURKEY POINT PLANT, UNIT 4 F Security, medical, emergency & fire protection plans
- S208030404 Forwards IE Safeguards Insp Repts 50-250/82-27 & 50-251/62-27 on S20712-16 No noncompliance noted, DANCE, H C. Division of Project & Resident Programs S2/07/2 UHRIO, R E. Florida Fouer & Light Co 2pp. 15154 008 24X Fichs 50-250, 82/07/29, 8208030404 82/07/29
- ---BZ08030417 IE Bafeguards Insp Repts 50-250/82-27 & 50-251/82-27 on BZ0712-14 No noncompliance noted Major areas inspected: security plan & implementing procedures, security organisation & personnel Details withheld (ref IOCFR73 21). BTANSBERRY, W W Division of Engineering & Technical Programs BZ/07/29. 1p 15154:010. 24% Fichs. 50-250, 82/07/29, 8208030404.
- 8208090061 Forwards Revision 5 to security plan & discussion on Section 8 4.4d) referenced in 8A Varga 920517 ltr Encis withheld (ref 100FR73, 21).

 UHRIO, R E Florida Power & Light Co. 82/07/30 EISENHUT, D Q Division of Licensing 1p, 14270 357 24X Fiche 50-250, 82/07/30, 8208090061

- 8208110240 Releases public version of emergency plan implementing procedure FELTON, J M Division of Rules and Records 82/08/05 Document Management Branch 1p 14331 030 24% Fiche 50-250,82/08/05, e2/0810240
- --B20B110242 Forwards public version of Emergency Plan Implementing Procedure 20124, "Offsite Dose Calculations." per 820727 telcon UHRIO.R E Florida Power & Light Co 82/07/28 O'REILLY, J P Region 2. Office of Director 10 14331 032 24X Fichs 50-250,82/08/05,8208110240
- --8208110244 Public version of Emergency Plan Implementing Procedure 20126, "Offsite Dose Calculations"

 HAYS, J. C. WILLIAMS, J. W. Fibrida Power & Light Co. 82/05/17
 28pp 14331 033 24X Fiche 50-250,82/08/05,8208110240
- 8208230007 Forwards corrected discussion of Section 8 4(d) of physical security plan referenced in 8 Varga 820517 ltr Discussion withheld (ref 10CFR73 21) UHRIOR E Florida Power & Light Co 82/08/14 EISENHUT, D 0 Division of Licensing ip 14517 273 24X Fiche 50-250.82/08/16, 8208230007

H General correspondence

- 8207300503 Responds to 820618 ltr re steam generator tube degradation at plant Encl safety evaluation & Amend 80 provides basis for approval to operate Unit 4 until Oct 1982 Special actions based on Ginna event under consideration M/o encl DIRCKS,M J Office of the Executive Director for Operations 82/07/09 FASCELL,D B House of Rep 7pp 14172 OD1 24X Fiche 50-250,82/07/09,8207300503
- --8206200036 Expresses constituent concern re steam generator tube degradation problem at plant Basis of NRC decision allowing util to operate Unit 4 until Oct 1982 & hearing of event at Ginna on plant requested FAECELL.D B House of Rep 82/06/18 PALLADINO.N Commissioners 2pp 14172 007 24X Fiche 50-250,82/07/09,8207300503
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CF re Commission approved charter for CAGR Byc list encl DIRCKS; NJ Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 OOI 24X Fiche 50-000, 82/07/02, 8207080044
- B208030050 Consents to provide FERC w/access to documentation provided by util & required by FERC & PBC of FL to retain as backup to util record retention sys Util could establish symbiotic relationship to alleviate record keeping burden HAASS, H P Quality Assurance Branch B2/07/13, UHRIO, R E Florida PAWER & Light Co 2pp 14208 330 24X Fiche. 50-000, 82/07/13, 8208030050
- 8208060028 Notification of 820723 meeting w/util in Bethesda. ND to discuss findings & corrective action per License Condition 3 D I re steam generator leak OKDYENKUIS.M Operating Reactors Branch 1. 82/07/20 VARGA. 8 A Operating Reactors Branch 1 2pp. 14244 338. 24% Fiche 30-231.82/07/20.8208060028
- e208i102i3 Forwards evaluation of proposed Tech Epecs re organizations) changes,per 8202i6 Itr Proposal to sliminate Figure & 2∞1 & composition of FL Power & Light Nuclear Review Board unacceptable VARQA,S,A Dperating Reactors Branch i 82/07/20 UHRIG,R E Florida Power & Light Co 4pp 14328 360 24X Fiche 50-250,82/07/20,82081102i3,
- 8203160286 Agrees to changes in dates proposed for Sections 1 & 3 per util 820630 ltr.in response to 820408 confirmatory action ltr.Section 2 remains unchanged O'REILLY.J.P. Region 2. Office of Director 82/07/22 HANCGCK.J.A Florids Fower Corp 1p 14346 275 24X Fiche 50-302.62/07/22.8208160286
- 8208100130 Informs that info requested in BR0630 Itr re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys," will be transmitted on or before 821115 UMRIG.R.E. Florida Power & Light Co 82/08/02 VARGA, 8 A Operating Reactors Branch I ip 14298-179 24X Fiche. 30-250, 82/08/02, 8208100130

- 8208100075 Advises that radiological effluent Tech Spec & offsite dose calculation manual will be submitted by 820910
 UHRIGAR E Florida Power & Light Co 62/08/05 EISENHUT.D Q
 Division of Licensing 1p 14276 174 24X Fiche 50-250,82/08/05.
- 8208130039 Application for amend to Licenses DPR-31 & DPR-41, revising Tech Spec Tables 3 5-2 re emergency buses, 3 5-4 re undervoltage relay setpoints & 4 1-1 re 4 16-10 & 480-volt load ctr test requirements
 UHRIO,R E Florida Power & Light Co 82/08/06 FISENHUT, D 9 Division of Licensing 2pp 14335 075 24% Fiche 50-250, 82/08/06, 8208130039
- --8208130042 Tech Spec Tables 3 5-2 re emergency buses, 3 5-4 re undervoltage relay setpoints & 4 1-1 re 4 14-kV & 480-volt load ctr test requirements Florida Power & Light Co. 82/08/06 5pp. 14339 077 24X Fiche 50-250, 82/08/06, B208130039
- 820B090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D Ø Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208170102 Forwards addl info re schedular commitments for items in draft technical evaluation rept on control of heavy loads UHRIO.R E Florida Power & Light Cd 82/08/10 VAROA.8 A Operating Reactors Branch I 15pp 14366 003 24X Fiche 50-250.82/08/10.9208170102
- 820B170116 Advises that response to Guestion 1 of NRC 820316 request for add1 info re containment purge & vent valve operability will be submitted by 821001 Util awaiting analysis from valve manufacturer, due in early Sept 1982 UHRIO, R E Florida Power & Light Co 82/08/10 VAROA, S A Operating Reactors Branch 1 1p 14358 187 24X Fiche 50-250, 82/08/10, 8208170116
- 8208170123 Proposes mod to turbine runback sys.dejeting flux rate input Sys prone to spurious runbacks due to single failure of electrical component Encl safety evaluation discusses consequences of single dropped rod control cluster assembly UHRIG.R E Florida Power & Light Co 82/08/10 EISENHUT.D 0 Division of Licensing 4pp 14363 199 24X Fiche 50-250.82/08/10.8208170123
- 8208200133 Advises that final heat tracing components necessary for completion of containment hydrogen monitor, per NUREC-0737, Item II F1.6. received from manufacturer on 820801 Estimated completion of installation rescheduled until 820930 UHRIO, R E Floride Power & Light Co 92/08/12 VAROA, 9 A Operating Reactors Branch 1 1p 14500 087 24X Fiche 50-250, 82/08/12,8208200133
- 8208200293 Application for amend of Licenses DPR-31 & DPR-41, changing Tech Spece & 5 2 3.6 5 2 4.6 5 2 5.6 5 2 6 & Figure & 2-1 to ugdate offsite organization UHRIG, R E Florida Power & Light Co 82/08/12 EISENHUT, D. G Division of Licensing 2pp 14394 354 24X Fiche 50-250, 82/08/12. 8208200295
- --8208200279 Froposed changes to Tech Specs & 5 2 3.6 5 2 4.6 5 2 5. & 5 2 6 & Figure & 2-1 to update offsite organization # Florida Power & Light Co 82/08/12 4pp 14374:356 24X Fiche 50-250,82/08/12,8208200275
- 820B190152 Advises that NUREO-0737. Item II D 1 B, "PWR Relief & Safety Valve Testing" is satisfied by submitted of "PORV Block Valve Info Package" & listed info UHRIO.R. E. Floride Power & Light Co 82/08/13 EISENHUT, B. O Division of Licensing 2pp 14382 188 24X Fiche 50-250, 82/08/13, 820B190152
- Q Inspection reports. IE Bulletins & correspondence
- 8208030200 Forwards IE insp Repts 50-250/82-23 & 50-251/82-23 on B20615-17, No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/06 UHRIO, R E Florida Power & Light Co 2pp 14158, 278 24X Fiche 50-250, 82/07/06, 8208030200
- --B208030224 IE Insp Repts 50-250/B2-23 & 50-251/B2-23 on 820615-17. No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping (IE Bulletin 79-14) & pipe support baseplate design (IE Bulletin 79-02) ANG W P. ECONOMOS. N Division of Engineering & Technical Programs B2/07/01 App 1415B 280 24X Fiche 50-250,82/07/04, B208030200

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valva (MSIV) Leakage " Eve list enel JORDAN.E L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co. of New York 87pp 14356 274 24X Fiche 50-000.82/07/16.8204210393
- 8204210395 IE Info Notice 81-26, Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc 1(st encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fichs 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluorido Overpacks " Svc list encl COBBLL 1 Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14037 276 24X Fiche 50-000,82/07/20.8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/22, Consolidated Edison Co of New York 112pp 14194 321 24X Fiche: 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Svc list encl JORDAN, E. L. Division of Engineering & Guelity Assurance 62/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rad Brive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl. JORDAN, E. L. Division of Engineering & Guality Assurance. 82/07/23 Consolidated & Gison Co. of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PMR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357:013 24X Fiche.50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool," Syc list encl, JORDAN,E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- B20B160317 Forwards IE Insp Repts 50-250/B2-25 & 50-251/B2-25 on B20713-16 No noncompliance noted DANCE.H C Division of Project & Resident Programs B2/07/2B. UHRIO.R.E Filenida Power & Light Co 2pp 1434B 146 24X Fiche 50-250, B2/07/2B, B20B160317
 - 3208160416 IE Insp Repts 50-250/82-25 & 50-251/82-25 on 620713-16 No noncompliance noted Major areas inspected radiological environ monitoring mgt & administrative controls CC of analytical measurements & monitoring stations CUNNINOHAM. A L . MONTGOMERY, D M Division of Project & Resident Programs 82/07/28 5pp 14348 148 24X Fichs 50-250.82/07/28, 8208160317
 - 08030404 Forwards IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16. No noncompliance noted.

 DANCE: H.C. Division of Project & Resident Programs 82/07/29 URFIOR E. Florida Fauer & Light Co 2pp 14154-008 24% Fiche. 50-250, 82/07/29, 8208030404.
- 8208030417 IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16. No noncompliance noted Major areas inspected security plan & implementing procedures, security organization & personnel Details withheld (ref 100FR73 21). STANSBERRY, W W . MCGUIRE, D R. Division of Engineering & Technical Programs 82/07/29 is 14154 010 24% Fichs 50-250, 82/07/29, 8208030404
- #208160267 Forwards info in response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PHR Plants." Control rod drive flanges have onega seal weld design No injection sealant mati used UMRIO, R.E. Florids Power & Light Co. 82/08/02. D'REILLY, J.F. Region 2, Office of Director. 3pp 14347-035 24X Fiche: 50-250, 82/08/02, 8208160267.

- 8208160354 Ack receipt of 820618.25 & 0715 ltrs informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-250/82-21 & 30-251/82-21 DANCE.H C Division of Project & Resident Programs 82/08/03 UARTO,R E Florida Power & Light Co 1p 14349 084 24X Fiche 50-250.82/08/03.8208160354
- --8208160365 Forwards add1 response to NRC 820514 ltr re violations noted in IE Insp Repts 50-250/82-21 & 50-251/82-21 Corrective actions proposal for method of tracking plant work order will be incorporated into applicable plant procedures UHRIO,R E Florida Power & Light Co 82/07/15 O'REILLY, J P Region 2. Office of Director 2pp 14349 085 24x Fichs 50-250,82/08/03,8208160354
- --8208160376 Forwards response to NRC itr re violations noted in IE Insp. Repts 50-250/82-21 & 50-251/82-21 Corrective actions recorder switches for listed circuits returned to proper positions Response to Item B expected by 820714 UMRIG.R E Florida Power & Light Co 82/06/18 D'REILLY, J P Region 2. Office of Director 3pp 14349 087 24X Fichs 50-250, 82/08/03, 8208160354
- --8208160382 Forwards IE Insp Repts 50-250/82-21 & 50-251/82-21 on 820403-25 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/05/14 UKRIO.R E Florida Power & Light Co 2pp 14349 090 24X Fiche 50-250,82/08/03,8208160354
- --8208160386 Notice of violation from insp on 820403-25 * Division of Project & Resident Programs 82/05/14 2pp 14247 092 24X Fiche 50-290, 82/08/03,8208160354
- --B208160394 IE Insp Repts 50-250/82-21 & 50-251/82-21 on 820403-25
 Noncompliance noted failure to foliow procedure, failure to
 meet requirements of GA manual & failure to maintain updated
 procedures
 VQOT,R J, HARDIN,A K, Division of Project & Resident Programs
 82/05/12 6pp 14347,074 24X Fiche 50-250,82/08/03,8208160354
- 8204210407 IE Info Notice 62-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 62/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fichs. 50-000, 82/08/05, 8204210407.
- B20B160296 Forwards "Repts of Bteam Generator Inep & Tube Repair Jul 1982 Gutage " UHRIO,R E Florida Power & Light Co 82/08/09 EIBENHUY,D G Division of Licensing ip 14345-322 24X Fiche 50-251,82/08/09, 82/81460294
- --8208160303 "Rept of Steam Cenerator Insp & Tube Repair Jul 1982 "Outage" " Florida Power & Light Co 82/07/31 40pp 14345 323 24% Fiche 50-251.82/08/09.8208160296
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/07/13 UDELL. R A Critical Mass Energy Project 8pp 14679; 208 24X Fichs. 50-000, 82/07/13, 8208270010.
- --B208270066 Forwards "Man Rem Rept, 1981 "
 UNRID:R.E Florida Power & Light Co 82/03/02 D'REILLY, J P
 Region 2. Office of Director ip 14680'016 24X
 Fichs. 30-000, 82/07/13, 8208270010
- --8208270072 "Man Rem Rept, 1981." * Florida Power & Light Co 82/03/02 1p 14680 017 24X Fich# 50-000,82/07/13,8208270010
- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81." * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679:216 24X Fiche 80-000, 82/07/16,8208270010
- --8208270540 Forwards personnel monitoring repts for 1981, per 10CFR20.407. W/o 8t Lucie rept URIG.R.E. Florids Power & Light Co 82/03/04 Office of Hanagement and Program Analysis 1p 14680 028 24X Fiche 50-000, 82/07/13, 8208270010.
- --8208270545 Personnel monitoring repts for 1981 * Flatida Power & Light Go 82/03/04 ip 14680 029. 24X Fiche. 50-000, 82/07/13, 8208270010

- 8208120174 Forwards monthly operating repts for June 1982 & corrected Turkey Point 4 operating rept for May 1982 WILLIAMS, J H. Florida Power & Light Co. B2/07/13 Office of Resource Management. Director 1p 14326 001 24% Fiche 50-000, 82/07/15, 8208120174
- --8208120181 Monthly operating repts for June 1982 PACE.P Florida Power & Light Co 82/07/15 12pp 14326 002 24% Fiche 30-000.82/07/15.8208120174
- --B20B120186 Corrected monthly operating rept for May 1982 PACE,P Florida Power & Light Co 82/07/15 ip 14326 014 24X Fiche 50-000,82/07/15.8208120174
- S Reportable occurrences, LERs & related correspondence
- 8208020177 Forwards LER 82-009/03L-0 WILLIAMB.J H Florida Power & Light Co 82/07/23 O'REILLY.J P Region 2. Office of Director ip 14141 200 24X Fiche 50-251.82/07/23.8208020177
- --B20B0201B0 LER 82-007/03L-0 on 820623, biwsekly testing for Tave & Delta T protection channel was completed 2 days after latest data alloweble Caused by computation using completion date for previous test Channel test completed 820625 PACE, P L Florida Power & Light Co 82/07/23 Region 2, Office of Director 2pp 14141 201 24X Ficha 50-251,82/07/23, 8208020177
- 8208200128 Forwards LER 82~010/03L-0 HILLIAMS.J W Florida Power & Light Co 82/08/12 D'REILLY.J P Region 2. Office of Director ip. 14393 348. 24X Fiche 30-201.82/08/12.8208200128
- --B20B200144 LER 82-010/03L-0 on B20713, camera insp of steam generators revealed foreign objects & minor tube damage Leak & minor tube damage caused by foreign objects near tube sheet elevations Motal impact monitoring sys installed PACE.P.L Florida Power & Light Co 82/08/12 Region 2, Office of Director 4pp 14393 347 24X Fiche 50-251,82/08/12,8208120128
- OCCRET 50-252 UNIV OF NEW MEXICO RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 820B170231 Forwards IE Safeguards Insp Rept 50-232/82-02 on B20617-18 & notice of violation Rept & notice of violation withheld (ref 10CFR2 790)
 BEIDLE: H C Division of Resident, Reactor Project & Engineering Programs 82/08/13 WOODALL.D New Mexico, Univ of 2pp 14370,070 24X Fiche 50-232,82/08/13.8208170231
- O Inspection reports, IE Bulletins & correspondence
- 820B170231 Forwards IE Safeguards Insp Rept 50-252/82-02 on 820617-18 & notice of violation Rept & notice of violation withheld (ref 10GFR2.790)
 8EIDLEH C Division of Resident, Reactor Project & Engineering Progrems 82/08/13 WD0DALL, D New Merico, Univ of, 2pp 14370 070. 24X Fiche 50-252,82/08/13,8208170231
- 8208300117 Forwards corrected notice of violation re IE Insp Rept 50-252/82-02 on 820617-18 Notice of violation sent on 820813 did not show security level Notice of violation withheld (ref 100FR2 790) SEIDLE: W C. Division of Resident, Reactor Project & Engineering Programs 82/08/24 WOODALL.D New Mexico, Univ. of ip 14678 147 24X Fiche 50-252,82/08/24,8208300117
- DOCKET 50-254 QUAD-CITIES STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8208040469 Releases public version of revised emergency plan implementing procedures FELTON-J M Division of Rules and Records 82/07/23 Document Hanagement Branch ip. 14220,289 24X Fichs: 50-254,82/07/23,8208040469.
- --8208040475 Forwards public version of Revision 2 to Emergency P)an Implementing Procedure GEP 530-3, "Offshift Augmentation Drill" & Revision 10 to GEB 530-0, "Exercises & Drills " Receipt form encl ROMACK,T J. GERNER, L. Commonwealth Edison Co. 82/06/21, DENYON, H R. NRC No Detailed Affiliation Given 1p 14220:270 24X Fiche 50-254,82/07/23,8208040469.

- --8208040481 Public version of Revision 2 to Emergency Plan Implementing Procedure OEP 530-3, "Offshift Augmentation Drill" & Revision 10 to OEP 530-0, "Exercises & Dills "

 * Commonwealth Edison Co. 82/06/21 3pp 14220 291 24X Fiche 50-254, 82/07/23, 9208040469
- B20B200137 Forwards response to 820112 request re exercise objectives, scope of participation & scenario outline for Aug 1982 emergency plan exercise RAUSCH.T J Commonwealth Edison Co 82/08/02 KEPPLER.J G Region 3, Office of Director 7pp 14393 283 24% Fiche 50-254.82/08/02, 8208200137
- 8208110230 Releases public version of revision to emergency plan implementing procedure FELTON, J H Division of Rules and Records 82/08/05 Document Management Branch 1p 14330 309 24X Fiche 50-254,82/08/05,8208110230
- --8208110234 Forwards public version of Revision 12 to Emergency Plan Implementing Procedure GEP 330-0, "Assessment Actions" Receipt form encl KOVACK.T J. TIET.O C. Commonwealth Edison Co. 82/07/17 DENTON.H R. NRC - No Detailed Affiliation Given ip 14330 310 24X Fiche 50-254.82/08/05,8208110230
- --8208110238 Public version of Revision 12 to Emergency Plan Implementing Procedure GEP 330-0, "Assessment Actions" * Commonwealth Edison Co 82/07/17 2pp 14330.311 24X Fiche 50-254,82/08/05.8208110230
- 8208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures "
 FELTON.J M Division of Rules and Records 82/08/12 Document Management Branch 1p 14559 354 24X Fiche 50-000,62/08/12, 8208250559
- --8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures "
 HODRER D Commonwealth Edison Co 82/07/19 DENTON, H R NRC No Detailed Affiliation Given ip 14559 395 24X
 Fithe 50-000, 82/08/12, 8208230539
- --B208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures "
 + Commonwealth Edison Co 82/06/30 7pp 14559:356 24X Fiche 50-000,82/08/12.8208250559
- 8208230107 Forwards revised cable discrepancy lists re fire protection wafe shutdown analyses Lists Indicate how each discrepancy noted in fire protection associated circuit analysis & mod regts will be resolved RAUSCH.T J Commonwealth Efison Co. 82/08/13 EISENHUT, D O Division of Licensing 200 14515 001 24X Fiche 80-000.82/08/13, 8208230107
- --8208230122 "Fire Protection Cable Discrepancy List.Guad Cities Unit 1 "
 + Commonwealth Edison Co 82/08/06 250pp. 14515 293. 24X
 Fiche 50-000,82/08/13,8208230107
- 8208270523 Forwards IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722 & 23.No nuncompliance noted PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Bupport 82/08/13 REED, C. Commonwealth Edison Co. 2pp 14566:030 24X Fiche:50-254,82/08/13,8208270523
- --8208270527 IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722-23 No noncompliance noted. Hajor areas inspected prompt public notification/warning sys PATTERBON, J. P., AXELBON, W. L. Division of Emergency Preparedness & Operational Support. 82/08/13. 3pp 14566 032 24X Fiche 50-254, 82/08/13. 8208270523
- 8208230328 Ack receipt of 820806 ltr & 820812 telcon requesting that assembly & accountability portion of 820824 emergency exercise be conducted on 820819 Assembly & accountability should be conducted w/annual exercise PAPERIELLO.C J. Division of Emergency Preparedness & Operational Support. 82/08/18 KALIVIANAKIE,N Commonwealth Edison Co. 2pp. 14508-260 24X Fiche:50-254.82/08/18.8208230328
- --8208230333 Requests NRC approval to conduct site assembly portion of 820824 emergency exercise as separate drill on 820819 Heparate drill would allow will to more effectively use manpower during exercise KALIVIANAKIS, N Commonwealth Edison Co. 82/08/06 PAPERIELLO, C Division of Emergancy Preparedness & Operational Support 2pp 14508:262, 24X Fiche. 50-254, 82/08/18, 8208230328

@ Adjudicatory correspondence

- 9208240267 Response to ASLE 920728 order Requests leave to withdraw application w/o prejudice Need for transshipment in near-term reduced due to approval of installation of high density spent fuel racis Certificate of Byc encl STEPTOE.P Commonwealth Edison Co STEPTOE.P Isham, Lincoln & Beale 82708/18 About 8afety and Licensing Soard Panel Op; 14527 120 24% Fiche 50-000,82708/18.8208240267
- 8208240265 Response to ASL8 820728 order NRC does not object to proceeding termination since licensee has moved to withdraw license application w/o prejudice, due to decision in Dresden high density storage rack case W/Certificate of Svc WRIOHT.N A Hearing Branch 2 82/08/20 Abomic Safety and Licensing Board Panel 3pp 14527 126 24X Fiche 50-000,82/08/20,8208240265
- P Operating license stage documents & correspondence
- B20B050050 Forwards Amends 78 & 72 to Licenses DPR-29 & DPR-30, respectively, safety evaluation & notice of issuance & availability Amends change Tech Specs to extend operation to 820701 to allow completion of RHR svc water sys mods BEVANNR B Operating Reactors Branch 2 82/05/27 DELOGORDE.L Commonwealth Edison Co. 2pp. 14282-102 24X Fiche 50-254,82/05/27,820B050050
- --8208060060 Amends 78 & 72 to Licenses DFR-27 & DFR-30 respectively, changing Tech Specs to extend operation to 820701 to allow completion of mods to PHR svc Water sys WASSALLO, D B Operating Reactors Branch 2, 82/05/27 10pp 14282 104 24X Fiche 50-254,82/05/27,8208060050
- --8208060063 Safety evaluation supporting Amends 78 & 72 to Licenses PPR-29 & DPR-30, respectively • Office of Nuclear Reactor Regulation, Director 82/05/27 2pp 14282 114 24% Fiche 50-254-82/05/27.8208060050
- --B208060054 Notice of issuance & availability of Amends 78 & 72 to Licenses DPR-29 & DPR-30, respectively VASSALLO, D B Operating Reactors Branch 2 82/05/27 2pp 14282 i16 24% Fichs 30-254, 82/05/27, 8208060050
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of GP re Commission approved charter for GROR Svc list encl.

 DIRCKS.H J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York, 93pp 14194 001 24% Fiche 30-000,82/07/02,8207080064
- 8208090024 Requests formal notification within 30 days if NRC understanding that util will meet stated positions of NUREO-0737, Item III.D 3 3, "Improved In-Plant Lodine Instrumentation Under Accident Conditions," is correct VASSALLO, B 8 Operating Reactors Branch 2 82/07/21 DELGEGRGE, L. Commonwealth Edison Co 2pp 14293 358 24X Fiche 50-254,82/07/21,8208090024
- G208050066 Advises that ESF reset controls comply w/NRC criteria.subj to IE confirmation NDVAK T M Assistant Director for Operating Reactors 62/07/28 JORDAN E.L Division of Engineering & Guality Assurance 1p 14242 069. 24X Fiche 50-234,82/07/28,8208050066
- --9209050080 Safety evaluation supporting plant compliance w/ESF reset controls per NRC criteria e NRC - No Detailed Affiliation Given 82/07/28 2pp 14242 071. 24X Fiche 50-294.82/07/28.8208050066
- 8208180266 Forwards revised version of model Tech Specs for reactor protection sys/power monitoring sys design VASSALLO, D.B. Operating Reactors Branch 2 82/07/29 DELGEGRGE, L. Commonwealth Edison Co. 3pp 14387 318, 24X Fishe 50-000,82/07/28,8208180266
- --8208180271 Revised model Tech Specs re electric power monitoring of reactor protection sys design.

 * Operating Reactors Branch 2 82/07/28. 19 14389.321. 24X Fishe 50-000,82/07/28.8208180266

- 8208110041 Forwards response to request to cross-ref info re environ qualification of safety-related equipment & TMI action plan equipment SWARTZ-E D Commonwealth Edison Co 82/09/02 RISENHUT, D & Division of Licensing 557pp 14315 001 24X Fiche 50-000, 82/08/02.8208110041
- 820Bi30046 Requests approval to delay implementation of commitments in response to Generic Ltr 82-05 re NUREG-0737. Item If F I 6, "Containment Hydrogen Monitor" Completion postponed until 840I01 to accommodate schedule requirements SWARTZ.E D Commonwealth Edison Co 82/08/05 EIBENHUT.D 0 Division of Licensing 2pp 14335 333 24X Fiche 50-000, 82/08/05, 8208133044
- 8208240148 Requests add1 info.verifying satisfaction of encl acceptance criteria re NUREG-0737, Item II.K 3 22. "Automatic Switchover of Reactor Core Isolation Cooling Sys Suction " Response requested within 30 days
 VASSALLO.D B Operating Reactors Branch 2 82/08/05 DELOEORGE, L
 Commonwealth Edison Co 4pp 14548 181 24X Fiche 50-254, 82/08/05,
- 8208110188 Forwards revised pages to CE-1-A. "Comm Ed QA Program for Nuclear Generating Stations." Revision 21 Revised pages correct typographical & other minor errors EMARTZ.E Commonwealth Edison Co 82/08/06 HAASS.W P Quality Assurance Branch 1p. 14314:079, 24X Fiche 50-000.82/08/06, 820810188
- --820B110204 Revised pages to CE-1-A-Revision 21, "Comm Ed GA Program for Nuclear Generating Stations," • Commonwealth Edison Co 82/06/06 11pp, 14314-080 24X Fiche 30-000,82/08/06/8208)10189
- 8208240040 Forwards Amends 81 & 75 to Licenses DPR-29 & DPR-30, respectively & notice of Issuance & availability Amends authorize replacement of water quality requirements w/anviron protection plan VABSALLO, D 8 Operating Reactors Branch 2 82/08/06 DELGEORGE, L. Commonwealth Edison Co 3pp. 14529 316 24X Fiche 50-254.82/08/06, 82/08240040
- --8208240046 Amends 81 & 75 to Licenses DPR-29 & DPR-30 respectively, replacing water quality requirements w/environ protection plan
 VASBALLO.D B Operating Reactors Branch 2 82/08/06, 18pp
 14529 319 24X Fiche 50-254,82/08/06,8208240040
- --8208240050 Notice of issuance & availability of Amends 81 & 75 to Licenses DPR-29 & DPR-30, respectively VASBALLO, D B Operating Reactors Branch 2 82/08/06 2pp. 14529 337. 24X Fiche 50-254, 82/08/06,8208240040
- 8208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Bvc list encl EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356-332 24X Ficher 50-000, 82/08/09, 8208090194.
- 820B170135 Responds to NRC B20721 request to provide notification if util intends to deviate from NUREQ-0737. Item III D. 3 3, "Improved In-Plant Iodine Instrumentation Under Accident Conditions " Both facilities comply wirequirement SHARTI.E D Commonwealth Edison Co 82/08/12 EISENHUT, D 0 Division of Licensing 2pp 14365 211 24X Fichs.50-000.82/08/12, 8208170135
- 8208290455 Advises of satisfactory response to NUREG-0737, Item
 II K 3 24. "Adequacy of Space Cooling for HPCI & Reactor
 Core Isolation Cooling Sys " Befety evaluation encl
 VASBALLD, D B Operating Reactors Branch 2 82/08/13 DELGEORGE, L
 Commonwealth Edison Co 3pp 14562 283 24X Fiche 50-254,82/08/13,8208250455
- 8208270250 Application for amend to License DFR-29, proposing Tech Spec changes to implement IOCFR50 59 reload licensing w/ODYN transient analyses & extended exposure MAPLHOR limits Significant changes discussed, Class III amend fee encl RAUSCH.T. J Commonwealth Edison Co 82/08/19. DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 14544 601 24X Fiche 50-000, 82/08/19. 8208270250
- --820827025¢ Proposed Tech Spec changes to implement 100FR30 59 reload licensing ω/ODYN transient analyses & extended exposure MAPLHOR limits.

 Commonwealth Edison Co 82/08/19 20pp 14564,006, 24X Fiche. 50-000,82/08/19,8208270250,

- --B208270273 Errata & Addenda Sheet 7. replacing Pages 4-11 & 4-14 to "LOCA Analysis Rept for Dreaden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations " & General Electric Co NEDO-24246A ERR 07 B2/07/31 5pp. 14564 026 24% Fiche 50-000, B2/08/19, B208270250
- B20B270296 Informs that analysis to determine appropriate equipment quelification temp profiles will be submitted in Sept 1982, not Jul 1982, as previously indicated RAUGCH, T. J. Commonwealth Edison Co. 82/08/23 VASSALLO, D. B. Division of Licensing ip 14564 177 24X Fiche 50-000, 82/08/23, 8208270296
- 8208310402 Submits supplemental response to Generic Ltr B2-05 re NUREO-0737. Item II F 1 3, "Containment High-Range Radiation Manitor " Requests delay of implementation until 821030 due to delivery problems SKARTZ, E D Commonwealth Edison Co 82/08/27, EISENHUT, D 0 Division of Licensing 1p 14694 308 24X Fiche 50-254,82/08/27,8208310402
- O Inspection reports, IE Bulletins & correspondence
- 8208050414 Forwards IE Insp Repts 50-237/81-39.50-249/81-32, 10-254/81-23.50-265/81-23.50-275/81-31 & 50-304/81-27 on 810813-820503 No noncompliance noted KEPPLER. J 0. Region 3. Office of Director 82/07/12 REED. C Commonwealth Edison Co. ip 14217 166 24X Fiche 50-000.82/07/12, 8208050414
- --B208050441 IE Insp Repts 50-237/B1-39, 50-249/B1-32, 50-254/B1-23, 50-265/B1-23, 50-275/B1-31 & 50-304/B1-29 on B10813-B20503 No noncompliance noted Major areas inspected allegations re Comm Ed operation of facilities & compliance w/100FR21 MAYES, D W , PHILLIP, O A , HINDB, J M Division of Project & Resident Programs B2/07/09 154pp 14217 169 24X fithe 50-000, B2/07/12, B208050414.
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (HBIV) Leakage." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 30-000,82/07/16.8204210393.
- 820421039B IE Info Notice 81-26,Part 3.Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19, 2014/10.395
- 8208050424 Forwards IE Insp Repts 50-254/82-08 & 50-265/82-09 on 820428-0627 & notice of violation SPERSARD, R L Division of Project & Resident Programs 82/07/19, REED, C Communication Edison Co. 2pp 14214 076 24X Fiche 80-254,82/07/19,8208050424
- --B208050426 Notice of violation from insp on 820428-0629 SPESSARDR R L Division of Project & Resident Programs. B2/07/19. 2pp 14214,078 24% Fiche 50-224. B2/07/19. B208050424.
- --8208050435 IE Insp Repts 50-284/82-08 & 50-265/82-09 on 820428-0629. Noncompliance noted, failure to perform required testing after maint on safety-related equipment & failure to provide condensate flood protection CHRIGGOTIMOB,N. DUPONTIS.G., MALKER,R D Division of Project & Resident Programs 82/07/11 15pp 14214 080, 24X Fiche: 50-254,82/07/19:8208050424
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl.

 WORDAN,E L Division of Engineering & Quality Assurance, 82/07/20
 Conselidated Edison Co of New York, 112pp 14381 001 24X
 Fichs 50-000,82/07/20,8204210394.
- 8204210397 IE Info Notice 82-24, "Water Lesking From U Mexafluoride Overpacks" Byc list encl COBB.L.I. Division of Fuel Facilities, Materials & Bafeguards, 82207/20. Consolidate Edison Co of New York 7ipp, 14357 276, 24X Fiche: 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" 8vc list encl JCROAN.E L Division of Engineering & Guality Assurance. 82/07/22. Consolidated Edison Co of New York 112pp 14194 321 24X Fichs.50-000.82/07/22.8204210398.
- B2042i0401 IE Info Notice B2-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Evo list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/23. Consolidated Edison Co. of New York 122pp 14380:115 24% Fithe 50-000 82/07/23.82042i0401.

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Wastinghouse PWRs " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 02/07/23. Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000.82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Bvc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/26, Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, 82/07/26, B204210403
- 8204210405 IE Info Notice B2-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, B2/07/28, 8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
 JORDAN,E L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000,82/08/05,8204210407
- 8208270523 Forwards IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722 & 23 No noncompliance noted PAPERIELLO:C J Division of Emergency Preparedness & Operational Support 82/08/13 REED,C Commonwealth Edison Co 2pp 14566
- --8208270527 IE Insp Repts 50-284/82-12 & 50-265/82-13 on 820722-23 No noncompliance noted Major areas inspected prompt public notification/warning sys.

 PATTERSON.J P., AXELSON,M.L. Division of Emergency Preparedness & Operational Support 82/08/13, 5pp 14566 032, 24X Fiche 50-254,82708/13,8208270523
- 8208310336 Forwards IE Insp Repts 50-254/82-13 & 50-265/82-15 on 8200719-23,27 & 0806 No noncompliance noted.

 PAPERIELLOC J Division of Emergency Preparedness & Operational Support 82/08/17 REED,C Commonwealth Edison Co 2pp 14692,135 24X Fiche 50-254,82/08/17,8208310336
- --8208310351 IE Insp Repts 50-254/82-13 & 80-265/82-15 on 820719-23,27 & 0806 No noncompliance noted Major areas inspected confirmatory program & associated GC procedures NICHOLBON,N A. RDZAK.8. SCHUMACHER.M C. Division of Emergency Preparadness & Operational Support. 62/08/17 8pp 14692 137 24X Fiche 30-254,82/08/17.8208310336
- 8 Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for foruments detailing collective dose exposures in 1781 for operating nuclear power plants k analyzing said info Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13.8208270010
- --820827009B "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679.216 24X Fichs 50-000.82/07/13.8208270010
- --B208270263 Forwards "1981 Rept of Occupational Personnel Radiation Doses" KALIVIANAKIG, N. Commonwealth Edison Co. 82/02/17. KEPPLER, J. G. Region 3, Office of Director ip 14679 300. 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270268 "1981 Rept of Occupational Personnel Radiation Doses "
 * Commonwealth Edison Co 82/02/17 3pp 14679:301 24X
 Fiche 50-000,82/07/13,8208270010
- --B20B270539 Forwards "Recorded Annual Whole Body External Exposure for CVB1:" per 10CFR20.407(b) W/o Guad Cities, Zion, LaSalle, Byron & Braidwood repts RAVBCH, T J Commonwealth Edison Co. 82/03/31. Office of Management and Program Analysis ip 14680 075 24X Fiche: 50-000, 82/07/31, B208270010
- 8208160116 Forwards changes, tests & experiments completed during Jul 1982 KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/02 CASE, E Q. Office of Nuclear Reactor Regulation, Director 4pp. 14549: 295 24X Fiche 50-254, 82/08/02, 8208160116
- 820B160374 Forwards monthly operating repts for Jul 1982 KALIVIANAKIS N Commonwealth Edison Co B2/08/02 Director's Office. Office of Inspection and Enforcement 1p. 14348 320 24X Fiche. 50-254, 82/08/02.820B160374

- --8208160381 Monthly operating repts for Jul 1982 HEINFURTER, E., 8USS, R. Commonwealth Edison Co. 82/08/03 27pp 14348 321 24% Fiche 50-254,82/08/02.8208160374
- B Reportable occurrences, LERs & related correspondence
- 8208130210 Forwards LER 82-019/03L-0 KALIVIANAKIB Commonwealth Edison Co 82/07/14 KEPPLER, J Region 3. Office of Director 1p 14333 003 24X Fiche 50-234, 82/07/14, 8208130210
- --B208130218 LER 82-013/03L-0 on 820621, while diesel generator cooling water pump was being run in conjunction w/HPCI monthly operability surveillance, GGC 2300-2 pump observed to have no flow by local indications caused by pump being air bound BUSS.R. Commonwealth Edison Co. 82/07/14. Region 3. Office of Director 2pp. 14333 004 24X Fiche 50-254,82/07/14,8208130210
- 8208100049 Forwards LER 82-015/03L-0 KALIVIANAKIS,N Commonwealth Edison Co 82/07/21 KEPPLER,J Region 3, Opfice of Director. 1p 14296 230 24X Fichs 50-254,82/07/21.8208100049
- --9208100056 LER 82-016/03L-0 on 820711.during routine panel checks.HPCI MOU found on low speed stop Setpoint switched to high speed stop, but returned to low speed stop when switch released.

 Caused by failed amplifier circuit board HOELLER, J.P. Commonwealth Edison Co 82/07/21 Region 3, Office of Director 3pp 14276 231. 24X Fichs 50-254,82/07/21,8208100047
- 3208050230 Forwards LER 82-015/03L-0 KALIVIANAKIS.N Commonwealth Edison Co. 82/07/22 KEPPLER.J Region 3. Office of Director. ip. 14209 296 24X Fiche 50-254.82/07/22.8208050230
- -8208050232 LER 82-015/03L-0 on 820628,1/2A diesel fire pump taken out of svc for more than 7 days. Caused by need for overhaul. due to insurance company flow insp test revealing pump capacity marginal Pump overhauled WENDERLICH, J. Commonwealth Edison Co. 82/07/22, Region 3. Office of Director 2pp 14207.297 24X Fiche 50-254,82/07/22, 1200828333
- 8208100210 Forwards LER 82-017/03L-0 RALIVIANAKIS,N Commonwealth Edison Co 82/07/30. KEPPLER, J 9. Region 3. Office of Director. 1p 14294:315. 24X Fichs 50-294,82/07/30.8208100210
- -B208100217 LER B2-017/03L-0 on B20713, while taking inboard core spray injection valve (1-1402-258) out of svc for insp, valve failed to open from control room Caused by water from packing leak running into motor operator Motor repaired. MENDENHALL: E Commonwealth Edison Co B2/07/30 Region 3, Office of Director. 3pp. 14294 316 24X Fiche 50-254,82/07/30, B208100210.
- c08130240 Forwards LER 82-019/03L-0 KALIVIANAKIS, N. Commonwealth Edison Co 82/08/02 KEPPLER, J Region 3: Office of Director. Ip 14333 149. 24X Fiche 50-254,82/03/02.8208130240
- 8208130246 LER 82-019/03L-0; on B20713, during calibr of reactor automatic relief valves, controllers for valves 1-203-38, 3D & 3E found to trig at pressures in excess of Tech Spec limits Caused by setpoint calibr below limits PREUSB, M. Commonwaelth Edison Co 82/08/02 Region 3, Office of Director. 3pp 14333,170 24X Fichs 50-254,82/08/02,8208130240.
- 8208160427 Forwards LER 82-018/03L-0, KALIVIANAKIS, N Commonwealth Edison Co 82/08/02, KEPPLER, J Region 3, Office of Director. 1p 14349:195, 24X Fiche 50-254, 82/08/02, 8208160427
- --B208160438 LER B2-018/03L-0 on B20719, while performing reactor high pressure screw functional test, pressure switch PB-1-263-55A tripped high. Caused by instrument setpoint drift, Switch recallor & tested satisfactorily HIBAK, A Commonwealth Edison Co. B2/08/02, Region 3, Office of Director 2pp. 14349, 196 24X Fiche, 50-254, B2/08/02, B208160427
- 820810016B Forwards LER 82-014/03L-D KALIVIANAKIB, N Commonwealth Edison Co. 82/08/03 KEPPLER. J. C Region 3. Office of Director 1p. 14298:025 24x Fichs 50-254.82/08/03.8208100168

- --8208100174 LER 82-014/03L-0 on 820708, discharge damper on standby gas treatment train B failed to open when train auto-started Gaused by failure of auxiliary contact on motor starter Contact replaced KAEFPEL.F Commonwealth Edison Co 82/08/03 Region 3, Office of Director 3pp 14298 026 24X Fiche 50-254, 82/08/03, 8208100168
- 8208200282 Forwards LER 82-011/01T-1 KALIVIANAKIS N Commonwealth Edison Co 82/08/06 KEPPLER, J Region 3, Office of Director ip 14399 086 24X Fiche. 50-254, 82/08/06. 8208200282
- --8208200263 LER 82-011/017-1 on 820605, control valve 4 failed to fast close so that no reactor protective sys channel B trip received. Caused by personnel error Amphenal connector may have been damaged by maint personnel 171872, 0 Commonwealth Edison Co 82/08/05 Region 3, Office of Director 1p 14399 087 24X Fiche. 50-254, 82/08/06, 8208200252

DOCKET 50-255 PALIBADES NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8208030195 Provides update to 811104 response to NRC 811007 ltr re NUREO-0737. Item III A 1 2. "Staffing Levels for Emergency Bituations " Approval of emergency implementing procedure & training of required personnel expected by 820915. VANDEWALLE.D J Consumers Fower Co 82/07/30 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 14160 006 24X Ficher 50-255, 82/07/30, 8208030195
- 8208200210 IE Insp Rept 50-255/82-14 on 820621-25 No noncompliance noted Hajor areas inspected action taken per JG Keppler 811007 confirmation of action itr to RB DeWitt & 811203 amergency preparadness appraisal GRANT.W.B . AXELSON.W.L. Division of Emergency Preparadness & Operational Support 92/08/05 7pp 14399 177 24X Fiche 50-255,82/08/06.8208200202
- 8208200202 Forwards IE Insp Rept 50-255/82-14 on 820621-25 No noncompilance noted PAPERIELUG.C J Division of Emergency Preparadness & Operational Support 82/08/06 DEWITT,R B Consumers Power Co 2pp 14379-175 24X Fiche 50-255,82/08/06.8208200202
- 8208160109 Forwards IE Safeguards Insp Rept 50-255/82-17 on 820511-14 & 0623.No noncompliance noted MILLER, J. R. Division of Engineering & Technical Programs 82/08/10 DENTITY.R.B. Consumers Power Co ip 14345 167 24X Fichs: 50-255, 82/08/10, 8208160109
- --8208160122 IE Safeguards Insp Rept 50-255/82-17 on 820511-14 & 0623 No noncompliance noted Major areas inspected security organization, physical barriers, access controls, detection aids & alarm stations Details withheld (ref 10CFR73, 21) BELANGER, J. L., CREED, J. R. Region G. Office of Director 82/08/09, ip 14345 169, 24% Fiche, 50-255, 82/08/10, 8208160109
- 8208170154 Requests current version of full-size engineering drawings of facility layout & sys to review effectiveness of NRC safeguards regulations & validate vital area designations Drawing list encl CRUTCHFIELD. Operating Reactors Branch 5 82/08/11, VANDEHALLE, D Consumers Power Co. 4pp 14364.220, 24X Fichs. 50-255, 82/08/11, 8208170154,
- 820B270599 Releases public version of site emergency plan & revised emergency plan implementing procedures
 FELTON J. M Division of Rules and Records 82/09/16 Document Management Brench ip. 14681 020 24X Fiche 50-255,82/08/16,8208270599.
- --B208270A04 Forwards public version of Revision O to site emergency plan & ravised emergency plan implementing procedures, including Procedures EI-1 re activation of emergency plan & EI-3 re communications & notification VANDEWALLEDD, J. Consumers Power Co 82/08/04 CRUTCHFIELD, D. Operating Reactors Branch 5 in 14681.023, 24X Fiche: 50-255, 82/08/14, 8208270599.
- --8208270609 Public version of Revision O to site emergency plan * Consumers Power Co. 82/01/13 300pp 14681 024 24X Fiche: 50-255, 82/08/16, 8208270599
- --8208270515 Public version of revised emergency plan implementing procedures, including Procedure EI-1 re activation of emergency plan & EI-3 re communications & notification & Consumers Power Co. 82/03/25 200pp 14681.314 24X Fiche: 50-255, 82/08/14, 8208270599

- 8208310405 Responds to 820628 ltr re proposed changes to four of 29 acergency exercise deficiencies identified in IE Emergency Preparedness Rept 50-225/82-03 & addressed in util 820602 ltr Acceptable items listed PAPERIELLO.C J Division of Emergency Preparedness & Operational Bupport 82/08/25 DeWITT.R B Consumers Power Co 2pp 14693 265 24X Fiche 50-255,82/08/25,8208310403
- --B208310411 Revises schedule commitments on four responses to deficiencies identified in IE Emergency Preparadness Rept 50-255/82-03 Deficiencies re omergency facilities & emergency plan procedures discussed JUHNSON.B D Consumers Power Co 82/06/28 KEPPLER, J G Region 3. Office of Director 3pp 14693 267 24% Fiche 50-255, 82/08/25.8208310405

@ Adjudicatory correspondence

- 8208030295 Memorandum & Order CLI-82-18, vacating ASLB 810731 order, LBF-81-26 & ASLAS 820331 order, ALAD-670 Appellate review unaveilable since proceeding moot NRC & union settled cisagreement on allowable overtime.

 HOYLE, J. C. Office of the Secretary of the Commission 82/07/30 3pp 14158 117 24X Fichs 50-255,82/07/30,8208030295
- 8208110070 Order scheduling H20921 prehearing conference in St Joseph.
 HI Conference will be limited to issues re date of steam
 generator replacement. EIS status. ASLB jurisdiction over
 application fee forfeiture & discovery schedule
 CAURENSON, J A Atomic Bafety and Licensing Board Panel
 19p 14316 353 24X Fichs 30-255, B2/08/09, B208110070
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207110050 Summary of ACRS Subcammttee on SEP 820415 meeting in Rashington, DC + ACRS - Advisory Committee on Reactor Safeguards 82/06/03 2291 [4389 001 24% Fiche 50-255,82/06/03.8207110050
- P Operating license stage documents & correspondence
- 82070B006A Generic ltr to all licensess of operating plants applicants for OL & holders of CP re Commission approved charter for CRGR Bvc list encl
 DIRCKB,N J Office of the Executive Director for Operations
 82/07/02. Consolidated Edison Co of New York 73pp 14194 OOI
 24X Fichs 50-000, B2/07/02, B2070B0064
- 820B020282 Forwards application for amend to License DPR-20.requiring power operated relief valves to be in svc when shutdown capling sys not isolated from RCS VANDEWALLE.D J Consumers Power Co 82/07/29 CRUTCHFIELD, D Operating Reactors Branch 5 ip 14151 306 24X Fichs 50-255, 82/07/29, 8208020282
- --B208020287 Application for amend to License DFR-20, requiring power operated relief valves to be in svc when shutdown cooling sys not isolated from RCS REYNOLDS:J W Consumers Fower Co B2/07/27 2pp 14151 307 24X Fiche 50-255, B2/07/27, B208020282
- --8208020294 Proposed Tech Spec changes, requiring power operated relief valves to be in svc when shutdown cooling sys not isolated from RCS e Cansumers Power Co 82/07/29 2pp 14151 309 24X Fichs 30-218,82/07/29,8208020282
- 8208020299 Forwards application for amend to License DFR-20, requiring theck valve closure following use of low pressure safety injection sys for shutdown cooling VANDEWALLE, D. Goneumers Power Go. 62/07/29 CRUTCHFIELD, D. Operating Reactors Dranch 5 ip 14192-021, 24X Fiche 30-233, 82/07/29, 8208020299
- --B208020304 Application for amend to License DPR-20, requiring check valve closure following use of low pressure safety injection sys for shutdown cooling REYNOLDS. J W. Consumers Power Co. 82/07/29, 2pp. 14152 022 24X Fiche 50-255,82/07/29,8208020299
- --8208020310 Proposed Tech Space requiring chack valve closure following use of low pressure safety injection sys for shutdown cooling.

 Somewhers Power Co. 82/07/29 Gpp. 14152.024 24%

 Fichs 50-255,82/07/29,8208020299

- 8208020336 Forwards application for amend to License DPR-20 requiring add1 delamination insp if 5% or more of installed tendons must be retensioned to compensate for excessive loss of prestress
 VANDEWALLE, D J Consumers Power Co 82/07/27 CRUTCHFJELD, D Operating Reactors Branch 5 ip 14150,179 24% Fiche: 80-255,82/07/29,8208020336
- ~-8208020360 Application for amend to License DPR-20 requiring addl delamination insplif 5% or more of installed tendons must be restressed to compensate for excessive loss of prestress REYNOLDS. JW Consumers Power Co 82/07/29 2pp 14150 IBO 24X Fichs 50-255,82/07/29.8208020356
- --8208020365 Proposed Tech Specs requiring add1 delamination insp if 5% or more of installed tendons must be retunsioned to compensate for excessive loss of prestress * Consumers Power Co. 82/07/29 3pp 14150 182 24% Fiche 50-255.82/07/29.8208020336
- 8208050072 Comments on SEP, Phase II & proposals for Phase III Results of BEP do not justify costs
 DEWITT.R B Consumers Power Co 82/08/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 14213 267 24X
 Fiche 50-255.82/08/02,8208050072
- 8208130116 Forwards draft Revision 10 to "Inservice Testing of Plant Valves," per NRC inservice test program review & 820618 conference call Comments requested complete final draft JOHNSON. B D Consumers Power Co 82/08/06. CRUTCHFIELD.D Operating Reactors Branch 5 1p 14333 201, 24X Fiche 80-285.82/08/06.8208130116
- --8208130118 Draft Revision 10 to "Inservice Testing of Plant Valves" * Consumers Power Co 82/07/15 66pp 14333-202 24X Fiche, 50-255, 82/08/06, 8208130116
- 8208190062 Notification of 820819 meeting w/util in Betheade, MD to present proposed mods to HVAC eys, including mods for response to NUREQ-0737.Item III D 3 4, "Control Room Habitability."

 HAMBACH, T V Operating Reactors Branch 5 82/08/06 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 14507 048 24X Fiche 50-255, 82/08/06, 8208190062
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 100FR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT, D Q Division of Licensing, 82/08/09 Consolidated Edison Co of New York ip. 14356 332 24X Fiche 50-Q00.82/08/09, 8208090194
- 820B120317 Forwards revised Pages 14 & 15 to "Inservice Testing of Plant Valves, Table I," Revision 10, submitted on 820B06 JOHNSON, D. D. Consumers Power Co 82/08/10 GRUTCHFIELD, D. Operating Reactors Branch 5 1p 14324 230 24X Fiche: 50-205.82/08/10.8208120317
- --820BiR0322 Revised Pages 14 & 15 to "Inservice Testing of Plant Valves: Table 1." Revision 10 # Consumers Power Co. 82/07/15 2pp 14324 231 24X Fiche. 50-255. 82/08/10.8208120317
- 8208180012 Presents add1 info re auxiliary feedwater sys mod.per NRC 820325 telcon request JOHNSON, B D Consumers Power Co 82/08/11. CRUTCHFIELD.D Operating Reactors Dranch 5 4pp 14377 202 24X Fiche. 50-255. 82/08/11, 8208180012
- --B20BiB0016 "Evaluation of Auxiliary Feedwater Flow Requirements for High Pressure Befety Injection Pump Conversion " Consumers Power Co 62/08/11 78pp 14377-206 24% Fiche, 50-255, 82/08/11, 8208180012
- 8208230275 Forwards rept re BEP Topic III-1, "Classification of Structures Components & Bys (Baismic & Quality)." Plant meets current licensing requirements VINCENT.R.A. Consumers Power Co. 82/08/12 CRUTCHFIELD, D Operating Reactors Branch 5. 54pp 14512-264, 24X Fichs: 50-255, 82/08/12, 8208230275
- 8208230262 Forwards "SEP High Energy Line Breaks Inside Containment, Palisades Nuclear Station Phase IV Summary of Results " Final rept expected by 821190 VINCENT.R.A Consumers Power Co. 62/08/16 CRUTCHFIELD.D. Uperating Reactors Branch 5. 1p 14514 001. 24X Fiche: 50-255.82/08/16.8208290262.

- --6208230266 "SEP High Energy Line Breats Inside Containment.Palisades Nuclear Station Phase IV Summary of Results " * EDS Nuclear, Inc. 02-0540-1108 RB 82/07/31 120pp 14514 002 24% Fiche 30-255,02/03/16.8208330262
- B208230334 Submits revised schedule dates for selected action items resulting from SEP VANOEWALLE, D. J. Consumers Power Co. B2/OB/17 CRUTCHFJELD, D. Operating Reactors Branch 5 2pp. 14508 250 24X Fichs 50-255, 82/OB/17, 8208230334
- 8208230113 Forwards updated rept re SEP Topic III-1. "Classification of Structures. Components & Sys (Seismic & Guality), "originally submitted 820812 Submittal includes gressurizer fracture toughness data inadvartently amitted from B20812 submittal VINGENT.R.A. Consumers Power Co. 82/08/19. CRUTCHFIELD.D. Operating Reactors Branch 5. 54pp. 14542-022 24X Fichs 50-255,82/08/19,8208230113.
- 8208270234 Provides into to meet interim position for containment purge & vent valve operation & submits schedule for addressing long-term issue identified in NRC 781127 ltr for approval of modified purge sys Safety evaluation encl JOHMSON B. B. Consumers Power Co 82/08/24 CRUICHFIELD D Operating Reactors Branch 5 4pp. 14563-136 24X fiche: 80-255.82/08/24.8208270234
- 8208310091 Confirms B20817 telcon re-scheduling of 820708 mgt merting at site to discuss progress of regulatory improvement grogram. KEPFLER.J. G. Region 3. Office of Director 82/08/25 DEWITT, R. B. Consumers Power Co. ip 14689.318 24X Fiche: 50-255, 82/08/25, 8208310091
- 8208310414 Provides results of analysis re NRC evaluation of BEP Topic IX-3, "Station Svc & Cooling Hater Sys " Calculations of water drainage capability of intake structure shows drainage capacity adequate to handle largest slot break VANDEHALLESD, J Consumers Power Co 82/08/23 CRUTCHFIELD, D Operating Reactors Breach 5. 19 14694:309 24X Fiche 50-255,82/08/25,8208310414

G. Inspection reports, IE Bulletins & correspondence

- 8208040040 Ack receipt of 820610 ltr & full payment of civil penalty proposed in NRC 820512 enforcement action Violation correctly categorized as Security Level III due to history of containment integrity violations LIEBERMAN, J. Enforcement Branch (Pre 820201), 82/06/30 DEWITTR B Consumers Power Co. 2pp 14235 360 24X Fiche: 50-255, 82/06/30, 8208040040.
- B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV)
 Lestage " Syc list encl
 JORDAN E. L. Division of Engineering & Guality Assurance, 82/07/16
 Consolidated Edison Co. of New York 87pp 14356 274 24X
 Fiche: 50-000: 82/07/16: 8204210393
- 1204210395 IE Info Notice 81-28, Part 3: Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Syx list entl JORDAN, E.L. Division of Engineering 4 Quality Assurance 82/07/19 Michigan, Univ. of. 112pp. 14358, 001. 24X Fiche, 50-000, 82/07/19, 8204210395.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Fressure " Svc list encl. JORDANIE L. Division of Engineering & Guality Assurance 82/07/20. Consolidated Edison Co of New York 112pp. 14381 001. 24X Fiche: 50-000, 82/07/20, 8204210396.
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks," Syc list encl COBB.L I. Division of Fuel Facilities, Materiels & Bafeguards, 82/07/20. Concelidated Edison Co. of New York 7ipp 14357:276 24X Fiche: 50-000, 82/07/20, 8204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list excl.
 JORDAN,E.L. Division of Engineering & Quality Assurance 82/07/22.
 Consolidated Edison Co. of New York. 112pg. 14194.321 24%
 Fiche: 50-000.82/07/22.8204210398.
- 8208100271 Forwards IE Insp Rept 50-255/82-15 on 820601-30 & notice of violation.
 KNOP,R.C Division of Project & Resident Programs. 62/07/22
 DENITIR B. Consumers Power Co 2pp. 14295.132. 24X
 Fichs: 50-255, 82/07/22, 8208100271
- --8208100276 Notice of violation from insp on 820401-30, MMDP.R C Division of Project & Resident Programs. 82/07/22. 1p. 14275:134. 24X Fiche: 50-255, 82/07/22, 8208100271

- --8209:00283 IE insp Rept 50-255/82-15 on 820401-30 Noncompliance notes failure to perform required comparison of auxiliary feed pump flow indications for May 1982
 JORGENSEN, B. L., HELLER, J. K. Region 3. Office of Director
 BOYD, D. C. Division of Project & Resident Programs 82/07/21
 10pp 14295 138 24X Fichs 50-255.82/07/22,8208100271.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 62/07/23 Consolidated Edison Co. of New York 122pp 14360 115. 24X Fiche: 30-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PMRs " Bvc list encl JORDAN, E L Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Nestinghouse PMR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24% Fiche 30-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Hork in Fuel Stanage Pool " Svc list encl URDAN:E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357.146 24X Fiche: 50-000, 82/07/28, 8204210405.

١

- 8208050257 Responds to Action Item 3 of IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants "Carbon steel studs being replaced w/stainless steel JUHNEON, B D Consumers Power Co 82/08/02 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 14209-333 24X Fiche: 50-255, 82/08/02, 8208050257
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JURDAN,E.L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388:201 24X Fiche: 50-000, 82/08/05, 8204210407
- 8208200202 Forwards IE Insp Rept 50-255/82-14 on 820621-25 No noncompliance noted.
 PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Suggest. 82/08/06 DEWITT, R. B. Consumers Power Co. 200. 14399:175 24% Fiche 50-255.82/08/06.8208200202
- --B208200210 IE Insp Rept 50-255/82-14 on B20621-25 No noncompliance noted. Major areas inspected action taken per JG Kepgler Bil007 confirmation of action ltr to RB DeWitt & Bil203 emergency preparedness appraisal, QRANT, W. B. AXELEON. W. L. Division of Emergency Preparedness & Operational Support B2/08/05. 7pp 14397, 177 24X Fiche: 50-255, B2/08/06, B208200202
- 8208160109 Forwards IE Safeguards Insp Rept 50-235/82-17 on 820511-14 & 0623 No noncompliance moted MILLER, J R Division of Engineering & Technical Programs 82/08/10 DENTITY, R B Consumers Power Co. 1p 14345, 167. 24X Fiche: 50-255, 82/08/10, 8208160109
- --BROBIGOIRZ IE Safeguards Insp Rept 50-255/82-17 on BRO511-14 & 0623, No noncompliance noted, Major areas inspected security organization, physical barriers, access controls, detection aids & alarm metations Details withheld (ref 10CFR73 21), BELANDER.J. , CREED.J. R Region 3, Diffice of Director 82/08/09 1p 14345 169. 24X Fiche 50-255, B2/08/10, B208160109
- 8208160258 Forwards add1 provisions re SEP Topic III-7 A. "Inservice Insp Including Prestressed Concrete Containments W/Either Grouted or Ungouted Tendons."
 VINCENT, R.A. Consumers Power Co 82/08/12 CRUTCHFIELD, D. Deparating Reactors Branch 5 7pp 14347.056 24%
 Fichs 50-255,82/08/12,8208160258
- 8208170344 Documents resolution of SEP Topic III-3 C, "Inservice Insport Water Control Structures." Program discussed in util 820324 ltr will be implemented w/addl annual functionability checks of warm water recirculating pump. VINCENT.R.A. Consumers Power Co. 82/08/12 CRUTCHFIELD.D Departing Reactors Branch 5. 1p 14367-018, 24X Fiche: 50-255, 82/08/12, 8208170344
- 8208200016 Ack receipt of 820723 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/82-13. SPESSARD, R L. Division of Project & Resident Programs. 82/08/13. DEWLTTR. R Consumers Power Co. ip. 14392, 201 24X Fiche: 50-255, 82/08/13, 8208200016.

- --B20B200023 Responds to NRC 820624 ltr re violations noted in IE Insp Rept 50-255/82-13 Corrective actions contractor mgt counseled personnel re restricted area exitine at tracing sys procedures revised & setpoints returned to specific values DEWITT.R.B Consumers Power Co B2/07/23 KEPPLER.J @ Region 3. Office of Director App 14392 202 24% Fiche: 50-255, 82/08/13,8208200016
- 9208310223 Forwards IE Insp Rept 50-255/82-18 on 820728-29 & notice
 - of violation KILLER, J. R. Division of Engineering & Technical Programs DEHITY, R. B. Consumers Power Co. 2pp. 14693,141. 24X Fiche 50-255,82/08/13,8208310223
- --8208310227 Notice of violation from insp on 820728-29
 HILLER, J R Division of Engineering & Technical Programs
 82/08/13, ip 14493.142 24X Fiche 50-285.82/08/13, 8208310223
- --8208310232 IE Insp Rept 50-255/82-18 on 820728-29 Noncompliance noted: failure to follow Section 3 to Administrative Procedure 3 4, "ALARA Committee"
 LOVENDALE, P.C., MILLER, D.E., GREGER, L.R. Region 3, Office of pirector 82/08/12 4pp 14693 144 24x Fiche 50-255,82/08/13, 8208310223
- 8208310406 Responds to 820628 ltr re proposed changes to four of 23 sargency exercise deficiencies identified in IE Emergency Preparedness Rept 50-225/82-03 & addressed in util 820602 ltr Acceptable items listed PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/08/25 DEWITT, R. B. Consumers Power Co. 2pp 14693,265 24X Fiche: 50-255,82/08/25,8208310405.
- --B208310411 Revises schedule commitments on four responses to deficiencies identified in IE Emergency Preparadness Rept 30-255/82-03, Deficiencies re emergency facilities & samagency plan procedures discussed JOHNSON B D Consumers Power Co 82/06/28 KEPPLER, J Q. Region 3, Office of Director. 3pp 14693 267 24X Fiche: 50-255. 3, 0ffice of Director. 3pp 82/08/25:82 08310405
- R Pariodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose sepasures in 1981 for operating nuclear power plants & analysing said info. Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R. A. Critical Mass Energy Project Spp 14679 208 24X Fichs. 50-000, 82/07/13, 82082/0010.
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYGI" & NRC No Detailed Affiliation Given 82/07/13 48pp 14679 216. 24% Fiche. 50-000, 82/07/13.8208270010
- --8209270635 Forwards "Annual Exposure Range Rept. 1981, " per 100FR20 407 WANDEWALLE, D. J. Consumers Power Co 82/03/29 Office of Management and Program Analysis 1p 14680 062 24X Fiche: 20-000, 82/07/13, 8208270010
- --8208270637 "Annual Exposure Range Rept, 1981 "
 s Consumer's Power Co 82/03/29 tp 14680.063 24X
 Fichs. 50-000, 82/07/13, 8208270010
- 8208(3027) Forwards monthly operating rept for Jul 1982 & corrected monthly operating rept for June 1982 and 1982 & corrected waspenberg, D. Consumers Power Co. 82/08/09. NRC No Details: Affiliation Given ip 14333 055 24X Fiche. 50-259, 82/08/09, 8208(3027) NRC - No Dutailed
- --8208/30273 Monthly operating rept for Jul 1982 PETERBON, D. A. Consumers Power Co 82/08/03 4pp. 14333: 086 24% Fiche: 50-265, 82/08/09, 8208/30271.
- --8208130274 Corrected monthly operating rept for June 1982 PETERBON, D. A. Consumers Power Co. 82/07/01 ip 143 Fiche 50-255.82/08/09.8208130271 14333, 060, 24V
- & Reportable occurrences: LERs & related correspondence
- 8208130028 Forwards repts to State of MI re NPDES nonradiological persit violations from May 1981 to Apr 1982 JOHNSON, B.D. Consumers Fower Co. 62/05/26 KEPPLER, J.O. Region Office of Director, 44pp 14335 098 24X Fiche, 50-255, 82/05/26,

- 8208310045 Telecopy message of RO on 820814, containment integrity momentarily lost Caused by failed gasket on escape air lock. ROGERS: D W Consumers Power Co 82/08/16 REYES: L Region 3, Office of Director 4pp 14689 294. 24X Fiche 50-255,82/08/16,8208310045
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8207060127 Forwards response to Section III Q of App R to 10CFR50 re fire probection plan
 HILLS.L. H Tennesses Valley Authority. 82/06/30 DENTON.H.R
 Dfffce of Nuclear Reactor Regulation. Director 202pp 13712
 24X Fiche. 50-259.82/06/30, 8207060127.
- 8207120070 Releases public version of revision to State of AL radiological emergency response plan.
 FELTON-J M Division of Rules and Records. 82/07/06 Documenagement Branch. ip 13827 312 24X Fiche: 50-257,82/07/06 Document 8207120070
- --8207120078 Forwards public version of Revision BFN-REP-82-003 to State of AL radiological energency response plan, constituting App F to Browns Ferry radiological energency response plan.
 HILLS, L. R. Tennesses Valley Authority. B2/06/23 DENTON, .H R Office of Nuclear Reactor Regulation, Director 2pp 19827 314.
 24X Fiche 50-259,82/07/06,8207120070
- --8207120083 Public version of Revision BFN-REF-82-003 to State of AL radiological emergency response plan.constituting App F to Browns Ferry radiological emergency response plan. 4 Tennesses Valley Authority. 82/06/16 92pp. 13829.316 Fichs. 50-259.82/07/04.8207120070 13829.316 24%
- 8208090046 Forwards revisions to physical security plan Revisions withheld (ref [OCFR73 21]

 HiLLG/L H Tennesses Valley Authority 82/07/22, DENTON, H. R

 Defice of Nuclear Resitor Regulation: Director. 1p 14270-035

 Fiche: 50-259. 82/07/22.8208070046
- 8208110219 Releases public version of revised emergency plan implementing procedures FELTON. J M Division of Rules and Records. 82/08/04 Docum Management Branch. 1p. 14318-084 RAX Fiche 50~259,82/08/04,8208110219
- --8208it022i Forwards public version of revised amergency plan implementing procedures, including Procedures IP-2 renotification of unusual event, IP-4 resite emergency & IP-5 regental emergency & SLICER, & K. Tennessee Valley Authority B2/07/16 MRC Detailed Affiliation Given ip. 14318:087. 24x Fiche 50-259, 82/08/04, 8208110219 NRC - No
- --BR08110223 Public version of revised emergency plan implementing procedures, including Procedures IP-2 re notification of unusual event, IP-4 re site emergency & IP-5 re general emergency * Tennessee Valley Authority. 6 Fiche: 50-259,82/08/04.8208110219. 82/07/16 110pp. 14318:088. 24X
- 8208260338 Releases public version of revised radiological emergency notification directory.
 FELTON, J M Division of Rules and Records 82/08/13 Document Management Branch, ip 14575, 275 24X Fiche, 50-259, 82/08/13, 8208260338.
- ~-8208260343 Forwards public version of Revision 5 to rediological smarqsncy notification directory. Receipt form encl HILLS.L.M., SLIGER,E.K. Texnesses Valley Authority, 82/08/04. DENTON,H.R. Office of Nuclear Rescaler Regulation, Director 14375, 276. 24X Fiche 50-259, 82/08/13, 6208260338.
- -- 8208260346 Public version of Revision 5 to radiological emergency roacousto rupits version of keyleion 5 to radialogical emergency notification directory * Tennesses Valley Authority, 82/08/03, 32pp 14575 278, 24% Fiche: 50-257,82/08/13,8208260338
- 8208230351 Forwards addl info on implementation of App R. Item III. J re emergency lighting.per D8 Vassallo 820622 ltr to HO Parris. Schedule for item also contained in LM Mills 820715 itr, KAMMER.D 8. Tennessee Valley Authority 82/08/17 DENTON.H.R Office of Nuclear Reactor Regulation. Director, 2pp. 14508:283 24% Fiche: 50-259,82/08/17,8208230351.

- 8208230331 Notifies that add1 info re post-accident sampling facility & response schedule requested 820713 will be provided by 821115
 - MILLS,L H Tennesse Valley Authority 82/08/18 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 14508 325 24x Fiche 50-259.82/08/18,8208230331

O Adjudicatory correspondence

8208270270 Informs that LBP-62-50 accepted for referral by ASLAB & remanded for reconsideration in ALAB-687 RAHBON:R J. Hearing Branch 4 82/08/25 CHILK: 8 J Qffice of the Secretary of the Commission 3pp 14563 088 24X Fiche 50-259,82/08/25.8208270270

I Financial information

- 8208100002 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr ending 810630 & "1981 Power Program Summary," for fiscal yr ending 810930, per Section 50 71(b) of 100FR50 HILLS,L M Tennessee Valley Authority 82/08/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 116pp. 14294 024 24% Fishe 50-000,82/08/06,8208100002
- 8208270457 Forwards financial statements for FY81, power quarterly rept & internal cash flow projection
 HILLS,L. H. Tennessee Valley Authority 82/08/23 SALTZMAN, J.
 Assistant Director for State & Licensee Relations 48pp. 14566 135
 24X Fiche 50-000.82/08/23,8268270457

J Insurance & indemnity information

- 8208310200 Advises that onsite property damage insurance has been purchased, in accordance w/100FR50, 54 Coverage status epc1 MILLS.L H Tennessee Valley Authority 82/08/25, 8ALTZMAN, J Assistant Director for State & Licensee Relations 2pp 14693-160 24X Fiche 50-000,82/08/25,8208310200
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8208170283 Forwards updated FSAR for Browns Ferry Nuclear Plant. Vols 1-7 MILLS.L.H. Tennessee Valley Authority, 82/09/12 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 14852 001 24X Fiche: 50-259, 82/08/12, 8208170283
- --8208170293 Updated FBAR for Browns Ferry Nuclear Plant, Vols 1-7

 * Tennessee Valley Authority. 82/08/12 3430pp 14852 002 24x
 Fiche 50-259, 82/08/12, 8208170283
- 820B170295 Chapter 1 to Browns Ferry updated FBAR, "Introduction & Bugmary " * Tennessee Valley Authority 82/08/12 150pp 14852 017 24X Fiche 50-259,82/08/12,8208170295
- 8208170297 Chapter 2 to Browns Ferry updated FSAR. "Site." + Fennessee Valley Authority 82/08/12 450pp 14852 202, 24X Fithe: 50-259, 82/08/12, 8208170297
- 8208170299 Chapter 3 to Browns Ferry updated FSAR, "Reactor" * Tennessee Vallay Authority, 82/09/12 170pp 14852 188 24X Fiche 50-259, 82/08/12, 8208170299
- 8208170301 Chapter 4 to Browns Ferry updated FBAR, "RCS "
 * Tennessee Valley Authority 82/08/12 170pp 14854 006 24X
 Fiche: 30~239, 82/08/12, 8208170301
- 8208170304 Chepter 5 to Browns Ferry updated FSAR, "Containment,"

 * Tennessee Valley Authority 82/08/12, 100pp 14854, 150, 24X
 Fiche: 50-259, 82/08/12, 82/08170304.
- 9208170307 Chapter 6 to Browns Ferry updated FSAR, "Core Standby Coolant Sys "

 * Tennessee Valley Authority 82/08/12 75pp. 14854 294. 24% Fiche: 50-259, 82/08/12, 8208170307.
- 8208170308 Chapter 7 to Browns Ferry updated FSAR. "Control & Instrumentation "
 4 Tennessee Valley Authority 82/08/12 500pp 14855 024. 24X Fiche. 30-257. 82/08/12. 8208170308.
- 8208170310 Chapter 8 to Browns Ferry updated FBAR. "Electrical Power Sys." * Tennessee Valley Authority 82/09/12 275pp 14856,133 24X Fiche: 50-257,82/08/12,8208170310

- B208170311 Chapter 9 to Browns Ferry updated FSAR, "Radwaste Control 6ys" + Tennessee Valley Authority 82/08/12 120pp 14857-177 24X Fiche 50-259, 82/08/12, 8208170311
- 8208170315 Chapter 10 to Browns Ferry updated FSAR, "Auxiliary By: "
 # Tennessee Valley Authority 82/08/12 400pp 14857 177 24%
 Fiche 50-259, 82/08/12, 8208170315
- 8208170317 Chapter 11 to Browns Farry updated FSAR, "Power Conversion 8ys " * Tennesses Valley Authority, 82/08/12 50pp 14858 059 24x Fiche 50-259, 82/08/12, 8208170317
- 8208170319 Chapter 12 to Browns Ferry updated FSAR, "Structures & Shielding" + Tennessee Valley Authority 82/08/12 200pp 14858 114 24X Fiche 30-239, 82/08/12, 8208170319
- 8208170322 Chapter 13 to Browns Ferry updated FSAR, "Conduct of Operations "

 * Tennessee Valley Authority 82/08/12 70pp 14859 039 24x Fiche 50-259, 82/08/12, 8208170322
- 8208170328 Chapter 14 to Browns Ferry updated FSAR, "Plant Safety Analysis" " Tennesses Valley Authority 82/08/12 120pp 14857 224 24X Fichs 50-257,82/08/12,8208170328
- 820B170333 App A to Browns Ferry updated FBAR, "Conformance to AEC Proposed General Design Criteria" # Tennessee Vallsy Authority B2/08/12 22pp 14860 029 24x Fiche, 50-259, 82/08/12,8208170333
- 8208170334 App B to Browns Ferry updated FBAR, "Tech Specs" * Tennesses Valley Authority 82/08/12 ip 14860 051 24X Fiche 50-259,82/08/12,8208170336
- 8208170339 App C to Browns Ferry updated FSAR, "Structural Loading Criteria" * Tennesses Vallay Authority. 82/08/12 81pp 14860 052 24x Fiche: 50-259, 82/08/12, 8208170339
- 820B170340 App D to Browns Ferry updated FSAR, "GA Plan for Browns Ferry Nuclear Plant." # Tennessee Valley Authority 82/08/12 29pp 14860 136 24X Fiche 50-259,82/08/12.8208170340
- 8208170375 App E to Browns Ferry updated FSAR. "Site Oaseous Release Rate Limit Calculation "
 # Tennessee Vallay Authority 82/08/12 3pp 14860 163 24X Fiche 50-259,82/08/12.8208170375
- 820Bi70377 App F to Browns Ferry updated FSAR. "Unit Sharing & Interactions " # Tennessee Valley Authority. 82/08/12 30pp 14860.166 24X Fiche 80-239.82/08/12.8208170377
- 820B170379 App 0 to Browns Ferry updated FSAR, "Plant Nuclear Safety Operational Analysis" * Tennessee Vallay Authority 82/08/12 200pp 14860-196 24X Fiche 50-259.82/08/12.8208170379
- 8208170380 App H to Browns Ferry updated F8AR, "Core Thermal Design" # Tennessee Valley Authority 82/08/12 App 14860 347, 24% Fiche 50-259,82/08/12,8208170380
- 8208170382 App I to Browns Ferry updated FSAR, "Identification-Resolution of CP Concerns."

 * Tennessee Valley Authority 82/08/12 55pp. 14860:355 24% Fiche:50-237,82/08/12.8208170382
- B20B170384 App J to Browns Ferry updated FBAR. "Reactor Pressure Vessel Design Summary Rept-Unit 1"

 * Tennessee Valley Authority 82/08/12, ip 14841 050 24% Fiche. 50-259, 82/08/12.8208170384
- 8208170386 App K to Browns Ferry updated FSAR, "Reactor Pressure Vessel Design Summary Rept-Unit 2" * Tennessee Valley Authority 82/08/12 1p. 14861 051 24X Fiche: 50-259, 82/08/12, 8208170386.
- 8208170387 App L to Browns Ferry updated FBAR. "Reactor Pressure Vestel Design Summary Rept-Unit 3 " * Tennesses Velley Authority, 82/08/12, 1p, 14861 052 24X Fichs. 50-209, 82/08/12, 8208170387

- 8208170387 App M to Browns Ferry updated FSAR, "Rept on Pipe Failure Cutaide Containment in Browns Ferry Nuclear Plant " a Tennessee Valley Authority 82/08/12 50pp 14861 053 24X Fiche 30-259, 82/08/12, 8208170389
- 820B170392 App N to Browns Ferry updated FSAR, "Browns Ferry Nuclear Plant Unit 3 Bt8 Fuel Initial Core Loading" • Tennessee Valley Authority 82/08/12 100pp 14861,096 24X Fiche 50-259,82/08/12,8208170392
- P Operating license stage documents & correspondence
- 8208030077 Forwards request for addl info re NUREG-0737, Item II D i, "Testing of Relief & Bafety Valves," in order to complete review of generic test results VABSALLO, D B Operating Reactors Branch 2 82/06/30 PARRIS, H o Tennessee Valley Authority App 14200 314 24X Fiche 50-257, 82/06/30, 8208030077
- B208030698 Forwards safety evaluation of proposed method of implementing NURGO-0737. Item II K 3 15, "Isolation of NPCI & Reactor Core Isolation Cooling " Proposed method acceptable VASSALLO, D B. Operating Reactors Branch 2 62/06/30 PARRIB, H & Tennessee Valley Authority 4pp 14196 321 24% Fiche 50-259, 82/06/30, 8208030698
- 8207080064 Generic itr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CRR, SVC list encl
 DIACKB: M J Office of the Executive Director for Operations, 82/07/02 Consolidated Edison Co of New York, 93pp 66247 231 24X Fiche 50-000, 82/07/02, 8207080064
- 8208040077 Requests data to support conclusion of adequacy space coling for HCPI & reactor core isolation cooling Response of 811230 unacceptable since no analysis or test data to support conclusion submitted VABBALLO, D B. Operating Reactors Branch 2 82/07/08 PARRIE.H G. Tennasses Valley Authority 2pp. 14228 271, 24X Fiche 50-257, 82/07/08, 8208040077
- 8208040064 Notifies that generic issue to possible diesel generator lockout resolved Operator training program covers subj adequately VASSALLO, D B Operating Reactors Branch 2 82/07/15 PARRIS, H Q Tannesses Vailey Authority 4pp. 14228 280 24X Fishe 50-257, 82/07/13,8208040064
- 8207270454 Requests extension to 820812 for submittal of updated FSAR, MILLS.L H Tennesses Valley Authority 82/07/20, DENTON.H R. Office of Nuclear Resctor Regulation, Director ip. 14061.168 24X Fichs 50-257, 82/07/20,8207270454
- R208040555 Forwards draft technical evaluation rept. "Control of Heavy Loads." Conference cell requested within 30 days to discuss proposed recommendations in rept VASSALLO, D. 8. Operating Reactors Branch 2 82/07/22. PARRIS, H O. Tannessee Valley Authority 2pp 14221:150 24X Fiche 50-259, 82/07/22, 8208040365
- --B208040560 "Control of Heavy Loads," draft technical evaluation rept GARGENT: I. Franklin Institute/Franklin Research Center TER-C3287-181 82/07/07 CLEMENBON, F NRC - No Datailed Affiliation Given 38pp 14221 152, 24X Fichs 50-259,82/07/22, B208040555.
- 8208110279 Forwards Amends 85,82 & 56 to Licenses DPR-33, DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability, Amends consist of clarification & administrative changes & additions to reflect plant mods, CLARK, R J Operating Reactors Branch 2 82/07/22, PARRIS, H. & Tehnesser Valley Authority 2pp 14332:034, 24% Fithe 50-259, 82/07/22, 8208110279
- --8208110283 Amends 85,82 % 54 to Licenses DPR-53, DPR-52 & DPR-68, respectively, consisting of clarification & administrative thanges & additions to reflect plent mods & reorganization of some Tech Spec sections VASSALLO, D. B. Operating Reactors Branch 2 82/07/22, 128pp. 14332.036. 24X Fiche 50-259,82/07/22,8208110279
- --8208110287 Safety evaluation supporting Amends 85,82 & 56 to Licenses PPR-32.DPR-52 & DPR-68; respectively. By Office of Nuclear Reactor Regulation, Director. 82/07/22, Spp. 14332*165. 24X Fiche 50-259;82/07/22,8208110279.
- --820Bi10270 Notice of issuance & availability of Amends 85,82 & 56 to Licenses DPR-33.DPR-52 & DPR-68.respectively VABBALLO.D. B. Licensing Branch 2. 82/07/22. 2pp. 14932:170 24X Fiche:50-257.82/07/22.820Bi10277.

- 8208040663 Requests 820729 meeting in Chattanoga.TN to discuss MSIVs in BWR plants VABSALLO,D & Operating Reactors Branch 2 82/07/23 PARRIB.H Q Tennessee Valley Authority 2pp 14224 360 24X Fiche 50-259.82/07/23.8208040663
- 9208020221 Responds to NRC 920212 request for add1 info re need for chlorine detectors at facilities.per NUREO-0737,
 Item III D 3 4 No threat to control room habitability from chlorine on or off site evident
 MILLS.L M Tennesses Valley Authority 82/07/27 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 2pp 14151 222
 24X Fiche 50-259:82/07/27.8208020221
- B20B120363 Forwards revised version of model Tach Specs re electric power monitoring of reactor protection sys previously submitted in G11030 ltr vABSALLO, D B Operating Reactors Branch 2 B2/07/28 PARRIB, H O Tennessee Valley Authority. 3pp 14340.079 24X Fiche: 50-259, B2/07/28, B20B120363
- 8208i30444 Forwards safety evaluation & LLL technical evaluation rept on licenses response to NUREG-0737. Item II B 1. "RCS Vents." Issue resolved VASSALLO, D B Operating Reactors Branch 2 82/08/02 PARRIB, H G Tennesses Valley Authority 3pp 14354 343 24X Fiche: 50-257, 82/08/02, 8208130444
- ---B20813044B "RCS Vents," technical evaluation rept
 BUTCHER, E. BARNHART, B. Laurence Livermore Laboratory FIN
 A-0246-2 B2/06/02 Division of Licensing 4pp 14334-346,
 24X Fiche 50-259, B2/08/02, B208130444
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Sec list encl EISENHUT.D 0. Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p. 14356-332 24X Fiche 30-000,82/08/09,8208090194
- 820825037å Forwards mechanical snubber qualification test repts for Pacific Scientific Co Models PSA 1/4 PSA 100, as requested by NRC Only qualitative-type actuation tests planned at plants, beginning w/Browns Ferry 2 & Saquoyah 1
 MILLG. L. M. Tennesses Valley Authority 82/08/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 14541,002 24X Fiche 50-000, 82/08/18, 8208250376.
- --8208230383 Revision A to "Gualification Test Rept for Model 1801104-05 PSA 1/4 Shock " WHITNEY, R F. GLAUSER, J. E. HRIGHT, W B. Pacific Scientific. TR B39 RA 82/03/18 27pp 14541 005 24% Fiche 50-000, 82/08/18, 8208250376
- ~-82082503B7 Revision R to "Acceptance Test Procedure IT 527 P/N 1801104" LEVAN.H C Pacific Scientific. 79/11/09 13pp. 14541 032 24x Fiche. 50-000.82/08/18.8208250376
- --B208250371 "Qualification Test Rept for Model 1801104-07 PBA 1/2 Bhock Arrestor."

 WHITNEY,R F , OLAUBER, J E , WRIGHT, M B Pacific Scientific TR B40 79/12/12 27pp 14541 045, 24% Fiche 50-000, 82/09/18, 8208250376.
- --8208250402 Revision A to "Qualification Test Rept for Model 1801102-05 PSA 1 Shock Arrestor"
 WHITNEY R.F., GLAUSER, J E , WRIGHT, H B Pacific Scientific TR 841 RA 80/03/18 26pp 14541 085 24X Fiche 50-000, 82/08/18, 8208250374.
- --8208230409 Revision T to "Acceptance Test Procedure IT 519 P/N 1801102." LEVAN,H.G. Pacific Scientific. 79/06/13. 14pp 14541 111 24x Fiche 80-000,82/08/18.8208230376.
- --BROBZ50415 "Qualification Yest Rept for Model 1801104-05 P8A-3 Shock Arrestor."

 Arrestor.", DLAUSER, J. E., WRIGHT, W. B. Pacific Scientific FR B42. 80/01/22 27pp 14541, 125 24x Fiche 50-000, 82/08/18, 8208280374
- --8208250421 Revision R to "Acceptance Test Procedure IT 524 for 1801105" EVAN-H.C Pacific Scientific 79/02/16 13pp 14541 152, 24x Fiche: 50-000.82/08/18:8208250376

- --8208250426 "Qualification Test Rept for Model 1801103-07 PSA 10 Shock Arrestor "
 WHITNEY, R. F., QLAUSER, J. E., WRICHT, W. B. Pacific Scientific TR
 843 80/01/25 27pp. 14541 166 24X Fiche 50-000, 82/09/18, 8208250376
- --8208250431 Revision R to "Acceptance Test Procedure IT 523 P/N 1801103 " LEVAN, H C Pacific Scientific 79/08/15 14pp. 14541 193 24% Fiche 50-000, 82/08/18, 8208230376
- --8208250437 Revision A to "Qualification Test Rept for Model 1801112-11 P8A-35 Shock Arrestor"

 HHITNEY, R F , GLAUSER, J E , WRIGHT, W E Pacific Scientific TR 845 RA 80/02/07, 30pp 14541 207 24X Fiche 50-000,82/08/18,8208250376.
- --B208250441 Revision J to "Acceptance Test Procedure IT 534 P/N 1801112 " LEVAN.H C Pacific Scientific 77/05/10 12pp 14541 237 24x Fiche. 50-000, 82/08/18, 8208250376
- --8208250443 "Qualification Test Rept for Model 1801119-11 PSA-100 Shock Arrestor"
 WHITNEY.R F., QLAUSER, J E , WRIGHT, W B Pacific Scientific TR 846 80/05/12, 31pp 14541:249 24X Fiche 50-000.82/09/18. 8208250376.
- --8208250446 Revision H to "Acceptance Test Procedure IT 533 P/N 1801119 " LEVAN. H. C. Pacific Scientific 77/04/07 12pp 14541 280 24x Fiche 50-000.82/08/18.8208250376

O Inspection reports. IE Bulletins & correspondence

- 8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leakage." Swc list encl JORDAN,E.L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14336 274 24X Fiche. 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-24, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance. 82/07/19. Michigan Univ of 112pp. 14358 001. 24X Fiche 50-000, 82/07/19, 8204210395.
- 9204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Swc list enc! JORDAN,E L. Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381.001 24X Fiche, 50-000, 82/07/20, 8204210396
- 9204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Buc list enci CD89.t. I. Division of Fuel Facilities, Materials & Bafeguards, 82/07/20 Consolidated Edison Co of New York 7ipp. 14357-274 24X Fiche:50-000.82/07/20.8204210397
- 1204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl JCRDAN, E. L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of Rsw York 112pp. 14194 321 24X Fiche: 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Natice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." See list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York. 122pp 14380-115, 24X Fiche: 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Hestinghouse PHRs " Svc list and JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23, Consolidated Edison Co of New York 127pp 14194 120 24X Fiche: 50-000, 82/07/23, 8204210402.
- B204210403 IE Info Notice B2-30, "Loss of Thermal Steeves in RCS Piping at Certain Westinghouse PWR Power Plants," Svc list encl WRDAN,E. L. Division of Engineering & Quality Assurance B2/07/26 Consolidated Edison Co. of New York 121pp 14357:013, 24X Fiche, 50-000, 82/07/26, 8204210403
- 8208030582 Ack receipt of 820716 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-14.
 50-260/82-14 & 50-296/82-14.
 LENIS.R C. Division of Project & Resident Programs 82/07/26 PARRIS.H.Q. Tennesses Valley Authority 1p 14162 277 24X Fiche: 50-259, 82/07/26.8208030582.

- --B208030592 Responds to NRC B20609 ltr re violations noted in IE Insp Regts 50-259/82-14,50-260/82-14 & 50-296/82-14 Corrective actions posted signs identifying shield plugs that require presence of health physics personnel for removal KAMMER, D 8 Tennessee Valley Authority 62/07/16 O'REILLY, J P Region 2. Office of Director 4pp 14162 278 24X Fishe 50-259,82/07/26,6208030582
- --8208030597 Forwards IE Insp Repts 50-259/82-14.50-260/82-14 & 30-296/82-14 on 820503-04 & notice of violation LEWIS,R C Division of Project & Resident Programs 82/06/09 PARRIS,H G Tennessee Valley Authority 2pp 14162 282 24x Fiche 50-259,82/07/26.8208030582
- --8208030602 Notice of violation from insp on 820803-04 * Division of Project & Resident Programs 82/06/07 2pp 14162 284 24% Fiche 50-259,82/07/26,8208030382
- --8208030610 IE insp Repts 50-259/82-14.50-260/82-14 t 50-296/82-14 on 820503-04 Nancompliance noted failure to perform radiation survey after removal of shield plugs t failure to issue permit for removal of demineralizer cell shield plugs PEERY, W W , BARR. K P Division of Engineering & Technical Progress 82/06/02 4pp 14162 286 24x Fiche 50-259,82/07/26,8208030582
- 8208160375 Forwards IE Insp Repts 50-259/82-18,50-260/82-18 & 50-296/82-18 on 820626-0725 No noncompliance noted VERRELLI.D M. Division of Project & Resident Programs 62/07/26 PARRISH 0 Tennessee Valley Authority 2pp 14348 012 24% Fiche 50-259,82/07/26,8208160395
- --B208160408 IE Insp Repts 50-257/82-18,50-260/82-18 & 50-276/82-18 on 820626-0725 No noncompliance noted Major areas inspected operational safety, ROs, surveillance testing, maint observation. THI action items & independent insp effort CHASE. J. H. PAULK, G L. CANTREL, F B Division of Project & Resident Programs 82/07/26 8pp 14348 014. 24x fiche 50-259,82/07/26,8208160395
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, E L Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146, 24X Fiche 50-000,82/07/28,8204210405
- 8208160294 Forwards IE Insp Repts 50-259/82-21, 50-260/82-21 & 50-296/82-21 on 820628-0702 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/07/28 PARRIS, H Q Tennessee Valley Authority 2pp 14345 265 24% Fichs: 50-259, 82/07/28, 8208140294
- --B208160311 IE Insp Repts 50~259/B2-21.50~260/B2-21 & 50~296/B2-21 on 820628-0702 No noncompliance noted Major areas inspected radioactive meth packaging shipment & processing, posting of notices, housekeeping & instrument callibr COLLINS, T R . DEBS. B T . BARR, K F Division of Engineering & Technical Programs \$20/07/22. 5pp 14345 257 24X Fiche.50~259, 82/07/28, 8208160294
- 8208160484 Ack receipt of 820730 ltr informing NRC of steps taken to correct violations moted in IE insp Repts 30-239/82-19, 50-240/82-19 & 30-274/82-19 VERRELLI.D Division of Project & Resident Programs 82/08/03 PARRIS.H O Tennessee Valley Authority. ip 14348 104, 24% Fiche 30-259,82/08/03,8208160484
- --8208160491 Responds to NRC 820701 ltr re violations noted in IE Insp. Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19 Corrective actions torus area high radiation rope barrier reinstabled & radiological tape placed on floor.

 KAMER. D 8 Tennessee Valley Authority 82/07/30 0'REILLY, J P. Region 2, 0ffice of Director 3pp, 14348-105 24X Fiche 50-259,82/08/03,8208160484
- --8208160498 Forwards IE Insp Repts 50~259/82-19, 50-260/82-19 & 50-296/82-19 on 820526-0625 & notice of Violation.

 LONG. F. J. Division of Project & Resident Frograms 82/07/01 PARKER, H. Q. Tennessee Valley Authority 2pp 14348, 108. 24X Fichs 50-259, 62/08/03, 8208160484.
- --8208160507 Notice of violation from insp on 820526-0625 * Division of Project & Resident Programs 82/07/01. Ip 14348 110. 24X Fiche: 50-259, 82/08/03, 8208160484
- --E208160521 IE Insp Repts 50-259/82-19.50-260/82-19 & 50-296/82-19 on 820526-0625. Noncompliance noted failure to properly barricade two high radiation areas in torus area CHASE. J H , PAULX. Q. L. , CANTRELL, F. S. Division of Project & Resident Programs. 82/06/30 6pp 14348:111 24X Fichs. 50-259, 82/08/03, 8208160484

- B2QB160493 Ack receipt of B20720 ltr informing NRC of steps taken to appret violations noted in IE Insp Repts 50-259/82-15.
 50-260/82-15 & 50-296/82-15
 LEMIS, R C Division of Project & Resident Programs B2/08/04.
 PARRIS, H G Tennessev Valley Authority lp 14348 117 24X
 Fiche 50-259, 82/08/04, 8208160493
- --S208160502 Responds to NRC 820603 ltr re violations noted in IE Insp Repts 50-299/82-15.50-260/82-15 & 50-296/82-15 Corrective actions daily monitoring & drainage program will be continued Violations re Items A & B denied MILLS.L M Tennessee Valley Authority 82/07/20 O'REILLY, J. P Region 2. Office of Director Topp 14348 118 24X Fichs 50-259,82/08/04,8208160493
- --8208160515 Forwards IE Insp Repts 50-299/82-15.50-260/82-15 & 50-296/82-15 on 820426-0525 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/06/03 PARRIS.H G Tennessee Valley Authority 2pp 14348,125 24X Fichs 50-259.82/08/04.8208160493
- --8208160520 Notice of violation from insp on 820426-0525 * Division of Project & Resident Programs 82/06/03 2pp 14398 127 24% Fishe 50-259, 82/08/04, 8208160493
- --B208160528 IE Insp Repts 50-257/82-15.50-260/82-15 & 50-276/82-15 on B20426-0525 Noncompliance noted written safety evaluation re offgas post-treatment sampling station configuration mod not performed.

 CHASE, J. W. PAULK. 9 L. CANTRELL. F. B. Division of Project & Resident Programs B2/06/02 10pp 14348.127 24X Fiche 50-259.82/08/04.8208160493
- 9204210407 IE Info Notice 92-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 92/08/05 Consolidated Edison Co of New York 117pp. 14388.201. 24X Fiche 50-000, 82/08/05, 8204210407
- R. Periodic operating reports & related correspondence
- 9206270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analysing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R. A Critical Mass Energy Project 8pp 14679 208 24% Fiche 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Factitities for CV91"

 + NRC No Detailed Affiliation Given 82/07/13. 48pp 14477 216 24χ Fiche 50-000.82/07/13.8208270010
- --B20B270601 Forwards "Personnel Whole Body Exposures for CYB1," per 80CFR20 407. MILLS.L K Tennessee Valley Authority B2/03/23 DRGOKB, B.Q Licensee Operations Evaluation Branch 1p. 14680-053 24X Fighe 50-000-82/07/13
- --B208270605 "Personnal Whole Body Exposures for CYS1 "

 * Tennesses Valley Authority 82/03/23 2pp 14680-054 24X

 Fiche 50-000.82/07/13.8208270010
- 8208120226 Forwards monthly operating repts for June 1982 JONES,O T. Tennesses Valley Authority 62/07/14 Office of Management and Program Analysis in 14326.176 24X Fiche 30-209, 82/07/14,8208120226
- --8208120233 Monthly operating repts for June 1982.
 JONES, G T , THOM, T Tennessee Valley Authority 82/07/14 39pp
 14325:177 24X Fiche 50-259,82/07/14,8208120225.
- 5 Reportable occurrences, LERs & related correspondence
- 8208020111 Forwards updated LER 82-020/03X-1 GREEN:H J. Tehnessee Valley Authority 82/07/22. O'REILLY, J P Region 2: Office of Director ip 14142 108. 24X Fiche 30-259.82/07/22,8208020111
- --8208020113 Updated LER 82-020/09X-1 on 820320. Unidentified drywell leafage increased in excess of Tech Spec limits Caused by vibration induced fatigue crack in 3/4-inch reactor water cleanup systest connection Line rerouted.

 ROBERTS, W.A. Tennesses Valley Authority, 82/07/22 Region 2, Office of Director, 3pp 14142 109 24X Fiche: 50-259, 82/07/22, 8208020111

- 8208020319 Forwards updated LER 82-005/03X-1 OREEN.H J Tennessee Valley Authority. 82/07/22 0'REILLY, J P Region 2, Office of Director 1p 14151 112 24X Fiche 50-259, 82/07/22, 8208020319
- --820B020331 Updated LER 82-005/03x-1 on 820107.1 EN reactor motor operated valve board (LPCI) motor generator set removed from svc due to loss of lubrication on generator coupling Caused by change of consistency & loss of lubricant.

 FHIGHEM. R Tennessee Valley Authority 82/07/22 Region 2.

 Office of Director 2pp 14151 113 24X Fiche 50-259,82/07/22.
- B20B030160 Forwards LER B2-045/03L-0 GREEN, H J Tennessee Valley Authority B2/07/27 O'REILLY, J P Region 2. Office of Director ip 14160 118 24X Fiche 50-259, 82/07/27, 8208030160
- --8208030164 LER 82-045/03L-0 on 820701, trouble alarm received for control bay elevation 593 fire protection panel 1-25-325 Caused by failed soldered connections as result of mechanical stresses HURPHY,D Tennessee Valley Authority 82/07/28 Region 2, Office of Director 2pp. 14160 117 24X Fiche 50-259,82/07/27,8208030160
- 8208030175 Forwards LER 82-043/03L-0 GREEN.H J Tennesses Valley Authority 82/07/28 D'REILLY, J P. Region 2. Office of Director ip 14160, 192 24X Fiche 50-259, 82/07/28, 8208030175
- --B20B030178 LER 82-043/03L-0 on 820630 & 0704, delta air temp recorder 620-737 MSL (TDR-90-103) observed reading downscale Caused by blown fuses due to lightning striking in vicinity of anviron data station. Fuses replaced.

 IRBV: B J Tennesses Valley Authority 82/07/28 Region 2, 0ffice of Director 2pp 14160 193 24X Fichs 50-257, 82/07/2B, 8208030175
- 8208050208 Forwards updated LER 82-031/03L-1 OREEN.H J Tennessee Valley Authority 82/07/29 O'REILLY, J P Region 2. Office of Director. 1p. 14212 135 24X Fiche: 50-259, 82/07/29, 8208050208
- --B208050213 Updated LER 82-031/03L-1 on B20518, during normal operation, hydrogen analyzer B inoperable due to failure of hydrogen ample inlet pump Caused by failure to Allen Bradley relay Hodel 700-N40QA1 contacts Relay replaced CARTER, B Tennsasee Valley Authority B2/07/29 Region 2, Office of Director 2pp 14212,136 24X Fiche, 50-259, 82/07/29, 82/03030208
- 8208050229 Forwards updated LER 82-038/03X-1 GREEN,H J Tennesse Valley Authority 82/07/29 D'REILLY,J P Region 2, Office of Director 1p 14209 314 24X Fiche 30-259, 82/07/29, 8208050222
- --8208050231 Updated LER 82-038/03X-1 on 820601 & 22 while calibr & changing out pressure suitches.PS-2-748 sw 1 & 2 operated above Tech Bpec limits Caused by calibr drift Swithces recalibr-functionally tested & returned to syc IRBY.8 J. Tennesse Valley Authority 82/07/29 Region 2, Office of Director. 2pp. 14209.315 24X Fiche 50-259.82/07/29, 8208050229
- 8208050279 Forwards LER 82-046/03L-0 08EEN H J Tennessee Valley Authority 82/07/29. O'REILLY, J P Region R. Office of Director. 1p 14210,185, 24x Fiche. 50-259, 82/07/29, 8208050279
- --8208050283 LER 82-046/03L-0.on 820701-03, intermittent trouble alarms received from fire protection panel 1-25-311 Caused by common control card giving intermittent trouble alarms. Gircuit board replaced HUAPHY, D E Tennessee Valley Authority 82/07/29 Region 2, Office of Director 2pp 14210 186 24X Fiche 50-259, 82/07/29, 8208050279
- B208030450 Forwards LER 82-044/03L-0 ORECN,H J Tennesses Valley Authority B2/07/29. O'REJLLY, J P Region R, Office of Director. Ip. 14214 158 24X Fiche 30-259. 82/07/29. 8208050450
- --8208050457 LER 82-044/03L-0'on 820625 & 0709, drywell sump pump discharge valve i-FCV-77-2A failed to close Caused by failed solenoid valve. Valve VBO-3521 replaced, Alf Versa solenoid valves will be replaced during future outages. ROBERTS: H A. Tennessee Velley Authority 82/07/29. Region 2. Diffice of Director. 2pp 14214, 159 24X Fiche: 80-259, 82/07/29, 8208050450.

- 8208100037 PNO-II-82-090 on 820730. w/Unit 2 shutdown for scheduled refueling & mods, Units 1 & 3 failed secondary containment integrity tests & were shutdown Caused by in-leakage between common refueling ions & three individual reactor iones BUTCHER.R C . VERRELCI.D M Region 2. Office of Director 82/08/05 ip 14294 261, 24x Fiche 30-257,82/08/05.8208100037
- 8208200062 Forwards updated LER 82-013/01X-1 QREEN.H J Tennessee Valley Authority 82/08/10 O'REILLY, J P Region 2. Office of Director 1p 14392 181 24X Fithe 50-239, 82/08/10.8208200062
- --8208200073 Updated LER 82-013/01X-1 on 820202.during calibr of degraded voltage relays on 4 kV shutdown boards, trip setpoint of 12 relays found below Tech Space Caused by setpoint drift Could-Brown Boveri relays recalibr.

 60LLEY.S W Tennessee Valley Authority 82/08/10 Region 2. Office of Director 2pp 14392 182 24X Fiche 50-259,82/08/10, P208200062
- 8208270492 Forwards LER 82-048/03L-0 GREEN.H J Tennessee Valley Authority 82/08/13 0'REILLY, J P Region 2, Office of Director 1p 14564 092 24X Fiche. 50-259, 82/08/13,8208270492
- --B20B270507 LER B2-048/03L-0 on 820718, ceil for relay 16A-K37 failed, resulting in partial primary containment feolation Caused by burned out GE Type CR 120A-Model 50000016002 ceil Relay ceil replaced MURPHY. D Tennessee Valley Authority B2/08/13 Region 2, Gffice of Director 2pp 14564 093 24% Fiche, 50-259, 82/08/13, 8208270492
 - '08270510 Forwards LER 82-049/03L-0 GREEN.H J Tennesse Valley Authority 82/08/13 O'REILLY, J. P Region 2. Office of Director 1p 14564 106 24x Fiche 30-259.82/08/13.8208270510
 - 8208270524 LER 82-049/03L-0 on 820721 & 23, 51 4 1 A-11 (MSIV closure functional test) & 81 4 5 E 1, c (HPCI motor operated valve operability test) & 81 4 5, E 1 d & a (HPCI flow rate) not performed, Caused by defective procedure CAMPBELL O Tennessee Valley Authority 82/08/13 Region 2, Office of Director 2pp 14564-107 24x Fiche 50-259.82/08/13, 8208270510
- 8208270544 Forwards LER 82-047/03L-0 OREEN.H.J Tennesses Valley Authority 82/08/13 O'REILLY.JP Region 2. Office of Director 1p 14566.053 24X Fiche 50-259.82/08/13.8208270544
- --B208270548 LER 02-047/03L-0 on B20721, while performing SI 4 2 A-3 (reactor water level indicating switch) LIS-3-360, switches I & 2 operated at 454 56 inches Caused by sticking pointer on indicator Pointer adjusted IRBY, BJ Tennessee Valley Authority B2/08/13 Region 2, Office of Director 2pp 14566 054 24X Fiche, 80-259, 82/08/13, 8208270544,
- 208270086 Forwards LER 82-053/01T-0 QREEN-H J. Tennesses Valley Authority 82/08/19 8'REILLY, J P Region 2. Office of Director 1p 14563,190. 24X Fiche 50-259, 82/08/19, 8208270086
- -8208270091 LER 82-053/01T-0 on 820730, while performing Safety Insp 4 7 C.1 prior to refueling, secondary containment integrity could not be confirmed Caused by displaced relief panel in steem tunnel, allowing inleakage Relief panel replaced WILLIAMSON, B Tennessee Valley Authority. 82/08/19 Region 2 Office of Director 3pp 14363 191 24X Fiche. 50-259, 82/08/19, 8208270086
- 18270231 Forwards LER 82-054/01Y-0 REEN.H J Tennesses Valley Authority 82/08/19 O'REILLY, J P legion 2. Office of Director. ip 14564 133. 24X iche: 50-259, 82/08/19.8208270231
- 08270252 LER 82-054/01T-0 on 820804.during computer analysis of ranch lines for suppression chamber attached piping.drywell . torus purge eys found to have branch line anchored to . loor Caused by design deficiency Anchor design changed. EMET.J.R. Tennessee Valley Authority 82/08/19 Region 2, 14fice of Director 2pp. 14564 154 24K Fiche: 50-259, 82/08/19, 208270231.
- 300290 Forwards LER 82-056/017-0 EEN.H.J. Tennessee Valley Authority, 82/08/23 O,REILLY, J.P., Jion 2, Office of Director, 1p 14599 343, 24X he: 50-259, 82/08/23,8208300290

- --8208300304 LER 82-056/01T-0 on 820810, during shutdown, insp in drywell revealed crack in elbow weld of defunct 1-inch pressure differential indicating switch line on jet pump riser Cause unknown filtown replaced Rept expected within 60 days OARRIOAN, R W Tennessee Valley Authority 82/08/23 Region 2, Office of Director 2pp 14997 344 24X Fiche 50-259, 82/08/23, 8208300290
- 8208310097 PND-II-82-097 on 820819, truck transporting low specific radioactive matl from facility to Richland. WA found to have liquid dripping from truck bed On 820821, drum found to have small holes near base.

 COLLING.T R . BARR, K P Region 2, Office of Director 82/08/24 ip 14495 084 24% Fiche 50-259, 82/08/24, 8208310097
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8207060127 Forwards response to Section III G of App R to 10CFR30 re fire protection plan HILLS.L M Tennessee Valley Authority 82/06/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 202pp 13712 142 24X Fiche 50-259.82/06/30.8207060127
- 8207120070 Releases public version of revision to State of AL radiolegical emergency response plan FELTON. J. M. Division of Rules and Records 82/07/06 Decument Management Branch 1p 13829 312 24X Fichs 50-259.82/07/06.8207120070
- --8207120078 Forwards public version of Revision BFN-REP-82-003 to Bta of AL radiological emergency response plan, constituting App F to Browns Ferry radiological emergency response plan HILLS, L M Tennessee Valley Authority 82/06/23 DENTON.; H R Office of Nuclear Reactor Regulation, Director 2pp 13827 314 24X Fiche 50-259,82/07/06,8207120070
- --8207120083 Public version of Revision DFN-REF-82-003 to State of AL radiological emergency response plan constituting App F to Browns Ferry radiological emergency response plan * Tennesse Valley Authority 82/06/16 92pp 13829 316 24X Fiche. 50-259, 82/07/06, 8207120070.
- 8208090046 Forwards revisions to physical security plan Revisions withheld (ref 10CFR73 21)
 MILLS,L M. Tennesses Valley Authority 82/07/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 14270 035
 Fiche: 50-259, 82/07/22, 8208090046
- 8208110217 Releases public version of revised emergency plan implementing procedures FELTON. J M Division of Rules and Records 82/08/04 Document Hangeavet Branch Ip 14318 084 24X Fiche 50-259,82/08/04.
- ~-B208110221 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-2 renotification of unusual event. IP-4 resite emergency & IP-5 regeneral emergency & SLIOER, E.K. Tenneseee Valley Authority B2/07/16 NRC ~ No Detailed Affiliation Given ip 14318 087 24X Ficher 50-259, 82/08/04, 820810219
- --8208110223 Public version of revised emergency plan implementing procedures, including Procedures IP-2 re notification of unusual event, IP-4 re site emergency & IP-5 re general emergency.

 * Tennessee Valley Authority 82/07/16 110pp 14318 088. 24% Fiche 50-237, 82/08/04, 8208110217
- 8208260338 Releases public version of revised radiological emergency notification directory FELTON, J.M. Division of Rules and Records 82/08/13 Document Management Branch. 1p 14575 275, 24X Fiche 50-259,82/08/13,8208260338
- --8208260346 Public version of Revision 5 to radiological emergency notification directory.

 * Tennesses Valley Authority 82/08/03, 32pp. 14575 278 24% Fiche. 50-259, 82/08/13, 8208260338.

- 220823035: Forwards add1 info on implementation of App R. Item III J re emergency lighting.per D8 Vassallo 820622 Itr to MO Parris Schedule for item also contained in LM Mills 820715 Itr KAMMER, D 8 Tennessee Vailey Authority 82/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14508 283 24% Fiche 30-237,82/08/17,8208230351
- 8208230331 Notifies that additinfore post-accident sampling facility to response schedule requested 820713 will be provided by 821115 MICLS.L M Tennesse Valley Authority 82/08/18 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 14508 325 24% Fiche 30-259.82/08/18.8208230331

G Adjudicatory correspondence

6208270270 Informs that LSP-82-50 accepted for referral by ASLAB & remarked for reconsideration in ALAB-687
RAMSON:R J Hearing Branch 4. 82/08/25 CHILK: B J Office of the Secretary of the Commission 3pp 14563 OSS 24X
Fiche 50-259.82/08/25.8208270270

1 Financial information

- 8208100002 Forwards "TVA Power Program Bummary," Vol 2, for fiscal yr anding 810630 & "1981 Power Program Bummary," for fiscal yr anding 810930, per Section 50 71(b) of 100FR50 MILLS, L. M. Tennessee Valley Authority 82/08/06 DENTON-H R. Office of Muclear Reactor Regulation, Director 116pp 14294.024 24x Fiche 50-000.82/08/06.8208100002.

J Insurance & indemnity information

- 8208310200 Advises that onsite property damage insurance has been purchased in accordance w/100FR50 54 Coverage status encl HILLS,L M. Tennesses Valley Authority 82/08/25 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 14693 160 24K Fichs 50-000.82/08/25.8208310200
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- B20B170283 Forwards updated FSAR for Browns Ferry Nuclear Plant, Vols L-7 HILLS&L M Tempesses Valley Authority 82/08/12 DENTON, N R Office of Nuclear Reactor Regulation, Director ip 14852:001 24: Fiche 50-239, 82/08/12, 8208170283
- --8208170273 Updated FBAR for Browns Ferry Nuclear Plant, Vols 1-7, + Tennesse Valley Authority 82/08/12 3430pp 14852-002 24% Fiche 50-259,82/08/12,8208170283
- 8208170295 Chapter I to Browns Ferry updated FSAR, "Introduction & Bommary."

 4 Tennessee Valley Authority 82/08/12 150pp 14852-017 24X Fiche 50-259, 82/08/12, 8208170295
- 8208170297 Chapter 2 to Browns Ferry updated FSAR. "Bite "
 + Tennessee Valley Authority 82/08/12 450pp 14852 202 24X
 Fiche 50-257, 82/08/12, 8208170297.
- 8208170279 Chapter 3 to Browns Ferry updated FBAR, "Reactor" + Tennesses Valley Authority 82/08/12, 170pp 14833,188 24X Fiche:50-259,82/08/12,8208170279.
- 8208170301 Chapter 4 to Browne Ferry updated FSAR, "RCG "
 # Tennessee Valley Authority, 82/08/12 170pp. 14854,006. RAX
 F(che: 50-259, 82/08/12, 8208170301
- 8208170304 Chapter 5 to Browns Ferry updated FSAR, "Containment" # Tegnesaes Valley Authority, 82/08/12 100pp. 14854.150 24: Fichs 50-257.02/08/12.8208170304
- 8208170307 Chapter A to Browns Ferry updated FBAR, "Core Standby Coolant Sys "

 * Farnesse Valley Authority, 82/08/12 75pp 14854,274, 24x
 Fichs, 50-257,82/08/12:8208170307
- 8208170308 Chapter 7 to Browns Ferry updated FBAR, "Control & Instrumentation" e Tennesses Valley Authority 82/08/12, 500ap 14855:024, 24X Ficbs 30-257, 82/08/12,8208170308

- 8208170310 Chapter 8 to Browns Ferry updated FSAR, "Electrical Power Sya " * Tennessee Valley Authority 82/08/12 278pp 14886 133 24X Fiche 50-259,82/08/12.8209170310
- 8208170311 Chapter 9 to Browns Ferry updated FSAR, "Radwaste Control Syg " * Tennessee Valley Authority, 82/08/12 120pp 14837 177 24x F1che 50-259,82/08/12,8208170311
- 8208170313 Chapter 10 to Browne Ferry updated FBAR, "Auxiliary Bys" * Tennessee Valley Authority 82/08/12 400pp 14857-177 24X Fichs 30-257, 82/08/12, 8208170315
- 820B170317 Chapter 11 to Browns Ferry updated FSAR, "Power Conversion Sus" " Tennessee Valley Authority 82/08/12 30pp 14859 057 24X Fiche 30-259,82/08/12,8208170317
- 8208170319 Chapter 12 to Browns Forry updated FSAR. "Structures & Shielding "

 * Tennesses Valley Authority 82/08/12 200pp 14858 114. 24X Fiche 30-239,82/08/12,8208170319.
- 8208170322 Chapter 13 to Browns Ferry updated FBAR, "Conduct of Operations"

 " Tennesses Valley Authority, 82/08/12 70pp 14859-039 24x Fichs. 50-259, 82/08/12, 8208170322
- 8208170328 Chapter 14 to Browns Ferry updated FSAR. "Plant Sefety Analysis" * Tennessee Valley Authority 82/08/12 120pp 14859-224 24X Fiche 50-259, 82/08/12, 8208170328
- 8208170333 App A to Browns Ferry updated FSAR, "Conformance to ACC Proposed General Design Criteria" # Tennessee Valley Authority 82/08/12 22pp 14860;029, 24x Fiche 30-259, 82/08/12.8208170333
- 8208170336 App B to Browns Ferry updated FSAR, "Tech Specs "
 # Tennessee Valley Authority 82/08/12 ip 14860 091. 24X
 Fiche 50-259, 82/08/12,8208170336
- 8208170339 App C to Browns Ferry updated FBAR, "Structural Loading Criteria" * Tennesses Valley Authority 82/08/12 8ipp 14860 052 24X Fithe 50-259, 82/08/12.8208170339.
- 8208170340 App D to Browns Ferry updated FSAR, "QA Plan for Browns Ferry Nuclear Plant "

 * Tennessee Valley Authority 82/08/12 27pp 14860 136 24x
 Fiche 30-259, 82/08/12, 8208170340
- 8208170375 App E to Browns Ferry updated FSAR, "Site Gaseous Release Rate Limit Calculation" * Tennessee Valley Authority. 82/08/12 3pp 14860 163 24% Fichet 30-259, 82/08/12, 8208170375
- 8208170377 App F to Browns Ferry updated FSAR, "Unit Sharing & Interactions."

 **Tennessae Valley Authority. 82/08/12 30pp 14860:166 24X Fiche: 30-259, 82/08/12, 8208170377.
- 8208170379 App 0 to Browns Ferry updated FBAR, "Plant Nuclear Befety Desemblenal Analysis " • Tennesses Valley Authority 82/08/12 200pp 14860 196. 24x Fiche 50-289, 82/08/12, 8208170379
- 8208170380 App H to Browns Ferry updated FBAR. "Core Thermal Design " * Tennesses Valley Authority 82/08/12. Opp 14840 347 24X Fiche: 50-259, 82/08/12, 8208170380
- 820Bi703B2 App I to Browns Ferry updated FSAR, "Identification-Resolution of CP Concerns." • Tennesses Valley Authority 82/08/j2 55pp 14860-355 24X Fichs: 50-257, 82/08/j2, 820Bi70382.
- 8208170386 App K to Browns Farry updated FSAR, "Reactor Pressure Vessel Design Summery Rept-Unit 2" a Tennessee Valley Authority 82/08/12 ip. 14861.051 24X Fichs. 50-257, 82/08/12, 8208170386.
- 8208170389 App M to Browns Ferry updated FBAR, "Rept on Pipe Failure Outside Containment in Browns Ferry Nuclear Plant." * Tennesses Valley Authority, 82/08/12 50pp 14861,033 24X Fichs, 50-229, 82/08/12, 8208170389.

- P Operating license stage documents & correspondence
- 9208030077 Forwards request for add1 info re NUREO-0737. Item II D 1. "Teeting of Relief & Safety Valves:" in order to complete review of generic test results VASSALLO.D B Operating Reactors Branch 2 92/06/30 PARRIS.H G Tennessee Valley Authority 4pp 14200 314 24X Fiche 30-239. 82/06/30. 8208030077.
- 8208030698 Forwards safety evaluation of proposed method of implementing NUREG-0737, item II K 3 15, "Isolation of HPCI & Reactor Gore Isolation Cooling." Proposed method acceptable
 VABBALLO, D 8 Operating Reactors Branch 2 82/06/30 PARRIS. H G Tennesses Valley Authority 4pp 14196 321 24X
 Fiche 50~289, 82/06/30, 8208030498
- 8207080064 Generic 1tr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Byc list encl
 DIRCKS, W J Diffice of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14174 001
 24X Fiche: 50-000, 82/07/02. 8207080064
- 8208040077 Requests data to support conclusion of adequacy space cooling for HCPI & reactor core isolation cooling Response of 811230 unacceptable since no analysis or test data to support conclusion substited.

 VASSALLO, D. B. Operating Reactors Branch 2 82/07/08 PARRIS, H G Tennessee Valley Authority 2pp 14228 271 24X Fiche 50-257, 82/07/08, 8208040077
- B208040064 Notifies that generic issue repossible diesel generator jockout resolved Operator training program covers subjudgequately VASSALLO, P.B. Operating Reactors Branch 2. 82/07/15 PARRIS, H.O. Tennessee Valley Authority 4pp. 14228: 280 24X Fiche 50-259, 82/07/15, 8208040064.
- 8207270454 Requests extension to 820812 for submittal of updated FSAR HILLE:L M Tennessee Velley Authority 82/07/20 DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p 14061 168. 24X Fiche. 50-259, 82/07/20. 8207270454
- 8208040555 Forwards draft technical evaluation rept, "Control of Heavy Loads," Conference call requested within 30 days to discuss proposed recommendations in rept VASSALLO, D.B. Operating Resctors Branch 2. 92/07/22 PARRIS, H.O. Tennesses Valley Authority 2pp 14221-150 24X Fichs. 50-259, 82/07/22, 8208040555.
- 8208110279 Forwards Amends 85,82 & 96 to Licenses BPR-33.DPR-52 & DPR-68 respectively, safety evaluation & notice of issuance & availability Amends consist of clarification & administrative changes & additions to reflect plant mods CLARK, R. J. Operating Reactors Branch 2 82/07/22 PARRIB, H. & Tennessee Valley Authority 2pp. 14332 034 24X Ficha 50-259, 82/07/22.8208110279.
- --8208110283 Amends 85,82 & 56 to Licenses DPR-33.DPR-52 t DPR-68, respectively, consisting of clarification & administrative changes & additions to reflect plant mode & reorganization of some Tech Spec sections
 VASSALLO
- --8208110287 Bafety evaluation supporting Amends 85.82 & 56 to Licenses DPR-33.DPR-52 & DPR-68, respectively # Office of Nuclear Reactor Regulation, Director 14332:165 24X Fichs 50-259,82/07/22.8208110279
- --8208110270 Notice of issuance & aveilability of Amends 85,82 & 56 to Licenses DFR-33.DFR-52 & DFR-66, respectively. VASSALLO, D B Licensing Branch 2 82/07/22 2pp 14332; 170 24X Fiche: 50-259,82/07/22,8208110279
- 9208040663 Requests 820729 meeting in Chattanogge, TN to discuss HSIVs in BWR plants.
 VASSALLO, D B Operating Reactors Branch 2. 82/07/23 PARRIS, H O Tennesses Valley Authority 2pp 14224 360 24X
 Fiche 50-259, 82/07/23, 8208040663
- 8208020221 Responds to NRC 820212 request for add1 info re need for chlorine detectors at facilities, per NUREG-0737, Item III D 3,4 Ns threat to control room habitability from chlorine on or off site evident MILLS.L M Tempessee Valley Authority 82/07/27 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 14151-222 24X Fiche 50-239,82/07/27.8208020221.

- 820B12O363 Forwards revised version of model Feth Specs re plactric power monitoring of reactor protection sys previously submitted in 911030 ltr VASSALLO, D.B. Operating Reactors Branch 2 82/07/28 PARRIS, H.G. Tennessee Valley Authority 3pp 14340 079 24X Fiches 50-259, 82/07/28, 820Bi2O363
- 8208130444 Forwards safety evaluation & LLL technical evaluation rept on licenses response to NUREO-0737, Item [I B 1, "RCS Vents" Issue resolved VASSALLD, D B Operating Reactors Branch 2 82/08/02 PARRIB, H G Tennessee Valley Authority 3pp 14354 343 24X Fiche 30-289, 82/08/02, 82808130444
- --8208130446 "RCS Vents," tochnical evaluation rapt
 BUTCHER, E , BARNHART, B Lawrence Livermore Laboratory FIN
 A-0246-2 82/06/02 Division of Licensing 4pp 14354 346
 24X Fiche 50-259, 82/08/02.8208130444
- 8208070174 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl EISENHUT, D G. Division of Licensing 82/08/07 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000, 82/08/09, 8208070174
- 8208250376 Forwards mechanical snubber qualification test repts for Pacific Scientific Co Models P8A 1/4 P6A 100 as requested by NRC Only qualitative-type actuation tests planned at plants, beginning w/Browns Ferry 2 & Sequeyah 1 MILLS.L M Tennesses Valley Authority 82/08/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14541 GOZ 24X Fiche 50-000, 82/08/18, 8208250376
- --8208250383 Revision A to "Qualification Test Rept for Model 1801104-05 PSA 1/4 Shock " WHITNEY,R F , QLAUSER,J E , WRIGHT,W 8 Pacific Scientific TR 837 RA. 82/03/18 27pp 14541 005 24X Fiche 50-000,82/08/18, 8208250376
- --8208250387 Revision R to "Acceptance Test Procedure IT 527 P/N 1801104." LEVAN.H C Pacific Scientific 79/11/09 13pp 14541 032 24x Fiche 50-000,82/08/18,8208250376
- --8208250391 "Gualification Test Rept for Model 1801104-07 PSA 1/2 Short Arrestor "
 WHITNEY:R F , QLAUSER.J E , WRIGHT.W S Pacific Scientific TR 840 79/12/12 27pp 14541:045 24X Fiche 50-000.82/08/18.8208250376
- --8288250402 Revision A to "Gualification Test Rept for Model 1801102-05 PBA 1 Shock Arrestor" WHITNEY:R F. SLAUSER:J E. WRIGHT:W S. Pacific Scientific TR 841 RA 80/03/18 26pp 14541 085 24X Fiche 90-000,82/08/18, 8288250376
- ~-B208250409 Revision T to "Acceptance Test Procedura IT 319 P/N 1801102 " LEVAN:H C Pacific Scientific 79/06/13 14pp 14541 111 24X Fiche 50-000,82/08/18,8208250376
- --8208250415 "Qualification Test Rept for Model 1801106-05 PBA-3 Short Arrestor "
 HHITNEY,R F , GLAUSER, J E , WRIGHT,W S Pacific Scientific TR 842. 80/01/22 27pp. 14541 125 24X Fiche 50-000,82/08/18,8208250376
- --8208250421 Revision R to "Acceptance Test Procedure IT 524 for 1801106"

 LEVAN.H C. Pacific Scientific 79/02/16 13pp 14541:152 24X Fiche: 50-000,82/08/18,8208250376
- --8208250425 "Gualification Test Rept for Model 1801103-07 PSA 10 Shock Arrestor "
 HHITNEY.R F , QLAUSER, J E , WRIGHT, W 8 Pacific Scientific. TR
 843 80/01/25. 27pp 14541 166 24X Fichs 50-000.82/08/18.
- --8208250431 Revision R to "Acceptance Test Procedure IT 523 P/N 1801103" LEVAN, H C Pacific Scientific 79/08/15 14pp. 14541 193 24X Fiche 50-000,82/08/18,8208250376.
- --8208250497 Revision A to "Gualification Test Rept for Model 1801112-11 PSA-35 Shock Arrestor." WHITNEY.R.F., GLAUSER.J E., WRIGHT.W 8 Pacific Scientific TR 845 RA 80/02/07 30pp 14541 207 24X Fiche 50-000,82/08/18. 8208250376

- --9208250441 Revision J to "Acceptance Test Procedure IT 534 P/N IB01112" LEVAN.H C Pacific Scientific 77/05/10 12pp 14541 237 24X Fiche 50-000.82/08/18.8208250376
- --P209250443 "Qualification Test Rept for Model 1801119-11 PBA-100 Shock AFFESSOR WHITNEY, R. F., OLAUSER, J. E., WRIGHT, W. B. Pacific Scientific 848 80/05/12 31pp 14541 249 24X Fiche 50-000,82/08/18, 820825037A
- -- 8208250446 Revision H to "Acceptance Test Procedure IT 533 P/N 208290446 Nevision of to "Acceptance lest Procedure IT 533 P/N LEVAN.H C Pacific Scientific 77/04/07 12pp 14541 280 24X Fiche, 50-000, 82/08/18, 8208250376
- 3 Imagestion reports, IE Bulletins & correspondence
- 6204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV)
 Leatage." Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance. 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274. 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26.Part 3. Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Fadiation" Svc list onci UNRDAME L Bivision of Engineering & Quality Assurance 82/07/19
 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19.
- E234210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York 112pp 14361 001, 24X Fichs 50-000, 82/07/20, 8204210396
- 6204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Cystpacis " Syc list encl COSB.t. I Division of Foel Facilities, Materials & Safeguards 62/07/20 Consolidated Edison Co of New York 71pp 14357 2: 24K Fiche 50-000, 62/07/20, 8204210397
- P204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JCRDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York. 112pp 14194 321 24X Fichs 50-000, 82/07/22, 8204210398
- P204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- E204210402 IE Info Natice 82-29, "Control Rod Drive (CRD) Quide Tube Eveport Pin Failures at Westinghouse PWRs " 8vc list and ORDAN.E L Division of Engineering & Quality Assurance. 82/07/29 Consolidated Edison Co of New York, 127pp 14194:120 24X Fishs 50-000.82/07/29.8204210402
- 62:06210403 IE Info Notice 62-30. "Loss of Thermal Siseves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDANIE L Division of Engineering & Quality Assurance. 82/07/26 Censolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8200000582 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14 CENIS.R C Division of Project & Resident Programs. 82/07/26 PARRIS.H O Tennesses Valley Authority ip 14162.277 24X Fichs 50-259.82/07/26,8208030582
- --S206030572 Responds to NRC 820607 Itr reviolations noted in IE Insp. Repts 50-299/82-14.50-260/82-14 & 50-296/82-14 Corrective actions posted signs identifying shield plugs that require presence of health physics personnel for removal. KAMMER.D B Tennessee Valley Authority 82/07/16. D'REILLY, J. P. Region 2. Office of Director 4pp 14162:278 24X Fishe 50-259,82/07/26,8208030582
- --3208030597 Forwards IE Insp Repts 50-259/82-14,50-260/82-14 & 50-295/82-14 on 820503-04 & notice of violation LEWIS,R C Division of Project & Resident Programs. 82/05/09 PARRISJI Q Tennessee Valley Authority 2pp 14162 282 24X Fiche. 50-259, 82/07/26, 8208030582.
- R208030602 Notice of violation from insp on 890503-04
 B Division of Project & Resident Programs 82/06/09, 2pp. 14162 264 24X Fiche: 50-259, 82/07/26, 8208030582

- --8208030610 IE Insp Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14 on 820903-04 Noncompliance noted failure to perform radiation survey after removal of shield plugs & failure to issue permit for removal of denineralizer cell shield plugs PEERY: W W . BARR.X P Division of Engineering & Technical Programs 82/06/02 4pp 14162 286 24X Fiche 50-259,82/07/26,8208030582
- 8208160395 Forwards IE Insp Repts 50-289/82-18.50-260/82-18 & 50-296/82-18 on 820626-0725 No noncompliance noted VERRELLI.D H Division of Project & Resident Programs 82/07/2ARRIS.H Q Tennesses Vallsy Authority 2pp 14348 012 24X Fichs 50-259,82/07/26.8208160395 82/07/26
- --B208160408 IE Insp Repts 30-299/82-16, 30-260/82-18 & 30-296/82-18 on 820626-0725 No noncompliance noted Major areas inspected operational safety RDs. surveillance testing, maint observation, TMI action items & independent insp effort CHASE, J W. PAULKO L. CANTRELL, F. 9 Division of Project & Resident Programs. S2/07/26 Spp 14348 014 24X Fiche 50-259, 82/07/26, 8208160395
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 9204210405
- 8208160274 Forwards IE Insp Repts 50-259/82-21,50-260/82-21 & 50-296/82-21 on 820628-0702 No noncompliance nated VERRELLI.D M Division of Project & Resident Programs 62/07/28 PARRIS, H G Tennessee Valley Authority 2pp 14345 255. 24X Fiche 50-259,82/07/28,8208160294
- ---8208160311 IE Insp Repts 50-259/82-21, 50-260/82-21 & 50-296/82-21 on 820628-0702 No noncompliance noted Major areas inspected; radioactive matl packaging, shipment & processing, posting of notices, house is eping & instrument callir COLLING, T R, DEBS, B T, BARR, K P Division of Engineering & Technical Programs 82/07/22 5pp 14345 257 24X Fiche 50-259, 82/07/28, 8208160294
- 8208160484 Ack receipt of 820730 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-19, 50-260/82-19 & 50-276/82-19
 VERRELLI, D. Division of Project & Resident Programs 82/08/03 PARRIE, H G Tennessee Valley Authority 1p 14348 104 24% Fiche 50-259, 82/08/03, 8208160484
- --8208160491 Responds to NRC 820701 ltr re violations noted in IE Insp. Repts 50-259/82-19.50-260/82-19 & 50-296/82-19 Corrective actions torus area high radiation rope barrier reinstalled & radiological tape placed on floor.

 KAMER.D S Tennessee Valley Authority 82/07/30 D'REILLY, J.P. Repton 2. Office of Director 3pp 14348 105 24X Fiche 50-259, 82/08/03.8208160484.
- --8208160498 Forwards IE Insp Repts 50-239/82-19,50-260/82-19 & 50-296/82-19 on 820324-0623 & notice of violation LONG, F J Division of Project & Resident Programs 82/07/6 PARTS. H O Tennessee Valley Authority 2pp 14348 108 Fiche 50-259,82/08/03.8208160484
- ---8208160507 Notice of violation from insp on 820324-0625 * Division of Project & Resident Programs 82/07/08 14348 110 24X Fiche 50-259, 82/08/03, 8208160484
- --8208160521 IE Imsp Repts S0-259/82-19, 50-260/82-19 & 50-295/82-19 on 820526-0625 Noncompliance noted failure to properly barricade two high radiation areas in torus area CHASE, J W, PAULK, O L, CANTRELL, F S. Division of Project & Resident Programs 82/06/30. App. 14348-111 24X Fiche: 50-259, 82/08/03. 8208160484
- B208160493 Ack receipt of B20720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-259/82-15, 30-260/82-15 & 50-276/82-15 ELHIS,R C Division of Project & Resident Programs, B2/08/04, PARRIB, H O Tennesses Valley Authority ip 14348 ii7 24% Fichs, 50-259, 82/08/04, 8208160493
- --8208160502 Responds to NRC 820603 ltr re violations noted in IE Insp Repts 50-259/82-15, 50-260/82-15 & 50-276/82-15 Corrective actions daily monitoring & drainage program will be continued, Violations re Items A & B denied MILLS, L. M Tannessee Valley Authority 92/07/20 D'REILLY, J P Ragion 2, Défice of Director 7pp. 14348 ii8 24X Fiche 50-259, 82/08/04, 8208160493

- --8208160515 Forwards IE Insp Repts 50-259/82-15, 50-260/82-15 & 50-296/82-15 on 820426-0325 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/06/03 PARRIS.H Q Tennessee Valley Authority 2pp 14348 125 24X Fiche 50-259,82/08/04.8208160493
- --8208160520 Natice of violation from insp on 820426-0525 * Division of Project & Resident Programs 82/06/03 2pp 14348 127 24% Fich 50-259, 82/08/04, 8208160493
- --B208160528 TE Insp Repts 50-297/82-15,50-260/82-15 & 50-296/82-15 on B20426-0923 Noncompliance noted written safety evaluation re offgas post-treatment sampling station configuration mod not performed CHABE.J W. PAULK.O L. CANTRELL.F S Division of Project & Resident Programs 82706/02 10pp 14348 129 24X Fiche 50-259,82/08/04,8208160493
- 8204210407 IE Info Notice 82-27, "Fuel Rad Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl URBDAN,E L. Division of Engineering & Quality Assurance 82/08/05 Consulidated Edison Co. of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05,8204210407,
- R Pariodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dome exposures in 1981 for operating nuclear power plants 2 analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project Epp 14679: 209 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1 " * NRC - No Detailed Affiliation Given 82/07/13 48pp 14479:216. 24% Fiche: 50-000,82/07/10/8208270010
- --8208270601 Forwards "Personnel Whole Body Exposures for CY81," per 10CFR20 407
 HILLS.L M Tennesses Valley Authority 82/03/23 BROOKS, B G. Licensee Operations Evaluation Branch 1p 14680 053 24X
 Fiche 50-000,82/07/13.8208270010
- --9208270605 "Personnel Whole Body Exposures for CY81"

 * Tennessee Valley Authority 82/03/23 2pp 14680 054 24X
 Fiche 50-000,82/07/13.8208270010
- 8208120226 Forwards monthly operating repts for June 1982 JONES, G. T. Tennessee Valley Authority 82/07/14 Defice of Management and Program Analysis 1p 14326-176 24X Fiche 50-259, 82/07/14,8208120226
- --8208120233 Monthly operating repts for June 1982 JONES, 0 T , THOM, T Tennessee Valley Authority 82/07/14 39pp 14326 177 24% Fiche: 50-259, 82/07/14, 8208120226
- 8 Reportable occurrences, LERs & related correspondence
- B208020094 Forwards updated LER 81-050/03X-3 OREEN.H.J Tennesses Valley Authority 82/07/22 O'REILLY, J P Region 2, Office of Director. Ip 14144 084 24X Fichs-50-260, 82/07/22:8208020094
- --8208020096 Updated LER 81-080/03X-3 on 811003, containment atmosphere torus hydrogen analyser 2-f2H-76-104 removed from svc for corrective maint Caused by presence of water in sensing lines Design change under review BURNS.R Tennessee Valley Authority 82/07/22 Region 2, Cffice of Director 2pp 14144,085 24X Fiche. 50-260,82/07/22,8208020094
- B208050215 Forwards LER B2-020/03L-0 OREEN.H J Tennessee Valley Authority B2/07/29. O'REILLY, J. P Region 2. Office of Director ip. 14209:263 24X Fiche:50-260, 02/07/29, 8208050215
- --8208050222 LER 82-020/03L-0 on 82071i, while performing surveillance on main steam tunnel high temp switched TS-1-29A failed to operate Caused by valve leakage onto switch junction box.

 Leak reduced & junction box sealed

 IRBY, B J Tennessee Valley Authority 82/07/29 Region 2.

 Diffice of Director 2pp. 14209.264 24X fiche 50-260,82/07/29,8208030215
- 8208050324 Forwards updated LER 81-054/03X-2 OREEN.H J Tennessee Valley Authority. 82/07/30. G'REILLY.J.P Region 2. Office of Director ip 14237-290. 24X Fiche-50-260.82/07/30.8208050324

- --820805034i Updated LER 81-054/03X-2 on 8i1010.hydrogen analyzer D sample return pump discovered inoperable Caused by tripped motor overloads due to motor current reaching 10X to 15X high On-load tap changer limits lowered CARTER.8 Tennessee Valley Authority 82/07/30 Region 2. Office of Director 2pp 14237 271 24X Fiche 50-260,82/07/30,8208050324
- 8208100157 PNO-II-82-091 on 820802.airborne 1-131 detected by radiation monitor in occupied space above refueling floor Caused by leaking flange in spray line connected to reactor vessel head Clothing of three workers contaminated BARR.K., GIBBON, A.F. Region 2. Office of Director 82/08/03 2pp 14298 041 24X Fichs 50-260,82/08/03,8208100157
- 820B120184 Forwards LER 82-023/01T-0 OREEN.H J Tennesses Valley Authority 82/08/05 O'REILLY, J P Region 2. Office of Director ip 14325; 360, 24X Fichs 50-260, 82/08/05, 8208120184
- --8208120190 LER 82-023/01T-0 on 820723, equalizer valve on differential pressure switch 2-Pdia-73-18 three-valve block manifold would not close rendering switch inoperable Caused by improperly seated valve manifold equalizer valve * Tennessee Valley Authority 82/08/05 Region 2, Office of Director 2pp 14325 361 24X Fiche 50-260,82/08/05,8208120184
- 8208270282 Forwards LER 82-021/03L-0 GREEN-H J Tennessee Valley Authority. 82/08/12. O'REILLY, J P Region 2. Office of Director ip 14564 156 24X Fiche 50-260.82/08/12.8208270282
- --620827029; LER 62-021/03L-0, on 820720, hydrogen analyzer B became inoperable. Caused by Valcor Engineering Corp solenoid operator P/N V52630-529-1 failure. Solenoid replaced but failed again Valve will be repaired during refueling outage CARTER. 8 D. Tennessee Valley Authority 82/08/12 Region 2. Office of Director 2pp 14564.157 24X Fichs 50-260, 82/08/12. 8208270282
- 8208200118 Forwards LER 82-022/03L-0 GREEN H J Tennesse Valley Authority, 82/08/13 O'REYLLY, J P Region 2, Office of Director 1p 14393 335. 24X Fichs 50-260, 82/08/13, 8208200118
- --8208200129 LER 82-022/03L-0 on 820721, calculated R factor less than A factor used to set average power range monitor scram & rod block Caused by high core exposure & reduced core reactivity Tech Spec changes issued NAVE-E D Tennessee Valley Authority 82/08/13 Region 2. Office of Director. 2pp. 14393 334 24X Fiche 50-260,82/08/13. 8208200118
- 8208270078 Forwards LER 82-025/03L-0 OREEN.H J Tennessee Valley Authority 82/08/17 O'REILLY.JF Region 2. Office of Director 1p 14563 133, 24X Fichs 50-260,82/08/17,8208270078
- --8208270082 LER 82-025/03L-0 on 820719, during startup, relay coil failed, resulting in partial primary containment isolation Caused by burned out coil relay, causing relay to fail in safe direction for primary containment isolation MURPHY.D.E Tennesses Valley Authority 82/08/17 Region 2, Office of Director 2pp, 14563 134 24X Fiche 50-260.82/08/17, 8208270078
- 8208310097 PNO-II-B2-097 on 820819, truck transporting low specific redicactive matl from facility to Richland, WA found to have liquid dripping from truck bed On 820821, drum found to have small holes near base COLLINS, T.R., BARR, K.P., Region 2, Office of Director 82/08/24, Ip., 14695-084 24X Fiche 30-259, 82/08/24, 8208310097
- DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8208100228 Forwards IE Safeguards Insp Rept 50-261/82-16 on 820510-14 Details & notice of violation withheld (ref 10CFR73.21) LEWIB:R C Division of Project & Resident Programs 82/06/09 JONES, J A Carolina Power & Light Co 2pp 14274-037, 24X Fiche.50-261:82/06/09,8208100228.
- --B20B100R35 IE Bafeguards Insp Rept 50-261/B2-16 on B20510-14.
 Noncompliance noted failure to supply NRC w/rept describing change to security plan & to perform audit at required frequency, Details wishhald (ref 10CFR73, 21).
 PERNY, C D · MCGUIRE, D, R. Division of Engineering & Technical Programs B2/06/02. Ip. 14294:339, 24% Fiche:50-261, B2/06/09, B208100228

- #CH0326 Releases public version of revision to Vol 13 of emergency response plan FELTCH, J M Division of Rules and Records 82/07/23 Document "amagement Branch 1p 14231 183 24X Fiche 50-261,82/07/23,82/8040326
- EACCOM 0330 Forwards public version of Revision 11 to Vol 13 of eaergency response plans per NRC 820316 ltr re emergency preparations appraisal MOMER PW Carolina Power & Light Co 82/07/15 O'REILLY, J P Fagion 2. Office of Director 2pp 14231 186 24X Fich 8 50-261, 82/07/23, 8208040326
- 9208040334 Public version of Revision 11 to Vol 13 of Emergency response plan
 a Carolina Power & Light Co 82/07/02 78pp 14231 188 24X Fich # 50-261, 82/07/23, 8208040326

- -R2OS1&0110 IE Safeguards Insp Rept 50-261/B2-26 on B2072&-30 No non-compliance noted Major areas inspected security plan & implementing procedures, security organization-mgt, personnel & response Details withheld (ref locFR/3 21)
 IOBIN,H, STANSBERRY,W W. MCGUIRE, D. R. Division of Engineering & Technical Programs 82/OB/10 2pp 14345 158 24X
 Fiche 50-261, B2/OB/11, B20B160106
- 208270563 Releases public version of revised emergency plan procedures FELYON.J M Division of Rules and Records 82/08/11 Document Management Branch 1p 14682 156 24X Fiche 50-261,82/08/11, 8208270563
- --B2O8270571 Forwards public version of revised emergency plan procedures, including Procedures PEP-2 1 re initial emergency actions, PEP-2 2 re emergency control unusual event & PEP-2 3 re emergency control alert 11MMERMAN.S Carolina Power & Light Co 92/07/30 O'REILLY, J.P. Region 2, Office of Director 5pp 14682 159 24X Fiche 50-261, 82/08/11, 8208270563
- --8208270578 Public version of revised emergency plan procedures, including Procedures PEP-2 i re initial emergency actions, PEP-2 2 re emergency control unusual event & PEP-2 3 re emergency control alert & Carolins Power & Light Co 82/07/02 350pp 14682:164 24X Fiche 50-261,82/08/11,8208270563
- 82G8260470 Requests full-size engineering drawings of plant layout & eys.needed to support programs eimed at reviewing effectiveness of NRC safeguards regulations & at validating vital area designations VARGALB A Operating Reactors Branch 1 82/08/12 JDNES.J. A Carolina Power & Light Co 4pp 14595 060 24X Ficha 50-261.82/08/12.8208260470
- 9208300166 Forwards IE Bafeguards Insp Rept 50-261/82-28 on 820816-17. No noncompliance noted VERRELLI, D Division of Project & Resident Programs 82/08/25. JOHES, J A Carolina Power & Light Co 2pp 14599-190. 24X Fiche 30-261.82/08/25,8208300166
- --BROB300167 IE Safeguards Insp Rept 50-261/B2-28 on B20816-17 No noncompliance noted Major areas inspected site security apprecions during investigation of alleged drug usage by security personnel Details withheld (ref 10CFR73 21) HALL, B L : MCQUIRE, D R Division of Project & Resident Programs B2/08/24. 1p 14599.192 24X Fichs 50-261, B2/08/25, 8208300166
- P Operating license stage documents & correspondence
- 8207140517 Informs of forthcoming refunds of fees paid re applications resulting in Amends 67 & 68
 MILLER.W O License Fee Management Branch, 82/07/01 JONES, J. A. Carolina Power & Light Co ip 13848 361, 24X
 Fiche 50-261,82/07/01,8207140517

- 8207080064 Generic ltr to all licensees of operating plants, applicants for CL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS, N J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000,82/07/02,8207080064
- 8208020438 Requests util provide rept documenting relief & safety valve failures for Apr 1980 to present & commitment to rept all failures promptly & all challenges periodically Info needed to complete review of TMI Item II K 3 3 VARGA: 8 A Operating Reactors Branch 1 82/07/07 JUNES, J A Carolina Power & Light Co 2pp. 14181 039 24X Fiche \$0-261:82/07/07,8208020438
- 8208040058 Forwards request for add1 info necessary to complete review of responses to Generic Ltr 81-14 re seismic qualification of auxiliary feedwater sys Response due by 820806 VAROA B A Operating Reactors Branch 1 82/07/21 JONES, J. A Carolina Power & Light Ca 3pp 14228 358. 24X Fiche 50-261, 82/07/21, 8208040058
- 8208110228 Forwards Amend 71 to License DPR-23, safety evaluation & notice of issuance & availability Amend authorizes Gucle 9 operation at reduced level & revises App A Tech Specs & License Conditions 3 I arb.c. & dre steam generator insp VAROA.8 A Gperating Reactors Branch 1 82/07/23 JONES, J A Carolina Power & Light Co 2pp 14330 340 24% Fiche 50-261, 82/07/23, 8208110228
- --8208110231 Amend 71 to License DPR-23, authorizing Cycle 9 operation at resuced power level & revising App A Tech Specs & License Conditions 3 I a, b, c & d to include steam generator insp & tube leakage criteria VAROA, S A Detrating Resctors Branch 1 82/07/23 RBpp 14330 342 24X Fiche 50-261, 82/07/23, 8208110228
- ---8208110233 Safety evaluation supporting Amend 71 to License DPR-23. * Office of Nuclear Reactor Regulation, Director 82/07/23. 20pp 14331-008 24X Fiche: 50-261,82/07/23,8208110228.
- --B20Bi10237 Notice of issuance & availability of Amend 71 to License ppR-23.
 VARQA.S A Operating Reactors Branch 1 82/07/23 2pp 14331 028 24% Fiche. 50-241.82/07/23.820Bi10228
- 8208240137 Forwards safety evaluation of response to TMI Action Item II F 1. "Containment High Range Radiation Monitor " Response acceptable VAROAS A Operating Reactors Branch I 82/07/26 JUNES, J A Carolina Power & Light Co 3pp 1454B 168 24X Fiche 50-261, 82/07/26, 8208240137
- 8208110191 Requests extension of implementation date for Amend 70 to License DPR-23 until B20913 Request due to delays in plant start up from current refueling nutage HOME.P.W Cerolina Power & Light Co. 82/08/04 VARQA.8.A Operating Reactors Branch 1 ip 14314 286 24X Fichs 30-261.82/08/04.8208110151.
- B208090194 Qeneric i.tr B2-i4 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements by provides alternatives to requirements Bvc list encl EIBENHUT, D O Division of Licensing. 82/08/09. Consolidated Effson Co. of New York ip 14356-332. 24X Fiche 50-000, 82/08/09, 8208090194
- 8208240166 Responds to 820721 ltr requesting clarification of auxiliary fredwater sus boundaries assumed in Bit231 response to Orneric Ltr Bi-14, Analyses conducted for IE Bulletin 79-14 adequate for use in response to generic ltr, IINKERNANS R Carolina Power & Light Co 82/08/20 VAR9A, B A Operating Reactors Branch 1 2pp. 14519-001. 24% Fiche 50-261, 82/08/20, 8208240166
- Q Inspection reports. IE Bulletins & correspondence
- 8208100228 Forwards lE Safeguards Insp Rept 50~261/82-16 un 820510-14 Details & notice of violation withheld (ref 100FR73 21). LEWIS.R.C. Division of Project & Resident Programs. 82/06/09. JONES.J.A. Carolina Power & Light Co. 2pp 14294.337. 24X Fiche: 50-261, 82/06/09.8208100228.
- --8208100235 IE Bafeguards Insp Rept 50-261/B2-16 on 820510-14.

 Noncompliance noted failure to supply NRC w/rept describing change to security plan & to perform audit at required frequency Details withheld (ref 10CFR3, 21).

 PERNY.C.D. MCQUIRED R. Division of Engineering & Technical Programs. 82/06/02. 1p 14294:339. 24X Fichs 50-261.82/06/09.8208100228

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356-274 24X Fiche 50-000,82/07/16,8204210393
- 8204210395 JE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan. Univ of 112pp 14358 001 24% Fiche 50-000, 82/07/19, 8204210395
- B204210396 IE Info Notice B2-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Byo list end! JORDAN,E L Division of Engineering & Quality Assurance B2/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 JE Info Notice 82-24, "Water Leaking From U Herafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14337 274 24X Fiche 50-000,62/07/20,6204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Svc list encl JGRDAN.E L Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list and! URBAN,E L Division of Engineering & Quality Assurance 62/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23,8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JURDAN.E L Division of Engineering & Quality Assurance 62/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000. 82/07/23.8304210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sieeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl URBDAN.E L Division of Engineering & Quality Assurance Gonsolidated Edison Co of New York 121pp 14337 013 24X Fiche 50-000.82/07/26.8204210403
- 8208160180 Forwards IE Insp Rept 50-261/82-24 on 820628-0702 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/07/26 JUNES, J A Carolina Power & Light Co 2pp 14345 103 24X Fiche 50-261,82/07/26,8208160180
- --8208i60186 IE Insp Rept 50-26i/82-24 on 820628-0702 No noncompliance noted Hajor areas inspected previous enforcement matters, organization & administration, housekeeping & cleanliness, test & measurement equipment program & calibr program BELISE,0 A , FREDRICKSON.P , UPRIGHT.C M Division of Engineering & Technical Programs 82/07/20 11pp 14345 105 24% Fiche 50-261,82/07/26,8208160180
- ROB160522 Forwards IE Insp Rept 50-261/82-25 on 820706-09 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/07/26 JONESJ A Carolina Power & Light Co 2pp 14348 082 24X Fiche 50-261, 82/07/26, 8208160522
- 8208160526 IE Insp Rept 50-261/82-25 on 820706-09 No noncompliance noted Hajor areas inspected radiation protection & transportation of radioactive matis ALBRIGHT,R H , BARR,K P Division of Engineering & Technical Programs. 82/07/20 App 14348 084 24% Fiche 50-261,82/07/26.8208160522
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208160344 Ack receipt of 820702 ltr informing NRC of steps taken to correct violations noted in IE Investigation Rept 50-261/82-03 on 820111-0226
 VERRELLI.D M Division of Project & Resident Programs 82/07/29. JONES J A Carolina Power & Light Co ip 14348 001 24X
 Fiche 50-261. 82/07/29. 8208160344

- --8208160338 Responds to NRC 820624 ltr re violations noted in IE Investigation Rept 50-261/82-03 on 820111-0224 Corrective actions verification made to ensure that curves in reactor vessel would not result in nonconservative operation . STARKEY, R B Carolina Power & Light Co 82/07/24 0'REILLY, J P Region 2. Office of Director 3pp 14348 002 24X Fiche 50-261,82/07/29,8208160344
- --8208160363 Forwards IE Investigation Rept 50-261/82-03 on 820111-0226 & notice of violation O'REILLY, J.P. Region 2, Office of Director 82/06/24 JONES, J.A. Carolina Power & Light Co. Zpp. 14348 005 24x Fiche 50-261,82/07/27,8208160344
- --8208160367 Notice of violation from investigation on B20111-0223 + Region 2, Dffice of Director 82/06/24 ip 14348 007 24K Fiche 50-261.82/07/29.8208160344
- --8208160377 IE Investigation Rept 50-261/82-03 on 820111-0226
 Noncompliance noted failure to process info received from
 contractor & failure to request amend to Toch Spacs to make
 heatup & cooldown curves more conservative
 VORSE, J Y . ALDERSUN.C E Region 2. Office of Director 82/04/22
 4pp 14348 008 24X Fiche 50-261.82/07/27,8208160344
- 8208160278 Provides info re Action Item 3 in response to IE Bulletin 02-02. "Degradation of Threaded Fasteners in RCPB of PWR Plants" Control rod drive flanges & pressurizer heater connections seal welded FURR.8 J. Carolina Power & Light Co. 82/07/30 O'REILLY, J.P. Region 2. Office of Director 2pp 14346 259 24% Fiche 50-261, 82/07/30, 8208160278
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jøt Impingøment" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000.82/08/05,8204210407
- 8208160405 Discusses util actions based on confirmation of action ltree cracking of reactor coolant pump bolts Util insps, evaluations & final results of main coolant pump bolt problem comply w/NRC request Restart may proceed O'REILLY.J P Region 2. Office of Director 82/08/07 JONES.J A Carolina Power & Light Co ip 14348 317 24X Fiche 50-261.82/08/07,8208160405
- 8208160104 Forwards IE Safeguards Insp Rept 50-261/82-26 on 820726-30 No noncompliance noted VERRELLI,D Region 2, Office of Director 82/08/11 JONES,J A Carolina Power & Light Co 2pp 14345 156 24X Fiche 50-261,82/08/11,8208160106
- --8208160110 IE Bafeguards Insp Rept 50-261/82-26 on 820726-30 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization-mgt, personnel & response Details withheld (ref 10CFR73 21) TOBIN, W. STANBBERY, W. W. MCGUIRE, D. R. Division of Engineering & Technical Programs 82/08/10 2pp 14345 158 24X Fiche 50-261,82/08/11,8208160106
- 8208300166 Forwards IE Bafeguards Insp Rept 50-261/82-28 on 820816-17 No noncompliance noted VERRELLI,D Division of Project & Resident Programs 82/08/25 JONES,J A Carolina Power & Light Co 2pp 14597 170 24X Fiche 50-261,82/08/25,8208300166
- --8208300167 IE 8afeguards Insp Rept 50-261/82-28 on 820816-17 No noncompliance noted Major areas inspected atte security operations during investigation of alleged drug usage by security personnel Details withheld (ref 10CFR73 21) HALL B L : MCGUIRE. D R Division of Project & Resident Programs 82/08/24 ip 14599 192 24X Ficha 30-261,82/08/25,8208300166
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analysing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R. A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- ~~8208270042 Forwards "Statistical Summary Rept for CY81," per 10CF820 407 STAKEY,R B Carolina Power & Light Co 82/03/01 BASSETT,H S Office of Management and Program Analysis 1p 14680,014 24X Fiche 50-000,82/07/13-8208270010
- --8208270044 "Statistical Summary Rept for CY81" * Carolina Power & Light Co 82/03/01 1p 14680-015 24X Ficha 30-000, 82/07/13, 8208270010

1

- --B20B27007B "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBI "

 NRC - No Detailed Affiliation Given 82/07/13 48pp
 4479 216 24% Fiche 50-000, 82/07/13,8208270010
- 8208130014 Forwards monthly operating rept for Jul 1982 STARKEY,R B Caroline Power & Light Co 82/08/09 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement Ip 14335 142 24X Fiche 50-261.82/08/09.8208130014
- --B208130014 Monthly operating rept for Jul 1982 NORRIB.H R Carcinia Fower & Light Co 82/08/02 3p 14335 143 24X Fiche 50-261.82/08/07,8208130014
- S Reportable accurrances, LERs & related correspondence
- 8208230456 Forwards LER 81~00B/03L-0 STARKEY,R B. Carolina Power & Light Co B1/03/27 O'REILLY,J P Region 2, Atlanta, Dffice of the Director (B1/03/01) 1p 14527 035 24X Fiche 50-261,B1/03/27.820B230456
- --8208230488 LER 81-008/03L-0 on 810225 while performing monthly periodic test CPL-PT-5 5. Hagan signal comparator module found inoperable Cause not stated Comparator replaced MCGIRT, R B Caroline Power & Light Co 81/03/27 Region 2, Atlanta, Office of the Director (81/03/01) 2pp 14329 036 24X Fiche 50-261.81/03/27 8208230450
- 8207050071 FOIA request for five documents re sys interaction in LWR, inadvertent containment spray for primary sys blowdown, biweekly rept for LER screening project & LER analysis & summary UDELL: A Critical Mass Energy Project 82/07/02 FELTON, J Division of Rules and Records 19 14559 261 24X Fiche 50-000, 82/07/02, 8207050071
- 8208250001 Responds to FOIA request for five separate documents reincidents at facilities. Documents available in PDR FELTON, J M Division of Rules and Records 82/07/26 UDELL, R A Critical Mass Energy Project ip 14959 262. 24X Fiche 50-000.82/07/26,8208250001
- --8103180387 Describes 810129 problems w/hydraulic pumps on turbine slectro-hydraulic control sys.Relief valve bellows has been replaced & 200-C valve has been tightened Continued operation is acceptable HODB, H W Events Evaluation Soction 81/02/12 JORDAN, E L Director's Office Spp 14559 281 24X Fiche 50-000, 82/07/26, 3206250001
- 8208050337 Forwards LER 82-006/01T-0 8TARKEY,R,B Carolina Power & Light Co 82/07/28 G'REILLY,J P Region 2, Office of Director 1p 14209 180 24X Fiche' 50-261.82/07/28.8208050357
- --8208050397 LER 82-006/01T-0 on 820715, motor cooler leak found in containment fan cooler HVH-2 HVH-2 shut down & svc water to unit isolated Caused by corrosion/prosion of cooler tubing Leak repaired & motor coolers will be replaced w/new units COX:HLT Caroline Power & Light Co 82/07/28 Region 2, Office of Director 2pp 14209 181 24X Fichs 50-261, 82/07/28, 8208050357
- 8208090172 Forwards LER 82-007/01T-0 STARKEY,R B Carolina Power & Light Co P 82/07/31 O'REILLY.J P Region 2, Office of Director 1p 14272 066 24X Fiche: 50-261.82/07/31,8208090172.
- --8208070174 LER 82-007/01T-0 on 820717, during plant heatup from refueling outage, primary to secondary leak in A steam generator confirmed Caused by defective well teaking welded plug removed & mechanical plug installed COX.H T Carolina Power & Light Co 82/07/31 Region 2, Office of Director 2pp 14272-067 24X Fiche, 50-261, 82/07/31, 820800172
- 8208200203 Forwards LER 82-008/03L-0 8TARKEY, R. B. Carolina Power & Light Co 82/08/09 D'REILLY, J.P., Region 2, Office of Director 1p. 14500, 132 24X Fithe 50-261, 82/08/09, 8208200203
- --8208200211 LER 82-008/03L-0.on 820710.summator NM-412C found inoperable during Periodic Test 5.1 Caused by summator failing to zero output. Bummator replaced COX.H.T Consumers Power Co. 82/08/09 Region 2. Office of Director, 2pp. 14800-133. 24X Fiche 50-261,82/08/09,8208200203
- 8209200110 Forwards LER 82-007/03L-0 STARKEY,R B. Carolina Power & Light Co 82/08/13 D'REILLY, J P. Region 2, Office of Director, 1p 14393 309 24X Fiche 50-261, 82/08/13, 8208200110

- --8208200123 LER 82-009/03L-O on 820715 & 27. motor operated valve RHR-759A, RHR HX discharge valve A failed to open Caused by improper setting of motor operator torque switch winsufficient lubrication of valve stem & packing COX.H T Carolina Power & Light Co 92/08/13 Region 2, Office of Director 3pp 14393 310 24X Fiche 50-261,82/08/13,8208200110
- 8208240241 PNO-II-82-094 on 820813,12 Burns Intl employees suspended from security staff for suspected drug use Investigation thus far has not implicated either licensee employees or NRC-licensed operators FERNY, C D , McQUIRE, D R Region 2, Office of Director 82/08/16 ip 14520 049 24% Fiche 50-261,82/08/16,8208240241
- 8208270244 Forwards LER 82-010/017-0 STARKEY,R B Carolina Power & Light Co 82/08/17 D'REILLY.J P Ragion 2, Office of Director 1p 14563,115 24X Fiche 50-261,82/08/17.8208270244
- --8208270249 LER B2-010/01T-0 on 820803, control rod drive mechanism for rod L-11 observed to have steam leaking from 1/4-inch vent valve at top Caused by vent valve being improperly torqued shut during repair in 1982 outage COX.H T Carolina Power & Light Co 82/08/17 Region 2, Office of Director 3pp 14563 116 24X Fiche 50-261,82/08/17. 8208270244
- 8208300275 Forwards updated LER 81-002/017-2 STARKEY.R B Carolina Power & Light Co 82/08/20 G'REILLY.J P. Region 2. Office of Director 1p 14673,009 24X Fiche 30-261.02/08/20.8208300275
- ~-B208300277 Updated LER 81-002/01T-2 on 810113, review of svc water sys revealed potential unmonitored release path on svc water return lines from containment for hydrogen vent header motor coolers Caused by design error Bys will be modified STARKEY, R B Carolina Power & Light Co. 82/08/20 Region 2, 0ffice of Director 2pp 14673 010 24X Fiche 50-261,82/08/20,8208300275
- DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR
- O Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-25.Part 3.Suppl 1. "Clarification of Flacement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/19. Michigan
- DOCKET 50-249 MONTICELLO NUCLEAR GENERATING PLANT
 F Security, medical, emergency & fire protection plans
- 8208030371 Charifies confusion during LANL/Science & Engineering Associates 820706-09 site visit re authority to take site data collected for vital area analysis & whether visit was officially sanctioned by NRC KEPPLERIJ 9 Region 3. Office of Director B2/07/27 MUSOLF,D M Northern States Power Co 1p 14154 002 24% Fiche 50-263, B2/07/27, B208030371
- --B208030374 Forwards draft ltr clarifying confusion during LANL 820706-09 sits visit to collect data for vital area analysis program. Concerns re releasing of data resolved Future visits will be endowed w/official imprimatur.

 BURNETT.R F Division of Safeguards 82/07/13 KEPPLER.J G Region 3, 0ffice of Director 2pp 14154 003 24X Fichs: 50-263,82/07/27,8208030371
- 9209060127 Releases public version of revised emergency response plan. FELTON, J. M. Division of Rules and Records 62/08/03 Document Hanagement Branch 1p 14244 063 24X Fiche 50-263,82/08/03, 82/08/0127
- --8208060129 Forwards public version of Revision 2 to emergency response plan
 LARSUN, C E Northern States Power Co 82/07/27 Region 3,
 Office of Director 1p 14244 066 24X Fiche. 50-263, 82/08/03,
 8208060127.
- --8208060130 Public version of Revision 2 to emergency response plan FEV.F L Northern States Power Co 82/07/13, 180pp 14244 067 24X Fiche, 50-263,82/08/03,8208060127

DOCKETED ITEMS

- 9208190081 Forwards "Final Rept on Monticello Nuclear Power Plant
 Full-Scale Joint Emergency Exercise 820302" State of MN &
 Wright & Sherburne Counties demonstrated adequate level of
 preparedness to protect public
 KRIMMAR W Federal Emergency Management Agency 82/08/05
 GRIMES, B Division of Emergency Preparedness 8pp 14386 182 24X
 Fiche 50-263, 82/08/05,8208190081
- --8208190084 "Final Rept on Monticello Nuclear Power Plant Full-Scale Joint Emergency Exercise, 820302 " + Federal Emergency Management Agency 82/04/12 53pp 14386 190 24% Fiche 50-243, 82/08/05,8208190081
- B20B2600B9 Releases public version of revised corporate emergency plan FELTON, J M Division of Rules and Records 82/08/13 Document Management Branch 1p 14576-196 24X Fische 50-000, 82/08/13, 820826.0069
- --8208260315 Forwards public version of Revision 5 to corporate nuclear emergency plan Updated info on App C items identified in NRC 820504 ltr encl LARSON.C E Northern States Power Co 82/08/02 Region 3, Office of Director. 4pp 14576 199 24X Fiche 50-000,82/08/13, 8208260889
- --8208260319 Public version of Revision 5 to corporate nuclear emergency plan HUDSON, Q., WARD, E., LARSON, C.E. Northern States Power Co 82/08/02 140pp 14576 203 24X Fiche 50-000, 82/08/13, 8208260089
- 8208260353 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/08/13 Documen Hanagement Branch 1p 14575 069. 24X Fiche 50-000,82/08/13,8208260383
- --8208260358 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1 1 2 re notifications & EPIP 1 1 5 re startup & operation of emergency operations facility WARD, E C Northern States Power Co 82/08/11 Region 3, Office of Director 1p 14575 072 24X Fiche 50-000, 82/08/13, 8208260353
- --B208260360 Public version of revised emergency plan implementing procedures including Procedures EPJF 1 1.2 re notifications & EPJF 1 1 5 re startup & operation of emergency operations facility

 Northern States Power Co. 82/08/11. 72pp 14575.073 24X Fiche 50-000.82/08/19.8208260353
- J Insurance & indemnity information
- 820B100092 Forwards Endorsements 62 & 63 to NELIA Policy NF-174 & Endorsements 51 & 52 to MAELU Policy MF-51
 JOHNSON, R 9 Northern States Power Co 82/08/05 DINITZ, I Antitrust & Economic analysis Branch (Utility Finance) 5pp 14297 348 24X Fiche, 50-263, 82/08/05, 8208100092
- Deerating license stage documents & correspondence
- 1207080064 Deneric ltr to all licensess of operating plants, applicants for DL & holders of CP re-Commission approved charter for CROR Sty list encl
 DIRCKS,W J. Office of the Executive Director for Operations
 82/07/02. Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche: 50-000.082/07/02.8207080064
- 208040029 Advises that shift technical advisor training program is acceptable per NUREO-0660 & NUREO-0737. Item I A I 1 Training of candidates w/o bachelor degrees acceptable in interim VASSALLO, D. B Gperating Reactors Branch 2 82/07/14 MUSOLF, D M Northern States Power Co 3pp. 14232 355 24X Fiche 50-263. 82/07/14, 8208040029
- 8208040084 Orants extension from 820701 to 830201 to implement requirements of NUREO-0654 Table 1-8. "Min Staffing Requirements for Nuclear Power Plant Emergencies." Util making good faith affort to comply as soon as possible, VASSALLO,D. Operating Reactors Branch 2. 82/07/16 MUSOLF,D M Northern States Fower Co. 3pp 14228 319 24X Fiche: 50-263, 82/07/16, 8208040084
- 8208020320 Revision 1 to 770501 application for amend to License DPR-22, changing radioactive effluent Tech Specs & revising offsite dose calculation manual for cement-sodium silicate sys Implementation of changes on 830101 requested, MUSOLF, D. Northern States Power Co. 82/07/23 Office of Nuclear Reactor Regulation, Director 1p 14150,185, 24x Fiche 50-263,82/07/23,8208020320

- --8208020323 Application for amend to License DPR-22, changing radioactive effluent Tech Specs & revising offsite dose calculation manual.
 NUSDLF,D M. Northern States Power Co. 82/07/23 3pp. 14150 186-24X Fiche 50-263,82/07/23.8208020320
- --8208020324 Proposed revised App A radioactive effluent Tech Specs * Northern States Power Co 82/07/23 77pp 14150 189 24x Fichs 50-263,82/07/23,8208020320
- --8208020330 Revision 2 to offsite dose calculation manual • Northern States Power Co 82/07/23 200pp 14150 263 24X Fiche 50-263,82/07/23,8208020320
- 620818024B Forwards safety evaluation of util B11231 & B20524 submittals on TMI Action Plan Items II F 1 4.II F 1 5 & II F 1 6.re containment pressure.uater level & hydrogen monitors, respectively NUREO-0737 requirements met VASSALLO.D B Operating Reactors Branch 2 82/07/28 MUSDLF, D M Northern States Power Co 10pp 14387 327 24X Fiche 50-263, 82/07/28, 8208180248
- 8208190006 Forwards revised version of model Tech Specs for electric power monitoring of reactor protection sys, encl in 811124 ltr VASBALLO, D B Operating Reactors Branch 2 82/07/28 MUSOLF, D M Northern States Power Co 2pp 14506 314 24X Fiche 30-283, 82/07/28, 8208190006
- --8208190008 Revised version of model Tech Specs for electric power monitoring of reactor protection sys * Office of Nuclear Reactor Regulation, Director 82/07/28 jp 14506 316 24% Fiche 50-263,82/07/28,8208190006
- 8208100067 Provides supplemental info for 820625 amend request to License DPR-22.in response to NRC questions re codes & inputs used in safety analysis for Cycle 10 MUSQLF.D Northern States Power Co 82/08/03 Office of Nuclear Reactor Regulation, Director 1p, 14276 182 24X Fiche 50-263,82/08/03.8208100067
- B20B230111 Requests verification of satisfaction of encl acceptance criteria re NUREO-0737. Item II K 3 22. "Automatic Switchover of Reactor Core Isolation Cooling Sys Suction " Response due in 30 days
 VASBALLO.D B Operating Reactors Branch 2 82/08/05 MUSOLF.D M
 Northern States Power Co 4pp 14517 355 24X
 Fiche 50-263.82708/05.8208230111
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP i applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EIBENHUT, D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194.
- 8208170247 Provides info re intentions concerning open items & commits to resolutions developed at 820415-16 meeting w/NRC & EG&G Resolutions will be incorporated into Revision 4 to ASME Code inservice testing program.

 MUSDLF-D M Northern States Power Co. 82/08/12 Office of Nuclear Reactor Regulation, Director 12pp 14369 354 24X Fiche 50-263,82/08/12,8208170247
- 8208260118 Forwards fee for 800515 license amend request.per NRC 82081 ltr Util will resubmit request for Tech Spec changes following issuance of proposed changes to 10CFRBO, App 0 MUSDLF.D Northern States Fower Co 82/08/17 D1095.R M. License Fee Menagement Branch 2pp 14556 276 24X Fiche 50-263.82/08/17.8208260118
- 8208300232 Provides supplemental info re 820625 license amend request to lower Cycle 9 ratio. 9E 820506 & 28 ltrs re extension of ECCS performance limits applicable MUSOLF. D Northern States Power Co. 82/08/24, Office of Nuclear Reactor Regulation. Director 1p 14679 141 24X Fiche: 50-263, 82/08/24, 8208300232
- Q Inspection reports, IE Bulletins & correspondence
- B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage, " Svc list encl.

 JURDAN.E L. Division of Engineering & Quality Assurance. 82/07/16

 Consolidated Edison Co of New York. 87pp 14356 274 24X

 Fiche: 50-000, 82/07/16, 8204210393

- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/19 Michigam. Univ of 112pp 14358 001 24X Fiche 50-000,82/07/17, 2010/10/208 JORDAN, E L Division Michigan, Univ of 8204210375
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Evc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Haxafluoride Overpacks" Svc list encl COBB, L 1 Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 820421039B IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Bvc list and] JURDAN.E.L. Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 143B0 115 24X Fiche 50-000, 82/07/23, 8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rad Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31. "Gyeresposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fichs.50-000.82/07/28.8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" 8vc list encl.
 JORDAN,E L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000, 82/08/05, 8204210407
- 8208230164 Forwards IE Insp Rept 50-263/82-08 on 820530-0703 No noncompliance noted. STREETER, J F Division of Project & Resident Programs 82/08/05 GILBERTS, D E Northern States Power Co 2pp 14514 314 24X Fiche. 50-263, 82/08/05, 8208230164
- --8208230176 IE Insp Rept 50-263/82-08 on 820530-0703 No montompliance CUBLAUI/O IE INSP MEPT DO-283/82-08 on 820530-0703 No noncomposted Major areas inspected licensee action on previous inspitems. operational safety verification. LER followup, IE infonctice followup & onsite review committee BROWN, C H · MADISON, A L · REYES, L A Division of Project & Resident Programs. 82/08/05 6pp. 14514 316 24X Fiche 50-263,82/08/05,8208230164
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A. Critical Mass Energy Project 8pp 14479 208 24X Fiche 50-000.82/07/13.8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81 " * NRC No Detailed Affiliation Given 82/07/13 48pp 14679: 216. 24X Fiche, 50-000, 82/07/13, 8208270010
- --B20B270644 Forwards "Number of Personnel & Man Rem by Work & Job Function for CYBI," per NUREQ-0737, Item II K 3 3 MAYER.L. D. Northern States Fower Co. B2/02/26. Region 3, Office of Director, ip, 14679-348 24X Ficher 50-000, 82/07/13, 820B270010.

- -8208270448 "Number of Personnel & Man Rem by Work & Job Function: for CY81" rur LYBL " * Northern Btates Power Ca 82/02/26 ip 14679 349 24% Fiche 80-000,82/07/13.8208270010
- 820B1300B2 Forwards monthly operating rept for Jul 1782 MUSGLF, D. Northern States Power Co. 62/08/10 Director Office of Inspection and Enforcement ip 14336 008 24X Fiche 50-263, 62/08/10, 820B130082 Director's Office,
- --8208130087 Monthly operating rept for Jul 1982 MYRABO, A L Northern States Power Co 82/08/02 4pp 14336:009 24% Fiche 50-264.82/08/10.8208130082

DOCKET 50-264 DOW CHEMICAL CO

- G Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice Bi-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp. 14358 001 24X Fiche 50-000, 82/07/19.

DOCKET 50-265 GUAD-CITIES STATION, UNIT 2

- F Security, medical, emergency & fire protection plans
- 8208040469 Releases public version of revised emergency plan implementing procedures.
 FELTON.J.M Division of Rules and Records. 82/07/23 Docum
 Management Branch ip 14220 289 24X Fiche 50-254.82/07/23,
- --B20B040475 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure GEP 330-3, "Offshift Augmentation Drill" & Revision 10 to GEB 530-0, "Exercises & Drills " Drill & Revision to to GEB 530-0, "Exercises & Drills " Receipt form and KDVACK, T J, GERNER, C. Commonwealth Edison Co. 82/06/21 DENTON, H R NRC - No Detailed Affiliation Given 1p 1: 24% Fiche 50-284, 82/07/23, 8208040449 14220 290
- --8208040481 Public version of Revision 2 to Emergency Plan Implementing Procedure GEP 530-3, "Opfshift Augmentation Drill" & Revision 10 to GEP 530-0, "Exercises & Dills " * Commonwealth Edison Co 62/06/21 3pp. 14220 291 24X Fiche 50-254,82/07/23,8208040469
- 8208200137 Forwards response to 820112 request re exercise objectives, scope of participation & scenario outline for Aug 1782 emergency plan exercise RAUSCH T J. Commonwealth Edison Co 82/08/02 KEPPLER.J G Region 30 Pfice of Director 7pp 14393 283 24X Fiche 50-254,82/08/02,8208200137
- 9208110230 Releases public version of revision to emergency plan resolved reseases pousic version or revision to emergency plan implementing procedure FELTON, J.M. Division of Rules and Records 82/08/05 Docum Management Branch Ip 14330 309 24X Fiche 50-254.82/08/05, 82/0810230
- --B20Bii0234 Forwards public version of Revision i2 to Emergency Plan Implementing Procedure GEF 330-0, "Assessment Actions " Receipt form enci KOVACK,T J., TIET.Q.C Commonwealth Edison Co 82/07/17 DENTON,H R NRC No Detailed Affiliation Given ip 14330 310, 24X Fiche 50-254,82/08/05,8208110230 14330 310
- --8208i10238 Public version of Revision 12 to Emergency Plan Implementing Procedure GEP 330-0, "Assessment Actions"
 Commonwealth Edison Co 82/07/17 2pp 14330 311. 24X Fiche 50-234,62/08/05,8208110230
- 8208300179 Forwards IE Bafeguards Insp Rept 50-265/82-14 on 820720-23. No noncompliance noted

 No LLER, J R Division of Engineering & Technical Programs 82/08/05, REED, C. Communuealth Edison Co 2pp 14599 219 24X
 Fiche 80-265, 82/08/05, 8208300179
- --B20B30D180 IE Bafeguards Insp Rept 50-265/82-14 on 820720-23 No noncompliance noted Major areas inspected facility organization & operations inventory & internal controls Details withheld (ref 10CFR2 790). FINLEY.A Q., CREED.U.R Region 3. Office of Director. 82/08/04 ip 14599 221 24X Fiche: 50-265, 92/08/05, 8208300179.

- 8208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
 FECTON J M Division of Rules and Records 82/08/12 Document
 - FELTON, J M Division of Rules and Records 82/08/12 Document Management Branch 1p 14559 354 24% Fiche 50-000,82/08/12,8208250559
- --8208260024 Forwards gublic version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures,"

 MDORE, R. D. Commanwealth Edison Co. 82/07/19 DENTON, H. R. NRC No Detailed Affiliation Given ip 14559.355 24X
 Fiche 50-000,82/08/12.8208250559
- --8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures" * Commonwealth Edison Co 82/04/30 7pp 14559 354 24x Fichs 50-000,82/08/12,8208250559.
- 820B230107 Forwards revised cable discrepancy lists re fire protection safe shutdown analyses Lists indicate how each discrepancy noted in fire protection associated circuit analysis & mod repts will be resolved RAUSCH.T J Commonwealth Edison Co 82/08/13 EISENHUT, D Q Bivision of Licensing 2pp. 24X Fiche S0-000.82/08/13.8208230107
- --8208230130 "Fire Protection Cable Discrepancy List, Quad Cities Unit 2 "
 * Commonwealth Edison Co 82/08/02 250pp. 14516 216 24X
 Fiche 50-000, 82/08/13, 8208230107
- 8208270523 Forwards IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722 & 23 No noncompliance noted PAPERIELLO, C. J. Division of Emergency Proparedness & Operational Support 82/08/13 REED, C. Commonwealth Edison Co. 2pp
- --8208270527 IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722-23 No noncompliance noted Major areas inspected; prompt public notification/warning sys PATTERSON, J.P. Division of Emergency Preparedness & Operational Support 82/08/13 5pp 14566.032 24X Fiche 50-254.82/08/13, 8208270523
- 8208230328 Ack receipt of B2080A ltr & 820812 telcon requesting that assembly & accountability portion of 820824 emergency exercise be conducted on 820819. Assembly & accountability should be conducted w/annual exercise PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/08/18 KALVINNAKIS.N Commonwealth Edison Co. 2pp 14508-260 24X Fiche: 50-254, 82/08/18, 8208230328.
- --B208230335 Requests NRC approval to conduct site assembly portion of B20824 emergency exercise as separate drill on B20819 Separate drill mould allow off to more affectively use manpower during exercise KALIVIANAKIS,N Commonwealth Edison Co 82/08/06 PAPERIELLO,C Division of Emergency Preparedness t Operational Support 2pp 14508 262 24X Fiche. 50-254, 82/08/18, 8208230328

O Adjudicatory correspondence

- 8208240267 Response to ASLB 820728 order Requests leave to withdraw application w/o prejudice. Need for transshipment in near-term reduced due to approval of installation of high density spent fuel racks. Certificate of 80% encl.

 8TEPTOE, P Commonwealth Edison Co 82/08/18. Atomic Safety and Licensing Board Panel. App. 14527 120. 24% Fiche 50-000.82/08/18, 8208240267.
- B20B240265 Response to ABLB 82072B order.NRC does not object to proceeding termination since licensee has mayed to withdraw license application w/o prejudice due to decision in Dresden high density storage rack case W/Certificate of Byc. WRICHTIN A. Hearing Branch 2 82/08/20. Atomic Safety and Licensing Board Panel 3pp 14527:126 24X Fiche: 50-000, 82/08/20, 8208240265
- P. Operating license stage documents & 'correspondence
- 8208060050 Forwards Amends 78 & 72 to Licenses DPR-29 & DPR-30, respectively, safety evaluation & notice of issuance & savailability Amends changs Tech Specs to extend operation to 820701 to allow completion of RHR svc water sys mods BEVAN.R B Operating Reactors Branch 2. 82/05/27. DELOGURGE, L. Commonwealth Edison Co. 2pp. 14282, 102. 24X Fichs 50-254, 82/05/27, 8208060050.

- --B208060060 Amends 78 & 72 to Licenses DPR-29 & DPR-30, respectively, changing Tech Specs to extend operation to B20701 to allow completion of mods to PHR svc water sys WASSALLO, D B Operating Reactors Branch 2 82/05/27 10pp 14282 104 24X Fiche 50-254.82/05/27,8208060050
- --8208060063 Bafety evaluation supporting Amends 78 t 72 to Licenses DPR-29 t DPR-30, respectively e Office of Nuclear Reactor Regulation, Director 82/05/27 2pp 14282 114 24x Fichs 50-254/82/05/27,8208060050
- --8208060064 Notice of issuance & availability of Amends 78 & 72 to Licenses DPR-29 & DPR-30, respectively VASBALLO, 0 B Operating Reactors Branch 2 82/05/27 2pp 14282 116 24X Fichs 50-234, 82/05/27, 8208060050
- B2070B0064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR. Svc list encl
 B10CKB, WJ Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194 003
 B24X Fiche 50-000, 82/07/02, 82070B0064
- 8208090024 Requests formal notification within 30 days if NRC understanding that util will meet stated positions of NNREO-0737. Item III D 3 3, "Improved In-Plant Indine Instrumentation Under Accident Conditions," is correct VABSALLO, D 8 Operating Reactors Branch 2 82/07/21 DELOGORGE, L Commonwealth Edison Co 2pp. 14283, 358 24X Fiche 50-254,82/07/21, 2000090024
- 8208050066 Advises that ESF reset controls comply w/NRC criteria.subj to IE confirmation NOVAN.Y M Assistant Director for Operating Reactors 82/07/28, JORDAN,E L Division of Engineering & Guality Assurance 1p. 14242 069 24X Fichs 50-254,82/07/28,8208050066
- ~-8208050080 Safety evaluation supporting plant compliance w/ESF reset controls per NRC criteria
 NRC No Detailed Affiliation Given 82/07/28 2pp, 14242 071 24X Fiche 50-294.82/07/28.8208050066.
- --8105210393 "Technical Evaluation of Licensee's Response to IE Bulletin 80-06 re Engineered Bafety Feature Reset Controls for Guad cities, Units 1 & 2 " KOUNTANIB, B . absolete code . FIN A-0250 EGG-1183-4212 81/05/30 Bpp 14242, 072 24X Fiche, 50-254, 82/07/28, 8208050066
- 8208180266 Forwards revised version of model Tech Specs for reactor protection mys/power monitoring sys design VA88ALLO,D D Operating Reactors Branch 2, 82/07/28 DELOEDRGE,L Commonwealth Edison Co Spp 14389 318 24X Fiche 50-000,82/07/28,8208180266.
- --8208180271 Revised model Tech Specs re electric power monitoring of reactor protection sys design * Operating Reactors Branch 2 82/07/28. ip 14389 321 24X Fiche 30-000.82/07/28.8208180266
- 8208110041 Forwards response to request to cross-ref info re environ quelification of safety-related equipment & TMI action plan equipment SHARTZ.E D Commonwealth Edison Co 82/08/02 EISENHUT, D Q Division of Licensing 500pp. 14313 001 24X Fiche 50-000, 82/08/02,8208110041
- 8208130046 Requests approval to delay implementation of commitments in response to Generic Ltr 82-05 re NUREO-0737, Item II.F.i 6, "Containment Hydrogen Monitor" Completion postponed until 840101 to accommodate schedule requirements SHARTZ.E D Commonwealth Edison Co. 82/08/05 EISENHUT.D.G Division of Licensing 2pp 14335 383, 24X Fichs 50-000,82/08/05,8208130046
- 8208240168 Requests add1 info, verifying satisfaction of encl acceptance criteria re NUREO-0737. Item II K. 3 22. "Automatic Switchover of Reactor Core Isolation Cooling Sys Suction " Response requested within 30 days VASBALLO.D.B Operating Reactors Branch 2 82/08/05 DELGEORGE, L. Commonwealth Edison Co. 4pp. 14548 181 24X Fiche 50-254, 82/08/05, 8208240168
- 820Bi1016B Forwards revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations." Revision 21 Revised pages correct typographical & other minor errors SWARTZ.E Commonwealth Edison Co 82/08/06 HAASS.W F. Quality Assurance Branch. Ip 14314 079 24X Ficher 50-000,82/08/06. 820Bi1018B

- --B20Bii0204 Revised pages to CE-1-A.Revision 21, "Comm Ed QA Program for Nuclear Generating Stations" & Commonwealth Edison Co B2/06/06 lipp 14314 080 24X Fiche 50-000.82/08/06.B20Bii0188
- 8208240040 Forwards Amends 81 & 75 to Licenses DPR-29 & DPR-30, respectively & notice of issuance & availability Amends authorize replacement of water quality requirements w/environ protection plan VA89ALLO, D R Operating Reactors Branch 2 82/08/06 DELGEORGE, L Commonwealth Edison Co 3pp 14529, 316 24X Fichs. 50-254, 82/08/06, 8208240040
- --B20B240046 Amends 81 % 75 to Licenses DPR-29 & DPR-30, respectively, replacing water quality requirements w/environ protection plan.
 VABBALLO, D 8 Operating Reactors Branch 2 82/08/06 18pp 14527 319 24X Fiche 50-254, 82/08/06.8208240040
- --B20B240090 Notice of issuance & availability of Amends 81 & 75 to Licenses DPR-29 & DPR-30, respectively VASBALLO, D B Operating Reactors Branch 2 B2/08/06 2pp 14529 337, 24X Fiche 50-254, 82/08/06, 8208240040,
- 8208090194 Ceneric Ltr 82-14 to all reactor licensess, holders of CP & applicants re-submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements by 11st secil EISENHUT.D 0 Division of Licensing 82/08/07 Consolidated Edison Co. of New York 1p 14356 332 24X Fichs 50-000,82/08/09,8208090194
- 820B170135 Responds to NRC B20721 request to provide notification if util intends to deviate from NUREG-0737. Item III D 3 3, "Improved In-Plant Iodine Instrumentation Under Accident Conditions "Both facilities comply w/requirement SWARTZ, E D, Commonwealth Edison Co 62/08/12 EISENHUT, D Q Division of Licensing. 2pp 14365 211 24X Fiche 50-000.82/08/12, 8208170135.
- B20B250455 Advises of satisfactory response to NUREQ-0737, Item II K. 3 24. "Adequacy of Space Cooling for HPCI & Reactor Core Isolation Cooling Sys " Safety evaluation encl VABBALLO,D B Operating Reactors Branch 2 82/08/13 DELOEDROE,L, Commonwealth Edison Co Spp 14962,283 24X Fiche 50-254,82/08/13,820B250455.
- 8208270250 Application for amend to License DPR-29, proposing Tech Spec changes to implement 10CFR50, 59 reload licensing w/DDYN transient analyses & extended exposure MAPLHOR limits Bignificant changes discussed Class III amend fee enci RAUBCH, T J Commonwealth Edison Co 82/08/19 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 14564 001 24X Fiche. 50-000, 82/08/19, 8208270250
- --8208270273 Errata & Addenda Sheet 7, replacing Pages 4-11 & 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Guad Cities 1 & 2 Nuclear Power Stations."

 # Qeneral Electric Co & NEOD-24246A ERR 07 82/07/31 5pp 14564:026. 24X Fiche 50-000,82/08/19,8208270250
- 8208270296 Informs that analysis to determine appropriate equipment qualification temp profiles will be submitted in Sept 1982, not Jul 1982, as previously indicated. RAUBCH, T J Commonwealth Edison Co 82/08/23 VABSALLO, D Bivision of Licensing 1p. 14564 177 24X Fiche 50-000,82/08/23, 2000270324
- 8208310402 Submits supplemental response to Constit Ltr 82-05 rs MVREQ-0737, Item II F 1 3, "Containment High-Range Rediation Monitor " Requests delay of implementation until 821030 due to delivery problems.

 SWARTZ, E D Commonwealth Edison Co 82/08/27 EISENHUT, D 0.
 Division of Licensing. ip 14674 308 24X Fichs 50-254,82/08/27,8208310402.
- a Inspection reports. IE Bullatins & correspondence
- 8208050414 Forwards IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-275/81-31 & 50-304/81-29 on 810813-820503 No noncompliance noted KEPPLER.J. 0. Region 3, Office of Director 82/07/12 REED, C Commonwealth Edison Co ip 14217:166 24X Fiche, 50-000, 82/07/12, 8208050414,
- --B208030441 IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 on 810813-820503 No noncompliance noted Major areas inspected allegations recum Ed operation of facilities & compliance w/10CFR21. HAYES, D.W.: BRAUND, C : TONGUE, T. Division of Project & Resident Programs, B2/07/09 i55pp i4217 i69, 24X Fiche. 50-000, B2/07/12, B208050414

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14336 274 24X Fiche 80-000
- 8204210395 IE Info Notice 81-26, Part 3, Suppl i. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, EL Division of Engineering & Guality Assurance, 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395
- 8208050424 Forwards IE Insp Repts 50-254/82-08 & 50-245/82-09 on 820428-0629 & notice of violation SPESBARD, R L Division of Project & Resident Programs 82/07/19 REED. C Commonwealth Edison Co. 2pp. 14214 076 24X Fichs 50-254, 82/07/19, 8208050424
- --8208050435 IR Insp Repts 50-254/82-08 & 50-265/82-09 on 820428-0629 Noncompliance noted failure to perform required testing after maint on safety-related equipment & failure to provide condensate flood protection CHRISGOTINGS, N. DUPONT. S. G. WALKER, R. D. Division of Project & Resident Programs 82/07/11 15pp 14214 080 24% Fiche 50-254,82/07/19.8208050424
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svr list encl JORDAN.E L Division of Engineering & Guality Assurance. 82/07/20, Consolidated Edison Co of New York 112pp 14381-001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 consolidated Edison Co of New York 7ipp 14397-274 24X Fiche,50~000,82/07/20,8204210397
- 8204210398 IE lnfo Notice 82-24. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 62/07/22 Consolidated Edison Co of New York 112pp 14194-321 24X Fiche 50-000.82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Svc list antl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co. of New York. 122pp 14380-115 24x Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Cantrol Rod Drive (CRD) Quide Tube Support Pin Failures at Mestinghouse PMRs," Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co of New York 127pp 14174*120 24X Fiche 50-000, 82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl.

 JORDAN: E. Division of Engineering & Quality Assurance 82/07/26

 Consolidated Edison Co of New York 121pp. 14397 013 24X

 Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28, Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " Svc list entl JOROAN, E. L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York, 117pp. 14388 201 24X Fiche: 50-000, 82/08/05, 8204210407.
- 8208300179 Forwards IE Bafeguards Insp Rept 50-265/82-14 on 820720-23, No noncompliance noted MILLERJR Division of Engineering & Technical Programs 82/08/05, REED, C Commonwealth Edison Co 2pp. 14599 219 24X Fichs 50-265,82/08/05,8208300179
- --8208300180 IE Safeguards Insp Rept 50-265/82-14 on 820720-23 No noncompliance noted Major areas inspected facility organization & operations inventory & internal controls Details withheld (ref 10CFR2, 790) FINLEY, A G, CREED, J R. Region 3, Office of Director 82/08/04. (p. 14599 221 24% Fiche, 50-265, 82/08/05, 8208300179

- 8208270523 Forwards IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722 & 23 No noncompliance noted PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/08/13 REED,C Commonwealth Edison Co 2pp 14566 030 24X Fiche 50-254.82/08/13,8208270523
- --8208270527 IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722-23 No noncompliance moted Major areas inspected prompt public notification/warning sys PATTERSON.J.P., AXELSON.H.L. Division of Emergency Preparadness & Operational Support 82/08/13 5pp 14564 032 24X Fiche 50-254,82/08/13,8208270523
- 8208310336 Forwards IE Insp Repts 50~254/82-13 & 50~265/82-15 on 8200719-23,27 & 0806 No noncompliance noted. PAPERIELLO,C. J Division of Emergency Preparedness & Operational Support 82/08/17 REED.C Commonwealth Edison Co 2pp 14692-135 24X Fiche: 50~254,82/08/17,8208310336
- --8208310351 IE Insp Repts 50-254/82-13 & 50-265/82-15 on 820789-23,27 & 0806 No noncompliance noted Major areas inspected confirmatory program & associated GC procedures NICHOLSON,N A, ROZAK,S, 8CHUMACHER,M C Division of Emergency Freparedness & Operational Support 82/08/17 8pp 14692 137 24% Fiche 50-254,82/08/17,8208310336
- R. Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyting seid info. Forwards documents listed in App A FELTON.J M. Division of Rules and Records. 82/07/13 UDELL,R A Critical Mass Energy Project 8pp 14679, 208 24% Fiche. 30-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY91" 4 NRC No Detailed Affiliation Given. 82/07/13 48pp 14479:216 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270263 Forwards "1981 Rept of Occupational Personnel Radiation Doses."

 KALIVIANAKIS, N. Commonweelth Edison Co. 82/02/17 KEPPLER, J. O. Region 3, Office of Director 1p. 14679 300 24X Fiche, 50-000, 82/07/13, 8208270010
- --8209270268 "1981 Rept of Occupational Personnel Radiation Doses "
 * Commonwealth Edison Co 82/02/17 3pp 14679 301. 24X Fiche: 50-000, 82/07/13, 8208270010.
- --B20B270559 Forwards "Recorded Annual Whole Body External Exposure for CYB1:" per 10CFR20 407(b) W/o Guad Cities, Zion, LaBalle, Byron & Braidwood rapts RAUSCH, T J Commonwealth Edison Co B2/03/31. Office of Management and Program Analysis. ip. 14680 075 24% Fiche 50-000, 82/07/13, 8208270010
- 8208160116 Forwards changes, tests & experiments completed during Juj 1982. KALIVIANAKIS, N., Commonwealth Edison Co. 82/08/02. CASS, E. G. Office of Nuclear Reactor Regulation, Director. App. 14349: 295 24X Fiche: 50-254, 82/08/02, 8208160116
- 8208160374 Forwards manthly operating repts for Jul 1982 KALIVIANAKIS M. Commonwealth Edison Co 82/08/02 Director's Office, Office of Inspection and Enforcement. 1p 14348, 320 24) Fiche 50-234, 82/08/02, 8208160374
- --8208160381 Monthly granting repts for Jul 1982 MEINFURIER, E., BUSS, R. Gommonwealth Edison Co. 82/08/03. 27pp 14348-321. 24X Fiche 50-254.82/08/02.8208160374
- 8 Reportable occurrences, LERs & related correspondence
- 8208050290 Forwards LER 82-007/03L-0. KALIVIANAKIS,N Commonwealth Edison Co. 82/07/19. KEPPLER, J Region 3. Office of Director 1p. 14210.215 24X Fichs: 90-265,82/07/19. 8208050290
- ---B208050304 LER B2-007/03L-0. on 820622, electrometic relief valve 2-203-3C failed to open on menual open signal Caused by valve plug compression rings binding in plug sleeve groove. Valve replaced Specs for alseves modified.

 WEINFURTER, E. Commonwealth Edison Co B2/07/17. Region 3, Office of Director 3pp. 14210:216 24X Fiche 50-265,82/07/19,8208030290

- 8208090246 Forwards LER 82-011/01T-0 KALIVIANAKIS N Commonwealth Edison Co 82/07/28 KEPPLER, J Region 3, Office of Director ip 14271 048 24X Fichs 50-265, 82/07/28, 8208090246
- --8208090255 LER 82-0i1/01T-0 on 820715, LPCI inboard injection valve MO-2-1001-278 faifed to open Caused by detached electrical lead on torque switch of valve motor operator Inboard valve manually opened & torque switch replaced BUSS, R Commonwealth Edison Co 82/07/28 Region 3, Office of Birector 3pp 19271 049 24X Fiche 50-265, 82/07/28, 8208090246
- 8208130222 Forwards LER 82-012/03L-0 KALIVIANAKIS Commonwealth Edison Co 82/08/02 KEPPLER, J Region 3. Office of Director 1p 14333,184 24X Fiche 50-265,82/08/02. 8208130222
- --8208130227 LER 82-012/03L-0 on 820714.controllers for valves 2-203-3A, 3B, 3C & 3E found to trip at pressures in excess of specified Tech Spec limits Caused by improper calibr of pressure switches REED, H Commonwealth Edison Co. 82/08/02 Region 3, Office of Director 2pp 14933 185 24X Fiche 50-263,82/08/02,8208130222
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8208040283 Releases public version of revised emergency plan implementing procedures. FELTON: J M Division of Rules and Records 92/07/20 Ducument Management Branch ip 14231 001 24X Fiche 50-266,82/07/20, 8208040283
- ---B208040288 Forwards public version of revised emergency plan implementing procedures, including Procedures EP 1 3 reset to the procedures of the procedures of the extension of the procedures of the entry of the
- ~-8208040293 Public version of revised emergency plan implementing procedures, including Procedures EP 1,3 re estimation of source term, EPIP 3 i re altert immediate actions & EPIP 4 i re site emergency immediate actions & EPIP 8 if the emergency immediate actions will be site emergency immediate actions will be site
- 8208190188 Forwards revisions to security force training & qualification plan as requested in 820715 ltr Revision withheld (ref 100FR2 790)
 BURSTEIN, 8 Historian Electric Power Cd 82/08/06 GLARK, R A Operating Reactors Branch 3 ip 14387 048 24X
 Fiche, 50-266, 82/08/06, 8208190188
- B208190224 Advises that scheduling conflicts & reluctance of State of Wi to participate in annual emergency exercise during Summer 1983, support util 820630 request for exemption from 10CFR App E. Exercise scheduled for 830920 FAY.C H Wisconsin Electric Power Co 82/08/09, DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 14387 177 24X Fiths 50-266, 82/08/09, 8208150224
- 8208260831 Ack receipt of 820715 ltr re emergency operations facility. Daviations from physical proximity guidelines to plant site must be approved by NRC.

 COLBURN, T Q Operating Reactors Branch 3 82/08/11 FAY, C W Hisconsin Electric Power Co 2pp 14572 337 24X Fiche 50-266, 82/08/11 8208260531
- 8208260054 Releases public version of emergency plan manual FELTON.J M Division of Rules and Records. 82/08/13. Document Management Branch 1p. 14574-078 24X Fiche 50-266,82/08/13.
- --8208260059 Forwards public version of amergency plan manual, including revisions to Procedures EP 2 O re emergency plan definitions (EP 4 O re emergency conditions & EP 6.0 re emergency measures.

 BURSTEIN, S Wisconsin Electric Power Co 82/08/02 DENTON, M R Office of Nuclear Reactor Regulation, Director CLARK, R A. Operating Reactors Branch 3 Spp 14574, 079 24X Fiche, 50-266, 82/08/13, 8208260054
- --8208260067 Public version of emergency plan manual, including revisions to Procedures EP 2 O me emergency plan definitions. EP 4 O me emergency conditions & EP 6. O me emergency measures Wisconsin Electric Power Co 82/07/30 250pp 14574 084 24X Fiche: 50-256, 82/08/10, 8208260054.

@ Adjudicatory correspondence

- 8208110180 Responds to ASLB 811013 memorandum & order re removal of explosive or mechanical plugs from tubes prior to sleeving Supporting documentation & DK Porter affidavit encl CHURCHILL.8 H., RIDGWAY, D.A. Wisconsin Electric Power Co CHURCHILL.8 H. Shaw. Pittman, Potts & Trowbridge 81/10/16 30pp 14314 141 24X Fiche 50-266,81/10/16.8208110180
- 820B100031 Advises that NRC will not respond to licensee 820722 motion to conduct discovery of WI Environ Decade re Decade contacts w/sleeving demonstration program workers BACHMANN, R O Hearing Branch 1 82/08/06 BLOCH, P R , PAXTON, H C , KLINE, J R Atomic Safety and Licensing Board Panel 1p 14296 274 24X Fiche 50-266,82/08/06,8208100031
- 8208100076 Response to interrogatories re safety avaluation on full-scale sleeving Certificate of Svc encl BACHMANN.R G Hearing Branch i 82/08/06 Wisconsin's Environmental Decade 17pp. 14296 157 24X Fiche 50-266.82/08/05.8208100076
- 8208270315 Forwards licensee response to WI Environ Decade motion re litigable issues & WD Fletcher statement Proprietary versions served on NRC & Decade Nonproprietary version served on remainder of svc list CHURCHILL, B Shaw, Pittman, Potts & Trowbridge CHURCHILL, B Wisconsin Electric Power Co. 82/08/09 BLOCH, PB, KLINE, JR, PAXTON, H C Atomic Safety and Licensing Board Panel 2pp 14563 207 24X Fiche 50-266,82/08/09,8208270315
- --8208270319 Response to WI Environ Decade 820720-21 motion concerning litigable issues Decade estopped from relating number of proposed contentions. Decade fails to justify untimeliness Some proposed issues irrelevant CHURCHILL, B. W. Wisconsin Electric Power Co. CHURCHILL, B. W. Pittman, Potts & Trowbridge 82/08/09 Atomic Safety and Licensing Board Panel 71pp 14563 209 24X Fichs 50-266,82/08/09,8208270315
- --B208270323 Testimony of MD Fletcher re issues raised in Contentions [,2,3(a)-(e),4 & 5 in WI Environ Decade B20721 motion cancerning litigable issues Prof qualifications & Certificate of Bvc encl FLETCHER, W D. Wisconsin Electric Power Co. FLETCHER, W D. Wastinghouse Electric Corp. B2/08/04. 30pp. 14563-280 24X Fiche 30-266,82/08/09,8208270315
- S20B120009 Forwards PQ Easley affidavit of preparation of response to MI Environ Decade Interrogatory 2 Affiant not available to sign affidavit in time to meet 820B06 filing deadline BACHMANN.R 0 Hearing Branch 1 B2/OB/10 RLOCH,P.R , PAXTON,H C , MLINE,J R Atomic Safety and Licensing Board Panel 2pp 14323-337 24X Fiche 50-246,82/OB/10.820B120009
- B20Big0i19 Petition for leave to intervene in steam generator replacement proceeding & petition for hearing WI Environ Dacade has recognized life, property & financial interests Cartificate of Svc anci ANDERSON, P Wisconsin's Environmental Decade 82/08/10 Commissioners 3pp. 14327 031 24X Fiche 50-266.82/08/10,
- 8208160446 Responds to 820706 notice of proposed issuance of amend to facility OL re plans to replace two steam generators Licensee apposes Commission determination to provide notice of apportunity for hearing on generator replacement BURSTEIN, 8 P Wisconsin Electric Power Co. 82/08/10. Dacketing & Services Branch 2pp 14348 253 24X Fiche 50-266,82/08/10, 8208160446
- 8208160219 Informs of 820809 telcon w/PR Bloch re Nucleonics Wk 820805 article, "Utils Given NRC Laundry List of Steam Generator Proposals," Author informed Bloch on 820810 that NRC will not provide info on article due to preliminary nature 9ACHMANNR 0 Hearing Branch 1 82/08/12 8LGCH,P R, KLINE, J.R, PAXTON, H C Atomic Safety and Licensing Board Panel. 5pp. 14342.330 24X Fichs.50-266,82/08/12,8208160219
- 820Bi8011B Response to WI Environ Decade B20721 motion concerning litigable issues. Contentions 1-5 & alternative contention on interrelationship withermal shock Only Contentions 3(a) & 3(b) edmissible Notice of appearance encl BACHHANN, R 0, MCOURREN, H. J. Hearing Branch 1. 82/08/16 Atomic Bafety and Licensing Board Panel 36pp 14378'203. 24X Fiche. 50-266, 82/08/16, 8208180118.
- --8208180123 Statement of mati fact as to which there is no ganuing issue BACHMANN,R O. Hearing Branch 1 82/08/16. Atomic Gafety and Licensing Board Panel. 14pp. 14378; 237 24X Fiche 50-266,82/08/16.8208180118.

- --8208180127 Affidavit of TO Colburn re WI Environ Decade 820721 motion concerning litigable issues. Contentions 1.2a, 2c, 3b, 3c, 4 5 COLBURN, T Q Operating Reactors Branch 3 82/08/16 10pp 14378 253 24X Fiche 50-266, 82/08/16, 8208180118
- --B208180131 Affidavit of PO Easley re WI Environ Decade 820721 motion concerning litigable issues.Contention 2(a)
 EASLEY.P O Accident Evaluation Branch 82/08/16 2pp
 14378 243 24X Fiche 50-266.82/08/16.8208180118
- --8208180134 Affidavit of EL Murphy re HI Environ Decade 820721 motion concerning litigible issues, Contentions 3(a), 3(d) & 3(e) Certificate of Svc encl.
 MURPHY.E L. Materials Engineering Branch 82/08/12 10pp 14378 265 24X Fiche 50-266, 82/09/16,8208180118
- 8208200087 Notice of ASLD constitution PB Bloch chairman & HC Parton k JR Kline, members COTTER, B. P. Atomic Safety and Licensing Board Panel 2pp 14393 251 24X Fiche 50-266.82/08/18,8208200087
- B20B200293 Confirms licensee understanding w/WI Environ Decade re time for filing Decade amend to Decade mation concerning litigable issues Licensee provided disputed documents to Decade on B20B1B Amend to motion due B20B20 Syc list encl CHURCHILL.B W Shaw Pittman, Potts & Trombridge. CHURCHILL.B.W Hisconsin Electric Power Co. 82/08/18 BLOCH.P.B.. WLINE.J.R., PAKTON.H C Atomic Gafety and Licensing Board Panel 3pp 14398 326 24% Fiche 50-266.82/08/18.8208200293
- 9208240409 Memorandum ordering all filings in proceeding about replacement of tube bundles to be designated 50-266-0LA2
 Designation necessary due to two separate OLA proceedings
 BLOCH, P B Atomic Safety and Licensing Board Panel 82/0B/20 ip. 14522 350 24% Fiche 50-266.82/08/20.8208240409.
- 8208270448 Amend to motion re third litigable issue on increased probability of tube failures due to sleeving per ABLB direction during 820601 conference Change adds Contention F on sleeves in corroded tubes. WCertificate of 80c ANDERSON. P. Wisconsin's Environmental Decade 82/08/20 Atomic 82fety and Licensing Board Fanel 3pp. 14565-253 24x Fiche: 50-266, 62/08/20, 8208270448
- 8208270411 Answer opposing HI Environ Decade 820810 petition to intervene & request for hearing Standing not demonstrated & aspects as to which intervention sought not specified.

 Nobices of appearance & Certificate of Syc encl
 RIDGHAY, D. A. Hisconsin Electric Power Co. RIDGHAY, D. A. Shaw,
 Pittman. Potts & Trowbridge, 82/08/24 Atomic Safety and
 Licensing Board Panel 25pp 14565 193 24% Fiche 50-266,82/08/24,
 8208270411
- B20B2704B6 Response to MI Environ Decade B20721 amend to motion relitigable issues Proposed Contention 3(f) fails to estisfy requirements for establishing litigable lawer Motion should be rejected Certificate of Svc encl RIDOMAY.D.A Wisconsin Electric Power Co RIDOMAY.D.A Shaw, Pittens, Potts & Troubridge 82/08/24 Atomic Safety and Licensing Board Panel 12pp 14565 061 24X Fiche: 50-266.82/08/24, 8208270484
- 8208270503 Correction to 820824 Certificate of Byc re licensee answer to WI Environ Decade petition to intervene & petition for hearing Copies hand delivered on 820825 RIDOMAY, D.A. Wisconsin Electric Power Co. 82/08/25, 2pp 14563 361 24K Fiche: 50-266, 82/08/25, 8208270503
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR SVc list encl
 BIRCKB.H. J Office of the Executive Director for Operations
 82/07/02. Consolidated Edison Co. of New York. 93pp. 14194-001
 24X Fichs 50-000-82/07/02,8207080064
- 8208040650 Ack receipt of 820622 ltr stating objections re replacement of steam generator major components Licensee 820527 ltr considered application for amend COLBURN. TO Operating Reactors Branch 3. 82/07/22 ANDERSON, P. Wisconsin's Environmental Decade 2pp. 14224.060 24% Fichs 50-266.82/07/22.8208040650
- 8208130128 Forwards Amends 62 & 67 to Licenses DPR-24 & DPR-27, respectively & notice of issuance & availability. Amend changes Tech Specs to modify limiting conditions for operation re auxiliary feedwater pump operation CDLBURN, T. 0. Operating Reactors Branch 3 82/07/27, FAY, C. W. Wisconsin Electric Power Co 5pp 14350 001. 24X Fiche: 50-266, 62/07/27, 8208130128

- --B208130132 Amends 62 & 67 to Licenses DFR-24 & DFR-27, respectively.
 changing Tech Specs to modify limiting conditions for operation re auxiliary feedwater pump operation
 CLARK, R A Grerating Reactors Branch 3 B2/07/27 Bpp
 14350 005 24X Fichø 50-266,82/07/27,8208130128
- --8208130135 Notice of issuance & availability of Amends 62 & 67 to Licenses DPR-24 & DPR-27, respectively CLARK, R A Operating Reactors Branch 3 82/07/27 ip 14350 013 24X Fiche 50-266,82/07/27,8208130128
- 8208030440 Forwards response to NRC 820619 request for add1 info re proposed reactor vessel water level instrumentation sys required by NUREQ-0737, Item II F 2 FAY. CW Wisconsin Electric Power Co 82/07/28 DENTON, H R Office of Nuclear Reactor Regulation. Director CLARK, R A Operating Reactors Branch 3 28pp 14154 019 24X Fichs 50-266, 82/07/28, 8208030440
- 8208040140 Forwards proprietary Figure 6.2.7-2. "Alternating Stresses at Location of Max Fatique Usage" & revised Page 6.85 to KCAP-9760. "Point Beach Nuclear Plant Steam Generator Sleeving Rept "Proprietary info withheld (ref 10CFR2 790) FAY, C.W. Wisconsin Electric Power Co. 82/07/28 DENTON. H.R. Office of Nuclear Reactor Regulation, Director CLARK. R.A. Operating Reactors Branch 3. 2pp. 14189 301 24X Fische 50-266. 82/07/28. 8208040140
- ~-8208040145 Submits application for withholding supplemental info to WCAP-9960, "Point Beach Nuclear Plant Steam Generator Siseving Rept " Affidavit (AM-80-53) enc! HIESEMANN.R A Westinghouse Electric Corp 82/07/15 DENTON.H R Office of Nuclear Reactor Regulation, Director Spp. 14189 303 24X Fiche 90-266.82/07/28.8288040140
- 8208100084 Forwards add! info re generation of temp/pressure profiles for typical high energy line breaks outside containment in response to 820701 request Info based on analysis performed by Bechtel Power Corp in 1973
 BURSTEIN.S Wisconsin Electric Power Co 82/08/03 DENTON, N R Office of Nuclear Reactor Regulation. Director CLARK, R A Operating Reactors Branch 3 5pp 14294 136 24X
 Fiche 50-266,82/08/05,8208100084
- 8208090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter J requirements & provides alternatives to requirements Svc list enc! EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York. 1p 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- 8208130109 Submits add1 response to NUREG-0737. Item 11 D i re block valves Marshall test data indicates that installed valves will function properly over range of operating & accident conditions

 FAY, C W Hisconsin Electric Fower Co 82/08/09 DENION, H R Office of Nuclear Reactor Regulation, Director 2pp 14333 272 24X Fiche 50-266, 82/08/09, 8208130109
- 8208130130 Advises that info addressing criteria of NUREO-0737, Item 11 8 3, "Post-Accident Sampling Sys," will be provided by 820930 FAY.C W Wisconsin Electric Power Co 82/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 lp 14336 018, 24X Fiche 50-266, 82/08/07, 8208130130
- 8208160446 Responds to 820706 notice of proposed issuance of smend to facility OL me plans to replace two steam generators. Licensee opposes Commission determination to provide notice of opportunity for hearing on generator replacement BURBTEIN-S P Wisconsin Electric Power Co 82/08/10 Docketing & Services Branch 2pp. 14348 253 24% Fishe 50-266,82/08/10,8208160446
- 8208170268 Discusses plans & Tech Spec changes for compliance w/requirements of IOCFR50 App J.per 820625 ltr Full compliance re plant design mode to containment spray sys will be achieved by Mar 1983 FAY.C W Misconsin Electric Power Co 82/08/13 DENTON, H R Office of Nuclear Reactors Regulation. Director 4pp 14367 270 24X Fiche 50-266,82/08/13,8208170268
- O Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Bleam Isolation Valve (MSIV) Leakage "Svr list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/16, Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000

- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc I st enc!

 JORDAN, EL Division of Engineering & Guality Assurance 82/07/19

 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list enci JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 30-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacts " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 consolidated Edison Co of New York 71pp 14357 27& 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion Hhile Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 82042(0402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 (20 24X Fiche 50-000,82/07/23,8204210402
- 9204210403 IE Info Notice 92-30, "Loss of Thermal Sleeves in RCS Piping at Cartain Westinghouse PWR Power Plants" Syc list encl JORDAN.E L. Division of Engineering & Guality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24% Fichs 50-000,82/07/26,8204210403
- 8208020273 Responds to request for add1 info re sleeving process insp Sampling insp of 10% of upper & lower sleeve joints will be made Insp will be expanded if unacceptable measurements are noted FAY.C W Hisconsin Electric Pawer Co 82/07/26 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 14152,273 24% Fiche 50-266.82/07/26,8208020273
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357:146 24X Fiche 50-000,82/07/28.8204210405
- 8208030472 Responds to IE Bulletin 79-14 re as-built, safety-related piping sys Ninety-eight isometric drawings revised to incorporate mechanical corrections & represent as-built piping Remaining isometrics will be completed by 821231 FAY.C W Wisconsin Electric Power Co 82/07/28 KEPPLER.J 9 Region 3, Office of Director 2pp 14154 090, 24% Fiche 50-246,82/07/28,8208030472
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." 8vc list encl
 JORDAN.E L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co. of New York 117pp 14388 201 24X
 Fiche.50-000.82/08/05.8204210407
- 8208200151 Submits response to 1E Bulletin 82-02 re incidents of severe degradation of threaded fasteners in closures of RCPB of PWR plants
 FAY.G.W Wisconsin Electric Power Co 82/08/11 KEPPLER.J 0
 Region 3. Office of Director. 10pp 14393 269 24X
 Fiche 50-266,82/08/11,8208200151
- 8208240365 Ack receipt of 820730 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-01 & 50-301/82-01.

 SPESSARD, R L Division of Project & Resident Programs 82/08/16, BURSTEIN, B Wisconsin Electric Power Co, 1p 14520 171 24X Fiche 50-266, 82/08/16, 8208240365
- --8208240370 Responds to NRC 820621 ltr reviolations noted in 1E Insp Repts 50-266/82-01 & 50-301/82-01 Corrective actions in-house procedure revised re personnel responsibilities & in-house chemistry procedure issued.

 BURSTEIN, 8, Wisconsin Electric Power Co 82/07/30, KEPPLER, J Q Region 5, Office of Director 5pp 14520 172 24X Fichs 50-266.82/08/16.8208240365

- B20B260240 Requests NRC approval of encl inservice inspirelief requests for second i0-ur insp Approval of Tech Spec Change Request 42 necessary for adoption of ASME Section XI as governing document for inservice inspirate insp
- 8208310165 Ack receipt of 820813 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~266/82-10 & 50~301/82-09 SPESSARD, R L Division of Project & Resident Programs 82/08/24 BURSTEIN, S 41sconsin Electric Power Co 1p 14693 185 24X F1che 50-266, 82/08/24, 8208310165
- --B20B3i0171 Responds to NRC B20716 ltr re violations noted in IE Insp Repts 50-266/B2-10 & 50-301/B2-09 Corrective actions minor adjustment to door closer made Fire doors for safe shutdown equipment have been identified & labelled FAY, C.W. Hisconsin Electric Power Co. B2/08/13 KEPPLER, J.G. Region 3, Office of Director 2pp 14693 186 24X Fiche, 50-266, 82/09/24, 8208310165
- R Periodic operating reports & related correspondence
- 82Q8270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL.R A. Critical Mass Energy Project 8pp 14677 208, 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYG1"

 * NRC No Detailed Affiliation Given 82/07/13 48pp 14679 216. 24X Fiche 50-000,82/07/13.8208270010
- --8208270877 Forwards "Rept on Personnel Exposure & Monitoring for CY81," per 10CFR20 407
 FAY.C W. Misconsin Electric Power Co 82/02/22 Office of Management and Program Analysis 19 14679 318 24X
 Fichs 50-000.82/07/13,8208270010
- --8208270581 "Rept on Personnel Exposure & Monitoring for CY81 "

 # Hisconsin Cleatric Pawer Co 82/02/22 ip 14679 319 24X

 Fiche 50-000,82/07/13,8208270010
- 8208160041 Forwards monthly operating repts for Jul 1982 FAY, C W Wisconsin Electric Power Co 82/08/10 NRC - No Detailed Affiliation Olven 1p 14344 220 24X Fiche: 30-266.02/08/10.8208160041
- --8208160043 Monthly operating repts for Jul 1982 FAY, C W. Wisconsin Electric Power Co 82/08/06 8pp 14344 221 24X Fichs 50-266.82/08/10,8208160041
- S Reportable occurrences, LERs & related correspondence
- 8208020109 Forwards LER 82-012/03L-0 BURBTEIN B Wisconsin Electric Power Co. 82/07/21 KEPPLER.J 9 Region 3. Office of Director 1p 14142 112. 24X Fiths 50-266.82/07/21.8208020109.
- --8208020115 LER 82-012/03L-0 on 820621, during annual diesel insperence of tiesel generator 3D output breaker failed to close Caused by broken latch check switch Buitch replaced FAY.C.W Wisconsin Electric Power Co 82/07/21 Region 3, Office of Director 2pp 14142 113 24X Fiche 50-266,82/07/21,8208020109
- T Hearing transcripts on non-antitrust matters
- 8208270315 Forwards licensee response to WI Environ Decade motion re litigable issues & WD Fletcher statement Proprietary versions served on NRC & Decade Nonproprietary version served on remainder of evc list CMURCHILL, B Bhaw, Pittman, Potts & Trowbridge CHURCHILL, B Misconsin Electric Power Co 82/08/09 BLUGH, P B , KLINE, J R., PAXTON, H C. Atomic 8dety and Licensing Board Panel 2pp 14363 207 24X Fiche 50-266,82/08/09,8208270315
- --B203270323 Testimony of WD Fletcher re issues raised in Contentions 1,2,3(a)-(e),4 & 5 in WI Environ Decade 820721 motion concerning littgable issues Prof qualifications & Certificate of 8vc encl FLETCHER.W D Wisconsin Electric Power Co FLETCHER.W.D Wastinghouse Electric Corp 82708/04 30pp 14363 280 24X Fiche 50-266,82708/09,8208270315

- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION
 F Security, medical, emergency & fire protection plans
- B208040490 Releases public version of revised radiological emergency response plan FELTON.J M Division of Rules and Records 82/07/22 Document Management Branch ip 14220 322 24X Fiche 50-267,82/07/22, 8208040490
- --B20B040503 Public version of notice that revised radiological emergency response plan is being forwarded under separate cover, per NRC B20315 request
 WAREMBDURG, D. W. Public Service Co. of Colorado. B2/07/12
 EISENHUT, D. O. Division of Licensing ip 14220-323 24X
 Fithe 50-267, B2/07/22, 8208040470
- 8208040512 Releases public version of revised radiological emergency response plan field monitoring procedure & Worksheet i for in-field sampling data FELTON.J M Division of Rules and Records 82/07/22 Document Management Branch ip 14221 007 24X Fiche 50-267.82/07/22.8208040512
- --820804052; Forwards public version of Issue 1 of radiological emergency response plan field monitoring procedure & Worksheet i for in-field sampling data = Public Service Co of Colorado 82/07/09 NRC No Detailed Affiliation Given ip. 14221 008 24X Fiche 50-267, 82/07/22, 8208040512
- --8208040526 Public version of Issue i of radiological emergency response plan field monitoring procedure & Worksheet i for in-field sampling data # Public Service Co of Colorado 82/07/09 32pp 14221 009 24X Fiche 50-267.82/07/22.8208040512
- B2080&0165 Ack receipt of \$20602 ltr & partial response to confirmatory action ltr Site visit anticipated MADBEN, G L Division of Resident, Reactor Project & Engineering Programs B2/0B/02 LEE.O R Public Service Co of Colorado ip 14239 238 24% Fiche 50-267.B2/0B/02.8208040145
- --8208060169 Informs of completion of response to confirmatory action items re integration of emergency action isvels into amergency procedure, procurement of add1 self-contained breathing apparatus & personnel emergency accountability WAREHBOURG. D. Public Service Co of Colorado 82/06/02 COLLINS, J. T. Region 4. Office of Director 2pp. 14239 239 24X Fiche 50-267,82/08/02.8208060165
- 8208160390 Ack receipt of 820723 itr re early warning alert sys.
 Approach to determining distribution & effectiveness of sys
 adequate.
 MADSEN.O L. Division of Resident, Reactor Project & Engineering
 Programs, 82/08/10 LEE.O R Public Service Co of Colorado Ip
 14349 001 24% Fiche 50-267,82/08/10.8208160390
- --8208160399 Notifies that survey of residents within 5-mile emergency planning zone to evaluate effectiveness of early warning sys successful Status of early warning radio problems identified by FEMA encl WAREHBOURG, D. M. Public Service Co. of Colorado 82/07/23 COLLINS, J. T. Region 4. Opfice of Director 5pp 14349 002 24x Fichs 50-267, 82/08/10, 8208160390
- 8208160444 Ack receipt of B20615 itr re emergency appraisal audit
 Requested extension dates for responses to App A & B to
 820818 & 820927, respectively, approved
 MADSEN, G L. Division of Resident, Reactor Project & Engineering
 Programs 82/08/ii LEE. O R Public Service Co of Colorado i
 14348 250 24X Fiche 50-267,82/08/ii.8208160444
- --B20Bi60456 Requests extension of response time to App B of emergency preparedness appraisal Considers response to App A unnecessary.

 WAREMBDURG. D. W. Public Bervice Co. of Colorado B2/06/15 GOLLINS.J T. Region 4. Office of Director 2pp 14348 251. 24X Fiche 50-267.82/08/11.8208160444
- P Operating license stage documents & correspondence
- 820B040176 Requests submittal addressing enti criteria re NUREO-0737, Item II B 3, "Post-Accident Sampling Sys " Schedule for responding to encl requested within 20 days of receipt of ltr CLARK.R.A Dparating Reactors Branch 3 82/07/09 WAREMBOURG,D W Public Service Co of Colorado Iipp 14229 348 24X Fiche. 50-267, 82/07/09, 8208040176

- 8208020429 Advises of forthcoming invoice for fee re util 820506 request for approval of route to cover spent fuel shipment MILLER.W O License Fee Management Branch 82/07/16 WAREMBOURO.D Public Bervice Co of Colorado ip 14181 053 24X Fiche 50-267, 82/07/16, 8208020429
- 8208040350 Forwards request for add1 info based on util response to IE Bulletin 80-11. "Masonry Wall Design" & "Control of Heavy Loads at Nuclear Power Plants." draft technical evaluation rept based on reaponse to 801222 generic 1tr CLARK. R A Operating Reactors Branch 3 82/07/21 LEE. O R Public Brivice Co of Colorado 4pp 14223, 128 24X Fiche 50-267, 82/07/21.8208/24350
- --8208040353 "Control of Heavy Loads at Nuclear Power Plants" STICKLEY.T H E0&9, Inc. 82/06/30. NRC - No Detailed Affiliation Given 29pp 14223 132 24X Fiche 50-267,82/07/21, 8208040350.
- 8208020252 Forwards updates to P & 9 ltr logs through Pages 75 & 140, respectively, listing correspondence from util to governmental regulatory agency per telcon MCBRIDE, L M Public Bervics Co of Coloredo 82/07/22 KUZMYCZ, O NRC Na Detailed Affiliation given 14pp 14152 213 24X Fiche: 50-267, 82/07/22, 8208020252
- 8208100011 Forwards startup rept "Initial Approach to Power Tests (B-Series), Interim Rept 23 for Period Ending 820522 "
 WAREH8GURO, D Public Bervice Co of Colorado 82/07/22
 COLLING.J.T. Region 4. Office of Director 2pp 14296-331 24%
 Fiche, 50-267, 82/07/22, 8208100011
- --8208100016 "Initial Approach to Power Tests (8-Series), Interim Rept 23 for Period Ending 820822 "

 * Public Service Co of Colorado 82/07/22 2pp 14296 333 24% Fiche: 50-267.82/07/22.8208100011
- 8208040198 Responds to NRC 820709 request re schedule for responding to it criteria of NVREO-0737. Item II B 3 concerning postactions tampling say Numerous submittals addressing item already provided. Stand-alone response will be forwarded WAREMBUURO, D. W. Public Service Co of Colorado 82/07/28 CLARK A. Operating Reactors Branch 3 ip 14239 008 24% Fiche 50-267. 82/07/28.8208060198.
- 8208170136 Forwards complete submittel list & statement re MUREO-0737 per discussion.

 MAREMBOURG, D W Public Service Co of Colorado 82/07/29 COLLING.J.T. Region 4: Office of Director. 9pp 14358 203 24X Fiche: 50-267.82/07/29.8208170136
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8xc list enc! EISENHUT, D. © Division of Licensing 82/08/09 Consolidated Edison Co. of New York. Ip. 14354-332 24X Fiche; 50-000, 82/08/09, 8208090194.
- 208190234 Forwards Class III fee for proposed Tech Spec changes re Limiting Conditions for Operation 4 1 7,per 820706 ltr. MAREMBOURG, D. Public Service Co. of Colorado. 82/08/11 MILLER, U. License Fee Management Branch. 2pp. 14388 190 [24] Fiche: 50-267, 82/08/11, 8208190234
- DB240221 Forwards draft summary of changes incorporated into updated FSAR.

 HOLMES: H H Public Service Co of Colorado. 82/08/13 KUZMYCZ, Q

 Office of Nuclear Reactor Regulation, Director 200pp 14522.001.

 24X Fiche: 50-267.82/08/13,8208240221
- 208310355 Comments on CRNL 820804 ltr re util 820705 request for release from 70% power Util will conduct rise-to-power progrem gethering sufficient data to evaluate core parameters as well as effects of temp redistribution, HAREMBOURG, D. H., Public Service Co of Colorado, 82/08/23 KUZNYCZ, O NRC No Detailed Affiliation Given, 2pp. 14693 244 24% Fiche; 50-267, 82/08/23, 8208310355.
 - Inspection reports, IE Bulletins & correspondence
- 204210393 IE Info Notice 82-23. "Nain Steam Isolation Valve (MSIV) Leakage." Svc list enci. JORDAN.E.L. Division of Engineering & Guality Assurance 82/07/16 Consolidated Edison Co. of New York 87pp. 14356,274, 24X Fiche: 50-000, 82/07/16.8204210393
- 204210394 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oraquel Loss of Air 'Pressure," Svc list encl. UCRJAN, E. L. Division of Engineering & Quality Assurance, 82/07/20 Consolidated Edison Co. of New York 112pp. 14381.001, 24X Fiche: 50-000, 82/07/20, 8204210394.

- 8204210397 IE Info Notice 82-24, "Water Leaking From V Hexafluoride Overpacks" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 27& 24X Fiche
- 8208040350 Forwards request for add1 info based on util response to IE Bulletin 80-11. "Masonry Well Design" & "Control of Heavy Loads at Nuclear Power Plants." draft technical evaluation rept based on response to 801222 generic 1tr CLARK.R A. Operating Reactors Branch 3 82/07/21 LEE.G R. Public Service Co of Colorado. 4pp 14223 128 24X Fiche 50-267, 82/07/21, 8208040350
- --8208040335 "Control of Heavy Loads at Nuclear Power Plants," SYICKLEY, T H E080, Inc 82/06/30 NRC - No Detailed Affiliation Given 29pp 14223 132 24X Fiche 50-267,82/07/21, 8208040350
- 8204210398 IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/22 Consolidated Edison Co of New York 112pp 14194,321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Fube Support Fin Failures at Westinghouse FWRs." Svc list encl, JORDAN,E L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp. 14194 120 24X Ficher 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Siseves in RCS Piping at Certain Westinghouse PNR Power Plants " Svc list and JRRDAN.E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York. 121pp 14357 013 24X Fichs 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Fool" Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/28, Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405.
- B204210407 IE info Notice B2-27. "Fuel Rod Degradation Resulting From Saffie Water-Jet Impingement " Svz list and 1 JURDAN. E L. Division of Engineering & Quality Assurance. B2/08/05. Consolidated Edison Co of New York 117pp 14388 201 24X Fiche. 50-000. B2/08/05. 8204210407
- 8208100267 Ack receipt of 820727 itr informing NRC of steps taken to correct deviations noted in IE Insp Rept 50-267/82-15 Rept withheld (ref 100FR2 790).

 NORDERMAUG, L. R. Division of Radiological Safety & Safeguards Program 82/08/06 LEC.O R. Public Service Co. of Colorado. ip 14294 141 24X Fiche: 50-267, 82/08/06, 8208100267
- 8208160444 Ack receipt of 820615 ltr re emergency appraisal audit.
 Requested extension dates for responses to App A & B to
 820818 & 820927, respectively approved
 MADSEN. O L Division of Resident, Reactor Project & Engineering
 Programs, 62/08/11 LEE. O R Public Service Co of Colorado ip.
 14348.250. 24X Fichs 50-267.62/08/11.8208160444.
- --B20Bl60456 Requests extension of response time to App B of emergency preparedness appraisal Considers response to App A unnecessary MAREHBURG, D W Public Service Co of Colorado 82/06/15 COLLINS, J Region 4. Office of Director 2pp 14348'251 24X Fiche: 50-25-182/08/11, B20Bl60444.
- 8208300220 Responds to IE Bullatin 80-ii, "Mesonry Wall Design," per NRC 820721 request. Responses to Questions 2.4 % 14 re stack bonding & modeling techniques encl LEE.O.R. Public Service Co of Colorado. 82/08/24. CLARK, R A Operating Reactors Branch 3 14pp 14679, 029. 24X Fiche 50-267, 82/08/24, 8208300220.
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A FELTON.J.M. Division of Rules and Records 82/07/13 UDELL.R A. Critical Mass Energy Project 8pp. 14679, 208 24X Fiche: 50-000, 82/07/13, 8208270010

- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" " NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270592 Forwards "Personnel Occupational Exposures CY81." per 10CFR20 407 BORST,F J Public Service Co of Coloredo 82/02/23 BROOKS.B Director's Office. Office of Inspection and Enforcement 1p 14677 329 24X Fiche:50-000:82/07/13.8208270010
- B2OB130201 Forwards monthly operating rept for Jul 1982 WAREHBUURG, D. Public Service Co. of Colorado B2/08/09 Director's Office, Office of Inspection and Enforcement ip 14039 098 24X Fiche 50-267, 82/08/09, 8208130201
- B2OB130176 Forwards monthly operating rept for Jul 1982, WAREHBOURD, D. Public Service Co. of Colorado. 62/08/10 GARMILL, W.P. Assistant Director for Operating Reactors. 2pp 14039, 114 24% Fiche 50-267, 82/08/10, 8208130196
- --8208130197 Monthly operating rept for Jul 1982 MCBRIDE, L M Public Service Co of Colorado 82/08/09 8pp 14339 116 24X Fiche 50-267,82/08/10,8208130196.
- S Reportable occurrences, LERs & related correspondence
- 82080\$0349 Forwards LER 82-024/03x-1 Datailed event analysis encl MAREHBUURD, D Public Service Co of Colorado 82/07/30, COLLINS, J T Region 4. Office of Director 8pp 14219-319 24X Fiche: 50-267, 82/07/30, 8208080349
- --B208050379 LER 82-024/03X-1 on 820605, all three 480-volt segantial buses lost. Caused by Westinghouse type CV-2 volt relay being improperly calibr. due to inadequacy of relay calibr procedure Procedure updated FULLER, C Public Service Co of Colorado 82/07/30 Region 4, Office of Director, ip 14219:327 24X Fiche, 50-267, 82/07/30, 8208050349
- 8208160025 Forwards LER 82-028/09L-0 Detailed event analysis encl. WAREHBOURG, D Public Service Co of Colorado 82/08/06 CCLLINS. J T Region 4. Office of Director 5pp 14345-038 24X Fiche, 50-267, 82/08/06, 8208160025.
- --B20Bi60027 LER B2-02B/OSL-O on B20707, excessive water laskage through PV-21244 necessitated isolation of emergency feedwater supply header Caused by water cut in valve seat & plug Valve ring seat:plug assembly hody & seat gaskst replaced FULLER:C Public Service Co of Colorada B2/08/06 Region 4, Office of Director 1p 14345 043, 24X Fiche 50-267,82/08/06,820B160025
- B2OB200117 Forwards LER 82-024/03X-2 Detailed event analysis sncl.
 WAREMBOURG, D Public Service Co of Colorado B2/0B/11
 COLLINS.J.T Region 4, Office of Director. 7pp. 14393,321 24X
 Fische 50-267,82/0B/11.820820017
- --B208200124 LER 82-024/03x-2.on 820605.3 480-volt essential buses lost Reactor manually scrammed. Caused by improperly calibr undervoltage relays & inadequate relay calibr procedure. FULLER.C Public Bervice Co of Colorado. B2/08/11 Region 4. Office of Director 2pp 14393 328 24X Fichs 50-267,82/08/11. B208200117.
- B20B200126 Forwards LER 82-029/03L-0 Detailed event analysis encl. MAREMBOURD, D. Public Service Co of Colorado. 82/08/11. COLLINS.J.T Region 4, Office of Director 4pp 14399.358. 24X Fiche 50-247,82/08/11.8208200126.
- --8208200141 LER 82-029/03L-0.on 820712, emergency feedwater headers to helium circulator pelton wheel drives were isolated to perform maint on leaking header safety valves. Caused by need to rework valve seats & discs. Drives returned to svc FULLER: C Public Service Co. of Colorade. 82/08/11 Region 4, Office of Director. 1p. 14399.362 24X Ficha: 50-267.82/08/11, 6208200126.
- 8208240053 Forwards LER 82-030/03L-D. Detailed event analysis encl. MAREMBOURG, D. Public Service Co. of Colorado. 82/08/17, COLLINS, J.T. Region 4, Office of Director. 5pp. 14520-015. 24X Fiche 50-267, 82/08/17, 820824005

- ~~8208240056 LER 82~030/03L-0 on 820719, total primary coolant exidents esceeded Tach Specs twice Caused by offgassing of moisture due to increasing temp during recovery from reactor scram FULLER, C Public Service Co of Colorado 82/08/17 Region 4. Office of Director ip 14520 020 24X Fiche 50-267, 82/08/17, 8208240053
- 820B240074 Forwards LER 82-029/03X-1 Detailed event analysis encl MAREMBOURG, D Public Service Co of Colorado 82/08/17 COLLINS, J T Region 4, Office of Director 5pp 14519 349 24X Fiche 30-267, 82/08/17, 8208240074
- ~-8208240079 LER 82-029/03X-1 on B20712,20 & 21.emergency feedwater headers to helium circulator pelton wheel drives isolated to perform maint on leaking header safety valves Cause of leakage not stated FULLER,C Public Service Co of Colorado 82/08/17 Region 4, Office of Director 1p 14519 354 24X Fiche 50-267,82/08/17,8208240074

DOCKET 90-268 MIDWEST FUEL RECOVERY PLANT

- Q Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Evc list encl JURDANNEL Division of Engineering & Quality Assurance 82/07/19, Michigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210395

DOCKET 50-269 OCCURE NUCLEAR STATION: UNIT 1

- F Security, medical, emergency & fire protection plans
- 8208040450 Forwards request for add1 info re standby shutdown facility to determine acceptability to resolve NRC concerns regarding fire protection to turbine bidg flooding STOLZ.JF Operating Reactors Branch 4 82/07/17 PARKER.W O Duke Power Co 9pp 14220 253 24X Fichs 30-249,82/07/17.8208040450
- 8208:10182 Informs of planned installation of fire hose cabinets of entrances to cable rooms & of planned utilization of existing turbine hidg hose stations for protection of equipment rooms Mod affects 77:122 commitment TUCKER.H B Duke Power Co 82/08/03 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 14313 360 24% Fichs 50-269.82/08/03.8208110182
- 8208190405 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/08/10 Document Management Branch 1p 14504 186 24X Fiche 50-269, 82/08/10.
- --B20B190412 Forwards gublic version of revised emergency plan implementing procedures, including Station Directive 2, 92 remergency response organization & Procedure CP/07A/2003/20 re post-accident determination of gamma isotopic accivity TUCKER.H B Duke Power Co B2/08/03 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactors Branch 4 2pp 14504 187, 24X Ficher 50-269, B2/08/10, B20B190405
- --8208190422 Public version of revised emergency plan implementing procedures, including Station Directive 2 92 re emergency response organization & Procedure CP/D/A/2005/20 re post-accident determination of gamma isotopic activity, OMEN.T.B. Duke Power Co. 82/07/23 94pp 14504 189 24X Fiche 50-269.82/08/10.8208190405
- 8208260418 Releases public version of revised crisis mgt plan FELTON, J, M Division of Rules and Records 82/08/11 Document Management Branch ip 14572 098 24X Fiche 50-000,82/08/11,8208260418.
- --8208260430 Forwards public version of Revision 5 to crisis mgt plan Revision involves reorganization of crisis mgt team & updates of Sections D.K & M PARKER, M.O. Duka Fower Co. 82/07/19 DENTON, M.R. Office of Nuclear Reactor Regulation, Director ip 14572:099, 24X Fiche 50-000,82/08/11,8208260418
- --8208260437 Public version of Revision 5 to crisis mgt plan TUCKER, H B Duke Power Co 82/07/09 134pp 14572:100. 24X Fiche: 50-000, 82/08/11, 8208260418

- 0200240529 Releases public version of emergency plan implementing procedures
 FELTON V M Division of Rules and Records 82/08/13 Document Management Branch 1p 14569 001 24% Fiche 50-269, 82/08/13, 8200240529
- --8208240537 Forwards public version of Emergency Plan Implementing Procedures AP/0/A/1000/10 re emergency evacuation & HP/0/B/1009/15 re sampling & quantifying high level gaseous radiotodine & particulate radioactivity TUCKER.H I Duke Pauer Co. 82/08/05 DENTON.H R. Office of Nuclear Reactor Regulation, Director STOLZ.J F. Operating Reactors Branch 4 ip 14567 003 24X Fichs 50-269,82/08/13,8208240529
- --B208260542 Public version of Emergency Plan Implementing Procedures AP/0/A/1000/10 re dmergency evacuation & HP/0/B/1009/15 re sampling & quantifying high level gaseous rediciodine & particulate radioactivity
 TUCKER.H B Duke Power Co B2/07/30 44pp 14549 004 24X
 Fiche 50-269,82/08/13,8208260529

I Financial information

- 8208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981 TUCKER, H B Duke Power Co 82/08/24. DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14599, 227 24X Fiche 50-000 82/08/24
- --8208300335 Annual Financial Rept 1981 HDRN, C Duke Power Co 82/02/15 48pp 14599:006 24X Fiche: 50-000, 82/08/24, 8208300328
- 8208300342 Forwards Annual Financial Rept 1981
 TVCKER,H B Duke Power Co 82/08/24 DENTON,H R Office of
 Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactor:
 874004 4 1p 14599,110 24X Fiche,50-269,82/08/24,8208300342
- P Operating license stage documents & correspondence
- 6207080064 Ceneric ltr to all licensees of operating plants applicants for OL & holders of CP re Commission approved charter for CRGR SVc list encl
 DIRCKS:W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fiche 50-000 82/07/02 8207080044
- 8208040546 Notification of B20818-17 meetings w/util & consultants in Seneca.80 to discuss radiological effluent Tack Space WAGNER.P C Operating Reactors Dranch 4 82/07/27 STOLZ.J F Operating Reactors Branch 4 2pp. 14220,357 24X Fiche 50-269.82/07/27,8208040546
- 8208030223 Submits changes to completion dates for NUREG-0737, Items II, 8 3, "Post-Accident Sampling," & II F 1, "Noble Oss Monitors;" per 820416 status rept PARKER, W O Duke Power Co 82/07/28. DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 14159 325 24X Fiche 50-249,82/07/28,8208030223
- 3208030841 Application for amend to Licenses DPR-38.DPR-47 & DPR-55, revising Tech Specs 6 0 through 6 3 re util reorganization, superinteendent of operations qualification requirements & organization chart Class I & II amend feet and PARKER, W O. Duke Power Co. 82/07/30 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J.F Operating Reactors Granch 4 3pp 14162 353 24X Fiche 50-000.82/07/30.8208030541
- -8208030551 Forwards Class I & II amend fees to cover revisions to Tech Specs & 2 re offsite & station organization & 6 O through & 3 re reorganization PARKER, # 0 Duke Power Co 82/07/30 MILLER, W E Office of the Controller 1p 14462 356, 24X Fiche 50-000.82/07/30.8208030541
- 8208030560 Proposed Tech Specs 6 0-6 3 re administrative controls, review & audit.Organization chart encl # Duke Power Co 82/07/30 13pp. 14162 357 24X Fiche: 50-000, 82/07/30, 8208030541
- OB040311 BOCIDECONDMIC IMPACTS OF NUCLEAR GENERATING STATIONS:
 DCONEC CASE STUDY Docket Nos. 50-269 And 50-270 (Duke Power
 Company)
 TJYNN-J Social Impact Research, Inc. * Mountain Hest Research,
 Inc. FIN 8-6268 NUREG/CR-2749 VO7
 62/07/31 Division of
 dealth, Siting & Environment. 185pp Available at NTIS, \$7.00
 4229:001. 24X Fiche: 50-269, 82/07/31, 8208040311

- 8208100193 Responds to NRC 820708 request for schedule for responding to NUREO-0737. Item II 8 3, "Post-Accident Sampling Sys "
 Info will be submitted by 821101
 TUCKER.H B Duke Fower Co 82/08/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 5TOLZ.JF Operating Reacters Branch 4 ip 14278 197 24X Fiche 50-269.82/08/05.8208100193
- 8208120028 Provides add1 info re availability of steam generator cooling water in event of tornedo strike.per NRC 820408 safety evaluation Configuration, as modified by standby shutdown facility, acceptable TUCKER.H B Duke Power Co 82/08/04 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ.JF Operating Reactors Branch 4 2pp 14324 058 24X Fishe 50-267,82/08/06,8208120028
- 8208120216 Advises that responses to questions re adequacy of station electric distribution sys voltages will be submitted no later than 821008.per 820608 request Delay caused by required addl research & manpower limitations TUCKER.H B Duke Power Co 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ.JF Operating Reactors Branch 4 1p 14326 171 24X Fiche 50-269.82/08/06.8208120816
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT.D O Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fichs 50-000,82/08/09,8208090194.
- 8208170151 Responds to NRC 820709 ltr revisions shift technical advisor training programs required by Item I A I 1 of NUREO-7070 & NUREO-0660 Disagrees w/NRC expectation that all new hires have backelors degree or equivalent TUCKER: H B Duke Power Co 82/08/12 DENTON. H R Office of Nuclear Resottor Regulation, Director STULY. JF Operating Reactors Branch 4 2pp 14364 218 24% Fiche 50-269,82/08/12.6206170151
- 8208200025 Advises that util response to NRC 820713 ltr re schedule for submitting supplemental ECCS calculations utilizing cladding models of NURGO-0630 will be submitted by 830301
 TUCKER, H B Duke Power Co 82/08/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 670L7, J F Operating Reactors Branch 4 lp 14392.246 24X Fiche 50-269,82/08/12,8208200029
- 8208240242 Disagrees w/NRC expectations that all new hires have backslors degree or equivalent pending new guidance per 820707 ltr & NUREO-0737. Item I A I I." Shift Technical Advisor" & NUREO-0640 TUCKER. H B Duke Power Co 82/08/12 DENTON, H R Office of Nuclear Reactor Regulabson, Director STOLZ, J F Operating Reactor Branch 4 2pp 14520 070 24X Fiche 50-269.82/08/12.8208240242
- 8208310236 Forwards summary of licensee efforts to resolve NUREQ-D737. Item II K. 3 GO re revised small break LOCA methods Util util support B&W owners group effort to provide integral systest data.utilizing CERDA test facility
 TUCKER.H D Duke Fower Co 82/08/25 DENTON, H R Office of Nuclear Reactor Regulation, Director. STOLZ.J F Operating Reactors Branch 4 11pp 14695 096 24X Fiche 50-269, 82/08/25,8208310234
- O Inspection reports, IE Bulletine & correspondence
- 8208030579 Forwards IE Insp Repts 50-269/82-21.50-270/82-21 & 50-287/82-21 on 820614-18 No noncompliance noted LEWIS.R C Division of Project & Resident Programs 82/07/09 PARKER, W D Duke Power Co. 2pp 14162 313 24X Fiche 50-269, 82/07/09, 8208030599
- --B208030413 IE Insp Repts 50-269/B2-21.50-270/B2-21 & 50-287/B2-21 on B20614-18 No noncompliance noted Major areas inspected review of chemistry & radiochemistry procedures & airborns effluent sampling & accountability EVANS.C D , MONTOPIERY.D M Division of Emergency Preparedness & Operational Support & B2/07/07 10pp, 14162 315 24X Fithe 50-269, B2/07/09, B208030399
- 8208030548 Forwards IE Insp Repts 50-269/82-26.50-270/82-26 & 50-287/82-26 on 820706-09 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/14 PARKER, W D Dute Power Co 2pp 14162 096, 24% Fiche: 50-269, 82/07/14, 8208030548
- --8208030557 IE Insp Repts 50-269/82-26, 50-270/82-26 & 50-287/82-26 on 820706-09 No nancompliance noted Major areas inspected followor of extraction steam line rupture ORDERS.W. PUCKET.M., KLEINSORGE.W. Division of Project & Resident Programs 82/07/14 Spp. 14162-098 24% Fiche 50-249, 82/07/14, 8208030548

- B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakago " Svc list encl
 JORDAN.EL Division of Engineering & Quality Assurance B2/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/07/19
 Michigan, Univ of 112pp 14398 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210376
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks" Bvc list encl COBB.L I. Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & MPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp. 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208160163 Forwards IE Insp Repts 50-269/82-24,50-270/82-24 & 50-267/82-21 on 820614-25 No noncompliance noted. DANCE, H. C Division of Project & Resident Programs 82/07/22 PARKER, W U Duke Power Co 2pp 14345 069 24X Fiche 50-269,82/07/22,8208160163
- --B208160169 IE Insp Repts 50-R69/82-R4,50-270/82-R4 & 50-287/82-R1 on 820614-R5 No noncompliance noted Major areas inspected Unit 3 10-yr inservice ultrasonic insp of steam generators, pressurizer reactor vessol & RCPB pips COLEY,J L , ECONOMOS,N Division of Engineering & Tochnical Programs 82/07/19 7pp 14345 071 24X Fiche.50-269.82/07/22, 8208160163
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Gvc list encl URDAN,E.L. Division of Engineering & Quality Assurance 82/07/23. Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23,8204210401
- 8204210402 IE Info Notice 82~27, "Control Rod Drivs (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174:120 24X Fiche. 50-000, 82/07/23, 8204210402
- 8288020303 Responds to NRC 820625 itr re violations noted during IE insp Corrective actions missing cap for test tee replaced & instrument procedures revised to identify all equipment removed from syc Util protests civil penalty.

 PARKER, W. O Duke Power Co 82/07/23 DEYQUNO, R C. Director's Office, Office of Inspection and Enforcement 40pp 14151 345, 24X Fiche 50-267, 82/07/23, 8208020303
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 62/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche: 50-000. 82/07/26. 8204210403
- 9208160194 Forwards IE Insp Repts 50-269/82-27, 50-270/82-27 & 50-287/82-27 on 820610-0718 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/26. PARKER, W D Dyke Power Co 2pp 14344 127 24X Fiche: 50-269, 82/07/26, 8208160194
- --8208160202 IE Insp Repts 50-269/82-27,50-270/82-27 & 50-287/82-27 on 820610-0715. No noncompliance noted Major areas inspected, operations safety verification, surveillance testing, station maint activities & plant trips ORDERS.W. FALCONER, D , BRYANT, J Division of Project & Resident Programs. 82/07/26 11pp 14344, 131 24X Fichs 50-269,82/07/26,8208160194
- 8208030595 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17

 LEHIS.R C Division of Project & Resident Programs, 82/07/27 PARKER, M O, Duke Pawer Co ip 14162, 232 24X

 Fiche: 50-269, 82/07/27, 8208030595

- --B208030609 Responds to NRC B20616 ltr reviolations noted in IE Insp. Repts 50-269/82-17,50-270/82-17 & 50-287/82-17 Corrective actions stronger door closure devices will be installed by B20915 & preventive maint program will be re-evaluated PARKER.W O Dute Power Co 82/07/16 D'REILLY, J.P. Region 2, Office of Director 2pp 14162 233 24X Fiche 50-249,82/07/27,8208030395
- --8208030618 Forwards IE Insp Repts 90-249/82-17, 50-270/82-17 & 50-287/82-17 on 820510-14 & notice of violation DANCE, H C Division of Project & Resident Programs 82/06/16 PARKER, W D Duks Power Co 2pp 14162 235 24X Fiche 50-269, 82/07/27, 8208030595.
- ~-8208030625 Notice of violation from insp on 820310-14 * Division of Project & Resident Programs B2/06/16 [p 14162 237 24% Fiche 50-269, 82/07/27, 8208030595
- --8208030636 IE Insp Repts 50-269/82-17.50-270/82-17 & 50-287/82-17 on B20310-14 Noncompliance noted door providing access to radwaste compacting area found unlocked & positive access control not in effect CGLLINS.T R , BARR.K.P Division of Engineering & Technical Programs 82/06/10 Gpp 14162 238 24X Fiche 50-269,82/07/27,8208030395
- 8208160364 Forwards IE Insp Repts 50-269/82-29,50-270/82-29 & 50-287/82-29 on 820712-16 No noncompliance noted DANCE H C Division of Project & Resident Programs 82/07/27 PARKER W 0 Duke Power Co 2pp 14349.041 24X Fiche 50-269,82/07/27,8208160364
- --B208160375 IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on B20712-16 No noncompliance noted Major areas inspected radiation protection, shipment of radioactive matl.personnel dosimetry, portable instrument calibr & review of LERs. COLLINS, T R , BARR, K P Division of Engineering & Technical Programs 82/07/23 App 14349 043 24X Fichs. 50-269, 82/07/27, B208160364
- --B208160375 IE Insp Repts 50-269/82-27, 50-270/82-29 & 50-287/82-29 on B20712-16 No noncompliance noted Major areas inspected radiation protection, shipment of radioactive matl.personnel dosimetry.portable instrument calibr & review of LERs COLLINS.TR Region 2. Office of Director B2/07/23 App. 14349 043 24X Fiche 50-269, 82/07/27,8208160364
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146, 24X Fiche, 50-000, 82/07/28, 8204210405
- 820Bi6029i Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Improved design gasket is onsite & ready for use to repair reactor coolant pump PARKER, W II Duke Power Co 82/07/29 O'REILLY, J P Region 2, Defice of Director 3pp 14346-265 24X Fiche 50-269, 82/07/29, 820Bi6029i
- 8204210407 IE Info Notice 92-27, "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of Arew York 117pp 14388 201 24X Fichs 50-000, 82/08/05, 8204210407.
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON. J M Division of Rules and Records. 82/07/13 UDELL. R A Critical Mass Energy Project Bpp 14679, 208 24X Fiche. 50-000, 82/07/13, 8208270010
- --B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" "

 » NRC No Detailed Affiliation Given 82/07/13 48pp 14679 216. 24% Fiche: 50-000: 82/07/13: 8209270010

- --8208270503 Forwards "Statistical Rept of Recorded Personnel Whole Body Exposures for CY01." per 10CFR20 407 PARKER.H D Buke Power Co 82/02/25 Office of Management and Program Analysis 1p 14579 340 24X Ficha 50-000,82/07/13, 8208270010
- ---8208270612 "Statistical Rept of Recorded Personnel Whole Body Exposures for CYSI," LEMIS.L Duke Fawer Co 82/02/25 ip 14679 341 24X Fiche 50-000,82/07/13.8208270010
- 8208170087 Forwards monthly operating repts for Jul 1982 TUCKER, H B Dute Power Co 82/08/13 Director's Office, Office of Inspection and Enforcement 1p 14358 149 24X Fiche 30-249, 82/08/13, 8208170087
- --8208170091 Honthly operating repts for Jul 1982 REAVIS, J. A. Dute Power Co. 82/08/13 16pp 14358 150 24X Fiche 50-269, 82/08/13, 8208170087
- 8 Reportable occurrences, LERs & related correspondence
- 8208020079 RD 269/82-13 on 820706, emergency feedwater pump declared inoperable when required surveillance testing discovered not performed investigation & rept will be completed, reviewed & submitted by 820803

 PARKER, N D Duke Power Co. 82/07/20 D'REILLY, J P Region 2, Diffice of Director ip 14144 104 24X Fiche 50-269, 82/07/20, 8208020079.
- --B208020164 LER 82-012/01T-0 on B20623.both trains of reactor bldg apray inoperable due to train B pump out of set while train A pump suction valve was shut Caused by personnel error Train B pump racted in pump breaker

 KUTZER, J F Duke Power Co B2/07/21 Region 2, Office of Director 1p. 14141 068 24% Fiche 50-269.B2/07/21,8208020160
- 8208020168 Advises that RO-269/82-11 providing details of 820622 incident when unit declared inoperable due to main the breaker to overhead transmission path not closing, will be submitted no later than 820820 PARKER-W O Duke Power Co 82/07/22 O'REILLY, J P Region 2, Office of Director ip 14141-020 24X Fiche-50-269, 62/07/22, 8208020168
- 8208030460 Forwards updated LER 82-008/01X-1. Detailed event analysis encl
 PARKER, W D Dute Power Co 82/07/23 O'REILLY, J P Region 2,
 Office of Director. 3pp. 14154 060. 24X Fiche 50-269,82/07/23,
 6208030460.
- -8208030465 Updated LER 82-008/01X-1 on 820323.air found leaking into reactor bldg through instrument line test tee in penetration HB-13. Caused by personnel error Pressure switch not properly returned to see after last calibr. Cap replaced NORRIE. J. F Duke Power Co 82/07/23 Region 2. Office of Director ip 14154-063 24% Fiche. 50-267, 82/07/23, 8208030460
- 3208120172 Forwards LER 82-013/01Y-0 Detailed event analysis encl TUCKER H B. Duke Power Co 82/08/03 O'REILLY, J. P. Region 2, Office of Director. 2pp. 14324-239 24X Fiche: 30-249, 82/08/03, 8208120172,
- --B208120178 LER 82-013/01T-0 on B2070& emergency feedwater initiation logic pressure switches determined not surveillance tested from B2032-070B, rendering pumps inaperable. Caused by inadequate review of Tech Spec change Tests performed.

 KUTZERJF Duke Power Co 82/08/03 Region 2, Office of Director ip, 14324 241. 24X Fishe 50-269, 82/08/03, 8208120172
- DOCKET 50-270 OCCNEE NUCLEAR STATION, UNIT 2

 F. Becurity, medical, emergency & fire protection plans
- 8208040450 Forwards request for add1 info re standby shutdown facility to determine acceptability & resolve NRC concerns regarding fire protection & turbine hidg flooding BTOL2.0 F. Operating Reactors Branch 4. 82/07/17. PARKER, M. D. Duke Pawer Go. 9pp. 14220-253. 24X Fiche. 50-269, 82/07/17, 8208040450.

- 820810182 Informs of planned installation of fire hose cabinets at entrances to cable rooms & of planned utilization of existing turbine bidg hose stations for protection of equipment rooms Mod affects 771122 commitment TUCKER.H B Duke Power Go 82/08/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 14313 360 24X Fiche 50-269, 82/08/03.8208110182
- 8208190405 Releases public version of revised emergency plan implementing procedures FELTON.JM Division of Rules and Records 82/08/10 Document Management Branch ip 14504 186 24X Fiche 50-269, 82/08/10, 8208190405
- --8208190412 Forwards public version of revised emergency plan implementing procedures, including Station Directive 2 92 reemergency response organization & Procedure CP/07A/2003/20 re post-accident determination of gamma isotopic activity YUCKER, H B Duke Power Co 82/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 8TOLZ, J F Operating Reactors Branch 4 2pp 14504 187 24X Fiche 50-269, 82/08/10, 8208190405
- --8208190422 Public version of revised emergency plan implementing procedures including Station Directive 2 92 re emergency response organization & Procedure CP/0/A/2005/20 re post-accident determination of gamma isotopic activity OMEN.T B Duke Power Co 82/07/23 94pp 14504 189 24X Fiche 50-269, 82/08/10, 8208190405
- 8208260418 Releases public version of revised crisis mgt plan FELTON, J M Division of Rules and Records 82/08/11 Document Management Branch 1p. 14572 098 24X Fiche 50-000,82/08/11, 8208280418
- --8208260430 Forwards public version of Revision 5 to crisis mgt plan Revision involves reorganization of crisis mgt team & Updates of Sections D.K & M. PARKER, M.O. Duke Power Co. 82/07/19 DENTON. H.R. Office of Nuclear Reactor Regulation, Director ip 14572 099 24X Fiche: 50-000, 82/08/11, 8208260418
- --B208260437 Public version of Revision 5 to crisis mgt plan TUCKER,H 8. Duke Power Co 82/07/09 134pp 14572 100 24X Fiche 50-000,82/08/11,8208260418
- 8208260529 Releases public version of emergency plan implementing procedures.
 FELTON.J M Division of Rules and Records 82/08/13 Document Management Branch ip 14569 001 24X Fiche 50-269,82/08/13, 8208260529.
- --8208260837 Forwards public version of Emergency Plan Implementing Procedures AP/0/A/1000/10 re emergency evacuation & HP/0/B/1009/15 re sampling & quantifying high level gaseous radioiodine & particulate radioactivity.

 TUCKER:H B Duke Power Co. 82/08/03 DENTON:H R Office of Nuclear Reactor Regulation Director STQL7.J F Operating Reactors Branch 4 Ip. 14569 003 24X Fichs.50-269,82/08/13,8208260529
- --8208260542 Public version of Emergency Plan Implementing Procedures AP/0/A/1000/10 re emergency evacuation & HP/0/B/1007/15 re sampling & quantifying high level gaseous radioiddins & particulate radioactivity.

 TUCKER, H B Duke Power Co 82/07/30 44pp 14569-004 24X Fiche-50-269,82/08/13,8208260529.
- I Financial information
- 8208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981. TUCKER, H B. Duke Power Co. 82/08/24, DENTON, H. R. Office of Nuclear Reactor Regulation. Director 2pp 14599 227 24X Fiche: 50--000, 82/08/24, 8208300328.
- --8208300335 Annual Financial Rept 1981 HORN.C. Duke Fower Co 62/02/15 48pp, 14599.006, 24X Fiche 30-000,82/08/24,8208300328
- 8208300342 Forwards Annual Financial Rept 1981 TUCKER,H.B. Duke Power Co. 82/08/24 DENTON,H R Office of Nuclear Reactor Regulation, Director. 570LZ.J.F Operating Reactors Branch 4. 1p. 14599,110 24X Ficher 50-269,82/08/24,8208300342

- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP rs Commission approved charter for CRGR. Byc list encl
 BIRCKS, W Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche, 50-000, 82/07/02, 8207080064
- 820B040346 Notification of 820818-19 meetings w/util & consultants in Saneca. SC to discuss radiological effluent Tech Specs.
 WAGNER.P C Operating Reactors Branch 4 82/07/27 STULZ, J F Operating Reactors Branch 4 20 1420
- 8208030223 Bubmits changes to completion dates for NUREO-0737, Itams II B 3, "Post-Accident Bampling," & II F 1, "Noble Cas Monitors," per 820416 status rept FARKER, W O Duke Power Co 82/07/28 DENTON, H R Office of Nuclear Reactor Regulation. Director STOLZ, JF Operating Reactors Branch 4 2pp 14159 325 24% Fiche 50-249,82/07/26,8208030223
- 8208030541 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs 6.0 through 6.3 re util reorganization, superintendent of operations qualification requirements & organization chart Class I & II amend fees encl PARKER, W.O. DUKE POWER GO. 82/07/30, DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director 57012, J.F. Operating Reactors Branch 4. 3pp. 14162-353, 24% Fiche 50-000,82/07/30,8208030341
- --B208030551 Forwards Class I & II amend fees to cover revisions to Tech Space 6 2 re offsite & station organization & 6.0 through 6 3 re reorganization. PARKER, W O Duke Power Co 82/07/30, MILLER, W E Office of the Controller 1p. 14162 356 24X Fiche 50-000, 82/07/30, 8208030541
- --8208030560 Proposed Tech Specs 6 0-6 3 re administrative controls, revisw & audic. Organization chart encl w Duke Power Co 82/07/30 i3pp. 14162-357 24X Fiche 50-000,82/07/30,8208030541
- 8208040311 80CIDECONOMIC IHPACTS OF NUCLEAR GENERATING STATIONS OCONEE CASE STUDY, Docket Nos 50-269 And 50-270 (Duke Power Company)
 FLYNN, J Bocial Impact Research, Inc * Hountain West Research, Inc. FIN 8-6268 NUREO/CR-2749 V07 82/07/31 Division of Health, Siting & Environment 185pp Available at NTS \$7 00. 14229 001 24X Fiche 50-269,82/07/31,8208040311.
- B20B100193 Responds to NRC 820708 request for schedule for responding to NURCO-0737. Item II B 3: "Post-Accident Sampling Bys "
 Info will be submitted by B21101
 TUCKER, H B Duke Power Co 82/08/05 DENTON, H R Office of Nuclear Reactor Regulation, Director BTDLZ, J F Operating Reactors Branch 4. 1p 14298 197 24X Fiche 50-269, 82/08/05, 8208100193
- 8208120028 Provides addl info re availability of steam generator cooling water in event of tornado strike, per NRC 820408 safety evaluation. Configuration. as modified by standby shutdown facility, acceptable.
 TUCKER.H B. Duke Fower Co. 82/08/06 DENTON.H.R Office of Nuclear Reactor Regulation. Director. STOLZ.J F Operating Reactors Oranch 4 2pp 14324:038 24X Fiche. 30-269, 82/08/06, 8208120028
- 820B120216 Advises that responses to questions re adequacy of station electric distribution sys voltages will be submitted no tater than 821008.per 820608 request Delay caused by required addi research & manpower imitations.

 TUCKER, H. B. Duke Power G. 82,08206 DENTON H. Office of Nuclear Reactor Regulation, Director BTOLZ, J. F. Operating Reactors Branch 4 ip 14326.171 24X Fiche, 50-269, 82/08/06, 8208120216.
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CF & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Byc list encl.
 EIBENHUT, D. O Division of Licensing 82/08/09 Consolidated Edison Co. of New York. ip. 14356-332 24X Fiche 50-000,82/08/09,82/08/09/194.
- 820B170151 Responds to NRC 820709 ltr reviewing shift technical advisor training programs required by Item I A 1,1 of NURE9-7370 & NURE9-0560 Disagrees w/NRC expectation that all new hires have backelors degree or equivalent. TUCKER.H.R. Duke Power Co. 82/08/12 BENTON.H R Diffice of Nuclear Reactor Regulation. Director 870LZ.J.F. Operating Reactor Branch 4, 2pp. 14364:218. 24X Fiche. 50-269.82/08/12.8208170151

- 8208200025 Advises that util response to NRC 820713 ltr re schedule for submitting supplemental ECCS calculations utilizing cladding models of NUREQ-0630 util be submitted by 830301
 TUCKER.H B Duka Power Co 82/08/12 DENTON.H R Office of Nuclear Reactor Regulation, Director STCL.Z.J F Operating Reactors Branch 4 1p 14392 246 24X Fiche 50-269.82/08/12,8208200025
- 8208240242 Disagrees w/NRC expectations that all new hires have backelors degree or equivalent pending new guidance per 820707 ltr & NUREO-0737. Item I A 1 1.º Shift Technical Advisor" & NUREO-0640
 TUCKER.H B Duke Power Co B2/08/12
 Nuclear Reactor Regulation. Director Branch 4 2pp 14520 070 24X Fiche 50-267,82/08/12,8208240242
- 820B310236 Forwards summary of licensee efforts to resolve NUREQ-0737, Item II K 3 30 re revised small break LOCA methods Util will support B&H owners group effort to provide integral systest data. utilizing GERDA test facility TUCKER. H B Duke Power Co 82/08/25 DENTON, H R Office of Nuclear Reactor Regulation, Director STOL Z. J F Operating Reactors Branch 4 lipp, 14695 076 24X Fiche 50-269,82/08/25,820B310236
- Q Inspection reports. IE Bulletins & correspondence
- 8208030599 Forwards IE Insp Repts 50-269/82-21.50-270/82-21 k 50-287/82-21 on 820614-18 No noncompliance noted LEWIS,R.C Division of Project & Resident Programs 82/07/09 PARKER,W O Duke Power Co 2pp 14162 313 24X Fiche 50-269.82/07/09.8208030599
- ---B208030613 IE Insp Repts 50-269/B2-21:50-270/B2-21 & 50-287/B2-21 on B20614-18 No noncompliance noted Major areas inspected review of chemistry & radiochemistry procedures & airborne affluent sampling & accountability EVANS, C D: MONTODMERY, D M Division of Emergency Preparedness & Operational Support B2/07/07 10pp, 14162 315 24X Fiche 50-269,82/07/09,8208030599
- B20B030548 Forwards IE Insp Repts 50-269/B2-26.50-270/B2-26 & 50-287/B2-26 on B20706-09 No noncompliance noted DANCE, H C Division of Project & Resident Programs B2/07/L4 PARKER, H O Duke Power Co 2pp 14162 096 24X Fiche 50-269.82/07/14.8208030548
- --B208030557 IE Insp Repts 50-269/82-26, 50-270/82-26 & 50-287/82-26 on 820706-09. No nencompliance noted Major areas inspected followsp of extraction steam line rupture GRDERB, W. PUCKETT, M. KLEINSORGE, W. Division of Project & Resident Programs 82/07/14 5pp 14162 098 24X Fiche 50-269, 82/07/14, 9208030548
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage." Svc list encl
 UORDAN.E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation," Syc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19, Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Fressure " Syc list encl UPONDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fichs 50-000: 82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Hater Leaking From U Hexafluoride Oysrpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194-321, 24X Fiche: 50-000; 82/07/22, 8204210398
- 820B160163 Forwards IE Insp Repts 50-269/82-24, 50-270/82-24 & 50-267/82-21 on 820614-25 No noncompliance noted DANCE.H.C Division of Project & Resident Programs 82/07/22 PARKER, W U Duke Power Co 2pp 14345 069, 24X Fichs. 50-269, 82/07/22, 8208160163.

- --8208160167 IE Insp Repts 50-269/82-24.50-270/82-24 & 50-287/82-21 on 820614-25 No noncompliance noted Major areas inspected Unit 3 10-yr inservice ultrasonic insp of steam generators, pressurizer reactor vessel & RCPB pipe COLEY. J L . ECONOMIS. N Division of Engineering & Technical Programs 82/07/19 7pp 14345 071 24X Fiche 50-269,82/07/22,8208160163
- 8204210401 IE Info Notice 82-28. "Mydrogen Esplosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 30-000, 62/07/23, 8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westingbouse PWRs " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24% Fiche 50-000.82/07/23.8204210402
- 8204210403 IE info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/26 Consolidate Edison Co of New York 12ipp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8208160194 Forwards IE Insp Repts 50-269/82-27, 30-270/82-27 & 30-287/82-27 on 820610-0715 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/07/26 PARKER, U Dute Power Co 2pp 14244 129 24% Fiche 50-269, 82/07/26, 8208160194
- --8208160202 IE Insp Repts 50-269/82-27,50-270/82-27 & 50-287/82-27 on 820610-0715 No noncompliance noted Major areas inspected operations sefety verification, surveillance testing, station maint activities & plant trips ORDERS, M. FALCOMER, D. BRYANT, J. Division of Project & Resident Programs 82/07/26 11pp 14344 131 24X Fiche 50-267,82/07/26,8208160194
- 8208030595 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-269/82-17, 50-270/82-17 bo-270/82-17 bo-270/82-17 LEHIS.R C Division of Project & Resident Programs 82/07/27 PARKER.H U Dute Power Co ip 14162 232 24X Fiche 50-269, 82/07/27, 8208030595
- --8208030607 Responds to NRC 820616 ltr re violations noted in IE Insp Repts 30-269/82-17.50-270/82-17 & 50-287/82-17 Corrective actions stronger door closure devices will be installed by 820915 & preventive maint program will be re-evaluated PARKER. H D Dute Power Co 82/07/16 O'REILLY. J P Region 2, Office of Director 2pp 14162 233 24X Fiche 50-269,82/07/27, 8208030595
- --8208030618 Forwards IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17 on 820510-14 & notice of violation DANCE.H C Division of Project & Resident Programs 82/06/16 PARKER.H O Dute Power Co 2pp 14162 235 24X Fiche 50-269, 82/07/27, 8208030393
- --8208030625 Notice of violation from insp on 820510-14 * Division of Project & Resident Programs 82/06/16 ip 14162 237 24% Fiche 50-269.82/07/27,8208030595
- --8208030636 IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17 on 820510-14 Noncompliance noted door providing access to radwaste compacting area found unlocked & positive access control not in effect CCLLINS.TR . BARR.K.P. Division of Engineering & Technical Programs, 82/06/10 Bpp 14162 238 24X Fiche 50-269,82/07/27,8208030595
- 8208160364 Forwards IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on 820712-16 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/07/27 PARKER.W O Dute Power Co 2pp 14349 041 24X Fiche 50-269, 82/07/27, 8208160364
- --820Bi60375 IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on B20712-16 No noncompliance noted Hajor areas inspected radiation protection shipment of radioactive matilipersonnel dosimetry.portable instrument callibr & review of LERs COLLINS.T R . BARR.K P Division of Engineering & Technical Programs 82/07/23 opp 14349 043 24X Fiche 50-249,82/07/27,8208160364
- B204210405 IE Info Notice B2-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list enc! JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405

- 820B160271 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants" Improved design gasket is ensite a ready for use to repair reactor coolant pump PARKER. W O Duke Power Co. 82/07/27 O'REILLY, J P Region 2, Office of Director 3pp 14344 255 24X Fiche 50-267, 82/07/29, 82/08/8291
- 8204210407 IE Infa Notice 82-27, "Fuel Rod Dogradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN-E L Division of Engineering & Quality Assurance 82/00/05 Consolidated Edison Co of New York 117pp 14368 201 24X Fiche 50-000,82/08/03.8204210407
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing cullective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13. UDELL,R A Critical Mass Energy Project 8pp 14679 200 24X Fiche 50-000,82/07/13,8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVBI" * NRC - No Betailed Affiliation Given 82/07/13 40pp 14677 216 24X Fiche 50-000,82/07/13.8208270010
- --8208270603 Forwards "Statistical Rept of Recorded Personnol Whole Body Exposures for CYB1," per 10CFR20 407
 PARKER,W D Duke Power Co 82/02/25 Diffice of Management and Program Analysis Ip 14679,340 24X Fiche 50-000,82/07/13,8208270010
- --8208270612 "Btatistical Rept of Recorded Personnel Whole Body Exposure: for CYBI " LEWIS/L Duke Power Co 82/02/25 ip 14679 341 24X Fiche 50-000, 82/07/13, 8208270010
- 8208170087 Forwards monthly operating repts for Jul 1992 TUCKER, H B Duke Power Co. 82/08/13 Director's Office, Office of Inspection and Enforcement Ip 14358 149 24X Fiche 50-269, 82/08/13, 8208170087
- --8208170091 Monthly operating repts for Jul 1982 REAVIS, J A Duke Power Co 82/08/13 15pp 14358 150, 24X Fiche 50-269,82/08/13,8208170087
- S Reportable occurrences, LERs & related correspondence
- 8208120271 Forwards LER 82-009/03L-0 Detailed event analysis encl PARKER, H O Duke Power Co 62/07/30 O'REILLY, J P Region 2, Office of Director 2pp 14326 335 24% Fiche 50-270.62/07/30, 8208120271
- --8208120275 LER 82-009/03L-0 on 820616.valve 2FDW-316 would not open fully Valve declared inoperable making emergency feedwater flowpath 20 inoperable Apparently caused by valve manual handukes being partially shut Handukes to be locked open KUTZER.J F Duke Power Co 82/07/27 Region 2, Office of Director ip 14326.337 24X Fiche 50-270.82/07/30.8208120271.
- 8208160284 RO 270/82-10 on 820722, util informed NRC that upper surge tank indicator read below Tech Spec min required water level investigation & preparation of rept incomplete Final review & rept expected by 820819
 TUCKER.H. B. Duke Power Co. 82/08/05 O'REILLY.J.P. Region 7, Office of Director. 1p. 14346-261 24X Fiche 50-270, 82/08/05, 8208160284.
- 9208270403 Forwards LER 92-010/01T-0 Detailed event analysis enci TUCKER.H. B Duke Power Co 92/09/13 D'REILLY, J.P. Region 2, Office of Director 3pp 14545; 118 24X Fiche 50-270, 92/08/13, 8208270403
- --8208270407 LER 82-010/01T-0 on 820722, while investigating erroneous instrument readings, upper surge tank water level found to be less than 5 ft Caused by stuck suction relief valve on main feedwater pump 28 Valve reseated Instrumentation repaired PETTY, J C. Duke Power Co 82/09/13 Region 2, Office of Director. 1p 14565-121 24X Fiche 50-270, 82/08/13, 8208270403

- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION
- F Security, medical, emergency & fire protection plans
- 8208030405 Forwards accident scenario package consisting of emergency plan exercise scenario.simulation list, emergency plan execution list & radiological data package, in response to NRC 811026 lfr Package withheld (ref 100FR2 790)
 SMITH.R L Vermont Yankoe Nuclear Power Corp 82/01/21
 HAYNESI R C Region 1. Philadelphia, Office of the Director (81/03/01) 2pp 14164 065 24X Ciche 50-271.82/01/21.8208030405
- 8208020187 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/07/13 Document Management Branch ip 14179 046 24X Fiche 50-271.82/07/13, 8208020187
- --B20B020188 Forwards public version of revised emergency plan implementing procedures. Including Procedures D P 3501 re alert. D P 3502 re site area emergency & O P 3503 re general emergency Receipt form enci MARKT, D I Vermont Yankse Nuclear Power Corp B2/06/30 Office of Nuclear Reactor Regulation, Director 1p 14179 047 24X Ficha 50-271, B2/07/13, B208020187
- --B208020189 Public version of revised emergency plan implementing procedures including Procedures D P 3501 re electio P 3502 re site area emergency & O P 3503 re general emergency Receipt form encl MURPHY. W P Vermont Yankes Nuclear Power Corp 82/06/29 9pp 14179 048 24X Fiche 50-271.82/07/13.8208020187
- B20B080440 Forwards IE Bafeguards Insp Rept 50-271/B2-10 on B20601-04 No noncompliance noted. MARTIN.T T Division of Engineering & Technical Programs B2/07/16 SINGLAIR.J B Yankee Atomic Electric Co 2pp 14218:006 24X Fiche 50-271:02/07/16:8208050440
- --820B050467 IE Safeguards Insp Rept 50-271/82-10 on 820601-04 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization testing & sys supply Details withheld (ref 10CFR73 21)
 SMITH, O H , DUNLAP, J, M Region 1, Office of Director GODY, A T Division of Engineering & Technical Programs 82/07/09 ip 14218 008 24X Fiche 50-271,82/07/14,8208050440
- 8208050264 Forwards IE Emergency Preparedness Appraisal Rept 30-271/82-05 on 820316-24 & emergency preparedness findings & improvement items EMITH.0 H Division of Emergency Preparedness & Operational Support 82/07/22 JACKSON.E W Vermont Yankes Nuclear Power Corp 14210 001 24X Fiche 50-271,82/07/22,8208050264
- --8209050267 IE Emergancy Preparedness Appraisal Rept 50-271/82-05 on 820316-24 Deficiencies noted augmentation goals of NUREO-0654 not met & post-accident sampling deficient MCKENNA, T. J. EP Licensing Branch, MOJTA, M. T. Division of Project & Resident Programs 82/06/30 62pp 14210 033, 24X Fiche 30-271, 82/07/22, 8208050264
- 8208090116 Confirmatory Action Ltr 82-13, informing NRC of corrective & preventive actions Request for extension to 820730 granted to complete incorporation of comments of VT state officials into new procedures
 SMITH.O H Division of Emergancy Preparedness & Operational Support.
 82/07/30 BINCLAIR, J B Vermont Yankes Nuclear Power Corp ip.
 14269 322 24X Fiche 50-271,82/07/30,8208090116
- --B20B090120 Requests extension to 820930 in order to further revise procedures & retrain operators Procedures were initially revised on 820602 Nocessary operator training initiated GUNHAY, M. F. Vermont Yankee Nuclear Power Corp. 82/07/16 HAVNES, R. C. Region 1. Office of Director 1p. 14269-323 24X Fiche 50-271, 82/07/30, 8208090116
- 820B300074 Grants extension requested in util 820B19 response to NRC 820722 ltr re IE Emergency Preparedness Appraisal Insp Rept 30-271/82-05, Apps A & B EMITH O H Division of Emergency Preparedness & Operational Support 82/08/25 SINCLAIR. J B Vermont Yankes Nuclear Power Corp 1p. 14598-302 24X Fiche 50-271.82/08/25.820B300074
- --8208300078 Requests extension to respond to 820722 IE Emergency Preparedness Appraisal Insp Rept 50-271/82-05. Apps A & B Requested info will be submitted by 820907 BINCLAIR, J. B Vermont Yankes Nuclear Power Corp. 82/08/19 BMITH. O H Division of Emergency Preparedness & Operational Support ip 14598 303, 24X Fichs 50-271.82/08/25.8208300074.

P Operating license stage documents & correspondence

- 8207080064 Ceneric ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Stv list encl
 DIRCKS.W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000, 82/07/02, 8207080064
- 8208050061 Forwards safety evaluation of util 820105 response to NUREO-0737. Item II K 3 24, "Adequacy of Space Cooling for HPCI & Reactor Core Isolation Cooling Sus "Item resolved VA6SALLO.D B Operating Reactors Branch 2 82/07/27 81NCLAIR.J B Vermont Yankes Nuclear Power Corp Jpp 14244 052 24X Fichs 30-271.82/07/27.8208050061
- B208240160 Requests add1 info.verifying satisfaction of encl acceptance criteria re NUREO-0737.ftem II K 3 22. "Automatic Switchover of Reactor Core Isolation Cooling Bys Suction " Response requested within 30 days VASSALLO,D B Operating Reactors Brench 2 B2/08/05 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 4pp 14548 173 24X Fiche 50-271.B2/08/05.B208240160
- B20B090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EIBENHUT, D G Division of Licensing 82/08/07 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- 8208140193 Ack receipt of 820530 ltr informing of results of iodine plate-out test, in response to NRC 820428 ltr Evaluation of amount of sample lost resulting from iodine plate-out will be submitted within 45 days of receipt of ltr SMITH, 0 H Division of Emergency Preparedness & Operational Support 82/08/09 SINCLAIR, J B Vermont Yankse Nuclear Power Corp. 2pp 14342 354 24X Fiche 50-271, 82/08/09, 8208160193
- B20B260514 Forwards request for add1 info re util proposal to extend operation w/presently installed feedwater spargers beyond 1983 refueling outage VABSALLO, D B Operating Reactors Branch 2 82/08/10 SINCLAIR, J B. Vermont Yankee Nuclear Power Corp 9pp 14579 281 24X Fichs 50-271, 82/08/10. 8208260514
- 8208240289 Releases reactor noise data tapes from Mar 1981 stability test to NRC & ORNL.per agreement reached at 820813 meeting w/NRC Affidavit supporting proprietary nature of info encl PFEFFERLEN.H C General Electric Co 82/08/13 BERLINGER.C H Care Performance Branch 5pp 14528 118 24X Fiche.50-271.82/08/13.8208240289
- B208230165 Application to amend License DPR-2B, revising Tech Spec Page 180-01 re max critical power ratio to reflect changes based on methodology per util 820331 ltr
 MEIDER, L H Vermont Yankes Nuclear Power Corp 82/08/19 Dêfice of Nuclear Reactor Regulation, Director 3pp. 14514 322 24X
 Fiche 50-271, 82/08/19, 8208230165
- --8208230170 Tech Spec Table 3 11-2 re max critical power ratio operating limits Updata to core performance analysis rapt, YAEC-1275, encl

 * Vermont Yankse Nuclear Power Corp 82/08/19 9pp 14514 325 24X Fiche 50-271,82/08/19,8208230165
- 8208270353 Advises that plant unique analysis for Mark I containment effort will be submitted by 820917 SINCLAIR, J B Varmont Yankes Nuclear Power Gorp 82/08/23 VASSALLO, D B Operating Reactors Branch 2 1p 14565 008 24X Fiche 50-271.82/08/23.8208270353
- O Inspection reports, IE Bulletins & correspondence
- B204210393 IE 1nfo Notice 62-23, "Main Steam Isolation Valve (MSIV)
 Leakage." Svc list encl
 JDRDAN,E L Division of Engineering & Quality Assurance 62/07/16.
 Consolidated Edison Co of New York 87pp 14356 274. 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8208050440 Forwards IE Sefeguards Insp Rept 50-271/82-10 on 820601-04.
 No noncompliance noted.
 MARTIN.T T Division of Engineering & Technical Programs 82/07/16
 BINGLAIR.J B Yankes Atomic Electric Co 2pp 14218-006 24X
 Fichs: 50-271, 82/07/16, 8208050440

- --8208050449 IE Safeguards Insp Rept 50-271/82-10 on 820601-04 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization testing & syssupply Details withheld (ref 10CFR73 21) SMITH.O H., DUNLAP.J M. Region 1. Office of Director ODDY, A.T. Division of Engineering & Technical Programs 82/07/09 1p 14218 008 24% Fichs 50-271.82/07/16.8208050440
- 8204210395 IE Info Notice 81-26.Part 3. Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " 8νc list enc!

 JORDAN, E L Division of Engineering & Quality Assurance β2/07/19

 Michigam. Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,
 8204210395
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list enc! JORDAN, E Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Byc list encl COBB.L! Division of Fuel Facilities, Haterials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14337 276 24X Fiche 50-000.82/07/20,8204210397
- 8204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Ethaust Check Valve Failures." Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208050264 Forwards IE Emergency Preparedness Appraisal Rept 50-271/82-05 on 820316-24 & amergency preparedness findings & improvement items 8/fifth.g.H Division of Emergency Preparedness & Operational Support 82/07/22 JACKSON,E H, Vermont Yankee Nuclear Power Corp 32pp. 14210 001 24X Fiche 50-271,82/07/22,8208050264
- --B208050269 IE Emergency Preparedness Appraisal Rept 50-271/82-05 on B20316-24 Deficiencies noted augmentation goals of NURCO-0654 not met & post-accident sampling deficient MCKENNA: T J EP Licensing Branch MOJTA: M T Division of Project & Resident Programs B2/06/30 62pp 14210 033 24X Fiche, 50-271, 82/07/22, B208050264
- 8204210401 IE Info Notice 82-28. "Hydragen Explosion Hhile Grinding in Vicinity of Drained & Open RCS " Svc list encl
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
 Consolidated Edison Co. of New York 122pp 14380 115 24X
 Fiche: 50-000, 82/07/23, 8204210401
- B204210402 IE Info Notice B2-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JCRDAW. EL Division of Engineering & Quality Assurance. B2/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche: 50-000. 82/07/23, 8204210402
- 82042:0403 IE Info Notice 82-30. "Loss of Thermal Bleeves in RCS Piping at Certain Restinghouse PNR Power Plants " Svc list encl JORDAN E.L. Division of Engineering & Guality Assurance 62/07/26 Consolidated Edison Co. of New York 121pp 14357-013 24X Fiche: 50-000. 82/07/26 8204210403.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl DRDAN,E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357:146 24X Fiche: 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingment " Svc list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co. of New York 117pp 14388 201 24X Fichs 50-000,82/08/05.8204210407
- 8208300074 Grants extension requested in util 820819 response to NRC 820722 ite re IE Emergency Preparedness Appraisal Insp Rept 50-271/82-05. Apps A & B 8MITH, G H Division of Emergency Preparedness & Operational Support 82/08/25 SINGLAIR. J B Vermont Yankee Nuclear Power Corp. 19 14398:302. 24X Fiche. 50-271, 82/08/25, 8208300074
- --B208300078 Requests extension to respond to B20722 IE Emergency Preparedness Appraisal Insp Rept 50-271/82-05, Apps A & B Requested info will be submitted by 820907 SINCLAIR, J. B. Vermont Yankse Nuclear Power Corp. 82/08/19 SMITH. O H. Division of Emergency Preparedness & Operational Support. 1p. 14598-303 24X Fiche 50-271,82/08/25,8208300074

- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Emergy Project 8pp 14679 208 24X Fiche 50-000,82/07/13,8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVB1" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000, 82/07/13,8208270010
- --8208270369 Forwards whole body range rept for CY81, per 10CFR20 40/ BMITH,R L. Vermont Yankee Nuclear Power Corp 82/02/22 HALLER,N M Office of Management and Program Analysis ip 14679 316 24X Fiche 50-000, 82/07/13,8208270010
- ~~8208270573 Whole body range rept for CY81

 Vermont Yankee Nuclear Power Corp 82/02/22, ip 14479 31/
 24% Fiche 50-000,82/07/13,8208270010
- 8208170174 Forwards monthly operating rept for Jul 1782 JACKBON, E W Vermont Yankes Nuclear Power Corp 82/08/13 Division of Data Automation & Management Information ip 14366 275 24X Fiche 50-271.82/08/13,8208170174
- --8208170196 Monthly operating rept for Jul 1982
 BURGER,F J Vermont Yankee Nuclear Power Corp 82/08/13 App
 14366 276 24X Fiche 50-271,82/08/13,8208170194,
- S Reportable occurrences, LERs & related correspondence
- 8208050259 Forwards LER 82-016/03L-0 MURPHY: W P Vermont Yankee Nuclear Power Corp 82/07/22 HAYNES: R C Region 1: Office of Director 1p 14210.104. 24X Fiche 30-271:82/07/22:8208050259
- --8208050263 LER 82-016/03L-0 on 820622.primary containment isolation valves were cycled on cold shutdown per surveillance procedure.contrary to Tech Specs Caused by failure to address proper surveillance requirement MURPHY.W P Vermont Yankee Nuclear Power Corp 82/07/22 Region I, Office of Director Zpp 14210 105 24X Fiche 50-271.82/07/22,8208050259
- U Congressional/Exacutive Correspondence
- 820B100370 Responds to B20421 ltr re alleged conditions near facility Airborne & waterborne radioactivity monitoring programs discussed. No reason exists to believe that there is any radiological impact on environ from operation of facility DIRCKS.W. J. Office of the Executive Director for Operations 82/07/19 HUMPHREY, 0. J. Benate 5pp 14308.331 24X Fiche 50-271.82/07/19.8208100370
- --8206200050 Requests response to encl magazine article from constituent re alleged cancer rate increase & agricultural abnormalities in vicinity of plant HUMPRRY, 0 J Senate 82/06/21 PALLADING, N J Commissioners. 12ps. 14308 335 24% Fiche 50-271,82/07/19,8208100370
- DOCKET 50-272 BALEM NUCLEAR GENERATING STATION, UNIT 1
 P Operating license stage documents & correspondence
- B2070B00b4 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Sty list encl
 DIRCKS, W J Gffice of the Executive Director for Operations
 B2/07/02 Consolidated Edison C of New York, 93pp 14194,001
 24X Fiche, 50-000, 82/07/02, 82070B0064
- 8208030101 Requests submittal documenting compliance w/criteria in NUREG-0737. Item II 8.3. "Post-Accident Bampling Bys " Criteria & guidelines to conduct NRC review encl VARQA,8 A Operating Reactors Branch 1. 82/07/12 UDERITZ.R A. Public Bervice Electric & Gas Co of New Jersey. 10pp 14196;354. 24X Fiche 50-272,82/07/12,8208030101
- 8208060021 Notification of 820726 meeting w/util in Hancocks Bridge:NJ to review component fouling problems associated w/entrainment of American oysters & review status of ETS.

 ROSS.W J. Operating Reactors Branch 1 82/07/19, VARGA, S. A Operating Reactors Branch 1 82/07/19, VARGA, S. A Fiche, 50-272, 82/07/19, 8208060021

- 8208040453 Forwards Amends 45 & 10 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance to & availability Amends provide undervoltage protection to emergency safety features actuation instrumentation sys ROSS, W J Operating Reactors Branch 1 82/07/23 UDERITZ,R A Public Service Electric & Oas Co of New Jersey 2pp 14220 263 24X Fiche 50-272.82/07/23.8208040453
- --8208040458 Amends 45 & 10 to Licenses DPR-70 & DPR-75, respectively, providing undervoltage protection to emergency safety features actuation instrumentation sys VARGA,S A Operating Reactors Branch 1 82/07/23 12pp 14220 265 24X Fiche 50-272,82/07/23,8208040453
- --8208040461 Safety evaluation supporting Amends 45 & 10 to Licenses PPR-70 & DPR-75, respectively * Office of Nuclear Reactor Regulation, Director 62/07/23 2pp 14220 277 24X Fiche 50-272,82/07/23,8208040453
- --8208040444 Notice of issuance & availability of Amends 45 & 10 to Licenses PPR-70 & DPR-75, respectively VARQA.5 A Operating Reactors Branch i 82/07/23 2pp 14220:279 24X Fiche 50-272,82/07/23,8208040453
- 8208110076 Advises that shift supervisor engineer considered to be acceptable equivalent to shift technical advisor, per util 820616 request Tech Spec should be revised accordingly. VARQA. B. A. Operating Reactors Branch i 82/07/29. UDERITI.R. A. Public Bervice Electric & Oas Co. of New Jersey 2pp 14327 361 24X Fiche 50-272,82/07/27,8208110096
- 8208190189 Forwards "Salam Nuclear Generating Station Unit 1, Gycle 4 Startup Test Rept " LIDEN.E A Public Service Electric & Oas Co of New Jersey 82/08/03 HAYMES.R C Region 1, Office of Director. 1p. 14387: QQ7 24X Fichu 50-272, 82/08/03, 8208190189
- --8208170174 "Belem Nuclear Generating Station Unit 1.Cycle 4 Startup Test Rept " JACKERON. J. CHILLEA.L K. AGEENFELD.E 8. Public Service Electric 4. Cas Co of New Jersey 82/08/03 31pp 14387 008 24X Fiche 50-272.82/08/03
- 8208090194 Generic Ltr B2-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl EIBENHUT, D, Q Division of Licensing B2/08/09 Convolidated Edison Co of New York Ip 14356 332, 24X Fiche 50-000, 82/08/09, 8208090194
- 820825019B Responds to NRC 820712 ltr re post-accident sampling/post-implementation review Post-accident sampling sys for each unit expected to be installed & operational prior to startup following upcoming refueling outage LIDEN, E. A., Public Service Electric & Gas Co of New Jersey. 82/08/13 VARGA, B. A. Operating Reactors Branch I. ip 14541,330 24X Ficher 50-272,82/08/13,8208250198
- 8208250097 Forwards summary of responses to NRC 820720 request for add1 info re auxiliary feedwater pump endurance test as discussed in 820818 conference call LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey 82708718 VAROA: B.A. Operating Reactors Branch 1, 2pp 14540-347 24X Fiche 50-272,82708/18,8208250097
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list enc! JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/16 Consolidated Edison Co. of New York 87pp 14356.274, 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice Bi-R6, Part 3, Buppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/19 Kichigan, Univ. of, 112pp. 14358.001 24X Fiche 50-000,82/07/19,8204210395
- 8204210396 IE Info Notice 8R-25, "Failures of Hiller Actuators Upon Oraqual Loss of Air Fressure " 8vc list encl JORDAN E. L Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co of New York 112pp. 14381 001 24X Fichs. 50-000, 82/07/20, 8204210394
- 8204210397 IE Info Notice BR-24, "Water Leaking From U Haxafluoride Overpacks." Byo list andl. COBB.L. I. Division of Fuel Facilities, Materials & Bafeguards. 82/07/20 Consolidated Edison Co of New York. 7ipp. 14357,276 24% Fiche. 50-000, 82/07/20, 8204210397.

- 8208040072 Requests submittal of insp program prior to 821016 refueling to prevent misinterpretation of Amend 43 re modified Tech Specs to provide alternative sampling method for steam generator tube insps
 NEIOHBORS-J D Operating Reactors Branch 1 82/07/20 UDERITZ,R A Public Service Electric & Oas Co of New Jersey 2pp 14228 285 24X Fiche 50-272,82/07/20,8208040072
- 8204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " 8vc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice B2-2B, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Yube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Figing at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 62/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8208020112 Responds to 820420 request for add1 info on postulated main steam line break inside containment (IE Bulletin 80-04) Add1 analysis beyond design basis not necessary LIDEN,E,A Public Service Electric & Gas Co of New Jersey 82/07/26 VARGA.B A Operating Reactors Branch i 2pp 14142-106 24X Fiche 50-000,82/07/26,8208020112
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance. 82/07/28 Consolidated Edison Co of New York 122pp 14357 146, 24X Fiche 50-000, 82/07/28, 8204210405
- B20B100162 Responds to Action Item 1 of IE Bulletin B2-02 re
 degradation of threaded fasteners in RGPB of PWR plants All
 word performed within confines of RGPB is accomplished per
 approved unitten maint procedures & vendor manuals
 LIDEN: E A Public Service Electric & Gas Co of New Jersey
 82/07/29 DEYQUNO, R C Director's Office. Office of Inspection and
 Enforcement 3pp 14298 030 24X Fiche. 80-272.82/07/29,8208100162
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Daffle Water-Jet Impingement" Svc list encl
 JORDAN.E L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co. of New York 117pp 14388, 201 24X
 Fiche 50-000.82/08/05.8204210407
- 820816006B Forwards fourth rept of exems & surveillances re integrity of piping sys containing stagnant borated water.per IE Circular 76-06
 LIDENSE A Public Service Electric & Oas Co of New Jersey.
 82/08/05 HAYNES, R C Region 1. Office of Director 3pp.
 14342 036 24% Fiche. 50-272.82/08/05.8208140068
- 8208300300 Forwards IE Insp Repts 50-272/82-17 & 50-311/82-17 on 820707-0803 & notice of violation STAROBIECKLIR Division of Project & Resident Programs 82/08/12, UDERITY, R A Public Service Electric & Gas Co of New Jersey. 2pp 14673 201 24X Fiche 50-272.82/08/12.8208300300
- ---B20B300313 Notice of violation from insp on B20707-0B03 BTAROSTECKI,R Division of Project & Resident Programs 82/0B/12 2pp. 14673,203 24X Fiche,50-272,82/0B/12,620B300300
- --8208300317 IE Insp Repts 50-272/82-17 & 50-311/82-17 on 820707-0803 Noncompliance noted no incident rept prepared for failure of vital ventilation control ctr feeder breaker 10 on 820623. NORRHOLM, J. SUMMERS, R., TRIPP, L. E. Division of Project & Resident Programs. 82/08/10 13pp. 14673 205 24X Fiche 50-272,82/08/12,8208300300
- 8208310358 Ack receipt of 820804 ltr informing NRC of steps taken to correct violation noted in IR Insp Repts 50-272/82-14 & 50-31/92-14 BTAROSTECKI.R Division of Project & Resident Programs, 82/08/26 UDERITZ, R. A Public Service Electric & Qas Co of New Jersey, ip. 14692, 123, 24% Fiche 50-272, 82/08/26, 8208310358

- --8208310366 Responds to NRC ltr re violation noted in IE Insp Rept 50-272/82-14. Corrective actions personnel will be retrained by 821001 re locking valves UDERITZ.R A Public Service Electric & Qas Co of New Jersey 82/08/04 HAYNES.R C Region 1. Office of Director STANOSTECKI.R Division of Project & Resident Programs 3pp 14672 124 24X Fiche.50-272,82/08/26,8208310358
- R Periodic operating reports & related correspondence
- B20B270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELYON.J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project Bpp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1 "
 * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000, 82/07/13, 8208270010.
- --B20827017& Forwards, "Annual Wholetady Exposures for CY81," per 10CFR20 407 2UPXG, J M Public Service Electric & Gas Co of New Jersey B2/01/29 Office of Management and Program Analysis 2pp 14679 269 24% Fiche 50-000,82/07/13,8208270010
- --B20B270586 Forwards errets to "Number Personnel & Man Rem by Job Function Rept for CYG1." personnel exposures ZUPKO, J M Public Bervice Electric & Qas Co of New Jersey B2/02/23 HAYNES, R C Region 1. Office of Director 2pp 14679 320 24X Fichs 50-000,82/07/13,820B270010
- ---B20B2705B9 Errata to "Number Personnel & Man Rem by Job Function Rept for CYB1 " * Public Bervice Electric & Gas Co of New Jersey 82/02/23. 4pp 14679 322 24% Fiche, 50-000: 82/07/13, 8208270010
- --8208270701 "Annual Whole Body Esposures for CY81"

 * Public Service Electric & Qas Co of New Jersey 62/01/29 1p,
 14679.270 24X Fiche 50-000.82/07/13.8208270010
- 3208160048 Forwards monthly operating rept for Unit 2 for Jul 1982 Also forwards corrected monthly operating repts for Unit 1 for Mar. Apr. May & June 1982
 MIDURA: H J Public Service Electric & Qas Co of New Jersey
 82/08/10 Director's Office, Office of Inspection and Enforcement,
 1p 14344:233 24% Fiche: 50-272,82/08/10,8208160048
- -8208160049 Monthly operating rept for Jul 1982 MILLER.L K Public Service Electric & Qas Co of New Jersey 82/08/10. 23pp 14344 234 24X Fiche 50-272,82/08/10,8208160048
- -8208160051 Corrected monthly operating rept for Mar 1982 MILLER,L K Public Service Electric & Gas Co of New Jersey 82/04/18 fp. 14344 287 24X Fiche 50-272,82/08/10,8208160048.
- -8208(5053 Corrected monthly operating rept for Apr 1982
 MILLER,L K Public Service Electric & Gas Co of New Jersey
 82/05/10, 1p, 14344 258 24X Fiche 50-272,82/08/10,8208160048.
- -8208160055 Corrected monthly operating rept for May 1982 MILLER, L K Public Service Electric & Oas Co of New Jersey 82/06/10 lp 14344 259. 24X Fiche 50-272,82/08/10,8208160048
- -8208660056 Corrected monthly operating rept for June 1982 MILLER,L K Public Service Electric & Cas Co of New Jersey. 82/07/10 1p 14344:260 24% Fiche 50-272,82/08/10,8208160048
- 208160085 Forwards monthly operating rept for Jul 1982 MIDMA.H. J Public Service Electric & Oas Co of New Jersey. 82/08/10 Director's Office, Office of Inspection and Enforcement ip 14342 073 24X Fiche: 50-272.82/08/10.8208160085
- 8208160089 Monthly operating rept for Jul 1982 MILLER,L,K. Public Service Electric & Qas Co of New Jersey 82/08/10 25pp 14342 074 24% Fiche 50-272,82/08/10,8208160085
- '08300217 Forwards NPDES discharge monitoring rapts for Jul 1982 MILLER-L K Public Service Electric & Gas Co of New Jarsey 82/08/18 BAKER.R A Environmental Protection Agency. 2pp. 14679 010, 24X Fiche: 50-272, 82/08/18
- 8208300219 NPDES discharge monitoring repts for Jul 1982 MILLER, L, K Public Service Electric & Qas Go, of New Jersey, 82/08/18 17pp, 14679 012 24X Fiche: 50-272, 82/08/18,8208300217.

- S Reportable occurrences, LERs & related correspondence
- 820802D137 Forwards LER 82-069/03X-1. Detailed event analysis encl MIDURALH J Public Bervice Electric & Gas Co of New Jersey 82/07/21 HAYNES.R C Region 1. Office of Director 3pp 14142 037 24X Fiche 50-272.82/07/21.8208020137
- --B208020141 LER B2-069/03X-1 on B20703,flow control valve 128H127 would not open Caused by marred valve tube bundle Tube bundle cut back to allow free movement Design change request implemented Valve 125H127 replaced w/naw design HELLER,R Public Service Electric & Gas Co of New Jersey B2/07/21 Region 1, Office of Director ip 14142 040 24X Fiche 50-272,02/07/21 8208020137
- 8208020315 Forwards LER 82-041/03L-0 Detailed event analysis ancl MIDURA,H J Public Service Electric & Oas Co of New Jersey 82/07/21 HAYNES,R C Region 1, Office of Director 4pp 14131-123 24X Fichs 50-272,82/07/21,8208020315
- --8208020327 LER 82-041/03L-0 on 820626, during routine insp, water discovered in charging pump 12 gear oil reservoir Caused by leak through gear oil cooler Cooler & oil replaced FRAHM, R Public Service Electric & Oas Co of New Jersey 82/07/21, Region 1, Office of Director ip 14151 127 24x Fiche 30-272,82/07/21,8208020315
- 8208050335 Forwards LER 82-005/01X-1 Detailed event analysis encl MIDURA,H J Public Service Electric & Gas Co of New Jersey 82/07/21 MAYNES,R C Region 1. Office of Director 3pp 14219 351. 24x Fichs. 50-272,88/07/21.8208050335
- --8208050344 LER 82-005/0iX-i on 820131, degradation of fuel cladding on fuel assembly C-04 discovered Caused by fuel lockup due to wedged fuel pellet Fuel assembly placed in spent fuel pit All C assemblies scheduled for reuse in core HELLER, R Public Bervice Electric & Gas Co of New Jersey 82/07/21 Region 1. Office of Director ip 14219 354 24X Fiche 50-272, 82/07/21, 8208050335
- 8208050492 Forwards LER 82-042/03L-0 Detailed event analysis encl HIDURAH J Public Service Electric & Oas Co of New Jersey 82/07/21 HAYNES, R C Region 1. Office of Director Spp 14214 105. 24% Fiche. 50-272, 82/07/21,8208050492
- --8208050509 LER B2-042/03L-0 on 82062B, valves discovered open & not properly locked. Caused by improperly locked valve upon completion of valve position verifications Review of incident incorporated into safety tagging training program HELLER, R Public Service Electric & Gas Co of New Jersey 82/07/21 Region 1. Office of Director. ip 14214.10B 24X Fiche: 50-272,82/07/21,8208050492
- 8208100010 Forwards LER 82-046/03L-0. Detailed event analysis encl MIDURAH J Public Service Electric & Oas Co of New Jersey. 82/07/28. HAYNES.R C Region 1. Office of Director 3pp 14274.287. 24X Fichs 50-272,82/07/28.8208100010
- ---B20B100018 LER 82-044/03L-O on 820712, two floor genetrations in control room found to be nonfunctional & not included in surveillance Caused by penetrations being left open at time of installation. Dennings seeled FRAHM.R Fublic Service Electric & Gas Co of New Jersey B2/07/2B. Region i. Office of Director ip 14294 270 24X Fich 50-272,82/07/28,820B100010
- 820B100079 Forwards LER 82-045/03L-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Gas Co of New Jersey 82/07/28 HAYNES, R C. Region 1. Office of Director Jpp 14277-286. 24X Ficher 50-272, 82/07/28, 820B100079
- ---8208100086 LER 82-048/03L-0 on 820710, sample from waste monitor tank 12 discarded before composite analysis could be performed. Caused by technician error Eample from similar release doubled composited FRAHM.R Public Service Electric & Gas Co of New Jarsey 82/07/28 Region 1. Office of Director 1p. 14297 289 24X Fiche. 50-272, 82/07/28, 8208100079
- B20B130113 Forwards LER 81-060/99X-1 Detailed event analysis encl-MIDURA, H. J. Public Bervice Electric & Gas Co of New Jersey. B2/07/28 HAYNES, R C. Region I. Office of Director 3pp 14333:288 24X Fiche:30-272, B2/07/28, B20B130113.
- --920B130117 LER 81-060/99X-1 on B10611, diesel fire suppression pump 2 failed to start in automatic mode Caused by shearing off of drive shaft counterweight gear Bhaft replaced HELLER,R. Public Bervice Electric & Gas Co. of New Jersey 82/07/28. Region 1, Office of Director. ip 14333,271, 24X fiche.50-272,82/07/28,8208130113

- 8208130249 Forwards LER 82-043/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Gos Co of New Jersey 92/07/28 HAYNES,R C Region 1. Office of Director 3pp 14333 110 24% Fiche 50-272,82/07/28,8208130249
- --8208130253 LER 82-043/03L-0 on 820704, control room operator received air particulate detector trouble alarm on Panel 1RP1. Caused by exhausted filter paper supply roll due to increased use of paper from clearing filter in fast mode Roll replaced HELLER, R Public Bervice Electric & Gas Co of New Jersey 82/07/28 Region 1. Office of Director 1p 14333 113 24X Fiche 30-272, 82/07/28, 8208130249
- 8208060327 Forwards incident reporting sys repts re spill of contaminated water & contamination of personnel in auxiliary bldg & failure of control rod guide tube support pins for transmittal to NEA MICHELSON. C Director's Office 82/07/29 LAFLEUR, J D Office of International Programs. Director 17pp 14281 234 24X Fiche 50-000.82/07/29.8208060327
- 8208180071 Forwards LER 82-050/03L-0 Detailed event analysis encl MEDURA.H. J Public Service Electric & Gas Co of New Jersey 82/08/06 HAYNES.R C. Region 1. Office of Director 3pp 14376,351 24% Fiche 50-272,82/08/06.8208180071
- --8208180080 LER 82-050/03L-0 on 820710. Atlantic loggerhead turtle impinged on circulating water sys intake tresh bar Turtle dead when collected Bys circulates large amounts of river water & dead/damaged turtles can easily be impinged FRAHM.R Public Service Electric & Cas Co. of New Jersey 82/08/06 Region i. Office of Director ip 14376-354, 24: Fiche 50-272, 82/08/06, 8200180071
- 6208260148 Forwards LER 81-053/03X-1 Detailed event analysis encl MIDURA:H J Public Service Electric & Gas Go of New Jersey, 82/08/12, HAYNES:R C. Region 1. Office of Director Spp 14555-345 24X Fiche. 50-272:82/08/12:8208260140.
- --B20B260153 LER 81-053/03X-1 on 810520.diesel generator IB 1/4-inch nipple on water jacket discovered leaking Caused by personnel using nipple for support Nipple replaced to generator tested HELLER, R Public Service Electric & Gas Co of New Jersey. 82/08/12. Region 1. Office of Director 1p 14555 348 24X Fiche 50-27g, 82/08/12.0208260148
- 8208250252 Forwards LER 92-047/03L-0 Detailed event analysis encl HIDURA,H J Public Service Electric & Gas Co of New Jersey 82/08/12 HAYNES,R C Region 1, Office of Director 3pp 14554 293. 24% Fiche.50-278,82/08/12,8208260252
- --B208260261 LER 82-047/03L-0'on 820726, containment plant vent monitor sample pump found de-energized & failed to start Supply breaker found tripped Cause undetermined Breaker reset & closed & pump successfully started from control room. FRAHM.R Public Service Electric & Oas Co of New Jersey 82/08/12 Region 1 Office of Director ip. 14554-296 24X Fiche 50-272,82/08/12,8208260252
- 8208250320 Forwards LER 82-049/03L-0 Detailed event analysis encl. HIDURA: H J. Public Bervice Electric t Oas Co of New Jersey B2/08/12 HAYNES; R. C Region 1, Office of Director 3pp 14555, 332 24% Fichs 50-272, 82/08/12; 8208260320
- --8208260323 LER B2-049/03L-0 on 820724.hot leg pressure wide range instrument indication read lower than ectual RCS pressure. Caused by failed printed circuit board in pressure transmitter Circuit board replaced & channel recalibr FRAHM.R Public Service Electric & Gas Co of New Jersey 82/08/12. Region 1. Office of Director. 1p. 14355-395. 24X Fiche 50-272,82/08/12.8208260320.
- 820B310285 Forwards LER 82-048/03L-0. Detailed event enalysis encl MIDURA: H J Public Bervice Electric & Oas Co, of New Jersey 82/08/12. HAYMER R C Region 1: Office of Director. Spp 14688:249 24X Fiche 50-272,82/08/12,828
- --8208310287 LER 82-048/03L-0.on 820724, inner door seel leakage of 100 ft elevation containment air lock door greater than Tech Bosc Caused by personnel closing door w/excesive force Seel replaced & personnel trained in proper door closing. HELLER,R. Public Service Electric & Oas Co. of New Jersey BZ/08/12. Region 1, Office of Director. 1p. 14688, 272. 24X Fiche: 50-272, 82/08/12,8208310285

- DOCKET 50-274 U B OEOLOGICAL BURVEY RESEARCH REACTOR

 Q Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/19 Hichigan
- 8208130209 Forwards IE Bafeguards Insp Rept 50-274/82-02 on 820614-15.
 No noncompliance noted Encl withheld (ref 10CFR2 790)
 MADBEN.O L Division of Resident, Reactor Project & Engineering
 Programs 82/08/10 MILLARD, H Interior. Dept of, Geological
 Survey 2pp 14333 001 24X Fiche 50-274,82/08/10,8208130209
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

 F Sacurity, medical, amergency & fire protection plans
- 8208310105 Forwards IE Emergency Preparedness Appraisal Repts 50-273/81-33 & 50-323/81-19 on 811207-17 ENGELKEN.R H Region 5, Office of Director. 82/07/08 CRANE, P A Pacific Oas & Electric Co 2pp 14689 319 24X Fichs. 50-275, 82/07/08, 8208310105
- ~~8208310113 IE Emergency Preparedness Appraisal Regts 50-275/81-33 & 50-323/81-19 on 811207-17, Deficiencies noted equipment, emergency plan implementing procedures & coordination w/offsite groups
 FIBH.R.F., SCOHN.K Region 5, Office of Director 82/07/07 51pp 14689:325 24X Fiche.50-275,82/07/08,8208310105
- 8208040527 Approves changes to physical security plan w/erception of items listed in encl.in response to 820827 ltr Revised pages to plan requested within 45 days of receipt of ltr HiRAGLIA,F J Licensing Branch 3. 82/07/30 GRANE,P Pacific Gas & Electric Co 2pp. 14220'344 24X Fiche 50-279,82/07/30,8208040527
- 820Bi10266 Releases public version of emergency plan implementing procedures
 FELTON.J M Division of Rules and Records. 82/08/05 Documen Hanagement Branch 1p 14331.151. 24X Fiche 50-275.82/08/05.820Bi10266
- --8208110269 Forwards public version of Vols 3A & 3B of emergency plan implementing procedures, including Procedures EP OP-14 rehigh activity in RCB. OP-23 renetural circulation of reactor coolant & EP R-1 re employee injury (radiological) OOLEBBY, D A Parific Oas & Electric Co. 82/07/29 ENGELKEN, R. H. Region 5. Office of Director. 4pp 14331 152 24X Fichs 50-275, 82/08/05, 8208110266
- --8208110275 Public version of Vols 3A & 38 of emergency plan implementing procedures, including Procedures EP OP-14 rehiph activity in RCS-0P-23 renatural circulation of reactor coolant & EP R-1 re employee injury (radiological) w Pacific Oas & Electric Co. 82/06/11 150pp 14331.156 RAX Fiche: 50-279.82/08/05.820811026
- 8208230019 Forwards Attechments A & B re changes implemented to Revision 11 of security plan Attachment A identifies & describes changes & B consists of replacement pages Encis withheld (ref 10CFR73 21)
 CRANE.P.A Pacific Oss & Electric Co 82/08/12 DENTON,H.R Office of Nuclear Reactor Regulation, Director 1p 14517:228 24X Fiche 50-275,82/08/12,8208230019

O. Adjudicatory correspondence

- 8206300352 Order CLI-82-7 deciding that definition of "several" does not warrant Commission review in context of proceeding Commission will re-evaluate design basis threat generically. CHILK, 8 J Office of the Escretary of the Commission 82/04/22 Commissioners, 4pp 14380:111 24X Fiche 50-275,82/04/22,8206300352.
- 8208020317 Order directing all copies of Order ALAB-653 be returned since order contains classified nabl security info.NRC will direct parties to return parts of underlying record which contains such info. CHILK.B. J. Office of the Secretary of the Commission. B2/07/29. Commissioners. 2pp. 14151:150. 24X Fiche:50-275.82/07/29. B208020317.

- 208030275 Order CLI-82-19 releasing public versions of ALAB-653 & Governor Brown 811013 petition for review of ALAB-653 Meaning of "several" as used in design basis threat of 10CFR73 1(a)(1) is safeguards info HDYLE, J C Office of the Secretary of the Commission 82/07/30-2pp 14155 354 24X Fiche 50-275,82/07/30,8208030275
- -8208030280 Public version of petition for review of ALAB-653 Decision is of first impression re meaning of Part 73 in contested proceeding & raises important & critical questions of law. Professing & releast amplication of Control of Svc BROWN, H H California, State of BROWN, H H Hill, Christopher & Phillips B1/10/13 Commissioners 13pp 14156 161 24X Fiche 50-275, 82/07/30, 8208030275
- POBOSO338 Comments on Teledyne Engineering Svcs 820618 Phase II Program Mgt Plan, per Commission invitation Commission should require listed specific changes to audit program REYNOLDS, J.R., FLEIBCHAKER, D. Center for Law in the Public Interest REYNOLDS, J.R. Joint Intervenors-Diable Canyon 82/08/02 PALLABINO, N. J., OILINBKY, V. AMERNE, J. Commissioners Spp 14219 344 24X Fiche 50-275.82/08/02,8208050338
- OB05053B Motion to reasen proceeding to take evidence on QA ABLB does not have info re implementation of QA program
 Certificate of Byc enc!
 BROWN.H H California. State of BROWN.H H Kirkpatrick, Lockhart,
 Hill, Christopher & Phillips 82/08/02 Atomic Safety and
 Licensing Board Panel 13pp 14213 288 24X Fiche 50-275,82/08/02,8208050538
- OBIIO148 Order granting extension until 820931 to comment on effect of expunction of classified matl from ALA8-653 & underlying
- or exponential of the Secretary of the Commission 82/08/09.

 California, State of 1p 14314 294 24x Fiche 50-275,82/08/09.
-)6(90)39 Response apposing Governor Brown 820802 motion to reopen ecord to take evidence on QA Commission 811119 action eaves ASLB v/o jurnsdiction to grant requested relief iertificate of 8vc encl
 IGATON.8 Pacific Gas & Electric Co NORTON.8 Norton, Burke, levry & French 82708/16 Atomic Sefety and Licensing Board lanel 23pp 14382 190 24X Fiche 50-275,62/08/16.8208190139
- 208190142 Affidavit of HB Friend re independent design verification program Prof qualifications encl FRIEND.HB Pacific Oas & Electric Co 82/08/13 8pp 14382 215 24X Fich# 50-275.82/08/16.8208190139
- 8200250 Request for hearing on util 820803 application for amend to icense DPR-76,which would renew low power license granted n 810921 & suspended on 811119 Certificate of Svc encl Canyon REYNOLDS, J R 82/08/17 n 810921 & suspended on BILLIY CETATIVES AND REYNOLDS, J R
 ENVOLDS, J R Jeint Intervenors-Diable Canyon REYNOLDS, J R
 enter for Law in the Public Interest 82/08/17 Commissioners
 typ 14399 316 24% Fiche 50-275.82/08/17.8208200250
- 3200262 Response supporting Governor Drown 820802 motion to reopen roceeding to take evidence on GA Outdated & obviously reneous findings re GA & seismic design should not stand intifficate of Svc enc!
 YNOLDS.J R Joint Intervenors-Diable Canyon REYNOLDS.J R meter for Law in the Public Interest 82/08/17, Atomic Safety the 50-275, 82/08/17, 8208200262
- 250241 Response apposing Governor Brown B20802 mation to reopen occeding to take evidence on GA Reopened hearing would hve no useful purpose Certificate of Byc enc1
 BBELL, D. F Hearing Branch i 62/08/23 Atomic Safety and censing Board Panel 17pp. 14542 332 24X Fiche 50-275,82/08/23,08230241
- 250356 Order extending time until 820914 for Commission to consider ther to review ALAB-BH ILK/8 J Office of the Secretary of the Commission 82/08/24 amissioners ip 14540 209 24X Fiche 50-275, 82/08/24.
- 310077 Errata to NRC 920823 response to Governor Brown motion to spen proceeding to take evidence on GA Certificate of Syc
- SELL, D F Hearing Branch (82/08/27. Atomic Gafety and ensing Board Panel 3pp. 14695 146 24X Fiche 50-275,82/08/27. 8310077

H General correspondence

- 8208030431 Advises that R Wray will serve as project manager during 80803-04 & 12-24

 COOPER, W. E. Teledyne Engineering Services 82/07/29 DENTON, H.R.
 Office of Nuclear Reactor Regulation, Director ENGELKEN, R.H.
 Region 5. Office of Director MANEATIS, O.A. Pacific Gas & Electric
 Co. 1p. 14154-142 24X Fich. 50-275,82/07/29,8208030431
- M Antitrust correspondence
- 8208180018 Discusses PGLE refusal to allow interconnection of Northern CA Power Agency geyser units w/Diablo Canyon units for testing purposes except under provisions in violation of license conditions

 MCDIARMID, R C Spiegel, G MCDIARMID, R C Northern Celifornia Power Agency, California, State of, 82/08/13 DENION, H R Diffice of Nuclear Reactor Regulation, Director Spp 14377 188 24% Fiche 50-275, 82/08/13, 8208180018
- P Operatino license stage documents & correspondence
- 8207070414 Forwards amended Order 82-24. "Waste Discharge Requirements 207070414 Forwards amended Order 82-24, "Waste Discharge Rei for PO&E, plablo Canyon Power Plant Units 1 & 2.5an Luís Obispo County & "Order 82-54 Amending NPDES Permit CAOO03751, Waste Discharge Requirements , "adopted 820611 JONES.K R Dept of Water Resources. California. State of, 82/06/30 MCMENZIE, J F Pacific Oas & Electric Co 30pp 13/39.088 24% Fiche 50-275.82/04/30:8207070414
- 8208020435 Forwards Teledyne Engineering Svcs B20518 independent design verification program, Phase II program mpt plan Comments due in 15 days W/o enri DENTON, HR Office of Nuclear Reactor Regulation, Director 82/07/08 BROWN E O California, State of. 5pp 14181 034 24X Fiche, 50-275, 82/07/08, 8208020435
- 8208020444 Forwards Teledyne Engineering Svcs 820518 independent design verification program. Phase II program mgt plan Comments due in 15 days W/o enci

 DENTON.H R Office of Nuclear Reactor Regulation, Director 82/07/08 REYNOLDS, J. PHILLIPS, J. R. Center for Law in the Public Interest Spp 14181 048 24% Fiche 50-275.82/07/08.8208020444
- 8208040532 Responds to 820615 ltr re concerns over amount of radiation & increase of tritium proposed for release into Pacific Ocean Required design measures taken to process contaminated liquid effluents to minimize release

 DENTON.H R. Office of Nuclear Reactor Regulation, Director

 82/07/21 JUNES.K R California, State of 23pp 14223 241 24X

 Fiche.50-275.82/07/21,8208040532
- --8206200027 Forwards CA Regional Water Quality Control Board 820119 & 0218 ltrs voicing concerns re increase in tritium over background levels & amount of radiation to be released to Pacific Ocean
 JONESI K R. California, State of 82/06/15 PALLADINO,N J ,
 AHEARNE, J , GILINSKY, V Commissioners ip 14223,264 24X
 Fiche 50-275,82/07/21,8208040532
- 8208190356 Informs that Commission will be briefed in late Aug 1482 re recommendations concerning Phase I & II of facility design verification program conducted per Order CLI 81-30 DIRCKS, M J Office of the Executive Director for Operations 82/07/27 PALLADINO, M, GILINSKY, V, AMERINE, R Commissioners 4pp 14504 132 24% Fiche 50-275,82/07/29,8208190356
- 8208050338 Comments on Teledyne Engineering Svcs 820618 Phase II Program Mgt Plan.per Commission invitation Commission should require listed apecific changes to audit program REYNOLDS.JR. FLEISCHAKER.D Center for Law in the Public Interest SEYNOLDS.JR. Joint Intervenors-Dlablo Canyon. 82/08/02 PALLADINO.N J. J. GILINSKY.V. A MEARNE.J. Commissionera 5pp 14219-344 24X Fiche 50-275.82/08/02.8208050338
- 820B1903BB Forwards request for addl info re GA program Info should be in form of marked revisions to GA program GA program approved contingent upon submittal of requested revisions H/o encl E18ENHUT.D G. Division of Licensing 82/08/02 CRANE.P.A Pacific EISENHUT, D 0, Division of Licensing 82/08/02 CRANE, P. A F Oas & Electric Co 1p 14506 097 24X Fiche 50-275, 82/08/02, 8208190388 Pacific
- 8208260362 Board Notification 82-80 forwarding thard interim technical rept, "Plablo Canyon Unit 1 Independent Design Verification Program Tanks"

 EISENHUT, D. Q Division of Licensing 82/08/02 PALLADINO, N J . oll INSKY, V. , AHEARNE, J Commissioners 3pp 14575 145 24X Fiche: 50-275, 82/08/02, 8208260362.

7

- 8208040204 Forwards License Amend Request 82-05 for License DPR-76 Amend changes expiration date of license from 1 yr from date of issuance to 2 yrs from date of issuance CRANE.P A Pacific Gas & Electric Co 82/08/03 DENTON.H R Dffice of Nuclear Reactor Regulation. Director 1p 14238 354 24X Fiche 90-275.82/08/03.8208060204.
- --8208060207 License Amend Request 82-05 for License DPR-76, changing expiration date of license from 1 yr from date of issuance to 2 yrs from date of issuance 8CHV/LER.J 0 Pacific Cas & Electric Co 62/08/03 2pp 14238 355 24X Fiche 50-275,82/08/03.8208060204
- B20R100218 Forwards "Balem Unit 1 17x17 Fuel Assembly," Jan 1982
 Rept adequately resolves question of guide tube wear for
 both units & satisfies NRC acceptability criteria
 CRANE, F A Pacific Cas & Electric Co 82/08/05 HIRAQLIA, F J
 Licensing Branch 3 ip 14297 040. 24X Fiche 50-275,82/08/05,
 820R100218
- 8208130069 Forwards Revision 0 to "Independent Design Verification Program Interface Between Independent Design Verification Frogram Participants & PG&E"
 CODPER, WE Teledyne Engineering Services 82/08/05, DENTON, H. R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R. H. Region 5, Office of Director MANEATIES, O.A. Pacific Cas & Electric Ca ip 14336 024 24% Fiche 80-275,82/08/05,8208130069
- ---820813007: "Independent Design Verification Program. Interface Between Independent Design Verification Program Participants & PCAE," Revision O. CODPER.H.E. Teledyne Engineering Services. 82/08/02. 11pp. 14336-025 24X Ficher 50-275, 82/08/05, 8208130069.
- B208270480 Staff requirements memo re 820729 affirmation/discussion session. Commission approved orders releasing samitized version of ALAB-653, reviewing ALAB-670 & denying patition to intervene in proceeding for mod of Pilgrim CL.

 KOYLE, J C Office of the Secretary of the Commission 82/08/06
 BICKHIT, L Office of the General Counsel. DIRCKH.W. J Office of the Executive Director for Operations 4pp. 14683:185. 24%
 Fiche. 50~000, 82/08/06, 8208270680
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC. Summarizes 100FR Chapter I requirements & provides alternatives to requirements. Svc list encl EIBENHUT, D Q Division of Licensing. 82/08/09 Consolidated Edison Co of New York 1p. 14356.332, 24X Fiche 50-000,82/08/09,8208090194
- 8208130075 Advises that upgrading of Class IE vent radioactive particulates & Gas Monitoring Bus RE-14 A & 8 & RE-28 A & B will be completed by 821130.per 811125 submittal CRANE, P A Facific Gas & Electric Co 82/08/09 MIRAGLIA, F J Licensing Branch 3, 1p 14336.037. 24X Fiche 50-275,82/08/09,8208130075
- 82082606i3 Forwards request for add1 info re analysis of containment annulus structure, as agreed in 920727 meeting at BML.
 HIRAGLIA,F J Licensing Branch 3. 82/09/11. REICH,M. Brookhaven
 National Laboratory 3pp 14547.357 24X Fiche 50-275,82/08/11.
- 820B170157 Advises that filing of application for amend to License DPR-76.extending expiration date for 1-yr.was timed to comply w/10CFR2.109
 CRANE.P A. Pacific Oas & Electric Co. 82/08/13. DENTON.H.R
 Office of Nuclear Reactor Regulation. Director 1p. 14364:209. 24X
 Fiche: 50-275.82/08/13.8208170157
- 9208170161 Forwards add1 info re GA program in response to NRC 820802 request. Encl consists of statements providing clarifications & revisions to 820618 submittel. Changes to submittel modify scape of GA program.

 CRANE.P A. Pacific Gas & Electric Co. 82/08/13 MIRAGLIA.F. J. Licensing Branch 3 20pp 14364: 274 24X Fiche: 50-275, 82/08/13, 8208170161
- 8208230336 Informs that no fixed implementation date for requirements of Milestone 7 to NUREG-0737. Item III A.2. 2 re description of Class B model, can be set until NRC clarifies meteorological & modeling sys requirements.

 CRANE, P A Pacific Cas & Electric Co. 82/08/16. MIRAGLIA.F. J. Licensing Branch 3. 2pp. 14508.326. 24X Fiche: 50-275, 82/08/16. 8208230336
- 8208230194 Forwards "Reactor Containment Bldg Integrated Leak Rate Test," for 820212-15. CRANE.F.A Pacific Gas & Electric Co. 82/08/18 MIRAQLIA.F.J. Licensing Branch 3 ip. 14513.234. 24X Fiche: 50-275, 82/08/18, 8208230194.

- ~-8208230204 "Reactor Containment Bldg Integrated Leak Rate Test," for 820212-15 * Pacific Gas & Electric Co 82/08/18 34pp 14513; 235 24X Fichy 50-273, 82/08/18, 8208230196
- 8208270204 Forwards Revision O to "Independent Design Verification Program Design Chain," interim technical rept DENISON,E Robert L. Cloud Associates, Inc. 82/08/19 DENTON,H.R Office of Nuclear Reactor Regulation, Director MANEATIS, G.A. Pacific Gas & Electric Co ENGELMEN,R.H. Region 5, Office of Director ip 14543:144, 24% Fiche: 50-275,82/08/19,8208270204.
- ~-8208270212 "Independent Design Varification Program Design Chain," Revision O DENISON,E Robert L Cloud Associates, Inc. P 105-4-839~005 ROO. 82/08/19 43pp 14563 145 24X Fiche 50-275,82/08/19,8208270204
- 8208310364 Requests info based on Teledyne understanding of util corrective action program in response to independent design verification & internal technical programs Util should provide addl detailed info on corrective action program. EISEMHUT.D 0 Division of Licensing 82/08/19. COOPER.W E Teledyne Engineering Services 4pp 14697:117. 24% Fiche: 50-273, 82/08/19, 8208310364.
- 8208250202 Forwards preliminary outline developed for final rept Phase I of design varification program Description of scope, criteria & methodology for certain corrective action program elements will be submitted by 820901.

 CRANE, P. A. Pacific Gas & Electric Co. 82/08/20 EISENHUT, D. G. Division of Licensing 17pp. 14541:340. 24X Fiche: 50-275, 82/08/20, 8208250202
- 8208310144 Advises that panel mounted instruments required for safe shutfown were replaced w/instruments qualified to operate submerged, per util 770914 & 1228 evaluations, Design change initiated, Gealent requirements removed, CRANE, P A Pacific Qas & Electric Co. 82/08/26, HIRAQLIA, F.J. Licensing Branch 3 ip 14693.179 24X Fiche 50-275.82/08/26, 8208310144.
- 8208310429 Requests concurrence w/util proposal to submit one Tech Spec change re mode to snubbers at conclusion of independent design verification program prior to fuel loading & plant operation.

 CRANE, P. A. Pacific Oas & Electric Co 82/08/27. HIRACLIA, F. J. Licensing Branch 3 Sp. 14692 066 24% Fiche 50-275, 62/08/27, 8208310429.
- Q Inspection reports, IE Bullstins & correspondence
- 8207080424 Forwards IE Insp Rept 50-275/82-19 on 820302-0604. No noncompliance noted STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs. 82/06/18 CRANE, P. A. Pacific Cas & Electric Ca. 2pp 13772 266. 24% Ficher 50-275, 82/06/16. 8207080424.
- --8207080426 IE Insp Rept 50-275/82-19 on 820502-0604 No noncompliance noted Major areas inspected; plant operations, surveillance testing, physical security, maint, LER followup & GA program, CARLSON, J. D., MENDONCA, M. M., YOUNG, T. Division of Resident, Reactor Project & Engineering Programs. 82/06/18, 4pp, 13772, 268. 24X Fiche: 50-275, 82/06/18, 8207080424
- 8208310105 Forwards IE Emergency Preparedness Appraisal Repts 50-275/81-33 & 50-323/81-19 on 811207-17. ENGELKEN, R. H. Region 5, Office of Director 82/07/08. CRANE, P. A. Pacific Que & Electric Co. 2pp. 14689:319, 24X Fiche: 50-275, 82/07/08, 8208310105.
- ---9208310113 IE Emergency Preparedness Appreisal Repts 50-275/81-33 & 50-323/81-19 on 811207-17, Deficiencies noted, equipment, emergency plan implementing procedures 4 coordination w/ offsite groups.
 FIGH.R.F. BCOMN.K. Region 5, Office of Director. 82/07/07.
 51pp 14689.325. 24X Fiche: 50-275,82/07/08,8208310105.
- 8204210393 IE Info Notice 82-23, "Main Bleem Isolation Valve (MSIV) Leakags." Bvc list encl. JORDAN,E L Division of Engineering & Quality Assurence 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356:274. 24%, Fiche: 50-000, 82/07/16, 8204210393.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure," Svc list encl, JORDAN, E. Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York, 112pp. 14381.001. 24X Fiche: 50-000. 82/07/20, 8204210396

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl CD8B.L I Division of Fuel Facilities, Materials & Safaguards 82/07/20 consolidated Edison Co of New York 7(pp 14357 270 24X Fiche 50-000.82/07/20.8204210397
- 8208030018 Discusses NRR 820526-28 seismic reverification program insp Major areas inspected Blume independent internal review of past Blume structural analyses, util document control manual & impacts of new project organization HERRING.K S Systematic Evaluation Program Branch 82/07/21 MIRAQLIA,F J Licensing Branch 3 7pp 14237 345 24X Fiche 50-275,82/07/21,8208030018
- --B208030020 Revision 2 to "Procedure for PO&E Evaluation of Review Comments Received From Blume Independent Internal Review "

 SCHUURMAN, A B , BETTINGER, R V , MODRE, G H Pacific Oas & Electric Co 82/04/17 6pp 14237 352 24% Fiche 50-275,82/07/21,8208030018
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208160309 Forwards IE Insp Rept 50-275/82-21 on 820606-0703 No noncompliance noted SYERNBERQ,D M Division of Resident, Reactor Project & Engineering Programs 82/07/22 CRANE,P A Pacific Oas & Electric Co App 14345 293 24X Fiche 50-275,82/07/22,8208160309
- --8208160314 IF Insp Rept 50-275/82-21 on 820606-0703 No noncompliance noted Major areas inspected plant operations, surveillance testing, physical security, maint, LER followup & licensee GA program, GARLSON, J D. MENDONGA, M M , YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/07/19 4pp 14345, 297 24% Fiche 50-275, 82/07/22, 8208160309
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rad Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PARs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- B204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PMR Fower Plants " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, B2/07/26, B204210403
- 8208160128 Forwards IE Insp Regts 50-275/82-22 & 50-323/82-11 on B20526-28 & 0628-0702 No noncompliance noted BISHOP.T.W Division of Resident, Reactor Project & Engineering Programs B2/07/27 CRANE.P A Pacific Gas & Electric Co App 14345 185 24X Fiche 50-275,82/07/27.8208160128
- --8208160127 IE Insp Repts 50-275/82-22 & 50-323/8R-11 on 820526-28 & OA28-0702 Na noncompliance noted Major areas inspected action on previous items, mods to piping & electrical raceway supports & Unit 2 vessel BURDOIN.J F . ECKHARDI.J H Division of Resident, Reactor Project & Engineering Programs 82/07/26 8pp 14345 189 24X Fiche 50-275,82/07/27,8208160128
- 0204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list enc! JORDAN-E L Division of Engineering & Quality Assurance 02/07/28 Consolidated Edison Co of New York 122pp 14357:146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208040305 IE Insp Repts 50-275/82-12 & 50-323/82-07 have been canceled BEIERLE.C. Region 5, Office of Director 82/07/28 Ip 14183 087, 24X Fiche.50-275,82/07/28,8208040305
- B208160466 Forwards IE Insp Repts 50-275/82-23 & 50-323/82-12 on B20721-23 No noncompliance noted B0DK,H E Division of Radiological Safety & Safeguards Program 82/07/30 CRANE,P.A Pacific Oss & Electric Co 4pp. 14348 220 24X Fiche,50-275,82/07/30.8208160466

- --8208160475 IE Insp Repts 50-275/82-23 & 50-323/82-12 on 820721-23 No noncompliance noted Major areas inspected followup on IE circulars, info notices & bulletins, preoperational testing & monitoring calibr NORTH, H S . WENSLANGKI, F. A . BOOK, H E Division of Radiological Barety & Safeguards Program 82/07/30 App 14348 224 24% Fiche 50-275, 82/07/30, 8208160466
- 820B16017B Responds to Action Item 3 of IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PMR Plants " No incidents of leakage in bolted closures evident Maint procedures specify FEL-PRO-M-500 per Westinghouse Itr SCHUYLER, J O Pacific Gas & Electric Go 82/08/02 ENGELKEN, R H Region 5. Office of Director 3pp 14345 051 24X Fiche 50-275,82/08/02,8208160178
- 8208160523 Forwards IE Insp Rept 50-275/82-24 on 820712-15 No noncompliance noted STERNBERG, D M Division of Resident, Reactor Project & Engineering Program 82/08/02 CRANE, P A Pacific Gas & Electric Co ip 14348 076 24X Fiche 50-275.82/08/02.8208160523
- --8208160525 IE Insp Rept 50-275/82-24 on 820712-15 No noncompliance noted Major areas inspected plant operations, onsite review committee & independent insp MORRILL.P J , YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/08/02 Jpp 14348 077 24X fiche 50-275,82/08/02,8208160523
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000,82/08/05,8204210407
- 8208200144 Forwards four inservice insp specific repair program plans to meet requirements of Section XI of ASME boiler & pressure vessel code CRANE, PA Pacific Gas & Electric Co 82/08/12 ENGELKEN, R H Region 5. Office of Director LEBLOW-R California. State of THOMPSON, C O Hartford Steam Soller Inspection & Insurance Co 2pp 14393 270 24X Fiche 50-275,82/08/12.8208200144
- --8208200148 "Relief Valve for Waste Gas Compressor Beal Water Cooler "
 # Pacific Gas & Electric Co 82/06/25 ip 14393 292 24X
 Ficha 50-275,82/08/12,8208200144
- --8208200150 "Auxiliary Saltwater Fressure Indicator PS-185A Isolation Valve " * Pacific Gas & Electric Co. 82/06/25 2pp 14393 293 24X Fiche 50-275,82/08/12,8208200144
- --8208200154 "Chemical & Vol Control Bys Cold Leg Loop Charging Valve 8108 "

 * Pacific Gas & Electric Co 82/06/25. 2pp 14393 295 24X Fiche 50-275,82/08/12,8208200144
- --8208200188 "Drain Stop Valves for RHR Pump 1-2 Loop 4 Cold Leg "
 4 Pacific Cas & Electric Co 82/07/21 ip 14393 297 24X
 Fiche 50-275,82/08/12,8208200144
- R Periodic operating reports & related correspondence
- 8208120072 Forwards monthly operating rept for June 1982 THORNERRY.R C Pacific Oas & Electric Co 82/07/06 Office of Resource Management: Director 2pp 14327.172 24X Fiche. 50-275. 82/07/04. 8208120072
- --8208120074 Monthly operating rept for June 1782 8COTT.W B Pacific Cas & Electric Co 82/07/02 3pp. 14327 174 24X Fiche: 50-275: 82/07/06: 8208120072
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A. Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000.82/07/13.8208270010
- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24% Fiche 50-000,82/07/13,8208270010
- 8208070333 Board Notification 82-76 forwards info re design verification program, consisting of semimonthly repts EIBENHUT, D. G. Division of Licensing. 82/07/22 PALLADIND, N. J. GILINBKY, V. AHEARNE, J. Commissioners 4pp 14308 001 24X Fiche 50-275, 82/07/22, 8208090333.

- 8208030273 Forwards Revision 1 to "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Semimonthly Rept "COVFER, W E Teledyne Engineering Services 82/07/29 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIB, 0 A Pacific Oas & Electric Co lp 14158 150 24% Fiche 50-275,82/07/29,8208030273
- --B208030274 Revision 1 to "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Semimonthly Rept " * Teledyne Engineering Services 82/07/27 53pp 14158 151 24% Fiche 50-275,62/07/29,8208030273
- 8208030376 Retracts independent design verification program semimonthly rept for Jul 1982, sent on 820726 Rept not necessary under Phase II program REEDY,R F R F Reedy. Inc 82/07/29 DENTON,H R Office of Nuclear Reactor Regulation. Director ENGELKEN,R H Region 5. Office of Director MNNATIS, G A Pacific Gas & Electric Ca. 2pp 14154 209 24X Fichs 50-275,82/07/29,8208030376
- 8208180025 Advises that no open item repts issued since Jul semimonthly rept
 SEBTAK, P Stone & Mubster Engineering Corp 92/08/12 DENTON, H R, Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS. 0 A Pacific Oas & Electric Co ip 14377 170 24% Fiche 50-275,82/08/12,8208180025
- 8208170270 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for Aug 1982 COOPER, W.E. Teledyna Engineering Bervices. 82/08/13 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R.H. Region 5, Office of Director MONEATIS, 9. A. Pacific Oas & Electric Co. 1p. 14369, 247 24X Fiche 50-275, 82/08/13, 8208170290
- --B208170291 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for Aug 1982 * Teledyne Engineering Services 62/08/13 100pp 14369:248 24X Fiche 50-275,82/08/13.8208170290
- 8208180035 Forwards Open Item Repts 1097, 1098 & 1097, Revision O.issued during Aug semimonthly reporting period DENISON, E. Robert L. Cloud Associates, Inc. 82/08/13 DENITON, H. R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R. H. Region 5, Office of Director MANEATIS, Q. A. Pacific Oss & Electric Co. 4pp. 14378:141 24X Fiche 50-275, 82/08/13, 8208180035
- B20B18010B Submits Semimonthly Rept 18 for 820710-0813 No open item repts issued Contractor personnel completed statement repotential or apparent conflicts of interest REEDY, R F R F Ready, Inc 82/08/13. DENTON, H R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5. Office of Director MNCATIS, Q A Pacific 0ss & Electric Co 3p 14378: 146 24X Fiche 50-275, 82/08/13, 8208180108
- 8208200267 Forwards nineteenth semimonthly status rept dtd 820813 re design verification program for 820719-0809 CRANE,P A Pacific Oas & Electric Co 82/08/13 DENTON,H R Office of Nuclear Reactor Regulation Director ENGELKEN,R H Region 5, Office of Director ip 14379 088 24X Fiche. 50-278, 82/08/13, 8208200267
- --8208200272 "PO&E Semimonthly Rept 19. Diablo Canyon Verification Program." # Pacific Qas & Electric Co. 82/08/13 43pp. 14399.089 24X Fiche: 50-275, 82/08/13.8208200267
- 8 Reportable occurrences: LERs & related correspondence
- 8208060030 Forwards incident reporting sys repts re effects of fire protection sys actuation on safety-related equipment & seismic qualification of safety-related sys for transmission to NEA.

 MICHELBON, C Director's Office 82/07/29 LAFLEUR, J D Office of International Programs, Director 21pp 14244:315 24X Fichs:80-000,82/07/29,8208060030
- B20B230071 Board Notification 82-86 forwarding Part 21 deficiency rept reservor in PIREBD computer program for piping analysis. EIBENNUT, D.O. Division of Licensing B2/08/17 PALLADINO, N.J., OILINBKY, V.V., AHEARNE, J.F., Commissioners 2pp. 14517:207 24X Fiche 30-275,82/08/17,8208230071
- --B20B230073 Part 21 rept re potential error in computer software program pIPERD for CYBERNET sys Revised version of program prepared Svc list encl STATON,O K. Control Data Corp 82/07/07 STELLO,V Regional Operations & Generic Requirements. 12pp 14517,207 24X Fiche 50-275,82/08/17,8208230071.

- DOCKET 50-274 GEORGIA TECH RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26.Part 3.Suppl i. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl
 JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19
 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210395
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8208040371 Releases public version of revisions to emergency plan implementing procedures FELTON. J M Division of Rules and Records 82/07/13 Document Management Branch ip 14224 062 24X Fiche 50-277, 82/07/13, 8208040374
- --B208040374 Forwards public version of revisions to emergency plan implementing procedures, including Procedures EP-C-320 re recovery phase implementation & EP-2034 1 re operation of post-accident sampling station
 DALTROFF, S L Philadelphia Electric Co B2/QA/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 14224 064 24X Fiche 50-277, 82/07/13,8208040371
- --8208040375 Public version of revision to emergency plan implementing procedures including Procedures EP-C-320 re recovery phase implementation & EP-205A 1 re operation of post-accident sampling station Philadelphia Electric Co. 82/06/11 110pp 14224 068 24X Fiche. 50-277,82/07/13,8208040371
- 8208050218 Forwards IE Insp Repts 50-277/82-12 & 50-278/82-12 on 820616 No noncompliance noted 8MITH.0 H Division of Emergency Preparedness & Operational Support 82/07/21 80YER.V S. Philadelphia Electric Co., 2pp 14209:317 24X Fiche 50-277.82/07/21.8208050218
- --B208050225 IE Insp Repts 50-277/82-12 & 50-278/82-12 on 820616. No noncompliance noted Major areas inspected emergency preparedness exercise TERG, N, M, CROCKER, H W Division of Emergency Preparedness & Operational Support 82/07/19 10pp 14209 319 24X Fiche: 50-277, 82/07/21, 8208050218
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CP re Commission approved tharter for CROR. Svc list encl
 DIRCKS:N J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000, 82/07/02, 8207080064.
- 8208020451 Summarizes status of NRC review of NUREO-0737, Item II. 6 4 2 re containment purging & venting 816 encl for guidance in completing item Info on purga/vent valve leakage tests also encl 870L7. J F Operating Reactors Branch 4 82/07/07 BAUER, E. 9 Philadelphia Electric Co 6pp. 14180 172 24X Fiche 50-277, 82/07/07, 8208020451
- --8208020454 Draft safety evaluation for containment purging & venting during normal operation Add1 info required before review of purge/vent sys can be completed e NRC No Detailed Affiliation Given 82/07/07 5pp 14180
- B208040378 Forwards revised model Techs Specs re reactor protection syspower monitoring sys design mod STOLZ.JF Operating Reactors Branch 4 82/07/19. BAUER.E OPhiladelphia Electric Co 2pp 14224 187. 24x Fichs. 50-277, B2/07/19, 8208040378
- --B208040379 Revised model Tech Spacs 3/4 8.4 4 re electrical power sys reactor protection sys electric power monitoring. * NRC - No Detailed Affiliation Given B2/07/19 ip 14224 189. 24X Fiche: 50-277,82/07/19,8208040378
- B20B060357 B0CIDECONOMIC IMPACTS DF NUCLEAR GENERATING STATIONS PEACH B0TTOM CASE BTUDY. Docket Nos 50-277 And 50-278 (Philadelphia Electric Company) PIJANKA, K D. Hountain West Research, Inc. # Social Impact Research, Inc. FIN B-6269 NUREO/CR-2749 VOB 82/07/31 Division of Health, Biting & Environment. 215pp. Available at NTIS 47 00 14272 143 24X Fiche 50-277.82/07/31,8208060357.

- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Sv list end!
 EISENHUT, D @ Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- B20B200065 Requests withdrawal of 820B06 application for amends to Licenses DPR-44 & DPR-56 Application submitted 770301 will be amended later this yr to reflect guidance contained in Tech Spec for gaseous radiation monitors DALTROFF.S L. Philadelphia Electric Co B2/08/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 14392 219 24X Fichs 50-277.82/08/16.8208200065
- 8208270689 Informs that review of NUREG-0737. Item II K 3 15, "Mod Break Detection Logic HPCI/Reactor Core Isolation Cooling," completed Reactor core isolation cooling sys adequate Safety evaluation encl
 STOLZ.JF Operating Reactors Branch 4 82/08/17 BAUER.E G
 Philadelphia Electric Co 4pp 14683 065 24X
 Fiche 50-277.82/08/17,8208270689
- 8208310096 Forwards summary rept of util efforts & findings re TMI Item II E 4 2 on containment purge & vent sys.per 820707 request for info DALTROFF, S L. Philadelphia Electric Co 82/08/26 STDLZ, J F Operating Reactors Branch 4 15pp 14689 303 24X Fiche 50-277, 82/08/26, 8208310096
- A inspection reports. IE Bulletins & correspondence
- 8206270075 FOIA request for sections of IE Insp Repts 30-277/81-07 & 50-278/81-09 not containing 10CFR2 790 info SPECTOR.C Technical Analysis Corp 81/06/29 Office of Administration ip 14528 133 24X Fichs 50-277.82/06/29, 820627075
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list enc! JORDAN-E L Division of Engineering & Guality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Syc list encl JORDAN. E L Division of Engineering & Quality Assurance 82/07/19 Michigan. Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210395
- 8208020264 Forwards IE Insp Repts 50-277/82-08 & 50-278/82-08 on 820426-29 & 0513-14 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 82/07/19 DALTROFF.S L Philadelphia Electric Go 2pp 14152 263 24X Fiche:50-277, 82/07/19, 8208020264
- --B208020270 Natice of violation from insp on B20426-29 & 0513-14, MARTIN.T T Division of Engineering & Technical Programs 82/07/19 2pp 14152 265 24X Fiche 50-277.82/07/19,8208020264.
- --8208020278 IE insp Repts 90-277/82-08 & 50-278/82-08 on 820426-29 & 0313-14 Nancampliance noted failure to follow radiation protection procedures: to perform surveys & to instruct workers on radiation conditions

 NIMITZ.R L . ROME: C A . OREENMAN.E Q Division of Engineering & Technical Programs 82/07/16 26pp 14152 267 24x

 Flehe 50-277,82/07/19,8208020204
- 8208230444 Responds to FOIA request for sections of IE Insp Repts 50-277/82-07 to 50-278/82-09 not containing 10CFR2 790 info Forwards requested info Documents also available in PDR. FELTON.J M Division of Rules and Records 82/07/19 ROSENBAUM.D Technical Analysis Corp ip. 14328 134 24x Fiche 50-277.82/07/19, 8208230444
- --8208230467 Nonproprietary version of notice of violation from insp on Bl0301-0407 BRUNNER,E. J. Division of Resident & Project Inspection B1/07/01 Spp. 14328:138 24X Fiche 50-277.82/07/19,8208230444
- --8208230470 Nonproprietary version of notice of violation from insp on 810301-0407. BRUNNER,E J Division of Resident & Project Inspection 81/07/01 1p 14528 141. 24X Fiche 50-277,82/07/19,8208230444

- --8208230473 Nunproprietary version of IE Insp Repts 50-277/81-07 & 50-278/81-09 on Bio301-0407 Noncompliance instead failure to have adequate radwaste collection procedures & to follow administrative procedures for mods COMOILL, C J , BLOUGH, A R , REYNOLDS, S D Reactor Projects Section 28 Bi/06/01 Sipp 14528 142 24X Fiche 50-277, 82/07/19, 8208230444
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- B204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fich# 50-000,82/07/20,8204210397
- 8208050218 Forwards IE Insp Repts 50-277/82-12 & 50-278/82-12 on 820616 No noncompliance noted SHITM, 0 H Division of Emergency Preparedness & Operational Support, 82/07/21 80YER, V & Philadelphia Electric Co 2pp 14209, 317 24X Fichs 50-277, 82/07/21, 8208050218
- --8208050225 IE Insp Repts 50-277/82-12 & 50-278/82-12 on 820616 No noncompliance noted Major areas inspected emergency preparedness exercise

 TERC, N M . CROCKER, H W Division of Emergency Preparedness & Operational Support 82/07/19 10pp 14209 317 24X Fichs 50-277,82/07/21,8208050218
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Bvc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000.82/07/22.8204210398
- 820421040i IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl URDANNE L Division of Engineering & Quality Assurance 62/07/23, Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guida Yuhe Support Pin Failures at Westinghouse PWRs " Svc list and JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp. 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Blauves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 12ipp 14357 013, 24K Fichs 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN E. L Division of Engineering & Guality Assurance. 82/07/28 Consolidated Edison Co of New York, 122pp 14357 146, 24X Fichw 50-000,82/07/28,8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Dagradation Resulting From Baffle Water-Jot Impingement" Svc list encl
 JORDAN.E L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche: 50-000.82/08/05,8204210407
- 8208300049 Forwards IE Enforcement Conference Repts 50-277/82-17 & 50-278/82-15 on 820722
 STARGETECKIR Division of Project & Resident Programs 82/08/10 DALTROFF, B L Philadelphia Electric Co 2pp 14598 297 24K Fiche 50-277, 82/08/10, 8208300049
- --B208300051 IE Enforcement Conference Repts 50-277/B2-17 & 50-278/82-15 on B20722 No noncompliance noted Major areas discussed findings of previous inspire health physics program & primary containment integrity BLOUGH, A.R., MCCABE, E.G. Division of Project & Resident Programs, 82/08/04 3pp 14598; 299 24X Ficher 50-277, B2/08/10, 8208300049,
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R.A. Critical Mass Energy Project 8pp 14679, 208, 24X Fiche 30-000, 82/07/13, 8208270010

- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000, 82/07/13, 8208270010
- 8208190078 Forwards monthly operating repts for Jul 1982 COONEY, M J Philadelphia Electric Co 82/08/13 Director's Office, Office of Inspection and Enforcement 1p 14383 164 24X Fiche: 50-277, 82/08/13, 8208190098
- --8208190102 Monthly operating repts for Jul 1982 ALDEN.W H Philadelphia Electric Co 82/08/11 9pp 14383 145 24% Fichs 30-277,82/08/13,8208190098
- S Reportable occurrences, LERs & related correspondence
- 8208050317 Forwards LERs 82-015/01T-0 & 82-016/01T-0 Detailed event analysis submitted COONEY, M J Philadelphia Electric Co 82/07/16 HAYNES, R C Region 1, Office of Director. 3pp 14237 315 24X Fiche 50-277, 82/07/16, 8208050317
- --8208050321 LER 82-015/01T-0 on 820703, operator observed no steam flow indication on D main steam line Caused by equalizing valve being left open as result of instrument work done during outage Instrument checked to verify proper valving COONEY, M J Philadelphia Electric Co 82/07/16 Region 1. Office of Director ip 14237 318 24X Ficha 50-277,82/07/16,8208030317
- --8208050325 LER 82-016/01T-0 on 820709, operator observed discrepancy between indication of 1 of 4 A main steam line high flow trip transmitters & other 3 Caused by equalizing valve left open following instrument work during outage COONEY, M J Philadelphia Electric Co 82/07/16 Region 1. Office of Director 1p 14237 319 24X Fiche 50-277.82/07/16. 8208080317.
- 820Bi00147 LER 82-014/03L-0 on 82070; after installation of modified printed circuit board on drywell pressure transmitter PT 250BA lost signal, Caused by blown fuse due to new board Original board reinstalled COONEY. M J Philadelphia Electric Co. 82/07/31. HAYNEB, R. C Region 1. Office of Director ip. 14297:217 24K Fiche 50-277,82/07/31,8208100147
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
 F Security, medical, emergency & fire protection plans
- 8208040371 Releases public version of revisions to emergency plan implementing procedures FELTON.J.M Division of Rules and Records 82/07/13 Document Management Branch. ip. 14224 062, 24X Fiche; 50-277, 82/07/13, 8208040371.
- --B208040374 Forwards public version of revisions to emergency plan implementing procedures including Procedures EP-C-320 re recovery phase implementation & EP-205A i re operation of post-accident sampling station.

 DALTROFF, S. L. Philadelphia Electric Co. 82/06/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp 14224,064 24X Pichs 50-277,82/07/13,8208040371
- --8208040375 Public version of revision to emergency plan implementing procedures including Procedures EP-C-320 re recovery phase implementation & EP-203A I re operation of post-accident sampling station.

 * Philadelphia Electric Co. 82/06/11. 110pp 14224.068 24X Fiche 50-277, 82/07/13.8208040371
- 8208050218 Forwards IE Insp Repts 50-277/82-12 & 50-278/82-12 on 820816 No noncompliance noted.
 8MITH, G, H Division of Emergency Preparedness & Operational Support 82/07/21 BOYER, V.8 Philadelphia Electric Co 2pp 14209-317 24X Fiche: 50-277, 82/07/21, 8208050218.
- ---8208050225 IE Insp Rapts 50-277/82-12 & 50-278/82-12 on 820616. No noncompliance noted Major areas inspected emergency preparedness exercise.

 TERC: N M Division of Emergency Preparedness & Operational Bupport. 82/07/19 10pp. 14209 319. 24X Fiche: 50-277: 82/07/21. 8208090218

- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CP re Commission approved charter for CRGR Svc list and DIRCKS.W J Office of the Executive Director for Operations B2/07/02 Consolidated Edison Co of New York 93pp 14194-001 24X Fiche 50-000, B2/07/02, 82070810064
- 8208020451 Summarizes status of NRC review of NUREO-0737, Item II E 4,2 re containment purging & venting STS encl for guidance in completing item Info on purge/vent valve leakage tests also encl
 STOLZ, J P Operating Reactors Branch 4 82/07/07 BAUER, E Q
 Philadelphia Electric Co App 14180 172 24X
 Fiche 50-277, 82/07/07, 8208020451
- --8208020454 Draft safety evaluation for containment purging & venting during normal operation Addl info required before review of purge/vent sys can be completed * NRC No Detailed Affiliation Given 82/07/07 5pp 14180 178 24X Fiche 50-277.82/07/07.8208020451
- 8208040378 Forwards revised model Techs Specs re reactor protection syspower monitoring sysdesign mod 870LZ.J F Operating Reactors Branch 4 82/07/19 BAUER,E & Philadelphia Electric Co 2pp. 14224 187 24X Fichs. 50-277. 82/07/19. 8208040378.
- --8208040379 Revised model Tach Specs 3/4.8 4 4 re electrical power systemator protection systemators power manitoring **NRC No Detailed Affiliation Given 82/07/19 ip 14224:189, 24X Fiche 50-277.82/07/19.8208040378
- B208130041 Forwards Amend B5 to License DPR-56, safety evaluation k notice of issuance & availability Amend changes Tech Bpec to amend min critical power ratios during mid-Cycle 5 operation FAIRTILE, M B Operating Reactors Branch 4 B2/07/29, BAUER, E, Q, Philadelphia Electric Co 2pp 14340 275 24X Fiche, 50-278, 82/07/29, 8208130041
- ---8208130043 Amend 85 to License DPR-56, changing Tech Spec to amend min critical power ratios during mid-Cycle 5 operation STOLZ.J.F. Operating Reactors Branch 4 82/07/29, 7pp 14340:297 24X Fiche: 50-278, 82/07/29, 8208130041
- --8208130047 Safety evaluation supporting Amend 85 to License DPR-56 * Office of Nuclear Reactor Regulation, Director 82/07/29 4pp 14340 304 24X Fiche 50-278,82/07/29,8208130041,
- --8208130067 Notice of issuance & availability of Amand 85 to License ppR-54
 MINER.8 Operating Reactors Branch 4 82/07/29 2pp 14340.308
 24X Fiche 50-278.82/07/29.8208130041
- 8208060357 BGCIDECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS.PEACH BOTTOM CASE STUDY Docket Nos 50-277 And 50-278 (Philadelphia Electric Company) PIJAHKA: K D Mountain West Research, Inc. * Social Impact Research, Inc. FIN B-6268 NUREQ/CR-2749 VOS 82/07/31 Division of Health, Siting & Environment 215pp Available at NTIS \$7 00 14272.143, 24% Fiche 30-277.82/07/31.8208060357
- 8208090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittel of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Sur list encl.
 EISENHUT.D.O Division of Licensing, 82/08/09 Consulidated Edison Co of New York Ip 14356-332 24X Fiche, 50-000, 82/08/09, 8208090194.
- 8208200065 Requests withdrawal of 820806 application for amends to Licenses DPR-44 & DPR-56. Application submitted 790301 will be amended later this yr to reflect guidance contained in Tech Spac for gaseous radiation monitors DALTROFF,S L. Philadelphia Electric Co 82/08/16 DENTON,H.R Office of Nuclear Reactor Regulation, Director 2pp 14392, 219, 24% Fichs, 50-277, 82/08/16, 8208200065
- 8208270689 Informs that review of NUREO-0737, Item II K 3 15, "Mod Break Detection Logic HPCI/Reactor Core Isolation Cooling," completed, Reactor core isolation cooling sys adequate Safety evaluation encil STOLZ, J. F. Operating Reactors Breach 4, 82/08/17 BAUER, E. 9. Philadelphia Electric Co. 4pp. 14683, 045 24X Fiche: 50-277, 82/08/17, 8208270687.

- 8208310096 Forwards summary rept of util efforts & findings re IMI Item II E 4 2 on containment purge & vent sys.per 820707 request for info DALTROFF, St. Philadelphia Electric Co 82/08/26 STOLZ, J F Operating Reactors Branch 4 13pp 14689 303 24x Fiche 50-277, 82/08/26, 8208310096
- G Inspection reports, IE Bulletins & correspondence
- 8206270075 FOIA request for sections of IE Insp Repts 50-277/81-07 & 50-278/81-07 not containing 100FR2 790 info SFECTOR.C Technical Analysis Corp 81/06/27 Office of Administration ip 14528 133 24X Fiche 50-277, 82/06/29, 8206270075
- 8204210373 [E Info Notice 82-23, "Main Steam Isolation Valve (M8IV) Leatage " Svc list enr! JORDAN, E Division of Engineering & Quality Assurance 82/07/16 Consolidates Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 [E Info Notice 81-26.Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Styr list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395
- 8208020264 Forwards IE Insp Repts 50-277/82-08 & 50-278/82-08 on 820424-29 & 0513-14 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 82/07/19 DALTROFF, S L Philadelphia Electric Co 2pp 14152-263 24X Fiche.50-277, 82/07/19, 8208020264
- --8208020270 Notice of vialation from insp on 820426-27 & 0513-14 MARTIN,T.T Division of Engineering & Technical Programs 82/07/19 2pp 14152-265 24% Fiche 50-277,82/07/19,8208020264
- --6208020278 IE Insp Repts 50-277/82-08 & 50-278/82-08 on B20426-29 & O513-14 Noncompliance noted failure to follow radiation protection pracedures, to perform surveys & to instruct workers on radiation conditions
 NIMITZ:R L , ROME.C A , OREENMAN E O Division of Engineering & Technical Programs 82/07/14 26pp 14152 267 24%
 Fiche 50-277,82/07/19,8208020264
- 8208230444 Responds to FOIA request for sections of IE Insp Repts 50-277/82-07 & 50-278/82-09 not containing 10CFR2 790 info Forwards requested info Documents also available in PDR FELTON, J H. Division of Rules and Records 82/07/19 ROSENBAUM, D. Tachnical Analysis Corp 1p 14528 134 24X Fiche 50-277, 82/07/19, 82082030444,
- --BR08230467 Nonproprietary version of notice of violation from insp an 810301-0407 BRUNNER, E J Division of Resident & Project Inspection 81/07/01 3pp 14528 138 24% Fiche 50-277,82/07/19,8208230444
- --8208230470 Nonproprietary version of notice of violation from insp on 810301-0407

 BRUNNER, E. J. Division of Resident & Project Inspection 81/07/01

 1p 14528-141 24X Fiche 50-277, 82/07/17, 8208230444
- --8208230473 Nonproprietary version of IE Insp Repts 50-277/81-07 & 50-276/81-09 on 810301-0407 Noncompliance noted failure to have adequate radueste collection procedures & to follow administrative procedures for mods CQMOILL.C J . BLDUOH.A R . REYNOLDS, S.D. Reactor Projects Section 23 81/06/01 31pp 14528 142 24% Fiche 50-277,82/07/19, 8208230444
 - 210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon adval Loss of Air Fressure " Svc Iist enc! "RDAN E L Division of Engineering & Gwality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24% Fiche 50-000, 82/07/20, 8204210376
 -)4210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride verpacks" Svc list encl.
 1881.L. I. Division of Fuel Facilities, Materials & Safeguards 2/07/20 Consolidated Edison Co. of New York, 71pp 14337 272
 - .d050218 Forwards IE Insp Repts 50-277/82-12 & 50-278/82-12 on 120616 No noncompliance noted.

 MITH.6.H. Division of Emergency Preparedness & Operational Support 82/07/21 BOYER.V S. Philadelphia Electric Co 2pp 14209 317.

- ~-8208050225 lE Insp Repts 50-277/82-12 & 50-278/82-12 on 820616 No noncompliance noted Major areas inspected emergency preparedness exercise
 TERC:N M : CRUCKER:H W Division of Emergency Preparedness & Operational Support 82/07/19 10pp 14209 319 24X
 Fiche 50-277,82/07/21,8208050218
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Buc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of Now York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23. Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23.8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failurgs at Westinghouse PWRs " Svr list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 62-30, "Loss of Thermal Sleeves in RCS Piping at Cartain Westinghouse PWR Power Plants" Svt list encl JGRDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24X Fichs 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice B2-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list and!
 JORDAN: E L Division of Engineering & Quality Assurance 82/07/28
 Consolidated Edison Co of New York 122pp 14357 146 24X
 Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IR Info Notice 82-27, "Fuel Rad Degradation Resulting From Baffle Water-Jet Impingement" Svc list oncl
 JORDAN,E L Division of Engineering & Quality Assurance 82/09/09
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000,82/08/05.8204210407
- 8208300049 Forwards IE Enforcement Conference Repts 80-277/82-17 & 50-278/82-15 on 820722 STAROSTECKI.R Division of Project & Resident Programs 82/08/10 DALTROFF, B L Philadelphia Electric Co 2pp 14898 297 24% Fichs 50-277, 82/08/10,8208300049
- ---B208300051 IE Enforcement Conference Repts 80-277/82-17 & 50-278/82-15 on 820722 No noncompliance noted Major areas discussed findings of previous insp re health physics program & primary containment integrity BLOUGH.AR. MCCABE.E C Division of Project & Resident Programs 82/08/04 3pp 14598:299 24X Fiche 50-277.92/08/10,8208300049
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOLA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J.M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24x Fiche 50-000,82/07/13,8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBI" " NRC - No Detailed Affiliation Qiven 82/07/13 48pp, 14677 216 24X Fiche 50-000, 82/07/13:8208270010
- 8208190098 Forwards monthly operating repts for Jul 1982 COONEY.M J Philadelphia Electric Co 82/08/13 Director's Office, Office of Inspection and Enforcement 1p (4383 164 24X Fiche 50-277.82/08/13.8208190098
- --8208190102 Monthly operating repts for Jul 1982 ALDEN,W M Philadelphia Electric Co. 82/08/11 7pp 14383:145 24% Ficha 50-277,82/08/13,8208190098
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8208030218 Forwards IE Insp Repts 50-280/82-13 & 50-281/82-13 on 820601-02 No noncompliance noted DANCE.H C. Division of Project & Resident Programs 82/07/07 LEASBURGR H Virginia Electric & Power Co 2pp. 14159 331 24X Fichs 50-280,82/07/07,8208030218

- --8208030221 IE Insp Repts S0-280/82-13 t 50-281/82-13 on 820601-02 No noncompliance noted Major areas inspected emergency planning; specifically interface between licensee & Region 3 at emergency response facility
 TAYLOR.P A Division of Project & Resident Programs JENKINS, 0 R
 Division of Emergency Proparedness & Operational Support 62/07/07 4pp 14159 333 24X Fichs 50-280.82/07/07,8208030218
- 8208030321 Ack receipt of 820624 1tr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisel Repts 50-280/82-05 & 50-281/82-05 LEWIS,R C Division of Project & Resident Programs 82/07/27 LEWISBURG,R H Virginia Electric & Power Co 1p 14163 130 24X Fiche 50-280,82/07/27,8208030521
- ~~8208030334 Responds to NRC 820525 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05 Corrective actions task force formed in Mar 1982 to perform complete revision of emergency plan LEASBURG, R H Virginia Electric & Power Co 82/06/24 O'REILLY, J P. Region 2. Diffice of Director 13pp 14163 131 24X Fichs 80-280,82/07/27.8208030521
- --B20803056i Forwards list of items that should be improved re emergency preparadness program Some corrective actions in progress prior to 820315-26 site visit d'REILLY,J P Region 2, Office of Director B2/04/06 LEABURG,R H Virginia Electric & Power Co 13pp 14163 147 24X Fiche 50-280,82/07/27,8208030521
- --8208030574 IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05 on 820315-26 Noncompliance noted deficiencies in emergency plan re training procedures & initial dose assessment HUFFMAN.9 N , MCFARLAND, C R , MARETON, R R Division of Emergency Preparedness & Operational Support 82/05/21 48pp 14163 160 24X Fiche, 80-280, 82/07/27, 82/8030321
- 8208190097 Provides status of eight items identified in NRC 810213 ltr as unresolved fire protection issues LEASBURG,R H Virginia Electric & Power Co 82/08/13 DENTON,H R Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch 1 2pp, 14383 136 24X Fiche 50-280,62/08/13,8208190097
- 8208240315 Forwards changes to security plans Changes withheld (ref 10CFR2 790) LEASBURGER H. Virginia Electric & Power Co 82/08/23 DENTON, H R Dffice of Nuclear Reactor Regulation, Director VAROA, S A Operating Reactors Branch 1 p 14520 350 24X Fiche 50-000, 82/08/23,8208240315

P Operating license stage documents & correspondence

- 8207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CF re Commission approved charter for CROR 8yc list encl
 DIRCKS:N J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp, 14194 001
 24X Fichs. 50-000; 82/07/02, 8207080064.
- 9209280483 Approves 920713 request for routes to be used for transporting spent fuel SHERR.T 8 Material Transfer Safeguards Licensing Branch 92/07/28 LEABBURG.R.H Virginia Electric & Power Co 1p 14542 260 24X Fichs 50-280
- 8208030444 Suppl to 801028 application for amend to Licenses DPR-32 & DPR-37 modifying auxiliary bldg ventilation sys & expanding control room air filtration sys Requests 30 days to implement Tech Space.

 LEASBURG, R H Virginia Electric & Power Co. 82/07/29 DENTON, H R Office of Nuclear Reactor Regulation Director VARGA, 8 A Operating Reactors Branch 1 3pp 14155 320 24X Fiche 50-280.82/07/29.8208030444
- --8208030448 Proposed Tech Spec changes re auxiliary bldg ventilation sys & control room air filtration sys * Virginia Electric & Power Co 82/07/29 19pp 14155 323, 24X Fiche. 50-280.82/07/29.8208030444
- 920B040245 BOCIOECONOMIC IMPACTS OF NUCLEAR OENERATING BTATIONS; SURRY CASE STUDY. Docket Nos 50-280 And 50-281 (Virginia Eisetric Power And Light Company)
 FLYNN, J Social Impact Research, Inc * Mountain West Research, Inc FIN B-6268 NUREG/CR-2749 VII 82/07/31 Division of Health, Biting & Environment 182pp Available at NTIS \$6.50 14233:001. 24X Fiche 50-280,82/07/31,8208040245

- 8208090101 Suppl to 820316 & 0628 applications for amend to Licenses DPR-32 & DPR-37.correcting inadvertent administrative error on Tech Spec 6 4-4 to reflect revised list of procedures & persons designated for approval in Section 6 4 E LEASBURG.R H Virginia Electric & Power Co 82/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch i 2pp 14269 247 24X Fiche 50-280.82/08/03.8208090101
- --8208090105 Proposed Tech Spec Pages & 4-4 & 6 4-5 reflecting revised list of procedures & persons designated for approval in Sections & 4 E & 6 4 F ** Virginia Electric & Power Co 82/08/03 2pp 14269 249. 24% Fiche 50-280.82/08/03.8208090101
- 8208100110 Forwards calculations indicating that relative humidity in lab testing used charcoal samples from auxiliary ventilation says does not exceed 76 25% upon entering Category I filter train

 LEABBURG, R H Virginia Electric & Power Co 82/08/05 DENTON, H R

 Office of Nuclear Reactor Regulation, Director VAROA, S A.

 Operating Reactors Branch 1 25pp 14298 106 24X

 Fiche 50-280, 82/08/05, 8208100110
- 8208090194 Opneric Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements See list encl EIBENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208120283 Application for amend to Licenses DPR-32 & DPR-37, changing Tech Bpec 6 4 E 4 & correcting administrative error in 820803 amend application re assistant health physics supervisor or health physicist LEASBUROR. H. Virginia Electric & Power Co. 82/08/09. DENTON, H. R. Office of Nuclear Reactor Regulation. Director VARQA, S. A Operating Reactors Branch i 2pp 14324 3i1 24X Fichs 50-280, 82/08/09, 8208120283
- --8208120289 Proposed Tech Spec & 4 E 4 re assistant health physics supervisor or health physicist * Virginia Electric & Power Co 82/08/09, ip 14324 313, 24X Fiche 50-280,82/08/09,8208120283
- 8208190195 Responds to NRC request for add1 info re Generic Ltr 81-14 concerning seismic qualification of auxiliary feedwater sys Revised Sketch 12846.01-MKS-3 will be forwarded when available LEASBURG,R H Virginia Electric & Power Co 82/08/13 DENTON,H R Office of Nuclear Reactor Regulation, Director VARGA,S A Operating Reactors Branch 1. 3pp 14499 070 24X
- 8208230280 Application for amend to Licenses DPR-32 & DPR-37 changing Tech Specs to reflect degraded voltage protection sys mod LEASBURG, R H Virginia Electric & Power Co 82/08/17 DENTIN, H, R Office of Nuclear Reactor Regulation, Director VARQA, B, A Operating Reactors Branch I, App. 14512 250 24X Ficha 50-280, 82/08/17, 8208230280
- --8208230284 Proposed Tech Specs 4 6-2 & Tables 3 7-2,3.7-4 & 4.1-1 re degraded voltage protection sys * Virginia Electric & Power Co 82/08/17 4pp 14512 254 24X Fichs 30-280,82/08/17.8208230280
- 8208250346 Forwards oversize Sketch 12846 01-MKB-3 re seismic qualification of auxiliary feedwater sys ref in 820813 ltr Aperture card is available in FDR LEABBURG, R H Virginia Electric & Power Co 82/08/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch i 1p 14541 001 24X Ficher 50-280, 82/08/20, 8208250346
- 8208270076 Advises of revised commitment date to 830101 re completion of reactor coolant sampling sys, per Generic Ltr 82-05 & NUREO-0737, Item II B 3 Delay due to need for const of environmentally controlled encl around monitoring panels LEABBURG, R. H. Virginia Electric & Power Co. 82/08/23, DENYON, H. R. Office of Nuclear Reactor Regulation, Director, EISENBUT, D. Q. Division of Licensing 3pp. 14563 130 24% Fiche. 50-280, 82/08/23, 8208270076.
- Q Inspection reports, IE Bulletins & correspondence
- 8208030218 Forwards IE Insp Repts 50-280/82-13 t 50-281/82-13 on 820601-02 No noncompliants noted.

 DANCE:H G Division of Project & Resident Programs 82/07/07 LEASBURG:R H Virginia Electric & Power Co 2pp 14159:331. 24X Fiche: 50-280:82/07/07.8208030218

- --B208030221 IE Insp Repts 50-280/82-13 & 50-281/82-13 on 820601-02 No noncompliance noted Major areas inspected emergency planning, specifically interface between licensee & Region 3 at emergency response facility
 TAYLOR, P A Division of Project & Resident Programs JENKINB, O R
 Division of Emergency Preparedness & Operational Support 82/07/07 4pp 14159 333 24X Fiche 50-280,82/07/07,8208030218
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393
- B204210375 IE Info Notice 81-26, Part J. Buppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Suc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan
- 8204210396 IE Info Natice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Bvc list encl JORDAN E L Division of Engineering & Quality Assurance 62/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000.82/07/20.8204210396
- 8204210377 IE Info Notice 82-24, "Water Leaking From U Hexafluorida Overpacks" Svc list encl CDBs,L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14337 276 24X Fiche 50-000:82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Evc list encl JORDAN, E. L. Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Ficha 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PMRs " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000.82/07/23.8204210402
- 8204210403 IE Into Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8208030521 Ack receipt of 820624 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05 LEHIS.R C Division of Project & Resident Programs 82/07/27 LEASBURG.R.H. Virginia Electric & Power Co ip 14163.130 24X Fiche 50-280.82/07/27,8208030521
 - 8208030534 Responds to NRC 820525 ltr re violations noted in IE Emergency Preparedness Appreisal Repts 50-280/82-05 & 50-281/82-05 Corrective actions task force formed in Mar 1982 to perform complete revision of emergency plan. LEABSURG: R H Virginia Electric & Power Co 82/06/24 C/REILLY, J P. Region 2. Office of Director 13pp 14163 131. 24X Fiche 50-280.82/07/27,8208030521
- --B208030546 Forwards IE Emergency Preparadness Appraisal Repts 50-280/82-05 & 50-281/82-05 on 820315-26 Planned changes for correcting each deficiency due within 120 days of receipt of ltr.

 O'REILLY, J P Region 2, Office of Director 82/05/25 LEASBURG, R H Virginia Electric & Power Co 3pp 14163 144 24X Fiche 50-280.82/07/27.8208030521.
- -8208030561 Forwards list of items that should be improved re emergancy preparedness program Bome corrective actions in progress prior to 820315-26 site visit 0'REILLYJ P. Region R. Office of Director 82/04/06 LEASBURO.R H. Virginia Electric & Power Co 13pp. 14163:147 24X Fiche.50-280,82/07/27.8208030521.

- --8208030574 IE Emergency Preparedness Appraisel Repts 50-280/82-05 & 50-281/82-05 on 820315-26 Noncompliance noted deficiencies in emergency plan re training, procedures & initial dose assessment HUFFMAN, G.N., MCFARLAND, C.R., MARGTON, R.R. Division of Emergency Preparedness & Operational Support 82/05/21 48pp 14163 160 24% Fiche 50-280,82/07/27,8208030521
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14387,146 24X Fiche 50-000,82/07/28,8204210405
- 8208030615 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-280/82-09 & 50-281/82-09 O'REILLY, J P Region 2, Office of Director 82/07/28 LEASBURG, R, H Virginia Electric & Power Co 1p 14161 138 24X Fiche. 50-280, 82/07/28, 8208030615
- --8208030622 Responds to NRC 820616 ltr re violations noted in IE Insp Repts 50-280/82-09 & 50-281/82-09 Corrective actions repaired relief valve & revised health physics & radioactive release notification procedures LEASBURG:R H Virginia Electric & Power Co. 82/07/16 0'REILLY:J P Region 2. Office of Director 5pp 14161 139 24X Fiche 50-280,82/07/28.8208030615
- --8208030626 Forwards IE Inep Repts 50-280/82-09 & 50-281/82-09 on 820419-23 & notice of violation O'REILLY, J P Region 2, Office of Director 82/06/16 LEABBURG, R H Virginia Electric & Power Co 2pp 14161,144 24X Fichs 50-280,82/07/28,8208030615
- --8208030630 Notice of violation from insp on 820419-23 * Region 2, Office of Director 62/06/16 2pp 14161 146. 24X Fiche 50-280, 82/07/28, 8208030615
- --8208030638 IE Insp Repts 50-280/82-09 % 50-281/82-09 on 820419-23
 Nancompliance noted exceeded instantaneous Tech Spec limit
 for gaseous waste, failure to perform adequate evaluation of
 unplanned release & failure to promptly notify NRC
 HOSEY.C M. BARR.K P Division of Engineering & Technical
 Programs 82/05/28 7pp 14161 148. 24X Fiche 50-280, 82/07/28,
 8208030615
- 8208260424 Ack receipt of util 820609 ltr & payment of civil penalty.
 Based on review of incidents no basis for remission or
 mitigation of penalty identified
 LIEBERMAN.J. Enforcement Staff 82/07/29 LEASBURO.R H Virginia
 Electric & Power Go Opp 15574.313 24X Fiche 50-280,82/07/29,
 8208260424
- 8208160402 Responds to IE Bulletin 82-02, "Dagradation of Threaded Fasteners in RCPB of PHR Plants" Info provided re use of lubricants & injection sealants & leakage bolted connections
 LEABURG, R H Virginia Electric & Power Co 82/07/30.
 0'REILLY, J P Region 2. Office of Director 5pp 14347 357 24X Fiche 50-000, 82/07/30, 8208160402
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN: E.L. Division of Engineering & Quality Assurance, 82/08/05 Consolidated Edison Co of New York 117pp 14388.201 24X Fiche 50-000.82/08/05.8204210407
- 8208300195 Responds to NRC 820714 1tr requesting written documentation on installation of flow restricting orifices in auxiliary feedwater sys in ref to IE Bulletin 80-04 Orifices installed under Design Change Package 80-975 & completed 810708, LEASBURG, R H Virginia Electric & Power Co 62/08/23, DENTON, H. R. Office of Nuclear Reactor Regulation, Director VARGA, B A. Operating Reactors Branch I ip 14575-357 24X Fiche 50-280,82/08/23,8208300195
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13. UDELL, R A, Critical Mass Energy Project 8pp 14679, 208 24X Fiche 30-000, 82/07/13, 8208270110
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBI "

 # NRC No Detailed Affiliation Given 82/07/13, 48pp. 14479, 216 24% Fiche 50-000, 82/07/13, 8208270010

- 208270303 Forwards "Recorded Annual Whole Body Exposures CYB1." per 10CFR20 407 LEABBURG, R H Virginia Electric & Power Co 82/02/19 HALLER, N M Office of Management and Program Analysis 1p 14679 312 24X Fiche 50-000, 82/07/13.8208270010
- #208270312 "Recorded Annual Whole Body Exposures CY81," # Virginia Electric & Power Co 82/02/19 ip 14679 313 24X Fiche 50-000, 82/07/13, 8208270010
- OB120203 Forwards monthly operating repts for June 1982 EASBURG,R H Virginia Electric & Power Co 82/07/15 HALLER,N,M Office of Resource Management, Director 1p 14326 222 24X iche 50-280.82/07/15.8208120203
- 208120204 Monthly operating rapts for June 1982 JONES, V H Virginia Electric & Power Co. 82/07/08. 39pp. 14326 223 24% Fiche 50-280, 82/07/15,8208120203
 - Reportable occurrences, LERs & related correspondence
- DB270668 Forwards LERs 81-005/03L-0 & 81-006/03L-0

 JILSON, J L Vippinia Electric & Power Co B1/03/30, Q'REILLY, J. F.

 Region 2, Atlanta, Office of the Director (81/03/01) 1p

 14683 189 24X Fiche. 50-280, 81/03/30, 82082
- ### 1008270674 LER 81-005/03L-0 on 810301, radiation monitor recorder RR-175 found printing erratically Caused by dirty slidewire resistor in circuit that controls positioning of printing device Resistor cleaned & recorder returned to svc WILBON, J. L. Virginia Electric & Power Co 81/03/30, Region 2, Atlanta, Office of the Director (81/03/01), 2pp 14683 190 24x Fiche 50-280, 81/03/30, 8208270668
- → ■208270677 LER 8i-006/03L-0 on 8i0306, alerm setpoint for companent cooling water radiation monitor RM-CC-106 found to be greater than twice background Caused by instrument drift, Monitor reset to proper setpoint & returned to svc WILSON, J L Virginia Elactric & Power Co 81/03/30, Region 2, Atlanta, Office of the Director (8i/03/01). 2pp 14683 192, 24X Fiche 50-280,81/03/30,8208270668
- ## 208030285 Forwards LERs 82-077/03L-0 & 82-079/03L-0
 ###LBON.J L. Virginta Electric & Power Co 82/07/26 O'REILLY.J P.
 ## agion 2. Office of Director ip 14136/263. 24X
 ## iche 50-280.82/07/26.8208030285

- □ 208060200 Forwards LER: 82-078/03L-0 & 82-038/03L-0
 WILSON, J. L. Virginis Electric & Pawer Co 82/07/26 G'REILLY, J. P
 Region 2, Office of Director 1p. 14239:001 24X
 Fiche 50-280, 82/07/26, 8208060200.
- 9208060208 LER 82-078/03L-0, on 820701; w/unit at full power, 8 corsecoling monitor displayed erratic indications Caused by feiled relay on plug-in module on circuit board A-1. Failed component replaced, Module returned to circuit board, WILBON, U.L. Virginia Electric & Power Co. 82/07/26, Region 2 Office of Director 2pp 14239 002 24X Fiche: 50-280, 82/07/26, 8208060200
- © 208060218 LER 82-038/03L-0 on 820703, alarm check revealed that amp reading for heat tracing panel 9 circuit 208 was below acceptance criteria. Caused by excessive heat. Defective heat tracing replaced & tested.

 WILBON, J. L. Virginia Electric & Power Co. 82/07/26. Region 2, Office of Director 2pp 14237 004 24X Fiche 50-280, 82/07/26, 8208060200.
- OBO60030 Forwards incident reporting sys repts re effects of fire wrotection sys actuation on safety-related equipment & wismic qualification of safety-related sys for transmission NEA.
 NEA.
 NICA.
 TICHELBON.C. Director's Office. 82/07/29, LAFLEUR, J.D. Diffice of International Programs. Director. 2ipp. 14244-315 24X

- 8208120166 Forwards LERs 82-069/03L-0 & 82-042/03L-0 HILBON, J L Virginia Electric & Power Co 82/08/02 D'REILLY, J. P Region 2, Office of Director ip 14319 150 24X Fiche 50-280, 82/08/02, 8208120166
- --B20Bi20i70 LER 82-069/03L-0 on B20706, charging gump A found leaking oil Water found in lube oil Caused by leak in tube in charging pump lube oil cooler A & B gump coolers interchanged & A pump returned to svc WILBON, J.L. Virginia Electric & Power Co. 82/08/02, Region 2, Office of Director. 2pp 14319 151 24X Fiche: 50-280,82/08/02,8208120166
- --8208120175 LER 82-042/03L-0 on 820706, main steam line snubber found wo oil in reservoir Caused by leaking rod seal due to improper installation Spare snubber tested & installat MIL80N, J L. Virginia Electric & Power Co. 82/08/02 Region P. Office of Director. 2pp 14319,153, 24X Fiche 50-280,82/08/02,8208120166
- 8208120110 Forwards updated LERs 81-047/03X-1 & 82-049/03X-1. WILBON, J. L. Virginia Electric & Power Co., 82/08/03 O'REILLY, J. P. Region 2. Office of Director. ip 14327:017 24X Fiche: 50-280, 82/08/03, 8208120110.
- --8208120112 Updated LER 81-047/03X-1 on 810910, following reactor trip to white returning to power, specific activity of RCS indicated dose equivalent I-131 level greater than Tech Spec limit. Caused by furl alterent defect in reactor core.

 WILSON, J.L. Virginia Electric & Fower Co. 82/08/03 Region 2, Office of Director. 3pp 14327.018. 24X Fiche: 50-280,82/08/03, 8208120110.
- --8208120116 Updated LER 82-049/03X-1 on 820419, at 100X power, charging pump syc water pump 1-8W-P 108 found w/zero discharge pressure Caused by loss of syction to pumps due to increased use of syc water by chillers, Pump operation restored WILBON, J.L. Virginia Electric & Power Co 82/08/03 Region 2, Office of Director, 2pp 14327.021. 24X Fiche 50-280,82/08/03,8208120110.
- 8208100071 RO'on 920721, rate of exchange of condenser cooling water outlet temp reached max of 12 F/hour exceeding max rate of change of 3 F/hour per Tech 8pec 4.14.A.3. Caused by loss of electrical power to four of sight circulating water pumps.

 LEASBURG, R H Virginia Electric & Power Co. 82/08/05. DENTON, H R. Office of Nuclear Reactor Regulation, Director VARGA, 8, A Operating Reactors Branch 1 ip 14276-181 24X Fiche. 50-280, 82/08/05, 8208100071
- 8208160268 Forwards LERs 82-082/03L-0 & 82-043/03L-0 MIL80N, J. L. Virginia Electric & Power Co. 82/08/06. G'REILLY, J. P. Region 2, Gffice of Director. 1p. 14346:187 24X Fiche 50-280, 82/08/06.8208160268.
- ---B208160275 LER 82-0B2/03L-0.on B20713, post-reactor trip specific activity samples of RCS indicated dose equivalent I-131 level greater than Tech Specs. Caused by fuel defects in reactor core. Accelerated sampling frequency implemented HTLBON, J L. Virginia Electric & Power Co. 82/08/06. Region 2, Office of Director. 6pp 14346 188. 24% Fiche 50-280,82/08/06, 8208160268
- --B208160285 LER 82-043/03L-0 on 820713, w/unit at 100X power, performance of PT-27 revealed ampere reading for heat tracing panel 10, circuit 6A below acceptance criteria. Caused by defective heat tracing due to excessive heat Heat tracing replaced.
 HILBON, J. L. Virginia Electric & Power Co. B2/08/06 Region 2, Office of Director 2pp. 14346:174, 24X Fiche 50-280,82/08/06, 82/08/06
- 8208160529 PNO-II-82-092: on 820808. Xe-133 gaseous radioactivity from ventilation sys exhaust exceeded controlled release rate. No particulate or iodine activity released. No personnel contamination occurred. HOSEY, C. M., BARR, K. P. Region 2, Office of Director. 82/08/09. 2pp. 14356-146 24X Fiche. 50-280, 82/08/09, 8208160529.
- 8208300332 Forwards LERs 82-044/03L-0 & 82-084/01T-0 HILBON, J. L. Virginia Electric & Power Co. 82/08/20. O'REILLY, J. P Region 2. Defice of Director. 1p. 14599:103. 24X Fiche: 50-280, 82/08/20, 8208300332
- ---3208300337 LER 62-044/03L-0. on 820720, operators noted RMS7 temp indicators reading 44 F & 46 F Calibr of channels revealed 46 F correct & above limit, Caused by one inoperable refrigeration unit.

 WILSON, J. L. Virginia Electric & Power Co. 82/08/20 Region 2, Office of Director. 3pp. 14599:104. 24X Fiche: 50-280, 82/08/20, 2308200032

- --8208300340 LER 82-084/01T-0 on 820808, during venting of charging pump A via charcoal filter to ventilation sys, venting evolution resulted in max instantaneous release rate being exceed HILSON, J. Virginia Electric & Power Co. 82/08/20 Region 2, Office of Director 3pp 14579 107 24X Fiche 50-280,82/08/20, Region 2003/20
- 8208310118 PNO-11-82-097 on 820826, controlled radioactive gaseous release rate exceeded Tech Specs during sampling of waste gas stripper surge drum at primary sample tank Cause not stated Estimated 3 2 Cl Xe-133 released HDSEY,C H. BARR,K P Region 2. Office of Director 82/08/27 2pp 14695 082 24X Fiche 50-280.82/08/27.8208310118

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

- 8208030218 Forwards IE Insp. Repts 50-280/82-13 & 50-281/82-13 on 820601-02 No noncompliance moted DANCE.H C Division of Project & Resident Programs 82/07/07 LEASBURG.R H Virginia Electric & Power Co 2pp 14159 331 Fithe 50-280.82/07/07.8208030218
- --8208030221 IE Insp Repts 50-280/82-13 & 50-281/82-13 on 820601-02 No COBUSOR21 IE Insp Repts 50-280/82-13 & 50-281/82-13 on 820501-02 honcompliance noted Major areas inspected semergency planning, specifically interface between licensee & Region 3 at emergency response facility TAYLORP PA Division of Project & Resident Programs 82/07/07 4pp 14159 333 24X Fiche 50-280,82/07/07,8208030218
- 8208030521 Ack receipt of 820624 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-280/62-05 to 50-281/62-05 LEMIS.R C Division of Project & Resident Programs 82/07/27 LEASBURG.R H Virginia Electric & Power Co ip 14163 130 24X Fiche 50-280,82/07/27,8208030521
- --8208030534 Responds to NRC 820525 ltr re violations noted in IE Emergency Preparadness Appraisal Repts 50-280/62-05 & 50-281/82-05 Corrective actions task force formed in Mer 1982 to perform complate revision of emergency plan LEASBURG. R H Virginia Electric & Power Co 82/06/24 O'REILLY. J P. Region 2. Office of Director 13pp 14163 131 24X Fiche 50-280,82/07/27,8208030521
- -8208030546 Forwards IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05 on 820315-26 Planned changes for correcting each deficiency due within 120 days of receipt of itr O'REILLY, J P Region 2, Office of Director 82/05/25 LEASBURG, R H Virginia Electric & Power Co 3pp 14163 144 24X Fiche 50-280, 82/07/27, 8208030521
- --8208030861 Forwards list of items that should be improved re emergency preparedness program Some corrective actions in progress prior to 820315-26 site visit
 O'REILLY, J P Region 2, Office of Director 82/04/06
 LEASBURG, R H Virginia Electric & Power Co 13pp 14163 147
 24X Fiche 50-280,82/07/27,8208030521
- --8208030574 IE Emergenty Preparedness Appraisal Repts 50-280/82-05 & 50-280/82-05 on 820315-26 Noncompliance noted deficiencies in emergency plan re training procedure & initial dose assesment HUFFMAN, G N , JENKINS, G R Division of Emergency Preparedness & Operational Support 62/05/21 4Bpp 14163 160 24X Fiche 50-280, 82/07/27, 8208030521
- 20Big0097 Provides status of eight items identified in NRC Bi0213 ltr as unresolved fire protection issues LEASBURG,R H Virginia Electric & Power Co B2/0B/13 DENTON, H. R Office of Nuclear Reactor Regulation, Director VARGA, B A Operating Reactors Brench i 2pp i43B3 134 24X Fiche 30-280, 82/08/13, 820Bi90097
- 3240315 Forwards changes to security plans Changes withheld (ref DENTON, H.R.

NCFRZ 7401 ASBURO,R H Virginia Electric & Power Co 82/08/23 Di fice of Nuclear Reactor Regulation, Director VARGA,S A reating Reactors Branch 1 1p 14520 350 24X he 30-000.82/08/23.8208240315

perating license stage documents & correspondence

)64 Generic ltr to all licensees of operating plants, applicants & holders of CP re Commission approved tharter for

vo list encl

W J Office of the Executive Director for Operations
O2 Consolidated Edison Co of New York 93pp 14
che 50-000.82/07/02.8207080044 14174 001

- 8208030444 Suppl to 801028 application for amend to Licenses DPR-32 & DPR-37 modifying auxiliary bldg ventilation sys & expanding control room air filtration sys Requests 30 days to implement Tech Specs
 LEASBURG,R H Virginia Electric & Power Co 82/07/29 DENTON,H R Office of Nuclear Reactor Regulation, Director VARGA,S A Operating Reactors Branch 1 3pp 14155 320 24X
 Fiche 50-280,82/07/29,8208030444
- --8208030448 Proposed Tech Spec changes re auxiliary bldg vantilation sys & control room air filtration sys * Virginia Electric & Power Co 82/07/29 19pp 14155 323 24% Fiche 50-280,82/07/29.8208030444
- 820B040245 80C10ECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS SURRY CASE BTUDY Docket Nos 50-280 And 50-281 (Virginia Electric CASE SIDVY DOCKET NOS 30-280 AND 30-281 (Virginia Electric Power And Light Company)
 FLYNN, J Social Impact Research, Inc. * Mountain West Research, Inc. FIN B-6268 NUREO/CR-2749 VII 82/07/31 Division of Health, Siting & Environment 182pp Available at NTIS *6 50 14233 001 24X Fiche 50-280, 82/07/31, 8208040245
- 8208090101 Suppl to 820316 & O628 applications for amend to Licenses DPR-32 & DPR-37, correcting inadvertent administrative error on Tech Spec 6 4-4 to reflect revised list of procedures & persons designated for approval in Section 6 4 E LEASBURG, R H Virginia Electric & Power Co 82/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director VARQA, B A Operating Reactors Branch 1 2pp 14267 247 24X Fiche 50-280, 82/08/03, 8208090101
- --8208090105 Proposed Tech Spec Pages 6 4-4 & 6 4-5, reflecting revised list of procedures & persons designated for approval in Sections 6 4 E & 6 4 F * Virginia Electric & Power Co 82/08/03 2pp 14269 249 24X Fiche 50~280,82/08/03,8208090101
- 8208100110 Forwards calculations indicating that relative humidity in lab testing used charcoal samples from auxiliary ventilation sys does not exceed 76 25% upon entering Category I filter train LEASBURG,R H Virginia Electric & Power Co 82/08/05 DE Office of Nuclear Reactor Regulation, Director VAROA, S A Operating Reactors Branch | 25pp 14298 106 24X Fiche 50-280, 82/08/05,8208100110
- B208070194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208070194
- 8208120283 Application for amend to Licenses DPR-32 & DPR-37, changing Tech Spec & 4 E 4 & correcting administrative error in 820803 amend application re assistant health physics supervisor or health physicist LEASBURG, R H Virginia Electric & Power Co 82/08/09 DENTON, H R. Office of Nuclear Reactor Regulation, Director VARGA, S A Derating Reactors Branch i 2pp 14324 311 24X Fiche. 50-280, 82/08/09, 8208120283
- --8208120289 Proposed Tech Spec & 4 E 4 re assistant health physics supervisor or health physicist * Virginia Electric & Power Co 82/08/09, ip 14324 313 24X Fiche 30-280,82/08/09,8208120283
- 8208170175 Responds to NRC request for add1 info re Generic Ltr 81-14 concerning seismic qualification of auxiliary fredwater sys Revised Sketch 12846 01-MKS-3 will be forwarded when DENTON H R
- 8208230280 Application for amend to Licenses DPR-32 & DPR-37 changing Tech Specs to reflect degraded voltage protection sys mod LEASBURG, R H Virginia Electric & Power Co 82/08/17, DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, B A Operating Reactors Branch 1 App 14512 250 24X Fiche 50-280, 82/08/17, 8208230280
- --8208230284 Proposed Tech Specs 4 5-2 & Tables 3 7-2,3 7-4 & 4 i-1 ra degraded voltage protection sys * Virginia Electric & Power Co 82/08/17 4pp 14512 254 24X Fichs 50-280,82/08/17.8208230280

- 8208250346 Forwards oversize Sketch 12846 01-MKS-3 re seismic qualification of auxiliary feedwater sys ref in 820813 ltr Aperture card is available in FDR LEARSURG.R H Virginia Electric & Power Co 82/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 1p 14341 001 24% Fiche 50-280,82/08/20,8208250346
- 8208270076 Advises of revised commitment date to 830101 re completion of reactor coolant sampling sys.per Generic Ltr 82-05 & NUREO-0737. Item II B. 3 Delay due to need for const of environmentally controlled enci around monitoring panels LEABBURG, R H Virginia Electric & Power Co 82/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 3pp 14563 130 24X Fiche. 50-280, 82/08/23, 8208270076

O Inspection reports, IE Bulletins & correspondence

- 8208030218 Forwards IE Insp Repts 50-280/82-13 & 50-281/82-13 on 820601-02 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/07, LEARSURO, R H Virginia Electric & Power Co 2pp 14159, 331 24X Fichs 50-280, 82/07/07, 8208030218
- --8208030221 IE Insp Repts 50-280/82-13 & 50-281/82-13 on 820601-02 No noncompliance noted Major areas inspected emergency planning, specifically interface between licensee & Region 3 at emergency response facility TAYLOR, P A Division of Project & Resident Programs JENKINS, G R Division of Emergency Preparedness & Operational Support 82/07/07 4pp 14159 333 24X Fiche, 50-280, 82/07/07, 8208030218,
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV)
 Leakage " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance B2/07/16
 Consolidated Edison Co of New York B7pp 14356 274 24X
 Fiche. 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice Bi-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Suc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp, 14358, OO1, 24X Fiche 50-000, 82/07/19, 8204210375
- 8204210396 IE Info Notice 82-23, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure" 8vc list encl
 JORDAN.E L. Division of Engineering & Quality Assurance 82/07/20
 Consolidated Edison Co of New York 112pp, 14381:001, 24X
 Fiche.50-000.82/07/20,8204210396
- 8204210397 IE Info Notice B2-24, "Hater Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L.! Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York. 7ipp 14357.276, 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN E L Division of Engineering & Quality Assurance, 82/07/22 Consolidated Edison Co. of New York 112pp 14194,321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Syr list and I JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380, 115. 24% Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14174,120 24X Fiche 50-000,82/07/23,8204210402.
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Fower Plents." Svc list encl JORDAN.E L Division of Engineering & Quality Assurance. 82/07/26, Consolidated Edison Co of New York 12ipp 14357:013 24X Fiche 50-000.82/07/26.8204210403
- 8208030521 Ack receipt of 820624 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 80-280/02-05 & 50-281/82-05 LEMIS,R.G. Division of Project & Resident Programs, 82/07/27, LEASBURG,R.H Virginia Electric & Power Co. 1p. 14163,130, 24% Fiche 50-280,82/07/27,8208030521.

- --8208030534 Responds to NRC 820525 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05 Corrective actions task force formed in Mar 1982 to perform complete revision of smergency plan LEASBURG, R H Virginia Electric & Power Co 82/06/24 O'REILLY, J P. Region 2. Office of Director 13pp 14163, 131 24X Fiche 50-280,82/07/27,8208030521
- --8208030546 Forwards IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05 on 820315-26 Planned changes for correcting each deficiency due within 120 days of receipt of ltr O'REILLY, J P Region 2, Office of Director 82/05/25 LEABBURG, R H Virginia Electric & Power Co 3pp 14163 144. 24X Fiche 50-280,82/07/27,8208030521
- --8208030361 Forwards list of items that should be improved to emergency preparedness program Some corrective actions in progress prior to 820315-26 site visit
 O'REILLY, J P Region 2, Office of Director 82/04/06
 LEASBURO, R H Virginia Electric & Power Co 13pp 14163 147
 24X Fiche 50-280, 82/07/27, 8208030521
- ---820B030574 IE Emergency Preparedness Appraisal Repts 50-280/B2-05 & 50-281/B2-05 on 820315-26 Noncompliance noted: deficiencies in emergency plan re training, procedures & initial dose assessment HUFFMAN.0 N , MCFARLAND,C R , MARSTON.R R Division of Emergency Preparedness & Operational Support 82/05/21 48pp. 14163:160. 24X Fichs 50-280.82/07/27.8208030521
- 8204210409 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance. 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8208030615 Ack receipt of 820716 ltr informing NRC of stape taken to correct violations noted in IE Insp Repts 50-280/82-09 & 50-281/82-09 U'REILLY, J P Region 2. Office of Director. 92/07/28 LEABBURG, R H Virginia Electric & Power Co 1p. 14161, 138 24X Fiche 50-280, 82/07/28, 8208030615
- --8208030622 Responds to NRC 820616 ltr re-violations noted in IE Insp. Repts 50-280/82-09 & 50-281/82-09, Corrective actions. repaired relief valve & revised health physics & radioactive release notification procedures LEASBURG, R H Virginia Electric & Power Co. 82/07/16 O'REILLY, J P. Region 2, Office of Director 5pp 14161 139, 243 Fichs 50-280, 82/07/28, 8208030615
- --8208030626 Forwards IE Insp Repts 50-280/82-07 & 50-281/82-07 on 820417-23 & notice of violation O'REILLY, J. P. Region 2, Office of Director. 82/06/16 LEASBURG, R H. Virginia Electric & Fower Co 2pp 14161 144 24X Fiche 50-280,82/07/28,8208030615
- --8208030630 Notice of violation from insp on 820419-23
 * Region 2, Office of Director 82/06/16 2pp 14161 146. 24X
 Fiche 50-280,82/07/28,8208030615
- --8208030635 IE Insp Repts 50-280/82-09 & 50-281/82-09 on 820419-23.

 Noncompliance noted exceeded instantaneous Tech Spec Limit for gassous waste, failure to perform adequate evaluation of unplanned release & failure to promptly notify NRC.

 HUSEY, C M . BARR, K P Division of Engineering & Technical Programs 82/05/28 7pp 14161 148 24% Fiche 50-280, 82/07/28, 8208030615
- 8208160402 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Info provided re use of lubricants & injection sealants & leakage bolted connections LEABBURO, R H Virginia Electric & Power Co 82/07/30. O'REILLY, J. P. Region 2, Office of Director 5pp 14347; 359 24) Fiche. 50-000, 82/07/30, 8208160402.
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl.
 JORDAN.E L. Division of Engineering & Quality Assurance 600001idated Edison Co. of New York 117pp 14388: 201 24X
 Fichs. 50-000. 82/08/05. 8204210407.
- 8208300195 Responds to NRC 820714 1tr requesting written documentation on installation of flow restricting orifices in auxiliary feedwater sys in ref to IE Bulletin 80-04 Orifices installed under Design Change Package 80-575 & completed 810708.

 LEASBURG, R H Virginia Electric & Power Co. 82/08/23. DENTON, H R Office of Nuclear Reactor Regulation. Director. VARGA, S. A. Operating Reactors Branch 1 1p 14595 357 24X Fichs: 50-280, 82/08/23, 8208300195.

- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analysing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL,R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 30-000.82/07/13.8208270010
- --B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CV81" * NRC - No Detailed Affiliation Given B2/07/13 48pp 14679 216 24x Fiche 50-600, 82/07/13:8208270010
- --8208270303 Forwards "Recorded Annual Whole Body Exposures CY81," per 10CFR20 407 LEASBURG,R H Virginia Electric & Power Co 82/02/19 HALLER,N M Office of Management and Program Analysis 1p 14679 312 24X Fichs 50-000,82/07/13,8208270010
- --8208270312 "Recorded Annual Whole Body Exposures CYB1 "

 * Virginia Electric & Power Co 82/02/19 fp 14679 313 24X
 Fiche 80-000, 82/07/19, 8208270010
- 8208120203 Forwards monthly operating repts for June 1982 LEASSURO.R H Virginia Electric & Power Co 82/07/15 HALLER, N H Office of Resource Management. Director ip 14326 222 24X Fiche 50-280, 82/07/15, 8208120203
- S Reportable occurrences, LERs & related correspondence
- 8208030463 Forwards LERs 82-040/03L-0 & B2-041/03L-0 WILBON, J L Virginia Electric & Pawer Co 82/07/26 O'REILLY, J P Region 2, Office of Director 1p 14155 285 24X Fichs 50-281, 82/07/26, 8208030463
- --B208030470 LER B2-040/03L-0 an B20703, containment spray chemical addition tank level found to be 5% below Tech Spec requirement Cause resulted from minor leaks through one or both isolation valves Tank level restored WILSON, J L Virginia Electric & Power Co 82/07/26 Region 2, Office of Director 2pp 14155 286, 24% Fiche 50-281,82/07/26,8208030463
- ~-8208030477 LER 82-041/03L-0 on 820626, steam generator B level indication Li-2-486 drifted high Caused by wire broken at splice Splice replaced & channel returned to svc WILEON, J L Virginia Electric & Power Co. 82/07/26 Region 2, Office of Director 3pp 14155 288 24X Fiche 50-281, 82/07/26.
- 8208060200 Forwards LERs 82-078/03L-0 & 92-038/03L-0 WILSON, J. L. Virginia Electric & Power Co 82/07/26 O'REILLY, J P Region 2, Office of Director ip 14239 001 24X Fiche 50-280.82/07/26.8208060200
- --8208060218 LER 82-038/03L-0 on 820703, alarm check revealed that amp reading for heat tracing panel 9 circuit 208 was below acceptance criteria Caused by excessive heat Defective heat tracing replaced & tested
 WILSON, J L Virginia Electric & Power Co 82/07/26 Region 2.
 Office of Director 2pp 14239 004 24X Fiche 50-280, 82/07/26, 8208060200
- 8208060030 Forwards incident reporting sys repts re effects of fire protection sys ectuation on safety-related equipment & seismic qualification of safety-related sys for transmission to NEA NEA HICHELSON.C Director's Office 82/07/27 LAFLEUR, J D Office of International Programs. Director, 21pp 14244 315 24x Fiche. 50-000. B2/07/29. 8208060030
- 8208060327 Forwards incident reporting sys repts re spill of contemtnated water & contamination of personnel in auxiliary bldg & failure of control rod guide tube support pins for transmittal to NEA HICHELBON: C Director's Office. 82/07/29 LAFLEUR, J D Office of International Programs. Director 17pp. 14281 224 24X Fiche 50-000.82/07/29.8208060327
- 8208120166 Forwards LERs 82-069/03L-0 & 82-042/03L-0 WILSON, J : Vinginia Electric & Power Co 82/08/02 D'REILLY, J. P Region 2. Office of Director | Ip. 14319 150. 24X Fiche 50-280, 82/08/02, 8208120166

- --8208120175 LER 82-042/03L-0 on 820706 main steam line snubber found u/ oil in reservoir Caused by leaking rod seal due to improper installation Spare snubber tested & installed WILBON.J L Virginia Electric & Power Co 82/08/02 Region 2, Office of Director 2pp 14319 153 24X Fiche 50-280,82/08/02, 8208120166
- 8208100071 RD on 820721, rate of exchange of condenser cooling water outlet temp reached max of 12 F/hour exceeding max rate of change of 3 F/hour per Tech Spec 4 14 A 3 Caused by loss of electrical power to four of sight circulating water pumps LEASBURG, R H Virginia Electric & Power Co 92/08/05 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch 1 [p 14276 181 24X Fichs 50-280, 82/08/05, 8208100071
- 820816026B Forwards LERs 82-082/03L-0 & 82-043/03L-0 HILSON, J L Virginia Electric & Power Co 82/08/06 O'REILLY, J P Region 2. Office of Director 1p 14346 187 24X Fiche 30-280: 82/08/04. 820816026B
- --820B1602B5 LER B2-043/03L-0 on 820713, w/unit at 100% power, performance of PT-27 revealed ampere reading for heat tracing panel 10, circuit 6A below acceptance criteria Caused by defective heat tracing due to excessive heat Heat tracing replaced WILBON.J L. Virginia Electric & Power Co. 82/08/06 Region 2, Office of Director 2pp. 14346 194 24% fiche 50-280, 82/08/06, 8208160268
- 8208200142 Forwards LER 82-046/03L-0 & updated LER 80-010/01X-1 WILSON.J L Virginia Electric & Power Co 82/08/13 O'REILLY, J P Region 2. Office of Director ip 14394 349 24X Fiche 50-281.82/08/13.8208200142
- ---8208200153 LER 82-046/03L-0.on 820715, periodic test 2 9 revealed that high steam flow trip setpoint for steam generator 8 comparator FC-2-485 was high & could not be adjusted Caused by malfunctioning comparator Comparator replaced WILSON.J L Virginia Electric & Power Co 82/08/13 Region 2, Office of Director 2pp 14394 350 24X Fiche 50-281,82/08/13,820820142
- --8208200169 Updated LER 80-010/01X-1 on 800721, containment gaseous & particulate radiation monitor found to have one automatic function incapable of operating during fuel movement Caused by bypass of containment exhaust fan relay in design change WILSON.J L. Virginia Electric & Power Co 82/08/13 Region 2, Office of Director 2pp 14394 352 24X Fiche 50-281.82/08/13, 8208200142
- 8208300332 Forwards LERs 82-044/03L-0 & 82-084/01T-0 WILSON, J. L. Virginia Electric & Power Co. 82/08/20 O'REILLY, J. P. Region 2. Defice of Director 1p. 14599 103 24X Fiche 50-280, 82/08/20, 8208300332
- --8208300337 LER 82-044/03L-0 on 820720, operators noted RWST temp indicators reading 44 F & 46 F Calibr of channels revealed 46 F correct & above limit Caused by one inoperable refrigeration unit WILSON, J L. Virginia Electric & Power CD 82/08/20 Region 2 Office of Director 3pp 14597 104 24X Fiche 30-280, 82/08/20, 820830332
- DDCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8208030038 Releases public version of revised emergency plan implementing procedures
 FELTON.J M Division of Rules and Records 82/07/19 Document Management Branch ip 14182 219 24X Fiche 50-282,82/07/19,8208030038
- --8208030090 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-14 2 re operations emergency surveys & F3-8 re recommendations for offsits protective actions MUSGLF, D M Northern States Power Co 82/07/07 Region 3, Office of Director 1p 14182 220 24X Fiche 30-282,82/07/19,8208030038.
- --8208030091 Public version of revised emergency plan implementing procedures, including Procedures F3-14 2 re operations amergency surveys & F3-8 re recommendations for offsite protective actions
 SCHUELKE.D.A. Northern States Power Co. 82/07/01 175pp 14182 221 24X fiche.50-282.82/07/19.8208030038.

- 8208170399 Advises that exemption from fire protection schedular requirements of 10CFR50 48(c) re emergency lighting cannot be granted based on 820520 request alone Complete chronology of Section III J implementation efforts requested CLARK.R A Operating Reactors Branch 3 82/07/29 MUSQLF,D FNorthern States Power Co 4pp 14372 349 24x Fiche 50-282,82/07/29,8208170399
- 8208260089 Releases public version of revised corporate emergency plan FELTON, J M Division of Rules and Records 82/08/13 Document Management Branch 1p 14576 196 24X Fiche 50-000, 82/08/13, 8208260089
- --B20B2603i5 Forwards public version of Revision 5 to corporate nuclear emergency plan Updated info on App C items identified in NRC B20504 ltr encl LARSON,C E Northern States Power Ca 82/08/02 Region 3, Office of Director 4pp 14576 199 24% Fiche 50-000,82/08/13, B208260089
- --8208260319 Public version of Revision 5 to corporate nuclear emergency plan HUBGON, G , WARD, E , LARSON, C E Northern States Power Co 82/08/02 140pp 14576-203 24X Fiche 50-000,82/08/13, 8208260089
- 8208240353 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/08/i3 Document Management Branch ip 14375 069 24X Fiche 50-000,82/08/i3, 8208260353
- --8208260338 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1 1 2 renotifications & EPIP 1 1 5 re startup & operation of emergency operations facility HARD, E C Northern States Power Co 82/08/11 Region 3, Office of Director 1p 14575 072 24X Fiche 50-000,82/08/13, 8208240383
- --8208260360 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.2 re notifications & EPIP 1.1.5 re startup & operation of emergency operations facility

 * Northern States Power Co. 82/08/11 72pp 14575 073 24X Fiche 50-000, 82/08/13, 8208260353
- 8208300324 Provides add1 info in support of util 820520 request for relief from schedule for completion of 100FR50, App R. Section III J re emergency lighting mods Mods will be implemented by 830101 MUSOLF, D. Northern States Power Co. 82/08/23, Office of Nuclear Reactor Regulation, Director 8PP, 14597-084 24X Fiche 50-282, 82/08/23, 8208300324
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR 8vc list encl
 DIRCKS.W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York. 93pp 14174 001 24X Fiche.50-000.82/07/02.8207080064
- 8208020446 Provides results of post-implementation review of shift technical advisor training program Program meets intent of NUREG-0737, Item II A 1 i In future, all new hires into program should have bachelor degree or equivalent CLARK.R A Operating Reactors Branch 3 82/07/06 MUSDLF, D M Northern States Power Co 3pp. 14181.045. 24% Fiche 50-282, 82/07/06, 8208020446
- 8208020051 Forwards Amends 56 & 50 to Licenses DFR-42 & DFR-60, respectively, safety evaluation & notice of issuance & availability Amend increases peak burnup limit.
 DIIANNI.D C. Operating Reactors Branch 3 82/07/16. MUSQLF, D M. Northern States Power Co 3pp 14181.007 24X
 Fiche 50-282,82/07/16,8208020051
- --8208020054 Amends 56 & 50 to Licenses DFR-42 & DFR-60, respectively, revising App A Tech Spec peak burnup limit from 41,850 to 47,000 MWD/MTU CLARK, A Derating Reactors Branch 3. 82/07/16 6pp 14181 010 24X Fichs 50-282,82/07/16,8208020051.
- --8208020056 Safety evaluation supporting Amends 56 & 50 to Licenses DPR-42 & DPR-60.respectively. * Office of Nuclear Reactor Regulation, Director, 82/07/16 5pp 14181 016 24X Fiche 50-282,82/07/16,8208020051

- 820B040642 Advises that plant operation in Cycle 7 acceptable w/thermal margins for core loadings containing mixture of TOPROD & Exxon std fuel assemblies
 CLARK.R A Operating Reactors Branch 3 82/07/22 MUSDLF.D M
 Northern States Power Co 2pp 14224 023 24%
 Fiche 50-282.82/07/22.8208040642
- --8208040646 Safety evaluation supporting thermal hydraulic margins for Exxon TOPROD for Cycle 7

 " Office of Nuclear Reactor Regulation, Director 81/10/20 2pp 14224 025 24% Fiche 30-282,82/07/22,8208040642
- --B208040651 Safety evaluation supporting thermal hydraulic margins for Exxon TOPROD for Cycle 7

 ** Office of Nuclear Reactor Regulation, Director B2/07/09. 3pp 14224 027 24X Fiche 50-282, B2/07/22, B208040642
- 8208030228 Advises that Tech Spac change request re NUREO-0737, Items II E 1 1 & II E 1 2 concerning auxiliary feedwater sys uill be submitted by 820915 Delay due to organizational changes, workload & Unit 2 outage MUSDUF.D Northern States Power Co 82/07/28 Office of Nuclear Reactor Regulation, Director 1p 14158 295 24X Fiche 50-282, 82/07/28, 8208030228
- 8208110088 Forwards request for addl info re pressure & temp profiles outside containment as part of equipment environ qualification review to perform calculations for pipe breaks outside containment Info requested within 30 days CLARK, R A Operating Reactors Branch 3 82/07/29 MUSDLF, D M Northern States, Power Co. App. 14329 337 24X Fiche 50-282,82/07/29,8208110088
- 820Bi00194 Advises that Exxon 820708 itr transmitting XN-NF-82-49 (P) should be considered util response to TMI Item II K 3 30 Nethod/model changes have been made where necessary MUSQLF, D M Northern States Power Co 82/08/03 Office of Nuclear Reactor Regulation. Director ip 14298 196 24X Fiche 50-282, 82/08/03, 8208100194
- 820B100055 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Table 4, I-2A for waiver of end-of-cycle monthly turbine valve test Approval requested 2 months prior to Unit 1 refueling outage scheduled for B21113 MUSCLF, D. Northern States Fower Co. 82/08/06 Office of Nuclear Reactor Repulation, Director 1p 14296-224 24X Fiche 50-282,82/08/06,820B100055
- --8208100062 Application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Teble 4 1-24 for waiver of end-of-cycle turbine valve test Description of proposed changes & reasons encl. MWSDLF,D M Northern Bates Power Co 62/08/06 3pp 14296 225 24X Fiche 30-282.82/08/06.8208100055
- --8208100074 Revised Tach Spac Table 4 1-2A re min frequencies for equipment tests. Licensing fee determination encl * Northern States Fouer Co 82/08/06 2pp 14294 228 24X Fiche 50-282, 62/08/06: 6208100055
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc 1ist sucl EISENHUT, D. 0 Division of Licensing 82/08/09 Consolidated Edison Co. of New York 1p 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- B20B120151 Forwards proprietary version. "Computer Program Control Procedure." NAP 5.01P Procedure contains supplemental info to util reload methodology topical repts submitted B20212 Procedure withheld (ref 100FR2 790). Affidavit encl MUSOLF.D Northern Btates Power Co B2/0B/07 Office of Nuclear Reactor Regulation, Director. 5pp. 14326 030 24X Fichs. 50-282, 82/08/07, 820B120151.
- 8208200294 Forwards Revision 1 to application to amend DL & proposed Tech Spec changes re radiological effluent Tech Specs & environ monitoring MUSDLF,D Northern States Power Co 82/08/13 Office of Nuclear Reactor Regulation, Director 2pp 14394-146 24X Fiche 50-282, 82/08/13, 8208200294
- --820B200297 Revision 1 to application to amend OL, changing Tech Speca to enhance radiological effluent & environ monitoring * Northern States Power Co 82/08/13 3pp 14394; 148 24X Fichs 50-282,82/08/13,8208200294

- --8208200298 Revisions 1 to proposed Tech Spec changes, enhancing radiological effluent & environ monitoring Northern States Power Co. 82/08/13 63pp 14394 151 24X Fiche 50-282, 82/08/13.8208200274
- --8208200300 Revision 1 to "Offsite Dose Calculation Manual "
 MUSOLF.D Northern States Power Co 82/08/13 125pp 14394 214
 24% Fiche 50-282,82/08/13,8208200294
- 8208230338 Forwards "Process Control Program for Solidification of Radwaste from Liquid Sys " & proprietary pages to "Radwaste Bolidification Sys " Encls withheld (ref 10CFR2 790) HUSQLF,D M Northern States Power Co 62/08/13 Office of Nuclear Reactor Regulation, Director 3pp 14913 196 24X Fiche 50-282,82/08/13,8208230338
- 8208200084 Forwards responses to 820603 questions re station electric distribution sys voltage study Installation of second startup transformer will provide fizzible & reliable distribution sys MUSOLF, D. Northern States Power Co. 82/08/17 Office of Nuclear Resector Regulation, Director 20pp 14373 221 24X Fiche 50-282,82/08/17,8208200084
- 8208240136 Advises that Tech Spec Section 3 3 A 1 (g) applies to safety injection pump discharge cross-connect valves & other ECC3 valves.in response to NRC Bi1201 ltr Section work instruction requires monthly surveillance of subj valves MMSDLF.D M Northern States Power Co 82/08/19 Office of Nuclear Reactor Regulation, Director 1p 14517 333 24X Fiche 50-282,82/08/19,8208240136
- B208270294 Provides confirmation of info discussed in earlier telcoms re containment purging & venting during normal operation MUSOLF,D Northern States Fower Co 82/08/23 Office of Nuclear Reactor Regulation, Director 4pp 14564 178 24X Fiche 50-282,02/08/23,8208270294
- Q. Inspection reports: IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDANIE L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8208050508 Forwards IE Insp Repts 50-282/82-09 & 50-306/82-09 on 820601-30 No noncompliance noted STREETER, J F Region 3, Office of Director 82/07/19 LARSON, C E Northern States Power Ca 2pp 14214 061 24X Fiche 50-282, 82/07/19, 8208050508
- --8208050521 IE Insp Repts 50-282/82-09 & 50-306/82-09 on 820601-30 No noncompilance noted Major areas inspected plant operation,maint, organization, surveillance, socurity, radiation protection, Let followup & refueling activities FEIERABEND, C D . BURGESG, B L . REVES, L Region 3, Office of Director 82/07/15 9pp 14214 063 24X Fiche 50-282,82/07/19,8208050508
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure" Svc list enci JORDAN,E L Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fichs 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edsson Co of New York 71pp 1435/276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPC1 Turbine Exhaust Check Valve Failures." 8vc list enci JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321. 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Byc list and JORDAN-E L Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRO) Quide Tube Support Pin Failures at Westinghouse PMRs " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 JE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Cartain Westinghouse PWR Power Plants " Svc list encl JORDAN: E.L. Division of Engineering & Quality Assurance 82/07/24 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000: 82/07/26. 8204210403
- 8204210405 lE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc 11st encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000.82/07/28.8204210405
- 8208100080 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants" RCPB insps performed at regular intervals Few leakage problems experienced at facility LARSON, C.E. Northern States Power Co. 82/08/02 KEPPLER, J. Q. Region 3, Office of Director. 4pp. 14294 145 24X Fiche 50-282,82/08/02,8208100080
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Daffle Water-Jet Impingoment" Svc list encl JORDAN.E L. Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co. of New York 117pp 14388 201 24X Fiche 50-000,82/08/05,8204210407
- 8208240037 Forwards Franklin Research Ctr request for addi info re 811130 response to IE Bulletin 60-11, "Masonry Walls " Info requested within 30 days CLARK, R A Operating Reactors Branch 3 82/08/12 MUSOLF, D M Northern States Power Co 5pp 14548 185 R4X Fichs 50-282,82/08/12,8208240037
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24% Fiche 90-900, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1" * NRC - No Detailed Affiliation Given 82/07/13, 48pp. 14679 216 24% Fiche 50-000.82/07/13,8208270010
- --8208270209 Forwards annual rept of occupational radiation exposures for CY81.per 10CFR20 407
 SCHUELKE, D A Northern States Power Co 82/02/02 Office of Hanagement and Program Analysis 1p 14679 282 24X
 Fiche 50-000,82/07/13.8208270010.
- --8208270215 Annual occupational radiation exposure rept for CY81 * Northern States Fower Co 82/02/02 ip 14679 283 24X Fiche. 50-000, 82/07/13, 8208270010
- 8208270619 Forwards rept on number of personnel & man rem by work & job function for 1981, per NUREO-0737, Item II K 3 3 MAYER, L O Northern States Power Co 62/02/26 KEPPLER, J Q Region 3, Office of Director ip 14679, 342 24X Fiche: 50-000, 82/07/13, 8208270619
- ---8208270626 Rept on number of personnel & man rem by work & job function for 1981 * Northern States Power Co 82/02/26 2pp 14679 343 24X Fiche 50-000,82/07/13,8208270619
- 8208130198 Forwards monthly operating repts for Jul 1982 MUSGLF,D Northern States Power Co. 82/08/10 Director's Office, Office of Inspection and Enforcement ip 14339 105 24X Fichs 50-282,82/08/10,8208130198
- --8208130202 Monthly operating repts for Jul 1982, DUOSTAD:D Northern States Power Co. 82/08/04 8pp 14339:106, 24% Fichs 50-282,82/08/10,8208130198
- S Reportable occurrences, LERs & related correspondence
- 8208020119 Forwards LER 82-011/03L-0 MUSDLF.D Northern Btates Power Co 82/07/20 Region 3, Office of Director 1p 14142 104, 24X Fiche 50-282,82/07/20,8208020119

--8208020123 LER 82-011/03L-0 on 820622, motor-driven auxiliary feedwater pump 12 failed to start during surveillance test Caused by installing self-cleaning oil filter backwards, allowing build up of sludge Filter reversed HUNBTAD. A A Northern States Power Co. 82/07/20 Region 3, Office of Director 1p 14142 105 24x Fiche 50-282, 82/07/20, 8208020119

DOCKET 50-284 IDAHO STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc 11st and Included Included

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

- 8208030475 Forwards IE Sefeguards Insp Rept 50-285/82-08 on 820513-14 No noncompliance noted Rept withheld (ref 10CFR2 770) SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs. 82/07/19 JONES, W C Ommah Public Power District 2pp, 14164 067. 24X Fiche. 50-285, 82/07/19, 8208030475
- B208060032 Releases public version of revision to emergency plan implementing procedures.

 FELTON, J M Division of Rules and Records 82/08/02 Document Management Branch 1p 14244-286 24X Fiche 50-285, 82/08/02, 8208060032.
- --8208060034 Forwards public version of Revision B to Emergency Plan Implementing Procedure EPIF-OBC-2. "Emergency Plan Activation" & Revision 2 to EPIF-EDF-18-1. "Gffsite Radiological Burveys"

 JONES, W C Omaha Public Power District 82/07/22 SEIDLE, W. C Division of Resident, Reactor Project & Engineering Programs 1p 14244:287 24X Fiche 50-285,82/08/02,8208060032
- --B208060036 Public version of Revision 3 to Emergency Plan Implementing Procedure EFIP-08C-2, "Emergency Plan Activation" & Revision 2 to EFIP-EGF-18-1, "Offsite Radiological Surveys " Revised table of contents encl # Omaha Public Power District 82/07/15 28pp 14244 288 24X Fichs 50-285,82/08/02,8208060032.
- 8208120165 Approves 1982 emergency exercise scope scanario description transmitted w/820701 ltr Item 8 of exercise objectives assumed not to include simulation of evacuation for monessential personnel from vital & protected areas, SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/08/09, JÜNES, W C Gmaha Public Power District. lp, 14319:279 24% Fiche 50-285,82/08/09,8208120165
- ---8208120168 Forwards 1982 emergency exercise scope scenario description in response to 820114 request.

 JONES, W.C. Omaha Public Power District 82/07/01, COLLINS, J.T., Region 4. Office of Director. Spp. 14319, 280 24X
 Fiche 50-285, 82/08/09, 8208120165
- B20B160452 Forwards IE Bafeguards Insp Rept 50-285/82-10 on 820504-05 No noncompliance noted Rept withheld (ref 10CFR2.790). SEIDLE: W C Division of Resident, Reactor Project & Engineering Programs. B2/08/10 JONES: W C C
- B20B3i0376 Advises that util design meets requirements of 10CFR50, App R. Itams III Q.3 & III L w/respect to safe shutdown in event of fire in control room or cable spreading room BER revision encl.

 CLARK, R. A. Operating Reactors Branch 3, B2/0B/12, JQNES, W C Omaha Public Power District, 5pp 14697*123 24% Fiche. B0-285. 82/08/12, B20B3i0376.
- 8208190170 Ack receipt of util 820722 ltr re changes to emergency plan implementing procedures Confirmation of transmittal enci per request SEIDLE, M. C. Division of Resident, Reactor Project & Engineering Programs, 82/08/16 JONES, M. C. Omaha Public Power District. ip. 14386-314, 24x Fishe, 50-285, 82/08/16.8208190170.
 - 14386 314, 24% Fighe 50-285, 82/08/16, 8208190170.
- --8208190172 Requests completion of encl transmittal sheets confirming receipt of util emergency plan implementing procedures.

 JONES W C. Dmaha Public Power District, 82/07/22, 8EIDLE, W C Division of Resident Reactor Project & Engineering Programs 4pp 14386:315 24X Fiche. 50-285, 82/08/16, 8208190170

- B208240153 Requests clarification of B20601 ltr re exact location of emergency plan implementing procedure changes concerning deficiencies noted in IE smergency preparedness appraisal on B11207-16
 BEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/08/18 JUNES.W C Dmaha Public Power District. ip. 14520 129 28% Fiche 50-285.82/08/18:8208240153
- 8208270354 Confirms 820818 telcon re licensee 820804 request for installation of health physics network & emergency notification systelephones in permanent technical support ctr. Installation will take at least 60 days.

 SEIDLE: W C Division of Resident, Reactor Project & Engineering Programs 82,08/20, JONES,W C Omaha Public Power District. 2pp 14565 078 24X Fiche 50-285,82/08/20,6208270354
- --B20B270362 Requests installation of health physics network & emergency notification sys telephones in permanent technical support ctr by 820907.

 JONES, W. C. Omaha Public Power District. 82/08/04 GEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 2pp. 14565

J Insurance & indemnity information

8208310193 Forwards Endorsements 44 & 47 to MAELU Policy MF-63 & Endorsements 51-55 to NELIA Policy NF-207 PETERBEN.H E Omaha Public Power District 82/08/26 DINITZ, I Antitrust & Economic analysis Branch (Utility Finance), 12pp. 14693 163, 24X Fichs 50-285.82/08/26,8208310193

K Utility Final Safety Analysis Report (FSAR) & amends

- 8208030549 Forwards Fort Calhoun 1 updated FBAR, incorporating plant mods & reflecting info & analyses submitted to NRC since previous submittal of FBAR Afridavit & list of plant changes made under 100FR50 55, but not previously reported, encl.

 JONES, W C Gmaha Public Power District 82/07/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. App. 14846:001. 24X Fiche 50-285,82/07/22,8208030549
- --8208030554 Fort Calhaun 1 updated FBAR, Vols 1-7, + Omeha Public Power District 82/07/22 2,115pp. 14846.005, 24% Fiche 50-285, 82/07/22, 8208030549.
- 8208030558 Chapter 1 to Fort Calhoun 1 updated FBAR, "Introduction & Summary "

 * Omaha Public Power District. 82/07/22 200pp 14846.011 24X Fiche.50-285.82/07/22,8208030558
- 8208030563 Chapter 2 to Fort Calhoun 1 updated FSAR, "Bite & Environs."

 * Omaha Public Power District. 82/07/22 190pp 14846 147 24K
 Fiche: 50-285, 82/07/22, 8208030563
- 8208030566 Chapter 3 to Fort Calhoun 1 updated FSAR, "Reactor" * Omaha Public Power District 82/07/22, 100pp, 14846:265 24X Fiche: 50-285, 82/07/22, 8208030566
- 8208030571 Chapter 4 to Fort Calhoun 1 updated FSAR, "RCS" * Omaha Public Power District 82/07/22, 100pp, 14847-011. 24X Fiche. 50-285, 82/07/22, 8208030571
- 8208030575 Chapter 5 to Fort Calhoun 1 updated FSAR, "Structures." * Omeha Public Power District. 82/07/22 250pp 14847:127, 24X Fichs. 50-285, 82/07/22, 8208030575.
- 8208030580 Chapter & to Fort Calhoun 1 updated FSAR, "Engineered Bafeguards."

 * Omaha Public Power District 82/07/22 75pp 14847:354, 24X Fiche 50-285,82/07/22,8208030580.
- 8208030584 Chapter 7 to Fort Calhoun 1 updated F8AR, "Instrumentation & Control "

 * Omaha Public Power District 82/07/22 100pp. 14846 064. 24X
 Fiche: 80-285, 82/07/22, 8208030584
- 8208030590 Chapter 8 to Fort Calhoun 1 updated FSAR. "Electrical 84s." * Omaha Public Power District. 82/07/22 75pp 14848:179. 24% Fiche 50-285,82/07/22,8208030590
- 8208030593 Chapter 9⁴ to Fort Calhoun I updated FSAR, "Auxiliary Bys." * Cmaha Public Power District 82/07/22 150pp. 14848,247 24X Fiche: 50-285,82/07/22,8208030593
- 8208030601 Chapter 10 to Fort Calhoun 1 updated FSAR, "Steam & Power Conversion 8us" # Omaha Public Power District 82/07/22, 23pp 14849-030, 24X Fiche 50-285, 82/07/22, 8208030601

- 8208030606 Chapter i1 to Fort Calhoun I updated FSAR. "Radwaste & Radlation Protection & Monitoring "

 * Unmaha Public Power District 82/07/22 100pp 14849 053 24X Fiche 50-285, 82/07/22.8208030606
- 8208030612 Chapter 12 to Fort Calhoun 1 updated FSAR, "Conduct of Querations
 - uperations "
 4 Omaha Public Power District 82/07/22 29pp 14849 154 24X
 Fiche 30-265-82/07/22.8208030612
- 8208030514 Chapter 13 to Fort Calhoun 1 updated FSAR, "Initial Tests & * Omaha Public Power District Fiche 50-285, 82/07/22, 8208030614 82/07/22 7pp 14849 183 24X
- 8208030619 Chapter 14 to Fort Calhoun 1 updated FSAR, "Safety
- * Omaha Public Power District 82/07/22 225pp 14849 190 24X Fiche 50-285, 82/07/22, 8208030619
- 8208030623 Chapter i5 to Fort Calhoun i updated FSAR, "Tech Specs * Omaha Public Power District 82/07/22 ip 14850 076 24 Fiche 50-285, 82/07/22, 8208030623
- 8208030628 App A to Fort Calhoun 1 updated FSAR. "GA Program " Umaha Public Power District 82/07/22 38pp 14850 077 Fichs 50-283, 82/07/22, 8208030628
- 8208030632 App B to Fort Calhoum 1 updated FSAR, "81te Environ
- # Omaha Public Power District 82/07/22 3pp 14850 115 24X Fishe 50-285,82/07/22,8208030632
- 82/07/22 101nn
- 9208030637 App D to Fort Calhoun 1 updated FBAR, "Pile Load Test * Dames & Moore 82/07/22 100pp Omaha Public Power District 14850 218 24x Fiche 50-285,82/07/22,8208030437
- 8208030642 App E to Fort Calhoun 1 updated FSAR, "Qualifications & Resumes of Station Operating & Technical Personnel "

 * Omaha Public Power District 82/07/22 12pp 14850 334 2/Fiche 50-285,82/07/22,820803042 14850 334 24X
- 8208030647 App F to Fort Calhoun 1 updated FBAR. "Classification of Structures & Equipment & Seismic Criteria " * Omaka Public Power District 82/07/22 60pp 14850 346 24X Fiche 50-285.82/07/22,8208030647
- 8208030652 App G to Fort Calhoun 1 updated FBAR, "Responses to 70 Criteria " # Omaha Public Power District 82/07/22 80pp 14851 044 24X Fiche 50-285,82/07/22,8208030652
- 208030457 App H to Fort Calhoun 1 updated FBAR, "Training Summaries of Fort Calhoun Station Unit 1 Related Personnel " + Omaha Public Power District 82/07/22 75pp 14051 128 24X Fiche 50-285, 82/07/22, 8208030657
- **OB030661 App 1 to Fort Calhoun 1 updated FSAR, "Startup Manual"

 ** Omaha Public Power District 82/07/22 50pp 14851 209 2
 Fiche 50-285,82/07/22,8208030661
- 208030664 App J to Fort Calhoun & updated FSAR, "Bupplementary Meteorological Correlations "

 Dasha Public Power District 82/07/22 ip 14851 271 24X
 Fiche \$0.285.82/07/22, 82/80830664
- 208030673 App L to Fort Calhoun 1 updated FBAR, "Predicted Creep Collapse Behavior for Fort Calhoun Fuel Cladding,"

 8 Clasha Public Power District 82/07/22 2pp 14851 273 2/Fiche 50-285.82/07/22,8208030673 14851 273 24X
- 3BO30675 App M to fort Calhoun 1 updated FSAR, "Postulated High "sergy Line Rupture Dutside Containment" Gmaha Public Power District B2/07/22 50pp 14851 278 24X che 50-285, 82/07/22,8208030675

- 8208030679 App N to Fort Calhoun & updated FSAR, "Reclassification of Sys Umaha Public Power District 82/07/22 6pp 14851 325 24X Fiche 30-285, 82/07/22, 8208030679
- 8208240177 Requests ack of receipt of Copies 85 & 86 of updated FBAR forwarded under separate cover Transmittal sheets should be completed & returned Other responsible person should be designated on transmittal sheets JONES, W.C. Omaha Public Power D JONES, W C Omaha Public Power District 82/08/12 SEIDLE, plyssion of Resident, Reactor Project & Engineering Programs 14521 212 24X Fiche 50-285, 82/08/12, 8208240177
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for For DL & notices of CP Te Commission approved charter for CROR Svc list encl
 DIRCKS.W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14
 24X Fiche 50-000.82/07/02:8207088064 14174 001
- 8208040083 Requests schedule for responding to evaluation criteria guidelines re NUREG-0737. Item [I B 3. "Post-Accident Sampling Bys." within 20 days CLARK.R A Operating Reactors Branch 3 82/07/14 JONES, W C Omaha Public Power District 10pp 14228 309 24X Fiche 50-285, 82/07/14, 8208040083
- 8208050012 Forwards safety evaluation identifying three open items re App J containment leak testing review NRC review put on hold pending receipt of licensee Info Response due in 30 days Supplemental EER will be issued upon review completion CLARK, R A Operating Reactors Branch 3 82/07/23 JUNES, W C Omake Public Power District 3pp 14243 073 24X Fichs 30-285, 82/07/23, 8208080012
- --- 8208050013 Safety evaluation re App J review Three open items identified
 - ** Operating Reactors Branch 3 82/07/23 3pp 14243 076 24x Fiche 50~285,82/07/23,8208090012
- 8208090038 Forwards request for add1 info needed to review 820318 request re spent fuel storage mod to increase storage capacity capacity CLARK,R A Operating Reactors Branch 3 82/07/26 Omaha Public Fower District 5pp 14301 109 24) Fiche 50-285,82/07/26,8208090038
- 8208130038 Advises that procedure for natural circulation cooldown implemented effective 820630 Procedure will be modified to incorporate use of reactor gas vent sys Sys could significantly reduce time to achieve cold shuddown JONES.W C Omaha Public Power District 82/08/05 CLARK.R A Operating Reactors Branch 3 1p 14335 074 24X Fichs 50-285,82/08/05,8208130038
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Svc list and EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York lp 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208130248 Responds to 820714 request for schedule for providing post-accident sampling sys info per TMI Action Item II B 3 Requested info substantially deviates from NUREG-0737 criteria Info will be provided by 82130 J
- 8208240165 Forwards rept on cleanup following introduction of 40 gallons of Texaco Tupe 46 hydraulic fluid into spent fuel pool due to failure of fuel insp stand hydraulic line JONES, W C. Omaha Public Power District 82/08/18 CLARK, R A, Operating Reactors Branch 4 22pp 14520 107 24X Fiche 50-285, 82/08/18, 8208240165
- B20B24017B Responds to 820714 ltr requesting add1 info re NUREG-0737, Item II K 3 17, "Rept on Outages of ECCS" LERs re maint outages encl JUNEB.W C Omaha Public Power District 82/08/17 CLARK, R A JUNEB, H C Omaha Public Power District 82/08/17 CLARK, R A Operating Reactors Branch 3 3dpp 14521, 215 24X Fiche 50-285, 82/08/19, 8208240178

- 8208310139 Forwards addl info re 820312 application for increased spent fuel atorage capacity at facility. In reponse to NRC 820726 1tr Summary of 820232 telcon & four oversize drawings encl Aperture cards are available in PDR JONES-H C Omaha Public Power District 82/08/27 CLARK,R A Operating Reactors Branch 3 54pp 14687 257 24X Fiche 30-285, 82/08/27, 8208310139
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list encl.
 JORDAN:E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14336 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1; "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list enci JORDAN, Et. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8208030475 Forwards IE Safeguards Insp Rept 50-285/82-08 on 820513-14 No noncompliance noted Rept withheld (ref 10CFR2 790) SEIDLE-W C Division of Resident, Reactor Project & Engineering Programs 82/07/19 JONES-W C Qmaha Public Power District. 2pp 14164 067. 24X Fiche 50-285/82/07/19,8208030475
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Syc list entl JURDAN.E L Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co. of New York 112pp 14381:001. 24X Fiche.50-000.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357, 276 24X Fiche: 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Bvc list encl, JORDAN E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208090040 Forwards safety evaluation of util analysis of main steam line break w/continued feedwater addition, submitted par IE Bulletin 80-04 Analysis acceptable CLARK,R.A. Operating Reactors Branch 3. 82/07/22 JONES,W C Omaha Public Power District 2pp 14283:327 24X Ficha 50-285,82/07/22,8208070040
- --8208090042 Bafsty evaluation supporting util analysis submitted per IE Bulletin 80-04 of main steam line break w/continued feedwater addition, submitted per IE Bulletin 80-04, * NRC No Detailed Affiliation Given 82/07/22 7pp. 14283, 329 24X Fiche 50-285, 82/07/22,8208090040.
- B204210401 IE Info Notice B2-2B, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS," Bvc list encl JORDAN, E.L. Division of Engineering & Quality Assurance B2/07/23, Consolidated Edison Co of New York, 122pp 143B0 115 24X Fiche: 50-000, 82/07/23, 8204210401
- B204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Bupport Pin Failures at Westinghouse PWRs " Evc list encl. JORDANIE L Division of Engineering & Guality Assurance B2/07/23, Consolidated Edison Co. of New York. 127pp. 14194-120, 24X Fiche 50-000, 82/07/23,8204210402.
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl, JORDAN, E L pivision of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York. 121pp. 14357.013. 24X Fiche 50-000.82/07/26.8204210403.
- 8204210405 lE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool," Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28, Consolidated Edison Co. of New York. 122pp 14357 146, 24X
 Fiche: 50-000: 82/07/28, 8204210405
- 8208180070 Forwards IE Insp Rept 50-285/82-12 on 820601-30 & notice of violation BEIDLE, M. C. Region 4, Office of Director. 82/07/28, JONES, W.C. Omaha Public Power District. 4pp, 14377; 042 24X Fiche: 50-285, 82/07/28, 8208180070.

- --8208180074 Notice of violation from insp on 820401-30
 * Region 4, Office of Director 82/07/28 ip 14377 044 24X
 Fiche 50-285,82/07/28,8208180070
- --8208180081 IE Insp Rept 50-285/82-12 on 820601-30 Noncompliance noted failure to follow radiation protection manual procedures
 YANDELL, L A , HALL, R E Region 4, Office of Director. 82/07/22 opp 14377 047. 24X Fiche 50-285,82/07/28,8208180070
- 82080&0213 Ack receipt of 820421,0503 & 0715 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/82-02 SEIDLE-W.C Division of Resident, Reactor Project & Engineering Programs 82/08/02 JONES.W C Omeha Public Power District 1:14241 086. 24% Fichs 50-285,82/08/028,8208060213
- --8208060216 Responds to NRC 820322 & 0702 ltrs re violations noted in IE Insp Rept 50-285/82-02. Corrective actions requalification exams will commence in Fall 1982 using randomly selected questions from training dept bank JONES, W C Omaha Public Power District, 82/07/15. BEIDLE, W. C Division of Resident, Reactor Project & Engineering Programs. 1p 14241 087 24X Fiche 50-285, 82/08/02, 8208060213
- 820B1800B9 Forwards response to 1E Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants."

 JONES, W. C. Omaha Public Power District 82/08/02 COLLING, J. T. Region 4, Office of Director App 14376 319 24X
 Fiche. 50-285, 82/08/02, 8208180089
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl. URDANNE, L. Division of Engineering & Quality Assurance. 82/08/05, Consolidated Edison Co. of New York 117pp 14388: 201. 24X Fiche 50-000.82/08/05.8204210407.
- 8208160452 Forwards IE Bafeguards Insp Rept 50-285/82-10 on 820504-05 No noncompliance noted Rept withheld (ref 10CFR2, 790). SEIDLE: W C Division of Resident, Reactor Project & Engineering Programs 82/08/10 UNES, W C Omaha Public Power District 2pp 14349-289 24X Fichs 50-285,82/08/10.8208160452
- 8208190236 Ack receipt of 820210,0512 & 0601 ltra informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/81-30 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs, 82/08/13, J
- --8208190247 Responds to NRC 820111 ltr re violations noted in IE Insp Rept 50-285/81-30 Corrective actions Standing Order 9-26 revised & review of all surveillance test procedures completed JONES, W. C. Omaha Public Power District. 82/05/12 SEIDLE, W. C. Region 4. Office of Director 2pp. 14388.193 24X Ficher 30-285,82/08/13,8208190236
- --8208170264 Responds to NRC 820111 ltr re violations noted in IE Insp Rept 50-285/81-30. Corrective actions Standing Order 9-22. "Storage of Critical Quality Elements." revised to incorporate tagging program UNNES, W C Omaha Public Power District 82/06/01 SEIDLE, W. C Division of Resident Reactor Project & Engineering Programs. 1p 14388, 174 24% Fiche 50-285, 82/08/13, 8208170236.
- --8208190276 Responds to NRC 820111 ltr re violations noted in IE lnsp Rept 50-285/81-30 Corrective actions Standing Order 0-28. "Stolen Fire Protection Plan," will be revised to include responsibilities of assistant general manager, JONES, M.C. Omaha Public Power District 82/02/10, COLLINS, J. T. Region 4, Office of Director App 14388.195, 24X Fiche, 50-285, 82/08/13, 8208190236
- 8208270318 Forwards IE Insp Rept 50-285/82-14 on 820701-31 No noncompliance noted. SEIDLE,W C Division of Resident, Reactor Project & Engineering Programs 82/08/13, JONES,W C. Omaha Public Power District. Rpp 14565:031 24X Ficher 50-285,82/08/13,8208270318.
- --8208270320 IE Insp Rept 50-285/82-14 on 820701-31.No noncompliance noted, Major areas inspected; operational safety verification, surveillance testing, maint & LER followup, YANDELL, L. A. JAUDON, J. P. Division of Resident, Reactor Froject & Engineering Programs 82/08/12, 5pp. 14545; 033, 24X Fiche: 50-285,82/08/13,8208270318.

- 8208240153 Requests clarification of 820601 ltr re exact location of emergency plan implementing procedure changes concerning deficiencies noted in IE emergency preparedness appraisal deficiencies notes in its emergency preparations appresses.

 BEIDLE: W C Division of Resident, Reactor Project & Engineering Programs 62/08/18 JONES, W C Omaha Public Power District 14520 129 24X Fiche 50-285, 82/08/18, 8208240153
- 8208240274 Ack receipt of 820625 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/82-06
 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/08/18 JONES, W C Omaha Public Power District 1p 14528 093 24X Fiche 50-285,82/08/18,8208240294
- --8208240298 Responds to NRC 620527 ltr re violations noted in IE Insp. Rept 50-285/B2-06 Corrective actions contractor personnel involved in handling & insp. of irradiated fuel rods reinstructed further control of future work to be provided JONES. W. C. Cmaha Public Power District 82/06/25 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 3pp. 14528 094 24X Fiche 50-285,82/08/18.8208240294
- 8208270367 Forwards Bystematic Assessment of Licensee Performance Rept 50-285781-37 for Jul 1980-June 1981 Major area discussed mgt_involvement in GA Rept being issued as NRC rept H/o COLLINS. J T Region 4. Office of Director 82/08/20 JONES, W C Omaha Public Power District 2pp 14564 239 24X Fiche 50-285, 82/08/20, 8208270367
- --8208270371 Forwards Systematic Assessment of Licensee Performance Rept 50-285/81-37 for June 1980-Jul 1981 Major area discussed mgt involvement in GA Comments requested within 20 days 6EIDLE,N C Division of Resident, Reactor Project & Engineering Programs 82/06/25 JONES.N C Omaha Public Power District 19ap 14564 241 24X Fiche 50-285.82/08/20,8208270367
- 8208310278 Ack receipt of util 820729 ltr re insps.analyses & mods completed in response to IE Bulletins 79-02 & 79-14 EEGIDLE.H C Division of Resident, Reactor Project & Engineering Programs 82/08/23 JONES.H C Omaha Public Power District : 14688: 273 24X Fich# 50-285,82/08/23,8208310278
- --B208310282 Submits final rept re IE Bulletins 79-02 & 79-14 re piping sys Insps, analyses & mods completed prior to June 1980 startup Consultant verified that safety-related piping seismically qualified
 JONES,W C Omaha Public Power District 82/07/29 SEIDLE,W C
 Division of Resident. Reactor Project & Engineering Programs :
 14688 275 24% Fiche 50-285,82/08/23,8208310278
- R Periodic operating reports & related correspondence
- 9208270010 Responds to FOIA request for documents detailing collective 20B2/0010 Responds to FULA request for documents detailing collects dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON. J M Division of Rules and Records 02/07/13 UDELL,R A "Critical Hass Energy Project 8pp 14679 208 24X Fiche 50-000,82/07/13,8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVB1 " NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24x Fiche 50-000, 82/07/13, 8208270010
- 3208190089 Forwards monthly operating rept for Jul 1982 JONES, W C Omaha Public Power District 82/08/10 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 14383 174 24x Fiche 50-285,82/08/10.8208190089
- --8208190093 Nonthly operating rept for Jul 1982 8HORT,R W Omaha Public Power District 82/08/ 14383 175 24X Fiche 50-285,82/08/10,8208190089 82/08/10 12pp
- S Reportable occurrences. LERs & related correspondence
- 8208100003 RD on 820521, no flow candition observed on blowdown sample 209100003 AU on B20521, no flow condition observed on blowdown; flow from RC-2B Caused by closure of KCV-2507A (containment isolation blowdown sample valve) Valve immediately opened Investigation continuing, JGNES, W.C. Omaha Public Power District B2/05/21 SEIDLE, W. Division of Resident, Reactor Project & Engineering Programs 14296 361 24X Fiche 50-285,82/05/21,8208100003 SEIDLE H C
- 8208200135 Forwards LER 82-016/03L-0 JONES, W C Omaha Public Power District 82/08/10 SEIDLE, W Division of Resident, Reactor Project & Engineering Programs 14393:342 24K Fiche 50-285,82/08/10.8208200135

- --8208200149 LER 82-016/03L-0 on 820714, Channel B of reactor protective sys axial gower distribution unit had negative axial shape index setpoint out of tolerance Caused by setpoint drift due to dirty contact in flow dependent setpoint selector switch MUELLER, R. Omaha Public Power District B2/07/26 Region 4, Office of Director 4pp 14393 343 24% Fiche 50-285,82/08/10,8208200135
- 820824017B Responds to 820714 ltr requesting addl info re NUREG-0737, Item II K 3 17. "Rept on Outages of ECCS" LERs re maint outages encl
 JONES. W C Umaha Public Power District 82/08/19
 Operating Reactors Branch 3 36pp 14521 215 24
 Fiche 50-285.82/08/19/8208240178 19 CLARKIR A 24X
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8208030080 Responds to Rockland County Legislature Resolution 320 prohibiting use of county employees funds for federally mandated radiological response plans for facilities FEMA will provide findings on adequacy of offsite preparedness DEYOUND.R C Director's Office. Offsice of Inspection and Enforcement 82/07/06 GRANT.J T Rockland County, NY 2pp 14200 287 24X Fiche 50-247.82/07/06.8208030080
- --8208030085 Requests FEMA findings on adequacy of offsite preparedness around facilities to determine whether to invoke provisions of NRC regulations requiring licensee to demonstrate removal of identified significant deficiencies ORIMES, B K Division of Emergency Preparedness 82/06/16
 KRIMM.R M Federal Emergency Management Agency. 4pp 14
 24X Fiche 50-247,82/07/06,8208030080
- 820730050B Responds to 820602 ltr concerning amergency response plans for facilities & requesting initiation of 120-day regulatory clock against facilities FEMA will provide findings on adequacy of plant offsite preparedness
 DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/07/07 DEL BELEG.A B Westchester County,NY 4pp. 14172 063 24X Fiche 50-247,82/07/07,8207300508
- --8206060006 Expresses concerns re facility emergency response plans & 200000000 Expresses concerns re facility emergency response pla requests initiation of 120-day regulatory clock against facilities Critiques on emergency drill encl DELBELLO.A B Westchester County, NY 82/06/02 PALLADIND, N Commissioners 57pp 14172 066 24X Fiche 50-247, 82/07/07, 8207300508
- 8208050295 Forwards IE Emergency Preparedness Appraisal Rept 50-286/82-02 on 820208-11 No noncompliance noted SMITH, O H. Division of Emergency Preparedness & Operational Support 82/07/22 RRNS, J C Power Authority of the State of New York 2pp 14210 188 24X Fiche 50-286,82/07/22,8208030295
- --B20B050306 IE Emergency Preparedness Appraisal Rept 50-286/82-02 on 820208-11 No noncompliance noted Major areas inspected followup of emergency preparedness items from prior appraisal on 810511-20 TERG: N M . CROCKER, H W Division of Emergency Preparedness & Operational Support 82/07/22 13pp 14210.190 24X Fiche, 50-286, 82/07/22.8208050295
- 8208050050 Forwards FEMA 820802 ltr & interim findings rept on adequacy of radiological emergency response preparedness of state & local govts near plant
 HABSELL, D.F. Hearing Branch 1 82/08/02 CARTER, L. J. Safety and Licensing Board Panel 36pp, 14213 231 24
 Fiche 50-247, 82/08/02, 8208050050 Atomic 244
- 820B100143 Notifies that NRC will determine whether reactor should be shutdown if significant deficiencies identified in FEMA 820B02 ltr are not corrected within 120 days Written statement describing plans requested within 30 days HAYNES.R C Region 1. Office of Director 82/08/03 BAYNE, J P. Power Authority of the State of New York 2pp 14298.053 24X Fiche 50~286, B2/08/03, 8208100143
- --8208100151 Forwards FEMA interim findings rept on adequacy of radiological emergency response preparedness of state & local govts at Indian Point Power Btation Plans & preparedness inadequate
 THOMAS,L M Federal Emergency Management Agency 82/08/02
 DIRCKS.W Office of the Executive Director for Operations 14298 055. 24X Fiche 50-286, 82/08/03, 8208100143
- ---B208100195 Interim findings on adequacy of radiological emergency response preparadness of state & local govts at Indian Point Nuclear Power Station PETRONE, F.P. Fadaral Emergency Management Agency 82/07/30 33pp. 14278

- 8208190196 Forwards Revision 3 to security force training & qualification program Rept withheld (ref 10CFR2 790)
 BAYNE, J P Power Authority of the State of New York 82/08/09
 VARGA, 8 A Operating Reactors Branch 1 2pp 14387 046 24X
 Fiche 50-286, 82/08/09, 8208190196
- 8208270155 Forwards Revision 7 to security plan Revision withheld (ref 10CFR2 790 & 10CFR73 21)
 BAYNE, J P Power Authority of the State of New York 82/08/09 VARGA, B A Derating Reactors Branch 1 Ip 14563 318 24% Fiche: 50-286, 82/08/07, 8208270155
- 8208170407 Ack receipt of 820427 & 0515 ltrs transmitting changes to security plan Changes consistent w/provisions of 10CR50 54(p)

 VAROA: B A Operating Reactors Branch 1 82/08/10 BINCLAIR, L W Power Authority of the Btate of New York 2pp 14372 345 24X Fiche 50-286, 82/08/10. 2008170407
- 820B310499 Releases public version of licenses advice re revisions to emergency plan procedures FELTON.J M Division of Rules and Hecords 82/08/13 Document Management Branch. 1p 14697 284 24X Fiche 50-284,82/08/13, 820B310499
- --8208310503 Rubmits public version of advice that most recent revisions to emergency plan procedures were distributed to NRR, Region I Resrgency Preparedness Section & NRC facility resident inspector

 BRONS.J C Power Authority of the State of New York 82/07/30 HAYNES.R.C, Region I, Office of Director 1p 14697 285 24X Fiche 50-286,82/08/13,8208310499

9 Adjudicatory correspondence

- 8208110236 Rexponse to UCB/NY PIRQ 820521 request for admissions Affidavits & Certificate of Bvc encl MCGURREN. H J Hearing Branch 1 82/06/11 Union of Concerned Scientists 25pp 14330.315 24X Fiche 50-247.82/06/11,8208110236
- 8208270458 Expresses appreciation for opportunity to address ASLB, DIAMANT.L Affiliation Unknown 82/07/07 CARTER.L Atomic Safety and Licensing Board Panel ip. 14965 272, 24X Fiche 50-247, 92/07/07, 8208270458.
- 8208030348 Response to final set of interrogatories & document requests re Commission Question I Certificate of Syc encl Related correspondence POBNER.P Parents Concerned About Indian Point. 92/07/23 Consolidated Edison Co
- 8208030335 Attempts to clear confusion of ASLB 820714 & 16 telcons to Comm Ed Conversation on 820714 was substantive Discussions re-merits of motions or issues should be entertained only w/all parties participating. W/Certificate of Svc SDHINKI,S M Consolidated Edison Co of New York 82/07/27 CARTER,L J Atomic Safety and Licensing Board Panel 7pp 14156 351. 24X Fichel 50-247,82/07/27,8208030335
- 820Bi60223 Memorandum & Order CLI-B2-i5 denying PABNY request for directed certification of charges that ASLB exceeded or misapplied jurisdiction in admitting UCS & other intervenor contentions Addl Commissioner views encl CHILK-B.J. Office of the Secretary of the Commission B2/07/27. 30pp 14346, 270. 24x Fiche 50-247, 82/07/27, 820Bi60223
- B208020275 Urges Order CLI-82-15 be rescinded Interests of nearby residents must be considered MESSINGER, R L , FRIEDLANDER, M , GREITZER, C New York, NY 82/07/28 PALLADINO, N J , AHEARNE, J , GIL INSKY, V Commissioners 19 14152-262 24X Fichs 50-247,82/07/28,8208020275.
- 820B020281 Expresses outrage on behalf of Alliance to Close Indian Point at order CLI-82-15 narrowing scope of hearing. POSMER: P Affiliation Unknown 82/07/28, FALLADINO, N J . AHEARNE. J F. . ROBERTS . T M Commissioners. ip 14151.311. 24X Fichs. 50-247, 82/07/28, 820B020281.
- 8208050050 Forwards FEMA 820802 ltr & interim findings rept on adequacy of radiological emergency response preparedness of state & local govts near plant HABSELL, D.F. Hearing Branch 1 82/08/02, CARTER, L.J., 8HON, F.J., PARIS, O.H. Atomic Sefety and Licensing Board Fanel 36pp. 14213-231. 24X Fiche: 50-247, 62/08/02, 8208050050

- 8208D&0100 Requests immediate suspension of plant QLs until determination made that adequate emergency plans exist that are capable of protecting public wells. ER is SHDLLY, S C Union of Concerned Scientists WEISB.ER Harmon & Weiss B 2708/04 PALLADING, N J OILINSKY, V , AHEARNE, J Commissioners Spp 14238 173 24X Fiche 50-247,82/08/04,82080A0100
- 8208100053 Forwards Region 1 820803 ltrs to licensees re emergancy preparedness HABSELL, D F Hearing Branch 1 82/08/05 CARTER, L J, SHON, F J, PARIS, O H Atomic Bafety and Licensing Board Panel. Spp 14296 234 24X Fiche 50-247, 82/08/05, 8208100053
- 8208110079 Memorandum & certification seeking further Commission guidance on witness testimony on consequences & probabilities & evidence on status & degree of conformance w/NRC/FEMA guidelines CARTER.L J. PARTS.O H: SHON,F J Atomic Bafety and Licensing Board Panel 82/08/09 6pp 14316 344 24X Fiche 50-247.82/08/09.
- 820Bi10085 Errata to 820809 memorandum & certification, correcting typographical errors CARTER, L. J. Atomic Safety and Licensing Board Panel 82/08/09 ip 14316 343 24% Fichs 50-247,82/08/09,8208110085
- 8208170274 Bolicits support for ancl Croton-Harmon Board of Ed 820704 resolution demanding NRC institute 120-day clock to develop acceptable evacuation plan GERADI.K A Affiliation Unknown 82/08/10 PARIS.O H Atomic Bafaty and Licensing Board Panel 2pp. 14369 226 24X Fiche 50-247,82/08/10,8208170274
- 8208160440 Supports UCS/NY PIRO motion for order to show cause requesting shutdown Cancellation of testimony & tardiness of objections to 820423 order unsupported FLEISHER, Z B West Branch Conservation Association 82/08/11, PALLADINO, N Commissioners, ip 14348 255 24X Piche 50-247, 82/08/11,8208160440
- 8208170120 Forwards Town of Cortlandt 820810 Resolutions 250-62 & 251-62 committing to cooperate in formulating evacuation plans from utils BOYLE.H L Cortlandt Town of NY. 82/08/12 Docketing & Services Branch 3pp 14365 206 24% Fishe 50-247,82/08/12. 8208170120
- B20B170284 Opposes congressional investigation re-conduct of ongoing adjudicatory proceeding Investigation could irreparably impair legal validity of subsequent agency decisions Memodetailing concerns encl
 DUFFY, J. F. Power Authority of the State of New York 82/08/13
 DTTINGER, R. L. House of Rep., Energy & Commerce 7pp 14369 195, 24X Fiche 50-247, 82/08/13, 8208170284
- 8208170285 Response supporting ASLB 820807 memorandum & order on two questions to Commission re probabilities & Consequences Certificate of Svc encl RANDENBURG.B Consolidated Edison Co of New York HORGAN, C. Power Authority of the State of New York MORGAN, C Morgan Associates 82/08/13 Commissioners, 12pp 14367, 183 24X Fiche: 50-247, 82/08/13, 8208170285.
- 8208190119 Lists corrections to licensee 820813 response to ABLB B20809 memorandum & cartification COLARULLI,PF Consolidated COLARULLI,PF Consolidated Edison Co of New York COLARULLI,PF Power Authority of the Btate of New York 82/08/17. 87UCKY,B W Docketing & Services Branch 1p. 14381 294 24X Fiche 50-247.82/08/17.8208190119
- --8208190123 Corrected copy of response to ABLB 820809 memorandum & certification Commission should reaffirm 820727 decision w/o further appinion.

 BRANDENBURO, B Consolidated Edison Co of New York MOROAN, C, Power Authority of the State of New York MOROAN, C. Horgan Associates. 82/08/17 8908190119.
- 8208200120 Forwards documents in response to Interrogatory 7 filed on 820719 W/o encl MODRE, J. E. Hearing Branch 1 92/08/19, WEISS, E. R. Harmon & Weiss, WEISS, E. R. Union of Concerned Scientists WEISS, E. R. Public Interest Research Group, New York 1p. 14300 086. 24x Fichet 50-247, 82/08/19, 8208200120
- 8208240367 Submits informal Commission response to ASLB 8208079 memorandum & certification of questions re intent to issue 820727 memorandum & order, CLI-82-15 Formal response expected during who of 820830 CHILK, 8 J Office of the Secretary of the Commission 82/08/23 CARTER, L J. SHON, F J. PARIS, 0 H. Atomic Sefety and Licensing Board Panel 3pp. 14520-168 24X Fichs. 50-247, 82/08/23, 8208240367

R General correspondence

- B208020270 Ack receipt of NRC ltr in response to Westchester County, NY request for 120-day regulatory clock against Pacilities County appreciates NRC efforts to meet concerns by requesting interim findings from FEMA DELBELLO.A B Hestchester County.NY 82/07/13 PALLADINO, N Commissioners ip. 14151 301 24X Fiche 50-003, 82/07/13, 8208020290
- 8208180044 Informs of concerns & objections to proposed NRC plans for evacuation of residents from areas surrounding facilities in event of accident ELBON.0 Gray Panthers 82/07/22 Commissioners 2pp 14376 300 24X Fiche 50-247.82/07/22.8208180044
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Byc list enci
 DIRCKS, M J Diffice of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 OOJ
 24X Fiche 50-000, 82/07/02, 8207080064
- B20B200291 Forwards advance notification of shipment of nuclear waste from facilities to Barnwell, SC O'TOOLE, J D Consolidated Edison Co of New York B2/07/14 HAYNES, R C Region 1, Office of Director 3pp 14398-323 24X Fich
- 8208030263 Notifies of changes in mgt organization structure to be Incorporated in proposed Tech Specs HILVERDING, OM Power Authority of the State of New York 82/07/21 VAROA, S. A. Operating Reactors Branch 1 VASSALLO, 8 A. Operating Reactors Branch 2 2pp i4158 142 24X Fiche 50-000, 82/07/21, 8208030263
- 8208040518 Notification of 820728 meeting w/util in Bethesda. MD to discuss scheduling of open items
 THOMA. J O Deprating Reactors Branch i 82/07/21 VAROA. S A Openating Reactors Branch i 2pp 14220 340 24X
 Fiche. 50-286, 82/07/21, 8208040518
- 208110050 Requests info re NY City water supply sys to aid R Codell testimony for hearing on risk re water contamination by ralease of radioactivity in event of severe accident, per 820707 discussion HAMAUER, S.H. Division of Safety Technology 82/07/22 CONHAY, J. New York, State of 4pp 14330 218, 24X Fiche 50-003,82/07/22, 8208110050
- 8208020426 Notification of 820727 meeting w/Bandia Natl Lab & Pickard Lowe & Carrick in Albuquerque. NM to obtain info re open technical issues raised during meeting in June 1982 HANNON: J Operating Reactors Branch 1 82/07/26 VAROA, 6 A Operating Reactors Branch 1 2pp 14181 023 24X Fiche: 50-247, 82/07/26, 8208020426
- 3208050449 Advises that addl info in response to TMI Action Plan Item II K 3 17 re outages of ECCS will be provided by end of Oct 1982, per 820625 request BAYNELJ P. Power Authority of the State of New York 82/08/02 VAROALS A Operating Reactors Branch 1 ip 14216.347 24X Fiche 50-286,82/08/02,8208050449
- 1208100300 Forwards add1 info re masonry well design, in response to NRC 820428 ltr W/32 oversize drawings Aperture cards are available in PDR BAYNE, J.P Fower Authority of the State of New York, 82/08/05 VARCA: 8 A Operating Reactors Branch I 37pp 14274 146, 24X Fiche. 50-286, 82/08/05, 8208100300
- 208070174 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submitted of documents to NRC Summarizes IOGFR Chapter I requirements & provides alternatives to requirements. By a list entl EISENNUT. D. 9 Division of Licensing 82/08/07, Consolidated Edison Co. of New York. ip. 14356-332 24X Fiche-50-000,82/08/07,8208070174
- 3208200119 Responds to NRC 820530 ltr re NUREG-0737, Item II. B 3, "Post-Accident Sampling Sys." Util will provide requested criteria in two parts within 60 days & 180 days BAYNE. J.F Power Authority of the State of New York. 82/08/13 VARGALB A Operating Reactors Branch 1 2pp 14393; 243, 24X Fiche: 50-286, 82/08/13, 8208200119

- 8208260270 Forwards description of conceptual design of auxiliary feedwater sys mods to resolve concerns re environ qualification of safety-related equipment within pump room & simultaneous blowdown of two steam generators BAYNE, J.P. Power Authority of the State of New York 82/08/23 VARGA, S.A. Operating Reactors Branch 1 6pp 14554 275 24X Fiche 50-286, 82/08/23, 8208260270
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fichs 50-000
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure," Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fichs 50-000,82/07/20,8204210394
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list entl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Cnsolidated Edison Co of New York 7ipp 14357 27 24X Fiche 50-000, 82/07/20, 8204210397
- 8204210398 IE info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valva Failures." Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208050295 Forwards IE Emergency Proparedness Appraisal Rept 50-286/82-02 on 820208-11 No noncompliance noted SMITH, O H Division of Emergency Preparedness & Operational Support 82/07/22 BRONS, J C Power Authority of the State of New York 2pp 14210 188 24X Fiche 50-286,82/07/22,8208050298
- ~~8208050306 IE Emergency Preparedness Appraisal Rept 50-286/82-02 on 820208-fi No noncompliance noted Major areas inspected followup of emergency preparedness items from prior appraisal on 8105fi-20
 TERC.N M. CROCKER.H W. Division of Emergency Preparedness & Operational Support 82/07/22, 13pp 14210-190 24X Fiche 50-286, 82/07/22.8208050295
- 8204210401 IE Info Notice 82-28, "Hydragen Explosion While Grinding in Vicinity of Drained & Open RCS," Svc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 62/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Fiche, 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Fin Failures at Westinghouse PWRs " Svc list encl. JORDAN.E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants" Svc list encl JORDAN.E.L. Division of Engineering & Guality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Syc list encl JORDAN E L Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8208160009 Forwards IE Insp Rept 50-286/82-10 on 820616-0715 No noncompliance noted STAROBTECKI.R Division of Project & Resident Programs 82/07/30 BRDNS.J.C Power Authority of the State of New York 2pp . 14344-319 24X Fiche 50-286/82/07/30,8208160009
- --8208160010 IE Insp Rept 50-286/82-10 on 820616-0715 No noncompliance noted Major areas inspected shift logs & records, action on previous findings, audits, loss of offsits power & followp on IE bulletins, FOLEY, T. KENNY, T. J. KISTER, H. Division of Project & Resident Programs 82/07/29 10pp. 14344-321 24X Fiche 50-286, 82/07/30, 8208160009.

- 820B130234 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PNR Plants " Approx 70 manhours expended in bulletin preparation BRONS, J C Power Authority of the State of New York 82/08/03 HAYNES, R C Region 1, Office of Director 2pp 14333-144 24X Fiche 50-284, 82/08/03, 8208130234
- 8204210407 IE Info Notice 82-27, "Fuel Rad Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05 Consultdated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8208180091 Ack receipt of 820723 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/82-08 STARGSTECKI:R Division of Project & Resident Programs 82/08/12 BRDNS.J C Power Authority of the State of New York ip 14378 186 24% Fichs.50-286.82/08/12,8208180091
- --8208180098 Responds to NRC 820629 ltr re violations noted in IE Insp Rept 50-286/82-08 Corrective actions instructed personnel in proper method of baling machine operation & developed more appropriate procedure for baling operations BRONS.J C Power Authority of the State of New York, 82/07/23 STAROSTECKI, R Division of Project & Resident Programs 2pp 14378 187 24X Fiche 50-286, 82/08/12.8208180091

R Periodic operating reports & related correspondence

- 820B110049 "Core Melt Matls Interactions Evaluations," annual progress rept for Apr 1980-Mar 1981 BMAN8DN.D 0 . CATTON.I Applied Ecience Associates, Inc NRC-03-80-104 ABAI-81-001 Bi/03/31 Division of Systems Integration (post 811005) 21pp 14330-001 24X Fiche 50-247,81/03/31,8208110049
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON-J M Division of Rules and Records 82/07/13 UDELL.R.A Critical Mass Energy Project 8pp. 14679-208. 24X Fiche 50-000,82/07/13,8208270010
- --8208270098 "Annual Hhois Body Dose At Licensed Nuclear Power Facilities for CY61" # NRC - No Detailed Affiliation Given 82/07/13, 48pp 14479:216 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270632 Forwards "Personnel Whole Body Exposures For CY81," per 10CFR20 407
 8R0NGJ C Power Authority of the State of New York. 82/02/26
 Diffice of Management and Program Analysis. 1p 14679 345 24X
 Fiche 50-000, 82/07/13, 8208270010
- --8208270640 "Personnel Whole Body Exposures for CY81 "

 # Power Authority of the State of New York 82/02/26 1p.
 14679 347. 24X Fiche 50-000,82/07/13.8208270010
- 8208120215 Forwards monthly operating rept for June 1982 BRDNS,J C Power Authority of the State of New York. 62/08/06 Office of Management and Program Analysis. ip 14326 164 24X Fiche 30-286, 82/08/06, 8208120215
- --8208120217 Monthly operating rept for June 1982 AUTERING.L. Fower Authority of the State of New York 82/07/01 4pp 14324 165 24X Fiche 50-284, 82/08/04, 8208120215.

8 Reportable occurrences. LERs & related correspondence

- 8208020381 Forwards LER 82-004/01T-0. 9RONS.J.C Power Authority of the State of New York. 82/07/26 HAYNES.R C. Region I. Office of Director. 1p. 14148.224. 24X Fichs 30-286.82/07/26.8208020381
- --8208020385 LER 82-004/01T-0 on 820713, setpoints for Crosby Model HB pressurizer tafety relief valves PCV-466 & PCV-468 discovered below Tech Spec limit during cold testing. Caused by mechanical valve drift Valves reset QUMBLE, FW Power Authority of the State of New York, 82/07/26 Region 1, 04fice of Director, 2pp. 14148-225 24X Fiche: 50-286, 82/07/26, 8208020381

T. Hearing transcripts on non-antitrust matters

8208040397 Transcript of Commission 820722 public meeting/affirmation session in Washington.DC re SECY-82-270A on alternative Commission of decision in Indian Point special proceeding tommissioners, 82/07/22 10pp. 14223 170, 24X Fiche 50-247,82/07/22,8208040357.

U Congressional/Executive Correspondence

- 8208100350 Responds to 820608 ltr to Chairman Palladino requesting that facilities be shut down pending NRC review of results of hearings Protective measures imposed by NRC cited Results of current hearings to be reported to Commissioners Sept 1982 DIRCKG.W. J Office of the Executive Director for Operations 82/07/09 01LMAN.B A House of Rep. 5pp. 14308 347 24X Fiche 30-247, 82/07/09, 8208100350
- --820&0&0022 Urges shutdown of facilities until adequate emergency plan can be formulated & ASLB findings studied Constituent concern re plant safety & inadequate evacuation plan cited. QI_MAN,B A House of Rep B2/06/0B PALLADINO,N Commissioners 4pp. 14308 351. 24X Fiche. 50-247.82/07/09.8208100350

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

- 8208040450 Forwards request for add1 info re standby shutdown facility to determine acceptability & resolve NRC concerns regarding fire protection & turbine bldg flooding STOLZ, JF Operating Reactors Branch 4 82/07/17 PARKER, W D. Dute Power Co 9pp. 14220 253 24X Fiche 50-269, 82/07/17, 8208040450
- 8208110182 Informs of planned installation of fire hose cabinets at entrances to cable rooms & of planned utilization of existing turbine blig hose stations for protection of equipment rooms Mod affects 771122 commitment.

 TUCKER, H B. Duke Fouer Co 82/08/03. DENTON, H R Office of Nuctear Reactor Regulation, Director. 2pp 14313-360 24X Fiche: 50-269, 82/08/03, 8208110182
- 820B190405 Releases public version of revised emergency plan implementing procedures FELTON.J N Division of Rules and Records B2/0B/10 Document Management Branch. 1p. 14504-164 24X Fiche 50-269.62/0B/10, 820B190405
- --B20B190412 Forwards public version of ravised emergency plan implementing procedures, including Station Directive 2 92 resemergency response organization & Procedure CP/O/A/2005/20 resposs-accident datermination of gamma isotopic activity. TUCKER.H B Duke Power Co. 82/08/03. DENTON:H R. Office of Nuclear Reactor Regulation, Director STOLZ.J.F. Operating Reactors Branch 4. 2pp. 14504 187 24% Fichs. 50-269, 82/08/10, 82/08/10488
- --820B190422 Public version of revised emergency plan implementing procedures, including Station Directive 2 92 re emergency response organization & Procedure CP/D/A/2003/20 re post-accident determination of gamma isotopic activity, OMEN, T B. Duke Power Co 82/07/23 94pp, 14504.189 24X Fiche.50-269,82/08/10,820B190405
- 8208260418 Relwases public version of revised crisis mgt plan. FELTON.J. M. Division of Rules and Records 82/08/11 Document Management Branch, 1p. 14572 078. 24X Fichw:50-000.82/08/11, 8208260418.
- --8208260430 Forwards public version of Revision 5 to crisis mgt plan Revision involves reorganization of crisis mgt tsam & updates of Sections D.K. & M. PARKER, W.O. Duke Power Co. 82/07/19 DENTON, H.R. Oppice of Nuclear Reactor Regulation, Director. 1p 14572:099, 24X Fiche. 50-000, 82/08/11, 8208260418.
- --B208260437 Public version of Revision 5 to crisis agt plan. TUCKER.H B. Duke Power Co. 82/07/09, 134pp. 14572,100, 24X Fiche 50-000,62/08/11.8208260418.
- 8208260527 Releases public version of amergency plan implementing procedures.
 FELTON.J.M. Division of Rules and Records. 82/08/13 Document Management Branch. 1p. 14567:001. 24X Fiche 50-267.82/08/13. 8208260529.
- --8208260537 Forwards public version of Emergency Plan Implementing Procedures AP/O/A/1000/10 rs emergency evacuation & HP/O/B/1009/15 re sampling & quantifying high level gaseous radiodatine & particulate radioactivity.

 TUCKER, H. B. Duke Power Co. 82/08/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4 1p. 14567-003. 24X Fiche 50-267, 82/08/13, 8208260529.

- --8208260942 Public version of Emergency Plan Implementing Procedures AP/0/A/1000/10 re emergency evacuation & HP/0/B/1009/15 re sampling & quantifying high level gaseous radioiodine & particulate radioactivity
 TUCKER.H B. Duke Power Co 82/07/30 44pp 14567 004 24X
 Fiche 50-269,82/08/13,8208260529
- I Financial information
- 8208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981 TUCKER.H 8 Duke Power Co 82/08/24 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 14599 227 24X Fiche 50-000.82/08/24.8208300328
- --B20B300335 Annual Financial Rept 1981 HORN, C Duke Power Co 82/02/15 48pp 14599 006 24X Fiche 50-000, 82/08/24, 820B300328
- 9208300342 Forwards Annual Financial Rept 1981 TUCKER,H B Duke Power Co 82/08/24 DENION.H R Office of Nuclear Reactor Regulation, Director 870L7_JF Operating Reactors Branch 4. 1p 14599 110 24X Fiche 50-269, 82/08/24, 8208300342
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR 8vc list encl
 DIRCKS, M J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000, 82/07/02, 8207080064
- 8208040546 Notification of 820818-19 meetings w/util & consultants in Seneca,8C to discuss radiological effluent Tech Beecs MAGNER,P C Operating Reactors Branch 4 82/07/27 STOLZ.J F Operating Reactors Branch 4 2pp 14220 357 24X Fiche:50-269,82/07/27,8208040544
 - '08030223 Submits changes to completion dates for NUREO-0737, tems II B 3, "Post-Accident Sampling." & II F 1, "Noble is Monitors." per B20416 status rept RKER, H D Duke Power Co 82/07/28 DENTON, H R Office of clear Reactor Regulation, Director STOLZ, J F Operating Reactors anch 4 2pp 14159 325, 24X Fiche 50-249,82/07/28,8208030223
 - 230541 Application for amend to Licenses DPR-38.DPR-47 & DPR-55, vising Teth Specs 6 O through 6 3 re util reorganization, perintendent of operations qualification requirements & ganization chart Class I & II amend fees encl RKKR.W D Duke Power Co 82/07/30 DENTON.H R Office of utlear Reactor Regulation, Director STOLZ.JF Operating Reactors and 4 3pp 14162 353 24X Fiche 50-000.82/07/30.8208030541
 - B20B030551 Forwards Class [& II amend fees to cover revisions to Tech Bpecs 6 2 re offsite & station organization & 6 0 through 6 3 re reorganization PARKER, W D Duke Power Co B2/07/30 MILLER, W E Office of the Controller 1p. 14162 356 24X Fiche 50-000.82/07/30.8208030341
 - 1208030560 Proposed Tech Specs 6 0-6 3 re administrative controls, review & audit Organization chart encl * Duke Power Co. 82/07/30 13pp 14162 357 24X Fiche 30-000,82/07/30,8208030541
 - B060163 Forwards BAM-1732, "Evaluation.Repair & Replacement of amaged Internal Auxiliary Feedwater Header at Davis Resse. October 3 & Rancho Seco." per 820624 meeting w/NRC in athesda. HD & NRC 820623 request Response summary submitted ALBRIDGE.W C. Bacramento Municipal Utility District 82/08/03 TOLZ.J F. Operating Reactors Branch 4 8pp 14238 089 24% iche 50-000.82/08/03,8208060163
 - 20806016B "Evaluation,Repair & Replacement of Damaged Internal Auxiliary Feedwater Header at Davis Basse 1.0conee 3 & Rancho Seco " BAW-1732 82/07/01, 32pp 14238 097 24X Fiche 50-000.82/08/03.8208060163.
 - 3100193 Responds to NRC B2070B request for schedule for responding > NUREO-0737, Item II.B 3. "Post-Accident Sampling Sys " 160 will be submitted by 821101 ICKER.H B. Duke Power Co B2/08/05 DENTON,H R Office of Iclear Reactor Regulation, Director STOLZ,JF Operating Reactor: sanch 4 ip 14298 197. 24X Fichs 50-269, 82/08/05, 8208100193

- 8208120028 Provides addl info re availability of steam generator cooling water in event of tornadd strike, per NRC 820408 safety evaluation Configuration, as modified by standby shutdown facility, acceptable TUCKER. H B Duke Power Ca 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director BTOLZ, J F Operating Reactor Branch 4 2pp 14324 058 24% Fichs 50-269.82/08/06.8208120028
- 8208120216 Advises that responses to questions re adequacy of station electric distribution sys voltages will be submitted no later than 82:005, per 820608 request Delay caused by required addI research & manpower limitations TUCKER. H B Duke Power Co 82/08/06 DENTON. H R Office of Nuclear Reactor Regulation, Director STUZ. J F Operating Reactors Branch 4 1p 14326 171 24X Fichs 50-269, 82/08/06.8208120216
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208070174
- 8208240234 Application for amend to License DFR-47, changing Tech Specs re reload design calculations for Cycle 7 TUCKER.H B Duke Power Co 82/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 14521 268 24X Fichs 50-287,82/08/11,8208240234
- --B208240237 Proposed Tech Spec revisions re reload design calculations for Cycle 7 s Duke Power Co 62/06/11 25pp 14521 271 24X Fiche 30-287,62/08/11,6208240234
- --8208240239 "Oconee Unit 3.Cycle 7 Relaad Rept." Revision 1 * Duke Power Co DFC-RD-2001 R01 82/07/31 59pp 14521 296 24% Fiche 50-287.82/08/11.8208240234
- 820B170151 Responds to NRC 820709 ltr reviewing shift technical advisor training programs required by Item I A 1 i of NUREQ-7370 & NUREQ-0660 Disagrees unlaw NRC expectation that all new hires have bachelors degree or equivalent TUCKER, H B Duke Power Co 82/09/12 DENTON, H R Office of Nuclear Reactor, Regulation, Director STOLZ, J F Operating Reactor, Branch 4 2pp 14364 218 24X Fiche 50-269,82/08/12.8208170151
- 8208200025 Advises that util response to NRC 820713 ltr re schedule for submitting supplemental ECCS calculations utilizing cladding models of NURE0-0430 will be submitted by 830301
 TUCKER.H B Duke Power Co 82/08/12 DENTON.H R Office of Nuclear Reactor Regulation. Director STULX.JF Operating Reactors Branch 4 1p 14392 246 24X Fiche 50-269.82/08/12.8208200029.
- 8208240242 Disagrees w/NRC expectations that all new hires have backslors degree or equivalent pending new guidance per 820707 ltr & NUREO-0737. Item I A 1., "Shift Technical Advisor" & NUREO-0660
 TUCKER: H B Duke Power Co 82/08/12 DENTON, H R Office of Nuclear Reactar Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 14520 070 24X Fiche 50-247.82/08/12.8208240242
- 8208240440 Forwards internal pin pressure calculation results for Ocones 3 Cycle 7.psr 820812 telcom re Cycle 7 reload rept & Tech Spec changes submitted 820503.revised 820811 Info re peak burnup also provided TUCKER.H.B Duke Power Co 82/08/16 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactors Branch 4 2pp 14526 359 24X Fiche 50-287.82/08/16.8208240440.
- 8208310236 Forwards summary of licensee efforts to resolve NUREC-0737, Item II K 3 30 re revised small break LOCA methods Util will support 8%N owners group effort to provide integral sys test data-utilizing GERDA test facility TUCKER.H B Duke Power Co 82/08/25 DENTON.H R, Office of Nuclear Reactor Regulation, Director 670L7,J, F Operating Reactors Branch 4 11pp, 14695 076 24% Fiche 50-269,82/08/25,8208310236
- G Inspection reports, IE Bulletins & correspondence
- 8208030599 Forwards IE Insp Repts 50-269/82-21,50-270/62-21 & 50-287/82-21 on 820614-18 No noncompliance noted. LEMIS,R C Division of Project & Resident Programs 82/07/09 PARKER,W D. Duke Power Co 2pp 14162 313 24X Fiche 50-269,82/07/09,8208030599
- ---8208030613 IE Insp Repts 50-269/82-21.50-270/82-21 & 50-287/82-21 on 820614-18 No noncompliance noted Major areas inspected review of chemistry & radiochemistry procedures & airborne efficient sampling & accountability EVANS.C D. MONTOURERY.D M Division of Emergency Preparedness & Operational Support 82/07/07 10pp 14162 315 24X Fichs 50-269,82/07/09,8208030579.

- 0030548 Forwards IE Insp Repts 50-269/82-26, 50-270/82-26 & 50-287/82-26 on 820706-09 No nancompliance noted pance: A C Division of Project & Resident Programs 82/07/14 pance: Duke Power Co 2pp 14162 096 24x pichs 50-269, 82/07/14, 8208030548
- 208030557 IE Insp Repts 50-269/82-26,50-270/82-26 & 50-287/82-26 on 820706-09 No noncompliance noted Major areas inspected followup of extraction steam line rupture GRDERS, W. PUCKETT, M. KLEINSORGE, W. Division of Project & Resident Programs 82/07/14 5pp 14162.098 24X Fiche 50-269,82/07/14,8208030548
- 04210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leatage." Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000
- 04210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of placement of Personnel Monitoring Devices for External Radiation " Bvc list one! "ORDAN,E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 30-000, 82/07/19, g204210395
- B204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon gradual Loss of Air Pressure " Svc list enci. UDRPAN.E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001. 24% Fiche 50-000. 82/07/20.8204210376
- P204210397 IE Info Notice 82-24, "Water Leaking From V Hexafluoride Overpacks " Svc list encl COBB:L I. Division of Fuol Facilities, Materials & Safeguards P2/07/20, Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- ⊕204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance. 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Piche 50-000.82/07/22,8204210398
- © 208160163 Forwards IE Insp Repts 50-269/82-24.50-270/82-24 & 50-287/82-21 on 820614-25 No noncompliance noted DAYCE: H C Division of Project & Resident Programs. 62/07/22. PARKER: H O Duke Power Co 2pp 14345 069 24X Fiche 50-269. 82/07/22, 8208160163
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained % Open RCS" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Compolidated Edison Co. of New York 122pp 14380 115 24% Fiche 50-000, 82/07/23, 8204210401
- B204210402 IE Info Notice 82-27, "Control Rod Drive (CRD) Ouide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche: 50-000, 82/07/23, 8204210402
- S204210403 IE Info Notice 82-30. "Loss of Thermal Bleeves in RCB Piping et Certain Westinghouse PWR Power Plants " Svc list encl VORDAN, E L Division of Engineering & Quality Assurance B2/07/26 Gonselidated Edison Co of New York 121pp 14357 013, 24X Fiche 50-000, B2/07/26, B204210403
- □⊇08160194 Forwards IE Inap Repts 50-269/82-27, 50-270/82-27 & 50-287/82-27 on H20610-0715 No noncompliance noted.

 □ANCE, H. C. Division of Project & Resident Programs 82/07/26 PARKER, W O Duke Power Co 2pp 14344 127 24X Fiche: 50-269, 82/07/26, 8208160194
- **S208160202 LE Insp Repts 50-269/82-27.50-270/82-27 & 50-287/82-27 en 820610-0715. No noncompliance noted Major areas inspected operations safety verification surveillance testing, station maint activities & plant trips ORDERE, W. FALCONER, D., BRYANT, J. Division of Project & Resident Programs 82/07/26 | 11pp | 14344, 131 | 24X Fichs, 50-269, 82/07/26, 8208160194

- 8208030895 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/82-17. 50-270/82-17 & 50-267/82-17 LEWIS, R C Division of Project & Resident Programs 82/07/27 PARKEN, W O Dute Power Co ip 14162 232 24X Fiche 30-269, 82/07/27, 8208030395
- --9208030607 Responds to NRC 820616 ltr re violations noted in lE Insp
 Repts 50-269/82-17,50-270/82-17 to 50-287/82-17 Corrective
 actions stronger door closure devices will be installed by
 820915 to preventive maint program will be re-evaluated.
 PARKER: NO Dute Power Co 82/07/16 O'REILLY, J P Region 2,
 Office of Director 2pp 14162 233 24X Fiche: 50-249,82/07/27,
 8208030395
- --8208030618 Forwards IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17 on 820510-14 & notice of violation DANCE:HC Division of Project & Resident Programs 62/06/16 PARKER:W D Dute Power Co 2pp 14162 235 24X Fiche 50-269, 82/07/27, 8208030395
- --8208030625 Notice of violation from insp on 820510-14 * Division of Project & Resident Programs 82/06/16 ip 14162 237 24X Fiche 50-269, 82/07/27, 8208030595
- ---8208030636 IE Insp Repts 30-267/82-17.50-270/82-17 & 50-287/82-17 un 820810-14 Noncompliance neted door providing access to radwaste compacting area found unlocked & positive access control not in effect CULLINS.T R . BARR.K P Division of Engineering & Technical Programs 82/06/10. Spp 14162 238 24X Fiche 50-269.82/07/27, 8208030595
- 6208160364 Forwards IE Insp Repts 50-269/82-29.50-270/62-29 & 50-287/82-29 on 820712-16 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/07/27 PARKER, W O Dute Power Co 2pp 14349-041. 24x Ficho 50-269.82/07/27,8208160364
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN E L Division of Engineering & Guality Assurance. 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- B2OBi60291 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PMR Plants " Improved design gesket is onsite & ready for use to repair reactor coolant pump PARKER, M. D. Duke Power Co. B2/07/29 D'REILLY, J. P. Region 2, Office of Director Jpp 14346-265 24X Fiche. 50-269, 82/07/29,
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Daffle Water-Jet Impingement " Svc list encl. JORDAN,E L Division of Engineering & Quality Assurance, 82/08/05, Consolidated Edition Co. of New York 117pp. 14388:201 24X Fiche: 50-000, 82/08/05, 8204210407
- R. Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records. 82/07/13. UDELL, R A Critical Mass Energy Project 8pp 14679; 208 24X Ficher 30-000, 82/07/13, 8208270010
- --B20827009B "Annual Whole Body Dose At Licansed Nuclear Power Facilities for CyBI " * NRC - No Detailed Affiliation Given. 82/07/13 48pp 14679.216 24% Fiche 50-000.82/07/13.8208270010
- --8208270603 Forwards "Statistical Rept of Recorded Personnel Whole Bod Exposures for CYBI," per 10CFR20 407 PARKER,W O. Dute Power Co 82/02/25 Office of Management and Progrem Analysis 1p 14479 340 24X Fiche 50-000,82/07/13, 8208270010
- --9208270612 "Statistical Rept of Recorded Personnel Whole Body Exposur for CYSI "
 LENIS,L Duke Power Co. 82/02/25. ip 14679.341 24X
 Fiche 50-000,82/07/13,8208270010,

- 8208170087 Forwards monthly operating repts for Jul 1982 TUCKER.H B Duke Power Co 82/08/13 Director's Office, Office of Inspection and Enforcement ip 14358 149 24X Fiche 50-269, 82/08/13, 8208170087
- --8208170091 Monthly operating repts for Jul 1982 REAVIS.J A Duke Power Co 82/08/13 16pp 14358 150 24x Fiche 50-249,82/08/13,8208170087
- 8 Reportable occurrences. LERs & related correspondence
- 8208310076 Forwards LER 81-005/03L-0 Detailed event analysis enci PARKER: H 0 Duke Power Co 81/04/22 O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) 3pp 14697 246 24) Fiche 50-287,81/04/22,8208310076
- --9208310079 LER 81-005/03L-0 on 810323, engineering safeguard valve 3C8-5 failed to operate Causad by operator failure since valve could be operated manually Valve operator will be inspected during next outage JONES, J. L. Dute Power Co. 81/04/22 Region 2, Atlanta, Office of the Director (81/03/01) ip (4697-247 24X Fiche 50-287,81/04/22,8208310076
- 8208030297 Forwards LER 82-007/01T-0 Detailed event analysis encl PARKER, W O Duke Power Co 82/07/23 O'REILLY, J P Region 2, Office of Director 3pp 14156 239 24X Fiche 50-287, 82/07/23, 82/8010297
- --B20B030303 LER 82-007/01T-0 on B20S21.furing video insp of fuel assembles broken holddown springs found on fuel assembles NAODMH & NAODMH Caused by fatigue induced cracking at existing surface flaw Springs will be replaced. KUTZER, J F Duke Power Co 82/07/23 Region 2, Office of Director ip 14156 242 24% Fiche 50-287, B2/07/23. B208030297
- CHET 50-288 REED COLLEGE RESEARCH REACTOR

 Inspection reports, IE Bulletins & correspondence
- 204210395 IE Info Notice 81-26. Part 3. Suppl 1. "Clarification of Flacement of Personnel Monitoring Devices for External Radiation " Bwc list encl JORDAN.E L. Division of Engineering & Guality Assurance 62/07/19 Hishigan
- OCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

 Becurity, medical, emergency & fire protection plane
- OB190124 Forwards objectives & progosed table of events for 1982 annual amergency plan exercise scheduled for 820811 Utj supports PA Emergency Mgt Agency concept of limited risk county participation Beanario to be submitted by 820706 HUKILL-H D Caneral Public Utilities GPU Service Corp 82/06/23, ORIMES 8 D Division of Emergency Preparadness, 5pp 14381-138 24X Fiche 50-289, 82/06/23, 8208190124
- OB190186 Forwards objectives for annual exercise to be held 820811, per Enci I to FEMA Radiological Emergency Plan Quidance Yemorandom 17, HUKILL, H D General Public Utilities QPU Service Corp. 82/07/02 4AVNES, R C. Region 1, Office of Director. 91pp 14386 089, 24X 7(che: 50-289, 82/07/02, 8208190186
-)8040265 Releases public version of revised smargency plan mplementing procedures, ELTON.J.M. Division of Rules and Records 82/07/20 Document lanagement Branch 19. 14230 220 24X Fiche: 50-289, 82/07/20, 1208040265
- 208040274 Forwards public version of revised amergancy plan implementing procedures; including Procedures 1004 1 re unusual event; 1004, 2 re alert & 1004 3 re site emergency. Receipt form encl.

 VASIA, 8. General Public Utilities OPU Bervice Corp. 82/07/0; MENTON, H. R. Office of Nuclear Reactor Regulation, Director. 14230-221. 24X Fiche: 50-289, 82/07/20, 8208040265.

- --B208040278 Public version of revised emergency plan implementing procedures, including Procedures 1004 1 re unusual event, 1004 2 re alert & 1004 3 re site emergency NRLSUN, H A. TOULE, R J. Ceneral Public Utilities GPU Service Corp. 82/07/02 150pp 14230 222 24X Fiche 50-289,82/07/20, 2308040245
- 8208270247 Forwards Revision 3 to guard training & qualification plan Revision withheld (ref 10CFR73 71) HUK[(L:H D General Public Utilities - QPU Service Corp 82/07/23 STOLZ, J F Operating Reactors Dranch 4 1p 14563 091 24X Fiche 50-289, 82/07/23, 8208270247
- 8208050121 Releases public version of temporary change notice to emergency procedure FELTON.J M Division of Rules and Records 82/08/02 Document Management Branch ip 14243 007 24% Fiche 50-289.82/08/02, 8208050121
- --8208050125 Forwards public version of Temporary Change Notice 1-82-0107 to Revision 4 of Emergency Procedure 1004 6, "Addl Assistance & Notification" Receipt form encl NASH, B. Ceneral Public Utilities - OPU Bervice Corp. 82/07/23 DENTON.H R. Office of Nuclear Reactor Regulation, Director. Ip 14243 008 24% Fiche 50-289, 82/08/02, 8208050121
- --B208050130 Public version of Temporary Change Notice 1-82-0107 to Revision 4 of Emergency Procedure 1004 6, "Addi Assistance & Notification" NELSON.H A , TOOLE.R J General Public Utxlities -- OPU Bervice Corp 82/07/16 2pp 14243 009 24X Fiche 50-287,82/08/02, B208050121
- 8208270262 Forwards Revision 4 to guard training & qualification plan Revision withheld (ref 10CFR73 71) HUKILL-H D General Public Utilities - OPU Service Corp 62/08/03 8TOLZ-J F Operating Reactors Branch 4 1p 14563 356 24X Fiche 50-287.62/08/03.8208270262
- B20B160292 Forwards annual exercise requirements exemption fee, per 10CFR170 22 HUKILL-H D General Public Utilities QPU Service Corp. 82/08/09 CHILK-S J Office of the Secretary of the Commission 2pp 14346 263 24X Fishe 50-289/82/08/09/8208160292
- 8208170354 Releases public version of revision to emergency plan procedure FELTON, J M Division of Rules and Records 82/08/10 Document Management Branch ip 14373,166 24X Fiche 80-289,82/08/10,8208/10354.
- --8208170357 Forwards gublic version of Revision 4 to Emergency Plan Procedure 1004 7. "Offsite/Onsite Dose Projections" Receipt form encl + General Public Utilities - OPU Bervice Corp 82/08/02 BENTON, H.R. Office of Nuclear Reactor Regulation, Director lp 14373 167. 24X Fiche 50-289, 82/08/10, 8208170354
- --8208170359 Public version of Revision 4 to Emergency Plan Procedure 1004 7, "Offsite/Onsite Dose Projections"
 NELSON, H. A. TODLE, R. J. General Public Utilities OPU Service Corp. 82/07/30 24pp 14373 168 24X Fiche 50-289, 82/08/10.
- 8208310177 Forwards. "TMI-1 Once-Through Steam Generator Repair Safety Analysis," supplementing 811208 & 820216 responses Affidavit requesting withholding encl Evaluation withheld (ref 10CFR2, 790) HUKILL-H D General Public Utilities GFU Service Corp 82/08/20 EISENHUT, D Q Division of Licensing App 14687 005 24% Fichs 50-289, 82/08/20,8208310177
- O Adjusticatory correspondence
- 8208160467 Ack suggestion to be eliminated from TMI restart svc list Mailings from ASLB & NRC staff sufficient LEWIS,M I Lewis, M 82/05/08 EMITH.I W. Atomic Safety and Licensing Board Panel ip 14349 282 24X Fiche 50-289,82/05/08, 8208160467.
- 8208160054 Order CLI-82-13 denying licensee 820524 request that Commission decide expeditiously whether NRC intended to prepare supplemental EIS on psychological health effects. NRC does not yet have enough info to decide CHILK, S. J. Office of the Secretary of the Commission 82/07/16. Metropolitan Edison Co. 5pp. 14344-273 24X Fiche-50-289,82/07/16,820816054

- 8208030261 Memorandum & Order ALAB-685, delineating scope of appellate review & scheduling oral argument on plant design procedures & separation for 820901 hearing in Bethesda. HD Suspends util obligation to answer ASLB 820714 Question III E SHOEMAKER.C. J. Atomic Safety and Licensing Appeal Panel. 82/08/02 7pp 14158 135 24% Fiche 30-289,82/08/02
- 8208040259 Addendum to 820727 partial initial decision, supplementing Paragraph 2411 which imposed monetary penalty of \$100.000 upon licensee for failure to safeguard integrity of examprocess & adding condition to Paragraph 2421 SMITH.I W Atomic Safety and Licensing Board Panel 82/08/03 2pp, 14183:085, 24X Fiche 50-289,82/08/03.8208040239
- 8208050058 Forwards completed procedures 8P-A 2.8P-A 4.8P-A 5.8P-A.6 & SP-A 8 as part of Region I incident response suppl W/o encl. GRAY.J R Hearing Branch 4 82/08/03 Atomic Safety and Licensing Board Panel 1p 14213 229 24X Fiche 50-289, 82/08/03, 8208050058
- 8208090238 Motion for extension of time until 820820 & 27 to file comments & reply comments re ASLB 820727 decision re restart. Delay due to conflicting commitments AAMODTA M Aamodts, The 82/08/03 Commissioners 3pp 14271
- --8208090240 Mution for extension of time until 820820 & 0920 to file exceptions & supporting brief in response to ABLB 820727 decision re restart, Delay due to conflicting commitments AAMODT: M.M. Asmodts: The 82/08/03 Atomic Safety and Licensing Appeal Panel 2pp 14271 094 24X Ficher 50-289, 82/08/03.8208090238
- 8208090258 Notifies that oral argument for UCS will be presented by ER Weiss w/technical assistance by RD Pollard WEISB.E.R Harmon & Weiss. WEISB.E.R Union of Concerned Scientists 82/08/03. SHOEMAKER.C.J Abomic Safety and Licensing Appeal Panel 1p. 14270 347 24X Fiche 50-289,82/08/03.8208090258
- 8208050387 Memorandum correcting ASLB 820727 Partial Initial Decision LBP-82-86 LBP-82-86 SMITH.I.W Atomic Safety and Licensing Board Panel 82/08/04, 2pp. 14209 176 24X Fiche. 50-289, 82/08/04, 8208050387.
- 8208090155 Notification of action re ABLB 820727 partial initial decision. Ltr-designated Individuals 0 & H accept 2-wk suspension w/o pay in lieu of proceedings to consider suspension/mod of operator licenses Certificate of Svc encl TROWBRIDGE, 0 F Metropolitan Edison Co. TROWBRIDGE, 6, F. Shaw, Pittman, Potts & Trowbridge, 82/08/06 6pp 14271, 340, 24% Fiche, 50-289, 82/08/06, 8208090155
- 920B1100B9 Memorandum & order releasing cross-examination plans of restart proceeding Documents availabile at PDR SMITH, I M Atomic Bafety and Licensing Board Panel 82/08/06. 2pp 14916:337. 24X Fiche 50-289, 82/08/06. 820B1100B9.
- 8208110091 Order granting Asmodt request for 8-day extension to file exceptions to ASLB 820728 partial initial decision Exceptions due by 820820. Time for filing brief to be calculated on basis of last-filed appellant brief SHOEMAKER.C. J. Atomic Bafety and Licensing Board Panel 82/08/06 Asmodts, The. 3pp 14316 334. 24X Fichs: 50-289.82/08/06, equalings:
- 8208110192 Comments re new info provided by licensee & NRC in response to ABLAB 820629 memorandum & order NRC & licensee integrity remains principle issue & should be considered in review of appeal. Certificate of Bvc encl
 AAMODT:N. D. Aamodts, The 82/08/06 7pp 14313;340 24X
 Fiche. 50-289, 82/08/06, 8208110192
- 8208240119 Forwards 820806 memorandum & order & cross-examination plans used during TMT-1 restart adjudicative proceeding. Requests documents he treated as single document & made available for insp in PDR.

 SMITH, I W. Atomic Safety and Licensing Board Panel. 82/08/06.
 CDLLINS:M Document Management Branch. 700pp. 14544'180. 24X
 Fiche: 50-289, 82/08/06, 8208240119
- 8208110147 Response opposing Aamodt 820803 motion for extension until 820820 to file comments on ASLS 820727 decision favoring restert Aamodt on notice throughout proceeding that Commission would decide within 35 days. W/Certificate of 8vc. TROMBRIDGE.9.F. Hetropolitan Edison Co. TROMBRIDGE.9.F. Shaw, Fittman, Fotts & Troubridge. 82/08/07. Commissioners 7pp. 14314:275 24% Fiche: 50~289,82/08/09.8208110147

- 8208110198 Response to ASLAB 820714 order directing certain questions be addressed in advance of oral argument on appeals of partial initial decision re plant design & procedures & separation is sues Affidavits & Certificate of Svc enci CUTCHIN, J H Hearing Branch 3. 82/08/09 Atomic Safety and Licensing Appeal Panel 2pp 14313 061. 24X Fiche 50-289,82/08/09,8208110198
- --B208i10200 Affidavit of RH Jacobs ra questions raised in ABLAB 820714 short-term order Items 1 & 2 JACOB8,R H. Operating Reactors Branch 4 82/08/06 App. 14313-065 24X Fiche 50-289,82/08/09,8208110198
- ~-8208110203 Affidavit of HL Jensen re status of licensee compliance w/long-term Item 2 of CLI-78-8 & ASLAB 820714 order, duestions II.D.III L.IV.A.IV.C.IV E & IV Q JENBEN, H L. Reactor Systems Branch 82/08/06 16pp 14313:069, 24X Fiche 50-289,82/08/09,8208110198
- --B20Bil0206 Affidavit of JH Conran re ABLAB B20714 order.ltem III J re status of generic reviews of sys interactions CONRAN.J H Reliability & Risk Assessment Branch B2/08/06 6pp 14313 085 24X Fiche 30-287.B2/08/07.B20Bil019B
- --8208110207 Affidavit of ZR Rosztoczy re A6LAB 820714 order. Item III 0 ROSZTOCZY. Z R Equipment Qualification Branch 82/08/05. 3pp 14313 091 24X Fiche: 50-289, 82/08/09, 8208110198.
- --8208110209 Affidavit of LE Phillips re ABLAB 820714 order. Question IV H
 PHILLIPS, L E Core Performance Branch. 82/08/06. 7pp
 14313 094 24X Fiche 50-289, 82/08/09, 8208110198
- --B208110210 Affidavit of OP Chopra re ABLAB B20714 order. Item IV B(4)
 Prof qualifications, Certificate of Byc & documents cited in
 RH Jacobs B20804 affidavit encl.
 CHOPRA: O P. Division of Bystems Integration (post B11005).
 B2/08/05. 106pp. 14313.101. 24X Fiche. 50-289.82/08/09.
 B208110198
- 820Bi30i33 Provides info re changes on mgt issues, since close of record, per Bi100i commitment RO Hurd prof qualifications & svc list encl BAUBER, D B. Bhaw. Pittman, Potts & Trowbridgs BAUBER, D B. Hetropolitan Edison Co. 82/08/10 EDLEB, O.J., BUCK, J.H., KOHL, C, N Atomic Eafety and Licensing Board Panel 7pg 1433B, 085 24X Fiche. 50-289, 82/08/10, 8208130153.
- 8208120139 Order granting MM Asmodt 820806 request for extension until 820820 to comment on ASLS 820727 decision. CHILKS J. Office of the Secretary of the Commission 82/08/11 Asmodts, The ip 14327.108 24X Ficher 50-289, 82/08/11,8208120139.
- 8208160139 Response to ABLAB 820714 order, consisting of status rept on restart mode & description of short & long-term emergency feedwater mode, per NUREO-0737, Item II, E 1, I. Affidavit & Certificate of Svc encl.

 BAXTER, T. A Metropolitan Edison Co BAXTER, T A Shaw, Pittman, Potte & Troubridge. 82/08/12, 35pp. 14344,179. 24x

 Fiche: 50-289, 82/08/12, 8208160139
- 8208150433 Order directing Commonwealth of PA & util to advise whether communications drill conducted per Partial Initial Derision LBP-81-89 & when next scheduled drill or annual exercise anticipated Response due by 820820 SHOEMAKER.C J. Atomic Bafety and Licensing Appeal Panel. 82/08/13, Fennsylvania, State of. 1p. 14349:263. 24X Fiche 50-289, 82/08/13,8208160433.
- B208240414 Notice of Anti-Nuclear Group Representing York change of address PHELPS, 0, B Anti-Nuclear Group Representing York. 62/08/17. 1p. 14522:357. 24X Fiche, 50-289, 82/08/17, 8208240414.
- 8208170153 Response to ASLAB 820813 order requesting add1 into re communications drill & annual exercise. Drill required by ASLB partial initial decision completed on 810014 Annual exercise for 1962 conducted on 820811. W/Certificate of 8vc ZAHLER, R. E. Metropolitan Edison Co. ZAHLER, R. E. 8haw, Pittman. Potts & Troubridge. 82/08/18 pp. 14381, 121. 24% Fiche. 50-289. 82/08/18, 8208190153
- B20B230059 Advises that author will represent NRC at B20901 oral argument CUTCHIN, J.M. Hearing Branch 4. B2/08/18. BHOEHAKER, C. J. Atomic Bafety and Licensing Appeal Panel. 1p. 14517-226, 24x Fiche: 50-289, 82/08/18, 8208230059.

- 8208230085 Response supporting licensee 820726 objection to answering Ovestion III E of ASLAB 820714 order Answer would provide info beyond info included in evidentiary record Rulemaking on environ qualification controls Certificate of Svc encl CUTCHIN. J M Hearing Branch 4 82/08/20, Atomic Safety and Licensing Appeal Panel 12pp 14517 128 24% Fiche 50-287, 82/08/20, 8208230085
- 8208240245 Exceptions to ASLB 820727 partial initial decision retestart
 BRADFORD,L Three Mile Island Alert 82/08/20 Atomic Safety and Licensing Board Panel 20pp 14520 072 24X Fiche 50-289,82/08/20,8208240245
- 82082402&0 Comments on immediate effectiveness of ASLB 820727 partial initial decision on cheating issues, per Commission 820310 order Decisions remove AII bases for immediately effective shutdown order Order should be lifted W/Certificate of 8vc OCLOBERO, J. R. Hearing Branch 2 82/08/20 Commissioners 20pp 14527 014 24x Fichs 50-889.82/08/20,8208240260
- 8208240272 Informs that NRC will not file any exceptions to ASLB B20727 partial initial decision. QCLDBERG,J R. Hearing Sranch 2 82/08/20 EDLES,G J. BUCK,J H. KOHL,C N. Atomic Safety and Licensing Appeal Panel ip. 14527 18: 24X Fiche 50-289.82/08/20.8208240272.
- 8208240338 Advises that licenses will remove grahibition; contained in amergency procedures, against connecting pressurizer heaters when only one diesel generator available Change has bearing on issue presently before ABLA8
 TRONBRIDGE, G. F. Shaw, Pittman, Potts & Troubridge TROMBRIDGE, G. F. Hetropolitan Edison Co. 82/08/20 EDLES, G. J., BUCK, J. H., GOTCHY, R.L... Atomic Sefety and Licensing Appeal Penel 3pp 14520 293 24% Fichs 50-289,82/08/20,8208240338
- 8208240342 Forwards comments on immediate effectiveness of ASLB B20727 partial initial decision on chesting Licenses will file no exceptions to decision W/o encl TROUBRIDGE. OF Shaw, Pittman, Potts & Trowbridge TROUBRIDGE. OF Hetropolitan Edison Co. 82/08/20 EDLES. O. J., BUCK, J. H., KOHL, C. N. Atomic Safety and Licensing Appeal Fanel. Zpp. 14520 304 24X Fiche 50-289, 82/08/20, 8208240342
- 3208240417 Comments opposing immediate effectiveness of ASLB 820727 partial initial decision on cheeting Reaffirms request for stay of 810827 partial initial decision & requests stay of 820727 decision.

 BRADFGRD, L. Three Mile Island Alert 62/08/20 2ipp 14524.001 24X Fiche 50-289,82/08/20.8208240417
- 1208240432 Comments supporting immediate effectiveness of ASLB 810817, 1214, & 820727 partial initial decisions. Immediate affectiveness of NRC 770702 & 0807 orders suspending operating authority should be 11fted W/Zertificate of Bvc. TROUBRIDGE.9 F Hetrogolitan Edison Co TROUBRIDGE.9 F. Shaw. Pittman. Potts & Troubridge 82/08/20 17pp 14526 233 24X Fiche: 50-287, 82/08/20, 82/08/40432.
- 8209240449 Comments opposing immediate effectiveness of ASLB 820727 partial initial decision on cheating Decision failed to resolve issues re ability of licensee personnel to operate plant safely. Winotice of appearance & Certificates of Evc. BLAZEY.D R. Pennsylvania, State of 24% Fiche 50-289, 82/08/20, 8208240449
- 8208240454 Comments opposing immediate effectiveness of ASLB partial initial decisions authorizing restart. No reason for Commission to act before ABLB reviews decisions, since plant not ready to restart.

 WEISB.E.R. Union of Concerned Scientists. WEISB.E.R. Harmon & Weiss 82/08/20 Spp 14526 328 24% Fiche 50-289,82/08/20,8208240454
- --B208240437 Exceptions to ASLB 820727 partial initial decision on cheating issues, Certificate of Svc encl.
 WEISS.E R. Union of Concerned Scientists WEISS.E R. Harmon & Weiss 82/08/20. Atonic Safety and Licensing Appeal Panel App 14526 331, 24X Fiche 50-287,82/08/20,8208240454
- 8208250270 Exceptions to ASLB 820727 partial initial decision on cheating Certificate of Svc encl AAMODT, M. Aamodts, The. 82/08/20. Atomic Safety and Licensing Appeal Panel 19gp. 14545-010 24X Fiche: 50-289, 82/08/20, 8208250270
- 8208250281 Comments on ASLB 820727 partial initial decision on cheating issues Cartificate of Syc encl AAMODT.M M. Aamodts. The. 82/08/20 48pp 14542*136. 24X Fithe.50-289, 82/08/20,8208230281.

- 8208270470 Response to ASLAB 820813 order is schedule of communication, drill Initial notification drill conducted on Bilol4 TMI C482 annual exercise held on B20811 Next regularly scheduled communications drill in Sept 1982 W/Certificate of Svc ADLER, R W Hetropolitan Edison Co 82/08/20 4pp 14565 323 24x Fichs 50-289.82/08/20,8208270470
- 8208250280 Advises that two separate mailings of 820820 sent stapled together WEI88, E R Harmon & Weiss 82/08/23 EDLES, O J , BUCK, J H , OUTCHY, R. L Atomic Safety and Licensing Appeal Panel 1p 14543, 063 24% Fiche 30-289, 82/08/23, 8208250280
- 8208270532 Motion for ltr-designated Individuals 0 & VV to intervene Certificate of 8vc encl VOIOT.H H Affiliation Unknown VOIOT.H H LeBoeuf, Lamb, Leiby & MacRae 82/08/23 Atomic Bafety and Licensing Appeal Panel &pp 14364
- B20B2704B7 Reply to NRC B20B09 response to ASLAB 820714 order Util disagrees w/HL Jensen summary & current status of NRC & util actions taken per NURE9-0737, Item II K 3 30 BAXTER, T A Metropolitan Edison Co BAXTER, T A Shaw, Pittman, Potts & Troubridge 82/08/25, 2pp 14565 040 24x Fiche 50-289, 82/08/25, 8208270487.
- --8208270495 Affidavit of RW Keaten rs NRC & licenses actions taken in response to NUREO-0737. Item II. K 3 30 Licenses does not agree w/NRC summary of actions Certificate of Bvc encl KEATEN, R. W. Metropolitan Edison Co. KEATEN, R W. General Public Utilities QPU Service Copp 82/08/25 16pp 14565 042 24K Fiche 50-289, 82/08/25, 8208270487
- 8208270477 Supplemental memorandum of ltr-designated Individuals 0 & VV.clarifying intended involvement on appeal if permitted to intervene Cartificate of Svc encl., VDIOT, H H Affiliation Unknown VDIOT, H H LeBosuf, Lamb, Leiby & MacRae. 82/08/26 6pp 14565 343 24X Ficha 50-289,82/08/26,8208270477
- 8208300079 Order directing parties objecting to 1tr designated Individuals 0 & VV 820823 motion to intervens to inform ASLAB of objection by 820901 BHOEMAKER, C J Atomic Sefety and Licensing Appeal Panel 82/08/27 2pp 14596

H General correspondence

- 8208040061 Responds to 820607 ltr expressing concern over TMI restart delays. Due to steam generator tube degradation plant would be unable to restant until end of yr at earliest NDVAK, T M Assistant Director for Operating Reactors 82/07/13 PETERS, E Friends & Family of TMI 2pp. 14236 306 24X Fiche, 50-289, 82/07/13, 8208040061
- --B208040067 Expresses concern over delays in restarting plant PETERS.E Friends & Femily of TMI B2/06/07 PALLADING,N J Commissioners 2pp, 14236 308 24% Fiche 50-289,82/07/13,8208040061.
- 8208100364 Informs that NRC made arrangements w/Pattee Library, PA State Univ to receive publicly available hearing transcripts for TMI-1, per 820615 request SOUDER, J. Division of Rules and Records 82/07/20 HARVEY, E State Gollege, PA. ip 14308:355 24X Fiche, 50-289, 82/07/20.
- 8208120351 Responds to 820712 ltr reiterating concerns of Kent County, MD residents re possible disposel of waste water from TMI into Susquehenna River & Chesepeake Bay Two studies underway to evaluate impacts of 27 disposition alternatives, DIRCKS.H J Office of the Executive Director for Operations 62/08/04 DY60N.R P House of Rep 3pp. 14339 286. 24X Fiche. 50-289. 82/08/04. 8208120351
- ---B20B120356 Responds to B20517 ltr re future disposition of redwastrs from TMI. Two studies underway to evaluate potential impacts of 27 possible disposition alternatives SNYDER.B J TMI Program Office 82/06/07 HORBEY.E E Maryland. State of. 10pp 14339:289 24X Fiche 50-289.82/08/04.820B120351
- --8207050016 Expresses concern re possibility that waste water from TMJ may be discharged into Susquehanna River & Chesapeake Bay.

 DYSON, R.F. House of Rep. 82/07/12 MARTIN, J.B. Division of Waste Management 2pp. 14339 299 24% Fiche. 50-287, 82/08/04.
 82/08/20351

- 8208120130 Informs that restart proceeding contains duplicate addressee Correspondence need not be sent to director. Ofc of Radiological Health CERUSKY, T.M. Pennsylvania, State of 82/08/06 Office of the Secretary of the Commission ip 14323 283 24X Fiche 50-289, 82/08/06, 8208120130
- 8208250042 Responds to concerns re steam generator corrosion problem NRC shares some valid concerns particularly w/respect to performance of repaired tubes in event of transients &/or accidents during operation EISENHUT, D O Division of Licensing 82/08/09 LEHIB, M I Lewis, M 2pp 14559 178 24X Fiche 30-289,82/08/09.8208250042

K Utility Final Safety Analysis Report (FSAR) & amends

- 8208030299 Forwards Update 1 to TMI-1 updated FSAR.consisting of Figures 12 1-1, 12 1-2,7 1-5,7 1-6 & 7 1-7 MATES, J S Gibbs & Hill. Inc (subs of Dravo Corp.) 82/07/28 DENTON, H R Office of Nuclear Reactor Regulation. Director 1p 14157 183 24X Fiche 50-289,82/07/28,8208030299.
- --8208030307 Update 1 to TMI-1 updated F8AR, consisting of Figures 12 1-1, 12 1-2, 7 1-5, 7 1-6 & 7 1-7 re station organization & logic diagram for M8-V-130 & EF-P28 actuation
 * General Public Utilities OPU Service Corp 82/07/28 10pp 14157 184 24X Fiche 50-289, 82/07/28, 8208030299

P Operating license stage documents & correspondence

- 8207080044 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Bvc list encl
 DIRCKS, W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14174 001
 24X Fiche, 50-000, 82/07/02. 8207080064
- 8208030088 Draft Commission paper informing of present status of OPU program for recovery from steam generator tube corrosion problem & describing NRC intended response to OPU 820430 ltr re need for hearings DIRCKB.W J Office of the Executive Director for Operations 82/07/19 9pp 14193 343 24X Fiche 80-289.82/07/19.8208030088
- 8208040633 Forwards preliminary "Short Form Spec for Once-Through Steam Cenerator Tube Repair" & "Explosive Expansion Qualification Requirements for Mechanical Testing for Explosive Expansion Repair of TMI-1 Once-Through Steam Generators "
 MCCRACKEN.C Chemical Engineering Branch 82/07/19 JACOBS.R Operating Reactors Branch 4 37pp 14228, 162 24X Fiche 50-289, 82/07/19, 8208040633
- 8208040030 Confirms 820720 telcon re decision to start sending all publicly available hearing transcripts for TMI-1 to Pattee Library at PA State Univ SGUDER, J L Division of Rules and Records 82/07/20 SMITH.D Pennsylvania State Univ 1p 14235 354 24X Fiche.50-289,82/07/20, 2000/24070
- 8208190076 Board Notification 82-75 forwarding summary info re issues on probability of accidents for nuclear power reactors MOVAK.T M Assistant Director for Operating Reactors 82/07/21 Atomic Safety and Licensing Appeal Panel. 18pp 14506 102 24X Fichs 50-289,82/07/21.8208190076
- 8208260580 Notification of contract execution. "Reanalysis of Existing Data from Telephone Surveys Concerning TMI," awarded to Nati Inst of Hental Health FLEEMOR, C M Technical Assistance Contracts Branch FIN 8-8621 82/07/21 VOLLMER, R. H., REGAN, W H Division of Engineering ip 14566.045, 24x Fichs 50-287,82/07/21,8208260580
- ---B208260985 Memorandum of Agresment between NRC & Natl Inst of Hental Health expanding Grant MH33425 to encompass "Reanalysis of Existing Data from Telephone Surveys Concerning TMI" MATTIA-M Division of Contracts PARDES, H Health & Human Services, Dapt, of, FIN 8-8621 82/07/14 3pp 14568-046 24X Fiche 50-289, 82/07/21, 8208260580.
- 8208130031 Forwards request for add1 info re containment flood leval calculations Response requested within 30 days 870LZ: F Operating Reactors Brench 4 82/07/26 HUKILL, H. D Ceneral Public Utilities QPU Bervice Corp 7pp 14340-355. 24: Fiche: 50-289, 82/07/26, 8208130031
- 8208060369 Board Notification 82-71 informs that NRC did not rely on feed & bleed cooling to protect core & forwards info supporting info LAINAS. G C Assistant Director for Operating Reactors 82/07/27. Atomic Safety and Licensing Appeal Panel 20pp 14281:359 24X Fiche: 50-289, 82/07/27. 8208060369

- B208110036 Informs of util finalized steam generator repair plans. Dates of scheduled future meetings & areas of concern listed MCCRACKEN.C Chemical Engineering Branch. B2/07/29 BENARDYA.V Chemical Engineering Branch. 3pp 14330 296 24X Fiche 50-289, G2/07/29, B20B110036
- 8208090010 80CIOECONOMIC IMPACTS DF NUCLEAR GENERATING STATIONS THREE MILE ISLAND CASE STUDY Oct 1,1978-January 4,1982 Docket Nos 30-289 and 50-320 (Metropolitan Edison et al.)
 FLYNN, C Social Impact Research, Inc. + Mountain West Research, Inc. FIN 8-6268 NUREO/CR-2749 VI2 82/07/31, Division of Health, Siting & Environment 242pp Available at NTIS, \$7 50, 14302 168 24X Fiche 50-289,82/07/31,8208090010
- 8208030123 Forwards description & evaluation of main steam line rupture detection sys design changes Approval requested HUKILL: H D General Public Utilities GPU Service Corp 82/08/02 STOLZ: J F Operating Reactors Branch 4 3pp. 14213 119 24X Fiche 50-289: 82/08/02: 8208030123.
- 8208170358 Forwards supplemental safety evaluation re util response to NVREO-0737, them II K 2 9 concerning failure made effects analysis on integrated control sys Design meets all current regulatory requirements
 STOLZ-J F Operating Reactors Branch 4 82/08/02 HUKILL-H D. Oeneral Public Utilities CPU Service Corp 4pp 14373 229. 24X Fiche 30-289, 82/08/02, 8208170358
- B208240035 Responds to approval request for info collection repsychological stress of THI-1 restart on residents of surrounding communities Request not approved (withdrawn at agency request)

 BCURRY, N, Office of Management & Budget 82/08/02 8COTT, B. Document Management Branch 2pp 14529 256 24X

 Fichs. 50-289: 82/08/02. 8208240035
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT.D G Division of Licensing 82/08/09 Consolidated Edison Co of New York Ip 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208170209 Forwards addi info on reactor bldg spray sys mods in support of Tech Spec Change Request 107 Drawdown test of borated waste storage tank & sodium hydroxide tank not warranted HUKILL.H D Ceneral Public Utilities QPU Service Curp B2/08/11.
 STOLZ.V F Operating Reactors Branch 4 24pp 14362 061 24X Fiche 50-289, 82/08/11, 8208170209
- 8208190200 Forwards Tech Spec Change Request 116 supporting amend to License DPR-50. App A Change implements Branch Technical position CBB 6-4 Item 8. 4. providing for leak rate testing of purge/vent sys isolation valves
 HUKILL.H D General Public Utilities OPU Service Corp 82/08/13.
 BYOLZ.J.F Operating Reactors Branch 4 ip. 14386 331 24X
 Fiche 50-289. 82/08/13, 8208190200
- --8208190204 Tech Bpec Change Request 116 supporting amend to License DPR-50, App A Change implements Branch Technical Position CSB 6-4, providing for leak rate testing of purge/vent sys isolation valves Certificate of Svc encl HVKILL.H. D General Public Utilities GPU Service Corp 82/08/13 Spp. 14386 332 24X Fiche 50-289, 92/08/13,8208190200
- --B208i902i0 Proposed Tach Spacs supporting amend to License DPR-50, App A, implementing Branch Tachnical Postetion CSB 6-4 Item B 4, providing for leak rate testing of purge/vent sys isolation valves

 * General Public Utilities OPU Service Corp 82/08/13 12pp 14386, 337 24% Fiche. 50-289, 82/08/13,8208190200
- 820B1900B6 Formalizes proposals made at 820720 meeting w/NRC for resolution of NUREO-0737. Item II.K 3 30, "Revised Email Break LOGA Methods "Followup Itr w/addl details k milestones will be provided within next several wks. WILBON.R F General Public Utilities OPU Service Corp. 82/08/16 DENTON.H R Office of Nuclear Reactor Regulation. Director 10pp 14383.187. 24X Fiche 30-289.82/08/16,820B190086.
- 8208310393 Forwards for comment, B&W rept: "Evaluation of Tube Samples From THI-1 Steam Generators " Add1 results from later tube pulls including BMI exam results to be evailable in near future, W/o encl.

 MCCRACKEN, C Chemical Engineering Branch 82/08/19, BENARDYA, V. Chemical Engineering Branch. 1p. 14697 128, 24X Fiche: 50-289, 82/08/19, 8208310393

- 82082A0201 Forwards supplemental response to NRC 820316 request for add1 info re NUREQ-0737.ltam II 8 1. "RCS Vents "
 One oversize drawing encl Aperture card is available in PDF HUKILL.H D General Public Utilities OPU Service Corp 82/08/23 STOLZ, J F Operating Reactors Branch 4 18pp 14552 329 24x Fiche 50-289,82/08/23,8208240201
- O Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Mein Stram Isolation Valve (MSIV) Leakage " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-24, Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigam
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list entl JURDAN.E L. Dávision of Engineering & Quality Assurance 82/07/20 Consolidated Edison Go of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- B204210397 IE Info Natice 82-24, "Water Leeking From U Hexafluoride Overpacks " Byc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 7jpp 14357 274 24X Fiche 50-000,82/07/20,8204210397
- 9208020372 Forwards IE Insp Rept 50~289/82-09 on 820409-0705 No noncompliance noted STARQSTECKI.R Division of Project & Resident Programs 82/07/20 HUKILL,H D General Public Utilities - OPU Service Corp 2pp 14/150 119 24X Fiche 50~289.82/07/20.8208020372
- --B208020377 IE Insp Rept 50-289/02-09 on 820609-0705 No noncompliance noted Major areas inspected selective exam of procedures & representative records interviews w/persunnel & inspector observations
 CONTE.R., NAPUDA, 9. MEYER, 0. Division of Project & Resident Programs 82/07/10 10pp 14150 121 24X Fiche 50-289,82/07/20,8208020372
- 8208040652 Forwards safety evaluation of util 800507 & 20 responses to IE Bulletin 80-04: "Analysis of PHR Main Steam Line Break H/Continued Feedwater Addition" Analysis acceptable STOLZ, JF Operating Reactors Branch 4 82/07/ZI HUKILL, H D General Public Utilities OPU Service Corp 4pp. [4225 174 24X Fiche 50-289.82/07/ZI, 8208040652
- --8208040657 Safety evaluation re main steam line break w/continued feedwater addition No further action required by licenese re IE Sulletin 80-04 * NRC No Detailed Affiliation Given 82/07/21 6pp 14225-198 24X Ficher 50-289, 82/07/21, 8208040652.
- 8205280525 "PHR Main Steam Line Break H/Continued Feedwater Addition (8-69). Med Ed, TMI-1, " technical evaluation rept VOSBURY, F. M. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5504-141 82/06/23 HEARN, P. NRC No Detailed Affiliation Given 2ipp 14225 205 24X Fiche 50-289, 82/07/21, 8208040652
- '04210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list ancl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York 112pp 14174 321 24X Fi
- 04210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Gyc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/29, Cansolidated Edison Co. of New York 122pp 14380 115 24X Fiche. 50-000. 82/07/29, 8204210401.
- 204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Fatiures at Westinghouse PWRs " 8vc list encl. JORDAN.E.L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co. of New York 1276p, 14194-120 24X Fiche.50-000, 82/07/23, 8204210402
- |210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping Certain Westinghouse FWR Power Plants " Syc list encl. RDAN.E. L Division of Engineering & Guality Assurance, 62/07/26, Cansol(dated Edican Co. of New York 121sp, 14357:013 24X the 50-000 82/07/26,8204210403.

- 8204210405 IE lnfo Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000.82/07/28,6204210405
- 8208130013 Forwards response to Items 3 & 5 of IE Bulletin 82-02 re
 RCPB closures Encls identify bolted closures that leaked,
 corrective actions & closures using fastener lubricants or
 injection seajant matl
 HUKILLH D General Public Utilities OPU Service Corp 82/08/03
 HAYNES.R C Region 1, Office of Director 5pp 14335 051 24X
 Fiche 50-289, 82/08/03, 8208130013
- B204210407 IE lnfo Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/08
 Consolidates Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000 82/08/05.8204210407
- 820B190227 Ack receipt of 820729 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/82-07
 STANGBTECKIR Division of Project & Resident Programs 82/08/12
 HUKILL HD General Fublic Utilities 0FU Service Corp 2pp 14387 141 24X Fiche 50-289,82/08/12,8208190227
- --B208190237 Responds to NRC B20701 ltr re violations noted in IE Inep
 Rept 50-289/82-07 Corrective actions demaged tubing supports
 repaired & Drawing B-308-854 changed to reflect new slope
 criteria for transmitter sensing lines.
 HUKILL.H D General Public Utilities GPU Service Corp
 82/07/29 HAYNES.R C Region I. Office of Director 3pp
 14387 143 24X Fiche 50-289, 82/08/12,8208190227
- 8208300002 Board Notification 82-83 forwarding IE Insp Rept 50-320/82-04 identifying inadequate corrective maint actions on TMI-2 ventilation sys important to safety Region i will inspect TMI-1 maint sys to determine if problems exist LAIMAS-9 C Assistant Director for Operating Reactors 82/08/13 Atomic Safety and Licensing Appeal Panel. 5pp 14683-326 24x Fiche 50-289,82/08/13,8208300002
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info forwards documents listed in App A. FELTON. J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp. 14679 208 24% Fiche 50-000, 82/07/13, 8208270010
- --8208270019 Forwards "Statistical Summary Rept of Personnel Monitoring Info for CYSI," per 10CFR20 407
 HUKILL, H D General Public Utilities OPU Service Corp 82/03/01 HAYNES, R C. Region I. Office of Director. 1p. 14680 001 24% Fiche 50-000,82/07/13,8208270010.
- --8208270023 "Btatistical Summary Rept of Personnel Monitoring Info for CYGL."

 * General Public Utilities GPU Service Corp 82/03/01. 2pp. 14680.002 24X Fiche 50-000,82/07/13.8208270010
- --B20827009B "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1."

 * NRC No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche: 50-000, B2/07/13, B208270010.
- --B20B270649 Forwards "Number of Personnel & Han Rems By Work & Job Function for CYG1,"
 HUKILL, H. D. General Public Utilities QPU Bervice Corp B2/03/01 HAYNEG: R C Region 1: Office of Director. 1p. 14679-352 24X Fiche 50-000, 82/07/13.8208270010.
- ---8208270656 "Number of Personnel & Man Rems Dy Work & Job Function for CYB1" ** General Public Utilities -- OFU Bervice Corp 82/03/01. 5pp 14679.353. 24X Fiche 50-000,82/07/13.8208270010
- 820B100275 Forwards "TMI Aquatic Study," monthly rept for June 1982 TEITT.T R General Public Utilities - QPU Service Corp. B2/08/05. HICKEY.C NRC - No Detailed Affiliation Given ip 14295 145. 24x Fiche: 50-289, 82/08/05, 8208100275
- --BE08100278 "TMI Aquatic Study," monthly rept for June 1782 NARDACCI, 6 A., RANEY, E.C. Ichthyological Associates, Inc. 82/08/05 32pp 14275-146. 24X Fiche, 50-287, 82/08/05, 8208100275
- 8208190074 Forwards monthly operating rept for Jul 1982 HUKILL, H D. General Public Utilities - QPU Service Corp MCDUNALD, N. C Diffice of Resource Management, Director 1p 14383 197. 24X Fiche 50-289, 82/08/13, 8208190074,

--8208190077 Monthly operating rept for Jul 1982 SMYTH.C W Qeneral Public Utilities - OPU Service Corp 82/08/13 12pp 14383 198 24X Fiche 50-289,82/08/13,8208190074

T Hearing transcripts on non-antitrust matters

8208260551 Add1 response to FOIA request for documents made available by NRC to CM McMurray (FOIA Request 82-176) Documents listed in Apps A & B provided on 820707 & 0713, respectively Forwards App B documents PELTON.J M Division of Rules and Records 82/07/15 ELLIB, T B Munton & Williams 3pp 14569 045 24X Fiche 50-289, 82/07/15, 8208260551

DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8208170140 Forwards IE Emergency Preparedness Appraisal Rept 50-273/81-15 on 810713-24 No noncompliance noted. 8MITH, G. H Division of Emergency Preparedness & Operational Support 82/06/22 HARRINGTON.W D Boston Edison Co 30pp 14366 145 24X Fiche 50-293.82/06/22,8208170140
- 8208120058 Ack receipt of 820709 itr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-293/81-15 EHITH O H Division of Emergency Preparedness & Operational Support 82/08/04 HARRINOTON W D Boston Edison Co 2pp 14323 347 24 Fiche 50-293.82/08/04.8208120058
- --820Bi20060 Responds to NRC 820622 ltr re violations noted in IE Emergency Preparedness Appraisal Rept 50-293/81-15 Corrective actions will be submitted by 820B01 Many App A items should be placed in App B HARRINGTON W D Philadelphia Electric Co 82/07/09 EMITH, 0 H Division of Emergency Preparedness & Operational Support 2pp 14323,349 24X Fiche 50-293,82/08/04,8208120058
- 9208239277 Forwards summary of 920805 mgt meeting w/util in King of Prussia.PA re emergency preparedness program SMITH.9 H Division of Emergency Preparedness 92/08/17. HARRINOTON.W D Boston Edison Co 2pp 14512.260 24X Fiche 50-293.82/08/17.8208230277
- --8208230281 Bummary of 820805 mgt meeting w/util in King of Prussia.PA re emergency liason function, 820728 emergency preparedness implementation appraisal response.App C response & status of siren sys coverage MOJFA.M T Region 1. Office of Director 82/08/17. Region 1. Office of Director 2pp 14512 262 24X Fiche: 50-293, 82/08/17, 8208230277
- 8208300213 Ack receipt of 820728 ltr informing NRC of steps taken to improve items identified in Apps A & B of NRC 820622 ltr transmitting IE Emergency Preparedness Appraisal Rept 50-293/81-15
 SMITH O. H Division of Emergency Preparedness & Operational Support. 82/08/24 HARRINOTON. W D, Boston Edison Co 2pp 14679.072 24% Fiche 50-293,82/08/24,8208300213
- --B20B300215 Forwards responses to items identified in Apps A & B of NRC B20622 ltr transmitting IE Emergency Preparedness Appraisal Rept 50-293/81-15. Meeting will be scheduled in early Aug to discuss subj HOWARD, J E Boston Edison Co 82/07/28. SMITH, O H Division of Emergency Preparedness & Operational Support. 62pp 14679 074 24% Fiche 50-293,82/08/24,8208300213.

O Adjudicatory correspondence

8208020312 Order extending time until 820806 for Commission to decide whether to review IE Director denial of Commonwealth of MA Executive Ofc of Energy Resources 820318 request for action per 10GFR2 206, HOYLE, J.C., Office of the Secretary of the Commission, 82/07/29, Commissioners ip, 14151,130, 24X Fiche 80-293,82/07/29,8208020312

- 8208030302 Order CLI-82-16, denying Commonwealth of MA 820217 petition to intervene & request for hearing re IE 820118 order Stated concerns beyond scope of proceeding State of MA not entitled as of right to any formal hearing MOYLE, J C Office of the Secretary of the Commission B2/07/30 Massachusetts, State of App 14157 156 24X Fiche 50-293, 82/07/30,8208030302
- 8208090142 Order estending time for Commission to decide whether to review IE denial of State of MA Executive Ofc of Energy Resources 820318 request for action under 10CFR2 206 until 820811 HOYLE, J C Office of the Secretary of the Commissions 82/08/06 Commissioners 1p 14271 307 24X Fiche, 50-293, 82/08/06.
- 8208160083 Forwards request of MA Atty General for submission of documents re mgt & safety of facility since 82011B, GOMES, JR Hassachusetts, State of 82/08/10 NRC No Detailed Affiliation Given 1p 14342.066 24X Fiche 50-293,82/08/10, 820814083
- --82081600B7 Request of MA Atty General for submission of documents remoted safety of facility since 82011B Patition for review of Commission 820730 decision denying patition to intervene filed w/Court of Appeals Cartificate of Byc ancl GOMES, JR Massachusetts, Bate of 82/08/10 Commissioners, 3pp 14342,067 24% Fiche 50-293,82/08/10.8208160083
- 8208170321 Informs that Commission declined to review Director's Decision DD-62-4. Decision designated final agency action on 820811 CHILK, S. J. Office of the Secretary of the Commission 62/08/16. KENNY, P. J. Massachusetts. State of ip 14366-338 24X Fichs 50-293. 82/08/16. 8208170321.
- P Operating license stage documents & correspondence
- 8207080064 Ceneric ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKE: W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 OOL.
 24X Fiche 50-000.82/07/02.8207080064
- B208050040 Forwards safety evaluation & LLL technical evaluation rept supporting reactor protection sys power monitoring sys mod If NRC understanding re mod implementation incorrect NRC must be notified within 30 days VASBALLO, D B Operating Reactors Branch 2 82/07/28 MORIBI.A V Boston Edison Co 2pp 14243 189 24X Fichs. 50-293,82/07/28.
- --8208050042 Safety evaluation supporting reactor protection sys power monitoring sys mod.

 AHMED, I NRC No Detailed Affiliation Oiven 82/07/28 2pp 14243 191 24% Fiche 50-273, 82/07/28, 8208050040
- --8208030044 "Monitoring of Electric Power to Reactor Protection 8ys for Pilgrim Nuclear Power Station:" technical evaluation rept SELAN.J C Lawrence Liveragre Laboratory. FIN A-0250 82/04/29, NRC No Detailed Affiliation Given. 7pp 14243 193, 24X Fiche 50-293,82/07/28.8208050040
- 820B100104 Advises that Tech Space reliadine concentration limit will not be madified until final disposition of BWR owners group study is completed by NRC MORIBIA V Boston Edison Co 82/07/28, VASSALLO, D. B. Operating Reactors Branch 2 ip. 14277:303. 24X Fiche 50-293,82/07/28, 8208100104
- 8208120279 Forwards revised version of model Tech Brecs re reactor protection sys power monitoring sys design mod Tech Brecs less restrictive.

 VASSALLO.D B Operating Reactors Branch 2 82/07/28, MORIBI.A V Boston Edison Co Spp. 14332:252 24X Fiche 50-293,82/07/28,8208120299
- 8208180265 Advises that TMI Item II K 3.15 re isolation of HPCI/reactor core isolation cooling sys (RCIC) resolved for facility.
 Proposed mathod for preventing spurious isolation of HPCI/
 RCIC approved implementation may require revised Tech 8pec.
 VABSALLO,D.8 Operating Reactors Branch 2. 82/07/28 MORISI.V.
 Boston Edison Co 3pp 14389,315 24X Fiche 50-293,82/07/2B,
 8209180245
- 8208230038 Forwards Amend 62 to License DPR-35, safety evaluation & notice of issuance & evaluability Amend clarifies alternate rod insertion sys operation & core spray, LPCI & diesel generator testing requirements.

 ECCLEBTON, K. T. Operating Reactors Branch 2, 62/08/05 MORISI, A. V. Boston Edison Co. 2pp. 14507; 272 24X Fiche 50-273, 82/08/05, 8208230038

- --8208230040 Amend 62 to License DPR-35, clarifying alternate rod insertion sys operation & core spray, LPCI & diesel generator testing requirements RODNEY, V L. Operating Reacturs Branch 2 82/08/05 lipp 14907 274 24X Fiche 50-293, 82/08/05, 8208230038
- --8208230043 Safety evaluation supporting Amend 62 to License DPR-35 * Office of Nuclear Reactor Regulation, Director 82/08/05 3pp 14507 305 24% Fiche 50-293,82/08/05,8208230038
- --8208230046 Notice of isquance & availability of Amend 62 to License DRR-35 RODNEY, V L Operating Reactors Branch 2 82/08/05 2pp 14507 308 24X Fiche 50-293, 82/08/05,8208230038
- 8208270680 Staff requirements memo re 820727 affirmation/discussion session Commission approved orders releasing sanitized version of ALAB-653, reviewing ALAB-670 & denying petition to intervene in proceeding for mod of Pilgrim OL. HOYLE.J C Office of the Secretary of the Commission 82/08/06 BICKWIT.L Office of the General Counsel. 4pp 14683 185 24X Fiche 50-000, 62/08/06.8208270680
- 8208090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements five list encl EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000,82/08/09,8208090194.
- 8208190391 Requests documentation indicating completion of NUREO-0737. ITEM II B 3 re post-accident sampling Schedule requested within 20 days of receipt of ler VASSALLO,D B Operating Reactors Branch 2 82/08/09 MORIBI.A V Boston Edison Co 10pp 14504 166 24X Fichs 50-293,82/08/09,82/08190391
- 920B230R34 Forwards proposed agenda for 820B24 joint util/NRC performance improvement update meeting at Region i ofte Agenda item 3 re Unrevised Bafety Question 50 59 will be discussed per onsite inspector request HARRINGTON W D Boston Edison Ca 82/08/16 HAYNES, R C Region 1, Office of Director 2pp 14508/339 24X Fiche 50~293,82/08/16,8208230234
- G Inspection reports, IE Bulletins & correspondence
- 8208170140 Forwards IE Emergency Preparedness Appraisal Rept 50-273/81-15 on 810713-24 No noncompliance noted 8M17H, G H Division of Emergency Preparedness & Operational Support 82/06/22. HARINOTON, M D Boston Edison Co. 30pp 14366:145 24X Fiche 50-273.82/06/22.8208170140
- --8208170141 IE Emergency Preparedness Appraisal Rept 80-293/81-15 on 810713-24 No noncompliance noted Major areas inspected emergency facilities & equipment-emergency implementing procedures & emergency organization MCKENNA.T J. CROCKER.H W Division of Emergency Preparedness & Operational Support 82/06/16 59pp 14366-175 24X Fiche 50-293,82/06/22,8208170140
- 204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Evc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 62/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 204210395 IE Info Notice 81-26,Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance, B2/07/19
 Michigam, Univ. of 112pp 14358,001 24X Fiche.50-000,82/07/19,8204210395
- B208050162 Forwards results of insp & re-evaluation of as-built configuration of safety-related piping sys, per requirements of IE Bullstins 79-02 & 79-14 Mods should be completed in late 1982.

 MORISI, A V Boston Edison Co 82/07/19 HAYNES, R C. Region 1, Office of Director. 32pp 14212 085 24X Fiche 50-293,82/07/19,820690162
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure," Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York 112pp 14381 001, 24X Fiche 50-000, 82/07/20, 8204210394

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluorida Overpacks" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357*276 24X Fiche 50-000, 82/07/20, 8204210397
- 8208050239 Forwards IE Insp Rept 50-293/82-14 on 820517-21 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/07/21 HARRINGTON,W D Boston Edison Co 2pp 14209 269 24X Fichs 50-293,82/07/21,8208050239
- --B208050243 IE Insp Rept 50-293/82-14 on 820517-21 No noncompliance noted Major areas inspected radiation protection program, including transportation & radwate mgt COLLINS, D J , WRAY, J R , GREENMAN. E 0 Region 1, Office of Director 82/07/09 Bpp 14209 271 24X Fiche 50-293,82/07/21, 8208050239
- B20421039B IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000: B2/07/22, 820421039B
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Bvc list encl JBRDAN.E L Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24% Fiche 50-000.82/07/23.8204210401.
- 8204210402 IE Info Natice 82-29. "Control Rod Drive (CRD) Guide Tubu Support Pin Failures at Westinghouse PWRs " Svc list encl URDAN, E L Division of Engineering & Quality Assurance 82/07/83 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000.82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants." 8vc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000: 82/07/26.8204210403
- 6204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/28, Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8208020338 Ack receipt of 820607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-13
 MARTIN.T T Division of Engineering & Technical Programs. 82/07/28
 HARRINOTON W Boston Edison Co ip 14147 097 24X
 Fichs 50-293,82/07/28,8208020338
- --8208020342 Responds to NRC 820511 itr reviolations noted in IE Insp. Rept 50-293/82-13 Corrective actions nuclear organization policy issued on 820513, requiring complete identification of design criteria & deviations before design change approval HARRINGTON, W.D. Boston Edison Co. 82/06/07 MARTIN.T.T. Division of Engineering & Technical Programs App. 14147 098 24X Fiche 50-293,82/07/28.8208020338
- 8208050531 Ack receipt of 820719 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-04 MARTIN.T T Division of Engineering & Technical Programs 82/07/30 HARRINGTON, W D Boston Edison Co 1p 14214 058 24X Fiche 50-293, 82/07/30, 8208080531
- --B20B050539 Responds to NRC 820621 ltr re-violations noted in IE Insp. Rept 50-293/B2-06 Corrective actions revised training manual re-requalification of nuclear auxiliary operations & developed training schedule. Completion expected by B30101 HARRINOTON, P. M. Boston Edison Co. B2/07/19 MARTIN, T. T. Division of Engineering & Technical Programs 2pp 14214 057 24X Fiche 50-293, 82/07/30.8208050531
- 8208120058 Ack receipt of 820709 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-293/81-15
 SMITH, G H Division of Emergency Preparedness & Operational Support 82/08/04 HARRINGTON, W D Doston Edison Co. 2pp. 14323 347. 24X Fiche 50-273,82/08/04,8208120058
- --B208120060 Responds to NRC B20622 ltr re violations noted in IR Emergency Preparadness Appraisal Rept 50-293/81-15 Corrective actions will be submitted by B20801 Many App A items should be placed in App B HARRINGTON.W D. Philadelphia Electric Co. B2/07/09 BMITH, G. H Division of Emergency Preparadness & Operational Support 2pp 14323-349. 24X Fiche, 50-293, 82/08/04, 8208120058

- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Bvc list encl JURDAN, E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201, 24X Fiche 50-000, 82/08/05,8204210407
- 820B300245 Forwards IE Insp Rept 50-293/82-20 on 8206i1-13 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs 82/08/13 HARRINOTON, W D Boston Edison Co 2pp 14679 155 24X Fiche 50-293,82/08/13,8208300245
- --B20B30024B IE Insp Rept 90-293/82-20 on 820611-13 No noncompliance noted Major areas inspected initial contamination identification, contamination surveys, posting & barricading & rasin source determination NIMITZ.R L, MCRRIDE.M H, KOTTAN, J J Division of Engineering & Technical Programs B2/08/05 8pp 14679 197 24X Fiche 50-293, 82/08/13.8208300245
- 8208300184 Forwards 1E Insp Rept 50-293/82-19 on 820614-0801 & notices of violation & deviation STAROSTECKI, R Division of Project & Resident Programs 82/08/16 HARRINOTON, W Boston Edison Co 2pp 14596 015 24X Fiche 50-293
- --B208300185 Notice of violation from insp on B20614-0801 * Region 1, Office of Director B2/08/16 3pp 14596 017 24X Fiche 50-293,82/08/16,6208300184
- --B208300186 Notice of deviation from Insp on 820614-0801.

 * Region 1, Office of Director 82/08/16 1p 14596 020 24X Fich 50-293,82/08/16,8208300184
- --920830018B IE Insp Rept 50-293/82-19 on 820414-0801 Noncompliance noted fire door blocked open w/o proper controls failure to evaluate fire loading prior to moving combustibles & failure to translate design info into drawings
 JOHNSON, J . EICHENHOLZ, H . BRIGOSIL Region 1, Office of Director.
 82/08/12 20pp 14596 021 24X Fiche 50-293,62/08/16,8208300184
- 8208300213 Ack receipt of 820728 ltr informing NRC of steps taken to improve items identified in Apps A & B of NRC 820622 ltr transmitting IE Emergency Preparedness Appraisal Rept 50-293/81-15
 SMITH.0 H Division of Emergency Preparedness & Operational Support 82/08/24 HARRINGTON.W D Boston Edison Co 2pp 14679.072 24 Fiche 50-293.82/08/24,8208300213
- --8208300215 Forwards responses to items identified in Apps A & B of NRC 820622 1tr transmitting IE Emergency Preparedness Appraisal Rept 50-293/Bi-I5 Meeting will be scheduled in early Aug to discuss subj HOMARD. J. E. Boston Edison Co. 82/07/28, BMITH, O H. Division of Emergency Preparedness & Operational Support 62pp 14679 074 24X Fiche 50-293,82/08/24.8208300213
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL,R A. Critical Hass Energy Project 8pp. 14679 208 24X Fiche. 50-000. 82/07/13, 8208270010
- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" • NRC - No Detailed Affiliation Given 82/07/13 48pp. 14679 216 24X Fiche 50-000,82/07/13,8208270010
- --B208270620 Forwards "Personnel Whole Dody Exposures for CY81," par 10CFR20 407(a) & (b) MACHON,R D Boston Edison Co 82/03/26 Office of Management and Program Analysis 1p 14680 058 24X Fiche 50-000,82/07/13, B208270010
- --8208270623 "Personnel Whole Body Exposures for CY81 "
 * Boston Edison Co 82/03/26 ip 14680.059. 24X
 Fiche, 50-000, 82/07/13, 8208270010
- 8208120141 Forwards monthly operating rept for June 1782.

 MACHON, R. D. Boeton Edison Co 82/07/14 Management Information
 Branch 1p 14317.167 24X Fiche 50-273, 82/07/14,8208120141
- ---8208120143 Monthly operating rept for June 1982 WHITNEY, 9 9 Boston Edison Co 82/07/14 App. 14319:170 24X Fiche: 50-273, 82/07/14, 8208120141.

- S Reportable occurrences, LERs & related correspondence
- 8208050266 Forwards LER 82-021/03L-0
 MACHON, R D Boston Edison Co 82/07/21 HAYNES, R C Region 1,
 Office of Director 1p 14210 120 24% Fiche 50-293, 82/07/21,
 8208050264
- --6208050271 LER 82-021/03L-0 on 820624, fire door 153 on 37 ft elevation of turbine bldg ennex found blocked opened. Caused by door being blocked to remove mat! Faulty lock replaced MCLAUGHLIN, MT Boxton Edison Co. 82/07/21 Region 1, Office of Director ip 14210 121 24X Fichs 50-293, 82/07/21, 8208050264
- 8208130186 LER 82-022/01X-0 on 820801 during power ascension following scheduled power reduction, speed of A recirculation pump went above 15% allowable Tech Spec limit Caused by broken timing belt on pump scoop tube positioner WHITNEY, 0 G Boston Edison Co 82/08/03, Region 1, Office of Director 1p 14338 282 24% Fiche 30-273.82/08/03,8208130186
- 8208260316 Telecopy message of LER 82-023/01X-0 on 820813, reactor scram occurred due to main steam line high flow trip signal Caused by damage to main steam flow instruments on panel 2256 due to moving pipe staging Instruments recallor.
 WHITNEY, 0 9 Boston Edison Co 82/08/13 Region i, Offico of Director ip 14555 351 24X Fiche 50-293,82/08/13,8208260316
- 8208300210 Telecopy LER 82-025/01X-0 on 820815, hydrogen sample valves failed to meet containment isolation single failure criteria Probably caused by design errors Appropriate wiring changes made to provide redundant isolation signals OTARDIELLO, FF Boston Edison Co 82/08/16 Region 1, Office of Director 19 14478 231 24X Fiche 50-273,82/08/16,8208300210
- 8208300214 Telecopy LER 82-026/01X-0 on 820817. determined that Tech Spec 4 5 B 1 6 inadequate to demonstrate standby svc water sys capability Caused by apparent incorrect translation of FBAR design basis into Tech Spec surveillance requirements OIARDIELLO, P Boston Edison Co 82/08/17 Region 1, Uffice of Director 1p 14678, 230 24X Ficher 50-293, 82/08/17, 8208300214
- 820B3002B9 Forwards LER B2-027/03L-0 MACHON, R D Boston Edison Co B2/08/19 HAYNES, R. C Region i, Office of Director 1p 14599 331 24X Fiche, 50-293, 82/08/19, B20B3002B9
- ---B20B300296 LER 82-027/03L-0 on 820720, review of data from performance of Procedure 8 H 2-2.1.3 indicated changes to input data for calibr were made prior to mgt approval Caused by personnel error Revised procedure approved GIARDIELLO.P F Boston Edison Co 82/08/19 Region i, Office of Director ip 14579 332. 24X Fiche 50-293,82/08/19,8208302889

DOCKET 50-294 MICHIGAN STATE UNIV REBEARCH REACTOR

G Inspection reports, IE Bullstins & correspondence

8204210395 IE Info Notice 81-26, Part 3. Suppl 1. "Clarification of Placement of Parsonnel Honitoring Devices for External Radiation " Svc list encl.
JORDAN. E. L. Division of Engineering & Quality Assurance, 82/07/19
Michigan. Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395

DOCKET 50-295 ZION NUCLEAR POWER STATION. UNIT 1

F Security, medical, emergency & fire protection plans

- 8208090231 Forwards IE Insp Repts 30-293/82-11 & 50-304/82-09 on B20510-0625 & notice of violation HIND: J A Division of Emergency Preparedness & Operational Support, 82/07/22 REED, C Commonwealth Edison Co. 2pp 14271:105 24X Fichs. 50-295. 82/07/22, 8208090231
- --8208070236 Notice of violation from insp on 820510-0625. HIND.J A Division of Emergency Preparedness & Operational Support 82/07/15 ip 14271 107 24X Fiche 50-295,82/07/22. 8208070231.
- ---8208070241 IE Insp Repts 50-275/82-11 & 50-304/82-07 on 820510-0625. Noncompliance noted failure to follow & maintain emergency response plan & meet stds of 10CFR50 47(b) & to implement plan by 810401.

 JANUSKA:A.O., AXELSON,W.L. Division of Emergency Preparedness & Operational Support 82/07/15 5pp. 14271 108 24X Fiche 50-295,82/07/22.8208070231

- 8208030186 Application to amend Licenses DPR-39 & DPR-48, clarifying responsibilities of licenses during emergencies to take actions necessary to protect health & safety of public LENTINE, F Q Commonwealth Edison Co 82/07/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14160 157 24X Fiche 50-295, 82/07/23, 8208030186
- 8208030503 Forwards final revised "Fire Protection Associated Cable Rept Zion i & 2 " LENTINE.F O Commonwealth Edison Co 82/07/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 10pp 14195 031 24X Fiche 30-275,82/07/30,8208030603
- --B20B03O621 Final revised "Fire Protection Associated Cable Rept Zion 1 & 2 " W/77 oversize drawings Aperture cards are available in PDR # Commonwealth Edison Co #2/07/31 135pp 14195 033 24X Fiche 50-295,82/07/30,8208030603
- 8208110254 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 82/08/05 Document Management Branch 1p 14331 141 24X Fiche 50-295,82/08/05,8208110254
- --8208110256 Forwards public version of Revision 5 to Emergency Plan Implementing Procedure EPIP 110-1, "Station Director" Receipt form encl PLIML,O Commonwealth Edison Co 82/07/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 19 14331 142 24X Fiche. 50-275, 82/08/05, 8208110254
- --B208110261 Public version of Revision 5 to Emergency Plan Implementing Procedure EPIP 110-1. "Station Director" • Commonwealth Edison Co 82/07/22 Spp. 14331 143 24X Fiche 50-275.82/08/05.8208110224
- B20B110259 Releases public version of revised page to emergency plan implementing procedure. FELTON, J M Division of Rules and Records 82/08/05 Document Hanagement Branch Ip 14332 172 24X Fiche 50-295, 82/08/05, 820B110259
- --B20Bi10263 Forwards public version of revised Page B to Revision 3 to Emergency Plan Implementing Procedure EPIP 700-1, "Corporate Command Ctr Group Directory" Receipt form encl PLIML, G Commonwealth Edison Co B2/07/22 DENTON, H R NRC - Nn Detailed Affiliation Given ip 14332 173 24X Fiche: 50-295, 82/08/05, 820Bi10259
- --B208110265 Public version of revised Page 8 to Revision 3 to Emergency Plan Implementing Procedure EPIP 700-1, "Corporate Command Ctr Group Directory " # Commonwealth Edison Co 82/07/22 2pp 14332 174 24X Fiche 50-275,82/08/05.8208110259
- 20B180090 Forwards exemption requests from sections of post-fire shutdown capability rept to assist in fire protection review LENTINE, F G Commonwealth Edison Co 82/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 14378 189 24X Fiche 50-295,82/08/10.8208180090
- 208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
 FELTON.J M Division of Rules and Records B2/08/12 Document Management Branch ip 14559 354 24X Fiche 50-000,82/08/12,8208280559
- -8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures "MODRE.R D Commonwealth Edison Co 82/07/19 DENTON, H R NRC -No Detailed Affiliation Given Ip 14559 355 24X Fiche: 30-000.82/08/12.8208280559
- -8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures " * Commonwealth Edison Co 82/06/30 7pp 14559,356 24X Fiche 50-000,82/08/12.8208250559.
- Operating license stage documents & correspondence
- PO7080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 VIRCKS, W J Office of the Executive Director for Operations
 PO7/02 Consolidated Edison Co of New York, 93pp. 14194 001
 TX Fiche 50-000,82/07/02,8207080064

- 8208040580 Forwards revised criteria to be used to review submittal on TMI Action Item II B 3. "Post-Accident Sampling Sys "
 Schedule for responding to info requested in 20 days of itr receipt
 NEIGHBURS. J D Operating Reactors Branch 1 82/07/22
 DELOEURGE, L O Commonwealth Edison Co 10pp 14228 225 24X
 Fiche 50-295,82/07/22.8208040580
- 820B030186 Application to amend Licenses DPR-39 & DPR-48.clarifying responsibilities of licenses during emergencies to take actions necessary to protect health & safety of public LENTINE.F G Commonwealth Edison Co 82/07/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 14160 157 24X Fiche 30-295.82/07/23.8208030186
- 8208070103 Provides actions to be taken re startup of units w/equipment required by out of svc Tech Specs & interpretation of phrase "recovery from inadvertent trip," discussed during 820721 meeting
 LENTINE,F G Commonwealth Edison Co 82/07/23 KEPPLER,J G Region 3, Office of Director 2pp 14267 273 24X
 Fichs 50-295,82/07/23,8208090103
- 8208030239 Application to amend Licenses DPR-39 & DPR-48, adding Tech Spec on sealed source contamination LENTINE, FO Commonwealth Edison Co 82/07/29 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 1p 14158 219 24X Fiche 50-295, 82/07/29, 8208030239
- --8208030245 Proposed Tuch Spec Pages 295AD, 295AE & 295AF re sealed source contamination
 * Commonwealth Edison Co 82/07/29 4pp 14158 220 24X Fiche 50-295, 82/07/29, 8208030239
- B208130072 Forwards Amend 75 to License DPR-39, safety evaluation & notice of issuance & availability Amend changes Tech Specs to allow one safety injection pump to be inoperable when power does not exceed 57 WIGOINTON, D. Operating Reactors Branch 1 92/07/30 DELGEGROE, L. G. Commonwealth Edison Co. 2pp. 14340-338 24X Fiche 50-295, 82/07/30, 8208130072
- --B20Bi30077 Amend 75 to License DPR-39, providing one-time Tech Spec change to allow inoperability of one safety injection pump while power levels do not exceed approx 5% of rated power VAROA.S A Operating Reactors Branch 1 B2/07/30 4pp 14340 340 24% Ficha S0-295, 62/07/30, 820Bi30072
- --B20Bi30079 Bafety evaluation supporting Amond 75 to License DPR-39 * Office of Nuclear Reactor Regulation, Director B2/07/30 Pp 14340-344 24X Fiche 50-295.82/07/30.820Bi30072
- --8208130083 Notice of issuance & availability of Amend 75 to License DPR-39 VARQA,8 A Operating Reactors Branch 1 82/07/30 2pp 14340 346 24X Fiche 50-295,82/07/30,8208130072
- 820Bi300iB Application to amend Licenses DPR-39 & DPR-48, changing frequency at which reactor protection & engineered safeguard instrumentation must be functionally tested LENTINE, F9 Commonwealth Edison Co 82/08/05 DENTON, HR Office of Nuclear Reactor Regulation, Director App 14335 082 24X Fiche 50-275, 82/08/05,820Bi300iB
- --B20B130023 Proposed Tech Spec Tables 3 1 2, 4 1-1 & 3 4-2 re functional testing of reactor protection & engineered safety instrumentation Commonwealth Edison Co B2/08/05 7pp 14335 086 24X Fichs 50-295, 82/08/05. B20B13001B
- 8208130166 Application for amend to Licenses DPR-39 & DPR-48, changing Tech Spec 3 2 3 re control rod sys operability LENTINE, F O Commonwealth Edison Co 82/08/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14339 015 24X Fiche 50-275,82/08/05,8208130166
- --B208130172 Proposed changes to Tech Spec 3 2 3 re control rod sys operability * Commonwealth Edison Co 82/08/05 4pp 14339 017 24X Fiche 50-295,82/08/05,8208130166
- 820811018H Forwards revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 21 Revised pages correct typographical & other minor errors ENARTZ.E Commonwealth Edison Co 82/08/06 HAASB.W P Quality Assurance Branch 1p 14314 079 24X Fiche 50-000,82/08/06,820811018B
- --8208110204 Revised pages to CE-1-A.Revision 21. "Comm Ed QA Program for Nuclear Generating Stations" * Commonwealth Edison Co 82/06/06 11pp 14314 080 24X Fichs 30-000, 82/09/06.8208110188

- B20B070174 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D O Division of Licensing 62/08/09 Consolidated Edison Co of New York ip 14356 332 24% Fiche 50-000,82/08/09,8208070174
- 8208250137 Forwards add1 info re diesel generator outages for 1976-81, per Franklin Research Ctr 820628 request & NUREG-0737, Item II K 3 17, "ECCS Outage Rept" LENTINE, F G Commonwealth Edison Co 82/08/16 EISENHUT, D O Division of Licensing 21pp 14541 309 24X Fiche 50-275,82/08/16,8208250137
- 8208240305 Bubmits updated schedule for submittal of add1 info recontainment purge valve operability Program scheduled for Fell 1982 completion Summary of stress values calculated by hand encl LENTINE.F O Commonwealth Edison Co 82/08/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 14527,197 24X Fiche. 50-293,82/08/19,8208240305

Q Inspection reports, IE Bulletins & correspondence

- 8208050414 Forwards IE Insp Repts 50-237/81-39, 50-249/81-32, 50-234/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-27 on BiO813-820503 No noncompliance noted XEPPLER, J Q Region 3, Office of Director 82/07/12 REED, C. Commonwealth Edison Co ip 14217 166, 24X Fiche 50-000, 82/07/12, 8208050414.
- --B20B050441 IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 on 810813-B20503 No noncompliance noted Major areas inspected, allegations re Comm Ed operation of facilities & compliance w/10CFR21 HAYES, D W , BRAUND, C , TONQUE, T Division of Project & Resident Programs. B2/07/09 155pp 14217.169, 24X Fiche 50-000, B2/07/12:8208050414
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDANIEL Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co. of New York 87pp. 14356 274 24X Fichs 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl UDRDAN.E L Division of Engineering & Guality Assurance 82/07/19 Michigan. Univ. of 112pp 14358 001 24X Fiche.50-000.82/07/19, 8204210395.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Syc list and I JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co of New York 112pp 14381.001, 24X Fiche: 50-000, 82/07/20, 8204210396
- 92042|0397 IE Info Notice 82-24, "Water Leaking From U Hexefluoride Overpacks " Byo list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards. 82/07/20 Consolidated Edison Co of New York 71pp 14357:276 24X Fiche 50-000:82/07/20,8204210397
- B20421039B IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl JORDAN.E L Division of Engineering & Guality Assurance, 82/07/22 Consolidated Edison Co of New York 112pp. 14194;321 24X Fiche 50-000,82/07/22,8204210398
- 8208090231 Forwards IE Insp Repte 50-275/82-11 & 50-304/82-09 on 820510-0625 & notice of violation.
 HIND,J A Division of Emergency Preparedness & Operational Support 82/07/22 REED,C Commonwealth Edison Co. 2pp 14271:105, 24X Fiche 50-295,82/07/22,8208090231
- --8208090236 Notice of violation from insp on 820510-0625 HIND: J. A. Division of Emergency Preparedness & Operational Support 82/07/15, ip 14271.107, 24X Fiche:50-295,82/07/22,8208090231.
- --8209090241 IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820510-0625 Noncompliance noted feilure to follow & maintain emergency response plant to meet stds of 10CFR50.47(b) & to implement plan by 810401 JANUSKA:A Q., AXELBON, W.L. Division of Emergency Preparedness & Operational Bupport 82/07/15 5pp. 14271,10B. 24X Fiche 50-295.82/07/22.8208090231.

- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24% Fiche 50-000: 82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Hestinghouse PWRs " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/23 Consolidates Edison Co of New York 127pp 14194 120, 24X Fiche: 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list enc1
 JORDAN E L Division of Engineering & Quality Assurance, 82/07/26
 Consolidated Edison Co. of New York 121pp 14357 013 24X
 Fiche 50-000 82/07/26 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche, 50-000, 82/07/28, 8204210405
- 8208050490 Forwards response to IE Bulletin 82-02 re bolted connections Visual or surface exams not typically performed on bolting in RCB unless requested No trend of leakage recurrence detected SMARTZ, E. D. Commonwealth Edison Co. 82/07/29, KEPPLER, J. Q. Region 3, Office of Director. 14pp 14214-109 24X Fiche. 50-295, 82/07/29, 8208050490,
- 8208090130 Ack receipt of 820716 ltr informing NRC of steps taken to correct nuncompliance noted in IE Insp Rept 50-295/82-08. NORELIUS, C E Division of Project & Resident Programs. 82/08/04, REED.C. Commonwealth Edison Co. 1p. 14269 342 24X Fiche 50-295/82/08/04/8208090130.
- --B208090132 Responds to NRC 820618 ltr re noncompliance noted in IE Insp Rept 50-295/82-08 Corrective actions, station procedure will be written to govern control of personnel, tools & equipment entering RCS & steam generating channel heads DELOCORCE, O Commonwealth Edison Co 82/07/16 KEPPLER, J. Q. Region 3, Office of Director. 4pp 14269 343 24X Fiche 50-295,82/08/04,8208090130.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance. 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche. 50-000, 82/08/05, 8204210407
- 8208130163 Forwards remittance of civil penalties imposed in connection w/IE Insp Rept 50-295/82-09 re 820325 personnel overexposure.

 LEE.B. Commonwealth Edison Co 82/08/09 DEYOUNG.R C. Director's Office. Office of Inspection and Enforcement ip. 14333 148. R4X Fiche: 50-295.82/08/09.8208130163
- --8208130262 Responds to NRC 820707 ltr re-violations noted in IE Insp. Rept 50-275/82-09 concerning circumstances surrounding averexposure received by worker during entry beneath reactor vessel on 820325

 LEE,8 Commonwealth Edison Co. 92/08/09, DEYCKNO,R C. Director's Office, Office of Inspection and Enforcement 8pp. 14333 149 24X Fiche. 50-295, 82/08/09, 8208130163.

R. Pariodic operating reports & related correspondence

- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A. FELTON. J. M. Division of Rules and Records. 82/07/13 UDELL, R. A. Critical Mase Energy Project Bpp 14679. 208 24X Fiche 50-000. 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVBI."

 + NRC No Detailed Affiliation Given 82/07/13 48pp 14679:216. 24X Fiche: 50-000, 82/07/13.8208270010.
- --BR08270559 Forwards "Recorded Annual Whole Body External Exposure for CYB1," per 10CFR20, 407(b) W/o Qued Cities, Zion, LeBalle, Byron & Braidwood repts.

 RAUSCH, T. J. Commonwealth Edison Co. 82/03/31. Office of Hangement and Program Analysis. 1p 14680:075 24X Fiche: 50-000, 82/07/13, 8208270010.
- 820B130103 Forwards monthly operating repts for Jul 1982, ORAEBSER, K. Commonwealth Edison Co 82/08/06 Director's Office: Office of Inspection and Enforcement. 1p. 14335;340. 24X Fichs 80-295,82/08/06.8208130103.

- --8208130106 Monthly operating repts for Jul 1982 COOK, J. Commonwealth Edison Co. 82/08/06 lipp 14335 341 24X Fiche 50-295,82/08/06.8208130103
- S Reportable occurrences, LERs & related correspondence
- 8208050233 Forwards LER 82-022/03L-0 GRAESSER, K L Commonwealth Edison Co β2/07/28 KEPPLER.J G Region 3. Office of Director 1p 14209 294 24X Fiche 50-295. 82/07/28, 8208050233
- ---B208050236 LER 82-022/03L-0 on B20709, low pressure & high flow alarms received on Zone 1 of panetration pressure system to leak in rupture disc on Zone 1 Caused of failure unknown Rupture disc replaced GLOVER, J Commonwealth Edison Co B2/07/28 Region 3, Office of Director 1p 14209 275 24X Fiche 50-275, 82/07/28.
- 8208050310 Forwards LER 82-023/03L-0 QRAEBERR,K L Commonwealth Edison Co 82/07/28 KEPPLER,J 9 Region 3. Office of Director 1p 14237 323 24X Fiche 50-275,82/07/28,8208050310
- --B208050322 LER 82-023/03L-0 on 8207i3, during normal operation, component cooling supply valve to pump oil cooler & seal glate isolated Cause unknown Component cooling alignment procedure changed to require complete lineup check BINOGELI.B L Commonwealth Edison Co 82/07/28 Region 3, Office of Director ip. 14237 324 24% Fiche 50-275.82/07/28, 8208050310
- DOCKET 50-296 BROWNS FERRY NUCLEAR FOWER STATION. UNIT 3

 F. Security, medical, emergency & fire protection plans
- 8207060127 Forwards response to Section III 0 of App R to 10CFR50 refire protection plan MILLB,L M Tempessee Velley Authority 82/06/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 202pp 13712-142 24X Fiche 50-259,82/06/30,8207060127
- 8207120070 Releases public version of revision to State of AL radiological emergency response plan FELTON, J H Division of Rules and Records 82/07/06 Document Hanagement Branch. 1p 13829 312 24X Fiche 50-259, 82/07/06, 8207120070
- ---B207120078 Forwards public version of Revision BFN-REP-82-003 to State of AL radiological emergency response plan.constituting App F to Browns Ferry radiological emergency response plan MILLS.L M Tennessee Valley Authority B2/06/23 DENTON..H R Office of Nuclear Reactor Regulation, Director 2pp 13829 314 24% Fichs 50-257.82/07/06.8207120070
 - B207120083 Public version of Revision BFN-REF-82-003 to State of AL radiological emergency response plan, constituting App F to Browns Ferry radiological smergency response plan * Tennessee Valley Authority 82/06/16 92pp 13829 316 24X Fiche 50-259, 82/07/06, 8207120070
 - @090046 Forwards revisions to physical security plan Revisions (ithheld (ref 10CFR73 21) (ILLS,L M Fannesse Valley Authority 02/07/22 DENTON, H R Utfice of Nuclear Reactor Regulation, Director ip 14270 035 24X Fiche 50-259, 82/07/22, 8208090046
 - OBIIO219 Releases public version of revised smergency plan implementing procedures "ELTON, J H Division of Rules and Records. 82/08/04, Document tanagement Branch. 1p 14318 084. 24X Fiche 50-259,82/08/04, 3208110219
 - 3208110221 Forwards public version of revised emergency plan implementing procedures including Procedures IP-2 renotification of unusual event.IP-4 re site emergency & IP-5 re general emergency 8LIDER: E K Tennessee Valley Authority 82/07/16, NRC No Detailed Affiliation Diven lp 14318-087, 24X Fiche 50-259,82/08/04.820810219
 - B20Bi10223 Public version of revised emergency plan implementing procedures, including Procedures IP-2 re notification of unusual event, IP-4 re site emergency & IP-5 re general emergency # Tennesses Valley Authority, 82/07/16 i10pp, 14318.088, 24X Fiche 50-259,82/08/04.8208110219

- 8208260338 Releases public version of revised radiological emergency notification directory FELTON.J M Division of Rules and Records 82/08/13 Document Management Branch 1p 14575 275 24X Fichs 50-259, 82/08/13, 8208260338
- --8208260343 Forwards public version of Revision 5 to radiological emergency notification directory Receipt form encl HILLS,L M: SLIGER,E K Tennessee Valley Authority 82/08/04 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 14575 276 24% Fiche 50-259,82/08/13,6208260338
- --8208260346 Public version of Revision 5 to radiological emergoncy notification directory * Tennessee Valley Authority 82/08/03 32pp 14575 278 24X Fiche 50-259, 82/08/13.8208260338
- 8208230351 Forwards add1 info on implementation of App R. Item III J re emergency lighting.per DB Vassallo 820622 ltr to HO Parris Schedule for item also contained in LM MIIIs 820715 ltr KAMMER.D 8 Tennesse Valley Authority 82/08/17 DENTON,H R Diffice of Nuclear Reactor Regulation, Director 2pp 14508 283 24X Fiche 50-295,82/08/17.8208230331
- B208230331 Notifies that add1 info re post-accident sampling facility & response schedule requested 820713 will be provided by 821115
 MILLB:L M Tennesses Valley Authority 82/08/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 14508 325 24x Fiche 50-259, 82/08/18, 8208230331
- Q Adjudicatory correspondence
- 8208270270 Informs that LBP-82-50 accepted for referral by ASLAB & remanded for reconsideration in ALAB-687 RAWSON:R J Hearing Branch 4, 82/08/25 CHILK:S J Office of the Secretary of the Commission 3pp 14563 088 24X Fich
- I Financial information
- 8208100002 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr ending 810630 & "1981 Power Program Summary," for fiscal yr ending 810930, per Section 50 71(b) of 100F850 MILLS, L M Tennessee Valley Authority 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 116pp 14294 024 24X Fiche 50-000, 82/08/06, 8208100002
- 8208270457 Forwards Pinancial statements for FYBI, power quarterly rept & internal cash flow projection HILLS.L M Tennessee Valley Authority 82/08/23 SALTZMAN, J Assistant Director for State & Licensee Relations. 48pp 14566:135 24X Fiche: 50-000, 82/08/23, 8208270457
- J Insurance & indomnity information
- 8208310200 Advises that onsite property damage insurance has been purchased, in accordance #/10CFR50 54 Coverage status encl MILLS.L M Tennesses Valley Authority. 82/08/25 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 14693 160 24X Fiche 50-000.82/08/25.8208310200
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8208170283 Forwards updated FSAR for Browns Ferry Nuclear Plant. Volt 1-7
 MILLB.L M Tennessee Valley Authority 82/08/12 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 14852 001 24X
 Fiche 50-257, 82/08/12, 8208170283
- --B208170293 Updated FSAR for Browns Ferry Nuclear Plant, Vols 1-7
 * Tennessee Valley Authority 82/08/12 3430pp 14852 002 24X
 Fiche 50-259,82/08/12,8208170283
- 8208170275 Chapter 1 to Browns Ferry updated FBAR. "Introduction & Summary."

 * Tennessee Valley Authority 82/08/12 150pp 14852:017 24X Fiche 50-239, 82/08/12, 8208170295
- 8208170297 Chapter 2 to Browns Ferry updated FSAR, "Site "

 * Tennessee Valley Authority 82/08/12, 450pp 14852 202 24X
 Fiche 50~259, 82/08/12, 8208170297
- 8208170299 Chapter 3 to Browns Ferry updated FSAR, "Reactor" * Tennessee Valley Authority 82/08/12 170pp 14853,188 24X Fiche 50-259, 82/08/12, 8208170299,

- 820B170301 Chapter 4 to Browns Ferry updated FSAR, "RCS "
 * Tennessee Valley Authority 82/08/12 170pp 14854 006 24X
 Fiche 50-239,82/08/12,8208170301
- 8208170304 Chapter 5 to Browns Ferry updated FSAR, "Containment " + Tennessee Valley Authority 82/08/12 100pp 14854 150 24X Fiche 30-259, 82/08/12, 8208170304
- 8208170307 Chepter 6 to Browns Ferry updated FSAR, "Core Btandby Coolant Sys "

 Tennessee Valley Authority 82/08/12 75pp 14884 294 24X Fiche 50-259, 82/08/12, 8208170307
- 8208170308 Chapter 7 to Browns Ferry updated FSAR, "Control & Instrumentation"

 * Tennessee Valley Authority 82/08/12 500pp 14855 024 24X F1che 30-259,82/08/12,8208170308
- 8208170310 Chapter 8 to Browns Ferry updated FBAR, "Electrical Power Bys " • Tennessee Valley Authority 82/08/12 275pp 14856 133 24 Fiche 50-259,82/08/12,8208170310
- 8208170311 Chapter 7 to Browns Ferry updated F8AR, "Radwaste Control Sys" # Tennesise Valley Authority 82/08/12 120pp 14857 177 24X Fichs 50-259.82/08/12,8208170311
- 820B170315 Chapter 10 to Browns Ferry updated FSAR, "Auxiliary 8ys" * Tennessee Valley Authority 82/08/12 400pp 14857 177 24X Fiche 50-259,82/08/12,8208170315
- 8208170317 Chapter 11 to Browns Ferry updated FBAR, "Power Conversion Bys" 4 Tennessee Valley Authority 82/08/12 50pp. 14858 059 24: Fiche 50-259.82/08/12,8208170317
- 8208170319 Chapter 12 to Browns Ferry updated FBAR, "Structures & Shielding"

 * Tennessee Valley Authority 82/08/12 200pp 14858:114 24X
 Ficks 50-259,82/08/12,8208170319
- 8208170322 Chapter 13 to Browns Ferry updated FSAR, "Conduct of Operations "

 Tennessee Valley Authority 82/08/12 70pp 14859 039 24X Fiche: 50-257, 82/08/12, 8208170322
- 8208170328 Chapter 14 to Browns Ferry updated FSAR. "Plant Safety Analysis" a Tennessee Valley Authority 82/08/12 120pp 14859 224 24X Fiche 50-259,82/08/12,6208170328
- 820B170333 App A to Browns Ferry updated F8AR, "Conformance to AEC Proposed General Design Criteria"

 Tennesse Valley Authority 82/08/12 22pp 14860 029 24X Fiche: 50-257, 82/08/12, 820B170333
- 8208170336 App B to Browns Ferry updated FBAR, "Tech Bpecs " * Tennesses Valley Authority 82/08/12, 1p 14860 051 24X Fiche: 50-259, 82/08/12, 8208170336
- 8208170339 App C to Browns Ferry updated FSAR, "Btructural Loading Criteria" * Tennessee Valley Authority 82/08/12 81pp 14860 052. 24X Fiche 50-259,82/08/12,8208170339,
- 8208170340 App D to Browns Ferry updated F8AR, "QA Plan for Browns Ferry Nuclear Plant."

 Tennessee Valley Authority 82/08/12 29pp 14860 136 24X Fiche 50-259, 82/08/12. 8208170340
- 8208170375 App E to Browns Farry updated FBAR, "Site Gaseous Release Rate Limit Calculation," • Tennessee Valley Authority 62/08/12, 3pp. 14860,163 24X Fiche 80-297,62/08/12,8208170375
- 8208170377 App F to Browns Ferry updated FBAR, "Unit Bharing & Interactions."

 * Tennessee Valley Authority 82/08/12, 30pp, 14860 166, 24X Fiche 50-259, 82/08/12, 8208170377.
- 8208170379 App Q to Browns Ferry updated FSAR. "Plant Nuclear Bafety Operational Analysis " * Tennessee Valley Authority, 82/08/12 200pp 14860;196. 24X Fichs 50-259.82/08/12,8208170379

- 8208170380 App H to Browns Ferry updated FSAR, "Core Thermal Design "
 * Tennessee Valley Authority 82/08/12 App 14860 347 24X
 Fiche 50-259, 82/08/12, 8208170380
- 8208170382 App I to Browns Ferry updated F8AR, "Identification-Resolution of CP Concerns" * Tennessee Valley Authority B2/08/12 55pp 14860,355 24X Fiche 50-257,82/08/12,8208170382
- 82081703B7 App L to Browns Ferry updated FBAR, "Reactor Pressure Vessel Design Summary Rept-Unit 3." * Tennesses Valley Authority 82/08/12 ip 14861 052 24X Fichs 50-259, 82/08/12, 82081703B7
- 8208170387 App M to Browns Ferry updated F8AR. "Rept on Pipe Failure Outside Containment in Browns Ferry Nuclear Plant " * Tennessee Valley Authority 82/08/12 50pp 14861 053 24X Fiche 50-257.82/08/12,8208170389
- 8208170392 App N to Browns Ferry updated FSAR, "Browns Ferry Nuclear Plant Unit 3 8x8 Fuel Initial Core Loading" " Tennessee Valley Authority. 82/08/12 100pp 14861 096 24X Fiche 50-259, 82/08/12, 8208170392
- P Operating license stage documents & correspondence
- 8208030077 Forwards request for add1 info re NUREQ-0737, Item II D 1, "Testing of Relief & Bafety Valves," in order to complete review of generic test results VASSALLO, D B Operating Reactors Branch 2 82/06/30. PARRIS, H Q. Tennessee Valley Authority 4pp 14200 314. 24% Fiche 50-257, 82/06/30, 8208030077.
- 8208030698 Forwards safety evaluation of proposed method of implementing NUREO-0737, Item II K 3 15. "Isolation of HPCI & Reactor Core Isolation Cooling. "Proposed method acceptable VASBALLO,D B Operating Reactors Branch 2 82/06/30 PARRIS,H G. Tennessee Valley Authority 4pp 14196 321. 24X Fichs 50-257, 82/06/30, 8208030698
- 8207080064 Deneric ltr to all licensees of operating plants, applicants for DL & holders of GP re Commission approved charter for CROR Bvc list encl DIRCKS, H.J. Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp, 14194 ODI, 24X Fichs 50-000, 82/07/02, 8207080064
- B20B040077 Requests data to support conclusion of adequacy space cooling for HCPI & reactor core isolation cooling Response of B11230 unacceptable since no analysis or test data to support conclusion submitted VABBALLO, D. B. Operating Reactors Branch 2 82/07/08. PARRIE, H O Tennessee Valley Authority 2pp 14228 271 24X Ficha 50-259. B2/07/08. B208040077
- 8208040064 Notifies that generic issue re possible diesel generator lockout resolved Operator training program covers subjudged tell. VASSALLO, D.B. Operating Reactors Branch 2. 82/07/15 PARRIB, H.O. Tennessee Valley Authority. App. 14228 280 24X Fiche 50-259.82/07/15,8208040064
- B207270454 Requests extension to B20812 for submittal of updated FBAR MILLB.L.M. Tennessee Valley Authority 62/07/20 DENTON.H. R Office of Nuclear Reactor Regulation. Director. 1p 14061'168 24X Fichs 50-259. B2/07/20.8207270454
- 8208040555 Forwards draft technical evaluation rept. "Control of Heavy Loads." Conference call requested proposed recommendations in rept VASSALLO, D. B. Operating Reactors Branch 2. 82/07/22. PARRIG.H G Tennessee Valley Authority 2pp 14221 150 24X Fiche. 30-259. 82/07/22. 8208040555
- 820Bi10279 Forwards Amends 85,82 & 56 to Licenses DPR-33,DPR-52 & DPR-58 respectively, safety evaluation & notice of issuance & availability Amends consist of clarification & administrative changes & additions to reflect plant mods. CLARK.R. J Operating Reactors Branch 2 82/07/22 PARRIB,H G Tennessee Valley Authority 2pp. 14332 034. 24X Fiche: 50-259,82/07/22,820Bi10279.
- --8208110283 Amends 85,82 % 56 to Licenses DPR-33, DPR-52 % DPR-48, respectively, consisting of clarification & administrative changes & additions to reflect plant mods & reorganization of some Tech Spec sections.

 VABSALLO,D B. Operating Reactors Branch 2. 82/07/22, 128pp 14332 036. 24X Fiche 50-259,82/07/22,8208110279

- --8208110287 Safety evaluation supporting Amends 85,82 % 56 to Licenses PRR-33.PRR-32 & PRR-68, respectively * Office of Nuclear Reactor Regulation, Director 82/07/22 5pp 14332 165 24X Fiche 50-259.82/07/22.8208110279
- --8208110290 Notice of issuance & availability of Amends 85.82 & 54 to Licenses DPR-33,DPR-52 & DPR-68:respectively VASSALLO.D B Licensing Branch 2 82/07/22 2pp 14332 170 24% Fiche 50-259,82/07/22,8208110279
- 8208040643 Requests 820727 meeting in Chattanooga, TN to discuss M81Vs in DHR plants VABSALLO,D B Operating Reactors Branch 2 82/07/23 PARRIS, H G Tennesses Valley Authority 2pp 14224 360 24X Fichs 50-299, 82/07/23, 8208040464
- B208020221 Responds to NRC 820212 request for add1 info re need for chlorine detectors at facilities.per NUREO-0737.
 Item III D 3 4 No threat to control room habitability from chlorine on or off site evident
 MILLS,L M Tennessee Valley Authority 82/07/27 DENTON, H R
 Office of Nuclear Reactor Regulation. Director 2pp 14151 222
 24X Fiche 50-259,82/07/27.8208020221
- 8208120363 Forwards revised version of model Tech Specs re electric power monitoring of reactor protection sys previously submitted in 811030 ltr
 VASSALLO, D 8 Operating Reactors Branch 2 62/07/28 PARRIS, H 9 Tennessee Valley Authority 3pp 14340 079 24% Fiche 50-257, 82/07/28, 8208120363
- 8208130444 Forwards safety evaluation & LLL technical evaluation rept on licensee response to NUREQ-0737. Item II B 1, "RCS Vents" Issue resolved VASSALLO.D B Operating Reactors Dranch 2 82/08/02 PARRIS.H 6, Tennessee Valley Authority 3pp 14354 343 24X Fichs 30-257,02/08/02.8208130444
- --8208130448 "RCB Vents," technical evaluation rept. BUTCHER, E , BARNHART. B Lawrence Livermore Laboratory FIN A-0246-2 82/06/02 Division of Licensing 4pp 14354 346 24% Fiche 50-237,62/08/02,8208130444
- B208090194 Generic Ltr B2-i4 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes IGGFR Chapter I requirements & provides alternatives to requirements Svc list encl EIGENHUT.D 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York. ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208250376 Forwards mechanical snubber qualification test repts for Pacific Scientific Cm Models PSA 1/4 PSA 100, as requested by MRC Only qualifative-type actuation tests planned at plants; baginning w/Browns Ferry 2 & Sequaph 1 MILLS.L H Tennessee Valley Authority 82/08/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14541 002 24X Fiche 50-000,82/08/18,8208250376
 - 208250383 Revision A to "Qualification Test Rept for Model 1801104-09 PSA 1/4 Bhock "
 HHITNEY,R F , QLAUSER, J E , WRIGHT, W 8 Pacific Scientific TR
 837 RA 82/03/18 27pp. 14541.005 24X Fiche 50-000, 82/08/18, 8208250376
- -8208250387 Revision R to "Acceptance Test Procedure IT 527 P/N 1801104 " LEVAN, H C Pacific Scientific 79/11/09 13pp 14541 032 24x Fiche 50-000,82/08/18,8208250376
- -8208250391 "Qualification Test Rept for Model 1801104-07 PSA 1/2 Bhock Arrestor " WHITNEY.R F , GLAUSER.J E , WRIGHT.W B Pacific Scientific TR 840 79/12/12 27pp 14541 045 24% Fiche 50-000.82/08/18, 8208250376
- -9208250402 Revision A to "Gualification Test Rept for Model 1801102-05 PSA 1 Shock Arrestor " WHITNEY.R.F. CLAUSER.J.E., WRIGHT.W 8 Pacific Scientific TR 841 RA 80/03/18 26pp 14541 085 24X Fiche 50-000,82/08/18, 8208250376
- --8208250409 Revision T to "Acceptance Test Procedure IT 519 P/N 1801102" LEVAN; H C. Pacific Scientific 79/06/13 14pp 14541 111 24x Fiche, 50-000, 82/08/18, 8208250376
- B208250415 "Gualification Test Rept for Model 1801106-05 PBA-3 Bhock Arrestor." WHITNEY, R F , GLAUSER, J E , WRIGHT, W. S Pacific Scientific TR 842 80/01/22 27pp 14541.125 24X Fiche: 50-000, 82/08/18,

- --8208230421 Revision R to "Acceptance Test Procedure IT 524 for 1801106 " LEVAN.H C Pacific Scientific 79/02/16 13pp 14541 152 24x Fiche 50-000,82/08/18,8208250376
- --8208250426 "Qualification Test Rept for Model 1801103-07 PSA 10 Shock Arrestor "
 WHITNEY!R F , QLAUSER.J E , WRIGHT.W B Pacific Scientific TR 843 80/01/25 27pp 14541 166 24X Fiche 50-000.82/08/18.
- --B20B250431 Revision R to "Acceptance Test Procedure IT 523 P/N 1801103 " LEVAN,H C Pacific Scientific 79/08/15 14pp 14541 193 24x Fiche 50-000, B2/08/16, B20B250376
- --8208250437 Revision A to "Qualification Test Rept for Model 1801112-11 PSA-35 Shock Arrestor" WHITNEY, R F., GLAUBER, J E., WRIGHT, W S. Pacific Scientific TR 845 RA 80/02/07 30pp 14541 207 24X Fiche 50-000,82/08/18,8208250376
- --8208250441 Revision J to "Acceptance Test Procedure IT 534 P/N 1801112 " LEVAN.H C Pacific Scientific 77/05/10 12pp 14541 237 24x Fiche 50-000,82/08/18,8208250376
- --8208250443 "Qualification Test Rept for Model 1801119-11 PSA-100 Bhock Arrestor " WHITNEY, R F , GLAUSER, J E , WRIGHT, W B Pacific Scientific TR 846 80/05/12 31pp 14541 247 24X Fiche 50-000,82/08/18, 8208250376
- --8208250446 Revision H to "Acceptance Test Procedure IT 533 P/N 1801119 " LEVAN, H C Pacific Scientific 77/04/07 12pp 14541 280 24x Fiche: 50-000, 82/08/18, 8208250376
- Q Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- B204210395 IE Info Notice Bi-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E. Division of Engineering & Quality Assurance B2/07/19 Michigan
- 8204210396 IE Info Notice 92-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/20 Consolidated Edison Co of New York 112pp 143B1 001 24X Fiche 50-000,82/07/20,8204210396
- 82042i0397 IE Info Notice 82-24, "Water Leaking From U Hexafluorida Overpacks " Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 62/07/20 Consolidated Edison Co of New York 7ipp. 1435/ 276 24X Fichs: 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Bvc list encl JCRDAN,E L. Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co of New York. 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- B204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Bupport Pin Failures at Westinghouse PWRs " Svc list encl JORDAN E. L. Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120, 24X Fiche. 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PWR Power Plants," Syc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York. 121pp 14397 013 24X Fichs 50-000, 82/07/26, 8204210403

- E208030582 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-239/82-14, 50-260/82-14 & 50-296/82-14 LEHIS.R C Division of Project & Resident Programs 82/07/26, PARRIS.H O Tennessee Valley Authority 1p 14162 277 24X Fiche 50-259, 82/07/26, 8208030582
- --B20B030592 Responds to NRC B20609 ltr re violations noted in IE Insp Rests 50-259/82-14,50-260/82-14 & 50-296/82-14 Corrective actions-posted signs identifying shield plugs that require presence of health physics personnel for removal XAMHER, D 8 Tennessee Valley Authority 82/07/16 D'REILLY, J P Resion 2. Office of Director 4pp 14162 278 24X Fiche 50-259,82/07/26,8208030582
- --8205030597 Forwards IE Insp Repts 50-259/82-14,50-260/82-14 & 50-296/82-14 on 820303-04 & notice of violation LEMIS,R C Division of Project & Resident Programs 82/06/09 PARRIE,H O Tennessee Valley Authority 2pp 14162 282 24X Fichs 50-259,82/07/26.8208030582
- --8208030402 Notice of violation from insp on 820503-04 * Division of Project & Resident Programs 82/04/09 2pg 14162 284 24% Fiche 50-259, 82/07/26, 8208030582
- --820803D610 IE Insp Repts 50-259/82-14.50-260/82-14 & 30-276/82-14 on 820503-04 Noncompliance noted failure to perform radiation survey after removal of shield plugs & failure to issue permit for removal of demineralizer cell shield plugs PEERY,W W. BARR,K P Division of Engineering & Technical Programs 82/06/02 4pp 14162 286 24X Fichs 50-259.82/07/26, 8208030582
- 8208160395 Forwards 1E Insp Repts 50-259/82-18,50-260/82-18 & 50-296/82-18 on 820626-0725 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/07/26 PARRIS, H G Tennessee Valley Authority, 2pp. 14348 012 24X Fichs 50-259,82/07/26,8208160395
- --8208160408 IE Insp Repts 50-257/82-18,50-260/82-18 & 50-276/82-18 on 820626-0725 No noncompliance noted Major areas inspected. operational safety, ROs, surveillance testing, maint observation, THI action items & independent insp effort CHABE, J W. PAULK, G L. CANTRELL, F B Division of Project & Resident Programs 82/07/26 8pp i4348 014, 24X Fiche 50-259,82/07/26,8208160375
- 82042;0405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Syc list encl "ORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146, 24X Fiche: 50-000, 82/07/28, 8204210405
- 8208160274 Forwards IE Insp Repts 50-259/82-21.50-260/82-21 & 50-276/82-21 on 820628-0702 No noncompliance noted, VERRELLI.D M Division of Project & Resident Programs. 82/07/28 FARRIS.H G Tennessee Valley Authority 2pp 14345:255 24X Fiche 50-259,82/07/28.8208160294
- --8208160311 IE Insp Repts 50-259/82-21, 50-240/82-21 & 50-296/82-21 on 820628-0702 No noncompliance noted Mayor areas inspected, radioactive matl packaging, shipment & processing, posting of notices, housekeeping & instrument calibr COLLINS, T R, DEBS, B T, DARR, K, P Division of Engineering & Technical Programs 8 82/07/22 5pp 14345-257 24X Fiche-50-259,8208160274
- 82081&0484 Ack receipt of 820730 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19 VERELLI.D. Division of Project & Resident Programs, 82/08/03 PARRIS, H G Tennesses Valley Authority ip 14348-104, 24X Fiche 50-259, 82/08/03, 8208140484
- --8208160491 Responds to NRC 820701 ltr re violations noted in It Insp Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19 Corrective actions torus area high radiation rope berrier reinstalled & radiological tape placed on floor KAMERID S Tennessee Valley Authority 82/07/30 0'REILLY, J. P. Repion 2. Office of Director 3pp. 14348:105 24X Fiche 50-259,82/08/03,8208160484
- --8208160498 Forwards IE Insp Repts 50-259/82-19.50-260/82-19 & 50-296/82-19 on 820526-0625 & notice of violation LONG, F J Division of Project & Resident Programs 82/07/01 PARTBJ.H 0 Tennessee Vallsy Authority 2pp, 14348:108 24X Fichs 50-259.82/08/03.8208160484.

- --8208160521 IE Insp Repts 50-259/82-19, 50-260/82-19 k 50-296/82-19 on 820526-0825 Noncompliance noted failure to properly barricade two high radiation areas in torus area CMASE.J W , PAULK, G L , CANTRELL, F 8 Division of Project k Resident Programs 82/06/30 6pp 14348 iii 24X Fiche 50-259, 82/08/03, 8208160484
- 8208160493 Ack receipt of 820720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-15, 50-2260/82-15 & 50-296/82-15 LEMIS.R C Division of Project & Resident Programs 82/08/04 PARRIES
- --8208140502 Responds to NRC B20403 ltr re violations noted in 1E Insp Repts 50-259/82-15,50-240/82-15 & 50-294/82-15 Corrective actions deily monitoring & dealmage program will be continued Violations re Items A & B denied MILLS.L M Tennessee Valley Authority 82/07/20 0'REILLY, J.P. Region 2, Office of Director 7pp 14348 118 24X Fiche 50-259,82/08/04.8208160493
- --8208160515 Forwards IE Insp Repts 50-259/82-15,50-260/82-15 & 50-296/82-15 on 820426-0525 & notice of violation LEMIB.R.C Division of Project & Resident Programs 82/06/03. PARRIS.H Q Tennessee Valley Authority, 2pp 14348 125 24X Fiche. 50-259, 82/08/04, 8208160493
- --92081&0520 Notice of violation from insp on 82042&-0525 * Division of Project & Resident Programs. B2/06/03 2pp 14348 127 24X Fichs 50-259, 82/08/04.8208160493
- ~~B20B16052B IE Insp Repts 50~259/82-15,50~260/82-15 t 50~296/82-15 on 820426-0525 Noncompliance noted written safety evaluation re offgas post-treatment sampling station configuration mod not performed CHASE.JW, PAULX,OL, CANTRELL,F S, Division of Project t Resident Programs 82/06/02 10pp 14348'129 24X Fiche 50-259,82/08/04,820B160493
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/08/05, Consolidated Edison Co of New York 117pp 14388, 201 24% Fiche 50-000, 82/08/05, 8204210407
- R Periodic operating reports & related correspondence
- 820B270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/07/10. UDELL.R A. Critical Mass Energy Project Bpp 14679 208. 24X Fiche 80-000.82/07/10.8208270010
- ---B20B27009B "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVBI" % NRC - No Detailed Affiliation Given, B2/07/13, 4Bpp. 14679 216 24X Fiche.50-000,82/07/13.820B270010
- ---B20B270601 Forwards "Personnel Whole Body Exposures for CVB1," per 10CFR20 407.
 MILLB.L M. Tennessee Valley Authority, 82/03/23 BROOKS, B. O. Licensee Operations Evaluation Branch ip 14680 053 24% Fiche 50-000, 82/07/13, 8208270010
- --B208270605 "Personnel Whole Body Exposures for CY81 "
 * Tennessee Valley Authority B2/03/23 2pp 14680:054, 24X
 Fiche 50-000.82/07/13.8208270010
- 820Bi20226 Forwards monthly operating repts for June 1982 JONES, G. T. Tennessee Valley Authority 82/07/14 Defice of Management and Program Analysis ip 14926.176, 24X Fiche: 50-259, 82/07/14.8208120226.
- --820B1R0233 Monthly operating rapts for June 1982, JDNEB.G.T., THDM.T Tennessee Valley Authority 82/07/14. 39pp. 14326.177. 24X Fiche.50-259,82/07/14.8208120226,
- 8 Reportable occurrences, LERe & related correspondence
- 8208050164 Forwards LER 82-030/03L-0 QREEN.H.J Tennessee Valley Authority 82/07/29. D'REILLY, J.P Region 2. Office of Director. ip. 14212-075. 24X Fiche 50-296, 82/07/29, 8208050164.

- --8208050170 LER 82-030/03L-0 on 820713, flow bias compactor trip initiated Flow bias A drifted from accurate value of 94/ to 100% causing high-flow trip points Caused by proportional amplifier FG-68-5 drifting upscale Amplifier replaced GOODMIN.D C Tennesse Valley Authority 82/07/29 Region 2, Office of Director 2pp 14212 076 24% Fiche 50-296, 82/07/29, 8208050164
- B208050394 Forwards updated LER 81-034/03X-1 QREEN.H.J Tennesses Valley Authority 82/07/29 O'REILLY.JP Region 2. Office of Director 1p 14209 204 24X Fiche 50-296. B2/07/29. B208050394
- --8208050401 Updated LER B1-034/03X-1 on B10709.RHR pump 3C tripped on ground overcurrent Caused by turn-to-turn failure of motor coil in nonconnection end knuckle Motor replaced SOLLEY.8 W Tennessee Valley Authority 82/07/29 Region 2, Dffice of Director 3pp 14209 205 24X Fichs 50-296,82/07/29,8208050394
- 8208100037 PNO-II-82-090 on 820730, w/Unit 2 shutdown for scheduled refueling & mods. Units 1 & 3 failed secondary containment integrity tasts & were shutdown Caused by in-leakage between common refueling tone & three individual reactor zones BUTCHER.R C . VERRELLI.D M Region 2. Office of Director 82/08/05 ip 14296 261 24X Fiche 30-259.82/08/05.8208100037
- 8208200030 Forwards LER 82-032/03L-0 OREEN.H J Tennessee Valley Authority 82/08/12 0'REILLY, J P Region 2, Office of Director 1p 14392 211 24X Fichs 50-296.82/08/12.820820030
- --820820004! LER B2-032/03L-0 on 820722, two degraded voltage relays on 4-tV shutdown boards 3EB & 3ED found to operate above max allowable setpoint Setpoints apparently drifted up due to increased room temp since last calibr Relays recalibr CHRISTOPHER,W Tennessee Valley Authority 82/08/12 Region 2, 0ffice of Director 2pp 14392 212 24X Fiche 50-296,82/08/12,8208200030
- 8208270474 Forwards LER 82-031/031-0 OREEN.H J Tennessee Valley Authority 82/08/12 O'REILLY, J.P. Region 2, Office of Director 1p 14565 337 24X Fiche 50-296, 82/08/12,8200270474
- --8208270488 LER 82-031/03L-0 on 820716, two degraded voltage relay timers on 4-kV SDB 3EC & 3ED found set at 0 26-s Caused by timer setpoints change in 860329 Tech 8pec revision; but not incorparated into 81 4 9 A 4 c Timers recalibr CRRISTOPHER; W Tennessee Valley Authority 82/08/12 Region 2. Office of Director 2pp 14545 338 24X Fiche 50-296,82/08/12, 8208270474
 - 18310097 PNO-II-82-097 on 820819, truck transporting low specific adjoactive math from facility to Richland, WA found to have iquid dripping from truck bed On 820821, drum found to have small holes near base OLLINS.T R Region 2, Office of Director 82/08/24 ip 4695 084, 24X Ficher 50-296, 82/08/24, 8208310097
- JCKET 50-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR
 Inspection reports, IE Bulletins & correspondence
- 204210395 IE Info Notice B1-24, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Sec list encl JURDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan. Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395

DOCKET 50-298 COOPER NUCLEAR STATION

- F Security, medical, emergency & fire protection plans
- 9209240176 Forwards IE Insp Rept 50-278/82-11 & IE Investigation Rept 50-278/82-09 on 820311 & 22-23 & 0315-30. respectively No noncompliance noted COLLING. J T Region 4. Defice of Director 92/08/09 HILL. D. W Nebraska Public Power District 2pp. 14519:268 24X Fiche: 30-278.82/08/09.8208240176
- --B208240179 IE Insp Rept 50-298/B2-ii on 820311 & 22-23 No noncompliance noted Major areas inspected capability of emergency warning sys to notify gopulation promptly JUHNSON,E H, MILBORN,L, MURRAY,B. Region 4, Office of Director B2/04/08 Bpp. 14519 270 24X Fiche: 50-298, B2/08/09, B208240176

- --820B240184 IE Investigation Rept 50-298/B2-09 on 820315-30 No noncompliance noted Major areas investigated apparent math felse statement in util 82020B itr to NRC re status of facility compliance w/10CFR App E MATAKAS, R A , HACKNEY, C A , MADSEN, G L. Region 4, Office of Director 82/05/17 19pp 14519 27B 24X Fiche 50-298,82/08/09,8208240176
- 8208310441 Discusses IE insp on 820311 & 22 & forwards notice of violation & notice of proposed imposition of civil penalty DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/08/09 KASMAN.H B Nebrask
- --8208310446 Notice of violation & notice of proposed imposition of civil penalty in amount of \$300,000 Noncompliance noted licensee had not demonstrated that administrative & physical means had been established for alerting public during emergency DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/08/09 3pp. 14697 332 24X Fiche 50-298,82/08/09.8208310441
- --B20B310452 Order modifying license effective immediately Licensee sholl submit to Region 4 for review & approval, camprehensive plan of action including independent apprecial of site & corporate mgt organizations & functions within 30 days DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/08/09 Nebraska Public Power District Upp 14697 335 24X Fiche 50-298, B2/08/09, B208310441
- 8208240437 Ack receipt of 820725 ltr w/entl Emergency Plan Implementing Procedure 5 7 27, "Early Waining Sys " Procedure under review MADBEN.O L. Division of Resident, Reactor Project & Engineering Programs 82/08/13 PILANT, U M. Nebreska Public Power District ip 14326 361 24X Fishe 80-298.82/08/1/3.8208240437
- --8208240438 Forwards Emergency Plan Implementing Procedure 5 7 27, Revision 1, "Early Warning Sys " W/o encl PILANT.J M Nobraske Public Power District 82/07/26 CGLLINS.J T Region 4, Office of Director 1p 14526-362 24X Fiche 50-298.82/08/13.8208240437
- 8208310130 Forwards IE Safeguards Insp Rept 50-298/82-17 on 820628-0702 No noncompliance noted Rept withheld (ref 10CFR2 790)
 MADSEN. 6 L Division of Resident, Reactor Project & Engineering Programs 82/08/27, PILANT, J M Nebraska Public Power District 2pp 14695 128 24% Fiche 50-298/82/08/27, B208310130
- G Adjudicatory correspondence
- 8208110155 Statement of Commission directing NRC to issue notice of violation & order imposing civil penalties on licenses for failure to complete prompt public notification sys by 820201 & for three matl false statements re on-line status CHILK, S. J. Office of the Secretary of the Commission 62/08/07 7pp 14314 274 24X Fiche 50-278,82/08/09,8208110155
- 1 Financial information
- B208020106 Forwards info demonstrating ability to obtain funds of \$10 million for payment of deferred premiums PILANT, J M Nebraska Public Power District B2/07/28 Office of Nuclear Reactor Regulation, Director B7pp 14142 117 24% Fiche 50-298, 82/07/28, 8208020106
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicante for OL & holders of CP re Commission approved charter for CRGR. Svc 11st encl
 DIRCKS, M J Office of the Executive Director for Operations, 82/07/02 Consolidated Edison Co of New York 93pp 14194 OOI 24X Fichs 50-000,82/07/02,8207080064
- B208020442 Forwards safety evaluation finding util 810630 response to NUREO-0737. Item II K 3 24 re adequacy of space cooling for HPCI & reactor core isolation cooling sys acceptable VABBALLO.D B Operating Reactors Branch 2 82/07/08 PILANT, J. H Nebraska Public Power District. 3pp 14181, 041 24X Fiche. 50-298, 82/07/08. 8208020442
- 8208160297 Forwards revisions to 820224 P&ID list FILANT, J M Nebraska Public Power District 82/07/27 COLLING, J T. Region 4. Office of Director 3pp 14346 276 24X Fiche:50-298,82/07/27,8208160297

- 2208020126 Forwards revised Tech Specs updating 800805 submittal re single loop operation PILANIJM Nebraska Public Power District 82/07/28 VASSALLO.D B Operating Reactors Branch 2 2pp 14142 076 24X Fiche 50-298,82/07/28,8208020126
- -- P208020129 Revised Tuch Specs re single loap operation * Nebraska Public Power District 82/07/28 26pp 14142 078 24X Fiche 50-298,82/07/28,8208020124
- 9200240435 Forwards safety evaluation supporting conclusion that proposed method for implementing guidance of NUREG-0737, team II K 3 15, "Isolation of HPCI & RGIC." acceptable Item
- canaldered resolved VASSALLO, D.B. Licen canaldered resolved VASSALLO, D.B. Licensing Branch 2 82/08/03 PILANT, J.H. Nebraska Public Power District 3pp 14544 177 24X Fiche 50-298, 82/08/03, 8208240435
- \$209090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Bummaries 10CFR Chapter I requirements & provides alternatives to requirements Svc list enci EISEN#UT.D 9 Division of Licensing 82/08/09 Consolidated EffeN#UT.D 9 Division of Licensing 82/08/09 Consolidated 82/
- 2002200088 Informs that due to terminations of 6 senior licensed operators, overtime being used to regularly fill 3 positions on regular reactor operator crews Crew shifting necessary in order to properly train license candidates.

 PILANI, J. M. Nebraska Public Power District 62/08/13, VASSALLO, D.B. Operating Reactors Branch 2 2pp 14393 245

 Fiche 50-298,82/08/13,8208200088
- 8208270340 Responds to 820708 request for info re Cycles 7 & 8 operating limit min critical power ratio Util has been informed by 9E that decrease is result of normal cycle-to-cycle differences & not correction in ODYN code FILANT, J M Nebraska Public Power District. 82/08/20 WASSALLO, D B Operating Reactors Branch 3 lp 14565 105. 24X Fiche 50-278,82/08/20,8208270340
- 2003:10386 Requests that 820930 order date for completion of Mark I containment program mods be changed to Spring 1983 refueling outage to complete remaining work on torus temp monitoring
- eys. FILANT, J M Nebraska Public Power District. 82/08/23 VASBALLD. D B Operating Reactors Branch 2. 2pp 14692 111. 24X Ficha 50-298,82/08/23,8208310386
- 1 Inspection reports. IE Bulletins & correspondence
- 204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN:E L Division of Engineering & Guality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000,82/07/16,8204210393
- 8204210395 JE Info Notice 81-26, Part G. Suppl 1. "Clarification of Placement of Personnel Monitoring Davices for External Radiation." Svc Jist entl JORDANIE L Division of Engineering & Guality Assurance 82/07/19 Nichigan. Univ of 112pp. 14358 001 24% Fiche 50-000.82/07/19, 8204210395
- 8204210395 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/20, Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc fist encl COBB.L I. Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14387; 2 24X Fiche 50-000,82/07/20,8204210397
- 2204210398 IE info Notice 82-26, "RGIG & HPGI Turbine Exhaust Check Valve Failures " Byc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22, Compositated Edison Co of New York 112pp 14194 321 24X F1fitte:50-000 82/07/22, 8204210398
- \$204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Visinity of Drained & Open RCB." Svc list encl JORDANIE L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380,115, 24X Fishe 30-000,82/07/23,8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidates Edison Co of New York 127pp 14174 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8208160465 Forwards IE Insp Rept 50-298/82-17 on 820621 No noncompliance noted MADBEN.O L Division of Resident. Reactor Project & Engineering Programs 82/07/23 PILANT.J M Nebraska Public Power District 2pp 14349 283 24X Fichs 50-298.82/07/23.8208160465
- --8208160470 IE Insp Rept 50-298/82-17 on 820621 No moncompliance noted Major areas inspected followup insp of C-E reactor vessel stud evaluation TAPIA.J I. WESTERMAN.T F, HUNNICUTT.D H Division of Resident, Reactor Project & Engineering Programs 82/07/22 3pp 14349 285 24X Fiche 50-298,82/07/23.8208160465
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance. B2/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " 8vc list encl. JORDANIE L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208190292 Forwards IE Insp Rept 50-298/82-18 on 820622-24 No noncompliance noted MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/08/02 PILANT, J M Nebraeka Public Power District 2pp 14387 109 24X Fiche 50-298, 82/08/02, 8208190292
- --8208190293 IE Insp Rept 50-298/82-18 on 820622-24 No noncompliance 208190293 IE Insp Rept 50-298/82-18 on 820622-24 No noncompliance noted Major areas inspected licensee action on previously identified items & review of insp & repair activities rereplacement of degraded pipe in reactor water cleanup sys. GILBERT, L D , WESTERMAN, T F , HUNNICUTT, D H Division of Resident, Reactor Project & Engineering Programs 82/07/28 5pp 14387 111 24X Fiche 50-298,82/08/02.8208190292
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN: E.L. Division of Engineering & Quality Assurance 82/08/03 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche: 50-000, 82/08/05, 8204210407
- 8208100033 EN-82-028 on 820809, notices of violation & proposed .
 imposition of civil penalty & order modifying license
 effective immediately issued to licensee
 LIEBERHAN. J. DEYOUNG, R. Director's Office, Office of Inspection and
 Enforcement 82/08/09 ip 14296,273. 24X Fichs 50-298,82/08/09, 8208100033
- 8208240176 Forwards IE Insp Rept 50-298/82-11 & IE Investigation Rept 50-298/82-09 on 820311 & 22-23 & 0315-30, respectively No noncompliance noted COLLINS.J.T Region 4. Office of Director. 62/08/09 HILL.D W. Nebraska Public Fower District 2pp 14519 268 24X Fichs 50-298, 82/08/09, 8208240174
- --8208240179 IE Insp Rept 30-298/82-11 on 820311 & 22-23 No noncompliance noted Major areas inspected capability of emergency warning sys to motify population promptly JOHNBON,E H, MILBORN,L, MURRAY,B Region 4, Office of Director 82/04/08, Spp. 14519.270 24X Fiche 50-298,82/08/09,8208240176,
- --8208240184 IE Investigation Rept 50-298/82-09 on 820319-30. No noncompliance noted Mejor areas investigated, appearent matifalse attacement in util 820208 Ifor to NRC re status of facility compliance w/100FR App E
 MATAKAB:R A , HACKNEY,C A , MADSEN,O L Region 4, Office of Director 82/05/17 19pp, 14519, 278, 24X Fiche: 50-298, 82/08/09, 8208240176
- B20B310441 Discusses IE insp on B20311 & 22 & forwards notice of violation & notice of proposed imposition of civil penalty. DEYOUND.R.C Director's Office. Office of Inspection and Enforcement B2/08/07 KASMAN.H B. Nebraska Public Power District. Spp 14697: 327. 24% Fiche. 50-298.B2/08/09.B20B310441
- --8208310446 Notice of violation & notice of proposed imposition of civil penalty in amount of \$300.000 Noncompliance noted: licensee had not demonstrated that administrative & physical means had been established for alerting public during emergency DEYOUNO, R. C. Director's Diffice, Office of Inspection and Enforcement, 82/08/09 3pp. 14697 332 24X Fichs, 50-298,82/08/09,8208310441.

- --8208310452 Order modifying license effective immediately Licensee shall submit to Region 4 for review & approval comprehensive plan of action including independent appraisal of site & corporate mgt organizations & functions within 30 days DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/08/09 Nebraska Public Power District Bpp 14697 335 24% Fiche 50-298,82/08/09,8208310441
- ## 8208270471 Forwards IE Insp Rept 50-298/82-15 on 820706-09 No noncompliance noted ### MADSEN, O L. Division of Resident, Reactor Project & Engineering Programs 82/08/10 PILANT, J.M. Nebraska Public Power District 2pp 14564 047 24X Fiche. 50-298, 82/08/10, 8208270471
- --B20827047B IE Insp Rept 50-298/82-15 on 820706-09 No noncompliance noted Major areas inspected organization & administration calibr & fire prevention UAUDON.JP, MURPHY.M E. WESTERMAN.TF Division of Resident, Reactor Project & Engineering Programs 82/08/06 App 14564 049 24% Fiche 50-298.82/08/10,8208270471
- 8208240216 Forwards errata to IE Insp Rept 50-298/82-09,containing Exhibits 1-2: MADSEN.Q L. Division of Resident, Reactor Project & Engineering Programs 82/08/19 PILANT,J M Nebraska Public Power District 1p 1452: 11: 24X Fiche 50-298,82/08/19,8208240216
- ---8208240223 Errata to IE Insp Rept 30-298/82-09, containing Exhibits 1-21. MADBEN, O L Division of Resident, Reactor Project & Engineering Programs 82/08/19 53pp 14521 II2 24X Fiche 50-298/82/08/19, 8208240216
- 8208310130 Forwards IE Safeguards Insp Rept 50-298/82-19 on 820628-0702. No noncompliance noted Rept withheld (ref 10CFR2.790)
 MADSEN.O L. Division of Resident, Reactor Project & Engineering Programs. 82/08/27 PILANT, JM Nebraska Public Power District 2pp 14695:128 24X Fiche 30-298.82/08/27.8208310130
- R. Periodic operating reports & related correspondence
- 8208120040 Forwards monthly operating rept for June 1982 LESSOR.L. C Nebraska Public Power District 82/06/29 Hanagement Information Branch 1p 14323.351 24X Fiche: 50-298, 82/06/29, 8208120040.
- --8208120042 Monthly operating rept for June 1782
 BALLINGER, B L. Nebraska Public Power District 82/06/29. 4pp
 14323,352. 24X Fiche 50-298,82/06/29,8208120040
- 9209270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear your plants & analyting said info Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fiche. 50-000. 82/07/13. 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBI." * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24% Fiche 50-000:82/07/13.8208270010
- --B208270182 Forwards "Personnel Whole Body Exposures for CYB1," per. 10CFR20 407(a) & (b) LEBBOR.L.C. Nebraske Public Power District B2/01/29 Office of Hanagement and Program Analysis 1p 14679 271 24X Fichs: 50-000, 82/07/13, 8208270010
- --8208270185 "Personnel Whole Body Exposures for CY81" * Nebraska Public Fower District 82/01/29 ip 14679 272 24X Fiche: 50-006, 82/07/19, 8208270010.
- S. Reportable occurrences: LERs & related correspondence
- 8208100277 Forwards noncompliance rept submitted on 820803 to NE Dept of Environ Control, Max temp of 103.5 F experienced on 820725 while circulating water pump A was removed from svc COOPER.1. J Nebraska Public Power District. 82/08/03 IPPOLITO, T A Operating Reactors Branch 2 2pp. 14277:068. 24X Fiche: 50-298, 82/08/03, 8208100277
- 8208160173 Forwards LER 82-015/03L-0 Detailed event analysis submitted LEBSOR.L.C Nebraska Public Power District 82/08/05 COLLING.J T Region 4. Office of Director. 4pp 14345.116 24X Fiche:50-298, 82/08/05.8208160173

- --8208160176 LER 82-015/03L-0 on 820706, eleven penetrations leaked excessively during leak rate test Cause not stated Valve repairs performed on anchor gates, globes & checks Anchor 6 gate valve replaced Final leakage within limit MOLKEN, M A Nebraska Public Power District 82/08/05 Region 4, Office of Director ip 14345 120 24X Fiche 50-298, 82/08/05, 82/08160173
- 8208200103 Forwards LER 82-016/03L-0 Detailed event analysis submitted LESSOR.L C Nebraska Public Power District 82/08/10 COLLING.J T Region 4. Office of Director 2pp 14399 153 24X Fiche 50-298.82/08/10,8208200103
- --8208200109 LER 82-014/03L-0 on 820712, diesel generator tripped w/no alarms or indications Redundant sys operable Caused by drift in holding mechanism of safety trip valve overspeed device Valve & section of control air line replaced FLAHERTY, J. R. Nebraska Public Power District 82/08/10 Region 4. Office of Director ip 14397 155 24X Fiche 50-298.82/08/10, 8208200103
- 8208200166 Forwards LER 82-017/03L-0 Detailed event analysis submitted LESSOR, L C Nebraska Public Power District 82/08/10 COLLING, J 7 Region 4. Office of Director 2pp. 14394 022 24X Fiche 50-298, 82/08/10, 8208200166
- --8208200176 LER 82-017/03L-0 on 820713, at completion of overspeed test on dissel generator 2, dissel tripped before loading Caused by low lube oil pressure switch Switch replaced FLAHERTY, J. R. Nebraska Public Power District 82/08/10 Region 4, Office of Director 1p 14394 024 24X Fiche 50-298, 82/08/10, 8208200166
- 8208240369 Forwards LER 82-019/03L-0 Detailed event analysis submitted LESSDR.L C Nebraska Public Power District 82/08/13 CDLLINS, J T Region 4. Office of Director 2pp 14522 347 24X Fiche 30-298,82/08/13,8208240369
- --8208240380 LER 82-019/03L-0.on 820726, drywell equipment sump 10 high level alarm w/subsequent automatic pump operation observed Caused by blown fuse in power supply 20-545A for flow recorder & flow integrator. Fixe replaced KRAUSE, R W Nebraska Public Power District 82/08/13 Region 4, Office of Director 1p 14522 347 24X Fiche 50-298,82/08/13,8208240349
- DDCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- B20B0402B3 Releases public version of revised emergency plan implementing procedures FELTON.J.H Division of Rules and Records B2/07/20 Document Hanagement Branch ip 14231 001 24X Fiche 50-246.82/07/20.
- ---82080402BB Forwards public version of revised emergency plan implementing procedures, including Procedures EP 1 3 reestimation of source term.EPIP 3 1 re alert immediate actions & EPIP 4.1 re site emergency immediate actions FAY, C W Hisconsin Electric Power Co. 82/07/09 DENTON, H R Office of Nuclear Reactor Regulation, Director, CLARK, R A Operating Reactors Branch 3 4pp 14231 002 24X Fiche 50-266, 82/07/20, 8208040283
- --8208040293 Public version of revised emergency plan implementing procedures, including Procedures EP 1 3 re estimation of source term. EPIP 3 1 re elect immediate actions & EPIP 4 1 re site emergency immediate actions & EPIP 4 1 re site emergency immediate actions & Fisconsin Electric Power Co 82/06/25 54pp 14231 006 24x Fiche: 30-266, 82/07/20, 8208040283
- 8208190188 Forwards revisions to security force training & qualification plan as requested in 820715 ltr Revision withheld (ref 100FR2 790)
 BURSTEIN:6 Wisconsin Electric Power Co 82/08/06 CLARK:R A Operating Reactors Branch 3. ip 14387 048. 24X Fichs. 30-266:82/08/06.8208190188
- 8208190224 Advises that scheduling conflicts & reluctance of State of NI to participate in annual emergency exercise during Summer 1983, support util 820630 request for exemption from 10CFR App E Exercise scheduled for 830920 FAY, C W. Wisconsin Electric Power Co. 82/08/09 DENTON, H R Office of Nuclear Reactor Regulation. Director, CLARK, R A. Operating Reactors Branch 3, 3pp. 14387 177. 24% Fiche. 50-266, 82/08/09, 8208190224

- 8208260531 Ack receipt of 820719 ltr re emergency operations facility Ceviations from physical proximity guidelines to plant site event be approved by NRC COLBURN: T. G. Operating Reactors Branch 3 82/08/11 FAY.C W. Hisconsin Electric Power Co. 2pp. 14572 337 24X Fiche 30-266,82/08/11,8208260531
- 8208260054 Releases public version of emergency plan manual FELTON, J M Division of Rules and Records 82/08/13 Document Management Branch ip 14574 078 24% Fiche 50-266,82/08/13, 8208260054
- -- 2208260059 Forwards public version of emergency plan manual, including revisions to Procedures EP 2 O re emergency plan definitions. EP 4 O re emergency emergency measures EURSTEIN.5 Misconsin Electric Power Co 62/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 5pp 14574 079 24X Fichs 50-266, 62/08/13, 6206260054
- --8208250057 Public version of emergency plan manual including revisions to Procedures EP 2 0 re emergency plan definitions, EP 4.0 re emergency conditions & EP 6 0 re emergency measures.

 Wisconsin Electric Power Co 82/07/30 250pp 14574 084 24X Fichs 50-256, 82/08/13, 8208250054

@ Adjudicatory correspondence

- 8208110180 Responds to ASLB Bil013 memorandum & order re removal of alglosive or mechanical plugs from tubes prior to sleaving Supporting documentation & DM Porter affidavit and CHURCHILL. B H , RIDGWAY, D A Wisconsin Electric Power Co. CHURCHILL. B W Shaw, Pittman, Potts & Troubridge Bi/10/16 30pp 14314 141 24X Fiche 50-266, 81/10/16, 8208110180
- BCG100031 Advises that NRC will not respond to licensee B20722 motion to conduct discovery of WI Environ Decade to Decade contacts w/sleeving demonstration program workers BACHMANN, R.O. Hearing Branch 1 B2/08/06 BLOCH, P.R., PAXTON, H.C., XLING, J.R. Atomic Bafety and Licensing Board Panel ip 14296:274, 24% Ficha 50-266,82/08/06,8208100031
- 8208100076 Response to interrogatories re-safety evaluation on full-scale sleeving Certificate of Svc encl BACHEANNIR © Hearing Branch 1 82/08/06 Wisconsin's Environmental Decade 17pp 14296-157, 24X Fiche 50-266-82/08/06, 82/08/00076
- 8208270315 Forwards licensee response to MI Environ Decade motion re litigable issues & MD Fletcher statement Proprietary versions served on NRC & Decade Nonproprietary version served on remainder of svc list CHURCHILL.B Bhaw, Pittman. Potts & Troubridge CHURCHILL.D Miscensin Electric Power Co. 82/08/09 BLUCH.PB., KLINE.J R., PAXTCM,H C Atomic 8afety and Licensing Board Panel 2pp 14363 207 24X Fiche 50-266,82/08/09,8208270315
- --B208270319 Response to WI Environ Decade 820720-21 motion concerning Litigable issues Decade estopped from raising number of proposed contentions Decade Fails to justify untimeliness. Some proposed issues irrelevant CHURCHILL, B. W. Hisconsin Electric Power Co. CHURCHILL, B. W. Bhau. Pittman. Potts & Troubridge 82/08/09 Atomic Bafety and ticensing Board Panel 71pp 14563 209 24X
 Fiche 50-266.82/08/09.8208270315
- 8208120009 Forwards PO Easley affidavit of preparation of response to WI Environ Decade Interrogatory 2 Affiant not available to sign affidavit in time to meet 820806 filing deadline BACHMANN, RO Hearing Branch 1 62/08/10, BLOCH, P.R., PAXTON, H.C., FLINE, J.R., Atomic Safety and Licensing Board Fanel, 2pp 14323:337, 24X Fiche 50-266,82/08/10,8208120009
- 8208160219 Informs of 820809 telcon w/PR Bloch re Nucleonics Wk 820805 article, "Utils Given NRC Laundry List of Steam Generator Progosals" Author informed Bloch on 820810 that NRC will not provide info on article due to preliminary nature, BACHMANN, R 0 Hearing Branch I. 82/08/12, BLUCH, P R , KLINE, J, R., PAXTON, H C Atomic Safety and Licensing Board Panel 5pp. 14342 330 24X Fiche 50-266,82/08/12,8208160219.
- 8208180118 Response to WI Environ Dacade 820721 motion concerning 18tigable issues. Contentions 1-5 & alternative contention on interrelationship w/thermal shock Only Contentions 3(a) & 3(b) admissible Notice of appearance encl. 8ACHMANN.R 9. MCQURREN.H J. Hearing Branch 1. 82/08/16 Atomic Safety and Licensing Board Panel. 36pp 14378:203. 24X Fiche: 30-266, 82/08/16, 8208180118.

- --B20B1B0123 Statement of matl fact as to which there is no genuine issue BACHMANN.R G Hearing Branch 1 82/08/16 Atomic Safety and Licensing Board Panel 14pp 14378 239, 24X Fiche 50-266.82/08/16.8208180118
- --920B180127 Affidavit of TO Colburn re WI Environ Decade 820721 motion concerning litigable issues. Contentions 1.2a, 2c, 3b, 3c, 4 & 5 COLBURN, T O. Operating Reactors Branch 3 82/08/16 10pp. 14378 253 24X Fiche 50-266, 82/08/16, 8208180118
- --8208180131 Affidavit of PO Easley re WI Environ Decade 820721 motion concerning litigable issues.Contention 2(a)
 EABLEY.P O Accident Evaluation Branch 82/08/16 2pp
 14378 263 24% Fiche 50-266. 82/09/16.8208180118
- --8208180134 Affidavit of EL Murphy re WI Environ Decade 820721 motion concerning litigible issues. Contentions 3(a), 3(d) & 3(e) Certificate of Svc encl MURPHY.E L Materials Engineering Branch 92/08/12 10pp 14378 265 24X Fiche 50-266, 82/08/16,8208180118
- 8208200293 Confirms licensee understanding w/HI Environ Decade re time for filing Decade amend to Decade motion concerning litigable issues, Licensee provided disputed documents to Decade on 820818 Amend to motion due 820820 Svc liet encl CHURCHILL, B. W. Shaw, Pittman, Potts & Trombridge. CHURCHILL, B. W. Hisconsin Electric Power Co. 82/08/18 BLOCH, P. B., KLINE, J. R. PAXTON, H. C. Atomic Safety and Licensing Board Panel Spp. 14398 326 24X Fiche 50-266,82/08/18,8208200293
- 8208270448 Amend to motion re third litigable issue on increased probability of tube failures due to sleeving.per A6LB direction during 820601 conference Change adds Contention F on sleeves in corroded tubes W/Certificate of Svc ANDERSON,P Wisconsin's Environmental Decade 82/08/20 Atomic Safety and Licensing Board Panel. 3pp. 14565-253, 24% Fiche 30-266,82/08/20,8208270448.
- 8208270486 Response to WI Environ Decade 820721 amend to motion relitigable issues Proposed Contention 3(*) fails to satisfy requirements for establishing litigable issues Motion should be rejected Certificate of Svc encl RIDGWAY.D A Wisconsin Electric Power Co. RIDGWAY.D A Bhaw, Pittman, Potts & Troubridge, 82/08/24 Atomic Bafety and Licensing Board Panel. 12pp. 14565-061 24X Fiche: 50-266, 82/08/24, 8208270486
- P. Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS, W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co. of New York. 93pp. 14194 ODI
 24% Fiche, 50-000, 82/07/02, 8207080064,
- 8208130128 Forwards Amends 62 & 67 to Licenses DPR-24 & DPR-27, respectively & notice of issuance & availability. Amend changes Tech Specs to modify limiting conditions for operation re auxiliary feedwater pump operation COLBURN. T.O. Operating Reactors Branch 3 82/07/27. FAY. C. H. Hisconsin Electric Fouer Co. 3pp. 14350.001 24X Fiche. 50-266, 82/07/27, 8208130128
- --820Bi30132 Amends 62 % 67 to Licenses DPR-24 % DPR-27, respectively, changing Tech Specs to modify limiting conditions for operation re auxiliary feedwater pump operation CLARK, R A. Operating Reactors Branch 3. 62/07/27. Epp. 14350:005. 24X Fiche:50-266,82/07/27,820Bi3012B
- --8208130135 Notice of issuance & availability of Amends 62 & 67 to Liceness DPR-24 & DPR-27, respectively CLARK,R.A Operating Reactors Branch 3. 82/07/27. ip. 14380:013 24% Fiches30-268.82/07/27.8208130128.
- 9208030440 Forwards response to NRC 820619 request for add1 info re proposed reactor vessel water level instrumentation sys required by NUREO-0737, item II F. 2
 FAY, C W Misconsin Electric Power Co 82/07/28 DENYON, H R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A Operating Reactore Branch 3 28pp 14154:019. 24X
 Fiche. 50-266, 82/07/28, 8208030440.
- 820B040140 Forwards proprietary Figure 6. 2.7-2, "Alternating Stresses at Location of Max Fatigue Usage" k revised Page 6.86 to McAP-9760, "Point Beach Nuclear Plant Steam Generator Slaeving Rept." Proprietary info withheld (ref 10CFR2.790) FAY.C.W. Hisconsin Electric Power Co. 82/07/28 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. CLARK.R.A. Operating Reactors Branch 3 2pp. 14189.301 24x Fiche: 50-266, 82/07/28, 8208040140.

- --B208040146 Submits application for Uithholding supplemental info to WCAP-9760, "Point Beach Nuclear Plant Steam Generator Siesving Rept " Affidavit (AH-80-53) encl WIESEMANN, R A Wastinghouse Electric Corp 82/07/15 DENTON, H R Office of Nuclear Reactor Regulation. Director 8pp 14189 303 24X Fiche 50-266.62/07/28.6208040140
- 8208100084 Forwards addl info re generation of temp/pressure profiles for typical high energy line breaks outside containment.in response to 820701 request Info based on analysis performed by Bechtel Power Corp in 1973
 BURSTEIN,S Wisconsin Electric Power Co 92/08/05 DENTON,H R OFfice of Nuclear Reactor Regulation Director CLARK,R A Operating Reactors Branch 3 5pp 14276 136 24X
 Fiche: 50-266, 62/08/05, 8208100084
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISCHHUT.D G. Division of Licensing 82/08/09 Consolidated Edison Co of New York. Ip 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208130107 Submits add1 response to NUREO-0737, Item II D 1 re block valves Marshall test data indicates that installed valves will function properly over range of operating & accident conditions FAY, G W Hisconsin Electric Power Co 82/08/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14333 272 24X Fiche 50-264, 82/08/09, 8208130109
- 8208130130 Advises that info addressing criteria of NUREG-0737, Item II 8.3, "Post-Accident Sampling Sys," will be provided by 820930 FAY.C W Wisconsin Electric Power Co 82/08/09 DENTON, W R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 ip 14336 018 24X Fiche 80-266,82/08/09,8208130130
- 820B170066 Forwards "Rept of Reactor Containment Bldg Integrated Leakage Rata Test for Point Beach Unit 2 " FAY.C W Hisconsin Electric Power Co 82/08/11 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 14362 102 24X Fiche 50-301.82/08/11.8208170066
- --8208170068 "Rept of Reactor Containment Bldg Integrated Leakage Rate Test for Point Seach Unit 2" * Wisconsin Electric Power Co 82/07/31 18pp 14362 104 24x Fiche 50-301.82/08/11,8208170066
- 8208170268 Discusses plans & Tech Spec changes for compliance w/requirements of 10GFR50 App J.per 820625 ltr Full compliance re plant design mods to containment spray sys will be achieved by Har 1983 FAY.C W Misconsin Electric Power Co 82/08/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 14367 270 24X Fiche 50-266.82/08/13.8208170268
- O Inspection reports, IE Bulletins & correspondence
- 6204210393 IE Info Notice 62-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN,EL Division of Engineering & Quality Assurance 62/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche. 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26,Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for Externel Radiation," Sec list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/19 Hichigan
- 8204210394 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks " Syc list encl CORBLI. Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York, 71pp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche.50-000.82/07/22.8204210398

- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guida Tube Support Pin Failures at Westinghouse PURs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PNR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/0//26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 30-000, 82/07/26, 8204210403
- 8208020273 Responds to request for addl info re slepving process insp Sampling insp of 10% of upper & lower sleeve joints will be made Insp will be expended if unacceptable measurements are noted FAY, C W Wisconsin Electric Power Co Office of Nuclear Reactor Regulation. Director 2pp 14152 273 24% Fiche 30-266,82/07/26,8208020273
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list uncl JORDANIE L Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8208030472 Responds to IE Bulletin 79-14 re as-built, safety-related
- pining sys Ninety-sight isometric drawings revised to incorporate mechanical corrections & represent as-built pining Remaining isometrics will be completed by 82:231 FAY.C.W Hisconsin Electric Power Co 82/07/28 KEPPLER.J @ Region 3. Office of Director 2pp 14:54 070 24X Fiche 50-266:82/07/28.8208030472
- B204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
 JGRDAN.E L. Division of Engineering & Quality Assurance B2/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000.82/08/05.8204210407
- 8208200151 Submits response to IE Bulletin 82-02 re incidents of severe degradation of threaded fastoners in closures of RCPB of PWR plants
 FAY.C W Hisconsin Electric Power Co 82/08/11, KEPPLER, J C. Region 3, Office of Director 10pp 14393 269 24X
 Fiche 50-266,82/08/11.8208200151
- 8208240365 Ack receipt of 820730 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-01 & 50-301/82-01 BPESSARD,R L Division of Project & Resident Programs 82/08/16 BURSTEIN,6 Wisconsin Electric Power Co ip 14520 171 24X Fiche: 50-266,82/08/16,8208240365
- ---B20B240370 Responds to NRC B20621 ltr re violations noted in IE Insp Repts 50-266/B2-01 & 50-301/B2-01 Corrective actions in-house procedure revised re personnel responsibilities & in-house chemistry procedure issued BURGTEIN.8 Misconsin Electric Power Ca 62/07/30 KEPPLER, J Q. Region 3. Office of Director 5pp 14520 172 24X Fiche 50-266, 82/08/16, 8208240365
- 8208310165 Ack receipt of 820813 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-266/82-10 k 50-301/82-09 SPESSARD, R L Division of Project & Resident Programs 82/08/24 BURSTEIN, 8 Wisconsin Electric Power Co ip 14693 185 24% Fiche 50-266, 82/08/24, 8208310165
- --8208310171 Responds to NRC 820716 ltr re violations noted in JE Insp
 Repte 50-266/82-10 & 50-301/82-09 Corrective actions minor
 adjustment to door closer made Fire doors for safe shutdown
 equipment have been identified & labelled
 FAY.C W Wisconsin Electric Power Co 82/08/13 KEPPLER, J 9
 Region 3, Office of Director, 2pp 14693 186 24X
 Fiche 50-266,82/08/24,8208310165
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 VOELL. R A Critical Hass Energy Project, 8pp 14679 208 24% Fichs 50-000,82/07/13,8208270010

- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1" + NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24% Fiche 50-000.82/07/13.8208270010
- --- P205270577 Forwards "Rept on Personnel Exposure & Monitoring for CY81," prr 10CFR20 407 FAY.C W Wisconsin Electric Power Co 82/02/22 Office of Management and Program Analysis ip 14679 818 24X Fiche 50-000, 82/07/13, 8208270010
- 8208160041 Forwards monthly operating repts for Jul 1982 FAY.C W Misconsin Electric Power Co 82/08/10 NRC - No Detailed Affiliation Given 1p 14344 220 24X Fiche 50-266, 82/08/10.8208160041
- --8208160043 Monthly operating repts for Jul 1982 FAY.C W. Wisconsin Electric Power Co 82/08/06 8pp 14344 221 24X Fiche 30-266/82/08/10.8208160041
- S. Reportable occurrences, LERs & related correspondence
- 8208160510 Forwards LER 82-005/01T-0 FAY,C W. Wisconsin Electric Power Co 82/08/10 KEPPLER, J G. Region 3, Office of Director ip 14348 137 24X Fiche 50-301, 82/08/10, 8208160510
- --8208160518 LER 82-005/01T-0 on 920727, discovered two of three level instruments on boric acid storage tank C powered from common source Causs unknown due to lack of maint documentation Wiring will be charged to correct problem FAY,C W Wisconsin Electric Power Co 82/08/10 Region 3, Office of Director 3pp 14348 140 24X Fiche 50-301,82/08/10,8208160510.
- 8208310264 Ferwards LER 82-006/03L-0 FAY,C W Histonsin Electric Power Co 82/08/20 KEPPLER,J Q Ragion 3, Office of Director 1p 14688 160 24X Fiche 50-301, 92/08/20.8208310264
- --820B310269 LER B2-006/03L-0 on 82072B, during pipe restraint welding to section of chemical & vol control sys divert line piping, pinhole leak developed in pipe adjacent to weld Caused by welding process Hole repaired & hydrostatically tested FAY, C H Wisconsin Electric Power Co 82/08/20 Region 3, Office of Director 2pp 14688, 161 24X Fiche, 50-301, 82/08/20, 820B310264.
- T. Mearing transcripts on non-antitrust matters
- 8208270315 Forwards licensee response to MI Environ Decade motion re litigable issues & MD Fletcher statement Proprietary v varsions served on NRC & Decade Nonproprietary version served on remainder of svc list CHURCHILL, B. Shaw, Pittman, Potts & Trowbridge 82/08/09, 810CH, P B Atomic Safety and Licensing Board Panel. 2pp 14563 207 24X Fiche 50-266,82/08/09,8208270315
- --8208270323 Testimony of WD Fletcher re issues reised in Contentions 1.2,3(a)-(e),4 & 5 in WI Environ Decade 820721 motion concerning litigable issues Prof qualifications & Certificate of Svc encl.
 FLETCHER W D. Wisconsin Electric Power Co FLETCHER, W.D Westinghouse Electric Corp. 82/08/04. 30pp 14563 280 24X Ficher 30-266,82/08/09,8208270315
- POCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3
 F. Security, medical, smergency & fire protection plans
- 8208090013 Responds to util 820608 ltr re guard training & qualification plan. Commitments for guard force during 2-yr leptementation period acceptable.

 STOLE-U. Operating Reactors Branch 4 82/07/23 HANGOCK, J. A. Florida Power Corp 1p 14283:336 24X Fiche: 50-302,82/07/23,820839013
- 8208140505 Forwards IE Insp Rept 50-302/82-13 on 820628-0702 No nencompliance noted DAKE.H.C. Division of Project & Resident Programs 82/07/26 HANCOKI, J A Florida Power Corp. 2pp 14348,088, 24x Fichs 50-302,82/07/26,8208160505

- --8208160513 IE Insp Rept 50-302/82-13 on 820628-0702 No opincompliance noted Major areas inspected followup on previous emergency preparedness findings HUFFHAN, 0 N , JENKINS, 6 R Division of Emergency Preparedness & Operational Support 82/07/23 14pp 14348 070 24X Fiche 50-302,82/07/26,8208160505
- B20B24014B Advises that changes re-modified amended security plan. Revision 2 are consistent w/provisions of 10CFR50 54(p), in response to 82062B itr Bafeguards info will be withheld (ref 10CFR73 21)
 STOLZ.J Operating Reactors Branch 4 82/08/03 HANCOCK.J A Florida Power Corp 2pp 14527 361 24X Fiche 50-302,82/08/03.82/08/04B
- 8208270700 Forwards request for add1 info in response to 820906 submittal re Revision 4 to facility security plan Response requested within 30 days Encl withheld (ref 10CFR73 21) 870L7.J Operating Reactors Branch 4 82/08/18 HANCOCK.J A Florida Power Corp 2pp 14683 043 24X Fiche 50-302,82/08/18,8208270700
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CRGR Bvc list encl
 DIRCKB. U J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194 OD1
 24X Fiche 30-000.82/07/02.8207080064
- B208040360 Forwards criteria contained in NUREC-0737. Item II B 3, "Post-Accident Bampling Sys," for use in post-implementation review Bubmittal showing compliance w/criteria requested within 20 days of receipt STOLZ.J F Operating Reactors Branch 4 B2/07/12 HANCOCK.J A Florida Power Corp 10pp 14221 348. 24X Flohe 50-302, 82/07/12, 82080403260
- 8208040052 Requests schedule be provided for submittal of supplemental ECCS calculations, which may be generic to other B&W plants & which may employ offsetting margins
 NOVAK.T M. Assistant Director for Operating Reactors
- B20B1602B6 Agrees to changes in dates proposed for Sections 1 & 3 per util 820630 ltr, in response to 820408 confirmatory action ltr Section 2 remains unchanged O'REILLY, J P Region 2. Office of Director B2/07/22. HANCOCK, J. A Florida Power Corp Ip 14346 275, 24X Fiche 50-302, 82/07/22, 82081602B6
- 8208040563 Requests submittal of Class III fee for review of 820409 amend application to operate at 75% power w/four reactor coolant pumps operating & power monitors bypassed MILLER.W O. License Fee Management Branch 82/07/29, WANCOCK, J.A. Florida Power Corp 1p. 14221 142 24% Fiche 50-302,82/07/29,8208040363
- B20B030292 Informs that util will provide response to NRC B20712 request for schedule to document satisfaction of NUREC-0737. Item II B 3. "Post-Accident Sampling Bys:" within 90 days of Mar 1983 outage during which sys scheduled to be installed MARDIS.D.O. Florida Power Corp B2/07/30 BIOLZ.J.F. Operating Reactors Branch 4 ip 14155 178 24X Fiche 50-302,82/07/30,820B030292
- 8208040215 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS CRYSTAL RIVER UNIT 3 CASE STUDY Docket No. 50-302 (Florida Power Corporation)
 BEROKAN-F A Mountain West Research, Inc. * Social Impact Research, Inc. FIN 3-6268 NUREO/CR-2747 VO3 82/07/31
 Bivision of Health, Siting & Environment 239p Available at NTIS, 47 50 14234 225, 24X Fiche 50-302, 82/07/31, 8208040215
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements by fist encl.
 EISENHUT,D G, Division of Licensing 82/08/07 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000,82/08/09,8208090174
- 820818002i Formalizes proposals made at BMJ owners group 820720 meeting re scope of program to resolve NUREG-0737. Item II K 3 30, "Revised Small Break LOCA Methods to Show Compliance W/ 10CFR50, App K " BAYWARD, P.Y Florida Power Corp 82/08/13 DENTON, H.R Défice of Nuclear Reactor Regulation, Director 12pp 14377 175 24X Fiche 50-302, 82/08/13, 8208180021

- 8208160046 Submits add1 info re NUREC-0737. Item II K 3 17 re rept on outages of ECCS, in response to NRC 820331 ltr Total outage time minimal Cumulative outage limitation for ECCS unwarranted MARDIS, D. G. Consumers Power Co 82/08/13 STGLZ, J, F Operating Reactors Branch 4 2pp 14376 210 24X Fiche 50-302. 82/08/13, 82081800AA
- 8208200093 Ack receipt of 820713 ltr requesting schedule for submitting supplemental ECCS calculations similar to those discussed in Midland SER. Calculations will be submitted on or perfore 830214

 MARDIS, D. G. Fiorida Power Corp. 82/08/13 LAINAS, 6 C. Assistant Director for Operating Reactors. 8p 14393 215 24X

 Fiche: 50-302, 82/08/13, 8208200093

G. Inspection reports, IE Bulletins & correspondence

- 8208160213 Documents B20407 verbal request for 20-day extension to allow add1 time to prepare formal response to 16 Insp Rept 50-302/81-15. Items A 2.A 3 & B MARDISD G Florida Power Corp B2/04/14 O'REILLY, J P Region 2, Office of Birector 2pp 14344 165 24X Fiche 50-302. B2/04/14, 8208160213
- 8208160468 Responds to NRC 820309 ltr re Items A 2.A 3 & B of IE Insp Rept 50-302/Bi-15. Emergency procedures include all reliable operator aides & safety-related monitors Monitors do not serve mitigation function LUTKEHAUS,T C , MARDIS,D 0 Fiorida Power Corp 82/05/11 0'REILLY.J.P Region 2 Office of Director 2pp 14348 214 24X Fiche 50-302,82/05/11,8208160468
- 8208030531 Farwards IE Insp Rept 50-302/82-12 on 820616-18 No noncompliance moted. LEWIB.R C. Division of Project & Resident Programs 82/07/14 HANCDCK.J.A Florida Power Corp 2pp 14163:013 24X Fiche 50-302,82/07/14,0208030531
- ---8208030539 IE Insp Rept 50-302/82-12 on 820616-18 No noncompliance noted Major areas inspected action on previous insps, followup on IE Bulletin 80-11-quality records for reactor bidg tendon & bidg dame surveillance programs LENAHAN, J J, CONLON, T E. Division of Engineering & Technical Programs 82/07/07. Spp. 14163 015 24X Fichs 50-302,82/07/14,8208030531.
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (HSIV)
 Leakage." Svc list encl
 JORDAN.E.L Division of Engineering & Quality Assurance 82/07/16,
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche: 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Syc list encl JORDAN.E L. Division of Engineering & Guality Assurance 82/07/19 Hickigan, Univ of. 112pp 14358 001. 24X Fiche 50-000.82/07/19, 8204210395.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Syc list encl.

 JORDANIE L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York. 112pp 14381 001 24X Fiche: 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl COBB.L.I Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co of New York. 71pp 14357:276 24X Fiche. 50-600, 82/07/20, 8204210397
- 8204210378 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN, E. L. Division of Engineering & Guality Assurance, 82/07/22 Consolidated Edison Co. of New York 112pp, 14174,321 24X Fichs. 50-000,82/07/22,8204210378
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl.

 JORDAN E.L. Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York 122pp. 14380 115 24X Fiche: 50-000; 82/07/23, 8204210401
- 204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Wastinghouse PWRs " Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 62/07/23 Consolidated Edison Co. of New York. 127pp 14194 120. 24X "iche: 50-000, 82/07/23, 82/04210402.

- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list enc1 JORDAN.E L Division of Engineering & Quality Assurance B2/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8208160305 Forwards IE Insp Rept 50-302/82-13 on 820628-0702 No noncompliance noted DANCE H C Division of Project & Resident Programs 82/07/26 HAMCOCK, J A Florida Power Corp 2pp 14348 088 24X Fiche 50-302.82/07/26.8208160505
- --8208160513 IE Insp Rept 50-302/82-13 on 820428-0702 No noncompliancy noted Hajor areas inspected followup on previous emergency preparedness findings.

 HUFFMAN, 0 N. JENKINS, 0 R. Division of Emergency Preparedness & Operational Support 82/07/23 14pp 14348 090 24X Fiche 50-302.82/07/26.8208160505
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN E L Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208160310 Ack receipt of 820625 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/82-09 DANCE/H. C Division of Project & Resident Programs 82/07/30 HANCCK/J A, Florida Power Corp Ip 14345 303 24X Fichs 50-302,82/07/30,8208160310
- --8208160316 Responds to NRC 820328 ltr re violations noted in JE Insp. Rept 50-302/82-09. Corrective actions future license amends will be circulated among personnel Withdrawal of violation re-calibr procedure requested MARDIS, D 0 Florida Power Corp 82/06/25 D'REILLY, J.P. Region 2, Office of Director. 2pp 14345 304 24% Fiche 50-302, 82/07/30, 8208160310
- --8208160324 Forwards IE Insp Rept 50-302/82-09 on 820327-0426 & notice of violation
 LEWISR RC Division of Project & Resident Programs 82/05/28
 HANCOCK, JA Florida Fower Corp 2pp 14345 306 24X
 Fiche 50-302,82/07/30,8208160310.
- --8208160327 Notice of violation from insp on 820327-0426 * Division of Project & Resident Programs 82/05/28 ip 14345 308 24% fiche, 50-302, 82/07/30, 8208160310
- --8208160333 IE Insp Rept 50-302/82-09 on 820327-0426 Noncompliance noted failure to receive prior NRC approval for Tech Spec change & failure to review & approve seismic monitoring calibr procedure prior to implementation

 BTETKA: T F . BMITH: 8 W. . BROWNLEE; V L Division of Project & Resident Programs 82/05/17 10pp 14345-309 24X

 Fiche 50-302,82/07/30.8208160310
- 8208160360 Responds to IE Bulletin 82-02. "Degradation of Threaded Fasteners in RCPB in FWR Plants " Control rod drive mechanism found w/sxcessive leakage on flanges No injection sealant matl used HARDIS.D 9 Fiorida Power Corp 82/08/02 D'REILLY.J P Region 2. Office of Director. Bpp 14347.107 24X Fiche 50-302.82/08/02.8208160360
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000,82/08/05,8204210407
- R. Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1781 for operating suclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL,R A Critical Mass Energy Project 8pp. 14679 208 24X Fiche 50-000,82/07/18,8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVB1" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14477-216. 24% Fiche 50-000,82/07/13.8208270010.
- 8208160086 Forwards monthly operating rept for Jul 1982 MARDIS,D O Florida Power Corp. 82/08/09 DEYDUNO,R C Director's Office. Office of Inspection and Enforcement. 1p. 14342 021. 24X Ficher 30-302,82/08/09,8208160086

- --8208160093 Monthly operating rept for Jul 1982 809ART, D. CULVER, H. W. Floride Power Corp. 82/08/03 5pp 14342 022 24% Fiche 50-302,82/08/09,8208160086
- S Reportable occurrences: LERs & related correspondence
- 8208310507 Forwards LER 81-013/03L-0 MANCOCK, J A Florida Power Corp 81/03/31 D'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) 1p 14497 278. 24x Fiche 50-302, 91/03/31, 9208310507
- --B2GB310311 LER B1-013/03L-0 on B10302, during routine testing in Hode 5 operation.RCB discovered w/chloride concentration of 0 18 ppm Caused by release of chlorides from makeup Procedures will be revised by 810430 MOMARA.B P Florida Power Corp B1/03/31 Region 2, Atlanta, Office of the Director (B1/03/01) 2pp 14697 279 24X Fiche 50-302, B1/03/31, B20B310507
- B206070133 Forwards LER 82-047/04T-0
 MARDI8: D G Fiorida Power Corp 82/08/02 D'REILLY, J P Region 2,
 Office of Director ip 14271 304 24X Fiche 90-302, 82/08/02,
 8206070133
- --B20B090135 LER B2-047/04T-0 on B20720.waste disposal tank iill discharged w/flow rate meter WD-101-FR inoperable Caused by operator error Rate meter power supply reset Procedures to be revised BROWN.C G. Florida Power Corp B2/08/02 Region 2. Office of Director. 2pp 14271 305 24X Fiche 30-302.82/08/02.820B090133
- 8208200095 Forwards LER 82-046/03L-0
 MARDIS, D G. Florida Power Corp 82/08/11 O'REILLY, J F Region 2
 Office of Director 1p 14393 211 24X Fiche 50-302, 82/08/11,
 8208200895
- --8208200100 LER 82-046/03L-0 on 820712, emergency diesel generator B falled to start in required time Cause attributed to manual timing techniques used for determining elapsed start time Generator restarted RNCHN.C G Florida Power Corp 82/08/11 Region 2, Office of Director 2pp 14373 212 24X Fiche 50-302,82/08/11.8208200095
- B20B200156 Forwards LER 82-050/01T-0 Detailed event analysis encl MRD18:D Q. Florida Power Corp 82/08/13 O'RCILLY.J.P Region 2, Office of Director 2pp 14394 019 24X Fiche 50-302,82/08/13,
- --B208200172 LER 82-050/01T-0 on 820730, util & AE determined that two actor control ctrs for four emergency feedwater valves could not withstand satisfic event & were located in nonselsmic bldg Caused by design inadequacy Problem under review.

 BROWN.C 0 Florida Power Corp 82/08/13 Region 2, Office of Director 1p 14394 021 24X Fiche 50-302,82/08/13,8208200156
- 8208200219 Forwards LER 82-048/03L-0 Detailed event analysis encl. MARDIE.D 0 Florida Power Corp. 82/08/13 O'REILLY.J P. Region R. Office of Director 2pp. 14399-342 24X Fiche 50-302.82/08/13. 8208200219.
- --8208200229 LER 82-048/03L-0 on 820715. windspeed & temp channels for 33 & 175-ft meteorological tower elevations failed to function properly Caused by lightning strike Damaged equipment removed, repaired & calibr RENWN.C 0 Florida Power Corp. 82/08/13 Region 2, Office of Director 1p 14399 344 24X Fiche 50-302,82/08/13.8208200219
- 8208270355 Forwards LER 82-049/03L-0 MARIER D & Florida Power Corp 82/08/16 O'REILLY, J P Region 2. Office of Director 1p. 14565 012 24X Fiche 80-302,82/08/16. 8208270355
- --9208270338 LER 82-049/03L-0 on 820717, during normal plant operation, rentrol complex ventilation monitor, RM-A5, discovered inoperatis. Gaused by failure of vacuum pump carbon impeliar vanes. Pump replaced BROWN, C 9 Florida Power Corp 82/08/16. Region 2, Office of Director. 2pp 14365:019 24X Fiche. 50-302, 82/08/16.8208270395
- COCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 82(809023) Forwards IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820510-0625 & notice of violation.

 HIND, J. A Division of Emergency Preparedness & Operational Support 82/07/22 REED, C. Commonwealth Edison Co. 2pp. 14271:105, 24X Fichs: 50-295, 82/07/22, 8208090231

- --8208070236 Notice of violation from insp on 820510-0625 HIND.J A Division of Emergency Preparedness & Operational Bupport 82/07/15 ip 14271 107 24X Fiche 50-275,82/07/22, 8208090231
- --8208090241 IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820510-0625 Noncompliance noted failure to follow & maintain amergency response plan to meet stds of 10CFR50 47(b) & to implement plan by 810401 JANUSKA, A Q Division of Emergency Preparedness & Operational Support 82/07/15 5pp 14271 108 24X Fiche 50-295,82/07/22,8208090231
- 8208030186 Application to amend Licenses DPR-39 & DPR-48, clarifying responsibilities of licensee during emergencies to take actions necessary to protect health & safety of public LENTINE.F G Commonwealth Edison Co 82/07/23 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 14160 157 24X Fiche. 50-295, 82/07/23, 8208030186
- 8208030603 Forwards final revised "Fire Protection Associated Cable Rept Zion 1 & 2 " LENTINE: F O Commonwealth Edison Co 82/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 14195.031 24X Fiche 50-295,82/07/30,8208030603
- ---8208030521 Final revised "Fire Protection Associated Cable Rept Zion
 1 & 2 " W/77 oversize drawings Aperture cords are available
 in PDR
 # Commonwealth Edison Co. 82/07/31 135pp 14195 033 24X
 Fiche 80-275,62/07/30,8208030603
- 8208110254 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 82/08/05 Document Management Branch ip 14331 141 24X Fiche 50-275, 82/08/05, 8208110254
- --8208110286 Forwards public version of Revision 5 to Emergency Plan Implementing Procedure EPIF 110-1, "Station Director," Receipt form encl PLIML, O Commonwealth Edison Co 82/07/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 14331 142 24X Fichs. 30-275, 82/08/05, 8208110254
- --8208110261 Public version of Revision 5 to Emergency Plan Implementing Procedure EPIP 110-1. "Station Director" ** Commonwealth Edison Co. 82/07/22 Spp. 14331-143 24X Fishe 50-275,82/08/05.8208110254
- B20B110259 Releases public version of revised page to emergency plan implementing procedure FELTON.J. M Division of Rules and Records B2/08/05 Document Management Branch 1p 14332 172 24X Fiche 50-295,82/08/05,820B10259.
- --B208110263 Forwards public version of revised Page B to Revision 3 to Emergency Pian Implementing Procedure EPIP 700-1, "Corporate Command Ctr Group Directory " Receipt form encl PLIML, O Commonwealth Edison Co 82/07/22 DENTON, H R NRC Na Detailed Affiliation Given ip 14332 173, 24% Ficha 50-295,82/08/05,8208110259
- --B20B11Q263 Public version of revised Page B to Revision 3 to Emergency Plan Implementing Procedure EPIP 700-1, "Corporate Command Ctr Oroup Directory."

 * Commonwealth Edison Co 82/07/22 2pp 14932 174 24X Fiche 50-295,82/08/05,820B110259
- 820B180070 Forwards exemption requests from sections of post-fire shutdown capability mept to assist in fire protection review LENTINE.F 0 Commonwealth Edison Co 82/08/10. DENTON.H R. Office of Nuclear Reactor Regulation. Director 14pp 14378.189 24X Fiche 30-295,82/08/10.8208180090
- 8208250557 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures." FELTON, J M Division of Rules and Records. 82/08/12 Document Management Branch. 1p. 14557:354 24X Fiche:50-000,82/08/12,8208250557
- --B208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 HOUREJR D Commonwealth Edison Co B2/07/19. DENTON, H R NRC No Detailed Affiliation Given 1p. 14559, 355. 24X
 Fiche 50-000, 82/08/12.8208250559

- --8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 + Commonwealth Edison Co 82/06/30 7pp 14559 356 24X Fiche 50-000,82/08/12.820825559
- P Operating license stage documents & correspondence
- 8208110098 "Bimulation of Zion Unit 2 Cycle-1 Operation." interim rept KOHUT.F , COKINOS.D , CAREW.J Brookhaven National Laboratory FIN A-3374 8208110098 82704/30 DUNENFELD.M Division of Systems Integration (post B11005) 80pp 14339 158 24X Fiche 50-304.82/04/30.8208110098
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Bvc list encl
 DIRCKS: M J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 CO1
 24X Fiche 50-000:82/07/02,8207080064
- 820B040590 Forwards revised criteria to be used to review submittal on TMI Action Item II.B 3. "Post-Accident Sampling Sys" Schedule for responding to info requested in 20 days of itr receipt NEICHBORB, J D Operating Reactors Branch 1 82/07/22 DELGEGROEL D Commonwealth Edison Co 10pp 14228 225 24X Fichs 30-275.82/07/22.8208040580
- 8208030186 Application to amend Licenses DPR-39 & DPR-48, clarifying responsibilities of licensee during emergencies to take actions necessary to protect health & safety of public LENTINE.F O Commonwealth Edison Co 82/07/23 DENTON,H R Offic of Nuclear Reactor Regulation, Director 2pp. 14160 157 24X Fiche 50-293,82/07/23.8208030186
- 8208090103 Provides actions to be taken re startup of units w/equipment required by out of svc Tech Specs & interpretation of phrase "recovery from inadvertent trip," discussed during 820721 aceting
 LENTINE,F O Commonwealth Edison Co 82/07/23 KEPPLER,J G Region 3, Office of Director 2pp 14269 273 24X
 Fiche 50-295,82/07/23,8208090103
- 8208030237 Application to amend Licenses DPR-37 & DPR-48, adding Tech Spec on sealed source contamination LENTINE, FO Commonwealth Edison Co 82/07/29 DENTON, H R Office of Nuclear Reactor Regulation. Director 1p 14158 219 24X Fiche 50-295,82/07/29,8208030239
- --8208030245 Proposed Tech Spec Pages 295AD, 295AE & 295AF re sealed source contamination * Commonwealth Edison Co 82/07/29 4pp 1415B-220 24X Fiche 50-295,82/07/29,8208030239
- 8208130018 Application to amend Licenses DPR-39 & DPR-48, changing frequency at which reactor protection & engineered safeguard instrumentation must be functionally tested LENTINE, FO Commonwealth Edison Co 82/08/05, DENTON, HR OPFice of Nuclear Reactor Regulation, Director 4pp 14335 082 24X Ficher 50-295, 82/08/05, 8208130018
- --8208130023 Proposed Tech Spec Tables 3 1.2.4 i-1 & 3 4-2 re functional testing of reactor protection & engineered safety instrumentation & Commonwealth Edison Co 82/08/05 7pp 14335 086 24X Fiche 30-275.82/08/05.8208130018
- 8208130166 Application for amend to Licenses DPR-39 & DPR-48, changing Tech 8pec 3 2 3 re control rod sys operability. LENTINE, F G. Commonwealth Edison Co 82/08/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14339 015, 24X Fiche: 50-275, 82/08/05, 8208130166
- --8208130172 Proposed changes to Tech Spec 3 2 3 re control rod sys operability * Commonwealth Edison Co 82/08/05 4pp 14339 017 24X Fiche 50-295,82/08/05,8208130166
- 8208110188 Forwards revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 21 Revised pages correct typographical & other minor errors SHARTZ,E, Commonwealth Edison Co 82/08/06 HAASS,W P Quality Assurance Branch ip 14314 079 24X Fiche 50-000,82/08/06,82
- --820Bii0204 Revised pages to CE-1-A.Revision 21. "Comm Ed GA Program for Nuclear Generating Stations "

 * Commonwealth Edison Co 82/06/06 11pp 14314 OBO 24X Fiche.50-000,82/08/06/820Bii0188

- 8208090194 Openeric Ltr 82-14 to all reactor licensees, holders of CP L applicants re submittal of documents to NRC Summarizes iOCFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D G Division of Licensing 82/08/09 Consulidated Edison Co of New York ip 14356 332 24% Fiche 50-000.82/08/09, 8208090194
- 8208280137 Forwards addl info re diesel generator outages for 1976-81, per Franklin Research Ctr 820628 request & NUREG-0737. Item II K 3 17. "ECCS Outage Rept "
 LENTINE.F 0 Commonwealth Edison Co 82/08/16 EI8ENHUY.D O
 Division of Licensing 21pp 14541 309 24% Fiche 50-275, 82/08/16, 8208250137
- 8208240305 Submits updated schedule for submittal of add1 info recontainment purge valve operability Program scheduled for Fall 1982 completion Summary of stress values calculated by hand enc1 LENTINE.F O Commonwealth Edison Co 62/00/19 DENTON,H R Offic of Nuclear Reactor Regulation, Director App 14327:197 24X Fiche 50-295, 82/08/19, 8208240305
- Q Inspection reports, IE Bulletins & correspondence
- 8208050414 Forwards IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-275/81-31 & 50-304/81-29 on 810813-820503 No nancompliance noted KEPPLER, J G Region 3, Office of Director 82/07/12 REED, C Commonwealth Edison Co 1p 14217 166 24% Fiche 50-000, 82/07/12, 8208050414
- --8208050441 IE Insp Repts 50-237/81-37,50-249/81-32,50-254/81-23, 50-265/81-23,50-295/81-31 & 50-304/81-27 on 810813-820503 No soncompliance noted Major areas inspected,allegations re Comm Ed operation of facilities & compliance w/10CFR21 HAYEG,D W , CHRIBBUTIMOS,N , KOHLER,J Division of Project & Resident Programs 82/07/09 I55pp 14217 169 24X Fiche 50-000,82/07/12,8208050414
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (HBJV)
 Leakage " Svc list enc!
 JORDAN E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Ficha 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26.Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of, 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395
- 9204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 30-000.82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexaflubride Overpacks " Bvc list enci COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208090231 Forwards IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820510-0625 & notice of violation HIND, J A Division of Emergency Preparedness & Operational Support 82/07/22 REED, C Commonwealth Edison Co 2pp 14271,105 24X Fiche, 50-295,82/07/22,8208090231
- --8208090236 Notice of violation from insp on 820510-0625 HIND, J. A. Division of Emergency Preparedness & Operational Support 82/07/15 ip 14271 107 24X Fiche 50-295,82/07/22, 8208090231.
- ---8208090241 IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820510-0625
 Noncompliance noted failure to follow & maintain emergency response plan, to meet stds of 10CFR30 47(b) & to implement plan by 810401
 JANUSKA, A Q , AXELBON, W L Division of Emergency Preparedness & Operational Support 82/07/15 5pp 14271 108 24X
 Fichs 50-295,82/07/22,8208090231

- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl "ORDAN, E L Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 122pp 14380 115 24% Fiche 50-000.82/07/23.8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche. 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Cartain Westinghouse PWR Power Plants." See list enci JORDAN, E L Division of Engineering & Quality Assurance 82/07/26 Consalidated Edison Co of New York 12ipp 14357 013 24X Fiche: 50-000, 82/07/26, 8204210403
- \$294210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28 Convolidated Edison Co. of New York 122pp. 14357-144 24X Fiche: 50-000, 82/07/28, 8204210405
- 8208050490 Forwards response to IE Bulletin 82-02 re bolted connections Visual or surface exams not typically performed on bolting in RCS unless requested No trend of leakage recurrence detected SMARTI, E D. Commonwealth Edison Co 82/07/29 KEPPLER, J 9 Region 3, Defice of Director 14pp 14214, 109 24% Fiche 50-295, 82/07/29, 8208050490
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffile Mater-Jet Impingement " Syr list encl JORDAN, E L Division of Engineering & Quality Assurance. 82/08/05 Consolidated Edison Co of New York 117pp 14388:201 24X Fichs 30-000, 82/08/05, 8204210407
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analysing seld info Forwards documents listed in App A FELTON J.H Division of Rules and Records 82/07/13 UDELL,R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000.82/07/13.820827010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81"

 e NRC No Datailed Affiliation Given 82/07/13 48ap 14679:216. 24X Fiche 50-000, 82/07/13, 8208270010
- --B208270559 Forwards "Recorded Annual Whole Body External Exposure for CY81;" per 10CFR20 407(b) W/o Quad Cities, Zion, LaHalle, Byron & Braidwood repts
 RAUSCH, T J Commonwealth Edison Co 82/03/31, Office of Hanagement and Program Analysis ip 14680,075 24X
 Fiche 50-000,82/07/13,8208270010,
- 820B130103 Forwards monthly operating ropts for Jul 1982 QRAESBER K.L. Commonwealth Edison Co 82/08/06 Director's Office, Office of Inspection and Enforcement. 1p 14335,340. 24X Fiche 50-295,82/08/06.8208130103
- --8208130106 Monthly operating repts for Jul 1982 CDOK. J Commanualth Edison Co 82/08/06 lipp 14335.341 24X Fish: 50-275, 82/08/06.8208130103
- B Reportable occurrences, LERs & related correspondence
- 8208130225 Forwards LER 82-017/03L-0 GRAEGER: K.L. Commonwealth Edison Co 82/08/06 KEPPLER: J. G Region 3. Office of Director in 14333 180, 24X Fith: 50-304, 82/08/06, 8208130225
- --B2OBi30231 LER 82-017/03L-0.on 82070B, during hot shutdown & after taking MBIV 28 out of sequence MBIV drifted open & was rendered inapprable Caused by failure to open drain valve. Bigns reminding operators to verify drain position posted. MARBH.R.L. Commonwealth Edison Co 62/08/06 Region 3, Office of Director 19 14333-181. 24X Fiche 50-304,82/08/06,8208130225.

- DOCKET 50-305 KEVAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8208020190 Releases public version of revised Tabiological emergency response plan implementing procedures
 FELTON, J H Division of Rules and Records 82/07/13 Document Hanagement Branch ip 14179 057 24X Fiche 50-305, 82/07/13, 8208020190
- --8208020191 Forwards public version of revised radiological emergency response plan implementing procedures including Procedures EP-AD-17 re communications & EP-RET-3C re post-accident operation of high radiation sample room GIESLER, C. W. Wisconsin Public Service Corp. 82/04/30 DENIGN.H R. Office of Nuclear Reactor Regulation, Director. 1p 14179 058 24X Fiche 50-305, 82/07/13,8208020190.
- --8208020192 Public version of revised radiological emergency response plan implementing procedures, including Procedures EP-AD-17 re communications & EP-RET-3C re post-accident operation of high radiation sample room GIESLER, C. H. Hisconsin Public Service Corp. 82/06/18 100pp 14179 060. 24X Fiche 50-308, 82/07/13,8208020190
- B208060322 Releases public version of revised radiological amergency response plan implementing procedures
 FELTON.JM Division of Rules and Records. 82/08/02, Document
 Management Branch ip 14281 151 24X Fithe 50-305.82/08/02.
- --8208050324 Forwards public version of revised radiological emergency response plan implementing procedures, including Revision & to Procedure EP-ENV-3A, "Environ Protection Director Actions & Directives "
 OIESLER, C W Misconsin Public Service Corp 82/07/26
 DENTON, H R. Gffice of Nuclear Reactor Regulation, Director. ip
 14281 152 24X Fiche 50-305, 82/08/02,8208060322.
- --B208060328 Public version of revised radiological emergency response plan implementing procedures, including Revision E to Procedure EP-ENV-3A. "Environ Protection Director Actions & Directives "Revised index encl LANGE,R H. Wisconsin Public Service Corp 82/07/02 59pp 14201,153 24X Fiche 50-305,82/08/02,8208060322.
- 8208090253 Summarizes info presented at 820623 menting re request that shutdown sys by considered dedicated rather than alternate Schedule & scope of work encl OIESLER, C W Wisconsin Public Service Corp. 82/08/04 DENTON, H. R Office of Nuclear Reactor Regulation, Director 29pp. 14272 020 24X Fiche: 50-305, 82/08/04, 8208090253
- B208310422 Forwards IE Bafaguards Insp Rept 50-305/82-15 on B20810-13 & notice of violation
 HILLERJ R Division of Engineering & Technical Programs 82/08/24.
 GIESLER,C. H. Hisconsin Public Service Corp 2pp. 14692 062 24X
 Fiche 30-305.82/08/24.8208310422.
- --8208310424 Notice of violation from insp on 820813-15.
 MILLER, J R Division of Engineering & Technical Programs.
 82/08/24. 1p 14692 064. 24% Fishe 50-305,82/08/24,8208310422
- --B208310431 IE Bafeguards Insp Rept 50-305/62-15 on 820813-15
 Noncompliance noted failure to comply w/reporting
 requirements for receipt & shipment of SNM reported on Forms
 NRC-741 Details withheld (ref 10CFR2.790)
 FINLEY,A 0 : CREED,J R Region 3, Office of Director 82/08/24,
 1p 14692.065 24X Fiche 50-305,82/08/24,8208310422,
- 8208310305 Responds to NRC 820727 request for info on diesel generator outages per TMI Action Plan Item II K 3 17, "Rept on Outages of ECCS " Info previously submitted in 811125 response to Unresolved Bafety Issue A-44, "Station Blackout" 0IESLERIC W Wisconsin Fublic Service Corp 92/08/27 VARGA, B. A. Operating Reactors Branch 1. ip 14687-355 24X Fiche 50-305,82/08/27,8208310305
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8208240181 Forwards Figure 10 2-2 entitled "Flow Diagram-Condensete & Oland Beel Bys." inadvertently omitted from updated FSAR. OLESLER.C.W Wisconsin Public Service Corp. 82/08/20 VAROA.B A. Operating Reactors Branch 1. 3pp. 14527 079. 24X Fiche: 50-305, 82/08/20, 8208240181.

- P Operating lacense stage documents & correspondence
- B207080044 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list enci DIRCKS.W J Office of the Executive Director for Operations B2/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fiche 50-000.B2/07/02.B2070B0064
- 8208030513 Forwards Revision 2 to "Reactor Test Program, Newaunee Nuclear Power Plant" OIESLER, C W Wisconsin Public Service Corp 82/07/22 VARGA,S A Operating Reactors Branch 1 2pp 14163 253 24X Fiche: 50-305, 82/07/22, 8208030513
- --8208030517 Revision 2 to "Reactor Test Program, Kowaunge Nuclear Power Plant" Wisconsin Public Service Corp 82/07/22 30pp 14163 255 24X Fiche 50-305, 82/07/22, 8208030513
- 8208110095 Forwards Franklin Research Ctr request for additinfore TMI Action Plan Item II K 3 17, "Rept on Outages of ECC8" Response requested within 30 days of itr receipt VAROA.8 A Operating Reactors Branch I 82/07/29 GIESLER.C W Hisconsin Public Service Corp 3pp 14331 062 24X Fiche 50-305,82/07/29,8208110095
- 8208030396 Revises commitment date to develop procedures utilizing containment high-range radiation monitors for emergency class determination per TMI Action Item II F I Emergency plan implementing procedures to be revised 821001 OIESLER, C W Wisconsin Public Service Corp 82/07/30 EIESLMUT, D 0 Division of Licensing 1p 14154 007 24X Ficher 50-305, 82/07/30, 8208030396
- J208050276 Forwards response to request for add1 info re environ qualification of safety-related electrical equipment Listing of design change requests in response to NUREO-0737, "Clarification of TMI Action Plan Items" enc! OFEBLER, C. W. Wisconsin Public Service Corp. 82/08/02 VAROA, 8 A Operating Reactors Branch I 50pp 14209 212 24X Fiche 50-305, 82/08/02, 8208050276
- 8208100178 Forwards revised Table 1. "Acceptance & Review Criteria for Reactor Tests," to "Reactor Test Program, Kewaunee Nuclear Power Plant:" Revision 2, submitted on 820722 OIEBLER, C. W. Hisconein Public Service Corp. 82/08/06 VAROA, B. A. Operating Reactors Branch 1 1p. 14278 221 24% Fiche 80-305, 82/08/06, 8208100178
 - 320810018] Revised Table i, "Acceptance & Review Criteria for Neactor Tests," to "Reactor Test Program, Kewaunee Nuclear Power Plant," Revision 2, submitted on 820722 * Wiscomsin Public Service Corp 82/08/06 1p 14298 222 24X Fiche 50-305, 82/08/06, 8208100178
 - **O8090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl EIEENHUT, D 0 Division of Licensing B2/08/09 Consolidated Edison Co. of New York | p 14386 332 24X Fiche 50-000, 82/08/09, B208090194
- 208130137 Requests extension to 830115 for submittal of proposed amends to radiological effluent Tech Spec.per NRC 820713 request GIEBLER.C W Misconsin Public Bervice Corp 82/08/09, VARQA, 8. A Operating Reacture Branch 1 ip 14335-328 24% Fiche 50-305,82/08/09,8208130137
- 8208240250 Application for Amend 49 to License DPR-43-proposing Tech Byec changes including rearrangement of table of contents, correction of typographical errors & other administrative changes. Class II amand fee encl OIESLER.C W. Wisconsin Public Service Corp 82/08/18 EIGENHUT, D. 9 Division of Licensing 6pp 14521 065 24X Fichs.50-305,82/08/18,8208240250
- --8208240253 Proposed Tech Specs, rearranging table of contents & correcting typographical errors & other administrative changes.

 # Wisconsin Public Service Corp 82/08/18 33pp 14521 071. 24% Fichs 50-305.82/08/18,8208240250
- 8208310205 Requests util 770104 proposed Amend 23 be disregarded New amend request on App J will be submitted by 821101 New amend proposed Preferable to updating proposed Amend 23 OIEBLER.C. H. Hisconsin Public Service Corp. 82/08/27 VARGA.8 A Operating Reactors Branch 1, 19 14493.124 24X Fichs 50-305.82/08/27,8208310205

- 8208310305 Responds to NRC 820727 request for info on diesel generator outages per TMI Action Plan Item II K 3 17, "Rept on Outages of ECCB " Info previously submitted in 811125 response to Unresolved Safety Issue A-44, "Station Blackout" GIEBLER, C W Wisconsin Public Service Corp 82/08/27 VARGA, 9 A Operating Reactors Branch 1 ip 14687 355 24X Fiche 50-305, 82/08/27, 8208310305
- Q Inspection reports, IE Bulletins & correspondence
- 8208040026 Forwards request for addl info to complete review of B20507 ltr re IC Bulletin 80-04. "Analysis of PWR Main Steam Line Break N/Continued Feedwater Addition." VARGA, S A Operating Reactors Branch 1 B2/07/15 GIESLER, C H Wisconsin Public Service Corp. 4pp. 14233 357 24X Fiche 30-305, 82/07/15, 8208040026
- B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN,E L. Division of Engineering & Quality Assurance 82/07/36
 Compolidated Edison Co. of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1: "Clarification of Placement of Personnel Monstoring Dovices for External Radiation " Syc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20.8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl CDBs.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co. of New York 7ipp 1435/276 24X Fiche 50-000:82/07/20:8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & MPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RC8 " Bvc list encl JORDAN,E L Division of Engineering & Ouality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tubb Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice B2-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Byo list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Hork in Fuel Storage Pool" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 12Rpp 14357 146, 24X Fiche, 50-000, 82/07/28, 8204210408
- 920B100159 Bubmits response to Item 5 of IE Dulletin 82-02.
 "Degradation of Threaded Fasteners in RCPB of PWR Plants "
 Boric acid wastage found on bonnet studs of RCPB valves
 OIESLER.C W Wisconsin Public Service Corp 82/08/02 KEFPLER.J Q
 Region 3, Office of Director 5pp 14298 036 24X
 Fiche.50-305,82/08/02.820B100159
- 820823008B Forwards IE Insp Rept 50-305/82-10 on 820601-30 & notice of violation.

 SPEBBARD, R L Division of Project & Resident Programs 82/08/02 GIESLER, C W Wisconsin Public Service Corp 2pp 14517, 322 24X Ficks. 50-305, 82/08/02, 8208230088
- --8208230072 Notice of violation from insp on 820601-30. SPEGBARD, R L Division of Project & Resident Programs 82/08/02 1p. 14517:324 24X Fiche 50-305.82/08/02.8208230088

- E208230100 FE Insp Rept 50-305/82-10 on 820601-30 Nancompliance noted failure to conduct maint activities of safety-related activities & components per approved procedures NEUSON, R. I. KONKLIN, J. E. Division of Project & Resident Programs 82/08/02, 6pp 14517 325 24X Fiche 50-303,82/08/02,8208230088
- 204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From faffle Water-Jet Impingement " 8vc list encl 2000AN, E L Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- X8310422 Forwards IE Bafeguards Insp Rept 50-305/82-15 on 820810-13 b notice of violation KILLER, J R Division of Engineering & Technical Programs 82/08/24 GIEBLER. C W Misconsin Public Service Corp Rpp 14692 062 24) Fich
- -8208310424 Notice of violation from insp on 820813-15
 MILLER, JR Division of Engineering & Technical Programs,
 82/08/24 ip, 14692 044 24% Fiche 50-305,82/08/24,8208310422.
- -8208310431 IE Bafeguards Insp Rept 50-305/82-15 on 820813-15 Noncompliance noted failure to comply w/reporting requirements for receipt & shipment of SNM reported on Forms NRC-741.Details withheld (ref 10CFR2 790) FINLEY.A 0 . CREED.J R Region 3. Office of Director 82/08/24 1p 14692-065 24X Fiche 50-305-82/08/24,8288310422
- I Periodic operating reports & related correspondence
- 9208120213 Forwards monthly operating rept for June 1982 QIEBLER, C. W. Wisconsin Public Service Corp. 82/07/12 Office of Nanagament and Program Analysis. ip. 14326, 159 24X Fiche 50-305, 82/07/12, 8208120213
- --8208120214 Monthly operating rept for June 1982 RULTER, 0 H Wisconsin Public Service Corp 82/07/01. 4pp 14326, 160. 24X Fiche 50-305, 82/07/12, 8208120213
- 8208270010 Responds to FOIA request for documents detailing collective dosw exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL,R A, Critical Mass Energy Project 8pp 14679 208, 24X Fiche 50-000,82/07/13,8208270010
- --820B270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CV81 " = NRC - No Detailed Affiliation Given 82/07/13 48pp 14677:216. 24X Fiche 50-000.82/07/13.8208270010
- 8 Reportable occurrences, LERs & related correspondence
- 8208050486 Forwards LER 82-019/03L-0 OIEBLER.C W Wisconsin Public Service Corp 82/07/28 KEPPLER, J G. Region 3, Office of Director 1p. 14213 278, 24X Fichs. 50-305. 82/07/28. 8208080486
- --8208050499 LER 82-019/03L-0 on 820428, in shield bldg ventilation retirculation fan found out of svc Caused by shutdown due to meint check because of repeated trips of circuit breaker during extended fan runs. Logse contactor block replaced, BERNHUFT, S. L. Wisconsin Public Service Corp 82/07/28, Region 3. Office of Director ip 14213, 279 24X Fiche 50-305, 82/07/28, 8208050486
- 8208090209 Forwards LER 82-020/03L-0
 OIESLERIC 4 Wisconsin Public Service Corp 82/07/30 KEPPLER, J. Q.
 Region 3, Office of Director 1p. 14270 360, 24X
 Fiche 50-305, 82/07/30, 8208090209
- --820B090214 LER 82-020/03L-0 on 820702, while performing control rod exercise, rod deviation monitor failed to operate. Caused by rod positions not updated on process computer following last computer failure Procedure updated.

 BERNHOFT B L Wisconsin Public Service Corp 82/07/30 Region 3, Diffice of Director ip, 14270.361 24X Fiche 50-305, 82/07/30, 8208090209
- B208130235 Forwards updated LER 82-009/03X-1, OTESLER.C. W. Misconsin Public Service Corp. 82/08/05. KEPPLER.J.O. Region 3. Office of Director 1p. 14337: 149. 24X Fighe 50-305.82/08/05.8208130235.

- --B20B130243 Updated LER 82-009/03X-1 on 820410, while in hot shutdown prior to scheduled refueling outage, both source range nuclear instruments determined inoperable Caused by water accumulation in instrument canisters
 MOLZAHN, D J Hisconsin Public Bervice Corp B2/08/05 Region 3, Office of Director 1p 14337 150 24X Fiche 50-305, 82/08/05, 8208130235
- 8208130093 Forwards LERs 82-021/01T-0 & 82-022/01T-0 OIEBLER.C % Misconsin Public Service Corp 82/08/06 KEPPLER, J G Region 3. Office of Director 19 14336-013 24X Fiche 50-305. 82/08/06, 8208130093
- ---B20B33009B LER 82-021/01T-0 on 820723. while performing test on containment fan coil units & associated duct work.massyred flows found low Gaused by fan interactions between two fans feeding common containment ring haader duct work MOLZAHN, D J , BCHROCK, C A Wisconsin Public Service Corp 82/08/06 Region 3, Office of Director 2pp 14336 014 24X Fiche 50-30 5, 82/08/06.8208130093
- --B20B130102 LER B2-022/01T-0 on B20727, conteinment fan coil unit 1A failed to restart during tast of sys heat removal & flow capabilities Causad by high instantaneous current due to fan having to overcome back pressure from sys Breaker reset BERNHOFT, B. L. , BHOKER, C. S. Wisconsin Public Bervice Corp B2/08/10 Region 3, Office of Directur ip 14336 016 24X Fiche: 50-305, 82/08/06: 820B130093
- 8208170078 Forwards LER 82-023/03L-0 OIESLER,C W Hisconsin Public Service Corp 82/08/10 KEPPLER, J. Q. Region 3, Office of Director 1p 14358 133 24X Fiche 30-305, 82/08/10, 8208170078
- --B20B1700B1 LER 82-023/03L-0 on B20711, iA dissel generator declared out of svc due to generator startup air compressor not maintaining proper pressure Caused by suction valve on secondary stage having cracked leaf Valves replaced BERNMOFT. B. L. Hisconsin Public Service Corp. B2/08/10. Region 3. Office of Director ip i4358 134. 24% Fiche 30-305,82/08/10. B208170078.
- 8208230142 Forwards updated LER 82-002/03X-1 & LERS 82-024/03L-0 & 82-025/03L-0
 01E8LER,C W Wisconsin Public Service Corp 82/08/13 KEPPLER,J. 9. Region 3. Office of Director 1p. 14514 304. 24X Piche 50-305, 82/08/13, 8208230142.
- --B208230153 Updated LER 82-002/03X-i on B20114 during normal operation, pressurizer level transmitter LT427 found out of apec. Caused by instrument drift Transmitter recalibr. Barton transmitters will be changed as part of long-term upgrade SMOKER.C B Hisconsin Public Service Corp. B2/08/i3 Region G. Office of Director ip 14514 305 24% Fiche.50-305,82/08/13,8208230142.
- --B20B230161 LER 82-024/03L-0:on 820716, while at full power, overpower delta T channel 3 rod stop alarm observed cycling in & out Caused by maifunction of TAVO signal conditioner causing channel to drift Spere signal box installed & calibr BERNHOFT.8 L Wisconsin Public Service Corp. 82/08/13, Region 3. Office of Director ip 14514 306. 24X Fiche 50-305,82/08/13,8208230142.
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

 F. Becurity, medical, emergency & fire protection plans
- B20803003B Releases public version of revised bmergency plan implementing procedures FELTON, J M Division of Rules and Records. B2/07/19 Document Management Branch. ip 14182-219. 24X Fiche 50-282,82/07/19,820803003B.
- --8208030070 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-14.2 reoperations emergency surveys & F3-8 reracommendations for offsite protective actions
 MUSDLF,D.M. Northern States Power Co. 82/07/07. Region 3, Office of Director ip 14182-220. 24K Fiche.50-282,82/07/19,8208030038.

- --8208030091 Public version of revised emergency plan implementing procedures, including Procedures F3-14 2 re operations emergency surveys & F3-8 re recommendations for offsite protective actions SCHUELME, D.A. Northern States Power Co. 82/07/01 175pp 14182 221 24x Fiche 50-282, 82/07/19, 8208030038
- 820B170399 Advises that gremption from fire protection schedular requirements of IOCFR50 4B(c) re emergency lighting cannot be granted based on 820520 request alone Complete chronology of Section III J implementation efforts requested CLARK, R A Operating Reactors Branch 3 82/07/29 MUSDLF, D M Northern States Power CO 4pp 14372 349 24% Fiche 50-282,82/07/29,820B170399
- 8208260089 Releases public version of revised corporate emergency plan FELTON. J M Division of Rules and Records 82/08/13 Document Management Branch ip 14576 176 24% Fiche 50-000, 82/08/13. 8208260089
- ~-B20B2&0315 Forwards public version of Revision 5 to corporate nuclear energency plan Updated info on App C items identified in NRC B20504 itr encl
 LARSON.C E Northern States Power Co 82/08/02 Region 3,
 Office of Director 4pp 14576 199 24X Fiche 50-000, 82/08/13,
 B20B2&0089
- --8208260319 Public version of Revision 5 to corporate nuclear emergency plan HUDSON.G. HARD.E., LARSON.C.E. Northern States Power Co 82/08/02 140pp 14576 203 24X Fichs 50-000,82/08/13, 8208260089
- 8208260353 Releases public version of revised emergency plan laplementing procedures FELTON.J M Division of Rules and Records 82/08/13 Document Management Branch 1p 14575 069 24X Fiche 50-000,82/08/13, 8208260333
- ---8208260358 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP 1 1 2 rm notifications & EPIP 1 1 5 re startup & operation of emergency operations facility

 HARD. 5 C Northern States Power Co 82/08/11 Region 3, Office of Director. 1p 14575 072 24% Fiche 30-000,82/08/13, 8208240357
- --9209260360 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1 1 2 re notifications & EPIP 1 1 5 re startup & operation of emergency operations facility

 Northern States Power Co 82/08/11 72pp 14975 073 24X Fiche 50-000, 82/08/13, 8208260353
- OBJOOJED Provides add1 info in support of util B20520 request for railef from schedule for completion of 10CFR50,App R. Section III J re smergency lighting mods Mods will be implemented by B30101

 **WSDLF.D Northern States Power Co B2/08/23 Office of Nuclear Regulation, Director BPP 14599 086 24X
 Fiche 30-282,82/08/23,8208300326
- Operating license stage documents & correspondence
- O7080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Byc list encl Director for Operations B2/07/02 Consolidated Edison Co of New York 93pp 14194 ODI 24X Fiche 50-000,82/07/02,8207080064
- 8208020446 Provides results of post-implementation review of thift technical advisor training program Program meets intent of NUREO-0737. Item II A I I In future, all new hires into program should have bachelor degree or equivalent CLARLR A Operating Reactors Branch 3 82/07/06 MUSOLF, D M Northern States Power Co 3pp 14181 045 24X Fiche 50-282, 82/07/06, 8208020446
- 8208020051 Forwards Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability Amend increases peak burnup limit DITANNIO C Operating Reactors Branch 3 82/07/16 MUSOLF, D M Northern States Power Co 3pp 14181 007 24X Fiche 50-282, 82/07/16, 8208020051
- --B2DB020054 Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively, ravising App A Tech Spec peak burnup limit from 41,850 to A7.000 HWD/HTU CLARK.R A. Operating Reactors Branch 3 82/07/16 App 14181 010 24X Fiche 50-282,82/07/16.8208020051.

- --8208020036 Safety evaluation supporting Amends 56 & 50 to Licenses DPR-42 & DPR-60 respectively * Office of Nuclear Reactor Regulation. Director 14181 016 24% Fiche 50-282.82/07/16.8208020051
- --8208020062 Notice of issuance & availability of Amends 56 & 50 to Licenses DPR-42 & DPR-60 respectively CLARK.R A Operating Reactors Branch 3. 82/07/16 2pp 14181 021 24X Fiche 50-282,82/07/16.8208020051
- 8208040642 Advises that plant operation in Cycle 7 acceptable w/therma) margins for core loadings containing mixture of TOPROD & Exxon std fuel assemblies CLARK.R A Operating Reactors Branch 3 82/07/22 MUGDLF, D N Northern States Power Co 2pp 14224 023 24% Fiche 50-282,82/07/22,8208040642
- 8208030228 Advises that Tech Spec change request re NUREO-0737, ltems II E 1 1 & II E 1 2 concerning auxiliary feedwater sys will be submitted by 820713 Delay due to organizational changes, workload & Unit 2 outage MUSOLF.D Northern States Power Co 82/07/28 Office of Nuclear Reactor Regulation. Director 1p 14158 285 24X Fiche 50-282,82/07/28,8208030228
- 820811008B Forwards request for addl info re pressure & temp profiles outside containment as part of equipment environ qualification review to perform calculations for pipe breaks outside containment Info requested within 30 days CLARK, R A Operating Reactors Branch 3 82/07/29 MUSDLF, B H Northern States Power Co 4pp 14329 357 24X Fichs 50-292, 82/07/29, 820811008B
- 8208100194 Advises that Exxon 820708 ltr transmitting XN-NF-82-49 (P) should be considered util response to TMI I tem II K 3 30 Method/model changes have been made where necessary MUSOLF, D M Northern States Power Co 82/08/03 Office of Nuclear Reactor Regulation, Director 1p 14298 196 24X Fiche 50-282,82/08/03,8208100194,
- 820B100055 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Table 4 I-2A for waiver of end-of-cycle monthly turbine valve test Approval requested 2 monthe prior to Unit i refueling outage scheduled for 821113 MUBGLF.D Northern States Power Co 82/08/06 Office of Nuclear Reactor Regulation, Director ip 14294 224 24X Fiche 50-282,82/08/06,8208100055
- --8208100062 Application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Table 4 1-2A for waiver of end-of-cycle turbine valve test Description of proposed changes & reasons encl MUSDLF, D M. Northern States Power Co. 82/08/06 3pp 14276 123 24X Fiche 50-282, 82/08/06, 8208100055
- --8208100074 Revised Tech Spec Table 4 1-2A re min frequencies for equipment tests Licensing fee determination encl * Northern States Power Co 82/08/06 2pp 14296 228 24X Fiche 50-282,82/08/06.8208100055
- 8208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP thapplicants re-submittal of documents to NRC Bummarizes iOCFR Chapter I requirements & provides alternatives to requirements Syc list encl EIBENMUT, D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,62/08/09, 8208090194
- 820B1R0191 Forwards proprietary version, "Computer Program Control Procedure: "NAP 5 OIP Procedure contains supplemental info to util reload methodology topical repts submitted 820212 Procedure withheld (ref 10CFR2 790) Affidavit encl MUSOLF.D. Northern States Power Co. 62/08/09 Office of Nuclear Reactor Repulation, Director Spp. 14326, 030 24X Fichs: 50-282, 82/08/09, 8208120151
- 8208200274 Forwards Revision 1 to application to amend OL & proposed Tech Spec changes re radiological effluent Tach Specs & environ monitoring MUSOLF.D Northern States Power Co 82/08/13 Office of Nuclear Reactor Regulation, Director 2pp 14374.146, 24X Fichs. 50-282.82/08/13, 8208200294.
- --B208200297 Revision 1 to application to amend OL: changing Tech Specs to enhance radiological effluent & environ munitoring * Northern States Power Co B2/08/13. 3pp 14394 148 24X Fiche 50-282,82/08/13.8208200294
- --8208200278 Revisions 1 to proposed Tech Spec changes, enhancing radiological effluent & environ monitoring * Northern States Power Co 82/08/13 63pp, 14374, 151 24X Fichs 50-282, 62/08/13, 8208200274.

- 2.6230338 Forwards "Process Control Program for Solidification of Isfasts from Liquid Sys " & proprietary pages to "Radwasta Stliffication Bys " Encis withheld (ref 10CR2 770) ASQLF,D H Northern States Power Co 82/08/13 Office of Killer Reactor Regulation, Director 3pp 14513 196 24% Fighs 50-282.82/08/13.8208230338
- E:3220084 Forwards responses to B20603 questions re-station electric fistribution sys voltage study installation of second startup transformer will provide flexible & reliable distribution sys RESOLF.D Northern States Power Co. 62/08/17 Office of Nuclear Paector Regulation, Director 20pp 14393-221 24X Fiche: 50-282, 82/08/17, 8208200084
- Office of Nuclear
- 2. 6240136 Advises that Tech Spec Section 3 3 A i (g) applies to safety imjection pump discharge cross-tonnect valves to other SCCS relives in response to NRC 811201 itr Section work instruction requires monthly surveillance of subj valves MSOMF, D H Northern States Power Co 82/08/19 Defice of Nullear Reactor Regulation, Director ip 14519 333 24X Fichs 50-282, 82/08/19, 8208240134
- 872270294 Provides confirmation of info discussed in earlier telcons is containment purging & venting during normal operation MSQLF.D Northern States Power Co 82/08/23 Office of Nuclear Flacts Regulation, Director App 14564 178 24X Fighs 50-262, 82/08/23, 8208270294
- & Inspection reports, IE Bulletins & correspondence
- E2M210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leatage " 5vc list encl
 JARDAN,E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14336 274 24%
 Fichs 50-000, 82/07/16, 8204210393
- 2204210395 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Flacement of Personnel Monitoring Devices for External Radiation " Svc list encl.

 JORDANIE L Division of Engineering & Quality Assurance 82/07/19

 Kichigan. Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19.8204210395
- 6206050508 Forwards IE Insp Repts 50-282/82-07 & 50-306/82-09 on E20601-3D No noncompliance noted STREETER, J.F. Region 3. Office of Director 82/07/19 LARSON, C.E. Northern States Fower Co. 2pp 14214 061 24X Fiche 50-282
- --8208050521 IE Insp Repts 50-282/82-09 & 50-306/82-09 on 820601-30

 No noncompliance noted Major areas inspected plant
 aperation,maint,organization, surveillance-security, radiation
 protection, LER followup & refueling activities
 FEIERABEND.C.D. BURGESS.B.L., REYES.L. Region G. Office of
 Director 82/07/15 9pp 14214 043 24X Fiche 50-282.82/07/19,
 8208050508.
- 8204210396 IR Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381-001 24X Fiche 50-000 82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacie " 8vc list encl COSB.C. I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York, 71pp 14237 276 24K Fiche: 50-000, 82/07/20, 8204210397
- 8204210398 IE info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Syc list encl JORDAN.E L Division of Engineering & Quality Assurance, B2/07/22 Consolidated Edison Co. of New York 112pp 14174 321 24X Fiche: 50-000, 82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl.

 JORDAN E L. Division of Engineering & Quality Assurance 82/07/23
 Consolidated Edison Co of New York 122pp. 14380 115. 24%
 Fiche: 50-900, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) guide Tube Support Pin Failures at Westinghouse PWRs," Svc list encl. JORDAN.E.L. Division of Engineering & Guality Assurance. B2/07/23 Consolidated Edition Co of New York 127pp 14194-120, 24X Fische 50-000,82/07/23,8204210402

- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Cartain Westinghouse PWR Power Plants" Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN-E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 144
- 820Bi000BO Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in 8CPB of PWR Plants " RCPB insps performed at regular intervals Fow leakage problems experienced at facility.

 LARSON: C E Northern States Power Co 82/08/02 KEPPLER, J G Region 3, Office of Director 4pp 14276, 145 24X Fiche. 50-282, 82/08/02, 82081000B0
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" But list enci JORDAN E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000 82/08/05 8204210407
- 8208240037 Forwards Franklin Research Ctr request for add1 info re 81130 response to IE Bulletin 80-11: "Mesonry Halls " Info requested within 30 days CLARK.R A Operating Reactors Branch 3 82/08/12 HUSOLF.D K Northern States Power Co 5pp 14548 185 24X Fiths. 50-282: 82/08/12: 8208240037.
- R Periodic operating reports & related correspondence
- B20B270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON-J M Division of Rules end Records B2/07/13 UDELL,R A Critical Mass Energy Project Bpp 14679 208 24X Fiche: 50-000: 82/07/13.820B270010
- --B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBL." * NRC No Detailed Affiliation Given 82/07/13 48pp 14679,216 24% Fiche 50-000:82/07/13.8208270010
- --B208270307 Forwards annual rept of occupational radiation exposures for CY81.per 10CFR20. 407
 SCHUELKE.D. A. Northern Btates Power Co. 82/02/02 Office of Nanagement and Program Analysis ip 14477 282 24X
 Ficha: 50-000, 82/07/13, 8208270010.
- --8209270219 Annual occupational radiation exposure rept for CYBI 4 Northern States Power Co 82/02/02 ip 14679 283 24% Fichs 50-000,82/07/13,8208270010.
- B208270619 Forwards rept on number of personnel & man rem by work & job function for (98).per NUREG-0737.Item II K 3 3 MAYER.L D. Northern States Power Co B2/02/26 KEPPLER.J G Region 3. Office of Director in 14679 342 24X Fiche 50-000,82/07/13.8208270619.
- --- 8208270626 Rept on number of personnel & man rem by work & job function For 1981
 For 1981
 For 1981
 Northern States Power Co 82/02/26 2pp 14679 343 24X
 Fiche 50-000, 82/07/19, 8208270619
- 820813019B Forwards monthly operating repts for Jul 1982 MUBOLF,D. Northern States Power Co 82/08/10 Director's Office, Office of Inspection and Enforcement 1p, 14339 105 24X Fichs. 30-282,82/08/10.8208130198
- --8208130202 Monthly operating repts for Jul 1982 DUGBTAD.D. Northern States Power Co 82/08/04 8pp 14339:106 24X Fiche: 50-282, 82/08/10, 8208130198
- B. Reportable occurrences: LERs & related correspondence
- 8208090259 Forwards LER 92-012/03L-0 KUSDLF, D. Northern States Power Co. 82/07/30 Region 3, Office of Director 1p. 14270 345 R4X Fiche. 50-304, 82/07/30, 8208090259
- --8208090267 LER 82-012/03L-0 on 820702 radiation monitor sample return isolation valve gave dual (open/closed) indication Cause not determined Valves will be cycled periodically HURSTAD.A A. Northern States Fower Co 82/07/20 Region 3, Office of Director. Ip 14270 346 24X Fiche 50-306.82/07/30, 8208090289

- 8208310017 Forwards LER 82-013/03L-0 MUSDLF,D Northern States Power Co 82/08/18 Region 3, Office of Director 1p 14694 360 24X Fiche 50-306,82/08/18,8208310017
- --8208310025 LER 82-013/03L-0 on 820719, pressurizer steam space sample isolation valve, CV-31303, would not close on demand Cause unknown Valve inaccessible during operation Repairs will be made during shutdown Manual valve in penetration closed HUNSTAD, A A Northern States Power Co 82/08/18 Region 3, Office of Director 1p 14694 361 24X Fiche 50-306, 82/08/18, 8208310017

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

- F Becurity, medical, emergency & fire protection plans
- 8208040314 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/07/20 Document Management Branch ip 14231 156, 24X Fiche 50-309.82/07/20, 82/08/0314
- --B208040317 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure 2 50 0, "Declaration & Categorization of Emergency Condition " Receipt form encl * Haine Yenkee Atomic Power Co 82/07/09 Office of Nuclear Reactor Regulation, Director 1p 14231 157 24X Fiche 50-304,82/07/20,8208040314
- -8208040319 Public version of Revision 3 to Emergency Plan Implementing Procedure 2 50 0. "Declaration & Categorization of Emergency Condition " Revised table of contents encl * Maine Yankes Atomic Power Co. 82/07/09 27pp 14231 158 24X Fiche 50-309, 82/07/20, 8208040314
-)8060246 Urgss participation in 820818 meeting w/Bureau of Civil Imergency Preparedness of ME & FEMA to discuss state of ME radiological incident plan EMITH.0 H Division of Emergency Preparedness & Operational Support 82/08/03 ORIMES.8 K Division of Emergency Preparedness 2pp 14241-315. 24X Fichs 50-309,82/08/03,8208040246
- -- 3208050251 Requests that NRC representative attend 820818 meeting in Augusta, ME to discuss State of ME radiological incident plan THOMAS, E. A. Federal Emergency Management Agency 82/07/26 MGUNAS, E. Region I, Office of Director 1p 14241 317 24X Fiche 50-309, 82/08/03, 8208050246
- **NBITO362 Releases public version of revised emergency plan splementing procedures to the procedures of Rules and Records B2/08/10 Document agement Branch ip #4373 001 24% Fiche: 50~309, B2/08/10, B170362
- .8170364 Forwards public version of revised emergency plan implementing procedures, including Procedures 2 50 2 replent 2 50 3 resite area smergency 8 2 50 4 regeneral emergency plant shift supervisor Receipt form encl.

 * Maine Yankee Atomic Pawer Co 82/07/30 Office of Nuclear Reactor Regulation, Director 2pp 14373 002 24X Piche 50-309, 82/08/10, 8208170362
- 208170366 Public version of revised emergency plan implementing procedures; including Procedures 2 50 2 re elert, 2,50 3 re site area emergency & 2 50 4 re general emergency plant shift supervisor e Maine Yankee Atomic Power Co 82/07/27 150pp 14373,004 24% Fiche 50-309,82/08/10,8208170362
- 18250000 Exemption from requirements of App R to 10CFR50, Bertion II 0 3 b re installation of fixed fire suppression sys in ontrol room
 URPLE,R.A Division of Licensing 82/08/11 Haine Yanker tomic Power Co 5pp 1455; 348 24X Fiche. 50-309, 82/08/11, 208250025

Q Adjudicatory correspondence

- 8208090331 Advises that Commissioner Roberts will visit plant on B20807 Due to time restrictions intervenors will not accompany Commissioner Intervenors probably will be allowed to visit plant in conjunction w/ASLB review ZECH, 0 0 Commissioners B2/08/03 AMREMS, P Maine, State of MILLER, D B Miller, D S ip 14219 360 24X Fiche 50-309, 82/08/03, 8208050331
- 8208240263 Notice of Bensible ME Power change of address Certificate of Svc enc! HILLER.D B Sensible Maine Power 82/08/20 ip 14527 129 24X Fiche 50-309.82/08/20,8208240263
- P Operating license stage documents & correspondence
- 8207080064 Generic 1tr to all licensees of operating plants, applicants for OL & holders of GP re Commission approved charter for CRGR Svc list enc!
 BIRCKS.W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 COL 24X Fiche 50-000,82/07/02,8207080064
- 8208030060 Forwards Amend 61 to License DPR-36, safety evaluation & notice of issuance & availability Amend increases required number of operable safety injection actuation signal sensors
 NELSON, C C Operating Reactors Branch 3 82/07/14 QARRITY, J H Haine Yankes Atomic Power Co 3pp 14200, 323 24X Fiche 30-309, 82/07/14, 8208030060
- --8208030063 Amend 61 to License DPR-36, increasing required number of operable safety injection actuation signal sensors & establishing training dept & other organizational changes CLARK, R A Operating Reactors Branch 3 82/07/14 9pp 14200 326 24K Fiche 50-309, 82/07/14,8208030060.
- --8208030065 Safety evaluation supporting Amend 61 to License DPR-36
 * Office of Nuclear Reactor Regulation, Director 82/07/14 59
 14200 335 24% Fiche 50-309.82/07/14.8208030060
- --8208030070 Notice of issuance & availability of Amend 61 to License DPR-36 CLARK.R A Operating Reactors Branch 3 82/07/14 2pp 14200.340 24X Fiche 50-309, 82/07/14,8208030060
- 8208040094 Forwards request for add1 info needed to review environ qualification of safety-related equipment CLARK.R A Decrating Reactors Branch 3 82/07/16 OARRITY.J H Haine Yankes Atomic Power Co 4pp 14228 333 24X Fiche 50-309, 82/07/16, 8208040094
- 8208090028 Forwards Tech Spec Page 5 2-3 (Figure 5 2-2), inadvertently omitted from 820714 package forwarding Amend 51 to License DPR-36, establishing separate training dept NELSON, C C Operating Reactors Branch 3 82/07/21 GARRITY, J H Haine Yankes Atomic Power Cs 2pp 14283 360 24X Fiche 50-309, 82/07/21, 8208090028
- --8208090030 Tech Spec Page 5 2-3 Figure 5 2-2) establishing separate training dept & other organization changes Page inadvertently omitted from original transmittal + Operating Reactors Branch 3 82/07/21 ip 14283 342 24% Fiche 50-309,82/07/21,8208090028
- 8208050145 Forwards rept of preliminary findings re insulation debrid matl studies being performed at Alden Lebs Rept provided to assist in insulation or debris control changes NELSON.C.C. Operating Reactors Branch 3 82/07/22 GARRITY.J H Maine Yankes Atomic Power Co 12pp 14243 026. 24X Fiche 30-309.82/07/22,8208050145
- 8208040645 Forwards technical note. "Status Rept on Quantitative Safety Quals." to provide understanding of NRC basis for Part 50 App I, Section II D valves to be used in cost benefit analysis re population dose HEITNER.K.L Operating Reactors Branch 3 82/07/23 GARRITY.J H Maine Yankee Atomic Power Co 7pp 14224 051 24X Fiche 50-307,82/07/23,8208040645
- 8208050356 Advises that util will respond to 820713 request for schedule for TMI post-accident sampling sys, post-implementation review by 830301 GARRITY.J H. Maine Yanker Atomic Power Co. 82/08/02 CLARK.R A Operating Reactors Branch 3. Ip. 14237 300 24X Fiche: 50-309. 82/08/02. 8208050356

- CSICOJS7 Advises that control element assembly drop transient will be reamalyied for menon burnout effects Results will be institled w/Gycle 7 reload analysis ARRITY.J H Haine Yankee Atomic Power Co B2/0B/03 CLARK,R A Instaling Reactors Branch 3 ip 14297 25; 24x Fiche 50-309, 82/0B/03, 8208100087
- .GLOO222 Forwards "Valve Inlet Fluid Conditions for Pressurized Safety & Relief Valves.ME Yankee Power Station." per request for addition for respecific test Condition justification for safety & relief valves (ASRITY.JH Maine Yankee Atomic Power Co. 82/08/05 CLARK.R A Corrating Reactors Branch 3 19 14297 015 24X Fishes 90-309, 82/08/05,8208100222
- -2203100227 "Valve Inlet Fluid Conditions for Pressurizer Bafety & Relief Valves, ME Yankes Power Station" + Haine Yankes Atomic Power Co 82/07/31 24pp 14297 016 24x Fiche 50-309, 82/08/05, 8208100222
- INTECO428 Notification of 820819 meeting w/util in Betheada. MD to discuss small-break LOCA models being developed for facility in accordance w/NURGE-0737. Item II K 3 30 KSLSQN.C C Sperating Reactors Branch 3 82/08/05 CLARK, R A Operating Reactors Branch 3 82/08/05 CLARK, R A Operating Reactors Branch 3 82/08/05 CLARK, R A Fiche. 30-307.82/08/05.8208230421
- CMIOCOO4 Provides info re control element assembly bank mode be changes to analytical methods utilized in design & analysis of Cycle 7 reload core Control element assembly ejection aralysis physics input encl
 GARRITY, J H. Haine Yankee Atomic Power Co. 82/08/06 CLARK, R A
 Cystating Reactors Branch 3 12pp 14297 171 24X
 Fiche 50-309, 82/08/06, 8208100304
- 43B090194 Generic Ltr 82-14 to all reactor licentees, holders of CP & applicants re submittal of documents to NRG Summarises 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISERCHUI, D 0 Division of Licensing. 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- 108160070 Forwards add1 into re containment purging & venting when not in cold shutdown or refueling mode, in response to 820321 request info provided re debris screens, time limitation for on line purge & B-inch globe valve GARRITY, J H Maine Yankee Atomic Power Co 82/08/10 CLARK, R A Cperating Reactors Danch 3 3pp 14342 051 24X Fache 30-309, 82/08/10, 8208160070
- 3208170128 Forwards add1 into re available equipment to achieve & raintain hot shutdown & emergency power sys periodic testing requested during 820617 meeting 8 820625 telcon OARRITY.J H Mains Yankee Atomic Power Co 82/08/11 CLARK.R A Operating Reactors Branch 3 4pp 14365 230 24X Fiche 80-307.82708/11.8208170128
- 820B180045 Forwards grogram plan rept for conducting detailed control room design review per NUREG-0700. "Quidelines for Control Room Design Reviews " Program serves as basis for providing human factors enpineering input on long-term basis W/o encl GARRITY. J H: Maine Vankee Atomic Power Co. 82/08/12 CLARK.R A Operating Resctors Dranch 3 pp. 14376 212 24X Fichs 30-309.82/08/12.8208180045
- \$2083|0261 Forwards addl info on NUREO-0612 re control of heavy loads, including info re safe load paths, load handling procedures, crams operator training, lifting devices, crams & crams detign GARRITY, J H. Maine Yankes Atomic Power Co. 82/08/27 CLARK, R A. Operating Reactors Branch 3. 45pp. 14688 195 24X Fichs 30-309, 82/08/27, 8208310261
- 620B310380 Notifies that facility already required to rept failures or malfunctions of pressurizer, steam generator & relief valves promptly, per NURGO-0737. Item II K 3 3 GARRITY, J, H Maine Yankse Atomic Power Co 82/08/27 CLARK, R. A Operating Reactors Branch 3 ip 14692 109, 24X Fische 50-309, 82/08/27, 8208310380
- O Imagection reports, IE Bulletins & correspondence

- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JURDAN, E L Division of Engineering & Quality Assurance 82/07/19 Michigan
- 8208020279 Forwards IE insp Rept 50-309/82-09 on 820608-0707 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 82/07/19 RANDAZZA.J B Maine Yankee Atomic Power Co 2pp 14152 247 24X Fiche 30-309.82/07/19.8208020279
- --8208020265 1E Insp Rept 50-309/82-09 on 820608-0707 No noncompliance noted Major areas inspected control room, turbine primary auxiliary & spray bldgs & auxiliary feed pump room SWETLAND, P. GALLO, R. Division of Project & Resident Programs 82/07/16 9pp 14152 249 24X Fiche 80-309, 82/07/19, 8208020279
- 6204210396 |E Info Notice 82-25. "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list and I JORDAN E L Division of Engineering & Quality Assurance B2/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Ficha 50-000, 82/07/20, 8204210396
- B204210397 IE Info Notice 82-24. "Hater Leaking From U Hexafluoride Overpacks " Syc list encl CDBDL I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 27 24X Fiche 50-000.82/07/20,9204210397
- 8204210398 IE info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 11200 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Orinding in Vicinity of Orsined & Open 808 " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of Abew York 122pp 14380 115 24% Fiche 50-000, 82/07/23.8204210401
- B2042i0402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Bupport Pin Failures at Westinghouse PHRs " Svc list encl. JURDAN.E L. Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000. B2/07/23,82042i0402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PMR Power Plants " Syt list enci JORDAN, E L Division of Engineering & Guality Assurance 62/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24% Fichs 50-000, 82/07/26, 8204210403
- 8208190001 Advises that util analysis performed in response to 1L Bulletin 60-04 re main steam line break w/continued feadwater addition acceptable Safety evaluation encl CLARK, R A Operating Reactors Branch 3 82/07/26 GARRITY, J H Haine Yankee Atomic Power Co 2pp 14806 280 24x Fiche 30-309, 82/07/26,8208190001
- ---R20Bi90004 Rafety evaluation supporting util analysis of main steam line break w/continued feedwater addition (IE Bulletin 80-04)

 # Office of Nuclear Reactor Regulation, Director 82/07/26 7pp 14506 282 24x Fichs 50-309,82/07/26,820Bi90001
- --9206280418 *PHR Main Steam Line Break H/Continued Feedwater Addition (8-69)." technical evaluation rept VOBBURY-F.# Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05506-132. 82/06/23 HEARN,P NRC No Detailed Affiliation Given 22pp 14506 289 24X Fiche 50-309,82/07/26,8208190001
- 8204210405 IE Info Notice 82-31. "Over-sposure of Diver During Work in Fuel Storage Fool " Svc IIst anc! JORDAN, E L Division of Engineering & Quality Assurance B2/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche: 50-000, 82/07/28, 8204210405
- 8208020383 Ack receipt of 820412 Itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-309/81-26 Response withheld (ref 10CFR73 21) MARTIN,T T. Division of Engineering & Technical Programs 82/07/29 RANDAZA,J B Maine Yankee Atomic Power Co 2pp 14150 065. 24% Fichs: 50-309, 82/07/29, 8208020383.

- 8208080410 Act receipt of 620707 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/81-16
 SHITH G H Division of Emergency Preparedness & Operational Support 82/07/29 RANDAZZA-J D Maine Vankee Atomic Power Co 1p 14217 337 24x Fiche 50-309, 82/07/29, 8208050410
- ~-8208050416 Responds to NRC 520609 ltr re violations noted in IE Insp Rept 50-309/Bi-16 Corrective actions plant operations review compittee reviewed & approved Teledyne procedures for analysis of 57-89/90 GARRITY. J H Hains Yanke Atomic Power Co 82/07/07 HAYNES R C Division of Emergency Preparedness & Operational Support 2pp 14217 340 24X Fiche 50-309, 82/07/29, 8208050410
- 8208100009 Responds to Item 3 of IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCP8 of PNR Plants" Info provided revalve body to bonnet leakage & corrective actions taken RANDAZZAJB Haine Yankee Atonic Power Co 82/07/30 HAYNES,R C Region I. Office of Director 3pp 14296 345 24X Fiche 50-309.82/07/30.8208100005
- 8204210407 IE Info Nutice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement ' Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14368 201 24X Fiche 50-000.82/08/05,8204210407
- 8208140141 Act receipt of 820730 itr informing NRC of steps taken to correct violations noted in IE insp Rept 50~309/81-14
 SYAROSTECKI.R Division of Project & Resident Programs 82/08/11
 ARIOALIA.J B Maine Yankee Atomic Power Co ip 14344 176 247
 Fiche 50~309.82/08/11.8208160141
- --B20B160143 Responds to NRC ltr re violations noted in IE Insp Rept 50-309/B1-14 Corrective actions battery backup power supply for security equipment will be installed & operational by and of 1982 refueling outage OARRITY.J H Maine Yansee Atomic Power Co B2/07/30 HAYNES,R c Region 1, Office of Director 2pp 14344 177 24X Fiche 50-309.82/08/ti.8208160141
- 8208190283 Supple 620730 response to IE Bulletin 82-02, "Dagradation of Threaded Fasteners in RCPB of PHR Plants" Breakdown of constituents of Fel-Pro N-5000 & Furmenite Nuclear F-700-N lubricants used in RCPB submitted GARRIEVI, H Maine Yankee Atomic Power Co 82/08/13 HAYNES,R C Region 1. Office of Director 4pp 14500 082 24X Fiche 50-309,82/08/13,8208190283
- '208230263 Forwards request for addl into re 820528 IE Insp Rept 50-309/82-05 & weaknesses in mgt control of design change & reporting activities, per 10CFR50 54 Weakness exists in manner to which responses to correspondence prepared HAYKES.R C Region 1. Office of Director 82/08/19 RANDAZZA, J B Haine Yankes Akonic Power Co 3pp 14510 320 24X Fiche 50-309, 82/08/19, 8208230263
- /208240388 Ack receipt of 820611 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/82-04 MARTIN, T T Division of Engineering & Technical Programs 82/08/20 RANDAZZA, J B Maine Yanhee Atomic Power Co 2pp 14524 068 24X Fich 50-309, 82/08/20, 8208240388
- --B20B240392 Responds to NRC B20421 ltr re violations noted in IE Insp Rept 50-309/82-04 Corrective actions review of mgt control sys being conducted to identify procedural & programmatic weaknesses RANDATIA.J B Maine Yankee Atomic Rower Co B2/06/JI HAYNES:R C Region 1. Office of Director Spp 14524 070 24X Fithe 50-309,82/08/20,8208240388
- R Periodic operating reports & related correspondence
- 8208120128 Forwards monthly operating rept for June 1982 GROCE,R H Maine Yantee Atomic Power Co 82/07/09 Management Information Branch 1p 14323 277, 24X Fiche 50-309, 82/07/09, 8208120128
- 3208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear gower plants & analyzing said info Forwards documents listed in App A FELTON.0 H Division of Rules and Records 82/07/13 UDELL.R A Critical Hass Energy Project 8pp 14679 208 24X Fiche 50-000.82/07/13.8208270010

- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBI" e NRC - No Detailed Affiliation Given 82/07/13 Adap 14679 216 24% Fiche 50-000,82/07/13,82082/0010
- --8208270526 Forwards number of individuals by whole body, range reptin 1981, per 10CFR20-407(b) OARRITY, J. H. Maine Yankee Abomic Power Co. 82/03/03 - (Iffice of Management and Program Analysis - Ip. 14680-024 - 24X Fiche 50-000.82/07/13.8208270010
- ---8208270330 Number of individuals by whole body, range rept for 1981 4 Maine Yankee Atomic Power Co 62/03/03 ip 14680 025 24 Fiche, 50-000, 82/07/13, 8208270010
- S Reportable occurrences. LERs & related correspondence
- 8208260547 Forwards LER 81-002/03L-0 W00B.E.C. Matne Yankee Atomic Power Co. 81/04/14 Region 1. Philadelphia. Office of the Director (81/03/01) ip 14372 331 24X Fiche 50-309, 81/04/14, 8208260947
- --B20B260555 LER 81-002/03L-0 on 810318, svc air isolation to containant failed Redundant equipment available Caused by inadequate lubrication tubrication mati applied to valve linkage BRINKLER.J E Maine Yankee Atomic Power Co 81/04/14 Region. Philadelphia. Office of the Director (81/03/01) lp 14572 332 24X Fiche 50-309, 81/04/14/820B260547
- 8208050459 LER 82-019/01T-0 refueling water storage tank temp streeded temp assumed in safety analysis Steps taken to reduce temp to permitted levels WOODE C Maine Yankee Atomic Power Co 82/07/16 Region 1, Office of Director, 1p 14216 335 24X Fiche 50-309, 82/07/16, acceptions
- 8208050315 Forwards LER 82-020/03L-0 WOOD E C Mains Yankse Atomic Power Co 82/07/20 Region 1. Office of Director IP 14237 320 24X Fichs 50-309.82/07/20, 8208050315
- --8208050337 LER 82-020/03L-0 on B20622, procedure change rept not reviewed by plant operations review committee within 14 days of generation Caused by rept being misplaced Method of handling repts changed per 820627 & 27 moetings PAINE.W J Meine Vankee Atomic Power Co 82/07/20 Region 1, 07fice of Director 2pp 14237 321 24X Fiche 80-307, 02/07/20, 82808050315
- 8208020328 LER 82-019/01T-0 on 8207t6, discovered low pressure safety injection pumps NPSH consideration 86 f may be appropriate upper temp limit for refueling water storage tank Tank temp will remain below 86 f until complete analysis accomplished HODDE C Mains Yankee Atomic Power Co 02/07/21 Region 1. Office of Director 1p 14151:145 24x fiche 30-309,82/07/21.
- 8208050513 Forwards LER 82-018/03L-0 WQQD,E C Maine Yankee Atomic Power Co 92/07/23 Region 1, Office of Director 1p 14213 275 24X Fichs 50-309,82/07/23. 8208050513
- --B20B030526 LER 62-018/03L-0 on B20707, while performing quarterly surveillance testing, RCB loop fill & drain header cross tip valve failed to open Cause unknown due to inaccessibility of valve Valve cycled once per wk for 1 month PAINE, W J. Maine Yankee Atomic Power Co B2/07/23 Region 1, Office of Director 2pp 14213 276 24X Fiche 50-309, B2/07/23, B208050513.
- 8208090072 Forwards LER 82-019/017-0 WOOD, E. C. Mains Yankee Atomic Power Co. 82/07/29 HAYNEB, R. C. Region 1, Office of Director is 14270 J31 24X Fiche 50-309, 82/07/29, 8208090072
- --B20B090076 LER 82-019/01T-0 on 820715 refueling water storage tank treexceeded temp assumed in safety analysis Investigation indicated that BS F is appropriate interim upper temp limit to maintain low pressure safety injection pumps NPSH PAINE, W J Maine Yankee Atomic Power Co B2/07/27 Region 1. 0ffice of Director 2pp 14270 332 24X Fiche 50-309,82/07/29, 8208090072,
- 8208100170 LER 82-021/01T-0 based on review of C-E owners group training mat), discovered that if dropped control rod not expeditiously retrieved, further increase in planer radial peaking may occur Control rod drop procedure revised WOOD, E.C. Maine Yankee Atomic Power Co., 82/07/30. Region J. Diffice of Director ip 14298 233 24X Fiche 50-309, 82/07/30.

- &xe200202 Forwards LER 82-021/01T-0 #CODE C Maine Yankee Atomic Power Co 82/08/11 HAYNES,R C Pagion 1, Office of Director 1p 14513 348 24X //che 50-309,82/08/11,8208230202
- -\$208230210 LER 82-021/01T-0 on 820729, potential increase in planar radial peaking discovered Caused by local xenon burnout in core areas away from dropped rod resulting in violation of fuel design limits Drop procedure revised BRINKLER, J C Maine Yankee Atomic Power Co 82/08/11 Region 1. Office of Director 2pp 14813 346 24X Fiche. 50-309, 82/08/11.8208230202
- 2X6230186 Forwards LER 82-022/03L-0 WCD.E C Maine Yanker Atomic Power Co 82/08/13 Region 1, 0ffice of Director 1p 14513 356 24X Fiche 50-309, 82/08/13, 8208230186
- --8208230194 LER 82-022/03L-0 on 820714, during testing of automatic bus transfer switch, return from alternate power to normal power was not accomplished within required time frame Caused by failure of Agastat time dolay relay Delay relays replaced BRINKLER.U E Maine Yankee Atomic Power Co 82/08/13 Region 1, Office of Director 2pp 14513 357 24X Fiche 50-309, 82/08/13.8206230486
- EX8260271 LER 82-023/01T-0 on MN-82-165. Cycle 6 main steam line break analysis did not take into account potential increase in caferator defect reactivity addition if cold leg temp is higher than programmed valve WCOD. E C Maine Yankee Atomic Power Co 82/08/19 Region 1, Office of Director ip 14552 362 24X Fiche 50-309, 82/08/19, 8206260271.
- OCYET 50-31: SALEM NUCLEAR GENERATING STATION, UNIT 2

 F Operating license stage documents & correspondence
- P207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of GP re Commission approved charter for CRGR Svc list encl
 DIRCKS.H J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194 OOL
 24X Fiche 50-000,82/07/02,8207080064
- 8208030101 Requests submittal documenting compliance w/criteria in NURE2-0737. Item II B 3. "Post-Accident Sampling Bys "Criteria & guidelines to conduct NRC review encl VARQA. & A Operating Reactors Branch 1 82/07/12 UDERITZ. R A Public Service Electric & Gas Co of New Jersey 10pp. 14176 354 24% Fiche 50-272.82/07/12.8208030101
- 820805002; Notification of B20726 meeting w/util in Hencocks Bridge,NJ to review component fouling problems associated w/entrainment of American cystems & review status of ETB R059. N J Operating Reactors Branch 1 82/07/19 VAROA, 8 A Operating Reactors Branch 1 2pp 14244 3B4. 24X Fiche 30-272,82/07/19,8208060021
- 8208040453 Forwards Amonds 45 & 10 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability, Amends provide undervoltage protection to satigated a safety features actuation instrumentation sys. PDSS: N J Operating Reactors Branch 1. 82/07/23 UDERITZ.R A Public Service Electric & Oss Co. of New Jersey 2pp 14220-263 24% Fiche: 30-272,82/07/23,8208040453
- --6208040458 Amends 45 & 10 to Licenses DPR-70 & DPR-75, respectively, providing undervoltage protection to emergency safety features actuation instrumentation sys VAROA: 8 A Operating Reactors Branch 1 82/07/23 12pp 14220 265. 24X Fiche 50-272.62/07/23.8208040453.
- --820804046i Safety evaluation supporting Amenda 45 & 10 to Licenses DPR-70 & DPR-75. respectively. • Office of Nuclear Reactor Regulation. Director 14220 277. 24X Fiche. 50-272. B2/07/23. 8208040453
- --9208040464 Notice of issuance & availability of Amends 45 & 10 to Licenses DPR-70 & DPR-75 respectively. VAHOA, 8 A Operating Reactors Branch I 82/07/23 2pp. 14220;279. 24X Fiche.50-272.82/07/23.8208040453.
- 820B170036 Forwards revised Tech Spec Pages 3/4 5-6 & 3/4 5-6s to Asends 44 & 8 to Licenses DPR-70 & DPR-75, respectively Effective requirement in footnote inadvertently deleted RDSS, N J Operating Reactors Branch 1 B2/07/23 UDCRITZ, R A Public Service Electric & Oas Co of New Jersey 2pp 14373.332, 24% Fiche 50-311,82/07/23,820B170056

- --8208170059 Revised Pages 3/4 5-6 & 3/4 5-6a of Amends 44 & 8 to Litenses DPR-70 & DPR-75, respectively, re-automatic isolation & interlock of RHR sys from RCS & Office of Nuclear Reactor Regulation, Director 82/07/23 2pp 14373 334 24X Fiche 50-311,82/07/23,8208170056
- 8208090293 Advises that based on review of util control sys failure analysis, events postulated in FSAR Chapter 14 adaquately bound consequences of single control sys failures. Unresolved Safety Issue A-47 will address control sys designs VARQA:8 A Operating Reactors Branch 1 82/07/29 UDERITZ.R A Public Service Electric & Qas Co of New Jersey 2pp 14307 104. 24X Fiche 50-311, 82/07/29, 8208090293
- 8208110096 Advises that shift supervisor engineer considered to be acceptable equivalent to shift technical advisor, per util 820616 request Tech Spet should be revised accordingly. VARGA.8.A Operating Reactors Branch 1 82/07/29 UDERITZ.R A Public Service Electric & Oas Co of New Jarsey. 2pp 14329 361 24% Fiche 50-272.82/07/29.8208110096
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl.
 EISENNUT.D O Division of Licensing 82/08/09 Consolidated Edison Co of New York Ip 14356:332 24X Fiche 50-000.82/08/09, 8208090194.
- 820825019B Responds to NRC 820712 ltr re post-accident sampling/post-implementation review Post-accident sampling sys for each unit expected to be installed & operational prior to startup following upcoming refueling outage LIDEN.E A Public Service Electric & Oas Co of New Jersey 82/08/13 VAROA:B A Operating Reactors Branch 1. ip 14541.330, 24X Fiche 50-272,82/08/13,8208250198,
- B20B250097 Forwards summary of responses to NRC B20720 request for addition of auxiliary fredwater pump endurance test, as discussed in B20B1B conference call.

 LIDEN,E A Public Service Electric & Qas Co of New Jersey B2/08/18 VARQA,B A Degrating Reactors Branch i 2pp 14540 349 24X Fiche 50-272,82/08/18,8208250097
- G Inspection reports. IC Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Bteam Isolation Valve (MSIV) Lafage " Svc list enc! JURDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York. 87pp. 14356 274. 24X Fiche, 50-000, 82/07/16, 8204210393
- 8204210395 IE 1nfo Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19 Michigan, Univ of 112pp 14358 001, 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure" Evo list encl.

 JORDAN.E L. Divinion of Engineering & Quality Assurance. 82/07/20 Consolidates Edison Co. of New York. 112pp 14381 001 24X Fiche, 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hezafluoride Gverpacks " Byc list encl. COBB:L. I Division of Fuel Facilities, Meterials & Safeguards 82/07/20. Consolidated Edison Co of New York. 71pp 14357, 276 24% Fiche: 50-000, 82/07/20, 8204210397.
- 8204210398 IE lneo Notice 82-25, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Evc list encl.
 JURDAN, E.L. Division of Engineering & Quality Assurance. 82/07/22
 Consolidated Edison Co. of New York 112pp. 14174 321. 24X
 Fiche 50-000 82/07/22 8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Stained & Open RCS " Svc list encl.
 URBOAN E. L. Division of Engineering & Quality Assurance Consolidated Edison Co of New York. 122pp. 14380:115 24X
 Fichs. 50-000.82/07/23.8204210401
- 8204210402 IE Info Notice 82-29, "Control Red Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co of New York. 127pp 14194-120 24% Fiche 50-000,82/07/23,8204210402

- BZ04210403 (E Info Notice B2-30, "Loss of Thermal Sleeves in RCB Piping at Cartain Westinghouse PMR Power Plants " Svc list encl JORGAN.E L Division of Engineering & Quality Assurance BZ/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fische 30-000.B2/07/26 8204210403
- E208020112 Responds to B20420 request for add1 info on postulated main sterm line break inside containment (IC Bulletin 80-04) Add1 analysis beyond design basis not necessary LIDEN,E A Public Service Electric & Qas Co of New Jersey 82/07/26 VARÇA: S A Operating Reactors Branch I 2pp 14142 106, 24X Fichs 50-000,82/07/26,8208020112
- 8204210405 IE Info Notice 82-31, "Overesposure of Diver During Work in Fuel Storage Pool " Svc list ancl JORDAN.E L Division of Engineering & Guality Assurance 82/07/28 Consolidates Edison Co of New York 122pp 14357 146 24% Fichs 50-000.82/07/28,8204210405
- 8208100162 Responds to Action Item 1 of 1E Bulletin 82-02 red degradation of threaded fastoners in RCPB of PMR plants All work performed within confires or RCPB is accomplished per approved written maint procedures & vendor manuals LIDEN, E.A. Public Service Electric & Gas Co. of New Jersey 82/07/29 Deroung, R.C. Director's Office. Office of Inspection and Enforcement 3pp. 14278-030 24% Fiche 50-272,82/07/29,8208100162
- 8208060153 Act receipt of 820624 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-311/81-23 MARTIN.7 T Division of Engineering & Technical Programs 82/07/30 UDERITION A Public Service Electric & Oas Co of New Jersey ip 14240 036 24X Fiche 50-311.82/07/30.8208060153
- --E208060158 Responds to NRC 820526 ltr re-violations noted in 1E Inap Rapt 30-311/81-23 Corrective actions alarm setpoints of R-19 tlowdown radiation monitor reset w/o defeating automatic features during initial moisture carryover test UDERITI.R A Public Service Electric & Gas Co of New Jersey 82/06/24 HAYNES.R C Region I. Office of Director 3pp 14240 037 24x Fiche 50-311,82/07/30.8208060153
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement" Svc list enti URBOAN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 9208300300 Forwards IE Insp Repts 50-272/82-17 & 50-311/82-17 on 820707-0803 & notice of violation STAROSTECKIR Division of Project & Resident Programs 82/08/12 USCRIFICH & Public Service Electric & Gas Co of New Jersey 2pp 14673 201 24X Fiche 50-272.82/08/12.8208300300
- *208300317 lE Insp Repts 50-272/82-17 & 50-311/82-17 on 820707-0803 Noncomp[lance noted no incident rept prepared for failure of vital ventilation control ctr feeder breaker IC on 820823 NORRHOLM, J. SUMMERS.R., TRIPP.LE Division of Project & Resident Programs 82/08/10 13pp 14673 205 24X Fiche 50-272,82/08/12,9208300300
- G3(0358 Act receipt of 820804 ltr informing NRC of steps taken to oract violation noted in IE Insp Repts 50-272/82-14 & 0-311/82-14 7AROSTECKI:R Division of Project & Resident Programs 82/08/26/06RITZ:R A Public Service Electric & One Co. of New Jersey. [p. 14492-123 24X Fichs 50-272:82/08/26.8208310359
- Pariodic operating reports & related correspondence
- 208270010 Responds to FOIA request for documents detailing collective dots esposures in 1981 for operating nuclear power plants & analysing said into Forwards documents listed in App A FELTON. J. Division of Rules and Records 82/07/13. UDELL,R,A Critical Mays Energy Project 8pp 14679 208 24X Fiche 50-000,82/07/13,8208270010
- -8208270586 Forwards errata to "Number Personnel & Man Rem by Job Function Rept for CyBi." personnel exposures ZUPKO, J M Public Bervice Electric & Oas Co of New Jersey 82/02/23 HAYNES.R C Region 1. Office of Director 2pp
- --8208270389 Errata to "Number Personnel & Man Rem by Job Function Rept for GY81" - Public Bervice Electric & Gas Co of New Jarsey 82/02/23 4pp 14679 322 24X Fiche 50-000, 82/07/13, 8208270010

- 8208160048 Forwards monthly operating rept for Unit 2 for Jul 1982 Also forwards corrected monthly operating repts for Unit 1 for Har. Apr. Hay & June 1982 MIDURA: H J Public Service Electric & Cas Co of New Jursey 82/08/10 Director's Office, Office of Inspection and Enforcement 10 14344 233 24X Fichs 90-272, 82/08/10, 8208160048
- --8208160049 Monthly operating rept for Jul 1982 MILLER, L K Public Bervice Electric & Gas Co of New Jersey 82/08/10 23pp 14044 234 24% Fiche 90-272,82/08/10,8208160048
- 8208300217 Forwards NPDES discharge monitoring rapts for Jul 1981 MILLER, L. R. Public Service Electric & Gas Co. of New Jorsey 82/08/18 BAKER, R. A. Environmental Protection Agency 2pp 14677 010 24X Fichs 50-272, 82/08/18, 8208300217
- --8208300219 NPDEE discharge monitoring repts for Jul 1982 MILLER,L K Public Service Electric & Gab Co of New Jorsey 82/08/18 17pp 14679 012 24% Fiche 50-272,82/08/18,8200300217
- S Reportable occurrences. LERs & related correspondence
- 8208020353 forwards LER 82-058/03L-0 Detailed event analysis and i MIDURALH J. FRAHM,R Public Service Electric & Oas Co of New Jarsey 82/07/21 HAYNES,R C. Region I. Office of Director Sp; 14150 112 24X Fiche 50-311,82/07/21.8208020353
- --B208020399 LER 82-058/03L-0 on 820702, svc water flow to containment fan coil unit 23 less then amount required for low spend operation Caused by oysters plugging valve Oysters removed Development of chlorination program in progress FRAHM. R Public Service Electric & Gas Co of New Jersey 82/07/21 Region I, Office of Director ip 14150 115 24X fiche 50-311,82/07/21,8208020393
- G208050097 Forwards LER 82-057/03L-0 Detailed event analysis encl MIDURA:H J Public Service Electric & Cas Co of New Jersey 62/07/21 HAYNES,R C Region 1. Office of Director Jrp 14213.187. 24x Fiche 30-31; B2/07/21, B208050077
- --8208050077 LER 82-057/03L-0 on 820630, foodwater pump 27 tripped cousing operator to reduce turbine load & commence control rod insertion Caused by decrease in suction pressure associated wiplacing feedwater heater 26 in svc FRAHM. Public Service Electric & Gas Co of New Jarsey 82/07/21 Region 1, Office of Director ip 14233 170 24X Fiche 50-311,82/07/21,8208050077
- 8208050368 Forwards LER 82-036/03L-0 Detailed event analysis encl MIDURAL H J Public Service Electric & Oas Co of New Jersey 82/07/21. HANNES,R G Region 1. Office of Director App 14207 155 24X Fiche 30-311,82/07/21,8208050368.
- --8208050380 LER 82-056/03L-0 on 820701, personnel discovered inner dopr seal leskage in 100-ft elevation containment air lock Caused by door slamming, forcing seal out of proper position Geal regositioned FRAHM.R. Public Service Electric & Gas Co of New Jorgey 82/07/21 Region 1, Office of Director 1p 14209, 139 24X Ficher 50-911, 82/07/21, 8208050368
- 8208130214 Forwards LER 82-059/03L-0 Detailed event analysis encl Hipora, H J. Public Service Electric & Oas Co of New Jersey 82/08/04. HAYNES, R C Region 1. Office of Director App 14333 023 24X Fiche: 50-311, 82/08/04, 8208130214
- --B208130219 LER B2-059/03L-0 on B20706.during warmup of main steam lines, steam generator safety valve 23MS15 lifted below satepoint Cause undetermined valve gagged shut & power range trip setpoints raduced. Investigation continuing FRAMM, R Public Service Electric & Gas Co. of New Jersey 82/08/04, Region 1, Office of Director ip 14333 027 24X Fiche 50-311.82/08/04,8208130214.
- 8208190003 Porwards LER 82-066/03L-0 Detailed event analysis encl MIDURAH H. J. Public Service Electric & Oas Co. of New Jersey 82/08/04, HAYNES, H. J. Region 1, Office of Director 3pp 14383 210 24X Fiche 50-311,82/08/04,8208190003
- --8208170011 LER 82-066/03L-0 on 820720, during monthly channel functional test for steam generator 21 steam flow channel II.high trip setpoint exceeded Tech Spec. Caused by failed capacitors Capacitors replaced FRAHM.R Public Service Electric & Gas Co of New Jersey 82/08/04 Region 1. Office of Director 1p 14383 213 24X Fiche, 50-311, 82/08/04, 8208190003.
- 6208190113 Forwards LER 82-065/03L-0 Detailed event analysis encl MIDURA: H J. Public Service Electric & Qas Co of New Jersey 82/08/04, HAYNES: R C Region 1, Office of Director 3pp 14382,184, 24X Fiche 50-311.82/08/04.8208190113

- --8208190118 LER 82-045/03L-0 on 820720, zero svc water flow to containment fan coil Unit 24 discovered during surveillance testing Caused by failure of actuator on valve 245M223 Rod and bearing assembly replaced FRAM4.R Public Service Electric & Gas Co of New Jarsey 82/08/04 Region 1, Office of Director. Ip 14382 187 24X Fichs 50-311,82/08/04,8208190113
- 2208190127 Forwards LER 82-067/03L-0 Detailed event analysis encl HIDURALH J Public Service Electric & Gas Co of New Jersey 82/08/04 HAYNES,R C Region I, Office of Director 3pp 14381 128 24X Fichs 50-311.82/08/04.82081
- --8208190133 LER 82-067/03L-0 on 820720, during channel testing, control room operator discovered that steam generator 24 feedwater channel 2 flow indication was operating erratically Caused by failure of flow transmitter Transmitter replaced PELLER, Public Service Electric & Cas Co of New Jersey 82/08/04 Region 1. Office of Director 1p 14381 131 24X Fiche 80-311,82/08/04.8208190127
- 220B19013B Forwards LER 82-062/03L-0. Detailed event analysis encl HIDURA.H J Public Bervice Electric & Qas Co of New Jeraey 82/08/04 HAYNEB.R C. Region I. Office of Director 3pp 143B1 080 24X Fiche: 50-311,82/08/04,820B1
- --820B190144 LER 82-062/03L-O on 820715, discovered that annual cycling of testable automatic valves in fire suppression sys not garformed since 810116 Caused by failure to issue new grocedure due to prematurally canceled computer insp order HELLER.R. Public Bervice Electric & Qas Co of New Jersey. 82/08/04 Region 1 Office of Director ip 14381.083 24X Fiche 50-311,82/08/04,8208190138.
- 920G190143 Forwards LER 82-053/03L-0, Detailed event analysis encl HIDURA.H J Public Service Electric & Oas Co of New Jersey 92/09/04 MAYNESI.R C. Region 1. Diffice of Director 3pp 14381 035 24X Fichs. 50-311.02/08/04.8208190143
- --8208190149 LER 82-063/03L-0 on 820718,4-kV supply breaker 21 A8D tripped open, demensfyiling 2A vital bus, starting 2A diesel generator & demensfyiling bus loads, Caused by failed card fite assembly Assembly replaced FRAMIR Public Service Electric & Gas Co of New Jersey, 82/08/04 Region i, Office of Director ip, 14381 038 24X Fiche 50-311,82/08/04,8208190143
- 8208190165 Forwards LER 82-064/03L-0. Detailed event analysis encl. HIDWRAH J Public Service Electric & Oas Co. of New Jersey 82/08/04 HAYNES,R C Region 1, Office of Director Spp 14381 039 24X Fiche 50-311, 82/08/04, 8208190165
- --8208190166 LER 82-064/03L-0 on 820717.ECC8 heat tracing circuits 2610A & 26088 found reading less than Tach Specs Caused by broken wire in circuit 2610A control panel. Mire trimmed & reconnected & heat tracing circuit replaced FRANH.R Public Service Electric & Oas Co of New Jersey 62/08/04 Region in Office of Director. ip 14381:042. 24X Fiche: 50-311, 82/08/04, 8208190165
- 820B190216 Forwards LER B2-061/03L-0, Detailed event analysis encl. MfDVRA-H J Public Service Electric & Oas Co of New Jersey. B2/08/04 HAYNEB.R C Region 1. Office of Director. Spp 14386 085. 24X Fiche 50-311.B2/08/04.B20B190216
- --8208190230 LER 82-061/03L-0. on 820716, control operator noticed that 21 steam generator level channel II indication was erratic, rendering channel inoperable Caused by leakage past packing on root velve 218728. Valve repacked & channel recalibn. FRAMM.R. Public Service Electric & Oas Co of New Jersey B2/08/04. Region 1. Office of Director, ip 14384 088 24X Fiche 50-311,82/08/04.8208190216
- 8209300056 LER 82-070/01P: on 820809, during routing power operation, syc water leak discovered inside containment bldg on containment fen coil 24 at 0 5 gpm Leak isolated Investigation in progress.

 B1DURA: H. J. Public Service Electric & Gas Co. of New Jersey.
 82709/10, HAYNES: R G. Region 1, Office of Director ip.
 14578 310 24X Fiche. 50-311, 82/08/10, 8208300056.
- 8208240395 Forwards LER 82-068/03L-0. Detailed event analysis and M1DJRA, H J. Public Service Electric & Qas Co. of New Jersey. 82/08/12 HAYNES, R. C. Region 1. Office of Director. Spp 14322, 332. 24X Ficher 50-311, 82/08/12, 8208240395
- --B208240399 LER 82-068/03L-0.on B20722.control room operator raceived Indication of malfunction of containment plant monitoring tys Gaused by improper screw adjustment resulting in binding of Channel 2RilA filter paper Screws adjusted.

 MELLER.R. Public Bervice Electric & Gas Co. of New Jersey.
 B2/06/12. Region 1. Office of Director 1p. 14522,355. 24X
 Fiche: 59-311,82/08/12.8208240395.

- 8208260137 Forwards LER 82-069/03L-0 Detailed event analysis encl MIDURA.H J Public Service Electric & Gas Co of New Jersey B2/08/12 HAYNES,R C Region 1, Office of Director 3pp 14554 353 24% Fiche 50-311, B2/08/12, 8208260137
- --B20B2&0141 LER 82-0&9/03L-0*on B20724, control operator observed erratic operation of reactor coolant pump 23 flow channel III Caused by flow transmitter ferrite slug failure. Failed transmitter replaced & channel recelibr.

 FRAMMIR Public Bervics Electric & Gas Co of New Jersey, B2/08/12 Region 1, Office of Director ip 14554,356, 24% Fiche: 5C-311,82/08/12.820B2&0137
- 8208300330 LER 82-073/01P on 820813.syc water leak discovered inside containment bldg on containment fan coil unit 23.at rate of approx 1.5 gpm Leak isolated Investigation in progress Detailed rept will be submitted per IE Bulletin 80-24 HIDURA-H J Public Service Electric & Oas Co of New Jersey 82/08/13 HAVMESR C Region 1.0Price of Director ip. 14579.078 24% Fiche 50-311.82/08/13.8208300330.
- 8208300206 LER 82-075/0if on B20814 & 15, avc water leaks discovered on containment fan coil units 22 & 24 Cause undetermined Investigation in progress Detailed rept to be submitted MIDURA, H J. Public Service Electric & Gat Co of New Jersey. 82/08/16 HAYNES-R C Region i. Office of Director ip 14596 056. 24X Fiche 50-311,82/08/16.8208300206
- 8208300208 LER 82-074/01P.on 820813.svc water leak discovered on containment fan coil unit 25 Cause undetermined. Investigation in progress Detailed rept to be submitted MIDURA.H J. Public Service Electric & Gas Co. of New Jersey 82/08/16. HAYNES, R. C. Region 1. Office of Director ip 14678 245 24X Fiche 50-311.62/08/16.8208300208
- 8208300095 LER 82-077/01P, on 820818, svc water leak discovered inside containment blig on containment fan coil unit 21 Gause under investigation Leak isolated.

 MIDURA, H J Public Service Electric & Gas Co. of New Jersey, 82/08/18 HAYNES, R.C. Region 1, Office of Director ip 14597-152 24X Fiche 50-311,82/08/18,8208300095.
- 8208300227 Forwards LER 92-070/01T-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Oas Co of New Jersey 82/08/18 HAYNES,R.C Region 1. Office of Director App 14679 058. 24% Fichs 50-311.82/08/18.8208300229
- --BR0B300233 LER B2-070/01T-0 on B20B09,0 5 gpm svt water leak observed on containment fan coil unit 24. Caused by failed cooling coil due to erosion from sitt particles in svc water Leakage stopped by blanking flanges in lines to coils.

 FRAMMIR. Public Bervice Electric & Qas Co of New Jersey 82/08/18 Region in Office of Director 1p. 14679 062 24X Fiche 50-311,82/08/18.8208300229.
- 8208310180 Forwards LER 62-075/01T-0 Detailed event analysis encl MIDURA,M.J Public Service Electric & Oas Co. of New Jersey 82/08/18 HAYNEG,R C, Region 1, Diffice of Director. App 14674:348. 24X Fiche 50-311.82/08/18.82
- --8208310153 LER 82-075/01T-0:on 820814.1 gpm svc water leat discovered on containment fan coil unit 22 Cause not stated. On 820815; similar leat discovered on unit 24 Unit 22 repaired by blanking flanges in svc water piping to coil FRAHM. R. Public Service Electric & Gas Co. of New Jersey 82/08/18. Region i. Office of Director ip. 14694 352 24X Fiche 30-311,82/08/18.8208310150
- 6208310271 Forwards LER 82-073/01T-0 Detailed event analysis encl. HIDURA,H J. Public Service Electric & Oss Co. of New Jersey 82/08/18 HAYNES.R C Region 1. Office of Director 4pp 14688:132 24K Fiche 50-311.82/08/18,8208310271.
- --8208310274 LER 82-073/017-0:on 820813, control operator observed increased leakage to containment sump Caused by failed cooling coil resulting from erosion by silt particles in svc water Leak repaired widelicon metal filler FRAHM, R. Public Service Electric & Gas Co. of New Jersey. 82/08/18 Region 1, 0ffice of Director 1p, 14688:156, 24X Fiche: 50-311,82/08/18,8208310271.
- 8208310318 Forwards LER 82-074/01T-0. Detailed event analysis encl. HIDURA: H.J.: FRAHM: R Public Service Electric & Gas Co of New Jarsey 82/08/18, HAYNES: R.C. Region 1, Office of Director. App. 14693: 203. 24X Fiche: 50-311, 82/08/18, 8208310318.
- --B20B310322 LER 82-074/01T-0: on B20B13, lesiage to containment sump increased Caused by cooling coil failures resulting from srosion by silt particles in svc water Leak repaired by blanking flanges in lines to coil FRAHM.R. Public Service Electric & Gas Co of New Jersey B2/08/18. Region 1, Office of Director. 1p 14693,207. 24X Fiche 30-311,82/08/18,820B310318

- 8208310395 Forwards LER 82-060/03L-0 Detailed event analysis ancl MIDURA:H J Public Service Electric & Oas Co of New Jersey 82/08/18 HAYMEGR C Region 1. Office of Director 4pp 14694 297 24X Fiche 50-311.02/08/18.0208310395
- --8208310400 LER 82-060/03L-0 on 820722, level accumulators 24 & 23 determined balow operating band & declared inoperable Caused by drift of level indications Sightglase indications installed on both accumulators HELLER, R Public Service Electric & Gas Co of New Jersey 82/08/18 Region 2, Office of Director ip 14694 301 24X Fiche 50-311,82/08/18.8208310395
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

 F. Security, medical, emergency & fire protection plans
- 820B160114 Forwards Amend 10 to physical security plan Amend withheld (ref 100FR2 790)

 MAMMOND, M J Sacramento Municipal Utility District 82/07/21

 NRC No Detailed Affiliation Given ip. 14345 227 24X

 Fiche 50-312, 82/07/21, 8208160114
- 8208260431 Requests written statement re statum of operability of prompt notification sys & basim for util conclusion that mechanism in place meets requirements of 10CFR30.App E Rept should be submitted at least 1 wk prior to startup DEYOUNGR C Director's Office. Office of Inspection and Enforcement 82/07/30 NALBRIDGE, N C 9acramento Nunicipal Utility District 3pp 14394 179 24X Fiche 50-312,82/07/30.8208260431.
- 8208090078 Forwards Revision 4 to security training & qualification plan & summary of reasons for changes Revision withheld (ref 10CFR2, 790)

 HAMMOND.H J Sacramento Hunicipal Utility District 82/08/02

 STOLZ.J F Operating Reactors Branch 4 ip 14269 355 24x

 Fiche 50-312,82/08/02,8208090078.
- 8208240284 Forwards IE Insp Rept 50-312/82-03 on 820622-25 No noncompliance noted 800K:HE Division of Radiological Safety & Safeguards Program 82/08/03 MATTIMOE.J J Sacramento Municipal Utility District 4pp 14527:139 24X Fiche 50-312.82/08/03.8208240284
- --8208240288 lE Insp Rept 50-312/82-03 on 820622-25 No honocompliance noted Major areas inspected emergency plan exercise & associated critiques
 FISH.R F. O'BRIEN, J. WENSLAWSKI, F.A. Division of Rediological Safety & Bafeguards Program 82/08/02 7pp 14527 143 24X Fiche 50-312,82/08/03,8208240284
- 8208130183 Submits info re status of prompt notification sys, in response to 820730 request Deficiencies found after sys activation bn 820430 corrected. Additesting verified sys operability
 Operability
 MATTIMOS. J Bacramento Municipal Utility District 82/08/10
 DEYOUNG, R G Director's Office Office of Inspection and Enforcement 2pp 14338 316 24% Fiche 50-312,82/08/10,8208130183
- 8208180117 Forwards Emergency Plan Procedure AP 525,per NRC 820812 request MATTIMOE, J J Sacramento Municipal Utility District 82/08/13 EISENMUT, D Q Division of Licensing. 3pp 14378,150 24X Fiche, 50-312, 82/08/13, 8208180117
- --8208180122 "Rancho Seco Emergency Plan Procedure AP 525," Revision 1.
 # Sacramento Municipal Utility District 82/06/16 15pp.
 14378 153 24X Fiche 50-312,82/08/13,8208180117
- @ Adjudicatory correspondence
- 8208090328 Board Notification 82-75 presents initial results of precursor program which uses LERs to evaluate potential nuclear plant accident precursors occurring at operating reactors info relates to eccident probability NOVAK, T.M. Assistant Director for Operating Reactors. 82/07/21. Atomic Safety and Licensing Appeal Panel. 17pp 14307, 347 24X Fiche 50-312, 82/07/21, 8208070328
- 8208130149 Notifies that facility will reach criticality by 820821 Because of uncertainties re length of heatup cycle.licensee cannot provide precise schedule for plant criticality Cartificate of Bvc enci BAXTER.T A Shaw, Pittmen, Potts & Trowbridge BAXTER.T.A Sacramento Municipal Utility District 82/08/10, ROBENTHAL, A.S Atomic Bafety and Licensing Appeal Panel, BUCK, J. H., KOHL, C.N. Atomic Safety and Licensing Soard Panel 4pp. 14339-045, 24X Ficher 80-312, 82/08/10, 8208130149

- 8208180103 Summarizes 820813 telcon w/ASLAB re questions posed to licensee & NRC concerning sua sponte review of Initial Decision LBP-81-12 & adequacy of modes required by NRC 790507 order Licensee expects reactor to become critical on 820818 BAXTER.T A Shaw, Pittman, Potts & Trowbridge BAXTER.T A Sacramento Municipal Utility District 82/08/16 R05ENTHAL.AS. 8UCK.J H. KOHL,C N Atomic Safety and Licensing Appeal Panel 4pp 14378 277 24X Fiche 50-312.82/08/14.8208(80103)
- S20B240297 Summarizes & confirms NRC response to ABLAB questions in B20B13 teleon S How affidavit on NRC HPI notale analysis of thermal cycles & ML Padovan affidavit on missing thermal sleeve encl
 BLACK, R L Hearing Branch 3 92/08/18 ROSENTHAL, A S , KOHL, C N , BUCK, J H Atomic Safety and Licensing Appeal Panel 3pp 14520 192 24X Fichs 50-312, B2/08/18, B208240297
- --B208240300 Forwards S How affidavit re NRC HPI nozzle analysis of thermal cycles per ASLAB 820813 request for status rept KNIGHT, J P Assistant Director for Components & Structures Engineering 82/08/17 BLACK/R L Hearing Branch 3 ip 14920 193 24X Fiche 50-312,82/08/18,8208240297
- --8208240302 Affidavit of S Hou re current status of NRC HP3 notals analysis NRC review 50% complete Design code provisions used as basis for evaluation & general analystical methodology employed appropriate Prof qualifications encl HOU.B Mechanical Engineering Branch 82/08/17 3pp 14520,176 24X Fichs 50-312,82/08/18,8208240297
- --8208240320 Forwards ML Padovan affidavit re HPI notile thermal sleaved supplying supplemental info to UF Stols 820421 testimony in response to ASLAB 820415 memorandum & order LAINAS.0 C Assistant Director for Operating Reactors 82/08/17 BLACK.R L Hearing Branch 3 ip 14520 199 24X Fiche 30-312,82/08/18,8208240297
- --8208240326 Affidavit of ML Padovan supplying supplemental info to JF Stolz 820421 testimony NRC concurs w/licensee analysis on loose thermal strave Degraded thermal straves replaced w/new sleave design to assure sleeve retention on noizle PADDVAN,M L. Operating Reactors Branch 4 82/08/17 7pp 14520 200 24X Fiche 50-312,82/08/18,8208240297
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS M J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 008 24X Fiche 50-000.82/07/02.8207080064
- 8208030741 Requests schedule for submitting supplemental ECCB calculations, which may be generic to other B&W plants & which may employ offsetting margins derived from compensating models
 NOVAM.T M Assistant Director for Operating Reactors 82/07/13
 MATTIMOE.J J Sacramento Municipal Utility District 5pp
 14196 347 24X Fiche, 50-312, 82/07/13, 8208030741
- 9208020181 Application to amend License DFR-54, consisting of Revision 2 to proposed Amend 51 revising Tech Spec 3 7 1, I re min switch/yerd voltage H/Class III amend fee MATTIMOE. J Sacramento Municipal Utility District 62/07/16 EISENHUT. D. 0 Division of Licensing 1p 14141 034 24X Fiche: 50-312, 82/07/16, 8208020181
- --8208020183 Proposed Tech Spec 3 7 1 I re min switchyard voltage * Becramento Municipal Utility District 82/07/16 2pp 14141 035 24X Fiche 50-312,82/07/16,8208020181,
- 820B030420 Responds to NRC 820721 request for addl info re TMI Action Item II E.1.2 concerning auxiliary feedwater sys flow indication. Currently installed indicator will be replaced w/ssfety grade differential pressure flow indicator.
 MATTIMDE, J. J. Sacramento Municipal Utility District 82/07/27
 BTOLZ, J.F. Operating Reactors Branch 4 1p 14154 217 24%
 Fiche: 50-312.82707/27,8208030420
- 8208040001 Responds to NRC 820711 telcon re annunciation of manual bypass of auxiliary feedwater auto initiation New control sys will annunciate in control room when auxiliary feedwater auto initiator is bypassed MATTIMCE, J J Sacramento Municipal Utility District 82/07/27. STOLZ, J F Operating Reactors Branch 4 ip 14193 217 24x Fiche 50-312,82/07/27,8208040001

- OBO30278 Application for Amend 82, Revision 1 to License DPR-54, correcting typographical errors in Tech Spec Table 4 14-1 & eddressing temporary use of mechanical snubbers on steam generator external auxiliary feedwater header hadranter acternal auxiliary feedwater header Secremento Municipal Utility District 82/07/28 EIBENRUF,D Q Division of Licensing 1p 14158 120 24X Fiche 50-312,82/07/28,8208030278
- 8208030300 Corrected Tech Bpec Table 4 14-1 re surveillance stds of anubbers during power operations

 * Sacramento Municipal Utility District 82/07/28 2pp
 14:198 | 121 | 24% Fiche 50-312,82/07/28,8208030298
- OB240005 Forwards safety evaluation concluding requirements of MUREO-0737, Items II F 1 4, II F 1 5 & II F 1.6 re containment monitoring resolved STQLZ, J F Operating Reactors Branch 4 82/07/28 MATTIMOE, J J Sacramento Municipal Utility District 12pp 14529 227 24X Fiche 50-312, 82/07/28, 8208240005
- OB240030 Board Notification 82-71 forwarding rept re feed & bleed cooling of reactor core upon loss of feedwater to steam generators Rept submitted in response to 820429 request LAINAS, Q C Assistant Director for Operating Reactors 82/07/30 Atomic Bafety and Licensing Appeal Panel 17pp 14529,095 24X Fiche 50-312,82/07/30,8208240030
- OBO 40208 SOCIDECONDMIC IMPACTS OF NUCLEAR GENERATING STATIONS, RANCHO SECO CASE STUDY Docket No. 50-312 (Sacramento Municipal Utility District)
 BERGMAN, P. A. Mountain West Research, Inc. * Social Impact Research, Inc. FIN 8-6268 NUREO/CR-2749 VO9 82/07/31
 Division of Health, Biting & Environment 226pp Available at NTIS, 67, 50, 14235 102 24X Fiche 50-312,82/07/31,8208040208
- OB120029 Forwards justification for extension of exemption from 10CFR50, App H, "Reactor Vessel Matl Burveillance Program" requirements Exemption granted on 771020 Categorized as Class III request MALBRIDGEN C Sacramento Municipal Utility District B2/08/02 SECLZ, J. Operating Reactors Branch 4 7pp 14324 066 24KF\$Che 50-312, 82/08/02, 8208120029
- CBOA0163 Forwards BAM-1732, "Evaluation.Repair & Replacement of Damaged Internal Auxiliary Feedwater Header at Davis Besss 1. Occures 3 & Rancho Beco." per 820624 meeting w/RRC in Bethseda: HD & NRC 820623 request Response summary submitted. WALBRIDGE.W C Bacramento Municipal Utility District 82/08/03 STOLZ.J F Operating Reactors Branch 4. 8pp 14238-089 24X Fichs 50-000,82/08/03,8208060163
- B208060168 "Evaluation, Repair & Replacement of Damaged Internal Auxiliary Faedwater Header at Davis Besse 1. Oconee 3 & Flancho Seco " # Bebcock & Wilcox Co BAW-1/32 82/07/01, 32pp 14238.097. 24x Fiche 50-000, 82/08/03, 8208060163
- OBIO013B Advises that present Tech Specs re reactor vessel math irradiation are valid Limits will be modified before expiration to account for ongoing irradiation & to extend applicability period Continued plant operation acceptable MALBRIDGE W C Sarramento Municipal Utility District 82/08/04 STOLZ, J F Operating Reactors Branch 4 2pp 14298,016, 24X Fiche 50-312,82/08/04,8208100138
- 08250471 Forwards identification of IAEA representatives requesting 820B18 visit to svc spent fuel storage pool camera & examine guel accountability records Identification withheld STOLZ, J.F. Operating Reactors Branch 4 82/08/05 MATTIMOE, J.J. Bacramento Municipal Utility District Spp. 14562,267 24X Fiche, 50-312, 82/08/05, 8208250471
- 08250476 Concludes commitments & exceptions to requirements of Reg Ouide 1 58, Revision 1 & Reg Ouide 1.146 acceptable, per util 810731 response to generic Ltr 81-01 STYCLE, JF Operating Reactors Branch 4 82/08/05 MATTIMOE, J. J. Bacramento Municipal Utility District 4pp 14562 263, 24X Fiche: 50-312, 82/08/05, 8208250476
- OBO 70174 Ceneric Ltr 82-14 to all reactor licensees; holders of CP & applicants re submitted of documents to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl. EISENHUT, D Q. Division of Licensing. 82/08/09, Consolidated Edison Co of New York. 1p. 14356:332 24X Fiche:50-000,82/08/09,8208090174
- OB230293 Advises that schedule for response to NUREO-0737, Itam II.B.3, "Post-Accident Sampling Bys," will be provided by 821001, in response to 820712 ltr MATTIMOE, J J Bacramento Municipal Utility District 82/08/10. STOLZ, JF. Operating Reactors Branch 4 ip 14509, 335, 24X Fiche: 50-312, 82/08/10, 8208230293.

- 8208200027 Bubmits startup schedule following auxiliary feedwater 20820004/ Buomits startoy state of the second of the secon
- 8208160425 Formalizes proposals made at 820720 meeting re scope of program for resolution of NUREG-0737. Item II K. 3.30, "Revised Small Break LGCA Methods to Show Compliance w/100FR50.App K " Followup Itr expected within 3 wks. MATTIMOE. J. J Bacramento Municipal Utility District 82/08/12 DENTON.H R GPfice of Nuclear Reactor Regulation. Director Sp. 14356 157 24X Fiche: 50-312,82/08/12,8208160425.
- --8208160431 "GERDA General Test Specs" * Babcock & Wilcox Co 82/02/28 42pp 14356 162, 24X Fiche 50-312,82/08/12,8208160425
- --8208160435 "Overview of GERDA Test Facility." * Bebrock & Wilcox Co 12-1132517. 82/03/31 24pp 14356:204. 24X Fiche 50-312,82/08/12,8208160425.
- -8208160443 "Research Plan to Assess Dynamic Response of Scaled BtW Reactor Model " KIAN9.R L SRI International 82/08/12 13pp 14356 228 24X Fithe 50-312.82/08/12.8208160425
- 8208170145 Submits corrected startup schedule for unit following auxiliary feedwater header repair Ltr dtd 820811 should be disregarded AATTIMDE, J. J. Bacramento Municipal Utility District 82/08/12 EISENNUT, D 0 Division of Licensing 1p 14364 273 24X Fiche 50-312, 82/08/12, 8208170165
- 8208230185 Advises that info re supplemental ECGS calculations will be submitted by 830214 in response to NRC 820713 ltr MATTIMOE.J J. Sacramento Kunicipal Utility District 82/08/12 NOVAN, T M Assistant Director for Licensing 1p 14514 339. 2016
- 8208250303 Forwards addl info requested at 820813 meeting in Hashington DC re-cracks known to exist in internal auxiliary feedwater headers resouver massers MATTHOE,J J. Bacramento Municipal Utility District B2/08/16. STDLZ,JF Operating Reactors Branch 4 7pp 14538 073 24% Fiche 50-312,82/08/16.8208250303
- 8208230250 Advises of agreement w/NRC to test auxiliary feedwater header mods Test to include full flow test & observations to detect water hammer Tests constitute final util action required to receive 100% power approval
 MATTIMDE, J. J. Batramento Municipal Utility District 82/08/17
 EISEMUNT.D 0 Division of Licensing 1p. 14508 357 24X
 Fiche 50-312,82/08/17.8208230250
- 8208240377 Describes auxiliary feedwater mod test referred to in util 820817 itr Purpose of test is to verify no feedwater hammer problems exist MATTIMOE, J J Sacramento Municipal Utility District 82/08/18 EISENHUT, D Q. Division of Licensing ip. 14522 361 24X Fichs. 50-312, 82/08/18, 8208240379
- B20B300:36 Advises that addl info to complete Generic Item B-24 & NUREO-0737: Item II E 4 2, "Containment Isolation Dependebility," will be provided by B21001, per 820629 request L L.30MITTAM MATTIMOE, J J Sacramento Municipal Utility District 82/08/1 BTOLZ, J F Operating Reactors Brench 4 ip 14579 165 24% Fiche 50-312, 82/08/19, 8209300136 82/08/19
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV)
 Leakage " Svc list encl
 JORDAN, E. L Division of Engineering & Quality Assurance. 82/07/16
 Consolidated Edison Co. of New York. 87pp 14356:274 24X
 Fiche 50-000, 82/07/16, 8204210393.
- 8204210395 IE Info Notice Bi-26, Part 3, Suppl i, "Clarification of Piacement of Personnel Hunitoring Devices for External Radiation." Svc list encl.

 JORDAN, E. Division of Engineering & Guality Assurance. 82/07/19,

 Michigan Univ. of 112pp. 14358 001 24X Picke: 50-000, 82/07/19
 8204210395.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure." Evo list encl Upon URDAN, E. L. Division of Engineering & Quality Assurance, 82/07/20, Consolidated Edison Co of New York. 112pp 14381:001 24X Fiche: 50-000, 82/07/20, 8204210396.

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPC1 Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explusion While Grinding in Vicinity of Drained & Open RCS " Evo list encl JORDAN. E.L. Division of Engineering & Quality Assurance. 82/07/23, Consolidated Edison Co. of New York 122pp 14380.115 24X Fiche 50-000.82/07/23,8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Syc list encl JORDANIE L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche. 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Bvc list encl JORDAN.E L Division of Engineering & Quality Assurance. 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fichs 50-000, 82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Oversiposure of Diver During Work in Fuel Storage Poul " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 62/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000. 82/07/28.8204210405
- 8208160069 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners on RCPB of FMR plants " Valves in which Molykote 0 lubricant, Fel-Prog-N-100 lubricant & injected sealant mati used identified Table of bolted closure data encl MATIMOE. J J Sacramento Municipal Utility District 82/07/28 ENGELKEN, R H. Region 5. Office of Director 12pp 14942 039 24x Fiche 50-312, 82/07/28.8208160069
- 8208160118 Forwards IE Insp Rept 50-312/82-20 on 820510-14 & notice of violation BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 82/07/29 HATTIMOE,J J Sacramento Municipal Utility District 2pp. 14349 302 24X Fiche 50-312,82/07/29,8208160118
- --B20B160120 Notice of violation from insp on B20510-14 ECKHARDTJ H Division of Resident. Reactor Project & Engineering Programs B2/07/29 2pp 14349 304 24% Fichs 50-312,82/07/29, 820B160118
- --8208160123 IE Insp Rept 50-312/82-20 on 820510-14. Noncompliance notes. Gilson shater & screens used by onsite testing lab for performing coarse aggregate tests found out of calibr. HERNANDEZ.O., ECKHARDT.J H. Division of Resident, Reactor Project & Engineering Programs 82/07/20 Spp. 14349 306 24X Fiche 50-312.82/07/29.8208160118
- 9208100310 Forwards response to 820722 request for addl info re method used in masonry wall analysis, per IE Bulletin 80-ii Component factor method more conservative than SRP method WALBRIDDE, H.C. Bacramento Municipal Utility District 92/07/30 STGL7.J F Operating Reactors Branch 4 App. 14297 165 24X Fiche 50-312, 82/07/30, 8208100310
- 8208160527 Forwards IE Insp Rept 50-312/82-27 on 820721-23, No noncompliance noted.

 STERNBERG,D M Division of Resident: Reactor Project & Engineering Programs. 82/08/02 MATTIMOE, J. J. Sacramento Municipal Utility District. 2pp. 14356-148 24X Fiche, 50-312, 82/08/02, 8208160527
- --8208160530 IE Insp Rept 50-312/82-27 on 820721-23 No noncompliance noted Major areas inspected bulletins & circulars.unresolved items & open items
 8TEWART.J P., YOUNG.T Division of Resident. Reactor Project & Engineering Programs 82/07/30. 5pp. 14356-150. 24X Fiche. 50-312, 82/08/02, 8208160527
- 8208160500 Forwards IE Insp Rept 50-312/82-29 on 820629-0702.No noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs. 82/08/03 MATTIMOE.J.J Sacramento Municipal Utility District 4pp 14348:258 24X Fiche: 50-312,82/08/03,8208160500

- --8208160509 IE Insp Rept 50-312/82-29 on 820629-0702 No noncompliance noted Major areas inspected mods & repair activities associated w/steam generator auxiliary feedwater headers & HPI norzie/makeup lines HERNANDEZ, G , ECKHARDT, J H Division of Resident, Reactor Project & Engineering Programs 82/07/30 4pp 14348 262 24% Fiche, 50-312, 82/08/03, 8208160500
- 8208230244 Suppls 820728 response to IE Quiletin 82-02, "Degradation of Threaded Fasteners in RCPB of PMR Plants," consisting of results of chemical analysis of Molykote G used on reactor coolant pump 8 fasteners
 MATTIMGE, J J Sacramento Municipal Utility District 82/08/03 ENGELKEN, R H Region 5, Office of Director 2pp 14508 349 24X Fiche 50-312, 82/08/03, 8208230244
- 8208240284 Forwards IE Insp Rept 50-312/82-03 on 820422-23 No moncompliance noted BODK.H E Division of Radiological Safety & Safeguards Program 82/08/03, MATTIMOE.J J Bacramento Municipal Utility District 4pp 14527 137 24% Fiche 30-312,82/08/03,8208240284
- --B20B2402BB IE Insp Rept 50-312/B2-03 on B20622-25 No noncompliance noted Major areas inspected emergency plan exercise & associated critiques FIBH: RF: 0'BRIEN.J: WENBLAWSKI.FA Division of Radiological Safety & Bafeguards Program 62/08/02 7pp 14527 143 24% Fiche 50-312,82/08/03.8208240284
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN: E L Division of Engineering & Quality Assurance 82/08/09 Consolidated Edison Co of New York 117pp 14388.201, 24% Fiche, 50-000, 82/08/05, 8204210407
- 8208250054 Forwards summary statement of IAEA insp activity & facility attachment for review & determination of whether info can be publicly released Encl withheld (ref 10CFR2 790) BTOLZJJ. F Operating Reactors Branch 4 82/08/06 MATTIMOE, J J Sarramento Municipal Utility District 3pp 14559 173 24X Fithe: 50-312, 82/08/06, 8208250054
- 8208270221 Responds to IE Bulletin 81-02 suppl, "Feilure of Oate Type Valves to Close Against Differential Pressure " No Westinghouse Electro-Mechanical Div valves installed or maintained as spares No further response necessary HATTIMOE, J J Bacramento Municipal Utility District 82/08/10. ENGELKEN,R. H. Region 3. Office of Director 1p 14567 018 24% Fiche. 50-312, 82/08/10. 8208270221
- 8208270226 Responds to IE Bulletin 81-01, "Surveillance of Mechanical Shubbers" No mechanical shubbers installed on safety-related sys Requested action unnecessary MATTIMDE, J J Secremento Municipal Utility District 82/08/10 ENGELKEN, R M Region 5, Office of Director 1p 14567 017 24X Fiche 50-312,82/08/10,8208270226
- 8208270339 Responds to IE Bulletin Bi-O3, "Flow Blockage of Cooling Water to Bafety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus Bp (Mussel) "No evidence of subj species found.

 MATTIMOE, J J Bacramento Municipal Utility District 82/08/10.
 ENOELKEN, R, H Region 5, Office of Director 2pp 14564 298 24X Fiche 50-312,82/08/10,8208270339
- 8208270338 Responds to 820804 request re IAEA insp rept Info can be released to public MATTIMOE, J J Bacramento Municipal Utility District 82/08/17 870L2, J F Operating Reactors Branch 4 lp. 14564 297 24X Fiche 50-312,82/08/17,8208270338
- R. Periodic operating reports & related correspondence
- 820B270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J.M Division of Rules and Records B2/07/13 UDELL.R A Critical Mass Energy Project Bpp 14679.20B 24X Fiche 50~000,82/07/13.8208270010
- --B208270098 "Annual Hhole Body Dose At Licensed Nuclear Power Facilities for CYGI"

 * NRC No Detailed Affiliation Given. 82/07/13 48pp 14679-216. 24% Fiche: 50-000, 82/07/13, 8208270010.
- B20B190265 Forwards monthly operating rept for Jul 1982 RDDRIGUEZ/R, J. Bacramento Municipal Utility District B2/08/05 Director's Office: Office of Inspection and Enforcement 2pp 14387.314 24X Fiche: 50-312, 82/08/05, 8208190265.

- \$208170270 Monthly operating rept for Jul 1982 COLOMBO, 8, EDMAR05, J. Sacramonto Municipal Utility District 62/08/07 13pp 14387 316 24X Piche 50-312.82/08/05.8208190265
- : Fagortable occurrences, LERs & related correspondence
- . GO20201 Forwards LER 82-015/03L-0 Detailed event analysis submitted MATTHMOR, J J Bacramento Municipal Utility District 82/07/14 Region 5. Office of Director 2pp 14141 001 24X facks 50-312.82/07/14.8208020201
- -920902020 LER 82-015/03L-0 on 820624, during maint procedure on B inverter, power lost momentarily to B bus & decay heat reboval sys Caused by technician maint error Procedures will be rewritten to enhance personnel communication COLOMBO.R W Sacremonto Municipal Utility District 82/07/14 Region 5. Office of Director 1p 14441 003 24X Fiche 50-312, 82/07/14, 8208020201
- MCG20257 Forwards LER 82-016/04T-0

 FATTIMOE, J.J. Sacramento Municipal Utility District. 82/07/19

 EWSELKEN, R.H. Region 5, Office of Director. 19. 14152-331, 243

 Ficha. 30-312.82/07/19.8208020257
- -8208020262 LER 82-016/04T-0 on 820713, effluent chlorine level exceeded Fech Spec min Caused by leaking chlorine injection pump Dilution flow increased & pump repaired COLOMBOR W Sacramento Municipal Utility District 82/07/19 Region 5, Office of Director 1p 14152 332 24X Fiche 50-312,82/07/19,8208020257
- E332200R12 Forwards LER 82-017/97X-0 Detailed event analysis submitted HATTIMOE, J J Bacramento Municipal Utility District 82/08/03 ENGELKENR H Region 5, Office of Director 3pp 14399, 267 24X Fiche 50-312, 82/08/03, 8208200212
- --B20B200224 LER 82-017/99X-0 on 820715 four broken bolts discovered on reactor bidg polar crane rail holddown clips Hammer impact test revealed add1 if failed bolts Apparently caused by high tycle fatigue Bolts will be replaced COLOMBD.R W Sacramento Municipal Utility District 82/07/20 Region 5. Office of Director 1p 14399 270 24X Fiche 50-312,82/08/03,8208200212
- 6208200135 Forwards LER 62-001/01X-1 Detailed event analysis submitted MATTIMOE-J J Sacramento Municipal Utility District 62/08/05. ENGELMENR H. Region 5. Office of Director 3pp 14393 279 24X Fiche 50-312, 82/08/06. 8208200336
- --B2QB200160 LER B2-001/01X-1 on B20130, both air lock doors opened during purpe, causing loss of containment integrity. Caused by personnel error Sys of door status lights initiated to prevent recurrence CQLOHBO, R W Sacramento Municipal Utility District B2/0B/05 R9450n 5. Office of Director ip 14393 282 24X Fichs 50-312,82/0B/06,8208200136
- 8208200122 Forwards LER 82-018/03L-0 Detailed event analysis submitted MATTIMOS, J Secremento Municipal Utility District 82/08/16 ENGEL-MEN,R H. Region 5. Office of Director ip 14393-338 24X fich 50-312, 82/08/16, 8208200122
- --8208200130 LER 82-018/03L-0 on 820714, during anubber surveillance insp. snubber ISW-23823-7A failed acceptance criteria Caused by law fluid level Bnubber rebuilt & passed functional test. Enubber surveillance interval set at 12-months COLOHBO.R W. Sacramento Municipal Utility District 82/08/16, Region 5. Office of Director ip 14373 339 24% Fithe 50-312,82/08/16,8208200122
- 1 TINU 1940 RADIO BERNAMA ELE-05 TEMPOO
- F Security, medical, emergency & fire protection plans
- 6208020257 Ack receipt of 820714 ltr in response to 820625 Bystematic Assessment of Licenses Performance Board rept 2nconsistencies in functional area of security & safeguards will be corrected SEIDLE-N-C Division of Resident, Reactor Project & Engineering Programs 82/07/27 CAVANAUGH: W Arkansas Power & Light Co. 2pp 14152 312 24X Fiche 50-313,82/07/27,8208020259
- --8208020267 Comments on 820625 Bystematic Assessment of Licensee Performance Board rept increasing frequency of NRR project manager site visits suggested Inconsistencies in Settions III & K 2 re security & safeguards noted MARSHALL, J. R. Arkansas Power & Light Co 82/07/14, SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs, 3pp 14152 314 24X Fiche 50-313,82/07/27,8208020259

- 8208030312 Clarifies wtil 820701 documentation of results of review of fire zones for compliance w/100FR50 4B & 100FR50 App R
 MARSHALL, J R Arkansas Power & Light Co 82/07/29 EISENHUT, D 0
 Division of Licensing 2pp 14156 276 24% Fiche 50-313,82/07/29,820803012
- 8208050374 Confirms agreements reached in 820730 telcon re corrective action concerning early warning sys on 820731, licensee shall commence door-to-door canves within 10-mile emergency planning zone COLLINS, J.T. Region 4, Office of Director 82/07/30 CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 14209 164 24X Fiche 30-313, 82/07/30, 8208050374
- 8208260096 Release public version of revised emergency procedures FELTON, J M Division of Rules and Records 82/08/11 Document Management Branch. 1p 14574 317 24X Fiche 50-313, 82/08/11, 8208260096
- --8208260101 Forwards public version of revised emergency procedures, including Procedures 1904 02 re offsite dose projection -- pocket computer method & 1904 04 re estimating airborns release rates rates rates at Arkansan Power & Light Co. 82/07/30. NRC No Detailed Affiliation Olven 6pp. 14974 320 24X Fiche 30-313,82/08/11,8208240940
- --B20B260106 Public version of revised emergency procedures, including fracedures 1704.02 to offsite dose projection -- pocket computer method & 1904.04 te estimating airborne release rates

 Arkansas Power & Light Co. 82/07/30. 60pp 14574:327 24X Fiche 50-313,82/08/11.9208260094
- 8208190180 Ack receipt of 820721 request for 60-day extension to prepare response to emergency plan evaluation rept Request grantsd, establishing 820923 as new date for receipt of response SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/08/16 CAVANAUGH,W Arkanses Power & Light Co 1p 14382 247 24% Fichs 30-313,82/08/16,8208190150
- ~-BROBI90156 Requests 60-day extension to provide response to NRC emergency plan availation rept
 MARSHALLJ R Arkansas Fower & Light Co B2/07/21 COLLINS, J T
 Region 4, Office of Director 1p 14382 248 24%
 Fichs 50-313.B2/08/16.B20B190150
- 8208270467 Ack receipt of 820803 ltr discussing massive tone alert radia distribution program developed in response to 820727 & 30 discussions & 820730 confirmatory action ltr SEIDLE-H C. Division of Resident, Reactor Project & Engineering Programs 82708720 CAVANAUGH.W Artenses Power & Light Co 1p. 14567 045 24% Fiche 50-313,82708/20,8208270467
- --B20B270473 Discusses massive tone alert radio distribution program developed in response to B20729 & 30 discussions & B20730 confirmatory action itr Quersiza pamphlet enci Aperture card available in PDR MARCHALL, J R Arkansas Power & Light Co B2/08/05 COLLING, J T Region 4, Dffice of Director 15pp 14567 046 24X Fiche 50-313, 82/08/20,8208270467
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CRQR Byc list encl
 DIRCKS.N J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24% Fiche 50-000.82/07/02.8207080064
- B208020311 Forwards six Tech Spec figure change requests for approval.
 Changes will allow extension of Cycle 5 from 435 plus or
 minus 10 effective full power days to 455 & operation w/
 axial power shaping roos fully inserted H/o encl
 CAVANAUGH.W Arkanses Power & Light Co B2/07/15 BTGLZ.J F
 Operating Reactors Branch 4 2pp 14151 131 24X
 Fichs 50-313.82/07/15.8208020311
- 8208060042 Summary of 820622-24 meetings w/util in Russellvills, AK re App i (radiological effluent Tech Specs) review to resolve outstanding issues VISSING, 0 S Operating Reactors Branch 4 82/07/15 Operating Reactors Branch 4 3pp 14282, 043 24% Fiche 50-313, 82/07/15, 8208060042

- --8208060054 Forwards lists of questions to be discussed w/plant personnel re radiological effluent Tech Specs & offsite dose calculation manual AddI areas of discussion during review w/plant personnel may ariss SERRAND, W ECLO, Inc. 82/05/04 WILLIS, C A Effluent Treatment Systems Branch 34pp 14282 047 24X Fiche 50-313,82/07/15,82/05/0444
- 8207270387 Forwards ten oversite revised P&IDs Drawing transmittal list ent!
 EWINO, E Arkansas Power & Light Co 82/07/16 NRC No Detailed Affiliation Given 2pp 14062 287 24X Fiche 50-313, 82/07/16, 820/07/087
- 8208060174 Forwards responses to 820413 request for add1 info re training & requalification program MARBHALL,JR Arkanses Power & Light Co 82/07/21 CLARK,R A Operating Reactors Branch 3 STOL2,JF Operating Reactors Branch 4 43pp 14239 053 24X Fichm 50-313,82/07/21,8208060174
- 8208100201 Forwards responses to 820618 ltr addressing several open items re emergency feedwater sys One train of existing emergency feedwater sys capable of operating for 2-h w/o ac power under manual controls MARSHALL. J R Arkansas Power & Light Co 82/07/22 8TOLZ, J F Operating Reactors Branch 4 3pp 14294 278 24X Fiche 50-313, 82/07/22,8208100201
- 8208050026 Forwards NRC safety evaluation & Franklin Research Ctr technical evaluation of util response to NUREO-0737. Item If E 12 re emergency feedwater automatic initiation & flow indication Util meets long-term safety requirements STOL2.U F Operating Reactors Branch 4 B2/07/26 CAVANAUOH. W Arkansas Power & Light Co 3pp 14243.106 24X Fiche 50-313,82/07/26,8208050026
- --8208050028 "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication," technical evaluation rept KACCHER, J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-306 82/05/28 KENDALL, R , WIGDOR, M NRC No Detailed Affiliation Olven, 17pp 14243 111, 24 X Fishe 50-313,82/07/26,8208050026
- 8208110196 Forwards info on outages of ECCB, per NUREQ-0737.

 Item II K 3 17, in response to 820324 request for addl info MARSHALL, J R Arkansas Power & Light Co 82/07/26 EISENHUT.D 9 Division of Licensing 26pp. 14313 227 24X Fiche: 50-313,82/07/26,8208110196
- 8208160504 Forwards add1 info re Items 1I.F 1.4, "Containment Pressure Monitor." & II.F 1.5, "Containment Hater Level Monitor." & II.F 1.6, "Containment Hydrogen Monitor" MARSHALL.JR Arkamses Power & Light Co. 82/07/26 EISENHUT, D. Q. Division of Licensing 6pp 14348 287 24X Fiche 50-313.82/07/26, 8208160504
- 8208020072 Ack receipt of 820630 ltr re progress rept of Grawing control progrems Plant operators should be provided w/up-to-date PkIDs SEIDLE-W C Division of Resident, Reactor Project & Engineering Programs 82/07/27 MARSHALL JR Arkansas Power & Light Co. 2pp. 14144 113 24X Fiche 50-313.82/07/27.8208020072
- --B208020078 Bubmits status of efforts & decription of progress made re drawing control Onsite bldp removation accomplished, required procedure changes completed & reproduction & drafting equipment received

 MARSHALL, JR Arkenses Power & Light Co B2/06/30 BEIDLE, W C Division of Resident: Reactor Project & Engineering Programs 2pp, 14144:115 24X Fiche 50-313, 82/07/27, 82/88020072
- 8208090039 Responds to 820429 request for add1 info re 5-yr reactor bldg tendon surveillance rept MARBHALL,J R Arkansas Power & Light Co 82/07/27 BTOLZ,J F. Operating Reactors Branch 4 App 14270.042 24X Fiche.50-313,82/07/27,8208090039.
- 8208100190 Informs that info per NUREG-0737. Item II.8 3 re post-accident sampling systell be provided by 821115 in response to NRC 820701 request.

 MARSHALL,J R Arkenses Power & Light Co 82/07/27 CLARK,R.A Operating Reactors Branch 3, ip. 14298 200, 24X Fiche: 50-313, 82/07/27.8208100190.
- 8208060253 Responds to NRC 810929 request for submittal re NUREO-0737. Item II.D i, "Pressurizer Bafety/Relief Valve Operability."
 Subj valves function predicted under all credible operating & accident conditions analyzed in FSAR.
 MARBHALL.J R Arkenses Power & Light Co 82/07/28 STOLZ, J. F. Operating Reactors Branch 4 3pp. 14241 312, 24X
 Fiche: 50-313, 82/07/28, 8208060253

- 8208100102 Responds to NRC 820125 & 20 1trs requesting add1 info re environ qualification of safety-related electrical equipment High energy line break analysis enc? Add1 response will be completed by 820815
 MARBHALL.J R Arkansas Power & Light Co 82/07/29 STDLZ, J F Operating Reactors Branch 4 CLARK.R A Operating Reactors Branch 3 15pp 14277 304 24X Fiche 50-3(3.82/07/29.8208100102.
- 8208100369 Forwards Amends 66 & 34 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends modify ETS. App B re reporting of radiological gaseous effluents CLARK, R A , STOLZ, J F Operating Reactors Brench 3 82/07/29 CAVANAUGH, W Arkansas Power & Light Co 4pp 14308 251 24) Fiche 30-313.82/07/29,8208100369
- --B20Bi00372 Amends 66 & 34 to Licenses DPR-51 & NPF-6, respectively, modifying ETS, App B re reporting of radiological gaseous effluents
 BTOLZ, J.F. Operating Reactors Branch 4 82/07/29 15pp 14308 255 24X Fiche 50-313, 82/07/29, 9208100369
- --8208100375 Notice of issuance & availability of Amends &6 & 34 to Licenses DPR-51 & NPF-6, respectively MINER, S Operating Reactors Branch 4 82/07/29 2pp 14308-271 24X Fiche 30-313,82/07/29,8208100369
- 8208090021 SDCIOECONDMIC IMPACTS OF NUCLEAR GENERATING STATIONS-ARKANSAS NUCLEAR ONE STATION CASE STUDY Docket Nos 50-313 and 50-368 (Arkansas Power And Light Company) PIJANKA: K. D Mountain West Research, Inc FIN B-6268 NUREG/CR-2749 VOI 62/07/31 Division of Health, Siting & Environment 194pp Available at NTIS \$7 00 14304, 332 24X Fiche 50-313, 82/07/31, 8208090021
- 8208190354 "Technical Evaluation Rept of Overpressure Protection Sysfor AR Nuclear One, Unit 1," informal rept
 RANSOM; C B E0&0, Inc FIN A-6436 8208190354 82/07/31
 LANTZ, E Division of Systems Integration (post 811005) 15pp
 14504 118 24X Fiche 50-313,82/07/31,8208190354
- 8208160015 Submits add1 info requested in 820602 ltr re request for exemption from 10CFRSO 44 concerning installation of reactor vasues head vents Leakage or inadvertent operation of valves could result in degradation of valve components MARBHALL JR. Alabama Fower Co 82/08/06 STOLZ, JF Operating Reactors Branch 4 2pp 14344 218 24% Ficher 50-313, 82/08/06, 8208160015
- 8208090194 Oeneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EIBEMHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip. 14356 332 24X Fiche, 50-000, 82/08/09, 82/08/09174.
- 8208180030 Confirms work in progress re rept on effect of power-operated relief valve (PQRV) isolation sys (Item II K 3 2) & evaluation of PORV opening during overpressure transient (Item II K 3 7) Submittal expected by 820915 MARSHALL, J. R. Arkaness Power & Light Co. 82/08/10 STOLZ, J F Operating Resctors Branch 4 2pp 14376 202 24X Fiche 50-313, 82/08/10, 8208180030
- 8208170127 Forwards add1 info re "Emergency Feedwater Sys Upgrade Reliability Analysis for AR Nuclear One, Unit 1," in response to NRC 820421 request One oversize drawing encl Aperture card is available in PDR MARSHALL.J R. Arkansss Power & Light Co 82/08/11 STOLZ.J F. Operating Reactors Branch 4 5ipp 14364 144 24X Fiche: 50-313,82/08/11,8208170127
- 820B180001 Advises that response to NRC 820R23 & 0329 request for additing & recommendations re reactor vessel overpressurization will be issued by 820930.

 MARSHALL, J. R. Arkanses Power & Light Co. 82/08/11 8TOLZ, J F. Operating Reactors Branch 4 ip 14376 214 24X Fichel 30-31d, 82/08/11, 8208180001
- 8208230356 Advises that supplemental ECCS calculations will be provided by 830215; in response to 8207;3 request Calculations address potential impact of cladding models in NUREG-0630 on B&W ECCS calculations
 MARSHALL.J R Arkanses Power & Light Co 82/08/13, STOLZ, J F Operating Reactors Branch 4 ip 14508.324 24X Fiche 80-313, 82/08/13, 8208230336

- :8230278 Forwards add1 info re RCS high point vents in response to MFC 820120 t 0301 ltrs.Final responses will be submitted by 520917

 FARSHALL, J. R. Arkensas Fower & Light Co. 82/08/18 STDLZ. J. F. Castaing Reactors Branch 4 CLARK.R A Departing Reactors Branch 3 Sep. 14538 065 24X Fiche 50-613,82/08/18.82082820298
- :8000120 Provides projected schedule for completion of several NRC fisquests for info.

 AARSHALL, J R Arkansas Power & Light Co 82/08/23 670LZ, J F Granting Reactors Branch 4 2pp 14579 194 24X

 Fichs 50-313,82/08/23,8208300120
- M3310:54 Forwards proposed Tech Spec changes per 820714 ltr. in response to NUREO-0737, Item III 3 4. "Control Room M4354ahllity "
 CAYANAUGH, M. Arkansae Power & Light Co 82/08/24 STOLZ, J F Cayanaugh, Reactors Branch 4. 2pp 14693 193 24X Fighe, 50-313, 82/08/24, 8208310156
- -P208310172 Proposed Tech Spec Table 3 5 1-1 re functioning of channels * Arkansas Power & Light Co 82/08/24 2pp. 14693 195 24X Fichs. 50-313, 82/08/24, 8208310156
- 208260479 INTERIK RELIABILITY EVALUATION PROGRAM ANALYSIS OF THE AFKANSAS NUCLEAR ONE-UNIT : NUCLEAR POWER PLANT Dockst No 50-313 (Arkshasa Power And Light Company) F.C.B.O J Sandia Laboratorias FIN A-1241, NUREQ/CR-2787 VOI 82/08/31 275pp Available at NTIS 14571 035. 24X Fichs 30-313,82/08/31.8208260479
- i Inspection reports: IE Bulletins & correspondence
- ### Propries | Biscusses | Elinsp Rept 50-313/82~13 on 820601-03 & forwards notice of violation | Section | Fig. | Section | Section | Fig. |
- --8208180133 Notice of violation from insp on 820601-03 Noncompliance noted, failure to adequately measure & evaluate radiation Assard associated w/beta radiation prior to maint personnel entry into steam generator menuay # Region 4, Office of Director 82/06/14 2pp 14377 071 24x Fichs 50-313,82/06/14,8208180128
- 8204210393 1E Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leatage * Svc list encl
 JCRDAN, EL Division of Engineering & Quality Assurance 82/07/16,
 Consolidated Edison Co of New York 87pp 14956 274, 24X
 Fishs 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part S. Suppl i. "Clarification of Pfacement of Personnel Monitoring Devices for External Radiation." Byc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Histigan, Univ of. 112pp. 14358 001 24X Fiche. 50-000, 82/07/19, B204210395
- 82-04210374 iE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list ancl. JORDAN, E.L. Division of Engineering & Quality Assurance, 82/07/20 Censolidated Edison Co of New York 112pp 14381,001 24X Fichs: 50-000, 82/07/20, 8204210396.
- 8204210397 IE Info Notice B2-24, "Water Leaking From U Hexafluoride Overpacks." Bvc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards, 82/07/20 Consolidated Edison Co of New York, 71pp, 14357, 276 24/
- B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS." Svc list encl ACRDAN.E.L. Division of Engineering & Guality Assurance. B2/07/23. Commolidated Edison Co of New York 122pp 14380.115 24X Fiche: 50-000, 82/07/23, 8204210401.

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Mestinghouse PMRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/07/23 Consolidates Edison Co of New York 127pp, 14194 120 24X Fiche: 50-000, 82/07/23, 8204210402
- 8208050247 Ack receipt of 820528 ltr re re-evaluation of response to IE Bulletin 80-06. "ESF Reset Controls " No further questions at this time Bulletin will be held open pending review completion
 SEIDLE: W C Division of Resident, Reactor Project & Engineering Programs 82/07/23. CAVANAUPH.W Arkansas Power & Light Cu ip 14209 277 24X Fiche 50-313,82/07/23. 6208050247
- ~-8208050251 Submits re-evaluation of response to IE Bulletin 80~06, "EBF Reset Control" List of completed actions encl No further testing or mod required MARGHALLUR. Arkanses Power & Light Co 82/05/28 COLLING. J. Rapion 4. Office of Director 14pp 14209 300 24% Fiche 30~313,82/07/23,8208050247
- 8208160250 Submits final response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Performance history meets intent of Action Itsm 2 re verification of proper functioning No further action contemplated HARGHALL.JR Arkansas Power & Light Co. 82/07/23 COLLING.JT Region 4, Office of Director 2pp 14347.043, 24X Fiche 50-313,82/07/23,8208160250
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PHR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/24 Consolidated Edition Co of New York 121pp 14357:013 24X Fichs, 50-000, 82/07/26, 8204210403
- --8208180057 Notice of violation from insp on 820601-30.

 * Division of Resident, Reactor Project & Engineering Programs 82/07/27 2pp 14379.245 24X Fiche 50-313,82/07/27,8208180055
- --B208180066 IE Insp Repts \$0-313/82-13 & 50-368/82-10 on B20601-30 Noncompliance noted failure to perform adequate survey for beta radiation. ALARA committee review not performed & failure to control access to security key issue room JOHNBON.H D. CALLAN.L J. HALL.R E. Division of Resident. Reactor Project & Engineering Programs 82/07/15. 13pp 14379 247 24% Fiche 50-313,82/07/27.8208180055
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl.

 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Efison Co of New York 122pp 14357 146 24X Fichs. 50-000. 82/07/28. 8204210405
- 820Bii0i15 Bubmits add1 info re IE Bulletin 80-04, "Main Steam Line Break W/Continued Feedwater Addition." in response to NRC 820421 request Assumption of "no operator action" made to preclude manual isolation of main feedwater by operators. MARBHALL.J R. Arkansas Pawer & Light Co 82/07/30 BTOLZ, J F Operating Reactors Branch 4. 19 14314:326 24X Fiche 50-313,82/07/30,8208110115
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Evc list encl URADANIE L. Division of Engineering & Quality Assurance 82/08/05. Consolidated & Edison Co. of New York 117pp. 14388 201 24X Fithe 50-000, 82/08/05, 8204210407.
- 8208j90213 Forwards IE Into Repts 50-313/82-15 & 50-369/82-12 on 820621-25 & notices of violation & deviation SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 82/08/06. GAVANANOR, W. Arkansas Power & Light Co 2pp 14387 156. 24X Fiche: 50-313,82/08/06,8208170219.
- --8208170213 Notice of violation from Insp an 820621-25 # Region 4, Office of Director 82/08/06 ip. 14387,158, 24x Fithe: 50-313,82/08/06,8208190213
- --8208190219 Notice of deviation from imap on 820621-25 * Region 4, Office of Director. 82/08/06 ip. 14387:189. 24X Fiche. 50-313.82/08/06.8208190213

- --B20Bi90225 (E Insp Repts 50-313/82-15 & 50-36B/82-12 on 82042i-25 Noncompliance moted failure to electrically supervise or lock fire doors between adjacent redundant safe shutdown equipment JAUDON, J.P., MURPHY, M.E. Region 4, Office of Director 62/07/30 17pp 14387 160 24X Fiche 50-313-82/08/04,8208190213
- B20818008B Ack receipt of 820708 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-313/82-13 SEIDLE,W C Region 4. Office of Director B2/08/13 CAVANAUGH,W Arkansas Power & Light Co 1p 14376 325 24X Fichs 50-313,82/08/13.8208180088
- --8208180096 Responds to NRC 820414 ltr re violations noted in IE Insp. Rept 90-313/82-13 Corrective actions Procedure 1622 026 implemented to require beta surveys prior to personnel entry into steam generators

 MARSHALL. J R Arkansas Power & Light Co. 82/07/08 SEIDLE, W C. Region 4. Office of Director 4pp. 14376 326 24X Fichs 50-313,82/08/13,8208180088

R Periodic operating reports & related correspondence

- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/07/13 UDELL,R A Critical Mass Energy Project Bpp 14679 208 24X Fiche 30-000,82/07/13,8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYGI" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000,82/07/13.8208270010
- ~-8208270652 Forwards "Annual Occupational Radiation Exposure Rept, Personnel Whole Body Exposure for CY81," per 10CFR20 407 MARSHALL, J R Arkensas Power & Light Co 82/02/26 DEYOUNG, R. C Director's Office, Office of Inspection and Enforcement ip 14679 350 24X Fiche 50~000, 82/07/13, 8208270010
- --8208270655 "Annual Occupational Radiation Exposure Rept, Personnel Whole Body Exposure for CYB1 " * Arkansas Power & Light Co. 82/02/26 Ip 14679 351 24X Fische 50-000, 82/07/13.8208270010
- 8208120085 Porwards monthly operating rept for June 1982 MARSHALL,JR Arkanss-Power & Light Co 82/07/14 HALLER,N M Office of Resource Management, Director 1p 14327 132 24X Fiche 50-313,82/07/14,8208120085
- --8208120086 Monthly operating rept for June 1982 GERYBCH, A J Arkansa's Power & Light Co 62/07/09 App 14327 133 24X Fiche 50-313,82/07/14,8208120085
- 8208030526 Forwards results of intake impingement monitoring data for June 1982 MARSHALL, J.R. Arkanses Power & Light Co. 82/07/26 STOLZ, J.F. Operating Reactors Branch 4 Ip. 14163-023 24X Fiche 50-313,82/07/26,8208030526
- --8208030530 Intake impingement monitoring data for June 1982 * Arkansas Power & Light Co 62/07/20 27pp 14163 024 24X Fiche 50-313,82/07/26,8208030526
- 82080&0149 Forwards NPDES discharge monitoring repts for Apr-June 1982 repts for Apr-June 1982 MARBHALL, J.R. Arkamas Power & Light Co. 82/07/29 CGLLINS, J.T. Region 4, Office of Director 2pp 14240 040 24X Fichs 50-313, 82/07/29, 82080&0149
- --8208060155 NPDES discharge monitoring repts for Apr-June 1982 * Arkaneas Power & Light Co 82/07/28 18pp 14240 042 24x Fiche 50-313,82/07/29,8208060149

8 Reportable occurrences, LERs & related correspondence

- 8208050334 Forwards LER 82-013/03L-0 MARSHALL.JR Arkansas Power & Light Ca 82/07/26 SEIDLE, W C Region 4. Office of Director 1g. 14219.355 24X Fiche 30-313, 82/07/26, 8208050334
- --8208050339 LER 82-013/03L-0 on 820628, vent pipe for casing of spent fuel cooling pump P40A found leaking Caused by fatigue cracking due to normal pump vibration Vent pipe replaced Vibration study will be performed RGOERS,P. Arkansas Power & Light Co 82/07/26 Region 4, 00ffce of Director 2pp. 14219 396 24X Fiche 50-313,82/07/26, 8208050334

- 8208200137 Forwards LER 82-014/03L-0 MARSHALL, J R Arkansas Power & Light Co 82/07/28 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs Ip 14500 096 24% Fiche 50-313,82/07/28,8208200157
- --8208200170 LER 82-016/03L-0 on 820714, during monthly surveillante testing control rad drive 0 breaker failed to trip immediately upon receipt of trip signal Cause undetormined since breaker parformed properly during 10 subsequent tests MCEGOENBERG, D. Arkansas Power & Light Co. 82/07/28 Region 4. Office of Director 2pp 14500 097 24% Ficha 50-313,82/07/28.
- 8208060327 Forwards incident reporting sys repts re spill of contaminated water & contamination of personnel in auxiliary bldg & Failure of control rod guide tube support pins for transmittal to NEA MICHELBON, C Director's Office 82/07/29 LAFLEUR, J D Office of International Programs, Director 17pp 14281 234 24X Fiche 50-000, 82/07/29, 8208060327
- B20B100116 Forwards LER B2-014/03L-0 MARGHALL.JR Arkanses Power & Light Co 82/07/29 B&IDLE.W C Division of Resident, Reactor Project & Engineering Programs ip 14278 100 24X Fiche 50-313,82/07/29,8208100116
- --B208100121 LER 82-014/03L-0 on 820706, vent line separated from casing of borated water recirculation pump P-66 for spont fuel cooling sys Caused by fatigue crack in threads due to pump vibration Gracked vent pipe replaced ROCERB, P. Arkansas Power & Light Co. 82/07/28 Region A. Defice of Director 2pp 14298 iol 24% Fiche 50-313,82/07/29. R20810016
- 8208160079 Forwards LER 82-015/03L-0 MARBHALL.J R Arkansas Power & Light Co 82/07/29 SEIDLE, W C Region 4. Office of Director ip 14342 124 24X Fiche 50-313.82/07/29,8208160079
- --8208160082 LER 82-015/03L-0 on 920713, diesel generator i fuel oil transfer pump overfilled day tank, fuel oil trouble alarm tripped & diesel generator room filled w/smoke Caused by malfunction of high level limit switch L8H-9205 WADE,P B Arkansas Power & Light Co 82/07/29 Region 4, Office of Director 2pp 14342 125 24X Fiche 50-313,82/07/29,8208160079
- B20B200277 Forwards LER 82-017/03L-0 MARSHALL, J R Arkanses Power & Light Co 82/07/29 SEIDLE, 4 C Division of Resident, Reactor Project & Engineering Programs ip 14399-311 24X Fiche 30-313.82/07/29.8208200277
- --8208200282 LER 82-017/03L-0 on 820714, while performing reactor bldg isolation & miscallaneous valve stroke test, control valve closed, but failed to open due to circuit breaker trip Gause undetermined Control valve & circuit tested successfully WADE.P B Arkansas Power & Light Co 82/07/29 Region 4. Office of Director ip 14399, 312 24X Fiche 50-313, 82/07/29, 8208200277
- 8208050361 PNO-IV-82-028 on 820731. Itemsee will implement procedures to assure adequate public notification of warning sys operablists Rural areas will be provided w/tone receivers Actions will be completed by 820802

 ACTIONS WILL BE COMPLETED BEIDLE: W C Region 4. Office of Director 82/07/30 2pp 14237. 298. 24% Fiche 50-313.82/07/30.8208050361
- 820B100081 PNO-IV-62-02BA on 820730, licensee field teams visited residences, businesses & organizations located within 10-mile emergency planning tone outside area of siren coverage delivering EBB tone alert receivers HACKNEY.C , JAUDON, J.P., SEIDLE, W.C. Region 4, Office of Director 82/08/03 2pp 14296 143 24X Fiche 50-313,82/08/03,820B1000B1
- 8208270272 Forwards LER 82-018/03L-0 MARSHALL, J R Arkansas Power & Light Co 82/08/05 8EIDLE, W C Region 4, Office of Director 1p 14564 166, 24X Fiche 50-313,82/08/05,8208270272
- --- 8208270286 LER 82-018/03L-0.on 820716, ten improperly sealed penetrations through fire barriers discovered Caused by personnel failure to recognize sealing requirements during installation Penetrations properly sealed ROGERS, P. Arkansas Power & Light Co 82/08/05 Region 4. Office of Director ip 14564 168 24X Fiche 50-313,82/08/05,8208270272
- 8208160157 PNO-IV-82-029 on 820804, control rod 11, group 7, dropped During subsequent runback, reactor tripped Reactor protection sys indicated loss of both main feedwater pumps when pump 8 tripped Low resistence readings found on rod drive stator JOHNSON, W D., JAUDON, J.P. Region 4. Office of Director 82/08/06 ip. 14345 081 24X fiche 50-313,82/08/06,8208160197

16080 PMO-IV-82-029A on B20808, seal on reactor coolant pump C lid furing heatup following weld repair on valve MU-458 hige rate on pump reached max of 51 gpm State of AR MINIST STATE OF AR ASSISTED AND ASSISTED ASSISTED AND ASSISTED ASSISTED AND ASSISTED AND ASSISTED AND ASSISTED AND ASSISTED AND ASSISTED ASSISTED AND ASSISTED ASSISTED AND ASSISTED ASSISTED ASSISTED AND ASSISTED ASSIS

1890.4 D , JAUDON, J P , SEIDLE, W C Region 4, Office of Director 1889.9 2pp 14342 127 24X Fiche 50-313, 82/08/09, 8208160080

14950 PRO-IV-B2-030: on B20818, turbine tripped during routine rup test When relatched, governor valve opened causing the transient Bteam demand initiated emergency feedwater CLARL U I UM

310099 Forwards LER 82-020/03L-0 ASMALL JR Arkanaas Power & Light Co 82/08/19 BEIDLE, W.C. vision of Resident. Reactor Project & Engineering Programs. 1: 195 137 24X Fiche 50-313.82/08/19.8208310099

00310102 LER B2-020/03L-0 on B20805, while at 100% full power, control ref [1] of group 7 dropped, Caused by control red drive michanism stator failure Stator replaced aichanlam stator failure Stator replaced ROSERS.P. Arkameae Power & Light Co. 82/08/19 Region 4, Office of Director. 1p. 14695 138 24X Fiche 50-313,82/08/19,

1300122 PNO-1V-82-032 on 820822 unit tripped due to fault in main which the past control sys card Repairs completed & unit in mai trink to operation expected on 820823 Whiterfo M , JCHNSON, W D Region 4. Opfice of Director 2/08/23 1p 14099 189, RAX Fichs 50-315,82/08/23,8208300122.

RET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1 Security, medical, amorgancy & fire protection plans

9070054 Forwards revised pages of new training & qualification plan for security personnel Pages withheld (ref 10CFR73 21)

KMIER,R E Indiana & Michigan Electric Co 82/07/23 DENTON, H. R. Hifte of Nuclear Reactor Regulation, Director Spp 14270 006

141 Fiche: 50-315, 82/07/23, 8208090054

28390036 Application to amend Tech Space re fire protection fire (election instrumentation, fire suppression sys & fire rated

ISTIMETER, 8 Indiana & Michigan Electric Co. 82/08/02 DENTON, I Office of Nuclear Reactor Regulation, Director. 3pp 14269, 275 24X Fiche, 50-315, 82/08/02, 8208090054 NENTON, H. D.

820909039 Proposed Tech Spuc changes re fire detection Instrumentation, fire suppression sys, spray & sprinklar sys, low rated assemblikes, fire hose stations, Halon sys & pressure carben dioxide sys, a Indiana & Hichigan Electric Co. 82/08/02, 17pp. 14269, 278 24% Fiche 50-315, 82/08/02, 8208090056

>>200218 Forwards 1E Mgt Meeting Repts 50-315/82-14 & 50-316/82-14 on

920707

EFFLER. J G Region 3, Office of Director 82/08/02 DDLAN, J E
Asticen Electric Power Service Corp DDLAN, J E, Indiana & Michigan
Electric Co 2pp. 14379 280 24X Fiche: 50-315,82/08/02,8208200218

-6200200228 IE Mgt Meeting Repts 50-315/62-14 & 50-316/62-14 on CRECOURT IE Mgt Meeting Repts 30-313/82-14 to 30-313/82-14 to 320707 Hajor areas discussed concerns re schedule for completion of permanent emergency operating facility AXELBON.W L. PAPERIELLO, C.J., RAMBB.B. Division of Emergency Preparedness & Ciperational Bupport 82/07/28 5pp 14399 290 24X Fithe. 50-315, 82/08/02,8208200218.

20020034D Forwards info re emergency plan exercise scheduled for 21021, in response to NRC 820112 request Encl info includes 11161 for scope of exercise & objectives to be fulfilled. Stanario will be submitted by 820706 HERING, R F Indiana & Michigan Electric Co 82/08/09, REPPLES Asgion 3. Office of Director 4pp 14508-267 24X Fiche 50-315, 82/08/09, 8208230340 82/08/09, KEPPLER, J G.

82.8300035 Aubmits status of five areas in each plant protected witerbon dioxide suppression sys.but w/o dampers in all winsitation openings. Design review continues.

MMTER, R. B. Indiana & Michigan Electric Co. 82/08/20, DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 3pp. 14598: 252

24K Fiche. 30-315, 82/08/20, 8208300035

8208310242 Ack receipt of 820809 itr describing scope, objectives, effsite governmental participation & other facets of upcoming emergency preparedness exercise scheduled for colonia.

J Insurance & indemnity information

8208040006 Forwards Endorsement 43 to MAELU Policy MF-79, Endorsements ROBO40006 Forwards Engorsement Au to mattu rosity mr-77, Engoisement.

8 & 9 to MAELU Binders EB-45 & XB-44, respectively.

Endorsement 53 to NELIA Policy NF-206 & Endorsements 10 & 11

to NELIA Binders EB-45 & EB-64, respectively

BUCKLES, J Hersh & McLennan, Inc. H & M Nuclear Consultants, Inc

Div 62/07/29 BALTZMAN, J Assistant Director for State & Licen,

Relations 7pp 14193 184 24X Ficher 50-315,82/07/29,8208040006

K Utility Final Bafety Analysis Report (FBAR) & amends

8208230054 Forwards Page 8.2-1 of Vol V of updated FBAR inadvertently omitted from 820721 submittal HONTER.R.B. Indiana & Michigan &lectric Co. 82/08/18 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 14517 167 24X Fiche 50-315.82/08/18.8208230054

-8208230057 Page 8 2-1 to Vol V of updated FSAR

* Indiana & Michigan Electric Co. 82/07/31 ip 14517 168 24X
Fiche. 50-315.82/08/18.8208230054

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Bvc list encl
DIRCKS, H J Office of the Executive Director for Operations
82/07/02 Consolidated Edison Co of New York 93pp 14194 001
24% Fiche: 50-000, 82/07/02, 820708064

8208060173 Forwards payment of fees for processing Tech Spec change contained in 820407 application, per 820629 request ALEXICH.M P American Electric Power Service Gorp 82/07/20 DENTON.H R Diffice of Nuclear Reactor Regulation, Director ip 14239:155, 24X Fiche: 50-315, 82/07/20, 8208060173

8208040523 Notification of 820804 meeting w/utils in Betherda.HD to discuss results of R&D program for hydrogen control & combustion in ice condenser plants.

87AHE, C Licensing Branch 4 82/07/21, ADENSAM.R 0 Licensing Branch 4 2pp. 14220 342 24x Fiche: 50-000.82/07/21.8208040523.

B208020156 Forwards payment of fees for processing proposed mods to rod position indicator sys Tech Specs, per 820709 request ALEXICH.M P. American Electric Power Barvice Corp. 82/07/23 DENTON, H R Office of Nuclear Reactor Regulation, Director, MILLER, W Q, License Fee Management Branch 2pp 14144:133 24X Fiche 50-315, 82/07/23, 8208020156

82081900B7 Forwards Amend 56 to License DPR-58, safety evaluation be notice of issuance & availability. Amend redefines containment purge & exhaust isolation sys during current conteanment purge a minaust isolation sys during refueling outage VARGA, B.A. Operating Reactors Branch 1 82/07/2 Indiana & Michigan Electric Co. 2pp. 14506-120 Piche, 30-315-82/07/23:8208190087. 82/07/23 D

-8208190092 Amend 56 to Licensa DPR-58, redefining containment purge isolation bys during current refueling outage to allow mode to upgrade sys VARQA, B, A Operating Reactors Branch 1. 82/07/: 14506.122 24X Fiche 50-315, 82/07/23, 8208190087 82/07/23 App

--8208190377 Barety evaluation supporting Amend 56 to License DPR-58

• Office of Nuclear Reactor Regulation, Director 82/07/23 State 82/07/2

-B208190381 Notice of issuance & availability of Amend 36 to License PPR-58 VARDA, B A Operating Reactors Branch 1. 82/07/ 14506 130 24X Fiche 50-315, 82/07/23, 8208190087 82/07/23 200

8208030527 Forwards response to 820621 ltr re distribution of NUREGO-0020, "Licensed Operating Reactors - Status Summary Rept." Updated distribution list and! HUNTER:R B Indiana & Michigan Electric Co. 82/07/26 DENTON, M. R Office of Nuclear Reactor Regulation, Director App 14163 340 24% Fiche 50-315,82/07/26,8208030527. DENTON: H. R.

8208050014 Advises of completion of action on TMI Item II.E 4 2. Position 7 re purge & vent valves closing on high radiation in primary containment NRC awaiting Tech Spec change request.
VARQA.B.A. Operating Reactors Branch 1 82/07/27 DC
Indiana & Michigan Electric Co. 2pp 14243.079 24X
Fiche: 30-315,82/07/27,8208050014 DOLAN, J

- 8208060045 Forwards request for addition to hydrogen control issues for ice condenser plants in support of review of CLASIX computer program in Topical Rept OPS-07A35 Response requested within 30 days VARGA. B A Operating Reactors Branch I 82/07/30 DOLAN. J Indiana & Michigan Electric Co 14pp 14282 088 24X Fiche 50-315, 82/07/30, 8208060045
- B2000A0172 Forwards "Reactor Containment Bldg Integrated Leak Rate Test.810713-30" HANTER R B Indiana & Michigan Electric Co 82/08/02 DENTON, H I Office of Noclear Reactor Regulation. Director 3pp 14239: 156 24X Fishe 50-315,82/08/02.8208060172
- --8208040179 "Reactor Containment Bldg Integrated Leak Rate Test. 810713-30 " • Indiana & Michigan Electric Co 82/08/02 69pp 14239 159 24X Fiche 30-315-82/08/02.8208060172
- 8208090056 Application to amend Tech Specs re fire protection, fire detection instrumentation, fire suppression sys & fire rated assemblies
 HUNTER, R.S. Indiana & Michigan Electric Co. 82/08/02 DENTON, H. & Office of Nuclear Reactor Regulation, Director 3pp. 14269 275 24X Fices 50-315,82/08/02,8208090056
- -- 8208090039 Proposed Tech Spec changes re fire detection instrumentation, fire suppression sys. spray & sprinkler sys. low rated assemblies, fire hose stations. Halon sys & pressure carbon dioxide sys a fire hose stations. Halon sys & pressure a lodden & Michigan Electric Co 82/08/02 19pp 14269 278 24X Fiche 30-315,82/08/02.8208090056
- 8208100295 Provides schedule for submittal of detailed info re NUREG-073/, Item II B 3 on post-accident sampling sys.in response to 820630 request Info will be transmitted by 821029 HERINO.R F Indiana & Hichigan Electric Co 82/08/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14294 189 24X Fiche 50-315,82/08/04,8208100295
- 8208090194 Ceneric Ltr B2-14 to all reactor licensees: holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list enci EISEN-MIT. D 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- 8208270317 Forwards 820804 itr to MI Water Resources Commission notifying of high iron concentration in heating boiler blowdown discharge on 820801 Caused by boiler not being in continuous use since 820222
 SHITH.W G Indiana & Michigan Electric Co 82/08/09 KEPPLER.J O Region 3. Office of Director 2pp 14564 233 24X
 Fiche 50-315, 82/08/09.8208270317
- 8208260276 Application for amend to Licenses DFR-58 & DPR-74, proposing Tech Spec changes re radiation monitoring sys upgrade including implementation of post-TM1 requirements per NUREO-07370 bescription of changes encl HUNTER: R 5 Indiana & Michigan Electric Co 82/08/20 DENTON, H R. Office of Nuclear Reactor Regulation, Director 4pp. 14554-254 24X Ficha 50-315,82/08/20,8208240276
- --B208260284 Proposed Tech Spacs 3/4 3 3.3/4 4 5 & 3 9 9 & Tables 3 3-3, 3 3-6 & 4 3-3 re radiation monitoring instrumentation. RC9 Jeakage & containment purge & exhaust isolation sys indiana & Michigan Electric Co B2/08/20 14pp 14554 258 24X Fiche 50-315.82/08/20,8208260276.
- O Inspection reports, IE Builetins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage * Bvc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " But 15st and JORDAN, E. Division of Engineering & Quality Assurance 82/07/19, Michigan, Univ of 112pp 14358 001 24x Fiche 50-000, 82/07/19, 8204210395

- 8204210396 IE Info Notice 82-29, "Faitures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fichs 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " 8vc list encl C080t I Division of Fuel Facilities, Materials & Bafaguards 82/07/20 Consolidated Edison Co of New York 71pp 1435/276 24X Fiche 50-000,82/07/20,8204210397
- 9204210398 IE info Notice 82-26, "RCIC & MPCI Turbine Exhaust Check Valve Failures " Syc list enc! JORDAN,E L. Division of Engineering & Quality Assurance B2/07/22 Consolidated Edison Go of New York 112pp 14194 321 24X Fichs 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Bvc list encl JORDAN-E L Division of Engineering & Guality Assurance #22/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23,8204210401
- B204210402 IE Info Notice B2-27, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list and JURDAN: EL Division of Engineering & Quality Assurance 62/07/29 Consolidated Edison Co of New York 127pp 14174 120 24% Fiche, 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thormal Bleeves in RCB Piping at Certain Westinghouse PNP Power Plants " Svx list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storege Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York, 122pp 14357 146 24% Fiche 50-000.82/07/28.8204210405
- 8208100175 Responds to Item 3 of IE Bulletin 82-02, requesting info re leakage of bolted closures in RCPB. Info covers period Jan 1981-Jul 1982 List of leakages & corrective actions taken encl. Furnanite seplant used on two occasions to seal leaks HERING.R F Indiana & Michigan Electric Co 82/07/30 KEPPLER. J G Region 3. Office of Director 7pp 14298 223 24X Fiche 3D-315,82/07/30,8208100175
- 8208100356 Notification of 820805 meeting w/util & Science Applications inc in Bethesda, MD to discuss inservice insperogram
 CILIMBERG, R L. Operating Reactors Branch I 82/08/02 VARGA, 8 A
 Operating Reactors Branch I 2pp 14308 356 24X
 Fiche 50-315, 82/08/02, 8208100358
- 8208200218 Forwards IE Mgt Meeting Repts 50-315/82-14 & 50-314/82-14 on 820707 KEPPLER, J. G. Region 3: Office of Director 82/08/02 DDLAN, J E American Electric Power Service Corp DOLAN, J E. Indiana & Michigan Electric Co. 2pp. 14399 288 24X Fiche 30-315,82/08/02,8208/00/18.
- --8208200228 IE Mgt Meeting Repts 50-315/82-14 & 50-316/82-14 on 820707 Major areas discussed concerns re schedule for completion of permanent amergency operating facility ARELGENIAL 1. PAFERICLLO, C. U., RAMDB. 8. Division of Emergency Preparedness & Operational Support 62/07/28 5pp 14399-290 24% Fiche 50-315,82/08/02,8208200218
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Saffle Water-Vet Impingement" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 62/08/05, 8204210407
- 8208300194 Forwards IE Insp Repts 50-315/82-13 & 50-316/82-13 on 820821-25 & 0712-13. No noncompliance noted filter, I R Division of Engineering & Technical Programs 82/08/12 DDLAN, J E American Electric Power Bervice Corp DDLAN, J. E Indiana & Michigan Electric Co 2pp 14596 040 24X Fiche, 50-315, 82/08/12, 8208300194
- --8208300196 IE Insp Repts 50-315/82-13 & 50-316/82-13 on 820621-25 & O712-13 No noncompliance noted Major areas inspected: licensee action in response to noncompliance noted in health physics appreated significant findings MUETER. L. J., GREGER. L. R. Division of Engineering & Technical Programs 82/08/12 12pp 14596 042 24X Fiche 80-315,82/08/12.

- ECOB240052 Forwards addl info re evaluation performed per IE Bulletin 80-11, "Masonry Walls," in response to NRC 820713 request Three oversize drawings encl Aperture cards are evailable in PDR HUNTER.R S Indiana & Michigan Electric Co 82/08/20 DENTON.H R Office of Nuclear Reactor Regulation, Director 27pp 14527 082 24X Fiche 50-315,82/08/20,8208240052
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL,R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000,82/07/13,8208270010
- --B20B270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81 " * NRC No Detailed Affiliation Given 82/07/13 48pp \$4679 216 24X Fiche 50-000,82/07/13.8208270010
- --8208270643 Bubmits personnel exposure monitoring rept for CY81 per COS2/0843 Educates personner approve monitoring reperformal TOCFR20 407
 SMITH, W 0 Indiana & Michigan Electric Co 82/03/12
 Management and Program Analysis 1p 14680 052 24X
 Fiche 50-000, 82/07/13, 8208270010 Office of
- 820B120210 Forwards monthly operating rept for June 1982 BMITH.W O Indiana & Michigan Electric Co 82/07/14 Resource Management, Director 1p 14325 315 24X Fiche 50-315,82/07/14,8208120210 Office of
- B208120210
- S Reportable occurrences. LERs & related correspondence
- E208050354 Forwards LER 82-050/03L-0 SMITH.W 9 Indiana & Michigan Power Co 82/07/28 KEPPLER, J. G. Region 3, Office of Director 1p 14237 301 24X Fiche 50-315, 82/07/26, 8208050354
- --8208050362 LER 82-050/03L-0 on 820707, containment isolation valve ECR-32 for containment air participation detector failed to close from control room switch Caused by defective solenoid valve afg by ABCO Valve repaired PALMER, RA Indiana & Michigan Power Co 82/07/28, Region 3, Diffice of Director ip 14237 302 24X Fiche 50-315, 82/07/28, 8208050354
- 8208100338 Forwards LERs 82-051/03L-0 & 82-052/03L-0 SMITH.W 0 Indiana & Michigan Electric Ca 82/07/30 KEPPLER, J 0, Region 3, Office of Director ip 14297 098 24X Fiche 50-315,82/07/30,8208100338
- --B208100342 LER 82-051/03L-0 on 820707, during surveillance test of diesal generator load shedding relays, degraded voltage relay 27-3-T11C actuated at voltage in excess of Tech Spec Caused by instrument drift Load shedding relay readjusted PALMERR A Indiana & Michigan Electric Co 82/07/30 Region 3, Office of Director 1p 14297 099 24X Fiche 50-315,82/07/30,8208100338
- --8208100347 LER 82-052/03L-0 on 820704, during surveillance test on automatic load sequence timing relays, four timers were not functioning properly & exceeded max tolerance Caused by relay timer not being repeatable. Timer replaced PALMER.R A Indians & Michigan Electric Co 82/07/30 Regions, 09/fice of Director 2pp 14297 100 24X Fiche 50-315, 82/07/30.8208100338.
- 9208100052 Forwards LER 92-053/03L-0 8MITH.W 0 Indiana & Michigan Electric Co 92/08/02 KEPPLER, J. 0 Region 3, Office of Director ip 14276 237 24X Fiche 50-315,82/08/02,8208100052
- --8208100058 LER 82-053/03L-0 on 820702, ladder found in doorway of fire door between AB & CD 600-volt bus areas, rendering fire barrier inoperable. Investigation did not reveal person responsible, Ladder removed Training to be increased. SVENBBON, B. A. Indiane & Michigan Electric Co 82/08/02 Region 3, Office of Director ip 14296 240 24% Fiche 50-315,82/08/02,8208100052

- 8208100125 PNO-III-82-076 on 820804. Fuel assembly became wedged in device used to move assemblies from vertical to horizontal position for movement through fuel transfer canal Caused by tilting device in horizontal position instead of vertical. HAYES.D., KNOP.R. Region 3. Office of Director 82/08/04. Ip 14278 184 24X Fiche 50-315.82/08/04. \$208100125
- 820B100163 PNO-III-82-076A on 820B04, stuck fuel assembly freed & transferred w/o incident to spent fuel storage pool No release of radipactivity evident Assembly placed in normal storage location in spent fuel storage HAYES.D. KNDP.R. Region 3. Office of Director 92/08/05 1; 14298 029 24X Fiche 50-315,82/08/05. 8208100163
- E20B160006 Forwards LER B2-054/03L-0 SMITH.W G Indiana & Michigan Electric Co 82/08/06 KEPPLER, J Q Region 3. Office of Director ip 14344 316 24X Fiche 50-315, B2/08/06, B2/08/6006
- --B208160007 LER 82-054/03L-0 on B2070P, during operation of diesel generator AB, auto voltage regulator was not functioning properly & exciter field overload relay tripped Caused by failed auto voltage regulator card Relay reset PALMER:R A Indiana & Michigan Electric Co G2/08/06 Reg: 3, Office of Director 2pp 14344 317 24X Fiche 50-315, pp. 14344 317 24X Piche 50-315, pp. 14344 317 24X Piche 50-315, pp. 14344 82/08/06, 8208160006
- 8208160345 Forwards LER 82-055/03L-0 8MITH.W Q. Indiana & Michigan Electric Co 62/08/06 KEPPLER, J Q Region 3, Office of Director ip \$4348 070 24X Fichs 30-315, 82/08/06, 8208160345
- --B20B160351 LER B2-055/03L-0.on B2070B & OP, fire seals F-B195, H-3061 & H-3082 discovered to be in degraded condition Fire watches posted Cause unknown Penetration fire barrier seals restored to functional status CAPLE, O H Indiene & Michigan Electric Co B2/08/06, Region 3, Office of Director ip 14348 071 24X Fiche 50-315, B2/08/06, B20B160345
- 8208230212 Forwards LER 82-056/03L-0 EMITH.W 0 Indiana & Michigan Electric Co 82/08/13, KEPPLER.J.@ Region 3, Office of Director 1p 14508.333, 24X Fiche 50-315.82/08/13.8208230212
- --B208230223 LER 62-056/03L-0 on B20717, during surveillance test of automatic load sequence timing relays, three relay timers exceeded ellowable tolerance Caused by instrument drifft Timers adjusted Use of new solid state relay under review. PALMER, R A Indiana & Michigan Electric Co B2/08/13 Region 3, Office of Director. ip 14508 334 24X Fiche 50-315,82/08/13,8208230212
- 8208230235 Forwards LER 82-057/03L-0 ENITH.W 0 Indians & Michigan Electric Co 82/08/13, KEPPLER, J 0 Region 3, Office of Director. ip 14508 935 24X Fiche. 50-315, 82/08/13, 8208230235
- --B20B230256 LER 82-057/03L-0.on 820716. surveillance test performed to prove operability upon completion of maint Pump breaker racked contrary to Tech Specs Surveillance or operability run cannot be performed in compliance w/Tech Specs.

 DRAPER.D.M Indiana & Michigan Electric Co 82/08/13 Region 3. Office of Director 1p 14508.336 24X Fithe 50-315,82/08/13,8208230235
- 8208270373 Forwards LERe 82-059/03L-0 & 82-059/03L-0 8MITH.W 0 Indiane & Michigan Electric Co 82/08/18, KEPPLER, J. 0, Region 3, Office of Director 1p, 14564 280 24X Fiche, 30-315, 82/08/18, 8208270373
- --B208270379 LER 82-05B/03L-0 on 820721, total valve lask rate exceeded Tech Spec limits No cause stated Testing of remainder of valves currently underway.

 PALMER, R. A. Indiana & Michigan Electric Co. B2/08/18 Region 3, Office of Director. ip 14564, 281 24X Fiche 50-315, 82/08/18, 8208270373.
- -8208270386 LER 82-057/03L-0.on 92072D, two 4-kv loss of voltage relays, 27-i-Ti1A & 27-2-T-11A exceeded Tech Spec tulerances Caused by instrument drift Diesel generator load shedding relays readjusted to within allowable limits PALMER, RA Indiena & Michigan Electric Co. 82/08/18 Region 3, Office of Director ip 14564-282. 24X Fiche.50-315,82/08/18,82/08270373
- 8208310103 Forwards LER 82-060/03L-0 BHITH:W O Indiana & Michigan Electric Co. 82/08/2 Region 3. Office of Director. ip. 14495, 135. 24X Fichs 80-315.82/08/20.8208310103 82/08/20. KEPPLER, J 0

- ~-8208310105 LER 82-040/03L-0 on 820723, while shutdown for refueling, swargancy dietal generator rendered inoperable when motor operated valves on cooling water supply closed & power supply rendued Course by supervisor error DRAPER.D N Indiana & Michigan Electric Co. 82/08/20 Region 3 Office of Director 1p 14695 136 24X Fiche 50-315,82/08/20,820810103
- COCKET 50-316 DOMALD C COUR MUCLEAR POWER PLANT, UNIT 2
 F Security, medical, energency & fire protection plans
- 8208090054 Forwards revised pages of new training & qualification plan for security personnel Pages withheld (ref 10CFR73 21) MUNTER.R S Indiana & Michigan Electric Co 82/07/23 DENTON, H R Office of Nuclear Reactor Regulation, Director Jpp 14270 006 24X Fiche 59-315.82/07/23.8208090054
- 8208090056 Application to amend Tech Specs or fire protection, fire detection instrumentation, fire suppression sys & fire rated assemblies WANTER, R. S. Indiana & Michigan Electric Co. 82/08/02 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 3pp. 14269-275-24X Fiche 50-315,82/08/02.8208090056
- --8208090059 Proposed Tech Spec changes re fire detection instrumentation, fire suppression sys, spring & sprinkler sys, low rated assemblies, fire hose stations, Halon sys & pressure carbon digide sys Indiana & Michigan Electric Co 82/08/02 19pp 14267 278 24X Fiche 30-315.82/08/02.8208090096
- 8208200218 Forwards IE Mgt Maeting Repts 50-315/82-14 & 90-316/82-14 on 820707

 KEPPLER.J O Region 3, Office of Director 82/08/02 DOLAN, J E American Electric Power Service Corp 2pp 14399 288 24X

 Fichs 50-315,82/08/02,8208200218
- --8208200228 IE Mgt Meeting Repts 50-315/82-14 & 50-316/82-14 on 820707 Major areas discussed concerns re schedule for completion of permanent emergency operating facility AXELBON.W L Division of Emergency Preparedness & Operational Support 82/07/28 Spp 14397 290 24X Fiche 50-315,82/08/02,8208200218
- 8208230340 Forwards info re emergency plan exercise scheduled for 821021, in response to NRC 820112 request Encl info includes preliminary scope of exercise & objectives to be fulfilled 8cenario will be submitted by 820706 MERING.R F Indiana & Hichigan Electric Co 82/08/09 KEPPLER.J G Region 3. Office of Director 4pp 14508 267 24X Fichs 50-315.82/08/09.8208230340
- B20B310242 Act receipt of B20B09 ltr describing scape, objectives, offsite governmental participation & other facets of upcoming emergency preparedness exercise scheduled for B21021 HIND, J. A. Division of Emergency Preparedness & Operational Support B270B725 HERING, R. F. American Electric Power Co. Inc. HERING, R. F. Indiana & Michigan Electric Co. 2pp. 146BB 359 24X Fiche 50-315, 8270B725, 820B310242
- J Insurance & insemnity information
- 8208040006 Forwards Endorsement 43 to MAELU Policy MF-79, Endorsements 8 & 9 to MAELU Binders EB-45 & XB-64, respectively.

 Endorsement 33 to MELIA Policy NF-206 & Endorsements 10 & 11 to MELIA Binders EB-45 & EB-64, respectively.

 BUCKLES, J. March & McLennan, Inc. N & M. Nuclear Consultants, Inc. Div. 82/07/29 SALTIMAN, J. Assistant Director for State & Licensee Relations 7pp 14193 184 24X Fiche 50-315,82/07/29,8208040006
- K Utility Finel Safety Analysis Report (FSAR) & amends
- 8208230054 Ferwards Page 8 2-1 of Vol V of updated FSAR inadvertently HANTER R 9 1-140-1-100 (CCC)
 - /08/18 DENTON, H R 14517 167 24X

- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Byc list encl
 DIRCKS, W.J. Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 73pp 14194,001
 24X Fiche 50-000,82/07/02,8207080064
- 8208060173 Forwards payment of fees for placessing Foch Spec thange contained in 820407 application.per 820627 request ALEXICH, M.P. American Electric Power Service Corp. 82/07/20 DENTON.H.R. Office of Nuclear Reactor Regulation. Director 19 14237 135 24X Fiche 30-315.82/07/20.8208060173
- 8208040529 Notification of 820804 mosting w/utils in Bethesda, HD to discuss results of RbD program for hydrogen control & combustion in ice condenser plants
 STAMLE, C Licensing Branch 4 820 824 Fichs 50-000, 82/07/21, 8208046523
- 8208020154 Forwards payment of fees for processing proposed mode to reposition indicator sys Tech Specs.per 820709 request ALEXICH.M P American Electric Power Service Corp 82/07/23 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER.W O License Fee Management Branch 2pp 14144 133 24X Fiche 50-315.82/07/23.8208020154
- 8208030527 Forwards response to 820621 ltr re distribution of NUMEGO-0020. "Licensed Operating Reactors - Status Summary Rept " Updabed distribution list enc! HUNTER.R B Indiana & Michigan Electric Co 82/07/26 DENTON.N R Office of Nuclear Reactor Regulation; Director App 14163 3/10 24X Fiche 50-315; 82/07/26,8208030527
- 8208050014 Advises of completion of action on TMI Item II E 4 2. Position 7 re purpe & vent valves closing on high radiation in primary containment NRC awaiting Tech Spec change request VARGA:8 A Operating Reactors Branch 1 82/07/27, DULAN. J. Indiana & Michigan Electric Co. 2pp. 14243 079 24X Fiche 50-315, 82/07/27, 8208050014
- 8208060045 Forwards request for eddl info re hydrogen control issues for ice condenser plants in support of review of CLABIX computer program in Topical Rept OPS-07A33 Response requested within 30 days VARGA.8 A Operating Reactors Branch 1 82/07/30, DDLAN, J Indiana & Michigan Electric Co 14pp 14282 088 24X Fichs 30-315, 82/07/30, 8208060045
- 8208090019 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS D C COOK CASE STUDY Docket Nos 50-315 And 50-316 (Indiana And Michigan Electric Company)
 BRANCH: K Mountain West Research: Inc * Social Impact Research: Inc FIN 8-4288 NURED/CR-2749 V04 B2/07/3]. Division of Health: Biting & Environment 270pp Available at NTIS. \$0 00-14304-058 24X Fiche 50-315,62/07/31:8208090019
- 8208060172 Forwards "Reactor Containment Bidg Integrated Leak Mater Test, 810713-30" HUNTER: R B Indiana & Michigan Electric Co 82/08/02 DENFON, H.R Office of Nuclear Reactor Regulation. Director 3pp 14239 155 24X Fiche 50-315, 82/08/02, 8208060172
- ~-8208060179 "Reactor Containment Bidg Integrated Leak Rats Test, 810713-30 " " Indiana & Michigan Electric Co 82/08/02 47pp, 14239; 159 24X Fiche: 50-315, 82/08/02, 8208060172
- 8208090056 Application to amend Tech Specs to fire protection, fire detection instrumentation, fire suppression sys & fire rated assemblies HUNTER, R.S. Indiana & Michigan Electric Co. 82/08/02 DENYON, H.R. Office of Nuclear Reactor Regulation, Director Spe. 14269-2/5-24X Fiche 50-315, 82/08/02, 8208090056
- ---8208070037 Proposed Tech Spec changes re fire detection instrumentation, fire suppression systematic synther system rated assemblies, fire hose stations, Halon systematic carbon dioxide systematics. Fire hose stations, Halon systematics of systematics. Fire hose stations, Halon systematics of systematics. Fire hose stations, Halon systematics. Fire hose stations of systematics. Fire hose systematics of systematics. Fire hose stations, Halon systematics. Fire hose stations in the hose stations. Fire hose stations is supplied by the hose stations of the hose stations. Fire hose stations is supplied by the hose stations of the hose stations is supplied by the hose stations of the hose stations is supplied by the hose stations of the hose stations is supplied by the hose stations of the hose stations of the hose stations is supplied by the hose stations of the hose sta
- B20B190007 Notification of B20B05 meeting w/util & Exxon Nuclear Corp in Setheada, MD to discuss deficiencies in info re Cycle 4 reload. CILIMBERO, R L Operating Reactors Branch | 62/08/03 VARQA, B A Greating Reactors Branch | 2pp | 14506-318 244 Fiche 50-316-82/08/03, 820B190009

- 8208100295 Provides schedule for submittal of detailed info re NUREG-0737, Item II B 3 on post-accident sampling sys.in response to 820630 request Info will be transmitted by 821029 HERING, R F Indiana & Michigan Electric Co 82/08/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14294 189 24x Fiche 50-315,82/08/04,8208100295
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Sv list encl EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24% Fiche 50-000, 82/08/09, 82/08/09/194
- 8208270317 Forwards 820804 ltr to MI Water Resources Commission notifying of high from concentration in heating boiler blowdown discharge on 820801 Gaused by boiler not being in continuous use since 820222 SMITH W O Indiana & Michigan Electric Co 82/08/09 KEPPLER, J & Region 3, Office of Director 2pp 14564 233 24% Fichs 50-315.82/08/09.8208270317
- 820B270622 Summary of B20B05 meeting w/util & EXXON Nuclear Co in Bethesda, MD re application for uprating of power & change of fuel from Westinghouse to EXXON for Cycle 4 reload CILIMBERG, R L Operating Reactors Branch 1 B2/08/11 Operating Reactors Branch 1 5pp 14483 200 24X Fiche 50-316,82/08/11.
- --B208170090 Recommends licensee submit revised safety analyses using W-3 critical heat flux correlation for review of XN-NF-82-21, "Application of EXXON Nuclear Co PWR Thermal Margin Methodology to Mixed Core Configurations "BERLINGER, CI Core Performance Branch 82/08/02 VARGA, B A, Operating Reactors Branch 1 2pp 14683 205 24X Fiche 50-316,82/08/11,8208270622
- 8208260276 Application for amend to Licenses DPR-58 & DPR-74, proposing Tech Spec changes re-radiation monitoring sys upgrade including implementation of post-TMI requirements per NUREG-0578 & NUREG-0737 Description of changes enci HUNTER.R S Indiana & Michigan Electric Co 82/08/20 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp 14554, 254 24% Fiche 50-315.82/08/20,8208260276
- --8208260284 Proposed Tech Specs 3/4 3 3,3/4 4 4 & 3 7 9 & Tables 3 3-3, 3 3-4 & 4 3-3 re radiation monitoring instrumentation, RCS leakage & containment purge & exhaust isolation sys, a Indiana & Michigan Electric Co 82/08/20 14pp 14554 258 24% Fiche 50-315,82/08/20,8208260276
- G Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage," Svc list encl JORDAN,E L. Division of Engineering & Guelity Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Placement of Personnal Monitoring Devices for External Radiation" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ. of 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210395
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/20 Consolidated Edison Co of New York 112pp 14381,001 24X Fiche 50-000,82/07/20,8204210376
- 8204210397 IE Info Notice B2-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB:L. I Division of Fuel Facilities, Materials & Safeguards B2/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000.82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Byc list encl JORDAN:E L Division of Engineering & Quality Assurance. 82/07/22, Consolidated Edison Co of New York 112pp 14174-321 24X Fichs 50-000, 82/07/22,8204210398
- B204210401 IE Info Notice 82-29, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl. JORDANIE L. Division of Engineering & Quality Assurance, 82/07/23, Consolidated Edison Co. of New York 122pp 14380-115 24X Fiche 50-000, 82/07/23, 8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Hestinghouse PWRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120. 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Steeves in RCS Piping at Certain Westinghouse PWR Power Plants " Byc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24% Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208100175 Responds to Item 3 of 1E Bulletin 82-02 requesting info re leakage of bolted closures in RCPB Info covers period Jan 1981-Jul 1982. List of leakages & corrective actions taken encl. Furmanite sealant used on two occasions to seal leaks HERINO.R F Indiana & Michigan Electric Co. 82/07/30 KEPPLER.J Q Region 3. Office of Director 7pp 14298 223 24X Fiche 50-315,82/07/30,8208100175
- 8208100358 Notification of 820805 meeting w/util & Science Applications, Inc. in Bethesda, MD to discuss inservice insp program CILIMBERG, R L. Operating Reactors Branch 1 82/08/02 VARGA, S. A. Operating Reactors Branch 1 2pp 14308 356 24X Fiche 50-315, 82/08/02, 8208100358
- 8208200218 Forwards IE Hgt Heeting Repts 50-315/82-14 & 50-316/82-14 on 820707 KEPFLER, JO Region 3, Office of Director, 82/08/02 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp. 14377 288 24X Fiche 50-315,82/08/02,8208200218
- --8208200228 IE Mgt Heeting Repts 50-315/82-14 & 50-316/82-14 on 820707 Major areas discussed concerns re schedule for completion of permanent whereency operating facility AXELSON, M.L., PAPERIELLO, C.J. RAMGS 8 Division of Emergency Preparadness & Operational Support 82/07/28 3pp 14399 270 24X Fiche 50-315.82/08/02,8208200218
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E.L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14389-201 24X Fiche:50-000,82/08/05,8204210407.
- 8208300194 Forwards IE Insp Repts 50-315/82-13 & 50-316/82-13 on 820621-25 & 0712-13 No noncompliance noted HILLER, JR. Division of Engineering & Technical Programs 82/08/12 DOLAN, JE. American Electric Power Service Corp DOLAN, JE. Indiana & Michigan Electric Co 2pp 14596 040 24x Fiche: 50-315, 82/08/12, 8208300194
- --820830019å IE Insp Repts 50-315/82-13 & 50-316/82-13 on 820621-25 & 0712-13,No noncompliance noted Major areas inspected Ifcenses action in response to noncompliance noted in health physics appraisal significant findings HUETER,L J. QREGER,L R Division of Engineering & Technical Programs 82/08/12 12pp 14596 042 24X Fiche 50-315.82/08/12, 8208300194
- 8208240052 Forwards add1 info re evaluation performed per IE
 Bulletin 80-11, "Mayonry Walls," in response to NRC 820713
 request. Three oversize drawings encl. Aperture cards are
 available in FDR.
 HUNTER,R 8 Indiana & Michigan Electric Co 82/08/20, DENTON.H R
 Office of Nuclear Reactor Regulation. Director 27pp. 14527:082
 24X Fiche: 50-315,82/08/20,8208240052
- R. Pariodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards focuments listed in App A FELTON, J M Division of Rules and Records. 82/07/13 UDELL, R A Critical Mass Energy Project 8pp. 14679, 208 24X Fiche. 50-000, 82/07/13, 8208270010.
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."

 * NRC - No Detailed Affiliation Oiven 82/07/13 48pp 14679-216. 24X Fiche: 50-000, 82/07/13, 8208270010.

- --8208270643 Submits personnel exposure monitoring rept for CY81 per 10CFR20 407 SMITH.W @ Indiana & Michigan Electric Co 82/03/12 Office of Management and Program Analysis [p 14480 052 24X Fiche 50-000,82/07/13,8208270010
- 8208120260 Forwards monthly operating rept for June 1982 SMITH.W O Indiana & Michigan Electric Co 82/07/14 Office of Resource Management, Director 1p 14326 351 24X Fiche 50-316.82/07/14.8208120260
- --8208120274 Monthly operating rept for June 1982 MIGHT, A Indiana & Michigan Electric Co 82/07/14 6pp 14326 352 24X Fiche 50-316,82/07/14,8208120260
- S Reportable occurrences, LERs & related correspondence
- 8208030205 Forwards LER 82-055/03L-0 SNITH,W G Indiana & Michigan Power Ca 82/07/27 KEPPLER, J G Region 3, Office of Director ip 14160 001 24X Fiche 50-316.82/07/27,8208030205
- --A208030209 LER 82-055/03L-0 on 920628, during normal operation, Train fi bit heaters discovered w/thormal overload tripped & declared inoperable Caused by shorted Chromalor TH-18 heater Heater replaced & train declared operable Reason for short unknown PIEML, R H Indiana & Michigan Power Co 82/07/27 Region 3, Office of Director ip 14160 002 24X Fiche 50-316,82/07/27, 8288630205
- 8208050367 Forwards LER 82-058/03L-0 8MITH-W 0 Indiana & Michigan Power Co 82/07/28 KEPPLER, J G Region 3. Office of Director ip 14209 153 24X Fiche 50-316.82/07/28.8208050367
- --B208090372 LER 82-058/03L-0 on 820629, carbon dioxide sys forquadrant 2 reactor cable tunnel area was isolated & fire door blocked open w/o fire watch posted Compliance w/fire protection requirements emphasized PIEHL.R H Indiana & Michigan Power Co 82/07/28 Region 2. Office of Director 19 14209 154 24X Fiche 50-316, 82/07/28, 8208050367
- 8208100042 Forwards LER 82-059/03L-0 5M1TH.W 9 Indiana & Michigan Power Co 82/07/30 KEPPLER, J G Region 3. Office of Director 1p 14296 254 24X Fiche 50-316.82/07/30,8208100042
- --8208100048 LER 82-059/03L-0 on \$20709, flowpath from boric acid tanks via boric acid transfer & charging pumps to RCB isolated for 38 minutes to repair leaking isolation valve CB-485 Caused by diaphram failure Valve diaphragm & bonnet replaced WIZNER, D G Indiana & Michigan Power CC 82/07/30 Region 3, Office of Director ip 14296 253 24X Fiche 50-316, 82/07/30, 82081001042
- 8208100317 PNG-III-82-073 on 820731.unit shut down after tubo look rate of 0.17 gpm determined in steam generator 2 Licensus estimates unit will be down for several days for testing & leak location activities

 HAYES-D, STREETER, J Region 3, Office of Director 82/08/03 ip 14297 i27 24% Fiche 50-316.82/08/03,8208100317
- B208230062 Forwards LERs 82-060/03L-0 & 82-061/03L-0 SMITH W G. Indiana & Michigan Electric Co 82/08/13 KEPPLER, J G Region 3. Office of Director 1p 14517 222 24X Fiche 30-316, 82/08/13, B208230062
- B208230066 LER 82-060/03L-0 on B20717, during normal operation, train A heaters for boron injection tank declared inoperable while heater controls were repaired Caused by faulty resistance to current converter (R/I) Converter replaced DELONG, 8 D Indiana & Mithigan Electric Co B2/08/13 Region 3, Dffice of Director 1p 14517 223 24X Fiche 50-316, B2/08/13, B208230062
- -8208230068 LER 82-061/03L-0 on 820717. while performing operability test.neither fuel oil transfer pump for CD emergency dissel generator would pump fuel oil to day tank Caused by failure of nonoperating pump discharge check valve to seat properly PIEHL.R H Indiana & Michigan Electric Co 82/08/13 Region S Office of Director 2pp 14517 224 24X Fiche 50-316, 82/08/13, 8208200.52
- 9208270314 Forwards LER: 82-062/03L-0 & 82-063/03L-0 8MITH W O. Indiana & Michigan Electric Ca. 82/08/18 KEPPLER: J & Region 3. Défice of Director 1p 14564 213 24X Fiche: 50-316,82/08/18,8208270314

- --8208270321 LER 82-062/03L-0 on 820719.carbon dioxide isolation switch for CD diesel generator room discovered in isolate position w/no personnel in area & no fire watch posted Caused by personnel error Sys returned to normal CASTLE.L W Indiana & Michigan Electric Co 82/08/18 Region 3. Office of Director ip 14564 214 24X Fiche 50-316.82/08/18, 8208270314
- --8208270334 LER 82-063/03L-0 on 820720, starting time for 2-HV-CER-2 fan exceeded Tech Spec tolerance Caused by instrument repeatability characteristics Fan retested several times within allowable limits PALMER.R A Indiana & Michigan Electric Co 82/08/18 Region 3. Office of Director 2pp 14564 215 24X Fiche 50-316, 82/08/18, 8208270314
- 8208310359 Forwards LER 82-064/03L-0 SNITH W 0 Indiana & Michigan Electric Co 82/08/23 KEPPLER, J 0 Region 3, Office of Director 1p 14692 127 24X Fiche 30-316, 82/08/23, 8208310359
- --B208310365 LER 82-064/03L-0 on B20724, loop 3 overtemp delta 7 trip setpoint drifted high Caused by Foxboro generator module 66RC-0LA drifting out of spec Module recalibr & again drifted Module replaced PALMER, R A Indiana & Michigan Electric Co B2/08/23 Region 3. Dffice of Director 1p 14692 128 24X Fiche 50-316,82/08/23,8208310399
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 820B040609 Ack receipt of 820404 & 29 ltrs transmitting temporary mode to physical security program to allow for const of svc tunnel & storage of fresh fuel onsite Mode consistent w/ IOCFR50 \$4(p) & are acceptable CLARK, R A Operating Reactors Branch 3 82/07/29 BAUMAKER, N J Baltimore Gas & Electric Co ip 14225 297 24X Fiche 50-317, 82/07/29, 82080404009
- 8208060069 Releases public version of revised amergency plan implementing procedures FELTON.J M Division of Rules and Records 82/08/02 Document Management Branch 1p 14282 210 24X Fiche 50-317,82/08/02.8208060067
- --8208060072 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 3 I reinitial notification checklist ERPIP 3 5 re immediate action personnel injury # Baltimore Qas & Electric Go 82/07/27 CLARK,R A. Operating Reactors Branch 3 3pp 14282 211 24X Fiche 50-317,82/08/02,8208060067
- --B20B060078 Public version of revised emergency plan implementing procedures including Procedures ERPIP 3 1 re initial notification checklist & ERPIP 3 5 re immediate action personnel injury * Baltimore Qas & Electric Co 62/d6/09 250pp 14282 214, 24% Fiche 50-317,82/08/02,8208060069
- 8208120239 Ack receipt of 820623 itr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-317/81-17 & 50-316/81-18
 SMITH. G H Division of Emergency Preparedness & Operational Support 82/08/04 LUNDVALL. A E Baltimore Gas & Electric Co 2pp 14326-322 24X Fiche-50-317.82/08/04.8208120259
- --8208120272 Responds to NRC 820526 ltr re violations noted in IE
 Emergency Preparedness Appraisal Repts 50-317/81-19 &
 50-318/81-18 Corrective actions emergency planning unit
 established & staffed on 820401
 POINDEXTER. C Baltimore Que & Electric Co 82/06/25 SMITH. C H
 Region i. Office of Director 7pp 14326 324 24X
 Fichs 50-317,82/08/04,8208120259
- 8208230101 Summary of B20618 meeting w/util & BNL re open items on post-fire alternative safe shutdown capability

 JAFFE, D H Operating Reactors Branch 3 82/08/09 Operating Reactors Branch 3 6pp 14518 004 24X Fiche 50-317, 82/08/09, 8208230101
- 8208270257 Forwards revisions to security plan & safeguards contingency plan Revisions withheld (ref 10CFR73 21) GMIAZDOWSKI, O Baltimore Gas & Electric Co. 82/08/17 CLARK, R A. NRC No Detailed Affiliation Given 1p. 14563.355 24X Fiche 50-317,82/08/17,8208270257.

- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CP we Commission approved charter for yor UL a noiders of CP re Commission approved charter for CRCR Syc list encl
 DIRKS.W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24% Fiche 50-000,82/07/02,8207080064

- 6208040197 Responds to 820422 ltr & 0708 meeting reparticipation in resolution of Unresolved Bafety Issues A-47 & A-49 re safety implications of control sys & pressurized thermal shock, respectively NRC cannot fund effort on A-49 EISENHUTLD 0 Division of Licensing 82/07/20 LUNDVALL.A & Baitioner Qas & Electric Co 2pp 14229 361 24X Fiche 50-317,82/07/20,8208040197
- 6209030745 Bummary of 820524 meeting w/util re implementation of integrated schedule program Util recently retained consultant to institute commitment control sys JAFFE, D H Operating Reactors Branch 3 82/07/21 FURPLE, R Assistant Director for Licensing ip 14176 310 24X Fiche 50-317, 82/07/21, 8208030745
- E20B040577 Advises that util commitments & exceptions to Reg Guide 1 58 Revision 1 & Reg Guide 1 146 acceptable based on review of util 310803 response to Generic Ltr 81-01. "Gualifications for Insp. Exam. Testing & Audit Personnel "CLARK, R & Operating Reactors Branch 3 82/07/23 LUNDVALL, A E Baltioner Gas & Electric Co 2pp 14225 361 24% Fiche 50-317, 82/07/23, 8208040577
- P20B0A0170 Reiterates position against outright release of environ qualification data from util central environ qualification file Reasons listed Incumbent upon NRC to make reasonable arrangements to review file
 LUNDVALLA.E., ARCHITZEL.R.E., CRANE.C. Baltimore Gas & Electric Co B2/07/27 EISERNUT.D G Division of Licensing, 2pp 14239 233 24% Fiche 50-317,82/07/27,8208040170
- 3208130095 Forwards Amends 73 & 54 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amend allows operation through several operational modes w/one inoperable indicating channel JAFFE.D H Operating Reactors Branch 3 82/07/29 LUNDVALL Baltimore Gas & Electric Co 3pp 14340 320 24X Fiche 50-317, 82/07/29, 8208130095 LUNDVALL, A E
- --8208:30:00 Amends 73 & 54 to Licenses DPR-53 & DPR-69, respectively, allowing operation during several operational modes w/one inoperable control element assembly position indicating channel inoperable CLARK, R A Operating Reactors Branch 3 82/07/29 10pp 14340 323 24X Fiche 50-317.82/07/29.8208130095
- --8208130104 Safety evaluation supporting Amends 73 % 54 to Licenses DPR-53 & DPR-69, respectively * Office of Nuclear Reactor Regulation, Director. 82/07/29 Opp 14340 333 24X Fiche 50-317.82/07/29,8208130095
- --8208130121 Notice of issuance & availability of Amends 73 & 54 to Licenses DPR-53 & DPR-67: respectively CLARK,R A Operating Reactors Branch 3 82/07/27 2pp 14340 336 24X Fiche 50-317, 82/07/29, 8208130095
- 3208100141 Application for amend to Licenses DPR-53 & DPR-69, adding list of safety-related hydraulic snubbers to Tech Spec Table 3 7-4.
- 37-4, LUNDVALL:A E Baltimore Gas & Electric Co 82/07/30 CLARK,R A Operating Reactors Branch 3 3pp 14298 090 24X Fiche 50-317,82/07/30,8208100141
- --8208100144 Proposed Tech Spec Table 3 7-4 re safety-related hydraulic Shubbers ** Baltimore Gas & Electric Co 82/07/30. 7pp. 14298 093 24X Fiche 50-317,82/07/30,8208100141
- 9208110001 Forwards Amends 74 & 55 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to extend date for operability of hydrogen analyzers to 820930.

 JAFFE, D H Operating Reactors Branch 3 82/07/30 LUNDVALL, A E. Baltimore Qas & Electric Co 3pp 14330, 222. 24X Fiche 50-317, 82/07/30, 8208110001
- --8208110002 Amends 74 & 55 to Licenses DPR-53 & DPR-69, respectively, revising Tech Specs to extend date for operability of hydrogen analyzers to 820930 GLARK:R A Operating Reactors Branch 3, 82/07/30 10pp 14330,225 24X Fiche,50-317,82/07/30,8208110001

- --8208110003 Safety evaluation supporting Amends 74 & 55 to Licensea DPR-53 & DPR-69, respectively 4 Office of Nuclear Reactor Regulation, Director 14330 235 24% Fiche 50-317, 82/07/30, 8208110001
- --820Bil0004 Notice of issuance & availability of Amends 74 & 55 to Licenses DPR-53 & DPR-49, respectively. CLARK A Derating Reactors Branch 3. B2/07/30 2pp 14330.237 24X Fiche 50-317, 82/07/30,820B110001.
- 8208040323 BDCIDECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS CALVERT CLIFFS CASE STUDY Docket Nos 50-317 And 50-318.

 (Baltimore Oas And Electric Company)
 FLYRNJ Social Impact Research, Inc Inc FIN B-6268 NUREG/CR-2749 VO2 B2/07/31 Division of Health, Siting & Environment 214pp Available at NTIS \$7 14230 001 24X Fichs 50-317.82/07/31.8208040323 * Mountain West Research: \$7 00
- 820B100272 Application to amend Licenses DPR-53 & DPR-69, revising Tech Specs to incorporate listed changes re ASME Code addenda. RCB, Reg Guide I 33 & leak rate testing. LUNDVALLA E Baltimore gas & Electric Co 82/08/02 CLARK, R A Operating Reactors Brench 3 5pp 14297, 070 24X Fiche 50-317, 82/08/02, 820B100272
- -8208100282 Tech Specs 3 4 3,4 4 3,4 4 10 1 2,6 7,6 8,Table 3 7-4, 3 6 1 2,4 6 1 2,3 6 1 3,4 6 1 3,4 6 4 1 3,4 6 4 1 4 \$ 4 6 4 1 2 re 808 operation & survaillance requirements ### Baltimore Quarter Co. 62/08/02. 15pp 14297 075 Fiche 50-317,82/08/02,8208100272 14297 075 24X
- 8208130081 Forwards Bection IV re background matl for Section III of 820104 Phase I rept on control of heavy loads ABH.R F Baltimore Gas & Electric Co. 62/08/02 EISENHUT.D G Division of Licensing. 48pp 14335 001 24X Fiche 80-317.82/08/02.
- 8208160029 Approves request for withholding 820413 response to NRC questions re use of C-E analytic methods as related to facility Cycle 6 analyses.

 CLARK, R A Operating Reactors Branch 3 82/08/02 LUNDVALL, A 8 Baltimore Oas & Electric Co 3pp 14370, 080 24X Fiche 50-317, 82/08/02, 8208160029 82/08/02 LUNDVALL, A E
- 8208250358 Approves request for withholding rept, "Extended Burnup Operation of C-E PWR Fuel," per 10CFR2,790. CLARK.R A Operating Reactors Branch 3 82/08/02 LUNDVALL,A.E Baltimore Gas & Electric Co 3pp 14562 202 24X Fiche 50-317.82/08/02.8208250558
- 8208260177 Submits list of questions raised & procedures developed re Unresolved Safety Issue A-49, "Pressurized Thermal Shock" study GA program & procedures which govern conduct of study requested
 TITLAND.L E. Beltimore Qas & Electric Co 82/0B/04. JOHNSON.C.E
 Division of Risk Analysis 3pp 14554 319 24X
 Fiche 50~317.62/08/04.8208260177
- 8208110124 Advises that info documenting compliance w/RUREQ-0737, Item II.B 3, "Post-Accident Sampling Bus," will be submitted within 120 days, in response to NRC 820630 request. Response to recent clarification items in 820630 iter inappropriate LUNDVALL.A E Baltimore Oss & Electric Co 82/08/06 CLARK, R A Operating Reactors Branch 3. Ip 14314:350 24X Fiche 50-317, 82/08/06, 8208110124.
- 8208120301 Application for emend to License DPR-53, proposing Tech Spec changes to include automatic initiation of auxiliary feadwater to each steam generator for Modes i t 2 per NUREO-0737, Item II E 1 2 W/Class III fee
- --8208120307 Proposed Tech Spac Figure 3.7-1 & Pages B 3/4 7-2 & 3/4 7-re auxiliary feedwater sys. * Baltimore Gas & Electric Co 82/08/06. 3pp 14324.304. 24X Fiche 50-317.82/08/06.8208120301
- 820B090194 Centric Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summerizes 10CFR Chapter I requirements & provides alternatives to requirements Sec list encl EISENHUT, D 0 Division of Licensing, 82/08/09, Consolidated Edison Co. of New York. 1p 14356-332, 24X Fiche: 50-000, 82/08/09, 8208090194

- 8208180038 Clarifies 820722 response to NUREO-0737. Item 2 K 3 25, "Effect of Loss of AC Current on Pump Seals " Loss of power would tender reactor coolant pumps inoperable reducing need for component cooling water supply to pumps LUMDVALL, A E Baltimore Gas & Electric Co 82/08/11 CLARK, R A Operating Reactors Branch 3 2pp 14377 286 24% Fiche 50-317.82/08/11.8208180038
- 8208230305 Forwards C-E proprietary & nonproprietary versions of "Slides From C-E/NRC/BNHL Meeting on FATES 3, Betheada-MD, 820709" Affidavit for withholding entl Proprietary version withheld (ref 100FR2 790) LUNDVALL, A E Baltimore Gas & Electric Co 82/08/17 CLARK, R A Operating Reactors Branch 3 5pp 14513 151 24X Fiche 50-317, 82/08/17, 8208230305
- G Inspection reports, IE Bulletins & correspondence
- 8208100366 Forwards IE Performance Appraisal Insp Repts 50-317/82-01 & 50-318/82-01 on 820118-28 & 0208-31 & executive summary Significant weaknesses identified TAYLOR. J M Division of Reactor Programs 82/04/14 LUNDVALL. A E, Baltimore Gas & Electric Co. 6pp 14308 274 24X Fiche 50-317, 82/04/14, 8208100366
- --8208100371 IE Performance Appraisal Insp Repts 50-317/82-01 & 50-318/82-01 on 820118-28 & 0208-11 Major area inspected mgt controls over selected licensed activities. HUESSNER R J. SHAFER W. CHOULES N. Division of Reactor Programs 82/04/12 46pp 14308 280 24X Fiche 50-317.82/04/14. 82/04/12 46pp 8208100366
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Lesiage " Svc list encl
 JORRANN E L Bivision of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp. 14356 274, 24X
 Fichs 50-000.82/07/16,8204210393
- B2080S0412 Forwards IE Insp Repts 50-317/82-16 & 50-318/82-14 on B20615-0713 & notice of violation BTARGSTECKI.R Division of Project & Resident Programs 82/07 LUNDVALLAE. Baltimore Gas & Electric Co 2pp 14217 324 Fiche, 50-317, 82/07/16, 8208050412
- ---8208050423 Natice of violation from inep on 820615-0713 8747087ECKI,R Division of Project & Resident Programs 1p 14217.326 24X Fiche 50-317,82/07/16.8208050412
- --9208050429 IE Insp Repts 50-317/82-16 & 50-318/82-14 on 820615-0713 Noncompliance noted auxiliary feedwater sys inoperable in Mod4 3 ARCHITZEL.R.E., TRIMBLE,D.C., MCCABE,E.C., Division of Project & Resident Programs 827/07/15 12pp 14217 327 24X Piche 50-317,82/07/16,8208050412
- B204210393 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Syc list encl URDAN EL Bivision of Engineering & Quality Assurance. 82/07/19. Michigan. Univ of 112pp 14358 001 24X Ficha 50-000.82/07/19.
- 8204210376 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Oradual Loss of Air Fressure" 8vc list encl JORDAN.E L. Division of Enganeering & Quality Assurance. 82/07/20 Consolidated Edison Co of New York. 112pp 14381 001. 24X Fiche.50-000.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Dverpacts." Bvc list encl COBB.L I Division of Fuel Facilities. Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357.2 24X Fish 14357, 276
- 8204210378 IE Info Notice 82-25, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl UCRDANE L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321. 24X Fiche: 50-000, 82/07/22, 8204210378
- B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Evo list and. UORDANIE. L. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co. of New York 122pp 14380 113. 24X Ficher 50-000, 92/07/23, 8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl JORDAN E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp. 14194 120, 24X Fiche 50-000 82/07/23 82040/400

- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Mestinghouse PWR Power Plants " Svc list encl URDAN.E L Division of Engineering 1 Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000. 82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Biver During Work in Fuel Storage Pool " Bvc list encl URDAN,E L Division of Enganeering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28,8204210405
- 8208070049 Forwards response to 1E Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants "Encls summarize bolted closure leakage history & provide chemical composition of lubricants Approx 155 manhours expended LUNDVALL, A E Baltimore Gas & Electric Co 82/07/JD HAYNES, R Region 1. Office of Director 18pp 14270 014 24X 5(5)-813-914-91902/GB-20080689 HAYNES, R. C. Fich . 50-317, 82/07/30, 8208070047
- 8208160017 Forwards IE Insp Rept 50-317/82-15 on 820416-18,21 & 22 & notice of violation.

 MARTIN T. T Division of Engineering & Tachnical Programs 68
 LUNDVALL.A E Baltimore Cas & Electric Co 3pp 14342 099
 Fiche 30-317, 82/07/30, 8208160017
- --8208150018 Notice of violation from insp on 820616-18.21 & 22 * Division of Engineering & Technical Programs 82/07/30 14342-102 24X Fiche. 50-317.82/07/30.8208160017
- --8208160063 IE Insp Rept 50-317/82-15 on 820616-18,21 & 22 Noncompliante noted failure to adequately control work on safety-related sys & failure to establish adequate procedures to maintain containment integrity
 REMITO, W.A., BETTENHAUSEN, L. Division of Engineering & Tachnical
 Programs 82/07/19 10pp 14342 104 24% Fiche 50-317,82/07/30,8208140017
- 820B170D98 Forwards IE High Meeting Rept 50-317/82-21 on 820707 STAROBYECKI.R. Division of Project & Resident Programs 82/08/02 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 14358 225 24X Fiche, 50-317, 82/08/02, 8208170098
- --8208170104 IE Mgt Meeting Rept 50-317/82-21 on 820707 Major items discussed NRC concerns re recent insp findings on insperability of hydrogen analyser during Gutle 5 & concerns about containment leakage rate
 ARCHITZEL, R E . TRIMBLE.D C . MCCABE, E C Division of Project & Resident Programs 82/07/21 Spp 14358 227 24X
 Fiche 50-317,82/08/02.8208170098
- 8208230187 Forwards IE Insp Repts 50-317/82-17 & 50-318/82-15 on CORROLL OF No noncompliance noted
 MARTIN.T. Division of Engineering & Technical Programs 82/08/0;
 LUNDVALL, A E Baltimore Cas & Electric Co 2pp 14517-156. R4X Fiche 50-317, 82/08/03, 8208230189.
- --8209230197 IE Insp Repts 50-317/82-17 & 50-318/82-15 on 820706-09 No Augustity is inspired Major areas inspected licenses action on IE Bullstin 79-24 & administrative controls for safety—related surveitlances; per Reg Quide 1 33 SHAND, E. T. CAPHION, D.L. Division of Engineering & Technical Programs. 82/08/02 9pp 14517 158. 24X Fiche 50-317,82/08/03,8208230189
- 8208230333 Forwards IE Insp Rept 50-317/82-19 on 820713-16 No noncompliance noted MARTIN,T.T Division of Engineering & Technical Programs LUNDVALL, A E Baltimore Oas & Electric Co. 2pp 14508 25 Fiche: 50-317, 82/08/03, 8208230333. 14508 252
- --B208230342 IE Insp Rept 50-317/82-19 on 820713-16 No noncompliance noted Major areas inspected, inservice insp data & licensee action on previous insp findings.
 MCSREARTY:R.A., DURR:U.F. Region 1, Office of Director 82/09/02 4pp 14508:254 24X Fiche. 50-317, 82/08/03, 8208230333
- 8208120259 Ack receipt of 820625 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-317/81-19 & 30-318/81-18 SMITH, G.H. Division of Emergency Preparedness & Operational Support 82/08/04, LUNDVALL, A S. Baltimore Gas & Electric Co 2pp 14326-322 24X Fiche: 50-317, 82/08/04, 8208120259,
- --B20Bi20272 Responds to NRC B20526 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-317/Bi-19 & 50-318/Bi-18 Corrective actions emergency planning unit established & staffed on B20401.
 POINDEXTER, C. Baitimore Gas & Electric Co B2/06/25 BMITH, Q, H Region i, Office of Director. Top 14326: 324 24X Fiche: 50-317, B2/08/04, B208120259

- #2:04007 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " Svc list encl Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388-201 24X Fithe 50-000,82/08/05,8204210407
- emajaoo43 Ack receipt of 820715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/81-25 & 50-318/81-24
- --8208180091 Responds to NRC 820615 itr re violations noted in IE Insp Repts 50-317/81-25 & 50-318/81-24 Corrective actions plant procedure requirements incorporated to move non-fuel assembly SNM inside security fence LWNDVALL.A E Baltimore Oas & Electric Co 82/07/15 MARTIN,T T Division of Engineering & Technical Programs 3pp 14376 303 24X Fiche 50-317.82/08/11.8208180043
- E08300197 Forwards IE Insp Repts 50-317/82-18 & 50-318/82-16 on E20713-0810 & notice of violation STARGSTECKI, R Division of Project & Resident Programs 82/08/16 LUNDVALLA E Baltimore Gas & Electric Co 2pp 14596 057 24X Fiche 50-317, 82/08/16, 8208300197
- --9208300200 Notice of violation from insp on 820713-0810 + Division of Project & Regident Programs 82/08/16 1p 14376 059 24X Fiche 50-317, 82/08/16, 8208300197
- -E208300203 IE Insp Repts 50-317/82-18 & 50-318/82-16 on B20713-0810 Nancompliance noted failure to properly clear tag for 2-PB-192 & B20804 insevertent actuation of safety injection actuation sys
 ARCHITZELR E., TRIMBLE, D.C., MCCABE, E.C. Division of Project & Resident Proprams 82/08/13 20pp 14596 060 24X
 Fiche 50-317,82/08/16,8208300197
- 208230322 Ack receipt of 820727 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/81-17 & 50-386/81-17 & 50-386/81-17 & Francisco of Engineering & Technical Programs 82/08/2
- SO-366761-16

 MARTIN.T T Division of Engineering & Technical Programs 82/08/19,
 LUNDVALL.A E Baltimore Cas & Electric Co 1p 14508 229 24X

 Fiche.50-317, 82/08/19, 8208230322
- -8208230323 Responds to NRC 820628 ltr re violations noted in IE Insp Repts 30-317/81-17 & 90-318/81-16 Corrective actions Radiation Safety Procedure 2-204 will be upgraded to include signoffs for resin solidification process control. LUNDVALLA E Baltimore Oas & Electric Co 82/07/27 NARTIN, T T Division of Engineering & Technical Programs 3pp 14508 230 24X Fiche 50-317.82/08/19.8208230322
- Periodic operating reports & related correspondence
- 208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & enalyzing said info Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fishe 50-000.82/07/13.8208270010
- -8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000, 82/07/13,8208270010
- -8208270555 Forwards "Number of Personnel & Man Rem By Work & Job Function, CY81" TIERNAN, J A Baltimore Gas & Electric Co 82/03/05, HAYNEB, R. C Region 1, Defice of Director 1p 14680 033 24X Fiche 50-000, 82/07/13, 8208270010
- -8208270558 "Number of Personnel & Man Rem By Work & Joh Function, CYB1 "

 * Baltimore Oas & Electric Co 82/03/05 2pp 14680 034 24X
 Fichs 50-000, 82/07/13, 8208270010
- -8208270568 Forwards "Personnel Whole Body Exposures for CY81," per 100FR20,407
 TIERNAN,J A Baltimore Cas & Electric Co 82/03/05, Office of Hanagement and Program Analysis 1p. 14680,037 24X
 Fichs 30-000,82/07/19,8208270010.
- -8209270574 "Personnel Whole Body Exposures for CY81 "
 TIERNAN, J A Baltimore Cas & Electric Co 82/03/05 1
 14680 038 24% Fiche 50-000, 82/07/13,8208270010.

- 8208230371 Forwards monthly operating repts for Jul 1982 LOTITOLE H Baltimore Cas & Electric Co 82/08/17 Director's Office, Office of Inspection and Enforcement ip 14512 329 24) Fiche 50-317, 82/08/17, 82/08/230371
- --B208230373 Monthly operating repts for Jul 1982 LOTITO.E Baltimore Gas & Electric Co B2/0B/17 14512 330 24% Fiche 50-317, 82/09/17, 8208230371
- 8 Reportable occurrences. LERs & related correspondence
- 8208240488 Forwards LER 81-015/03L-0 RUSSELL,L B Baltimore Cas & Elettric Co 81/03/26 ORIER,B.H Region I. Philadelphia. Office of the Director (81/03/01). 1p. 14544 158 24X Fichs.50-317.81/03/26.8208240488
- --B20B240491 LER B1-015/OSL-0: on B10226, shift supervisor informed that sample pump for control room radiation monitor was out of sycirendering auto recirculation of control room inoperable on high radiation. Caused by pump selsure DAVIS.6 M , RAYBURN.C L Baltimore Oas & Electric Co B1/03/26 Region 1, Philadalphia. Office of the Director (B1/03/01) 2pp. 14544 159 24X Fiche 50-317,81/03/26,820B24048B
- 8208240493 Forwards LER 81-014/03L-0 RUSSELL,L B. Baltimore Gas & Electric Co. 81/03/27. GRIER, B H Region i. Philadelphia. Office of the Director (81/03/01). 1p. 14544 143 24X Fiche 50-317,81/03/27,8208240493.
- --B208240494 LER 81-014/03L-0.on B10227.diessi generator i2 started automatically Generator stop & start failure elerm received Gaused by insufficient contact wipe provided by diesel start switch LAGIEMSKI, J. B., RIZZO, P.O. Baltimore Oas & Electric Co. 81/03/27, Region 1, Philadelphia, Office of the Director (81/03/01). 2pp. 14544 144. 24% Fiche, 50-317.81/03/27, 8208240493
- 8208260496 Forwards LER 81-028/04T-0. RUSSELL,L B. Baltimare Oas & Electric Co. 81/03/04. ORIER,B.H Region I, Philadelphia. Office of the Director (81/03/01) 1p. 14595-034 24X Fiche 50-317,81/05/04,8208260496.
- --B208240504 LER B1-O2B/O4T-O; on B10423, drain valve for waste neutralizing tank II discovered open. Caused by failure of operators to follow procedures. Involved operators disciplined.

 DAVIS.8 M Baltimore Cas & Electric Co 81/05/04 Region i, Philadelphia, Office of the Director (81/03/01), 2pp. 14595;035, 24X Ficha 30-317, OB/O5/04, 8208260476
- 8208310032 Forwards LER 81-038/04T-0. RUSSELL,L B Baltimore Gas & Electric Co 81/04/09 GRIER, B, H Region 1, Philadelphia. Office of the Director (81/03/01) 1p. 14697 206 24X Fiche 50-317,81/06/09,8208310032
- --8208310036 LER 81-038/04T-0 on 810526, Apr 1981 bay water tritium sample concentration measured 10 times higher than background Effluent limits not exceeded therefore corrective action not necessary RAFI.A. BROBBT.Q E Baltimore Oas & Electric Co 81/06/07. Region 1. Philadelphia. Office of the Director (81/03/01) 1p. 14697.207. 24X Fiche: 50-317, 81/06/09, 8208310032.
- 8208250546 Forwards LER 81-026/01T-0. RUSSELLL 8 Baltimore Oas & Electric Co. 81/06/10. ORIER. B. H. Region 1. Philadelphia. Office of the Director (81/03/01). ip 14562 209 24% Fiche: 50-317,81/06/10.8208250346
- --B208230551 LER B1-026/01T-0. on 810527.acoustic flow indicator for pressurizer safety valve 1-RV-201 found inoperable Caused by work in progress resulting in heavy object resting on a severing steel-sheathed cable. Repair completed on 810530.

 Baltimore Gas & Electric Co. B1/06/10 Region 1. Philadelphia. Office of the Director (81/03/01). 2pp 14562;210. 24X Fiche: 50-317, 81/06/10, 8208250546
- 8208250160 Forwards E.ER 81-040/03L-0. RUSSELL-L. 8. Baltimore Oas & Electric Co 81/06/16 QRIER, B. H. Region 1, Philadelphia, Office of the Director (81/03/01) 1p. 14559-230. 24X Fiche: 50-317, 81/06/16, 8208250160.
- --8208250171 LER 81-040/03L-0:on 810601, during normal startup, pressurizer level deviated from program level by more than 5% during changes in RCS temp. Caused by normal startup operations. DAVIS.8 H Baltimore Gas & Electric Co. 81/06/16. Region 1, Philadelphia, Dffice of the Director (81/03/01). 2pp. 14559; 231, 24X Fiche: 50-0:17, 81/06/16. 8208250160

- 8208250370 Forwards LER 81-039/03L-0 RUSSELL,L B Saltimore Gas & Electric Co 81/07/04 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 14362 293 24x Fiche 50-317,81/07/06.8208250390
- --B20B250393 LER B1-039/03L-O on B10606.during preventive maint test, control element assembly 21 dropped into core Power reduced to 70% & assembly withdraum Electrical test disclosed no cause for event Test results forwarded to supplier JUNOE, M A . RIZZO, P G Baltimore Gas & Electric Co 81/07/06 Region 1, Philadelphia, Office of the Director (81/03/01) ip 14562 294 24X Fiche 50-317, B1/07/06, B208250390
- 8208020387 RO on 820717, safety injection tank ilB level on narrow range indicator decreased below Tech Spec limit during investigation of similar discrepancy on wide-range indicator Water added RUSSELL, L B Baltimore Oas & Electric Co 82/07/19 HAYNES, R C Region 1. Office of Director ip 14148 209 24% Fiche 50-317.82/07/19,8208020387
- 8208050088 Forwards updated LER 82-021/03X-1 RUSSELL.L B Baltimore Gas & Electric Co 82/07/19 HAYNES,R C Region 1. Office of Director ip 14213 191 24X Fiche 50-317.82/07/19.8208050088
- --B208050092 Updated LER 82-021/03x-1 on 820417.main steam safety valve RV-3793 did not lift at required setpoint No cause stated Valve reset & retested LA01EWSKI.J S . HUSEBY.D E Baltimore Gas & Electric Co 82/07/17 Region 1. Office of Director 2pp 14213 192 24X Fiche 50-317.82/07/17.8208050088
- 8208050359 Forwards updated LER 81-073/03X-1 RUSSELL.L B Baitmore Gas & Electric Co 82/07/19 HAYNES.R C Region 1. Office of Director ip 14209 183 24X Fiche 50-317.82/07/19.8208050359
- --8208050392 Updated LER 81-073/03X-1 on 811103, unidentified RCB leakage increased to 1 23 gpm Caused by loose valve packing Valve repacked MENDERLICH, R L . HUSEBY, D E Baltimore Gas & Electric Co 82/07/19 Region 1. Office of Director 1p 14209 184 24X Fiche 50-317, 82/07/19, 8208050359
- 8208050364 Forwards LER 82-001/03X-1 RUSSELL,L B Baltimore Gas & Electric Ca 82/07/21 HAVNES,R C Region 1, Office of Director 1p 14209 149 24X Fichs 50-317, 82/07/21,8208050364
- --B2080503B6 LER 82-001/03%-1 on B20119, during performance of surveillance test procedure, discovered excessive leak rate past containment personnel air lock outer door Caused by loose seal packing New packing inserted JUNGE.H A. WEIR.P J Baltimore Gas & Electric Co 82/07/21 Region 1. Office of Director ip 14209 150 24% Fiche 50-317,82/07/21,8208050364
- 8208020389 Forwards updated LER 82-022/01T-1 RUSSELL.L B Baltimore Oas & Electric Co 82/07/22 HAYNES.R C Region 1. Office of Director ip 14150 073 24X Fiche 50-317.82/07/22.8208020388
- --8208020391 Updated LER 82-022/017-1 on 820503, total Type B & C penetration leakage calculations compared to brong spec Caused by incorrectly revised local leak rate surveillance test procedure Procedure revised SYBNOR.R Baltimore Cas & Electric Co 82/07/22 Region 1. Office of Director 3pp 14150 074 24X Fiche 50-317,82/07/22,8208020388
- 8208100041 Forwards LER 82-032/03L-0 RUSSELL, L 8 Baltimore Gas & Electric Co 82/07/29 Region 1, Office of Director 1p 14296 256 24X Fiche 50-317, 82/07/29, 8208100041
- --8208100057 LER 82-032/03L-0 on 820629, motor operated isolation valve in salt water sys supply to circulating water pump room air coolers inoperable electrically & would not respond properly to SIAS Caused by tripped thermal overloads PAVIS.0 S . BASSOL F Baltimore Oas & Electric Co 82/07/29 Region 1. Office of Director in 14296 257 24X Fiche 50-317,82/07/29,8208100041
- 8208090044 Forwards LER 82-039/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 82/07/30 HAYNES,R C Region 1. Office of Director 1p 14270 036 24X Fiche 50-317,82/07/30.8208090044

- --B208070045 LER B2-039/03L-0 on B20701. safety injection tank 11B level transmitter i-LT-321 found out of calibr Caused by zero shift Transmitter replaced & recalibr PAVIS,0 S , BASBOL F Baltimore Oas & Electric Co 82/07/30 Region 1, Office of Director ip 14270 037 24X Fiche 50-317,82/07/30,8208090044
- 8208090064 Forwards LER 82-031/03L-0 RUSSELL.L B Baltimore Cas & Electric Cu 82/07/30 HAYNES.R C Region 1. Office of Director ip 14269 229 24X Fithe 30-317.82/07/30.8208090064
- --B208090068 LER 82-031/03L-0 on 820702, auxiliary feedwater flow indication to steam generator 11 indicated 100 gpm w/no flow in line Caused by bent ficture wire in flow transmitter i-FT-4509 Transmitter replaced PAVIG.6 S , RAYNOR, J Baltimore Gas & Electric Co 82/07/30 Region 1. Office of Director ip 14269 230 24X Fiche 50-317.82/07/30,8208090064
- 8208070074 Forwards LER 82-033/03L-0 ROSEELL,L B Baltimore Gas & Electric Co 82/07/30 HAYNES,R.C Region I. Office of Director ip 14270 176 24X Fiche 50-317,82/07/30,8208097074
- --B208090077 LER 82-033/03L-0 on B20701, during Mode 2 operation w/high pressure safety injection pump running, leak into 11A safety injection tank discuvered Caused by deterioration of disc sealing O-ring Disc O-rings replaced MENDERLICH.R L. PRICE.W J Baltimore Gas & Electric Co B2/07/30 Region 1, Office of Director 2pp 14270 177 24X Fiche 50-317,82/07/30.8208090074
- 820B090080 Forwards LER 82-030/03L-0 RUSSELL.L B Baltimore Oas & Electric Co 82/07/30 HAYNES.R C Region 1. Office of Director ip 14270 188 24X Fiche 50-317.82/07/30.8208090080
- --8208070083 LER 82-030/03L-0 on B20627, while in Mode 3, auxiliary feedwater flow indication to steam generator 11 indicated 350 gpm w/no flow in line Caused by installation of pressure sensing line snubbers Snubbers removed PARVIG.0 8 , RAYNOR.J Baltimore Gas & Electric Co 82/07/30 Region 1, Office af Director 2pp 14270 189 24% Fiche 50-317,82/07/30,8208070080
- 8208090110 Forwards LER 82-037/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 82/07/30 HAYNES,R C Region 1. Office of Director 1p 14269 326 24X Fiche 50-317.82/07/30.8208090110
- --B20B090ii5 LER B2-037/03L-0 on B20701.pressurizer level deviated slightly from program level by more than plus/minus 5% & pressurizer pressure decreased below 2, 225 psia to changes in RCB temp necessitated by startup tests JUNOELM A Baltimore Cas & Clectric Co B2/07/30 Region 1, Office of Director 2pp 14269 327 24X Fichs 50-317,82/07/30,8208090110
- 8208090221 Forwards LER 82-035/01T-0 RUSSELLL B Baltimore Gas & Electric Co 82/07/30. MAYNES.R C Region 1. Office of Director ip 14271:183 24X Fiche 50-317.82/07/30.8208090221
- --8208090227 LER 82-035/017-0 on 820717. safety injection tank nerrow range level was 192 but read 180 inches Caused by narrow 11B range indicator sticking due to dirt Procedures will be revised Indicator repaired PAVIS, 0 8 Baltimore Gas & Electric Co. 82/07/30 Region 1. 0ffice of Director ip 14271 184 24X Fiche 50-317, 92/07/30, 8208090221
- 8208100064 Forwards LER 82-036/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 82/07/30. HAYNES, R & Region 1. Office of Director ip 14296 219 24X Fichs. 50-317, 82/07/30, 8208100064
- --8208100068 LER 82-036/03L-0 on 820701. during startup physics testing, control element assembly (CEA) 35 dropped into core. CEA was withdraun & aligned w/remainder of Group 5 CEAs Cause not determined No recurrence of event identified JUNGE, M A , RIZZO, P 0 Baltimore Cas & Electric Co 82/07/30 Region 1, Office of Director ip 14296 220 24X Fiche: 50-317,82/07/30,8208100064
- 8208100077 Forwards LER 82-034/03L-0 RUSEELL.L B Baltimore Gas & Electric Co 82/07/30 HAYNEB,R C Region 1, Office of Director. ip 14277 328 24X Fiche 50-317,82/07/30,8208100079

- --820Bi00105 LER 82-034/03L-0 on 820409 & 0702, snubbers in main steam sys not periodically tested per surveillance test program Caused by discrepancy between G list & piping stress analysis Snubbers upgraded & tested PAVIS.O S Baltimore Gas & Electric Co 82/07/30 Region i, Office of Director ip 14297 329 24X Fiche 50-317,82/07/30,8208100099
- 8208130020 Forwards LER 82-038/03L-0 RUSSELL,L B Baltimore Gas & Electric Co 82/08/05 HAYNES,R C Region 1, Office of Director ip 14333 199 24X Fiche 50-317.82/08/05,8208130020
- --8208130025 LER 82-038/03L-0 on 820706, following loss of steam generator feed pump 11, pressurizer level deviated from program level by greater than 5% Caused by increasing steam generator level too quickly, resulting in RCS temp decrease JUNGE, M. A. Baltimore Gas & Electric Co. 82/08/05 Region 1, Office of Director 1p 14333 200 24% Fiche 50-317,82/08/05, 8209130020
- 8208300084 RO 82-40 on 820805, while in Mode 3, pressurizer pressure transmitters for four safety channels found out of calibr Transmitters recalibr Pressure transmitter readings will be taken periodically & compared against test gauges RUSSELL.L B Baltimore Oas & Electric Co 82/08/06 HAYNES, R C Region 1. Office of Director 1p 14578 243 24X Fiche 30-317, 82/08/06, 8208300084
- 8208230175 Forwards LER 82-041/03L-0 RUBSELL.L. B Baltimore Gas & Electric Co 82/08/12 HAYNES,R C Region 1. Office of Director ip 14514 334 24X Fiche 50-317.82/08/12.8208230175
- --8208230178 LER 82-041/03L-0 on 820713, channel A high gower, thermal margin/low pressure & axial shape index trip units bypassed to allow failing hot leg temp element signal to be removed from reactor protective sys Caused by changing temp element JUNGE, M A.: RAYNOR.J W Baltimore Oas & Electric Co 82/08/12 Region i. Office of Director ip 14514 335 24X Fiche 50-317,82/08/12,8208230175
- 8208260218 Forwards LER 82-040/01T-0 RUSSELL,L B Baltimore Gas & Electric Co 82/08/18 HAYNES,R C. Region 1. Office of Director 19 14554 305 24X Fiche 30-317.82/08/18,8208260218
- --8208260225 LER 82-040/0iT-0 on 820805, pressurizer pressure transmitters for four safety channels removed from svc for recalibr Caused by suspected failure of Barton transmitter. Model 763 to meet thermal effect spec WENDERLICH.R L . 8ASBO, L F Baltimore Gas & Electric Co 82/08/18 Region i. Office of Director 2p. 14854 306, 24% Fiche. 50-317.82/08/18, 8208260218
- 8208260227 Forwards LER 82-042/03L-0 RUSSELL.L B. Baltimore Qas & Electric Co 82/08/20 HAYNES,R C. Region 1. Office of Director I p 14552 354 24X Fitch 50-317.82/08/20,8208260229
- --8208260235 LER 82-042/03L-0 on 820722, charging pump 12 had reduced capacity w/charging pump 13 out of svc Caused by normal end of life of pump packing Charging pump 12 repaired & returned to svc Design spec change implemented LADIEMEKI, J, B., HUBERY, D, E. Baltimore Cas & Electric Co 82/08/20 Region 1. Office of Director. ip 14552 355 24X Fiche, 50-317, 82/08/20, 8208260229
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

 F Sacurity, medical, emergency & fire protection plans
- 8208040607 Ack receipt of 820604 & 27 ltrs transmitting temporary mods to physical security program to allow for const of sve tunnel & storage of fresh fuel onsite Mods consistent w/ 10CFR50 54(p) & are acceptable CLARK, R A Operating Reactors Branch 3 82/07/27 BAUMAKER, N J Baltimore Oss & Electric Co 1p 14225 277 24X Fiche 50-317, 82/07/27, 820804040407
- 8208060069 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/08/02 Document Management Branch ip 14282 210 24X Fiche, 50-317, 82/08/02, 82/08/04067

- --8208060072 Forwards public version of revised emergency plan implementing procedures including Procedures ERPIP 3 1 re initial notification checklist & ERPIP 3 5 re immediate action personnel injury * Baltimore Gas & Electric Co 82/07/27 CLARK, R. A Decrating Reactors Branch 3 3pp 14282 211 24X Fiche 50-317,82/08/02,8208060069
- --B208060078 Public version of revised emergency plan implementing procedures including Procedures ERPIP 3 1 re initial notification checklist & ERPIP 3 5 re immediate action personnel injury & Baltimore Qas & Electric Co 82/06/09 250pp 14282 214 24X Fiche 50-317,82/08/02.8208040069
- B20B120259 Ack receipt of B20625 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-317/81-19 & 50-318/81-18
 SHITH.O K Division of Emergency Preparedness & Operational Support B2/08/04 LUNDVALL.A E Baltimore Oas & Electric Co 2pp 14326 322 24X Fiche 50-317,82/08/04,8208120259
- --B20B120272 Responds to NRC B20526 ltr reviolations noted in IE
 Emergency Preparedness Appraisal Repts 50-317/B1-19 &
 50-31B/B1-1B Corrective actions emergency planning unit
 established & staffed on B20401
 PDINDEXTER, C Baltimore 9as & Electric Co 82/06/25 SMITH, Q M
 Region 1, Office of Director 7pp 14326 324 24X
 Fiche 50-317, 82/08/04, 820B120259
- 8208230101 Summary of 820618 meeting w/util & BML re open items on post-fire alternative safe shutdown capability JAFFE.D H Operating Reactors Branch 3 82/08/09 Operating Reactors Branch 3 6pp 14518 004 24X Fiche 50-317.82/08/09, 8208230101
- 8208270257 Forwards revisions to security plan & safeguards contingency plan Revisions withheld (ref 10CFR73 21).

 GRIAZDOMSKI, 0 Baltimore Gas & Electric Co 82/08/17 CLARK, R A NRC No Datailed Affiliation Given 1p 14563 355 24X

 Fiche 50-317.82/08/17,8208270257
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for GL & holders of CP re Commission approved charter for CROR Byc list encl
 DIRCKS.W J Defice of the Executive Director for Operations
 82/07/02 Consolidated Edison Co. of New York 93pp 14194 001
 24X Fichs 50-000.82/07/02.8207080064
- 8208040197 Responds to 820622 ltr & 0708 meeting re participation in resolution of Unresolved Safety Issues A-47 & A-49 re safety implications of control sys & pressurized thermal shock, respectively NRC cannot fund effort on A-49 EISENHUT, D 0 Division of Licensing 82/07/20 LUNDVALL, A E Baltimore 9as & Electric Co 2pp 14229 361 24% Fiche: 50-317, 82/07/20, 8208040197
- 8208030745 Summary of 820524 meeting w/util re implementation of integrated schedule program Util recently retained consultant to institute commitment control sys JAFFE.D H Operating Reactors Branch 3 82/07/21 PURPLE.R. Assistant Director for Licensing ip 14196 310 24X Fiche. 50-317, 82/07/21, 8208030745
- 820B040577 Advises that util commitments & exceptions to Reg Quide i 5B Revision i & Reg Quide i 146 acceptable based on review of util 810805 response to Generic Ltr Bi-Oi, "Qualifications for Insp.Exam. Testing & Audit Personnel" "CLARK.R A Operating Reactors Branch 3 82/07/23 LUNDVALL:A E Baltimore Oas & Electric Co. 2pp 14225 361 24X Fiche: 50-317, 82/07/23, 8208040577
- 8208060170 Reiterates position against nutright release of environ qualification data from util central environ qualification file. Reasons listed incumbent upon NRC to make reasonable arrangements to review file.

 LUNDVALL, A E , ARCHITZEL.R.E , CRANE.C Baltimore Oas & Electric Co 82/07/27. EISENHUT.D @ Division of Licensing. 2pp 14239 233. 24X Fiche 50-317.82/07/27.828060170
- 8208130095 Forwards Amends 73 & 54 to Licenses DFR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amend allows operation through several operational modes w/one inoperable indicating channel JAFFE, D H Operating Reactors Branch 3 82/07/29, LUNDVALL, A E, Baltimore Qas & Electric Co 3pp 14340:320, 24X Fiche 50-317, 82/07/29, 8208130095.

- --8208130100 Amends 73 & 54 to Licenses DPR-53 & DPR-69, respectively, allowing operation during several operational modes w/one inoperable control element assembly position indicating channel inoperable CLARK.R A Operating Reactors Branch 3 82/07/29 (Opp 14340 323 244 Fiche 50-317.82/07/29,8208130095
- --B208130104 Safety evaluation supporting Amends 73 & 54 to Licenses PPR-53 & DPR-69, respectively • Office of Nuclear Reactor Regulation, Director 82/07/29 3pp 14340 333 24X Fiche 50-317,82/07/29,8208130095
- --8208i30121 Notice of issuance & availability of Amends 73 & 54 to Licenses DPR-53 & DPR-69, respectively CLARK,R A Operating Reactors Branch 3 82/07/29 2pp 14340 336 24X Fiche 50-317, 82/07/29,8208i30095
- 8208100141 Application for amend to Licenses DPR-53 & DPR-49, adding list of safety-related hydraulic snubbers to Tach Spec Table 3 7-4 LUNDVALL, A E Baltimore Gas & Electric Co 82/07/30 CLARK, R A Operating Reactors Branch 3 3pp 14298 090 24X Fichs 50-317, 82/07/30, 8208100141
- --8208100144 Proposed Tech Spec Table 3 7-4 rs safety-related hydraulic snubbers * Baltimore Gas & Electric Co B2/07/30 7pp 14298 093 24X Fichs 50-317.82/07/30.8208100141
- 8208110001 Forwards Amends 74 & 55 to Licenses DPR-53 & DPR-67, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to extend date for operability of hydrogen analyzers to 820930

 JAFFE D H Operating Reactors Branch 3 82/07/30 LUNDVALL.A E Baltimore Oas & Electric Co 3pp 14330-222 24X

 Fiche 50-317.82/07/30.8208110001
- --820B110002 Amends 74 & 55 to Licenses DFR-53 & DFR-69, respectively, revising Tech Specs to extend date for operability of hydrogen analyzers to 820930 CLARK, A Operating Reactors Branch 3 82/07/30 10pp 14330 225 24X Fiche 50-317, 82/07/30, 820B110001
- --8208110003 Bafety evaluation supporting Amends 74 & 55 to Licenses DPR-53 & DPR-69, respectively e-Office of Nuclear Reactor Regulation. Director 82/07/30 2pp 14330 235 24X Fiche 50-317, 82/07/30, 8208110001
- --8208110004 Notice of issuance & availability of Amends 74 & 55 to Licenses DPR-93 & DPR-69, respectively CLARK, R A Operating Reactors Branch 3 82/07/30 2pp 14330 237 24X Fiche 50-317, 82/07/30,8208110001
- B20B040323 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS CALVERT CLIFFS CASE STUDY Docket Nos 50-317 And 50-318 (Baltimore Qas And Electric Company)
 FLYNN, J Social Impact Research, Inc # Mountain West Research, Inc FIN B-6268 NUREG/CR-2749 VO2 82/07/31 Division of Health, Siting & Environment 214pp Available at NTIS \$7 00 14230 001 24x Fiche 50-317, B2/07/31, B208040323.
- 820B100272 Application to amend Licenses DPR-53 & DPR-69, revising Tech Specs to incorporate listed changes re ASME Code addenda. RCB.Reg Guide 1 33 & leaf rate testing LUNDVALL.A E Baltimore Oas & Electric Co B2/08/02 CLARK.R A Operating Reactors Branch 3 5pp 14297 070 24X Fiche 50-317,82/08/02.8208100272
- --8208100282 Tech Specs 3 4 3,4 4 3,4 4 10,1,2,6 7,6 8,Table 3 7-4, 3 6 1 2,4 6,1 2,3 6 1 3,4,6 1 3,4 6 4 1 3,4 6 4 1 4 & 4 6 4 1 2 re RCS operation & surveillance requirements # Baltimore 9as & Electric Co 82/08/02, 15pp 14297 075 24X Fiche 50-317,82/08/02,8208100272
- 8208130081 Forwards Section IV re background mat1 for Section III of S20104 Phase I rept on control of heavy loads
 ASH.R.F Baltimore Gas & Electric Co 82/08/02. EIBENHUT, D. G. Division of Licensing 48pp 14335 001 24X Fiche 50-317,82/08/02,8208130081.
- 820Bi10124 Advises that info documenting compliance w/NUREG-0737, Item II.B 3. "Post-Accident Sampling Bys." will be submitted within 120 days in response to NRC 820630 request Response to recent clarification items in 820630 ltr inappropriate LUNDVALL.A E Baltimore Oss & Electric Co 82/08/06 CLARK.R. A Operating Reactors Branch 3 ip 14314 350 24X Fiche 50-317, 82/08/06, 8208110124

- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208180038 Clarifies 820722 response to NUREO-0737. Item 2 K 3 25, "Effect of Loss of AC Current on Pump Seals" Loss of power would render reactor coolant pumps inoperable, reducing need for component cooling water supply to pumps LUNDVALL. A E Baltimore Gas & Electric Co 82/08/11 CLARK.R A Operating Reactors Branch 3 2pp 14377 286 24X Fiche 50-317,82/08/11.8208180038
- 8208230305 Forwards C-E proprietary & nonproprietary versions of "Slides From C-E/NRC/BNWL Meeting on FATES 3, Bethesda, MD, 820709 "Affidavit for withholding anci Proprietary version withhold (ref 10CFR2 790) LUNDVALL.A E Baltimore Qas & Electric Co 82/08/17 CLARK.R A Operating Reactors Dyanch 3 5pp 14513 151 24X Fiche 50-317, 82/08/17, 8208230305
- Q Inspection reports. IE Bulletins & correspondence
- 8208100366 Forwards IE Performance Appraisal Insp Repts 50-317/82-01 & 50-318/82-01 on 820118-28 & 0208-11 & executive summary Significant weatnesses identified. TAYLOR.J M Division of Reactor Programs. 82/04/14 LUNDVALL.A E Baltimore Gas & Electric Co 6pp , 14308 274 24X Fiche 50-317.82/04/14.8208100364
- --8208100371 IE Performance Appraisal Insp Repts 50-317/82-01 & 50-318/82-01 on 820118-28 & 0208-11 Major area inspected most controls over selected licensed activities WDESGNER, R J , SHAFER, H , CHOULES, N Division of Reactor Programs B2/04/12 46pp 14308, 280 24X Fiche 50-317,82/04/14, 8208100366
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakape " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co of New York 87pp. 14356 274 24% Fiche 50-000,82/07/16,8204210393
- 8208050412 Forwards IE Insp Repts 50-317/82-16 & 50-318/82-14 on 820615-0713 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/07/16 LUNDVALL, A E Baltimore Gas & Electric Co 2pp. 14217 324, 24X Fichs. 80-317, 82/07/16, 8208050412.
- --B208050429 IE Insp Repts 50-317/82-16 & 50-318/82-14 on B20615-0713 Noncompitance noted auxiliary feedwater sys inoperable in Mode 3 ARCHITZEL.R E , TRIMBLE.D C , MCCABE.E C Division of Project & Resident Programs B2/07/15 12pp 14217 327 24X Fishe 50-317.82/07/16, 8208050412
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Buc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan
- 8204210396 IE Info Notice 82-25, "Failures of Hillur Actuators Upon Gradual Loss of Air Pressure," Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co. of New York, 112pp 14381 001 24X Fiche 50-000.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks," Svc list encl. COBB.L I Division of Fuel Facilities, Materials & Gafeguards. 82/07/20 Consolidated Edison Co of New York 7ipp. 14357, 276 24X Fiche 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-26, "RCIG & HPCI Turbine Exhaust Check Valve Failures " Syc list encl.
 JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/22.
 Consolidated Edison Co of New York 112pp 14194 321, 24%
 Fiche. 50-000, 82/07/22, 8204210398
- BR04210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding In Vicinity of Drained & Open RCS " Evc list encl.

 JORDAN, E.L. Division of Engineering & Guality Assurance B2/07/23 Consolidated Edison Co. of New York 122pp 14380 115. 24X Fiche, 50-000, 82/07/23, 8204210401

- 9204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PMRs " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fichs, 50-000: 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Syc list encl JORDAN.E L Division of Engineering & Quality Assurance 62/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L. Division of Engineering & Quelity Assurance 62/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208090049 Forwards response to 1E Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PMR Plants" Encls summarize bolted closure leakage history & provide chemical composition of lubricants Approx 195 manhours expended LUNDVALL.A E Baltimore Oas & Electric Co 82/07/30 HAYNEB,R C Region 1, Office of Director. 18pp 14270:014, 24X Fiche, 50-317, 82/07/30, 8208090049
- 8208230189 Forwards IE Insp Repts 50-317/82-17 & 50-318/82-15 on 820706-09 No noncompliance noted HARTIN.T.T. Division of Engineering & Technical Programs 82/08/0; LUNDVALL, A E Daltimore Oas & Electric Co 2pp 14517 156 24X Fiche; 80-317, 82/08/03, 8208230187.
- --8208230197 IE Insp Repts 50-317/82-17 & 50-318/82-15 on 820706-09. No noncompliance noted Major areas inspected licenses action on IE Bulletin 79-24 & administrative controls for safety-related surveillances, per Reg Guide I 33 SHAUD, E T., CAPHTON, D. L., Division of Engineering & Technical Propress. 82/08/02 9pp, 14517-158 24X Fichs. 80-317, 82/08/03, 8208230189
- 8208/20259 Ack receipt of 820625 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appreisal Repts 50-317/81-19 & 50-318/81-18 SHITH, Q H Division of Emergency Preparedness & Operational Support, 82/08/04, LUNDVALL, A E. Baltimore Gas & Electric Co 2pp 14326:322. 24X Fichs 50-317,82/08/04,8208120259
- --B20B120272 Responds to NRC B20526 ltr re violations noted in IE
 Emergency Preparedness Appraisal Repts 50-317/81-19 &
 50-31B/B1-16 Corrective actions emergency planning unit
 established & staffed on 820401.
 PDINDEXTER.C. Baltimore Oas & Electric Co 82/06/25. SMITH.O H
 Region 1. Office of Director 7pp 14326 324 24X
 Fichs: 50-317,82/08/04.820B120259
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " 8vc list encl.
 JORDAN.E.L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co. of New York 117pp 14388-201 24X
 Fiche.30-000.82/08/05.8204210407
- 8208180043 Ack receipt of 820715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/81-25 & 50-318/81-24
 - HARTIN.T.T. Division of Engineering & Technical Programs 82/08/11 LUMDVALL.A.E Baltimore Oas & Electric Co. 1p 14376 302 24X Fiche. 30-317, 82/08/11, 8208180043
- --B20BiB0051 Responds to NRC B20Ai5 ltr re violations noted in IE Insp Repts 50-317/Bi-25 & 50-31B/Bi-24. Corrective actions plant procedure requirements incorporated to move non-fuel assembly BNM inside security fence LUNDVALLIA E. Baltimore Cas & Electric Co B2/O7/i5. MARTIN,T.T Division of Engineering & Technical Programs 3pp 14376.303 24X Fiche: 50-317.82/08/II.8208180043
- 820B300197 Forwards IE Insp Repts 50-317/82-18 & 50-318/82-16 on 820713-0810 & notice of violation, STAROSTECKI.R Division of Project & Resident Programs 82/08/16 LUNDVALL, A.E. Baltimore Oas & Electric Co 2pp 14596 057 24X Fiche: 80-317, 82/08/16, 8208300197
- --B208300200 Notice of violation from insp on 820713-0810, # Division of Project & Resident Programs, 82/08/16, 1p 14594:059 24X Fiche:80-317,82/08/16,8208300177.
- --B208300203 IE Insp Repte 50-317/82-16 & 50-318/82-16 on 820713-0810 Noncompliance noted failure to properly clear tag for 2-P8-172 & 820804 inadvertent actuation of safety injection actuation sys.
 ARCHITZEL, R. E. TRIMBLE, D. C., MCCABE, E. C. Division of Project & Resident Programs. 82/08/13, 20pp 14596.060 24X Fithe: 50-317, 82/08/16, 8208300197.

- 8208230322 Act receipt of 820727 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/81-17 & 50-318/81-16
 MARTIN T T Division of Engineering & Technical Programs 82/08/19
 LUNDVALLA E Baltimore Cas & Electric Co ip 14508 227 24X
 Fiche 50-317, 82/08/19, 8208230322
- --8208230323 Responds to NRC 820528 itr reviolations noted in IE Insp Repts 50-317/91-17 & 50-318/81-16 Corrective actions Radiation Safety Procedure 2-204 will be upgraded to include signoffs for resin solidification process control LUNDVALL.A E Baltimore Oas & Electric Co 82/07/27 MARTIN.T. T Division of Engineering & Technical Programs 3pp 14508 230 24X Fiche 50-317.82/08/19.8208230322
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R. A Critical Mass Energy Project 8pp 14479; 208 24X Fiche 50-000.82/07/13.8208270010
- --B20B270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" e NRC - No Detailed Affiliation Given B2/07/13 48pp 14679 216 24X Fiche 50-000, B2/07/13, B20B270010
- --8208270555 Forwards "Number of Personnel & Man Rem By Work & Job Function.CY81" TIERNAN.J A Baltimore Gas & Electric Co 82/03/05 HAYNES, R C Region 1. Defice of Director 1p 14480 033 24X Fiche 50-000,82/07/13,8208270010
- --8208270558 "Number of Personnel & Men Rem By Work & Job Function, CYB1."

 * Baltimore Oas & Electric Co 82/03/05 2pp 14680.034 24X
 Fiche 50-000, 82/07/13, 8208270010
- --B20827056B Forwards "Personnel Whole Body Exposures for CYB1." par iOCFR20 407 TIERNAN.J A Baltimore Gas & Electric Co 82/03/05. Office of Hanegement and Program Analysis 1p 14680 037 24X Fiche, 50-000, 82/07/13, 82082
- --8208270574 "Personnel Whole Body Exposures for CY81 "
 TIERNAN, J A Baltimore Cas & Electric Co 82/03/05 1p.
 14680 038 24X Fiche 50-000, 82/07/13, 8208270010
- 8208230371 Forwards monthly operating repts for Jul 1982 LOTITO, E M Baltimore Gas & Electric Co 82/08/17 Director's Office, Office of Inspection and Enforcement ip 14512,329 24X Fiche 50-317,82/08/17,8208230371
- --8208230373 Honthly operating repts for Jul 1982 LOTITO.E Baltimore Cas & Electric Co 82/08/17 14512.330 24X Fiche 50-317,82/08/17,8208230371
- 8 Reportable occurrences, LERs & related correspondence
- 8208310502 LEA 81-016/03L-0 on 810317, during normal power operation, motor-operated main feedwater isolation valve 2-MOV-4517 experienced loss of power when main circuit breaker ground sensor tripped Caused by personnel error MENDERLICH R L . RIZZO, P Q Baltimore Gas & Electric Co 81/04/14 Region 1: Philadelphia, Office of the Director (81/03/01) 2pp 14697-281 24X Fiche 50-318,81/04/14.8208310502
- 8208310023 Forwards LER 81-025/03L-0 RUSSELL,L 8 Baltimore Qas & Elsctric Co 81/05/29 QRIER, 8 H. Region 1, Philadelphie. Office of the Director (81/03/01) ip 14697 208 24X Fiche 50-318,81/05/29,8208310023
- --S208310028 LER 81-025/03L-0 on 810430 & 0514 reactor protective systhamel 8 trip units bypassed to investigate T-hot channel 8 problem Caused by temp transmitter drift.
 WENDERLICH: R L RIZZO, P 0 Beltimore Gas & Electric Co 81/05/27 Region i, Philadelphia, Office of the Director (81/03/01) ip 14697 209 24% Fiche: 50-318, 81/05/29, 8208310023
- 820B050371 Forwards LER 82-031/03L-0 MIDURA, H. J Baltimore Gas & Electric Co 82/07/19 HAYNES, R C Region 1. Office of Director 1p 14209 162 24X Fiche 50-318, 82/07/19, 8208050371

- --8208130100 Amends 73 & 54 to Licenses DPR-53 & DPR-69, respectively, allowing operation during several operational modes w/one inoperable control element assembly position indicating channel inoperable

 CLARK, R & Deperating Reactors Branch 3 B2/07/29 (Opp 14340 323 24X Fichs 50-317, 82/07/29,8208130095
- --8208130104 Safety evaluation supporting Amends 73 & 54 to Licenses DPR-53 & DPR-69, respectively * Office of Nuclear Reactor Regulation, Director 82/07/29 3pp 14340 333 24X Fiche 50-317.82/07/29.8208130095
- --B20B130121 Notice of issuance & availability of Amends 73 & 54 to Licenses DPR-53 & DPR-69, respectively CLARK, R A Operating Reactors Branch 3 82/07/29 2pp 14340 336 24% Fiche 50-317, 82/07/29, B20B130095
- B208100141 Application for amend to Licenses DPR-53 & DPR-69.adding list of safety-related hydraulic snubbers to Tach Spec Table 3 7-4 LUNDVALL.A E Baltimore Gas & Electric Co 82/07/30 CLARK.R A Operating Reactors Branch 3 3pp 14298 090 24X Fiche, 50-317, 82/07/30, 8208100141
- ---8208100144 Proposed Tech Spec Table 3 7-4 re safety-related hydraulic snubbers 4 Baltimore Gas & Electric Co 82/07/30 7pp 14298 093 24X
 - * Baltimore Gas & Electric Co 82/07/30 7pp 14298 093 24X Fiche 50-317,82/07/30,8208100141
- 8208110001 Forwards Amends 74 & 55 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to extend date for operability of hydrogen analysers to 820930 JAFFE, D H Operating Reactors Branch 3 82/07/30 LUNDVALL, A E. Baltimore Gas & Electric Co 3pp 14330-222 24X Fiche 50-317, 82/07/30, 8208110001
- --8208110002 Amends 74 & 55 to Licenses DPR-53 & DPR-69, respectively, revising Tech Specs to extend date for operability of hydrogen analyzers to 820930 CLARK, R A Operating Reactors Branch 3 82/07/30 10pp 14330, 225 24x Fiche 50-317, 82/07/30, 8208110001
- --8208110003 Bafety evaluation supporting Amends 74 & 55 to Licenses PPR-53 & DPR-69, respectively • Office of Nuclear Reactor Regulation, Director 82/07/30 2pp 14330 235 24X Fiche 50-317,82/07/30,8208110001
- --8208110004 Notice of issuance & availability of Amends 74 & 55 to Licenses DPR-53 & DPR-69; respectively CLARK,R,A Operating Reactors Branch 3 82/07/30 2pp. 14330,237 24X Fiche,50-317,82/07/30.8208110001
- 8208040323 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS CALVERT CLIFFS CASE STUDY Docket Nos 50-317 And 50-318 (Baltimore Gas And Electric Company) FLYNN, J Social Impact Research Inc # Hountein West Research, Inc FIN B-6268 NUREO/CR-2749 VO2 Realth, Siting & Environment 214pp Available at NTIB \$7 00 14230 001 24X Fiche 50-317,82/07/31.8208040323
- 820B100272 Application to amend Licenses DPR-53 & DPR-69, revising Tech Space to incorporate listed changes re ASME Code addenda, RCS.Reg Guide I 33 & leak rate testing LUNDVALLA E. Baltimore Gas & Electric Co 82/08/02 CLARK.R.A Dperating Reactors Branch 3 5pg 14297 070 24X Fiche: 30-317, 82/08/02, 820B100272
- --8208100282 Tech Specs 3 A 3,4 A 3,4 A 10.1 2.6 7,6 B, Table 3.7-4, 3 6.1.2,4 6,1 2,3 6 1 3,4.6 1 3,4 6 A 1 3,4.6 4 1 4 & 4.6 4 1.2 re RCS operation & surveillance requirements # Baltimore Gas & Electric Co 82/08/02, 15pp 14297:075, 24% Fiche.50-317,82/08/02,8208100272
- 8208130081 Forwards Section IV re background math for Section III of 820104 Phase I rept on control of heavy loads ABH.R.F. Baltimore Oas & Electric Co 82/08/02 EISENHUT, D G Division of Licensing 48pp, 14335 001 24X Fiche 50-317,82/08/02, 8208130081
- 8208110124 Advises that info documenting compliance w/NUREG-0737. Item II B 3, "Post-Accident Bampling Sys," will be submitted within 120 days, in response to NRC 820630 request Response to recent clarification items in 820630 itr inappropriats. LUNOVALLA E, Baltimore Oas & Electric Co 82/08/06, CLARK,R. A Operating Reactors Branch 3 ip 14314 350 24X Fiche 50-317, 82/08/06, 8208110124

- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Symmarizes 10CFR Chapter I requirements & provides alternatives to requirements Syr list encl EIBENHUT, D @ Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208180038 Clarifies 820722 response to NUREO-0737. Item 2 K 3 25, "Effect of Loss of AC Current on Pump Seals " Loss of power would render reactor coolant pumps inoperable, raducing need for component cooling water supply to pumps LUNDVALL, A E Baltimore Gas & Electric Co 82/08/11 CLARK, R A Operating Reactors Branch 3 2pp 14377 286 24X Fiche 50-317,82/08/11.6208180038
- 8208230305 Forwards C-E proprietary & nonproprietary versions of "Slides From C-E/NRC/BNML Meeting on FATES 3. Bethesda, MD, 820709 " Affidavit for withholding encl Proprietary version withhold (ref 10CFR2 790) LUNDVALL, A E Baltimore Gas & Electric Co 82/08/17 CLARK, R A Operating Reactors Branch 3 5pp 14513 151 24X Fiche 50-317, 82/08/17, 8208230305
- O Inspection reports, IE Bulletins & correspondence
- 8208100366 Forwards IE Performance Appraisal Insp Repts 50-317/82-01 t 50-318/82-01 on 820118-28 & 0208-11 & executive summary Significant weatnesses identified TAYLOR.J M Division of Reactor Programs 82/04/14 LUNDVALL.A E Baltimore Ost & Electric Co App 14308 274 24X Ficht 50-317,822/04/14 #208100364
- ~-8208100371 IE Performance Appraisal Insp Repts 50-317/B2-01 & 50-318/B2-01 on 820118-28 & 0208-ii Major area inspected, mgt controls over selected licensed activities WOESBNER, R. J. SHAFER, W. CHOULES, N. Division of Reactor Programs 82/04/12 46pp 14308, 280 24X Fiche 50-317, B2/04/14, 8208100366
- B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 URDAN: EL Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co. of New York 87pp 14356 274 24X
 Fiche 50-000
- 8208050412 Forwards IE Insp Repts 50-317/82-14 & 50-318/82-14 on 820415-0713 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/07/14 LUNDVALL.A.E Baltimore Gas & Electric Co 2pp 14217 324 24X Fichs 50-317.82/07/14.8208050412
- --8208050429 IE Insp Repts 50-317/82-16 & 50-318/82-14 on 820615-0713
 Noncompliance nated auxiliary feedwater sys inoperable in
 Hode 3
 ARCHITZEL,R E , TRIMBLE,D C , MCCABE,E C Division of Project &
 Resident Programs, 82/07/15 12pp 14217 327 24X
 Fiche 50-317,82/07/16,8208050412
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation," Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp, 14358 001, 24X Fiche 50-000,82/07/19,8204210375.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list entl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co. of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210394
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Bafeguards, 82/07/20 Consolidated Edison Co of New York, 7ipp 14357: 276, 24X Fiche: 50-000, 82/07/20, 8204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN E L Division of Engineering & Quality Assurance. 82/07/22 Consolidated Edison Co of New York 112pp 14194.321 24X Fiche: 50-000, 82/07/22, 8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS." Svc list encl. JORDAN.E L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380.115 24X Fiche: 50-000.82/07/23,8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Bupport Pin Failures at Westinghouse PWRs " Syc list enci JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche, 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermai Sierves in RCS Piping at Cartain Westinghouse PWR Power Plants " Svc list enc]
 JORDAN,E L Division of Engineering & Quality Assurance 62/07/26
 Consulidated Edison Co of New York 121pp 14357 013 24X
 Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Querexposure of Diver During Work in Fuel Btorage Pool" Byo list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche. 50-000, 82/07/28, 8204210405
- 8208090049 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " EncIs summarize bolted closure leakage history & provide chemical composition of lubricants Approx 155 membours espended LUNDVALL, A.E. Baltimore 9as & Electric Co. 82/07/30 HAYNES, R.C. Region 1, Dffice of Director 18pp 14270 014 24X Ficher 30-317, 82/07/30, 8208090049,
- 8208230189 Forwards IE Insp Repts 50-317/82-17 & 50-318/82-15 on 820706-09. No noncompliance noted MARTIN.T. Division of Engineering & Technical Programs 82/08/03 LUNDVALL.A E Baithmore Gas & Electric Co 2pp 14517 156. 24X Fiche, 50-317, 82/08/03, 8208230189
- --B20B230197 IE Insp Repts 50-317/82-17 & 50-318/82-15 on B20706-09, No moncompliance noted Major areas inspected licenses action on IE Bulletin 79-24 & administrative controls for safety-related surveillances, per Reg Guide 1 33.

 SHAUB, E.T., CAPHTON. D. L. Division of Engineering & Technical Programs. B2/08/02 9pp. 14517:158 24X Fiche 50-317,82/08/03,8208230189
- 8208120259 Ack receipt of 820625 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-317/81-19 % 50-318/81-18.

 8HITH.O.H. Division of Emergency Preparedness & Operational Support 82/08/04, LUNDVALL, A E Baltimore Gas & Electric Co 2pp 14326:322 24% Fiche 50-317.82/08/04.8208120259.
- --8208120272 Responds to NRC 820526 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-317/81-19 & 30-318/81-18 Corrective actions emergency planning unit established & staffed on 820401 POINDEXTER, C Baltimore Oas & Electric Co 82/06/25, SHITH, O H Region 1, Office of Director 7pp 14326-324 24X Fiche: 50-317, 82/08/04, 8208120259
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl.
 JGROAN, E. L. Division of Engineering & Quality Assurance 62/08/05
 Consolidated Edison Co of New York 117pp. 14388-201 24X
 Fiche. 30-000, 82/08/05, 8204210407
- 8208180043 Ack receipt of 820713 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/81-25 & 50-318/81-24.

 MARTIN.T.T. Division of Engineering & Technical Programs 82/08/1 LUNDVALL, A E. Baltimore Cas & Electric Co ip. 14376 302 24X Fiche: 50-317, 82/08/11, 8208180043
- --B2081B0051 Responds to NRC 820615 ltr re violations noted in IE Insp. Repts 80-317/81-25 & 50-318/81-24 Corrective actions plant procedure requirements incorporated to move non-fuel assembly SNM inside security fence
 LUNDVALL.A E. Battimore Gas & Electric Co 82/07/15, MARTIN,T T. Division of Engineering & Technical Programs 3pp. 14376-303 24X Fiche: 50-317,82/08/11,8208180043.
- 820B300197 Forwards IE Insp Repts 50-317/82-18 & 50-318/82-16 on B20713-0B10 & notice of violation STARGSTECKI.R. Division of Project & Resident Programs 82/08/16. LUNDVALL.A.E. Baltimore Oas & Electric Co 2pp 14596 057. 24X Fiche: 50-317, 82/08/16.8208300197
- --8208300200 Notice of violation from insp on 820713-0810. * Division of Project & Resident Programs 82/08/16 ip 14396:059. 24X Fiche, 50-317, 82/08/16, 8208300197.
- --8208300203 IE Insp Rspts 50-317/82-18 & 50-318/82-16 on 820713-0810 Noncompliance noted failure to properly clear tag for 2-P8-192 & 820804 inadvertent actuation of safety injection actuation sys.

 ARCHITZELIR.E., TRIMBLE, D.C., MCCABE, E.C. Division of Project & Resident Programs. 82/08/13, 20pp 14576 040 24X Fiche: 50-317, 82/08/16, 8208300197.

- 8208230322 Ack receipt of 820727 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/81-17 & 50-318/81-16 MARTIN.T T Division of Engineering & Technical Programs 82/08/19 LUNDVALL.A E Baltimore Gas & Electric Co 1p 14508 229 24X Fiche 50-317,82/08/19,8208230322
- --8208230323 Responds to NRC 820628 ltr re violations noted in IE Insp. Repts 50-317/81-17 & 50-318/81-16 Corrective actions Radiation Bafety Procedure 2-204 will be upgraded to include signoffs for resin solidification process control LUNDVALL, A E Baltimore Oas & Electric Co 82/07/27 MARTIN.T.T Division of Engineering & Technical Programs 3pp 14508 230. 24X Fiche 50-317,82/08/19,8208230322
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000.82/07/13.8208270010
- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBI" + NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24% Piche 30-000,82/07/13,8208270010
- --8208270555 Forwards "Number of Personnel & Man Rem By Work & Job Function.CY81" TIERNAN, J.A. Baltimore Oas & Electric Co 82/03/05 HAYNEB, R C Region 1, Office of Director 1p 14680 033 24X Ficher 50-000,82/07/13,8208270010
- --8208270558 "Number of Personnel & Man Rem By Hork & Job Function.CY81 "
 # Baltimore Gas & Electric Co 82/03/05 2pp 14680 034 24X
 Fiche 50-000.82/07/13.8208270010
- --B208270568 Forwards "Personnel Whole Body Exposures for CYB1," per 10CFR20 407 TIERNAN, J.A. Baltimore Gas & Electric Co. B2/03/05 Office of Management and Program Analysis. 1p. 14680 037 24X Fiche 50-000, B2/07/13, 8208270010
- --8208270574 "Personnel Whole Body Exposures for CYB1 "
 TIERNAN, J A Baltimore Oas & Electric Co 82/03/05 ip
 14680 038 24X Fiche 50-000, 82/07/13, 8208270010
- 8208230371 Forwards monthly operating repts for Jul 1982 LOTITO E K Baitimore Oas & Electric Co 82/08/17 Director's Office, Office of Inspection and Enforcement 1p 14512 329 24X Fiche, 30-317, 82/08/17, 8208230371.
- --8208230373 Nonthly operating repts for Jul 1982 LOTITO,E Baltimore Gas & Electric Co 82/08/17 14pp 14512 330 24% Fiche 50-317.82/08/17.8208230371
- 8 Reportable occurrences, LERs & related correspondence
- 820B310302 LER 81-016/03L-0 on 810317, during normal power operation, motor-operated main feedwater isolation valve 2-HOV-4517 experienced loss of power when main circuit breaker ground sensor tripped Caused by personnel error HENDERLICH, R L , RIZZO, P O Baltimore Oas & Electric Co 81/04/14 Region 1, Philadelphia. Office of the Director (81/03/01) 2ap. 14697-281. 24X Fiche 50-318,81/04/14,8208310502
- 8208310023 Forwards LER 81-025/03L-0
 RUSSELL,L B Baltimore Oas & Electric Co 81/05/27 ORIER.B. H
 Region i, Philadelphia. Office of the Director (81/03/01) ip.
 14697 208 24% Fiche.50-318.81/05/29.8208310023
- --B20B31002B LER 81-025/03L-O on B10430 & 0514 reactor protective syschannel B trip units bypassed to investigate T-hot channel B problem Caused by temp transmitter drift WENDERLICH, R L , RIZZO, P G Baltimore Gas & Electric Co B1/05/27 Region i, Philadelphia, Opfice of the Director (81/03/01) lp. 14697-209 24X Fiche: 30-318, 81/05/27, 8208310023
- 8208050371 Forwards LER 82-031/03L-0 MIDURA: H J. Baltimore Gas & Electric Co 82/07/19. HAYNEB: R C. Region 1. Office of Director ip. 14209.162 24X Fiche.50-318:82/07/19:8208050371

- ---8208050375 LER 82-031/03L-O on 820519, diesel speed control 12 failed, preventing lowering or raising of load Cause not yet determined Adjustments made to governor Diesel generator tested & returned to svc
 JUNOE,M A. HUSEBY,D E Baltimore Gas & Electric Co 82/07/19
 Region 1, Office of Director 1p 14209 163 24X
 Fiche 50-318.82/07/19.8208050371
- 8208050389 Forwards updated LER 81-056/03X-1 RUSSELL,L B Baltimore Gas & Electric Co 82/07/19 HAYNES,R C Region 1. Office of Director 1p 14209 185 24X Fiche 50-318,82/07/19,8208050389
- --8208050405 Updated LER Bi-056/03X-I on 811230 normal containment sump isolation valve discovered open Caused by movement of valve stem bushing Valve repaired & all other containment sump isolations checked using new overhaul procedure UNNGE.M A, HUSEBY.D E Baltimore Gas & Electric Co 82/07/19 Region I. Office of Director 2pp 14209 186 24X Fiche 50-318,82/07/19,8208050389
- 8208020394 RO on 820720, svc water HX combined salt water outlet valve 2-54-197 failed shut resulting in loss of salt water to both exchangers Power decrease initiated RUSSELL.L B Baltimore Gas & Electric Co 82/07/21 HAYNEB, R C Region 1, Office of Director 1p 14150 069 24X Fiche 50-316, 82/07/21, 8208020394
- 8208090252 Forwards LER 82-035/03L-0 RUSSELL, L B Baltimore Oas & Electric Co 82/07/30 HAYNES, R C. Region I. Office of Director ip 14271 036 24X Fiche 50-31B, 82/07/30, 8208090282
- --8208090256 LER 82-039/03L-0 on 820701, discovered drain valve broken off saltwater discharge line from svc water HX 21 Caused by 3/4-inch corroded pipe nipple & valve impacted & severed from saltwater discharge line Repair made www.ided coupling JUNGE, HA, PRICE, WJ Baltimore Gas & Electric Co 82/07/30 Region 1, Office of Director 2pp 14271 037 24X Fiche. 50-318,82/07/30,8208090252
- 8208100197 Forwards LER 82-033/03L-0 RUSSELL,L B Baltimore Cas & Electric Co 82/07/30 HAYNES,R C Region 1. Office of Director ip 14274,250 24X Fichs 50-318,82/07/30.8208100197
- --8208100208 LER 82-033/03L-0 on 820702.six accessible snubbers in main feedwater & auxiliary steam supply sys not tested Caused by discrepancy between safety-related items list & piping stress analysis Snubbars upgraded & tested PAVIS.0 S Baltimore Oas & Electric Co 82/07/30 Region i. Office of Director ip 14294 251 24X Fiche 50-318,82/07/30,8208100199
- 8208160145 Forwards LER 82-034/01T-0 RUSSELL,L B Baltimore Oas & Electric Co 82/08/03 HAYNES,R.C Region 1, Office of Director 1p 14345 090 24X Fiche 30-316,82/08/03,8208160145
- --8208160148 LER 82-034/017-0 on 820720; salt water flow through svc water HX 21 & 22 lost rendering exchangers inoperable Caused by salt water valve 28M197 failure due to sheared pins New valve installed PAVIS:0 8, MAHON.C R Baltimore Gas & Electric Co. 82/08/02 Region 1, 09fice of Director. 2pp 14345 091 24X Fiche 50-318,82/08/03,8208160145
- 8208130275 Forwards LER 82-032/03L-0 RVSSELL,L B Baltimore Cas & Electric Co 82/08/05 HAYNES,R C Region 1, Office of Director 1, 14333-075 24X Fiche 50-318, 82/08/05,8208130275
- --B208130276 LER B2-032/03L-O on B20706 during routine surveillance testing diesel generator 21 failed to start Cause unknown Testing & investigation ongoing LA0IEMSKI.J B. HUSEBY D E Baltimore Gas & Electric Co B2/08/05, Region I. Office of Director, ip 14333 076 24X Fiche 50-318, 82/08/05, 8208130275
- 8208230080 Forwards LER 82-021/03L-0 RUSSELL,L.B. Baltimore Qas & Electric Co 82/08/13 HAYNES,R.C Region 1, Office of Director 1p 14517 319 24X Fiche: 50-318, 82/08/13, 8208230080
- --B208R30087 LER-0R1/03L-0. on 820714.22B safety injection tank pressure found decreased to 197 psig on 820427.Caused by loop (solator failure Isolator replaced HENDERLICH, R L., RAYNOR.J.H Baltimore Gas & Electric Co. 82/08/19 Region 1. Office of Director 2pp 14517.320 24X Fiche: 50-318.82/08/13.8208230080

- 8208260239 Forwards LER 82-036/03L-0 RUSSELL,L B Baltimore Gas & Electric Co 82/08/18 HAYNES,R C Region 1. Office of Director 1p 14552 350 24% Fiche 50-318, 82/08/18, 8208260239
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8208190124 Forwards objectives & proposed table of events for 1782 annual emergency plan exercise scheduled for 820811 Util supports FA Emergency Mgt Agency concept of limited risk county participation Scenario to be submitted by 820706 HUKILL, H D General Public Utilities GPU Service Corp 82/06/23 GRIMES, B K Division of Emergency Preparedness 5pp 14381 138. 24X Fiche 50-289,82/06/23,8208190124
- 8208270267 Forwards Revision 3 to guard training & qualification plan
 Revision withheld (ref 10CFR73 71)
 HUNILL,HD Oeneral Public Utilities GPU Service Corp. 82/07/23
 STOLZ,JF Operating Reactors Branch 4 ip 14563 071 24X
 Fiche 50-289, 82/07/23, 8208270267
- 820Bi102i6 Releases public version of revised emergency plan implementing procedures FELTON.J H Division of Rules and Records 82/07/30 Document Management Branch ip 14329 086 24X Fiche 50-320.82/07/30.82/0810214
- --8208110217 Forwards public version of revised Emergency Plan
 Implementing Procedures 1054 1 re unusual event 1054 2 re
 alert, 1054 3 re site emergency & 1084 4 re general
 emergency Receipt form encl
 MCKINNEY; M General Public Utilities OPU Service Corp.
 82/07/23 DENTON, H R. Office of Nuclear Reactor Regulation.
 Director 1p 14329 097 24X Fiche 50-320, 82/07/30, 8208110216.
- --8208110218 Public version of Emergency Plan Implementing Procedures 1054 i re unusual event,1054 2 re alert,1054 3 re site emergency & 1054,4 re general emergency # General Public Utilities - OPU Service Corp 82/07/19, 120pp 14329 088 24% Fiche 50-320,82/07/30,8208110216
- 8208060058 Releases public version of temporary change notices to emergency plan implementing procedures FELTON, J M Division of Rules and Records, 82/08/02 Documen Management Dranch 19 14282.157, 24X Fiche 50-320,82/08/02,8208060058
- --8208050052 Forwards public version of temporary change notices to Emergency Plan Implementing Procedures 1034 i re unusual event, 1034 2 re allert, 1034 3 re site emergency & 1034 4 re general emergency MCKINNEY.M General Public Utilities OFU Service Corp 82/07/21 DENTON.H R Office of Nuclear Reactor Regulation, Director. 1p 14282 160 24X Fiche 50-320, 82/08/02,8208050058
- --8208060066 Public version of temporary change notices to Emergency
 Plan Implementing Procedures 1054 1 re unusual event,
 1054 2 re atart 1054 3 re site emergency & 1054 4 re
 general emergency
 # General Public Utilities GPU Service Corp 82/07/16 13pp.
 14282 161 24X Fichs 50-320,82/08/02,8208060058
- 8208270262 Forwards Revision 4 to guard training & qualification plan.
 Revision withheld (ref 10CFR73 71)
 HUKILL:H,D Oeneral Public Utilities OPU Service Corp. 82/08/03.
 STOLZ.J F Operating Reactors Branch 4 ip. 14563.356. 24X
 Fiche 50-289.82/08/03.8208270262
- 8208100278 Bubmits description of evaluation re emergency procedures & training for station blackout events Consequences of station blackout are minor due to unique shutdown status. No specific instructions beyond existing emergency procedures initiated KANOA.B.K. General Public Utilities OPU Service Corp. 82/08/05 SNYDER.B J THI Program Office 2pp 14274 244 24X Fiche 50-320.82/08/05.8208100278
- 8208160292 Forwards annual exercise requirements exemption fee, per 10CFR170 22.
 HUKELL, H D. Oeneral Public Utilities GPU Service Corp 82/08/09, CHILK, B J. Defice of the Secretary of the Commission 2pp. 14346:263 24X Fiche: 50-289, 82/08/09, 8208160292.

2. Adjudicatory correspondence

- 8208060089 Forwards proposed Tech Spec pages correcting pages
 transmitted in NRC 820713 motion to conform proposed Tech
 Bpecs w/820618 amend of order
 HILCOVE,M N Hearing Branch 2 82/07/30 WDLF,JF, 8HDN,FJ,
 PARIS,O H Atomic Safety and Licensing Board Panel 1p 14238 129
 24X Fiche 50-320.82/07/30,8208060089
- H General correspondence
- 920B130345 Discusses future disposition of radwastes per 820517 ltr Two studies underway re potential technical, regulatory & socioeconomic impacts of 27 possible disposition alternatives Detailed technical raview expected in 1983 SNYDER, B. J. TMI Program Office 82/04/07 HORSEY, E. E. Kent County Council of Oovernments Chestortown, MD. 7pp 14340, 255 24X Fiche: 50-320, 82/04/07, 8208130345
- P. Operating license stage documents & correspondence
- 8207080064 Qeneric ltr to all licensees of operating plants applicants for DL & holders of CP re Commission approved charter for CROR 8vc list encl
 DIRGKS.W J Office of the Executive Director for Operations.
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24x Fichs 50-000.82/07/02.8207080064
- 8208030014 Responds to 820706 ltr forwarding safety evaluation to support control rod drive mechanism quick-look camera insp Program can be conducted in safe manner SNYDER, B J, TMI Program Office 82/07/13 BARTON, J J General Public Utilities OPU Service Corp 4pp 14208, 348 24X Fiche: 50-320, 82/07/13, 8208030014
- 9209260580 Notification of contract execution "Reanalysis of Existing Data from Telephone Surveys Concerning TMI." awarded to Nati Inst of Mental Health FLEENDR.C M Technical Assistance Contracts Branch FIN 8-8621 82/07/21. VOLLMER,R M. RECAN.W H Division of Engineering 1p 14568.045 24X Fiche 50-289,82/07/21.8208260580
- --- 8208260585 Memorandum of Agreement between NRC & Natl Inst of Mental Health expanding Grant MH35425 to encompass "Reanalysis of Existing Data from Telephone Burveys Concerning TMI" MATTIA-M Division of Contracts PARDES.H Health & Human Services, Dept of: FIN 8-8621 82/07/14 3pp 14568:046 24) Fiche:50-289,82/07/21,8208260580
- 8208260474 Responds to util 820514 & 0722 ltrs replans for inerting & shipping of EPICOR-FF liners Plans meet w/NRC approved procedures.

 ### BARRETT, L. H TMI Program Office 82/07/23 BARTON, J J Ceneral Public Utilities 0PU Service Corp 4pp 14594 346 24% Fiche: 50-320, 82/07/23, 8208260474
- B208230418 Responds to FOIA request addressed to NOAA for three categories of documents re emergency planning & nuclear accidents. Forwards documents listed in app. FELTON. J. N. Division of Rules and Records 82/07/29. HIATT: S. L. Affiliation Unknown 2pp. 14528 185 24X Fiche 50-320, 82/07/29, 8208230418
- ---B208230420 Forwards summary & assessment of branch involvement in responding to TMI accident MARKER,E H Hydrology Meteorology Branch 79/06/18 HALGREN,R Commerce,Dept of National Oceanographic & Atmospheric Administration ip 14528,187 24X Fiche 50-320,82/07/29,8208230418.
- 8208090010 80010ECDNOMIC IMPACTS DF NUCLEAR GENERATING STATIONS.THREE MILE ISLAND CASE STUDY Oct 1,1978-January 4,1982 Docket Nos. 50-289 and 50-320. (Metropolitan Edison et al.) FLYNN.C Social Impact Research, Inc. ** Mountain West Research, Inc. FIN 8-6268 NUREO/CR-2749 Viz 82/07/31 Division of Health, Biting & Environment 242pp Available at NTIS \$7.50 14302:168 24X Fiche 50-289,82/07/31,8208090010.
- B20B100177 Forwards Revision 5 to organization plan Revision reflects shift in reporting responsibility for Plant Operations Review Committee & realignment of functions reporting to Ofc of Director KANGA, B.K. Ogneral Public Utilities OPU Service Corp 82/08/05 SNYDER, B J TMI Program Office. 7pp 14274.006. 24X Ficher 50-320, 62/08/05.8208100177.

- 8208100302 Forwards Revision 1 to "Recovery Program, Standby Reactor Coolant Pressure Control Sys. Sys Description." which specifically addresses RCG draindown from control rod drive mechanism KANOA. B K Deneral Public Utilities GPU Bervice Corp 82/08/06 SNYDER. B J TMI Program Office 1p 14294 201 24X Fichs 50-320, 82/08/06.8208100302
- --8208100307 Revision 1 to "Recovery Program, Standby Reactor Coglant Pressure Control Sys. Sys Description" " 9 General Public Utilities - 0PU Bervice Corp 82/08/06 42pp 14294 202 24X Fiche: 50-320, 82/08/06, 8208100302
- B20B110116 Requests approval of revision to general project design criteria.incorporating changes requested in NRC B20401 ltr. w/exception of Section 3 2 7 River flow data will be collected from UBOS gaing stations KANOA: B.K. General Public Utilities QPU Bervice Corp BARRETT.L H. TMI Program Office 1p 14314 325 24X Fiche, 50-320, 82/08/06,8208110116
- 8208110123 Responds to Generic Ltrs 81-40,82-02.82-12 & 82-13 per NRC 820707 Itr Administrative procedures per NRC policy statements on nuclear power plant staff working hours will be implemented & Tech Spacs revised KANOA,8 K General Public Utilities GPU Service Corp. 82/08/06 SNYDER.8 J TMI Program Office 2pp 14314 337. 24X Fiche 50-320,82/08/06.8208110123
- 8208090194 Qeneric Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarires 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl EISENHUT, D.Q. Division of Licensing 82/09/09 Consolidated Edison Co of New York ip. 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208200033 Forwards recovery operations plan Tech Spec Change Request 17, adding EPICOR-II inerting radiation monitors. For approval. Replacement pages encl KANGA.B K. General Public Utilities GPU Service Corp. 82/08/16. BARRETIL.H THI Program Office 2pp 14392 346 24% Fiche: 50-320, 82/08/16, 8208200033
- ---B20B200036 Proposed Teth Specs re radiation monitoring instrumentation * General Public Utilities GPU Service Corp. B2/OB/16 3pp 14392 348, 24X Fishe 50-320, 82/OB/16, B209200033
- 8208300025 Notification of contract execution, Mod 4 to "Psychological Stress Response to Venting at TMI " Contractor Uniformed Svcs Univ of Health Sciences, Bethesda, MD MCLEAREN, T Technical Assistance Contracts Branch FIN 8-6892 62/08/16 VOLLMER, R., REOAN, W M Division of Engineering 1p. 14683: 361 24X Fichs 50-020, 82/08/16, 8208300025.
- --8208300027 Mod 4, deobligating unliquidated balance remaining in contract, to "Paychological Stress Response to Venting at THI"

 # Uniformed Services Unity of the Health Sciences HAGAN, T F Technical Assistance Contracts Branch, FIN B-6892, 82/08/16 ip 14683 362 24X Fichs 50-320, 82/08/16,8208300025.
- 8208270270 Informs that response to NRC 820706 request for plans to upgrade sys for monitoring reactor bidg airborne conditions will be available by 820827 KANOA, B.K. General Public Utilities OPU Service Corp. BARRETTLL H. TMI Program Office ip 14564.182 24X Fichs 50-320, 82/08/20, 8208270290.
- 8208250320 Forwards info re makeup & purification demineralizers.
 Collected info provides operating history of & resins loaded
 into demineralizer sys
 KANOA.B.K. General Public Utilities QFU Service Corp 82/08/23
 SNYDER.B J. TMI Program Office. 31pp. 14538,029 24X
 Fiche: 50-320,82/08/23,8208230320
- G Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Velve (MBIV) Leakage." Svc list enci. JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/16. Consolidated Edison Co of New York 87pp 14356 274 24X Fiche: 50-000, 82/07/16, 8204210393.
- G204210395 IE Info Notice 81-26, Part 3, Buppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation," Byc list and.

 JURDAN, E. L. Division of Engineering & Guality Assurance 82/07/19, Michigan, Univ of 112pp. 14358 001 24X Fiche: 50-000, 82/07/19, 8204210395

DOCKETED ITEMS

- Pi0376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon idual Loss of Air Pressure" Bvc list encl IDAN.E L. Division of Engineering & Quality Assurance 82/07/20 onsolidated Edison Co. of New York 112pp 14381 001 24X
- he 50-000, 82/07/20, 8204210396.
- 10397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride
- rpacks " Svc list encl B.L I Division of Fuel Facilities, Materials & Safeguards 07/20 Consolidated Edison Co of New York 71pp 1435 Fiche 50-000.82/07/20,8204210397
- 10398 IE info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check ve Failures " Svc list enc!
 DANIE L. Division of Engineering & Quality Assurance 82/07/22 onsolidated Edison Co of New York 112pp 14194 321 24X he 50-000: 82/07/22,8204210398
- 10401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in inity of Drained & Open RCS" Svc list encl
 DANSE L Division of Engineering & Quality Assurance 82/07/23 onsolidated Edison Co of New York 122pp 14380 115 24X he 50-000, 82/07/23, 8204210401
- 10402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube port Pin Failures at Westinghouse PMRs " Byt list encl.

 JANIE L Division of Engineering & Guality Assurance 82/07/23 ansolidated Edison Co of New York 127pp 14194 120. 24X 16 50-000. 82/07/23, 8204210402
- 10403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping Pertain Westinghouse PWR Power Plants" Byo list encl
 JAN, E. Division of Engineering & Quality Assurance B2/07/26
 Insolidated Edison Co of New York 12ipp 14357 013 24X
- 0405 IE Info Notice 82-31, "Overexposure of Diver During Work in Storage Pool " Svc list encl ANNEL Division of Engineering & Quality Assurance 82/07/28 nsolidated Edison Co of New York 122ep 14357 146 24X = 50-000, 82/07/28, 8204210405
- O177 Responds to IE Bulletins 79-03 & 79-03A, "Longitudinal Hold cts in ASME 9A-312. Type 304 Stainless Steel Pipe," Matl westion not in use at facility ON.J J Censral Public Utilities GPU Service Corp 82/07/28 ES.R C Region 1, Office of Director 2pp 14239 231 24% e 50-320, 82/07/28,8208060177
- 0445 Forwards IE Insp Rept 50-320/82-06 on 820512-28 & notice Tolation

 Tolation

 Tolation

 Tolation

 Tolation of Project & Resident Programs. 82/07/30

 Tolation of Project & Resident Project Pro
- 140451 Notice of violation from insp on 820512-28, NROSTECKI,R Division of Project & Remident Programs 1 14349 272 24X Fiche 50-320,82/07/30,8208160445. ams 82/07/30
- 60458 IE Insp Rept 50-320/62-06 on 820512-28 Noncompliance noted lure to deliver radioactive matl to carrier for transport strong & tight container NBAKY, M., FASANO, A Division of Project & Resident Programs 06/23 9pp 14349 273 24X Fiche 50-320,82/07/30,8208160445
- 474 Forwards 1E Insp Rept 50-320/82-07 on 820523-0705 No
- and forwards in inspress Sumazovazov on Sacozamovos No mpliance noted STECKI.R Division of Project & Resident Programs 82/07/30 N.J.J. Qeneral Public Utilities OPU Service Corp. 2pp. 197 24% Fiche 50-320,82/07/30.8208160474.
- 40483 IE Insp Rept 50-320/82-07 on 820523-0705 No noncompliance ad Major areas inspected exial power shaping rod ementiroutine health physics & environ areas, reactor bldg ries & radinactive matt shipments
 TE.R. 0'NEILL.B. THONUS.L. Division of Project & Resident press 82/07/22 14pp 14348 199 24X Fiche.50-320,82/07/30,3160474
- 194 Responds to IE Bulletin 79-18, "Audibility Problems **** respons to LE Bulletti 7**-18; "Audistility Problems
 'tered on Evacuation of Parsonnel From High Noise
 "Two deficient areas identified & corrective action
 Bys will be reviewed if & when restart considered.
 B K General Public Utilities - GPU Service Corp. 82/08/02.
 B.R C Region i, Office of Director 2pp. 14348-307-24X
 50-320.82/08/02.8208160494.
- 07 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Water-Jet Impingement," Syc list encl | E.L. Division of Engineering & Quality Assurance 62/08/05 olidated Edison Co. of New York. 117pp 14388;201 24X 50-000, 82/08/05,8204210407.

- 820B130184 Responds to IE Bulletin 81-01, "Surveillance of Mechanical Snubbers "No INC mechanical snubbers installed on safety-related sys or in storage at facility KANGA.B K General Public Utilities GPU Service Corp 82/08/05 HAYNES,R C Region 1, Office of Director 4pp 14338 285 24X Fiche 50-320.82/08/05.8208130184
- 8208300002 Board Notification 82-83 forwarding IE Insp Rept 50-320/82-04 identifying inadequate corrective maint actions on TMI-2 ventilation sys important to safety Region 1 will inspect TMI-1 maint sys to determine if problems exist LAINAS.0 C Assistant Director for Operating Reactors 82/4 Atomic Safety and Licensing Appeal Panel 5pp 14693 326 Fiche 50-289,82/08/13.8208300002
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective 2002/0010 Responds to FOIA request for documents detailing collect:
 dose exposures in 1981 for operating nuclear power plants &
 analyzing said info Forwards documents listed in App A
 FELTON.J M Division of Rules and Records 82/07/13 UDELL.R. A
 Critical Mass Energy Project Bpp 14679 208 24X
 Fiche 50-000.62/07/13.8208270010
- --8208270019 Forwards "Statistical Summary Rept of Personnel Monitoring Info for CY81," per 10CFR20 407 HUKILL:H D General Public Utilities OPU Service Corp 82/03/01 HAYNES:R C Region 1, Office of Director, 1p. 14680 001 24X Fiche 50-000,82/07/13,8208270010
- --8208270023 "Statistical Summary Rept of Personnel Monitoring Info for CYB1 " General Public Utilities - GPU Service Corp 82/03/01, 2pp, 880 002 24X Fiche 50-000, 82/07/13,8208270010 14680 002
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power ## NRC - No Detailed Affiliation Given 82/07/13 14679,216 24% Fiche 50-000,02/07/13,8208270010,
- --B208270649 Forwards "Number of Personnel & Man Rems By Work & Job Function for CYB1" HUKILL,H D. General Public Utilities QPU Service Corp 82/03/01 HAYNEB,R C Region 1. Office of Director. 14679 352. 24X Fiche. 50-000.82/07/13.8208270010
- --8208270654 "Number of Personnel & Man Rems By Work & Job Function for CYBI ' * General Public Utilities - OPU Service Corp 82/03/01 5pp 14679:353 24X Fiche:50-000,82/07/13,8208270010
- 8208130462 Forwards TMI Program Ofc weekly status rept for wk of Objection Formation 1. The Control of the Control o
- 8208170406 TMI Program Ofc weekly status rept for wk of 820718-24 BARRETT.L H TMI Program Office 82/07/26 DENTON.H R. Offi Nuclear Reactor Regulation, Director 4pp 14372 339 24X Fiche: 50-320.82/07/26.8208170406. Office of
- 8208250062 Forwards TMI Program Ofc weekly status rept for wk of 820725-31 B20720-31 BARRETT,L H TMI Program Office 82/08/02 DENTON,H R. Office of Nuclear Reactor Regulation, Director BNYDER.8 J TMI Program Office 9pp 14551 337 24X Fiche 50-320,82/08/02,8208250062
- B20B100275 Forwards "TMI Aquatic Btudy," monthly rept for June 1782, TEITT.T R. General Public Utilities OPU Barvice Corp. B2/0B/05, HICKEY.C NRC No Detailed Affiliation Given 1p 14275.145 afiche 50-289, 82/0B/05. 820B100275
- --8208100278 "TMI Aquatic Study," monthly rept for June 1982 NARDACCI.Q A , RANEY.E C Inhthyological Associates, Inc. 82/08/05. 32pp 14275.146 24X Fiche. 50-289, 82/08/05. 8208100275.
- S Reportable occurrences. LERs & related correspondence
- 8208050272 Forwards LER 82-020/01L-0.
 BARTON.J.J General Public Utilities QPU Service Corp 82/07/26,
 HAYNES:R.C Region 1. Office of Director 1p. 14210.107 24X
 Fiche.80-020.82/07/26.8208080272

- --B208050277 LER 82-020/01L-0 on B20603, determined that recent overflow of auxiliary bidg sump occurred due to influx of rainwater from borated water storage tank recirculation pump Caused by inadequate flood protection Procedures modified CHAPLINS D Oeneral Public Utilities QPU Service Corp 82/07/26 Region 1. Office of Director 4pp 14210 108 24x Fiche 50-320, 82/07/26, 8208050272
- 8208100238 Forwards LER 82-023/03L-0 BARTON, J J Ceneral Public Utilities - QPU Service Corp 82/07/2 HAYNES, R C Region 1, Office of Director 1p 14274 311 24X Fiche 50-320, 82/07/29, 8208100238
- --8208100250 LER 82-023/03L-0 on 820829, air intake tunnel (AIT) Halon sys actuated causing actuation of AIT deluge sys & tripping of supply & exhaust fens in auxiliary & fuel handling bldgs Caused by lightning actuating ultraviolet light detectors SMITH/S W General Public Utilities GPU Service Corp 82/07/29 Region I, Office of Director 3pp 14294 312 24% Fiche:50-320,82/07/29,8208100238
- B208:30211 PNO-TMI-82-018 on 620806, licensee will perform video inspof core Two add1 lead screws: 88 near edge of core & 95 between edge & ctr of core, have been removed. Met, black crud observed as 88 lead screw was removed MIEBE. J. FASANO, A., BARRETT. L. TMI Program Office 82/08/06 ip 84333 011 RAX Fiche. 50-320, 82/08/06, 8208130211
- 8208130267 PNO-TM1-82-018A on 820806, during video insp of reactor corp. radiation levels discovered in excess of max. Insp limited to two spider assemblies due to lack of mansuverability. Some melting of upper and fittings evident KALMAN. Q., FABAND, A., BARRETT, L. TMI Program Office 82/08/09 ip 14333, 052 24X Fichs 50-320, 82/08/09, 8208130267
- B2OB1B0033 Forwards LER 82-025/03L-0 KANOA,B K General Public Utilities - OPU Service Corp B2/08/09 HAYNEB,R C Region 1, Office of Director, 1p. 14378 281 24X Fiche. 30-320. 82/08/09, 8208180033
- ---8208180040 LER 82-025/03L-0 on 820709, following mod work in personnel girlock, outer door leak rate exceeded Tech Spec limit Caused by foreign mati on sealing surface preventing seal, Seal surfaces cleaned & O-rings replaced CHAPLIN.8 D General Public Utilities GPU Service Corp 82/08/09 Region i, Office of Director. 3pp 14378 282 24X Fiche: 50-320, 82/08/09, 8208180033
- E208180054 Forwards LER 82-024/03L-0 KANOA.B K Deneral Public Utilities - GPU Service Corp. 82/08/09 MAYNES.R C Region 1. Office of Director. 1p 14379 191 24X Fiche 50-030.82/08/09.8208180064.
- --820Bi80060 LER 82-024/03L-0 on 82070B, fuel handling bldg exhaust fans AH-E-10C/D trippad Gaused by inadvertently grounded lead during calibr procedure Resulting low flow condition of fans AH-E-10A/B due to open exhaust damper on fan 10D, CHAPLIN, S. D. General Public Utilities GPU Barvice Corp 82/08/09 Region 1, Office of Director 3pp 14379:192 24X Fiche 50-320,82/08/09,8208180054.
- B20B200044 PNO-TMI-82-019 on B20B17, first of 49 EPICOR II prefilters (PF-3) shipped from TMI to BNL, West Jefferson, OH Ion exchange vessel contained 1,800 Ci radioactive matl Shipment scheduled to arrive by 820B18 GRANTIF., WIEBEJJ, FABAND. A. TMI Program Office 82/08/17. ip 14392, 255. 24% Fiche: 50-320, 82/08/17, 8208200044
- 6208270300 Forwards schedule for long-term corrective actions re LER 82-020/01L-0 dtd 820626. XANOA,B K. General Public Utilities - GPU Bervice Corp 82/08/20, BARRETT,L H. TMI Program Office 2pp. 14564 210 24X Fiche 50-320, 82/08/20,8208270300.
- T. Hearing transcripts on non-antitrust matters
- B208230i40 Transcript of 820805 affirmation/discussion session in Hashington, DC re BECY-82-249 & SECY-82-214 Pp 1-6 + Commissioners 82/08/05, 7pp 14517;341 24X Fiche, 30-320, 82/08/05, 8208230i40.
- U Congressions1/Executive Correspondence
- \$207200095 Responds to \$20621 request for info re shipments of radwaste from facility through State of WI.Shipments resulting from cleanup efforts estimated to range from 350-1,000 CI DIRCKS.W.J. Office of the Executive Director for Operations \$2/07/08. ASPIN.L. House of Rep. 5pp 13760;319, 24X Fiche.50-320,82/07/08.8207200095.

- --8206200038 Requests add1 info re type number of shipments of radwaste passing through State of WI ASPIN.L. House of Rep. B2/06/21 PALLADINO.N J. Commissioners 2pp 13960 323 24X Fiche 50-320.82/07/08.8207200095
- DOCKET 50-321 EDMIN I HATCH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8208060040 Releases public version of revised emergency plan procedure FELTON, J M Division of Rules and Records. 82/08/02. Document Management Branch ip 14282 029 24X Fiche 30-321, 82/08/02, 82/08/040
- --8208060044 Forwards public version of Revision 11 to Emergency Plan Procedure HNP-8002, "Radiation Exposure Limits " Receipt form encl SORRELL,E C Georgie Power Co 82/07/23 NRC - No Detailed Affiliation Given 1p 14282 030 24X Fiche 50-321,82/08/02, 8208060040
- --8208060047 Public version of Revision 11 to Emergency Plan Procedure HNP-8002, "Radiation Exposure Limits " SNITH, D , PHILPOTTS, D Georgia Power Co 82/07/21, 11pp, 14282 031, 24X Fiche 50-321,82/08/02,8208060040
- 820806005; Releases public version of revision to emergency plan procedure. FELTON, J. M. Division of Rules and Records. 82/08/02. Document Management Branch ip 14282 118 24X Fiche 50-321,82/08/02,82081605;
- --B20B060055 Forwards public version of Revision 3 to Emergency Plan Procedure HNP-4621, "Actions for Ail Personnel in Bite Area Emergency "Receipt form encl.

 SORRELL,E C Georgia Power Co. B2/07/23 NRC No Detailed Affiliation Given ip 14282 119 24X Fiche. 50-321, 82/08/02, 82/88060051
- --B20B060057 Public version of Revision 3 to Emergency Plan Procedure HNP-462i, "Actions for All Personnel in Site Area Emergency "ROCERS W. H Georgia Power Co. 82/07/21, App. 14282 120 24X Fiche 50-321,62/08/02,8208060051
- 8208100308 Forwards IE Safeguards Insp Repts 50-321/82-22 & 50-366/82-20 on 820718-22 No noncompliance noted DANCE, H C. Division of Project & Resident Programs, 82/08/05, KELLY, R J Georgia Power Co 2pp 14297; 135 24X Fiche 50-321, 82/08/05, 8208100308.
- --8208100318 IE Bafeguards Insp Repts 50-321/82-22 & 50-366/82-20 on 820718-22 No noncompliance noted Hajor areas inspected: security plan & procedures, security organization, program audit, records & repts, Details withheld (10CFR73 21) MORE, D E , NGGUIRE, D, R Division of Project & Resident Programs, 82/08/03 1p 14277, 137 24X Fithe 50-321, 82/08/05, 8208100308
- 8208110245 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records, 82/08/05 Document Management Branch 1p. 14331-104. 24X Fiche 30-321,82/08/05,8208110245.
- --B20B11024B Forwards public version of Revision 5 to Emergency Plan Implementing Procedure HNP-B006, "Dacontamination" BORRELL,E.C. Georgia Power Co. 82/07/27, Office of Nuclear Reactor Regulation, Director ip. 14331 105, 24X Fiche: 50-321,82/0B/05,820B110246
- ---8208110249 Public version of Revision 5 to Emergency Plan Implementing Procedure HNP-8006. "Decontamination" ROGERS, W.H. Georgia Power Co. 82/07/24. 12pp. 14331·106. 24X Fiche: 50-321, 82/08/05, 8208110246
- B20B260217 Responds to NRC B20713 ltr re violations noted in 1E Bafeguards Insp Repts 50-321/B2-15 & 50-366/82-15. Corrective actions withheid (ref 10CFR73, 21) Full payment of civil penalty encl BECKHAN-J T Georgia Power Cp B2/0B/12. Director's Office, Office of Inspection and Enforcement, 3pp. 14554-308, 24% Fiche: 50-321, 82/08/12, 8208260217.
- 8208270197 Advises of error in assigning IE Bafeguards Insp Rept 50-366/82-20 on 820718-22 Correct rept number is 50-366/82-23 Transmittal 1tr & rept should be changed to reflect correction DANCE, H. C. Division of Project & Resident Programs. 82/08/24 KELLY, R. J. Georgia Power Co. ip. 14569: 206. 24X Fiche: 50-321. 82/08/24. 8208270197

[Financial information

- 8208120129 Forwards Annual Financial Rept 1981 Guarterly financial statements for period ending 820630 & projected source of funds statement for CY83 encl BCUN.M T Georgia Power Co 82/08/09 SALTZMAN.J Antitrust & Economic analysis Branch (Utility Finance) 7pp 14319 237 24% Fichs 50-000, 82/08/09, 8208120129
- --8208120134 Annual Financial Rept 1781 5CHERER, R W , MILLER, J H Georgia Power Co 82/02/19 29pp 14319 245 24X Fiche 50-000, 82/09/07, 8208120127
- J Insurance & indemnity information
- 8208170074 Forwards Endorsement 72 to ANI Policy NF-215 & Endorsement 58 to MAELU Pol.cy MF-78 FIEDLER, J. Marsh & McLennan, Inc. M & M. Nuclear Consultants, Inc. Div 82/08/12 SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp 14338 130 244 Fiche 50-321,82/08/12,8208170074
- 8208170200 Forwards Endorsement 73 to NELIA Policy NF-215 & Endorsement 39 to HAELU Policy HF-78
 FIELDER, J. Marsh & McLennan, Inc., H & M Nuclear Consultants, Inc. Div. 82/08/12 SALTIMAN, J. Assistant Director for State & Licensee Relations 3pp 14366 252 24X Fiche 50-321,82/08/12,8208170200
- P Operating license stage documents & correspondence
- B207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of GP re Commission approved charter for CROR Byc list encl
 DIRCKS.H J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 ODI
 24X Fiche 50~000, 82/07/02, 8207080064
- 8208030743 Advises that review of util 810901 & 0607 responses to Generic Ltr 81-01, "Qualifications for Insp.Exam.Testing & Audit Personnel," complete Commitments & exceptions to Reg Ouide 1 58.Revision 1 & Reg Ouide 1 146 acreptable STOLZ, J F Operating Reactors Branch 4 82/07/14 8ECKHAM, J T Georgia Power Co 2pp 14196 344 24X Fiche 50-321.82/07/14, 8208030743
- 8208040437 Agrees w/BWR owners group position that six safety/relief valves provide adequate venting in response to util 810701 & 820427 response to NUREG-0737. Item II B 1, "RCS Vents" LLL technical evaluation encl STOLZ-JF Operating Reactors Branch 4 82/07/22 BECKHAAM, J T Georgia Power Co 2pp 14220 182 24X Fiche 50-321.82/07/22, 8208040437
- ---B208040442 "Operating Reactor TMI Lessons Learned NUREG-0737 Response Evaluations (Program II), Project 1 RCS Vents (Item II B I), " final technical evaluation rept for Hatch 1 & Z BUTCHER.E . BARNHART.B Lawrence Livermore Laboratory FIN A-0246-2 B2/06/07 NRC NO Detailed Affiliation Olven 4pp 14220 184 24x Fiche 50-321, 82/07/22, 8208040437
- 8208030503 Forwards addl licensing fees based on 820714 reassessment BECKHAMLJ T Georgia Power Co 82/07/26 MILLER.W Q License Fee Management Branch 2pp 14163 123 24X Fiche 50-321,82/07/26, 8208030503
- 8208040192 Application to amend Licenses DPR-57 & NPF-5.changing ET8 to correct surveillance requirements for flow monitoring of gassous releases from hydrogen recombiner bldg vent BECKHAN, J T Georgia Power Co 82/07/28 Office of Nuclear Reactor Regulation, Director 2pp 14188 292 24X Ficher 50-321, 82/07/28, 8208040192
- --8208040196 Proposed ETS change correcting surveillance requirements for flow monitoring of gaseous releases from hydrogen recombiner bldg vent # Georgia Power Co 82/07/28 4pp 14188 294 24X Fiche 30-321,82/07/28.8208040192
- 8208090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Ser 1ist enc! EISENMUT.D.Q Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356.332 24X Fiche 50-000,82/08/09,8208090194

- 8208290500 Forwards Amend 89 to License DPR-57, safety evaluation & notice of issuance & availability. Amend changes Tech Spec Table 3 7-4 re primary containment testable isolation valves to agree w/as-built configuration STOLZ, J F Operating Reactors Branch 4 82/08/10 BECKMAM, J T Georgia Power Co 2pp 14062 246 24X Fiche 50-321,82/08/10,8208250500
- --8208250504 Amend 89 to License DPR-57, revising Tech Spec Table 3 7-4 re primary containment testable isolation valves to agree w/as-built configuration STOLZ, JF Operating Reactors Branch 4 82/08/10 4pp 14562 248 E4X Fiche 50-321, 82/08/10, 8208250500
- --B208250508 Safety evaluation supporting Amend 89 to License DPR-57

 4 Office of Nuclear Reactor Regulation, Director 82/08/10 jp
 14542 252 24X Fiche 50-321,82/08/10,8208250500
- --8208250511 Notice of issuance & availability of Amend 89 to License PRR-57 STOLZ.JF Operating Reactors Branch 4 82/08/10 1p. 14562 253 24% Fiche 50-321,82/08/10,8208250500
- 8208270690 Informs that review of NUREO-0737, Item II K 3 15, "Mod Break Detection Logic HPGI/Reactor Core Isolation Cooling," completed Reactor core isolation cooling sys adequate based on encl safety evaluation STOLLY JF Operating Reactors Branch 4 82/08/17, BECKHAM, J T. Operating Fower Co 4pp 14683 058 24X Fiche 50-321,82/08/17, BECKHAM, J 7, BEC
- 8208270693 Forwards for review draft technical evaluation re control of heavy loads Util will be asked to participate in conference call w/Franklin Research Ctr & NRC technical reviewers in approx 4 wks W/o encl STULZ, J F Operating Reactors Branch 4 82/08/19 BECKHAM, J T Georgia Power Co 2pp 14683 059 24% Fiche 50-321,82/08/19,8208270693
- O Inspection reports: IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV)
 Leakage " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274, 24%
 Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche. 50-600, 82/07/19, 8204210375
- 8208160257 Forwards IE Insp Rept 50-321/82-21 on 820708-09 No noncompliance noted DANCE:H C Division of Project & Resident Programs 82/07/19. KELLY:R J Georgia Power Co 2pp 14347 091 24X Fiche 50-321:82/07/19.8208160257.
- --8208160263 IE Insp Rept 50-321/82-21 on 820708-09 No noncompliance noted Major areas inspected disassembly of two safety-relief valves JAPE.F. HEADT.A R Division of Engineering & Technical Programs 82/07/19 8pp. 14347 093 24X Fiche 50-321,82/07/19,8208160257
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Graduel Loss of Air Pressure" Svc list encl JORDAN:E L Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York 112pp. 14381 001 RAX Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB,L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co. of New York, 71pp 14357.276. 24X Fiche 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl.
 JORDAN.E L Division of Engineering & Quality Assurance 82/07/22
 Consolidated Edison Co of New York 112pp 14174-321 24X
 Fiche 50-000,82/07/22,8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Oringing in Vicinity of Drained & Open RCS." Bvc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/07/23, Consolidated Edison Co of New York, 122pp 14380,115, 24X Fiche, 50-000, 82/07/23, 8204210401

DOCKETED ITEMS

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PMRs " Svc list encl JORDAN, & L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- B20B030375 Ack receipt of B20617 & 22 ltrs informing NRC of steps taken to correct violations noted in [E Insp Repts 50-321/B2-09 & 50-366/82-09 LEWIS.R C Division of Project & Resident Programs 82/07/23 KELLY,R J Georgia Power Co ip 14154 238 24X Fiche 50-321,82/07/23,8208030375
- --8208030377 Responds to NRC 820518 ltr re violations noted in IE Insp. Repts 50-321/82-09 & 50-366/82-09 Corrective actions isolation actuation instrumentation setpoint for reactor core isolation toolong inboard isolation valve corrected BECKHAM. J. T. Georgia Power Co. 82/06/22 LEMIS.R.C. Division of Project & Resident Programs 10pp 14154 239 24X Fichs 50-321,82/07/23,8208030375
- --8208030377 Responds to NRC 820518 ltr re violations noted in IE Insp. Repts 50-321/82-09 & 50-364/82-07 Speed setting for control rod valve not safety concern BECKHAMJ T Georgia Power Co 82/06/17 LEHIS,R C Division of Project & Resident Programs 2pp 14154 249 24X Fiche 50-321,82/07/23,8208030375
- --8208030382 Forwards IC Insp Repts 50-321/82-09 & 50-366/82-09 on 820121-0301 & notices of violation & deviation LEWIS.R C Division of Project & Resident Programs 82/05/18 KELLY.R J Georgia Fower Co 2pp 14154 251 24X Fiche 50-321,82/07/23,8208030375

- --B208030397 IE Insp Repts 50-321/82-09 & 50-366/82-09 on B20121-0301.
 Noncompliance noted failure to isolate & declare instrument channel w/nonconservative setpoint inoperable & failure to follow OC procedures
 ROGERS.R F , BROWNLEE.V L Division of Project & Resident
 Programs B2/05/17 7pp 14154 257 24X Fiche 50-321,82/07/23,8208030375
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl, UCRDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- B204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Syc list encl URDAN.E L Division of Engineering & Quality Assurance B2/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000.82/07/28,8204210405
- B2042i0407 IE Info Notice B2-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl

 JORDAN.E L Division of Engineering & Guality Assurance B2/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000, 82/08/05, 8204210407
- 820B10030B Forwards IE Safeguards Insp Repts 50-321/82-22 & 50-366/82-20 on 820718-22 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/08/05 KELLY: R J Georgia Power Co 2pp 14297 135 24X Fiche 50-321:82/08/05.8208100308
- --B208100318 IE Bafeguards Insp Repts 50-321/62-22 & 50-366/82-20 on 820718-22 No noncompliance noted Major areas inspected security plan & procedures, security organization, program audit, records & repts, Details withheld (10GFR73 21) MODRE, D E . MCQUIRE, D R. Division of Project & Resident Programs 62/08/03 ip 14297 137 24x Fiche.50-321,82/08/05,820B100308
- 8208260217 Responds to NRC 820713 ltr re violations noted in IE Safeguards Insp Repts 50-321/82-15 & 50-366/92-15 Corrective actions withheld (ref 10GFR73 21). Full payment of civil penalty encl BECKHAM, J T Georgia Power Co 82/08/12 Director's Office, Office of Inspection and Enforcement 3pp 14554 308, 24X Fiche 50-321, 82/08/12, 8208260217

- 8208300029 Forwards technical evaluation rept re NRC review of util responses to IE Bulletin 80-11, "Masonry Hall Design " Items 2 & 3 of bulletin have been fully implemented w/exception of removal of Halls C164-44 & 8 & C100-19c & D
 BTOLZ, J.F. Operating Reactors Branch 4 82/08/16 BECKHAM, J.T. Georgia Power Co. 3pp. 14683 287 24X Fiche 50-321, 82/08/16.
- --8206300163 "Masonry Hall Design," technical evaluation rept SUBRAMONIAN,N, CGN,V N Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05506-165 BZ/06/25 CHOKSHI,N,C NRC - No Detailed Affiliation Oiven 37pp 14683 290 24 X Fiche 50-321.82/08/16.8208300029
- 8208270199 Advises of error in assigning IE Bafeguards Insp Rept 50-366/82-20 on 820718-22 Correct rept number is 50-366/82-23 Transmittal 1tr & rept should be changed to reflect correction DANCE.H C Division of Project & Resident Programs 82/08/24 KELLY.R J Georgia Power Co ip 14563 206 24X Fiche 50-321.82/08/24.8208270199
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyring said info Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000.82/07/13.8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVB1" + NRC - No Detailed Affiliation Given 82/07/13 4Bpp 14679 216 24X Piche 50-000.82/07/13,8208270010
- --820827062B Forwards "Radiation Exposure Rept for CY81," per 10CFR20 407 MANRY.H Georgia Power Co 82/03/26 Office of Management and Program Analysis 1p 14680 060 24X Fiche: 50-000, 82/07/13, 8208270010
- --8208270631 "Radiation Exposure Rept for CY81 "
 * Georgia Power Co 82/03/26 Ip 14680 O61 24%
 Fiche 50-000,82/07/13,8208270010
- 8208160091 Forwards monthly operating rapts for Jul 1982 NIX.H C Georgia Power Co 82/08/10 Director's Office, Office of Inspection and Enforcement 1p 14342 006 24X Fiche 50-321, 82/08/10,8208160091
- --8208160094 Monthly operating repts for Jul 1982 EAZZETTA B A Georgia Power Co 82/08/10 13pp 14342-007 24X Fiche 50-22: 82/08/10 8208160091
- 8 Reportable occurrences, LERs & related correspondence
- 8208030442 Forwards LER 82-035/03L-0 NIX.H C Georgia Power Co 82/07/21 O'REILLY.J P Region 2. Office of Director ip 14155 342 24X Fiche 50-321,82/07/21, 8208030442
- --B208030430 LER 92-035/03L-0 on 820618.svc water pump iD seal & prelube water manual valve found not fully open & unlocked Cause not stated Valve positioned in open position & locked Valve lineup at intake structure checked

 TIPPS.B B Georgia Power Co B2/07/21 Region 2, Office of Director 2pp 14155 343 24X Fiche 50-321.B2/07/21.8208030442.
- 8208090271 Forward's LER 62-045/03L-0 NIX.H C Georgia Power Ca 82/07/27 G'REILLY, J.P Region 2, Office of Director. ip 14270 310 24X Fiche 50-321, 82/07/27. 8208090271
- --8208090277 LER 82-045/03L-0 on 820629, manufacturing errors discovered in 1031 reactor water conductivity indicator Gaused by use of incorrect valve components Incorrect components located & replaced w/proper components Indicator recalibr TIPPS, 8, 9. Georgia Power Co 82/07/27. Region 2, Office of Director 2pp. 14270, 311. 24X Fiche, 30-321, 82/07/27, 8208090271
- 8208070276 Forwards LER 82-054/03L-0 NIX,H C Quorgia Power Co 82/07/27 O'REILLY,J.P Region 2, Office of Director ip 14270 307 24X Fiche 50-321,82/07/27, 8208070276

- --B208090279 LER 82-054/03L-O on B2062B, RHR svc water pump C failed to pass operability & rate flow procedure requirements Cause undetermined Pump removed, rebuilt & retested satisfactorily Updated rept will be issued upon investigation completion TIPPS.B B Ogeorgia Power Co B2/07/27 Repion 2, Office of Director 2pp 14270 308 24X Fiche 50-321, B2/07/27, 8208090276
- 8208120199 Forwards updated LER 81-120/01T-1 NIX.H C Georgia Power Co 82/08/03 D'REILLY, J P Region 2, Office of Director, 1p 14326 027 24X Fiche 50-321, 82/08/03, 8208120199
- --8208120228 Updated LER 81-120/01T-1 on 811105.AE advised that in event of main steamline break or scram discharge, isolation of HPCI & reactor core isolation cooling sys could occur Caused by erroneous analysis Event would not occur SUMNER,H L Georgia Power Co 82/08/03. Region 2. Office of Director 2pp 14326 028 24X Fiche 50-321,82/08/03.8208120199
- 8208160272 Supplemental narrative summary to RO 50-321/1779-021, Revision 5, consisting of nonroutine radiological environ operating anomalous measurement rept Updated data on tritium levels on groundwater samples provided NIX, H C Georgia Power Co 82/08/06 O'REILLY, J P Region 2, Office of Director App 14346 175 24X Fiche 50-321, 82/08/06, 8208160322
- 8208160454 Forwards LER 82-061/03L-0 NIA: H C Georgia Power Co 82/08/06 D'REILLY, J P Region 2: Dfilce of Director (p 14348 235 24% Fiche 50-321, 82/08/06, 8208160454
- --B20B160469 LER B2-061/03L-0 on B20710, fire door separating unit east cableway from health physics ofc area would not close or latth properly Caused by separation of door facing from door resulting in binding between door frame & edge.

 SUMNER.H L. Georgia Power Co B2/08/06 Region 2, Office of Director 2p 14348 236 24X Fiche 50-321,82/08/06,8208160454.
- 9208270235 Forwards LER 82-067/01T-0
 NIX.H C Georgia Power Co 82/08/10 O'REILLY, J P Region 2.
 Office of Director ip 14563 123 24X Fiche 50-321, 82/08/10, 8208270235.
- --B203270241 LER 82-067/01T on 820802, starting station svc bank 1C undervoltage relays found inoperable during functional test procedure Caused by undervoltage relay failure due to sticking relay contacts Contacts burnished TIFFS:8 B Georgia Power Co 82/08/10 Region 2, Office of Director 2pp 14563 124 24X Fiche 50-321.82/08/10,8208270235
- 8208270297 Forwards LER 82-063/03L-0 NIX.H C Georgia Power Co B2/08/10 O'REILLY, J Region 2, Office of Director ip 14564 171 24X Fiche 50-321.82/08/10,8208270297
- --B208270302 LER 82-063/03L-0 on B20715, inboard reactor water cleanup primary containment isolation valve found open in presence of isolation signal Caused by loose electrical connection Loose connection tightened.

 TIPPS.B B Georgia Power Co B2/0B/10 Region 2, Office of Director 2pp 14564 172 24X Fiche 50-321,82/0B/10,8208270297
- B20B300173 Forwards LER 82-064/03L-0 MIX.H C Quorgia Power Co 82/08/10 O'REILLY, J P Region 2, Office of Director ip 14678 223 24x Fichs 50-321, 82/08/10, 820B300173
- --8208300174 LER 82-064/03L-0 on 820718, reactor water cleanup sys primary containment outboard isolation valve opened while sys inoperable. Caused by personnel failure to clear outstanding limiting condition for operation prior to opening valve, TIPPS.8 B Georgia Power Co 82/08/10 Region 2, Office of Director 2pp 14678 224 24X Fiche 50-321,82/08/10,8208300173
- B208200045 Forwards LER B2-062/03L-0 MIX.H C. Georgia Power Co 82/08/12 O'REILLY, J P Region 2, Office of Director. 1p 14392:343. 24X Fiche 50-321,82/08/12, 8208200045
- ---B20B200052 LER 82-062/03L-0 on 820714,RHR svc water pump D failed to meet Tech Spec requirements during inservice insp & operability test. Caused by light silt build-up around suction bell Bilt removed & pump retested satisfactorily TIPPS.S.B Georgia Fouer Co B2/0B/12 Region 2, Office of Director 2pp 14392-344, 24X Fiche-50-321,82/0B/12,8208200045

- --B20B300235 LER 82-066/03L-0 on 820719, discovered that spec release order to Barksdale pressure switch calibr procedure made for previously performed work Caused by personnel error Adherence to procedures stressed TIPPS, S B Georgia Power Co B2/08/17 Region 2, Office of Director 2pp 14679 177 24X Fiche 50-321, 82/08/17, 820B300230
- 8208300158 Forwards LER 82-068/03L-0 NIX.H C Georgia Power Co 82/08/19 O'REILLY.J P Region 2, Office of Director 1p 14599 215 24X Fiche 50-321,82/08/19, 8208300158
- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- 8208040184 Forwards Revision 2 to "Environ Qualification Rept for Class IE Equipment for Shoreham Nuclear Power Station Unit 1 " SMITH.J L Long Island Lighting Co 82/03/17 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 14187 010 24X Fiche 50-322, 82/05/17, 8208040184
- --8208040188 Revision 2 to "Environ Qualification Rapt for Class IE Equipment for Shoreham Nuclear Power Station Unit ; " + Long Island Lighting Co 82/05/17 468pp 14187 012. 24X Fiche 50-322,82/05/17.8208040184
- B2070B0064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list encl
 DIRCKS, W J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194-001
 24x Fichs 50-000/82/07/02.8207080064
- 8208040424 Requests add1 info rs proposed schedule for program concerning adequacy of design margins of Mark I & II containment sys Response within 14 days requested TEDESCO.R L Assistant Director for Licensing 82/07/08 POLLOCK.M 8 Long Island Lighting Co 2pp 14220 173 24X Fiche 30-322, 82/07/08, 8208040424
- 8208090022 Forwards requests for addl info to justify applicability of "Analysis of Ceneric BWR Safety/Relief Valve Operability Test Results " W/o and I SCHWENCER, A Licensing Branch 2 82/07/08 PDLLDCK, M B Long Island Lighting Co 2pp 14283 356 24X Fiche 50-322,82/07/08, 8208090022
- 8207140090 Forwards TR-5633-2, "Initial Status Rept Independent Design Review for Shoreham Nuclear Fower Station," technical rept KINO, J P Teledyns Engineering Services 82/07/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 13840 152 24% Fiche 50-322,82/07/09,8207140050
- --8207140053 "Initial Status Rept Independent Design Review for Shoreham Nuclear Fower Station," technical rept * Teledune Engineering Services TR-5633-2 82/07/09 90pp. 13840 155 24X Fiche 50-322.82/07/09,8207140050
- 8208310035 Responds to appeal re denial of FOIA request for eight categories of documents Appeal partially granted. Documents from interim guidance files encl Remaining documents withheld (ref FQIA Exemption 5)
 DIRCKS.W J Office of the Executive Director for Operations 82/07/13 MCQMRRAY.C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips 3pp 14695 178 24X Fiche 50-322,82/07/13,8208310035.
- 8208060368 Board Notification 82-70 notifies of differing prof opinion resensitisation of BHR stainless steel weldments TEDESCO.R. L. Assistant Director for Licensing 82/07/20. Atomic Safety and Licensing 80040 Panel 4pp 14281 355 24X Fiche 50-000,82/07/20,8208060368
- 8208040204 Requests evaluation of whether channel boxes & associated walds meet primary containment boundary acceptance criteria Rept needed to complete review of util proposal not to unplug boxes during integrated leak rate test.

 8CHWENCER.A. Licensing Branch 2 82/07/22 PDLLOGK.M S Long Island Lighting Co 2pp 14228 361. 24X Fiche; 50-322, 82/07/22, 8208040204

- 0208050021 Forwards request for addl info re environ qualification of electrical equipment for addl info re environ qualification electrical equipment SCHWENCER, A Licensing Branch 2 82/07/22 POLLOCK, M S Long Island Lighting Co 2pp 14243 087 24X Fiche 50-322,82/07/22,8208050021
- --8208050025 Trip rept of 820602-03 site visit re reaudit of util environ qualification files for safety-related electrical equipment Per NUREC-0588 ROBITOCZY, Z R Equipment Qualification Branch 82/06/30 ROBITOCZY, Z R Equipment Qualification Branch 15pp 24X Fiche, 50-322, 82/07/22, 8208050021
- 820B0A0283 Discusses systematic assessment of licensee performance on B20430 Performance of const & preoperational activities acceptable Comments on systematic assessment of licensee performance made at 820521 meeting under review HAYNES, R C Region 1. Office of Director. 82/07/22. PDLLUCK, M, 8 Long Island Lighting Co 30pp 14241, 206 24X Fiche 50-322, 82/07/22, 8208060283
- --B2080602B6 Forwards Bystematic Assessment of Licenses Performance on B20430 Meeting scheduled for B20321 to discuss assessment, plans to improve performance & any comments. STAROBTECKI,R Division of Project & Resident Programs. 82/05/19, POLLOCK,M & Long Island Lighting Co 2pp 14241-236. 24X Fiche 50-322,82/07/22.8208060283.
- --8208060292 Responds to NRC 820819 ltr re systematic assessment of licenses performance covering period 810301-820228, Corrective actions B&W performed evaluation of FSAR conformance program & project procedures.

 POLLOCK.M S Long Island Lighting Co. 82/06/21, GTARGSTECKI,R
 Division of Project & Resident Programs. Bpp. 14241;238 24X
 Fiche. 50-322, 82/07/22, 8208060283.
- 8208040569 Notification of 820728 & 29 meetings w/util & 8kW in Boston, MA to discuss reconciliation of Mark II containment hydrodynamic loads for piping sys OILDERTR A Licensing Branch 2 82/07/26. BCHWENCER, A. Licensing Branch 2 3pp. 14225 339 24X Fiche. 30-322,82/07/26,8208040369
- B20B030301 Responses to NRC B2070B request for add1 info re safety relief valve testing Certificate of Svc encl.
 IRWIN.D.P. Long Island Lighting Co. IRWIN.D.P. Hunton & Williams B2/07/29 19pp. 14157.162. 24x Fiche:50-322,82/07/29,820B030301
- 8208040007 Advises of completion of mod to reactor core isolation cooling sys automatic restart per NUREO-0737. Action Item II.K S. 13 Requeste items be closed SMITH.J L Long Island Lighting Co. 82/07/29. DENTON, H.R. D. of Nuclear Reactor Regulation. Director. 1p. 14189:129 24X Fiche 50-322, 82/07/29, 8208040009.
- 6208190024 Notification of 820810-11 meetings w/util in Wading River. NY to discuss Tech Specs WEINKAM.E J Licensing Branch 2. B2/07/30 SCHWENCER.A. Licensing Branch 2 3pp. 14506-354. 24X Fiche 50-322.82/07/30.8208190024.
- 8208130006 Notification of 820811-13 caseload forecast panel visit to discuss status of const discuss status of const GILBERT, R. A. Licensing Branch 2 82/08/02 8CHHENCER, A. Licensing Branch 2 7pp 14340.348 24X Fiche 50-322,82/08/02,8208130006.
- 8208270680 Staff requirements memo re 820729 affirmation/discussion session Commission approved orders releasing sanitized version of ALAB-653, reviewing ALAB-670 & denying patition to intervene in proceeding for mod of Filgrim OL HOYLE, J C Office of the Secretary of the Commission. 82/08/06, BICKWIT, L. Office of the General Counsel, DIRCKS, W. J. Office of the Executive Director for Operations, 4pp 14683:185, 24X Fiche: 50-000, 82/08/06, 8208270680.
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl. EISENNUT, D 0. Division of Licensing. 82/08/09. Consolidated Edison Co of New York ip. 14356:332 24X Fiche:50-000,82/08/09,8208090194.
- 8208200200 Forwards summary of evaluation performed to determine facility compliance w/Reg Guide 1.32, in response to NRC 820707 request B20/07 request SMITH, J. Long Island Lighting Go. 82/08/13. DENTON, H.R. G of Nuclear Reactor Regulation, Director. 6pp. 14399:167. 24X Fiche 50-322,82/08/13,8208200200.
- 8208260314 Notification of 820824 meeting w/util in Wading River, NY to discuse post-accident discharge of radioactive matl directly into reactor bldg & internal flood protection.

 WEINKAM, E. J. Licensing Brench 2. 82/08/18, 824MENCER, A. Licens Branch 2. 4pp. 14576: 117. 24X Fiche: 50-32R, 82/08/18, 8208260314.

- 8208240238 Commits to perform 100% re-evaluation of piping attached at three locations of concern in primary containment. Findings should be submitted by 821115 SMITH. JL Long Island Lighting Co 82/08/20 DENTON, HR Offic
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 820B1B0041 Forwards fire hazard analysis rept Rept submitted as confirmatory documentation in accordance w/Section 9 5.1 of Suppl 1 to SER SMITH.J L. Long Island Lighting Co. 82/08/06 DENTON.H R. of Nuclear Reactor Regulation. Director 2pp 14378-291 24Fichs 50-322.82/08/06.820B1B0041 Office 24Y
- 8208130171 Forwards qualification summary of equipment forms re SER Item 9. "Dynamic Gualification." Timely review required in order that audit can be scheduled at earliest possible date. SHITH.J L. Long Island Lighting Co. 82/08/10. DENTGN.H R. Offic of Nuclear Reactor Regulation. Director. 83pp 14338 200 24X Fiche 50-022.82/08/10.8208130191. Office
- 8208200246 Forwards Revision 3 to "Environ Qualification Rept for Class IE Equipment for Shoreham Nuclear Power Station Unit 1."

 Vols I & 2 rm SER Questanding Issue 7 Suppl projected for submittal by 820910 will address balance of equipment. SMITH. J L Long Island Lighting Co. 82/08/13. DENTON. H. R. Office of Nuclear Reactor Regulation, Director 2pp 14395 001 24% Fiche 50-322.82/08/13.8208200246.
- --8208200256 Revision 3 to "Environ Qualification Rept for Class IE Equipment for Shoreham Nuclear Power Station Unit 1," Vols 1 & 2, 4 Stone & Webster Engineering Corp. 82/08/31. 750pp. 14395.003 24X Fiche: 50-322,82/08/13.8208200246
- 8208240429 Closes SER Item 10 re seismic & LOCA loadings QE Topical Rept NEDE-21175-3-P. "BWR Fuel Assembly Evaluation of Combined 88E & LOCA Loadings," demonstrates util fuel response within acceptable limits BMITH.J L Long Island Lighting Co 82/08/18 DENTON,H R. Dffice of Nuclear Reactor Regulation, Director. 1p 14524.197, 24X Fiche 50-322, 82/08/18, 8208240429
- 8208240293 Forwards add1 info re control room mods & other work required by App C of NUREO-0420, conterning BER Suppl 1 BHITH.J.L Long Island Lighting Co 82/08/19 DENTON, H. R. O of Nuclear Reactor Regulation, Director 4pp 14522, 289, 24X Fiche 30-322, 82/08/19, 8208240293 Office
- 8208240431 Forwards engineering & design coordination repts documenting mode to safety-related masonry walls, per Item 12 of applicant 810730 Itr re SER Issue 2 Mode will be completed applicant SIO/30 let re den issue 2 //Out #11 to Compilere prior to fuel load BHITH-J L. Long Island Lighting Co 82/08/19. DENTON, H. R. Dffice of Nuclear Reactor Regulation. Director 550pp. 14525; OOI. 24X Fiche: 50-322, 82/08/19. 8208240401.
- 8208300176 Forwards add1 info re remote shutdown panel per 820706 request. Addition of instrumentation & controls & analysis performed on suppression pool temp measurement determined that panel design acceptable per 8ER Itsa 62 SMITH. J.L. Long Island Lighting Co. 82/08/24, DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director. 138pp. 14677:264. 24X Fichel 30-322, 82/08/24, 8208300176
- F. Security, medical, emergency & fire protection plans
- 8208050293 Forwards IE Safeguards Insp Rept 50-322/82-09 on 820425-29 No nuncompliance noted Datalis of rept withheld (ref 10CFR73, 21) MARTIN:T T Division of Engineering & Technical Programs 82/07/ii POLLOCK:M.8 Long Island Lighting Co. 2pp. 14210:212, 24X Fichs. 30-322, 82/07/14, 8208050293. 82/07/16
- --B20B050299 IE Bafeguards Insp Rept 50-322/B2-09 on B20425-29. No noncompliance noted. Major areas inspected; physical security plan, security organization, records & repts, testing & maint, locks, keys & combination, Details withheld (ref 100FR73, 21). BAILEY, R. J., QODY, A. T. Division of Engineering & Technical Programs B2/07/16, 1p. 14210; 214, 24X Fiche: 50-322, B2/07/16, B208050293
- 8208030004 Releases public version of revised emergency plan, emergency plan training menual & emergency plan implementing procedures.
 FELTON J. M. Division of Rules and Records. 82/07/19 Document Management Branch. 1p 14203:001. 24X Fiche:50-322,82/07/19,8208030004.

- --B208030005 Forwards public version of Revision 2 to emergency plans unergency plan training manual & emergency plan implementing procedures in response to SER (NUREG-0420) BMITH. J L Long Island Lighting Co B2/06/2B DENTON. H R Office of Nuclear Reactor Regulation, Director Ip 14203 004 24X Fiche 50-322, B2/07/19,8208030004
- --8208030006 Public version of Revision 2 to emergency plan Resolution cross-reference list encl + Long Island Lighting Co 82/01/11 311pp 14203 006 24X Fiche 50-322,82/07/19,8208030004
- 820BiBG041 Forwards fire hazard analysis rept Rept submitted as confirmatory documentation in accordance w/Section 9 5 1 pf Suppl 1 to SER SHITH.J L Long Island Lighting Co 82/08/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 14378 291 24X Fichs 50-522.82/08/06.8208180041
- --B20BiB0050 Forwards fire hazard analysis rept in response to 760930 ltr Rept provides evaluation of fire protection provisions considering guidelines in App A to Branch Technical Position APCSB 9 5-1
 BURKELT J Long Island Lighting Co B2/05/05 B0YD,R B Office of Nuclear Reactor Regulation, Director, 2pp 14378 293 24X Fiche 50-322,82/08/06,8208180041
- ~~8208;80058 "Fire Hazard Analysis Rept," Revision 1 * Long Island Lighting Co 82/06/30 300pp 14378 296 24) Fiche 50-322,82/08/06,8208;80041
- G Adjudicatory correspondence
- 8208020207 Metion to strike GC Minor testimony on Suffelk County Contention Id re ATMS Testimony beyond scope of admitted contention Certificate of Svc encl Related correspondence EARLEY.A F. Long Island Lighting Co. EARLEY.A F. Hunton & Hilliams 82/07/27 Atomic Eafety and Licensing Board Panel 10pp 14141 126 24X Fiche 30-322.82/07/27.8208020209
- B208030301 Responses to NRC 820708 request for add1 info re safety relief valve testing Certificate of Svc encl
 IRHNN P Long Island Lighting Co IRHIN D F Hunton & Williams 82/07/29 179p 14157 162 24X Fichs 30-322,82/07/29,8208030301
- 3208020307 Order CLI-82-17, directing util counsel be given access to portions of ALAB-653 on definition of design basis threat & number of responders Request for access to entire opinion denied Request for access by consultants referred to ABLB HOYLE, J C Office of the Secretary of the Commission 82/07/30 Long feland Lighting Co 3pp 14151 139 24X Fiche 50-322, 82/07/30,8208020307
- 3208050291 Answer opposing util 820627 motion to strike OC Minor testimony on Suffalk County Contention 16 re ATMS Motion too broad Many portions of testimony clearly relevant Certificate of 8 ve encl
 LAMPHER, L C Suffalk County, NY LAMPHER, L C Kirkpatrick, Lockhert, Hill, Christopher & Phillips 82/07/30 Atomic Safety and Licensing Board Panel 9pp 14210 203 24X
 Fiche 50-322,82/07/30,8208050291
- 208160047 Order CLI-82-17 directing that util & Suffolk County be given access to portions of ALAB-653 dealing w/definition of design basis threat & interpretation of Commission regulations re appropriate number of responders MOYLE, J C Office of the Secretary of the Commission 82/07/30 2pp 14344 270 24X Fiche 30-322,82/07/30,8208160047
- 208040017 Forwards, for info, NRC 820722 request for add1 info re environ qualification of electrical equipment & NRC 820630 trip rept re reaudit of util documentation for environ qualification of Class IE electrical equipment REPKA, DA Hearing Branch 3 82/08/02 BRENNER, L, CARPENTER, JL, MORRIS, PA Atomic Safety and Licensing Board Panel 19pp 14189 273 24X Fiche 50-322,82/08/02,8208040017
- '08040233 Forwards objections to prehearing conference order & motion for reconsideration or alternatively, for certification to Commission

 RCHURRAY. C M. Kirkpatrick, Lockhart, Hill, Christopher & Phillips

 MCHURRAY. C M. Suffolk County, NY 82/09/02 BRENNER, L L,

 CARPENTER, J L, MORRIS. P A Atomic Safety and Licensing Board Panel ip 14188, 115 24X Fiche 50-322, 82/08/02, 8208040233.
- 8208040239 Objections to ABLB 820627 prehearing conference order on emergency planning & motion for reconsideration or alternatively for cartification to Commission, Phase I & II issues should not be separated Cortificate of Svc encl. BROWN, H H Suffolk County, NY, BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 82/08/02 Atomic Safety and Licensing Board Panel, 23pp 14188 116, 24% Fiche 50-322,82/08/02,8208040233

- 8208040280 Submits status rept concerning security contention settlement negotiations pursuant to ASLB 820727 prehearing conference order Summary of NRC 820728 meeting w/applicant & Suffolk County in Yaphank. NY forthcoming BORDENICK. B M Hearing Branch 4 82/08/02 DRENNER, L , CARPENTER, J L , MORRIER P A Atomic Safety and Licensing Board Panel 2pp 14183 068 24X Fiche 50-322,82/08/02.8208040280
- 820B05048B Notice of appearance in proceeding Certificate of Svc encl DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, Hill. Christopher & Phillips 82/08/02 3pp 14214 164 24X Fiche 30-322,82/08/02,820805048B
- 8208040020 Forwards, for info, 820723 Amend 1 to Part 70 license W/o enci BORDENICK, B M Hearing Branch 3 82/08/03 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 14187 271 24% Fich
- 8208060116 Response to second request for production of emergency planning documents Certificate of 8vc encl
 SEDKY.C Suffelk County, NY SEDKY.C Kirkpetrick, Lockhart, Hill, Christopher & Phillips 82/08/04 Long Island Lighting Co 16pp
 14238 257 24X Fiche 50-322,82/08/04,8208060116
- 8208060140 Motion opposing util application for issuance of subpoenas to F Jones, RC Maunkle & L Palmer & to modify F Jones subpoena to allow deposition after 820827 Subpoenas moot & should be quashed Certificate of Svc enci MCMURRAY, C M Suffolk County, NY MCMURRAY, C M Kirkpatrick, Lockhart, Hill. Christopher & Phillips 82/08/04 Atomic Safety and Licensing Board Panel Opp 14241 251 24X Fiche 50-322, 82/08/04, 8208060140
- 8208110168 Application for issuance of subpoents to RC Meunkle. L Palmer & FR Jones to appear & give depositions on 820805 in Washington. DC re Phase I emergency planning issues W/draft subpoents & Gertificate of Svc Related correspondence. CHRISTMAN. J N Long Island Lighting Co CHRISTMAN. J N Hunton & Williams 82/08/04 Atomic Sefety and Licensing Board Panel 19pp 14314 185 24X Fiche 50-322.82/08/04.8208110168
- 8208110150 Response to ASLB 820803 request for refs from prefiled written testimony, attachments & exhibits re safety reliaf valves Certificate of Svc encl IRWIN, D P Long Island Lighting Co IRWIN, D P Hunton & Williams 82/08/05 6p 14314 287 24X Fich# 50-322.82/08/05,8208110150
- 8208110164 Notice of appearance in proceeding Certificate of Svc encl EDWARDS,W J Long Island Lighting Co EDWARDS,W J Hunton & Williams 82/08/05 3pp 14314 204 24X Fiche 50-322,82/08/05, 8208110164
- 8208110167 Notice of appearance in proceeding Certificate of Evc encl RUDLIN,D A Long Island Lighting Co RUDLIN,D A Hunton & Williams 82/08/05 3pp 14314 176 24% Fiche 50-322,82/08/05, 820810167
- 8208110169 Notice of appearance in proceeding Certificate of Byc encl POWELL.L F Long Island Lighting Co POWELL.L F Hunton & Williams 82/08/05 Gpp, 14314 179 24X Fiche 50-322,82/08/05, 8208110169
- 820B110170 Notice of appearance in proceeding Certificate of Svc encl SPIVEY, J M Long Island Lighting Co SPIVEY, J M Hunton & Williams 82/08/05 3pp 14314:182 24% Fichs 50-322,82/08/05, 8208110170
- 8208110214 Marked-up subposes directing FR Jones to appear on 820805 in Washington. DC to testify an development of util emergency response plan for Suffolk County Certificate of Svc encl Related correspondence BRENNER. L. Atomic Bafety and Licensing Board Panel 82/08/05 JONES, F.R. Suffolk County, NY 5pp 14313 040 24X Fiche 50-322, 82/08/05, 8208110214
- 8208170211 Special appearance opposing Suffolk County request for access by consultants to portions of ALAB-653 Consultants need analyze Shoreham security plan, not Diablo Canyon Certificate of Evc encl
 CRANE.P A Pacific Oas & Electric Co 82/08/11 Atomic Safety and Licensing Board Panel 4pp 14362 057 24X
 Fichs 50-322,82/08/11,8208170211,
- 8208170246 Forwards application for issuance of subposes & draft subposes duces tecum directing licenses to produce documents used in preparing 820621 ltr & 820627 direct testimony for insp & copying by 820823 DYNNER, A R. Kirkpatrick, Lockhart, Hill Christopher & Phillips, DYNNER, A R. Suffolk County, NY 82/08/13, BRENNER, L., CARPENTER, J L., MORRIS, P.A. Atomic Safety and Licensing Board Panel 2pp. 14368; 338 24X Fiche 50-322, 82/08/13, 8208170246,

- --B20B170249 Application for issuance of encl subpoens duces tecum to licensee Subpoens directs licensee to produce documents used in proparing 820621 ltr & 820629 direct testimony for insp & copying by 820823

 DYNNER, A R Suffolk County, NY DYNNER, A R Kirkgatrick, Lockhart, Hill, Christopher & Phillips 82/08/13 Atomic Bafety and Licensing Board Panel 14pp 14368 340 24X

 Fiche 50-322,82/08/13,8208170246
- 8208190126 Advises of withdrawal of Minor testimony on Suffolk County Contention 16 on ATMS County will not be submitting direct testimony on contention Related correspondence LETECHE.K J Kirkpatrick. Lockhart, Hill. Christopher & Phillips LETECHE.K J Suffolk County, NY 82/08/16 BRENNER.L . CARPENTER,J L., MCRRIS.P A Atomic Safety and Licensing Board Panel 1p 14381 072 24X Fiche S0-322.82/08/16.8208190126
- 8208190192 Advises that Suffolk County objects to procedure whereby County must conduct cross-examination w/o benefit of technical assistance LEYSCHE.K J. Kirkpatrick, Lockhart, Hill, Christogher & Phillips LETSCHE.K J. Suffolk County, NY 82/08/16 BRENNER,L , CARPENTER,J L. MORRIS.P A Atomic Safety and Licensing Board Panel 2pp 14381 126 24X Fiche 50-322.82/08/16.8208190132
- 8208200270 Motion for protective order from Suffolk County 820813 application for subposen to require production of 47 categories of documents Alternatively, moves to quash subposen Requests overbroad & untimely W/Certificate of Svc CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunton & Williams 82/08/17 Atonic Bafety and Licensing Board Panel 13pp 14397 039 24X Fiche 50-322,82/08/17,8208200270.
- 8208200155 Forwards stipulation on Suffolk County Contention 9 re ECCS pump blockage
 BORDENICK, B M Hearing Branch 3 82/08/19 BRENNER, L,
 CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel ip 14500 088 24X Fiche 50-322, 82/08/19, 8208200155
- --B208200163 Stipulation resolving Suffolk County Contention 9 re ECC8 pump blockage Data provided to County which demonstrate basis for 50% blockage assumption Util agreed to take listed actions in response to County concerns BORDENICK.B M Hearing Branch 3 REVELEY.T Long Island Lighting Co LETSCHER, Suffolk County, NY 82/08/18 7pp 14500 089. 24X Fiche 50-322,82/08/19.8208200155
- 8208240229 Phase I consolidated emergency planning contention.
 Certificate of Svc encl
 SEDRY.C Suffolk County, NY SHAPIRO.R North Shore Committee
 Against Nuclear & Thermal Pollution GHEA.JF Shoreham Opponents
 Coalition 82/08/20 Atomic Safety and Licensing Board Panel
 38pp 14519 101 24X Fiche 50-322.82/08/20.8208240229,
- B208240240 Responds to ASLB B20804 inquiry re effort to integrate development of emorgency response plan w/util County has offered to cooperate w/util in environ free of contentious litigation Certificate of Svc encl SEDKY, C Suffolk County, NY, SEDKY, C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 82/08/20 Atomic Safety and Licensing Board Fanel 10pp 14520 050 24X Fiche 50-322.82/08/20, 8208240240
- 8208240243 Motion to reschedule date for filing emergancy planning Phase I testimony to 821101 or 30 days after receipt of NRC final appraisal rept Interim rept inadequate. Certificate of Svc enci SEDKY, C Suffolk County, NY SEDKY, C Kirkpatrick, Lockhart, Hill. Christopher & Phillips 82/08/20 Atomic Bafety and Licensing Board Panel. 10pp 14520 060 24X Fiche 50-322, 82/08/20.
- 8208240390 Memorandum supporting Suffolk County 820813 application for issuance of subpoena Subpoena revised & narrowed, Explanation given of failure to request subpoenaed documents during discovery Certificate of Evc encl
 DYNNER, A R Suffolk County, NY DYNNER, A R, Kirkpatrick, Lockhart, Hill, Christopher & Phillips 82/08/23 Atomic Safety and Licensing Board Panel 35pp 14524 259 24X Fiche 50-322, 82/08/23, 8208240390
- 8208250253 Rept to ASLB & statement of position on Buffolk County application for subposed dutes tecum for GA documents Util will produce documents related to topics in util written testimony Certificate of Syc enci CHRISTMAN, J.N. Long Island Lighting Co CHRISTMAN, J.N. Hunton Nilliams 82/08/23 Atomic 8afety and Licensing Board Panel, 18pp 14542 314. 24X Fichs 50-322,82/08/23,8208250253
- 8208250264 Motion to compel production of emergency planning documents from Suffolk County County has failed to produce documents within dates set by ASLB Certificate of Svc enc! MCCLESKY.E B Long Island Lighting Co MCCLESKY E.B Hunton & Williams 82/08/23 Atomic Safety and Licensing Board Penel. 28pp 14543 031 24X Fiche 50-322.82/08/23.8208250264

- 8208250300 Rept on relevant SER sections No add1 witnesses will be required Certificate of Svc encl REPKA, D A Hearing Branch 3 82/08/23 50pp 14542 239. 24X Fiche 50-322, 82/08/23, 8208250300
- 8208250349 Notice of constitution of ASLB to preside over settlement efforts re security planning issues, JA Laurenson, chairman & WH Jordan & J Harbours members, COTTER, B P Atomic Sefety and Licensing Board Panel. 82/08/24 2pp 14540 265 24X Fiche 50-322, 82/08/24, 8208250349
- 8208260044 Objections to Phase 1 consolidated emergency planning contentions Certificate of Svc encl
 BLACK.R L Hearing Branch 3 82/08/24 Atomic Safety and Licensing Board Panel 20pp 14555 206 24X Fiche 50-322, 82/08/24, 8208260044
- 8208300305 Objections to Suffalk County & Bhareham Opponents Coalition phase one consolidated emergency planning contentions. ASLB should dismiss contentions lacking adequate bases since contentions submitted three times H/Certificate of Bvc MCCLERKEY, K E Long Island Lighting Co MCCLERKEY, K E Hunton & Williams 82/08/24 Atomic Safety and Licensing Board Panel 115pp 14673 219 24X Fiche 50-322, 82/08/24.8208300305.
- 8208270382 Order directing parties to suppl responses re status of settlement of security planning issues by 820907 In camera counsel conference will be held on 820913 in Bethesda. MD. LAUERNSON. J. A. Atomic Sefety and Licensing Board Panel 82/08/25. Office of the Esecutive Legal Director 2pp 14564 237 24X Fiche 30-322.82/08/25.8208270382

H General correspondence

- 8208040660 Opposes county funding for complete independent physical insp & design review of critical safety sys & request to force util to open plant for insp Pending hearings on QA contentions.no independent physical insp will be supported EISENHUT.D O Division of Licensing 82/07/14 PROSPECT.W Suffolk County, NY 3pp. 14237-218 24X Fiche: 50-322, 82/07/14.8208040460
- --8205060412 Requests NRC order util to open doors of facility for independent insp of safety features PROSPECT.W Suffolk County, NY 82/04/26 DENTON, HR Diffice of Nuclear Reactor Regulation, Director 6pp 14237 274 24X Fiche 50-322,82/07/14.8208040660.
- --8205060422 Resolution authorizing county executive to enter into agreement for physical insp of critical safety sys at facility # 80folk County, NY 82/03/22 4pp 14237:276 24X Fiche 50-322,82/07/14,8208040660
- Q Inspection reports, IE Bulletins & correspondence
- 8208020280 Forwards IE Insp Rept 50-322/82-13 on 820511-0618 & notices of violation & deviation STAROSTECKI.R Division of Project & Resident Programs 82/07/14. POLLOCK.M 8 Long Island Lighting Co 3pp. 14131 312 24X Fichs. 50-322, 82/07/14, 8208020280
- --8208020284 Notice of violation from insp on 820511-0518 STAROSTECKI.R Division of Project & Resident Programs 82/07/14, 3pp. 14151 315 24X Fiche 50-322,82/07/14,8208020280
- --8208020286 Notice of deviation from insp on 820511-0618 ** Division of Project & Resident Programs \$2/07/14, ip. 14181 318 24% Fiche. 50-322.82/07/14.8208020280
- ---B208020273 IE Insp Rept 50-322/82-13 on 820511-0618 Noncompliance noted failure to provide indication of protective action & failure to ensure adequate test control, Pages 13-17 containing safeguards into delated.
 H1001NS.J C , HANNES.F H , BAILEY.R.J. Division of Project & Resident Programs 82/07/08 16pp 14151 319. 24X Ficha-50-322,82/07/14,8208020280
- B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDANIE L. Division of Engineering & Quality Assurance. B2/07/16, Consolidated Edison Co of New York B7pp, 14356 274 24X Fiche 50-000, 82/07/16, 8204210393.

- 8208050293 Forwards IE Safeguards Insp Rept 50-322/82-09 on 820425-29 No noncompliance noted Details of rapt withheld (ref 10CFR73 21)
 - MARTIN, T T Division of Engineering & Technical Programs 92/07/16 POLLOGK, M B Long Island Lighting Co 2pp 14210 212 24X Fiche 50-322, 82/07/16, 8208050293
- --8208050299 IE Safeguards Insp Rept 50-322/82-09 on 820425-29 No noncompliance noted Major areas inspected physical security plans security organization, records & repts: testing & maint, locks, keys & combination Details withheld (ref 10CFR73 21) BAILEY,R J. (ODY,A T. Division of Engineering & Technical Programs 82/07/16 ip 14210 214 24X Fiche 50-322.82/07/16, 8208050293
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/19 Michigan. Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Evo list encl JORDAN.E. L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Ficher 30-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-84, "Water Leaking From U Hexafluoride Overpacts" Svc list enci COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24% Fiche 50-000.82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list enc! JGRDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fichs 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 62-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24% Fiche 50-000, 82/07/23, 8204210401
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JGRDAN-E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche, 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Natice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool," Svc list encl.

 JORDAN: E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York. 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 82/04210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement " Svc list enci JORDAN,E.L. Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co. of New York 117pp 14388 201 24X Fiche. 50-000, 82/08/05, 8204210407
- 8208230125 Ack receipt of 820625 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/82-08
 STAROSTECKI.R. Division of Project & Resident Programs 82/08/07
 POLLOCKIN 5 Long Island Lighting Co 2pp 14514 355
 Fiche 50-322, 82/08/09, 8208230125.
- --6208230135 Responds to NRC 820527 ltr re violations noted in IE Insp Rept 50-322/82-08. Corrective actions Startup Instruction 2. Revision 2. approved by lead startup engineer issued 820427 & distributed onsite by 820430 POLLOCK.M 8 Long Island Lighting Co 82/06/25 STAROBTECKI,R Division of Project & Resident Programs 4p 14514 357 24X Fiche, 50-322,82/08/09,8208230125
- 8208300137 Forwards add1 relief requests for preservice insp program Relief requested from ASME Section XI exams for Class I, Category J-1 re pressure retaining welds on hasis of partial inaccessibility & required vol SMITH, J L. Long Island Lighting Co 82/08/26 DENTON, H R Office of Nuclear Reactor Regulation, Director. 16pp 14599 166 24X Fiche: 30-322, 82/08/26, 8208300137
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Fa(lures at Mestinghouse PWRs," Syc list encl. JORDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194.120 24X Fiche: 50-000, 82/07/23, 8204210402.

- S Reportable occurrances, LERs & related correspondence
- B208020337 Interim deficiency rept re apparent accelerated corrosion on reactor olds avoc water pumps mfs by Bingham-Willamette Co Initially reported on B20609 First & second stage impellers experienced corrosion & pitting MILLIGAN, M H. Long Island Lighting Co B2/07/16 HAYNES, R C Region 1, Office of Director 3pp 14151 143 24X Fiche 50-322, 82/07/16, 8208020337
- 8208050348 Final deficiency rept re NFP-25 indented control cable mfg by Rockbestos Co Initially reported on 810514 Cable samples straightened & recoiled on metal cable reel MILLIOAN;M H Long Island Lighting Co 82/07/22 HAYNES,R C Region 1, Office of Director 5pp 14219 328 24X Fiche 50-322;82/07/22,8208050348
- 8208050\$11 Deficiency rept re water hammer loads affecting control red drive sys Initially reported on Bill30 In-plant test of parameters performed. Support mods will be complete prior to fuel load Investigation continuing MILLIOAN.M H Long Island Lighting Co 82/07/23 HAYNES,R C Region 1, Office of Director 3pp 14214 100 24X Fiche 50-322,82/07/23,8208050511
- 8208050425 PNO-I-B2-055 on 820727, Teamsters Union personnel demonstrated at facility access road to protest delivery of new fuel Maint personnel transported fuel to reactor bidg Intervenor press conference & demonstration planned HIGGINS, J., WIGGINS, J., BRUNNER, E. Region 1, Office of Director. 82/07/27 ip 14214-075 24X Fiche, 50-322, 82/07/27, 8208050425
- T Hearing transcripts on non-antitrust matters
- 8208020345 Transcript of 820729 hearing in Riverhead NY Pp 8,320-8,513 * Atomic Safety and Licensing Board Panel 82/07/29 248pp 14146 205 24X Fiche 50-322,82/07/29,8208020345
- B208030199 Transcript of 820730 hearing in Riverhead NY Pp 8,514-8.686 * Long Island Lighting Co 82/07/30 200pp 14159 065 24X Ficher 50-322, 82/07/30, 8208030199
- 8208050302 Transcript of 820803 hearing in Riverhead, NY, Pp 8,687-8,892 Supporting documentation enc! * Atomic Safety and Licensing Board Panel 82/08/03 313pp 14210 217. 24% Fiche 50-322,82/08/03,8208050302
- 8208060144 Transcript of 820804 hearing in Riverhead.NY Pp 8.893-9.133 * Atomic Bafety and Licensing Board Panel. 82/08/04 330pp 14240-122 24X Fiche 50-322.82/08/04.8208060144
- 8208090058 Transcript of 820805 hearing in Riverhead.NY Pp 9,134-9,302 * Atomic Bafety and Licensing Board Panel 62/08/05 170pp 14269 001 24X Fiche 50-322,82/08/05,8208090058
- B20B110062 Testimony of CE Rossi & JL Mauck on Suffolk County
 Contention 27 & Shorsham Opponents Coalition Contention 3
 re instrumentation for post-accident monitoring Compliance
 w/Reg Ouide 1 97 not yet determined Certificate of Syc encl
 ROSBI.C E., MAUCK, J L. Instrumentation & Control Systems Branch
 82/08/10 56pp. 14317 116 24X Fiche.50-322,82/08/10,820B110062
- 8208260242 Transcript of 820824 hearing in Hauppauge, NY Pp 9,303-9,498. Supporting documentation encl.

 * Atomic Bafety and Licensing Board Panel 82/08/24, 250pp 14552 001. 24% Fiche 30-322-82/08/24, 8208260242
- 8208270385 Transcript of 820825 hearing in Hauppauge, NY Pp 9,499-9,707. Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/08/25 225pp 14547 062. 24X Fiche 50-322.82/08/25,8208270385
- 8208300031 Transcript of 820826 hearing in Hauppauge, NY Pp 9.708-9.926 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/08/26 375pp 14997 187 24% Fichs 30-322,82/08/26,8208300031
- 8208310284 Transcript of 820827 hearing in Hauppauge, NY Pg 9.927-10.036 Supporting documentation encl # Atomic Sefety and Licensing Board Panel 82/08/27 150pp. 14691-284 24x Fiche 50-322-82/08/27.8208310284.

- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8207070414 Forwards amended Order 82-24, "Waste Discharge Requirements for PO&E. Diablo Canyon Power Plant, Units 1 & 2, San Luis Obispo County" & "Order 82-54 Amending NPDES Permit CA0003751, Waste Discharge Requirements ." adopted 820611 JONES, K R Dept of Water Resources, California, State of, 82/06/30 MCKENZIE, J F Pacific Gas & Electric Co 30pp 13739 088 24X Fiche 50-275, 82/06/30, 8207070414
- 8208040532 Responds to 820615 ltr re concerns over amount of radiation & increase of tritium proposed for release into Pacific Ocean Required design measures taken to process contaminated liquid effluents to minimize release DENITON, HR Office of Nuclear Reactor Regulation, Director 82/07/21 JONES, KR California, State of 23pp 14223 241 24x Fiche 50-275, 82/07/21.8208040532
- --8206200027 Forwards CA Regional Water Quality Control Board 820119 & 0218 ltrs voicing concerns re increase in tritium over background levels & amount of radiation to be released to Pacific Ocean JONEB.K R California, State of 82/06/15 PALLADINO, N J., AHEARNE, J., OLILNBKY, V Commissioners ip. 14223-264 24% Fiche 50-275,82/07/21,8208040532
- B20B170010 B0CIOECONOMIC IMPACTS OF NUCLEAR GENERATINO BTATIONS.DIABLO CANYON CASE STUDY Docket No 50-323, (Pacific Gas And Electric Company)
 PIJANKA, K D. YAGUINTO, O Mountain Heat Research, Inc # Bocial Impact Research, Inc. FIN B-6268 NUREG/CR-2749 VOS. 62/07/31 Division of Health, Siting & Environment 213pp Available at NTIS. \$7 00 14374.106 24X Fiche.50-323,82/07/31.8208170010.
- 8208050338 Comments on Teledyne Engineering Svcs 820618 Phase II
 Program Mgt Plan, per Commission invitation Commission should
 require listed specific changes to audit program
 REYNOLDS, JR Center for Law in the Public Interest, FLEIBCHAKER, D
 Joint Intervenors-Diable Canyon 82/08/02, PALLADINO, N J,
 ROBERTS, T F, ASSELSTINE, J K Commissioners Dpp 14219 344 24X
 Fiche 50-275, 82/08/02, 8208050338
- 8208190388 Forwards request for addl info re GA program Info should be in form of marked revisions to GA program GA program approved contingent upon submittal of requested revisions. W/O encl EISENHUT,D G, Division of Licensing 82/08/02, CRANE,P,A, Pacific Oas & Electric Co ip 14506-097 24X Fiche 50-275,82/08/02,8208190388
- B20B090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re-submittal of documents to NRC Bummarizes IOCFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
 EISENHUT, D 0 Division of Licensing B2/08/09 Consolidated Edison Co. of New York 1p 14356 332. 24X Fiche 50-000:82/08/09, B208090194
- 8208130260 Forwards application to amend CPPR-69, extending const completion date to 820930 CRANE, P A Pacific Gas & Electric Co. 82/08/09 MIRAQLIA, F J Licensing Branch 3 1p 14333:146 24X Fiche:50-323,82/08/09,8208130260.
- --8208130261 Application to amend CPPR-69.extending const completion date to 820930 SCHUYLER, J. D. CRANE, P. A. Pacific Qas & Electric Co. 82/08/09 ip 14333 147 24X Fiche. 50-323, 82/08/09, 8208130260,
- 8208260613 Forwards request for add1 info re analysis of containment annulus structure, as agreed in 820727 meeting at BNL.
 MIRAOLIA.F J Licensing Branch 3 82/08/11. REICH, M. Brookhaven
 National Laboratory 3pp 14567-357 24X Fiche-50-275,82/08/11.
 8208260613.
- 8208170161 Forwards addI info re QA program in response to NRC 820802 request Encl consists of statements providing clarifications & revisions to 820618 submittal Changes to submittal modify scope of QA program CRANE.P.A Pacific Gas & Electric Co. 82/08/13, MIRAGLIA,F J Licensing Branch 3 20pp 14364 294, 24X Fichs: 50-275, 82/08/13, 8208170161.
- 8208230336 Informs that no fixed implementation date for requirements of Milestone 7 to NUREO-0737. Item III.A. 2.2 re description of Class B model.can be set until NRC clarifies meteorological & modeling sys requirements CRANE.P.A Pacific Qas & Electric Co. 82/08/16. MIRAQLIA.F.J. Licensing Branch 3. 2pp. 14508.326. 24X Fiche 50-275.82/08/16.8208230336.

- 8208250202 Forwards preliminary outline developed for final rapt Phase I of design varification program Description of scope, criteria & methodology for certain corrective action program elements will be submitted by 820901 CRANE.P A Pacific Gas & Electric Co 82/08/20 EISENHUT.D.G Division of Licensing 17pp. 14541-340 24% Fiche-50-275.82/08/20, 8208250202
- 8208310144 Advises that panel mounted instruments required for safe shutdown were replaced w/instruments qualified to operate submarged.per util 790914 & 1228 evaluations Design change initiated dealant requirements removed CRANE.P A Pacific Oas & Electric Co 82/08/26, MIRAOLIA.F J Licensing Branch 3 1p 14693 179. 24X Fiche: 50-275,82/08/26,8208310144
- F Security, medical, emergency & fire protection plans
- 8208310105 Forwards IE Emergency Preparedness Appraisal Repts 50-275/81-33 & 50-323/81-19 on 811207-17. ENGELKEN.R H Region 5. Office of Director. 82/07/08 CRANE,P A Pacific 0ss & Electric Co 2pp 14689 319 24X Fiche 50-275,82/07/08.8208310105
- --B20B310113 IE Emergency Preparedness Appraisal Repts 50-275/81-33 & 30-323/Bi-19 on B11207-17. Deficiencies noted equipment: smergency plan implementing procedures & coordination w/offsite groups.
 FISH:R.F Region 5: Office of Director B2/07/07 51pp 14690:001 24X Fichs 50-275, 82/07/08, 8208310105
- 9208040527 Approves changes to physical security plan w/exception of items listed in encl.in response to 820527 ltr Revised pages to plan requested within 45 days of receipt of ltr MIRAOLIA.F. J Licensing Branch 3. 82/07/30 CRANE.P Pacific Gas & Electric Co 2pp 14220/344 24X Fiche 50-275,82/07/30,82/00/0527.
- 8208110266 Releases public version of emergency plan implementing procedures.
 FELTON J M Division of Rules and Records. 82/08/05. Document Management Brench ip 14331 151. 24X Fiche 50-275, 82/08/05, 82/08/1026
- --8208110269 Forwards public version of Vols 3A & 3B of emergency plan implementing procedures, including Procedures EP GP-14 rehigh activity in RCB, OP-23 renatural circulation of reactor coolant & EP R-1 re employes injury (radiological) OOLEBBY, D A Pacific Oas & Electric Co. 82/07/29. ENGELKEN, R. H. Region 5, Office of Director. 4pp. 14331 152, 24X Fiche. 50-275, 82/08/05, 8208110266.
- --8208110275 Public version of Vols 3A & 38 of emergency plan implementing procedures, including Procedures EP DP-14 rehigh activity in RCB-0P-23 rehastural circulation of reactor coolant & EP R-1 reemployee injury (radiological) # Pacific Oas & Electric Co. 82/06/11. 150pp 14331:156. R4X Fiche:50-275.82/08/05.8208110266
- 8208230017 Forwards Attachments A & 8 re changes implemented to Revision II of security plan. Attachment A identifies & describes changes & 8 consists of replacement pages Encls withheld (ref 100FR73 21).

 CRANE.P.A Pacific Oas & Electric Co. 82/08/12 DENTON, H. R. Office of Nuclear Resultor Regulation, Director. 1p. 14517:228 24X Ficher 50-275, 82/08/12, 8208230019.
- Q Adjudicatory correspondence
- 8205300352 Order CLI-B2-7 deciding that definition of "several" does not warrant Commission review in context of proceeding. Commission will re-evaluate design basis threat generically. CHILK: 8 J Office of the Secretary of the Commission. 82/04/22. Commissioners. 4pp 14380-111. 24X Fiche 50-275.82/04/22. 8206300352
- 8208020317 Order directing all copies of Order ALAB-653 be returned since order contains classified natl security info.NRC will direct parties to return parts of underlying record which contains such info.

 CHILK.B. J. Office of the Secretary of the Commission. 82/07/29.

 Commissioners. 2pp. 14151.150. 24X Fiche 50-275,82/07/29.

 8208020317.
- 8208030275 Order CLI-82-17 releasing public versions of ALAB-653 & Governor Brown 811013 petition for review of ALAB-653. Meaning of "several" as used in design basis threat of IOCFR73, I(a)(i) is safeguards info HOYLE, J C Office of the Secretary of the Commission, 82/07/30, 2sp. 14155-356, 24X Fichs.50-275,82/07/30,8208030275,

- --8208030280 Public version of patition for review of ALAB-653 Decision is of first impression re meaning of Part 73 in contested proceeding & raises important & critical questions of law, fact & policy, H/Certificate of Svc BROWN, H H California: State of BROWN, H H Hill, Christopher & Phillips Bi/10/13 Commissioners 13pp 14156 161 24X Fiche 50-275,82/07/30,8208030275
- 8208050338 Comments on Teledyne Engineering Svcs 820618 Phase II Program Mgt Plan, per Commission invitation Commission should require listed specific changes to audit program REYNOLDS, JR. FLEISCHAKER, D. Center for Law in the Public Interest REYNOLDS, JR. Joint Intervenors-Diablo Canyon 82/08/02 PALLADINO, N J. OILINSKY, V. AHEARRS, J. Commissioners 5pp 14219 344 24X Fiche 50-275,82/08/02,8208050338
- 8208050538 Motion to reopen proceeding to take evidence on GA ABLB does not have info re implementation of GA program
 Certificate of Svc enci
 BROWN-M H. California: State of BROWN-H H Kirkpatrick, Lockhart,
 Hill, Christopher & Phillips 82/08/02 Atomic Bafety and
 Licensing Board Penel 13pp 14213 288 24x Fiche 50-275,82/08/02,8208050538
- 8208110148 Order granting extension until 820831 to comment on effect of expunction of classified matl from ALAB-653 & underlying record CHILK.S J Office of the Secretary of the Commission 82/08/09 California, State of 19 14314 294 24X Fiche 50-275,82/08/09,820810148
- 820Bi90l39 Response opposing Oovernor Brown 820B02 motion to reopen record to take evidence on QA Commission Billi9 action leaves ABLB w/o jurisdiction to grant requested relief Certificate of Bvc encl NORTON.B Pacific Q
- --8208190142 Affigavit of HB Friend re independent design verification program Prof qualifications encl FRIEND, H B Pacific Qas & Electric Co 82/08/13 8pp 14382:215 24X Fichs 50-275.82/08/16.8208190199.
- 8208200230 Request for hearing on util 820803 application for amend to License DPR-76, which would renew low power license granted on 810921 & suspended on 811117 Centificate of Svc encl REYNOLDS, J R Joint Intervenors-Diablo Canyon REYNOLDS, J R Center for Law in the Public Interest 82/08/17 Commissioners 14pp 14399 316 24X Fiche 50-275,82/08/17,8208200250
- 8208200262 Response supporting Governor Brown 820802 motion to reopen proceeding to take evidence on GA Gutdated & obviously erroneous findings re GA & seismic design should not stand Cartificate of Svc encl REYNOLDS, J R Joint Intervenors-Diablo Canyon REYNOLDS, J R Center for Law in the Public Interest \$2708/17 Atomic Bafety and Licensing Board Panel 7pp 14378 327 24X Fichs 50-275.82708/17.8208200262.
- 8208250241 Response apposing Covernor Brown 820802 motion to reapen proceeding to take evidence on GA. Reopened hearing would serve no useful purpose Certificate of Svc enc1
 HABSELL.D. F Hearing Branch 1 82/08/23 Atomic Bafety and Licensing Board Panel 17pp 14542 332 24X Fiche 50-275, 82/08/23, 8208250241.
- B20B250356 Order extending time until B20914 for Commission to consider whether to review ALAB-6B1.
 CHILK, B. J. Office of the Borretary of the Commission B2/0B/24, Commissioners ip. 14540 209, 24X Fiche 50-275, B2/0B/24, B20B250356
- 8208310077 Errata to NRC 820823 response to Governor Brown motion to reapen proceeding to take evidence on GA Certificate of Svc anci.
 HASSELL, D.F. Hearing Branch 1, 82/08/27 Atomic Safety and Licensing Board Penel 3pp 14695 146 24X Fiche, 50-275, 82/08/27, 8208310077.
- M. Antitrust correspondence
- 8208180018 Discusses PO&E refusal to allow interconnection of Northern CA Power Agency geyser units w/Diablo Canyon units for testing purposes except under provisions in violation of license conditions.

 MCDIARMID,R C. Spiegel, O MCDIARMID,R C. Northern California.

 Power Agency, California-State of, 82/09/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 14377:188 24% Fiche 50-275,82/08/13,8208180019

- Q Inspection reports, IE Bulletins & correspondence
- 8208310105 Forwards IE Emergency Preparedness Appraisal Repts 50-275/81-33 & 50-323/81-19 on 811207-17 ENGELKEN,R H Region 5. Office of Director 82/07/08 CRANE,P A Pacific Qas & Electric Co 2pp 14589 319 24X Fiche 50-275,82/07/08,8208310105
- --8208310113 IE Emergency Preparedness Appraisal Repts 50-275/81-33 \$ 50-323/81-17 on 811207-17, Deficiencies noted equipment, emergency plan implementing procedures & coordination w/offsite groups
 FISH.R F , 8COWN.K Region 5, Office of Director 82/07/07 51pp 14687 325 24X Fichs 50-275,82/07/08,8208310105
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/1. Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Hater Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000,82/07/20.8204210397
- 8204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance. B2/07/22, Consolidated Edison Co of New York 112pp 14194 321 24X Fiche.50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Mydrogen Explosion While Granding in Vicinity of Drained & Open RCB " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23.8204210401
- 820A210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JURDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York. 127pp 14194-120 24X Fichs 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance Consolidated Edison Co of New York 121pp 14357 013 24X Fichs. 50-000. 82/07/26, 8204210403
- 8208160128 Forwards IE Insp Repts 50-275/82-22 & 50-323/82-11 on 820526-28 & 0628-0702 No noncompliance noted BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 86/07/27 CRANE, PA Pacific Qas & Electric Co 4pp 14345 185 24X Fichs 50-275,82/07/27,8208160128
- --8208160127 IE Insp Repts 50-275/82-22 & 50-323/82-11 on 820526-28 & 0628-0702 No noncompliance noted Major areas inspected; action on previous items, mods to piping & electrical raceway supports & Unit 2 vessel
 BURDOIN, J.F., ECKHARDT, J.H. Division of Resident, Reactor Project & Engineering Programs. 82/07/26 8pp 14345-187 24% Fiche 50-275,82/07/27,8208160128.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storags Pool " Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York, 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405.
- 8208040305 IE Insp Repts 50-275/82-12 & 50-323/82-07 heve been canceled BEIERLE, C Region 5, Office of Director, 82/07/28 ip 14183 087 24% Fiche 50-275,82/07/28,8208040305
- 8208160466 Forwards IE Insp Repts 50-275/82-23 & 50-323/82-12 on 820721-23 No noncompliance noted 800K.H E Division of Radiological Safety & Safeguards Program 82/07/30 CRAMS.P.A Pacific Qas & Electric Co. 4pp. 14348-220 24X Fiche: 50-275,82/07/30.8208160466

- --8208160475 IE Insp Repts 50-275/82-23 & 50-323/82-12 on 820721-23 No noncompliance noted Major areas inspected followup on IE circulars, info notices & bulletins, preoperational testing & monitoring calibr NORTH/H S. WENBLAWSKI,F A. BOOK/H E. Division of Radiological Safety & Safeguards Program 82/07/30 App 14348 224 24X Fiche 50-275, 82/07/30, 8208160464
- B20816017B Responds to Action Item G of IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " No incidents of leakage in bolted closures evident Maint procedures specify FEL-PRO-N-500 per Westinghouse 1tr SCHUYLER. J O Pacific Gas & Electric Co B2/08/02 ENGELKEN, R H Region 9, Office of Director 3pp 14345 051 24% Fiche 50-275, 82/08/02, 820816017B
- 8204210407 IE 1nfo Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JURDAN, E. L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201, 24X Fiche 50-000.82/08/05.8204210407
- 8 Reportable occurrences, LERs & related correspondence
- 8208060030 Forwards incident reporting sys repts re effects of fire protection sys actuation on safety-related equipment & seismic qualification of safety-related sys for transmission to NEA MICHELSON. C Director's Office 82/07/29 LAFLEUR, J D Office of International Programs, Director 21pp 14244 315 24X Fiche 30-000, 82/07/29, 8208060030
- DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 820B10026B Forwards IE Safeguards Insp Rept 50-324/B2-29 on 820603-04 & O720-21 No noncompliance noted Details withheld (ref 10CFR73 21)
 VERRELLI, D Division of Project & Resident Programs 82/08/05, JONES, J A Carolina Power & Light Co 2pp 14295 360 24X Fiche 50-324, 82/08/05. 820B10026B
- --B20B100274 IE Bafeguards Insp Rept 50-324/B2-29 on 820603-04 & 0720-21
 No noncompliance noted Major areas inspected access control
 to vital areas security plan & procedures & security force
 documentation Details withheld (ref 100FR73 2)
 MCOUIRE, D R , TILLMAN. A , PERNY, C Division of Engineering &
 Technical Programs B2/08/04 ip 14295-362 24X
 Fichs 50-324,82/08/05.8208100268.
- 8208260110 Relwases public version of NUS rept "Radiation Shielding Analysis for Brunswick Technical Support Ctr/Emergency Operating Facility "
 FELTON. JM Division of Rules and Records 62/09/11 Document Management Branch ip 14576 131 24X Fiche, 50-324, 82/08/11, 8208260110
- --8208260114 Forwards public version of NVB rept "Rediation Shielding Analysis for Brunswick Technical Support Ctr/Emergency Operating Facility "
 ZIMMERMAN, 8 & Consumers Power Co B2/08/04 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 14576-132 24X Fiche 50-324,82/08/11.8208260110
- --8208260350 Public version of "Radiation Shielding Analysis Brunswick Technical Support Ctr/Emergency Operating Facility " BRODE, R. W. NATHAN, 8 J. NUB Carp NUB-4148 82/06/30, 62pp 14576 134 24X Fiche 50-324,82/08/11,8208260110
- J Insurance & indemnity information
- 8208310240 Application for amend to Peragraph 2 A of License DPR-62 & DPR-71:reflecting Board of Commissioners Bli216 act whereby name of NC Municipal Power Agency Number 3 was changed to NC Eastern Municipal Fower Agency JONES, J A Carolina Power & Light Co 82/08/25, DENTON, H. R. Office of Nuclear Reactor Regulation. Director 3pp 14688: 147 24X Fiche 50-324.82/08/25, 8208310260
- --B208310283 Forwards unexecuted Amend 11 to Idemnity Agreement B-71, adding NC Municipal Power Agency Number 3 to agreement BALTZMANJ Assistant Director for State & Licensee Relations. B2/05/18 JONES. J A. Carolina Power & Light Co. 2PF. 14688-15(24X Fiche 50-324, B2/08/25, B208310260

- P Operating license stage documents & correspondence
- 8206070829 Application for amend to Licenses DPR-71 & DPR-62, revising Tech Specs to allow unit operation up to 50% of rated thermal power w/one recirculation loop out of svc Class I & III amend fees enci HOWE, P W Cerolina Power & Light Co 82/06/03 VA88ALLD, D B. Operating Reactors Branch 2 2pp 13387 209, 24% Fiche 50-324,82/06/03,8206070829
- ---B206070B6B "Brunswick Steam Electric Plant Units 1 & 2 Single-Loop Operation " * Oeneral Electric Co NEDO-24344 B1/09/30, 32pp. 13387:236 24X Fichs: 50-324,82/06/03,8206070829
- 8208030690 Transmits authorization for add1 license conditions extending deadlines for surveillance requirements as requested on 820701 Amend clauses encl NOVAK,T M Assistant Director for Operating Reactors 82/07/01, JONES,J A Carolina Power & Light Co 3pp 14194 316 24X Fiche 50-324,82/07/01,8208030690
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list encl DIRCKS, H J Offics of the Executive Director for Operations, 82/07/02 Consolidated Edison Co. of New York 73pp. 14194.001, 24X Fiche 50-000,82/07/02,8207080064
- 8208030693 Requests assistance in conducting electromagnetic interference measurement program Data base will be used to assess vulnerability of proposed or existing designs due to event involving electromagnetic interference VASSALLO,D B Operating Reactors Branch 2, 82/07/02 JONES,J. A Carolina Power & Light Co 5pp. 14176 311. 24X Fiche 50-324,82/07/02,8208030693.
- B20B030072 Confirms 820703 teleon authorization for add1 CL conditiona Licenses DPR-71 & DPR-62 amended as of B20703 by adding encl clauses re operability of electric sources NGVAK.T.M. Assistant Director for Operating Reactors 82/07/06. JUNKB.J A Carolina Power & Light Co. Spp. 14200 311. 24X Fiche. 50-324.82/07/06.820B030072
- 8208160166 Confirms 820716 & 19 telcons & 820720 meeting agreements relisted corrective actions to be performed to conform w/Tech Spec surveillance test requirements Long-term actions to be discussed w/NRC by 820730.

 O'REILLY, J P Region 2: Office of Director 82/07/20 JONES, J A Carolina Power & Light Co 2pp 14345 121 24%

 Fiche 50-324, 82/07/20, 8208160166
- 820B110201 Forwards revised version of reactor protection sys/power monitoring sys design model Tech Space. Space less restrictive in some requirements than earlier version VASSALLO, D. B. Operating Reactors Branch 2, 82/07/28, JONES, J. A Carolina Power & Light Co. 2pp. 1432B 357 24X Fiche 50-324, 82/07/28, 820B110201.
- --8208110202 Model Tech Specs re reactor protection sys/power monitoring sys design * NRC - No Detailed Affiliation Given 82/07/28, 1p, 14328 359, 24X Fiche 50-324,82/07/28,8208110201.
- 8208120345 Informs that proposed method for implementing NUREO-0737, Item II K 3 15, "Isolation of MPCI & Reactor Cors Isolation Cooling," acceptable VASBALLO, D B Operating Reactors Branch 2 82/07/28 JONES, J. A Carolina Power & Light Co 3pp. 14340.075, 24% Fiche: 50-324, 82/07/28, 8208120345
- 8208020318 Application to amend Licenses DPR-71 & DPR-62 Tech Specs, reflecting change in ECCS actuation instrumentation setpoints & concomitant surveil lance requirements Change request involves single technical issue HOME.P W Carolina Power & Light Co 82/07/29 VASSALLO.D B. Operating Reactors Branch 2. 2pp. 14:51.115 24% Fiche: 50-024, 82/07/29, 8208020318
- --B208020325 Proposed Tech Spacs to ECCS actuation instrumentation setpoints & concomitant surveillance requirements.

 * Caroline Power & Light Co. 82/07/29 opp. 14151:117 24X Fichs. 50-324. B2/07/29, 8208020318.
- 8208030309 Agrees to host LLL representatives to conduct electromagnatic interference measurement program at facility ZIMMERNAN.S R. Carolina Power & Light Co. 82/07/29. VABSALLO, D. B. Operating Reactors Branch 2. ip. 14157:146. 24X Fiche 50-324, 82/07/29, 8208030309.

- 8208100195 Forwards addi info requested in 820226 ltr re detector in-situ calibr, per TMI Item II F I In-situ source calibr unnecessary based on electronic check source function built into containment high range monitor sys ZIMMERMAN, S R Carolina Power & Light Co 82/08/04 VASSALLO, D B Operating Reactors Branch 2 2pp 14278 194 24X Fiche 30-324, 82/08/04, 8208100195
- 8208250002 Requests verfication of satisfaction of encl criteria re NUREG-0737. Item II K 3 22, "Automatic Switchover of Reactor Core Isolation Cooling Sys Buction "Response requested within 30 days VASSALLO,D B Operating Reactors Branch 2 82/08/05 JONES,J A Carolina Power & Light Co 4pp 14957 226 24X Fiche 50-324, 82/08/05, 8208250002
- 8208260367 Forwards Amends 48 & 72 to Licenses DPR-71 & DPR-62, respectively, safety evaluation & notice of issuance & availability Amends change Tach Specs to provide surveillance requirements for scram discharge valves VASSALLO,D B Operating Reactors Branch 2 82/08/05 JONES,J A Carolina Power & Light Co 2pp 14594 182 24X Fiche 50-324, 82/08/05,8208260367
- --8208260380 Amends 48 & 72 to Licenses DPR-71 & DPR-62, respectively, providing surveillance requirements for scram discharge volvent & drain valves & limiting conditions for operation for scram discharge vol limit switches VASSALLO, D B Operating Reactors Branch 2 82/08/05 20pp 14594 184 24X Fiche 50-324, 82/08/05, 8208260367
- --8208260393 Bafety evaluation supporting Amends 48 & 72 to Licenses DPR-71 & DPR-62, respectively ECCLESTON, K T Office of Nuclear Reactor Regulation, Director 82/08/05 2pp 14594 204 24X Fiche 50-324, 82/08/05, 8208260367
- --B208260410 Notice of issuance & availability of Amends 48 & 72 to Licenses DPR-71 & DPR-62, respectively ROONEY, V L. Operating Reactors Branch 2 B2/08/05 2pp 14574 206 24% Fiche 50-324, B2/08/05, B208260367
 - Bi60078 Comments on B20720 meeting re util comments on systematic issessment of licensee performance & status of missed reveillance test issue Meeting beneficial & provided reter understanding of util position

 (REILLY, JP Region 2. Office of Director B2/08/06 JUNES, JA irolina Power & Light Co ip 14342 131 24X iche 50-324, 82/08/06, 8208160078
- OBO90194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl EISENNUT.D O Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fichs 50-000,82/08/09,8208090194
- 8208190384 Requests documentation indicating how each criterion of NUREG-0737. Item II B 3 re post-accident sampling satisfied Schedule requested within 20 days of receipt of ltr VASSALLO. D B Operating Reactors Branch 2 82/08/09 JONES, J A Carolina Power & Light Co 10pp 14504 156 24X Fiche 50-324,82/08/09,8208190384
- 20B190312 Application for amend to Licenses DPR-71 & DPR-62 re reactor protection sys motor generator sets Changes supersede 820324 Tech Spec change request UTLEY. E E Carolina Power & Light Co 82/08/16 VASSALLO, D B Operating Reactors Branch 2 2pp 14397 135 24X Fiche, 30-324, 82/08/16, 8208190312
- 8208190313 Proposed Tech Spec changes providing time delay settings for reactor protection sys motor generator sets a Carolina Power & Light Co. 82/08/16, 4pp 14387 137 24X Fiche 50-324,82/08/16,8208190312
- OB240403 Confirms talcon w/JA Van Vliet re NUREQ-0737. Item II K 3 24, "Space Cooling for HPC1/Reactor Core Isolation Cooling Sys "Electrical power sys for all ECCS room coolers supplied by station emergency buses
 IIMMERMAN. 8 R Carolina Power & Light Co 62/08/19 VASSALLO. D B Operating Reactors Branch 2 is 14522-294 24X
 Fiche 50-324, 82/08/19, 8208240403
- 9208310260 Application for amend to Paragraph 2 A of License DPR-62 & DPR-71, reflecting Board of Commissioners 81:216 act whereby name of NC Municipal Power Agency Number 3 was changed to NC Eastern Municipal Power Agency JONES, J A Carolina Fower & Light Co 82/08/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 14688 147 24% Ficha 50-324, 82/08/25, 8208310240.

- --B20B3102B3 Forwards unexecuted Amend II to Idemnity Agreement B-71, adding NC Municipal Power Agency Number 3 to agreement BALTZMAN. J Assistant Director for State & Liconsee Relations B2/05/18 JUNES, JA Carolina Power & Light Co 2PP 146BB 15824X Ficher 50-324.82/08/25.820B310260
- Q Inspection reports. IE Bulletins & correspondence
- 8208i60517 Confirms 820628 telcon re 820714 enforcement meeting in Atlanta. 0A to review results of investigations of areas outlined in 820408 confirmation of action Itr Proposed agenda anci
 O'REILLY, J P Region 2, Office of Director 82/07/08 JONES, J A Carolina Power & Light Co 2pp 14348 080 24X
 Fiche 50-324, 82/07/08, 8208160517
- 8208030180 Forwards IE Insp Repts 50-324/82-24 & 50-325/82-24 on 820515-0615 No noncompliance noted LONG. F Division of Project & Resident Programs 82/07/13 JONES, J A Carolina Power & Light Co 2pp 14160 175 24X Fiche 50-324, 82/07/13, 8208030180
- --8208030182 IE Insp Repts 50-324/62-24 & 50-325/82-24 on 820515-0615 No noncompliance noted Major areas inspected review of LERs, maint activities, surveillance activities, operational safety verification & independent insp effort MYERS, D.O. GARNER, L. W. DURGER, C. W. Division of Project & Resident Programs 82/07/09 10pp 14160 177 24X Fichs 50-324,82/07/13,8208030180
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3. Buppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Byc list encl JORDAN. E.L. Division of Engineering & Quality Assurance 82/07/19 Hichigan. Univ of 112pp 14358.001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-28, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001, 24X Fiche 30-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Mater Leaking From U Hexafluoride Overpacks" Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357;276 24X Fiche 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-26, "RGIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl, JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York, 112pp 14194 321 24X Ficha 30-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28. "Hydragen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche, 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl. JORDAN,E L Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York 127pp. 14174 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/26 Consolidate Edison Co of New York 121pp. 14357 013 24X Fiche 50-000, 82/07/26, 8204210403.
- 8208160320 Provides supplemental response to IE Bulletins 79-02,79-07 & 79-14,per Bi0225 commitment Upon completion of long-term fixes discussed previously,pipe stress analysis summary tables will be updated to reflect completion of field mods DIETZ,CR Carolina Power & Light Co B2/07/26. 0'REILLY,J P Region 2, Office of Director, 5pp 14048-039 24X Fiche 50-324,82/07/26.8208160320
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp. 14357.146, 24X Fichs 50-000, 82/07/28, 8204210405.

- 8208160184 Suppls 801003 response to IE Bulletins 79-07, "Algebraic Summation Problem." & 79-14, "Seismic Analysis for As-Built Safety-Related Piping " Control rod drive insert & withdraw line clamps deficient Support problem corrected DIETZ, C R Carolina Power & Light Co 82/07/29 D'REILLY, J P Region 2, Office of Director 4pp 14345 059 24X Fiche 50-324, 82/07/29, 8208160184
- 820B180210 Forwards request for add1 info re response to IE Bulletin 80-11, "Masonry Wall Design " Response due in 45 days VASSALLO.D B Operating Reactors Branch 2 82/08/02 JDNES, J A Carolina Power & Light Co 4pp 14390 356 24X Fiche 50-324, 82/08/02, 8208180210
- 8208160133 Forwards IE Enforcement Meeting Repts 50-324/82-27 & 30-325/82-27 on 820714 O'REILLY, J P Region 2, Office of Director 82/08/04 JONES, J A Carolina Power & Light Co 1p 14345 252 24X Fiche 50-324,82/08/04,8208160133
- --8208160134 IE Enforcement Meeting Repts 50-324/82-27 & 50-325/82-27 on 820714 Major areas discussed, proposed corrective actions re 820321 & 25 events involving mispositioned breaker & valves LEMIS, R C Division of Project & Resident Programs, 82/08/03 2pp 14345 253 24X Fiche 50-324, 82/08/04,8208160133
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/08/05, Consolidated Edison Co of New York 117pg 14368 201 24X Fiche 50-000,82/08/05,8204210407
- 8208100268 Forwards IE Safeguards Insp Rept 50-324/82-29 on 820603-04 & 0720-21 No noncompliance noted Details withheld (ref 100FR73 21).

 VERRELLI, D Division of Project & Resident Programs 82/08/05 JONES, J A Carolina Power & Light Co 2pp 14295 380 24X Fichs 50-324,82/08/05,8208100268
- --B208100274 IE Bafeguards Insp Rept 50-324/B2-29 on B20603-04 & 0720-21.

 No noncompliance noted Major areas inspected access control to vital areas, security plan & procedures & security force documentation Details withheld (ref 10CFR73 21).

 MCGUIRE, D. R. TILLMAN, A. PERNY, C Division of Engineering & Technical Programs 62/06/04 ip 14295-362, 24x

 Fichs 50-324, 82/08/05, 8208100268
- 8208250207 Responds to NRC 820716 ltr re notice of violation & imposition of civil penalties, Corrective actions control operator & auxiliary operator daily surveillance repts have been reviewed & revised UTLEY, E E Carolina Power & Light Co 82/08/16 DEYQUNO, R C, Director's Office, Office of Inspection and Enforcement 9pp 14541 331 24X Fiche 50-324, 82/08/16, 8208250207

R Periodic operating reports & related correspondence

- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A. FELTON. J M Division of Rules and Records 82/07/13, UDELL.R.A. Critical Mass Energy Project 8pp 14679, 208, 24X Fiche 50-000, 82/07/13, 8208270010.
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY91"
 • NRC - No Detailed Affiliation Civen 82/07/13 48pp. 14679 216 24% Fiche 50-000, 82/07/13, 8208270010
- --8208270219 Forwards annual personnel & man-rem exposure by work & job function for CYB1
 DIETZ.C.R Caroline Power & Light Co B2/02/04 O'REILLY, J P Region 2. Office of Director 2pp 14679 284 24X
 Fiche. 50-000, 82/07/13, 8208270010
- --8208270225 Annual personnel & man-rem exposure by work & job function for CY81

 * Carolina Power & Light Co. 81/01/21, 1p. 14679.286 24X

 Fiche 50-000,82/07/13,8208270010
- --8208270229 Forwards statistical radiation exposure summary rept for CYBI, per 10CFR20, 407
 DIETZ, C.R. Cerolina Power & Light Co. 82/02/04, HALLER, N. M. Office of Management and Program Analysis, 1p. 14679;287 24X Fiche
- --8208270233 Statistical radiation exposure summary rept for CYB1

 4 Caroline Power & Light Co. 82/02/04 App. 14679, 288. 24X
 Fiche 50-000, 82/07/13, 8208270010

- 820B120015 Forwards monthly operating repts for Jul 1982 DIETZ.C R Carolina Power & Light Co. 82/08/04 DEVOUNG.R C Director's Office. Office of Inspection and Enforcement 1p 14323 308 24X Fichs 50-324, 82/08/04, 8208120015
- --8208120016 Monthly operating repts for Jul 1982. HARRISON.F Carolina Power & Light Co 82/08/03 11pp 14323 309 24X Fiche 50-324, 82/08/04, 8208120015
- 8 Reportable occurrences. LERs & related correspondence
- 8208020105 Forwards LER 82-081/03L-0 DIETZ.C R. Carolina Power & Light Co 82/07/21 @'REILLY.J P. Region 2. Office of Director ip 14142 203 24X Fiche 50-024. 82/07/21. 8208020105
- --8208020110 LER 82-081/03L-0.on 820621.rods 06-23 & 26-27 did not have RTOB indication at certain positions Caused by personnel failure to properly reconnect rod position indication probe connectors, Connectors checked & tightened PASTVA.M J Carolina Power & Light Co 82/07/21 Region 2, Office of Director 1p 14142 204 24X Fiche 50-324,82/07/21,8208020105
- 8208100161 PNO-II-82-088 on 820728, licensee reported updated info re failure of shaft-driven cooling pump on emergency diesel generator 2 Caused by sheared cap screws & broken dowel pins in pump coupling Cap screws & dowel pins replaced HEHLC W . BURGER, C W Region 2. Office of Director 82/07/28 2pp 14298 033 24X Fiche 50-324.82/07/28.8208100161
- 8208090168 Forwards LER 82-089/01T-0 DIETZ.G R Carolina Power & Light Co 82/08/02 O'REILLY.J.P Ragion 2. Office of Director. Ip 14271.360. 24X Fiche 30-024.82/08/02.8208090168
- --8208090170 LER 82-083/01T-0 on 820719 analysis of bypass line around core spray discharge test valves E21-F006A & 8 determined that structural integrity could not be maintained during seismic event Caused by const error Bypass lines removed PABTVA:M J Carolina Pawar & Light Co 82/08/02 Region 2, Office of Director, 2pp 14271 361 24X Fiche. \$0-324.82/08/02.8208090168
- 8208120012 Forwards LER 82-090/03L-0 DIETI.C R Carolina Power & Light Co 82/08/03 O'REILLY.J P Region 2. Office of Director ip 14323.320 24X Fiche 30-324.82/08/03.8208120012.
- --8208120013 LER 82-090/03L-0'on 820704, trip logic associated w/rod groups 1 & 4 automatically reset Gaused by loose operator set screw in reactor scram reset switch Switch adjusted & returned to svc After similar 820723 event, switch replaced. PASTVAIM J Carolina Power & Light Ca 82/08/03. Region 2, Uffice of Director. 2pp 14323 321. 24X Fiche. 50-324, 82/08/03, 8208120012
- 8208120142 Forwards LER 62-092/03L-0 DIETZ:C R Carolina Power & Light Co 62/08/04 G'REILLY, J P. Ragion 2. Office of Director 1p. 14319 176 24X Fichs 80-324.82/08/04.8208120142
- ---8208120146 LER 82-092/03L-0 on 820705, reactor coolant chloride concentration exceeded Tech Spec max Caused by high chloride content water from suppression pool Demineralized water added to vessel inventory to reduce concentration PASTVA, M J Carolina Power & Light Co 82/08/04 Region 2, Office of Director 2pp 14319 177, 24X Fiche 50-324,82/08/04,8208120142.
- 8208200061 RO 2-82-84 on 820811, two dampers in control bldg ventilation sys failed to receive close signal upon detection of chlorine Mod will be installed prior to unit startup, DIETZ, C R Caroline Power & Light Co. 82/08/11. O'REILLY, J P. Region 2. Office of Director ip 14392 356. 24X Fiche. 30-324. 82/08/11. 8208200061
- 8208200058 Forwards LER 82-087/03L-0.
 DIETZ: C R Carolina Power & Light Co 82/08/13 D'REILLY, J P. Region 2. Defice of Director 1p 14392'221. 24X Fiche: 50-324, 82/08/13. 8208200058
- --B208200068 LER 82-087/03L-0 on 820715, during routine plant equipment surveillante, fuel oil inventory in diesel generator 4 discovered less then required. Caused by bent guide assembly preventing free float mayment, Ouide tube replaced PASTVA, M. J. Caroline Power & Light Co. 82/08/13, Region 2, Office of Director ip 14392 222, 24% Fiche 50-324,82/08/13,8208200058.

- 8208200254 Forwards LER 82-086/03L-0 DIETZ,C R Carolina Power & Light Co 82/08/13 O'REILLY,J P Region 2, Office of Director 1p 14399 309 24X Fiche 50-324, 82/08/13, 8208200254
- --8208200264 LER 82-086/03L-0 on 820715, during refueling outage, source range munitors C & D indicated erratic upscale count rate Caused by guide tube sealing gland leak allowing moisture intrusion into detector cable connectors Leak repaired PASTVA, M J Carolina Power & Light Co 82/08/13 Region 2. Office of Director 1p 14397 310 24X Fichs 50-324,82/08/13,8208200254
- B20B200285 Forward: LER 82-083/03L-0 DIETZ.C R Carolina Power & Light Co 82/08/13 D'REILLY, J P Region 2. Office of Director 1p 14398 346 24X Fiche 50-324, 82/08/13, 8208200285
- --8208200288 LER 82-083/03L-0 on 820715, during 1982 refueling outage, while performing drywell to torus leak rate test drywell to torus leak rate test drywell to torus yacuw breakers for valves found leaking excessively Caused by debris on seating surface Valves cleaned PASTVA-M J Carolina Power & Light Co 82/08/13 Region 2, Office of Director 1p 14398 347 24X Fiche 50-324,82/08/13,8208200285
- 8208270150 Forwards LER 82-099/01T-0 DIETZ.C R Carolina Power & Light Co 82/08/13 O'REILLY, J P Region 2. Office of Director 1p 14563 324 24X Fiche 50-324, 82/08/13, 8208270150
- --8208270160 LER 82-099/01T-0 on 820731, pneumatic supply to cooler air operated fan exhaust dampers found not to be safety-grade air source-resulting in damper failure during interruptible instrument air loss Caused by design deficiency PASTVA:M J Carolina Power & Light Co 82/08/13 Region 2. Dffice of Director ip 14563 325 24X Fiche 50-324.82/08/13, 8208270150
- B20B190177 Part 21 rept re pipe stress & snubber loads exceeding Tech Bpec for main steam & safety relief valve discharge lines Btructural integrity will be assured by listed corrective actions by B21015 SARSTEN, Q.E. United Engineers & Constructors, Inc. (subs of Raytheon Co.) 82/08/17 Director's Diffice, Office of Inspection and Enforcement 5pp 14386-309 24X Fiche 50-324, 82/08/17, B20B190177
- B20B270365 Potential Part 21 rept re defect concerning pipe stress & support loads exceeding allowable limits Initially reported on B20B14 Piping sys structural adequacy not jeopardized SARSIEN, G E United Engineers & Constructors, Inc (subs of Raytheon Co) B2/08/17 Spp 14566 OOB 24X Fichs 50-324,82/08/17,8208270365
 - '08270491 Forwards LER 82-093/03L-0
 DIETZ-C R Carolina Power & Light Co 82/08/17 0'REILLY, J P
 Region 2, Office of Director ip 14564 090 24X
 Fiche 50-324, 82/08/17, 8208270491
 - 8208270499 LER 82-093/03L-0 on 820719, reactor protective sys (RPS), position switch PT01 3 IPC & actuation relay C72-K3A failed to actuate Caused by RPS logic wire to relay connected to Terminal 17 instead of 13 Wire reconnected to Terminal 13, PASTVA.M J Carolina Power & Light Co 82/08/17 Region 2, Office of Director 1p. 14564 091 24X Fiche 50-324,82/08/17, 8208270491
 - 8270417 Forwards LER 82-082/03L-0 'LETZ.C R Carolina Power & Light Co 82/08/20, G'REILLY, J. P. egion 2. Office of Director 1p 14545, 238 24x iche 50-324, 82/08/20, 8208270417
- 8208270421 LER 82-082/03L-0 on 820722, surveillance frequency outlined in Test Procedure PT-01 10 did not reflect required weekly testing while in operational Mode 5 Caused by aversight in development of test Periodic test revised PABIVA.M J. Caroline Power & Light Co 82/08/20 Region 2, Office of Director ip 14565 239 24X Fiche 50-324, 82/08/20, 8208270417
- 208270479 Forwards LER 82-089/03L-0, DIETZ.C R Carolina Power & Light Co 82/08/20 O'REILLY, J. P Region 2, Office of Director 1p 14565 354 24X Fiche 50-324.82/08/20,8208270479
- --8208270484 LER 82-089/03L-0 on 820722, review of plant maint procedure revealed that post-maint testing of primary containment isolation valves per App J was not established Caused by administrative oversight. Procedure revised PASTVA.M J Carolina Power & Light Co 82/08/20 Region 2, Defice of Director 1p 14565 355 24X Fiche 50-324, 82/08/20, 8208270479

- 8208300109 Forwards LER 82-084/01T-0 DIETZ.C R Carolina Power & Light Co 82/08/23 O'REILLY, J P Region 2, Office of Director 1p 14595 121 24X Fiche 50-324, 82/08/23, 8208300109
- --820B300110 LER 82-084/01T-0 on 820B10, two control bldg ventilation isolation dampers not receiving close signal upon dotection of chlorine Caused by faulty original design Design modified & will be installed prior to startup POULK, R M Carolina Power & Light Co 82/08/23 Region 2, Diffice of Director 2pp 14576 122 24X Fiche 50-324,82/08/23,820B300109
- 8208300144 Forwards LER 82-097/03L-0 DIETZ.C R Carolina Power & Light Co 82/08/23 D'REILLY, J P Region 2. Office of Director ip 14599 223 24X Fiche 50-324, 82/08/23, 8208300144
- -8208300147 LER 82-097/03L-0 on 820727, revise of time response test procedures for reactor water cleanup law level 2 isolation, revealed armature treval time for last relay in logic chain not timed Caused by improper terminals Procedures revised POULK, R M Carolina Power & Light Co 82/08/23 Region 2, Office of Director 2pp 14999 224 24X Fiche 50-324,82/08/23, 8208300144
- 8208300082 Forwards LER 82-094/03L-0 DIETZ, C R. Carolina Power & Light Co 82/08/24 O'REILLY, J P Region 2. Office of Director 1p 14598 250 24X Fiche 50-324, 82/08/24, 8200300082
- --B208300091 LER 82-074/03L-0, on 820727, review of source range monitor sys functional test revealed that surveillance frequency outlined in PT-01 2 1 did not reflect required froquency in Mode 5 Caused by procedural oversight PABTVALM U Carolina Power & Light Co 82/08/24 Region 2, Office of Director 1p 14598 281 24X Fiche 50-324,82/08/24,8208300082
- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
 F. Security, medical, emergency & fire protection plans
- B208260110 Releases public version of NUB rept "Radiation Bhielding Analysis for Brunswick Technical Bupport Ctr/Emergency Operating Facility "
 FELTON.J M Division of Rules and Records 02/08/11. Document Management Branch ip 14574 131. 24X Fiche 50-324.82/08/11. 8208260110
- --8208260114 Forwards public version of NUB rept "Radiation Bhielding Analysis for Drunswick Technical Support Ctr/Emergency Operating Facility "
 ZIMMERMAN,8 R Consumers Power Co. 82/08/04 DENTON,1/R Dffice of Nuclear Reactor Repulation, Director 2pp 14576 132 24X Fiche 50-324,82/08/11,8208260110
- --8208260350 Public version of "Radiation Shielding Analysis Brunswick Technical Support Ctr/Emergency Operating Facility"

 8800E.R W. NATHAN, 8 J. NUB. Corp. NUS-4148 82/06/30 62pp. 14576-134 24K Fiche 50-324, 82/08/11
- J Insurance & indemnity information
- 8208310240 Application for amend to Paragraph 2 A of License DPR-62 & DPR-71, reflecting Board of Commissioners 811216 act whereby name of NC Municipal Power Agency Number 3 was changed to NC Eastern Municipal Power Agency UNRES. J A Carolina Power & Light Co 82/08/25. DENTON, H R. Office of Muclear Reactor Regulation, Director 3pp 14688 147 24X Fiche 50-324, 82/08/25, 8208310260
- --B20B3102B3 Forwards unexecuted Amend ii to Idemnity Agreement B-71.
 adding NC Municipal Power Agency Number 3 to agreement
 BALTZMAN.J. Assistant Director for State & Licensee Relations
 B2/05/19 JONES.J.A. Caroline Power & Light Co 2PP, 146BB:150
 24X Fiche 50-324.82/08/25.8208310260
- P Operating license stage documents & correspondence
- 8204070829 Application for amend to Licenses DPR-71 & DPR-62, revising Tach Specs to allow unit operation up to 50% of rated thermal power w/one recirculation loop out of evc Class I & III amend fees enci HOWE.P W Carolina Power & Light Co. 82/04/03 VABBALLO.D B Operating Reactors Branch 2 2pp 13387 209 24X Fiche: 50-324, 82/04/03, 8206070829

ŀ

1

- --8205070868 "Brunswick Steam Electric Plant Units 1 & 2 Single-Loop Operation." a Owners1 Electric Co NEDG-24344 81/09/30 32pp 13387 236 24X Fiche 50-324,82/06/03,8206070829 Operation,
- 8208030690 Transmits authorization for addl license conditions 208030690 transmits action relation for add intense con-sitending deadlines for surveillance requirements as requested on 820701 Amend clauses encl NGVAK.T M Assistant Director for Operating Reactors JONES.J A Caroline Fouer & Light Co 3pp 14174 3: Fiche 50-324,82/07/01,8208030490 x reactors 82/07/01 14176 316 24X
- 8207080064 Generic ltr to all licensess of operating plants, epplicants for OL & holders of CP re Commission approved charter for CRGR 8vc list encl
 DIRCKS,W J Office of the Executive Director for Operations,
 82/07/02 Consolidated Edison Co of New York, 93pp 14194 001
 24X Fiche 50-000,82/07/02,8207080064
- 8208030493 Requests assistance in conducting electromagnetic interference measurement program Data base will be used to essess vulnerability of proposed or existing designs due to event involving electromagnetic interference VASSALLO, D B Operating Reactors Branch 2. 62/07/02 JDNES, J A Carolina Power & Light Co Spp 14196 311. 24X Fiche 30-324,82/07/02.6208030493
- 8208030072 Confirms 820703 telcon authorization for add1 OL conditions. Licenses DPR-71 & DPR-62 amended as of 820703 by adding encl clauses re operability of electric sources NDVAK.T M. Assistant Director for Operating Reactors. 82/07/06 JONES.J A Carolina Power & Light Co 3pp 14200 311, 24X Fiche: 50-324, 82/07/06, 8208030072
- 820Bi60166 Confirms 820716 & 19 telcons & 920720 meeting agreements re listed corrective actions to be performed to conform w/Tech Spec surveillance test requirements Long-term actions to be discussed w/NRC by 820730 O'REILLY, J P. Region 2, Office of Director, 82/07/20 JONES, J A Caroline Power & Light Co 2pp 14345 121. 24X Fiche, 50-324, 82/07/20, 820Bi60166
- 820811020i Forwards revised version of reactor protection sys/power monitoring sys design model Tech Bpecs Specs less restrictive in some requirements than earlier version VASSALLO, D.B. Operating Reactors Branch 2, 82/07/28 JONES, J. A. Caroline Power & Light Co. 2pp 14328-357 24X Fiche 50-324,82/07/28,8208110201.
- -8208110202 Model Tech Space re reactor protection sys/power monitoring sys design
 NRC - No Detailed Affiliation Given 82/07/28. ip 14328,359
 24X Fiche.50-324,82/07/28,8208110201
- 8208120345 Informs that proposed method for implementing NUREG-0737, Item II K.3 15, "Isolation of HPCI & Reactor Core Isolation Cooling," acceptable VASSALLO, D.B. Operating Reactors Branch 2 62/07/28 JUNES, J. A. Carolina Power & Light Co. 3pp 14340.076 24X Fiche 50-324,82/07/28,8208120345
- 8208020318 Application to amend Licenses DPR-71 & DPR-62 Tech Specs, reflecting change in ECCS actuation instrumentation setpoints & concomitant surveillance requirements Change request involves single technical issue HOWE:P W Carolina Power & Light Co. 82/07/29 VASSALLO.D. B. Operating Reactors Branch 2 2pp 14151 115 24X Fiche 50-324, 82/07/29, 8208020318.
- --8208020325 Proposed Tech Bpecs re ECC8 actuation instrumentation setpoints & concomitant surveillance requirements * Garoline Power & Light Co 82/07/29. 6pp 14151 117. 243 Fiche. 80-324, 82/07/29. 8208020318. 14151 117. 24X
- 8208030309 Agrees to host LLL representatives to conduct electromagnetic interference measurement program at Fiche: 50-324, 82/07/29, 8208030309
- 820B100195 Forwards add1 info requested in B20226 ltr re detector in-situ calibr.per TMI Item II.F i In-situ source calibr unnecessary based on electronic check source function built into containment high range monitor sys.

 ZIMMERNAN.S.R. Caroline Power & Light Co. B2/08/04 VABSALLO.D.B. Operating Reactors Breach 2 2pp. 14298:194. 24X

 Fiche: 50-324, 82/08/04, 8208100195.

- 8208280002 Requests verfication of satisfaction of encl criteria re NUREO-0737. Item II K 3 22. "Automatic Switchover of Reactor Core Isolation Cooling Bys Suction " Response requested within 30 days VASSALLD.D B Operating Reactors Brench 2 82/08/05. JONES, J A Caroline Power & Light Co 4pp 14557 226 24% Fiche 50-324.82/08/05,8208250002
- 8208260367 Forwards Amends 48 & 72 to Licenses DPR-71 & DPR-62, 200200367 Forwards Amends 48 & 72 to Licenses DRA-71 & DRA-62, respectively, selecty eveluation & notice of issuance & availability Amends change Tech Specs to provide surveillance requirements for scram discharge velves, VAESALLO, D.B. Operating Reactors Branch 2 82/08/05 JONES, J.A. Carolina Power & Light Co. 2pp 14594 182, 24X
 Fiche 30-324,82/08/05,8208260367
- --8208260380 Amends 48 & 72 to Licenses DPR-71 & DPR-62, respectively, providing surveillance requirements for scram discharge volvent & drain valves & limiting conditions for operation for screm discharge vol limit switches VABSALLO.D B Operating Reactors Branch 2 82/08/05, 20pp. 14594 184 24X Fiche 50-324, 82/08/05, 8208260367
- -8208260393 Bafety evaluation supporting Amends 48 & 72 to Licanses PR-71 & PR-62, respectively ECCLESTON, K. T. Office of Nucleer Reactor Regulation, Director, 82/09/05 2pp 14594, 204 24% Fiche 30-324, 82/08/05, 8208260367,
- --8208260410 Notice of issuance & availability of Amends 48 k 72 to Licenses DPR-71 & DPR-62, respectively ROONEY.V L Derating Reactors Branch 2 82/08/05 2pp. 14594 206. 24% Fiche 50-324, 82/08/05,8208260367.
- 8208160078 Comments on 820720 meeting re util comments on systematic assessment of licensee performance & status of missed surveillance test issue Meeting beneficial & provided better understanding of util position O'REILLY, JP Region 2. Office of Director 82/08/06 JUNES, J A Carolina Power & Light Co ip. 14342 131 24X Fiche 50-324, 82/08/06, 8208160078
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Bummarizes 10GFR Chapter I requirements & provides alternatives to requirements Bvc list end: EISENHUT, D G Division of Licensing. B2/08/09 Consolidated Edison Co. of New York ip 14356-332 24X Fiche. 50-000, 82/08/09, 8208090194
- 8208190384 Requests documentation indicating how each criterion of NUREG-0737. Item II B. 3 re post-accident sampling satisfied Echedule requested within 20 dees of receipt of itr VABBALLO, D.B. Operating Reactors Branch 2, 82/08/09 JONES, J. A. Carolina Power & Light Co. 10pp 14504 136, 24X Fiche 50-324, 82/08/09, 8208190384
- 8208190312 Application for amend to Licenses DPR-71 % DPR-62 re reactor protection sys motor generator sets Changes supersede 820824 Tech Spec change request. UTLEY, E. Carolina Power & Light Co 82/08/16 VASBALLO, D B. Operating Reactors Brench 2. 2pp. 14387 135. 24X Fiche. 30-324, 82/08/16, 8208190312.
- -8208190313 Proposed Tech Spec changes providing time delay settings for reactor protection sys motor generator sets * Carolina Power & Light Co 82/08/16. 4pp. 14387 137. 24X Fiche 50-324,82/08/16.8208190312
- 8208240403 Confirms telcon w/JA Van Vliet re NUREQ-0737, Item II.K. 3, 24, "Space Cooling for HPCI/Reactor Core Isolation Cooling Sys." Electrical power sys for all ECCS room coolers supplied by station emergency buses ZIMMERMAN.S R. Carolina Power & Light Co. 82/08/19. VASSALLO, D. B. Operating Reactors Branch 2. ip 14322: 294. 24X Fiche: 50-324, 82/08/19, 8208240403
- 8208310260 Application for amend to Paragraph 2, A of License DPR-62 & DPR-71, reflecting Board of Commissioners 811216 act whereby mans of NC Municipal Power Agency Number 3 was chenged to NC Eestern Municipal Power Agency.

 JONES: J A. Carolina Power & Light Co 82/08/25 DENTON, H R Office of Nuclear Resolution, Director 3pp 14688; 147, 24X Fiche. 50-324, 82/08/25, 8208310260
- G Inspection reports, IE Bulletins & correspondence
- 8208160517 Confirms 820628 teleon re 820714 enforcement meeting in Atlanta, GA to review results of investigations of areas outlined in 820408 confirmation of action 1tr Proposed agenda enci O'REILLY, J. F agence and UTREILLY, J.P. Region 2, Office of Director. 82/07/08 JONES, J. A Carolina Power & Light Co. 2pp. 14348, 080. 24% Fiche: 50-324, 82/07/08, 8208160317

- 8208030180 Forwards IE Insp Repts 50-324/82-24 & 50-325/82-24 on B20515-0615 No noncompliance noted LONG F Division of Project & Resident Programs 82/07/13 JUNES J A Carolina Fower & Light Ca 2pp 14160 179 24X Fiche 50-324, 82/07/13, 8208030180
- --R20B030182 IE Insp Repts 50-324/62-24 & 50-325/62-24 on 820515-0615 No noncompliance noted Major areas inspected review of LERs. maint activities, surveillance activities, operational safety verification & independent insp effort MYERS, D D. OARNER, L W. BURGER, C W. Division of Project & Resident Programs 82/07/09 10pp 14160 177 24X Fiche 50-324,82/07/13.8208030180
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16.8204210393
- 8208060125 Discusses IE insp on 820106-07 & forwards notice of violation & notice of proposed imposition of civil penalty O'REILLY, J P Region 2, Office of Director 82/07/16 JONES, J A Carolina Power & Light Go 4pp 14244 055 24X Fiche 50-325, 82/07/16, 8208060125
- --8208060139 Notice of violation & notice of proposed imposition of civil penalty in amount of \$120.000 Noncompliance noted w/reactor in operating condition i & reactor vessel water level low, instrumentation did not have two operable channels O'REILLY, J P Region 2, Office of Director 82/07/16 3pp 14244 060 24X Fiche 30-325,82/07/16,8208060125
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnal Monitoring Devices for External Radiation" 8yc list encl
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19
 Michigan. Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210395
- |204210396 IE Info Notice 82-25, "Failures of Hiller Actuatore Upon Gradual Loss of Air Pressure " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance B2/07/20 Consolidate & Edison Co of New York 112pp 14381 001 24X Fiche 50-000 82/07/20 8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacts " Svc list enc! COSBL I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Constituted Edison Co of New York 7ipp 14357 276 24% Fiche 50-000,82/07/20.8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Bvc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp 14194 321 24X Ficke 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydragen Explosion While Grinding in Vicinity of Drained & Open RCS " Bvc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Ficher 50-000, 82/07/23,8204210401
- 8204210402 IE Info Natice B2-29. "Control Rad Drive (CRD) Quide Tube Support Pin Failures at Wastinghouse PWRs." Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Hestinghouse PMR Power Plants " Syc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210403 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Bvc list and JORDAN.E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8208180210 Forwards request for add1 info re response to IE Bulletin 80-11, "Masonry Wall Design " Response due in 45 days VASSALLO.D B Operating Resctors Branch 2 82/08/02 JONES.J A Carolina Power & Light Co App 14390-356 24X Fiche 50-324,82/08/02.8208180210

- 8208160133 Forwards IE Enforcement Meeting Repts 50-324/82-27 & 30-325/82-27 on 820714 O'REILLY, J P Region 2. Office of Director 82/08/04 JUNES, J A Carolina Power & Light Co ip 14345 252 24X Fiche 90-324, 82/08/04, 8208160133
- --8203160134 IE Enforcement Meeting Repts 50-324/82-27 & 50-325/82-27 on 820714 Major areas discussed proposed corrective actions re 820321 & 25 events involving mispositioned breaker & valves LEWIS.R C Division of Project & Resident Programs 82/08/03 2pp 14345 253 24X Fiche 50-324.82/08/04.8208160133
- 8204210407 IE Info Notice 82-27, "Fuel Rod Dugradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000,82/08/05,8204210407
- 8208250207 Responds to NRC 820716 ltr re-notice of violation & imposition of civit penalties Corrective actions control operator & auxiliary operator daily surveillance repts have been reviewed & revised UTLEY.E E Carolina Power & Light Co 82/08/14 DEYOUNG.R C Director's Office. Dffice of Inspection and Enforcement 9pp 14341 331 24% Fiche 50-324,82/08/14,8208250207
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY91" + NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche: 50-000: 82/07/13, 8208270010
- --8208270217 Forwards annual personnel & man-rem exposure by work & job function for CYB1 pure & Light Co 82/02/04 O'REILLY, J P Region 2, Office of Director 2pp 14679 284 24X Fiche 50-000,82/07/13,8208270010
- --8208270225 Annual personnel & man-rem exposure by work & job function for CYBI * Carolina Power & Light Co 81/01/21 lp 14679 286 24X Fich* 50-000,82/07/13.8208270010
- --8208270227 Forwards statistical radiation exposure summary rept for CY81, per 10CFR20 407
 DIETZ.C R Carolina Power & Light Co 82/02/04 HALLER, N M Office of Management and Program Analysis 1p 14679 287 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270233 Statistical radiation exposure summary rept for CYB1
 Carolina Power & Light Co 82/02/04 App 14479 288 24X
 Fiche 50-000, 82/07/13, 8208270010
- 820B120015 Forwards monthly operating repts for Jul 1982 DIETZ.C R Carolina Power & Light Co 8270B704 DEYOUNG,R.C Director's Office of Gispection and Enforcement ip 14323 308 24X Fiche 50-324,82708/04.8208120015
- --8208120016 Monthly operating repts for Jul 1982 HARRIBON,F Carolina Power & Light Co 82/08/03 11pp 14323 309. 24% Fiche 50-324, 82/08/04.8208120015
- S Reportable occurrences, LERs & related correspondence
- 8208020085 Forwards LER 82-074/03L-0 DIETI.C.R. Carolina Power & Light Co. 82/07/21 0'REILLY.J P Region 2, Office of Director ip 14:144 091. 24X Fiche. 50-325, 82/07/21, 8208020085
- --8208020089 LER 82-074/03L-0 on 820A23, electrolyte level in pilot cell of Div II battery ID-1 found higher than max level mark on cell Caused by battery room ambient temp increase following filling to max level mark PABTVA; M J Carolina Power & Light Cp. 82/07/21, Region 2, Office of Director 2pp. 14144 092 24X Fiche 50-325,82/07/21,8208020085
- 8208020102 Forwards LER 82-057/03L-0.
 DIETZ.C R Carolina Power & Light Co 82/07/23, 0'REILLY, J P Region 2. Office of Director ip 14142, 207. 24X Fiche 50-325, 82/07/23, 8208020102

- --B208020107 LER B2-057/03L-0 on B20625, primary containment atmosphere organ analyser, i-CAC-AT-1259, indicated unexpected upscale drywell oxygen concentration Caused by failure of analyser electromagnetic unit photocell light due to end of life PASTVA, M. J. Carolina Power & Light Co. B2/07/23 Region 2, Office of Director ip 14142,208 24X Fiche 50-325,82/07/23,8208020102
- 8208020382 Forwards LER 82-068/03L-0 DIETZ, C R Carolina Power & Light Co. 82/07/27 O'REILLY, J P Region 2. Office of Director ip 14148-221 24X Fichs 50-025: 82/07/27, 8208020382
- --8208020386 LER 82-068/03L-0 on 820624, during plant operation, post-accident drywsll particulate radiation detection instrument 1-GAC-AGH-1262-1 tripped & would not restart Caused by power supply breaker thermal overload trip PABTVALM J Carolina Power & Light Co 82/07/27 Region 2, Office of Director 2pp 14148 222 24X Fiche 50-325,82/07/27,8208020382
- 8208050120 Forwards LER 82-073/03L-0.
 DIETZ, C R Carolina Power & Light Co 82/07/28 O'REILLY, J P. Region R. Office of Director ip 14213.122 24X
 Fiche 50-325, 82/07/28, 8208050120
- --8208030124 LER 82-073/03L-0 on 820628, while securing diesel generator 1 from loaded operation, diesel generator reverse power trip occurred causing lockout of diesel, making diesel unavailable for automatic emergency operation Caused by operator error PABTVA, M J Carolina Power & Light Co 82/07/28 Region 2, Office of Director 2pp 14213, 123, 24x Fiche 50-325,82/07/28, 8208050120
- 8208100161 PNO-II-82-088 on 820728, licensee reported updated info re failure of shaft-driven cooling pump on emergency diesel generator 2, Caused by sheared cap screws & broken dowel pins in pump coupling Cap screws & dowel pins replaced HEHL.C.W., BURGER,C.W., Region 2, Office of Director 82/07/28 2pp 14298:033. 24X Fiche.50-324,82/07/28,8208100161.
- 8208090125 Forwards LER 82-077/03L-0.

 DIETZ.C R Garolina Fower & Light Co. 82/07/30. G'REILLY, J P. Region 2. Office of Director. 1p 14269:347 24X

 Fiche 50-325, 82/07/30, 8208090125
- --B20B090128 LER 82-077/03L-0 on B20701.average power range monitor (APRM) F became inoperable due to upscale signal from input low power range monitor 28-07A while APRM B also inoperable Caused by moisture in detector cable connector PABTVA,M J Carolina Power & Light Co 82/07/30 Region 2, 02/07/30 GP Director 2pp 14269.348. 24X Fiche: 50-325.82/07/30, 8208090125
- 8208090212 Forwards LER 82-078/03L-0.

 DIETZ: C R Carolina Power & Light Co. 82/07/30 O'REILLY, J P. Region 2: Office of Director. 1p 14271.117. 24X Fichs 50-325.82/07/30.8208090212.
- --8208090218 LER 82-078/03L-0.on 820701, diesel generator 2 tripped due to low jacket water pressure Caused by separation of flex drive coupling drive plate from engine crankshaft due to shearing of dowel pins & cap screws Plate, pins & screws replaced. PASTVA, M J Carolina Power & Light Co. 82/07/30 Region 2, Office of Director 2pp. 14271 118 24X Fiche 50-325,82/07/30,8208090212.
- 8208120078 Forwards LER 82-072/03L-0 DIETZ.C.R Carolina Fower & Light Co. 82/07/30. O'REILLY, J. P. Ragion 2, Office of Director ip 14327:175. 24X Fiche: 50-325, 82/07/30, 8208120078
- --8208120082 LER 62-072/03L-0 on 820630, while investigating cause of reactor scram, discovered Tech Epac-required surveillance of emergency bus degraded voltage & undervoltage relays not performed, Caused by personnal error Review in progress.

 PABTVA: M J Carolina Power & Light Co. 82/07/30. Region 2, Office of Director. 2pp. 14327 176. 24X Fiche 50-325,82/07/30,8208120078
- 8208120021 Forwards LER 82-075/01T-0.
 DIETZ.C R. Carolina Power & Light Co. 82/08/04. O'REILLY, J. P. Region 2. Office of Director. 1p. 14323:287. 24X
 Ficha.50-325,82/08/04,8208120021.
- --8208120022 LER 82-075/01T-0:on 820620, while reviewing documentation of most recently completed local leak rate test, discovered 67 containment penetrations exceeded 2-yr requirement Caused by improper scheduling.

 PABTVA.M J Caroline Power & Light Co 82/08/04. Region 2, Office of Director 2pp 14323 288. 24X Fiche 50-325,82/08/04. 8208120021.

- 8208130284 Forwards LER 82-071/03L-0 DIETZ.C R Carolina Power & Light Co 82/08/06 O'REILLY.J P Region 2. Office of Director 1p 14333 067 24X Fiche 50-325.82/08/06.8208130284
- --B20Bi302B6 LER 82-071/03L-0 on B2070B, during insp of HPCI sys condensate storage tank low level water instrument, ref sensing valve i-E41-V150 discovered closed, rendering instrument inoperable Cause undetermined Valve reopened, PABTVA, H J Carolina Power & Light Co. B2/08/06 Region 2, Dffice of Director 2pp 14333 068 24X Fiche, 50-325, 82/08/06, B20B1302B4
- --8208130317 LER 82-067/03L-0. on 820708, primary containment atmosphere oxygen analyser i-CAC-AT-1259-2 indicated unexpected downscale drywell oxygen concentration Caused by calibr whift of electromagnetic unit on sero end. Unit calibr. PABTVA.H. J Carolina Power & Light Co 82/08/06 Region 2. Office of Director 1p 14336-352 24X Fiche 50-325, 82/08/06, 8208130314
- 8208200012 Forwards LER 82-080/03L-0 DIETT.C R. Carolina Power & Light Co 82/08/13 G'REILLY, J. P. Region 2. Office of Director 1p. 14392 260, 24X Fiche 30-325, 82/08/13, 8208200012
- --8208200019 LER 82-080/03L-0 on 820716, while inserting control rods during reactor shutdown, rod 30-39 did not have RTOB position indication of Position 36 Caused by failed PPIB read switch. Switch will be repaired at next refueling PABTVA. M J Caroline Power & Light Co 82/08/13 Region 2, Office of Director 1p 14392 261 24X Fichs 50-325, 82/08/13, 8208200012
- 8208200079 Forwards LER 82-069/03L-0 DIETZ, C.R. Carolina Power & Light Co. 82/08/13. D'REILLY, J.P. Region 2. Office of Director 1p 14393 218. 24X Fiche 50-329, 82/08/13, 8208200079.
- --B20B2000B9 LER B2-069/03L-O on B20715, during reactor core isolation cooling (RCIC) sys operability test, RCIC turbine immediately tripped upon start. Caused by lack of common ref signal between generator & electronic governor module PABTVA.M.J. Carolina Power & Light Co B2/08/13 Region 2, Office of Director 2pp 14393, 217, 24X Fiche 50-325, 82/08/13, 820B200079
- 8208270520 Forwards LER 82-088/03L-0, DIETZ.C R Carolina Power & Light Co 82/08/13. O'REILLY, J P. Region 2. Office of Director 1p 14564.137. 24X Fiche 50-325, 82/08/13, 8208270520.
- --8208270542 LER 82-088/03L-0.on 820716, during review of LLRT results, certain containment isolation valves were not addressed in LRT procedures. Caused by personnel error All containment isolation valves will be tested prior to startup. PABTVA.M.J. Carolina Power & Light Co. 82/08/13. Region 2, Uffice of Director. 6pp. 14564:138 24X Fiche: 50-325,82/08/13,8208270520
- B20Bi90177 Part 21 rept re pipe stress & snubber loads exceeding Tech Bpec for main steam & safety relief valve discharge lines. Btructural integrity will be assured by listed corrective actions by 82:005. BARSIEN.O.E United Engineers & Constructors: Inc. (subs. of Raytheon Co.). B2/08/17 Director's Office, Office of Inspection and Enforcement. 5pp 14386:309 24X Fiche.50-324,82/08/17. 8208190177.
- 8208270365 Potential Part 21 rept re defect concerning pipe stress & support loads exceeding allowable limits, Initially reported on 820814, Piping sys structural adequacy not jeopardized, BARBTEN, 0 E United Engineers & Constructors, Inc. (subs of Raytheon Co) 82/08/17 5pp. 14566:008 24X Fiche: 50-324, 82/08/17, 8208270365
- 8208270404 Forwards LER 82-082/03L-0.
 DIETZ.C.R Carolina Power & Light Co 82/08/17. O'REILLY, J P. Region 2. Office of Director. 1p. 14365: 226. 24X Piche: 30-325: 82/08/17. 8208270404.
- --8208270406 LER 82-082/03L-0.on B20718, reactor coolant chloride concentration exceeded Tech Spec limit, Caused by leakage of high chloride content main condenser cooling water into condensate sys Main condensare mater box leaks repaired. PASTVA: H J Carolina Power & Light Co. 82/08/17 Region 2. Office of Director. 2pp. 14565:227. 24X Fiche: 50-325:82/08/17, 8208270404.

- 8208270396 Forwards LER 82-076/03L-0 DIETZ,C R Carolina Power & Light Co 82/08/18 O'REILLY, J P Region 2. Office of Director 1p 14965 024 24X Fichs 50-325, 82/08/18, 8208270396
- --8208270401 LER 82-076/03L-0 on 820719.during Type 8 & C low leve) radiation test on containment isolation equipment combined leak rate of 11 primary containment valves exceeded Tech Specs Caused by packing & valve seat leaks Valves repaired PASTVA.H J Carolina Power & Light Co 82/08/18 Region 2, Office of Director 2pp 14565 025 24% Fiche 50-325.82/08/18, 8208270396
- 8208270412 Forwards corrected LER 82-088/03L-0
 DIETZ.C R Carolina Power & Light Co 82/08/18 O'REILLY, J P
 Region 2. Office of Director 19 14565 227 24X
 Fiche 50-325.82/08/18.8208270412
- --B209270416 Corrected LER B2-08B/03L-0 on 920716, discovered that containment isolation valves previously omitted or deleted from Unit 2 low level radiation test procedure were not addressed in Unit 1 procedure Caused by personnel error PABTVA: M J Carolina Power & Light Co 82/08/18 Region 2, Office of Director 6pp 14565 230 24X Fiche 50-325,82/08/18, 22/08/204270412
- 8208270258 Forwards LER 82-086/03L-0 DIETZ,C R Carolina Power & Light Co 82/08/20 O'REILLY,J P Region 20 Office of Director 1p 14563 092 24X Fiche 50-325,82/08/20,8208270258
- --8208270266 LER 82-086/03L-0 on 820722, during routing operator surveillance, source range monitor A declared inopgrable caused by intermittent failure of power supply causing erroneous indication Power supply replaced PASTVA-M J. Carolina Power & Light Co 82/08/20 Region 1. Office of Director ip 14563 093 24X Fiche 50-325,82/08/20,8208270258
- 3208270381 Forwards LER 82-084/03L-0 DIETZ.C.R Carolina Power & Light Co 82/08/20 O'REILLY.J P Region 2. Office of Director Ip 14564 230 24X Fiche 50-325.82/08/20.8208270381
- --8208270387 LER 82-084/03L-0 on 920723, review of procedure for channel calibr & functional test of main steam line high flow instrumentation, PT-A20 i, revealed that refueling frequency utilized vs required quarterly surveillance frequency PASTVA: M.J. Caroline fewer & Light Co. 82/08/20. Region 2, Office of Director. 2pp. 14564-231. 24X Fiche 50-325, 82/08/20, 8208270381.
- 3208300333 Forwards LER 82-083/03L-0 DIETZ-C R Carolina Power & Light Co 82/08/20 O'REILLY, J F. Region 2. Office of Director 1p 14599 101 24X Fiche 50-325, 82/08/20, 8208300333
- -8208300343 LER 82-083/03L-0 on 820723, while performing technical review of fire suppression water sys velve operability test PT-35 22; three valves were not included in test procedure Caused by personnel error Tenporary revision initiated PASTVA: H J Carolina Power & Light Co 82/08/20 Region 2; Office of Director ip 14599 102 24x Fiche 50-325,82/08/20, 8208300333
- '08300238 Forwards LER 82-090/03L-0
 DIETT.C R Carolina Pawer & Light Co 82/08/24 O'REILLY.J P
 Region 2. Office of Director ip 14679 069 24X
 Fiche: 50-325. 82/08/24. 8208300238
- --8208300244 LER 82-090/03L-0 on 820728, control bldg chloring detection sys calibr Procedure PT-46 3PC exceeded time limitation when performed on 82013 Caused by incorrect input into surveillance tracking computer program.
 PDULKIR M. Carolina Power & Light Co 82/08/24 Region 2. Office of Director 2pp 14679:070 24X Fiche 50-325.62/08/24, 8208300238
- DOCKET 50-326 UNIV OF GALIFORNIA AT IRVINE REG REACTOR

 F Security, medical, emergency & fire protection plans
- 8208230320 Ack receipt of 820805 itr informing NRC of steps taken to correct violations noted in 820707 notice of violation. Response withheld (ref 100FR2, 790) NORDERHAUO,L. R. Division of Rediological Sefety & Sefeguards Program 82/08/16 LILLYMAN,H J. California, Univ. of, Irvins ip. 14513 150 24X Fiche 50-326,82/08/16,8208230320.

H General correspondence

- 8208100291 Notifies of change in administrative personnel Future official communications re licensing matters should be addressed to MJ Lillyman, Vice Chancellor LILLYMAN, M J California, Univ of, Irving 82/08/06 Office of Nuclear Reactor Regulation, Director ip 14294 200 24X Fiche 50-326,82/08/06,8208100291
- Q Inspection reports, IE Bulletins & correspondence
- 8208230320 Ack receipt of 820805 ltr informing NRC of steps taken to correct violations noted in 820707 notice of violation Response withheld (ref 10CFR2 770)

 NORDERHAUG,L R Division of Radiological Safety & Safeguarde Program 82/08/16 LILLYMAN,W J California, Univ of, Irvine ip 14513,150 24X Fiche 50-326,82/08/16,8208230320
- R Periodic operating reports & related correspondence
- 8208060219 Forwards "Annual Rept for Jul 1981-June 1982, License R-116" MILLER, O E California, Univ of Irvine 82/07/30 Director's Office. Office of Inspection and Enforcement 1p 14241 069 24X Fiche 30-326, 82/07/30, 8208060219
- --8208060223 "Annual Rept for Jul 1981-June 1982, License R-116 " MILLER, 0 E Galifornia, Univ of Irvine 82/06/30 13pp 14241 070 24X Fiche 50-326, 82/07/30,8208060219
- DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8208160473 Confirms 820708 & 20 telcons re corrective action to resolve deficiencies in emergency proparedness program Areas include training for inplant emergency organization & upgrading technical support ctr Action will be completed by 821109 O'REILLY, J P Region 2, Office of Director 82/07/20 PARRIS, H Q Tennessee Valley Authority 2pp 14348 195 24X Fiche 50-327, 82/07/20, 8208160473
- 8208030547 Ack receipt of 820720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-11 & 30-328/82-11 UERRELLI, D M Division of Project & Resident Programs 82/07/26 PARIS, H 0 Tennessee Valley Authority 1p 14162 265 24X Fiche 50-327/82/07/26.8208030347
- --8208030562 Responds to NRC 820702 ltr re violations noted in 1E Insp. Repts 50-327/82-11 & 50-328/82-11 Corrective actions deficiencies evaluated to determine necessary design mods to evacuation alarm sys.

 MILLS,L.M. Tennessee Valley Authority 82/07/20 O'REILLY, J.P. Region 2. Defice of Director 2pp 14162, 266 24X Fiche 30-327, 82/07/26, 8208030547
- 8208160323 Forwards IE Insp Repts 50-327/82-13 & 50-328/82-13 on 820708-09 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/07/27. PARRIS.H 0 Tennesses Valley Authority 2pp 14349,027 24X Fiche 50-327,82/07/27.8208160323
- --8208160406 IE Insp Repts 50-327/82-13 & 50-328/82-13 on 820706-09. No moncompliance noted Major areas inspected full-scale sergency exercise ANDREMS, D L , MARSTON.R R , HUFFMAN O N Division of Emergency Preparedness & Operational Support 82/07/23 12pp. 14349 029. 24% Fiche 50-327,82/07/27,8208160323
- 8208090124 Forwards IE Bafeguards Insp Repts 50-327/82-17 & 50-328/82-17 on 820719-23 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 82/08/05 PARRIS, H O Tennessee Valley Authority 2pp 14269 350 24X Fiche 50-327, 82/08/05, 8208090124.
- --8208090127 IE Safeguards Insp Repts 50-327/82-17 & 50-328/82-17 on 820719-23 No noncompliance noted Major areas inspected security plan, security organization mgt & personnel Details withheld (ref 10CFR73 21)

 TILLMAN.A: MCGUIRE.D R Division of Project & Resident Programs 82/08/04 ip 14269-352 24X Fishe 50-327.82/08/05.8208090124
- 8208230004 Forwards proposed revision to physical security plan Revision withheld (ref 10CFR73 21) KAMMER.D.B Tennessee Valley Authority 82/08/17 ADENBAM, E. Licensing Brench 4. 1p 14517 288 24X Fiche 50-327, 82/08/17, 8208230004

[Financial information

- 8208100002 Forwards "TVA Power Program Summary," Vol 2. for fiscal yr ending 810630 & "1981 Power Program Bummary," for fiscal yr ending 810930, per Bection 50 71(b) of 10CFR80 MILLS.L M Tennessee Valley Authority 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 118pp 14294 024 24X Fiche 50-000, 82/08/06, 8208100002
- 8208270497 Forwards financial statements for FY81, power quarterly rapt & internal cash flow projection MILLS.L M Tennessee Valley Authority 82/08/23 SALTZMAN, J Assistant Director for State & Licensee Relations 48pp 14566 135 24X Fiche 50-000, 82/08/23, 8208270497

J Insurance & indemnity information

- 8208310200 Advises that onsite property damage insurance has been purchased in accordance w/iOCFR50 54 Coverage status encl, MILLS.L M Tennessee Valley Authority 82/08/25 BALTZMAN, J Assistant Director for State & Licensee Relations. 2pp 14693 160 24% Fiche 50-000, 82/08/25,8208310200
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licenses of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Byc list encl
 DIRCKS.W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 73pp. 14194 001
 24% Fiche 50-000.62/07/02.8207080064
- 8208030021 Forwards Amends 14 & 15 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends authorize 30-day changes in requirement re containment sump level instrumentation ADENSAM, E 0 Licensing Branch 4. 82/07/07, PARRIE, H Q Tennessee Valley Authority 3pp 14237 332 24X Fiche 50-327,82/07/07, 8208030021
- --B20B030023 Amends 14 & 15 to Licenses DPR-77 & DPR-79, respectively, authorizing 30-day changes in requirement re containment sump level instrumentation operability ADENSAM.E 0 Licensing Branch 4 82/07/07 6pp 14237-334 24X Fiche 50-327, 82/07/07, 8208030021
- --8208030026 Safety evaluation supporting Amends 14 & 15 to Licenses DPR-77 & DPR-79, respectively + Office of Nuclear Reactor Regulation, Director 82/07/07 2pp 14237 340 24% Fiche 50-327,82/07/07,8208030021,
- --8208030029 Notice of issuance & availability of Amends 14 & 15 to Licenses DPR-77 & DPR-79, respectively ADENSAH.E Q Licensing Branch 4 82/07/07. 2pp 14237 342 24X Fiche 50-327, 82/07/07. 8208030021
- 8208040523 Notification of 820804 meeting w/utils in Bethesda, MD to discuss results of R&D program for hydrogen control & combustion in ice condenser plants. STAHLE.C Licensing Branch 4. 82/07/21 ADENBAH.E G, Licensing Branch 4 2pp 14220 342 24X Fiche 50-000,82/07/21,8208040523.
- 820B090244 Application to amend Licenses DPR-77 & DPR-79, revising Tach Spec Table 4 3-9 to incorporate downscale failure alarms & changing surveillance requirements for ice condenser doors. KAMMER.D S Tennesse Valley Authority 82/07/29 DENTON.H.R Office of Nuclear Reactor Regulation. Director ip 14271.052 24X Fiche 50-627.82/07/27,8208090244.
- --8208090248 Proposed Tech Spec Table 4 3-9, incorporating downscale failure alarms & changing surveillance requirements for ics condenser doors # Tennessee Valley Authority 82/07/29. 8pp 14271.053 24X Fiche 50-327,82/07/29.8208090244.
- 9208100078 Application for amend to Licenses DPR-77 & DPR-79, deleting pressurizer relief tank level instrumentation from Tech Spec Tables 3 3-9 & 4 3-6 KAMMERD 8 Tennessee Valley Authority 82/08/02, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p, 14296:149, 24x Fiche 50-327, 82/08/02, 8208100078.
- --B20Bi000B2 Proposed Tech Spec Tables 3 3-9 & 4.3-6.deleting pressurizer relief tank level instrumentation Justification encl * Tennessee Valley Authority. B2/08/02. 6pp 14296;130 24X Fiche: 50-327,82/08/02.820Bi0007B

- 820B170013 Confirms B20803 telcon authorizing deletion of pressurizer relief tenk level indication in auxiliary control room from Table 3 3-9 & 4 3-6 of Yech Specs. Amends to Tech Spec & FR notice will be forwarded when completed NOVAK.T M Assistant Director for Licensing B2/08/04, PARRIB.H Q, Tennessee Valley Authority 4pp 14373 268, 24X Fiche 50-327, 82/08/04, 9208170013
- 8208240152 Requests addi plant data to provide adequate data base for development of baseline signatures re neutron noise data collection sys First phase nearly complete Addi info needed to continue effont into next fuel cycle
 NOVAK.T M Assistant Director for Licensing 82/08/04 PARRIB.H @ Tennesses Valley Authority 2pp. 14548 171 24X
 Fichs.50-327.82/08/04.8208240152
- 8208100315 Forwards proposed integrated schedule of work activities for Unit 1 over next 18 months Final integrated schedule for Unit 2 work activities espected by first wk in Feb 1783, HILLB.L M Tennessee Valley Authority, 82/08/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 2ipp, 14297,142, 24% Fiche 50-327,82/08/06,8208100315
- 8208090194 Generic Ltr 62-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D @ Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356-332 24X Fiche. 50-000, 82/08/09, 8208090194
- 8208190179 Application to amend License DPR-77, changing license conditions re low temp overpressure protection, addl accident monitoring instrumentation, RCB vents, post-accident sampling, instruments for inadequate core cooling & emergency support HILLB: L M Tennessee Valley Authority 82/08/12 ADENSAM, E Licensing Branch 4 lipp 14386 358 24X Fiche, 50-327, 82/08/12, 8208190179
- 8208200207 Application to amend Licenses DPR-77 & DPR-79, changing Tach Spec Table 4 3-9 to incorporate downscale failure alarms & modifying surveillance requirements for ice condenser doors
 HILLS.L M Tennessee Valley Authority 82/08/12 DENYON.H R.
 Office of Nuclear Reactor Regulation. Director 2pp 14399, 257, 24X Fichs 50-327, 82/08/12, 8208200207
- --8208200216 Proposed revisions to Tech Spec Table 4 3-9, incorporating downscale failure alarms & Tech Specs 4.6 5 3 1 & 4 6.5,3 2 modifying surveillance requirements for ice condenser doors. * Tennessee Valley Authority 82/08/12 Spp 14399,259, 24X Fiche, 50-327,82/08/12,8208200207.
- 8208230366 Application for amend to Licenses DPR-77 & DPR-79, changing Tach Specs re flood protection electrical power sys & rod position indication sys & Tables 3 3-13.4 3-9.3,6-2 & 4 4-5 HILLSIL M Tennessee Valley Authority 62/09/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp. 14513:010, 24X Fichs 80-327.82/08/16.8208230366.
- --8208230375 Proposed Tech Specs re flood protection, electrical power sys & rod position indication sys & Tables 3.3-13.4.3-9.36-2 & 4.4-5 **

 * Tennesse Valley Authority. 82/08/16. 52pp. 14513-012. 24X Fiche: 50-327.82/
- 8208250376 Forwards mechanical snubber qualification test repts for Pacific Scientific Co Models PBA 1/4 PBA 100.as requested by NRC Only qualitative-type actuation tests planned at plants; beginning w/Browns Ferry 2 & Sequoyah 1 HILLS,L M Tennesses Valley Authority 82/08/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp 14541:002. 24X Fiche. 50-000, 82/08/18, 8208250376
- --B208250383 Revision A to "Qualification Test Rept for Model 1801104-05 PSA 1/4 Shock " WHITNEY,R F Pacific Scientific. TR 839 RA 82/03/18. 27pp. 14541.005. 24% Fiche 50-000, 82/08/18,8208250376
- --8208250387 Revision R to "Acceptance Test Procedure IT 527 P/N 1801104"

 LEVAN. H C. Pacific Scientific 79/11/09 13pp. 14541'032. 24X Fiche 50-000.82/08/18.8208250376
- ---8208250391 "Qualification Test Rept for Model 1801104-07 PBA 1/2 Shock Arrestor." WHITNEY.R.F Pacific Scientific TR 840 79/12/12. 27pp 14541:045 24X Fiche 50-000, 82/08/18, 8208250376
- --8208250402 Revision A to "Qualification Test Rept for Model 1801102-05 PBA 1 Shock Arrestor " HHITNEY,R.F. Pacific Scientific TR 841 RA 80/03/18, 24pp. 14541,085, 24X Fiche 50-000.82/08/18.8208250376,

- --8208250409 Revision T to "Acceptance Test Procedure IT 519 P/N 1801102 " LEVAN.H C Pacific Scientific 79/06/13 14pp 14541 111 24X Fiche 50-000, 82/08/18, 8208250376
- --8208250419 "Qualification Test Rept for Model 1801106-05 PSA-3 Shock Arrestor " WHITNEY,R F Pacific Scientific TR 842 80/01/22 27pp 14541 125 24X Fiche 50-000,82/08/18.8208250376
- --8208250421 Revision R to "Acceptance Test Procedure IT 524 for 1801106 " LEVAN.H C Pacific Scientific 79/02/16 13pp 14541 152 24x Fiche 50-000,82/08/18,8208250376
- --8208250426 "Qualification Test Rept for Model 1801103-07 P8A 10 Shock Arrestor " WHITNEY.R F Pacific Scientific TR 843 80/01/25 27pp 14541 166 24X Fiche 50-000.82/08/18.8208250376
- ---8209250431 Revision R to "Acceptance Test Procedure IT 523 P/N 1801103 " LEVAN, H C Pacific Scientific 79/08/15 14pp 14541 193 24X Fiche 50-000,82/08/18,8208250376
- --8208250437 Revision A to "Qualification Test Rept for Model 1801112-11 PRA-33 Shock Arrestor " WHITNEY, R F Pacific Scientific TR 845 RA 80/02/07 30pp 14541 207 24X Fiche 50-000, 82/08/18, 8208250376
- 8208250441 Revision J to "Acceptance Test Procedure IT 534 P/N 1801112 " LEVAN. H C Pacific Scientific 77/05/10 12pp 14541 237 24x Fiche 50-000, 82/08/18.8208250376
- 8208250443 "Qualification Test Rept for Model 1801119-11 PSA-100 Shock Arrestor " WHITNEY.R F Pacific Scientific TR 846 80/05/12 31pp 14341 249 24X Fiche 30-000,82/08/18,8208250376
- -8208250446 Revision H to "Acceptance Test Procedure IT 533 P/N 1801119"
 LEVAN.H.C Pacific Scientific 77/04/07 12pp 14541 280 24x Fiche 50-000,82/08/18,8208250376
- Inspection reports, IE Bulletins & correspondence
- 904210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) 'eakage " Svc list encl 'ORDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X iche 50-000,82/07/16.8204210393
- 04210395 IE Info Notice 81-26,Part 3,Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Suc list encl JORDAN.EL Division of Engineering & Quality Assurance 82/07/19 Hichigan. Univ of 112pp 14358 001 24X Fiche 80-000.82/07/19, 204210395
- 4210396 1E Info Notice 82-25, "Failures of Hiller Actuators Upon radual Loss of Air Pressure " Svc list encl
 DRDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X 1che:50-000,82/07/20,8204210396
- D4210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Iverpacks " Bvc list encl COBB.L.I Division of Fuel Facilities, Materials & Safeguards 82/07/20 24X Fiche 50-000,82/07/20,8204210397
- 1204210398 IE Info Notice 82-26, "RCIC & HPC1 Turbine Exhaust Check Valve Failures " Syr list encl JGRDAN: E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp, 14194 321 24X Fiche'50-000,82/07/22,8204210398
- 1204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl
 JORDAN, E L Division of Engineering & Guality Assurance 82/07/23
 Consolidated & Gison Co. of New York 122pp. 14380 115 24X
 Fiche. 50-000, 82/07/23, 8204210401
- 204210402 IE Info Notice 82-29, "Control Rad Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/23 Cansolidated Edison Co of New York 127pp 14194 120, 24X Fiche 50-000, 82/07/23, 8204210402

- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list enci JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24% Fiche 50-000, 82/07/26, 8204210403
- 8208030547 Ack receipt of 820720 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-327/82-ii & 50-328/82-ii & VERRELLI,D M Division of Project & Resident Programs 82/07/26 PARRIS,H 0 Tennessee Valley Authority 1p 14162 265 24% Fiche 50-327,82/07/26,8208030547
- --8208030562 Responds to NRC 820702 ltr re violations noted in IE Insp Repts 50-327/82-11 & 50-328/82-11 Corrective actions deficiencies evaluated to determine necessary design mods to evacuation alarm sys MILLS.L M Tennessee Valley Authority 82/07/20 O'REILLY, J P Region 2. Office of Director 2pp (4162 266 24X Fiche 50-327, 82/07/26, 8208030547
- 8208160323 Forwards IE Insp Repts 50-327/82-13 & 50-328/82-13 on 820708-09 No noncompliance upted VERRELLI.D M Division of Project & Resident Programs 82/07/27 PARRIS.H O Tennessee Valley Authority 2pp 14349 027 24X Ficke 50-327.82/07/27.8208160323
- --B20B160406 IE Insp Repts 50-327/82-13 & 50-328/82-13 on 820704-09 No noncompliance noted Major areas inspected full-scale emergency exercise

 ANDREWS, D. L. MARBTON, R. R., HUFFMAN, O. N. Division of Emergency Preparedness & Operational Support 82/07/23 12pp 14349 029 24% Fiche 50-327,82/07/27,820B160329
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8208160233 Forwards response IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Table providing list of bolt closures within RCPB experiencing leakage encl KAMMER, D S Tennessee Valley Authority 82/08/02 0'REILLY, J P Region 2, Office of Director 10pp 14347 131 24X Fiche 50~327,82/08/02.8208160233
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JGRDAN.E L Division of Engineering & Quality Assurance 62/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000,82/08/05,8204210407
- 8208090124 Forwards IE Safeguards Insp Repts 50-327/82-17 & S0-328/82-17 on 820719-23 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 82/08/03 PARRIS, H 0 Tennessee Valley Authority 2pp 14269 350 24X Fiche 50-327, 82/08/05, 8208090124
- --8208090127 IE Safeguards Insp Repts 50-327/82-17 & 50-328/82-17 on 820719-23 No noncompliance noted Major areas inspected security plan, security organization mgt & personnel Details withheld (ref 10GFR73 21).

 TILLMAN.A · MCGUIRE.D R Division of Project & Resident Programs 62/08/04 1p 14269 332 24X Fiche 50-327, 82/08/05, 8208090124
- 8208160436 Ack receipt of 820601 & 25 ltrs re IE Insp Repts 30-327/82-05 & 50-328/82-05 Corrective actions re Violation A will be examined at later date Violation B designated unresolved item Response requested within 20 days LEWIS.R C Division of Project & Resident Programs 82/08/09 PARRIS.H Q Tennessee Valley Authority 4pp 14349 199 24X Fiche.50-327,82/08/07,8208160436
- --8208160447 Responds to NRC 820610 telcon request re IE Insp Repts 50-327/82-05 & 50-328/82-05 Info supports denial of Items B & C MILLS.L M Tennessee Valley Authority 82/06/25 O'REILLY.J P Region 2: Office of Director 32pp 14349 203 24X Fiche 50-327,82/08/09.8208160436
- --8208160464 Reponds to NRC 820420 ltr re violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05 Corrective actions extensive OET schedule implemented to bring current level of caurse requirements completed up to 98% HILLS:L M Tennessee Valley Authority, 82/07/01 O'REILLY, J P. Region 2, Office of Director 14pp 14349 235 24% Fiche 50-327,82/08/09,8208160436

- --8208160482 Forwards IE Insp Repts 50-327/82-05 & 50-328/82-05 on 820329-0402 & notice of violation LONG.F J Division of Project & Resident Programs 82/04/20 PARRIS.H G Tennessee Valley Authority 2pp 14347 247 24X Fich
- --8208160492 Notice of violation from insp on 820329-0402 4 Division of Praject & Resident Programs 82/04/20 2pg 14349 251 24X Fache 50-327, 82/08/07.8208160436
- --8208160501 IE Insp Repts 50-327/82-05 & 50-328/82-05 on 820329-0402 Noncompliance noted failure to implement retraining required by procedures & failure to train outage craftsmen in GA program SKINNER, P H Division of Project & Resident Programs UPRIGHT, C M Division of Engineering & Technical Programs 82/04/19 5pp 14349 253 24X Fiche 50-327,82/08/09,8208160436

R Periodic operating reports & related correspondence

- 8208120201 Forwards monthly operating repts for June 1982 MASON.C C. Tennessee Valley Authority 82/07/12 Office of Resource Management, Director ip 14326 135 24X Ficke 50-327,82/07/12,8208120201
- --8208120202 Monthly operating repts for June 1982 EDDINGS.M . DUPREE, D Tennessee Valley Authority 82/07/12 23pp 14326 136 24X Fiche 50-327.82/07/12,8208120201
- 8208030339 Forwards seventh interim quarterly progress rept on R&D program re hydrogen combustion & control KAMMER, D 8 Tennessee Valley Authority 82/07/28 ADENSAM, E Licensing Branch 4 36pp 14157 001 24X Fiche 50-327,82/07/28,82080303339.

8 Reportable occurrences, LERs & related correspondence

- 8207050071 FOIA request for five documents re sys interaction in LWR, inadvertent containment spray for primary sys blowdown, biweekly rept for LER screening project & LER analysis & summary UDELL, R A Critical Mass Energy Project. 82/07/02 FELTON, J Division of Rules and Records ip 14559 261 24X Fiche 50-000,82/07/02.8207050071
- 8207150417 Forwards LER 82-076/03L-0 OREEN,H J Tennessee Valley Authority 82/07/12 O'REILLY, J P Region 2, Office of Director 1p 13850 337 24X Fiche 50-327.82/07/12,8207150417
- --8207150422 LER 82-074/03L-0 on 820413, ice bed temp monitoring sysdeclared inoperable due to failure to meet surveillance requirements Caused by broken wire to ac power sypply Wire repaired & moved to prevent recurrence RODERS, H. R. MARDINO, M. R. Tennessee Valley Authority 82/07/12 Region 2, 04/ice of Director 1p 13850 338 24X Fiche 30-327,82/07/12,8207150417
- 8208020080 Forwards LER 92-080/01T-0 OREEN.H J Tennessee Valley Authority 82/07/21 Q'REILLY, J P Region 2, Office of Director 1p 14144 094 24X Fiche 50-327, 82/07/21.8208020080
- --8208020083 LER 82-080/01T-0 on 820708, control & auxiliary vent board 181-8 tripped due to failure of control transformer to control bldg emergency pressurization fan Caused by improperly sired fuse Control transformer replaced KIRK, O, B, HARDING, MR Tennessee Valley Authority 82/07/21 Region 2, Office of Director 3pp 14144 095 24X fiche 50-327,82/07/21,8208020080
- 8208110107 NPDES noncompliance notification on 820707, diffuser discharged into TN River Caused by analytical error re inoperable titrator Titrator repaired & returned to svc. Spare parts for titrator on emergency order EL-ASHRY,M.T. Tennessee Valley Authority 82/07/22 MARLAR, J Environmental Protection Agency 2pp 14314 351 24X Fiche: 50-327, 82/07/22, 8208110109
- 9208160332 Forwards LER 82-086/03L-0 QREEN, H. J. Tennessee Volley Authority 82/07/26 O'REILLY, J P Region 2, Office of Director ip 14349 293 24X Fishe 50-327, 82/07/26, 8208160332
- 8208250001 Responds to FOIA request for five separate documents re incidents at facilities. Documents available in PDR FELTON-J M Division of Rules and Records. 82/07/26 UDELL.R A. Critical Mass Energy Project. ip 14559 262 24X Fiche 50-000, 82/07/26, 8208250001

- --8103250395 Event Evaluation IE 81-2 on 810211, pressurizer low level alarm sounded, shutting down RCP 1 & RCP 2 Caused by operator opening FCV 72-40, which opened RHR sys to containment spray header Personnel training procedures must be improved MODDS.H W Events Evaluation Section 81/03/10 JDRDAN.E.L Director's Office 7pp 14359 286 24X Fiche 50-000, 82/07/26, 8208250001
- --8103250402 Confirms 810220 telcon re insp results concerning cause of 810211 inadvertent containment spray event Administrative controls will be evaluated & revised to assure clearly delineated written rules for operator responsibilities O'REILLY, J P. Region 2. Atlanta, Office of the Director 81/02/23 PARRISHO Tennessee Valley Authority 2pp 14559 293 24X Fiche 50-000.82/07/26.8208250001
- B208030150 Forwards LER B2-086/03L-0 GREEN.H J Tennessee Valley Authority B2/07/27 O'REILLY, J P Ragion 2, Office of Director ip 14160 124 24X Fiche 50-327, 82/07/27, 8208030150
- --B20B030154 LER 82-086/03L-0 on 820627, auxiliary feedwater backpressure control valve 1-PCV-3-122 found leaking oil Caused by cracked tubing tree in valve operator oil line, due to overtightening by maint personnel Tee replaced KIRK. 0 B , HARDINO, M R Tennessee Valley Authority, 82/07/27, Ragion 2, Office of Director ip 14160 125 24X Fichs 50-327, 82/07/27, 820B030150
- B20B050409 Forwards LER B2-0B2/03L-0 OREEN:H J Tennessee Valley Authority, B2/07/29 O'REILLY, J P Region 2. Office of Director ip 14217 349 24X Fiche 30-327, B2/07/29, B20B050409 "
- --8208050417 LER 82-082/03L-0 on 820627, auxiliary feedwater mys automatic control valve 1-LCV-3-164 declared inoperable due to failure to control in automatic mode. Caused by slipped setpoint indicator control belt Belt realigned HARDING.H R. ROGERSH R. Tennessee Vallmy Authority 82/07/26 Region 2, Office of Director ip 14217 350 24X Fiche 50-327,82/07/29,8208050409
- 8208050327 Forwards LER 82-089/03L-0 QREEN:H J Tennessee Valley Authority 82/07/30 O'REILLY, J P Region 2, Office of Director 1p 14237 288 24X Fiche 50-327:82/07/30.8208050327
- --B208050333 LER B2-089/03L-0:on B20703,waste gas sys oxygen analyzer (0-02A-43-5000) declared inoperable due to failure to meet surveillance requirements caused by faulty zero setpoint in potentiameter Potentiometer replaced ROGERS.H R , HARDING.H R. Tennessee Valley Authority B2/07/30 Region 2, Office of Director ip 14237 289 24X Fiche 50-327,82/07/30,8208050327
- 8208050336 Forwards LER 82-088/03L-0 ORECN:H J Tennesses Valley Authority 82/07/30 O'REILLY, J P Region 2, Office of Director, Ip 14219, 349 24X Fiche 30-327, 82/07/30, 8208050336
- --B208050342 LER 82-088/03L-0 on 820702, containment hydrogen monitor (1-H2A-43-210) declared inoperable due to failure to meet surveillance requirements caused by clogged sample line orifice Clog blown loose.

 ROCERB, H. R., HARDINO, M. R. Tennessee Valley Authority 82/07/30 Region 2, Office of Director 1p 14219 350, 24X Fiche 50-327,82/07/30,8208050334
- 8208090191 Forwards LER 82-072/03L-0 ORECN.H J Tennessee Valley Authority 82/08/03 O'REILLY, J P Region 2. Office of Director. ip 14272 006 24X Fiche. 50-327. 82/08/03. 8208090191
- --8208090175 LER 92-092/03L-0 on 820705, auxiliary feedwater level control valve i-LCV-3-164 failed to open in automatic position during performance of 51-276 Probably caused by dirty contacts in hand switch Valve returned to svc on 820706 KIRK, O B . HARDING, M R Tennessee Valley Authority 82/08/03, Region 2, Office of Director ip 14272 007 24X Fiche 50-327, 82/08/03, 8208090191.
- 8208120113 Forwards LER 82-093/03L-0. GREEN,H, J. Tennessee Valley Authority. 82/08/04 O'REILLY, J P Region 2. Office of Director ip 14326 361 24X Fichs. 50-327: 82/08/04:8208120113.
- --8208120124 LER 82-093/03L-0 on \$20706, ice condenser intermediate deck doors 1 & 5 in bay 7 & door 1 in bay 10 failed lift test \$1-108 after being found iced over. Caused by failed heat tape causing line to rupture. Drain line repaired, HARDINO.M.R., KIRK.G.B. Tennessee Valley Authority, 82/08/04. Region 2. Office of Director. 1p. 14926-362, 24% Fichs. 50-327, 82/08/04. \$208120113.

- 820B100209 NPDES noncompliance notification on 820721, three samples of ward drainage pond effluent contained oil & grease contentrations exceeding daily max permit limitation Caused by tanker overflowing Oil absorbent pillows deployed EL-ASHRY.M T Tennossee Valley Authority 82/08/05 MARLAR, J Environmental Protection Agency 3pp 14294 247 24% Fiche 50-327,82/08/05.8208100209
- 8208200002 Forwards LER 82-094/03L-0 OREEN,H J Tennessee Valley Authority 82/08/10 O'REILLY, J P Region 2, Diffice of Director ip 14392 001 24x Fiche 50-327, 82/08/10, 8208200002
- --B20B20000B LER 82-094/03L-0 on 820712, diesel generator iA-A declared inoperable when bearing oil sight glass discovered broken Gause not stated Bearing oil sight glass replaced & reservoir filled w/oil ROMINE.W D , HARDING.M R Tennessee Valley Authority 82/08/10 Region 2. Office of Director ip 14392 002 24X Fiche 50-327,82/08/10.8208200002
- 8208270207 Forwards LER 82-075/01T-0 GREEN.H J Tennessee Valley Authority 82/08/18 G'REILLY, J P Region 2, Office of Director 1p 14563 194 24X Fiche 30-327.82/08/18,8208270207
- ---9209270218 LER 82-095/017-0 on 920805, during Westinghouse solid state protection sign review discovered that undetectable failure could exist in online testing circuits for sys relays Test devised to determine position of switch circuits ROMENE. W D . HARDING, M R Tennessee Valley Authority 82/08/18 Region 2. Office of Director 1p 14563 195 24X Fiche 50-327, 82/08/18,8208270207
- DOCKET 50-328 SEGUDYAH NUCLEAR PLANT, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8208160473 Confirms 820708 & 20 telcons re corrective action to resolve deficiencies in emergency preparedness program Areas include training for inplant emergency organization & upgrading technical support ctr Action will be completed by 821109 D'REILLY./P Region 2. Office of Director 82/07/20. PARRIB.H G Tennessee Valley Authority 2pp 14348 175 24X Fiche 50-327.82/07/20.8208160473
- B208030547 Ack receipt of B20720 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-327/82-11 & 50-328/82-11 WERRELLI.D M Division of Project & Resident Programs B2/07/26 PARRIS.H 0 Tennessee Valley Authority 1p 14162 265 24X Fiche 50-327, 82/07/26, 8208030547
- --B208030562 Responds to NRC B20702 ltr re violations noted in IE Insp Repts 50-327/82-ii & 50-328/82-ii Corrective actions deficiencies evaluated to determine necessary design mods to evacuation alarm sys MILLS.L M Tennessee Valley Authority B2/07/20 O'REILLY, J P Region 2. Office of Director 2pp 14162 R66 24X Fiche, 50-327, 82/07/26, 8208030547
- 820B160323 Forwards IE Insp Repts 50-327/82-13 & 50-328/82-13 on 820708-09 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/07/27 PARRIES H G Tennessee Valley Authority 2pp 14349 027 24X Fiche
- --B20Bi60406 IE Insp Repts 90-327/82-i3 & 50-328/82-i3 on B20704-09 No noncompliance noted Major areas inspected full-scale emergency precise.

 ANDREWB, D L , JENKINS, O R Division of Emergency Preparedness & Operational Bupport B2/07/23 12pp 14349 029 24X
 Fiche 50-327, B2/07/27, 8208160323
- 8208090124 Forwards IE 8afeguards Insp Repts 50-327/82-17 & 50-328/82-17 on 820719-23 No noncompliance noted VERRELLI,D Division of Project & Resident Programs 82/08/05 PARRIS,H O Tennesses Valley Authority 2pp. 14269 350 24% Fiche 50-327,82/08/05,8208090124
- --8208090127 IE Safeguards Insp Rapts 50-327/82-17 & 50-328/82-17 on B20719-23. No noncompliance noted, Major areas inspected security plan security organization mpt & personnel Datails withheld (ref 10CFR/3 21)

 TILLMAN, A Division of Project & Resident Programs 82/08/04 ip 14269 352 24X Fiche 50-327,82/08/05,8208090124.
- 8208230004 Forwards proposed revision to physical security plan Rev(sion withheld (ref 10CFR73 21), KAMMER,D B Tennessee Valley Authority 82/08/17 ADENSAM,E Licensing Branch 4, ip, 14517:288 24X Fiche 50~327,82/08/17, 82

I Financial information

- 8208100002 Forwards "TVA Power Program Summary." Vol 2, for fiscal yr onding 810630 & "1981 Power Program Bummary." for fiscal yr ending 810930, per Section 50 71(b) of 10CFR50 MILLS.L M Tennessee Valley Authority 82/08/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 118pp 14274 024 24% Fiche 50-000:82/08/06.8208100002
- 8208270457 Forwards financial statements for FY81, power quarterly rept & internal cash flow projection MILLS,L M Tennessee Valloy Authority 82/08/23 SALTZMAN, J Assistant Director for State & Licensee Relations 48pp 14566 135 24x Fiche 50-000,82/08/23,8208270457

J Insurance & indemnity information

- 820G310200 Advises that onsite property damage insurance has been purchased, in accordance w/10CFR50 54 Coverage status encl MLLCs.L M Tennessee Valley Authority 62/08/25 SALTZMAN, J Assistant Director for State & Líconsee Relations 2pp 14493 160 24% Fiche 50-000.82/08/25.8208310200
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CRGR Svc list encl
 DIRCKS.H J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24% Fiche 50~000,82/07/02.8207080064
- 8208030021 Forwards Amends 14 & 15 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends authorize 30-day changes in requirement re containment sump level instrumentation.

 ADENSAME 0 Licensing Branch 4 82/07/07 PARRIS,H 0 Tennessee Valley Authority 3pp 14237 332 24X Fiche 50-327,82/07/07,8208030021
- --B208030023 Amends 14 & 15 to Licenses DPR-77 & DPR-79, respectively, authorizing 30-day changes in requirement re containment sump level instrumentation operability, ADENSAM.E O Licensing Branch 4 62/07/07 6pp 14237 334 24X Fiche 50-327, 62/07/07, 8208030021
- --8208030026 Safety evaluation supporting Amends 14 & 15 to Licenses PR-77 & DPR-79, respectively 4 Office of Nuclear Reactor Regulation, Director 82/07/07 2pp 14237 340 24% Ficha 50-327, 82/07/07, 8208030021
- --B20B030029 Notice of issuance & availability of Amends 14 & 15 to Licenses DPR-77 & DPR-79, respectively ADENSAM, E. G. Licensing Branch 4 B2/07/07 2pp 14237 342 24X Fiche 50-327, 92/07/07, B20B030021
- 8208040523 Notification of 820804 meeting w/utils in Bethesda.MD to discuss results of R&D program for hydrogen control & combustion in ice condenser plants STANLE.C Licensing Branch 4 82/07/21 ADENBAM,E 0 Licensing Branch 4 2pp 14220 342 24X Fiche 50-000,82/07/21.8208040523
- 820B090244 Application to amend Licenses DPR-77 & DPR-79, revising Tech Spec Table 4 3-9 to incorporate downscale failure alarms & changing surveillance requirements for ice condenser doors. KAMMER.D & Tennessee Valley Authority 82/07/29 DENTON,H R. Office of Nuclear Reactor Regulation, Director ip 14271 052 24X Fiche 50-327,82/07/29,8208090244
- --8208090248 Proposed Tech Spec Table 4 3-9, incorporating downscale failure alarms & changing surveillance requirements for ica condenser doors
 * Tennessee Valley Authority 82/07/29 8pp 14271 053 24X Fiche 50-327,82/07/29,8208090244
- 820Bi00078 Application for amond to Licenses DPR-77 & DPR-79, deleting pressurizer relief tank level instrumentation from Tech Bpsc Tables 3 3-9 & 4 3-6 KAMHER, D S Tennesses Valley Authority 82/08/02 DENTON, H. R Office of Nuclear Reactor Regulation, Director ip 14296.149 24X Fiche 50-327, 82/08/02, 8208100078
- --8208100082 Proposed Tech Spec Tables 3 3-9 & 4 3-4, deleting pressurizer relief tank level instrumentation Justification encl * Tennessee Valley Authority 82/08/02 6pp 14296 150 24X Fiche 30-327, 82/08/02 B208100078

- 8208170013 Confirms 820803 telcon authorizing deletion of preseurizer relief tank level indication in auxiliary control room from Table 3 3-9 % 4 3-6 of Tech Specs Amends to Tech Spec & FR notice will be forwarded when completed NOVAK,T M Assistant Director for Licansing 82/08/04 PARRIS;H & Tennesse Valley Authority 4pp 14373 248 24X Fiche 50-327, 82/08/04, 8208170013
- 820B100315 Forwards proposed integrated schedule of work activities for Unit 1 over next 18 months. Final integrated schedule for Unit 2 work activities expected by first wk in Feb 1983 MILLS.L M Tennessee Valley Authority 82/08/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 21pp 14297 142 24X Fiche 50-327,82/08/06,8208100315
- 8208090194 Ceneric Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT.D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208200207 Application to amend Licenses DPR-77 & DPR-77, changing Tech Spec Table 4 3-9 to incorporate downscale failure alarms & modifying surveillance requirements for ice condenser doors
 HILLS, L M Tennessee Valley Authority 82/08/12 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 14399 257
 24X Fiche 50-327, 82/08/12, 8208200207
- --8208200216 Proposed revisions to Tech Spec Table 4 3-9, incorporating downscale failure alarms & Tech Specs 4 6,5 3 1 & 4 6 5 3 2 modifying surveillance requirements for ice condenser doors * Tennessee Valley Authority 82/08/12 8pp 14399 259 24X Fiche 50-327,82/08/12,8208200207
- 8208230366 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Specs re flood protection, electrical power sys & rod position indication sys & Tables 3 3-13,4 3-9,3,6-2 & 4 4-5 HILLS,L M Tennessee Valley Authority 82/08/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 14513 010 24% Fiche 50-327,82/08/16,8208230366.
- --8208230375 Proposed Tech Specs re flood protection, electrical power sys & rod position indication sys & Tables 3 3-13,4 3-9, 3 6-2 & 4 4-5 * Tennessee Valley Authority 82/08/14 52pp 14513,012 24X Fiche 50-327,82/08/16,8208230366
- 8208250376 Forwards mechanical snubber qualification test repts for Pacific Scientific Co Models PSA 1/4 PSA 100, as requested by NRC Only qualitative-type actuation tests planned at plants, beginning w/Browns Ferry 2 & Sequoyah I MILLS, L. M. Tennessee Valley Authority. 82/08/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 14541 002 24X Fiche 50-000,82/08/18,8208230376
- --8208250383 Revision A to "Qualification Test Rept for Model 1801104-05 PSA 1/4 Shock " WHITNEY:R F Pacific Scientific TR 839 RA 82/03/16 27pp 14541.005 24X Fiche 50-000,82/08/18,8208250376
- --8208250387 Revision R to "Acceptance Test Procedure IT 527 P/N 1801104 " LEVAN, H C Pacific Scientific 79/11/09, 13pp 14541,032 24X Fiche, 50-000, 82/08/18, 8208250376
- --8208250391 "Qualification Test Rept for Model 1801104-07 PBA 1/2 Bhock Arrestor "WHITNEY R.F Pacific Scientific TR 840 79/12/12 27pp. 14541 045 24X Fithe 50-000, 82/08/18, 8208250376
- --8208250402 Revision A to "Qualification Test Rept for Model 1801102-05 PBA 1 Shock Arrestor." WHITNEY:R F Pacific Scientific TR 841 RA 80/03/18, 24pp 14541 085 24X Fiche 50-000,82/08/18,8208250376.
- --8208250409 Revision I to "Acceptance Test Procedure IT 519 P/N 1801102 " LEVAN, H C Pacific Scientific 79/06/13 14pp, 14541.111 24X Fiche 50-000, 82/08/18.8208230376
- --8208250415 "Qualification Test Rept for Model 1801106-05 PSA-3 Bhock Arrestor " WHITNEY.R F Pacific Scientific TR 842, 80/01/22, 27pp 14541 125 24X Fiche 50-000, 82/08/18,8208250374,
- --B208250421 Revision R to "Acceptance Test Procedure IT 524 for 1801104" LEVAN, H C Pacific Scientific 79/02/16, 13pp 14541,152, 24X Fiche 50-000,82/08/18,8208280376

- --8208250426 "Qualification Test Rept for Model 1801103-07 P8A 10 Shock Arrestor " WHITNEY.R F Pacific Scientific TR 843 80/01/25 27pp 14541 166 24X Fich# 50-000.82/08/19.8208250376
- --8208250431 Revision R to "Acceptance Test Procedure IT 523 P/N 1801103 " LEVAN, H C Pacific Scientific 79/08/15 14pp. 14541 193. 24X Fiche: 50-000, 82/08/18, 8208250376
- --8208250437 Revision A to "Gualification Test Rept for Model 1801112-11 PSA-35 Short Arrestor" WHITNEY.R F Pacific Scientific TR 945 RA 80/02/07 30pp 14541 207 24X Fichs 50-000, 82/08/18, 8208250376
- --8208250441 Revision J to "Acceptance Test Procedure IT 534 P/N 1801112" LEVAN, H C Pacific Scientific 77/05/10 12pp 14541 237 24X Fiche 50-000, 82/08/18, 8208250376
- --8208250443 "Qualification Test Rept for Model 1801119-11 P8A-100 Shock Arrestor " WHITNEY.R F Pacific Scientific TR 846 80/05/12 31pp 14541 247 24X Fiche 50-000, 82/08/18, 8208250376
- --8208250446 Revision H to "Acceptance Test Procedure IT 533 P/N 1801119 " LEVAN, H C Pacific Scientific 77/04/07 12pp 14541 280 24X Fichs 50-000,82/08/18,8208250376.
- Q Inspection reports: IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26. Part 9, Suppl 1, "Clarification of Placement of Parsonnel Monitoring Devices for External Radiation " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19 Michigan. Univ of 112pp 14358 001 24% Fiche 50-000, 82/07/19, 8204210395
- 9204210376 IE Info Notice 92-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York 112pp. 14381 001. 24X Fiche 50-000, 82/07/20, 8204210376
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluorida Overpacis " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards. 82/07/20 Canolidated Edison Co of New York 71pp. 14357 276 24X Fiche 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-24, "RGIC & HPGI Turbine Exhaust Check Valve Failures." 8vc list encl JRRDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194;321 24X Fiche: 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl URDAN,E L Division of Engineering & Quality Assurance S2/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fichs 50-000,82/07/23,8204210401
- 820A210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list enci. JORDAN, E. L. Division of Engineering & Guality Assurance. 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X Fichs 30-000.82/07/23.8204210402
- 820A210A03 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl URDAN.E. L. Division of Engineering & Quality Assurance. 82/07/26 Consolidated Edison Co. of New York 12ipp. 14357,013 24X Fiche.50-000.82/07/26.8204210403
- 8208030547 Ack receipt of 820720 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-327/82-11 & 50-328/82-11 VERRELLI, D M Division of Project & Resident Programs 82/07/26 PARRIS. H 0 Tennessee Valley Authority 1p 14162, 265 24 X Fichs. 20-327. 82/07/26 8208030847

- --8208030562 Responds to NRC 820702 itr reviolations noted in IE Insp. Regts 50-327/82-11 & 50-328/82-11 Corrective actions deficiencies evaluated to determine necessary design mode to evacuation alarm syg. MILLS.L. M. Tennessee Valley Authority 82/07/20 O'REILLY, J.P. Region 2. Office of Director 2pp 14162 266 24X Fiche 50-327, 82/07/26, 8208030547
- 8208160323 Forwards IE Insp Repts 50-327/62-13 & 50-328/82-13 on 820708-09 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/07/27 PARRIS.H G Tennessee Valley Authority 2pp 14349 027 24X Fiche 50-327.82/07/27,8208160323
- --8208160406 IE Insp Repts 50-327/82-13 & 50-328/82-13 on 820706-09 No noncompliance noted Major areas inspected full-scale emergency exercise ANDREWS, D L , MARSTON, R R , HUFFMAN, O N Division of Emergency Preparedness & Operational Support 82/07/23 12pp 14349 029 24X Fiche 50-327, 82/07/27, 8208160323
- 8204210405 IE Info Notice 82-31, "Gverexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 820B160233 Forwards response IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Table providing list of bolt closures within RCPB experiencing leakage encl KAMMER, D S Tennessee Valley Authority B2/08/02 O'REILLY, J P Region 2, Office of Director 10pp 14347 131 24X Fiche 50-327,82/08/02,820B160233
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list enc!
 JORDAN.E L Division of Engineering & Guality Assurance, 82/08/05
 Consolidated Edison Co of New York 1170p 14388 201 24X
 Fiche 50-000 82/08/05,8204210407
- 8208090124 Forwards IE Safeguards Insp Repts 50-327/82-17 & 50-328/82-17 on 620717-23 No noncompliance noted VERRELLI.D Division of Project & Resident Programs 82/08/05 PARRIS.H 0, Tennessee Valley Authority 2pp 14269 350 24X Fiche 50-327,82/08/05,8208090124
- --8208070127 IE Safeguards Insp Repts 50-327/82-17 & 50-328/82-17 on 820719-23 No noncompliance noted Major areas inspected security plans security organization mgt & personnel Details withheld (ref 10CR73 21)
 TILMAN.A . HCOUIRE. D R Division of Project & Resident Programs 82/08/04 ip 14269 352 24% Fiche 50-327.82/08/05,8208090124
- 8208160436 Ack receipt of 820601 & 25 itrs re IE Insp Repts 50-327/82-05 & 50-328/82-05 Corrective actions re Violation A will be examined at later date Violation B designated unresolved item Response requested within 20 days LEWIB.R.C Division of Project & Resident Programs 82/08/09 PARRISB.N 0 Tennessee Valley Authority 4pp 14349 199 24X Fiche, 50-327, 82/08/09, 8208160436
- --9208160447 Responds to NRC 820610 telcon request re IE Insp Repts 50-327/82-05 & 50-328/82-05 Info supports denial of Items B & C MILLS.L H Tennessee Valley Authority 82/06/25 O'REILLY.J P Region 2. Office of Director 32pp 14349 203 24X Fiche 50-327, 82/08/09,8208160436
- --B208160464 Reponds to NRC 820420 lir re violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05 Corrective actions: extensive OET schedule implamented to bring current level of course requirements completed up to 95%. MILLE, L. M. Tennessee Valley Authority B2/07/01 O'REILLY, J.P. Region 2, Office of Director 14pp 14347 235 24% Fiche: 50-327, 82/08/09, 8208160436
- ---B208160482 Forwards IE Insp Repts 50-327/82-05 & 50-328/82-05 on B20329-0402 & notice of violation LONG, FJ Division of Project & Resident Programs 82/04/20 PARRIS, H O Tennessee Valley Athority, 2pp 14349 249 24X Fiche, 50-327, 82/08/09, 8208160436
- --8208160492 Notice of violation from inep on 820329-0402 * Division of Project & Resident Programs B2/04/20 2pp 14349-251 24X Piche-50-327,82/08/09,8208160436
- --8208160501 IE Insp Repts 50-327/82-05 & 50-328/82-05 on 820329-0402. Noncompliance noted failure to implement retraining required by procedures & failure to train outage craftsmen in GA program SKINNER:P H. Division of Project & Resident Programs UPRIOHT.C M. Division of Engineering & Technical Programs 82/04/19 Spp 14349 253 24X Fiche 50-327.82/08/09.8208160436

- R Periodic operating reports & related correspondence
- 820B120201 Forwards monthly operating repts for June 1982 MASON,C C Tennessee Valley Authority 82/07/12 Office of Resource Management, Director 1p 14326 135 24X Fiche 50-327, 82/07/12, 8208120201
- --8208120202 Monthly operating repts for June 1982 EDDINGS.M., DUPREE.D. Tennessee Valley Authority 82/07/12 23pp 14326 136 24X Fiche 50-327,82/07/12,8208120201
- 8208030339 Forwards seventh interim quarterly progress rept on R&D program re hydrogen combustion & control KAMMER.D S Tennessee Valley Authority 82/07/28 ADENSAM. E Licensing Branch 4 36pp 14157 001 24X Fiche 50-327,82/07/28,8208030339
- S Reportable occurrences. LERs & related correspondence
- 8208020226 Final deficiency rept for Sequoyah, second interim rept for Watts Bar & fifth for Bellefonte, Hartsvills, Phipps Bend & Yellow Creek re inconsistent establishment of insp program Next rept for Watts Bar & Bellefonte expected 830103 MILLS,L M Tennesses Valley Authority 82/07/20 0'REILLY, J P Region 2, Office of Director & Opp 14152 344 24X Fiche 50-000, 82/07/20, 8208020226
- 820Bi10107 NPDES noncompliance notification on 820707, diffuser discharged into TN River Caused by analytical error reinoperable titrator Titrator repaired & returned to syr Spare parts for titrator on amergency order EL-ASHRY.M T Tennesses Valley Authority 82/07/22 MARLAR, J Environmental Protection Agency 2pp 14314 351 24X Ficha 50-327, 82/07/22, 8208110109
- 8208020163 Forwards LER 82-081/03L-0 OREEN.H J Tennessee Valley Authority 82/07/23 O'REILLY, J P Region 2, Office of Director. ip 14141 007 24X Fichs 50-328.82/07/23.8208020163
- --8208020167 LER 82-081/03L-0 on 820628 automatic control valve 1-PCV-3-122 failed to open on demand twice First event caused by low oil in hydraulic reservoir due to leaking fitting Becond event caused by foreign mati in oil ROSERS.H R . HARDING.M R Tennessee Valley Authority 82/07/23 Region 2. Office of Director ip 14141 008 24% Fiche 50-328,82/07/23.8208020163
- 8208020375 Forwards LER 82-083/03L-0 OREEN.H J Tennesse Valley Authority 82/07/23 G'REILLY, J P Region 2, Office of Director. ip 14150 116 24X Fithe 50-328.82/07/23.8208020375
- --B208020379 LER 82-0B3/03L-0 on B20624, during Mode 3 operation, containment isolation valve 2-FCV-43-61 would not open Caused by condulet cover pinching wire which resulted in ground in circuit Damaged wire spliced & tested ROMINE.W D . HARDING:M R Tennessee Valley Authority 82/07/23 Region 2. Office of Director ip 14150 117, 24X Fiche 50-32B,82/07/23.8208020375
- 8208050100 Forwards LER 82-085/03L-0 OREEN H J Tennasse Valley Authority 82/07/27 D'REILLY, J F Region 2. Office of Director 1p 142/3 185 24X Fiche 50-328, 82/07/29, 8208050100
- --B20B0B0105 LER 82-0B9/03L-0:on B20705 & 06, lower compartment average air temp was greater than 120 f. Caused by air discharging through lower compartment air cooler fan 2B-B which was out of svc. reducing air flow Flow passage blocked KIRK, 0 B., HARDINO, M R Tennessee Valley Authority 82/07/29 Region 2. Office of Director 1p 14213 186 24X Fiche 50-328, 82/07/29, 8208030100
- 8208050108 Forwards LER 82-084/03L-0 GREEN.H J Tennesse Valley Authority 82/07/29 O'REILLY, J. P Region 2. Office of Director 1p 14213, 180 24X Fiche 50-328, 82/07/29, 8208050108
- --B20B050111 LER B2-084/03L-0.on B20708.Foxbaro model E-110M-H9AE1 containment pressure transmitter 2-PDT-30-43 found inoperable Probably caused by instrument drift.Pressure transmitter recelibr RODERS.H R , HARDING.H R , Tennessee Valley Authority 82/07/29 Region 2. Office of Director ip 14213 181. 24X Fichs 50-328.82/07/29.8208050108.

- 8208050446 Revised final deficiency rept re foam seals in mechanical pipe sleeves Initially reported on 910416 Study indicated no significant impact of seals on pipe stresses Documents will be developed for sleeve designers & piping analysts MILLS, L. M. Tennessee Valley Authority 82/07/27 O'REILLY J. P. Region 2. Office of Director 4pp 14218 033 24X Fiche 30-328,82/07/29,8208050446
- 8208050158 Forwards LER 82-090/03L-0 GREEN.H J Tennessee Valley Authority 82/07/30 O'REILLY, J P Region 2, Office of Director 1p 14212 083 24x Fiche 50-328, 82/07/30, 8208050158
- --8208050161 LER 82-090/03L-0 on 820703, auxiliary feedwater level control valve 2-LCV-3-171 opened approx 2/3 open Probably caused by failure to retighten diaphragm spring tension adjustment nut during prior maint Tension adjusted KIRK, 0 B. HARDINO, M R. Tennessee Valley Authority 82/07/30 Region 2. Office of Director ip 14212 084 24X Fiche 50-328,82/07/30,8208050158
- 8208120254 Forwards LER 82-087/03L-0 GREEN.H J Tennessee Valley Authority 82/08/04 O'REILLY, J P Region 2, Office of Director ip 14324 270 24X Fiche 50-328, 82/08/04, 8208120254
- --820B120262 LER 82-087/03L-0 on 820709 & 13, one point of ire condenser ire bed temp exceeded 27 F Caused by loss of cold air through uncovered floor drains & unseated inlet doors & humidity entering through open drain line Temp reduced KIRK,G B, HARDING,H R Tennessee Valley Authority 82/08/04, Region 2, Office of Director 2pp 14324 271 24X Fiche 50-328,82/08/04,820B120294
- 8208120312 Forwards LER 82-091/03L-0 GREEN.H J Tennessee Vallmy Authority 82/08/04 D'REILLY, J P Region 2, Dffice of Director 1p 14324 263 24X Fiche 50-328,82/08/04.8208120312
- --8208120315 LER 82-091/03L-0 on 820709, during performance of 8I-166, upper limit switch of steam generator bloodown containment isolation valve 2-FCV-1-7 found out of adjustment Cause not stated Switch adjusted ROMINE, W D , HARDING, M R Tennessee Valley Authority 82/08/04 Region 2, Office of Director 1p 14324 264 24X Fiche 50-328,82/08/04,8208120312
- 8208100209 NPDES noncompliance notification on 820721, three samples of yard drainage pand effluent contained oil & grease concentrations exceeding daily max permit limitation Caused by tanker overflowing. Oil absorbent pillows deployed EL-ASKRY.N T Tennesser Valley Authority 82/08/05 MARLAR, J Environmental Protection Agency 3pp 14294 247 24X Fiche, 50-327, 82/08/05, 8208100209.
- 8208270298 Forwards LER 82-096/03L-0 OREEN.H J Tennessee Valley Authority 82/08/18 D'REILLY, J. P Region 2. Office of Director ip 14564.169 24X Fichs 50-328.82/08/18.8208270278
- --8208270304 LER 82-094/03L-0 on 820720, while in Hode i, safety injection pump failed to start w/handswitch in start position. Caused by improperly locked locking ring on plug connector in back of handswitch. Connector cloaned & reinstalled ROMINE.W D , HARDING.W R Tennessee Valley Authority 82/08/18 Region 2, Office of Director ip 14544 170, 24X Fiche. 80-328, 82/08/18, 8208270278
- 8208300211 Sixth interim deficiency rept re procurement control audits Initially reported on 610316 TVA quality engineering branch response to audit deficiencies undergoing review. Next rept due by 821007
 MILLS.L. H. Tennessee Valley Authority 82/08/23 O'REILLY. J. P. Region 2. Office of Director ip 14679 196 24X
 Fiche 50-000,82/08/23.8208300211
- DOCKET 50-329 HIDLAND PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for UL & holders of CP re Commission approved charter for CROR, Svc list enci DIRCKS, W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194.001, 24X Fichs. 50-000, 82/07/02, 8207080064

- 8208090220 Forwards systematic assessment of licensee performance for Jul 1980-June 1981 Working meeting will be arranged to clarify disputed issues KEPPLER. J G Region 3. Office of Director B2/07/19 COOK. J W Consumers Power Co 70pp 14272 073 24X Fiche 50-329,82/07/19,8208090220
- 8208040143 Forwards "Pump & Valve Inservice Testing Plan "
 COOK.J W Consumers Power Co 82/07/21 DENTON.H R Office of
 Nuclear Reactor Regulation. Director 3pp 14189 318 24X
 Fiche 30-329.82/07/21.8208040143
- --B208040148 "Pump & Valve Inservice Testing Plan," Revision O BOUMENS, J O , BRADER, C R , KRAMER, C E Consumers Power Co B2/07/0B 284pp 14189 321 24X Fiche. 50-329, 82/07/21, B208040143
- 8208090055 Documents commitments re concrete wall cracks in Category I safety grade bldgs affected by soil fill Repair program will be completed prior to first refueling Crack repairs apply to generator bldg & svc water pump structure COOK. J W Consumers Power Co 82/08/02 DENTON. H R Office of Nuclear Reactor Regulation. Director 5pp 14270 001 24% Fiche 50-329.82/08/02.8208090055
- 8208160308 Forwards latest revisions of piping design info for Midland Unit 2 decay heat removal & core flooding sys Info comprises Revision 8 of matl for NRC independent confirmatory piping analysis M/one oversize drawing Aperture card is in PDR CDOK. J W Consumers Power Co 82/08/05 DENTON. H R Office of Nuclear Reactor Regulation, Director 21pp 14347,142, 24X Fiche 50-329,82/08/05,8208160308
- --B20B160335 Revision 2 to "Design Spec for Component Bupports for Nuclear Svc Piping for Hidland 1 & 2." Sheet I.App C Revision data illegible Incomplete B&W Spec 18-1391000012-01 encl RIATID Bechtel Corp B2/08/05 104pp 14347 163 24X Fiche 50-329, 82/08/05 820B16030B
- --8208160342 Revision 6 to "Spec for Earthquake Resistance Design of Equipment Located in Reactor Bidg for Midland Unit 1 & 2 " * Bechtel Corp 82/03/19 98pp 14347 267 24X Fiche 30-329,82/08/05.8208160308
- 8208090194 Ceneric Ltr 82-14 to all reactor litensees, holders of CP & applicants re submittel of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENNUT.D 0 Division of Licensing 82/08/09. Consolidated Edison Co. of New York. ip 14356 332 24X Fiche 50-000.82/08/09, B208090194
- 820B120221 Forwards "Quality Plan for Underpinning Activities" & "Quality Plan for Remedial Boils Activities & Boils-Related Work in Quality Areas "
 COOK, J W Consumers Power Co 82/08/09. DENTON, H R Office of Nuclear Reactor Regulation. Director App 14325 322 24X
 Fiche 50-329,82/08/09,8208120221
- --8208120223 "Guality Plan for Underpinning Activities," Revision 3 BIRD.W . 8008, A J . MDONEY, J Consumers Power Co MPOP-1 RO3 82/07/26 23pp 14325-326 24X Fiche 50-329,82/08/09,8208120221
- 8208160393 Confirmatory action ltr're stop work order on remedial soils / area Region 3 approval required prior to lifting of stop work order in whole or part.

 KEPPLER.J.G Region 3. Office of Director 82/08/12. COOK.J.W Consumers Power Co 1p 14348 352 24% Fiche 50-327,82/08/12,8208160393
- 8208190137 Formalizes proposals made at 820720 Meeting re NURE9-0737, Item II K 3 30. "Revised Small Break LOCA Methods "
 Assurance of core cooling being evaluated under ongoing small break LOCA methods program
 CODK, J W. Consumbrs Power Co 82/08/12 DENTON, H. R Office of Nuclear Reactor Regulation, Director 11pp. 14381, 084, 24X Fiche. 50-329, 82/08/12, 8208190137
- 8208200249 Requests details re remedial soils activities scheduled for Aug 1982 Activities determined noncritical Portion of 1tr re procedures withheld.

 84HAFER: W D Region 3, Office of Director. 82/08/12. HILLER: D. B. Consumers Power Co. 3pp 14399-028 24X Fiche 50-329,82/08/12.

- 8208230376 Submits list of critical work activities re remedial soil work scheduled for Aug 1982 Authorization for proceeding u/work granted SHAPER.W D Region 3, Office of Director 82/08/13 MILLER.D B Consumers Power Co. 3pp. 14312-326 24X Fiche 50-329,82/08/13.8208230376
- 8208240308 Forwards NRC & CPC work authorization procedure developed to provide mechanism for Region 3 review & authorization of activities to be implemented at site as described in ASLB order SHAFER. W D NRC No Detailed Affiliation Given 82/08/16 NRC No Detailed Affiliation 2pp 14520 217 24% Fiche 50-329, 82/08/16, 8208240308
- --B208240309 NRC & CPC work authorization procedure MODNEY, J A Consumers Power Co SHAFER, H D NRC ~ No Detailed Affiliation Olven B2/08/12 4pp 14520 219 24X Fiche 50~329, B2/08/16.8208240308
- B20B2706B2 Forwards "Control of Heavy Loads at Nuclear Power Plants, Midland Units 1 & 2." draft technical evaluation rept NOVAK, T M Assistant Director for Licensing B2/08/16 CODK, J W. Consumers Power Co. 2pp 14683 140 24X Fishe 50-327,82/08/16.
- --8208270692 "Control of Heavy Loads at Nuclear Power Plants, Midland Units 1 & 2," draft technical evaluation rept DIXON, B W. STICKLEY, T H E040, Inc 82/05/31 NRC No Detailed Affiliation Given 37pp 14683 142 24X Fich # 50~329,82/08/16.8208270682
- B208270483 Forwards guidance useful in developing program for TMI
 Action Item II B 3, "Post-Accident Sampling Capability"
 Encl info Tepresents sampling of methods acceptable to NRC
 W/o encl
 ADENSAM. E G Licensing Branch 4, 82/08/18 COOK, J W Consumers
 Power Ca ip 14683 137 24X Fiche 50-329,82/08/18,8208270683
- 8208270246 Forwards Amend 107 to application for CPs & OLs containing Revision 3 to security plan & Revision 2 to safeguards contingency plan Revisions resolve all NRC 820601 SER review comments COOK. J W Consumers Fower Co 82/08/24 DENTON, H R Opplice of Nuclear Reactor Regulation. Director 2pp 14564 150 24% Fiche 50-329.82/08/24,8208270246
- --B208270253 Amend 107 to application for CPs & OLs containing Revision 5 to security plan & Revision 2 to safeguards contingency plan Revisions withheld (ref 10CFR73 21) COOK.J W Consumers Power Co 82/08/24 ip 14964 152 24X Fiche 50-329,82/08/24.8208270246
- 820831010B Forwards certified mat1 test rept for penetration sleeve in penetration 22-9B, inadvertently omitted from util 820330 ltr COCK, J H Consumers Power Co 82/08/25 DENTON, H R Gffice of Nuclear Reactor Regulation, Director 6pp 14695 076 24X Fiche 50-327, 82/08/25, 8208310108
- D NRC Draft/Final Environmental Statements, supplie & correspondence
- 8208310438 Summary of MI Environ Review Board 820726 meeting in Lansing, MI re EIS 4 Michigan, State of, Dept of Public Health 82/07/26 Michigan, State of, Dept of Public Health 14pp. 14705-001 24X Fiche 50-329, 82/07/26
- 8208170343 Forwards FES & notice of availability forwarded to Ofc of FR for publication H/o FES NOVAK.T K Assistant Director for Licensing 82/07/30 COOK.J W Consumers Power Co 3pp 14372 314 24X Fiche 50-329,82/07/30,8208170343
- --8208170346 Notice of issuance & availability of FES (NUREO-0537) ADENSAMLE Q Licensing Branch 4 82/07/30 2pp 14372 317 24X Fiche: 50-329, 82/07/30, 8208170343
- 8208170349 Forwards FE9, which includes discussion of problems & objections raised by federal state, local agencies & community W/o encl
 ADENSAM.E 0 Licensing Branch 4 82/07/30 GRANT.R
 Commerce, Dept of 3pp 14372 319 24X Fiche 50-329,82/07/30,8208170349
- 8208170352 Forwards FES which includes discussion of problems & objections raised by federal state local agencies & community W/o encl
 ADENSAM, E 0 Licensing Branch 4 82/07/30 Midland County, MI ip 14373 192 24X Fiche 50-329,82/07/30,8208170352,

- 8208170355 Forwards FES & notice of availability FES includes discussion of problems & objections raised by federal state, local agencies & community W/o encis
 ADENSAM, E O Licensing Branch 4 89/07/30 WILSON, K Environmental Protection Agency 1p 14373 235 24X Fiche 50-329, 82/07/30, 8208170355
- 9208170006 FINAL ENVIRONMENTAL STATEMENT RELATED TO THE DPERATION OF MIDLAND PLANT.UNITS 1 AND 2 Docket Nos 50-329 And 50-330 (Consumers Power Company) * Office of Nuclear Reactor Regulation, Director NUREO-0537 82/07/31 330pp Available at NTIS \$10 00 14375 082 24X Fiche 50-329,82/07/31,8208170006
- 8208240462 Forwards FR notice of availability of FE8 W/o encl ADENSAH.E 0 Operating Reactors Branch 4 82/08/02 Butzel & Kass 3pp 14544 174 24X Fiche 50-329,82/08/02,8208240462
- 8208240406 Informs that FES has been reviewed No comments differed HILNER, H R Agriculture, Dept of 82/08/16 NRC No Detailed Affiliation Olven Ip 14522 315 24X Fiche 50-327, 82/08/16, 82/08/4046
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8208230096 Summary of 820804 meeting w/util & Bechtel in Bethesda, MD re use of anchor bolts in masonvy walls at plant subj of SER Section 3 8 2 Masonry wall evaluation conclusions will be published in Suppl 2 to SER HERNAN, R W Licensing Branch 4 82/08/09 Licensing Branch 4 4pp 14517 331. 24X Fiche 50-329, 82/08/09, 8208230096.
- 8208160064 Forwards "Probabilistic Analysis to Verify Adaquacy of Hidland Plant Tornado Missile Protection: "supporting SER Open Item 3 CBCK:JW Consumers Power Co 82/08/11 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 14342 230 24X Fiche 30-329:82/08/11,8208160064
- --8208160067 "Probablistic Analysis to Verify Adequacy of Midland Plant Tornado Missile Protection " → Consumers Fower Co B2/06/30 56pp 14342 232 24% Fiche 90-329,82/08/11.8208160064
- 8208310475 Responds to 820621 request for mods to feedwater headers. Itsted as outstanding issue in SER (MUREG-0793), Section 1 7 Request for addl info to complete safety evaluation encl MOVAK, T M Assistant Director for Licensing 82/08/11 CODK. J W Consumers Power Co. 4pp. 14697 313 24X Fiche 50-329.82/08/11, 8208310475
- 8208310478 Requests info re action to be taken to resolve SER (NUREG-0793). Section 1 7 Open Item 8 on makeup nozzle cracking Response requested within 45 days of recept of ltr NOVAK.T M Assistant Director for Licensing 82/08/11 CODK.J. W Consumers Power Co 2pp 14697 311 24X Fiche 50-329,82/08/11,8208310478
- 8208270246 Forwards Amend 107 to application for CPs & OLs containing Revision 5 to security plan & Revision 2 to safeguards contingency plan Revisions resolve all NRC 820601 SER review comments CDDK.J W Consumers Power Co 82/08/24 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 14564 150 24% Fiche 50-327, 82/08/24, 8208270246
- 8208310276 Responds to B20608 info request for BER suppl info re ultimate containment capacities Further response to Question 130 28, to be incorporated in future FSAR revision, encl CODK, J W Consumers Power Co 82/08/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 14693 098 24X Fiche 50-327, 82/08/25, 8208310296
- F Security, medical, emergency & fire protection plans
- 8208310001 Forwards documents to enhance understanding of emergency planning process at nuclear power facilities W/o encis
 ABENSAM.E 0 Licensing Branch 4 82/08/16 KINZLEY.B Montana.
 Bate of 2pp 14697 129 24X Fiche 50-329.82/08/16.8208310001
- 8208270246 Forwards Amend 107 to application for CPs & OLs containing Revision 5 to security plan & Revision 2 to safeguards contingency plan Revisions resolve all NRC 820601 SER review comments
 COOK, J W Consumers Power Co 82/08/24 DENTON, H, R Office of Nuclear Reactor Regulation, Director 2pp 14564 150, 24X Fiche 50-329,82/08/24,8208270246

--8208270283 Amend 107 to application for CPs & CLs containing Revision 5 to security plan & Revision 2 to safeguards contingency plan Revisions withheld (ref 10CFR73 21) CODK, J W Consumers Power Co 82/08/24 ip 14564 152 24X Fichs 50-329,82/08/24,8208270246

G Adjudicatory correspondence

- 8208020218 Response opposing M Sinclair 820418 new contentions Contentions Untimely Good cause for late filing not shown Contentions lack basis & specificity &/or raise issues being resolved in another forum MEBT.A Consumers Power Co WEBT.A Isham, Lincoln & Beale 82/07/28 Atomic Safety and Licensing Board Panel 32pp 14141 083 24X Fiche 50-327,82/07/28,8208020218
- 8208020220 Further answer opposing B Stamiris petition to intervene as supplemented by 820709 amended contentions Petitioner fails to mest requirements for late intervention STEPTOE, PP Consumers Power Co STEPTOE, PP Isham, Lincoln & Beale 82/07/28 Atomic Safety and Licensing Board Panel 200pp 14147 253 24% Fiche 50-329, 82/07/28, 8208020220
- 8208110187 Response opposing MP Binclair 820723 new Contention 14 & request for add1 time to respond to new Contention 13 until prehearing conference on 820812 Contention has no basis Certificate of Svc & related documentation and STEPTOE, P F Consumers Power Co STEPTOE, P I Sham, Lincoln & Beale 82/08/02 Atomic Safety and Licensing Board Panel 35p 14313 001 24% Fichs 50-329,82/08/02,8208110187
- B20B060123 New Contention 15 re documentation on walds BINCLAIRM P Sinclain, M 82708/03 Atomic Gafety and Licensing Board Panel Ip 14238 317 24% Fishes 50-327,82708/03,8208060123
- 8208090137 Motion to strike M Sinclair Contentions 28-50 Sinclair failed to submit rewritten contentions per AGLB 820907 order. Contentions do not meet specificity & basis requirements of 10CFR2 714 Certificate of Svc encl WEBT. A E Consumers Power Co WEBT. A E I Sham, Lincoln & Beale 82/08/09 Atomic 8afety and Licensing Board Panel Spp 14271 296 24X Fiche 50-329,82/08/03,8208090137
- 8208120126 New Contention 16 adding info that should be covered as part of Zack Co nonconformance rept re unverified welder qualifications for fabrication weld BINCLAIR, M P Sinclair, M 82/08/06 Atomic Safety and Licensing Board Panel 1p 14327 065 24X Fiche 80-327,82/08/06,8208120126
- 8208110140 Denies 820803 request for payment of expenses of expert, C Anderson to attend 820814 site tour NRC FY82 appropriation act forbids payment of expenses to intervenor BECHHOEFER.C Atomic Safety and Licensing Board Panel 82/08/09, 81NCLAIR, M 81ncleir, M 1p 14314 305 24X Fiche 50-329, 82/08/09, 820810140.
- --B20Bil0i45 Requests C Anderson fees for attending 820Bi4 sits tour be paid by ABLB BINCLAIR,M Binclair,M 82/08/03 BECHHOEFER,C Atomic Safety and Licensing Board Panel ip 14314 306 24X Fiche 50-329,82/08/09,820Bil0i40
- 8208200275 Notice of appearance in proceeding 818H0P; L Binclair, M BISH0P; L Harmon & Weiss 1p 14397:052 24X Fiche 50-329.82/08/10.8208200275
- 8208200232 Restated contentions, superseding contentions filed on B20718,23 & 0803 *
 818H0P,L L Sinclair,M BISH0P,L L Harmon & Weiss 82/08/12 Atomic Bafety and Licensing Board Panel 5pp. 14399:351 24X Fiche 50-329,82/08/12.8208200232.
- 8208200265 Revised contentions based on discovery per A9LB 820325 order BISHOP, L. Binclair, M. BISHOP, L.L. Harmon & Weiss 82/08/12 Atomic Bafety and Licensing Board Panel App. 14398 356 24X Fiche 50-329, 82/08/12,8208200265
- B20B200257 Restated Contentions 6,8 & 16 re GA program Certificate of 8yc encl, B18HDP, L Sinnissippi Alliance for the Environment (BAFE) B18HDP, L. Harmon & Weiss 82/08/13, Atomic Safety and Licensing Board Panel 8pp 14399 330 24% Fiche 50-329,82/08/13,6208200257
- 8208180114 Prehearing Conference Order LBP-82-63 admitting MF Sinclair new Contentions 3, 5, 6, 7, 8 & 16 & B Stamiris Contentions 1, b, 1 c, 6 & 8 & dismissing B Stamiris Contention 13. pureuant to ABLB 820812-13 prehearing conference.

 BECHHOEFER, C. COWAN, F.P., HARBOUR, J. Atomic Safety and Licensing Board Panel 82/08/14 41pp 14378, 097 24X Fiche 50-329, 82/08/14, 820810114.

- 8208190110 Forwards Page 36a inadvertently omitted from util further answer to B Stamiris petition to intervene in OL proceeding, amended contentions & statement of good cause for late intervention STEPTOE.P P Isham, Lincoln & Beale STEPTOE.P P Consumers Power Co 82/08/16 Atomic Safety and Licensing Board Panel ip 14381 136 24X Fiche 50-329,82/08/16,8208190110
- --8208190146 Page 36a of util further answer to B Stamiris petition to intervens in OL proceeding, amended contentions & statement of good cause for late intervention, inadvertently omitted from original filing

 * Consumers Power Co 82/08/16 Atomic Safety and Licensing Board Panel 19 14381 137 24X Fiche 50-329.82/08/16, 8208190110
- 8208200171 Suppl to ASLB 820814 prehearing conference order LBP-82-63 Encl Pages 17.17a.33 & 33a should be substituted in order BECHHOEFER.C Atomic Safety and Licensing Board Panel 82/08/19 Spp 14500 123 24% Fiche 50-327,82/08/19.8208200171
- 8208290274 Memorandum memorializing 820820 telcon w/NRC, applicant, L Bishop, M Sinclair, B Stamiris & WH Marshall Applicant & NRC should reconcile differences on proposed fuel load date to finalize plans for 821116-20,22-23 & 1130-1203 hearings BECHHOEFER, C Atomic Safety and Licensing Board Panel 82/08/23 3pp 14542 001 24X Fiche 50-327,82/08/23,8208250274
- 8208300291 New contention based on FES re-cost production & cost saving analysis of FEB Statement of good cause for filing new contention encl
 STAMIRIO.B Stamiris. B 82/08/24 Atomic Safety and Licensing
 Board Panel 9pp 14679 187 24X Fiche 50-329,82/08/24,8208300291
- 8208260140 Advises that SER suppl will not be completed by scheduled 820827 date NRC will shortly notify ASLB & parties of schedule for finalization of SER suppl WILCOVE, K N Hearing Branch 2 82/08/25 BECHHOEFER, C , DECKER, R B , COHAN, F P Atomic Bafety and Licensing Board Panel 2pp 14554 357 24X Fiche 30-329,82/08/25,8208260140

H General correspondence

- 8207200110 Responds to 820622 ltr forwarding M Sinclair 820524 ltr rerights of intervenors during licensing proceedings
 Intervenors have right to participate in ACRS activities
 Applicant did not agree to addl tour of facilities
 DIRCKS,W J Office of the Executive Director for Operations
 62/07/07 LEVIN,C Senate App 13760 307 24X
 Fiche 50-327,82/07/09.8207200110
- --8206200044 Forwards H Sinclair 820524 ltr re rights of intervenors during proceedings for local plants Addl info requested re rights of intervenors & right to participate in ACRS activities Info needed by 820705
 LEVIN.C Senate 82/06/22 FALLADINO.N J Commissir 13960 314 24% Fiche 50-329, 82/07/09, 8207200110.
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8207070028 Forwards Amend 105 (Revision 13 to response re plant fill) to application for CPs & OLs Amend control and App D to FSAR CODK, J W Consumers Power Co 82/06/25 DENTON, H R Nuclear Reactor Regulation, Director 1p 13720 254 Fiche 50-327, 82206/25, 8207070028
- --B207070058 Amend 105 (Revision 13 to response to NRC fill) to application for CPs & OLs. consisting of note of SSAR COOK, J W Consumers Power Co 82/06/25 4,500pp. 24X Fiche 50-329.82/06/25,8207070028
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation V Leakage " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance Consolidated Edison Co of New York 87pp 14356-274 Fiche 50-000,82/07/16,8204210393
- B204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarificat Placement of Personnel Honitoring Devices for External Radiation" Svc list encl JORDAN, E. L. Division of Engineering & Guality Assuran Michigan, Univ of 112pp 14358 001 24X Fiche: 51 B204210395

- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list enc! JORDAN,E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche.50-Q00.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Herafluoride Gverpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safaguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X fiche 50-000,82/07/20.8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JDRDAN/E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357.013 24X Fiche 50-000, 82/07/26, 8204210403
- 8208160453 Forwards IE Insp Repts 50-329/81-23 & 50-330/81-23 on 811201-820630 No noncompliance noted KNOP.R C Division of Project & Resident Programs 82/07/26 CODM.J W Consumers Power Co 2pp 14348 238 24X Fichs 50-329,82/07/26.8208160453
- ---B20Bi60459 IE Insp Repts 50-329/Bi-23 & 50-330/Bi-23 on Bii20i-B20630
 No noncompliance noted Hagor areas inspected exam of site
 conditions & laydown areas, onsite storage of matl.mgt
 meetings & changes in site mgt
 COCK, R J , BOYD, D C Division of Project & Resident Programs
 B2/07/26 6pp 14348 240 24X Fiche 50-329,82/07/26,820B160453
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208130321 Forwards IE Insp Repts 50-329/82-10 & 50-330/82-10 on 820602-04,30 & 0701 No nomcompliance noted LITTLE.W 5 Division of Engineering & Technical Programs 82/07/28 COOK.J.W Consumers Power Co 2pp 14336 329 24X Fiche 50-329, 82/07/28,8208130321
- --8208130323 IE Insp Repts 50-327/82-10 & 50-330/82-10 on 820602-04.30 & 0701 No noncompliance noted Major areas inspected followup on 10CFR50 55e items re containment internal structures coating deficiency HAMKINS,F C , MILLIAMS, C C Region 3, Office of Director 82/07/22 4pp 14336 331 24X Fiche 50-327,82/07/28,8208130321
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " Svc list encl JORDAN, E L. Division of Engineering & Quality Assurance. 62/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000.82/08/05,8204210407
- 8208240413 Forwards IE Insp Repts 50-329/82-11 & 50-330/82-11 on 820519-0702 & notices of violation & deviation LITTLE, W S. Division of Engineering & Technical Programs 82/08/09 COOK, J W Consumers Pauer Co. 2pp 14524 031 24X Fiche 50-329, 82/08/09,8208240413
- ---B20B240416 Notice of violation from insp on 820519-0702 LITTLE.W.S. Division of Engineering & Technical Programs 82/08/09 ip. 14524.033 24X Fiche 50-329.82/08/09.8208240413.
- --8208240419 Notice of deviation from insp on 820517-0702 * Region 3, Office of Director 82/08/09 ip 14524 034, 24X Fiche 30-329,82/08/09,8208240413,

- --8208240425 IE Insp Repts 50-329/82-11 & 50-330/82-11 on 820519-0702 Noncompliance noted one 3/8-inch anchor on extensometer EX5 found to have embedment of only 1 inch & use of unapproved installation forms
 GARDNER,R N , LANDSMAN,R B , WILLIAMS,C C Region 3, Office of Director 82/08/02 10pp 14524 035 24X Fiche 50-329.82/08/09, 8208240413
- R Periodic operating reports & related correspondence
- 8208040049 Forwards ALAB-106 monthly rept for June 1982, consisting of Bechtel, 8&W & util repts written or closed during month re GA. audits, nonconformances & corrective actions
 COGK, J W Consumers Power Co 82/06/25 DEYGUNO, R C Director's Office. Office of Inspection and Enforcement 326pp 14191 219 24X Fiche 50-329, 82/06/23, 8208040049
- S Reportable occurrences. LERs & related correspondence
- 8208100126 PNU-III-82-068 on 820503, allegations from former employee of HVAC contractor received re false or incomplete GA documentation for HVAC work at sites Special insp of Zack Co & facilities initiated MALKER, B D. KNOP, R C. SPESSARD, R L. Region 3, Office of Director 82/07/22 1p 14278 183 24X Fiche 50-000,82/07/22,8208100126.
- 8208100097 Final deficiency rept re electrical components associated w/ MSIV actuators, logic cabinets & control panel inserts Initially reported on 820204 Purchase Order 7220-H-238(g) issued to procure corrective matls COOK.J W Consumers Power Co BALLMEG,T O, HUGHES, E. M Bachtel Corp 82/07/30 KEPPLER, J O Region 3, Office of Director 7pp 14297 330 24% Fiche 50-329,82/07/30,8208100097
- 8208100131 Amended final deficiency rept re nuclear instrumentation/ reactor protection sys (NI/RPS) Initially reported on 780405 NI/RPS grounding scheme modified to ground channelized circuits to Class IE instrument ground CODK, J W Consumers Power Co. 82/07/30 KEPPLER, J O Region 3, Office of Director 4pp. 14298 175 24X Fiche 50-329,82/07/30, 8208100131
- 820B1002B0 PNO-III-82-071 on 820729, received Part 21 rept via telcon w/Zack Co re documentation discrepancies for welds made to HVAC components at La Salle & possibly at Clinton & Hidland Welder of record may not be actual welder.
 WALKER, R D , KNOP, R C , SPESSARD, R L Ragion 3, Office of Director 82/07/30 1p 14294 352 24X Fiche 50-000,82/07/30,820B1002B0
- 8208iA024B Potential Part 21 rept re weld records Initially reported on 820729 Review of documents indicates possible discrepancy between welder of record & welder completing welds Investigation continuing DE ZUTEL, C Z Zack Co 82/08/02 KEPPLER, J G Region 3, Office of Director 10pp 14344 351, 24X Fiche. 50-000, 82/08/02, 8208160248
- 8208130215 Interim deficiency rept re-underrated terminal strips on Limitorque valve operators Initially reported on 810213 Underrated terminal blocks replaced w/correctly rated Harathon 300 Series blocks Next rept expected by 821022 COOK. J W Consumers Power Co 82/08/06 KEPPLER. J Q. Region 3. Office of Director 14pp 14333 028 24X Fiche 50-329,82/08/06,8208130215
- 8208160314 Interim deficiency rept to B&W steam generator auxiliary feedwater header design change Initially reported on 820826 Design mod provides for addition of external auxiliary feedwater distribution header w/eight injection nozzles. COOK.J W Consumers Power Co 82/08/06 KEPPLER.J G Region 3, Office of Director DENTON.H R Office of Nuclear Reactor Regulation, Director 37pp 14349 328 24X Fiche.50-329.82/08/06.8208160514
- 8208160472 PNO-III-82-078. on 820809. licensee issued stop work order for angoing remedial safety-related soils work at site, after NRC determination that work not approved by NRR Procedures requiring written approval of work will be developed WARNICK, R. DAVIS, A. Region 3, Office of Director 82/08/12. ip 14348 194 24% Fiche: 50-329, 82/08/12, 8208160472
- 8208240268 Interim deficiency rept re Q-related equipment cooled by non-Q HVAC sys Project engineering reviewing safety functions of Q devices to evaluate safety-related implications of failure Next rept by 821122 COCK.J W Consumers Power Co. 82/08/17. KEPPLER, J O Region 3. Office of Director Spp 14521:357 24X Fiche: 80-327, 82/08/17, 8208240268

- T Hearing transcripts on non-antitrust matters
- 8208170009 Transcript of 820812 hearing in Midland, MI Pp 8,100-8,316 * Atomic Safety and Licensing Board Panel 82/08/12 216pp 14360 122 24X Ficha 50-329,82/08/12,8208170009
- B20B170022 Transcript of 820B13 meeting in Midland.MI Pp 8,317-8,546

 * Atomic Bafety and Licensing Board Panel 82/08/13 231pp
 14359 251 24X Fiche 50-329,82/08/13,820B170022
- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CF re Commission approved charter for CRGR Svc list encl
 DIRCKS,W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000,82/07/02,8207080064
- 8208090220 Forwards systematic assessment of licensee performance for Jul 1980-June 1981 Working meeting will be arranged to clarify disputed issues KEPPLER. J. G. Region 3. Office of Director 82/07/19. COOK, J W. Consumers Power Co. 70pp 14272 073 24X Fiche 30-329,82/07/19,6208090220
- 8208040143 Forwards "Pump & Valve Inservice Testing Plan" COOK.J.W. Consumers Power Co. 82/07/21 DENTON.H.R. Office of Nuclear Reactor Regulation, Director 3pp 14189 318 24X Fiche 50-327, 82/07/21,8208040143
- --8208040148 "Pump % Valve Inservice Testing Plan," Revision O BOUWENS, J G., BRADER, C R . KRAMER, C E Consumers Power Co 82/07/08 284pp 14189 321 24X Fiche. 50-327, 82/07/21, 8208040143
- 8208070055 Documents commitments re concrete wall cracks in Category I safety grade bldgs affected by soil fill Repair program will be completed prior to first refueling Crack repairs apply to generator bldg & svc water pump structure COOK.J W Consumers Fower Co 62/08/02 DENTON.H R Office of Nuclear Reactor Regulation. Director. Spp 14270 001 24X Fiche 50-327, 82/08/02,8208070055
- 8208140308 Forwards latest revisions of piping design info for Midland Unit 2 decay heat removal & core flooding sys Info comprises Revision 8 of math for NRC independent confirmatory piping analysis W/one oversize drawing Aperture card is in PDR COOK, J. W. Consumers Power Co. 82/08/05 DENTON, H. R. Office of Nuclear Reactor Regulation, Director Sipp 14347-142 24X Fiche 50-327, 82/08/05,8208160308.
- --8208160335 Revision 2 to "Design Spec for Component Supports for Nuclear Svc Piping for Midland 1 & 2," Sheet 1, App C Revision data illegible Incomplete B&W Spec 18-1371000012-01 encl RIAT, D Bechtel Corp 82/08/05 104pp 14347 163 24X Ficha 50-329,82/08/05.8208160308
- ---8208160342 Revision 6 to "Spec for Earthquake Resistance Design of Equipment Located in Reactor Bldg for Midland Unit 1 & 2." * Bechtel Corp. 82/03/19 98pp, 14347 267. 24X Fiche 50-329,82/08/05.8208160308
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submitted of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Svc list encl EISEMHUT. D G. Division of Licensing. 82/08/09 Consolidated Edison Co of New York ip. 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208120221 Forwards "Quality Plan for Underpinning Activities" & "Quality Plan for Remedial Soils Activities & Boils-Related Work in Quality Areas," COOK, J. W. Consumers Power Co. 82/08/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 14325-322 24X Fiche: 50-327, 82/08/09, 8208120221
- --8208120223 "Guality Plan for Underpinning Activities," Revision 3 BIRD, W., BOOS, A, J, MOGNEY, J Consumers Pawer Co, MPGP-1 RO3 82/07/26 23pp 14325, 326, 24% Fiche: 50-329, 82/08/09, 8208120221
- --8208120224 "Quality Plan for Remedial Soils Activities & Soils-Related Work in Quality Areas: "Revision O BIRD.W: BDOS.A. MOONEY.J Consumers Fower Co. MPGP-2 ROO 82/07/26 App. 14325 349 24X Fiche 50-329,82/08/09,8208120821.

- 8208160393 Confirmatory action ltr re stop work order on remedial soils area Region 3 approval required prior to lifting of stop work order in whole or gart
 KEPPLER.J G Region 3. Office of Director 82/08/12 COOK.J W
 Consumers Power Co ip 14348 352 24X Fiche 50-329,82/08/12,8208160393
- 820Bi90i37 Formalizes proposals made at 820720 meeting re NURE9-0737, Item II K 3 30, "Revised Bmall Breek LOCA Methods" Assurance of core cooling being evaluated under ongoing small breek LOCA methods program COOK. J W Consumers Power Co 82/08/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 14381 084 24X Fichs 50-329,82/08/12,8208190137
- B20B200249 Requests details re remedial soils activities scheduled for Aug 1982 Activities determined noncritical Portion of ltr re procedures withheld SHAFER.W D Region 3. Office of Director 82/08/12 MILLER, D B Consumers Power Co 3pp 14399 028 24X Fiche 50-329,82/08/12,6208200249
- 8208230376 Submits list of critical work activities re remedial soil work scheduled for Aug 1982 Authorization for proceeding w/work granted SHAFER. H D Region 3. Office of Director 82/08/13 MILLER, D, B Consumers Power Co 3pp 14512:326 24X Fiche 50-329, 82/08/13. 8208230376
- 8208240308 Forwards NRC & CPC work authorization procedure developed to provide mechanism for Region 3 review & authorization of activities to be implemented at site as described in ASLB order SHAFER, W D NRC No Detailed Affiliation Given B2/08/16 NRC No Detailed Affiliation Given 2pp 14520 217 24X Fiche 30-329, 82/08/16, 8208240308
- --B20B240307 NRC & CPC work authorization procedure MOONEY, J A Consumers Power Co BHAFER.H D NRC - No Detailed Affiliation Given 82/08/12 4pp 14520 219 24X Fiche 50-329, B2/08/16.820B24030B
- 8208270682 Forwards "Control of Heavy Loads at Nuclear Power Plants, Midland Units 1 & 2," draft technical evaluation rept. NDVAK, T M Assistant Director for Licensing 82/08/16 COOK, J & Consumers Power Co 2pp 14683 140 24X Fichs 50-327,82/08/16, 8208270682
- --8208270692 "Control of Heavy Loads at Nuclear Power Plants, Midland Units I & 2," draft technical evaluation rept DIXON.B W , BTICKLEY, T H E08.0, Inc 82/05/31 NRC No Detailed Affiliation Given 37pp 14683 142 24X Fiche 50-329, 82/08/16, 8208270682
- 8208270683 Forwards guidance useful in developing program for TMI Action Item II B 3. "Post-Accident Sampling Capability "Encl info represents sampling of methods acceptable to NRC W/o encl.
 ADENBARIS G Licensing Branch 4 82/08/18 COOK, J W Consumers Power Co ip. 14683 139 24X Fiche 50-329,82/08/18,8208270683,
- 8208270246 Forwards Amend 107 to application for CPs & OLs containing Revision 5 to security plan & Revision 2 to safeguards contingency plan Revisions resolve all NRC 820601 SER review comments

 COOK. J W Consumers Power Co 82/08/24 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 14564 150 24X Fiche. 50-329, 82/08/24, 8208270246
- --8208270253 Amend 107 to application for CPs & OLs containing Revision 5 to security plan & Revision 2 to safeguards contingency plan Revisions withheld (ref 10CFR73 21) CCOK, J W Consumers Fower Co 82/08/24. 1p. 14564·152. 24X Fichs 50-329,82/08/24.8208270246
- 820831010B Forwards certified mat1 test rept for penetration sleave in genetration 22-88, inadvertently omitted from util 820330 ltr CODK.J W Consumers Power Co 82/08/25 DENTON.H.R Office of Nuclear Reactor Regulation, Director App 14495-074, 24X Fiche. 50-329, 82/08/25, 8208310108
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8208310438 Summary of MI Environ Review Board 820726 meeting in Lansing, MI re EIS # Michigan, State of, Dept of Public Health 82/07/26 Michigan, State of, Dept of Public Health 14pp 14705 001. 24X Fiche 50-329,82/07/26,8208310438

- Exhibit 13 forms as Policips of Availability forwarded to DFC of PR for Seal, All Ways and Assistant Control for Licensing 82/07/30 COOK, U W Cong pany Figure 12 14572 314 CAX Fiche 50-329.82/07/30, Panol 142
 - La 31" 45 hits and present 4 devotion 2pp (4372 317 24X Firm to availability of FES (NUREG-0537)

 A think to avail to capting 343
- Fig. Bit, 14 x Frequency Country includes discussion of problems & UD. a. viscon veryes by feteral state. Incel agencies & CORP. vistor & C. A.E.Y SM. E. ... L. ensury Branch & B2/07/32 GRANTLR Contrary & Capt by ... 1272 359 24x Fiche 50-329, 82/07/30, E. 117 July ...
- to Bircold Pywarss has crare includes discussion of problems & objections rates by federal, state local agencies & community with the series of Branch 4 82/07/30 Hidland County, MI is 1437314, 446 ft. he 50-327 82/07/20.
- The diff of Fire Englishment, Statement Felated to the Operation of Michael Flam, and is also a Coppet Nos. 30-329 and 50-330 in the area of the Coppet Nos. 30-329 and 50-330 in the area of the Coppet Nos. 30-329 and 50-330 in the Coppet Nos. 30-330 in
- 면도 전급적 14%도 Formands For riting of availability of FES M/o and AIC WAMM 은 다. 'Jeraning Reactors Franch 및 62/08/02 Buttal & MAMM 은 다. 'Jeraning Reactors Franch 및 62/08/02,8208R40462
- GINGLATA'S Individual that FET has been reviewed No comments offered minds in A Agri, , the last of 92/03/16 NRC No Detailed Affiliation of 147/2 315 241 Fiche 50-329, 82/08/16, 82/03/414 5
- E AR: Eafety Eveluation Region (SER), supply & correspondence
- GENERAL MURRO CLORARY OF 60 D14 members w/util & Bechtel in Bethesda. HD
 re was de archer bolte in membry walls at plant subj of BER
 Eartier I d E mastry well staluation conclusions will be
 published in Lugs. S to Service A GE/08/09 Licensing Branch 4
 App 16417 37; 240 Fiche 50-027, B2/08/09, B208230076
- 62 Bioline Fundance incomp. Listic Analysis to Verify Adequacy of Higians Plant Terned, Missis Protection: supporting SER Green Item 2 Growth of Computers Paper to 82/08/11 DENTON, N.R. Office of Nuclear Register Regulation Ciractor Epp 14042 230 24X Fichs 5, 327 62 A.1, 8219,60064
- BADR310475 Response to Ball request for ends to feedwater headers.
 Itseed as wisters, y issue to SER (AURECHO793), Section 1 7
 Request for each 1-20 to copiete safety evaluation end!
 AUCHAR T. M. Assistant Director for Licensing 82/08/11 COOK, J. W. Garaweers Rumar J2 6pp 14597 313 24% Fiche 50-029, 82/08/11.
- BSCB312478 Reduces the resistent to be taken to resolve SER INJESCHOTOLIS (1975) 17 Corn I tem 8 on makeup notale creating Response reliesed within 45 days of receipt of NOVAK M. Assistant Director for Licensing 82/08/11 COOK.J U BSCBJ1478
- BECBB310290 Response to B25000 into request for BER supplimito re ultimate rentermant tagacities Further response to Question CDOM J at 50 ps interporated in future FSAR revision encl COOM J at 20 payable to B2/08/25 DENTONIN R Office of Nurteer Peastor Brailette Director 700 14673 098 24X

- F Security, medical, emergency & fire protection plans
- 8208310001 Forwards documents to onhance understanding of emergency planning process at nuclear power facilities W/o encis ADENSAM.E O Licensing Branch 4 82/08/16 KINZLEY, B Montana. State of 2pp 14697 129 24X Fiche 50-329.62/00/16.8200310001
- 8208270245 Forwards Amend 107 to application for CPs & GLs containing Revision 5 to security plan & Revision 2 to safeguards contingency plan Revisions resolve all NRC 920601 988 review comments
 COCK-J W Consumers Power Co 82/08/24 DENTON, H R Office of Hyclear Reactor Regulation. Director 2pp 14564 150 24X Fiche 50-329.82/08/24, 8208270246
- --B208270253 Amond 107 to application for CPs & DLs containing Revision \$ to security plan & Revision 2 to safeguards contingency plan Revisions withheld trep toCFR73 2t1 CCOK, J W Consumers Power Co 82/08/24 ip 14564 152 24X Fichs 50-329,82/08/24,8208270246

Q Adjudicatory correspondence

- 8208020218 Response opposing M Ginclair 820616 new contentions.
 Contentions untimely Good cause for late filing not shown
 Contentions lack besis & specificity &/or raise issues peing
 resolved in another forum
 MEGT.A Consumers Pawer Co MEST.A Isham, Lincoln & Heale
 82/07/28 Atomic Safety and Licensing Board Panel 32pp
 14141 083 24X Fiche, 50-327, 82/07/28, 8208020218
- 8208020220 Further answer opposing B Stamiris petition to intervene as tupplemented by 820707 amended contentions Petitioner Pails to meet requirements for late intervention STEPTOE.P.P. Consumers Power Co. BIEFTOE.P.P. Isham, Lincoln & Reale 82/07/23 Atomic Safety and Litonsing Board Panel 200pp 14147 233, 24% Fiche 50-329,82/07/28,8208020220
- 8208110187 Response opposing MP Sinclair 820723 new Contention 14 & request for addI time to respond to new Contention 13 until prehearing conference on 820812 Contention has no basis.

 Certificate of Svc & related documentation encl STEPTOE.P.P. Consumers Power Co. STEPTOE.P.P. Isham, Lincoln & Beale 82/08/02, Atomic Safety and Licensing Doard Panel 35pp 14313.001 24X Fiche 50-327,82/08/02,8208110187
- B208060123 New Contention 15 re documentation on welds SINCLAIR. N P Sinclair. M B2/08/03 Abonic Safety and Licensing Board Panel 1p, 14238 317 24X Fiche 50-329, 82/08/03, 82/08/04/23
- 9208090137 Motion to strike M Sinclair Contentions 28-50 Sinclair failed to submit rewritten contentions per ASLB 820507 order Contentions do not meet specificity & basis requirements of 10CFR2 714 Certificate of Svc encl WEST, A E Consumers Power Co WEST, A E Isham, Lincoln & Deale, 82/08/03 Atomic Safety and Licensing Board Panel Spp 14271 276 24X Fiche 50-329,82/08/03,8208090137.
- 8208120126 New Contention 16 adding info that should be covered as part of Zack Co nonconformance rept re unverified welder qualifications for fabrication weld SINCLAIR, N.P. Sinclair, M. 82/08/06. Atomic Bafety and Licensing Board Panel 1p. 14327 065 24% Fiche 50-329, 82/08/06, 8208120126
- 8208110140 Denies 820803 request for gegment of expenses of expert, C Anderson, to attend 820814 site tour NRC FYB2 appropriation act forbids payment of expenses to intervenor SECCHREFER. C Atomic Safety and Licensing Board Panel. 82/08/09 SINCLAIR. M Sincleir, M. Ip. 14314 305 24X Fiche: 50-329.82/08/09.8208110140
- --8208110145 Requests C Anderson fees for attending 820814 site tour be gaid by ASLB SINCLAIR, H Sinclair, M 82/08/03, BECHHOEFER, C Atomic Befety and Licensing Board Panel 19 14314 306 24X Fiche 50-327, 82/08/07, 8208110140
- 8208200278 Notice of appearance in proceeding BISHOP.L. Binclair.M BISHOP.L.L Harmon & Weiss 82/08/10 Ip 14299 052 24% Fiche 50-229, 82/08/10, 8208200275
- 8208200232 Restated contentions, superseding contentions filed on 820718,23 & 0803.
 BISHOP, L. Binclair, M. BIGHOP, L.L. Harmon & Weiss 82/08/12, Atomic Safety and Licensing Board Panel Spp 14399; 351. 24X Fichs 50-329, 82/08/12, 8208200232

- 208200265 Revised contentions based on discovery per ASLB \$20525
 - order BIGHOP, L. Sinclair, M. BISHOP, L. Harmon & Weiss 82/08/12 Atomic Safety and Licensing Board Panel 6pp 14398 356 24X Fichs 50-329, 82/08/12, 8208200265
- #208200257 Restated Contentions & 8 & 16 re QA program Certificate of
 - 208200327 Retated Conventions 6.8 & 16 Fe do program Certificate of Svc enci
 BISHOP, L. Sinmissippi Alliance for the Environment (SAFE)
 BISHOP, L. Harmon & Weise 82/08/13 Atomic Safety and
 Licensing Board Panel 8pp 14399 330 24X Fiche 50-327,82/08/13,
 8208200257
- ©208180114 Prehearing Conference Order L8P-82-63 admitting MP Sinclair new Contentions 3,5,6,7,8 & 16 & 8 Stamiris Contentions 1 b,1 c,6 & 8 & dismissing B Stamiris Contention 13, pursuent to ABLB 820812-13 prehearing conference BECHMOEPER, C. COWAN, F.P., HARBOUR, J. Atomic Safety and Licensing Board Panel 82/08/14 41pp 14378 097 24X Fiche 50-329, 82/08/14,8208180114
- \$208170110 Forwards Page 36a inadvertently omitted from util further answer to B Stamiris petition to intervene in DL proceeding, amended contentions & statement of good cause for late amented conventions a section of good to the control of the contro Consumers Power
- --8208190146 Page 36a of util further answer to B Stamiris patition to intervene in QL proceeding.amended contentions & statement of good cause for late intervention.inadvertently omitted from original filing
 -- Consumers Power Co 82/08/16 Atomic Safety and Licensing Board Panel 1p 14381 137 24X Fichs 50-329,82/08/16.
- E3208200171 Suppl to ASLS 820814 prehearing conference order LBP-82-63 Entl Pages 17,17a,33 & 33a should be substituted in order BECHHOEFER.C Atomic Sefety and Licensing Board Panel 82/08/19 5pp. 14500 123 24X Fichs 50-329,82/08/19,8208200171
- 8208250274 Hemorandum memorializing 820820 telcon w/NRC, applicant, L Bishop, H Sinclair, B Stamiris & CH Marshall Applicant & NRC should reconcile differences on proposed fuel load date to finalize plans for 821116-20, 22-23 & 1130-1203 hearings BECHHOEFER, C Atomic Safety and Licensing Board Panel 82/08/23 Spp 14542 001 24X Fiche 50-529, 82/08/23, 8208260274 82/08/23
- 8208300271 New contention based on FES re cost production & cost saving analysis of FES Statement of good cause for filing new contention encl STAMIRIS. B Stamiris. B 82/08/24 Atomic Safety and Licensing contention enci STAMIRIS, B. Stamiris, B. 82/08/24 Atomic Safety and Licensing Board Panel 9pp. 14479 187 24X Fiche 50-329,82/08/24,8208300291.
- 8208240140 Advises that 8ER suppl will not be completed by scheduled 820827 date NRC will shortly notify ABLB & parties of schedule for finalization of SER suppl WILCOVE, M N Hearing Branch 2 82/08/25 BECHHOEFER, C. DECKER, R 8 , COWAN, F P. Atomic Safety and Licensing Board Panel 2pp 14554 357 24X Fiche 50-329, 82/08/25, 8208240140

H General correspondence

- 8207200110 Responds to 820622 1tr forwarding M Sinclair 820524 1tr re 20/200110 Responds to 82082 It Forwarding in Sinciair 821 rights of intervenors during licensing proceedings Intervenors have right to participate in ACRB activities Applicant did not agree to addit tour of facilities DIRCKB.H J Office of the Executive Director for Operat: 82/07/09 LEVIN.C Benate Opp 13760 307 24X Fiche 30-327.82/07/09.8207200110.
- --8206200044 Forwards M Sinclair 820524 ltr re rights of intervenors during proceedings for local plants Add1 info requested re rights of intervenors & right to participate in ACRB activities Info needed by 820705
 LEVIN.C Senate 82706/22 FALLADINO, N J Commissioners 3pp 13760-314 24X Fiche 50-329, 82/07/09,8207200110 Commissioners Spp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8207070028 Forwards Amend 105 (Revision 13 to response to NRC requests re plant fill) to application for CPs & OLs. Amend consists of new App D to FBAR.

 COOK.J H Consumers Power Co. 82/06/25 DENTON.H R Office of Nuclear Reactor Regulation, Director. ip. 13720.254 24X Fiche: 50-327, 82/06/25, 8207070028

- --8207070058 Amend 105 (Revision 13 to response to NRC requests re plant fill) to application for CPs & OLs.consisting of new App D to FSAR COCK.J H Consumers Power Co 82/06/25. 4.500pp 13720 255 24% Fiche 50-327.82/06/25.8207070028
- @ Inspection reports: IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leatage " Svc list encl.
 URDAN.E L Division of Engineering & Guality Assurance. B2/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 9204210395 IE Info Notice 81-24, Part 3. Suppl 1. "Clarification of Placement of Personnal Monitoring Devices for External Radiation " Svc list encl JORDAN, Et. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pg 14358 001 24% Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl.

 JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp, 14381 001, 24X Fiche 50-000, 82/07/20, 8204210396
- B204210397 IE Info Notice B2-24, "Hater Leaking From U Herafluoride Overpacks " Byo list encl. COBB,L I Division of Fuel Facilities, Materials & Safeguards. B2/07/20 Consolidated Edison Co of New York. 71pp 14357.2 24X Fiche 50-000.82/07/20.8204210397
- 8204R1039B IE Info Notice 82-25, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Bvc list enc! JRDAN.E L. Division of Engineering & Quality Assurance B2/07/22, Consolidated Edison Co of New York 112pp 14174:321, 24X Fiche 50-000, 82/07/22, 820421039B.
- 8204210401 1E Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl.

 JORDAN-E L Division of Engineering & Guality Assurance 82/07/23

 Consolidated Edison Co of New York 122pp. 14380-115 R4X

 Fichs. 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-27, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PMRs." Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14174 120 24X Fichs 50-000, 82/07/23, 8204210402.
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse FWR Power Plents." Svc list enci JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357:013. 24X Fichs 50-000, 82/07/26. 8204210403
- 8208160453 Forwards IE Inap Repts 50-329/81-23 & 50-330/81-23 on 811201-820630 No noncompliance noted, KNOP,R C. Division of Project & Resident Programs 82/07/26, COOK.J.W. Consumers Power Co. 2pp 14348:238 24X Fiche 50-329,82/07/26,8208160453
- --8208160459 IE Insp Repts 80-329/81-23 & 50-330/81-23 on 811201-820630 No noncompliance noted Major areas inspected exam of site conditions & laydown areas, onsite storage of matl.mgt meetings & changes in site mgt COOK.R.J. BOYD.D.C. Division of Project & Resident Programs. 82/07/26 App. 14348.240, 24X Fiche.50-329,82/07/26,8208160433,
- 8204210405 IE Info Notice 82-di, "Overexposure of Diver During Work in Fuel Storage Foo! " Svc list enc! JORDAN.E.L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York, 122pp 14357,146. 24X Fiche: 50-000, 82/07/28, 8204210405
- 8208130321 Forwards IE Insp Repts 50-329/82-10 & 50-330/82-10 on 620602-04,30 & 0701. No nomcompliance noted LITTLE: W S. Division of Engineering & Technical Programs. 82/07/28, CODK, J W. Consumers Power Co 2pp 14336: 329, 24X Fiche 50-329, 82/07/28, 8208130321.
- --B208130323 IE Insp Repts 50-329/82-10 k 50-330/82-10 on B20402-04,30 & 0701 No honcompliance noted, Major areas inspected followup on 100FR50, 55e items re containment internal structures coating deficiency
 HAWKINS.F.C., WILLIAMS.C.C. Region 3, Dffice of Director
 82/07/22 4pp. 14336:331, 24X Fiche 50~329,82/07/28,8208130321.

- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000.82/08/05.8204210407
- 8208240413 Forwards IE Insp Repts 50-329/82-11 & 50-330/82-11 on 820519-0702 & notices of violation & deviation LITTLE,N S Division of Engineering & Technical Programs 82/08/09 CODK, J W Consumers Power Co 2pp 14524 031 24X Fiche 50-329, 82/08/09,8208240413
- --8208240416 Notice of violation from insp on 820519-0702 LITTLE.W S Division of Engineering & Technical Programs 82/08/07 ip 14524 033 24X Fiche 50-327,82/08/09,8208240413
- --8209240419 Notice of deviation from insp on 820519-0702

 # Region 3, Office of Director 82/08/09 ip 14524 034 24X
 Fiche 50-329,82/08/09,8208240413
- --B20B240425 IE Insp Repts 50-329/B2-11 & 50-330/B2-11 on B20519-0702 Noncompliance noted one 3/B-inch anchor on extensioneter EX5 found to have embedment of only 1 inch & use of unapproved installation forms GARDMER.R N , LANDSMAN,R β , WILLIAMS.C C Region 3, Office of Director B2/0B/02 10pp 14524 035 24X Fiche 50-329.B2/0B/09, B20B240413
- R Periodic operating reports & related correspondence
- 8208040049 Forwards ALAB-104 monthly rept for June 1982, consisting of Bechtel. BEW & util repts written or clased during month re QA, audits, nonconformances & corrective actions COOK, J W Consumers Power Co 82/06/25 DEYOUND, R C Director's Office, Office of Inspection and Enforcement J26pp 14191 219 24X Fithe 50-329, 82/06/25, 8208040049
- S Reportable occurrences, LERs & related correspondence
- 8208100326 PNO-IXI-82-068 on 820503 allegations from former employee of HVAC contractor received re false or incomplete QA documentation for HVAC work at sites Special inep of Zat's Co & facilities initiated MALKER, D. KNOP, R.C. SPESSARD, R.L. Region 3, Office of Director 82/07/22 1p 14298 183 24X Fiche 50-000, 82/07/22, 8208100126
- 8208100077 Final deficiency rept re electrical components associated w/ MSIV actuators, logic cabinets & control panel inserts.
 Initially reported on 820204 Furchase Order 7220-M-238(g) issued to procure corrective matis
 CDDX.J N Consumers Power Co BALLWEG.T G. HUGHES, E M Bechtel
 Corp 82/07/30 KEPPLER.J G Region G. Office of Director 7pp
 14297 330 24X Fichs 50-329,82/07/30.8208100097
- 8208100131 Amended final deficiency rept re nuclear instrumentation/
 reactor protection sys (NI/RPS) Initially reported on
 780406 NI/RPS grounding scheme modified to ground
 channelised circuits to Class IE instrument ground
 COOK. J W Consumers Power Co. 82/07/30 KEPPLER, J G Region 3,
 Qffice of Director 4pp 14298 175 24% Fiche 50-329,82/07/30,
 8208100131
- 8208100280 PNO-111-82-071 on 8207R9, received Part 21 rept via telcon w/Zack Co re documentation discrepancies for welds made to HVAC components at La Salle & possibly at Clinton & Hiddend Helder of record may not be actual welder HALKER, R D . KNOP, R C . SPESSARD, R L Region 3, Office of Director 82/07/30 19 14294 352 24% Fiche 50-000, 82/07/30, 8208100280
- 8208160248 Potential Part 21 rept re weld records Initially reported on 820729 Review of documents indicates possible discrepancy between welder of record & welder completing welds investigation continuum; DE 2UTEL.C 2 Zact Co 82/08/02 KEPPLER.J 0 Region 3, Office of Director 10pp 14346 331 24X Fiche 50-000,82/08/02.8208160248
- 8208130215 Interim deficienty rept re underrated terminal strips on Limitorque valve operators Initially reported on 810213. Underrated terminal blocks replaced w/correctly rated Marathan 300 Series blocks Next rept expected by 821022. COOK, J W Consumers Power Co. 82/08/06 KEPPLER, J G Region 3, 07ffce of Director 14pp 14333 028 24X Fichs 50-329,82/08/06,8208130215
- B20Bi605i4 Interim deficiency rept re B&H steam generator auxiliary feedwater header design change initially reported on B20526 Design mod provides for eddition of external auxiliary feedwater distribution header w/eight injection noziles. COOK, J H Consumers Power Co 82/08/06 MEPPLER, J G. Region 3, Office of Director DENTON-H R Office of Nuclear Reactor Regulation, Director 37pp 14349 328 24% Fichs 50-329,82/08/06.

- 8208240268 Interim deficiency tept re Q-related equipment cooled by non-0 HVAC sys Project engineering reviewing safety functions of Q devicus to evaluate safety-related implications of failure Next rept by 031122 CODK, J W Consumers Power Go 02/08/17 KLPPLER, J Q Region 3, QFfice of Director 5pp 14521 357 24X Fiche 50-329,82/08/17, 2010200248
- T Hearing transcripts on non-antitrust matters
- 8208170009 Transcript of 820812 hearing in Midland, MI Pp 8,100-8,316 # Atomic Safety and Licensing Board Panel 02/08/12 216pp 14960 122 24X Fiche 50-724,82/08/12,8208170009
- 8208170022 Transcript of 820813 meeting in Midland MI Pp 8.317-8.546 * Atomic Bafety and Licensing Board Panel 82/08/13 23ipp 14359 251 24X Fiche 50-329.82/08/13.8200170022
- DOCKET 50-331 DUANE ARNOLD ENTROY CINTER

 F Security, medical, emergency & fire protection plans
- 8208040380 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/07/20 Document Management Branch ip 14224-190 24X Fiche 80-331.82/07/28, 8208040380
- --8208040381 Forwards public version of reviewd Emergency Plan Implementing Procedures EPIP 3 3b, "Followup Dose Projections" & EPIP 1.2, "Notification of Emergency Response Organizations & Offsite Agencies"
 MEYER.K.A. Jows Electric Light & Power Co. 82/07/19. DENTON.H.R. Office of Nuclear Reactor Regulation, Director ip 14224 191, 24X Fiche. 50-331. 82/07/26. 8208040380
- --8208040382 Public version of Revision I to Emergency Plan Implementing Procedure EPIP 3 3b, "Followup Dase Projections" & Revision 2 to EPIP 1.2, "Notification of Emergency Response Organizations & Offsite Agencies "

 ** Iowa Electric Light & Power Co 02/07/12 115pp 14224:192 24X Fiche 50-331,82/07/28,8280840380
- 820Bii0220 Releases public version of draft emargency preparedness scenario FELTON.J M Division of Rules and Records. 82/07/27 Document Hanagement Branch 1p 14310 177 24X Fiche 80-331.82/07/29, 820Bii0220
- --8208110222 Forwards public version of diaft "Emergency Preparedness Exercise Scenario, 820728" RAZLAFF, W J EDS Nuclean, Inc 62706/25, ORIMES, B K, Division of Emergency Preparedness in 14310-170 24X Fiche, 50-331, 82707/29, 0200110220
- --8208110225 Public version of draft "Emergency Preparedness Exercise Scenario, 820728" RIDOE, R H EDS Nuclear, Inc. # Iowa Electric Light & Power Co 82/06/25 223pp 14318; 179. 24X Fiche, 80-331, 82/07/29, 8208110220
- B208270391 Forwards IE Insp Rept 50-331/82-12 on 020/27-29 No noncompilance noted PAPERIELLO,C J Division of Emergency Preparedness & Operational Support B2/08/13 ARNOLD,D Town Electric Light & Power Co. 2pp. 14565 084 24X Fiche 80-331,82/08/13,8208270.391
- --BR08270375 IE Insp Rept 50-031/82-12 on 820727-29, No noncompliance noted Major areas inspected, emergency preparadness exercise PHILLIPS, M.P., PATTERSON, J.P., AXELSON, W.L., Division of Emergency Preparadness & Operational Support 02/08/13 15pp 14555.086 24X Fiche: 50-331.82/08/13.8200270371.
- H General correspondence
- 8208170243 Advises that L Liu elected President & Chief Operating Officer, effective 820803 ROOT, L. D. Iowe Electric Light & Power Co. 82/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director, 1p. 14368.337 24X Fiche 50-331,82/08/11,8288170243

- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licenases of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list encl
 DIRCKS, W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York, 73pp 14174 OOI 24X Fiche 50-000,82/07/02,8207080064
- 8208060048 Forwards Equipment Qualification Branch request for additing to NUREO-0737. Item II D i re relief & safety valve test requirements. Response requested within 45 days VASBALLO, D B Operating Reactors Branch 2 82/07/28. ARNOLD, D Towa Electric Light & Power Co 4pp 14282 084 24% Fiche 50-331.82/07/28.8208060048
- 8208180256 Advises that THI Item II.K 3 i5 resolved for facility Proposed method for preventing spurious isolation of HPCI/ reactor core isolation cooling sys acceptable Full implementation may require Tech Spec revision VASSALLO,D B Operating Reactors Branch 2 82/07/28 ARNOLD,I Joue Electric Light & Power Co 3pp 14389 287. 24X Fiche 30-331,82/07/28,8208180256
- 8208190005 Forwards revised version of model Tech Bpecs re electric power monitoring of reactor protection sys. VABSALLO, D B Operating Reactors Branch 2 82/07/28, ARNOLD, D Iowa Electric Light & Power Co 3pp 14506 311 24X Fichs 50-331, 82/07/28, 8208190005
- 8208310299 Responds to 820604 request for draft action plan to upgrade regulatory performance in vix areas in need of improvements. Areas include communications, mgt & supervisory involvement, station procedures, safety committee charter & training plan LIU, L lowa Electric Light & Power Co 82/07/30 KEPPLER, J Q. Region 3, Defice of Director. 28pp 14693.064, 24X Fiche 50-331,82/07/30,8208310299
- 8208250003 Requests verification of satisfaction of encl criteria re NUREO-0737. Item II, K 3 22, "Automatic Buitchover of Reactor Core Isolation Cooling Sys Buction " Response requested within 30 days VASSALLO, D. B Operating Reactore Branch 2 82/08/05 ARNOLD, D Iowa Electric Light & Power Co 4pp 14559 222 24X Fiche: 50-331, 82/08/05, 8208250003.
- 8208230465 Requests addifiee for review of Amends 67 % 77 to License DPR-49 re organization structure % definition of operable MILLER, W O License Fee Management Branch, 82/08/06 ARNOLD, D lowa Electric Light % Power Co 1p 14518 359 24% Fiche 50-331, 82/08/06, 8208230465
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list enci EIBENHUT, D. 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p. 14356 332 24X Fiche. 50-000, 82/08/09, 8208090194
- 8208190399 Requests documentation indicating how each criterion of NUREO-0737. Item II B 3 re post-accident sampling satisfied Schedule requested within 20 days of receipt of ltr VASBALLO, D B. Operating Reactors Branch 2 82/08/09 ARNOLD, D lows Electric Light & Power Co 10pp. 14504;176. 24X Fiche 50-331.82/08/09.8208190399
- 8208170092 Bubmits info supporting request for extension for implementation of hydrogen control interim requirements, Due to overlap of activities.combiner installation will exceed 18 months & thus cannot be completed during 1983 outage RODT.L.D. Iowa Electric Light & Power Co. 82/08/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director, 2pp 14358, 212, 24X Fiche, 50-331, 82/08/11, 8208170092.
- 8208230346 Documents intention to extend current Cycle 6 operating fuel cycle until first quarter 1783 Extension necessitated by fuel cycle & peak load economics Facility schedular commitments for NUREG-0737 items encl ROOT-L D lows Electric Light & Power Co. 82/08/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 4pp 14508-233, 24X Fiche 50-231.82/08/17.8208230346.
- 8208270462 Comments un dreft regulatory improvement program transmitted by 820730 ltr Pian does not incorporate problem areas identified in internal util assessments. INPO evaluations & consultant reviews. Program to be subj of 820713 meeting.

 KEPPLER. J Q. Region 3. Office of Director. 82/08/20. ARNOLD. D. Iowa Electric Light & Power Co. 3pp 14565-334 24X

 Fichs. 50-331, 82/08/20, 8208270462

- 8208270505 Application to amend License DPR-49, revising App A Tech Spacs to delay implementation of surveillance requirement for functional testing of mechanical snubbers until 830630 refueling outage Class II amend fee encl ROOT.L D Town Electric Light & Power Co 82/08/20 DENTON.H.R. Office of Nuclear Reactor Regulation. Director 2pp 14566 043. 24% Fiche 50-331,82/08/20,8208270505
- --8208270512 Proposed Tech Spec 3 6-13 re surveillance requirement for functional testing of mechanical equibers vious Electric Light & Power Co 82/08/20 1p 14566:045, 24X Fiche 50-331.82/08/20,8208270505
- 820B300190 Remits addi fee in response to NRC 820629 ltr re Class III fees for 820610 application for amend to Tach Specs ROOT.L D Towa Electric Light & Power Co. 82/08/23 DENTON.H. Office of Nuclear Reactor Regulation, Director ip. 14596-013. 24X Fiche 50-331.82/08/23.8208300190

Q Inspection reports: IE Bulletins & correspondence

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list ent! JRBAN.E L Division of Engineering & Guality Assurance, 82/07/16, Consolidated Edison Co of New York 87pp. 14356:274, 24X Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/19 Hichigan, Univ of 112pp 14358-001 24X Fiche. 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressurs " Svc list encl JORDAN:E L. Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York, 112pp. 14381 001, 24X Fiche.50-000.82/07/20.8204210394
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluorida Overpacks," Svc list encl. COBB.L I. Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York. 7ipp. 14357.276, 24X Fiche 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Bvc list enci JORDAN:E L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co of New York. 112pp 14194.321. 24X Fichs 50-000.82/07/22.8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Bvc list encl JORDANIE L Division of Engineering & Guality Assurance 82/07/23, Consolidates Edison Co of New York, 122pp 14380.115, 24% Fiche. 30-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) ouide Tube Bupport Pin Failures at Westinghouse PHRs." Bvc list encl JORDAN.E L. Division of Engineering & Guelity Assurance. 82/07/23, Consolidated Edison Co. of New York, 127pp 14194.120 24X Fiche: 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sheeves in RCS Piping at Certain Westinghouse PWR Power Plants." Byc list encl JORDAN.E.L. Division of Engineering & Quality Assurance, 82/07/26, Consolidated Edison Co. of New York, 12ipp. 14357.013, 24X Fichs 50-000.82/07/26,8204210403
- 8204210408 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl.
 JORDAN.E.L. Division of Engineering & Quality Assurance. B2/07/28
 Consolidated Edison Co of New York. i22pp. 14357:146 24x
 Fiche: 50-000, 82/07/28, 8204210405.
- 9208230309 Forwards IE Insp Rept 50-331/82-03 on 820401-0531 % notice of violation STREETER, J F. Division of Project & Resident Programs. 82/08/03. ARNOLD, D. Towa Electric Light & Pawer Co. 2pp 14510:340. 24X Fiche. 50-331:82/08/03,8208230309
- --8208230310 Notice of violation from insp on 820401-0531. STREETER, J.F. Division of Project & Resident Programs, 82/08/03. 1p. 14510.342. 24X Fiche 80-331.82/08/03.8208230309.

- --B20B230313 IE Insp Rept 50-331/B2-03 on B20401-0531 Noncompliance noted reactor protection sys trip occurred due to operator error, high pressure scran & Junper B2-146 removed from Cardos sys & urong clearance form signed off CLARDY, L., REYES, L. Division of Project & Resident Programs B2/08/03 9pp 14510 343 24x Fiche 50-331, B2/08/03, B20B230309
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Suclist entl JORDAN.E L Division of Engineering & Quality Assurante 62/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000.82/08/05 6204210407
- 8208190181 EN-82-029 on 820813 notice of violation & proposed imposition of civil pensity uill be issued to licensee Violations involved exceeding Tech Spec limits re starting & testing of emergency diesel generator BARBER.O. LIEBERMAN J Director's Office, Office of Inspection and Enforcement 82/09/10 ip 14385-352 24% Fiche 50-331.82/08/10,8208190181
- 8208300116 Forwards IE insp Rept 50-331/82-07 on 820601-30 & notice of violation SPESSARD.R L Division of Project & Resident Programs 82/08/10 ARNOLO,D low Electric Light & Power Co 2pp 14599 197 24X Fiche 50-331.82/08/10.8208300116
- --9208300118 Notice of violation from insp on 820601-30 SPEBSARD.R L Division of Project & Resident Programs 82/08/10 2pp 14599 199 24X Fiche 50-331.82/08/10.8208300116
- --820830012i IE Insp Rept 50-331/82-07 on 820401-30 Noncompliance noted failure to include data & lock valve after surveillance. failure to follow startup procedure during MSIV opening & failure to store tagout log records CLARDY.L S. REYES,L A Division of Project & Resident Programs 82/08/09 10pp 14599 201 24X Fiche 50-331.82/08/10.8208300116
- 8208240306 Discusses IE insp on 620315-0512 & forwards notice of violation & notice of proposed imposition of civil penalty KEPPLER, J G Region 3. Office of Director 82/08/13 LIV.L Iowa Electric Light & Power Co. 3pp j4520 207 24X Fiche 50-331,82/08/13.8208240306
- r-B20B240307 Notice of violation & notice of proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted failure to adequately ensure that post-maint testing completed after maint performed on safety-related equipment KEPFLER.J O Region 3. Office of Director 82/08/13 5pp 14520 210 24% Fiche 53-331,82/08/13.8208240306
- 8208270391 Forwards IE Insp Rept 50-331/82-12 on 820727-29 No noncompliance noted PAPERIELLO,C J Division of Emergency Preparedness & Operational Suggest 62/08/13 ARMOLD.D Iowa Electric Light & Power Co 2pp 14565 084 24% Fiche 50-331.82/08/13.8208270391
- -8208270375 IE Insp Rept 50-331/82-12 on 820727-29 No noncompliance noted Major areas inspected emergency preparedness exercise PHILLIPS.H P , PATTERSON, J P , AXELSON, H L Division of Emergency Preparedness & Operational Expepter & 82/08/13 15pp 14565 086 24 X Fiche 50-331,82/08270391

Periodic operating reports & related correspondence

- 208270010 Responds to FOIA request for documents detailing collective dose esposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTGN. J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000,82/07/13,8208270010
- --8209270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVB1" 4 NRC - No Detailed Affiliation Given 82/07/13 480e 14679 216 24X Fiche 50-000,82/07/13.8208270010
- --8208270535 Forwards "Personnel Whole Body Exposures for CY81," for Licenses id-15018-02 & DPR-49.per 10CFR20 A07(a) W/a rept for 14-15018-02 MINECK.D L fows Electric Light & Power Co 82/03/03 Office of Management and Program Analysis ip 14680 026 24X Fiche 50-000,82/07/13.8208270010
- 8208190106 Forwards monthly operating rept for Jul 1982 MINECK, D L I low Electric Light & Power Co 82/08/13 Director's Office, Office of Inspection and Enforcement ip 14383 138 24X Fiche, 50-331,82/08/13,8208190106

- --9208190109 Monthly operating rept for Jul 1982 HILL:K L I I was Electric Light & Power Co 92/08/13 6pt 14383 139 24X Fiche 50-331,82/08/13,8208190106
- 8 Reportable occurrences. LERs & related correspondence
- 8208090167 RO recirculation pump & jet pump flow instrumentation indicated riow imbalance between two recirculation loops Sixteen jet pumps declared inoperable Orderly shutdown initiated to cold shutdown conditions MINECK.D.L. Iowa Electric Light & Power Co. 82/07/20 KEPPLER, J. Region 3. Office of Director ip 14271 180 24X Fiche \$0-331,82/07/20,8208090167
- 8208050376 Forwards LER 82-045/03L-0 MINECK.D L IDWA Electric Light & Power Co 82/07/26 KEPFLER, J Q Region 3. Office of Director ip 14209 166 24X Fiche 80-331.82/07/26.8208050376
- --8208050383 LER 82~045/03L-0 on 820704, during cold shutdown surveillance testing, high pressure turbine switches P8-1005A:C & D tripped above Tech Specs Caused by instrument drift Buitches recalibr & retested HTLL:K L Idwa Electric Light & Power Co 82/07/26 Region 3, Office of Director ip 14209 167 24X Fiche 50-331, 82/07/26, 8208050376
- 8208060327 Forwards incident reporting sys repts re spill of contaminated water & contamination of personnel in auxiliary bids & failure of control rod guide tube support pins for transmittal to NEA MICHELSON.C Director's Office 82/07/29 LAFLEUR, J D Office of Internetional Programs, Director 17pp 14281 234 24X Fiche 50-000.82/07/29.8208060327
- --8208090076 LER 82-044/03L-0 on 820629, B control bldg standby filter unit flow controller would not control discharge valve AV-7318B & low flow slarm could not be cleared Caused by moisture in instrument air from capacity drugers HILL, K. L. Iowa Electric Light & Power Co. 82/07/29 Region 3, 0ffice of Director. 2pp. 14270-235. 24X Fiche 50-331, 82/07/29, 8208090093
- 8208100045 RD on 820729, during normal operation surveillance testing, differential pressure switches PD8-4304 & 4305 tripped out of spec high at 0.65 & 0.7 psid Pressure switches recalibr & functionally tested MINECK, D. L. Iowa Electric Light & Power Co. 82/07/29 KEPPLER, J. G. Region 3. Office of Director 1p. 14296 249 24X Fiche 50-331, 82/07/29, 8208100045
- 8208100139 RD 82-3. on 820727, health physics technician found offgas stack sample line isolation valve V-41-3 in partially closed position & process radiation filter holder 18-217 improperly connected Caused by personnel error MINECK, D. L. Iowa Electric Light & Power Co. 82/08/05 DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp 14297 361, 24% Fiche 50-331, 82/08/05, 8208100139
- 8208130140 Forward* LER 82-046/03L-0 MINECK, D.L. Jown Electric Light & Power Co 82/08/05 KEPPLER, J. Q. Region 3, Office of Director 1p 1433B 097 24X Fiche 80-331, 82/08/05, 8208130140
- --8208130144 LER 82-046/03L-0 on 820730, main steam line C high temp indicating switch TIS-4445 subchannel 2 tripped outside Tech Spec Caused by instrument drift Switch recalibr.
 HILL.K L Idwa Electric Light & Power Co 82/08/05 Region 3, Office of Director, ip 14338 098 24X Fiche 50-331,82/08/05, 8208130140
- 8208130233 Forwards LER 82-047/01T-0 MINECK.D L. Jowa Electric Light & Power Co 82/08/05 KEPPLER, J. G. Region 3. Office of Director ip 14333 177, 24X Fiche 50-331, 82/08/05, 8208130233

- --8208130237 LER 82-047/01T-0 on 820729, during testing, pressure differential switches which control reactor bldg to suppression chamber vacuum breakers CV-4304 & CV-4305 tripped out of spec Caused by instrument drift HILL.K L Iowa Electric Light & Power Co 82/08/05 Region 3, Office of Director 2pp 14333 178 24X Ficha 50-331,82/08/05,8208130233
- 8208230037 Unique Rept 82-1 on 820706, diesel fire pump 1P-49 declared inoperable when jacket cooling water boiled out during surveillance test Caused by abnormally high operating temp, due to malfunctioning HX HX cleaned & repaired MINECK, D. L. Iowa Electric Light & Power Co. 82/08/12 KEPPLER, J. Region 3, Office of Director 2pp 14517 260 24X Fiche 50-331,82/08/12,8208230037
- 8208240135 Forwards LER 82-049/03L-0 MINECK,D L Iowa Electric Light & Power Co 82/08/13 KEPPLER,J @ Region 3, Office of Director ip 14519 334 24X Fiche 30-331,82/08/13,8208240135
- --B208240139 LER B2-048/03L-0 on 820719 during startup surveillance testing, intermediate range monitor (IRM) D failed downscale & declared inoperable IRM F also declared inoperable previously Cause undetermined Evaluation will be performed VARNER.D M I dwa Electric Light & Power Co B2/08/13. Region 3, Office of Director ip 14519,339 24X Fiche 50-331,82/08/13,8208240135
- 8208240314 Forwards LER 82-049/03L-0 MINECK,D L lowa Electric Light & Power Co 82/08/13, KEPPLER.J Q. Region 3. Office of Director. 1p 14520 351 24X Fiche 50-331, 82/08/13, 8208240314.
- --B208240317 LER 82-049/03L-0 on 820720, during startup, intermediate range monitor (IRM) F found downscale & declared inoperable Cause undetermined IRM F bypassed & manual half-scram entered on reactor protection sys Channel B VARNER, D M Iowa Electric Light & Power Co 82/08/13 Region 3, Office of Director ip 14520 352 24X Fiche 30-331,82/08/13,8208240314.

DOCKET 50-332 BARNWELL REPROCESSING PLANT

- F Becurity, medical, emergency & fire protection plans
- B208040171 Expresses appreciation for hospitality extended during Mar & Apr site visits to review safeguards sys. BURNETT,R F Division of Safeguards 82/06/01 BUCKHAM,J A Allied General Nuclear Bervices ip 14236:315 24X Fiche 50-332,82/06/01,8208040171
- Q Inspection reports, IE Bulletins & correspondence
- B204210395 IE Info Notice 81-26.Part 3.Suppl 1, "Clarification of Placement of Personnel Monitoring Davices for External Radiation "Svc list encl.

 JORDAN,E.L. Division of Engineering & Quality Assurance B2/07/19

 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19, B204210395
- DOCKET 50-332 JAMES A FITZPATRICK NUCLEAR POWER PLANT

 F Security, medical, emergency & fire protection plane
- 8208190235 Informs'that scenario re postulated accident will be submitted as scheduled in response to NRC 811026 ltr FEMA will also receive exercise objective BAYNE.J P. Power Authority of the State of New York 82/06/02 HAYNES.R C Region 1. Office of Director 7pp 14387 147 24X Fiche 50~333,82/06/02.8208190235
- 8208190162 Forwards Revision 2 to security force training & qualification Plan Revision withheld (ref 10CFR2 790)
 BAYNE, J P Power Authority of the State of New York 82/08/09
 VASBALLO, D B. Operating Reactors Branch R 2pp 14381 020 24%
 Fiche 50-333, 82/08/09, 8208190162
- 9208270698 Ack receipt of 820412 ltr transmitting changes to facility security plan Changes acceptable VASBALLO, D B. Operating Reactors Branch 2 82/08/18, SINCLAIR, L W Power Authority of the State of New York 2pp 14683:049. 24X Fiche 50-333,82/08/18,8208270698.

- P Operating license stage documents & correspondence
- 8208250488 Forwards revised version of model Tach Specs re electric power monitoring of reactor protection sys VASSALLO,D B Operating Reactors Branch 2 82/06/28 SINCLAIR,L H Power Authority of the State of New York 3pp 14362 257 24X Fiche 30-333,82/06/28,8208250488
- 8207080064 Osneric ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl DIRCKS. W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 66247 23i, 24% Fiche 50-000.82/07/02.8207080064
- 8208030243 Notifies of changes in mgt organization structure to be incorporated in proposed Tech Epecs WILVERDING.O M Power Authority of the State of New York 82/07/21 VAROA.S A Operating Reactors Branch 2 2pp 14158 142 24X Fiche 50-000.82/07/21.
- 820B040225 Requests submittal documenting how each criterion of NUREO-0737 Item II B 3 has been satisfied within 20 days of receipt of itr Criteria guidelines for NUREO-0737 encl VABBALLO, D B. Operating Reactors Branch 2 B2/07/27 BINCLAIR.L W Power Authority of the State of New York 10pp 14232,243 24X Fiche 30-333.82/07/27.820B040225
- 8208040220 Concludes that commitments & exceptions to requirements of Reg Ouide 1 38, Revision 1 & Reg Ouide 1 146 re qualification of insp & audit personnel acceptable. Review of 820301 response to Generic Ltr 81-01 complete VASSALLO, D. B Operating Reactors Branch 2 82/07/28 8INCLAIR, L W, Power Authority of the State of New York 2pp 14232, 281. 24% Fiche 50-333, 82/07/28, 8208040220
- 8208130115 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS NINE MILE PLANT AND FITZPATRICK CASE STUDY Docket Nos 50-220, 50-410 & 50-333 (Niagara Mohawk Power Corporation And Power Authority Of the State of New York)
 BRANCH.K., MEALE, R. Mountain West Research, Inc. * Social Impact Research, Inc. FIN B-1268 NUREO/CR-2747 V06 82/07/31
 Division of Health, Siting & Environment, 287pp Available at NTIS \$8 00 14341 001 24% Fiche 50-000, 82/07/31, 8208130115
- 820BiB0262 Concludes that electrical plant sys design acceptable W/respect to adequacy of station distribution sys voltage Safety evaluation & technical evaluation rept encl VASBALLO.D B Operating Reactors Branch 2 82/08/02 BINCLAIR.L W Power Authority of the State of New York 5pp 14387:295 24X Fiche 30-333.82/08/02.8208180245
- --8208180267 "Technical Evaluation Rept, Adequacy of Station Electric Distribution Sys Voltages, James A Fitzpatrick Nuclear Power Station, Docket No. 50-333, "interim rept MEBER, D. A. E040, Inc. FIN. A-6427. E00-EA-5340. 81/01/31 SHEMANSKI, P. C. Division of Licensing 13pp 14389 300 24X Fiche 50-333,82/08/02.8208]80262
- B20B100246 informs that interim dose assessment sys is imperable due to electrical problems w/computer.per TMI Action Item III A 2 Repairs will be completed by 820B17.
 BAYNE, J P Power Authority of the State of New York, B2/08/05, VASBALLD, B Operating Reactors Brench 2, ig 14274 291, 24X Fiche 50-333,82/08/05,8208100246
- 8208240164 Requests add1 info, verifying satisfaction of entl acceptance criteria re NUREO-0737. Item II K 3 22, "Automatic Buitchover of Reactor Core Isolation Cooling Sys Suction " Response requested within 30 days VASBALLO.D B Operating Reactors Branch 2 82/08/05, BINCLAIR, L. W Power Authority of the State of New York. 4pp 14548 177 24X Fiche 50-333, 82/08/05, 8208240164
- 8208250012 Forwards request for add1 info re NUREO-0737. Item II.D.1.
 "Relief & Safety Velve Test Requirements." to justify
 applicability of generic test results in NEDE-24988-P to
 safety/relief valve requirements at facility
 POLK.P J Operating Reactors Branch 2 82/08/06. SINGLAIR.L W.
 POWER Authority of the State of New York 4pp. 14551.355 24X
 Fiche: 80-333.82/08/04.8208250012.
- 8208090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list end EISENHUT, D 9 Division of Licensing 82/08/09, Consolidated Edison Co. of New York Ip 14356-332 24X Fiche, 50-000, 82/08/09, 8208090194.

DOCKETED ITEMS

- Submits revised schedule for TMI Items II 8 3 2, "Post-Sampling Mods" & II F 1 6, "Containment Hydrogen stion Monitor "
- ation Monitor
 P. Power Auth
- Application for amend to License DPR-59 changing elief valve inoperability requirements & limiting ns for operation for HPCI sys Amend effective until
- P Power Authority of the State of New York 82/08/, D 8 Operating Reactors Branch 2 2pp 14540 281 -333,82/08/12,8208250143
- 44 Proposed Tech Spec, changing reactor operation to 30 days in that safety/relief valve becomes inoperable & limiting lons for operation of NPCI sys re Authority of the State of New York 82/08/12 9pp 283 24X Fiche 50-333,82/08/12.8208250143
- IS "Design Varification Test Summary, Model 7567F" jet Rock Corp 1834 76/12/02 21pp 14540 292 24X 10-333, 82/08/12, 8208250143
- Advises that correct completion date for NUREQ-0737, Items & II F 1 6 should be 830331, correcting error in r Revised schedule encl Power Authority of the State of New York 82/08/23 D B Operating Reactors Branch 2 3pp 14679 002 24X 333, 82/08/23, 8208300224
- Informs that hardware & software will be operational by inland pole & associated equipment will be & operational by 830701 per NUREG-0737, A 2 2
- Power Authority of the State of New York 82/08/2: D.B Operating Reactors Branch 2 2pp. 14694 310 333,82/08/25.8208310420 82/08/25
- on reports. IE Bulletins & correspondence
- IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
- E Info Notice 81-24, Part 3, Suppl 1, "Clarification of of Personnel Monitoring Devices for External "Svc list encl Division of Engineering & Guality Assurance 82/07/19 Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19,

- E Info Notice 82-25, "Failures of Hiller Actuators Upon so of Air Pressure" Svc list entl . Division of Engineering & Quality Assurance 82/07/20 attd Edison Co of New York 112pp 14381 001 24X 00.82/07/20,8204210396
- E Info Notice 82-24, "Water Leaking From U Hexafluoride
- " Svc list encl
 Division of Fuel Facilities, Materials & Safeguards,
 Consolidated Edison Co of New York 71pp, 14357,276
 50-000,82/07/20,8204210397
- E Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Jres " Svc 11st enc! Division of Engineering & Quality Assurance 82/07/22 Ited Edison Co of New York 112pp 14174 321 24X VO. 82/07/22,8204210398
- Enfo Notice 82-28, "Hydrogen Explosion While Orinding in Drained & Open RCB " Byo list encl Division of Engineering & Quality Assurance 82/07/23 ted Edison Co of New York, 122pp 14380*115 24X 10,82/07/23,8204210401
- Info Notice 82-24, "Control Rod Drive (CRD) Quide Tube Failures at Hestinghouse PHRs " Byc list encl Division of Engineering & Quality Assurance, 82/07/23, ted Edison Co. of New York, 127pp 14194-120 24X 0, 82/07/23, 8204210402
- Info Notice 82-30, "Loss of Thermal Biseves in RCS Piping Westinghouse PWR Power Plants," Svc list enci, Division of Engineering & Quality Assurance 62/07/26 ted Edison Co of New York 12ipp, 14357-013 24X 0.82/07/26.8204210403

- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list and!
 JORDAN-E L. Division of Engineering & Quality Assurance B2/07/20
 Consolidated Edison Co of New York 122pp 14357 146 24X
 Fiche 50-000,82/07/28,8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche SO-000.82/08/05.8204210407
- 8208230103 Ack receipt of 820518 & 0802 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept S0-333/82-06
 STAROSTECKI, R Division of Project & Resident Programs 82/08/17
 MCNFILL, C A Power Authority of the State of New York 1p 14517 291 24X Fiche 50-333,82/08/17,8208230103 82/08/17
- --8208230108 Responds to NRC 820414 ltr re violations noted in 1E Insp Rept 50-333/82-06 Corrective actions operator stationed at portable monitor to continuously monitor containment atmosphere atmosphere
 MCMEILL, C A Power Authority of the State of New York
 STAROSTECKI, R Division of Project & Resident Programs
 14517 272 24X Fichs 30-333, 82/08/17,8208230103 82/08/04 200.
- --8208230112 Responds to NRC 820414 ltr re violations noted in IE Imag Rept 50-933/82-01 Corrective actions valves 250C & BA8-4 repositioned to agree w/lineup list & procedures reviewed for control of plant status MCNEILLiC A Power Authority of the State of New York 82/05/18 BTARGSTECKI, R Division of Project & Resident Programs 4pp 14517 274 24X Fiche 50-933, 82/08/17.8208230103
- R Periodic operating reports & related correspondence
- 8208270237 Forwards annual personnel radiation monitoring rept for CYBI.per 10CFR20 407 MCNEILL.C. A Power Authority of the State of New York 82/02/0 CQLLINS.D. Radiological Assessment Branch 1p 14679 298 24 Fiche 50-000 82/02/08
- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1781 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000,82/07/13,8208270010
- --B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81 "

 * NRC - No Detailed Affiliation Given 82/07/1:
 14679 216 24X Fiche 50-000,82/07/13,8208270010 82/07/13. 48pp
- --8208270193 Forwards annual rept for personnel whole body exposures for CYBI.per 10CFR20 407

 MCMEILL,C A Power Authority of the State of New York, 82/02/01

 Director's Office, Office of Inspection and Enforcement 1p

 14679 273 24X Fiche 50-000,82/07/13,8208270010
- --8208270200 Personnel whole body exposures for CY81

 e Power Authority of the State of New York 82/02/01 ip
 14677 274 24X Fiche 50-000,82/07/13,8208270010
- --8208270259 Annual personnel radiation monitoring rept for CYB1, per 10CFR20, 407 100FH20, 407 * Power Authority of the State of New York 82 14679 297 24X Fiche 50-000, 82/07/13, 8208270010 82/02/08 ip.
- B208100036 Forwards monthly operating rept for Jul 1982 MCNEILL,C A Power Authority of the State of New York Director's Office, Office of Inspection and Enforcement 14296 262 24x fiche 50-333,82/08/06,8208100036 82/08/04
- --8208100040 Menthly operating rept for Jul 1982 COOK.J. Power Authority of the State of New York 14294 263. 24% Fiche. 50-333.82/08/06.820810036 82/08/04, 9pp
- & Reportable occurrences, LERs & related correspondence
- 8208260539 Forwards LER 81-026/03L-0
 PASTERNAK.R J. Power Authority of the State of New York. 81/04/16
 ORIER, B H Region 1. Philadelphia, Office of the Director
 (81/03/01) 1p 14572 335, 24X Fiche 50-333,81/04/16.8208260539.

- --8208260544 LER 81-026/03L-O on 810324.RHR svc water flow transmitter 8 found out of calibr by more than 50% Caused by instrument drift Instrument recalibr & surveillance frequency increased CHILDS.W V Power Authority of the State of New York 81/04/16 Region 1. Philadelphia: Office of the Director (81/03/01) ip 14572 335 24X Fiche 50-333,81/04/16.8208260539
- 8208050307 Forwards LER 82-028/03L-0 MCNEILL.C A Power Authority of the State of New York 82/07/27 MAYNES, R C Region 1. Office of Director ip 14213 284 24X Fiche 50-333, 82/07/27, 8208050507
- --8208050516 LER 82-028/03L-0 on 820701, during normal operation while conducting surveillance, drywell equipment drain sump flow integrator found out of calibr & could not be adjusted to within tolerance Cause unknown Assembly replaced CHILDS, W V Power Authority of the State of New York 82/07/27 Region 1. Office of Director 1p 14219, 285 24X Fiche 50-333,82/07/27,8208050507
- 8208070085 Forwards LER 82-027/03L-0 MCNEILL.C A Power Authority of the State of New York 82/07/21 HAYNES,R C Region 1, Office of Director 1p. 14270 184 24X Fiche 50-333, 82/07/28, 8208070085
- --8208070088 LER 82-027/03L-0 on 820707.during normal operation, main steam line radiation monitor A tripped in inoperable condition when required to be operable Caused by loose instrument high voltage fuse Fuse reinstalled CHILDS, W V Power Authority of the State of New York 82/07/28 Region 1. Office of Director 2pp 14270 185 24X Fiche 50-333,82/07/28.8208090085
- 8208090066 Forwards LER 82-030/03L-0 MCNEILL, C. A Power Authority of the State of New York 82/07/30, HAYNES, R C Region 1. Office of Director. 1p 14269-227, 24X Fiche 30-333,82/07/30.8208090066
- --8208070069 LER 82-030/03L-0 on B20709, rod black monitor B found out of calibr Caused by instrument drift Monitor recalibr

 * Power Authority of the State of New York 82/07/30. Region
 1. Office of Director. ip. 14269 228 24X Fiche 50-333,82/07/30,8208090066.
- 8208160028 Forwards LER 82-031/03L-0. MCNEILL.G A Power Authority of the State of New York 82/07/30. HAYNES.R C Region 1: Office of Director. 1p 14344:308. 24X Fiche 30-333, 92/07/30. 8208160028.
- --8208160030 LER 82-031/03L-0 on 820715 during routine startup control rod 02-23 declared inoperable in fully inserted position. Caused by directional control valve 123 (insert valve) sticking in open position resulting in continuous insertion CHILDS.W V Power Authority of the State of New York 82/07/30, Region 1. Office of Director 2pp. 14344:309, 24X Fiche 50-333,82/07/30,8208160028
- 8208160031 Forwards LER 82-032/03L-0 MCNEILL.C A Power Authority of the State of New York 82/07/30, HAYNES.R C Region 1. Office of Director 1p. 14344 215. 24X Fiche 50-333, 82/07/30. 8208160031
- --8208160033 LER 82-032/03L-0 on 820716, during routine startup, inerting of containment w/nitrogen & establishment of drywell to torus differential pressure not completed within 24-h Caused by delays in nitrogen delivery & unloading problems.

 CHILDS.M.V. Power Authority of the State of New York, 82/07/30 Region 1, Office of Director. 2pp 14344*216, 24X Fiche 50-333,82/07/30.8208160031
- 8208230360 Forwards LER 82-033/03L-0 MONEILL.C A Fower Authority of the State of New York 82/08/09. HAYNES,R C. Region 1, Office of Director. ip 14512,355. 24X Fiche 50-333,82/08/09.8208230360
- --8208230363 LER 82-033/03L-0 on 820706, reserve power breaker 10022 was open for approx 4 minutes, rendering Light House Hill Line 3 unavailable Caused by lightning strike No corractive action required.

 CHILDB, H.V., CONVERSE, R.J. Power Authority of the State of New York 82/08/06. Region 1, Office of Director 1e, 14512:356, 24% Fiche; 50-333,82/08/09,8208230360
- 8208260230 Forwards LER 82-034/03L-0. MCNEILL,C A. Power Authority of the State of New York. 82/08/16. MAYNESR C Region 1. Office of Director. Ip 14552:352, 24X Fiche 50-333,82/08/16,8208260230.

- --8208260236 LER 82-034/03L-0 on 820713 during calibr of feedweter flow transmitters. A & B transmitters found out of procedural tolerance in excess of Tech Spacs Cause under investigation Followup rept expected within 14 days CHILDS. W V Power Authority of the State of New York 82/08/13 Ragion i. Office of Director ip 14552 353 24X Fichs 50-333,82/08/16.8208240230
- 8208260243 Forwards LER 82-035/03L-0 MCNETLL.C A Power Authority of the State of New York 82/08/16 HAYNES,R C Region 1, Office of Director 1p. 14554 288 24X Fiche 50-333, 82/08/16, 8208260243
- --8208260248 LER 82-035/03L-0 on 820804, while inerting drywell during startup, indicated torus level was below Tech Spec Caused by displacement of water in downcomers during inerting Tech Spec amend to be submitted CHILDS.W V Power Authority of the State of New York 82/08/16. Region 1, Office of Director ip 14554 289, 24X Fichs 50-333, 82/08/16, 8208260243
- 8208260169 Forwards LER 82-036/03L-0 MCNEILL.C.A Power Authority of the State of New York, 82/08/17, HAYNES, R C Region 1, Office of Director ip 14554 327 24X Fiche 50-333, 82/08/17, 8208260169
- --B208260178 LER 82-036/03L-0.on 820723; offgas radiation monitor B observed spiking in upward direction Caused by failure of Zener diode within plus/minus 15-volt power supply Entire unit replaced w/spare & calibr CHILDB,W V Power Authority of the State of New York, B2/08/17 Region 1, Office of Director ip 14554 328 24X Fichs 30-333,82/08/17,8208260169
- 8208260161 Forwards LER 82-038/03L-0 MCNEILL.C A Power Authority of the State of New York 82/08/20 HAYNES.R C Region 1, Office of Director ip 14555 349 24X Fiche 30-333, 82/08/20, 8208260161
- --8208260170 LER 82-038/03L-0.on 820801. MSIV A inboard 10% switch did not trip when tested to satisfy Tech Spec 3 1-1. Note 1. Caused by drift between switch operator & striker plate. Position switch will be investigated during maint nutage # Power Authority of the State of New York 82/08/20. Region 1. Office of Director 1p. 14555. 350. 24% Fiche 50-333.82/08/20.
- 8208260208 Forwards LER 82-037/03L-0 MCNEILL, C. A. Power Authority of the State of New York 82/08/20 HAYNES, R. C. Region 1, Office of Director ip 14554 331. 24X Fiche: 50-333, 82/08/20, 8208260208
- --8208260216 LER 82-037/03L-0 on 820730, during ascension to power, abnormally high teil piece temps indicated on interim Target Rock model safety relief valve F Probably caused by valve leakage from pilot seat Daily surveillance initiated # Power Authority of the State of New York 82/08/20 Region 10 Office of Director 3pp 14554:332 24X Fiche.50-333, 62/08/20, 8208260208
- 8208260266 Forwards LER 82-040/04T-0 MCNEILL, C.A. Power Authority of the State of New York. 82/08/20, HAYNES, R.C. Region 1, Office of Director. 1p. 14552:058 24X Fiche: 80-333, 82/08/20, 8208260266
- --8208260283 LER 82-040/04T-0.on 820810.environ radiological sampling resulted in anomalous result in spring mollusk samples. Possibly caused by high bioaccumulation factor due to concentration of manganess in lake.

 * Power Authority of the State of New York 82/08/20. Region 1. Office of Director. 3pp. 14552.359 24X Fiche 50-333. 82/08/20.8208260266.
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8208030352 Forwards preliminary onsite emergency preparedness exercise scenario to be used in 820217 joint full-scale exercise for facility emergency planning zone, per Emergency Planning Ltr 81-03 Encl withheld (ref 10CFR2 790), SIEBER, J. D. Duquesne Light Co. 82/01/07. HAYNES, R. C. Region i, Philadelphia, Office of the Director (81/03/01) 2pp 14155; 348 24X Fichs. 50-334, 82/01/07, 8208030352
- 8208100014 Forwards IE Insp Rept 50-334/82-15 on 820714-15 No noncompliance noted.
 SNITH, 9 H. Division of Emergency Preparedness & Operational Support, 82/07/27. CAREY, J. J. Duquesne Light Co. 2pp 14296-325. 24X Fiche. 50-334-82/07/27, 8208100014

- --B20Bi00017 IE Insp Rept 50-334/B3-15 on B20714-15 No noncompliance noted Major areas inspected emergency preparedness & observation of licenses small-scale exercise w/Columbiana County, BK WDJNAS, E J , CROCKER, H W Division of Emergency Preparedness & Operational Eupport 62/07/23 4pp 14276 327 24X Fiche 50-334, B2/07/27, B20B100014
- 8208170099 Forwards description of plan for upgrading meteorological sys per Reg Quide 1 23 & NUREO-0694 Field testing program scheduled for Aug/Sept 1982 will be modified Procedure developed to compensate for uncertainties in 35-ft sensors CAREY, J J Duquesne Light Co 82/08/10 VAROA, 8 A Operating Reactors Branch 1 10pp 14358 231 24X Fiche 50-334,82/08/10,
- 8208270565 Informs that fee requested in NRC 820714 ltr for 820616 application for temporary waiver no longer due Refund authorized for fee remitted w/810519 proposed revision to physical security plan MILLER; W O License Fee Management Branch 82/08/17 CAREY, J Duquesne Light Co 1p 14683 283 24X Fiche 50-334,82/08/17,8208270565
- K Utility Final Safety Analysis Report (FSAR) & amends
- B20B3i0i0i Chapter i to Beaver Valley Unit i updated FBAR, "Introduction ද Summary " • Duquesne Light Co 82/01/31 300pp 15497 046 24X Fiche 50-534, 82/01/31, 8208310101
- B20B310104 App 1A to Beaver Valley Unit 1 updated FSAR, "1971 AEC General Design Criteria Conformance"

 # Duquesne Light Co B2/01/31 37pp 15497 236 24X Fishs 50-334, B2/01/31. B20B310104
- B20B3i0107 Chapter 2 to Beaver Valley Unit 1 updated FSAR, "Sits "
 * Duquesna Light Co 82/01/31 700pp 15497 273 24X
 Fiche 50-334,82/01/31,820B310107
- 820B310107 App 2A to Beaver Valley Unit 1 updated FBAR, "Meteorologica)
 Program "
 * Duquesne Light Co 82/01/31 45pp 15498 360 24X
 Fiche 50-334,82/01/31,8208310109
- 8208310110 App 2A 1 to Beaver Valley Unit 1 updated FSAR, "First Annual Rept Meteorological Program" * Duquesme Light Co 82/01/31 60pp 15499 044 24X Fiche 50-334,82/01/31,8208310110
- 8208310114 App 2A 2 to Beaver Valley Unit 1 updated FSAR, "Second Annual Rept Meteorological Program" * Duquesne Light Co 82/01/31 60pp 15499 08B 24X "Iche 50-334, 82/01/31, 8208310114
 - i3i0i17 App 2A 3 to Beaver Valley Unit 1 updated FSAR, "Annual Rept ir Beaver Valley Neteorological Program for 1980 " Duquesne Light Co 82/01/31 300pp 19499 158 24X iche 80-334.82/01/31,8208310117
 - J8310120 App 2B to Beaver Valley Unit 1 updated FSAR, "Geological Considerations Influencing Proposed Beaver Valley Power Station."

 ** Duquesne Light Co 82/01/31 23pp 15500 128 24X
 Fiche 50-334,82/01/31,8208310120
- 208310122 App 2C to Beaver Valley Unit 1 updated FSAR, "Bejemicity Analysis"

 * Duqueene Light Co 82/01/31 100pp 15500 196 24X
 Fiche 50-334.82/01/31.8208310122
- 12083j0126 App 2D to Beaver Valley Unit 1 updated FSAR, "Effect of Local Soil Conditions Upon Seismic Threat to Beaver Valley Fower Station,"

 * Duquesne Light Co 82/01/31 2ipp 15500 228 24X Fiche 30-034:82/01/31.8208310126
- 8208310129 App 2E to Beaver Valley Unit 1 updated FSAR. "Rept on Bubsurface Conditions - Shippingport Site " # Duquesne Light Co 82/01/31 100pp 15500 250 24X Fiche 50-334.82/01/31.8208310129
- B208310131 App 2F to Beaver Valley Unit 1 updated FSAR. "Boring Logs & Calculation Sheets"

 # Duquesne Light Co 82/01/31 300pp 15500 296 24X
 Fiche 50-334, 82/01/31, 8208310131

- 8208310134 App 20 to Beaver Valley Unit 1 updated FSAR, "Seismic Velocity Measurements" * Duquesne Light Ca 82/01/31 9pp 15501 052 24X Fiche 30-334, 82/01/31, 8208310134,
- 8208310137 App 2H to Beaver Valley Unit 1 updated FSAR, "Add1 Boring Spil Test Data " 4 Duquesne Light Co 82/01/31 400pp 15501 061 24X Fiche 50-334, 82/01/31, 8208310137
- 8208310140 Chapter 3 to Beaver Valley Unit 1 updated FSAR, "Reactor" * Duquesne Light Co 82/01/31 500pp 19501 239 24X Fiche 50-334, 62/01/31, 6208310140
- 8208310142 Chapter 4 to Beaver Valley Unit 1 updated FSAR, "RCS "
 * Duquesne Light Co 82/01/31 250pp 15502 193 24X
 Fiche 50-334,82/01/31,8208310142
- 8208310144 App 4A to Braver Valley Unit 1 updated FBAR. "Deternination of Reactor Pressure Vessel NDTT" * Duquesne Light Co 82/01/31 5pp 19503 002 24X Fiche 50-934. 82/01/31, 8208310144
- 8208310148 Chapter 5 to Beaver Valley Unit 1 updated FSAR, "Containment Sys"

 ** Duquesne Light Co 82/01/31 600pp 15503 051 24X
 Fiche 50-334, 82/01/31, 8208310148.
- 8208310149 Chapter & to Beaver Valley Unit 1 updated FSAR. "ESFs "

 * Duquesne Light Co 82/01/31 300pp 18503 355 24X

 Fiche %0-334,82/01/31,8208310149
- 8208310151 Chapter 7 to Beaver Valley Unit 1 updated FSAR, "Instrumentation & Controls " * Duquesne Light Co 82/01/31 400pp 15504 163 24X Fiche 50-334, 82/01/31, 8208310151
- 8208310152 Chapter 8 to Beaver Valley Unit 1 updated FSAR, "Electrical 8ys" * Duquesna Light Co 82/01/31 200pp 15505 069 24X Fiche 80-334,82/01/31,8208310152
- 8208310155 Chapter 9 to Beaver Vallay Unit 1 updated FBAR, "Auxiliary Emergency Sys" * Duquesns Light Co 82/01/31 400pp 15505 151 24X Fiche 50-334, 82/01/31, 8208310155
- 8208310158 Chapter 10 to Beaver Valley Unit 1 updated FSAR, "Steam & Power Conversion "

 * Duquesne Light Co 82/01/31 100pp 15506 083 24X Fiche 30-334, 82/01/31, 8208310158
- 8208310160 Chapter 11 to Beaver Valley Unit 1 updated FSAR, "Radwasters & Radiation Protection"

 * Duquesne Light Go 82/01/31 200pp 15506 184 24x Fiche 50-334.02/01/31.0208310160,
- 8208310162 App 11A to Beaver Valley Unit 1 updated FBAR, "Estimated Radioactive Nuclide Concentrations in Waste Disposal Sys & in Discharge to Environ "

 Duquesne Light Co 82/01/31 21pp 15506 325 24X
 Fiche 30-334.82/01/31,8208310162
- 8208310167 App 118 to Beaver Valley Unit 1 updated FSAR. "Evaluation of Doses From Radiation Exposure Due to Normal Operation of Unit 1 of Beaver Valley Fower Station " * Duquesne Light Co MARTIN. D E NUS Corp NUS-958 ROO 72/08/31 100pp 15506 347 24X Fiche 50-334,82/01/31.8208310167.
- 8208310168 Chapter 12 to Beaver Valley Unit 1 updated FSAR, "Conduct of Operations"
 * Duqueane Light Co 82/01/31 200pp 19507 082 24X Fichs 50-334-82/01/31,8208310168
- 82083/0173 Chapter 13 to Beaver Valley Unit 1 updated FBAR, "Initial Tests & Operations "
 # Duquesne Light Co 82/01/31 100pp 15507 180 24X
 Fithe 50-334.82/01/31.82083/0173
- 8208310176 Chapter 14 to Beaver Valley Unit 1 updated F8AR, "Oafsty Analysis " * Dequesne Light Co 82/01/31 600pp 15507 295 24X Fiche 50-334-82/01/31.8208310176
- 8208310184 App 14A to Beaver Valley Unit 1 updated FSAR, "Rept Covering Effects of High Pressure Turbine Rotor Fracture & Low Pressure Turbine Disc Fractures at Design Overspeed."

 * Duquesne Light Co 82/01/31 100pp 15509 049 24X Fiche 50-334,82/01/31,8208310184

- 8208310187 App 148 to Beaver Valley Unit 1 updated FSAR, "Radiation Sources" # Duquesne Light Co 82/01/31 21pp 15509 072 24X Fiche 50-334,82/01/31,8208310187
- 8208310191 App 14C to Beaver Valley Unit 1 updated FSAR, "Heat Transfer Coefficients Used in LOCTA-R2 Core Thermal Analysis "

 Duquesne Light Co 82/01/31 9pp 15509 093 24X
 Fiche 50-334,82/01/31,8208310191
- 8208310194 App 14D to Beaver Valley Unit 1 updated FSAR, "Condition I -Normal Operation & Operational Transients " 4 Duquesne Light Co 82/01/31 30pp 15507 102 24X Fiche 50-334,82/01/31.8208310194
- 8208310197 App 14E to Beaver Valley Unit I updated FBAR, "Generic Sensitivity Study Results for 3-Loop Plant w/17x17 Fuel "

 Duquesne Light Co 82/01/31 100pp 15509,132 24X Fiche 50-324,82/01/31,8208310197
- 8208310199 Chapter 15 to Beaver Valley Unit 1 updated FSAR, "Tech Specs & Bases "
 4 Duquesne Light Co 82/01/31 100pp 15509 189 24X Fiche 50-034, 82/01/31, 9208310199
- 8208310202 App A to Beaver Valley Unit i updated FSAR, "QA" * Duquesne Light Co 82/01/31 200pp 15509 262 24X Fiche 50-334,82/01/31,8208310202
- 8208310204 App B to Beaver Valley Unit 1 updated FSAR, "Seismit Design" # Duquesne Light Co 82/01/31 200pp 15510 027 24X Fiche 30-034, 82/01/31, 8208310204
- 8208310207 App C to Beaver Valley Unit 1 updated FSAR, "Emergency Preparedness Plan" # Duqueene Light Co 82/01/31 2pp 15510 220 24X Fiche 50-334, 82/01/31, 8208310207
- 8208120250 Forwards updated FSAR W/o encl CAREY.J J Duquesne Light Co 82/07/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 14324 257 24X Fiche 50-334.82/07/22,8208120250
- 8208310095 Forwards Beaver Valley Unit i updated FSAR CAREY.J J Duquesne Light Co 82/08/31 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 15497 001 24X Fichs 50-334.82/08/31.8208310095
- --8208310100 Updated FSAR for Beaver Valley Unit 1 * Duquesne Light Co 82/01/31 7,443pp 15497,002 24X Fiche 50-334,82/08/31,8208310095
- 8208310211 App D to Beaver Vallay Unit 1 updated FSAR, "Rept on Effects of Piping Bys Break Outside Containment"

 * Duquesne Light Co 82/01/31 250pp 15510 222, 24X
 Fiche 30-334, 83/01/31, 8208310211
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list ancl
 DIRCKB, W J Office of the Executive Director for Operations, 82/07/02 Consolidated Edison Co of New York 93pp 14194,001 24% Fiche,50-000,82/07/02,8207080064
- 8208030016 Requests Class III fee be remitted for 620616 application for temporary walver of accuracy requirements for position instrumentation when unit fells below normal operation temp DI008.R M License Fee Management Branch 82/07/14 CAREY. J Duquesne Light Co ip 14208 352 24X Fiche 50-334,82/07/14. 8208030016
- 8208020143 Advises that Amend 52 was revision to Amend 51 recently issued as part of original submittal on rod position indication sys Amends 51 & 52 are part of continuing review of safety issue & remain open items No Class III fee due CAREY. J J Duquesne Light Co 82/07/21 DIGGS,R.M. License Fee Management Branch 2pp 14142 025 24X Fiche 50-334,82/07/21,8208020143.
- 8208050013 Requests permission for BNWL to conduct site visit to obtain info on manpower issues, staffing practices, use of shift technical advisor & functions of safety review groups Info needed to develop long-term regulatory policy, VAROA, S. A. Operating Reactors Branch i 82/07/26 CAREY, J. Duquesne Light Co. 3pp 14243 OB1 24X Fiche 50-334,82/07/26,8208050019

- 8208110288 Forwards Amend 34 to License DFR-66, safety evaluation & notice of issuance & availability Amend changes station batteries to meet requirements of IEEE 8td 450-1980 & STS TAM.P B Operating Reactors Branch 1 82/07/27 CAREY.J J Duquesne Light Co 3pp 14331 124 24X Fiche 50-334, 82/07/27, 8208110288
- ~-B20Bi1027i Amend 54 to License DPR-66, changing station batteries to meet requirements of IEEE Std 450-1980 & BTB VARGA.8 A Operating Reactors Branch i 92/07/27. 8pp 14331 127 24X Fiche 50-334, 82/07/27, 820Bi10288
- ~-8208110292 8afaty evaluation supporting Amend 54 to License DPR-64. * Office of Nuclear Reactor Regulation, Director 82/07/27 2pp 14331 135 24X Fiche 50~334.82/07/27.8208110288
- --8208110274 Notice of issuance & availability of Amend 54 to License DPR-66 VAROA: 8 A Operating Reactors Branch 1 82/07/27 2pp 14931 137 24X Fiche 50-334, 82/07/27, 8208110288
- 8208090087 Forwards application for amend to License DPR-66, revising Table 3 3-6, Table 4 3 3 & Section B 3/4 3 3 1 re radiation monitoring instrumentation

 CAREY. J J Duquesne Light Co 82/07/30 VARGAS A Operating Reactors Branch 1 1p 14270 191 24X Fiche 50-334, 82/07/30, 9204090087
- --8208090090 Application for amend to License DPR-66 revising Table 3 3-6. Table 4 3 3 & Section B 3/4 3 3 1 re radiation monitoring instrumentation CAREY, J J Duquesne Light Co 82/07/30 2pp 14270 192, 24X Fichs 50-334,62/07/30.8208090087
- --8208090075 Proposed Yech Specs revising Tech 3 3-6, Table 4,3 3 & Bection 8 3/4 3 3 i re radiation monitoring instrumentation.

 → Dugussna Light Co 82/07/30 9pp 14270 194, 24X Ficha 30-334,82/07/30,8208090087
- 820B1002B1 Requests extension until 820B31 to respond to 820630 request for documentation of compliance w/NUREG-0737, Item II.B 3 repost-accident sampling capability Delay due to significant add1 research CAREY.J J Duquesne Light Co 82/07/30 VARGA.S A Operating Reactors Branch 1 2pp 14294 350 24X Fiche 50-334,82/07/30,8208100281
- 8208130034 Forwards Class III fee for 820730 Tech Spec Change Request 70 BIEBER, J D Duquesne Light Co 82/07/30 License Fee Management Branch ip 14335 097 24% Fiche 50-334, 82/07/30, 8208130034
- 8208070156 Forwards add1 info re NUREO-0737. Item II K 3 17, "Rept on Outages of ECCS," in response to NRC 820621 request Thirteen oversize drawings encl Aperture cards are available in PDR CAREY, J J Duquesne Light Co 82/08/02 VARGA, B. A Operating Reactors Branch 1 35pp 14271 001 24X Fiche 50-334, 82/08/02, 8208070156
- 820B170093 Forwards Amend 55 to License DPR-66 & notice of issuance & availability Amend deletes requirement for chlorine sampling VAR9A:8 A Operating Reactors Branch 1 82/08/02 CAREY, J J Duqueene Light Co 4pp 14372 353 24X Fiche 50-334.82/08/02, 8208170073
- --8208170103 Amend 55 to License DPR-66, deleting requirement for chloring sampling as requirement has already been satisfied for NPDE8 permit VAROA.S A Operating Reactors Branch 1 82/08/02 4pp. 14372 358 24X Fiche 50-334, 82/08/02.8208170093
- --8208170107 Notice of issuance & availability of Amend 55 to License DPR-66 VAROA,8 A Operating Reactors Branch 1, 82/08/02 2pp 14372 362 24X Fichs 50-334,82/08/02,8208170093.
- 820B10009i Forwards add1 justification re proposed Tech Spec Change 66, increasing multiplier from 0.2 to 0.3 at reduced thermal power, per NRC request CAREV.J. J. Duquesne Light Co. 82/08/03 VAROA.B. A. Operating Reactors Branch 1. 4pp. 14297 357 24X Fiche 50-334,82/08/03, contents of the contents of
- 6208120246 Forwards application for proposed Change Request 77 to Licensa DPR-66, revising Tech Specs 4 6 1 2d & Table 3 6-1 re containment isolation velves Class III amend fee enci CAREY, J Duquesne Light Co. 62/08/09 VARGA: S A Operating Reactors Branch 1, 1p 14324-197 24X Fiche 50-334,62/08/03,8208120246

- --B20B120253 Application for proposed Change Request 77 to License DPR-66. revising Tech Specs 4 6 1 2d & Table 3 6-1 recontainment isolation valve CAREY, J Duquesne Light Co 82/08/03 ip 14324 178 24X Fiche 50-334, 82/08/03. 820B120246
- --8208120257 Proposed changes to Tech Specs 4 6 1 2d & Table 3 6-1 re containment isolation valves Six oversize drawings enci Aperture cards are available in PDR e Dight Co 82/08/03 21pp 14324 199 24X Fiche 50-334, 82/08/03, 8208120246
- 8208200069 Forwards required Class III license fee for Tech Spec Change Request 77 dtd 820803 SIEBER, J D Duquesne Light Co 82/08/05 License Fee Management Branch 2pp 14392 214 24X Fiche 50-334,82/08/05,8208200069
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list end LEISENMUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356-332 24X Fiche 50-000, 82/08/09, 8208090194
- 8208250538 Concludes that commitments & exceptions to requirements of Reg Guide 1 58. Revision 1 & Reg Guide 1 146 per Generic Ltr 81-01 acceptable No further action needed VAROA.S A Operating Reactors Branch 1 82/08/12 CAREY.J J Duquesne Light Co 2pp 14562 241 24X Fiche 50-434, 82/08/12, 8208250538
- 8208270565 Informs that fee requested in NRC 820714 1tr for 820616 application for temporary waiver no longer due Refund authorized for fee remitted w/810519 proposed revision to physical security plan MILLER W O License fee Management Branch 82/08/17 CAREY, J Duquesne Light Ca ip 14683 283 24X Fiche 50-334.82/08/17, 8208270565
- 8208240312 Discusses resolution of analog RPI drift at low sys temps Amend 52 to Tech Specs enacted temporary license condition to waive accuracy requirements of analog RPI when RCS is below normal temp. Addl info will be provided by 820930 CAREY. J J Duquesns Light Co 82/08/18 VARQA.S A Operating Reactors Branch 1 1p 14520 353 24X Fiche 50-334,82/08/18,8208240312
- --8208240313 Proposed Tech Spec 3/4 1 3 3 re reactivity control sys, position indication sys shutdown, limiting condition for operation & surveillance requirements + Duquesne Light Co 82/08/18 1p 14520 354 24X Fichs, 50-334, 82/08/18, 8208240312
- 8208240167 Forwards "Reactor Containment Integrated Leakage Rate Test
 Results Rept 1982," summarizing performance of Type A & 1980
 & 1982 Type B & Type C local leek rate test results
 HILLIAMS,H P Duquesne Light Co 82/08/19 Office of Nuclear
 Reactor Regulation, Director 1p 14519 003 24X
 Fiche 50-334,82/08/19,8208240167
- --8208240169 "Reactor Containment Integrated Leakage Rate Test Results Rept. 1982 " • Duquesne Light Co 82/05/31 69pp 14517 004 24X Fiche 50-334,82/08/19,8208240167
- G Inspection reports, IE Bulletine & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York, 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list enci JORDAN, E. Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/17, 8204210395
- 8204210396 JE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Bvc list enc!
 JORDAN.E L. Division of Engineering & Guality Assurance 82/07/20
 Consolidated Edison Co of New York 112pp 14381.001 24X
 Fiche 30-000.82/07/20.8204210396
- 8204210397 IE Info Natice 82-24, "Water Leaking From U Hexafluoride Overpacks" Svc list encl. COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Constituted Edison Co of New York 71pp 14357 276 24X Fiche 50-000.82/07/20,8204210397

- 8208050287 Forwards IE Insp Rept 50-334/82-13 on 920601-0707 & notice of violation STAROBTECKI.R Division of Project & Resident Programs 82/07/21 CAREY, J J Duquesne Light Co 2pp 14210 148 24X Fiche 50-334,82/07/21,8208050287
- --8208050288 Notice of violation from insp on 820601-0707 STAROBTECKI.R Division of Project & Resident Programs 82/07/21 ip 14210 150 24X Fiche 50-334,82/07/21,8208050287
- --8209050292 IE Insp Rept 50-334/82-13 on 820601-0707 Noncompliance noted failure to follow radiation protection procedures & record pocket dosimetry readings on appropriate radiation access control permit dosimetry data record sheet TROSKOSKI.W M , LAZARUS.W , TRIPP, L E Division of Project & Resident Programs 82/07/20 17pp 14210 151 24X Fiche 50-334,82/07/21,8208050287
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list enc! JORDAN,E L Division of Engineering & Quality Assurance 62/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Hestinghouse PMRs " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 6204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Evc list encl JORDAN, E.L. Division of Engineering & Owality Assurance 62/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24X Fiche 30-000, 82/07/26, 8204210403
- 820B100014 Forwards IE Insp Rept 50-334/82-15 on 820714-15. No noncompliance noted SHITH, 0 H Division of Emergency Preparedness & Operational Support 82/07/27 CAREY, J Duquesne Light Co 2pp 14296 325 24X Fiche 50-334.82207/27, 820B100014
- --920Bi00017 IE Insp Rept 50-334/82-i5 on 920714-i5 No noncompliance noted, Major areas inspected emergency preparedness & observation of licensee small-scale exercise w/Columbiana County, OH NOJNAB: E. J., CROCKER, H. Division of Emergency Preparedness & Operational Support 82/07/23 4pp 14296 327 24X Ficher 50-334, 82/07/27, 8208100014
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list enc!
 JORDAN.E L Division of Engineering & Quality Assurance 82/07/28
 Consolidated Edison Co of New York 12Rpp 14357 146 24X
 Fiche 50-000.82/07/28.8204210405

1

1

- 8208160014 Forwards addl info requested by Action Item 3 of IE Bulletin 82-02, "Degradation of Threaded Fastmers in RCFB of PWR Plants," Remaining info will be submitted at future date CAREY, J Duquesne Light Co 82/08/02 HAYNES, R C Region 1, 00fice of Director 4pp 14344/331 24X Fiche 50-334, 82/08/02, 8208160014
- 8208130430 Informs that review of responses to IE Bulletin 80-04, "Main Steam Line Break W/Continued Feedwater Addition," complete. Analysis acceptable VARQA.8. A Operating Reactors Branch 1 82/08/04 CAREY, J J Duquesne Light Go 2pp 14354 337 24X Fiche 50-334,82/08/04,8208130430
- ---8208130436 Safety evaluation accepting util responses to IE Bulletin 80-04, "Main Steam Line Break W/Continued Feedwater Addition." 4 Office of Nuclear Reactor Regulation, Director 62/08/04 4pp 14354 337 24X Fiche 50-334,82/08/04,8208130430
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JURDAN.E L Division of Engineering & Quality Assurance 82/08/05, Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000,82/08/05,8204210407

- 8208190167 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/82-05
 MARTIN: T T Division of Engineering & Technical Programs 82/08/13
 CAREV.J J Duquesne Light Co 1p 14386 319 24X
 Fiche 50-334, 82/08/13. 8208190167
- --8208170169 Responds to NRC B20323 ltr re violations noted in IE Insp Rept 50-334/82-05 & B20304 Confirmatory Action Ltr 82-06 Corrective actions: EDS Nuclear, Inc audit verified compliance of NUREO-0737-related design mods CAREY, J J. Duquesne Light Co 82/05/25 HAYNES, R C Region 1, Office of Director lipp 14386 320 24X Fithe 50-334,82/08/13, 8208190167
- R Periodic operating reports & related correspondence
- 820812020B Forwards monthly operating rept for June 1982 CAREY. J Duquesne Light Co 82/07/12 Office of Management and Program Analysis ip 14326 216 24X Fiche 50-334,82/07/12,820812020B
- --8208120211 Monthly operating rept for June 1982 WEAVER, L W Duquesne Light Co 82/07/12 5pp 14326 217 24X Fiche 50-334,82/07/12,8208120208
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyting said into Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13, UDELL.R A Critical Mass Energy Project 8pp 14679 208 24% Fiche 30-000, 82/07/13, 8208270010
- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1" " NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000: 82/07/13,8208270010,
- --8208270600 "Personnel Whole Body Exposures for CYB1 "
 CAREY, J. J Duquesne Light Co 82/02/23 ip 14679 337, 24X
 Fiche 50-000, 82/07/13, 8208270010
- 8208030343 Forwards NPDEB discharge monitoring rept for June 1982, FEITKNECHT, C. Duquesne Light Co 82/07/30 REID,R W Operating Reactors Branch 4 3pp 14157.074 24X Fiche 50-334,82/07/30,8208030343
- --8208030345 NPDE8 discharge monitoring rept for June 1982 STEED, L B Duquesne Light Co 82/07/28 12pp 14157 077 24X Fiche 50-334,82/07/30,8208030343
- S Reportable occurrences, LERs & related correspondence
- 8207090205 Forwards LER 82-020/03L-0 WILLIAMB, H P Duquesne Light Co. 82/06/29 HAYNEB, R. C Region 1, Office of Director 2pp. 13794·137 24X Fichs 50-334, 82/06/29, 8207090205
- --8207070216 LER 82-020/03L-0 on 820410, chlorine detector CLA-V8-1018, found to have slow trip rate Caused by dirty wick. Wick checked & cleaned, Procedure revised to replace demineralized water w/distilled water.

 LACEY, W. B. Duquesne Light Co. 82/06/27. Region 1, Office of Director. 2pp. 13794, 137. 24X Fiche. 50-334, 82/06/27, 8207090205.
- 8208050128 Forwards LER 82-023/03L-0
 WILLIAMS, H. P. Duqueens Light Co. 82/07/23 HAYNES, R. C. Region 1,
 Office of Director. 2pp 14213.111 24X Fiche 50-334,82/07/23,
 8208050128
- --B20B050129 LER 82-023/03L-0 on B20710, during load increase, excore detector N-41 began periodically spiking & declared inoperable Caused by water in cable & connector of detector. Detector, associated cable & field cable connector replaced, LACEY, N B. Duqueane Light Co B2/07/23. Region 1, Office of Director 2pp. 14213:113 24X Fiche: 50-334,82/07/23,820B050128.
- 8208050445 Forwards LER 82-022/03L-0.
 WILLIAMS, H.F. Duquesne Light Co. 82/07/23, HAYNES, R.C. Region 1,
 Office of Director. 2pp. 14218-022, 24X Ficher 50-334, 82/07/23,
 8208050445.
- --B208080451 LER B2-022/03L-0:on B20707, high temp alarm received on component cooling pump C bearing. Caused by pump/motor misalignment Pump bearing replaced.
 LACEY, N. B. Duqueene Light Co. B2/07/23 Region 1, Dffice of Director. 2pp. 14218:024 24X Fiche: 50-334, B2/07/23, B208050445

- 8208100024 Forwards LER 82-025/03L-0
 WILLIAMS H P Duquesne Light Co 82/07/23 HAYNES R C Region 1,
 Office of Director 2pp 14276 320 24X Fiche 50-334,82/07/23,
 8208100024
- --8208100027 LER 82-025/03L-0 on 820713, control rod F10 indication declared inoperable when analog rod position indication & primary voltage curves indicated deviations less than 12 steps above bank demand indications

 LACEY.W 8 Dequeens Light Co 82/07/23 Region 1, Défice of Director 2pp 14276 322 24X Fiche 50-334,82/07/23,8208100024
- 8208130066 Forwards LER 82-027/03L-0
 HILLIAMS, H P Duquesne Light Co 82/07/30 HAYNES, R. C Region 1
 Office of Director 2pp 14336 017 24X Fiche 50-334,82/07/30,
 8208130066
- ~-BROBI30070 LER 82-027/03L-0 on B20725, containment vacuum pump 1A failed to start while performing RADCON sample procedure Caused by foreign matl jammed between rotor & cylinder bore Pumps will be run for 1-5 minutes daily LACEY, M B Duquesne Light Co 82/07/30 Region 1, Office of Director 2pp 14336 021 24X Fiche 50-334,82/07/30,0208130064
- 8208130064 Forwards updated LER 82-006/03L-1 WILLIAMS,H P Duquesne Light Co 82/08/02 HAYNES,R C Region 1, Office of Director 2pp 14336 004 24X Fiche 50-334,82/08/02, 8208130064
- --8208130073 Updated LER 82-004/03L-1 on 820204, reactor coolant pump cooling water return containment isolation trip valve (TV-CC-1035)) did not hold test pressure Cause not stated Corrective maint performed Valves retested.

 LACEY,W 8 Duquesne Light Co 82/08/02 Region 1, Office of Director 2pp 14336 006 24X Fiche 30-334,82/08/02,8208130064
- 8208130256 Forwards LER 82-024/03L-0 WILLIAMS, H P Duquesne Light Co 82/08/03 HAYNES, R. C Region 1, Office of Director 2pg 14333 042 24X Fiche 50-334, 82/08/03, 8208130256
- --8208130259 LER 82-024/03L-0 on B20718, during startup, high temp mlarm came in on B component cooling pump bearing Caused by failure of bearing due to pump/mator misslignment Pump vendor contacted to investigate recurring problem LACEY, W S Duquesne Light Co 82/08/03 Region 1, Défice of Director 2pp 14333-044 24X Fiche 30-334,82/08/03,8208130236
- 8208130241 Forwards LER 82-026/03L-0
 MILLIAMS, H P Duquesne Light Co 82/08/04 HAYNES, R, C, Region 1,
 Office of Director 2pp 14333 165 24X Fiche, 50-334, 82/08/04,
 8208130241
- --B20Bi30245 LER B2-024/03L-O on B20725, during investigation of spurious alarms from subcooling margin monitor monitor indicated all aight incore thermocouples spiking Cause unknown Cable connectors cleaned.

 LACEY. H B Duquesne Light Co. 82/08/04. Region 1, Office of Director 1p 14333 L67 24X Fiche-50-334, B2/08/04, B20Bi 30241.
- 8208260197 Forwards LER 82-030/03L-0, HILLIAMS,H.P. Dequesne Light Co. 82/08/12 HAYNES,R.C. Region 1, Office of Director. 2pp 14554:335 24X Fiche:50-334,82/08/12, 8208260197
- --B208260203 LER 82-030/03L-0 on 820803, while performing OBT 1 12.1, containment vacuum pump 1A failed to start. Caused by corrosion on sliding vanes & sump casting Pump replaced, LACEY, M.S. Duquesne Light Co. 82/08/12 Region 1, Office of Director 2pp. 14554 337. 24% Fiche 50-334,82/08/12,8208260197
- 8208300239 Forwards LER 82-028/03L-0.
 WILLIAMS.H P Duqueene Light Co. 82/08/19 HAYNES.R.C. Region 1.
 Office of Director. 1p 14679 142 24% Fiche.50-334.82/08/19,
 8208300239
- --8208300242 LER 82-028/03L-0 on 820722.min drip rate required for chlorine detector CLA-VS-101A could not be mat during routine shift surveillance, Caused by dirty wick & reservoir. Hick & reservoir cleaned LACEV.H & Duquesne Light Co 82/08/19. Region 1. Office of Director 3pp. 14407:143, 24X Fiche. 50-334,82/08/19,8208300239

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

- B20B110107 Transmits FEMA interim funding re offsite emergency preparedness, based on draft plans submitted by State of FL & B20210-12 esercise Adequacy of alert & notification sys must be verified in accordance w/NUREG-0654/FEMA REP-1 KRIMM.R W Federal Emergency Hanagement Agency B2/07/30 GRIMES. B Division of Emergency Preparedness 36pp 14316 196 24% Fiche 50-335,82/07/30,B20B110107
- 8208160071 Forwards Revision 6 to physical security plan.per 82080 discussion Revision withheld (ref lOCFR73 21 & Section 147 of Atonic Energy Act of 1954)
 URRIGAR E. STEVENS.R J Florida Power & Light Co 82/08/09 EISENHUT.D 0 Division of Licensing 1p 14342 070 24X Fichs 30-335,82/08/09.8208160071
- 8208160058 Forwards bases for using containment high range radiation monitor to estimate offsite doses during emergency, in response to Div of Emergency Preparedness request UHRIOR E Florida Fower & Light Co 82/08/10 EISENHUT, D O Division of Licensing 18pp 14344 281 24X Fiche 50-335,82/08/10,8208160058
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensers of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Styr list enci DIRCKS, W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24% Fiche 50-000, 82/07/02, 8207080064
- 8208030050 Consents to provide FERC w/access to documentation provided by util & required by FERC & PSC of FL to retain, as backup to util record retention sys Util could establish symbiotic relationship to alleviate recordsepting burden HAASS-N P Quality Assurance Branch 82/07/13 UHRIG.R E Florida Power & Light Co 2pp 14208 330 24X Fiche 50-000.82/07/13.
- 8208030064 Requests submittal documenting compliance w/criteria in NUREG-0737. Item II B 3, "Post-Accident Sampling Sys "Criteria & guidelines encl CLARK, R A Operating Reactors Branch 3 B2/07/13 UHRIG, R E Floride Fower & Light Co. 10pp 14200 349 24X Fiche 50-335.82/07/13,8208030064
- 8208040125 Requests remittance of license fees re 820628 application for deletion of Tech Spec requirement to test buried electrical cable periodically & 820628 application to increase min shift crew composition DIGOS-R M License Fee Management Branch 82/07/21 UHRIG-R E. Florids Fower & Light Co. 2pp 14228 352 24X Fiche 50-335,82/07/21.8208040125
- 8208030170 Forwards response to NRC 820412 ltr re evaluation of event postulated in Question 1 concerning overpressure mitigating sys Eristing design adequately addresses scenario postulated in Question 1 UHRIO, R E Florida Power & Light Co 82/07/28 CLARK, R A Operating Reactors Branch 3 2pp 14160, 106 24X Fichs 50-335, 82/07/28, 8208030170
- B20B030336 Responds to NRC 820513 Itr & draft technical evaluation rept re control of heavy loads Responses re Guideline 4 (special lifting devices) & Guideline 7 (crane design) require info from crane vendors Updated status expected by 820901. UMRIG.RE Floride Power & Light Co 82/07/28 CLARK, R, A Operating Reactors Branch 3 21pp 14157 040. 24X
- 8208040658 Forwards list of issues, request dates & scheduled responses to requests for add1 info Overdue info should be received within 7 days of receipt of ltr CLARK, A Operating Reactors Branch 3 82/07/28 UHRIO, R E Floride Fower & Light Co 3pp 14225 225 24X Fiche 50-335, 82/07/28, 8208040658
- 8208040037 Forwards Amend 51 to License DPR-67 & notice of issuance & aveilability Amend revises Tech Spec to increase min shift crew composition per NUREQ-0737, Item I A 1 3 CLARK.R.A Operating Reactors Branch 3 82/07/29 UHRIQ.R.E Florida Power & Light Co 4pp. 14229 333 24X Fiche 50-335, 82/07/29, 8208040057

- --8208040071 Notice of issuance & availability of Amend 51 to License DPR-67 CLARK.R A Operating Reactors Branch 3 82/07/29 2pp 14229 342 24X Fiche 50-335,82/07/29,8208040057
- 8208060278 Discusses NRC 820217 request for addl info re environ qualification of safety-related electrical equipment Engineering Analysis I-2 in Item 2 does not exist Repts withheld (ref 10CFR2 790)
 UHRIG: RE Florida Power & Light Co 82/07/30 CLARK, R A Operating Reactors Branch 3 6pp 14240 013 24X
 Fiche 50-335,82/07/30,8208060278
- 8208100114 Forwards add1 info on containment purging & venting, in response to NRC 820223 ltr Consequences of even gross leakage would be minimal due to containment & bldg design UHR10,R E Florida Power & Light Co 82/07/30 CLARK,R A Operating Reactors Branch 3 3pp 14278 103 24X Fiche 30-035,82/07/30,8208100114
- 8208090014 BOCIDECONDMIC IMPACTS OF NUCLEAR GENERATING STATIONS BAINT LUCIE CASE STUDY Docket Nos 50-335 And 50-387 (Fibrida Power And Light Company) WEISIGER, M L , PIJANKA, K D Mountain West Research, Inc * Social Impact Research, Inc FIN B-6268 NUREQ/CR-2749 VIO 82/07/31 Division of Health, Biting & Environment 303pp Available at NTIS \$7 00 14303 114 24% Fiche 50-335,82/07/31,8208090014
- 8208100095 Advises that util will respond to NUREO-0737, Item II B 3, "Post-Accident Sampling Sys," by 821206
 UHRIO,R E Florida Fower & Light Co 82/08/02 CLARK,R A Operating Reactors Branch 3 1p 14297:337 24X
 Fiche 50-335
- 8208100198 Forwards add1 info re use of Exxon fuel in Cycle 6 Tech Spec changes may be needed & NRC approval required prior to Cycle 6 startup Proposed changes expected to be submitted no less than 90 days prior to startup URRIO.R E Florida Power & Light Co 82/08/02 EIGENHUT, D 0 Division of Licensing 3pp 14294*281 24X Fiche 50-335,82/08/02,6208100198
- 8208100187 Forwards additinfo in response to Guestion 7 rs degraded grid protection.per 820419 request UHRIO.R E Florida Power & Light Co. 82/08/05 CLARK.R A Operating Reactors Branch 3 4pp 14298 210 24X Fiche 50-335,82/08/05,8208100187
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements A provides alternatives to requirements Sv list encl EISENHUT.D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fichs 50-000.82/08/09, 8208090194
- B20B120051 Advises that info re overpressure protection & heavy loads was submitted on B2072B, in response to B20726 ltr Info re offsite organization will be submitted on B20B11 UHRIOR E Florida Flower & Light Co B2/0B/09 CLARK, R A Operating Reactors Branch 3 lp 14323 361 24X Fiche 50-335, 82/0B/09, B20B120051
- 8208230370 Application to amend App A of License DPR-67 Amend updates offsite mgt organization to reflect recent corporate changes UHRIO, R E Florida Power & Light Co 82/08/11 EIBENHUT, D G Division of Licensing 3pp 14512 344 24X Fiche 50-335,82/08/11,8208230370
- 8208200194 Advises that NUREO-0737. Item II D i B satisfied by "Power Operated Relief Valve Block Valve Info Package" & listed info UHRIO, R E Florida Power & Light Co 82/08/13 EISENHUT, D Q Division of Licensing 1p 14397 271 24X Fiche 50-335,82/08/13,8208200194
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage." Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fichs 50-000
- 8208160220 Forwards IE Insp Repts 50-335/82-19 & 50-389/82-25 on 820614-18 No noncomplaints noted. Backer C Division of Project & Resident Programs 82/07/16 UHRIO,R E Florida Power & Light Co 2pp . 14347-104 24X Fiche 50-335,82/07/16,8208160220

- --8208160229 IE Insp Repts 50-335/82-19 & 50-389/82-25 on 820614-18 No noncompliance noted Major areas inspected backfit program, site organization & onsite design activities DEBBAGE: A G . WRIGHT.R W . UPRIGHT.C M Division of Engineering & Technical Programs 82/07/13 Spp 14347 106 24X Fiche 50-335.82/07/14.8208160220
- 8204210375 IE Info Notice Bi-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORPAN, E. Dimision of Engineering & Quality Assurance B2/07/19 Hichigan, Univ of 112pp 14358 OOI 24X Fiche 50-000,82/07/19,8204210375
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Bvc list one 1 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp. 14381 001 24X Fiche S0-000,82/07/20,8204210396.
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl C038.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357,276 24/ Fiche 50-000,82/07/20,8204210397
- 8208160362 Forwards IE Inquiry Rept 50-335/82-26 on 820615-17 O'REILLY, J.P. Region 2: Office of Director 82/07/20 UHRIG.R.E. Florida Power & Light Co. 2pp. 14348 354. 24X Fiche 30-335, 82/07/20, 8208160362
- --8208160370 IE Inquiry Rept 50-335/82-26 on 820618-17 Inquiry initiated to determine facts surrounding observations that individual of training staff was talking to examinees prior to reactor operator & senior reactor operator exams 8URCHAR H , URYC, B , ALDERSON, C, E Region 2, Office of Director 82/07/07 4pp 14348 356 24X Fiche 50-335,82/07/20,8208160362
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Byc list encl JORDANIE L Division of Engineering & Quality Assurance, 82/07/22 Conselldated Edison Co of New York 112pp 14194-321, 24X Fi
- 8208160190 Forwards IE Insp Repts 50-335/82-24 & 50-389/82-30 on 820628-0701 No noncompliance noted BANCE.H C Division of Project & Resident Programs. 82/07/22 UHRIG.R E Florida Power & Light Co 2pp 14342 324. 24X Fiche 50-335.82/07/22,8208160190
- --820B16019B IE Bafety Insp Rapts 50-335/82-24 & 50-389/82-30 on 82062B-070I No noncompliance noted Major areas inspected licenses action on previous insp findings training & qualifications of contractor-supplied temporary QC inspectors & records. LENAMAN.J J. CONLON.T E. Division of Engineering & Technical Programs 82/07/21. 4pp 14342.324 24X Fichs 50-335:82/07/22, 8208160190
- 8204210401 IE Info Natice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl, JORDAN, E. Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co of New York 122pp 14380,115 24X Fiche 50-000,82/07/23,8204210401,
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tubs Support Pin Failures at Westinghouse PWRs," Svc list encl. JORDAN.E L. Division of Engineering & Quality Assurance, B2/07/23, Consolidated Edison Co. of New York 127pp 14194-120 24X Fiche. 50-000.82/07/23, B204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Bvc list encl. JGRDAN, E L Division of Engineering & Quality Assurance 82/07/26, Consolidated Edison Co of New York 121pp 14357 013, 24X Fiche: 30-000, 82/07/26, 8204210403
- 8208030617 Ack receipt of B20709 ltr informing NRC of steps taken to correct violations noted in IE Inep Rept 50-335/82-15
 DANCEH C Division of Project & Resident Programs 82/07/26.
 URRIG.R E Florida Power & Light Co ip. 14162 217 24X
 Fichs 50-335/82/07/26,8208030617
- --8208030624 Responds to NRC 820611 ltr re violations noted in IE Insp. Rept 50-335/82-15. Corrective actions valve 7166 properly locked & procedure change request generated.
 UKRIO,R.E. Florida Power & Light Co. 82/07/09. O'REILLY, J P. Region 2. Office of Director. 2pp. 14162 218, 24X
 Fiche: 50-335, 82/07/26, 8208030617

- --8208030631 Forwards IE Insp Repts 50-335/82-15 & 50-389/82-21 on 820411-0514 & notice of violation DANCE, H C Division of Project & Resident Programs 82/06/11 UHRIO, R E Florida Power & Light Co 2pp 14162 220 24X Fiche 50-335, 62/07/26, 8208030617
- --8208030633 Notice of violation from insp on 820411-0514, + Division of Project & Resident Programs 82/06/11, 1p 14162 222 24% Fiche 50-335,82/07/26,8208030617
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Hork in Fuel Storage Pool " Svc list encl. JORDAN: E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000.82/07/28.8204210405
- 8208160197 Submits evaluation of IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PHR Plants " Two RCPB bolted closures have experienced leakage Injection sealant matts not used in RCPB closures UHRIO.R E Florida Power & Light Co 82/08/02 D'REILLY, J P. Region 2. Dff;ce of Director 3pp. 14342 351 24% Fiche 50-335,82/08/02.8208160197
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" 8vc list encl JORDAN: E.L. Division of Engineering & Quality Assurance 82/08/05, Consolidated Edison Co of New York 117pp 14388-201 24X Fiche 50-000.82/08/05.8204210407
- 8208240489 Forwards request for add1 info re submittals addressing masonry wall design (IE Bulletin 80-11) Response expected within 60 days of itr date.

 CLARK, R A Operating Reactors Branch 3 82/08/05 UHRIO, R E. Floride Power & Light Co 5pp. 14544 153 24X

 Fische 50-335,82/08/05,8208240489.
- 8208170203 Responds to 820513 request for add1 info re responses to IE
 Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/
 Continued Feedwater Addition" No further calculations re
 magnitude of peak pressure necessary
 UHRIG.R E Florida Power & Light Co 82/08/09 CLARK.R A
 Operating Reactors Branch 3 ip 14362 025 24X
 Fiche 50-335,82/08/09,8208170203
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyxing said info. Forwards documents listed in App FELTON.J M Division of Ruies and Records. 82/07/13 UDELL.R A, Critical Mass Energy Project. 8pp 14679'208 24X Fichs 30-000,82/07/13,8208270010
- --B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1" 4 NRC No Detailed Affiliation Diven 82/07/13 48pp. 14679, 216 24X Fiche: 50-000, 82/07/13, 8208270010
- --8208270540 Forwards personnel monitoring repts for 1981, per 10CFR20 407, W/o St Lucie rept UHRIO.R.E Florida Power & Light Co 82/03/04 Office of Hanagement and Progrem Analysis 1p 14680, 028, 24X Fichs 50-000, 82/07/13, 8208270010
- 8208120174 Forwards monthly operating repts for June 1982 & corrected Turkey Point 4 operating rept for May 1982 HILLIAMS.J W Fiorida Power & Light Co 82/07/15 Office of Resource Management, Director 1p. 14326: 001 24X Fiche, 50-000, 82/07/15, 8208120174.
- --8208120181 Monthly operating repts for June 1982 PACE,P. Florida Fower & Light Co 82/07/15, 12pp. 14326:002, 24% Fichs.50-000,82/07/15,8208120174
- B Reportable occurrences. LERs & related correspondence
- 8208020127 Forwards LER 82-028/03L-0. WILLIAMS, J W. Florida Power & Light Co 82/07/21. D'REYLLY, J. F. Region 2. Office of Director ip 14142, 074 24X Fichs: 50-335, 82/07/21, 8208020127

- --8208020135 LER 82-028/03L-0 on 820624.while performing periodic control element assembly exercise, control element assembly 54 dropped to full insertion Cause not determined PACE.P L Florida Power % Light Co 82/07/21 Region 2. Dffice of Director 1p 14142 075 24X Fiche 50-335,82/07/21,8208020127
- 8208020413 Forwards LER 82-026/03L-0 HILLIAMS.J W Florada Fower & Light Co 82/07/22 O'REILLY.J P Region 2. Office of Director ip 14145 110 24X Fiche 50-335,82/07/22,8208020413
- --8208020416 LER 82-026/03L-0 on 820622, one of four redundant 120-volt ac instrument power buses was lost when output breaker 1A static inverter opened Cause unknown Oscillator circuit board replaced PACE,P L Florida Power & Light Co 82/07/22 Region 2, Office of Director 1p 14145 111 24% Fiche 50-335,82/07/22.
- 8208030454 Forwards LER 82-023/99x-0 HILLIAMS,J W Florida Power & Light Co 82/07/26 O'REILLY,J P Region 2, Office of Director 1p 14154 058 24X Fiche 30-335,82/07/26,8208030454
- --820803046; LER 82-023/99X-0 on 820614, fire detection instrument channels 2 0; 13, 2 0; 14 & 2 02 13 in containment at 18-ft level & below alarmed Cause not determined Instrument repairs will be done when shutdown allows accesibility PACE, PL Florida Power & Light Co 82/07/26 Region 2, Office of Director 1p 14154 039 24X Fiche 50-335, 82/07/26, 8208030454
- 820805024B Forwards LER 82-029/03L-0 WILLIAMS,J W Florida Power & Light Co 82/07/29 O'REILLY,J P Region 2, Office of Director ip 14209 330 24X Fiche 50-335,82/07/29,8208050248
- --8208050252 LER 82-029/03L-0 on 820629, during full power operation, primary & backup heat tracing sys for boron injection flow paths from boric acid makeup tanks (solated Caused by personnel error Heat tracing re-energized PACE.P L Florida Power & Light Co 82/07/29 Region 2, Office of Director 2pp 14209 331 24% Fiche 50-335,82/07/29,8208050248
- 8208090237 Forwards LER 82-031/03L-0 HILLIAMS.J W Florida Power & Light Co 82/08/02 O'REILLY, J P Region 2. Office of Director 1p 1427J 096 24X Fichs 30-335,82/08/02,8208090237
- ---B208090239 LER 82-031/03L-0 on 820702, during normal operation containment isolation valve VS201 failed to shut Caused by leaking packing Valve repaired PACE.P.L Florida Power & Light Co 82/08/02 Region 2: Office of Director ip 14271 097 24X Fiche 50-335,82/08/02,8208090237
- 3208160512 Forwards LER 82-032/03L-0 WILLIAMS, J W Florida Power & Light Co 82/08/09 O'REILLY, J P. Region 2, Office of Director ip 14349 326 24X Fiche, 30-335, 82/08/09, 8208160512
- --8208160519 LER 82-032/03L-0 on B20708.MV-09-12 discharge valve for steam driven iC auxiliary feedwater pump to B steam generator would not cycle properly Caused by torque limiter switch malfunction New motor installed PACE.P L Florida Pawer & Light Co 82/08/09 Region 2, Office of Director ip 14349-327 24X Fiche 50-335.82/08/09, R203120512
- 8208200165 Forwards LER 82-027/03L-0 HILLIAMS, J W Florida Power & Light Co. 82/08/13 O'REILLY, J P. Region 2. Office of Director 1p 14500, 121 24X Fiche: 50-335, 82/08/13, 8208200165.
- --8208200175 LER 82-027/03L-0 on 820715.dc ground isolated on solenoid valve V6554 Caused by valve failing to properly indicate position due to shorted terminal lugs on terminal board of valve Lugs reconnected & valves returned to svc PACE.P L Florida Power & Light Co 82/08/13 Region 2, Office of Director ip 14500 122 24X Fiche 50-335.82/08/13.8208200165
- B208300346 Forwards LER 82-033/03L-0 WILLIAMS.J W Florida Power & Light Co B2/08/20 O'REILLY,J P Region 2. Office of Director ip 14679 199 24X Ficha-50-335, B2/08/20, B208300346

- --8208300348 LER 82-033/03L-0 on 820721, during normal surveillance testing, diesel generator turbocharger failed Caused by broken coupling on soak back oil pump due to insufficient lubrication to turbocharger guide % thrust bearings PACE.P L Florida Power & Light Co 82/08/20 Region 2, Office of Director ip 14479 200 24X Fiche 50-335.82/08/20, 820330344
- --8208300323 Updated LER 82-019/03X-1 on 820527, during 99% power operation, resident inspector noted shield bldg door A open w/hoses & electrical leads passing through Caused by personnel error Door mad provided penetration for hoses PACE, P.L. Florida Power & Light Co. 82/08/23 Region 2, Office of Director 3pp 14597-075 24X Fiche 50-335, 82/08/23, 820830319
- 8208300336 Forwards updated LER 82-016/03X-1 WILLIAMS, J W Florida Power & Light Co 82/08/23 D'REILLY, J P Region 2, Office of Director 1p 14599 159 24X Fiche 50-335,82/08/23,8208300336
- --B208300339 Updated LER 82-016/03X-1 on B20422,0 18 mCi cesium inadvertently disposed of in site landfill, outside of radiation controlled area Caused by apparent concentration of low level activity in steam generator blowdown facility PACE.P L Florida Power & Light Co 82/08/23 Region 2. Office of Director 2pp 14597 160 24X Fiche 50-335,82/08/23,82/0830334

V Operator Examinations

- 8208160362 Forwards IE Inquiry Rept 50-335/82-26 on 820615-17 O'REILLY, J P Region 2. Office of Director 82/07/20 UHRIG, R E Florida Power & Light Co 2pp 14348 354 24X Fiche, 30-335, 82/07/20, 8208160362
- --8208160370 IE Inquiry Rept 50-335/82-26 on 820615-17 Inquiry initiated to determine facts surrounding observations that individual of training staff was talking to examinees prior to reactor operator & senior reactor operator exams BURCH, R H . URYC. B . ALDERSON. C E Region 2, Office of Director 82/07/07 4pp 14348 356 24X Fiche 50-335, 82/07/20, 8208160362
- DOCKET 50-336 HILLSTONE NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 9208050406 Forwards addl info supporting exemption request from 10CFR50.App R fire protection requirements COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/07/16 EIERNHUT.D C Division of Licensing 7pp 14216 350 24% Fiche 50-336.82/07/16.8208050406
- --B2080504il "Fire Protection App R Review, Millstone Unit 2," supplemental info w Northeast Utilities B2/07/31 165pp 14216 357, 24X Fiche 50-334, B2/07/16, B20B050406
- 8208030013 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/07/20 Document Management Branch ip 14201 001 24X Fiche 50-000, 82/07/20, 8208030013
- --8208030019 Public version of revised emergency plan implementing procedures including Procedures EPIP 4102 rs alert EPIP 4103 re sits area emergency & EPIP 4104 re general emergency # Connecticut Yankse Atomic Power Co # Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/07/20 719pp 14201 005 24X Fiche 50-000,82/07/20,8208030013.
- 8208050082 Forwards IE Safeguards Insp Repts 50-245/82-11 & 50-336/82-11 on 820524-28 & notice of deviation Insp rept details & notice of deviation withheld (ref 10CFR73 21)

 MARTIN.T Y Division of Engineering & Technical Programs 82/07/21 COUNBIL.W. Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 14213 203 24% Fiche 50-245,82/07/21,8208050082
- --8208050085 IE Bafeguards Insp Repts 50-245/82-11 & 50-336/82-11 on 820524-28 Deviation noted failure to meet commitment Details withheld (ref 10CFR73 21) CCOANN J Region in Office of Director 82/07/19 ip 14213,205 24X Fichs.50-245,82/07/21,8208050082,

- 92080A02A7 Submits addl clarifications of 820301 App R review for facilities, in response to NRC 820A25 & 0707 requests (CUNSIL, W 9 Connecticut Yankee Atomic Power Co COUNSIL, W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 92/07/30 CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D gerating Reactors Branch 5 10pp 142A1 196 24X Fiche 50-000, 82/07/30, 8208060247
- 2008090312 Advises that fee sent w/820120 application for exemption from safeguarding requirements of 100FR73 21 will be refunded HILLER.W D License Fee Management Branch 82/07/30 COUNBIL, W Kortheast Nuclear Energy Co (subs of Northeast Utilities) 1p 14307 323 24% Fitche 50-000, 82/07/30, 8208090312 COUNSIL, N Q
- 8208160340 Forwards evitability, training & qualification plan Plan
- 20816934D Forwards suitability, training & qualification plan Plan withheld (ref 100FR2 790)
 ADDY,R J Northeast Utilities Service Co 82/08/04 DENTON,H R
 NRC Na Detailed Affiliation Given ip 14348 069 24X
 Fiche 30-245,82/08/04,8208160340
- 6208250474 Responds to 820603 ltr re Revision 9 to modified amended security plan Revised Page 12-2 should be changed to incorporate commitment to maintain (soletion zone CRUICHFIELD, D. Operating Reactors Branch 5 82/08/11 COUNSIL, W. Northeast Nuclear Energy Co (subs of Northeast Utilities). 1p. 14562 254 24X Fiche 50-245,82/08/11,8208250494 COUNSIL, W Q
- 208310448 Releases public version of revised emergency plan implementing procedures FELTON: J M Division of Rules and Records. 82/08/11. Docum hangement Branch in 14697 343 24X Fiche 50-245,82/08/11. 208310468
- --820831047; Forwarde public version of revised emergency plan implementing procedures, including Procedures EPIP 4105, "Bomb Threat" & EPIP Form 4103-1, "Bomb Threat Bearch Check List Unit i Shift Supervisor/Designee "COUNSIL, W G Northeast Nuclear Energy Co (eubs of Northeast Usilities) 82/07/30 EIBENNUT.D G Division of Licensing (4497 344 24% Fiche 50-245,82/08/11,8208310468
- -- 200310473 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4105, "Bomb Threat" & EPIP Form 4105-1, "Bomb Threat Search Checklist Unit 1 Shift Supervisor Designes" Northeast Nuclear Energy Co (subs of Northeast Utilities) 07/20 22pp 14697 345 24X Fiche 50-245,82/08/11,8208310468 22 p p

H General correspondence

- 6206250133 Notifies of recent changes in util organization reflected in OA program topical rept Revision 4A Details encl. COWSIL, W 9 . CAGNETTA-J P Northeast Utilities Bervice Co 82/08/17 HAASS, W P Guality Assurance Branch 7pp. 14541:302 24K Fiche 50-000, 82/08/17, 8208250135.
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL to holders of CP re Commission approved charter for CROR Byc list encl
 DIRCKS, 44 J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp. 14194 001
 24% Fiche 50-000.82/07/02,8207080044.
- 8208040240 Forwards corrected Tech Spac Pages 6-5,6-6,3/4 3-47 & 200040240 Forwards corrected tech Spac Pages 6-3,6-6,3/4 3-47 & 3/4 3-40 of Amend 78 to License DPR-65. Originally issued pages contained typographical errors CONVER, E. L. Operating Reactors Branch 3 82/07/16 COUNBIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 2pp. 14292:257 24X Fiche 50-336,82/07/16,8208040240.
- --8208040246 Corrected Tech Spec Pages 6-5,6-6,3/4 3-47 & 3/4 3-48 of Agend 78 to License DPR-65, reflecting organizational changes Pages correct typographical errors.

 4 NRC No Detailed Affiliation Oiven. 82/07/16. 4pp 14232 259 24X Fiche: 50-336,82/07/16,8208040240
- 8208040225 Forwards safety evaluation of util responses to NUREQ-0737, Item III D 3 4 re control room habitability Util responses acceptable subj to listed util commitments CLARK.R A Operating Reactors Branch 5 82/07/19. COUNSIL.H.Q Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 4pp. 14232.283. 24X Fiche.50-336.82/07/19.8208040221.

- 8208020074 Advises that facilities fully meet position of NUREO-0737, Item III D 3 3, "Improved In-Plant Iodine Instrumentation Under Accident Conditions" No deviations requested COUNSIL, W O Connecticut Vantee Atomic Power Co COUNSIL, W O. Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/07/20 CAUICHFIELD. D Operating Reactors Branch 5, ip 14144 106 24X Fiche 50-000,82/07/20,8208020076
- 8208020244 Notifies of proposed programmatic change to QA program topical rept. Revision 4A Exception to Paragragh I 4 of ANSI N45 2 9-1974 re definition of QA records will be added to App F of topical rept COUNSIL.W. G Northeast Utilities Service Co. COUNSIL.W G Northeast Utilities Service Co. COUNSIL.W G Northeast Utilities B2/07/26 HAASS.W P Quality Assurance Branch 2pp 14152 234 24X Fiche 50-000.B2/07/26.B208020244
- 8208060230 Notifies of delay in submittal of head vent procedures until 820901 CDUNBIL N O . CAGNETTA, J. P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBIL, N O Connecticut Yankee Atomic Power Co. 82/07/30 CRUTCHFIELD, D Operating Reactors Branch 5 CLARK, R A Operating Reactors Branch 3 2pp 14241 332 24X Fiche: 50-000, 82/07/30, 8208060230
- 8208060277 Provides further response to NRC 801222 request for info re NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants " Schedule for completion of remaining work expected Plants "Schedule for complexion or remaining our appearable by 820827.

 COUNSIL.W. O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL.W.O. Connecticut Yankee Atomic Power Co. 82/07/30 EISENHUT.D O Division of Licensing opp 14241 (24X Fiche 50-000,82/07/30,8208040279
- 8208160074 Forwards add1 info re individuals experience, collega ad & current operator licenses, per NUREG-0737. Item I A 1 i. "Shift Technical Advisor" COUNSIL.H G., CACHETTA.J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H O Northeast Utilities 82/08/06 EIEENHUT.D O Division of Licensing 3pp 14342 114 24X Fichs 50-245.82/08/06.8208160074
- 8208090174 Centric Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRG Summerizes 10CFR Chapter I requirements & provides alternatives to requirements Syc list encl requirements Byo list encl EIBENHUT D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356-332 24X Fiche. 50-000,82/08/09 8208090194
- 8208200072 Application to amend Licenses DPR-21 & DPR-65, incorporating revised radiological ETS in safety Tech Specs.
 CDUNSIL.W. 0 Northeast Nuclear Energy Co. (subs. of Northeast Utilities) CUMBIL.W 0, Northeast Utilities B2/08/12, CLARK.R A Operating Reactors Branch 3 CRUTCHFIELD.D Operating Reactors Branch 5, 5pp 14392 010 24% Fichs. 59-245, 82/08/12, 8208200072
- --8208200080 Proposed revisions to radiological ETS for incorporation CONCLUDED TO PROPOSE THE TEST OF THE OFFICE TO THE OFFICE THE OFFI
- B20B2403B4 Forwards addl info re NUREO-0737, Item II K 3 17, "EGCB Outages," in response to NRC 820622 request COUNBIL, W O, OPEKA, J F. Connecticut Yankes Atomic Power Co-COUNBIL, W O Arotheast Nuclear Energy Co. (subs. of Northeast Utilities), 82/08/16 CRUTCHFIELD, D Operating Reactors Brench 5. CLARK, R A Operating Reactors Branch 5. Fichs. 50-000, 82/08/16, 8208240384
- 8208310306 Forwards offsite dose calculation manual providing parameters & methodology for offsite dose & effluent monitor setpoint calculator COUNSIL.N Q. Northeast Nuclear Energy Co (subs of Northeast Utilities), 82/08/20. CLARK.R.A. Deparating Reactors Branch G. ip. 14688-057 24% Fichs 50-245/82/08/20.8208310306.
- --8208310310 Offsits dose calculation manual providing parameters & methodology for offsits dose & effluent monitor setpoint calculation # Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 82/08/31 86pp, 14688 058 24X Fiche. 50-245,82/08/20,8208310304.
- G. Inspection reports: IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDANIE L. Division of Engineering & Quality Assurance
 Consolidated Edison Co of New York, 87pp. 14356; 274,
 Fiche: 50-000: 82/07/16,8204210393.

- 8208050114 Forwards Inservice Insp Rept IR-IBI-010, "Fourth Refueling Outage Inservice Insp Rept for Northeast Utils Millstone Point Unit 2"

 MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 82/07/16 HAYNES, R. C. Region 1. Office of Director 19 14213 028 24% Fiche 50-336,82/07/16,8208050114
- ~~8208050117 Inservice Insp Rept IR-ISI-010, "Fourth Refueling Outage
 Inservice Insp Rept for Northeast Utils Millstone Point,
 Unit 2 " Class 1 piping inspected
 a Combustion Engineering, Inc. IR-ISI-010 82/06/04 79pp
 14213 029 24X Fiche 50-336, 82/07/16, 8208050114
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." See list encl. JORDAN.E 4. Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Ficha 50-000.82/07/19.8204210375
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Graduel Loss of Air Pressure " Svc list enc! JGRIAN, E. L. Division of Engineering & Quelity Assurance 82/07/20 Consolidated Edison Co. of New York 112pp 14381:001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Herafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Natorials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp. 14357 276 24X Firms 50-000.82/07/20,8204210397.
- 820808082 Forwards IE Safeguards Insp Repts 50-245/82-11 & 50-336/82-11 on 820524-28 & notice of deviation Insp rept details & notice of deviation withheld (ref 10CFR3 21)
 MARTIN:T T Division of Engineering & Technical Programs 82/07/21
 COUNSIL, W O. Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 14213 203 24X Fiche 50-245,82/07/21,8208050082 82/07/21
- --B208050085 IE Safeguards insp Repts 50-245/82-11 & 50-336/82-11 on B20524-28 Deviation noted failure to meet commitment Datails withheld (ref 10CFR73.21) COOMM.N.J., GODY.A T Region 1, Office of Director B2/07/19 OFR73.21) /.A T Region 1. Office of Director 82/07/19 24X Fiche 50-245.82/07/21.8208050082 14213 205
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list enc! JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fichs.50-000,82/07/22,8204210398
- 8204210401 IE info Notice B2-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 62/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X 'iche 50-000, 82/07/23, 8204210401
 - |4210402 IE Info Notice 92-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PMRs " Svc list encl IORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X 1che 50-000, 82/07/23, 8204210402
 - 04210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants " Syc list encl JORRAN.E L Division of Engineering & Quality Assurance 62/07/26 Consolidated Edison Co of New York 1219p 14357.013 24X Ficha 50-000.82/07/26.8204210403
 - OBO20146 Advises that positive results of control element assembly guide tube insps & insps at end of Cycles 2 & 3 demonstrate that sizevas are adequate resolution to guide tube wear problem Further insp superfluous COUNSIL.N O Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/07/27 CLARK.R. A Operating Reactors Branch 3 2pp 14145 104, 24% Fiche 50-336,82/07/27,8208020146
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Hork in Fuel Storags Pool " Syc list enc! URBANLE L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche, 50-000, 82/07/28, 8204210405
- 8208100142 Responds to IE Bulletin 82-02 re degradation of threaded fasteners in RCPB Action Item 1.procedures for threaded fastener practices, will be implemented prior to Action Item Z INSP COUNBIL,W 9 . CAGNETTA, J P. Connecticut Yankee Atomic Power Co GOUNSIC,W 0 . Northeast Nuclear Energy Co (subs. of Northeast Utilities), 82/07/28 HAYNES, R. C. Region I, Office of Director. 2pp. 14278 050 24X Fiche 50-213.82/07/28,8208100142

- 820B160423 Responds to Action Items 3 & 5 of IE Bulletin 82-02 re degradation of threaded fasteners in RCPB Occurrences of visible leakage from body to bonnet areas of valves noted No fastener corrosion observed CDUNSIL.W O Connecticut Yankee Atomic Power Co COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Dillities) 82/07/30 HAYMEB.R C Region 1, Office of Director App 1434B 173 24% Fiche 50-000.82/07/30.8208140423
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201. 24X Fiche 50-000, 82/08/05, 8204210407
- 8208180124 Ack receipt of 820805 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-336/82-06 STAROSTECKI R Division of Project & Resident Programs 82/08/13 COUNSIL.W C Northeast Nuclear Energy CO (%ubs of Northeast Utilities) ip 14377 074 24X Fiche 50-336.82/08/13.8208180124
- --8208180129 Responds to NRC 820707 ltr re violations noted in IE Insp Rept 50-335/82-06 Corrective actions operator watch established at boric actio pump discharge valve & temporary changes to applicable procedures approved by 820710 COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/08/05 SIARDSTECKI. R Division of Project & Resident Programs 2pp 14377 079 24X Fiche 50-336,82/08/13, Resident Programs 8208180124
- 8208300065 Forwards IE Insp Repts 50-245/82-10 & 50-336/82-14 on B20521-25 & notice of violation
 MARTIN.T T Division of Engineering & Technical Programs B2/0B/1
 COUNSIL W G Northeast Nuclear Energy Co (subs of Northeast
 Utilities) 2pp 14598 341 24X Fiche.50-245.82/0B/13.8208300065 82/08/13
- --8208300057 Notice of violation from insp on 820621-25 + Division of Engineering & Technical Programs 82/08/13 2pp 14598 343 24X Fiche 50-245, 82/08/13/8208300055
- --8208300068 IE Insp Repts 50-245/82-10 & 50-336/82-14 on 820621-25 Noncompliance noted failure to maintain procedures & engineering drawings NAPUDA, G , BIBSETT, P , MEYER, O Division of Engineering & Technical Programs 82/08/12 20pp 14598 345 24X Fichs 50-245,82/08/13,8208300065
- R Periodic operating reports & related correspondence
- B20B270DiO Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records S2/Q7/13 UDELL, R A Critical Mass Energy Project Spp. 14679 208 24X Fiche 50-000, 82/07/13, 820B270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVB1" e NRC No Detailed Affiliation Given 82/07/19 48pp 14679 216 24X Fithe:50-000.82/07/13.8208270010
- --B208270541 Forwards "Reporting of Retorded Personnel Whole Body Exposures for CYB1." per 10CFR20 407 MRCCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Ut11(ties), B2/03/31. Office of Management and Program Analysis 1p 14680 066 24X Fiche 50-000.82/07/13.8208270010
- --8208270543 "Reporting of Recorded Personnel Whole Body Exposures for Northeast Nuclear Energy Co (40bs. of Northeast Utilities) 703/31 ip 14680,067 24X Fiche 50-000,82/07/13,8208270010.
- 8208120276 Forwards monthly operating rept for June 1982.

 MRDCZKA,E J Northeast Nuclear Energy Go (subs of Northeast
 Utilities) MRDCZKA,E J Northeast Utilities 82/07/14. Office
 of Resource Management. Director ip 14324
- --8208120300 Monthly operating rept for June 1982. OIBSDN-J Northeast Nuclear Energy Co (subs of Northeast Utilities) 92/07/06 5pp 14324 331. 24X Fiche 50-336, 82/07/14,8208120896
- 8 Reportable occurrences, LERs & related correspondence
- 8208020147 Forwards LER 82-026/03L-0 MR0CZKA,E J Northeast Nuclear Energy Co (subs. of Northeast Ubilities) 82/07/23 HAYNEB,R C Ragion 1, Office of Director 1p 14145.102 24% Fiche 50-336,82/07/23,8208020147

- --8208020153 LER 82-026/03L-0 on 820623, three containment air radiation monitors (8123A, 8262A & 8262B) found w/function swithces in incorrect position Caused by technician error & procedural deficiency Technicians cautioned & procedure revised FILBURN.T Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/07/23 Region 1. Diffice of Director 1p 14145 103 24X Fiche 50-336, 82/07/23,8208020147
- 8208060166 RO 1982 second quarter liquid radwaste discharges were 9 94 Ci.exceeding ETB Caused by steam generator primary side to secondary side leakage & increased activity in RCB, due to degraded fuel performance Demineralizer effluent monitored MROCZMA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/07/29 HAYNES, R C Region 1. Uffice of Director 3pp 14239 235 24X Fiche 50-336,62/07/29,8208060166
- 820806020A Forwards LER 82-028/03L-0 Detailed event analysis encl MRDCZKA: E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA: E.J. Northeast Utilities 82/07/30 HAYNES: R.C. Region 1. Office of Director 3pp 14238 350 24X Fiche 50-334: 82/07/30: 8208040204

1

1

1

ı

ļ

- --8208060212 LER 82-028/03L-0 on 820712, surveillance testing indicated I-131 concentration higher than allowed by Tech Spec Caused by defective fuel pins Power increases will be limited to prevent addl fuel defects
 BORCHERT.R Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/07/30 Region I. Office of Director Ip. 14238 353 24X Fiche 50-336,82/07/30.8208060206
- 820B120277 Forwards LER 82-029/03L-0 MR0CZKA,E J Northwast Nuclear Energy Co (subs of Northwast Utilities) MR0CZKA.E J Northwast Utilities 82/08/02 HAYNEB,R C Region i, Office of Director, 1p. 14326 333, 24X Fichs 50-336, 82/08/02, 8208120277
- --B20B1202B0 LER 82-029/03L-0 on 820702, while at 100% power, weld leak discovered on 3/4-inch inlet line to charging pump B discharge relief valve Cause of weld failure unknown. New section of pipe installed FILBURN, T Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/08/02 Region 1, Diffice of Director. 1p 14326 334 24% Fiche 50-336, 82/08/02,8208120277
- 8208180006 Forwards LER 82-031/03L-0
 MR0CZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MR0CZKA.E J Northeast Utilities 92/08/10
 HAYNES.R C Region 1. Office of Director 1p. 14376 234 24X
 Fiche. 50-336, 82/08/10, 8208180006
- --B20B1B0015 LER 82-031/03L-0 on 820712, during routine surveillance testing, train A of EBFS could not be verified as operable.

 Caused by failure of Honeywell power supply circuit board H01 in humidity controller W7500 Board replaced KOMBSKY, Q E Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/08/10 Region 1, Dffice of Director ip 14376 235 24X Fiche 50~336, 82/08/10,8208180006,
- 8208200091 Forwards LER 82-030/03L-0 MRGCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/08/11 HAYNES.R G Region 1. Office of Director 1p 14393 216 24X Fiche 50-336.82/08/11.8208200091
- --B20B200078 LER 82-030/03L-0 on B20715.control element assembly motion inhibit interlock did not function properly.Caused by faulty operational amplifier in Oroup B of out-of-sequence scanner Amplifier replaced DEBLANDEBLK D Northeast Nuclear Energy Co. (subs of Northeast Utilities) B2/08/11 Region 1. Office of Director 1p. 14373 217 24X Fiche 50-336.82/08/11.B208200091
- 8208260126 Forwards LER 82-033/03L-0 MRDCZKA, E. J. Northeast Nuclear Energy Co (subs of Northeast Utilities) MRDCZKA, E. J. Northeast Utilities 92/08/18. HAYNES, R C Region 1. Office of Director 1p 14556 326 24X Fiche. 50-336, 62/08/18, 8208260126.
- --8208260131 LER 82-033/03L-0 on 820722, while testing steam driven auxiliary faedwater pump, turbine failed to reach min rpm. Caused by insufficient steam supply Steam valve collar adjusted.

 BERGIN, J M. Northwast Nuclear Energy Co. (subs. of Northwast Utilities) 82/08/19 Region 1, Office of Director ip 14556 327. 24X Fiche. 50-336, 82/08/19,8208260126.
- 8208260246 Forwards LER 82-032/03L-0.

 MROCZKA,E,J Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E J Northeast Utilities. 82/08/18

 HAYNES,R,C. Region 1. Office of Director. 1p 14554.290 24X Fiche, 50-336, 82/08/18, 8208260246

- --8208260254 LER 82-032/03L-0 on 820722, unidentified lest in RCB in excess of 1 gpm calculated Visual insp revealed valves 2-RC-403, 2-RC-405, 2-RC-1007, 2-RC-73 & 2-RC-74 to be leaking. Cause not stated Valves repaired BORCHERT. R Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/08/10 Region 1, Office of Director 2pp 14554 291 24X Fiche 50-336, 82/08/18,8208260246
- 8208260199 Forwards LER 79-014/03X-2 MRGCZKA:E J Northeast Nuclear Energy Co (subs of Northeast Ut(lities) 82/08/19 HAYNEB:R C Region 1. Office of Director. 1p 14352 348 24X Fiche 80-336:82/08/19:8208260159
- --8208260167 LER 79-014/03X-2 on 790604, during routine operations, small crack discovered in charging pump body C Caused by stress of fatigue failure in valve block Three charging pumps replaced w/Gaulin pumps CRISCIONE, J L Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/08/19 Region 1, Office of Director 1p 14552 349 24X Fiche 50-336, 82/08/19, 8208260159
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8208030393 Forwards IE Insp Repts 50-338/82-15,50-339/82-15 & 50-404/82-09 on B20603 No noncompliance noted BANCE,H C. Division of Project & Resident Programs 82/07/07 LEASBURG,R H Virginia Electric & Power Co. 2pp 15154 211 24X Fichs 50-338,82/07/07,8208030393
- --8208030398 IE Inep Repts 50-338/82-15.50-339/82-15 & 50-404/82-09 on 820603 No noncompliance noted Major areas inspected emergency planning, specifically interface between licensee & responding Region 2 organization at emergency facilities TAYLOR.P A Division of Emergency Preparadness & Operational Support 82/07/07 4pp 14154.213 24% Fiche.50-338.82/07/07, 8208030393
- 820Bi60400 Ack receipt of util 820609 ltr rs emergency exercise scheduled for Sept 1782 Bcenario will be reviewed upon receipt
 8TOHR.J P Division of Emergency Preparedness & Operational Support 82/07/16 LEASBURG,R H Virginia Electric & Power Co 1p. 14348 333 24X Fiche 50-339, 82/07/16, 820Bi60400
- 8208030469 Ack receipt of 820726 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appreisal Repts 50-338/82-05 & 50-339/82-05 LEWIS,R C. Division of Project & Resident Programs 82/07/27 LEASBURG,R H Virginia Electric & Power Co Ip 14163 344 24X Fiche 50-338,82/07/27,8208030469
- --9208030478 Responds to NRC 820310 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 Corrective actions Chapter 8, "Maintaining Emergency Preparedness," completely revised LEASBURGOR H. Virginia Electric & Power Co. 62/07/26 UREILLY, J. P. Region 2, Office of Director 2pp 14163 345. 24X Fiche 50-338,82/07/27,8208030469
- --8208030486 Forwards IE Emergency Preparedness Appraisal Repts 50-339/82-05 & 50-339/82-05 on 820216-26 O'REILLY, J P Region 2, Office of Director. 82/07/01 LEASBURG, R H Virginia Electric & Power Co 3pp 14163 347. 24X Fiche 50-338,82/07/27,8208030469
- --B208030494 Confirmation of action ltr re B20310 telcon concerning violations noted in IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 Initial emergency training & retraining program should be revised O'REILLY.J P. Region 2: Office of Director B2/03/10 LEASBURG.R N. Virginia Electric & Power Co Bpp 14163.350 24X Fiche 50-338.82/07/27.8208030469
- --B20B030509 IE Emergency Preparedness Appraisel Repts 50-33B/82-05 & 50-339/82-05 on 820216-26 Noncompliance noted emergency preparedness deficiencies in areas of training, smergency plan implementing procedures & initial dose assessment, KANTUR.F. HUFFMAN.G N. MARSTON.R.R. Division of Emergency Preparedness & Operational Support 82/06/30 dopp. 14163.358. 24X Fiche.50-338.82/07/27.8208030469
- 8208100215 Forwards IE Safeguards Insp Repts 50-338/82-26 & 50-339/82-26 on 820719-23 No noncompliance noted. DANCE, H. G. Division of Project & Resident Programs 82/08/05 LEASBURG, R. M. Virginia Electric & Power Co. 2pp 14294 347, 24X Fiche 50-338,82/08/05,8208100215

- --0208100224 IE Safeguards Insp Repts 50-338/82-26 & 50-339/82-26 on 820719-23 No noncompliance noted Major areas inspected site orientation, security plan & implementing procedures Details withheld (ref toCFR73 21)
 HALL,8 L , MCGUIRE,D R Division of Project & Resident Programs 82/08/05 1p 14294 349 24X Fitche 50-338.82/08/05,8208100215
- 8208190406 Releases public version of emergency plan & implementing procedures
 FELTON.J M Division of Rules and Records 82/08/09 Document Management Branch 1p 14501 270 24X Fiche 50-338,62/08/09,
- ~-8208190413 Public version of emergency plan + Virginia Electric & Power Co 82/07/24 150pp 14801 291 24X Fiche 50-338.82/08/09.8208190406
- --8208190426 Public version of emergency plan implementing procedures, including Procedures EPIP-1 01 re emergency manager controlling procedure.EPIP-1 02 re response to unusual event & EPIP-1 03 re response to alert # Virginia Electric & Power Co 82/07/24 600pp 14502 251 24X Fiche 50-338.82/08/09.8208190406
- 8208240315 Forwards changes to security plans Changes withheld (reficCFR2 790)
 LEABBURG, R H Virginia Electric & Power Co 82/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch 1 ip 14520 350 24X
 Fiche 50-000, 82/08/23,8208240315

Q Adjudicatory correspondence

8208300141 Confirms 820820 telcon re Louise County Board of Supervisors intention to intervene in util 820713 proceedings to amend OL to permit receipt & storage of spent fuel assemblies COLEMAN, J M Beveridge, Fairbanks, & Diamond 82/08/25 CLARK, R A Operating Reactors Branch 3 2pp 14599 211 24x Fiche 50-338, 82/08/25, 8208300141

Insurance & indomnity information

*208020249 Forwards Endorsement 40 to NELIA Policy NF-240 & Endorsement 30 to MAELU Policy MF-96
FORREST, B 0 Harsh & McLennan, Inc. , H & M Nuclear Consultants, Inc. Div B2/07/26 DINITZ, I Antitrust & Economic analysis Branch (Utility Finance) 3pp 14152 301 24% Fiche 50-338, 82/07/26, 8208020269

P Operating license stage documents A correspondence

- 8207080064 Ceneric itr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Evc list encl
 DIRCKS.H J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194 OOI
 24% Fiche 50-000,82/07/02,8207080044
- B208040098 Confirms B20716 telephone authorization for Tech Spec change granting relief from Surveillance Requirement 4 4 7 re draining RCS Amend will be forwarded when completed NOVAK.T M Assistant Director for Operating Reactors B2/07/16 LEABBURG.R H Virginia Electric & Power Co 2pp 14228 338 241 Fiche 50-338.82/07/16.8208040098
- 8208020086 Forwards VEP-FRD-50, "North Anna Unit 1.Cycle 3 Core Parformance Rept" LEASBURO,R H Virginia Electric & Power Co 82/07/26 DENTON,H R Office of Nuclear Reactor Regulation, Director CLARK,R A. Operating Reactors Branch 3 1p 14141 336 24X Fiche 50-338,82/07/26.8208020086
- --8208020088 "North Anna Unit 1, Cycle 3 Core Performance Rept"
 FORD.C A. DILLARD.F.D., SNOW, C T Virginia Electric & Power Co
 VEP-FRD-50 82/07/31 45pp 14141 337 24X
 Fiche 50-338,82/07/26.8208020086
- B208030310 Informs that util joined owners group that will establish position re compliance w/NUREO-0737. Item II B 3 concerning post-accident sampling sys. in response to NRC 820630 request Dumers group will meet in Aug 1982 LEABBURO, R H Virginia Electric & Power Co 82/07/29. DENTON, H R Office of Nuclear Reactor Regulation. Director CLARK, R A. Operating Reactors Branch 3 ip 14156 237 24X Fiche 50-338, 82/07/29, 8208030310

- 8208240055 Forwards Amend 41 to License NPF-4, safety evaluation & notice of issuance & availability Amend provides relief from requirement that RCS chemistry limits for chlorides & fluorides be sampled on continuing 72-h basis CLARK, R A Operating Reactors Branch 3 82/08/04 LEASBURG, R H Virginia Electric & Power Co 3pp 14548 147 24X Fiche 50-338, 82/08/04, 8208240055
- --B20B240065 Amend 41 to License NPF-4, providing relief from Surveillance Requirement 4 4 7, requiring RCB chemistry limits for chlorides % fluorides be sampled on continuing 72-b basis CLARK, R A Operating Reactors Dranch 3 B2/08/04 4pp 14548 i50 24X Fiche 50-338, B2/08/04, 920B240055
- --8208240072 Bafety evaluation supporting Amend 41 to License NPF-4

 * Office of Nuclear Reactor Regulation: Director 82/08/04 2pp
 14548 154 24% Fiche 50-338, 82/08/04, 8208240055
- --8208240073 Notice of issuance & availability of Amend 41 to License NFF-4 CHARLER A Operating Reactors Branch 3 82/08/04 2pp 14848 155 24% Fiche 50-338,82/08/04.8208240055
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT.D O Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24x Fiche 80-000,82/08/09,8208090194
- 820B190120 Application for amend to Licenses NPF-4 & NPF-7 re LOCA-ECCB reanalysis Request constitutes Class III & Class I fee category for Units 1 & 2, respectively LEASBURG, R H Virginia Electric & Power Co B2/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Departing Reactors Branch 3 37pp 14381 143 24X Fiche 90-338,82/08/16.8208190120
- --8208190122 Proposed Tech Bpecs re LOCA-ECC8 reanalysis + Virginia Electric & Power Co B2/08/16 15pp 14381 180 24x Fichs 50-338,82/08/16,8208190120
- 8208250190 Application for amend to Licenses NPF-4 & NPF-7, changing Tech Specs to identify new nominal ctr-tor-ctr spacing between fuel assemblies & modified spent fuel storage capacity LEASBURG, R H Virginia Electric & Power Co 82/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 4pp 14940 090 24X Fiche 30-338, 82/08/20, 8208250150
- --8208250154 Proposed Tech Spec 5 6 1 re fuel storage criticality & 5 6 3 re fuel storage capacity * Virginia Ejectric & Power Co 82/08/20 5pp 14540 094 24X Fiche 30-338.82/08/20.8208250150
- --8208250162 "Summary of Info in Support of Increasing Spent Fuel Storage Capacity of North Anna Power Station Units 1 & 2 " + Virginia Electric & Power Co 82/08/31 100pp 14540 099 24X Fiche 50-338,82/08/20,8208250150
- 8208270346 Bubmits supplemental response to Generic Ltr 82-05 per NUREG-0737. Item II B 3, "Reactor Coolant Sampling Sys."
 Due to difficulties w/vendor,date for completion of item is extended until 830101
 LEABBUROR H Virginia Electric & Power Co 82/08/23, DENTON,H R Office of Nuclear Reactor Regulation, Director EISENHUT,D 0 Division of Licensing 3pp 14565 015 24X Fiche 50-338,82/08/23,8208270366
- Q Inspection reports, IE Bulletins & correspondence
- 8208030393 Forwards IE Insp Repts 50-338/82-15,50-339/82-15 & 50-404/82-09 on 820603 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/07 LEASBURG, R H Virginia Electric & Power Co 2pp 14154:211 24X Fiche 50-338,82/07/07.8208030393
- --8208030398 IE Insp Repts 80-338/82-15,50-339/82-15 & 50-404/82-09 on 820603 No noncompilance noted Major areas inspected emergency plenning, specifically interface between licenses & responding Region 2 organization at emergency facilities. TAYLOR.P A., JENKINS.O R. Division of Emergency Preparedness & Operational Support 82/07/07 App 14153,213 24X Fiche 50-338,82/07/07.8208030393
- 8208030208 Forwards IE Insp Repts 50-338/82-14 & 50-339/82-14 on 820506-0605 No noncompliance noted DANCE, H. C. Division of Project & Resident Programs 82/07/13 LEARSURG.R H. Vinginia Electric & Power Co. 2pp. 14159 351 24. Fiche: 50-338, 82/07/13, 8208030208

- -B208030212 IE Insp Repts 50-338/82-14 & 50-339/82-14 on 820506-0605 No noncompliance noted Major areas inspected Lers, post-implementation review of NUREO-0737 items, licensee conditions for Unit 2 & plant operations

 UULIAN, C Division of Project & Resident Programs 82/07/13 6pp 14159 353 24X Fiche 50-338.82/07/13.8208030208
- 9208030528 Forwards IE Insp Repts 50-338/82-17 & 50-339/82-17 on 820822-25 No noncompliance noted DANCE H C Division of Project & Resident Programs 82/07/14 LEASBURG R H Virginia Electric & Power Co 2pp 14163 333. 24X Fichs 50-338/82/07/14/8208030528
- --820803053B IE Insp Repts 50-338/82-17 & 50-339/82-17 on 820622-25 No noncompliance noted Major areas inspected radiological environ monitoring program. including mpt & administrative controls & GC of analytical measurements CUNNINGHAM, A L. MONTGOMERY, D M. Division of Emergency Preparedness & Operational Support 82/07/13 5pp 14163-335 24% Fiche 50-338.82/07/14.8208030528
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 8i-26, Part 3. Suppl 1. "Clarification of Placement of Personnal Monitoring Devices for External Radiation " Svc list encl. JORGAN, E. Division of Engineering & Quality Assurance, 82/07/19, Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure." Svc list encl JORDAN E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001, 24X Fiche 50-000, 82/07/20, 8204210396.
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Bvc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York, 7ipp 14357,27, 24X Fishe 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JRRDAN E L Division of Engineering & Quality Assurance, 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000 82/07/22 8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl. JORDAN.E L Division of Engineering & Guality Assurance. 82/07/23 Consolidated Edison Co of New York. 122pp. 14380 115. 24X Fiche 50-000.82/07/23.8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp, 14174 120 24X Fiche 50-000, 82/07/23,8204210402.
- 8208160147 Forwards IE Insp Repts 50-338/82-23 & 50-339/82-23 on 820628-0702. No noncompliance noted DANCE:H C. Division of Project & Resident Programs. 82/07/23 LEASBURG,R H. Virginia Electric & Power Co. 2pp. 14345:085. 24X Fiche 50-338,82/07/23,8208160147
- --B20B160151 IE Insp Repts 50-338/82-23 & 50-339/82-23 on 820628-0702 No noncompliance noted Major areas inspected pipe supports, directional restraints & Types B & C leakage rate testing. IE Bulletin Bi-01 item rs mechanical snubbers remains open BROKR, E. H., JAPE, F. Division of Project & Resident programs 82/07/22. 3pp 14345:087. 24X Fiche:50-338,82/07/23,8208160147.
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PNR Fower Plants." Svc list encl.

 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26
 Consolidated Edison Co. of New York 121pp 14357-013. 24X

 Fiche: 50-000, 82/07/26, 8204210403.
- 8208030469 Ack receipt of 820726 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05.
 LEWIB:R C Division of Project & Resident Programs 82/07/27.
 LEABBURG:R H Virginia Electric & Power Co. Ip. 14163:344. 24X Fiche 50-338.82/07/27.8208030469.

- --8208030478 Responds to NRC 820310 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 Contractive actions Chapter 8. "Maintaining Emergency Preparedness." completely revised LEASBURG.R H Virginia Electric & Power Cb. 82/07/26 O'REILLY.J P. Region 2. Diffice of Director 2pp 14163 345 24X Fiche 50-338,82/07/27,8208030469
- --8208030486 Forwards IE Emergency Preparedness Appraisel Repte 50-338/82-05 & 50-339/82-05 on 820216-26 0'REILLY, P. Region 2. Office of Director 82/07/01 LEABBURG, R. H. Virginia Electric & Power Co 3pp 14163 347, 24X Fiche 50-338, 82/07/27.8208030469
- --B208030494 Confirmation of action ltr re B20310 telcon concerning violations noted in IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05. Initial emergency training & retraining program should be revised O'REILLY, J P Region 2, Office of Director B2/03/10. LEASBURG, R H Virginia Electric & Power Co Bpp. 14163, 350. 24x Fiche 50-338, 82/07/27,8208030469
- --B208030509 IE Emergency Preparedness Appraisal Repts 50-338/B2-05 & 50-339/B2-05 on B20216-26 Noncompliance noted emergency preparedness deficiencies in areas of training emergency plan implementing procedures & initial dose assessment. KANTOR:F: HUFFMAN:0 N: MARTON:R R: Division of Emergency Preparedness & Operational Support B2/06/30 & Opp 14163 35B 24X Fiche. 50-338, 82/07/27.8208030469.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl URDAN.E.L Division of Engineering & Quality Assurance. 82/07/28 Consolidated Edison Co of New York 122pp, 14357 146 24X Fiche.50-000.82/07/28.8204210405.
- 8208160402 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants" Info provided re use of lubricants & injection sealants & leakage bolted connections.

 LEASBURG, R H Virginia Electric & Power Co 82/07/30

 O'REILLY, J P. Region 2, Defice of Director 3pp 14347:359. 24X Fiche 30-000, 82/07/30, 8208160402
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list enc! JORDAN: E.L. Division of Engineering & Guality Assurance, 92/08/05 Consolidated Edison Co. of New York. 117pp 14388:201, 24X Fiche, 50-000, 82/08/05, 8204210407
- 8208100215 Forwards IE Safeguards Insp Repts 50-338/82-26 & 50-339/82-26 on 820719-23. No noncompliance noted. DANCE.H. C. Division of Project & Resident Programs. 82/08/05 LEASBURG.R.H. Virginia Electric & Power Co. 2pp. 14294.347. 24X Fichs: 50-338.82/08/05.8208100215
- --8208100224 IE Befeguards Insp Repts 50-338/82-26 k 50-339/82-26 on 820719-23. No noncompliance noted Major areas inspected site orientation, security plan & implementing procedures Details withheld (ref 100FR73 21) HALL,8 L., HGGUIRE,D.R Division of Project & Resident Programs, 82/08/05 ip 14274,349 24X Fiche 50-338,82/08/05,8208100215.
- 8208170166 Provides response to questions re facility inservice insp program per 820728 telcon Util will inspect pump & casing welds on internal basis & require relief from volumetric requirements. LEASBURG, R. H. Virginia Electric & Power Co. B2/06/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director, CLARK, R. A. Operating Reactors Branch 3 19 14366 240, 24X Fiche, 50-338, 82/08/12, 8208170166
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records. 82/07/13 UDELL, R. A. Critical Mass Energy Project. 8pp. 14679: 208 24X Fiche. 50-000, 82/07/13, 8208270010
- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYBI " *NRC - No Detailed Affiliation Given. 82/07/13 48pp. 14679.216. 24X Fiche.50-000.82/07/13.8208270010.
- --B208270293 Forwards "Recorded Annual Whole Body Exposure Rept for North Anna Power Station for 1981," per 10CFR20, 407. LEABBURG, R H. Virginia Electric & Power Co. 82/02/19, HALLER, N. H. Office of Management and Program Analysis, 2pp. 14679:308. 24X Fiche. 50-000, 82/07/13, 8208270010.

- --8208270279 "Recorded Annual Whole Body Exposure Rept for North Anna Power Station for 1981 " IRWINNER R . STAFFORD.A H . CARTWRIGHT.W R Virginia Electric & Power Co 82/02/19 2pp 14679 310 24X Fiche 50-000.82/07/13, 8208270010
- 820812014B Forwards monthly operating repts for June 1982 LEASBURG.R H Virginza Electric & Power Co 82/07/19 HALLER.N M Management Information Branch 1p 14327 093 24X Fiche 50-338,82/07/18,820812014B
- --8208120150 Monthly operating repts for June 1982 9CHMITENDORF, 0 Virginia Electric & Power Co 82/07/07 App 14327-094 24x Fiche 50-338,82/07/15,8208120148
- S Reportable occurrences, LERs & related correspondence
- 8208050235 Forwards LER 82-051/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co 82/07/26 O'REILLY,J P Region 2. Office of Director 1p 14209 289 24X Fiche 50-338, 82/07/26, 8208050235
- --B208050241 LER B2-051/O3L-0 on B20629, while in Mode 6, source range power level indication not audible in containment Caused by vol control switch turned to min output Vol turned up & audible indication restored Locked cover will secure unit CARTHRIGHT, W R Virginia Electric & Power Co B2/07/26 Region 2, Office of Director 2pp 14209 290 24X Fiche 50-338, B2/07/26, B208050235
- 8208050422 Forwards LER 92-052/03L-0 CARTHRIGHT.W R Virginia Electric & Power Co 82/07/28 O'REILLY.J P. Region 2, Office of Director ip 14214 095 24X Fiche 50-338,82/07/28,8208050422
- --B208050431 LER 82-052/03L-0 on 820702; loose parts found in steam generators A & C which initiated 820517 shutdown; identified as split pin retaining nuts Cause of loose nuts unknown Split pins will be replaced CARTHRIOHT, W R. Virginia Electric & Power Co B2/07/28 Region 2, Office of Director 3pp 14214 096 24X Fiche 50-338, B2/07/28, B208050422
- 8208060327 Forwards incident reporting sys repts re spill of contaminated water & contamination of personnel in auxiliary bldg & failure of control rod guide tube support pins for transmittal to NEA MICHELSON.C Director's Office 82/07/29 LAFLEUR.JD Office of International Programs, Director 17pp 14281 234 24X Fiche 50-000, 82/07/29, 8208060327
 - **OB200227 Forwards LER 82-054/03L-0
 CARTKRIGHT.W R Virginia Electric & Power Co 82/08/09,
 O'REILLY, J P Region 2. Office of Director 1p 14399 036 24X
 Ficae 50-33B, 82/08/09, 8208200227
- -8208200233 LER 82-054/03L-0 on 820716, valve guide discovered missing from 100p A cold leg reactor coolant loop step valve MOV-1591. Cause unknown Missing part found in reactor vessel on 820803 Valve guide will be removed CARTHRIGHT, M R Virginia Electric & Power Co 82/08/09 Region 2, Office of Director 2pp 14399 037 24X Fiche 50-338, 82/08/09, 8208200227
- 208270301 Forwards LER 82-049/03L-0 CARTHRIGHT W Virginia Electric & Power Co 82/08/18 O'REILLY, J. P. Region 2, Office of Director ip 14564 207 24X Fiche 30-338, 82/08/18, 8208270301
- B20B270307 LER B2-049/03L-0 on B20723, w/unit defueled, defective/failed welds found in two thermal sleeves Cause unknown Hestinghouse investigating failure Thermal sleeves will be removed during present outage CARTMRIGHT.WR Virginia Electric & Power Co. 82/08/18 Region 2, Office of Director 2pp 14564-208 24% Fiche 50-338, B2/08/18, B208270301
- CKET 50-337 NORTH ANNA POWER STATION, UNIT 2
- Security, medical, emergency & fire protection plans
 - '3 Forwards IE Insp Repts 50-338/82-15, 50-339/82-15 & 92-09 on 820603 No noncompliance noted C. Division of Project & Resident Programs 82/07/07
),R H Virginia Electric & Power Co. 2pp 15154, 211 24X
 1-338, 82/07/07, 8208030393

- --8208030398 IE Insp Repts 50-338/82-15,50-339/82-15 & 50-404/82-09 on 820603 No noncompliance noted Major areas inspected emergency planning, specifically interface between licensee & responding Region 2 organization at emergency facilities TAYLOR, P A Division of Emergency Preparadness & Operational Support 82/07/07 4pp 14154 213 24X Fiche 50-338,82/07/07,82082302323
- 8208160400 Ack receipt of util 820609 ltr re emergency exercise scheduled for Sept 1982 Scenario will be reviewed upon receipt STORR, J.P. Division of Emergency Preparedness & Operational Support 82/07/16 LEASBURG, R.H. Virginia Electric & Power Co. 1p 14348 353 24X Fiche 50-338,82/07/16.8208160400
- 8208030469 Ack receipt of 820724 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 30-338/82-05 & 50-339/82-05 LEWIS.R C Division of Project & Resident Programs 82/07/27 LEASBURG.R H Virginia Electric & Power Co 1p 14163 344 24X Fiche 30-338.82/07/27.8208030469
- --8208030478 Responds to NRC 820310 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 Corrective actions Chapter 8. "Maintaining Emergency Preparedness." completely revised LEASBURO.R H Virginia Electric & Power Co 82/07/26 O'REILLY. J P. Region 2. OPPicc of Director 2pp 14163 345 24 Fiche 50-338.82/07/27.8208030469
- --8208030486 Forwards IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 on 820216-26 O'REILLY, J. P. Region 2. Office of Director 82/07/01 LEASBURG, R. H. Virginia Electric & Power Co. 3pp. 14163 347 24X Fiche 50-338,82/07/27,8208030469
- --B20B030494 Confirmation of action ltr re B20310 telcon concerning violations noted in IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 Initial emergency training & retraining program should be revised O'REILLY, J P Region 2. Office of Director B2/03/10 LEASBURO, R H Virginia Electric & Power Co Bpp 14163 350 24X Fiche 50-338,82/07/27.8208030469
- --8208030507 IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 on 820216-26 Noncompliance noted emergency preparedness deficiencies in areas of training emergency plan implementing procedures & initial dose assessment KANTOR: F. JENKING: 0 R Division of Emergency Preparedness & Operational Support 82/04/30 60pp 14163 358 24X Fiche 50-338,82/07/27,8208030467
- B20B100215 Forwards IE Safeguards Insp Repts 50-338/82-24 & 50-339/82-26 on 820719-23 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/08/05 LEASBURG, R H Virginia Electric & Power Co 2pp 14294 347 24X Fichs 50-338,82/08/05,8208100215
- --8208100224 IE Safeguards Insp Repts 50-338/82-26 & 50-339/82-26 on 820719-23 No noncompliance noted Major areas inspected site orientation, security plan & implementing procedures Details withheld (ref 10CFR73 21) HALL
- 8208190406 Releases public version of emergency plan & implementing procedures
 FELTON,J M Division of Rules and Records, 82/08/09 Document Management Branch 1p 14501 270 24X Fiche 50-338,82/08/09,8208190406
- --8208190413 Public version of smergency plan * Virginia Electric & Power Co 82/07/24 150pp, 14501 271 24X Fiche 50-338,82/08/09,8208190406
- --8208190426 Public version of emergency plan implementing procedures, including Procedures EPIP-1 01 re emergency manager controlling procedure.EPIP-1 02 re response to unusual event & EPIP-1 03 re response to alert virginia Electric & Power Co 82/07/24 600pp 14502 251 24X Fiche 50-338,82/08/09,8208190406
- 8208240315 Forwards changes to security plans Changes withheld (ref 10CFR2 790) LEASBURO,R.H Virginia Electric & Power Co 82/08/23 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 14520 350 24X Fichs 30-000,82/08/28,8208240315

ory correspondence

on firms 820820 telcon re Louisa County Board of Bupervisors to intervene in util 820713 proceedings to amend it receipt & storage of spent fuel assemblies M Beveridge, Fairbanks, & Diamond 82/08/25 CLARK, R A Reactors Branch 3 2pp 14597 211 24X

, & indemnity information

orwards Endorsement 40 to NELIA Policy NF-240 & it 30 to MAELU Policy MF-96

Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc 17/26 DINITY, I Antitrust & Economic analysis Branch Tinance) 300 14152 301 24% Fiche 50-338, 82/07/26.

| license stage documents & correspondence

Personic 1tr to all licensums of operating plants, applicants to Idens of CP re-Commission approved charter for List encl
Juffice of the Executive Director for Operations
Consolidated Edison Co of New York, 93pp 14194 001
50-000.62/07/02.8207080864

50-000, 82/07/02, 8207080064

Informs that util joined owners group that util establish to compliance w/NUREO-0737, Item II B 3 concerning tent sampling sys. in response to NRC 820630 unders group will meet in Aug 1982 t. H. Virginia Electric & Power Co 82/07/29. DENTON, H R Nuclear Reactor Regulation. Director CLARK, R, A Reactors Branch 3 ip 14156 237 24% 338, 82/07/29,8208030310

Forwards "Loose Thermal Bleeve Bafety Evaluation," results anic testing & radiographic testing & description | Lance program for loose parts in RCB & tall loose parts monitoring sys | H Virginia Electric & Power Co | 82/08/04 | DENTON, H R Nuclear Reactor Regulation, Director | CLARK, R A Reactors Branch | 3 | 6pp | 14241 018 | 24X | 339, 82/08/04, 8208060220

5 "Loose Thermal Bleeve Bafety Evaluation " inghouse Electric Corp 26160:1 82/08/31 4ipp 26. 24X Fiche 30-337,82/08/04,8208060220

Denoric Ltr 82-14 to all reactor licensees, holders of CP & re submittal of documents to NRC Summarizes 10CFR requirements & provides alternatives to note Svc list encl
D O Division of Licensing 82/08/09 Consolidated of New York 1p 14356-332 24X Fiche 50-000,82/08/09,

Provides suppl to evaluation of RCS piping thermal sleeves used alternative would be to detect damaged or himble by increasing testing to verify operability detector leakage detection sys R. H. Virginia Electric & Power Co. 82/08/12. DENTON, H. R. Nuclear Reactor Regulation, Director CLARK, R. A. Reactore Branch 3 ip 14366-282, 24X 33-9. 82/08/12.8208170193

Forwards VEP-FRD-49, "North Anna Unit 2.Cycle 2 Startup est Rept"
R. H. Virginia Electric & Power Co. 82/08/12 DENTON.H.R. Nuclear Reactor Regulation. Director CLARK.R.A. Reactors Branch 3 1p 14499.001. 24X 339.82/08/12.8208190296.

8 "North Anna Unit 2, Cycle 2 Startup Physics Test Rept." D., BNOW, C. T., LOZITO, E. J. Virginia Electric & Power Go -49 82/07/31 68pp. 14499 002 24X 0-339,82/08/12:8208199296

Application for amend to Licenses NPF-4 & NPF-7 re LOCAalusis Request constitutes Class III & Class I fee
for Units i & 2. respectively
R. H. Virginia Electric & Power Co. 82/08/16 DENTON.H.R.
Nuclear Reactor Regulation, Director. CLARK.R.A
Reactors Branch 3 37pp. 14381, 143 24X
338, 82/08/16, 8208190120

2 Proposed Tach Specs re LCCA-ECCS reanalysis inia Electric & Power Co 82/08/16, 15pp. 14381 180, 24X 0-338,82/08/16,8208190120. B20B250130 Application for amend to Licenses NPF-4 & NPF-7, changing Tech Specs to identify new nominal ctr-to-ctr spacing between fuel assemblies & modified spent fuel storage capacity

LEABBURO, R H Virginia Electric & Power Co 82/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 4pp 14540 090 24X Fiche 30-338, 82/08/20 8208250150

--8208250154 Proposed Tech Spec 5 6 1 re fuel storage criticality & 5 6 3 re fuel storage capacity * Virginia Electric & Power Co 82/08/20 5pp 14540:094 24X Fiche 50-338,62/08/20.8206250150

--B208250162 "Summary of Info in Support of Increasing Spent Fuel Storage Capacity of North Anna Power Station Units 1 & 2 " * Virginia Electric & Power Co 82/08/31 100pp 14540 099. 24% Fichs 50-338.82/08/20.8208250150

8208270366 Submits supplemental response to Generic Ltr B2-05 per NURGO-0737. Item II B J. "Reactor Coolant Sampling Bys" "Due to difficulties w/vendordate for completion of item is extended until 830101 LEASBURG, R H Virginia Electric & Power Co B2/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 3pp 14565 015 24X Fichs 50-938.82/08/23, 8208270366

@ Inspection reports, IE Bulletins & correspondence

8208030393 Forwards IE Insp Repts 50-338/82-15,50-339/82-15 & 50-404/82-09 on 820603 No noncompliance noted DANCE, H C Division of Project & Resident Programs. 82/07/07 LEABBURG, H H Virginia Electric & Power Co. 2pp 14154,211 24X Fiche 50-338,82/07/07,8208030393.

--8208030398 IE Insp Repts 50-338/82-15,50-339/82-15 & 50-404/82-09 on 820603 No noncompliance noted Major areas inspected energency planning, specifically interface between licensee & responding Region 2 organization at emergency facilities TAYLOR,P A , JENKINS,O R Division of Energency Preparedness & Operational Support 82/07/07 4pp 14153-213 24% Fiche 50-338,82/07/07,8208030373

8208030208 Forwards IE Insp Repts 50-338/82-14 & 50-339/82-14 on 820506-0605. No noncompliance noted DANCE.H.C Division of Project & Resident Programs 82/07/13 LEASBURG.R H Virginia Electric & Power Co 2pp 14159:351. 24X Fiche 50-338,82/07/13,8208030208.

--B20B030212 IE Insp Repts 50-338/82-14 & 50-339/82-14 on B20504-0405 No noncompliance noted Major areas Inspected LERs, post-implementation review of NNREO-0737 items, licensee conditions for Unit 2 & plant operations
JULIAN.C Division of Project & Resident Programs 82/07/13. 4pp 14157 383 24X Fiche 50-338,82/07/13,820B030208

8208030528 Forwards IE Insp Repts 50-338/82-17 & 50-339/82-17 on 820622-25 No noncompliance notes DANCE:H C Division of Project & Resident Programs. 82/07/14 LEASBURG:R H Virginia Electric & Power Co. 2pp 14163 333 24X Fiche: 50-338:82/07/14:8208030528

--B20803053B IE Insp Repts 50-33B/82-17 & 50-339/82-17 on B20622-25, No noncompliance noted Major areas inspected radiological environ monitoring program, including mgt & administrative controls & GC of analytical measurements.

CUNNINOHAM. A L . MONTOCHERY. D M Division of Emergency Preparedness & Operational Support 82/07/13 5pp 14163 335 24X Fiche: 50-338, 82/07/14, 8208030528

8204210393 IE Info Notice 82-23: "Main Steam Isolation Valve (MSIV)
Leakage " Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York 87pp. 14356-274. 24X
Fiche 80-000,82/07/16,8204210393

8204210395 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl URDOAN.E.L. Division of Engineering & Quality Assurance 82/07/19. Michigan

8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list ancl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York, 112pp 14381.001, 24X Fiche 50-000, 82/07/20, 8204210396

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Dverpacks " Svc list encl CD8B.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24% Fiche 50-000.82/07/20.8204210397
- B20421037B IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Natice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23,8204210401
- 8204210402 IE Info Notice 82-29. "Control Rad Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PMRs," Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174-120 24X Fiche 50-000, 82/07/23, 8204210402
- 820B160147 Forwards IE Insp Repts 50-338/82-23 & 50-339/82-23 on 820A28-0702 No noncompliance noted DANCE:H C Division of Project & Resident Programs 82/07/23 LEASBURG:R H Virginia Electric & Power Co 2pp 14345 085 24X Fiche 50-338/82/07/23/8208160147
- --B208160151 IE Insp Repts 50-338/82-23 & 50-339/82-23 on 820628-0702 No noncompliance noted Major areas inspected pipe supports, directional restraints & Tupes 8 & C leakage rate testing IE Bulletin 81-01 item re mechanical snubbers remains open BROOKS.E K , JAPE.F Division of Project & Resident Programs, 82/07/22 3pp 14345 087 24X Fiche 50-338,82/07/23,8208160147
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PHR Power Flants " Svc list enci JORDAN,E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357-013 24X Fiche 50-000, B2/07/26, B204210403
- 8208030469 Ack receipt of 820726 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 LEHIS.R C Division of Project & Resident Programs 82/07/27 LEASBURO.R H Virginia Electric & Power Co 1p 14163,344 24X Fiche. 50-338,82/07/27,8208030469
- --B20B03047B Responds to NRC 820310 ltr re violations noted in IE Exergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 Corrective actions Chapter 8, "Maintaining Exergency Preparedness." completely revised LEASBURG, R H Virginia Electric & Power Co. 82/07/26, 0'REILLY, J P. Region 2, Office of Director 2pp. 14163 345 24% Fiche 50-338,82/07/27,8208030469
- --8208030486 Forwards IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 on 820216-24 0'REILLY.J P Region 2. Office of Director 82/07/01 LEASBURG.R H Virginia Electric & Power Co 3pp 14163.347. 24X Fich
- --8208030494 Confirmation of action ltr re 820310 telcon concerning violations noted in IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 Initial emergency training & retraining program should be revised O'REILLY, J P Region 2. Office of Director 82/03/10 LEASBURG, R H Virginia Electric & Power Ca 8pp 14163 350 24X Fiche 50-338,82/07/27,8208030449
- --8208030509 IE Emergency Preparedness Appraisal Repts 50-338/82-05 & 50-339/82-05 on 820216-26 Noncompliance noted emergency preparedness deficiencies in areas of training, emergency plan implementing procedures & initial dose assessment KANTOR, F., HUFFMAN, O. N. HARSTON, R. Division of Emergency Preparedness & Operational Support 82/06/30 60pp, 14163 358 24% Fiche.50-338,82/07/27,8208030449
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl JARDAN.E L. Division of Engineering & Guality Assurance, 52/07/28, Consolidates Edison Co of New York, 122pp, 14357
- 8208160402 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPS of PMR Plants." Info provided re use of lubricants & injection sealants & leekage bolted connections.

 LEABURO.R.H Virginia Electric & Power Co. 82/07/30
 0'REILLY.J.P. Region 2, Office of Director. 5pp. 14347.359 24X
 Fiche. 50-000. 82/07/30.8208160402.

- 8204210407 IE Info Notice 82~27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000, 82/08/05, 8204210407
- 8208100215 Forwards IE Safeguards Insp Repts 50-338/82-26 & 50-339/82-26 on 820719-23 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/08/05 LEASBURG.R H Virginia Electric & Power Co 2pp 14274 347 24X Fichs 50-338.82/08/05.8208100215
- --8208100224 IE 8afeguards Insp Repts 50-338/B2-26 & 50-339/82-26 on 820719-23 No noncompliance noted Major areas inspected site orientation, security plan & implementing procedures Details withheld (ref 100FR73 21)

 HALL,B L , MCGUIRE, D R Division of Project & Resident Programs 82/08/05 1p 14294 349 24% Fiche 50-338,82/08/05,8208100215
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info, Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81"

 * NRC No Detailed Affiliation Given 82/07/13 48pp. 14679 216 24% Fithe 50-000, 82/07/13, 8208270010
- --8208270293 Forwards "Recorded Annual Whole Body Exposure Rept for North Anna Power Station for 1981," per 10CFR20 407 LEASBURG,R,H Virginia Electric & Power Co 82/02/19 HALLER,N M Office of Management and Program Analysis 2pp 14679 308 24X Fiche 50-000,82/07/13,8208270010
- --8208270279 "Recorded Annual Whole Body Exposure Rept for North Anna Power Station for 1981 " IRWIN.R R , STAFFORD.A H , CARTHRIGHT.W R Virginia Electric & Power Co 82/02/19, 2pp 14679 310 24X Fiche 50-000.82/07/13, 8208270010
- 820812014B Forwards monthly operating repts for June 1982 LEABBURG.R H. Virginia Electric & Power Co 82/07/15 HALLER.N M Management Information Branch 1p 14327 093 24X Fiche 30-338.82/07/15.8208120148
- --8208120150 Monthly operating repts for June 1982 SCHMITENDORF, Q Virginia Electric & Power Co 82/07/07 App 14327 094 24X Fiche 50-338,82/07/15,8208120148
- 8. Reportable occurrences. LERs & related correspondence
- 8207230301 Forwards LER 82-027/03L-0 CARTWRIGHT.W. Virginia Electric & Power Co 82/07/13 O'REILLY, J. P. Region 2. Office of Director 1p 13998 329 24X Fiche 50-339, 82/07/13, 8207230301
- 8208030240 Forwards LER 82-038/03L-0 CARTHRIGHT. W R Virginia Electric & Power Co 82/07/23 O'REILLY, J P. Region 2. Office of Director, 1p 14158 208 24X Fiche 30-339, 82/07/23, 8208030240
- --8208030247 LER 82-038/03L-0 on 820626; quadrant power tilt ratio not determined within required 12-h Caused by failure to perform surveillance within required time interval Personnel counseled CARTMRIGHT.W, R Virginia Electric & Power Co 82/07/23 Region 2, Office of Director 2pp 14158 209 24X Fiche. 50-339. 82/07/23.8208030240
- 8208050094 Forwards LER 82-042/03L-0 CARTWRIGHT.W.R Virginis Electric & Power Co 82/07/28 O'REILLY, J P. Region 2. Office of Director ip 14213 182 24X Fiche 30-339.82/07/28.8208050094.
- --8208050103 LER 82-042/03L-0.on 820710.pressure in nitrogen supply tank A for pressurier power operated relief valve dropped below min Caused by leakage in nitrogen supply sys & inadequate method of replenishing nitrogen Sys to be modified CARTWRIGHT. W R Virginia Electric & Power Co 82/07/28. Region 2. Office of Director 2pp. 14213 183 24X Fiche: 50-337, 82/07/28, 8208050096

- 8208050323 Forwards LER 82-040/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 82/07/28 D'RE[LLY.J F Region 2, Office of Director 1p 14237 305 24X Fiche 50-339, 82/07/28, 8208050323
- --8208050330 LER 82-040/03L-0 on 820704.axial flux difference went less than 5% from target hand for 1 minute Caused by inserting A rod control bank 10 steps for rod operability periodic test Rods withdrawn & difference restored CARTHRIOHT. W R Virginia Electric & Power Ca 82/07/28 Region 2. Office of Director 1p 14237 306 24X Fiche 50-339,82/07/28,8208080323
- 8208050353 Forwards LER 82-039/03L-0 CARTWRIGHT, M. R. Virginia Electric & Power Co. 82/07/28 O'REILLY, J. P. Region 2, Office of Director 1p. 14217, 351 24X Fiche 50-339, 82/07/28, 8208050383
- --8208030407 LER 82-037/03L-0 on 820703.inner personnel hatch door found to have unacceptable leak rate Caused by dirty door seals. Seals cleaned & door tested satisfactorily CARTWRIGHT.W R Virginia Electric & Power Co 82/07/28 Region 2. Office of Director ip 14217 352 24X Fiche 50-339,82/07/28, 8208050353
- 8208050444 Forwards LER 82-041/03L-0 CARTWRIGHT:W R Virginia Electric & Power Ca 82/07/28 d'REILLY:J P. Regian 2. Office of Director Ip 14218 019 24X Fiche 50-339,82/07/28,8208050444
- --B20B050452 LER 82-041/03L-0 on 820706. Individual rod position indication for rod 8-08 in control bank D deviated from group demand position by greater than 12 steps w/no rod notion Caused by instrument drift Rod 8-08 recalibr CARTHRIOHT. W Virginia Electric & Power Co 82/07/28 Region 2. Office of Director 2pp. 14218 020 24% Fiche 50-339, 82/07/28.8208050444
- 820B070034 Forwards LER 82-047/03L-0 CARTWRIGHT:W R, Virginia Electric & Power Co 82/08/02 O'REILLY:J P Region 2, Office of Director 1p 14270'046, 24X Fiche 50-339,82/08/02.8208070034
- --8208070037 LER 82-047/03L-0 on 820714, fire door 8-54-11 between turbine bidg & emergency switchgear room found closed but unlatched since maint work on 820622 Caused by keeper welded 1 inch too high on frame Keeper rewelded CARTHRIOHT, W.R. Virginia Electric & Power Co. 82/08/02 Ragion 2. Office of Director 1p 14270 047 24X Fiche 50-339,82/08/02,8208090034
- 8208070143 Forwards LER 82-045/03L-0 CARTWRIGHT.W R Virginia Electric & Power Ca 82/08/02, O'REILLY, J F Region 2, Office of Director ip 14271 311 24X Fiche 50-339, 82/08/02, 8208070143
- --8208090151 LER 82-045/03L-0 on 920713, tube lane block device split plate on manway side discovered loose Caused by improper fitting of split plate & cracked welds on set screw nuts. Split plate rebuilt & tube lane block device replaced, CARTHRIOHT, WR Virginia Electric & Power Co 82/08/02 Region 2, Office of Director, 3pp 14271 312 24X Fiche 50-339, 82/08/02,8208090143
- 8208070162 Forwards LER 82-046/03L-0 CARTWRIGHT,W R Virginia Electric & Power Go 82/08/02 O'REILLY,J P Region R. Office of Director 1p 14271 332 24X Fiche, 50-337, 82/08/02, 8208070162.
- --8208090166 LER 82-046/03L-0 on 820719, w/unit defueled, operator discovered liquid samples not taken from RCS from 820402-12 Caused by high radiation level in RCS & RHM sus that prevented sampling NRC relief requirements expected CARTHRIOHT.W R. Virginia Electric & Power Co 82/08/02. Region 2. Office of Director 2pp 14271.353. 24X Fiche 50-339, 82/08/02.8208090162
- 8208200086 Forwards LER 82-043/03L-0 CARTWRIGHT,W R Virginia Electric & Pawer Co 82/08/09 O'REILLY,U'P. Region 2. Office of Director 1p. 14393 247, 24X Fichs 50-337, 82/08/09, 8208200086
- --B20B200i01 LER B2-043/03L-0 on B207i4, thermal sleeve on loop 9 safety injection accumulator to reactor coolant cold leg piping found displaced. Cavae not stated Failure of thermal sleeve mechanism being evaluated by Westinghouse.

 CARTWRIGHT. W. Virginia Electric & Power Co. B2/08/07 Region 2, Office of Director. 3pp. 14373.248 24X Fiche 50-339, B2/08/09, B208200086.

- \$208270331 Forwards LER 82-049/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 82/08/17 O'REILLY.J P Region 2. Office of Director ip 14554 292 24X Fiche 50-339, 82/08/17, 8208270331
- ~-8208270336 LER 82-049/03L-0 on 820717, RHR pump A removed from evc On 820730, suction to RHR pumps A & B lost On 820802, RHR flow was less than 3,000 gpm & pump amps were fluctuating Caused by inadequate RCS level at RHR pump suction penetration CARTHRICHT. HR Virginia Electric & Power Co 82/08/17 Region 2,009/17,8208270331
- 8208270274 Forwards LER 82-048/03L-0 CARTWRIGHT, W R Virginia Electric & Power Ca 82/09/18 O'REILLY, J P Region 2, Office of Director ip 14564 163 24X Fiche, 50-339, 82/08/18, 8208270274
- ---8208270279 LER 82-048/03L-0 on 820723, low head safety injection pump declared inoperable due to excessive vibration readings Caused by gradual deteoriation of upper motor bearing Motor bearing replaced GARTMRIGHT. WR Virginia Electric & Power Co 82/08/18 Region 2, Office of Director 2pp 14564 164 24X Fiche 50-339, 82/08/18,8208270274
- 8208310371 FNO-II-82-076 on 820822.electrical insulator bushing failed on 8 main transformer causing turbine & reactor trip from 30% power Hot transformer oil sprayed around area of failed transformer activated water deluge sys

 LANDIS-K , JULIAN, C A Region 2, Office of Director 82/08/23, 2pp 14693-062 24% Fiche 50-337,82/08/23,8208310371
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for GL & holders of CP re Commission approved charter for CRGR 9vc list enci
 DIRCKS:W J Office of the Executive Director for Operations
 82/07/02 Convalidated Edison Co of New York 93pp 14194 001.
 244 Fichs 50-000:82/07/02.8207080064
- 8208060368 Board Notification 82-70 notifies of differing prof opinion re sensitization of BHR stainless steel weldments TEDESCO.R L Assistant Director for Licensing 82/07/20 Atomic Safety and Licensing Board Panel 4pp 14281 355 24x Fiche 50-000,82/07/20,8208060368
- 820B180160 Forwards Table 1.inadvertently omitted from 820719 request for addl info re Mark I containment plant-unique analysis rept YOUNOBLOOD, B J Licensing Branch 1 82/07/21 TAUSER, H Detroit Edison Co. 3pp 14370 383 24X Fiche 50-341, 82/07/21, 820B180160.
- 8208060326 Board Notification 82-77 provides info re GA during const & emergency preparedness
 PURPLE: R A Assistant Director for Licensing 82/07/26 Atomic Safety and Licensing Board Panel 6pp 14281 212 24X
 Fiche 50-341
- B20B230003 Forwards "Bummary of Core Spray Sys Design Control Review" per Denton 820715 request for add1 assurance. Rept confirms all requirements met TAURER, H Detroit Edison Co 82/07/26 KINTNER, L L Division of Licensing App 14517 267 24X Fiche 50-341,82/07/26.8208230003.
- 8208050182 Notification of 820824-26 meetings w/util at site to observe const & obtain info re completion of const & preoperational tests for NRC caseload forecast panel KINTNER, L Licensing Branch 1, 82/07/27 YOUNOBLOOD, B J Licensing Branch 1 & pp 14242:111 24X Fiche. 50-341,82/07/27,8208050182
- 8208030183 Responds to NRC 820708 request for schedule for submitting program to address Humphrey concerns re Mark I containment Util is member of BMR Mark I owners group which has scheduled resolution of issue for 820930 TAUBER: Director for Licensing ip 14160 170 24X Fiche: 50-341, 82/07/28, 8208030183
- 8208230425 Forwards "Control of Heavy Loads at Nuclear Power Plants, Enrico Fermi Atomic Power Plant. Unit 2," draft technical rept. Rept based on util 811203 & 820403 responses to 801222 generic 1tr & 820203 request for info. YOUNOBLOOD, 8 J. Licensing Branch 1 82/07/30 TAUBER, H. Detroit Edison Co. 2pp. 14518 268 24% Fiche 50-341, 82/07/30, 8208230425.

- --8208230428 "Control of Heavy Loads at Nuclear Power Plants Enrico Fermi Atomic Power Plant, Unit 2." draft technical evaluation rept EHABER, C R E0&0, Inc 82/06/30 NRC No Detailed Affiliation Olven 24pp 14518 270 24X Fiche 50-341.82/07/30.8208230425
- 8208060148 Responds to 820629 request for add1 info re plant-unique analysis rept Upon NRC acceptance, response will be incorporated into original rept TAUBER, H Detroit Edison Co 82/08/02 YDUNOBLOOD, B Licensing Branch 1 60pp 14240 060 24X Fiche 50-341.82/08/02,8208060148
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Syc list enci EISENHUT.D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208190212 Forwards application to amend CPPR-87, substituting Wolverine Electric Cooperative for Northern Electric Cooperative interest in project * LeBoeuf, Lamb, Leiby & MacRae \$2/08/13 DENTON,H Office of Nuclear Reactor Regulation, Director 2pp 14386 243 24% Fiche 50-341,82/08/13,8208190212
- --B20Bi9O22i Application to amend CPPR-87 authorizing substitution of Wolverine for Northern interest in project following statutory merger Following merger, name Molverine will be changed to Wolverine Power Supply Cooperative, Inc HEIDEL.C M Detroit Edison Co 82/08/11 99pp 14384 245 24X Fiche 50-341,82/08/13,8208190212
- 8208200050 Submits Revision 1 to post-accident sampling analytical Procedure EF2-59 782 Dissolved oxygen will be verified by measurement of positive hydrogen residual greater than 10 cc/kg.if chloride is greater than 0.15 ppm
 TAUBER. H Detroit Edison Co 82/08/18 KINTER, L Division of Licensing ip 14392 231. 24X Fiche 50-341.82/08/18,8208200050
- 8208200121 Provides evaluation of drywell to wetwell vacuum breaker valves, in response to NRC 820323 Itr Matl ordering & mfg schedules expedited to allow mods to vacuum breakers prior to fuel load TAUBER, R. Detroit Edison Co 82/08/18 TEDESCO, R L Assistant Director for Licensing 5pp 14393 329, 24X Fiche 50-341,82/08/18,8208200121
- 8208200162 Forwards Revision O to "Safety Relief Valve In-Plant Test Plan," per NRC 820826 request Any comments re possible effect of proposed test on test instrumentation in torus need to be resolved expeditiously to meet startup schedule. TAUBER:N Detroit Edison Co 82/08/18 VOUNGELOOD. B J Licensing Branch 1 1p 14500 099 24X Fiche 50-341.82/08/18.8208200162
- --8208200168 Revision O to "Safety Relief Valve In-Plant Test Plan" LEONARO, JR , ROBERTS, C W, LEHMERT, R A. NUTECH (Nuclear Technology, Inc.) 82/07/31 15pp 14500 100 24X Fiche 50-34, 82/08/18,8208200162
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- B20B250550 Forwards request for add1 info re plant unique analysis rept to resolve BER open Items
 YOUNOBLOOD, B J Licensing Branch 1 82/07/30 TAUBER, H. Detroit
 Edison Co 3pp 14562 206 24X Fiche. 50-341. 82/07/30, 8208250550.
- 8208170101 Submits results of effort re compliance w/General Design Criteria 51, "Fracture Prevention of Containment Pressure Boundary," to assist in preparing SER TAUBER, H Detroit Edison Co 82/08/02 KINTNER, L L Division of Licensing 44pp 14365 321 24X Fiche 50-341.82/08/02.8208170101
- B208170106 Comments on SER & Guppl 1
 TAURER. H Detroit Edison Co 82/08/02 KINTNER. L L Division of Licensing. 5pp 14366 018 24% Fiche 50-341.82/08/02.8208170106.
- 8208200111 Advises that SER confirmatory open item re completion of OE evaluation of potential fuel assembly lift-off due to dynamic loadings from SSE & LOCA resolved Evaluation submitted to NRC on 820727 as Amend 3 to NEDE-21175-P TAUSER, H. Datroit Edison Co 82/08/18 KINTNER, L. L. Division of Licensing ip. 14393-340 24X Fiche. 50-341,82/08/18,8208200111
- B208200224 Forwards info to resolve seismic qualification review team audit open items identified in Section 3 10 of BER Suppl 2 TAUBER, H Detroit Edison Co 82/08/18 KININER, L Division of Licensing 108pp 14394 025 24X Fiche 50-341,82/08/18,8208200234.

- --8208200243 "Open GE Seismic Qualification Review Team Item Supplemental Amplifying Calculations" Hopper & Associates, Engineers 62/04/01 17pp 14394 126 24% Fiche 50-341,82/08/18,8208200234
- O Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/14 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN-E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210375
- 8204210396 IE Info Notice 82-28, "Failures of Hillor Actuators Upon Oradual Loss of Air Pressurs" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000: 82/07/20:8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14397 274 24% Fiche 50-000.62/07/20.8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & IPCI Turbine Exhaust Check Valve Failures " Svc list encl, JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210378
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN, E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380:115 24X Fiche 50-000,82/07/23.8204210401
- 8204210402 IE info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JARDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche 50-000.82/07/23.8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Syc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overoxposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14387 146 24X Fiche 30-000,82/07/28,8204210405
- 820Bi30341 Forwards request for add1 info on response to IE Bulletin 79-15. "Long-Term Operability of Deep Braft Pumps" OL application should be amended by providing add1 info Response needed by 820830 YGUNOBLOOD.B J Licensing Branch 1 82/07/30 TAUDER.H Detroit Edison Co 3pp 14340 245 24X Fiche 50-341.82/07/30.8208130341
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Bvc list encl JURDAN.E L. Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407.
- 8208230034 Forwards IE Insp Rept 50-341/82-07 on 820501-0630 No noncompliance noted BTREETER, J F Region 3. Office of Director 82/08/05 WELLS, D A Detroit Edison Ca 2pp 14507-327 24X Fiche 50-341,82/08/05, 8208230034
- --8208230036 IE Insp Rept 50-341/82-07 on 820501-0630 No noncompliance noted Major areas inspected.licensee action on previous insp findings.comst deficiency followup, meeting re licensee implementation of commitments & plant tours.

 LITTLE, B. H., KOMKLIN, J. E. Region 3, Office of Director 62/08/05, 6208230034

- 8208270308 Forwards IE Insp Rept 50-341/82-08 on 820823-28,0630 & 0701-02 & notice of violation NORELIUS.C E Division of Engineering & Technical Programs 82/08/10 HELLS.D A Detroit Edison Co 2pp 14544 217 24X Fiche 50-341.82/08/10.8208270308
- --8208270311 Notice of violation from insp on 820525-28,0630 & 0701-02 NORELIUB, C E Division of Engineering & Technical Programs, 82/08/10 2pp 14564 217 24X Fiche 50-341,82/08/10,8208270308
- --8208270324 IE Insp Rept 50-341/82-08 on 820525-28.0630 & 0701-02
 Noncompliance noted placement of snubbers adjacent to rigid
 restraints invalidated design analysis & deficiencies in
 Wesmer & Bocker document control sys
 YIN, I T , DANIELSON, D H Division of Engineering & Technical
 Programs 82/08/04 9pp 14564 221 24X Fiche 50-341,82/08/10,8208270308
- S Reportable occurrences, LERs & related correspondence
- 8208020132 Interim deficiency rept re improper assembly of core spray pump 71 Initially reported on 820615 Impeller installed backwards during replacement of bent shaft due to insufficient instructions Next rept expected by 821111 WELLS.D A Detroit Edison Co 82/07/14 KEPPLER.J G Region 3, Office of Director 2pp 14142 064 24X Fiche 50-341.82/07/14, 8208020132
- 8208020065 Interim deficiency rept re failure of MSIVs to operate properly due to improper onsite assembly of Belleville washers Initially reported on 820217 Assembly caused valve stem to bind Investigation continuing Next rept by 821112 WELLS.D A Detroit Edison Co 82/07/16 KEPPLER.J 9 Region 3 Office of Director 2pp 14144 127 24X Fiche 50-341,82/07/16,828080065
- 8208090140 Interim deficiency rept re cracking diesel generator fuel oil storage tank foundation Initially reported on 820222 Cracked padestal being repaired w/Embeco 636 grout per approved ropair procedure Next rept by 821117 WELLS,D A Detroit Edison Co 82/07/22 KEPPLER,J 0 Region 3, 02/fice of Director 2pp 14271 293 24X Fiche 50-341,82/07/22,8208090140
- 8208170134 Interim deficiency rept re ITE emergency diesel generator relay failures Initially reported on 820222 Contacts on all relays to be checked & relay coils tested Next rept expected 821117

 WELLB, D. A. Detroit Edison Co. 82/07/22 KEPPLER, J. G. Region 3, Office of Director 2pp. 14345 197 24X Fiche 50-341,82/07/22,8208170134
- 8208090131 Interim deficiency rept re calibr of torque wrenches Initially reported on 810303 Programs of site contractors performing GA Level 1 torquing reviewed & appropriate deviation disposition requests issued Next rept by 821119 WELLS, D A Detrait Edison Co 82/07/23 KEPPLER, J O Region 3 Office of Director ip 14269 341 24X Fiche 50-341, 82/07/23, 820008132
- 8208090154 Interim deficiency rept re reactor mode switch failure Initially reported on 820701 Switch repaired by QE Investigation of switch design continuing Next rept expected by 821124
 WELLS.D A Detroit Edison Co 82/07/30 KEPPLER.J O Region 3: 0ffice of Director 1p 14271 339 24X Fiche 50-341.82/07/30, 8208970154
- 8208090186 Interim deficioncy rept re rigid clamping of sway strut paddle. Initially reported on 820722 Investigation revealed one configuration of pipe clamp SK1014 resulting in overstress of support Next rept to be submitted by 821124 WELLS:DA Datroit Edison Co 82/07/30 KEPPLER.J O Region 3, Office of Director 1p 14272 018 24X Fiche 50-341,82/07/30,8208090186
- 8208170062 Final deficiency rept re Orafoil pipe scalant tape Initially reported on 820307 Non-nuclear brand scalants determined allowable for listed use Deficiency determined not reportable under 10CFR50 55(e)
 WELLS.D.A Detroit Edison Co 82/08/06, KEPPLER.J O. Region 3. Office of Director 2pp 14365 207 24% Fiche 50-341.82/08/06. 8208170062
- 8208170192 Interim deficiency rept re do sys battery cables Initially reported on 820312 All necessary design change notices issued to field No work on cables initiated Next rept expected 821203
 WELLS, D. A. Detroit Edison Co. 82/08/06 KEPPLER, J. G. Region G. Office of Director 2pp 14364 283 24X Fiche 50-341,82/08/06,8208170192

- 8208300080 Interim deficiency rept re calibr of Rosemount Model 510 DV trip units Initially reported on 820720 Majority of units could not be calibr due to oxidation of trip setpoint adjusting potentiameter windings Next rept expected 821216 WELLS, D.A. Detroit Edison Co. 82/08/18 KEPPLER, J.O. Region 3. Office of Director 1p 14578 271 24X Fiche 50-341,82/08/18,820930080
- X Onsite Storage of Low Level Waste
- 8208170011 Forwards requests for add1 info re safety analysis of onsite facility for contingency storage of iow level radwastes generated at facility, described in FSAR Amend 42 Environ analysis requested YOUNOBLOOD, D. Licensing Branch 1 82/07/26 TAUBER.H Detroit Edison Co. 6pp 14373 240 24X Fiche 50-341,82/07/26,8208170011
- 8208180087 Forwards add1 info re onsite storage of low level waste, in response to requests by Effluent Treatment Sus Branch & Chemical Engineering Branch FSAR will be modified in future amend
 - TAUBER.H Detroit Edison Co 82/08/16 YOUNGBLOOD, B J Licensing Branch 1 5pp 14376 306 24X Ficher 50-341.82/08/16.8208180087
- 8208180099 Forwards "Environ Evaluation of Onsite Storage Facility for Low Level Radwaste," discussing conclusion that facility const & operation has Insignificant effect on environ per environ rept & FES TAUBER.H Detroit Edison Co. 82/08/16 YOUNGBLOOD, B. J. Licensing Branch 1 lp. 14376-355 24X Fiche 50-341,82/08/16,8208180099
- ---8208180102 "Environ Evaluation of Onsite Storage Facility for Low Level Radwaste " * Sargent & Lundy, Inc 82/08/31 43pp 14376 356 24X Fiche 50-341,82/08/16:8208180099

DOCKET 50-344 TROJAN NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 9208170347 Releases public version of licensee request for NRC assistance re interpretations of NRC request to examine effects of volcanic eruptions on state & local emergency plans
 FELTON, J. H. Division of Rules and Records 82/08/10 Documen Hanagement Branch 1p 14373 193 24X Fiche 50-344,82/08/10,8208170347
- --8208170350 Submits public version of request for NRC assistance in correcting FEMA misinterpretation of NRC 801103 request to examine effects of volcanic eruptions on state & local emergency planning around site PEMA ltrs encl.
 WITHERS, B D Portland General Electric Co 82/07/30 CLARK, R A Operating Reactors Branch 3 App 14373 174 24X
 Fiche, 50-344, 82/08/10, 8208170347
- B20B250490 Advises that changes to plant security force training & qualification plan submitted in 820617 ltr are acceptable CLARK.R A Operating Reactors Branch 3 82/08/12 WITHERB, B D Portland General Electric Co 2pp 14562 255 24X Fiche 50~344.82/08/12.9208250490
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Syc list enci DIRCKS, W J Office of the Executive Director for Operations. 82/07/02 Consolidated Edison Co of New York 93pp 14194 00i, 24X Fiche 50-000, 82/07/02. 8207080064.
- 8208030485 Forwards plot indicating total peaking factor supporting B20510 LCA 87,per M Chatterton request.
 WITHERS, B D Portland General Electric Co 82/07/29 CLARK, R A. Operating Reactors Branch 3 2pp 14154 088 24X
 Fiche 50-344, 82/07/29, 8208030485
- 8208100354 Forwards Amend 75 to License NPF-1.safety evaluation & notice of issuance & availability Amend authorizes operation w/22 fuel assemblies containing three or five stainless steel rods in place of fuel rods for Cycle 5
 TRAMMELL.C. M Operating Reactors Branch 3 82/07/27 WITHERS. B D Fortland General Electric Co 3pp 14308 233 24X
 Fiche 50-344,82/07/27,8208100354
- --B20B100359 Amend 75 to License NPF-1, authorizing operation w/22 fuel assemblies containing three or five steinless attel rods in place of fuel rods for Cycle 5 CLARK, R A Operating Restfors Branch 3 B2/07/29 2pp 1430B 236 24X Fiche 50-344, B2/07/29, B20B100354

- --8208100362 Safety evaluation supporting Amend 75 to License NPF-1.

 Office of Nuclear Reactor Regulation, Director 62/07/29
 11pp 14308 238 24X Fiche 50-344.82/07/29.8208100354
- --- 8208100365 Notice of issuance & availability of Amend 75 to License NPF-1
- B208090070 Provides schedule for util response to NUREO-0737. Item II B 3. "Post-Accident Sampling Sys " Response to Criteria 1 through II will be provided by 821130 Post-accident sampling sys completion expected by 830701 WITHERS.B D Portland General Electric Co 82/07/30 EISENHUT.D C. Division of Licensing 2pp 14269 222 24X Fiche 50-344.82/07/30.
- 8208100264 Advises that main steam line radiation & containment hydrogen monitors will be operational by 821001, per NURED-0737 (tems If F i & II F i 6 HITHERS.B D Portland General Electric Co 82/09/03 EISENHUT, D E Division of Licensing 2pp 14294 299 24X Fiche 50-344, 82/08/03, 8208100264
- 8208090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24% Fiche 50-000.82/08/09, 9208090194
- 8208200102 Advises that NRC has no objections to resuming power operation for Fuel Cycle 5 withermal sleeves, as reported in 820709 & 22 submittals ENGELKEN, R H Region 5, Office of Director 82/08/12 WITHERS, B D Portland Ceneral Electric Co 2pp 14393 178 24X Fiche 30-344, 82/08/12, 8208200102
- 8208200184 Discusses util 820415 & 0720 ltrs re nonoperability of seismic monitoring equipment 6R-6340, bottom of containment triarial peak accelerograph & SR-6341, containment foundation triarial response recorder returned to svc YUNDT, C P Portland General Electric Co 82/08/12 ENGELKEN, R PRegion 5, Office of Director ip 14393, 361 24X Fiche 50-344, 82/08/12, 8208200184
- 8208230276 Submits status of NUREO-0737.TMI Action Items
 II D i 3.11 F i 5 & II F 2 & response to NRC 820617 ltr re
 THI Action Item II K 3 17.8005 outage rept Info suppls util
 820428 & 06ii 1trs
 HITHERS.B D Portland Ceneral Electric Co BR/08/16 EISENHUT.D Q
 Division of Lizensing 7pp 14510 333 24X Fiche 50-344.82/08/16.
- 8208240173 Forwards add1 info on util 820723 inservice testing relief requests Request re Event 5 valves withdrawn due to competibility w/testing requirements of ASME Section XI requirements

 HITHERS. 8 D Portland General Electric Co 82/08/18 CLARK.R A Operating Reactors Granch 3 Spp 14519.087 24X Fichs. 50-344.82/08/18.8208240173
- Q Inspection reports, IE Bulletins & correspondence
- 8208240348 Forwards IE Insp Rept 50-344/82-20 on 820601-0702 No noncompliance noted 8TERNBERG.D K Division of Resident, Reactor Project & Engineering Programs 82/07/15 HITHERS.B D Portland General Electric Co 2pp. 14520
- --8208240355 IE Insp Rept 50-344/62-20 on 620601-0702 No noncompliance noted Major areas inspected plant shutdown operations, surveillance testing maint refueling activities, security & followup on LERs.
 MALHROSA H J. ZHETZIO, 0 B. Division of Resident, Reactor Project & Engineering Programs 62/07/15 App 14520,357 24X Fiche 50-344,82/07/15.8208240348
- B204210393 IE Info Notice B2-23: "Main Steam Isolation Valve (MBIV) Leakage " Svc list encl JDRDAN,E.L. Division of Engineering & Guality Assurance. B2/07/16, Consolidated Edison Co of New York B7pp 14396,274, 24X Fiche: 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Parsonnel Monitoring Devices for External Radiation " Syc list encl JGRDAN, E.L. Division of Engineering & Quality Assurance. 92/07/19 Michigan, Univ of. 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395

- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Herafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000-82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-26, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JDRDAN, E L Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Byo list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche 50-000 82/07/23 8204210402
- 8204210403 IE Info Notice B2-30, "Loss of Thermal Sleeves in RGS Piping at Certain Hestinghouse PWR Power Plants" Syc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24X Fichs 50-000, 82/07/26, 8204210403
- 8208240270 Forwards IE Insp Rept 50-344/82-22 on 820706-09 No noncompliance noted BDDK-H E Division of Radiological Safety & Safeguards Program 82/07/26 WITHERS B D Portland General Electric Co ip 14527 109 24X Fiche: 50-344,82/07/26,8208240270,
- --8208240274 IE Insp Rept 50-344/82-22 on 820706-09 No noncompliance noted Major areas inspected licensee activities associated w/packaging k shipment of radioactive matls, licensee actions on previous insp findings & actions on IE circulars CILLIS.H. WENSLAWEKI.F A . 800K.H E Division of Radiological Safety & 88feguards Program 82/07/23 10pp 14527 110 24X Fichs 50-344,82/07/26.8208240270
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN.E. L. Division of Engineering & Guality Assurance 82/07/28 Consolidates Edison Co of New York 122pp 14357 146 24X Fiche. 50-000. 82/07/28. 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
 JORDAN.E L Division of Engineering & Quality Assurance 82/08/05
 Consolidate Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000, 82/08/05, 8204210407
- 8208230025 Certifies that util 800607.810504 & 0904 responses to IE Bulletins 80-12.81-02 & 81-02 Suppl 1.respectively.were true & correct WITHERS, B.D. Portland General Electric Co. 82/08/05 ENGELKEN, R.H. Region 5, Office of Director. 1p. 14517 281 24X Fiche 50-344, 82/08/05, 8208230025
- 8208240225 Forwards response to IE Bulletin 82-02. "Degradation of Threaded Fasteners in RCPB of PMR Plants " Insp holdpoints incorporated into Maint Procedure MP-5-1 to ensure insp per ABHE Code Section XI Sealant matts listed MITHERS.B.D Fortland General Electric Co. 82/09/10 ENGELKEN.R H Region 5, Office of Director & pp 14519 260 24X Fiche 80-344.82/08/10.8208240225
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dass exposures in 1781 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J. M. Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project Bpp 14679: 208, 24X Fiche 50-000: 82/07/13:8208270010.
- ---8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1" NRC - No Detailed Affiliation Oiven 82/07/13 48pp 14479:216 24% Fiche: 50-000, 82/07/13,8208270010

- S Reportable occurrences, LERs & related correspondence
- 8208100184 Informs that const delays for design change to mounting pedestal have been delayed pending return to svc of seismic monitoring equipment 87-6336,88-6340 & SR-6341 Info suppls RO transmitted in 820615 ltr
 YUNDT, C P Portland Ceneral Electric Cu 82/07/20 ENOELKEN, R H Region 5, Office of Director ip 14278 214 24X
 Fiche 50-344,82/07/20.8208100184
- 8208100046 Forwards LER 82-011/03T-0 Detailed event analysis encl YUNDT.C P. STEELE.R L Portland General Electric Co 82/07/26 ENGELKEN.R H Region 5. Office of Director 5pp 14296 243 24X Fiche 50-344.82/07/26.8208100046
- --8208100054 LER 82-011/03T-0 on 820608.during refueling, safety injection/RCB thermal sleevs mat! discovered below lower core plate Caused by vibration Affected sleeves removed Binflar thermal sleeve nozzles radiographed BAIR.0 Q Portland General Electric Co 82/07/09 Region 5, Office of Director ip 14276 248 24X Fiche 50-344,82/07/26,8208100044
- 8208060030 Forwards incident reporting sys repts re effects of fire protection sys actuation on safety-related equipment & seismic qualification of safety-related sys for transmission to NEA MICHELBON, C Director's Office 82/07/29, LAFLEUR, J. D Office of International Programs, Director 21pp 14244 315 24X Fiche 30-000, 82/07/29, 8208060030
- \$208100096 Forwards updated LER 82-007/01T-0 Detailed event enalysis encl YUNDT,C P , STEELE,R, L Portland General Electric Co 82/07/30 ENGELKEN,R H Region 5. Office of Director App 14297.276 24) Fiche 30-344,82/07/30,8208100096.
- --B208100108 Updated LER B2-007/01T-0 on B20514, during review of revised containment DBA analysis, nonconservative spray modeling error identified in model used to justify Tech Spec 3 6.1 4 re max positive containment operating pressure YOBHIHARA, O M. Portland General Electric Co 82/07/30 Region 5. Office of Director 1p 14297 302 24X Fiche 50-344.82/07/30, 8208100096
- 8208200292 Forwards LER 82-012/03L-0 Detailed event analysis encl. VUNDT.C P., STEELE.R L. Portland General Electric Co. 82/07/30 ENGELKEN.R H. Region 5, Office of Director 2pp 14394,360 24) Fiche: 30-344,82/07/30,8208200292
- --B208200296 LER 82-012/03L-0 on 820716, seismic category I snubber on 2-inch D reactor coolant loop drain line found disconnected. Gaussib by personnel error Snubber reconnected & personnel cautioned BAIR, 0 0 Portland General Electric Co. 82/07/30, Region 5, Office of Director. 1p 14394-362 24X Fiche 50-344,82/07/30,8208200292,
- 8208160255 EN-82-017A on B20812, order imposing civil monetary penalty in amount of \$50,000 issued to licensee, mitigating \$10,000 of penalty issued on B20528 Action based on prompt corrective action detailed in util B20702 itr.
 BARBER, 0. LIEBERHAN, J Director's Office, Office of Inspection and Enforcement 82/08/12, ip 14347 014. 24X Fiche 50-344, 82/08/12, 8208160255
- DUCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8208030036 Releases public version of administrative mamo re addl paople qualified to be radiation monitoring team members FELTON, J. M. Division of Rules and Records 62/07/28 Document Management Branch 1p 14208 317 24X Fiche 50-346, 82/07/28, 8208030036
- --8208030042 Forwards public version of Administrative Memo 42-16 listing add1 people qualified to be radiation monitoring team members

 * Toledo Edison Co. 82/07/08 FLOOD,N NRC No Detailed Affiliation Given 3pp. 14208
- 8208030047 Releases public version of revised emergency plan administrative procedure FELTON.J M. Division of Rules and Records. 82/07/28. Document Management Branch ip 14241-341 24X Fiche. 50-346, 82/07/28, 8208030047

- --820803005! Forwards public version of Revision 4 to Administrative Procedure AD 1850 04, "Post-Accident Radiological Sampling & Counting "* Toledo Edison Co 82/07/06 FLODD,N NRC No Detailed Affiliation Given 1p 14241 342 24X Fiche 50-346,82/07/28,8208030047
- --8208030086 Public version of Revision 4 to Administrative Procedure
 AD 1850 04, "Post-Accident Radiological Bampling &
 Gounting " Revision 143 to amergency plan supporting
 procedures revision index enc!
 BRIDEN.D Toledo Edison Co B2/06/26 20pp 14241 343 24X
 Fiche 50-346,82/07/28,8208030047
- 9208040444 Releases public version of revised emergency plan administrative procedure FELTON.J M Division of Rules and Records 82/07/28, Document Management Branch ip 14220 198 24X Fiche 50-344,82/07/28, 820804044
- --8208040449 Forwards public version of Revision 8 to Administrative Procedure AD 1827 12. "Protective Action Quidelines "

 * Toledo Edison Co 82/07/13 FL000, N NRC No Detailed Affiliation Qiven. ip 14220 199 24X Fichs 50-346,82/07/28,8208040444
- --8208040452 Public version of Revision 8 to Administrative Procedure AD 1827 12, "Protective Action Quidelines " Revision 145 to emergency plan supporting procedures revision index encl DOYEL, C. OREEN.W Toledo Edison Co 82/07/08 17pp, 14220 200 24X Fiche 50-346,82/07/28,8208040444
- B20Bi30334 Forwards IE Insp Rept 50-346/82-19 on 820713 No noncompliance noted PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/07/28 CROUSE, R P Toledo Edison Co 2pp 14336 320 24X Fiche 50-346, 82/07/28, 820Bi30334
- --8208i30337 IE Insp Rept 50-346/82-19 on 8207i3 No noncompliance noted Major areas inspected followup of prompt public notification/warning sys PATTERBON, J P. AXEL80N, W L Division of Emergency Preparedness & Operational Support 82/07/27 4pp 14336-322, 24% Fichs 50-346,82/07/28,8208i30334
- 8208040604 Releases public version of revised emergency plan implementing procedures FELTGN.J H Division of Rules and Records 82/07/30. Document Management Branch ip 14228 001 24% Fiche 50-346,82/07/30,8208040604
- --82080406i0 Forwards public version of revised emergency plan implementing procedures, including Revision 2 to Procedure EI i300 00 re station response to emergencies & Revision 3 to EI i300 01 re emergency plan activation

 * Toledo Edison Co. 82/07/09 FL00D.N NRC No Detailed Affiliation Given 6pp 14228 002 24X Fiche 50-346,82/07/30,8208040604
- --8208040616 Public varsion of revised emergency plan implementing procedures, including Revision 2 to Procedure EI 1300.00 restation response to emergencies & Revision 3 to EI 1300.01 response to emergency plan activation at Toledo Edison Co. 62/07/12 150pp. 14228 008 24X Fiche 50-346, 82/07/30, 8208040604
- 8208090382 Ack receipt of 820621 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rapt 50-346/82-17.

 MILLERIJ R. Region 3, Office of Director 82/07/30 CRDUSE, R. P. Toledo Edison Co. ip. 14209, 174 24X Ficher 50-346, 82/07/30, 8208050382
- --8208050385 Responds to NRC 820625 itr re violations noted in IE Safeguards Insp Rept 50-346/82-17 Corrective actions withheld (raf 10CFR2.770)

 CROUSE: R P Toledo Edizon Co 82/07/21 KEPPLER, J G Region 3, Office of Director. 1p 14209 175 24X Fiche 50-346, 82/07/30, 8208050382.
- 8208030500 Lists safeguards matls received during 820517-21 insp that NRC shredded Accountability of matls may be terminated Two documents retained per 10CFR73 21.
 MILLER, JR Ragion 3. Office of Director 82/08/02 Toledo Edison Co 2pp. 14213.286. 24X Fiche 50-346.82/08/02,8208050500.
- B20B060094 Releases public version of revision to emergency plan administrative procedure FELTON.J.M. Division of Rules and Records 82/08/02 Document Management Branch 1p 14283-189 24X Fiche 50-346,82/08/02, B20B060094

- --8208060f01 Forwards public version of Revision 8 to Emergency Plan Administrative Procedure AD 1827 12, "Protective Action Guidelines " Receipt form encl # Toledo Edison Co 82/07/22 FLOOD, N Office of the Executive Director for Operations 2pp 14283 190 24X Fiche 50-346,82/08/02,8208060094
- --B20B060109 Public version of Revision 8 to Emergency Plan Administrative Procedure AD 1827 12, "Protective Action Guidelines " Revision 145 to emergency plan supporting DOYEL, C. GREEN, W. MURRAY, T. Toledo Edison Co. 82/07/08 17pp 14283 192 24X Fiche 30-346,82/08/02,8208060094
- 8208060313 Releases public version of revision to emergency plan supporting procedures administrative memo FELTON, J M Division of Rules and Records 82/08/02 Docum Hanagement Branch 1p 14244 281 24X Fiche 50-346,82/08/02,
- --8208060316 Forwards public version of Revision 16 to Emergency Plan evaucusic rorwards public version of Revision 16 to Emergency Plan
 Supporting Procedures Administrative Memo 42-16 re
 radiation monitoring team members
 * Toledo Edison Go 82/07/22 FLOOD,N Office of the Executive
 Director for Operations 2pp 14244 282 24X
 Fiche 50-346,82/08/02.8208060313
- --8208060318 Public version of Revision 16 to Emergency Plan Supporting Fracedures Administrative Memo 42-16 re radiation monitoring team members Revision 144 to procedures index encl * Toledo Edison Co 82/06/28 2pp 14244 284 24X Fiche 50-346,82/08/02,8208060313
- 8208040317 Releases public version of revision to emergency plan administrative procedure
 FELTON, J M Division of Rules and Records 82/08/02 Docum
 Management Branch 1p 14281 127 24X Fiche 50-346,82/08/02,
 8208060319
- --8208060320 Forwards public version of Revision 4 to Emergency Plan Administrative Procedure AD 1850 04, "Post-Accident Radiological Bampling & Counting " Receipt form enci * Toledo Edison Co 82/07/22 FLOOD, N Office of the Executive Director for Operations 2pp 14281 128 24X Fiche 50-346,82/08/02,8208040319
- --820806032i Public version of Revision 4 to Emergency Plan Administrative Procedure AD 1850 04: "Post-Accident Radiological Sampling & Counting " Revision 143 to emergency plan supporting procedures index encl BRIDEN.D. NURRAY.T D Toledo Edison Co 82/06/26 2ipp 14281 130 24X Fiche 50-346.82/08/02.8208060319
- 8208110251 Releases public version of revision to administrative memo FELTON.J M Division of Rules and Records 82/08/05 Document Management Branch ip 14331 119 24X Fiche 50-344,82/08/05, 8208110251

B208110251

- --B20Bi10253 Public version of Revision 13 to Administrative Memo 39-i3, "Fire Brigade" Revision 146 to emergency plan supporting procedures revision index enci MURRAY.T Toledo Edison Co 82/07/15 3pp 14331 121 24X Fiche 50-346,82/08/05.820Bi10251
- 8208240334 Responds to open Items (c) & (e) re-training of personnel nated in 820728 emergency preparedness inspirept on 820713 Training scheduled for completion on 820813 Submittal completes response to 820223 action itr.

 CROUSE, R.P. Toledo Edison Co. 82/08/11 KEPPLER, J.G. Region 3, Office of Director. 19 14520 321 24% Fiche, 50-346, 92/08/11, 820082424
- 8208310235 Ack receipt of B20811 ltr informing NRC of steps taken to correct violations noted in IE insp rept, PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/08/25, CRUSELR P Toledo Edison Co ip 14695-10 24X Fiche 50-346.82/08/25,8208310235 14695-107
- --BZ0B310238 Responds to NRC 820728 ltr re-violations noted in IE insprept Corrective actions licensed operators retrained on SP 1105 17 & seismic monitoring sys procedure to be completed 820813 CROUSER P Toledo Edison Co 8208310235

H General correspondence

8208160024 Advises of recent organizational changes at facility DA Nelson designated as vice president, administrative svcs & industrial security & LC Phillips designated as vice president, corporate planning & development CROUSE, R P Taledo Edison Co B2/08/03 KEPPLER, J G Region 3, Diffice of Director ip 14344 265 24X Fiche 50-346, 82/08/03, B2008/60024 8208160024

M Antitrust correspondence

- OB230018 nt. application TOALSTON, A Antitrust "AAAAO DAGGETT, E L AAAAOAO, 8 8208230018 Requests responses to questions re antitrust review of QL Antitrust & Economic analysis Branch (Utility Finance) 82/08/09 DAGGETT.E L Bryan, OH 2pp 14518 001 24X Fiche 50-000, 82/08/09, 8208230018
- 8208230477 Requests responses to questions re antitrust review of QL application
 TOALSTON A Antitrust & Economic analysis Branch (Utility Finance)
 B2/08/09 HIKEBSELL,B L Cleveland, OH 2pp 14928 237 24X
 Fiche 30-000, 82/08/09, 8208230477
- 82082400B1 Requests responses to questions re antitrust review of QL 208240091 Requests responses to questions to entitrust review or of application
 TOALGTON, A Antitrust & Economic analysis Branch (Utility Finance)
 82/08/09 GREEN, T Painesville, CH 2pp 14529 313 24X
 Fiche 50-000, 82/08/09, 8208240081

P Operating license stage documents & correspondence

- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Byc list epcl DIRCKS, NJ Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001, 24% Fiche 50-000, 82/07/02, 8207080064
- 8208040446 Requests documentation of how util satisfied each criterion of NUREO-0737. Item II B 3 re post-accident sampling sys Response schedule requested by 820818 NUREO-0737. Item II B 3 criteria guidelinos encl STGLZ.J F Operating Reactors Branch 4 82/07/21 CROUSE.R P Toledo Edison Co 10pp 14220 217 24X Fiche 50-346.82/07/21.
- 8208120001 Concludes that anticipatory roactor trip sys bypasses classification as operating bypass is unacceptable unless addl features to alert operator to remove bypasses are BTOLZ, J.F. Operating Reactors Branch 4 82/07/27 CROUSE, R. P. Toledo Edison Co. 2pp. 14332 266 24X Fiche 50-346, 82/07/27, 8208120001 CROUSE R P
- 8208060091 Forwards Amend 45 to License NPF-3, safety evaluation & notice of issuance & availability Amend modifies Tech Spec to permit operation for third cycle STOLZ, JF Operating Reactors Branch 4 82/07/28 CROUSE, R.P. Teledo Edison Co 2pp 14283 099 24X Fiche 50-346, 82/07/28, 8208060091 CROUSE, R. P.
- --B208060098 Amend 45 to License NPF-3, modifying Tach Specs to permit operation for third cycle STOLZ, J.F. Operating Reactors Branch 4 82/07/28 74pp 14283 ioi 24% Fiche 50-346, 82/07/28, 8208060091
- --8208060103 Safety evaluation supporting Amend 45 to License NPF-3 * Office of Nuclear Reactor Regulation, Director 82/07/28 12pp 14283,175 24X Fiche 50-346,82/07/28,8208060091
- --8208060108 Notice of issuance & availability of Amend 45 to License NPF-3. NPF-3. MINER: S Operating Reactors Branch 4 82/07/28 2pp 14283.187. 24X Fiche 50-346.82/07/28.8208060091
- 82080&0331 Forwards safety evaluation supporting licenses 820&22 request for reliaf from certain ASME Boiler & Pressure Vassel Code Section XI requirements re hydrostatic testing STOL2. UF Operating Reactors Branch 4 82/07/27 CROUSE. R P Toledo Edison Co 4pp 14281 251 24X Fiche 50-346, 82/07/29, 82000A0231.
- --8208060332 Safety evaluation supporting licenses request for relief from ASME Boiler & Pressure Vessel Code Section XI hydrostatic test (insp) requirements w Office of Nuclear Reactor Regulation, Director 82/07/29 13pp 14281 256 24X Fiche 50-346,82/07/29,8208060331

ŀ

1 1

ŀ

- 8208030587 Forwards addl info in response to NUREO-0737. Item II K 3 17 re description of ECCS & emergency diesel generator outage time due to surveillance testing or preventive maint, per 820701 request CROUSE.R P Toledo Edison Co 82/07/30 STOLI, J F Operating Reactors Branch 4 3pp 14162 119 24X Fiche 50-346,82/07/30, 2004078507
- 820805023B Forwards application for amend to License NPF-3, revising Tech Spec Table 3 7-3 to reflect steam generator availiary feedwater header mod Class III fee entl CROUGE.R P Toledo Cidson Co 82/07/30 STOLZ, J F Operating Reactors Branch 4 1p 14209 279 24X Fiche 50-346,82/07/30,8209080238
- --8208050242 Application for amend to License NPF-3 revising Tech Spec Table 3 7-3 to reflect steam generator auxiliary feedwater header mod Identification of snubbers removed & relocated during mod to header enc! HURRAY, T D , CROUSE R P Toledo Edison Co 82/07/30 2pp 14209 280 24X Fiche 50-346,82/07/30,8208050238
- --8208050246 Tech Spec Table 3 7-3 re safety-related hydraulic snubbers Safety evaluation for auxiliary feedwater header replacement encl * Toledo Edison Co 82/07/30 7pp 14209 282 24X Fiche 50-346, 82/07/30, 8208050238
- 8208180270 Requests addl info re auxiliary feedwater repair based on 820715 ltr STOLZ, J F Operating Reactors Branch 4 82/07/30 CROUSE, R P Toledo Edison Co 3pp 14389 322 24X Fiche 50-346,82/07/30, 9208180270
- 8208060163 Forwards BAM-1732. "Evaluation, Repair & Replacement of Damaged Internal Auxiliary Feedwater Header at Davis Besse 1. Deconse 3 & Rancho Seco, "per 820624 meeting w/NRC in Bethesda. MD & NRC 820623 request Response summary submitted WALBRIDGE.W C Bacramento Municipal Utility District 82/08/03 STULZ.J F Operating Reactors Branch 4 8pp 14238,089 24X Fichs 50-000,82/08/03,8208060163
- --8208060168 "Evaluation,Repair & Replacement of Damaged Internal Auxiliary Feedwater Header at Davis Besse 1.0conee 3 & Rancho Beco " 4 Babcock & Wilcox Co BAW-1732 82/07/01. 32pp 14238 097 24X Fiche 50-000,82/08/03.8208060163
- B20809010B Forwards application to amend License NPF-3 allowing sway struts to replace snubbers on relocated pressurizer code safety valves CROUBE, R P Toledo Edison Co B2/0B/03 STOLZ, J F Operating Reactors Branch 4 Ip 14267 329 24X Fiche 50-346.82/0B/03, B20809010B
- --8208090112 Application for amend to License NPF-3, authorizing replacement of snubbers w/sway struts on relocated pressurizer code safety valves CRDV8E, R P Toledo Edison Co 82/08/03 2pp 14269 330 24X Fiche 50-346, 82/08/03, 8208090108
- --8208090113 Tech Spec Page 3/4 7-31 re safety-related snubbers * Toledo Edison Co 82/08/03 1p. 14249 332 24X Fiche 50-344,62/08/03,8208090108
- 8208110106 Forwards application to amend License NPF-3, changing Tech Bpecs re snubbers removed w/relocation of pressurizer code safety valves CROUSE.R P Toledo Edison Co 82/08/03 STOLZ, J F Operating Reactors Branch 4 1p 14314-328 24X Fiche 50-346,82/08/03, 92081101014
- --8208110108 Application to amend Tech Specs re snubbers removed w/relocation of pressurizer code safety valves CROUSE,R P Toledo Edison Co 82/08/03 2pp 14314.327 24X Fiche 50-346,82/08/03.8208110106
- --8208110110 Proposed Tech Spec Table 3.7-3 re safety-related hydraulic snubbers removed due to relocation of pressurizer code safety valves a Toludo Edigon Co 82/08/03 ip 14314°331 24X Fiche 50-346, 82/08/03.8208110106
- 8208170012 Forwards evaluation status rept on auxiliary feedwater systeliability Items for which review incomplete listed STOLZ, J.F. Operating Reactors Branch 4. 82/08/03 GROUSE, R.P. Toledo Edison Co. 22pp. 14373 246. 24X Fichs 50-346,82/08/03,82/08/70012

- 8208110131 Forwards add1 info re auxiliary feedwater header repair.in response to NRC 820623 request One oversize drawing encl Aperture card is available in PDR CROUSE.R P Toledo Edison Co 82/08/06 NOVAK,T Assistant Director for Operating Reactors 53pp 14316 264 24X Fiche 50~346, 82/08/06, 8208110131
- 8208090194 Oeneric Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D & Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14396 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208200007 Responds to 8207/3 ltr requesting schedule for submittal of supplemental ECCS calculations using cladding models of NUREO-0630 Calculations will be submitted by 830301 CROUSE.R P Toledo Edison Co 82/08/13 NOVAK.T M Assistant Director for Operating Reactors 1p 14392 200 24X Fiche \$0-346.82/08/13,8208200007
- 8208200114 Confirmatory action ltr referring to agreements made in 820813 discussion re actions associated w/startup from current refueling outage All outstanding NRR issues re modified auxiliary feedwater sys should be resolved MEPPLER.J G Region 3. Office of Director 82/08/13 CROUSE.R P Tolefo Edison Co 1p 14393 334 24X Fiche 50-344.82/08/13. 8208200114
- 8208230353 Forwards info re auxiliary feedwater heador/steam generator mod. in response to NRC questions in 820623 ltr Also discusses potential for crack propagation in retired header Util will propose changes to Tech Specs within 30 days GROUSE.R P Toledo Edison Co. 82/08/16 LAINAS.0 C Assistant Director for Operating Reactors 24pp 14508 296 24X Fiche 50-346, 82/08/16, 8208230353
- 8208270687 Reviews util auxiliary feedwater sys mods & steam generator repairs submitted in 820715 & 0806 ltrs Modified auxiliary feedwater sys acceptable LAINAB.C C Assistant Director for Operating Reactors 62/08/17 CROUSE.R P Toledo Edison Co 3pp 14683 062 24X Fiche 50-346, 62/08/17.0208270687
- 8208310192 Discusses program for resolution of NUREC-0737, Item IT K 3 30, "Revised Small Break LOCA Methods to show Compliance w/IOCFR50.App K "B&W will forward description of CERDA test program CROUSE, R P Toledo Edison Co 82/08/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 14693 115 24X Fiche 50-346, 82/08/25, 8208310192
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 JE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list enc!
 JORDAN,E L. Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000 82/07/16,8204210393
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation," Svc list encl JORDAN, Et. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24% Fiche 50-000, 82/07/19, 8204210395
- B204210396 IE Info Notice B2-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list enci JORDAN,E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381,001 24X Fiche: 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Syc list encl COBB-L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York, 71pp. 14397 276 24% Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 92-26, "RGIC & HPGI Turbine Exhaust Check Valve Failures " Syc list encl JRBAN,E L Division of Engineering & Quality Assurance, 82/07/22 Consolidated Edison Co of New York, 112pp 14194 321 24X Fiche 50-000, 82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl URDANNE L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Fiche: 50-000, 82/07/23, 8204210401

- B204210402 IE Info Notice 82-27. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche: 50-000, 82/07/23.8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance Consolidated Edison Co of New York 121pp 14357 013 24X Fiche: 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York. 122pp 14357:146 24X Fiche 50-000.82/07/28.8204210405
- 8208130334 Forwards IE Insp Rept 50-346/82-19 on 820713 No noncompliance noted PAPERIELLO, C J Division of Emergency Preparedness & Operational Support. 82/07/28 CROUSE, R P Toledo Edison Co 2pp 14336 320 24X Fiche 50-346
- --8208130337 IE Insp Rept 50-346/82-19 on 820713 No noncompliance noted Nagor areas inspected follows of prompt public notification/warning sys PATTERSON, J P. AXELSON, W L Division of Emergency Preparedness & Operational Support 82/07/27 4pp. 14336 382 24X Fiche: 50-346, 82/07/28, 8208130334
- --8208060332 Safety evaluation supporting licensee request for relief from ASME Boiler & Pressure Vessel Code Section XI hydrostatic test (insp) requirements.

 * Office of Nuclear Reactor Regulation, Director 82/07/29 13pp 14281 256. 24X Fiche, 50-346,82/07/29,8208060331
- --8208060336 FR notice of granting relief from certain requirements of AMSE Builer & Frequere Vessel Code, Section XI re inservice insp of nuclear pawer plant components MIMERS Depreting Reactors Branch 4 82/07/29 2pp 14281 269 24X Fiche 50-346.82/07/29.8208060331
- 82080503B2 Ack receipt of 820821 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 30-346/82-17
 MILLER, JR Region 3, Office of Director. 82/07/30 CROUSE,R PToledo Edison Co 1p 14209 174 24X Fiche 30-346,82/07/30, R208080382
- ---B208050385 Responds to NRC 820625 ltr re-violations noted in IE Bareguards Insp Rept 50-346/82-17. Corrective actions withheld (ref 10CFR2.790) CROUBE.R.P Toledo Edison Co 82/07/21. KEPPLER, J O Regson 3, Office of Director ip 14209.175 24X Fiche 50-346, 82/07/30, 8208050392.
- B20B200046 Responds to IE Bulletin B2-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants." Maint procedures written to include procedures for proper threaded fastener practices
 CROWSE, R.P. Toledo Edison Co. 82/08/04, KEPPLER, J.O. Region 3. Office of Director. Spp. 14392: 224 24X Fiche 50-346, 82/08/04, 220220044
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list enc! JRDAN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York. 117pp 14388.201 24X Fiche 80-000.82/08/05.8204210407
- 8208300298 Forwards IE Insp Rept 50-346/82-18 on 820602-0709 & notice of violation 8TREETER, J.F. Division of Project & Resident Programs, 62/08/10 CROUSE, R.P. Toledo Edison Co. 2pp 14597, 336 24X Fichs. 30-346, 82/08/10, 8208300298.
- --8208300303 Notice of violation from insp on 820602-0709, STREETER, J. F., Division of Project & Resident Programs, 82/08/10 1p 14599.338 24% Fiche 50-346,82/08/10.8208300298

- --8208300309 IE Insp Rept 50-346/82-18 on 820602-0709 Noncompliance noted failure to follow established procedures for locked valves ROCERS,W., REYES,L.A. Division of Project & Resident Programs 82/08/10 4pp 14599 339 24X Fiche 50-346/82/08/10.8208300298
- 8208240334 Responds to open Items (c) & (e) re training of personnel noted in 820728 emergency preparedness inspirept on 820713 Training scheduled for completion on 820813 Submittal completes response to 820223 action ltr CROUSE, R P Toledo Edison Co 82/08/11 KEPPLER, J O Region 3, Office of Director ip 14520 321 24X Fiche 50-346, 82/08/11, 8208240334
- 8208270309 Forwards IE Insp Rept 50-346/82-16 on 820521-0802 No noncompliance noted LITTLE:() S Division of Engineering & Technical Programs 82/08/11 CROUSE:R P Toleda Edison Co 2pp 14544 176 24X Fiche 50-346.82/08/11.8208270309
- --8208270313 IE Insp Rept 50-346/82-16 on 820521-0802 No noncompliance noted Major areas inspected repair & replacement of damaged internal auxiliary feedwater headers & A & B steam generators
 - gunerators WARD/K D. DANIELSON,D H Region 3. Office of Director 82/08/10 9pp 14564 198 24X Fiche 50-346.82/08/11,8208270309
- 8208200107 Ack receipt of 820430 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/82-03 NORELIUS, C E Division of Engineering & Technical Programs 82/08/16 CROUSE, R P Toledo Edison Co 2pp 14393 278 24X Fiche: 50-346,82/08/16,8208200107.
- --8208200166 Responds to NRC 820401 ltr re violations noted in IE Insp Rept 80-346/82-03 Corrective actions fire watch established until obstruction removed, closure mechanism replaced & combustibles removed from safety-related areas CROUSE, R P Toledo Edison Co 82/04/30 NORELIUS, C E Division of Engineering & Technical Programs 9pp 14393 300 24X Fiche 50-346, 82/08/16, 8208200107
- 8208310436 Provides status rept & outlines future activity in area of piping supports & anchor mods.per IE Bulletins 79-02 & 79-14 All piping supports meet or exceed criteria for interim sys operability Eleven mods to containment remain CROUSE.R P Tolede Edison Co 82/08/17 KEPPLER.J.O Region 3. Office of Director 2pp 14671 252 24X Fichs 50-346.82/08/19, 8208310436
- 8208270255 Ack receipt of 820730 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/82-08 SPESBARD, R L Division of Project & Resident Programs 82/08/20 CROUSE: R P Toledo Edison Co ip 14543 080 24X Fiche 50-346,82/08/20,8208270255
- --8208270264 Responds to NRC 820616 ltr reviolations noted in 1E Insp. Rept 50-346/82-08 Corrective actions Level C cable & unistrut removed from area & placed in storage & outside storage areas secured CROUSE, R.P. Toledo Edison Co. 82/07/30 SPCSSARD, R.L. Division of Project & Resident Programs 7pp 14563 081 24x Fiche 50-346,82/08/20,8208270255
- 8208310143 Ack receipt of 820813 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-346/82-09 BPE8BARD, R L Division of Project & Resident Programs 82/08/24 CROUSE R P Tolede Edison Co. 1p 14693 180, 24X Fiche. 50-346.82/08/24.8208310143
- --B208310147 Responds to NRC 820715 ltr re violations noted in IE Insp Rept 30-346/82-09 Corrective actions radiation meter cables tagged & spared according to requirements CROUBE, R P Toledo Edison Co 82/08/13 SPESSARD, R L Division of Project & Resident Programs 2pp 14693 181 24X Fiche 50-346,62/08/24,6208310143
- 8208310235 Ack receipt of 820811 ltr informing NRC of steps taken to correct violations noted in IE insp rept PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/08/25 CROUSE.R P Toledo Edison Co 1p. 14675 107 24X Fiche 50-346.82/08/25.8208310235
- --820831023B Responds to NRC 82072B itr re-violations noted in IE insprept Corrective actions licensed operators retrained on SP 1105 17 & seismic monitoring sys procedure to be completed 820813
 CROUSE, R P Toledo Edison Co 82/08/11 KEPPLER, J C Region 3, Office of Director ip 14695 108 24X Fiche 50-346,82/08/25, 8208310235.

- R Periodic operating reports & related correspondence
- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- ---8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" 4 NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270621 Forwards "Personnel Whole Body Exposures for CY81"
 MURRAY, T D Toledo Edison Co 92/03/12 Office of the
 Executive Director for Operations 1p 14680 047 24X
 Fiche 50-000.82/07/13.8208270010
- --8208270625 "Personnel Whole Body Exposures for CY81"
 MURRAY, T D Toledo Edison Co 82/03/12 2pp 14680 048 24X
 Fiche 50-000,82/07/13,8208270010
- S Reportable occurrences. LERs & related correspondence
- 8208050455 Forwards LER 82-031/03L-0 MMRRAY, T D Toledo Edison Co 82/07/23 KEPPLER, J G Region 3 Office of Director 1p 14216 338 24X Fiche 50-346.82/07/23, 8208050455
- --8208050458 LER 82-031/03L-0 on 820625 & 29 doors 500 & 302 found partially open, respectively Caused by design error Maint work requests 82-1187-177 & 169 written to replace door w/stronger close mechanism MDLFE, R Toledo Edison Co B2/07/23 Region 3, Uffice of Director 2pp 14216 339 24X Fiche 50-346.82/07/23,8208050455
- 820B100123 PNO-III-82-069; startup of facility delayed due to recent findings Base plate for hydraulic snubber on pressurizer surge line found pulled out from wall & pin from MSIV located Enubber & MSIV repairs in progress ROGERS, W. REYES, L. SPESSARD, R. Region 3, Office of Director 82/07/27 ig 14278 185 24X Fiche 50-346,82/07/27,8208100123
- 820B100200 Forwards LER 81-004/03X-1 MURRAY.T D Toledo Edison Co 82/07/28 KEPPLER.J 0 Region 3. Office of Director ip 14294 252 24X Fiche 50-346,82/07/28, 8208100200
- --8208100205 LER 81-004/03X-1 on 810107, during Mode 4 operation, decay heat pump 1-1 failed to start Caused by breaker failure due to bent motor cutoff switch operator Switch operator straightened & pump returned to svc
 MATHENY,D C, Toledo Edison Co 82/07/28 Region 3, Office of Director 2pp 14294 253 24X Fiche 50-346,82/07/28,8208100200
- 8208130148 Forwards LER 82-004/03L-1 , HURRAY.T D Toledo Edison Co 82/08/04 KEPPLER.J O Region 3, Office of Director 1p 14338 100 24X Fiche 50-346.82/08/04, 8208130148
- --8208130151 LER 82-004/03L-1 on 820122, operator found Door 108 to detergent waste drain tank & pump room left open Caused by personnel error due to worker not closing & latching door 8ubj will be addressed in training session WOLFE,R, STOTZ,J Toledo Edison Co 82/08/04 Region 3, Office of Director 2pp 14338 101 24X Fiche 50-346,82/08/04,8208130148.
- 8208130078 Forwards LER 82-032/03L-0 MURRAY, T D Toledo Edison Co 82/08/05 KEPPLER, J O Region 3 Office of Director, ip 14336 038 24X Fiche: 50-346,82/08/08, 8208130078
- --B20Bi300B6 LER 82-032/03L-0 on 820704, auxiliary feed pump 1-2 sycwater supply line isolation valve BM6 found out of position Caused by personnel error Operators counseled re locked valve operations
 U**CONNOR**B Tolado Edison Co 82/08/05 Region 3, Office of Director. 3pp 14336 039 24X Fiche 50-346,82/08/05,820Bi30078.
- 8208130281 Forwards LER 82-031/03L-1 MURRAY, T D Toledo Edison Co. 82/08/05 KEPPLER, J O Region 3, Office of Director 1p. 14333'063, 24X Fiche, 50-346, 82/08/05, 8208130281

- --8208130282 LER 82-031/03L-1 on 820625,27 & 0706, fire & negative pressure doors 500,302 & 426 found slightly open Caused by closure mechanism failure to seat doors tightly when released from nearly closed position due to design error MDLFE, R Toledo Edison Co 82/08/05 Region 3, Office of Director 2pp 14333 064 24X Fiche 50-346,82/08/05,8208130281
- 8208160450 Forwards LER 82-033/03L-0 MURRAY.T D Toledo Edison Co 82/08/06 KEPPLER.J G Region 3. Office of Director 1p 14348 246 24X Fiche 50-346.82/08/06. 8208160450
- --8208160462 LER 82-033/03L-0 on 820723 discovered that upper concrete expansion anchors & upper part of baseplate of hanger pulled away from wall approx 3/8 inch Caused by installation method Anchors replaced & other hangers checked WOOD. J Toledo Edison Co 82/08/04 Region 3, Office of Director 3pp 14348 247 24X Fiche 50-346.82/08/06.8208140490
- B20B300097 Forwards LER 82-034/03L-0 MURRAY, F D Toledo Edison Co B2/08/18 KEPPLER, J G Region 3, Office of Director 1p 14596 148 24X Fiche 50-346, B2/0B/18, B20B30097
- --8208300100 LER 82-034/03L-0 on 820720, manual actuation pushbutton for containment spray train 2 failed to work Caused by manual actuating switch MWD-1C-415-82 becoming loose from pushbutton Assembly tightened ISLEY, T Toledo Edison Co 82/08/18 Region 3, Office of Director 2pp 14976 149 24X Fiche 80-346.82/08/18.8208300097
- 8208300133 Forwards LER 82-035/03L-0 MURRAY, T D Toledo Edison Co 82/08/18 KEPPLER, J G Region 3, Office of Director. 1p 14595 294 24X Fichs 50-346,82/08/18, 820830133
- --8208300135 LER 82-039/03L-0 on 820719, source range indication NI-1 read less than 1 count per second Caused by degradation of insulation in NI-1 signal lead containment penetration module Module replaced SMARTZ. J Toledo Edison Co. 82/08/18 Region 3. Office of Director 2pp 14595 295 24X Fiche 50-346-82/08/18.8208300133
- 8208310217 Forwards LER 82-006/03L-I MURRAY.T D Toledo Edison Co 82/08/19 KEPPLER, J O Region 3. Office of Director 1p 14693 108 24X Fichs 50-346,82/08/19, 8208310217
- --8208310220 LER 82-006/03L-i on 820126.determination of reportability made re 820113 event During attempt to start component cooling water pump i-1.breaker AC113 would not close Caused by worn rack in mechanism Mechanism replaced MATHENY,D C Toleda Edison Co 82/08/19 Region 3, Office of Director 2pp 14693 109 24X Fiche 50-346.82/08/19.8208310217.
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8208090135 Forwards IE Bafeguards Insp Repts 50-348/82-14 & 50-364/82-13 on 820524-28 & notice of violation Notice of violation withheld (ref 10CFR73 21) LEHIS, R C Division of Project & Resident Programs 82/06/29 HCDDNALD, R P Alabama Power Co. 1p 14269, 238 24% Fiche: 50-348, 82/06/29, 8208090135
- --8208090138 IE Safeguards Insp Repts 50-348/82-14 & 50-344/82-13 on 820524-28 Noncompliance noted failure to provide compensatory measures for degraded assessment capability Details withheld (ref 100FR73.21)
 TILLMAN, A , STANSBERRY, W W Region 2, Office of Director. MCGUIRE, D, R Division of Engineering & Technical Programs 82/06/28, 3pp 14267 237, 24X Fiche 50-348,82/06/29,8208090135
- 8208030305 Forwards IE Insp Repts 50-348/82-15 & 50-364/82-14 on 820607-10 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/07 MCDQNALD, R P Alabama Power Co. 2pp. 14156 267 24X Fiche 50-348, 82/07/09, 8208030305
- --8208030323 IE Insp Repts 50-348/82-15 & 50-364/82-14 on 820607-10, No noncompliance noted Major areas inspected followup on emergency preparedness findings MARSTON,R R , JENKING,Q R. Division of Emergency Preparedness & Operational Support 82/07/07 5pp 14156;271 24x Fiche 50-348,82/07/09,8208030305

- B20B030467 Forwards IE Insp Repts 50-348/B2-17 & 50-364/82-16 on 820622-25 No noncompliance noted DANCE, H C Division of Project & Resident Programs B2/07/09 MCDDNALD, R P Alabama Power Co 2pp 14163 098 24X Fiche 50-348
- --8208030476 IE Imap Repts 50-348/82-17 & 50-364/82-16 on \$20622-25 No honcompliance noted Major areas inspected fire protection & prevention MILLER, H H , CONLON, T E. Division of Enganeering & Technical Frograms 82/07/06 7pp 14163 100 24X Fiche 50-348.82/07/09, \$208030467
- B208020059 Advises that B20412 changes to security plan & security personnel training & qualification plan acceptable Exceptions noted in enci Response to enci comments on exceptions requested within 30 days of receipt of itr VAROA: 8 A Operating Reactors Branch 1 82/07/13 CLAYTON: F L Alabama Power Co 3pp 14181 056 24X Fiche 50-348, 82/07/13, 8208020059
- 8208020243 Forwards addl info re mods to present containment fire protection measures for 10CFR50 App R requirements, per 820618 exemption request CLAYTON,F.L. Alabama Power Co. 82/07/27 VARGA,8 A. Office of Nuclear Reactor Regulation, Director 7pp 14151 224 24X Fiche. 50-348, 82/07/27, 8208020243
- B20B09017B Ack receipt of B20726 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-348/82-14 & 50-344/82-13 LEWIS.R C Division of Project & Resident Programs 82/08/05 MCDDNAKLD.R P Alabama Power Co ip 14270 358 24X Fiche 50-348,82/08/05,8208090178
- --8208090181 Responds to NRC 820629 ltr reviolations noted in IE Safeguards Insp Repts 50-348/82-14 & 50-364/82-13 Response withheld (ref 10CFR73 21) CLAYTON.F.L. Alabama Power Co. 82/07/26 LEWIS.R.C. Division of Project & Rosident Programs ip 14270 359 24X Fiche 50-348.82/08/05.8208090178
- 8208230079 Forwards details of screening measures applied to new employees prior to being granted interim unescorbed access, in response to NRC 880713 ltr Revised security plan will be submitted within next 2 wks.Encl withheld (ref 100FR73 21) CLAYTON,F L Alabama Power Co 82/08/11 VARQA,S A Office of Nuclear Reactor Regulation. Director ip 14517 140 24X Fiche 50-348, 82/08/11,8208230079,
- 8208310087 Releases public version of temporary change to revision of emergency plan procedure FELTON.J M Division of Rules and Records 82/08/11 Document Management Branch ip 14497 250 24X Fiche 50-346,82/08/11, 8208310087
- --B20B310090 Public version of Temporary Procedure Change 10A to Revision 10 of Emergency Plan Procedures FNP-0-EIP-16, "Emergency Equipment & Supplies " Procedure request form encl w Alabama Power Co B2/07/06 13pp 14697 251 24X Fiche 50-348,82/08/11,8208310087.

P Operating license stage documents & correspondence

- 8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of GP re Commission approved charter for GROR. 8vc list encl
 DIRCKS.W J. Office of the Executive Director for Operations.
 82/07/02. Consolidated Edison Co of New York 93pp 14194 001
 24K Fichs 50-000: 82/07/02. 8207080064
- 8208040342 Informs that evaluation of response to NUREG-0737, Item II K 3 25, "Loss of AC Power to Reactor Coolant Fump Seals," adequately demonstrates that integrity of seals is maintained during loss of offsice power Item resolved NEIGHBORS, J D. Operating Reactors Branch L. 82/07/21 CLAYYDN.F.L. Alabama Power Co 2pp 14223-335 24X Fiche. 50-348, 82/07/21, 8208040342.
- 820B130129 Forwards request for additinfore NUREG-0737. Item II B 3. "Post-Accident Sampling Bys " Response required within 20 days. Evaluation criteria guidelines encl VAROA, B.A. Operating Reactors Branch 1 82/07/22 CLAYYON, F.L. Alabama Power Co 10pp 14340 271. 24X Fiche 50-34B.82/07/22, 8208130129
- 8208050018 Forwards request for add1 info meaded to complete review of 820317 % 0421 applications for expansion to spent fuel pool capacity.

 NEIOHBORS.J D. Operating Reactors Branch 1 82/07/26 CLAYTON,F L, Alabama Power Co. 3pp 14243.084, 24X Fichs 50-348.82/07/26, 8208050018

- 8208260369 Forwards SER input concluding that requirements of NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 re accident monitoring instrumentation considered resolved VARGA.8 A Operating Reactors Branch 1 82/07/30 CLAYTON.F L Alabama Power Co 3pp 14588 217 24X Fiche 50-348,82/07/30, 2309040348
- 8208100172 Responds to 820624 request for addl info re TMI Item
 II K 3 17. "Outages of ECCS" During operating period from
 771201 to 801201 diesel generators tested once monthly for
 60 minutes
 CLAYTON F L Alabama Power Co 82/08/02 VARGA, 8 A Office of
 Nuclear Reactor Regulation, Director 3pp 14298 230 24X
 Fiche 30-348, 82/08/02, 8208100172
- 8208060240 Submits info re noninvasive vessel level sys results
 Neutron detector assemblies do not meet stds & are not
 compatible w/NUREC-0737. Item II F 2 Review of available
 sys initiated Status rept expected by 830201
 CLAYTON, F L Alabama Power Co 82/08/03 VARGA, S A Office of
 Nuclear Reactor Regulation, Director 2pp 14241 295 24X
 Fichs 50-348, 82/08/03, 8208060260
- 8208060263 Application to amend Tach Specs, changing testing & surveillance requirements to prevent overload testing of diesel generators Class III fee and CLAYTON, FL Alabams Power Co 82/08/03 VAROA, 8 A Office of Nuclear Reactor Regulation, Director 7pp 14241 282 24X Fiche 50-348, 82/08/03, 8208060263
- --8208060264 Proposed Tech Spec changes to Section 4 8 1 1 2 C 5 re surveillance requirements to prevent overload testing of diesel generators 4 Alabama Power Co 82/08/03 2pp 14241 271 24X Fiche 50-348,82/08/03,8208060263
- 8208250480 Informs that Div of Licensing has completed fee determinations for applications referenced in Amend 26 to License NFF-2 Add1 fee due DI008,R H License Fee Management Branch 82/08/06 CLAYTON,F L. Alabama Power Co 2pp 14562 261 24X Fichs 50-348,82/08/06, 8208250480
- 8208120162 Responds to Generic Ltr 82-12, "Nuclear Fower Staff Working Hours" Bhift manning requirements per NUREG-0737, Item I A 1 3 met No Tech Spec change required CLAYTON.F L Alabama Power Co. 82/08/08 EISENHUT, D O Office of Nuclear Regulatory Research, Director ip 14319 278 24X Fiche 50-348, 82/08/08.8208120162
- 8208090194 Oeneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EIGENHUT, D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194.
- 8208130061 Application to amend Licenses NPF-2 & NPF-8, incorporating Unit 1 Tech Spec acceptance criteria for leak testing reactor coolant sys isolation valves into Unit 2 Tech Spec & deleting Paragraph 4 4 7 3 2 from both units Tech Specs CLAYTON,F L. Alabama Power Co. 82/08/10 VAROA,8 A. Office of Nuclear Reactor Regulation, Director 5pp 14335;038 24X Fiche 50-348,82/08/10,8208130061
- --B20Bi30062 Proposed Tech Spec 3/4 4 7 3 for Unit 2 & revised Tech Specs 4 4 7 3 2 for Unit 1 & 3/4 4 7 2 for Unit 2 rs acceptance criteria for leak testing RCB isolation valves 4 Alabama Pawer Co 82/08/10 lipp 14335 063 24X Fiche 50-348,82/08/10,8208130061
- 8208170225 Forwards "Resurveillance Rept on Three-Yr Burveillance Tendons for Containment Post-Tensioning Sys." addendum to "Three-Yr Tendon Surveillance Rept "
 KINOSLEY,O,D Alabama Power Co. 82/08/11 REEVES,E A. Office of Nuclear Reactor Regulation, Director, ip 14369 030 24X
 Fiche: 50-348, 82/08/11, 8208170225
- --B208170228 "Resurveillance Rept on Three-Yr Surveillance Tendons for Containment Post-Tensioning Sys," addendum to "Three-Yr Tendon Surveillance Rept" # Bechtel Corp 82/06/30 400pp, 14369 031, 24X Fiche 50-349,82/08/11
- 9209200006 Provides info re Jan 1983 refueling outage plans to correct baffle jetting problem Reactor coolant flow will be converted batween core barrel & baffles from downflow to upflow CLAYTON, F.L. Alabama Power Co. 82/08/16 VARQA, B.A. Office of Nuclear Reactor Regulation, Director 2pp 14972 354 24X Fiche 50-348, 82/08/16, 8208200006

DOCKETED ITEMS

- B20B230315 Advises that schedule for submittal of addl info re NUREO-0737. Item II B 3, "Post-Accident Sampling Sys" will be provided by B30401, in response to NRC B20722 ltr Delay due to refueling outages & verification tests of procedures CLAYTON,F L Alabama Power Co 82/09/18 VARGA,S A Office of Nuclear Reactor Regulation, Director 1p 14510 352 24X Fiche 50-348, 82/08/18, 8208230315
- ©208250309 Forwards proposed Tech Spec change deleting river water sys loads from diesel generator automatic load sequence Application for license amend will be submitted by Dec 1782 CLAYTON,F L. Alabama Fower Co. 82/08/20 VARGA,E A. Office of Nuclear Reactor Regulation, Director Spp. 14538 080 24X Fiche 50-348,82/08/20,8208250309
- --8208250314 Proposed Tech Spec change deleting river water sys loads from diesel generator automatic load sequence Alabama Power Co 82/08/20 4pp 14538 085 24X Fiche 30-348,82/08/20,8208250309
- Q Inspection reports, IE Bulletins & correspondence
- B208090135 Forwards IE Safeguards Insp Repts 50-348/82-14 & 50-364/82-13 on 820524-28 & notice of violation Notice of violation withheld (ref 10CFR73 21)
 LEWIS,R C Division of Project & Resident Programs 82/06/29 MCDONALD,R P Alabama Fower Co ip 14269 238 24X
 Fiche 50-348,82/06/29,8208090135
- ---B20809013B IE Safeguards Insp Repts 50-348/82-14 & 50-364/82-13 on 820524-28 Noncompliance noted failure to provide compensatory measures for degraded assessment capability Datails withhald (ref 10CFR73 21)
 TILLMAN.A. SAMSBERTY.W W Region 2. Office of Director MCGUIRE.D R Division of Engineering & Technical Programs 82/06/28 3pp 14269 239. 24X Fiche 50-348.82/06/29.8208090135
- E208030305 Forwards IE Insp Repts 50-348/82-15 & 50-364/82-14 on 820607-10 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/07/09 MCDUNALD.R P Alabama Power Co 2pp 14156 269 24X Fiche 50-348,82/07/09,8208030305
- --8208030323 IE Insp Repts 50-348/82-15 & 50-364/82-14 on 820607-10 No noncompliance noted Major areas inspected followup on emergency preparadness findings. MARSTON, R R , JENKINS, G R. Division of Emergency Preparadness & Operational Support 82/07/07 5pp 14196 271 24X Fiche 50-348, 82/07/09, 8208030305
- B208030467 Forwards IE Insp Repts 50-348/82-17 & 50-364/82-16 on 820622-25 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/07/09 HCDONALD.R P Alabama Fower Co 2pp 14163 098 24X Fiche 50-348, 82/07/09, 8208030467
- --8208030476 IE Insp Repts 50-348/82-17 & 50-364/82-16 on 820622-25 No noncompliance noted Major areas inspected fire protection & prevention MILLER, M. H., CONLON, T.E. Division of Engineering & Technical Programs. 82/07/06 7pp 14163,100 24X Fichs 50-348,82/07/09,8208030467
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valva (MSIV)
 Leakage " Syc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 92/07/16
 Consolidated Edison Co of New York, 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Evc list encl, JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp. 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl JORDAN.E.L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche: 50-000, 82/07/20, 8204210396.
- 8204210397 IE Info Notica 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl COBB.L I, Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co of New York 7ipp 14357.276 24X Fiche 50-000.82/07/20,8204210397

- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 62/07/23. Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " 8vc list encl JORDAN,E L Division of Engineering & Guality Assurance 62/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23,8204210402
- 8208030353 Ack receipt of 820707 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/82-13 & 50-348/82-13 & 50-348/82-12 LEHIS,R C Division of Project & Resident Programs 82/07/23. MCDDNALD,R P Alabama Power Co ip 14157 089 24X Fichs 50-348, 82/07/23, 8208030353
- --B20B030355 Responds to NRC B20614 ltr re violations noted in IE Insp Repts 50-348/82-13 & 50-364/82-12 Corrective actions containment spray suction valves from refueling water storage tank opened & personnel counseled CLAYTON,F.L. Alabama Power Co. 62/07/07 LEHIS,R.C. Region 2, Office of Director. 2pp 14157-070 24X Fiche 50-348,82/07/23, 820B030353
- --B208030361 Forwards IE Insp Repts 50-348/B2-13 & 50-364/B2-12 on 820416-0515 & notice of violation LEWIS,R C Division of Project & Resident Programs 82/06/14 MCDUNALD,R P Alabama Power Co 2pp 14157 092 24X Fiche 50-348
- --8208030364 Notice of violation from insp on 820416-0515

 * Division of Project & Resident Programs 82/06/14 1
 14157 094 24% Fiche. 50-348, 82/07/23, 8208030353
- --B208030367 IE Insp Repts 50-348/B2-13 & 50-364/B2-12 on 820414-0515 Noncompliance noted failure to follow procedure to determine which engineered safety sys volves were in off-normal position BRADFORD: H H, PEEBLES, T A, BROWNLEE, V L Division of Project & Resident Programs B2/06/11 7pp 14157 095 24X Fiche 50-348,822/07/23,8208030353
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Flants" Svt list encl. JORDAN.E.L Division of Engineering & Quality Assurance 62/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche.30-000, 82/07/26, 8204210403.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Syc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp. 14357 146 24% Fiche. 50-000, 82/07/28, 8204210405
- 8208160211 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPD of PNR Pients" Possible leakage found past steam generator manuals on three generators List of bolted closures encl CLAYTON.F L Alabama Power Co 82/08/02 O'REILLY, J. P. Region 2, Office of Director 4pp 14344 161 24X Fiche 50-348,82/08/02, 82/08160211
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JRDAN,E L Division of Engineering & Quality Assurance B2/08/05, Consolidated Edison Co of New York, 117pp 14388 201, 24X Fiche: 50-000, 82/08/05,8204210407
- 8208090178 Ack receipt of 820726 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-348/82-14 & 50-364/82-13 LEWIS.R C **Division of Project & Resident Programs 82/08/05, MCDONALD,R.P. Alabama Power Co ip 14270 358, 24X Fiche.50-348, 82/08/05, 8208090178,
- --8208090181 Responds to NRC 820629 ltr reviolations noted in IE 8afeguards Insp Repts 50-348/82-14 & 50-364/82-13 Response withheld (ref 100FR73 21) CLAYTON,F.L. Alabama Power Co 82/07/26 LEWIS,R C Division of Project & Resident Programs. 1p 14270-359 24X Fiche: 50-348, 82/08/05, 8208090178

R Periodic operating reports & related correspondence

- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info forwards documents listed in App A FELTON. J M Division of Rules and Records 82/07/13 UDELL.R A Critical Mass Energy Project 8pp 14679 208 24X Fichs 50-000.82/07/13.8208270010
- --8208270098 "Annual Whole Body Dosp At Licensed Nuclear Power Facilities for CV81 " * NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fichs 50-000,82/07/13,8208270010
- --8208270564 "Annual Rept of Radjation Dose Distribution for 1981 "
 + Alabama Power Co 02/03/05 ip 14680 036 24X
 Fiche 50-000,82/07/13,8208270010
- 8208160020 Forwards monthly operating rept for Jul 1982 CLAYTON.F L Alabama Power Co 82/08/11 Office of Resource Management, Director 2pp 14345 004 24% Fiche 50-348,82/08/11, 8208160020
- ---8208160021 Monthly operating rept for Jul 1982 HAIRSTON: G Alabama Power Co 82/08/05 4pp 14345 006 24X Fiche \$0-348,82/08/11,8208160020
- S Reportable occurrences. LERs & related correspondence
- --B207010234 LER 82-027/03L-0 on 820526, turbine driven auxiliary feedwater pump declared inoperable when main control board annunciator indicated trip throttle valve closed Cause unknown Valve reopened HAIRSTON.H 9 Alabama Power Co 82/06/25 Region 2. Office of Director ip. 13672 314 24X Fichs 50-348,82/06/25,8207010228
- --8207010251 LER 82-023/03L-0 on 920528, determined that FNP-2-8TP-19 3
 not performed within time interval specified by Tech Spec
 4 0 5 Caused by personnel error FNP-2-8TP-19 3
 satisfactorily performed
 HAIRSTON, W 9 Alabama Power Co 82/06/25 Region 2, Office of
 Director 2pp 13672 315 24X Fiche 50-348, 82/06/25, 8207010228
- P207010234 LER 82-027/03L-0 on 820526, turbine driven auxiliary feedwater pump declared imperable when main control board impuriator indicated trip throttle valve closed. Cause inknown Valve respense fAIRSTON; H 9 Alabama Power Co 82/06/25. Region 2, Office of Director ip 13672 314 24X Fiche 50-348; 82/06/25, 8207010234
- OBO20074 Submits description of actions taken subsequent to initial 3-yr containment post-tensioning sys testing & insp.per LER 80-058/03L-1 Sys is performing design function w/margin of cafety, therefore no add1 action necessary CLAYTON.F.L. Alabama Power Co. 82/07/20. O'REILLY, J.P. Region 2, Office of Director 2pp. 14144-110 24X Fiche 50-348, 82/07/20, 8208020074
- /208020171 Forwards LER 82-032/03L-0 CLAYTON,F L Alabama Power Co 82/07/20 Region 2, Office of Director 1p 14141 023 24X Fiche: 50-348, 82/07/20, 8208020171.
- --8208020174 LER 82-032/03L-0 on 820701.iA reactor coolant pump underfrequency relay 81-2 failed to trip during underfrequency test Caused by faulty relay. Relay replaced & declared operable HAIRSTON: W Q Alabama Power Co 82/07/20 Region 2, Office of Director ip 14141-024 24X Fiche-50-348,82/07/20,8208020171
- 8208020116 Forwarde LERs 82-033/09L-0.82-034/03L-0 & 82-036/03L-0. CLAYTON, F. L. Alabama Power Co 82/07/22. Region 2. Office of Director 1p 14141 059, 24X Fiche: 50-348, 82/07/22, 8208020116
- --8208020118 LER 82-033/03L-0 on 820703, train II chlorine detector declared inoperable since detector tape would not advance. Caused by sheared pin in paper drive motor Pin replaced, HATRSTON N Q Alabama Power Co 82/07/22 Region 2, Office of Director. ip. 14141 040 24X Fiche 50-348.82/07/22,8208020116

- ~-8208020122 LER 82~034/03L~0 on B20626, main control board handswitch for recirculation fan suction damper fractured, rendering A train penetration room filtration sys inoperable Caused by broken shaft in handswitch HAIRSTON, W Q Alabama Power Co B2/07/22 Region 2, Office of Director ip 14141 061 24X Fiche 50-348.82/07/22,8208020116
- --E208020131 LER 82-036/03L-0 on 820623, boron injection tank flowpath train A heat tracing declared inoperable when temp fell below 145 F Caused by personnel error in setting controlling thermostat too low Thermostat adjusted HAIRBTON, W 9 Alabama Power Co 82/07/22 Region 2, Office of Director 1p 14141 062 24X Fiche 50-348,82/07/22,8208020116
- 8208120227 Forwards LERs 82-035/03L-0 & 82-026/03L-0 CLAYTON.F L Alabama Power Co 82/07/30 Region 2, Office of Director ip 14325 348 24% Fiche 50-348,82/07/30,8208120227
- --8208120231 LER 82-026/03L-0 on 820710, during performance of FNP-2-STP-612 0, 2A reactor coolant pump undervoltage relay 27-3 declared inoperable Caused by setpoint drift Relay setpoint adjusted & relay declared operable HAIRSTON.W o Alabama Power Co 82/07/30 Region 2, Office of Director 1p 14326 349 24X Fiche 50-348,82/07/30,8208120227
- --8208120236 LER 82-035/03L-0 on 820712. A train chlorine detector declared inoperable due to detector tape not advancing Caused by faulty paper drive motor Motor replaced following performance of FNP-0-STP-218 i HAIRSTON, W O Alabama Power Co 82/07/30 Region 2, Office of Director 1p 14326-350 24X Fiche 50-348,82/07/30,8208120227
- 8208200164 Forwards LERs 82-037/03L-0.82-039/03L-0 & 82-030/03L-0 CLAYTON,F L. Alabama Power Co 82/08/11 Region 2, Office of Director 1p 14399.272 24X Fiche 50-348.82/08/11.8208200164
- --B208200173 LER 82-037/03L-0 on B20718, overpower delta temp instrumentation loop D associated w/TE-422 declared insperable when bistables TS/422D-1 & TS/422D-2 tripped Caused by faulty amplifier card Card replaced HAIR8TON W Q Alabama Power Co B2/0B/11 Region 2, Office of Director Ip 14359 273 24X Fiche 90-348,82/0B/11,8208200164
- --8208200183 LER 82-039/03L-0 on 820713, hydrogen recombiner oxygen inlet analyser iA declared inoporable when calibr could not be performed Caused by faulty analyser cell Cell replaced HAIRSTON,H G Alabama Power Co 82/09/11 Region 2, Office of Director ip, 14399 274 24X Fiche 50-348, 82/08/11, 8208200164
- ---8208200190 LER 82-030/03L-0 on 820715, steam jet air ejector noble gas monitor (RE-15) declared inoperable due to erroneous high indication Caused by faulty detector Datector replaced HAIRSTON, W O Alabama Power Co 82/08/11 Region 2, Office of Director. 1p 14399 275 24% Fiche 50-348,82/08/11,8208200164
- 8208270254 Forwards LERs 82-038/03L-0 & 82-031/03L-0, CLAYTON.F L Alabama Power Co 82/08/17 Region 2, Office of Director ip 14563 094 24% Fiche 50-348,82/08/17,8208270254
- --8208270261 LER 82-038/03L-0 on 820727, determined that FNP-0-8TP-130 (fire hose stations-monthly) & FNP-0-STP-132 (hydrant hose house insp-monthly) not performed within required time interval Caused by personnel error MAIRSTON.W Q Alabame Power Co 82/08/17 Region 2, Office of Director 1p 14563 095 24X Fiche 50-348,82/08/17,8208270284
- --8208270269 LER 82-031/03L-0 on 820726, instrumentation loop associated wisteam flow transmitter FT-476 declared inoperable when transmitter failed low Caused by faulty power supply card Card replaced HARSTON O Alabama Power Co. 82/08/17 Region 2, Office of Director 1p 14563.096 24X Fiche 50-348.82/08/17.8208270254

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

8208090023 Requests add1 info identified in App E of NUREO-0588 re qualification of safety-related electrical equipment FSAR Escation 3 is must include qualification of equipment in harsh environ Scheduled response date requested in 7 days. SCHWENGER. A Licensing Branch 2 82/06/17 BAUER. E. Q Philadelphia Electric Co 3pp 14283:324 24% Fichs 50-352,82/06/17,8208090023

- 8207070390 Forwards Amend 35 to application for QL, consisting of Revision 7 to FSAR Revision 2 to emergency plan & proprietary version of Vol 3 of "Design Assessment Rept" Rept withheld (ref 100FR2 790)
 BRADLEY,E J Philadelphia Electric Co 82/06/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 13738 101 24X Fiche 50-332,82/06/30,8207070390
- --8207070401 Amend 35 to application for DL, consisting of Revision 7 to FBAR, Revision 2 to emergency plan & proprietary version of Vol 3 of "Design Assessment Rept"
 BDYER, V S Philadelphia Electric Co 82/06/25 7pp 13738:108 24X Fiche 50-352,82/06/30.8207070390
- 8208120003 Summary of 820514 meeting w/util in King of Prussia,PA re Revision 3 to probabilistic risk assessment Viewgraphs encl ABELSON,H Licensing Branch 2 82/07/06 Licensing Branch 2 97pp 14332 186 24X Fiche 50-352,82/07/06,8208120003
- 8208040427 Requests add1 info re proposed schedule for program concerning adequacy of design margins of Mark I & II containment sys Response within 14 days requested TEDESCO.R L. Assistant Director for Licensing 82/07/08 BAUER, E 0 Philadelphia Electric Co 3pp 14220 175 24X Fiche 50-352,82/07/08,8208040427
- B208060088 Forwards Reactor Bys Branch request for addl info re FSAR Section 15 concerning accident analyses Bohaduled response data requested within 7 working days from receipt of ltr W/o encl BCHMENGER:A Licansing Branch 2 82/07/08 BAUER:E 0 Philedelphia Electric Co 2pp 14283 211 24X Fiche 30-352:82/07/08.820806088
- 8208030081 Forwards request for add1 info necessary to complete review of FBAR OF FBAR SCHWENCER.A Licensing Branch 2 82/07/09 BAUER.E 0 Philadelphia Electric Co 5pp 14200 318 24X Fiche 50-352,82/07/09,8208030081
- 8208030087 Requests current description of diversion plan Description should identify changes in design location const & operation made since issuance of CP & should include assessment of incremental impacts or reductions in impacts.

 8CHMENCER.A Licensing Branch 2 82/07/07 BAUER, E G. Philadelphia Electric Co 2pp 14182 358 24X Fiche: 50-352, 82/07/09, 8208030087
- 8208030030 Forwards request for add1 info re meteorology & accident analysis to continue FSAR revisw SCHMENCER.A Licensing Branch 2 82/07/13 BAUER.E.O Philadelphia Electric Co 10pp 14208 353 24x Fiche 50-352, 82/07/13, 8208030030
- 8208030041 Forwards request for addl geotechnical info re foundation & soils to continue FBAR review SCHMENGER, A Licensing Branch 2, 82/07/13, BAUER, E G. Philadelphia Electric Co 4pp. 14208 321 24X Fiche, 50-352, 82/07/13, 8208030041
- 8208050039 Forwards request for add1 info re effluent treatment sys Schedule for response due in 7 days SCHMENGER.A. Licensing Branch 2 82/07/28 BAUER, E 0. Philadelphia Electric Co. 15pp 14243 174 24X Fiche 50-352,82/07/28,8208050039
- 8208030446 Informs that util will respond to 820719 request for additinfo from Accident Evaluation Branch via FBAR revision in Bept 1982 BRADLEY.E J Philadelphia Electric Co 82/07/30 BCHMENCER, A Licensing Branch 2 2pp 14155.299 24X Fiche 50-352,82/07/30,8208030446
- --8208030451 Informs that response to 820721 request for addl info from Accident Evaluation Branch will be provided in environ rept revision in Sept 1982

 BRADLEY.E J Philadelphia Electric Co 82/07/30. BCHWENCER.A Licensing Branch 2. 2pp 14155 301 24X Ficher 50-352,82/07/30,8208030446.
- 8208110040 Submits schedule of events for 820817-20 environ site visit, ABELSON, H Licensing Branch 3. 82/07/30 LEHR, J., MABNIK, M., PENTECOBT, E NRC No Detailed Affiliation Given 2pp. 14330 303 24X Fiche 50-352,82/07/30,8208110040
- 8208190025 Forwards requests for add1 info needed by pump & valve operability review team & seismic & dynamic qualification review team prior to conducting onsite audits.

 GCHWENCER.A Licensing Branch 2, 82/07/30 BAUER.E G. Philadelphia Electric Co. 28pp 14507.052 24X

 Fiche 30-352.82/07/30.8208190025

- 8208050329 Advises that response to Power Bys Branch questions will be submitted in Oct 1982 via FSAR revision, in response to NRC 820713 ltr BRADLEY, E.J. Philadelphia Electric Co. 82/08/02 BCHWENCER, A. Licensing Branch 2 2pp 14219 361 24X Fiche 50-352, 82/08/02, 8208050329
- 8208090439 Informs that util will respond in Oct 1982 by FSAR revision to questions from Geosciences Branch transmitted in NRC 820716 ltr
 BRADLEY.E J Philadelphia Electric Co 82/08/02 SCHMENCER.A Licensing Branch 2 2pp 14218 009 24X Fiche 50-352,82/08/02,8208050439
- 820B03016B Advises that response to NRC 820708 ltr re adequacy of GE Mark III containment design will be submitted by 820930 KEMPER, J B Philadelphia Electric Co 82/08/03 TEDESCO, R L Assistant Director for Licensing 1p 14160 10B 24X Fiche 50-352, 82/08/03, 820803016B
- 820B100122 Advises that util will respond to Biting Analysis Branch 820715 request for addl info via FBAR revision in Oct 1982 BRADLEY,E J Philadelphia Electric Co 82/08/05 SCHWENCER,A Licensing Branch 2 2pp. 14298 020 24X Fiche 50-352,82/08/05, 820B100122
- 820B1002B6 Notifies that response to Structural Engineering Branch request for addl info transmitted w/A Schwanzer 820715 ltr will be submitted via design assessment rept revision in Sept 1982
 8RADLEY.E J Philadelphia Electric Co 82/08/06 SCHWENCER.A Licensing Branch 2 2pp 14294 354 24X Fiche 50-352,82/08/06,820B1002B6
- GROBITO405 Confirms NRC 820B17-20 environ site visit Approx 15 persons from NRC & 10 persons from state & local govts expected to participate BCHWENCER, A Licensing Branch & 82/08/06 BAUER, E 0, Philadelphia Electric Co 4pp 14372 335 24X Fiche 50-352, 82/08/06, 8208170405
- 8208230129 Notification of B20818 public meeting in Pottstown, PA to allow individuals to express views re environ impact of facility
 ARELSON, H Licensing Branch 2 82/08/06 SCHWENCER, A Licensing Branch 2 4pp 14517 350, 24% Fiche 50-382, 82/08/06, 8208230129.
- 8208240469 Notification of B20818 meeting w/util in Pottstaun.PA to discuss licensee responses to draft environ questions ABELBON.H Licensing Branch 2 82/08/06 9CHMENCER.A Licensing Branch 2 4pp 14544 165 24X Fiche 50-352
- 820B090174 Ceneric Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements by 1ist encl EISENHUT. D Q Division of Licensing 82/08/07 Consplidated Edison Co of New York 19, 14356-332 24X Fiche 50-000, 82/08/07, 8208070174
- 8208240062 Requests add1 info re auxiliary sys based on review of FSAR, Scheduls for response requested within 7 days SCHWENCER.A Licensing Branch 2 82/08/09 BAVER, E 0 Philadelphia Electric Co. 3pp. 14548:158 24X Fiche: 50-352, 82/08/09.8208240062
- 8208260135 Informs of desire to schedule early info meeting between util & Licensee Qualifications Branch during wk of 820907 to discuss corporate & plant mpt structure staffing & training plans List of agenda items encl.

 8CHWENCER.A. Licensing Branch 2 82/08/09. BAUER.E. 0 Philadelphia Electric Go. 4pp 14574 298 24X Fiche 50-352, 82/08/09,8208260135
- 8208250004 Forwards request for add1 info needed to review probabilistic risk assessment.Revision 4
 8CHWENGER.A Licensing Branch 2. 82/08/10. BAUER.E Q
 Philadelphia Electric Co. 1ipp 14559.211. 24X
 Fiche.50-352.82/08/10.8208250004.
- 8208260477 Forwards request for add] info re noise associated w/ operation & const of Point Pleasant pumphouse & related structures
 8CHWENGER.A. Licensing Branch 2. 82/08/11 BAVER.E Q. Philadelphia Electric Co. 5pp 14574 350. 24X
 Fiche.50-352,82/08/11.8208260477

- B208180036 Ack receipt of NRC B20804 ltr re const impacts of Point Pleasant const activities planned by Philadelphia Electric Co in connection w/facilities Urges start of proceeding or referral to ALSB SUGARMAN, R J Sugarman, R J 82/08/13 DENTON, H R Defice of Nuclear Reactor Regulation, Director 3pp 14379 183 24X Fiche 50-352, 82/08/13, 82/08/80036
- 8208200077 Advises that FSAR will be revised to reflect code & addenda actually used to design, fabricate & test MSIVs, per 750715 & 1118 ltrs
 KEMPER, J & Philadelphia Electric Co 82/08/13 DENTON, H R
 Office of Nuclear Reactor Regulation. Director 2pp 14392 217
 24% Fiche 50-392,82/08/13,8208200077
- 8208240222 Responds to Environ Engineering Accident Evaluation & Hydrologic & Geotechnical Engineering Branches 820811 request for info Util util respond to questions via environ rept revision in Oct. 1982 BRADLEY, E. J. Philadelphia Electric Co. 82/08/20 SCHMENCER, A. Licensing Branch 2. 2pp. 14519-097 24X Fiche 50-352,82/08/20,8208240222
- --8208240226 Responds to GA Branch 820713 request for info Util Will respond to questions via FBAR revision in Dec.1982
 BRADLEY.E J Philadelphia Electric Co 82/08/20 SCHWENCER, A Licensing Branch 2 2pp 14517 077 24X Fiche 50-352,82/08/20,8208240822
- 8208310112 Forwards Amend 37 to license application, including Revision 9 to FBAR, Revision 3 to emergency plan & Revision 5 to environ rept OL stage Certificate of Svc enci BRADLEY, £ J Philadelphia Electric Co 82/08/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 14690 091 24% Fiche 50-352, 82/08/30, 8208310112
- --8208310136 Amend 37 to license application, changing FBAR to respond to NRC 820707 itr & changing emergency plan to respond to NRC 820706 itr BAUER, E G . BRADLEY, E J Philadelphia Electric Co 82/08/30 4pp 14690 097 24X Fichs 50-352, 82/08/30, 8208310112
- C Utility Environmental Report (ER), amends & correspondence
- 8208030025 Forwards request for addl info on environ rept-OL stage re metaorology SCHMENCER.A Licensing Branch 2 82/07/13 BAUER.E Q Philadelphia Electric Co 7pp 14241 334 24% Ficha 50-332,82/07/13,8208030025
- 8208260122 Forwards requests for add1 info re OL stage environ rept Items will be discussed at 820818 technical meeting in connection w/environ site visit Flanmed response date requested within 7 days from receipt of ltr SCHHENCER, A Licensing Branch 2 82/08/11 BAUER, E 0 Philadelphia Electric Co 11pp 14574 302 24X Fiche, 50-352, 82/08/11, 8208260122
- 1208160065 Forwards environ rept Refs 6 1-57. "Intl Std for Mapping Hethod in Bird Census Work Recommended by Intl Dird Census Committee" & 6 1-58. "Evaluation of Winter Bird Population Studies," per NRC 820623 request
 BRADLEY, Z J Philadelphia Electric Co 82/08/12 BCHWENCER, A Licensing Branch 2 25pp 14342 206 24X Fiche 50-352, 82/08/12, 8208160065
- 208310112 Forwards Amend 37 to license application, including Revision 9 to FBAR. Revision 3 to emergency plan & Revision 5 to environ rept OL stage. Certificate of Svc encl
 BRABLEY, E. J. Philadelphia Electric Co. 82/08/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 6pp 14690-091
 24X Fiche 50-352.82/08/30,8208310112
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 3208030094 Forwards draft SER input for Section 4 4 of FBAR re thermal-hydraulics Input describes Core Performance Branch position & current status of review SCHHENCER.A Licensing Branch 3 82/07/16 BAUER.E.O Philadelphia Electric Co 12pp 14193.352 24X Fiche 30-352.82/07/16.8208030074
- F Security, medical, emergency & fire protection plans
- 8207070390 Forwards Amend 35 to application for DL, consisting of Revision 7 to FBAR, Revision 2 to emergency plan & proprietary version of Vol 3 of "Design Assessment Rept," Rept withheld (ref 100FRZ 740)

 BRADLEY,E J. Philadelphia Electric Co 82/06/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director Sep. 13738 101 24X Fiche: 50-352, 82/06/30, 8207070390

- 8208020463 Releases public version of revision to emergency plan FELTON,J M Division of Rules and Records 82/07/14 Document Management Branch 1p 14179 [91 24X Fiche 50-352, 82/07/14, 8208020463
- --8208020464 Forwards public version of Revision 2 to emergency plan, Revision 7 of FSAR & Vol 3 of design assessment rept W/o FSAR revision & design assessment rept BRADLEY,E J Philadelphia Electric Co 82/06/30 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 14179 192 24X Fiche 30-352, 82/07/14,8208020463
- --8208020465 Public version of Revision 2 to emergency plan * Philadelphia Electric Co 82/06/30 245pp 14179 194 24X Fiche 50-352,82/07/14,8208020463
- 8208050035 Forwards request for add1 info re fire protection, including request to compare fire protection program w/NUREG-0800 guidelines

 65HkENCER, A Licensing Branch 2 82/07/28 BAUER, E 0
 Phitadelphia Electric Co 7pp 14280 022 24X
 Fiche 50-352, 82/07/28, 8208050035
- 8208310112 Forwards Amend 37 to license application, including Revision 9 to FBAR.Revision 3 to emergency plan & Revision 5 to environ rept OL stage Certificate of Svc encl BRADLEY.E J Philadelphia Electric Co 82/08/30 DENTON.H R Office of Nuclear Reactor Regulation. Director 6pp 14690 091 24% Fiche 30-352,82/08/30,8208310112
- @ Adjudicatory correspondence
- 8208020240 Advises that, per discussion w/Del-Aware counsel, revised notice of deposition is to be served MODODON, A P Hearing Branch 2 82/07/30 BRENNER, L, MORRIS, P A, COLE, R F Atomic Bafety and Licensing Board Panel 2pp 14152 05: 24X Fiche 50-352, 82/07/30, 8208020240
- 8208030368 Confirms arrangements for deposing listed witnesses on contentions re water issues CONNER,T B Conner & Metterhahn CONNER,T B Philadelphia Electric CO. 62/07/30 LEWIS,G H Hearing Dranch 4 SUGARMAN,R J. Sugarman, R J ip 14157 106 24X Fiche 50-352,82/07/30,8208030368
- 8208040021 Forwards matl from Bhoreham proceeding containing discussion to analysis of question of potential conflict of interest by Science Applications. Inc LENIS.8 H Hearing Branch 2 82/08/02 DRENNER, L. MORRIS.P.A. COLE.R.F. Atomic Safety and Licensing Board Panel 2pp 14189 157 24X Fiche 50-352,82/08/02.8208040021
- 8208050095 Advises that NRC employees JC Lehr, MT Masnik, BJ Richter & RO Wescott will be available for depositions in Bathesda, MD on 820810-11
 MDD0D0N, A P Hearing Branch 2 82/08/03 CONNER, T B Conner & Wetterbahn SUOARMAN, R J Sugarman, R J 1p 14213 230 24X
 Fiche 50-352, 82/08/03, 8208050055
- B208110193 Applicantion for issuance of subpoenas to listed persons Certificate of Bvc encl Related correspondence SUGARMAN,R J Del-Aware Unlimited, Inc BUGARMAN,R J Sugarman, R J 82/08/03 Atomic Gafety and Licensing Board Panel, 7pp 14313 333 24X Fiche 50-352,82/08/03,8208110193
- 8208050083 Response to interropatories & request for production of documents Certificate of Svc encl HODODON, A P. CHAN, E I Hearing Branch 2 82/08/04 Del-Award Unlimited, Inc. Spp. 14213 198 24X Fiche 50-352,82/08/04, 8208050083
- 8208120106 Answer opposing Friends of the Earth of DE Valley 820707 submittal of contention based on new info Commission expressly precluded such contentions in recent policy statement Contention filled inexcusably late WETTERHAHN.H J. Philadelphia Electric Co. WETTERHAHN.H J. Conner & Wetterhahn 82/08/04 Atomic Safety and Licensing Board Panel Jpp 14317 164 24X Fiche 50-352,82/08/04,8208120106
- 820B130217 Ack receipt of petition for suspension or revocation of CPs, per 10CFR2, 202 & 2 206(a), on behalf of Del-Aware Unlimited Final decision on petition will be made prior to const commencement FR notice encl
 DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
 82/08/04 8U0ARMAN.R.J Sugarman, R J 1p 14340 217 24X
 Fichs 50-352,82/08/04,8208/30217

- --8208130221 Notice of receipt of RJ Sugarman 820702 petition on behalf of Del-Aware Unlimited requesting suspension or revocation of CPs issued to Philadelphia Electric Co pending submission of plans for acceptable water supply sys DENTON.HR Office of Nuclear Reactor Regulation, Director 82/08/04 Spp 14340 220 24% Fiche 50-352.82/08/04.8208130217
- 8208110185 Motion to compel applicant answers to listed interrogatories re const of pumping stations in DE River Info may lead to relevant evidence Related documentation encl Related relevant evicence necession correspondence SUGARMAN,R J Bu SUGARMAN,R J Bu R J B2/08/08 Atomic Safety and Licensing Board Panel 14314 091 24% Fiche 50-352,82/08/08,8208110185 Sugarman,
- --B2081101B9 Application for reconsideration of ASLB 820714 order Decision should be reversed to hold that federal member of DE River Basin Commission did not finally concur in disposition of diversion Certificate of Bvc encl SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman, R J 82/08/08 Atomic Safety and Licensing Board Panel 11pp 14314 121 24X Fiche 50-352,82/08/08,8208110185
- 8208110181 Amend to 820803 application for issuance of subpoenas, changing date of deposition for listed persons Related correspondence SUQARMAN,R J Del-Aware Unlimited, Inc SUQARMAN,R J Su R J B2/08/09 Atomic Safety and Licensing Board Panel 14314 132 24X Fiche 50-352,82/08/09,8208110181 Sugarman,
- --B208110184 Notice of OM Hansler 820817 deposition in Philadelphia.PA re DE River flow.Point Pleasant intake & likely effects of proposed mgt plan on DE River on intake flows Related espondance espondance RMAN,R J Bel-Aware Unlimited, Inc. SUGARMAN,R J Buga 82/08/09 2pp 14314 135 24X Fiche 50-352,82/08/09,
- --8208110186 Application for issuance of subpoena to CM Hansler Certificate of Byc encl Related correspondence
 BUOARMAN.R J Del-Aware Unlimited, Inc BUOARMAN,R J Sugarman,
 R J 82/08/09 Atomic Safety and Licensing Board Panel App
 14314 137 24X Fiche 50-352,82/08/09.8208110181.
- 8208120115 Forwards applicant answers to Friends of the Earth of DE Valley 820707 proposed new contentions & revised Page 16 to applicant objections to interrogatories & request for production of documents Related correspondence WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 82/08/07 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 14327 023 24X Fiche 50-352,82/08/07,8208120115
- --8208120118 Corrected Page 16 to applicant objections to interrogatories & request for production of documents.correcting inadvertent transposition of text from another page
 * Philadelphia Electric Co. * Conner & Wetterhahn 82/07/27
 Friends of the Earth 1p 14327 028, 24X Fiche 50-352,82/08/09, Friends of the Earth 1p 8208120115
- 8208120121 Answer opposing Friends of the Earth of DE Valley 820707 proposed 10 new contentions he FSAR analysis of potential hazards from offsite explosions & releases of toxic fumes Contentions filed late & w/o basis Certificate of Svc encl WETTERHAHN.M J Philadelphia Electric Co METTERHAHN.M J Conne Wetterhahn 82/08/07 Atomic Safety and Liconsing Board Panel 11pp 14327 034 24% Fiche 50-352,82/08/09,8208120121.
- 820B120101 Opposition to Del-Aware Unlimited, Inc 820809 application for issuance of subpoenas to GM Hansler, G Pence & W Marazzo Application to subpoena GM Hansler inexcusably late G Pence & W Marazzo testimony irrelevant Certificate of Svc encl CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 82/08/10 Atomic Safety and Licensing Board Panel 10pp 14327 154 24X Fichs 50-352,82/08/10,8208120101
- 8208130157 Suppl to 820809 motion for order compelling applicant to respond to interrogatories Info requested in Interrogatory I(d),(e) & (f) relevant to admitted issues Certificate of SUCARMAN, R. J BUGARMAN, R J. Sugarman, Del-Aware Unlimited, Inc R.J 82/08/10 Atomic Safety and Licensing Board Fanel 14338 095 24X Fichs 50-352, 82/08/10, 8208130157.
- B20B170286 Forwards motion on behalf of GM Hansler re application filed by Del-Aware for B20B17 deposition Absence of GM Hansler requires that motion be denied or deposition be rescheduled 820830 GOLDBERG, D J. Delaware River Basin Commission 82/08/10 LAZO, R. Atomic Bafety and Licensing Board Panel 1p 14369, 341, 24X Fiche, 50-352, 82/08/10, 8208170286

- --8208170287 Motion to quash or modify Del-Aware application to take B20817 deposition of GM Hansler No individual can speak for Commission If motion for deposition granted, deposition cannot be scheduled until 820830 GOLDBERG, D J Delaware River Basin Commission 82/08/10 Abamic Safety and Licensing Board Panel 3pp 14369 342 24X Fiche 50-352,82/08/10,8208170286
- 8208130182 Order granting Del-Aware Unlimited Inc request for issuance of subpoenas for G Pence.R Dresnack.T May,W Major, H Brundage H Richmen & GM Hansler Application to subpoena R Flowers & DE River Basin Commissioner Marazzo denied COLE.R F Atomic Safety and Licensing Board Panul 82/08/11 Del-Aware Unlimited, Inc. 3pp. 14338 289 24% Fiche 50-352.82/08/11,8208130182
- 8208160066 Answer in apposition to Del-Awars Unlimited. Inc 820721 motion to compel answers to interrogatories Info requested beyond scope of three admitted contontions W/Certificate of Seyand scope of three aumittee Continuities W/Sertificate O. Svc Related correspondence RADER,R M Philadelphia Electric Co RADER,R M Conner & Wetterhahn 82/08/12 Atomic Safety and Licensing Board Panel 74pp 14342 132 24X Fiche 50-352,82/08/12,8208160066
- 8208240361 Comments taking exception to NRC 820727 denial of Friends of the Earth of DE Valley amended contention re fear & psychological stress caused by sight of reactor plume Post-traumatic anxiety generic H/Certificate of Svc ROMANO,F R Romano,F 82/08/12 Atomic Safety and Licensing 12 Atomic Safety and Licensing 24X Fiche, 50-352, 82/08/12, 8208240361. ROMAND, F.R. Romano, F. 82/08/1 Board Panel 2pp 14520 151
- 8208180110 Order quashing 0 Hansler 820817 deposition COLE, R.F. Atomic Safety and Licensing Board Panel 82/08/16 14379 190 24% Fiche 50-352, 82/08/16, 8208180110
- 8208240236 Response in opposition to Del-Aware Unlimited. Inc 820809 request for ABLI to reconsider 820714 memorandum & order refederal representative concurrence in decision on water allocation Motion untimely Certificate of 8vc encl CONNER. T B Philadelphia Electric Co CONNER. T D Conner & Wetterhahn. 82708/19 Atomic Safety and Licensing Board Panel 45pp. 14321 167 24X Fiche 50-352.82/08/19.8208240236
- 8208250322 Forwards responses to Del-Aware interrogatories Highed verification page to be transmitted later CONNER.T B Conner & Wetterhahn CONNER.T B Philadelphia Electric Co 82/08/20 BRENNER.L . COLLE.R F . MORRIB.P A Atomic Safety and Licensing Board Panel. 1p 14540 222 24X Fiche 50-352.82/08/20.
- -8208250326 Responses to interrogatories Certificate of Syc encl. BOYER, V B Philadelphia Electric Co 82/08/20 Del-Aware Unlimited, Inc 32pp 14540 223 24X Fiche 50-352.82/08/20, 8208250322
- 8208270432 Response to applicant answer to motion to compel answer to interrogatories. Applicant now admits availability of max flow at any river flow Thus, interrogatories re river flow below 3,000 cubic ft/s relevant Certificate of 8vc encl SUGARMAN, R J Del-Aware Unlimited, Inc. SUGARMAN, R J Bugarman, R J 82/03/20 Atomic Safety and Licensing Board Panel 23pp 14566 056 24X Fichs 50-352,82/08/20,8208270432
- 8208270489 Answers to discovery requests Related correspondence SUGARMAN.R J. Del-Aware Unlimited. Inc. SUGARMAN.R J. Sugar R J 82/08/20 Office of the Executive Legal Director. 1: 14564 031 24% Fiche 50-352.82/08/20.8208270489. Bugarman.
- 8208270500 Answers to interrogatories & request for production of documents Certificate of Svc encl 8UGARMAN.R J Del-Aware Unlimited, Inc BUGARMAN.R J Bugarman, R J 82/08/20 Philadelphia Electric Co 10pp 14564.060 & Fiche 50-352,82/08/20,8208270500
- 8208250258 Notice of 821004-08 evidentiary hearing in Norristown.PA re supplementary cooling water sys issues advanced by Del-Aware Unlimited.Inc
 - RENNER, L Atomic Bafety and Licensing Board Panel 82/09/23 2pp. 14543 008 24X Fichs 50-352,82/08/23,8208250258.
- 8208250361 Memorandum & order establishing schedule for filings retestimony on supplementary cooling water contentions.

 BRENNER, L Atomic Sefety and Licensing Board Panel. 82/08/23 Spp.

 14540 204 24X Fiche 50-352, 82/08/23, 8208280361
- 8208270447 Requests investigation of possible conflict of interest reutil use of results obtained by Radiation Mgt Corp reradiological &/or chemical analysis performed for util Corp partially owned by util ROMAND.FR Romano.F 82/08/23 BRENNER.L. COLE.R.F., MORRIS.P.A. Atomic Bafety and Licensing Board Panel 1p. 14563-262 24% Ficher 50-352, 82/08/23, 8208270449.

- 8208270409 Order ruling on Del-Aware 820809 motion to compel applicant answers to interrogatories Motion denied as to Interrogatories 5 & 11 & granted as to remainder Answers due control.
- 8208270438 Forwards executed copy of verification accompanying applicant response to Del-Aware Unlimited, Inc.
 interrogatories, per 820820 | tr Enci should replace previous version Related correspondence
 CONNER, T B Conner & Metterhahn
 CO 82708/24 REENER, L. COLE, R F. MORRIS, P A Atomic Safety and Licensing Board Panel 1p 14565 361 24X Fiche 50-352,82/08/24. Licensing Board Panel
- 2082/0442 Verification of applicant responses to Del-Aware Unic interrogatories EUYERV S Philadelphia Electric Co 82/08/20 Del-Awan Unlimited, Inc 1p 14565-362 24X Fiche 50-352,82/08/24,8208270438 -- 9208270442 Verification of applicant responses to Del-Aware Unlimited,
- 8208310061 Response opposing Del-Aware Unlimited. Inc 820808 application consistential No support a visits for conclusion that for reconsideration No support exists for conclusion that EIS would go beyond environ impacts associated w/operation CH4NNE I Hearing Branch 3 82/08/27 Atomic Safety ar Licensing Board Panel 10pp 14690 014 24X Fiche 50-352 8208310061. 32/08/27 Atomic Safety and 14690 014 24% Fichs 50-352,82/08/27.

H Concret correspondence

- 8208270501 Excoriates NRC, federal govt, utils & capitalism for burdening society w/nuclear energy & weaponry Bupports H Rickovers warcry of no nukes.

 ALKER, P Affiliation Unknown. 82/08/20 Office of Nuclear Reactor Regulation. Director 3pp 14564 057 24X Fiche: 50-352, 82/08/20, 8208270501
 - >8310372 Opposes licensing of facility due to expense to rate-payers proximity of site to large population ctr

 WKES.O Affiliation Unknown 82/08/27 Office of Nuclear leactor Regulation, Director p 14692 067 24X

 ·icha: 50-352, 82/08/27, 8208310372

Utility Final Bafety Analysis Report (FBAR) & amends

- PO70390 Forwards Amend 35 to application for DL, consisting of levision 7 to FSAR.Revision 2 to emergency plan & reprietary version of Vol 3 of "Design Assessment Rept" lept withheld (ref 100FRZ 790)

 RADLEY.E J Philadelphia Electric Co 82/06/30 DENTON, H R leftice of Nuclear Reactor Regulation. Director App 13738 101

 14X Fichs. 50-352, 82/06/30, 8207070390
- 1207070401 Amend 35 to application for CL. consisting of Revision 7 to FSAR, Revision 2 to emergency plan & proprietary version of Vol 3 of "Design Assessment Rept" BOYER, VB Philadelphia Electric Co 82/06/25. 7pp 13738 108 24% Fiche 50-352, 82/06/30, 8207070390
- 8207070406 Revision 7 to FSAR.

 * Philadelphia Electric Co 82/06/30 350pp 13738 115 24X
 Fiche: 50-352, 82/06/30, 8207070390
- DB310112 Forwards Amend 37 to license application, including Revision 7 to FBAR, Revision 3 to emergency plan & Revision 5 to environ rept DL stage. Certificate of Bvc encl.

 3RADLEY, E. J. Philadelphia Electric Co. 82/08/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. App. 14690 071.

 24X Fiche: 50-352, 82/08/30, 8208310112

Inspection reports, IE Bulletins & correspondence

- 204210393 IE Info Notice 82-23, "Hein Steam Isolation Valve (M9JV) Leakage," Svc list encl JORDAN,E.L. Division of Engineering & Guality Assurance 82/07/1 Consolidated Edison Co. of New York, 87pp. 14356-274 24X Fiche: 50-000, 82/07/16, 8204210393, 82/07/16
- "204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Syc list encl JORDAN E L Division of Engineering & Guality Assurance 82/07/2 Consolidated Edison Co. of New York. 112pp 14381:001. 24X Fiche: 50-000, 82/07/20, 8204210394 Assurance 82/07/20, 14381:001, 24X

- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks " Syc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 27 24% Fichs 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPC1 Turbine Exhaust Check Valve Failures " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp 14194 321 24X Fiche 50-000 82/07/22,8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Victority of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of, New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Hestinghouse PMRs " Svc list encl JURDAN, E.L. Division of Engineering & Quality Assurance 82/07/25 Consolidated Edison Co. of New York 127pp 14194 120 24X Assurance 82/07/23 14194 120 24X Fiche 50-000, 82/07/23, 9204210402
- 9208100024 Forwards IE Insp Repts 50-352/82-09 & 50-353/82-07 on 820524-28 & 0402-04 No noncompliance moted MARTIN.T T Division of Engineering & Technical Programs 82, KEMPER, J 8. Philadelphia Electric Co 2pp 14296 312 24X Fiche 50-352,82/07/23,8208100024 82/07/23,
- --BROBIO0032 IE Insp Repts 50-352/B2-09 & 50-353/B2-07 on B20526-28 & O602-04 No noncompliance noted Hajor areas inspected spray pond & electrical cable installation VARELA; A A PADLING.R J. RICHARDS.S A Region I. Office of Director B2/07/I3 App. 14296.314 24X Fiche 50-352.82/07/23, B208100026.
- 8204210403 IE Info Notice 92-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants " Syc list enci JORDAN,E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 12ipp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Hork in Fuel Storage Pool." Svc list encl JORDAN,E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357-144 24X Ficha 50-000,82/07/28,8204210405.
- 8204210407 IE Info Notice 82-27, "Fubl Rod Degradation Resulting From Baffle Water-Jet Impingament." Svc list encl JURDAN,E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co. of New York 117pp 14388-201 24X Fiche. 50-000, 82/08/05, 82/04210407.
- 8208120069 Ack receipt of 820719 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-352/81-17 & 50-353/81-15 00-353/81-15 STAROSTECKI,R Division of Project & Resident Programs 82, KEMPER,J B. Philadelphia Electric Co 1p 14327 165 24X Fiche: 50-352, 82/08/06, 8208120069
- --8208120073 Supple B2052B response to NRC 820204 ltr re violations noted in IE Insp Repta 50-332/81-17 % 50-333/81-15 TX Pipe mfg pipe spools w/min wall thickness violations discovered Complete insp of G-Iisted spools will be finished by 821230, KEMPER.J 8 Philadelphia Electric Co. 82/07/19, HAYNES.R C Region I, Office of Directon. 2pp. 14327:166 24X Fiche 50-352,82/08/06,8208120069
- 8 Reportable occurrences, LERs & related correspondence
- 8208130319 Final Bignificant Deficiency 63 re Colt Industries emergency diesel generator melfunctioning thermostatic valve Generators will be corrected per vendor instructions Also reported per Part 21 KEMPER, J. S Philadelphia Electric Co 82/08/03 HAYNES, R. Region 1, Office of Director 4pp. 14336, 343 24X Fiche: 50-352, 82/08/03, 8208130319 HAYNES, R. C.

U Congressional/Executive Correspondence

8208040488 Responds to B Shaneman 820525 itr re allegations of const deficiencies Faults not capable & methods used to repair fracture zones acceptable Allegations of improperly mixed & placed concrete investigated in previous insprepts.

DENTON.H R Office of Nuclear Reactor Regulation, Director 82/07/08. GREENLEAF.B.J. Pennsylvania. State of 9pp 14220-312 24% Fiche: 50-352, 82/07/08, 8208040488

- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8208090023 Requests addl info identified in App E of NUREQ-0588 re qualification of safety-related electrical equipment FSAR Section 3 ii must include qualification of equipment in harsh environ Scheduled response date requested in 7 days SCHWENCER.A Licensing Branch 2 82/06/17 BAVER.E 0 Philadelphia Electric Co 3pp 14283 324 24X Fiche 50-352,82/06/17,8208090023
- 8207070390 Forwards Amend 35 to application for IIL, consisting of Revision 7 to FSAR, Revision 2 to emergency plan & proprietary version of vol 3 of "Design Assessment Rept" Rept withheld (ref 10CFR2 790)
 RRADLEY, E. J. Philadelphia Electric Co. 82/06/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director App. 13738 10 24% Fiche 50-352,82/06/30,8207070390
- --8207070401 Amend 35 to application for CL. consisting of Revision 7 to FSAR.Revision 2 to emergency plan & proprietary version of Vol 3 of "Design Assessment Rept"
 BOYER,V S Philadelphia Electric Co B2/06/25 7pp, 13738 108
 24% Fiche 50-352,82/06/30,8207070390
- B20B120003 Bummary of B20514 mesting w/util in King of Prussia,PA re Revision 3 to probabilistic risk assessment. Viewgraphs encl ABELEON,H Licensing Branch 2 B2/07/06 Licensing Branch 2 97pp 14332 186 24X Fiche 50-352,82/07/06,820B120003
- 8208040427 Requests add1 info re proposed schedule for program concerning adaquacy of design margins of Mark I & II containment sys Response within 14 days requested. TEDESCO.R L Assistant Director for Licensing 82/07/08 BAUER.E G Philadelphia Electric Co 3pp 14220 173 24X Fiche 50-352:82/07/08.8208040427
- 8208060088 Forwards Reactor Sys Branch request for add1 info re FBAR Section 15 concerning accident analyses Scheduled response data requested within 7 working days from receipt of ltr W/o encl SCHWENCER, A Licensing Branch 2 82/07/08 BAUER, E. G. Philadelphia Elactric Co 2pp 14283 211 24X Fiche 80-352,82/07/08,8208060088
- B2080300Bi Forwards request for add1 info necessary to complete review of FBAR
 SCHWENCER, A Licensing Branch & B2/07/09 BAUER, E Q
 Philadelphia Electric Co 5pp 14200 318 24X
 Fiche 50-352, 82/07/09, 8208030081
- 8208030087 Requests current description of diversion plan Description should identify changes in design location const & operation made since issuance of CP & should include assessment of incremental impacts or reductions in impacts SCHWENCER. A Licensing Branch 2 82/07/09 BAUER. E O Philadelphia Electric Co 2pp 14182-358 24X Fichs 50-352,82/07/09,8208030087
- B20B030030 Forwards request for add1 info re meteorology & accident analysis to continue FBAR review SCHHENGER.A Licensing Branch 2 82/07/13 BAUER.E.O Philadelphia Electric Co 10pp. 1420B-353 24X Fiche 50-352.B2/07/13,B20B030030.
- 8208030041 Forwards request for add1 geotechnical info re foundation & soils to continue FSAR review SCHWENCER.A Licensing Branch 2 82/07/13 BAUER.E.O Philadelphia Electric Co 4pp 1420B 321 24X Fiche 50-352, 82/07/13,8208030041
- 8208050039 Forwards request for add1 info re effluent treatment sys Schedule for response due in 7 days SCHMENGER.A Licensing Branch 2 82/07/28 BAUER.E 0, Philadelphia Electric Co 15pp. 14243 174 24X Fiche.50-352,82/07/28,8208050039
- 8208030446 Informs that util will respond to 820717 request for addl info from Accident Evaluation Branch via FBAR revision in Sept 1982 BRADLEY,E J Philadelphia Electric Co 82/07/30 8CHWENCER,A Licensing Branch 2 2pp 14155 299 24X Fiche 50-352,82/07/30, 8208030446.
- --8208030451 Informs that response to 820721 request for add1 info from Accident Evaluation Branch will be provided in environ rept revision in Sept 1982
 BRADLEY, E. J. Philadelphia Electric Co. 82/07/30 BCHWENGER, A. Licensing Branch 2 2pp 14155, 301. 24X Fiche 50-352, 82/07/30, 8208030446

- 8208110040 Submits schedule of events for 820817-20 environ site visit ABELSON.H Licensing Branch 3 82/07/30 LERR,J. MARNIK,M., PENTECOST.E NRC - No Detailed Affiliation Given 2pp 14330,303 24X Fiche 30-352,82/07/30,82081
- 8208190025 Forwards requests for add1 info needed by pump & valve operability review team & seismic & dynamic qualification review team prior to conducting onsite audits SCHWENCER.A Licensing Branch 2 82/07/30 BAVER.E Q Philadelphia Electric Co 28pp 14507 052 24X Fiche 50-352.82/07/30.8208190025
- 8208030329 Advises that response to Power Sys Branch questions will be submitted in Oct 1982 via FSAR revision, in response to NRC 820713 ltr BRADLEY, E. J. Philadelphia Electric Co. 82/08/02 8CHHENCER, A Licensing Branch 2 2pp 14219 361 24X Fiche 50-352, 82/08/02, 8208030329
- 8208050439 Informs that util will respond in Oct 1982 by FSAR revision to questions from Geosciences Branch transmitted in NRC 820716 ltr
 BRADLEY.E J Philadelphia Electric Co 82/08/02 SCHWENCER.A Licensing Branch 2 2pp 14218 009 24X Fichs 50-352,82/08/02.8208050439
- 8208030168 Advises that response to NRC 820708 ltr re adequacy of QE Mark III containment design will be submitted by 820930 KEMPER, J S Philadelphia Electric Co. 82708703 TEDESCO, R L Assistant Director for Licensing 1p, 14160 108 24X Fiche: 50-352, 82/08/03, 8208030168
- 8208100122 Advises that util will respond to Siting Analysis Branch 820715 request for addl info via FBAR revision in Oct 1992 BRADLEY,E J. Philadelphia Electric Co 82/08/05 SCHWENCER, A Licensing Branch 2 2pp. 14278 020 24X Fiche 50-352, 82/08/05, 8208100122.
- B208100286 Notifies that response to Structural Engineering Stanch request for add1 info transmitted w/A Schwencer 820715 ltr will be submitted via design assessment rept revision in Sept 1982
 BRADLEY, E.J. Philadelphia Electric Co. 82/08/06 SCHWENCER, A Licensing Branch 2, 2pp. 14294, 354 24X Fiche 50-352, 82/08/06, 8208100286
- 9208170405 Confirms NRC 820817-20 environ site visit Approx 15 persons from NRC & 10 persons from state & local govts expected to participate SCHMENCER. A Licensing Branch 2 82/08/06 BAUER. E 0 Philadelphia Electric Co 4pp 14372 335 24% Fiche 50-352,82/08/06,8208170405
- 8208230127 Notification of 820818 public meeting in Pottstown, PA to allow individuals to express views to environ impact of facility
 ABELBON.H Licensing Branch 2 82/08/06 86HWENCER.A Licensing Branch 2 4pp. 14517:350 24X Fiche 50-352,82/08/06,8208230129
 - Branch 2 4pp, 14517:350 24% Fiche 50-352,82/08/04.8208230129
- 8208240469 Notification of 820818 maeting w/util in Pottstown, PA to discuss licensee responses to draft environ quastions.
 ABELSON, H Licensing Branch 2 82/08/06 SCHENCER, A. Licensing Branch 2 4pp 14944, 169 24X Fiche 50-352,82/08/06,8208240469.
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summerizes IOCFR Chapter I requirements & provides alternatives to requirements Bvc list encl EISENHUT,D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip. 14356 332. 24X Fiche: 80-000, 82/08/09, 8208090194.
- 82082400A2 Requests add1 info re auxiliary sys based on review of F8AR Bcheduls for response requested within 7 days 8CHMENCER.A Licensing Branch 2. 82/08/09 BAUER.E Q. Philedelphia Electric Co. 3pp. 14548.158 24X Ficher 50-352,82/08/09.82082400AZ
- 8208260135 Informs of desire to schedule early info meeting between util & Licensee Gusalifications Branch during wk of 820907 to discuss corporate & plant mgt structures staffing & training plans List of agenda items encl.

 93 SCHMENCER.A Licensing Branch 2. 82/08/09 BAUER.E.Q
 Philadeiphia Electric Co 4pp 14574 298 24X
 Fiche. 50-352, 82/08/09, 8208260135.
- B20B230004 Forwards request for add1 info needed to review probabilistic risk assessment, Revision 4.

 SCHMENGER.A. Licensing Branch 2 82/08/10. BAUER, E. O Philadelphia Electric Co. 11pp 14959; 211 24X Fiche. 50-352, 82/08/10, 8208250004

8208260477 Forwards request for addl info re noise associated w/ operation & const of Point Pleasant pumphouse & related structures SCHHENCER, A Licensing Branch 2 82/08/11 BAUER, E 0 Philadelphia Electric Co 5pp 14594 350 24X Fiche 50-352,82/08/11.8208260477

- 8208180036 Ack receipt of NRC 820804 ltr re const impacts of Point Pleasant const activities planned by Philadelphia Electric Co in connection w/accilities Urges start of proceeding or referral to ALSB SUGARMAN, R J Sugarman, R J 82/08/13 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pp 14379 183 24X Fiche: 50-352, 82/08/13, 8208180036
- 8208200077 Advises that FSAR will be revised to reflect code & addenda actually used to design, fabricate & test MSIVs, per 750715 & 1118 ltrs KEMPER. J B Philadelphia Electric Co 82/08/13 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 14392 224% Fiche 50-352,82/08/13,8208200077
- 8208240222 Responds to Environ Engineering Accident Evaluation & EUDZAUZZZ RESponds to Environ Engineering Accident Evaluation & Mydrologic & Geotechnical Engineering Branches 820811 request for info Util Util respond to questions via environ rept revision in Oct, 1982

 BRADLEY, E. J. Philadolphia Electric Co. 82/08/20 SCHWENCER, A. Licensing Branch 2. 2pp. 14517-097 24X Fiche 50-352, 82/08/20, 8208240222
- --8208240226 Responds to QA Branch 820713 request for info Util will respond to questions via FBAR revision in Dec. 1982
 BRADLEY, E J Philadelphia Electric Co 82/08/20 BCHMENCER, A Licensing Branch 2 2pp 14519 079 24X Fiche 50-352.82/08/20, 8208240222
- 8208310112 Forwards Amend 37 to license application, including Revision 208310112 Forwards Amend 37 to license application including Nev 9 to FSAR Revision 3 to emergency plan & Revision 5 to environ rept OL stage Certificate of Svc encl TRADLEY.E J Philadelphia Electric Co 82/08/30 DENTON.H R Jffice of Nuclear Reactor Regulation, Director App 14690 09 24X Fiche 50-352,82/08/30,8208310112 6pp 14690 091
 - 3208310136 Amend 37 to license application, changing FSAR to respond to NRC 820709 ltr & changing emergency plan to respond to NRC NRC 820709 | tr & changing emergency plan to respond to NRC 820704 | tr & changing emergency plan to respond to NRC 820704 | tr BAUER, E G . BRADLEY, E J Philadelphia Electric Co 82/08/30 App. 14690 097. 24X Fiche: 50-352, 82/08/30, 8208310112
 - Utility Environmental Report (ER), amends & correspondence
-)8030025 Forwards request for addl info on environ rept-DL stage 'e meteorology ICHNENCER, A Licensing Branch 2 82/07/13 BAI 'hiladelphia Electric Co 7pp 14241 334. 24X 'iche 50-392,82/07/13,8208030025 BAUER, E Q
-)8240122 Forwards requests for add1 info re OL stage environ rept 'tems will be discussed at 820818 technical meeting in onnection w/environ site visit Planned response date ,equested within 7 days from receipt of 1tr SCHMENCER.A Licensing Branch 2 82/08/11 BAUER,E 0 Philadelphia Electric Co 1ipp 14574 302 24X Fiche 50-352,82/08/11,8208260122
- OBIGOD65 Forwards environ rept Refs 6 1-57, "Intl Btd for Mapping Method in Bird Census Work Recommended by Intl Bird Consus Committee" & 6 1-58, "Evaluation of Winter Bird Population Studies," per NRC 820623 request, BRADLEY, E. J. Philadelphia Electric Co B2/08/12, SCHWENCER, A, Licensing Branch 2 23pp 14342 206 24X Fiche 50-352, 82/08/12, 82020140045
- 208310112 Forwards Amend 37 to license application, including Revision 9 to FSAR, Revision 3 to emergency plan & Revision 5 to environ rept OL stage Certificate of Svc encl
 BRADLEY, E J Philadelphia Electric Co 82/08/30 DENTON, H R
 Defice of Nuclear Reactor Regulation, Director App. 14690 091
 24X Fiche 50-352,82/08/30,8208310112
- * NRC Bafety Evaluation Report (BER), supple & correspondence
- 3208030074 Forwards draft SER input for Section 4 4 of FSAR re thermal-hydraulics Input describes Core Performance Branch position & current status of review SCHHENCER.A Licensing Branch 3 82/07/16 BAUER,E Q Philadelphia Electric Co 12pp 14193:352, 24X Fiche: 50-352, 82/07/16, 8208030074

- F Security, medical, emergency & fire protection plans
- 8207070390 Forwards Amend 33 to application for OL, consisting of Revision 7 to FSAR.Revision 2 to emergency plan & proprietary version of Vol 3 of "Design Assessment Rept "Rept withheld (ref 100FR2 790)

 BRADLEY,E J Philadelphia Electric Co 82/06/30 DENTON,H R Office of Nuclear Reactor Regulation, Director App 13738 10 244 Fiche 50-352,82/06/30,8207070390
- 8208020453 Releases public version of revision to emergency plan FELTON.J M Division of Rules and Records 82/07/14 Document Management Branch 1p 14179 191 24X Fiche 50-352.82/07/14, 8208020463
- --8208020464 Forwards public version of Revision 2 to emergency plan.
 Revision 7 of FGAR & Vol 3 of design assessment rept W/o
 FSAR revision & design assessment rept
 GRADLEY,E J Philadelphia Electric Co 82/06/30 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 2pp 14179 192
 24X Fiche 50-352,82/07/14,8208020463
- --8208020465 Public version of Revision 2 to emergency plan Philadelphia Electric Co 82/06/30 245pp 14179 194 Fichs 50-352,82/07/14.8208020463
- B208060035 Forwards request for add1 info re fire protection, including request to compare fire protection program w/NUREG-0800 guidelines guidelines SCHWENGER, A Licensing Branch 2 82/07/28 BAL Philadelphia Electric Co 7pp 14280 022 24X Fiche 50-332,82/07/28,8208060035
- 8208310112 Forwards Amend 37 to license application, including Revision 9 to FSAR, Revision 3 to emergency plan & Revision 5 to environ rept OL stage Certificate of Bvc encl.

 BRADLEY, E. J. Philadelphia Electric Co. 82/08/30 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 6pp. 14690 091 24X Fiche 80-392, 82/08/30, 82/08310112
- G Adjudicatory correspondence
- 8208020240 Advises that per discussion w/Del-Aware counsel, revised natice of deposition is to be served HODODON A P Hearing Branch 2 82/07/30 BRENNER, L. MORRIS, P.A., COLLE, R.F. Atomic Safety and Licensing Board Panel 2pp 14152-055 24% Fiche 50-352,82/07/30,8208020240
- 8208030368 Confirms arrangements for deposing listed witnesses on CONVERTING A PARAGRAPHICA FOR SEPSING TISTED WITHERSES ON CONTENTION FOR WASTERNAM CONNERT B Philadelphia Electric Co 82/07/30 LEWIS, 8 H Hearing Branch 4 SUSARMAN, R J Bugarman, R J ip 14157 106 24% Fiche 50-352, 82/07/30, 8208030368
- 8208040021 Forwards matl from Shoreham proceeding containing discussion & analysis of question of potential conflict of interest by Science Applications. Inc LEWIS.5 H Hearing Branch 2 82/08/02 BRENNER, L. MORRIB, P.A. COLE, R.F. Atomic Safety and Licensing Board Panel 2pp 14187 157 24X Fichs 50-352,82/08/02,8208040021
- 8208050055 Advises that NRC employees JC Lehr,MT Masnik,BJ Richter & RO Wescott will be available for depositions in Dethesda,MD RO Mescott will be available for depositions in Bethesda, MI on 820810-11
 HODODON A P Hearing Brench 2 82/08/03 CONNER, T B C. Wattarhehn SUGARMAN, R J Sugarman, R J Ip 14213 230 Fiche: 50-352, 82/08/03, 8208050055
- 8208110193 Applicantion for issuance of subposmas to listed persons.

 Certificate of Svc encl Related correspondence
 SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R, J Sugarman,
 R J 82/08/03 Atomic Safety and Licensing Board Panel 7pp
 14313 333 24X Fiche 50-352.82/08/03.8208110193
- 8208090083 Response to interrogatories & request for production of documents Certificate of Syc encl HODODON.A P., CHAN.C I Hearing Branch 2 82/08/04 Dal-Awar Unlimited, Inc 5pp 14213 198 24X Fiche 30-352,82/08/04,8208050083
- 8208120106 Answer opposing Friends of the Earth of DE Valley 820707 submittal of contention based on new info Commission expressly precluded such contentions in recent policy statement Contention filed inexcusably late WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M, J, Conner & Wetterhahn 82/08/04 Atomic Gafety and Licensing Board Panel Spp. 14319 164, 24% Fiche 50-352,82/08/04.8208120106

- 8208130217 Ack receipt of petition for suspension or revocation of CPs, per 10CFR2 202 & 2 206(a), on behalf of Del-Aware Unlimited Final decision on petition will be made prior to const commencement FR notice encl DENTON.H R Office of Nuclear Reactor Regulation, Director B2/08/04 SUOARMAN.R J Sugarman, R J ip 14340 219 24X Fiche 50-352,02/08/04.8208130217
- --B20813022) Nutice of receipt of RJ Sugarman 820702 petition on behalf of Del-Aware Unlimited requesting suspension or revocation of CPs issued to Philadelphia Electric Co pending submission of plans for acceptable water supply sys DENTON, HR Office of Nuclear Reactor Regulation, Director 82/08/04 5pp 14340 220 24X Fiche 50-352,82/08/04,8208130217
- B208110185 Motion to compel applicant answers to listed interrogatories re const of pumping stations in DE River Info may lead to relevant evidence Related documentation encl Related correspondence

 SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Bugarman, R J 82/08/08 Atomic Safety and Licensing Board Panel 30pp

 14314 091 24X Fiche 50-352,82/08/08,8208110185,
- --8208110189 Application for reconsideration of ASLB 820714 order
 Decision should be reversed to hold that federal member of
 DE River Basin Commission and not finally concur in
 disposition of diversion Certificate of Svc sncl
 SUGARRANIR J Dul-Aware Unlimited, Inc SUGARRANIR J Sugarman,
 R J 82/08/08 Atomic Safety and Licensing Board Panel 11pp
 14314 121 24X Fiche 50-352,82/08/08,8208110185
- 8208110181 Amend to 820803 application for issuance of subpoenas, changing date of deposition for listed persons Related correspondence

 8UQARMAN, R J Del-Aware Unlimited, Inc. 8UQARMAN, R J Bugarman,
 R J 82/08/09 Atomic Safety and Licensing Board Panel 3pp
 14314 132 24X Fiche 50-352,82/08/07,8208110181
- --B20Bii01B4 Notice of GM Hansler B20Bi7 deposition in Philadelphia.PA re DE River flow.Point Pleasant intake & likely effects of proposed mgt plan on DE River on intake flows Related correspondence SUGARMAN.R J Del-Aware Unlimited, Inc SUGARMAN.R J. Bugarman, R J 82/08/09 2pp 14314 135 24X Fichs 50-352,82/08/09, 820Bii0181
- --8208110186 Application for issuance of subpoens to OM Hansler Certificate of Svc encl Related correspondence SUGARMAN,R J Del-Aware Unlimited, Inc. SUGARMAN,R J Sugarman, R J 82/08/09 Atomic 8afety and Licensing Board Panel App 14314 137 24X Fiche 50-352,82/08/09,8208110181
- 8208120115 Forwards applicant answers to Friends of the Earth of DE Valley 820707 proposed new contentions & revised Page 16 to applicant objections to interrogatories & request for production of documents Related correspondence HETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 82/09/07 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 14327 023 24X Fiche 50-352,82/08/07,8208120115
- 8208120121 Answer opposing friends of the Earth of DE Valley 820707 proposed 10 new contentions re FSAR analysis of potential hazards from offsite explosions & releases of toxic fumes contentions filed late & w/o basis Cententions for Svc sncl METTERHAHN, M J Philadelphia Electric Co METTERHAHN, M J Conner & Wetterbahn 8,709/07 Atomic Bafety and Licensing Board Panel. 11pp. 14327 034 24% Fiche 50-392,82/08/09,8208120121
- 8208120101 Opposition to Del-Aware Unlimited, Inc B20809 application for issuence of subpoems to OM Hansler. O Pence & W Marairo Application to subpoems OM Hansler inexcusably late Q Pence & W Marairo testimony irrelevant Certificate of Svc encl CONNER. T B Philadelphia Electric Co CONNER. T. B Conner & Uetterhahn 82/08/10 Atomic Safety and Licensing Board Panel 10pp 14327 154 24X Fiche 50-352,82/08/10.8208120101
- 8208130157 Suppl to 820809 motion for order compelling applicant to respond to interrogatories. Info requested in Interrogatory 1(d), (e) & (f) relevant to admitted issues Certificate of Svc encl SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Bugarman, R. J. B2/08/10 Atomic Safety and Licensing Doard Panel. 2pp. 14338 095 24X Fiche SO-352,82/08/10.8208130157

- 8208170286 Ferwards motion on behalf of GM Hansler re application filed by Del-Aware for 820817 deposition Absence of GM Hansler requires that motion be denied or deposition be rescheduled for 820830 GULDBERG, D J Delaware River Basin Commission 82/08/10 LAZD,R Atomic Safety and Licensing Board Panel 1p 14369 341 24X Fiche 50-352,82/08/10.8208170286
- ---9209170287 Motion to quash or modify Del-Aware application to take B20817 deposition of GM Hansler.No individual can speak for Commission If motion for deposition granted deposition cannot be scheduled until 820830 GDLDBERO.D J Delaware River Basin Commission 82/08/10 Atomic Safety and Licensing Board Panel 3pp 14369 342 24% fiche 50-352.82/08/10.8208170286
- 8208130182 Order granting Del-Aware Unlimited. Inc request for issuance of subpoenas for 0 Pence. R Dresnack. T May, W Major, H Brundage. H Richman & GM Hansler Application to subpoena R Flowers & DE River Basin Commissioner Harazzo denied COLE. R F Atomic Safety and Licensing Board Panel 82/08/11 Del-Aware Unlimited. Inc. 3pp 14338 289 24X Fiche 50-352, 82/08/11,8208130182
- 8208160066 Answer in opposition to Del-Aware Unlimited, Inc 820721 motion to compel answers to interrogatories Info requested beyond scope of three admitted contentions W/Certificate of Svc Related correspondence
 RADER, R M Philadelphia Electric Co RADER, R M Conner & Wetterhahn 82/08/12 Atomic Safety and Licensing Board Panel,
 74pp. 14342 132 24X Fiche 50-352,82/08/12,8208160066
- 8208240361 Comments taking exception to NRC 820727 denial of Friends of the Earth of DE Valley amended contention re fear & psychological stress caused by sight of reactor plume Post-traumatic anxiety generic W/Certificate of Svc 80MANO, FR Romano, F 82/08/12 Atomic Safety and Licensing Board Panel 2pp 14520 151 24X Fiche 50-352,82/08/12,8208240361
- 8208240236 Response in opposition to Del-Aware Unlimited, Inc 820809 request for ASLB to reconsider 820714 memorandum & order refederal representative concurrence in decision on water allocation Motion untimely Certificate of Svc encl CONNER. T B Philadelphia Electric Co CONNER. T B Conner & Wetterhahn 82/09/17 Akomic Safety and Licensing Board Panel 45pg 14921.167 24X Fiche 50-332.82/09/19.8208240236
- 8208250322 Forwards responses to Del-Aware interrogatories, Bigned verification page to be transmitted later CONNER, T B Conner & Netterhahn CONNER, T B Philadelphia Electric Co 82/08/20 BRENNER, L., COLE, R F., MORRIS, P A Atomic Safety and Licensing Board Panel 1p 14540 222 24% Fiche 50-352, 82/08/20, 8208250322
- --8208250326 Responses to interrogatories Certificate of Bvc encl BBVER.V 5 Philadelphia Electric Co 82/08/20 Del-Aware Unlimited, Inc 32pp 14540 223 24X Fiche 50-352,82/08/20, 8208250322
- 8208270432 Response to applicant answer to motion to compel answer to interrogatories Applicant now admits availability of max flow at any river flow Thus.interrogatories re river flow below 3.000 cubic ft/s relevant Certificate of Syc anci SUGARMAN, R J. Del-Aware Unlimited, Inc. 8UGARMAN, R J. Bugarman, R J. 82/08/20, Abomic Safety and Licensing Board Panel 23pp 14566,056 24X Fiche 80-352,82/08/20,8208270432
- 8208270489 Answers to discovery requests Related correspondence SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. 82/08/20 Office of the Executive Legal Director 15pp. 14564 031 24X Fiche 50-352,82/08/20,8208270489.
- 8208270500 Answers to interrogatories & request for production of documents Certificate of Svc encl SUGARMAN, R J. Bugarman, R J. B2/08/20 Philadelphia Electric Co 10pp. 14564 060 24X Fiche. 50-352, 82/08/20, 8208270500
- 8208250258 Notice of 821004-08 evidentiary hearing in Norristown, PA re supplementary cooling water sys issues advanced by Del-Aware Unifacted, Inc BRENNER, L Atomic Safety and Licensing Board Panel 82/08/23. 2pp 14543 008 24X Fiche 50-352,82/08/23,8208250258
- 8208280341 Memorandum & order establishing schedule for filings retestimony on supplementary cooling water contentions.

 BRENNER, L. Atomic Bafety and Licensing Board Panel 62/09/23. 5pp 14540:204 24% Fiche 50-352.82/08/23,8208250341

- 8208270447 Requests investigation of possible conflict of interest reutil use of results obtained by Radiation Mgt Corp reradiological &/or chemical analysis performed for util Corp partially owned by util ROMANO, F. R. Romanou F. 82/08/23 BRENNER, L. COLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel 1p. 14565-262-24X Fiche 50-352, 82/08/23,8208270449
- 8208270409 Order ruling on Del-Aware 820809 motion to compel applicant answers to interrogatories Motion denied as to Interrogatories 5 & 11 & granted as to remainder Answers due 820901

 BRENNER: L. Atomic Safety and Licensing Board Panel 82/08/24

 Del-Aware Unlimited. Inc. 8pp. 14565 218 24X

 Fiche 50-352, 82/08/24, 8208270409
- 8208270438 Forwards executed copy of verification accompanying applicant response to Del-Aware Unlimited, Inc interrogatories, per 820820 itr Encl should replace previous version Related correspondence CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 82/08/24 BRENNER, L . COLE, R F . MORRIS, P A Atomic Safety and Licensing Board Panel 1p 14565 361 24X Fiche 50-352,82/08/24, 8208270438
- --8208270442 Verification of applicant responses to Del-Aware Unlimited, Inc. interrogatories
 BOYER.V.S. Philadelphia Electric Co. 82/08/20 Del-Aware
 Unlimited. Inc. ip. 14565-362 24x Fiche 50-352,82/08/24.
 8208270438
- 8208310061 Response opposing Del-Aware Unlimited, Inc 920808 application for reconsideration. No support exists for conclusion that EIS would go beyond environ impacts associated w/operation Certificate of Svc encl
 CHAN.E.I. Hearing Branch 3 82/08/27 Atomic Safety and
 Licensing Board Panel 10pp 14690-014 24X Fiche 50-352,82/08/27,8208310061.

tility Final Safety Analysis Report (FSAR) & amends

70370 Forwards Amend 35 to application for QL consisting of ision 7 to FBAR.Revision 2 to emergency plan & prietary version of Vol 3 of "Design Assessment Rept" to withheld (ref 10CFR2 770)

ADLEV.E J Philadelphia Electric Co 82/06/30 DENTON, H R fice of Nuclear Reactor Regulation, Director 6pp 13738 1014

K Fiche 50-352,82/06/30,8207070390

207070406 Revision 7 to FSAR * Philadelphia Electric Co 82/06/30 350pp 13738:115 24X Fiche: 50-352,82/06/30,8207070390.

C 310112 Forwards Amend 37 to license application, including Revision 5 to FBAR. Revision 3 to emergency plan & Revision 3 to swirgon rest DL stage Certificate of Svc encl E (ADLEY.E J Philadelphia Electric Co 82/08/30 DENTON.H R 'fice of Nuclear Reactor Regulation, Director App 14690 091 K Fiche. 50-352.82/08/20.8208310112

nspection reports. IE Bulletins & correspondence

4210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) eakage," Svc list enci.

URDAN.E L. Division of Engineering & Quality Assurance 82/07/16
Consolidated Edison Co. of New York 8799 14386 274 24% iche. 80-000, 82/07/16, 8204210393

4210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon radual Loss of Air Pressure " Syc list enc!

JRDAN.E.L. Division of Engineering & Quality Assurance 82/07/20, Consolidate Edison Co. of New York 112pp. 14391 001 24X iche: 50-000, 82/07/20, 8204210396

1210397 IE Info Notice 82-24, "Water Leaking From V Hexafluoride /erpacks." Syc list entl 188.L.I. Division of Fuel Facilities, Materials & Bafeguards, 2/07/20. Conselidated Edison Co. of New York 7ipp. 14357 276 IX Fiche 50-000, 82/07/20, 9204210397

1210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check live Failures," Syc list encl RDAN.E.L. Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York 112pp. 14194:321. 24X che 50-000, 82/07/22, 8204210398.

10405 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in nity of Drained & Open RCS." Svc list encl
1M.E.L. Division of Engineering & Quality Assurance. 82/07/23
180164846 Edison Co of New York. 122pp 14380.115. 24X
150-000.82/07/23.8204210401.

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs " Svc list enci JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23,8204210402
- 820B100026 Forwards IE Insp Repts 50-352/82-09 & 50-353/82-07 on 820526-28 & 0602-04 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/07/23 KEMPER.J S Philadelphia Electric Co 2pp 14276 312 24X Fiche 50-352, 82/07/23,8208100026
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Gleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 30-000, 82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool," Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingsment" Svc list encl JORDAN: EL Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 820B120069 Ack receipt of 820719 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/B1-17 & 50-352/81-15 STAROSTECKI.R Division of Project & Resident Programs 82/08/06 KEMPER.J S Philadelphia Electric Co ip 14327 165 24X Fiche 30-352.82/08/06.820B120069
- --B208120073 Suppls 62052B response to NRC 820204 ltr re violations noted in IE Insp Repts 50-352/81-17 & 50-353/81-15 TX Pipe mfg pipe spools w/min wall thickness violations discovered Complete insp of G-listed spools will be finished by 621230 KEMPER, U S Philadelphia Electric Co 82/07/19 HAYNES, R C Region 1, Office of Director 2pp 14327 164 24X Fichs 50-352,82/08/06.8208120069
- 820B180110 Order quashing 9 Hansler 820B17 deposition COLE, R F Atomic Safety and Licensing Board Panel 82/0B/16 1p 14377.190 24% Fiche 50-352, B2/0B/16, B208180110

B Reportable occurrences. LERs & related correspondence

820B130317 Final Significant Deficiency 43 re Colt Industries emergency diesel generator malfunctioning thermostatic valve Generators will be corrected per vendor instructions Also reported per Part 21 XEMPER. J 6 Philadelphia Electric Co 82/08/03 HAYNES, R. Gegion 1. Office of Director App 14336 343 24X Fiche 30-352.82/08/03.8208130319

U Congressional/Executive Correspondence

9208040488 Responds to 8 Shenaman 820525 ltr re allegations of const deficiencies Faults not capable & methods used to repair fracture tones acceptable. Allegations of improperly mixed & placed concrete investigated in previous insp repts DENTON. H R. Office of Nuclear Reactor Regulation, Director 82/07/08 QREEMLEARS J Pennsylvania, State of 9pp 14220 312 24% Fiche 50-352,82/07/08.8208040488

DOCKET 50-354 HOPE GREEK NUCLEAR STATION, UNIT 1

O Inspection reports, IE Bulletins & correspondence

annual part and in a part and

B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (M6IV)
Leakage " Svc list encl.
JRDAN.E L Division of Engineering & Quality Assurance. B2/07/16
Consolidates Edison Co. of New York B7pp 14356.274 24X
Fiche 50-000.82/07/16.8204R10393

- 8204210396 [E Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210394
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Byc list encl CBBL I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357, 276 24X Fichs 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HTCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 8208050205 Forwards IE Insp Rept 50-354/B2-07 on 820601-0705 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/07/22 MARTIN.T J Public Service Electric & Gas Co of New Jersey 2pp 14212 117 24X Fiche 50-354.82/07/22.8208050205
- --8208050209 Notice of violation from insp on 820401-0705 STAROSTECKI, R Division of Project & Resident Programs 82/07/22 2pp 14212 119 24X Fiche 50-354,82/07/22,8208050205
- --8208050214 IE Insp Rept 50-354/82-07 on 820401-0705 Noncompliance noted failure to bend test shear connector automatically welded studs in accordance w/AWS D i 1 code requirements BATEMAN.W H , TRIPPLE Division of Project & Resident Programs 82/07/20 10pp 14212 121 24X Fiche 50-354.82/07/22.8208050205
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Bvc list enci JORDAN.E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche, 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Syc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194.120 24X Fiche 50-000.82/07/23.8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8208020112 Responds to 820420 request for add1 info on postulated main steam line break inside containment (IE Bulletin 80-04) Add1 analysis beyond design basis not necessary LIDEN,E A Public Service Electric & Gas Co of New Jarsey. 82/07/26 VAROA:8 A Operating Reactors Branch 1 2pp 14142 106 24X Fiche 50-000,82/07/26,8208020112
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Hork in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405.
- 8208160160 Responds to IE Bulletin 82-01, Revision 1. "Alteration of Radiographs of Welds in Subassemblies." No artificial enhancement of ABME code penetrameter images found MARTIN.T J Public Service Electric & Cas Co of New Jersey 82/07/30 HAYNES.R C Region 1. Office of Director 3pp 14345 141. 24X Fiche, 50-354, 82/07/30.8208160160
- 820B100214 Ack receipt of 820614 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-354/82-05
 Initial corrective actions did not resolve underlying cause of QC problems
 STAROSIECKI, R. Division of Project & Resident Programs 82/08/02
 MARTIN.T J Public Service Electric & Cas Co of New Jersey 2pp 14297.060 24X Fiche 50-354,82/08/02.8208100214
- --8208100220 Responds to NRC 820513 ltr re violations noted in IE Insp Rept 50-354/82-05 Corrective actions contractor installation drawing 8M-131 will be revised & installed hangers reinspected MARTIN.T J Public Service Electric & Qas Co of New Jersey, 82/06/14 HAYNES:R C Region 1. Office of Director 5pp 14297 062 24X Fiche 50-354,82/08/02,8208100214

- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/0B/05 Consolidated Edison Co of New York 117pp 1438B 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8208300083 forwards IE Insp Rept 50-354/82-08 on 820706-0801 No noncompliance noted STAROSTECKI,R Division of Project & Resident Programs 82/08/13, MARTIN.T J Public Service Electric & Gas Co of New Jersey 2pp 14596 135 24X Fiche 50-354,82/08/13,8208300083
- --8208300085 IE Insp Rept 50-354/82-08 on 820706-0801 No noncompliance noted Major areas inspected work in progress, including structural steel wrection, concrete placement of panel walls & svc water intake structure foundation BATEMAN, M. H. TRIPP. L. E. Division of Project & Resident Programs 82/08/11 Bpp. 14596 137 24X Fiche 50-354,82/08/13,8208300083
- R Periodic operating reports & related correspondence
- 8208090089 80bmits monthly status completion rept Unit 50% complete at and of June 1982 Operation date remains Dec 1986 LANDRIEU, PR H Public Service Electric & Osa Co of New Jersey 82/07/13 TRIPP.L E Division of Proyect & Resident Programs 1 14270. 203 24% Fiche 50-354.82/07/13.8208090089
- S Reportable occurrences, LERs & related correspondence
- 620B090145 Interim significant const deficiency rept to HPCI/reactor core isolation cooling exhaust theck valves Initially reported on 81117 Bechtel analysis indicates potential valve failure Next rept expected 820915
 MARTIN.T J Public Service Electric & Gas Co of New Jersey 82/07/29 HAYNES, R C Region 1. Office of Director 2pp 14271 317 24X Fiche 50-354,82/07/29,8208090145
- 8208160016 Interim deficiency rept re deleterious affects corrosion inhibitors have on solder used to state locking nuts on thermostatic valve override assemblies Initially reported on 820702 Final rept expected by 820724 MARTIN, T T Public Service Electric & Oas Co of New Jersey 82/09/02 HAYNES, R C Region 1, Office of Director 2pp 14344 266 24X Fiche 50~354,82/08/02.8208160016
- 8208260223 Final significant const deficiency rept re torque values of stud to nut combinations securing spider assembly in diesel generator Initially reported on 820514 Matter not reportable per 10CFR50 55(e)
 MARTIN,T J Public Bervice Electric & Oas Co of New Jersey 82/08/13 HAYNES,R C. Region 1. Office of Director 2pp. 14554 277 24X Fiche 50-354.82/08/13.8208260223
- DOCKET 50-395 HOPE CREEK NUCLEAR STATION, UNIT 2

 G Inspection reports. IE Bulletins & correspondence
- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " 8vc list enc! JORDAN,E L Division of Engineering & Guality Assurance, 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24x Fiche 50-000, 82/07/16,8204210393
- B204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurence B2/07/20 Consolidated Edison Co. of New York, 112pp 14381.001 24X Fiche 50-000, B2/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacts " Bvc list and! COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276, 24X Fiche.50-000, 82/07/RO.8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & FPCI Turbine Exhaust Check Valve Failures " Byc list encl JORDAN,E L. Division of Engineering & Quality Assurance, 82/07/22, Consolidated Edison Co of New York 112pp 14194:321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Syc list and UGRDAN,E.L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380;115 24X Fiche 50-000, 82/07/23, 8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Ouide Tube Support Pin Failures at Hestinghouse PNRs " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche 50-000.82/07/23.8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RGS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JGRDAN.E L. Division of Engineering & Quality Assurance 82/07/24 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26.8204210403
- 8208020112 Responds to 820420 request for add1 info on postulated main steam line break inside containment (IE Bulletin 80-04) Add1 analysis beyond design basis not mecessary LIDEN,E A Public Service Electric & Cas Co of New Jersey 82/07/26 VAROA,E A Operating Reactors Branch 1 2pp 14142 106 24% Fichs 50-000.82/07/26,8208020112
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list enci JORDANIE L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list enc!
 JORDANIE L Division of Engineering & Guality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201, 24X
 Fichs 50-000, 82/08/05, 8204210407
- S Reportable occurrences: LERs & related correspondence
- 8208090145 Interim significant const deficiency rept re HPCI/reactor core isolation cooling exhaust check valves Initially reported on SIiii7 Bechtel analysis Indicates potential valve failure Next rept expected 820915 MARTIN.T. J. Public Service Electric & Oas Co. of New Jersey 82/07/29 HAYMEB.R C. Region 1. Office of Director 2pp 14271.317. 24X Fiche 50-354,82/07/29.8208090145
 - DB160016 Interim deficiency rept re deleterious effects corrosion inhibitors have on solder used to state locking nuts on thermostatic valve override assemblies Initially reported on B20702. Final rept espected by 820724 MARTIN T.T. Public Bervice Electric & Gas Co of New Jersey B2/08/02 H4YNEB.R C Region 1. Office of Director 2pp 14344-266 24X Fiche, 50-354,82/08/02,8208160016.
 - 108260223 Final significant const deficiency rept re torque values of stud to nut combinations securing spider assembly in diesel generator Initially reported on 820514 Matter not reportable per 100FR50, 55(s)
 MARTIN-T. J. Public Bervice Electric & Gas Co of New Jersey,
 82/08/13 HAYNES, R. C. Region 1: Office of Director 2pp
 14554-279, 24X Fiche 50-354, 82/08/13, 8208260223
 - :KET 50-356 UNIV. OF ILLINOIS LOPRA RESEARCH REACTOR
 Periodic operating reports & related correspondence
 - 08230270 Forwards "Annual Operating Rept. 810801-820801" BECK. 0 P. . WEHRING, B. W. Illinois, Univ. of, Urbana-Changaign 82/08/23, Division of Licensing, 1p. 14512-318 24X Fiche: 50-356, 82/08/23, 8208230270
- -8208230271 "Annual Operating Rept,810801-820801,"
 # Illinois, Univ of. Urbana-Champaign 82/08/23 2pp 14512,319. 24X Fiche'80-356,82708/23,8208230270.
- OCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1
 Application/construction stage documents & correspondence
- 1207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR. Evc list encl.

 DIRCKB, H. J. Office of the Executive Director for Operations
 82/07/02. Consolidated Edison Co of New York 93pp. 14194:001.
 24X Fiche 30-000,82/07/02,8207080064
- 208050368 Board Notification 82-70:notifies of differing prof opinion re-sensitization of BHR staintess steel weldments.
 TEDESCO.R.L. Assistant Director for Licensing 82/07/20. Atomic Bafety and Licensing Board Panel. 4pp. 14281 355, 24% Ficher 50-000, 82/07/20, 8208050368.

- 8208190023 Forwards request for add1 info re steady-state piping vibration triteria for preoperational testing YOUNGBLOOD, B J Licensing Branch 1 82/07/22 BOROMANN, E A Cincinnati Gas & Electric Co 3pp 14506 351 24X Firs
- 8208030418 Forwards revised Certificate of Svc for Amend 137 to application for OL. in form of Revision 85 to FSAR.changing ref from (ER-GL) to (FSAR) BOROMANN, E A Cincinnati Qas & Electric Co 82/07/29 DENTON, H R Office of Nuclear Reactor Regulation. Director App 14154 218 24% Fiche 50-358,82/07/27.8208030418
- 8208020288 Amend 138 to OL application consisting of Revision 86 to FSAR BOROMANN,E A Cincinnati Gas & Electric Co 92/07/30 DENTON,N Office of Nuclear Reactor Regulation, Director 2pp 14145 139 24X Fiche 50-358,82/07/30,8208020288
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Evc list encl EISENHUT, D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14354 332 24X Fiche 50-000, 82/08/09, 8208090194
- 8208160170 Advises that response to NRC 920722 Itr re piping vibration criteria will be submitted in form of FSAR revision in Sept 1982 FLYNN, J D Cincinnati Oas & Electric Co 82/08/12 YOUNGBLOGD, B J Licensing Branch i ip 14345 045 24X Fiche 50-358, 82/08/12, 8208160170
- 8208160183 Confirms info given to 0 Dick in 820811 telcon Util response to NRC 810428 request for info re four instrumentation & control sys concerns, submitted on 820416 as part of Revision 83 to FBAR FLYNN, J D Cincinnati Gas & Electric Co 82/08/12 YDUNOBLOOD, B J Licensing Branch 1 ip 14349,301 24X Fiche 50-358,82/08/12, 8208160185
- O Adjudicatory correspondence
- 8208020204 First set of interrogatories Certificate of Syc encl Related correspondence CONNER.T B Cincinnati Gas & Electric Co CONNER.T B Conner & Wetterhahn 82/07/29 Miami Valley Power Project 26pp 14141 302 24X Fiche 50-358.82/07/29.8208020204
- 8208030268 Order CLI-82-20 directing ABLB to issue order dismissing eight new contentions admitted by ASLB 820715 order.sua sponts Issues reised in contentions being dealt w/by NRC investigation & monitoring of 64 program HOYLE.J C Office of the Secretary of the Commission 82/07/30 Atomic Safety and Licensing Board Panel, 3pp 14158 131 24X Fichs 50-358, 82/07/30,8208030268
- 8208030331 Petition to disqualify C Darth from participation in licensing proceedings Counsel refused to develop full & fair record for ASLB & failed to represent NRC interests w/o conflict Certificate of Svc encl
 BERNABEI, L. Miami Valley Power Project BERNABEI, L. Oovernment Accountability Project 82/07/30 Commissioners 28pp 14156 323 24X Fiche 50-388,82/07/30,8208030331
- 8208030414 Requests inherent supervisory authority over ASLB be exercised to correct ASLB 820715 action raising sight new contentions sua sponte ASLB exercise of authority constitutes abuse of discretion W/Certificate of Byc CGNNER.T B Cincinnati Gas & Electric Co. CGNNER.T B Conner & Hetterbahn 82/07/30 Commissioners 25pp, 14154 177, 24X Fiche. 50-338. 82/07/30, 8208030414
- 8208040264 Mation for 10-day extension of time until 820820 to file petition for reconsideration of Commission 820730 order, dismissing aight Miami Valley Power Project contentions raised awa eponte by ASLB Certificate of 8vc encl DERNABELL. Miami Valley Power Project BERNABELL. Oggernment Accountability Project 82/08/03 Atomic 8afety and Licensing Board Penel 5pp 14183 080 24X Fiche 50-358.82/08/03,8208040264
- 8208090150 Petition for reconsideration of Commission 820730 order directing ASLB to dismiss eight contentions proposed by Miami Valley Power Project & raised sum sponte by ASLB Supporting memorandum forthcoming. W/Certificate of Svc BERNABEI, L. Miami Valley Power Project BERNABEI, L. Government Accountability Project 82/08/04 Commissioners Spp. 14271:328 24X Fichs 50-358,82/08/04.8208090150

- 820B180105 Forwards Commissioner Gilinsky separate views re GECY-82-318 (Ct.1-82-20) Views should be served on parties & published
- 8208190148 Answer opposing Miami Valley Power Project 820730 petition to disqualify NRC counsel C Barth from licensing proceedings Commission should explicitly axonerate Barth & strike Project petition Certificate of Svc encl CONNER, T B Cincinnati Gas & Electric Co CONNER, T B Conner & Wetterhahn 82/08/16 Commissioners 15pp 14382 232 24X Fiche 50-358,82/08/16.8208190148
- 8208200077 Response opposing Miami Valley Power Project 820730 petition to disqualify NRC atty CA Barth from OL proceedings & motion to have Project counsel conduct reviewed by ASLB Project petition filed in bad faith Certificate of Svc encl DAMBLV. D C Operations & Administrative Division 82/08/19 Commissioners 140pp 14393 049 24X Fiche 50-358.82/08/17, 8208200077
- 8208240362 Petition for reconsideration of 820730 order directing ABLB to dismiss Miami Valley Power Project eight contentions admitted sua sponte Contentions relate to adequacy of GA & util character & competence Certificate of Bvc encl BERNABEI, L. DEVINE, T. Miami Valley Power Project BERNABEI, L. Government Accountability Project 82/08/20 Commissioners 120pp 14527 217 24X Fiche 50~358, 82/08/20, 8208240362
- 8208240382 Forwards petition on behalf of Hiami Valley Power Project to suspend const pending completion of comprehensive reinsp & corrective actions for all safety-related work by independent organization CLARK. L. Government Accountability Project CLARK. L. Miami Valley Power Project 82/08/20 PALLADING.N. Commissioners 1p 14524 076 24X Fiche 50-358.82/08/20,8208240382.
- --8208240385 Patition on behalf of Miami Valley Power Project to suspend const pending completion of comprehensive reinsp & corrective actions for all safety-related work by independent organization

 # Government Accountability Project * Miami Valley Power Project 82/08/20 Commissioners 120pp 14524 077 24X Fiche 50-358,82/08/20,8208240382
- 8208270405 Memorandum & order authorizing NRR Director to issue license permitting fuel loading low power testing & 5% operation Applicant motion for reconsideration & clarification of ABLB 820621 initial decision denied FRYE, J H Atomic Bafety and Licensing Board Panel 82/08/24, Office of Nuclear Reactor Regulation, Director, 13pp. 14565 127 24X Fichs 50-358.82/08/24.8208270405

H General correspondence

- 8207110028 FUIA request for tape recordings of interviews w/F Oltz on BE0228 & 0604 & other tapes made in course of Zimmer investigation HICKEY, J P Shew, Pittmen, Potts & Trombridge 82/07/26 CARR, J Division of Rules and Records Ip 14368:074 24X Fiche 50-338.82/07/26.8207110001
- 8208260058 Partial response to FOIA request for tape recordings of interviews w/F Oltr on 810225 & Odo4 & other tapes made in course of Zimmer investigation Forwards 810604 tape W/o encl
 FELTON, J. M Division of Rules and Records 82/08/06 HICKEY, J. P. Shaw, Pittman, Potts & Troubridge ip. 14568 075 24%
 Fiche 50-358, 82/08/06, 8208260058

K Utility Final Bafety Analysis Report (FBAR) & amends

- 820803041B Forwards revised Certificate of Bvc for Amend 137 to application for OL. in form of Revision 85 to FBAR, changing ref from (ER-OL) to (FBAR)
 BORGMANN.E A Cincinnati Qas & Electric Co 82/07/29 DENTON.H R. Office of Nuclear Reactor Regulation, Director 4pp 14154.218.
 24X Fiche 50-358,82/07/27,8208030418
- 9208020288 Amend 138 to OL application consisting of Revision 86 to FBAR BORNHANN, E A Cincinnati Cas & Electric Co. 82/07/30 DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp 14145: 139. 24X Fiche 30-358, 82/07/30, 8208020288
- --8208020275 Revision 86 to FSAR

 * Cincinnati Gae & Electric Co 82/07/31 425pp 14/45.141.
 24X Fiche 50-358,82/07/30,8208020288.

- 8208090229 Forwards Certificate of Svc for Amend 138 to OL application, in form of Revision 86 to FBAR BOROMANN.E A Cincinnati Gas & Electric Co 82/08/03 DENTON.H Office of Nuclear Reactor Regulation, Director 2pp 14271 113 24X Fiche 50-358,82/08/03.8208090229
- O Inspection reports, IE Bulletins & correspondence
- 8203190055 Add1 response to FOIA request for documents rs IE Insp Rept 50-338/81-13 Forwards documents listed in App A Documents also available in PDR FELTON, J M Division of Rules and Records 82/06/23 DEVINE, T, ROSENTHAL, J. Government Accountability Project 2pp 14680 111, 24X Fiche 30-358, 82/06/23, 8208190055
- --B208190057 Forwards memo from 0 Walton & W Banders re NDE effort at plant site w/Region I NDE van operated by NRC & contractor personnel Matt intended as input to Region 3 rept covering overall insp/investigation
 TRIPP.L E Materials & Processing Section 81/10/09
 DANIELGON, D H Materials & Processes Section 1p 14680 113
 24X Fiche 50-358,82/06/23,6208190055
- --8208190058 Summary of Bil027 meeting re facility investigation
 Partinent info relative to Commissioner Aberne unanswered
 question re facility allegations provided
 KEPPLER.J G Region 3. Chicago, Office of the Director (BI/03/01)
 81/10/28 STELLO.V Office of International Programs, Director
 1p 14680 114 24X Fichs 50-358,82/06/23,8208190055
- --820B190065 Requests that Ofc of Inspector & Auditor & UB Atty Ofc be allowed to review investigative rept re allegations concerning deficient facility const, from criminal standpoint Premature release of rept could be detrimental CUHMINOB.J J Office of Inspector & Auditor BI/OB/10 KEPPLER.J O Director's Office. Office of Inspection and Enforcement 1p 14680 115 24X Fiche 50-358,82/06/23,82/06/29085
- 8207030083 Appeals denial of FOIA request for document re IE Insp Rept 50-358/81-13 DEVING.T Government Accountability Project 82/07/09 DIRCKS,W J Office of the Executive Director for Operations 1p 14697.210 24X Fiche 50-358,82/07/09,8207050083
- 8204210393 IE Info Notice 82-23, "Main Bleam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/07/16,
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000.82/07/16,8204210393
- 8204210395 IE Info Notice 81-26,Part 3.8uppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" 8vc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001. 24X Fiche 50-000,82/07/19,8204210398
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Syc list and! JORDAN,E L. Division of Engineering & Quality Assurance, 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl C088.L I Division of Fuel Facilities, Materials & Bafaguards, 82/07/20 Consolidated Edison Co. of New York 7ipp 14357*276 24X Fiche, 50-000, 82/07/20, 8204210397
- 8208050320 Forwards IE Mpt Mesting Rept 50-358/82-07 on 820504 No nuncompliance noted DAVIS.A B Region 3. Office of Director 82/07/20 BOROMANN, E A Cincinnati Qas & Electric Co 2pp 14237, 307 24X Fiche 50-358, 82/07/20, 8208050320
- --B208050326 IE Mpt Meeting Rept 50-358/82-07 on 820504 No noncompliance noted Major areas discussed status of quality confirmation program, 820408 immediate action it & licensee proposed changes to reinsp program for contractor HUNTER, D R , BPESSARD, R L Division of Project & Resident Programs 82/07/15 App 14237.309. 24% Fiche 50-358/82/07/20, 8208050320
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194,321 24X Fiche 50-000,82/07/22,8204210398

- 8204210401 IE Info Notice 82-29, "Hydrogen Esplosion While Orinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Ouide Yube Support Pin Feilures at Westinghouse PWRs " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PMR Power Plants " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche: 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York. 122pp 14357.146 24X Fiche 80-000, 82/07/28, 82042(0405
- 8204210407 IE Info Notice BE-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingment" Svc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 82/08/05. Consolidated Edison Co. of New York 117pp 14388-201. 24X Fiche: 50-000. 82/08/05.8204210407
- 8208310003 Responds to appeal re denial of FOIA request for documents concerning IE insp Rept 50-358/Bi-13 Appeal partially granted & partially deniad Forwards CH Weil B10914 memo Info partially withheld (ref FOIA Exemption 7).

 DIRCKS.W J Office of the Executive Director for Operations 82/08/12 B01/NE,T Government Accountability Project 1p. 14697:220. 24X Fiche 50-000.82/08/12.8208310003
 - '08310005 Forwards RT Carison B10724 memo re allegations reported to tagion 1 by anonymous complainant concerning facilities /andor Insp Branch will conduct insp of Nuclear Engineering 3vcs.

 #ELL.C.H Region 3. Chicago, Office of the Director (81/03/01), 11/09/14 Region 3. Chicago, Office of the Director (81/03/01) Jpp. 14697 221 24X Fiche: 50-000, 82/08/12, 8208310003.
 - 208310007 Forwards RE Shepherd memos re allegations concerning facility insp.design controls & accumulation of test data Confidential info deleted GARLSON.R. Y Enforcement & Investigation Staff 81/07/24 STREETER.J Enforcement & Investigation Staff 18pp 14697 224 24X Fiche 50-000.82/08/12.8208310003.
 - B310244 Confirms B20811 telcon requesting extension until 820831 or response to IE Insp Rept 50-358/81-27 DROMANN-E A. Cincinnati Cas & Electric Co 82/08/17, KEPPLER.J O Region 3, 8ffice of Director. Ip 14687-311, 24X iche 50-358, 82/08/17, 8208310244

teportable occurrences. LERs & related correspondence

1090226 Final deficiency rept re lack of QA program for control rod Iriya supports, Initially reported on 820510, All associated langer & support welds found unacceptable & will be replaced in discounted prior to fuel load IRROMANNIE A Cincinnati Cas & Electric Co. 82/07/21, KEPPLER, J Q Region 3, Defice of Director, 2pp 14271, 185 24X iche 50-358, 82/07/21, 8208070226

8050438 Potential Part 21 deficiency rept re 300 ft of A-36 plate urchased from EK Horris Co & produced by Bethlehem Steel o. Notification, interim or final repts will be submitted by pplicant EDZIK, W A Henry J Kalser Co 82/07/26 KEPPLER, J O Region 3, ffice of Director. 8pp 14218 011 24X Fiche 80-358, 82/07/26, 1208050438

OB090263 Second interim deficiency rept re-welds rejected upon radiographic review Initially reported on 820302. Difficulties re-lack of documentation ancountered in preparation of final rept Final rept expected by 821115. BURGMANN, E. A. Cincinnati Gas & Electric Co. 82/07/26 KEPPLER, J. G. Region 3. Office of Director 2pp. 14270-321 24X Fiche, 30-358, 82/07/26, 8208090269

OBD90078 Final deficiency rept re lamination in structural angle. All nonconformance repts for meth dispositioned "reject". lemoval of meth scheduled for completion by 820930. DRQMANN,E A. Gincinnati Gas & Electric Co 82/07/28. KEPPLER, J & Region 3. Office of Director. 2pp. 14269:242 24% che 80-358,82/07/28,8208090098.

- 8208090177 Final deficiency rept re Item M-47 in Henry J Kaiser Co QA program Initially reported on 820514 Specific occurrences identified during review will be handled in accordance w/ existing site procedures
 BOROMANN.E A Cincinnati Gas & Electric Co 82/07/28 KEPFLER, J Q
 Region 3, Office of Director 2pp 14271 166 24X
 Fichs 30-358,82/07/28,8208090177
- 8208090223 Interim deficiency rept re Item M-34.welders w/o ASME qualification to make welds in different positions on sacrificial shield initially reported on 820414 Investigation continuing Final rept expected by 821231 BOROMANN,E A Cincinnati Oas & Electric Co 82/07/28 KEPPLER,J @ Region 3. Office of Director 2pp 14270 362 24X Fiche 50-358.82/07/28.8208090223
- 8208100149 Final deficiency rept re lack of GC insp of ABME work Hork limited in scope to mechanically connected components All safety-related work performed under adequate GA coverage Condition not reportable per 10CFRSO 35(8) BDROMANN, EA Cincinnati Gas & Electric Co 82/07/28 KEPPLER, J G Region J, Office of Director 2pp 14298 043 24X Fiche 50-358, 82/07/28, 8208100149
- 8208160231 Interim deficiency rept re discrepancies in installation of OE Class IE essential panels containing reactor pressure sys &/or neutron monitoring cables Procedure to be revised to provide for insp of cables by 8/21201
 BOROMANN.E A Cincinnati Oas & Electric Co 82/08/04 KEPPLER, J O Region 3. Office of Director. 2pp 14346 320 24X
 Fichs. 50-358. 82/08/04. 8208160231
- 8208230110 Final deficiency rapt re Anchor/Darling Valve binding or jamming during closing Initially reported on 800314 Disc quide extensions installed in valves 1070068 & 1M133R Repair documentation on file BDROMANN,E A Cincinnati Qas & Electric Co 82/08/10 KEPPLER,J Repion 3. Office of Director 2pp 14517 289 24X Fiche 50-358,82/08/10,8208230110
- 8208240085 final deficiency rept re electrical separations Addl electrical separation criteria incorporated in installation spec & design documents Previously installed cables & raceways will be verified by walkdown insp BDROMANN,E A Cincinnati Gas & Electric Co 82/08/16 KEPPLER,J Q Ragion 3, Office of Director 2pp 14517 355 24X Fiche,50-358,82/08/16,8208240085

T Hearing transcripts on non-antitrust matters

- 8208090017 Commission determination withholding transcript of 820607 briefing re status of Zimmer investigation Meeting closed per 100FR9 108(c) & 100FR9 104(a)(5) & (7) # Office of the Secretary of the Commission 82/07/26 2pp 14283.353 24% Fiche 90~358.82/07/26.8208090017
- 8208090317 Transcript of Commission 820730 public meeting in Washington DC re affirmation/discussion session on 8ECY-BZ-318 Pp 1-7.

 4 Commissioners 82/07/30 lipp 14307 336 24X Fiche 50-358,82/07/30,8208090317

U Congressional/Executive Correspondence

- 8206130070 Forwards info re facility quality confirmation program, in response to 820614 & 0712 requests Info current as of 820530 PALLADINO,N J Commissioners 82/07/15 UDALL.M K House of Rep , Interior & Insular Affairs 8pp 14301:114 24X Fiche 50-358,82/07/15,8206130070
- ~~8208090053 Requests response by 820716 to 820614 request for info re util Quality Confirmation Program Delay in responding to request supports conclusion that Region 3 insufficiently sware of project status UDALL.M K. House of Rep., Interior & Insular Affairs 82/07/12 PALLADINO, N J Commissioners ip 14301 122 24X Fiche 50-358,82/07/15.8206130070
- --B206130005 Requests detailed info re findings of util quality confirmation program to date. Insufficient info provided at Bubcommittee 820610 hearing UOALL, M.K. House of Rep., Interior & Insular Affairs 82/06/14 FALLA

DOCKET 50-361 BAN DNOFRE NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list encl
 DIRCKS.W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 OOI
 24% Fiche SO-000.82/07/02.8207080064
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8208030068 Forwards Suppl 6 to SER re application for OL W/o encl MIRAGLIA,F J Licensing Branch 3 82/06/30 DIETCH,R Southern California Edison Co 4pp 14200 307 24X Fiche 50-361,82/06/30, 8208030068
- F Security, medical, emergency & fire protection plans
- 8208020376 Responds to 820721 telephone request for status of ingestion zone planning by State of CA State has retained consultants to do planning Plan will be submitted to FEMA in late Sept 1982

 KRIMM, R W Federal Emergency Management Agency 82/07/28

 ORIMES 8 Division of Emergency Preparedness ip 14150 118 24X Fiche 30-206.82/07/28.8208020376
- 8208030201 Revises position in 820727 ltr re fire separation of auxiliary feedwater pumps Metal barrier will be installed in pump room Util cannot commit to change completion prior to startup following second refueling outage BASKIN.K P Southern California Edison Co 82/07/29 MIRAOLIA, F Licensing Branch 3 ip 14158 257 24X Fiche 50-361,82/07/29,8208030201
- B208110077 Board Notification 82-74 Informs of problems w/implementation of Unit 1 physical security plan LISENHUT.D 0 Division of Licensing 82/08/02 PALLADING,N J OILINSKY,V : AHEARNE J Commissioners App 14327 242 24X Fiche 50-361 82/08/02, B208110097
- --8208110099 Advises that util plans to correct listed items re problems between security measures & operational response Emergency conditions will be discussed at 820617 meeting Encl withheld (ref 100FR73 21)

 ENOELKEN.R H Region 5, Office of Director 82/06/17 DIETCH, R Southern California Edison Co 2pp 14327 249 24X Fichs 50-361, 82/08/02.8208110097
- 8208190180 Discusses status of ingestion pathway planning in CA Final evaluation re capability of involved jurisdictions to implement ingestion pathway plans must await drills expected in late Aug/early Sopt 1982 KRIMM, R W Federal Emergency Menagement Agency 82/08/05 CRIMES, B K Division of Emergency Preparedness 4pp 14386 353 24% Fiche 50-206,82/08/03,8208190180
- B20B270696 Responds to B20630 ltr re changes to facility physical security plan, Revision 5 NRC concurs w/changes except provisions in Section 1 3 1 4 re protected & vital areas CRUTCHFIELD, D Operating Reactors Branch 5 82/08/17 BASKIN, K & Southern California Edison Co 3pp 14683 051 24X Fiche 50-204, 82/08/17, 8208270896
- B20B230023 Forwards Revision & to Mar 1981 physical security plan.
 Revision withheld (ref 10CFR73 21)
 BASKIN.K P Southern California Edison Co 82/08/18 EIRENHUT, D C
 Division of Licensing 1p 14517 227 24X Fiche 50-206, 82/08/18, 8208230023
- 8208260276 Releases public version of revised emergency plans FELTON.J M Division of Rules and Records 82/08/20. Document Management Branch ip 14577 270 24X Fiche.50-361.82/08/20. 8208260276.
- --8208260300 Forwards public version of revised emergency plans, including State of CA emergency response plan, County of Orange, CA incident response plan & facility onsite & offsite emergency response plans BABKIN, K P Southern California Edison Co 82/07/08 MIRAGLIA, F Licensing Branch 3 2pp 14579.272 24X Fiche 50-361.82/08/20, 8208260276
- --8208260307 Public version of revised emergency plan, including State of CA emergency response plan & County of Drangs, CA incident response plan One oversize drawing encl Aperture card available in PDR.

 * Gouthern California Edison Co * Sam Diego Gas & Electric Co. 82/06/11 2,000pp 14579 274 24X Fiche. 50-361,82/08/20, 8208260296

- --B208260309 Central Files version of Revision 3 to analysis of time required to evacuate transient & permanent population from various areas within plume strosure pathway emergency planning zone

 * Wilbur Smith & Associates 62/06/30 117pp 14886 235, 24X Fiche 50-361, 82/08/20, 8208260296
- O Adjudicatory correspondence
- B20B160050 Order CLI-B2-14 rendering ASLB B20111,0514 & 0616 decisions effective License allowing operation up to 5% power may be issued Order does not authorize issuance of full power licenses CMILK. B J Office of the Secretary of the Commission B2/07/16 4pp 14044 299 24% Fiche 50-361.82/07/16.820B160050
- 82081t0156 Brief in opposition to intervenor 820429 appeal of ASLB 820514 initial decision on emergency planning ASLB correctly assessed radiation monitoring capability Adequate measures will protect special populations W/Certificate of Byc P100TT, DR Southern California Edison Co PIGDTT, DR San Diego Cas & Electric Co PIGOTT, DR Anaheim CA 82/08/04 Atomic Safety and Licensing Appeal Panel 32pp 14314 242 24X Fiche 50-361, 82/08/04, 8208110156
- 8208100008 Confirmation of emergency preparedness items, transmitting DB Matthews affidavit certifying that siren sys performs in accordance w/Tech Bpecs Issue of ingestion pathway emergency planning zone to be addressed later CHANDLER.L.J Hearing Branch 2 82/08/06 ip 14296 335 24% Fiche 50-361,82/08/06,9208100008
- --B208100019 Affidavit of DD Matthews certifying that siren sys will perform in accordance w/Tech Specs Certificate of Svc encl MATTHEWS.D B Section D (Pre 802001) B2/08/06 7pp 14296 336 24X Fiche 50-361, D2/08/06, B208100008
- 8208110067 Memorandum & order re need for further proceedings on adequacy of offsite planning for medical svcs FEMA must respond to listed questions by 820903 KELLEY, J.L. Atomic Safety and Licensing Board Panel 82/08/06 7pp 14339 070 24X Fiche 50-361.82/08/06.8208110067
- 8208130146 Forwards ASLII 820806 memorandum & order directing FEMA to answer questions re adequacy of offsite planning for medical sycs SCINTO. J Hearings Division 82/08/11 PERRY, S W Federal Emergency Management Agency 1p 14339 069 24X Fithe 50-361, 82/08/11, 8208130146
- B20B160142 Response in opposition to QUARD & AS Carstens, et al. 820701 brief supporting appeal of ASLE Initial Decision. LCP-82-39, on emergency planning Intervenors failed to show reversible error. Certificate of Svc enci CHANDLER, L. J. Hearing Branch 1 82/08/13 Atomic Safety and Licensing Appeal Panel 40pp 14344 089 24X Fiche 50-361, 82/08/13,8208160142
- 8208200220 Order extending time until 820910 for Commission to act to review ALAB-680 CHIKK 8 J Office of the Secretary of the Commission 82/08/18 Commissioners ip 14399.341 24x Fiche 50-361.82/08/18.8208200220
- M Antitrust correspondence
- 8208030288 Forwards Amend i to Ban Onofre Units i & 2 participation agreement among Southern CA Edison Co. San Diego Qas & Electric Co.City of Anaheim & City of Riverside whereby City of Anaheim purchased addl ownership interest DIETCH.R Bouthern California Edison Co. 82/07/09 EISENHUT, D. G. Division of Licensing iopp 14154 247, 24% Fiche 50-361,82/07/09,8208030288
- P Operating license stage documents & correspondence
- 8208030119 Forwards Amend 4 to License NPF-10, safety evaluation & notice of issuance & availability Amend adds three inadvertently omitted valves to table of motor operated valves requiring surveillance
 MIRAGLIA: F J. Licensing Branch 3 82/07/16 DIETCH, R Bouthern California Edison Co. COTTON, 0 D. BERNATH. L. Ban Diego Gas & Electric Co. Spp. [4242 132 24X Fiche 50-361, 82/07/16, 8208050119.
- --8208050133 Amend 4 to License NPF-10, adding three valves omitted from table of motor operated valves, adding special test exceptions, correcting errors & clarifying administrative controls & air lock seal pressure MRAOLIAF J. Licensing Branch 3. 82/07/16 125pp 14242:135. 24X Fiche 50-361,82/07/16,8208050119

- --8208050137 Notice of issuance & availability of Amend 4 to Licenso NPF-10 MIRAGLIA,F J Licensing Branch 3 82/07/16 7pp 14242 239 24X Fiche 50-361,82/07/16,8208050[19
- 8208020248 Advises that util has completed review of surveillance procedures necessary for initial entry into Mode 2.per License Condition 20 DIETCH.R Southern California Edison Co 82/07/23 ENGELKEN,R H Region 5. Office of Director 2pp 14/52 229 24X Fiche 50-361,82/07/23.8208020248
- B208030075 Notification of B20729 meeting w/util in Bethesda,MD to discuss inadequate core cooling instrumentation ROOD.H Licensing Branch 3 02/07/26 MIRAGLIA.F J Licensing Branch 3 4pp 14200 342 24X Fische 50-364.82/07/26,8208030075
- 8208030487 Discusses shift manning Five-shift rotation will be initiated prior to operation above 5% power Four shifts operate plant & fifth shift provides licensed operator requalification training DIETCH R Southern Celifornia Edison Co 82/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 14154-087 24% Fiche 50-361, 82/07/30, 8208030489
- 6208030493 Informs that util is finalizing scope of work for preparation of responses to NRC 820327 questions re rapid depressurfiation & decay heat removal w/o power operated relief valves Responses will be sent by 830630 BASKIN.K P Bouthern California Edison Co 82/07/30 MIRAGLIA.F Licensing Branch 3 ip 14154 086 24X Fiche 50-361.82/07/30, 8208070303
- 8208040292 Forwards Amend 5 to License NPF-10, safety evaluation & notice of issuance & availability Amend changes date for tompletion of mods to control room ventilation sys & modifies Tech Specs
 MIRAGLIA: F J Licensing Branch 3 82/07/30 DIETCH.R Southern California Edison Co COTTCN.G D, BERNATH.L San Diego Cas & lectric Co 4pp 14183 001 24X Fiche 50-361.82/07/30,8208040892
 -)8040277 Amend 5 to License NPF-10 changing data for completion of nods to control room ventilation sys & modifying Tach Specs 1IRAGLIA.F J. Licensing Branch 3 82/07/30 7pp 14183 005 24X Fiche 50-361,82/07/30,8208040292
 - 08040300 Safsty evaluation supporting Amend 5 to License NPF-10

 * Diffice of Nuclear Reactor Regulation, Director 82/07/30 Spp
 14183:012 24X Ficho 50-361,82/07/30,8208040292
 - 3208040301 Notice of issuance & availability of Amend 5 to License NPF-10
 MIRAQLIA, F J Licensing Branch 3 82/07/30 3pp 14/83:015
 24X Fichs 50-361,82/07/30,8208040292
- '08040287 Forwards Revision 2 to "Inservice Testing Program Fian." in response to request for addl info per 820317 desting commitment BASKIN.K P. Southern California Edison Co. 82/08/02 MIRAGLIA.F. Licensing Branch 3 ip 14183 019 24X Fiche. 30-361, 82/08/02, 8208040287
- 8208040269 Revision 2 to "Inservice Testing Program Plan" * Bouthern California Edison Co 82/07/30 46pp 14183 019 24X Fiche 50-361.82/08/02.8208040287
- OBO90051 Forwards affidavit attesting that distribution of Amend B to License NPF-10 has been completed, per B20723 ltr MEDPORD, M O Bouthern California Edison Co 82/08/02 MIRAQLIA, F Licensing Brench G. 4pp 14270.010 24X Fiche 50-361,82/08/02, 3208090051.
- 09050171 Forwards "Bupplemental Rept Control of Heavy Loads for San Onofre Nuclear Generation Station Units 2 & 3." in response to 820617 telcon re 810707 submittal on NUREO-0612, "Control of Heavy Loads "BASKIN, K P. Southern California Edison Co 82/08/03 MIRAGLIA, F. Licensing Branch 3 2pp 14211 200 24X Fiche; 50-361, 82/08/03, 8208030171
- --8208050178 "Supplemental Rept Control of Heavy Loads for Ban Onofra Nuclear Generation Station Units 2 & 3 " # TERA Corp B-82-878 82/07/31 46pp 14211 202 24X Ficha:50-351,82/08/03/8208050171
- 208110117 Forwards for review & approval, proposed change to Tech Spsc 3,3 3,7, Table 3 3-13 re radioactive gaseous effluent monitoring instrumentation Change would permit limited containment purging w/purge sys activity monitor inogenable. BAGKIN.X P Southern California Edison Co. 82/08/05 MIRAGLIA.F Licensing Brench 3. Ip. 14314,332 24X Fiche 30-361,82/08/05,8208110117

- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements & to RC list encl EISENHUT. D G Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000,82/08/09,8208090174
- 8208260600 Summary of 820729 meeting w/util & contractors re ESF actuation sys surveillance requirements Addl info requested to support proposed Tech Spec changes ROSD.H Licensing Branch 3 82/09/12 Licensing Branch 3 1p
- 8208240396 Confirms 820806 teleon authorizing temporary changes to Tech Spec for License NPF-10 re radioactive gaseous effluent monitoring, requested in 820805 ltr NOVAK, T M Assistant Director for Licensing 82/08/13 DIETCH, R Southern California Edison Co COTTON, Q D , BERNATH, L San Diego Cas & Electric Co 2pp [4594 208 24X Fiche 50-361, 82/08/13, 8208260396
- 820B180049 Amend Application 9 consisting of Proposed Change NPF-10-26 to License NPF-10 Amend revises Tech Spec 3 7 1 3 recondensate storage tank inventory DIETCH.R Southern California Edison Co 82/08/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 14379 170. 24X Fiche 50-361.82/08/16.8208180049
- --8208180053 Proposed revision to Tech Spec 3 7 1 3 re condensate storage tank inventory + Southern California Edison Co 82/08/16 4pp 14379 179, 24x Fiche: 50-361,82/08/16,8208180049
- 8208200225 Requests NRC reconsider position & formally respond to util 820723 Amend Application B to License NPF-10 requesting extension of surveillance internal for ESF actuation sys subgroup relays to 18-month interval Justification sncl BASKIN.K P Bouthern California Edison Co 82/08/16 MIRAGLIA, F Licensing Branch 3 12pp 14399-295 24X Fiche-50-361,82/08/16,8208200225
- 8208250363 Discusses corrective actions per NUREO-0737, Item 1 D i. "Control Room Design Review." to identify significant human factors & instrumentation problems Seventeen corrective actions identifyied in License Condition 19F completed BASKIN.K F Southern California Edison Co 82/08/19 MIRAQLIA.F Licensing Branch 3 5pp 14540 268 24X Fiche 50-361.82/08/19, 8208250363
- 8208310360 Ack receipt of 810915, 820107 & 0201 applications, NRR review has determined that applications re Unit 2 are exempt from fee requirements Refund currently in progress MILLER, W O License Fee Management Brench 82/08/20 DIETCH, R Southern California Edison Co. 2pp 14697 115 24X Fiche, \$0-361, 82/08/20, 8208310360
- 8208280092 Affirms implementation of maint program procedures as required by License Condition 2 C(5): Procedures developed based on manufacturer recommended practices BABKIN.K P Southern California Edison Co 82/08/23, MIRAGLIA.F. Licensing Branch 3 2pp 14540 347 24% Fiche 50-361,82/08/23,8208200092.
- 8208300275 Forwards outline of sys & equipment required for initial fuel loading & for operational support during initial fuel load.based on listed assumptions Operational support sys not required during fuel load for public health & safety.

 CRANE.P A Pacific Gas & Electric Co 82/08/24, EIBENHUT.D Q Division of Licensing 6pp 14579 227, 24X Fiche 50-361,82/08/24,8208300275
- 8208270238 Forwards Affidavit of Svc re distribution of 820816 application for Amend 9 to License NPF-10 MEDFORD, M O Southern California Edison Co 82/08/25 MIRAOLIA, F Licensing Branch 3 4pp 14569 119 24X Fiche 50-361,82/08/25, 8208270238
- 8208270377 Forwards add1 info re turbine gantry crane in response to NUREO-0512. "Control of Heavy Loads" Crane excluded from further evaluation No load drop could impact both trains of any safe-shutdown sys
 BASKIN.K.P Bouthern California Edison Co 82/08/25, MIRAGLIA.F. Licensing Branch 3 Bpp 14564-283 24X Fichs. 50-361, 82/08/25, 8208270377

Q Inspection reports, IE Bulletins & correspondence

- B204210393 IE info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN.E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14956 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 82/07/19 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Evc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From V Hexafluoride Overpacks," 8vc list enci COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000.82/07/20,8204210397
- 8204210398 IE Info Notice 82-24. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Go of New York 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list enc!
 JORDAN.E L Division of Engineering & Quality Assurance 82/07/23
 Consolidated Edison Co of New York 122pp 14380 115 24X
 Fiche 50-000,82/07/23,8204210401
- B204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Syc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000. B2/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RGS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidate Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Bvc list encl JORDAN.E.L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14257 146 24X Fiche. 50-000, 82/07/28, 8204210405
- 8208160072 Reiterates Biiii3 response to IE Bulletin 81-02, "Failure of Oate Type Valves to Close Against Differential Pressure," signed under oath or affirmation Recommended corrective action completed BASKIN.K P. Bouthern California Edison Co B2/07/30 ENGELKEN.R H. Region 5. Office of Director 2pp 14342 071. 24X Fiche 50-361.82/07/30.8208160072
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement" Bvc list encl.

 JORDAN.E L Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche. 50-000, 82/08/05, 8204210407
- 8208230249 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants," consisting of rept of info requested in Action Item 3 on threaded fasteners Rept satisfies Action Item 5 requirements HAYNES, J O Southern California Edison Co 82/08/10 ENGELKEN, R H. Region 5. Dffice of Director. App 14508 351 24X Fichs 50-361,82/08/10,8208230249
- 8208270533 Ack receipt of 820812 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/82-22 & 50-362/82-12.

 BISHOP.T.W. Division of Resident, Reactor Project & Engineering Programs 82/08/20 PAPAY.L.T Southern California Edison Co ip 14566 024. 24x Fiche 50-361/82/08/20/8208270539

- --8208270538 Responds to NRC 820714 ltr re violations noted in IE Insp Repts 50-361/82-22 & 50-362/82-12 Corrective actions Unit 2 housekeeping conducted during wk of 820722-24 in preparation for initial criticality PAPAY.L T Southern California Edison Co 82/08/12 ENDELMEN.R H Region 5, Office of Director 5pp 14566 025 24X Fiche 50-361,82/08/20,8208270533
- R Periodic operating reports & related correspondence
- 8208120122 Forwards monthly operating rept for June 1782 RAY, H 9 Southern California Edison Co 82/07/15 Management Information Branch 1p 14327 045 24X Fiche 50-361.82/07/15, 8208120122
- --8208120125 Monthly operating rept for June 1982 HANAFURD.T Bouthern California Edison Co 82/07/01 5pp 14927'046 24% Fitche 50-361,82/07/15,8208120122
- 8 Reportable occurrences, LERs & related correspondence
- 8208020203 Forwards LERs 82-059/03L-0,82-060/03L-0,82-061/03L-0 & 82-062/03L-0 Detailed event analysis submitted RAY,H 8 Southern California Edison Co 82/07/20 ENGELKEN,R.H Region 5, Office of Director 2pp 14141 328 24X Fiche 50-361,82/07/20,8208020203
- --B208020204 LER B2-059/03L-0 on B20407, while in Mode 5, during check of high vibration in train A emergency chiller water pump, chiller found w/faulty control switch. Caused by switch out of calibr Switch recalibr RAY. H B Southern California Edison Co B2/07/20 Region 5, Office of Director ip 14141 330, 24X Fiche 50-361,82/07/20,8208020203
- --B20B020212 LER B2-060/03L-0 on B20416, while in Mode 5, emergency air cleanup sys train A became inoperable when emergency chiller tripped on low flow Caused by erratic flow control switch Bwitch replaced & sys returned to operable status RAV.H B Southern California Edison Co B2/07/20 Region 5, Office of Director ip 14141,331 24X Fiche 50-361,82/07/20, 8208020203
- --B20B020216 LER B2-061/03L-0 on B20411, while in Mode 5 & operating train B of control room emergency air cleanup sys to allow maint on train A train B became inoperable Caused by faulty flow controller Flow controller repaired, RAY.H B Southern California Edison Co 82/07/20 Region 5. Office of Director 1p 14141 332 24% Fiche 50-361, B2/07/20, B20B020203
- --B208020219 LER B2-062/03L-0 on 82040i.while in Mode 5 & operating train A of control room emergency air cleanup sys.vibration noted in chiller pump Caused by pump bearing failure. Bearings replaced & pump declared operable within 10 days RAV.H B Bouthern California Edison Co 82/07/20 Region 5, Office of Director ip 14141 333 24X Fiche 50-361,82/07/20, 8208020203
- 8208020253 RO 82-036 on 820720, invastigation of 820716 temporary loss of pressurizer level & pressure control revealed design error. Loss of offsite power would have rendered pressurizer heater controls inaparable RAY. H B Southern California Edison Co 82/07/21, ENGELKEN, R H Region 5, Office of Director 2pp. 14152 211 24% Fiche: 50-361, 82/07/21, 8208020253.
- 8208020414 Forwards LER 82-033/03L-0 Detailed event analysis submitted RAY, H 8 Southern California Edison Co 82/07/22 ENGELKEN, R H Region 5, Office of Director 2pp. 14145,136 24X Fiche: 50-361, 82/07/22, 8208020414.
- --B208020417 LER B2-033/03L-0 an B20609 turbine overspeed protection systemdered inoperable. Caused by need to repair oil leaks on unitized actuator Isolation immediately achieved because HSIV turbine stop valves closed.

 RAY.H B. Southern California Edison Co B2/07/23 Region 5, Office of Director ip 14145:138. 24X Fiche 30-361.82/07/22, B208020414
- 820Bi00297 Forwards LER 82-035/03L-0 Detailed event analysis submitted RAY, H 8 Southern California Edison Co. 82/07/22 ENGELKEN, R H Region 5, Office of Director 2 Dp. 14297:107 24X Fiche 50-341, 82/07/22, 820Bi00297
- --820B100303 LER B2-035/03L-0 on B20610, steam found leaking through 2HV-8421 mainsteam atmospheric dump valve Cause not stated Personnel unable to duplicate anomaly, Semiannual subgroup relay test performed on controller, relays & actuator RAY.H B. Southern California Edison Co 82/07/22 Region 5, Gffice of Director, ip 14297:109 24X Fich= 30-361, B2/07/22, B20B100297.

- 8208020306 Forwards LERs 82-052/03L-0, 82-054/03L-0, 82-055/03L-0 & 62-058/03L-0
 RAY, H B Southern California Edison Co 82/07/23 ENGELKEN, R H Region 5, Office of Director 2pp 14151 137 24X
 Fiche 80-361, 82/07/23, 8208020306
- --8208020314 LER 82-052/03L-0 on 820419, during routine shift surveillance, channel 8 ammonia analyter of toric gas isolation sys was declared inoperable Caused by Instrument drift Analyter repaired & recallor RAY, H B Southern California Edison Co 82/07/22 Region 5, Office of Director 1p 14151 139 24X Fiche 50-361,82/07/23,8208020306
- --8208020322 LER 82-055/03L-0 on 820228 channel 8 ammonia analyzer of totic gas isolation sys was declared indperable Caused by instrument drift Analyzer recalibr
 RAY.H B Southern California Edison Co 82/07/22 Region 5.
 Office of Director ip 14151 140 24X Fiche 50-361,82/07/23.
 8208020306
- --9208020334 LER 82-054/03L-0 on 820312, channel 8 ammonia analyzer of toxic gas isolation sys was declared inoperable & channel A butane analyzer flamed out Caused by instrument drift & flame out Analyzers regarred & receibr RAV.H B Southern California Edison Co 82/07/22 Region 5, Office of Director 1g 14351 141 24X Fiche 50-361,82/07/23, 200802020
- --8208020337 LER 82-058/03L-0 on 82022i, channel B ammonia analyzer in toxic gas isolation sys was declared inoperable & control room emergency air cleanup sys went into isolation mode w/channel A out of svc for routine maint Analyzers recalibr RAY,H B Bouthern California Edison Co 82/07/22 Region 5, Office of Director ip 14151 142 24X Fiche 50-361,82/07/23,8208020306
- 8208020350 Forwards LER 82-037/03L-0 Detailed event analysis submitted RAY,I/ 5 Southern California Edison Co 82/07/23 ENGELKEN.R H Region 5. Office of Director 2pp 14150 085 24X Fiche 50-361.82/07/23.8208020350
- -8208020366 LER 82-037/03L-0 on 820518 remote shutdown monitoring reactor coolant boron concentration instrument declared inoperable following receipt of erratic indications Caused by transmitter module including extra ground RAY. H B Southern California Edison Co 82/07/23 Region 5, Office of Director 1p 14150 087 24x Fiche 50-361.82/07/23, 8208020350
- 1208020393 Forwards LER 82-065/01T-0 Detailed event analysis submitted RAV:H & Southern Cellfornia Edison Co. 82/07/23 ENGELKEN:R H Region 5, Office of Director 2pp 14145 133 24X Fishe. 50-361. 82/07/23. 8208020393
- -B20B020395 LER 62-065/01T-0 on 620711, while testing control room smergency air cleanup sys chillers, train 8 chiller tripped immediately after starting Caused by faulty compressor motor bearing high temp alarm module flodule replaced RAY. H. B. Bouthern California Edison Co. 82/07/23 Region 5, 0ffice of Director, 1p 14145 135 24X Fiche 50-361,82/07/23, 8208020393
- 208020148 FNO-V-82-031 on 820726. Initial criticality achieved Boron concentration increased to 68 ppm, \(\omega\)/rod group six fully inserted & groups four & five partially inserted Predicted concentration was 830 ppm INETZIG. 0 Region 5. Office of Director 82/07/27 1p 14145 101 24X Fiche 50-361,82/07/27,8208020148
- '08100043 Forwards LER 82-036/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/07/30. ENGELKEN.R H Region 5. Office of Director 2pp 14296 251 24X Fiche 30-36t.82/07/30.8208)00043
- -8206100050 LER 82-036/03L-0 on 820717, during troublesheating in cabinets to locate ground lead, pressurizer heater control was lost for 2-3 minutes Caused by wiring error in high-high trip relay
 RAY.H B Southern California Edison Co 82/07/30 Region 5, Diffice of Director ip 14276 253, 24% Fichs 50-361, 82/07/30, 8208100043
- ROBO9D211 Forwards LER 82-043/03L-O Detailed event analysis submitted, RAY, H. B. Southern California Edison Co. 82/08/02 ENGELKEN, R. H. Region B, Dffice of Director. 2pp 14270 354 24X iche. 50-361, 82/08/02, 8208090211

- --8208090216 LER 82-043/03L-0 on 820708 emergency chilled water pump P-160 to train A of control room emergency air conditioning sys could not start w/o blowing fuses Caused by insufficient fuse size Larger fuses installed RAY. H B Southern California Edison Co 82/08/02 Region 5, Office of Director ip 14270 356 24X Fiche 90-361,82/08/02,8208090211
- 8208090233 Updated RD liquid radwaste treatment sys inoperable for more than 31 days after 820308 New limiting condition of operation procedure issued on 820720 Minor adjustments made & sys rendered operable on 820726
 RAY, H B Southern California Edison Co 82/08/02 ENGELKEN, R H Region 5, Office of Director 2pp 14271 103 24X
 Fiche 50-361,82/08/02,8208090233
- 8208120285 RO on 820803, while in Mode 3, engineering review of 820721 & 29 data during operability checks of valves within auxiliary feedwater sys indicated excessive valve stroke time LER & 14-day rept will be submitted RAY, H & Southern California Edison Co 82/08/03 ENGELKEN, R H Region 5, Office of Director in 14326 332 24X Fiche 50-361, 82/08/03, 8208120285
- 8208160149 Forwards LER 82-041/03L-0 Detailed event analysis submitted RAY, H B Gouthern California Edison Co 82/08/05 ENGELKEN, R H Region 5, Office of Director 2pp 14345 093 24X Fiche 30-361.82/08/05,8208160149
- --8208160153 LER 82-041/03L-0 on 820423 containment air lock outer door seal failed on local leak rate test Caused by dirt & foreign matter Sealing surfaces cleaned & testing successfully completed RAY.H B Southern California Edison Co 82/08/06 Region 5, 82/08/06 Price of Director ip 14345 095 24X Fiche 50-361,82/08/05,8208160149
- B20B180024 Forwards LER 82-048/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co B2/08/06 ENGELKEN.R H Region 5. Office of Director 2pp 14377 171 24X Fiche 30-361.82/08/06.8208180024
- --8209180031 LER 82-048/03L-0 on 820708, while in Mode 4, containment airborne monitor 2RT-7804-1 declared inoperable due to failure to meet surveillance requirements Caused by de-energizing of containment isolation valve 2HV-7801 RAY.H B Southern California Edison Co 82/08/06 Region 5, Office of Director 1p 14377 173 24X Fiche 80-361,82/08/06,820880024
- 8208180023 PND-V-82-034 on 820811.unscheduled shutdown initiated due to suspected increased RCS leakage rate from packing leakoff of pressurizer spray valves Completion of low power physics testing & natural circulation testing postponed KTRSCH.DF Region 5. Office of Director 82/08/12 ip 14377 174 24X Fiche 50-361,82/08/12.8208180023
- 8208200345 Forwards LER 82-069/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co 82/08/12 ENGELKEN, R H Region 5. Office of Director 2pp 14393 266 24X Fiche 30-361.82/08/12.8208200145
- --8208200152 LER 82-069/03L-0 on 820713. while in Mode 4, containment isolation valve declared inoperable due to failure to meet surveillance Tech Spac Caused by loosening of limit switch due to vibration Switch adjusted & tightened RAY. M.B. Southern California Edison Co. 82/08/12 Region 5, Office of Director. 1p. 14393-268 24X Fiche 50-361,82/08/12.
- 8208200251 Forwards LER 82-042/01T-0 Detailed event analysic submitted RAY, H B Southern California Edison Co 82/08/12 ENGELKEN, R H Region 5, Office of Director 2pp 14397 313 24X Fiche 50-361, 82/08/12, 8208200251
- --8208200269 LER 82-042/01T-0 on 820729; during Mode 3, stroke time for valves 2HV4706 & 2HV4713 exceeded Tech Spec allowable response times Caused by improper limit switch Setting corrected & acceptance criteria added RAY, M B Gouthern California Edison Co 82/08/12 Region 5, Office of Director 1p 14399 315 24X Fiche 50-361, 82/08/12, 8208200251.
- 8208200018 Forwards LER 82-046/03L-0 Detailed event analysis submitted RAY, H 8. Southern California Edison Co 82/08/13. ENGELKEN, R H Region 5. Office of Director 2pp 14392, 247 24X Fiche 50-361.82/08/13.8208200018

- --8208200027 LER 82-046/03L-0 on 820714, pilot flame of Train A toxic gas isolation sys butane monitor associated w/control room ventilation sys was extinguished Caused by depletion of hydrogen fuel to pilot Fuel replenished & pilot relit RAY.H B Southern California Edison Co 82/08/13 Region 5, Office of Director 1p 14372 249 24X Fiche 50-361, 82/08/13, 8208200018
- 8208200182 Forwards LERs 82-044/03L-0,82-049/03L-0,82-050/03L-0,82-051/03L-0,82-053/03L-0,82-057/03L-0,82-049/03L-0 &82-051/03L-0 Detailed event analysis submitted RAY,H B Southern California Edison Co 82/08/13 ENGELKEN,R H Region 5, Office of Director 2pp 14398 336 24% Fiche 50-361,82/08/13,8208200182
- --8208200204 LER 82-044/03L-0 on 820715, condensate storage tank T-121 water level fell below Yech Spec limit on four occasions Caused by inadequate makeup water control to tank Tech Spec change initiated to install automatic level control RAY.H B Southern California Edison Co 82/08/13 Region 5, Office of Director ip 14378 338 24X Fiche 50-361, 82/08/13, 8208200182
- --8208200213 LER 82-049/03L-0 on 820716, condensate storage tank T-121 water level fell below Tech Spec limit on two occasions. Gaused by inadequate makeup water control to tank Tech Spec change initiated to install automatic level control RAY.H B Bouthern California Edison Co. 82/08/13 Region 5, Office of Director lp 14398:339, 24X Fiche: 50-361, 82/08/13, 8208200182
- ---B20B200221 LER 82-050/03L-0 on B20717, condensate storage tank T-121 water level fell below Tech Spec limit on one occasion Caused by inadequate makeup water control to tank Tech Spec change initiated to install automatic level control RAY,H B Southern California Edison Co. B2/08/13, Region 5, Office of Director ip 14398 340, 24% Fiche, 50-361, 82/08/13, 820B200182
- --8208200230 LER 82-051/03L-0 on 820718, condensate storage tank T-12i water level fell below Tech Spec limit on three occasions Gaused by insdequate makeup water control to tank Tech Spec change initiated to install automatic level control.

 RAY.H B Southern California Edison Co 82/08/13. Region 5, 0ffice of Director. 1p 14398 341, 24X Fiche 50-361, 82/08/13, 8208200182
- --8208200236 LER 82-053/03L-0 on 820719; condensate storage tank T-121 water level fell below Tech Spec limit on seven occasions. Caused by inadequate makeup water control to tank Tech Spec change initiated to install automatic level control RAY.H B Southern California Edison Co 82/08/13 Region 5, Office of Director 1pp 14398 342 24X Fiche 50-361,82/08/13,820820182
- --B20B200248 LER 82-057/03L-0 on B20720, condensate storage tank T-121 water level fell below Tech Spec limit on four occasions. Caused by inadequate makeup water control to tank. Fech Spec change initiated to install automatic level control RAY.H B Southern Cellfornia Edison Co. B2/08/13. Region 5. Office of Director 19 14398:343 24X Fichs 50-361,82/08/13, 8208200182.
- --8208200258 LER 82-069/03L-0; on 820728, condensate storage tank T-121 water level fell below Tech Spec limit on two occasions. Caused by inadequate makeup water control to tank Tech Spec change initiated to install automatic level control, RAY, H. S. Southern California Edison Co 82/08/13 Region 5, 0ffice of Director 1p 14398,344 24% Fiche 50-361,82/08/13, 8208200182
- --8208200268 LER 82-071/03L-0 on 820727.condensate storage tank T-121 water level fell below Tech Spec limit on one occasion. Caused by inadequate makeup water control to tank Tech Spec change initiated to install automatic level control RAY.H B Southern California Edison Co 82/08/13 Region 5. Office of Director ip. 14398.345 24X Fiche.50-341.82/08/13.8208200182
- 8208200279 Forwards LER 82-037/03L-0. Detailed event analysis submitted. RAY, H B. Bouthern California Edison Co 82/08/13. ENGELKEN, R. H Region 5, Office of Director. 2pp 14398, 353. 24X Fiche, 50-361, 82/08/13, 8208200279
- --8208200270 LER 82-039/03L-Q on 820716 during monthly surveillance test, emergency chiller E-335 refrigerator compressor in control room emergency air cleanup sys failed to start Caused by defective impeller displacement switch. Buitch bypassed RAY.H B Bouthern California Edison Co. 82/08/13. Region 5. Office of Director ip 14378-355 24X Fiche. 50-361, 82/08/13. 8208200279.

- 8208300030 Forwards LERs 82-070/03L-0 & 82-063/03L-0 Detailed event analysis submitted RAY, H B Bouthern California Edison Co 82/08/18 ENGELKEN, R H Region 5, Office of Director 2pp 14598 244 24X Fiche 50-361, 82/08/18, 8208300030
- ---82083000032 LER 82-070/03L-0 on B20720, while in Mode 3, main steam safety valves found to have pressure setpoints lower than Tech Spec Caused by instrument drift & limitations in procedure used in performing initial adjustment & 18-month tests RAY. H B Southern California Edison Co 82/08/18 Region 5, Office of Director 1p 14598 246 24% Fichs 50-361,82/08/18, B208300030
- --8208300034 LER 82-063/03L-0 on 820719, while in Mode 3, main steam supply safety valve 2P8V-8416 failed to seat properly & pressure setpoint discovered below Tech Spec Caused by instrument drift Valve seating problem checked & corrected KAY. H B Southern California Edison Co 82/08/18 Region 5, 02fice of Director ip 14598 247 24X Fiche 50-361,82/08/18, 8208300030
- 8208300071 Forwards LER 82-040/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co 82/08/18 ENGELKEN, R H Region 5, Office of Director 2pp 14599 003 24X Fiche 50-361, 82/08/18,8208300071
- --9208300072 LER 82-040/03L-0 on 820719, control room emergency chiller E-335 tripped on high bearing temp Caused by faulty high temp bearing elarm module Module replaced RAV. H 8 Southern California Edison Co 82/08/18 Region 5, 0ffice of Director ip 14599 005 24X Fiche 50-361,82/08/18, 82087800071
- 8208300155 Forwards LER 82-066/01T-0 % 82-067/01T-0 Detailed event analysis submitted RAY. H. B Southern California Edison Co 82/08/18 ENGELKEN, R. H Region 5, Office of Director 2pp 14478 226 24X Fiche: 50-361: 82/08/18
- --8208300156 LER 82-066/01T-0 on 820719, while in Mode 3; auxiliary feedwater systrain vendered inoperable due to insbility of valve 2HV4706 to open fully Caused by bent & jammed antirotation plate/methanical indicator against yoke guides RAY.H B. Southern California Edison Co 82/08/18 Region 5, Office of Director 1p 14678,228 24X Fiche 50-361,82/08/18,8208300155
- --8208300189 LER 82-067/01T-D on 920720, while in Mode 3, second auxiliary feedwater systrain rendered inoperable due to inability of valve 28/47/3 to open fully Caused by loose coupling lock nuttallowing actuator shaft to separate from valve stem. RAY-H B Southern California Edison Co 82/08/18 Region 5, Office of Director 1s. 14678 229 24% Fichs 50-361,82/08/18, 8208300155
- 8208300037 Forwards LER 82-045/03L-0. Detailed event analysis submitted. RAY, H. B. Southern California Edison Co. 82/08/20 ENGELKEN, R. H. Region 5. Office of Director 2pp. 14598 274 24X fiche 50-361. 82/08/20. B208300037.
- --BROBESCOOST LER B2-045/OSL-O on R20723, while in Mode 4,120-voit ac vital bus 2VOI de-energized from associated inverter. Caused by disconnection of jumper placed across three fuses during replacement Bus re-energized to alternate power supply RAV.H B. Bouthern California Edison Co B2/OB/20, Region 5, Office of Director lp 14578 276 24X Fiche 50-361,82/OB/20,8208300037.
- T Hearing transcripts on non-antitrust matters
- 8208130026 Transcript of 820624 affirmation/discussion session & public meeting re unescorted access to protected area & low power OL for Ban Onofre 2 in Washington, DC Pp 1-7 Bupporting documentation encl
 # Commissioners 82/06/24 15pp, 14341, 289, 24X fiche. 50-361, 82/06/24, 8208130026
- 8208090282 Transcript of 820728 public meeting re discussion & possible vote on full power GL for facility in Hashington, DC, Pp 1-110 Viewgraphs encl.
 # Cammissioners 82/07/28 136pp. 14306-316, 24% Fiche: 50-361, 82/07/28, 8208090282.

- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3 A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list enci DIRCKS, H J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fiche 50-000,82/07/02,8207080064
- 8208030075 Notification of 820727 meeting w/util in Bethesda.MD to discuss inadequate core cooling instrumentation ROOD.H Licensing Branch 3 B2/07/26 MIRAGLIA.F.J Licensing Branch 3 4pp 14200 342 24X Fiche 50-361.82/07/26
- 8208030493 Informs that util is finalizing scope of work for EVOUGHTMS INFORMS that Util is finalizing scape of work for preparation of responses to NRC 820327 questions re rapid depressurfiation & decay heat removal w/a power operated relief valves Responses will be sent by 830,630 MRAGLIA Licensing Branch 3 ip 14154 086 24% Fiche 50-361,82/07/30,8208030493 B2/07/30 MIRAGLIA F
- 8208030171 Forwards "Supplemental Rept Control of Heavy Loads for San Onofre Nuclear Generation Station Units 2 & 3," in response to 820617 telcon re 810707 submittal on NUREG-0612, "Control of Heavy Loads"

 BASKIN,K F Bouthern California Edison Co 82/08/03 MIRAQLIA,F Licensing Branch 3 2pp 14211 200 24X Fiche 50-361,82/08/03, Licensing Branch 3 2pp 8208050171
- --9208050178 "Supplemental Rept Control of Heavy Loads for Ban Onofre Nuclear Generation Station Units 2 & 3 " * TERA Corp B-82-273 82/07/31 46pp. 14R11 202 24X Fiche 50-361.82/08/03.8208050171
 - OB090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & splicants re submittal of documents to NRC Summarizes 10CFR vapter I requirements & provides alternatives to quirements Stories to ENHUT, D Q Division of Licensing 82/08/09 Consolidated ison Co of New York ip 14356-332 24X Fiche 50-000.82/08/09, 08090194
 - 130085 Forwards first draft of Tech Specs, in response to NRC 820715 quest for all data to prepare Tech Specs BKINK P Bouthern California Edison Co 82/08/11 MIRAQLIA: F J icensing Branch 2 Ip 14333 275 24x Fiche 50-362.82/08/11. icensing Branch 3 3813089
 - DB13008B First draft of proposed Tech Specs * Southern California Edison Co 82/04/28 375pp 14333 276. 24X Fiche 50-362,82/08/11,8208130085
 - 140013 Forwards status/schedule of NUREG-0737 items for which util tuests implementation date exemptions,per NRC 820715 IVest SKIN, K P Southern California Edison Co. 82/08/12 MIRAGLIA.F ranch 3 3pp 14345 001 24% Fiche 50-362,82/08/12, MIRAGLIA, F J Icensing Branch 3 08160013
 - 260600 Bummary of 820729 meeting w/util & contractors re EBF twation sys surveillance requirements Addl info requested o support proposed Tech Spec changes (DOD), H Licensing Branch 3 82/08/12 Licensing Branch 3 4569 147 24X Fiche 50-361,82/08/12,8208260600 Licensing Branch 3 Ip econ, H 14569 147
 - 08200225 Requests NRC reconsider position & formally respond to util B20723 Amend Application B to License NPF-10, requesting extension of surveillance internal for ESF actuation syssubgroup relays to 18-month interval, Justification encl. BASKIN, K. P. Bauthern California Edison Co. B2/08/16 MIRAQLIA, F. Licensing Branch 3 12pp 14377 275 24X Fiche. 50-361, 82/08/16. icensing Branch 3 1209 3208200225.
 - 08280363 Discusses corrective actions per NUREC-0737. Item i D 1. "Control Room Design Review," to identify significant human factors & instrumentation problems Beventeen corrective actions identified in License Condition 19F completed RABKIN, K P Bouthern California Edison Co 82/08/19, MIRAGLIA, F Licensing Branch 3, 5pp. 14540 268. 24X Ficha 50-34i,82/08/19,8208250363
- TOB310360 Ack receipt of 810915.820107 & 0201 applications NRR review has determined that applications re Unit 2 are exempt from 'ee requirements Refund currently in progress ILLER,W C License Fee Hanagement Branch 82/08/20 DIETCH,R. 3uthern California Edison Co 2pp 14697 115. 24X 'che 50-361.82/08/20.8208310360

- 8208300295 Forwards outline of sys & equipment required for initial fuel loading & for operational support during initial fuel load, based on listed assumptions Operational support sys not required during fuel load for public health & safety CRANE, P A. Pacific Gas & Electric Co B2/08/24 EIBENHUT, D G Division of Licensing 6pp 14599 227 24X Fiche 50-361,82/08/2 9209300295
- 8208270377 Forwards addl info re turbine gantry crane in response to NUREO-0612. "Control of Heavy Loads " Crane excluded from further evaluation No load drop could impact both trains of ruriner evaluation No load drop could impact both trains of any safe-shutdown sys
 BASKIN,K P Southern California Edison Co 82/08/25 MIRAGLIA,F
 Licensing Branch 3 8pp 14564 283 24X Fiche 50-361,82/08/25,8208270377
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 820803006B Forwards Suppl 6 to SER re application for OL W/o encl MRAOLIA.F J Licensing Branch 3 82/06/30 DIETCH.R Southern California Edison Co 4pp 14200 307 24X Fiche 50-361,82/06/30, 820803006B
- F Security, medical, emergency & fire protection plans
- 8208020376 Responds to 820721 telephone request for status of ingestaon rone planning by State of CA State has retained consultants to do planning Plan will be submitted to FEMA in late Sept 1000 1702. KRIMM.R W Federal Emergency Management Agency 82 GRIMES, B Division of Emergency Preparadness ip Fiche 50-206.82/07/28,8208020376 14150 118 24X
- 8208030201 Revises position in 820727 Itr re fire separation of auxiliary fredwater pumps Metal barrier will be installed in pump room. Util cannot commit to change completion prior to startup following second refueling outage BASKIN, K P Southern California Edison Co 82/07/27 MIRAGLIA.F Licensing Branch 3 ip 14158 257 24% Fiche 50-361,82/07/27.8208030201
- 920Bii0097 Board Notification 82-74 informs of problems w/implementation of Unit 1 physical security plan EIBENHUT, D 0 Division of Licensing 82/08/02 PALLAD GILINBKY, V. AHEARNE, Commissioners 4pp 14329 242 plan /02 PALLADINO, N, J , Fiche 50-361, 82/08/02, 8208110097
- 8208190180 Discusses status of ingestion pathway planning in CA Final evaluation re capability of involved jurisdictions to implement ingestion pathway plans must await drills expected in late Aug/early Sept 1782 KRIMAR W Federal Emergency Management Agency 82/08/05 GRIMES, BK Division of Emergency Preparadness App 14386 353 24X Fiche 50-206,82/08/05,8208190180
- B208270696 Responds to 820630 ltr re changes to facility physical 208270676 Responds to 820630 itr me changes to facility pi security pian, Revision 5 NRC concurs w/changes except provisions in Section I 3 1,4 re protected & vital areas CRUTCHFIELD.D Operating Reactors Branch 5 82/08/17 Southern California Edison Co 3pp 14683 051 24X Fiche-50-206:82/08/17.8208270696 BASKIN, K P
- 8208230023 Forwards Revision 6 to Mar 1981 physical security plan.
 Revision withheld (ref lOCFR/3 21)
 BASKIN,K P Southern California Edison Co 82/08/18 EISENHUT,D 0
 Division of Licensing, ip 14517 227 24X Fiche 50~206,82/08/18,
- 8208260276 Releases public version of revised emergency plans FELTON, J M Division of Rules and Records 82/08/20 Docum Management Branch 1p 14579 290 24X Fiche 50-361,82/08/20,8208260276.
- --8208260300 Forwards public version of revised emergency plans, including State of CA emergency response plan, County of Orange, CA incident response plan & facility onsite & offsite emergency response plans
 BASKIN, K P Southern California Edison Co 82/07/08 MIRAGLIA.F
 Licensing Branch 3. 2pp 14579,292 24X Fiche 50-361.82/08/20, MIRAGLIA, F 8208240296
- --B208260307 Public version of revised emergency plan, including State of CA emergency response plan & County of Orange.CA incident response plan One oversize drawing encl Aporture card evailable in PDR

 * Southern California Edison Co * San Diego Gas & Electric Co B2/06/11 2,000pp 14579,274 24X Fiche 50-361.82/08/20, 8208260276

--8208260309 Central Files version of Revision 3 to analysis of time required to evacuate transient & permanent population from various areas within plume exposure pathway emergency planning some planning form * Wilbur Smith & Associates 82/06/30 117pp 14986 235 24X Fichs 50-361,82/08/20,8208260296

G Adjudicatory correspondence

- B208160050 Order CLI-82-14 rendering ASLB B20111,0514 & 0616 decisions effective License allowing operation up to 57 power may be issued Order does not authorize issuence of full power licenses

 CHILK.5 J Office of the Secretary of the Commission 82/07/16
 App 14344 299 24% Fiche 50-361,82/07/16,8208160050
- 8208i10156 Brief in opposition to intervenor 820629 appeal of ASLB 820514 initial decision on emergency planning ASLB correctly assessed radiation manitoring capability Adequate measures will protect special populations W/Certificate of 8vc PIGOTT, D R Southern California Edison Co PIGOTT, D R San Diego Cas & Electric Co PIGOTT, D R Anaheim, CA 82/08/04 Atomic 84fety and Licensing Appeal Panel 32pp 14314 242 24X Fiche 50-361, 82/08/04, 8208110156
- 8208100008 Confirmation of emergency preparedness items, transmitting DB Matthews affidavit certifying that siren sys performs in accordance w/Tech 8pecs Issue of ingestion pathway emergency planning ione to be addressed later.

 CHANDLER, L J Hearing Branch 2 82/08/06 ip 14276 335, 24X Fiche 50-361,82/08/06,8208100008
- --8208100019 Affidavit of DB Matthews certifying that siren sys will perform in accordance w/Tech Specs Certificate of Svc encl MATTHEWS.D.B Section B (Pre 820201) 82/08/04 7pp 14296 3: 24K Fiche 30-341.82/08/04.8208100008 14294 334
- 8208110067 Hemorandum & order re need for further proceedings on adequacy of offsite planning for medical svcs FEMA must respond to listed questions by 820903 KELLEY, J. L. Atomic Safety and Licensing Board Panel 82/08/06 7pg 14337 070 24X Fiche 50-361.82/08/06.8208110067
- 8208130146 Forwards ASLD 820806 memorandum & order directing FEMA to answer questions re adequacy of offsite planning for medical svcs SCINTO, J Hearings Division 82/08/11 PERRY, S W Federal Emergency Management Agency 1p 14339 069 24X Fiche 50-361, 82/08/11, 8208130144
- 8208160142 Response in opposition to QUARD & AS Carstens et al 820701 brief supporting appeal of ASLB Initial Decision.LBP-82-39, on emergency planning Intervenors failed to show reversible error Certificate of Svc encl
 CHANDLER,L J Hearing Branch | 82/08/13 Atomic Bafety and Licensing Appeal Panel | 40pp | 14344 089 | 24X Fiche.50-361, 82/08/13,8208160142
- 8208200220 Order extending time until 820910 for Commission to act to 10B200220 Dreet extending the Secretary of the Commission 82/08/18 Commission 82/08/18 Commission 82/08/18 Commission 82/08/18

M Antitrust correspondence

- 8208030288 Forwards Amend 1 to San Onofre Units 1 & 2 participation 200030298 rorwards Amend I to San Underworks I & 2 participation agreement among Southern CA Edison Co.San Diego Gas & Electric Co.City of Anaheim & City of Riverside whereby City of Anaheim purchased addl awnership interest DIETCH.R Southern California Edison Co 82/07/09 EISENHUT, D G. Division of Licensing 16pp 14156 247 24X Fiche, 50-361, 82/07/09.
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance B2/07/16
 Consolidated Edison Co of New York 87pp 14356,274 24X
 Fiche: 50-000.82/07/16.8204210393
- 8204210395 IE Info Notice 81-26.Part 3, Buppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ. of 112pp 14398 001 24X Fiche 50-000,82/07/19,8204210395 8204210375

- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuatore Upon Gradual Loss of Air Pressure " Svc list encl URDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/720 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HFCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194-120 R4X Fiche 50-000,82/07/23,8204210402
- 8204210403 lE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 12ipp 14357.013 24X Fiche 30-000,82/07/26,8204210403
- 8208160415 Forwards IE Insp Rept 50-362/82-14 on 820712-16 No Obligator visited and the moncompliance noted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/07/27 PAPAY, L. T Southern California Edison Co 20p. 14348 177 24X Fiche 50-362.82/07/27.8208160415
- ---8208160422 IE Insp Rept 50-362/82-14 on 820712-16 No noncompliance noted Major areas inspected safety-related components & structures & licensee action on previously identified insp items W.J., HERNANDEZ.O., PEREZ.O Division of Resident, Reactor Project & Engineering Programs B2/07/26 Spp 14348 179 24X Fiche 50-362,82/07/27,8208160415
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance. B2/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche. 50-000, 82/07/28, 8204210405
- 8208140072 Reiterates Biill3 response to IE Bullstin 81-02, "Failure of Gate Type Valves to Close Against Differential Pressure," signed under oath or affirmation Recommended corrective action completed BASKIN,K P Southern California Edison Co. 82/07/30, ENGELKEN,R.H. action completed BASKIN.K P Southern California Edison Co. B2/C Region 5. Office of Director 2pp 14342 071 Ficher 50-361.82/07/30.8208160072
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement," Svc list and I URDAN,E L Division of Engineering & Quality Assurance 82/08/05, Consolidated Edison Co of New York 117pp 14388 201, 24X Fiche 50-000, 82/08/05, 8204210407.
- 8208230249 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants," consisting of rept of info requested in Action Item 3 on threaded fasteners Ropt satisfies Action Item 3 on threaded HAYNEB.J 0 Southern California Edison Co. 82/08/10, ENGELKEN, R. H. Repton 5, Office of Director. App 14508-351 24X Fiche: 50-361, 82/08/10, 8208230249.
- 8208270533 Ack receipt of 820812 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/82-22 & 50-362/82-12.
 BISHOP,T W. Division of Resident, Reactor Project & Engineering Programs 82/08/20, PAPAY,L T Southern California Edison Co. ip 14566-024. 24X Fiche-50-361, 82/08/20, 8208270533
- --8208270538 Responds to NRC 820714 ltr re violations noted in IE Insp Repts 50-361/82-22 & 50-362/82-12 Corrective actions Unit 2 housekeeping conducted during wk of 820722-24 in preparation for initial criticality PAPAY.L.T Southern California Edison Co. 82/08/12 ENGELKEN.R H Region 5, 04916:e of Director 5pp 14566; 025, 24X Fiche: 50-361,82/08/20,8208270533

- S Reportable occurrences, LERs & related correspondence
- 8208030206 Final deficiency rept re misinterpretation of design documents & design error in wiring between control rod cabinets & core protection calculator Initially reported on 820623 Documents to be reviewed for clarity PAPAY.L T Southern California Edison Co 82/07/19 ENGELXEN, R. H Region 5, Office of Director 4pp 14159 360 24X Fiche 50-362, 82/07/19,8208030206
- 8208030337 Final deficiency rept re gas radiation monitors [nitially reported on 820622 Nuclear grade sealant.loctite PST 58031. applied to detector assembly leak area, spacer replaced & Instruments calibr PAPAV.L T Southern California Edison Co 82/07/21. ENGELKEN.R H Region 5, Office of Director 4pp 14156 338, 24X Fiche 50-362,82/07/21,8208030337
- 8208050434 Final deficiency rept re defective bearings mfg by Control Components. Inc in manual steam dump to atmosphere valve actuators Initially reported on 820628 Searings & races replaced in both Units 2 & 3 PAPAV.L T Southern California Edison Co 82/07/23 ENGELKEN.R H Region 5. Office of Director 3pp 14214 072 24X Fiche 50-362.82/07/23.8208050434

DOCKET 30-363 FORKED RIVER NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements to provides alternatives to requirements Bvc list enci EISEMHUT.D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14354 332 24X Ficher 50-000, 82/08/09, 8208090194
 - Inspection reports, IE Bulletins & correspondence
- 208160164 Act receipt of 820228 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-363/80-02 SNYDER.O L Division of Emergency Preparedness & Operational Support 82/08/09, CARROLL.J.T Jersey Central Power & Light Colp 14345 076 24X Fiche 50-363.82/08/09,8208160164
- --820816016B Responds to NRC itr re-violations noted in IE Insp Rept 50-343/82-02 Corrective actions soil stabilization work began 620504 & should be complete by 820830 CLARK.F R. Jersey Central Power & Light Co 82/07/28 HAYNES,R C Region I. Office of Director 2pp 14345:097 24X Fiche 50-363,82/08/09.8208160164
- Security, medical, emergency & fire protection plans
- |208090135 Forwards IE Safeguards Insp Repts 50-348/82-14 & 50-364/82-13 on 820524-28 & notice of violation, Notice of violation withheld (ref 10CFR/3, 21) LEMTS, R C Division of Project & Resident Programs 82/06/29, McDDNALD, R P Alabama Power Co. ip 14269 238 24X Fiche 50-348, 82/06/29, 8208090135
- --8208090138 IE Safeguards Insp Repts 50-349/82-14 & 50-344/82-13 on 820524-28. Noncompliance noted failure to provide compensatory measures for degraded assessment capability. Datails withheld (ref 10CFR 73 21)
 TILLMAN.A Region 2. Office of Director. 82/06/28 2pp 14249 237 24X Fiche 50-348, 82/06/29, 8208090135.
- 8208030305 Forwards IE Insp Repts 50-348/82-15 & 50-344/82-14 on 820407-10 No noncompliance noted DANCE, H C Division of Project & Resident Programs. 82/07/09 MCDONALD, R P Alabama Power Co 2pp 14156:269 24X Fiche 50-348,82/07/09.8208030305
- --8208030323 IE Insp Repts 50-348/82-15 & 50-364/82-14 on 820607-10.No noncompliance noted Major areas inspected followup on amergancy preparedness findings MARBION.R R Division of Emergancy Praparedness & Operational Support 82/07/07 5pp 14156:271 24X Fichs 50-348,82/07/07,8208030305
- 9208030467 Forwards IE Insp Repts 50-349/82-17 & 50-364/82-16 on 820622-25 No noncompliance moted, DANCE, H C. Division of Project & Resident Programs. 82/07/09 MCDONALD, R P. Alabama Power Co. 2pp. 14163 098 24X Fiche 50-348,82/07/09.8208030467.

- --8208030476 IE Insp Repts 50-348/82-17 & 50-364/82-16 on 820622-29 No noncompliance noted Major areas inspected fire protection & prevention MILLER, W.H. Division of Engineering & Technical Programs 82/07/06 7pp 14163 100 24X Fiche 50-348, 82/07/09, 8208030467
- 8208020059 Advises that 820412 changes to security plan & security personnel training & qualification plan acceptable Exceptions noted in encl Response to encl comments on exceptions requested within 30 days of receipt of itr. VARQA, S. A. Operating Reactors Branch 1 82/07/13 CLAYTON, F. L. Alabama Power Co. 3pp. 14181 056 24X Fiche 50-348, 82/07/13. 820802059
- 8208020243 Forwards add1 info re mods to present containment fire protection measures for 100FR50 App R requirements, per 820618 exemption request CLAYTON.F L Alabama Power Co 82/07/27 VARGA.B A Office of Nuclear Reactor Regulation, Director 7pp, 14151 224 24X Fiche 50-348, 82/07/27, 8208020243
- 8208090178 Ack receipt of 820724 ltr informing NRC of steps taken to correct violations noted in IE Gafeguards Insp Repts 50-348/22-14 & 50-344/82-13 LEWIS,R C. Division of Project & Resident Programs 82/08/05 MCDDNALD.R P Alabama Power Co 1p 14270 358 24X Fiche 50-348,82/08/05,8208090178
- --8208090181 Responds to NRC 820629 ltr re violations noted in IE
 Safeguards Insp Repts 50-348/82-14 & 50-364/82-13 Response
 withheld (ref 10CFR73 21)
 CLAYTON.F L Alabama Power Co 82/07/26 LEWIS.R C Division of
 Project & Resident Programs ip 14270 359, 24X
 Fiche 50-348,82/08/05.8208090178
- 8208230079 Forwards details of screening measures applied to new employees prior to being granted interim unescorted access, in response to NRC 820713 ltr.Revised security plan will be submitted within next 2 wks Encl withheld (ref 10CFR73 21). CLAYTON, F. L. Alabama Power Co. 82/08/11 VAROA, B.A. Office of Nuclear Reactor Regulation, Director 1p 14517 140 24X Fiche 50-348, 82/08/11,8208230079
- 8208310087 Releases public version of temporary change to revision of emergency plan procedure FELTON, J M Division of Rules and Records, 82/08/11 Document Hanagement Branch Ip 14697-250 24X Fiche 50-348,82/08/11,8208310087
- --8208310070 Public version of Temporary Procedure Change 10A to Revision 10 of Emergency Plan Procedures FNP-0-EIP-16, "Emergency Equipment & Supplies." Procedure request form encl. * Alabama Power Co 82/07/06 13pp 14597 251 24X Fiche 50-348,82/08/11,8208310087
- P Operating license stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl.

 DIRCKS, U J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co. of New York 93pp 14194 001
 24K Fiche 50-000,82/07/02,8207080064
- 8208040342 Informs that evaluation of response to NUREG-0737, Item II K 3 25. "Loss of AC Power to Reactor Coolant Pump Seals." adequately demonstrates that integrity of seals is maintained during loss of offsite power. Item resolved NEIGHBORS, J D Operating Reactors Branch 1 82/07/21 CLAYTON, F L Alabama Power Co 2pp 14223 335 24% Fiche 30-348, 82/07/21, 8208040342
- B20B130127 Forwards request for add1 info re NUREO-0737. Item II B. 3. "Post-Accident Sampling Sys." Response required within 20 days Evaluation criteria guidalines encl VARQA.S A Operating Reactors Branch 1 B2/07/22. CLAYTON.F L Alabama Power Co. 10pp 14340 271 24X Fiche 50-348.82/07/22. 820B130127
- 8208260369 Forwards BER input concluding that requirements of NUREO-0737. Items II F. 1 4, II F. 1, 5 & II F 1 6 re accident monitoring instrumentation considered resolved VAROA.8. A Operating Reactors Branch 1 82/07/30 CLAYTON, F L. Alabama Power Co 3pp. 14588.217 24X Fichs 50-349,82/07/30,8208260369
- 9208060255 Application to amend License NPF-8, revising Yech Spec for one-time examption to extend schedule in Surveillance Requirement 4,7 9,a until first refueling outage CLAYTON,F.L. Alabama Power Co. 82/08/02 VARQA,8 A. Office of Nuclear Reactor Regulation, Director, Spp. 14241 304, 24X Fiche: 50-364, 82/08/02, 8208060255

- ---8208060256 Proposed Tech Spec Page 3/4 7-20, extending schedule in Surveillance Requirement 4 7 9 a until first refueling outage for one-time only 4 Alabama Power Co. 82/08/02 1p 14241 309 24X Fiche 30-364,82/08/02,8208060255
- 8208040260 Submits info re noninvasive vessel level sys results
 Neutron detector assemblies do not meet stds & are not
 compatible w/NUREG-0737, Item II F 2 Review of available
 sys initiated Status rept expected by 830201
 CLAYTON, F L Alabama Power Co 82/08/03 VARGA, S A Office of
 Nuclear Reactor Regulation, Director 2pp 14241 295 24X
 Fiche 50-348, 82/08/03, 8208060260
- 8208040263 Application to amend Tech Specs, changing testing & survefilance requirements to prevent overload testing of diesel generators Class III fee encl CLAYTON, F. L. Alabama Power Co. 82/08/03 VARGA, S. A. Office of Nuclear Reactor Regulation, Director 9pp 14241 282 24X Fiche 50-348.82/08/03.8208060263
- --B208060264 Proposed Tech Bpec changes to Bection 4 B 1 1 2 C 5 re surveillance requirements to prevent overload testing of diesel generators # Alabama Power Co B2/08/03 2pp 14241 271 24X Fiche D0-348.82/08/03.8208060263
- 820Bi30174 Forwards Revision 2 to "Inservice Testing Program for Pumps & Valves," requesting further relief from ABME Code Section XI Changes reflect discussions w/E080 following review CLAYTON,F L Alabama Power Co 82/08/06 VARGA,8 A Office of Nuclear Reactor Regulation, Director ip 14338 330 24X Fiche 50~364,82/08/06,820Bi30176
- --820B130180 Revision 2 to "Inservice Testing Program for Pumps & Valves"

 # Alabama Power Co 82/08/06 46pp 14338 331 24X
 Fiche 50-364,82/08/06,8208130176
- B208120162 Responds to Generic Ltr B2-12. "Nuclear Power Staff Working Hours " Shift manning requirements per NUREG-0737. Item I A 13 met No Tech Spec change required CLAYTON.F L Alabama Power Co B2/08/08 EISENHUT.D 0 Office of Nuclear Regulatory Research. Director ip 14317 278 24X Fiche.50-348.82/08/08.8208120162
- 8208070194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list enci EISENHUT.D O Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14354 332 24X Fiche 50-000,82/08/09, 8208090194
- 8208130061 Application to amend Licenses NPF-2 & NPF-B, incorporating Unit 1 Tech Spec acceptance criteria for leak testing reactor coolant sys isolation valves into Unit 2 Tech Spec & deleting Paragraph 4 4 7 3 2 from both units Tech Bace & CLAYTON,F L Alabama Power Co 82/08/10 VAROA,B A Office of Nuclear Reactor Regulation, Director, Spp 14335,058 24X Fichs 50-348,82/08/10,8208130061
- --8208130062 Proposed Tech Spec 3/4 4 7 3 for Unit 2 % revised Tech Specs 4 4 7 3 2 for Unit 1 % 3/4 4 7 2 for Unit 2 re acceptance criteria for leak testing RCS isolation valves.

 * Alabama Power Co. 82/08/10 11pp 14335:063 24X
 Fiche 50-348,82/08/10,8208130061
- 8208230315 Advises that schedule for submittal of addl info re NVREO-0737, Item II B 3. "Post-Accident Sampling Bys" will be provided by 830401, in response to NRC 820722 ltr. Delay due to refueling outages & verification tests of procedures CLAYTON, F L. Alabama Power Co. 82/08/18. VAROA, 8 A. Office of Nuclear Reactor Repulsition, Director ip 14510 352, 24% Fiche 30-348, 82/08/18, 8208230315
- 8208250309 Forwards proposed Tech Spec change delating river water tys loads from diesel generator automatic load sequence Application for license amend will be submitted by Dec 1982. CLAYTON,F L. Alabama Power Cn 82/08/20 VAROA,S,A, Office of Nuclear Reactor Regulation, Director Spp 14538 080 24X Fiche 50-348, 82/08/20.8208250309
- --8208250314 Proposed Tech Spec change deleting river water sys loads from diesel generator automatic load sequence. * Alabama Power Co. 82/08/20. 4pp. 14538 065 24X Fiche 50-348,82/08/20,8208250309

- G Inspection reports. IE Bulletins & correspondence
- 8208090135 Forwards IE Safeguards Insp Repts 50-348/82-14 & 50-364/82-13 on 820524-28 & notice of violation Notice of violation withheld (ref 10CFR73 21) LEMIS,R C Division of Project & Resident Programs 82/06/29 MCDGNALD,R P Alabama Power Co tp 14269 236 24X Fiche 50-348,82/06/27,8208090135.
- --820807013B IE Bafeguards Insp Repts 50-348/B2-14 & 50-364/82-13 on 820824-28 Noncompliance noted failure to provide compensatory measures for depraded assessment capability Details withheld (ref 10CR73 21)
 TILLMAN.A. STANBBERRY.W W Region 2. Office of Director MCGUIRE.D R Division of Engineering & Technical Programs 82/06/28 3pp 14269-239 24X Fiche 50-348.82/06/29.8208090135
- 8208030305 Forwards IE Insp Repts 50-348/82-15 & 50-364/82-14 on 820607-10 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/09 MCDONALD, R P Alabama Power Co 2pp 14156 269 24X Fiche: 50-348, 82/07/09, 8208030305
- --B20B030323 IE Insp Repts 50-34B/82-15 & 50-344/82-14 on B20607-10 No noncompliance noted Major areas inspected followup on amergency preparedness findings MARSTON, R R, JENKINS, O R Division of Emergency Preparedness & Operational Bupport B2/07/07 Spp 14156 271 24X Fiche. 50-348, 82/07/09, 8208030305
- 8208030467 Forwards IE Insp Repts 50-348/82-17 & 50-344/82-16 on 820622-25 No noncompliance noted DANCE.H C. Division of Project & Resident Programs 82/07/09. HCD0NALD.R P. Alabama Power Co. 2pp 14143 098 24X Fiche 50-348, 82/07/09, 8208030467
- --8208030476 IE Insp Repts 50-348/82-17 & 50-364/82-16 on 820622-25 No noncompliance noted Major areas inspected fire protection & prevention MILLER, W.H., CONLON, T.E. Division of Engineering & Technical Programs 82/07/06 7pp 14163 100 24% Fichs 50-348,82/07/09,8208030467
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance. B2/07/16 Consolidated Edison Co. of New York 87pp 14356 274 24X Fichs 50-000, 82/07/14, 8204210393
- 8204210395 IE Info Notice B1-26, Part 3, Suppl i, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Bvc list encl,
 JORDAN, EL Division of Engineering & Quality Assurance, 82/07/19
 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395,
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl. JORDAN,E L. Division of Engineering & Quality Assurance, 82/07/20, Consolidated Edison Co. of New York 112pp 14381.001 24X Fiche: 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L.I Division of Fuel Facilities, Materials & Bafeguards, 82/07/20. Consolidated Edison Co of New York 7ipp, 14357:276 24X Fiche:50-000.82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures," Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Editon Co. of New York 112pp 14194:321 24X Fichs. 50-000, 62/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Bvc list enc! JORDAN, E.L. Division of Engineering & Quality Assurance, 62/07/23 Consolidated Edison Co. of New York 122pp. 14380;115, 24X Fiche: 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs," Svc list encl. JORDAN, E.L. Division of Engineering & Guality Assurance, 82/07/23, Consolidated Edison Co. of New York, 127pp. 14194:120 24X Fiche: 50-000, 82/07/23, 8204210402,
- 8208030353 Ack receipt of 820707 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-348/82-13 & 50-348/82-12 LEWIS.R.C. Division of Project & Resident Programs. 82/07/23, HCDDNALD.R.P. Alabama Power Co is 14157,089, 24X Fiche: 50-348, 82/07/23, 8208030353.

- --8208030356 Responds to NRC 820414 ltr re violations noted in IE Insp Repts 50-348/82-13 & 50-364/82-12 Corrective actions containment spray suction valves from refueling water storage tank opened & personnel counseled CLAYTON.F.L. Alabama Power Co. 82/07/07 LEWIS.R.C. Region 2. Office of Director 2pp 14157 090 24X Fiche 50-348,82/07/23. 8208030353
- --B208030361 Forwards IE Insp Repts 50-348/82-13 & 50-364/82-12 on 820416-0515 & notice of violation LEWIS.R G. Division of Project & Resident Programs 82/06/14 HCDDNALD.R P A14bama Power Co 2pp 14157 092 24X Fiche 50-348,82/07/23,8208030333
- --8208030367 IE Insp Repts 50-348/82-13 & 50-364/82-12 on 820416-0515 Nancompliance noted failure to follow procedure to determine which engineered safety sys valves were in off-normal position BRADFORN H , PEEBLES, T A , BROWNLEE, V L Division of Project & Resident Programs. 82/06/11, 7pp 14157 095 24X fiche 50-348, 82/07/23, 8208030353
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Steeves in RCS Piping at Certain Mestinghouse PNR Power Plants " Svc list encl JORBAN,E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche: 50-000, 82/07/28, 8204210405
- 8208160211 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants" Possible leakage found past steam generator manuays on three generators. List of botted closures entil CLAYTON.F.L. Alabama Power Co. 82/08/02 D'REILLY, J.P. Region: Office of Director 4pp 14344 161 24X Fiche 50-348,82/08/02,82/08/0211.
- 8204210407 IE Info Natice 82-27, "Fuel Rod Dagradation Resulting From Baffle Water-Jot Impingement" Svc list encl JDRDAN,E L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Ficher 50-000, 82/08/05.0204210407
- 8208090178 Ack receipt of 820724 ltr informing NRC of steps taken to correct violations noted in IE Safequards Insp Repts 50-348/82-14 & 50-344/82-13 LEWIS.R C Division of Project & Resident Programs 82/08/05 MCSDMALD,R P Alabama Power Co. 1p 14270 358 24X Fiche 50-348,82/08/03,8208090178
- -8208090181 Responds to NRC 820629 ltr re violations noted in IE
 Bafeguards Insp Repts 50-348/82-14 & BO-364/82-13 Response
 withhold (ref 10CFR73 21)
 CLAYTON,F L Alabama Power Co 62/07/26 LEWIS,R C. Division of
 Project & Resident Programs ip 14270 359 24X
 Fiche: 50-348, 82/08/05, 8208090178
- R Periodic operating reports & related correspondence
- 8208160096 Forwards monthly operating rept for Jul 1982 CLAYTON,F L. Alabama Power Co. 82/08/11 Office of Resource Management, Director. 2pp 14342 001 24X Fichs 50-364,82/08/11, 8208160096
- ~-8208160099 Monthly operating rept for Jul 1982 HAIRSTON, 0. Alabama Power Co 82/08/05 3pp 14342 003 24X Fishe 50-364,82/08/11,8208160096
- 8 Reportable occurrences. LERs & related correspondence
- #207010228 Forwards LERs 82-027/03L-0 & 82-023/03L-0 CLAYTON, F L Alabama Power Co 82/06/25. Region 2, Office of Director 1p 13672-313 24% Fiche 30-348,82/06/25,8207010228
- --8207010251 LER 82-023/03L-0 on 820528. determined that FNP-2-STP-19 3 not performed within time interval specified by Tech Spec 4 0 5. Caused by personnel error FNP-2-STP-19 3 satisfactorily performed HARRSTON, W. G. Alabama Power Co. 82/04/25. Region 2, Office of Director. 2pp 13472 315 24X Fiche 50-348.82/04/25.8207010228
 - 20227 Forwards LERs 82-035/03L-0 & 82-026/03L-0. .YIDN.F.L. Alabama Power Co 82/07/30 Region 2. Office of actor. ip. 14326-348 24X Fiche: 50-348, 82/07/30, 8208120227

- --8208120231 LER 82-026/03L-0 on 820710, during performance of FNP-2-STP-612 O, 2A reactor coolant pump undervoltage relay 27-3 declared inoperable Caused by sotpoint drift Relay setpoint adjusted & relay declared operable HAIRSTON W G Alabama Power Co 82/07/30 Region 2, Office of Director 1p 14326 349 24X Fiche 50-348, 82/07/30, 8208120227
- 8208200164 Forwards LERs 82-037/03L-0,82-039/03L-0 & 82-030/03L-0 CLAYTON,F L Alabama Power Co 82/08/11 Region 2, Office of Director 1p 14399 272 24X Fiche 50-348,82/08/11,8208200164
- --8208200190 LER 82-030/03L-0 on 820713, steam Jet air ejector noble gaj monitor (RE-15) declared inoperable due to erroneous high indication Caused by faulty detector Detector replaced HAIRSTON, W G Alabama Power Co 82/08/11 Region 2, Office of Director 1p 14379 275 24X Fiche 50-348,82/08/11,8208200164
- 8208270254 Forwards LERs 82-039/03L-0 & 82-031/03L-0 CLAYFON, F L Alabama Power Co 82/08/17 Region 2, Office of Director 1p 14563 094 24X Fiche 50-348,82/08/17,8208270254
- --B20B270267 LER 82-031/03L-0 on 820726, instrumentation loop associated wisteam flow transmitter FT-476 declared inoperable when transmitter failed low Caused by faulty power supply card Card replaced, HAIRBTON-60 Alabama Power Co. 82/08/17 Region 2, Office of Director. ip 14563 076 24X Fiche 30-348,82/08/17,8208270254
- 8208300311 Forwards LER 82-032/03L-0 CLAYTON,F L Alabama Power Co 82/08/19 Region 2, Office of Director 1p 14679 197 24% Fiche 50-364,82/08/19,8208300311
- --8208300320 LER 82-032/031-0.on 820722.RCS subcooling monitor Channal 2 & containment hydrogen analyzer 28 declared insperable when 20 inverter failed Caused by failure of primary power supply Power supply replaced HAIRSTON.H Q Aladema Power Co 82/08/19 Region 2, Office of Director 1p 14679 198 24X Fiche 50-344.82/08/19,8208300311
- DDCKET 50-346 EDWIN : HATCH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8208040040 Releases public version of revised emergency plan procedure FELTON.J K Division of Rules and Records 82/08/02 Document Management Branch 1p 14282,029 24X Fiche 50-321,82/08/02,82080640040
- --B208060044 Forwards public version of Revision 11 to Emergency Plan Frocedure MNP-B002, "Radiation Exposure Limits" Receipt form encl BORRELL.E C Georgia Power Co B2/07/29 NRC - No Detailed Affiliation Given to 14282 030 24X Fiche 50-321,82/08/02,
- --8208060047 Public version of Revision 11 to Emorgency Plan Procedure HNP-8002. "Radiation Exposure Limits" BHITH,D., PHILPOTTS,D Georgia Power Co. 82/07/21 11pp 14282 031 24X Piche 50-031-82/08/02.8208040040
- 8208060051 Releases public version of revision to emergency plan procedure FELTON, J M Division of Rules and Records 82/08/02 Document Management Branch ip 14282 1/8 24X Fiche 50-321,82/08/02, 8208060051
- --8208060055 Forwards public version of Revision 3 to Emergency Plan Procedure HNP-4621. "Actions for All Personnel in Site Area Emergency " Receipt form encl SURRELL.E' C Georgia Power Co 82/07/23 NRC No Detailed Affiliation Given ip 14282 119 24X Fiche 50-321.82/08/02:8208060051
- --8208060097 Public varsion of Revision 3 to Emergency Plan Procedure HNP-4621. "Actions for All Personnel in Site Area Emergency." RIDERS, H H Georgia Power Co 82/07/21 App 14282 120 24X Fiche 50-321,82/08/02,8208060051.
- 8208100308 Forwards IE Safeguards Insp Repts 50-321/82-22 & 50-366/82-20 on 820718-22 No noncompliance noted DANCE, H. C. Division of Project & Resident Programs 82/08/05 KELLY, R. J. Georgia Power Co. 2pp 14297:135 24X Fichs 50-321.82/08/05,8208100308

- --B20B10031B IE Bafeguards Insp Repts 50-321/82-22 & 50-346/82-20 on B20718-22 No noncompliance noted Major areas inspected security plan & procedures, security organization, program audit, records & repts Details withheld (ref 10CFR73 21) MOURE, D E Division of Project & Resident Programs 82/08/03 1p 14297 137 24X Fiche 50-321,82/08/05,820B10030B
- 8208110246 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 62/08/05 Document Management Branch 1p 14331 104 24X Fiche 50-321,82/08/05, 8208110246
- --8208110248 Forwards public version of Revision 9 to Emergency Plan Implementing Procedure HNP-8006, "Decontamination " SORRELL.E C Georgia Power Co 82/07/27 Office of Nuclear Reactor Regulation, Director ip 14331 105 24X Fiche 50-321.82/08/05.8208110246
- --820Bi10249 Public version of Revision 5 to Emergency Plan Implementing Procedure HNP-8006. "Decontamination" ROGERS,W H Georgia Power Co. 82/07/24 12pp 14331 106 24X Fiche: 50-321,82/08/05,820Bi10246
- B20B2&0217 Responds to NRC 820713 ltr re violations noted in IE Safeguards Insp Repts 50-321/82-15 & 50-366/82-15 Corrective actions withheld (ref 10CFR73 21) Full payment of civil penalty encl
 BECKHAM, J T Georgia Power Co 82/08/12 Director's Office, Office of Inspection and Enforcement 3pp 14554 308 24X Fiche 50-321, 82/08/12, 82/08260217
- 8208270199 Advises of error in assigning IE Safeguards Insp Rept 50-366/82-20 on 820718-22 Correct rept number is 50-366/82-23 Transmittal Itr & rept should be changed to reflect correction DANCE.H C Division of Project & Resident Programs. 82/08/24 KELLY.R J Georgia Power Co 1p 14563 206 24X Fiche 50-321,82/08/24,8208270199

I Financial information

- 8208120129 Forwards Annual Financial Rept 1981 Guarterly financial statements for puriod ending 820630 & projected source of funds statement for CV82 encl.

 BROWN,M T Georgia Power Co 82/08/09 SALTZMAN,J Antitrust & Ecanomic analysis Branch (Utility Finance) 7pp 14319 237 24X Fiche 50-000, 82/08/09, 8208120129.
- --B208120134 Annual Financial Rept 1981 SCHERER.R W , MILLER.J H. Georgia Power Co 82/02/19 27pp 14319 245. 24X Fiche.50-000, 82/08/09.8208120129

J Insurance & indemnity information

- 820B170074 Forwards Endorsement 72 to ANI Policy NF-215 & Endorsement 5B to MAELU Policy MF-70 FIEDLER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc DIV. 82/08/12 SALTZMAN J. Assistant Director for State & Licensed Relations 3pp 14358 130 24X Fiche 50-321,82/08/12,8208170074
- 8208170200 Forwards Endorsement 73 to NELIA Policy NF-215 & Endorsement 59 to MAELU Policy MF-78 FIELDER, J Marsh & McLennen, Inc., M & M Nuclear Consultants, Inc DIV 82/08/12 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 14366 252 24X Fiche 90-321,82/08/12.8208170200

P Operating license stage documents & correspondence

- 82070B0064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Bvc list encl.

 DIRCKE, W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York. 93pp 14194.001 24X Fiche 50-000,82/07/02,8207080064
- 9208030743 Advises that review of util 810701 & 0607 responses to Generic Ltr 81-01, "Qualifications for Insp. Exam. Testing & Audit Personnel," complete Commitments & exceptions to Reg Quide 1 58. Revision 1 & Reg Quide 1.146 acceptable, SYOLZ.JF Operating Reactors Branch 4 82/07/14 BECKHAM, J T. Georgia Power Co. 2pp. 14196-344 24X Fiche 50-321,82/07/14, B208030743
- 8208040437 Agraes w/BWR owners group position that six safety/relief valves provide adequate venting in response to util 810701 & 820427 response to NURGO-0737.Item II.B i. "RCB Vents."
 LLL technical evaluation encl
 STOLZ.JF Operating Reactors Branch 4 82/07/22 BECKHAAM.JT Georgia Power Co. 2pp. 14220 182 24X Fiche.50-321,82/07/22,

- --8208040442 "Operating Reactor TMI Lessons Learned NUREG-0737 Response Evaluations (Program III).Project i RCS Vents (Item II B 1)," final technical evaluation rept for Hatch I & 2 BUTCHER: BARNHART.B Laurence Livermore Laboratory FIN A-0246-2 82/06/07 NRC No Detailed Affiliation Given 4pp 14220 184 24x Fiche 50-321,82/07/22.8208040437
- B208030503 Forwards add1 licensing fees based on B20714 reassessment BECKHAM.JT Georgia Power Co 82/07/26 MILLER.W.O. License Fee Management Branch 2pp 14163 123 24X Fiche 50-321.82/07/26.
- 8208040192 Application to amend Licenses DPR-57 & NPF-5, changing ETB to correct surveillance requirements for flow monitoring of gaseous releases from hydrogen recombiner bldg vent BECKHAM, J T Georgia Power Co 82/07/20 Dffice of Nuclear Reactor Regulation, Director 2pp 14188 292 24X Fiche 50-321,82/07/28,8208040192
- --8208040196 Proposed ETS change correcting surveillance requirements for flow monitoring of gaseous releases from hydrogen recombiner bldg vent 4 Georgia Power Co 82/07/28 4pp 14:88 274 24X fiche 50-321,82/07/28,8208040192
- B208060173 Application for amend to License NPF-5, temporarily changing Tech Specs 3/4 8-1 & 3/4 8-2 to extend 72-h limiting condition for operation for one inoperable dissal generator HEAD, 0 F Georgia Power Co B2/07/27 Office of Nuclear Reactor Regulation, Director 3pp 14237 017 24X Fiche 50-366,82/07/27,82/80/60/5193
- ---8208060195 Proposed temporary changes to Tach Specs 3/4 8-1 & 3/4 8-2 to extend 72-h limiting condition for operation for one inoperable diesel generator # Georgia Power Co 82/07/27 13pp 14239 022, 24X Fiche 50-364,82/07/29,8208060193
- 8208090174 Oeneric Ltr 82-14 to all reactor licensees, holders of CF & applicants re submittal of documents to NRC Summarites 10CFR Chapter I requirements & provides alternatives to requirements Svc list enc1
 EISENHUT, D Q Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24% Fiche 50-000, 82/08/09, 8208090194
- 8208270670 informs that review of NUREO-0737. Item II K 3 15. "Mod Break Detection Logic HPCI/Reactor Core Isolation Cooling." completed Reactor core isolation cooling sys adequate based on encl safety evaluation

 STOLZ. J F Operating Reactors Branch 4 62/08/17 BECKHAM, J T Operating Reactors Branch 4 Fiche 50-321, 82/08/17, 8208270490
- 0208270693 Forwards for review, draft technical evaluation re control of heavy loads Util will be asked to participate in conference call w/Franklin Research Ctr & NRC technical reviewers in approx 4 wks W/o sncl STOLZ.JF Operating Reactors Branch 4 02/08/19 BECKHAM.JT Georgia Power Co 2pp 14693 055. 24% Fichs 50-321.82/08/19.8208270693
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE lnfo Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " 8vc list encl JORDAN: E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14354 274 24% Fiche 50-000, 82/07/16.8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E.L. Division of Engineering & Guelity Asserance 82/07/19 Michigan, Univ of 112pp. 14358 001 24X Fiche. 50-000, 82/07/19, 8204210395
- 8204210394 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure," Svc list encl URDAN,E L Division of Engineering & Quality Assurance, 82/07/20 Consolidated Edison Go of New York 112pp 14381.001, 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leating From U Hexafluoride Overpacks " Svc list anc! C088:L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidate Edison Co of New York 7ipp 14397 276 24X Fiche 50-000, 82/07/20, 8204210397.

- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list enci JORDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fithe 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Mestinghouse PMRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8208030375 Ack receipt of 820617 & 22 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-09 & 50-366/82-09 LEHIS:R C Division of Project & Resident Programs 82/07/23 KELLV:R J Osorgia Power Co ip 14154 238 24X Fiche 50-321,82/07/23.8208030375
- --8208030377 Responds to NRC 820518 ltr re violations noted in IE Insp. Repts 50-321/82-09 & 50-366/82-09 Corrective actions isolation actuation instrumentation setpoint for reactor core isolation cooling inboard isolation valve corrected BECMHAM.JT Georgia Power Cd 82/06/22 LEWIS,R C Division of Project & Resident Programs 10pp 14154 239 24X Fiche 50-321,82/07/23,8208030375
- --8208030377 Responds to NRC 820518 ltr reviolations noted in IE Insp. Rapts 50-321/82-07 & 50-366/82-07 Speed setting for control rod valve not safety concern BECKHAH.J T Georgia Power Co 82/06/17 LEWIS,R C Division of Project & Resident Programs 2pp 14184 247 24% Fiche 50-321,82/07/23,8208030375
- --8208030382 Forwards IE Insp Repts 30-321/82-07 & 50-346/82-09 on 820121-0301 & notices of violation & deviation LEMIS.R C Division of Project & Resident Programs 82/05/18. KELLY.R J Georgia Power Co 2pp 14154 251 24X Fiche 50-321.82/07/23.8208030375
- --8208030387 Notice of violation from insp on 820121-0301 * Division of Project & Resident Programs 62/05/18 3pp 14154 253 24X Fiche 50-321, 82/07/23, 8208030375
- --8208030377 IE Insp Repts 50-321/82-09 & 50-366/82-09 on 820121-0301
 Noncompliance noted failure to isolate & declare instrument
 channel w/noncompressive setpoint insperable & failure to
 follow GC procedures
 ROSERS, R F , BROWNLEE, V L Division of Project & Resident
 Programs 82/05/17 7pp 14154 257 24X Fiche 50-321,82/07/23,8208030375
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Biseves in RCS Piping at Certain Wastinghouse PWR Power Plants " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance, 82/07/26, Consolidated Edison Co. of New York 121pp. 14357-013 24X Fiche 30-000, 82/07/26, 8204210403
- 9204210405 IE Info Notice B2-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list enci JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000.82/07/28.8204210405
- 9204210407 IE Info Notice 92-27. "Fuel Rod Degradation Resulting From Daffle Hater-Jet Impingement " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 92/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000. 82/08/05. 8204210407
- 8208100308 Forwards IE Safeguards Insp Repts 50-321/82-22 & 50-366/82-20 on 820718-22 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/08/05. XELLY, R J Georgia Power Co 2pp. 14297, 135 24X Fichs 50-321, 82/08/05, 8208100308
- --B20B10031B IE Bafeguards Insp Repts 50-321/B2-22 & 50-366/B2-20 on B2071B-22 No noncompliance noted Hajor areas inspected security plan & procedures, security organization, program audit, records & repts Details withheld (100FR73 21) HODRE, D E , MCOUIRE, D R Division of Project & Resident Programs B2/08/03 1p 14297 137 24X Fiche 50-321, B2/0B/05, B20B10030B

- 8208260217 Responds to NRC 820713 ltr re violations noted in IE Safeguards Insp Repts 50-321/82-15 & 50-366/82-15 Corrective actions withheld (ref 10CFR73 21) Full payment of civil penalty encl
 BECKHAM: J T Georgia Power Co 82/08/12 Director's Office.
 Office of Inspection and Enforcement 3pp 14554 308 24X Fiche 50-321, 82/08/12, 8208260217
- 8208300029 Forwards technical evaluation rept re NRC review of util responses to IE Bulletin 80-ii, "Masonry Wall Design " Items 2 & 3 of bulletin have been fully implemented w/exception of removal of Walls C164-44 & B & C130-39C & D STOLZ, J F Operating Reactors Branch 4 82/08/16 BECKHAM, J T Georgia Power Co 3pp 14683 287 24X Fichs 50-321.82/08/16, 8208300029
- --8206300163 "Mesonry Wall Design." technical evaluation rept SUBRAHONIAN, N., CON.V. N. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C3506-165 82/06/28 CHOKSHI.N.C. NRC - NO. Detailed Affiliation Given 37pp 14683 270 24X Fichs 50-321.82/08/16.8208300029
- 8208270179 Advises of error in assigning IE Safeguards Insp Rept 50-366/82-20 on 820718-22 Correct rept number is 50-366/82-23 Transmittal ltr & rept should be changed to reflect correction DANCE.H C Division of Project & Resident Programs 82/08/24 KELLY.R J Ocorgia Pawer Co 1p 14563 206 24X Fiche 50-321, 82/08/24,8208270199

R Periodic operating reports & related correspondence

- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1781 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp 14677 208 24% Fiche 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CVB1 " * NRC - No Detailed Affiliation Given 82/07/13 48pp 14677 216 24X Fiche 50-000,82/07/13,8208270010
- --8208270628 Forwards "Radiation Exposure Rept for CYB1," per 10GFR20 407 MARRY,M Georgia Power Co 82/03/26 Office of Management and Program Analysis ip 14680 060 24X Fiche 50-000,82/07/13, 8208270010
- --8208270631 "Radiation Exposure Rept for CYB1" * Deorgia Power Co 82/03/26 ip 14680 061 24% Fiche 50-000,82/07/13.8208270010
- 8208160071 Forwards monthly operating repts for Jul 1982 NIX,H C Georgia Power Co 82/08/10 Director's Office of Inspection and Enforcement 1p 14342 006 24X Fiche 50-321 82/08/10.8208160091
- --8208160094 Monthly operating repts for Jul 1982 EAZZETTA.B A Georgia Power Co. 82/08/10 13pp 14342 007 24I Fiche 50-321.82/08/10.8208160091

S Reportable occurrences. LERs & related correspondence

- 8208060182 Forwards LER 82-041/03L-0 NIX.H C Georgia Power Co 82/07/27 O'REILLY, J P Region 2. Office of Director 1p 14239 151 24X Fiche 50-366, 82/07/27, 8208060182
- --B208060187 LER 82-041/03L-0 on 820627, torus water level recorder discovered to be inoperable Level indication erratic Caused by component failure. Differential pressure transmitter equalizing valve in valve manifold replaced TIPPS, B. B. Georgia Power Co. 82/07/27 Region 2, Office of Director 2pp 14237:152 24X Fiche 50-366,82/07/27,820806082
- 8208060189 Forwards LER 82-039/03L-0 NIX.H G. Georgia Power Co 82/07/27 O'REILLY.J P Region 2, Office of Director. 1p. 14239 096 24X Fiche 50-366,82/07/2/, 8208066189.
- --8208060194 LER 62-039/03L-0. on 620628, hydrogen/oxygen analyser failus alarm received on B primary containment hydrogen/oxygen analyser during steady-state operation at 97% power Caused by worm-out diaphragm on B sample pump. Diaphragm replaced TIPPs, S B. Georgie Power Co. 62/07/27 Region 2, Office of Director 2pp, 14239.097 24X Fiche 50-366, 82/07/27, 8208060189

- 8208270137 Forwards LER 82-076/03L-0 NIX.H C Georgia Power Co 82/07/27 O'REILLY, J P Region 2. Office of Director 1p 14563 196 24X Fiche 50-366.82/07/27. 8208270137
- --B208270145 LER B2-076/03L-0 on 920629, torus water level recorder found inoperable during steady state full power operation Caused by component failure Differential pressure transmitter equalizing valve in valve manifold replaced TIPPS, B B Georgia Power Co B2/07/27 Region 2, Office of Director 2pp 14563 197 24X Fiche 50-366,82/07/27,8208270137
- 8208120191 Forwards LER 82-069/03L-0 NIX, H C Georgia Power Ca 82/07/29 O'REILLY, J P Region 2, Office of Director 1p 14326 017 24X Fiche 50-366, 82/07/29, 8208120191
- --8208120198 LER 82-069/03L-0 on B20629, drywell oxygen concentration found greater than Tech Spec limit Caused by operator arror Operators instructed to maintain drywell suction when analyser is available
 TIPPS 8 B Georgia Power Co 82/07/29 Region 2, Office of Director 2pp 14326,018 24X Fiche 50-366,82/07/29,8208120191
- 6208100189 PNO-II-82-089 on 820730, facility shut down when repairs to emergency diesel generator not completed within required time Repairs to be completed by 820805 RGGGE, JF, DANCE, H C Region 2, Office of Director 82/08/02 ip 14298, 201 24X Fiche 50-366, 82/08/02, 8208100189
- 8208120109 Forwards LER 82-067/03L-0 NIX,H C Georgia Power Co 82/08/03 O'REILLY,J P Region 2, Office of Director 1p 14326 358 24X Ficha: 50-366,82/08/03, 8208120109
- ---B20Bi20ii4 LER 82-Q67/03L-0 on 820705,A & B svc water supply valves to RHR & core spray pump room cooler failed to pass core spray operability procedure requirements Caused by lack of lubrication, Valves lubricated & reassembled TIFPS.S B Georgia Power Co 82/08/03 Region 2, Office of Director 2pp 14326 357 24X Fiche 50-366.82/08/03,820Bi20107
- 8208130156 Forwards LER 62-068/03L-0 NIX,H.C Georgia Power Co 82/08/03. D'REILLY,J P Region 2. Office of Director ip 14338 092 24X Fiche 50-366,82/08/03. 8208130156
- --8208130159 LER 82-068/03L-0 on 820707 & 24. volumetric weighted average drywell air temp exceeded 135 F limit of Tech Bpecs Caused by combination of high ambient temp & failure of chiller fans 88 & 98 to provide adequate cooling TIPPS.8.8 Georgia Power Co 82/08/03 Region 2, Office of Director 2pp 14338 073 24X Fiche 50-366.82/08/03.8208130156.
- 8208160238 RO 50-366/1982-05 on 820629, reactor bldg Ei-130 NW fire detection circuit declared inoperable when continuous alarm signal could not be reset Caused by corrosion & dust & dirt accumulation Resistive load placed upstream NTX.H C Georgia Power Co 82/08/05 O'REILLY.J.P Region 2, Office of Director 2pp 14347 140 24X Fiche 50-366, 82/08/05, 8208160238.
- 8208140495 Forwards LER 82-070/03L-0 NIX,H C Georgia Power Co 82/08/05 O'REILLY,J P Region 2, Office of Director 1p 14348*275 24X Fiche 50-364,82/08/05, 8208160495
- --8208160503 LER 82-070/03L-0 on 820714, reactor bldg fire protection circuit EI-130NW declared insperable Caused by defective procedures Fire alarm response procedure mod will be made by 820901 TPPS.6 Georgia Power Co 82/08/05. Region 2. Office of Director. 2pp 14348.296. 24% Ficher 50-366,82/08/05.8208160495.
- 8208200284 Forwards LER 82-071/03L-0 NIX,H C Georgia Power Co 82/08/12 Q'REILLY,J.P. Region 2. Office of Director. 1p. 14378 348, 24X Fiche: 50-366, 82/08/12, 8208200284
- --B208200289 LER B2-07i/03L-0 on B207i4, power breaker for reactor core isolation cooling steam inlet isolation valve motor operator found open Cause undetermined. Breaker closed Add1 action deemed unnecessary TIPPS.B.B. Qeorgia Power Co. 82/08/i2 Region 2, Office of Director 2pp. 14378.349. 24X Fiche: 50-366.82/08/i2,8208200284.
- 8208270455 Forwards LER 92-074/03L-0 NIX,H C Georgia Power Co 82/08/12, 0'REILLY,J P, Region 2: Office of Director, ip 14565 269, 24X Fiche: 50-366,82/08/12, 8208270485.

- --8208270461 LER 82-074/03L-0 on 820715, condensate demineralizer precoat tank evenflowed condensate water & powdex resin during demineralizer precoat operation Caused by component failure compounded by procedural deficiency & personnel error TIPPS, 8 B Oeorgia Power Co 82/08/12 Region 2, Office of Director 1p 14565 270 24X Fiche 50-366.82/08/12.8208270455
- 8208270534 Forwards LER 82-072/03L-0 NIX,H C Georgia Power Co 82/08/12 0'REILLY, J P Region 2, Office of Director 1p 14564 144 24% Fiche 50-366,82/08/12, 8208270534
- --B208270537 LER 82-072/03L-0 on B20715, NPCI turbine exhaust discharge pressure hi & HPCI turbine trip solenoid energized alarms activated Caused by component failure due to fouled contacts on HPCI turbine exhaust pressure suitch Buitch cleaned TIPPS, S B Georgia Power Co 82/08/12 Region 2, Office of Director 2pp 14564 145 24X Fiche 50-366, 82/08/12, 8208270534.
- 8208270228 Forwards LER 92-073/03L-0 NIX.H C Georgia Power Co 82/08/13 D'REILLY.J P Region 2. Office of Director 1p 14563 127 24X Fiche 50-366, 82/08/13, 8208270228
- --8208270232 LER 82-073/03L-0 on 820716, core max fraction of limiting powder density found greater than fraction of rated thermal power Caused by rod withdrawals in areas of low zenon concentration Average power range monitor adjusted SUMNERHH L Georgia Power Co 82/08/13 Region 2, Office of Director 2pp 14563, 128 24X Fiche 50-366, 82/08/13, 8208270228
- 8208300113 Forwards LER 82-078/03L-0 NIX.H C Georgie Power Co 82/08/19 O'REILLY.J P Region 2, Office of Director. 1p 14679 152 24X Fiths 50-366.82/08/19, 8208300113
- --B208300115 LER 82-078/03L-0 on 820726, manual voltage regulator for diesel generator 2A found inoperative Caused by failure of diodes that supply power to manual adjustment motor. Diodes replaced TIPPS, S.B. Georgia Power Co. 82/08/19 Region 2, Office of Director 2pp 14679 153 24X Fiche: 50-366, 82/08/19, 8208300113.
- 8208300344 Forwards LER 82-075/03L-0.
 NIX.H.C Georgia Power Co B2/08/19 O'REILLY, J P Region 2,
 Office of Director 1p. 14679 201 24X Fiche 50-366, 82/08/19,
 B208300344.
- --B208300347 LER B2-075/03L-0 on B20724, while at reduced power level of 936 MHz for rod sequence exchange, control rod drive accumulator trouble alarm received Caused by slow bleeddown of accumulator pressure Accumulator recharged TIPPS, B B Georgia Power Co 82/08/19, Region 2, Office of Director 2pp 14479 202 24X Fiche 50-366,82/08/19,8208300344,

DOCKET 50-367 BAILLY GENERATING STATION

G Adjudicatory correspondence

- 8208090159 Order holding intervenor Business & Frof People for Public Interest request for award of atty fees & expenses under Equal Access to Justice Act until question of availability of funds solved NRC will seek Comptroller General apinion HOVLE.J C Office of the Beretary of the Commission 82/08/06 Businessmen for the Public Interest opp 14271.346 24X Fiche 50-367.82/08/06.8208090139.
- 8208110087 Requests Comptroller Owners! opinion re availability of funds to pay awards by US agency to intervenors under Equal Access to Justice Act (EAJA) EAJA conflicts w/NRC FY82 appropriations act
 BICKHIT/L Office of the Owners! Counse!, 82/08/06 BOWSHER, C.A. General Accounting Office 4pp 14316.339 24X
 Fiche 50-367,82/08/06.8208110087

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

- F Security, medical, emergency & fire protection plans
- 820B020259 Ack receipt of 820714 ltr in response to 820625 Systematic Assessment of Licensee Performance Board rept.
 Inconsistencies in functional area of security & safeguards will be corrected
 SEIDLE.M. C. Division of Resident, Reactor Project & Engineering Programs 82/07/27, CAVANAUGH.M. Arkansas Power & Light Co. 2pp. 14132:312 24X Fiche: 50-318, 82/07/27, 8208020259,

- --8208020267 Comments on 820625 Systematic Assessment of Licensee Performance Board rept Increasing frequency of NRR project manager site visits suggested Inconsistencies in Sections III & K 2 re security & safeguards noted MARSHALL. J R Arkansas Power & Light Co 82/07/14 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 3pt
- B208030312 Clarifies util B20701 documentation of results of review of fire zones for compliance w/ldCFR50 48 & 10CFR50 App R
 MARSHALL, J.R. Arkansas Power & Light Co. B2/07/29 EISENHUT, D.G. Division of Licensing 2pp 14156 276 24X Fiche 50-313,82/07/29,8208030132
- B20B050374 Confirms agreements reached in 820730 telcom re-corrective action concerning early warning sys On 820731. It censes shall commence door-to-door canvas within 10-mile smergency planning zone CQLLINS.JT Region 4. Office of Director B2/07/30 CAVANAUGH, WArkansas Power & Light Co 2pp 14207 164 24X Fiche 50-313, 82/07/30, 8208050374
- 8208250096 Release public version of revised emergency procedures FELTON, J H Division of Rules and Records 82/08/11 Document Management Branch 1p 14974 319 24X Fiche 50-313.82/08/11, 82/0826096
- --8208260101 Forwards public version of revised emergency procedures, including Procedures 1904 02 re offsite dose projection procedure method & 1904 04 re estimating airborne release rates

 * Arkansas Power & Light Co 82/07/30 NRC No Detailed Affiliation Given 6pp 14574 320 24X Fiche 50-313,82/08/11,8208260094
- --8208260106 Public version of revised emergency procedures, including Procedures 1904 02 re offisite dose projection pocket computer method & 1904 04 re estimating airborne release rates

 * Arkansas Power & Light Co 82/07/30 60pp 14574 327 24X Fiche 50-313,82/08/11,8208260096
 - DB190130 Ack receipt of B20721 request for 60-day extension to prepare response to emergency plan evaluation rept Request pranted, establishing B20923 as new date for receipt of response BEIDLE.W C Division of Resident, Reactor Project & Engineering Programs B2/08/16 CAVANAUGH.W Artansas Power & Light Co 14382 247 24X Fiche 50-313,82/08/16.8208190150
- -8208190156 Requests 60-day extension to provide response to NRC emergency plan evaluation rept MARSHALL.JR Arkansas Power & Light Co 82/07/21 COLLINS,J T Region 4. Office of Director ip 14382 248 24X Fishe 50-313,82/08/16,8208190150
- B208270467 Ack receipt of B20805 itr discussing massive tone alert radio distribution program developed in response to B20729 & 30 discussions & B20730 confirmatory action Itr SEIDLE.W C Division of Resident. Reactor Project & Engineering Programs 82/08/20 CAVANAUGH.W Arkansas Power & Laght Co i 14567 045. 24X Fiche 50-313.82/08/20.8208270447
- --8208270473 Discusses massive tone alert radio distribution program developed in response to 820727 & 30 discussions & 820730 confirmatory action itr Dversize pamphlet encl Aperture card available in PDR.

 MARSHALL JR Arkansas Power & Light Co 82/08/05 CDLLINS, J T Region 4, Defice of Director, 15pp 14567 046 24X Fiche 50-313,82/08/20.8208270467
- P. Operating license stage documents & correspondence
- B207080064 Generic 1tr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Box list enci DIRCKB.W J Office of the Executive Director for Operations. B2/07/02 Consolidated Edison Co of New York 93pp 14194-001 24X Fiche 50-000.B2/07/02,8807080064
- 3208060042 Summary of B30622-24 meetings w/util in Russellvills.AK re App 1 (radialogical effluent Tech Specs) review to resolve autstanding issues
 VISSINO.O S Operating Reactors Branch 4 82/07/15 Operating Reactors Branch 4 3pp 14282 043 24X Fiche: 50-313.82/07/15.
 3208060042

- --8208060054 forwards lists of questions to be discussed w/plant personnel re radiological effluent Tech Specs & offsite dose calculation manual Addl areas of discussion during review w/plant personnel may arise SERRAND. W EG&G. Inc 82/05/04 WILLIS.C A Effluent Treatment Systems Branch 34pp 14282 047 24X Fiche 50-313.82/07/15, 8208060042
- 8208030092 Forwards Amend 33 to License NFF-4, safety evaluation & notice of issuance & availability Amend allows operation w/loop resistance temp detector response time exceeding 4-s TRAMMELL,C H Operating Reactors Branch 3 82/07/21 CAVANAUGH, WARAMSAS Power & Light Co 4pp 14193 322 24% Fiche 50-368,82/07/21,8208030092
- --8208030099 Amend 33 to License NPF-6, amending Tech Specs per util B20303 & 20 application by allowing loop resistance temp detector response times to exceed 6-s, provided penalty factors inserted in core protection calculator sys CLARK, R A Operating Reactors Inanch 3 82/07/21 10pp 14193 326 24X Fiche 50-368,82/07/21,8208030092
- ~~8208030102 Safety evaluation supporting Amend 33 to License NPF-6 * Office of Nuclear Reactor Regulation, Director 82/07/21 5pp 14173 336 24X Fiche 50-368.82/07/21.8208030092
- --8208030104 Notice of issuance & availability of Amend 33 to License NPF-6 CLARK.R A Operating Reactors Branch 3 82/07/21 2pp 14193 341 24% Fiche 50-348,82/07/21,8208030092
- 8208060174 Forwards responses to 820413 request for add1 info re training & requalification program MARSHALL.J R Arkaneas Power & Light Co 82/07/21 CLARK,R A Operating Reactors Branch 3 STOL2.J F Operating Reactors Branch 4 43pp 14237 053 24X Fiche 50-313,82/07/21,8208060174
- 8208050466 Forwards eight oversize revised drawings Drawing transmittal list and Aperture cards are available in FDR FMINO, E Ankanasa Power & Light Co 82/07/22 NRC No Detailed Apriliation Given 2pp 14237 327 24X Fiche 50-368.82/07/22, 8308080464
- 820Bil0196 Forwards info on outages of ECC5, por NUREG-0737, Item II K 3 17. in response to 820324 request for addl info MARSHALL, JR Arkansas Power & Light Co 82/07/26 EISENHUT, D G Division of Licensing 26pp 14313 227 24X Fiche 50-313, 82/07/26, 820Bil0194
- 8208160504 Forwards add1 info re Items II F 1 4, "Containment Pressur, Monitor," II F 1 5, "Containment Water Level Monitor," & II F 1 5, "Containment Hydrogen Monitor " MARSHALL.JR Arkansas Power & Light Co 82/07/26 EISENHUT, D 0 Division of Licensing 6pp 14348 287 24X Fiche 50-313,82/07/26,8208160504
- 8208020072 Ack receipt of 820630 ltr re progress rept of drawing control programs Plant operators should be provided w/up-to-date P&IDs
 SEIDLE,W C Division of Resident, Reactor Project & Engineering Programs 82/07/27 MARSHALL,J R Arkansas Power & Light Co 2pp 14144,113 24X Fiche 50-313,82/07/27,8208020072
- --0200020078 Submits status of efforts & decription of progress made redrawing control Onsite bldg renovation accomplished, required procedure changes completed & reproduction & drafting equipment received MARSHALL JR Arkansas Power & Light Co 82/06/30 SEIDLE, W. C Division of Resident. Reactor Project & Engineering Programs 2pp 14144 115 24X Fiche 50-313, 82/07/27, 8208020072
- 820B100190 Informs that info per NUREG-0737, Item II B 3 re post-accident sampling sys.will be provided by 821115, in response to NRC 820701 request MARSHALL, J R Arkansas Power & Light Co 82/07/27 CLARK, R A Operating Reactors Branch 3 ip 14298 200 24X Fiche 50-313, 82/07/27, 8208100190
- 8208060266 Responds to NRC 810929 request for info re NUREG-0737. Item II D 1, "Pressurizer Safaty/Relief Valve Operability "
 Pressurizer safety valves function as predicted under all credible operating & accident conditions in FGAR
 MARSHALL, J R Arkansas Power & Light Co 82/07/28 CLARK, R A Operating Reactors Branch 3 3pp 14241 175 24X
 Fiche 50-368,82/07/28.8208060266
- 8208100102 Responds to NRC 820125 & 20 1trs requesting add1 info re environ qualification of safety-related electrical equipment High energy line break analysis encl Add1 response will be completed by 820815 MAREHALL.J R Arkansas Power & Light Co 82/07/29 STOLZ.J.F Operating Reactors Branch 4 CLARK.R A Operating Reactors Branch 3 15pp 14297 304 24X Fiche 50-313,82/07/29,8208100102

- B20B100369 Forwards Amends 46 & 34 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends modify ETS.App B re reporting of radiological gaseous effluents CLARK.R A , STOLZ.J F Operating Reactors Branch 3 82/07/
 - erriuents CLARK,R A , STOLZ,J F Operating Reactors Branch 3 82/07/29 CAVANAUGH,W Arkansas Power & Light Co 4pp 14308 251 24X Fiche 50-313,82/07/29,8208100369
- --B208100372 Amends &6 & 34 to Licenses DPR-51 & NPF-6, respectively, modifying ETS, App B re reporting of radiological gaseous effluents
 BTDLZ.J F Operating Reactors Branch 4 82/07/27 15pp
 14308 255 24X Fiche 50-313, 82/07/27, 8208100369
- --820B100375 Notice of issuance & availability of Amends 66 & 34 to Licenses DPR-51 & NPF-6, respectively MINER, 8 Operating Reactors Branch 4 82/07/29 2pp 14308 271 24% Fiche 50-313.82/07/27.8208100369
- 8208090021 SOCIDECONDMIC IMPACTS OF NUCLEAR GENERATING STATIONS ARKANSAS NUCLEAR ONE STATION CASE STUDY Docket Nos 50-313 and 50-368 (Arkansas Power And Light Company) PIJAMKA.K D Mountain West Research. Inc. FIN B-6268 NUREO/CR-2749 VOI 82/07/31 Division of Health. Siting & Environment 194pp Available at NTIS \$7 00 14304 332 24) Fiche 50-313.82/07/31.8208090021
- B20B070194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list enci EIBEMNUT, D G Division of Licensing B2/0B/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000, B2/0B/09, B20B070194
- 8208250298 Forwards addl info re RCS high point vents, in response to NRC 820120 & 0301 ltrs Final responses will be submitted by 820917 MARSHALL, J.R. Arkansas Power & Light Co. 82/08/18 STOLZ, J.F. Operating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch 3 8pp 14538-065 24X Fiche 50-313.82/08/18,8208250298
- 8208260128 Advises of audible control room alarms being installed on count rate to alert control room operators of boron dilution event during reactor shutdown, in response to 810619 request No Tech Spec changes necessary to assure maint of sys MARSHALL, J R Arkaneas Power & Light Co 82/08/19 CLARK, R A Operating Reactors Branch 3 2pp 14556 328 24% Fiche 50-368, 82/08/19. 8208260128
- 8208250379 Application to amend License NPF-6, changing Tach Specs to allow testing of containment penetration conductor overcurrent protective devices to demonstrate operability to remove unrealistic test conditions
 CAVANAUGH.W Arkansas Power & Light Co 82/08/23 CLARK, R A Operating Reactors Branch 3 3pp 14538 001 24X
 Fiche: 50-368, 82/08/23, 8208250379
- --8208250382 Proposed Tech Spec Table 3 8-1 re containment penetration conductor overcurrent protective devices & Tech Spec 3/4 8 2 5 re surveillance requirements ** Arkansas Power & Light Co. 82/08/23 25pp 14538 004 24X Fiche 50-368,82/08/23,8208250379
- G20B300120 Provides projected schedule for completion of several NRC requests for info MARBHALL,JR Arkansas Power & Light Co G2/0B/23 STOL2,JF Operating Reactors Branch 4 2pp, 14599 194, 24X Fiche 50-313, 82/08/23, 8208300120
- û Inspection reports, IE Bulletins & correspondence
- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN.E L Division of Engineering & Guelity Assurance 82/07/16,
 Consolidated Edison Co of New York 87pp 14386 274 24X
 Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-24.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list end JORDAN,E L. Division of Engineering & Quality Assurance. 82/07/19 Michigan, Univ. of 112pp 14358 001 24X Fiche 30-000,82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche, 50-000, 82/07/20, 8204210396

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list anci COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidate Edison Co of New York 7ipp 14357 276 24X Fich
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " 8vc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Bupport Pin Failures at Westinghouse PWRs " Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche 50-000.82/07/23.6204210402
- 8208160250 Submits final response to IE Bullstin 80-09, "Hydramotor Actuator Deficiencies" Performance history meets intent of Action Item 2 re verification of proper functioning No further action contemplated MARSHALL, JR Arkansas Power & Light Co 82/07/23 COLLING, JT Region 4, Office of Director 2pp 14347 043 24X Fiche 50-313,82/07/23.8208160250
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8208180055 Forwards IE Insp Repts 50-313/82-13 & 50-368/82-10 on 820601-30 & notice of violation SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/07/27 CAVANAUOH, W Arkansas Power & Light Co 2pp. 14379 243 24% Fiche 50-313,82/07/27,8208180055
- --8208180057 Notice of violation from insp on 820601-90 * Division of Resident, Reactor Project & Engineering Programs 82/07/27 2pp 14379 245 24% Fichs 50-319,82/07/27,8208180055
- --8208180066 [E lnsp Repts 50-313/82-13 & 50-368/82-10 on B20601-30 Noncompliance noted failure to perform adequate survey for beta radiation. ALARA committee review not performed & failure to control access to security key issue room JONNSON. W D . CALLAN. L J . HALL. R E Division of Resident, Reactor Project & Engineering Programs 82/07/19 13pp 14379 247 24X Fiche 50-313.82/07/27.8208180055
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl URDAN.E L Division of Engineering & Guality Assurance B2/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000 82/07/28, 8204210405
- 8208090286 Advises that util analysis performed on main steam line break w/continued feedwater addition per IE Bulletin 80-04 acceptable CLARK-R A Operating Reactors Branch 3 82/07/28 CAVANAUGH, W Arkansas Power & Light Co 2pp 14307 091 24X Fichs 50-368-82/07/28-8208090286
- --8208070289 Safety evaluation supporting util analysis of main steam line break w/continued feedwater addition # Office of Nuclear Reactor Regulation, Director. 62/07/28 7pp. 14307 093 24X Fiche 50-348.62/07/28.8208090286
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Bvc list encl JORDAN.E L. Division of Engineering & Quality Assurance B2/08/05, Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8208190213 Forwards IE Insp Repts 50-313/82-15 & 30-368/82-12 on 820621-25 & notices of violation & deviation 8 EIDLE.W C Division of Resident. Reactor Project & Engineering Programs 82/08/06 CAVANAUGH.W Arkensas Power & Light Co 2pp 14387 156. 24X Fiche 50-313,62/08/06.8208190213
- --8208190219 Notice of violation from insp on 820621-25, * Region 4, Office of Director 82/08/06 ip, 14387 is 24% Fiche 50-313,82/08/06,8208190213

- --8208170217 Notice of deviation from insp on 820621-25 * Region 4, Office of Director 82/08/06 ip 14387 159 24X Fiche 50-313,82/08/06,8208170213
- --8208190225 IE Insp Repts 50-313/82-15 & 50-368/82-12 on 820621-25 Noncompliance noted failure to electrically supervise or lock fire doors between adjacent redundant safe shutdown equipment JAUDON J P , MURPHY, M E Region 4. Office of Director 82/07/30 17pp 14387 160 24% Fiche 50-313,82/08/06.8208170213
- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL.R A Critical Hass Energy Project 8pp 14679 208 24X Fiche 50-000.82/07/13.208270010
- ---8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81" NRC - No Detailed Affiliation Civen 82/07/13 48pp 18679 216 24X Fiche 50-000,82/07/13,8208270010
- --8208270652 Forwards "Annual Occupational Radiation Exposure Rept.
 Personnel Whole Body Exposure for CY61," per 10CFR20 407
 MARSHALL, JR Advansas Power & Light Co. 82/02/26 DEYOUNG, R C
 Director's Office. Office of Inspection and Endocement ip
 14679 350. 24% Fiche 50-000.82/07/13.8208270010
- --B208270655 "Annual Occupational Radiation Exposure Rept, Personnel Whole Body Exposure for CY81"

 * Arkanasa Power & Light Co B2/02/26 19 14679 351 24X
 Fithe 50-000, 82/07/13, 8208270010
- B20B120194 Forwards monthly operating rept for June 1982 MARSHALL,J R Arkansas Power & Light Co 82/07/14 HALLER, N M Office of Resource Management. Director ip 14326 020 24 X Fiche: 50-368, 82/07/14, 820B120194
- --8208120197 Monthly operating rept for June 1982 BRAMLETT.L S Arkansas Power & Light Co 82/07/09 App 14326 021 24% Fiche 50-369.82/07/14.8208120194
- 8208060149 Forwards NPDES discharge monitoring repts for Apr-June 1982 rapts for Apr-June 1982 MARSHALL, J. R. Arkansas Power & Light Co. 82/07/29 CDLLINS, J. T. Region 4, Office of Director 2pp 14240 040 24X Fichs 50-313
- --8208060155 RPDES discharge monitoring repts for Apr-June 1982.

 * Arkansas Power & Light Co 82/07/28 18pp 14240 042 24X Fiche 50-313,82/07/29,8208060149
- S Reportable occurrences, LERs & related correspondence
- 8208050262 Forwards LER 82-024/03L-0 MARSHALL.J R Arkansas Power & Light Co 82/07/27 SEIDLE.W.C. Region 4. Dffice of Director 1p 14210 101 24X Fiche 50-368.82/07/27.8208050262
- --B208050265 LER B2-024/O3L-O.on B20704, containment high range radiation monitor failed while in Mode 1 at 100% power Caused by loosening of two power supply leads on terminal block in instrument cabinat associated w/monitor Leads tightened ROSERS, P. Arkansas Power & Light Co B2/07/27 Region 4, Office of Director 2pp 14210 102 24% Fiche 50-368, B2/07/27, B208050262
- 8208050199 Forwards LER 82-025/03L-0 MAR8HALL,JR Arkansas Power & Light Co 82/07/28 BEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs ip 14212:142 24X Fiche 50-246.82/07/28.8208050199.
- ---8208050207 LER 82-025/03L-0 on 920709, during Mode 1, emergency feedwater block valve failed to close following monthly surveillance test Caused by worn blocking arm at point of contact between arm & adjustment screw Mechanism adjusted & tested, MCEOGENBERG, D. Arkensas Power & Light Co 82/07/28 Region 4, Office of Director ip 14212:143 24X Fiche 50-368, 82/07/28, 8208050197.
- 8208030226 PNO-IV-82-027 on 820727, control rod drop occurred Caused by upper gripper coil on control slament drive motor faulting Interferences will be removed & control element drive motor 28 will be replaced GALLAN, L. J. JAUDON, J.P., SEIDLE, W.C. Region 4, Office of Director 82/07/29 ip 14158 284 24X Fiche 50-368, 82/07/29, 8208030226.

- 8208050361 PNO-IV-82-028 on 820731, licensee will implement procedures to assure adequate public notification of warning sys operability Rural areas will be provided w/tone receivers Actions will be completed by 820802 HACKNEY, C., JAUDGN, J.P., SEIDLE, W.C. Region 4, Office of Director 82/07/30 2pp 14237 298 24X Fiche 50-313,82/07/30,8208050361
- 8208100081 PNO-IV-82-028A on 820730.licensee field teams visited residences, businesses & organizations located within 10-mile emergency planning zone outside area of siren coverage delivering EBS tone alert receivers MACKNEY, C. JAUDON, J.P., SEIDLE, W.C. Region 4, Office of Director 82/08/03 2pp 14296 143 24X Fiche 50-313,82/08/03,8208100081
- 8208270275 Forwards LER 82-024/03L-0 MARSHALL.JR Arkansas fower & Light Co 82/08/13 SEIDLE, W C Region 4, Office of Director 1p 14564 174 24X Fichs 50-368, 82/08/13, 8208270275
- --8205270305 LER 62-024/03L-0 on 820704, containment high range radiation monitor 2RIT6-8725-7 failed Caused by inadequate tightening of power supply leads in instrument cabinet ROSERS,P Arkansas Power & Light Co 82/07/27 Region 4, Office of Director 2pp 14544 175 24X Fiche 50-368,82/08/13, 6208270295
- 8208300164 PNO-IV-82-031 on 820820 manual shutdown initiated due to primary sys leakage of approx 3 gallons per minute resulting from packing leak on low temp overpressurization isolation valve & leak through steam generator B gasket cover HURNICUTT, D.M. JOHNSON, W.D. Region 4, Office of Director 82/08/23 (p. 14599 193 24X Fiche 50-368,82/08/23,8208300164
- DDCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8208030066 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/07/19 Document Management Branch. 1p 14198 001 24X Fiche 50-369,82/07/19,8208030066.
- --B20B030073 Forwards public version of revised emergency plan implementing procedures, including Station Directive 3 7 3 retelephone procedures/bomb threat check list & Procedure EP/1/A/S000/01 re immediate actions & diagnostics PARKER, W O Duke Power Co. B2/07/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14198 002 24X Fiche 50-369,82/07/19.8208030066
- --8208030084 Public version of revised emergency plan implementing procedures, including Station Directive 3 7 3 re telephone procedures/bomb threat checklist & Procedure EP/1/A/5000/01 rs immediate actions & diagnostics # Duke Power Co 82/06/28 275pp 14198 004 24x Fiche 50-369,82/07/19.8208030066
- 820B100305 Requests amend to License Condition 2 C (11)n (2) to change deadline for installation of upgraded meteorological sys, from Oct 1983 to 830731.per 820729 telcon
 TUCKER.H.D Duke Power Co 82/08/03 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Branck
 4 19 14297 13B 24X Fiche 50-369.82/08/03.8208100305
- 8208260418 Releases public version of revised crisis mpt plan FELTON.J M Division of Rules and Records 82/08/11 Document Management Branch 1p 14572 098 24X Fiche 50-000,82/08/11, 8208260418
- --B20B260430 Forwards public version of Revision 5 to crisis mgt plan Ravision involves reorganization of crisis mgt team & updates of Bections D.K. & M PARKER, W.O. Duke Power Co. B2/07/19 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip 14572 099 24K Fiche: \$0-000, 82/08/11, 8208260418
- --8208260437 Public version of Revision 5 to crisis mgt plan TUCKER.H B Duke Power Co 82/07/09 134pp 14572 100 24X Fiche 50-000, 82/08/11.8208260418
- 8208260375 Releases public version of revision to emergency plan FELTON.J.M Division of Rules and Records 82/08/13 Document Hanagement Branch. 1p 14579 229 24X Fiche, 50-369, 82/08/13, 8208260376
- ---8208260385 Forwards public version of Revision 6 to emergency pion.
 Instruction sheat encl
 TUCKER,H B., GLDVER,H Duke Power Co. 82/08/06 DENTON,H R.
 Office of Nuclear Reactor Regulation, Director. 4pp. 14579, 230
 24X Fiche 50-369, 82/08/13, 8208260376

- --8208260392 Public version of Revision 6 to emergency plan MCINTOSH, M D Duke Power Co 82/07/31 47pp 14579 234 24X Fiche 50-369, 82/08/13, 8208260374
- 8208260336 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/08/16 Docum Management Branch 1p 14575 310 24X Fiche 50-369,82/08/16, 8208260336
- --B208260340 Forwards public version of revised emergency plan implementing procedures including Procedures EP/0/A/5000/05 re notification of unusual event, EP/0/A/5000/06 re alert & EP/0/A/5000/07 re site emergency
 TUCKER, H B , GLOVER, M S Duke Power Co B2/0B/05 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 3pp (4575 3)
 24% Fiche 50-369, 82/08/16.8208260336
- --8208260345 Public version of revised emergency plan implementing procedures including Procedures EP/0/A/5000/05 re notification of unusual event EP/0/A/5000/06 re alert & EP/0/A/5000/07 re site area emergency QLOVER, M S. ALMOND. J. MCCONNEL, T. Duke Power Co. 82/08/31 175pp 14575 315 24X Fiche 50-369, 82/08/16. 8208260336

I Financial information

- 8208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981 TUCKER: H B Duke Power Co 82/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14599 227 24X Fiche 80-000, 82/08/24, 8208300328
- --8208300335 Annual Financial Rept 1981 HORN.C Duke Power Co 82/02/15 48pp 14899 006 24X Fiche 50-000.82/08/24.8208300328

P Operating license stage documents & correspondence

- B207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS.W J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14:94 QDi
 24X Fiche 50-000:82/07/02.8207080064
- 8208040523 Notification of 820804 meeting w/utils in Bethesda.MD to discuss results of R&D program for hydrogen control & combustion in ice condenser plants STANLE: C Licensing Branch 4 82/07/21 ADENBAM,E 0 Licensing Branch 4 2pp 14220 342 24X Fiche 50-000,82/07/21,8208040523
- 8208030458 Forwards info requested in Sections 2 1 & 2 3 of NRC 801822 generic 1tr re NUREO-0612, "Control of Heavy Loads" One oversize drawing encl Apenture card is available in PDR PARKER, W O Duke Power Co 82/07/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 22pp 14160 205 24X Fiche 50-369,82/07/26.8208030458
- --8208030464 Revision 1 to "Reactor Bldg Polar Crane & Auxiliary Hoist Operation " * Duke Power Co 82/02/22 3pp 14160 227 24X Fiche 50-369, 82/07/26, 8208030458
- --8208030471 "Handling of Heavy Loads "
 # Duke Power Co. 82/04/14 2pp 14160 230 24X
 Fiche 50-369,82/07/26,8208030458
- --8208030479 Revision 1 to "Cranes & Hoists Safety Insp " HUNNING.R Duke Fower Co 82/06/17 18pp 14160 232 24X Fiche 50-369,82/07/26,8208030458
- --8208030487 "8lings Safety Insp " SUDDUTH.A : 810MAN.J Duke Power Co 74/06/15 Spp 14160,250 24% Fiche 50-369.82/07/26.8208030458
- --8208030495 "Chain Hoists Safety Insp " SUDDUTH,A , BIGMAN.J Duke Power Co 76/06/15 10pp 14160,255 24X Ficher 50-369,82/07/26,8208030458
- --8208030502 "Hooks Safety Insp " SUDDVTH.A., SIOMAN.J Duke Power Co 76/06/15 5pp 14160 265 24% Fiche 30-369,82/07/26,8208030458
- --8208030510 Revision 1 to "Cranes & Hoist Program" * Duke Power Co 82/03/16 7pp 14160 270, 24X Fishe 50-369,82/07/26,8208030458

- ~~8208030518 "Fuel & Component Handling " No date * Duke Power Co 82/07/26 53pp 14160 277 24X Fiche 50-369,82/07/24.8208030458
- 8208040169 Forwards final response to NRC 820325 request for info on Franklin Research Ctr concern re equipment qualification PARKER, N O Duke Power Co 82/07/28 DENTON, H R Office of Nuclear Reactor Regulation, Director Au
- 820804063B Summary of 820714 meeting w/util & Westinghouse in Bethesda, MD re exams & evaluations concerning thermal sleeves BIRKEL.R A Licensing Branch 4 82/07/28 Licensing Branch 4 33pp 14223 337 24X Fiche 50-369, 82/07/28, 8208040638
- 8208030541 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs & O through & 3 re util reorganization, superintendent of operations qualification requirements & organization chart Class I & II amend fees encl PARKER.W O Duke Power Co 82/07/30 DENTON,H R DFfice of Nuclear Reactor Regulation, Director 3pp 14142 353 24X Fiche 50-000.82/07/30,8208030541
- --8209030551 Forwards Class I & II amend fees to cover revisions to Tach Specs & 2 re offsite & station organization & 6 O through & 3 re reorganization PARKER, W O Duke Power Co 82/07/30 MILLER, W E Office of the Controller ip 14162 356 24X Fiche 50-000.82/07/30,8208030541
- 8208030572 Application for amend to License NPF-9, changing Tech Specs to revise descriptions of offsite b station organizations so that operations superintendent will not be required to maintain senior reactor operator license after appointment PARKER. W O Dute Power Co 82/07/30 DENTON H R Office of Nuclear Reactor Regulation, Director ADENBANA E 9 Licensing Branch 4 2pp 14162 250 24X Fishe 50-369, B2/07/30, 8208030372
- --8208030579 Proposed revision to Tech Spec & 2 re offsite & station organizations Discussion of revision encl a Duke Power Co 82/07/30 9pp 14162 253 24X Fiche 50-369.82/07/30.8208030572
- 820813033B Notifies that Apr 1982 Revision & to spent fuel transportation plan meets requirements of 10CFR73 37 & is approved Revised plan contains safeguards info which should be mithheld (ref 10CFR73 21)
 SHERR, T S Division of Safeguards 82/08/03 PARKER, W D Duke Power Co 1p 14340 240 24X Fiche 50-349, 82/08/03, 8208130338
- 8208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14354-332 24X Fichs 50-000, 82/08/09, 8208090194
- 8208230145 Forwards request for add1 info re CLASIX Code, Topical Rept OP8-07A35 Coordinated Util response suggested by 821001, since subj is generic to ice condenser plants.

 NOVAK,T M Assistant Director for Licensing 82/08/07 TUCKER,H M

 Duke Power Co. 14pp 14518 012 24X Fiche 50-369,82/08/09,
 8208230145
- 8208260506 Advises that operating program for Jul-Nov 1982 acceptable, including operation at 75% power for max 720-h (30 days) Summary of results of review encil NDVAN.T H Assistant Director for Licensing 82/08/13 TUCKER.H B Dute Power Co. 7pp 14595 037 24X Fiche 50-369,82/08/13,8208260506
- 8208260318 Notification of 820825 meeting w/Duke Power Co.SC Electric & Qas Co & TVA in Bethesda.MD to review BER for Model D steam generator mode XANE.W F Licensing Branch | 82/08/16 YOUNOBLOOD, B Licensing Branch | 5pp 14576 112 24X Fiche 50-000.82/08/16.8208260318.
- 8208260136 Forwards Revision 3 to "Pump & Valve Inservice Testing Program," per 10CFR50 55a(g), reflecting results of 820323-25 meetings between util & EG&O Program upgraded to 1980 Edition of ASME Boiler & Pressure Vessel Code TUCKER, H B Duke Power Co B2/08/17 DEMTON, H R Dffice of Nuclear Reactor Regulation, Director ADEMBAN, E G Licensing Branch 4 1p 14554 036 24X Fiche 50~367,82/08/17,8208240136
- --8208260138 Revision 3 to "Pump & Valve Inservice Testing Program" * Duke Power Co 82/08/17 200pp 14954 037 24X Fiche 50-369.82/08/17.8208260136

- 8208270596 Reviews licensee submittals re NUREG-0737, Items [I F] 4, II F I 5 & II F I 6. concerning containment pressure, water level & hydrogen monitors respectively Requirements met & items considered resolved NDVAK.T H Assistant Director for Licensing 82/08/23 TUCKER.H B Duke Power Co 4pp 14483 223 24% Fiche 50-344.82/08/23,
- 3 Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274, 24% Fiche 50-000, 82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3. Suppl 1. "Clarification of Placement of Personnel Homotoring Devices for External Radiation " Svc list encl JURDAN, E. L. Division of Engineering & Guality Assurance, 82/07/19 Hichigan, Univ. of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 tE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Fressure" Svc list and JORDAN,E L. Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 62/07/20 Consolidate Edison Co of New York 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche. 50-000, 82/07/22, 8204210398
- 8208160326 Forwards IE Insp Repts 50-369/82-23 & 50-370/82-15 on 820622-25 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/07/22 PARKER.H O Dute Power Co. 2pp 14348 030 24X Fiche 50-369.82/07/22.8208160326
- --8208160396 IE Insp Repts 50-369/82-23 & 50-370/82-15 on 820622-25 No noncompliance noted. Hajor areas inspected const progress, spent fuel storage racks, safety-related components, reactor vessel installation & licensee action on previous findings KLEINBOROE, H P. ECONOMOS, N. Division of Project & Resident Programs 82/07/16 7pp 14348 032 24X Fiche 50-369,82/07/22,8208160326
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23,8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Mestinghouse AWRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche. 50-000, 82/07/23, 8204210402
- 6208160256 Forwards IE Insp Repts 50-369/82-24 & 50-370/82-16 on 620516-0620 No noncompliance noted DANCE,H C. Division of Project & Resident Projemm 82/07/23 PARKER, W. O. Duke Power Co. 2pp 14347 001 24X Fiche 50-369, 82/07/23, 8208160256
- --B20Bi60262 IE Insp Repts 50-369/B2-24 & 50-370/B2-16 on B205i6-0602 No noncompliance noted Major areas inspected surveillance, plant transient & significant event followup operational setaty verification & maint BEMIS.P.R.; HOPKINS.P.; BRYANT.J.C. Division of Project & Resident Programs B2/07/22, lipp, 14347 003. 24X Fiche.50-369,B2/07/23,B20Bi60256
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JRRDAN:E L Division of Engineering & Quality Assurance, 82/07/26 Consolidated Edison Co of New York 12ipp 14337-013 24X Fiche. 50-000. 82/07/26, 8204210403
- 8208140167 Forwards IE Insp Rept 50-367/82-25 on 820708-09, No noncompliance noted DANCE, H C Division of Project & Resident Projects. 82/07/26 PARKER, H D Duke Power Co 2pp 14345:146 24X Fiche 50-369, 82/07/26, 8208160167.

- --8208160171 IE Insp Rept 50-369/82-25 on 820708-09 No noncompliance noted Major areas inspected missing thermal sleeve, personnel air lock door seals & eddy current exam of steam generator tubing KLEINSCROE, W.P. ECONOMOS, N. Division of Engineering & Technical Programs 82/07/23 App. 14345-148 24X Fiche 50-369,82/07/26,8208160167
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Hort in Fuel Storage Pool " Svc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14337,146, 24X Fiche 50-000, 82/07/28,8204210405
- 8208160201 Ack receipt of IE Insp Repts 50-369/82-16 & 50-370/82-11 No proprietary info PARKER, W O Dute Power Co 82/07/28 O'REILLY, J P Region 2, Defice of Director 1p 14342 361 24X Fiche 50-369,82/07/28, 9208160301
- 8208160196 Ack receipt of IE Insp Rept 50-369/82-22 No proprietary info PARKER, W D Duke Power Co 82/07/29 O'REILLY, J P Region 2, Office of Director, 10 14342 362 24% Fiche 50-369,82/07/29, 8208160196
- 8208160207 Ack receipt of IE Insp Repts 50-369/82-18 & 50-370/82-13 No proprietary info PARKER, N O Duke Power Co 82/07/30 O'REILLY, J P Region 2, Dffice of Director ip 14344 143 24X Fiche 50-369,82/07/30, 8208160207
- 8208160136 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Leak at reactor coolant pump iD noted No injection sealant matts used on closures or connections.

 TUCKER, H B Duke Power Co 82/08/02 O'REILLY, J P Region 2. Office of Director 4pp. 14344 172 24X Fiche 50-369,82/08/02,8208160136
- 8208160379 Ack receipt of 820709 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/82-17 & 50-370/82-12 BANCE, H C Division of Project & Resident Programs 82/08/02 PARKER, W O Duke Power Co ip 14349 063 24X Fiche 50-369, 82/08/02, 8208160379.
- --B20Bi603BB Forwards response to NRC B20611 ltr re violations noted in IE Insp Repts 50-369/82-17 & 50-370/82-12 Corrective actions Level IV cleanliness sign posted at entrance to lower annulus & program for signs being developed.

 PARKER, W D Duke Power Co B2/07/09 D'REILLY, J. P. Region 2, Office of Director 3pp 14349 064 24% Fiche 50-369,82/08/02,820B160379
- --8208160392 Forwards IE Insp Repts 50-369/82-17 & 50-370/82-12 on 820417-0515 & notice of violation DANCE.H C. Division of Project & Resident Programs 82/06/11 PARKER,H Q. Duke Power Co 2pp. 14349 067 24X Fiche 50-369,82/08/02,8208160379
- --8208160397 Notice of violation from insp on 820417-0515 * Division of Project & Resident Programs. 82/06/11, ip. 14349*067 24X Fiche 50-369,82/08/02,8208160379
- --8208180401 IE Insp Repts 50-369/82-17 & 50-370/82-12 on 820417-0515 Noncompliance noted failure to comply w/housekeeping & cleanliness requirements BEMIS.P.R. HOPKINS.P. HEATHERLY.T Division of Project & Resident Programs 82/06/11 9pp 14349 070 24X Fiche 50-369.82/08/02.8208160379.
- 8208030254 Forwards results of eddy current insp of steam generators for Apr-June 1982 Insp revealed tube wear rate at 75% power on 29 tubes. Operating time above 50% power will be restricted to 30 days.

 TUCKER.H. B Duke Power Co 82/08/03 DENTON.H.R Office of Nuclear Results of Regulation, Director ADENSAM E 0 Licensing Branch 4 9pp. 14209, 352 24% Fiche 50-369, 82/08/03, 8208050254
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffls Water-Jet Impingement" Svc list encl.
 JORDAN:E L Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp, 14388 201 24X
 Fiche: 50-000: 82/08/05: 8204210407
- 8208160499 Forwards Rayision 2 to util 791101 response to IE Bulletin 79-14. Rayision 1. Suppl 2. "Beismic Analysis for As-Built Safesty-Related Piping Bys" Dasign & srection of Unit 2 progressed to mear completion w/program similar to Unit 1. TUCKER. H. B. Duke Power Co. 82/08/05 O'REILLY. J. P. Region 2. Office of Director. 7pp 14348 298 24X Fiche 50-369. 82/08/05, 82/08/60499

- R Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dase exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 30-000.82/07/13.8208270010
- --8208270078 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CYB1" • NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24% Fiche 50-000.82/07/13.8208270010
- --B20B270597 Forwards "Tabulation of Number of Personnel & Person Ram By Hork & Jab Function for 1981: "per 10CFR20 407 PARKER,W D Duke Power Co B2/03/09 D'REILLY, J P Region 2, Office of Director 1p 14680 042 24X Fiche 50-000, B2/07/13, B20B270010
- --8208270398 "Tabulation of Number of Personnel & Person Rem By Work & Job Function for 1981"

 * Duke Power Co 82/03/09 2pp 14680 043 24X
 Fiche: 50-000, 82/07/13, 8208270010
- --8208270607 Forwards "Personnel Whole Body Exposures for CY81," per 10CFR20 407(a) & (b) PARKER, H O Duke Power Co 82/03/09 BASSETT, H 6 Office of Management and Program Analysis 1p 14680 045 24x Fiche 50-000, 82/07/13, 8208270010
- --8208270614 "Personnel Whole Body Exposures for CY81 " LEMIG.L. Duke Power Co. 82/03/07 ip 14680 046 24X Fiche 50-000,82/07/13,8208270010
- 820B170150 Forwards monthly operating rept for Jul 1982 TUCKER.H B Duke Power Co 82/08/13 Director's Office of Insection and Enforcement 1p 14364 210 24X Fichs 30-367.82/08/13.8208170150
- --8208170155 Monthly operating rept for Jul 1982 REAVIS.J A Duke Power Co 82/08/13 7pp 14364 211 24X Fiche 50-369,82/08/13.8208170150
- 8 Reportable occurrences, LERs & related correspondence
- 8208020121 Informs of delay in submittal of RO 369/82-54 re reactor trip sys instrumentation channel & interlock response times.violated on 820618 Rept will be submitted by 820727 PARKER.W O Duke Power Co 82/07/16 O'REILLY.J P Region 2, Office of Director ip 14150 058 24X Fiche, 50-369, 82/07/16, 8208020121
- 8208020075 Forwards LER 82-056/01T-0 PARKER,W O Duke Power Co 82/07/20 O'REILLY,J P Region D. Office of Director 2pp 14144 107 24X Fiche 50-369,82/07/20. 8208020075
- 8208020097 Forwards LER 82-048/03L-0 PARKER, W D Duke Pawer Ca 82/07/20 D'REILLY, J P Region 2, Office of Director 1p 14144 098 24X Fiche, 50-369, 82/07/20, 8208020087.
- --8208020090 LER 82-048/03L-0 on 820603, after receiving battery EVCD trouble alarm, no indication received on pressurized power operated relief valve NC-32 & valve not operable. Caused by ground which blew fuse Valve repaired NARDOCI.P B. Duke Power Co 82/07/20 Region 2, Office of Director ip 14144 099 24X Fiche 50-369, 82/07/20, 8208020087.
- 8208020144 RO 369/82-85 on 820620, accident monitoring instrumentation channels became inoperable Cause not stated Complete rept to be submitted by 820729 PARKER, N.O. Duke Fower Co 82/07/20 O'REILLY, J P Region 2, Diffice of Director. ip. 14142 024 24X Fichs. 50-369, 82/07/20, 8208020144
- 8208030211 Forwards LER 82-057/03L-0 PARKER, W. D. Duke Power Co. 82/07/23 O'REILLY, J. P. Region 2, Office of Director 1p 14159 348 24X Fiche: 50-369, 82/07/23, 8208030211

- --8208030215 LER 82-057/03L-0 on 820621.component cooling pump 1A2 declared inoperable during investigation of high bearing temp alarm on pump motor Caused by inboard bearing failure Cooling load responsibility changed to train B NARDOCI.P 8 Dute Power Ca 82/07/23 Region 2, Office of Director ip 14155 349 24X Fiche 30-369, 82/07/23, 8208030211
- 8208050197 Forwards LER 92-059/03L-0 PARKER,W C Duke Power Co 82/07/26 D'REILLY, J P Region 2, Office of Director 1p 14212 144 24X Fiche 50-369, 82/07/26, 8208050197
- --8208050203 LER 82-059/03L-0 on 820626, during Mode 4 & Mode 5 of maint outage, ice condenser bastets weighed less than Tech Spec min Caused by sublimation of ice Frosh ice & borax solution added to ice bastets

 NARDOCI,P B Duke Power Co 82/07/26 Region 2, Office of Director ip 14212 145 24X Fiche 50-369,82/07/26,8208050197
- 8208050244 RO 369/82-58 on 820624.RC6 lowest operating loop temp was not greater than or equal to 55! Flas required by Tech Specs All required info not available by 820723 Rept will be submitted by 820804 PARKER, W O Duke Power Co 02/07/26 O'REILLY, J P Region 2, Office of Director 1p 14211 199 24X Fiche 50-369,82/07/26,8208050244
- 8208050355 Forwards LER 82-054/03L-0 CARTWRIGHT, W.R. Duke Power Co. 82/07/27 O'REILLY, J.P. Region 2, Office of Director 10 14209 178 24X Fiche 50-359, 82/07/27, 920905035
- --8208080A02 LER 82-054/03L-0 on 820618.ex-core nuclear instrumentation sys power range channel N-41 declared imperable due to spurious indications of out-of-tolerance quadrant power tilt ratio Caused by failure of neutron detector NARDOCI,P B Duke Fower Co 82/07/27 Region 2, Diffice of Director 1p 14209 179 24X Fiche.50-369,82/07/27,8208030355.
- 8208090232 Forwards LER 82-055/03L-0 PARKER, H O Duke Power Co 82/07/29 O'REILLY, J P Region 2, Office of Director 1p 14271 098 24% Ficha: 50-369, 82/07/29, 8208090232
- --8208070235 LER 82-055/03L-0 on 820620, routine surveillance discovered that one channel of containment sump water level monitoring instrumentation indicated level of 1/2 ft w/no water in sump Caused by leak in capillary line NARDUCI,P B Duke Power Co 82/07/27 Region 2, Office of Director ip 14271 099 24X Fiche 50-369,82/07/29,8208090232
- 8208160412 Forwards updated LER Bi-IBI/O3X-1 Detailed event analysis encl TUCKER, H B Duke Power Co 82/08/03 Q'REILLY. J P Region 2, Office of Director 5pp 14349.140 24X Ficho 50-369,82/08/03, 8208160412
- --8208160418 Updated LER 81-181/03X-1·on 811112,125-volt do vital instrumentation & control power battery EVCB dislared inoperable & returned to svo twice before shutdown Caused by low specific gravity on cell 16 Cell jumpered out NARDOCI,P B Duke Power Co 82/08/03 Region 2, Office of Director ip. 14349 145 24X Fiche 50-369,82/08/03,8208160412
- 8208130175 Supplemental RO 369/82-13 due to ambiguity in procedure to recalibr level switches for upper head injection train A isolation valves, switches set at 73 8 plus/minus O 25 inches rather than 73 3 plus/minus O 25 inches TUCKER.H B Duke Power Co 82/08/04. O'REILLY, J P Region 2, Office of Director ip 14938 327 24X Fiche 50-969, 82/08/04, 8208130175
- B20B13023B Revision 1 to RO 369/B1-i5i: on B10914.during loss of control room test, excessive feedwater pumped into steam generators resulting in safety injection actuation Gaused by design deficiency Auxiliary shutdown panels will be modified TUCKER.H B. Duke Power Co 82/08/04. D'REILLY, J P Region 2, Office of Director App 14333.173 24X Fiche 50-369.82/08/04. 8208130238
- 8208200022 Forwards LER 82-058/03L-0 Detailed event analysis encl. TUCKER.H B. Duke Pawer Co. 82/08/06 O'REXLLY.J P Region 2, Office of Director. 3pp 14393 019. 24X Fiche 50-369,82/08/06,8208200022.
- --8208200034 LER 82-058/03L-0 on 820824.RCB average temp dropped below 551 F w/reactor critical Caused by operator attempting shutdown w/o corresponding drop in steam loads, Cautionary note added to procedure & personnel resinstructed NARDOCI.P.B. Duke Power Co 82/08/06 Region 2, Office of Director. 1p. 14373:022 24X Fiche.50-369,82/08/06.8208200022

- 8208200247 Forwards LER 82-040/03L-0 TUCKER: H B Duke Power Co 82/08/10 G'REILLY, J P Region 2, Office of Director ip 14399 307 24X Fiche 50-349,82/08/10, 6208200247
- --8208200261 LER 82-060/03L-0 on 820701.06 & 13.fire detection systrouble alarms could not be cleared & EFA Jones 63 & 64 declared inoperable Caused by corrosion due to water leakage into data gathering panel 1 Failed components replaced NARDBCF, P B Duke Power Co 82/08/10 Region 2, Office of Director 1p 14399 308 24x Fiche 50-369,82/08/10,820820024/
- DOCKET 80-370 WILLIAM 8 MCGUIRE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licenses of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list encl
 DIRCKS, W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 OOI
 24X Fiche 50-000,82/07/02,8207080064
- 8208040523 Notification of 820804 meeting w/utils in Bethesda.MD to discuss results of R&D program for hydrogen control & combustion in itse condenser plants 87AMLE.C Licensing Branch 4 82/07/21 ADENSAM.E & Licensing Branch 4 2pp 14220 342 24X Fiche 50-000.82/07/21.8208040523
- 8208030458 Forwards (nfo requested in Sections 2 1 & 2 3 of NRC 801222 generic ltr re NUREG-0612, "Control of Heavy Loads" One oversite drawing encl Aperture card is available in PDR PARKER, # 0 Duke Power Co 82/07/26 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 0 Licensing Branch 4 22pp 14160 205 24X Fiche 50-369.82/07/26.8208030458
- --8208030464 Revision 1 to "Reactor Bldg Polar Grane & Auxiliary Hoist Operation " # Duke Power Co 82/02/22 3pp 14160 227 24X Fiche 50-364,82/07/26.8208030488
 - Fiche 50-369, 82/07/26, 8208030458
- --8208030471 "Handling of Heavy Loads "

 * Duke Pawer Co 82/04/14 2pp 14160 230 24% fiche 50-369,82/07/26,8208030458
- --9208030479 Revision 1 to "Cranes & Hoists Safety Insp " HUNNING.R Duke Power Co 82/06/17 18pp 14160 232 24x Fich: 50-369,82/07/26.8208030458
- --9208030487 "8lings Bafoty Insp " SUDDUTH.A. SIGMAN.J Duke Power Co 76/06/15 5pp 14160 250 24X Fichs 50-349,82/07/26.0208030458
- --B206030495 "Chain Hoists Safety Insp " 5UDDTH:A , BIGMAN J Duke Power Co 76/06/15 10pp 14160 255 24x Fiche 30-369,82/07/26.8208030498
- --8208030502 "Hopks Safety Insp " SUDDUTH:A., GIGHAN, J. Duke Power Co. 76/06/15 Spp. 14160 265 24% Fiche 50-367,82/07/26,8208030458
- ~~8208030310 Revision i to "Crenes & Hoist Program"

 * Date Power Co 82/03/16 7pp 14160 270 24X
 Fishe 50-369,82/07/26,8208030459
- --8200030518 "Fuel & Component Handling " No date
 # Duke Power Co 82/07/26 83pp 14160 277 24x
 Fiche 50-369,82/07/26,8208030468
- 8208040169 Forwards final response to NRC 820325 request for info on Franklin Resoarch Ctr concern re equipment qualification PANKER, W O Duke Power Co 82/07/28 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAME O Licensing Branch 4 44pp 14185 319 24X Fiche 50-369.82/07/28,8208040169
- 3208040638 Summary of 820714 meeting w/util & Hestinghouse in Bethenda, MD re exams & evaluations concerning thermal sleeves SIRKEL.R A Liscensing Branch 4 82/07/28 Licensing Branch 4 33pp 14223 337 24X Fiche 50-369.82/07/28.8208040438
- **OBO90194 Generic Ltr 82-14 to all reactor litensees, holders of CP & applicants re submittal of documents to NRC Summarazes 10CFR hapter I requirements & provides alternatives to equirements Soc list encl 18ENHUT, D O Division of Licensing 82/08/09. Consolidated ison Co of New York Ip 14356 332 24X Fiche 50-000.82/08/09, 78090194

- 8208230145 Forwards request for add1 info re CLASIX Code. Topical Rept OPS-07A35 Courdinated util response suggested by 821001, since subj is generic to ice condenser plants NOVAK.T M Assistant Director for Licensing 82/08/09 TUCKER, H B Duke Power Co 14pp 14518 012 24X Fiche 50-369,82/08/09,8208230145
- 8208260318 Notification of 820825 meeting w/Duke Power Co.8C flectric ½ Gas Co & TVA in Bethesda.MD to review BER for Model D steam generator mods KANE.W F Licensing Branch 1 82/08/16 YOUNGBLOOD.B Licensing Branch 1 5pp 14576 112 24X Fiche 50-000.82/08/16.8208260318
- 8208270576 Reviews licenses submittals re NUREG-0737. Items II F 1 4, II F 1 5 & II F 1 6, concerning containment pressure, water level & hydrogen monitors, respectively Requirements met & items considered resulved NOVAK, T M Assistant Director for Licensing \$2/08/23 TUCKER, N B Duke Power Ca 4pp [4683 223 24X Fiche 50-369, 82/08/23, B208270576
- F Security, medical, emergency & fire protection plans
- 8208030066 Releases public version of ravised emergency plan implementing procedura FELTON, J M Division of Rules and Records 82/07/19 Document Management Branch ip 14198 OOI 24X Fiche 50-369,82/07/19, 8208030066
- --B208030073 Forwards public version of revised emergency plan implementing procedures, including Station Directive 3 7 3 rg telephone procedures/bomb threat check list & Procedure EP/1/A/3000/01 re immediate actions & diagnostics PARKER, W O Duke Power Co 82/07/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14198 002 24X Fiche 50-369,82/07/19,8208030066
- --B208030084 Public version of revised emergency plan implementing procedures, including Station Directive 3 7 3 re telephone procedures/bomb threat checklist & Procedure EP/1/A/5000/01 re immediate actions & diagnostics buke Power Co 82/06/28 275pp 14198 004 24% Fiche 50-369,82/07/19,8208030066
- B208100305 Requests amend to License Condition 2 C (11)n (2) to change deadline for anstallation of upgraded metaorological sys, from Oct 1983 to B30731.per 820727 telcon
 TUCKER.H B Duke Power Co B2/08/03 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E 9 Licensing Brench
 4 1p 14277 13B 24X Fiche 50-367,82/08/03.8208100305
- 8208260418 Releases public version of revised crisis mgt plan FELTON, J M Division of Rules and Records 82/08/11 Document Management Branch 1p 14572 098 24X Fiche 50~000,82/08/11, 8208260418
- --8208240430 Forwards public version of Revision 5 to crisis mgt plan Revision involves reorganization of crisis mgt team & updates of Sections D.K & M PARKER, M. O Duke Power Co 82/07/19 DENTON, M R Office of Nuclear Reactor Regulation, Director 1p 14572 099 24X Fiche 50-000, 82/08/11, 8208240418
- --B208260437 Public version of Revision 5 to crisis mgt plan TUCKER, H B Duke Power Co 82/07/09 134pp 14572 100 24X Fishe 50-000, 82/08/11, 8208260418
- 8208260376 Releases public version of revision to emergency plan FELTON.J M Division of Rules and Records 82/08/13 Document Management Branch 1p 14879 229 24X Fiche 50-369,82/08/13, 8208260376
- --8208260385 Forwards public version of Revision 6 to emergency plan
 Instruction sheet encl
 TUCKER, H B., GLOVER, M Duke Power Co 82/08/06 DENTON, H R,
 Office of Nuclear Reactor Regulation, Director 4pp 14579, 230
 24X Fiche 50-369, 82/08/13, 8208260376
- --8208260392 Public version of Revision 6 to emergency plan MCINTOSH, M D Duke Power Co 82/07/31 47pp 14579 234 24X Fiche 50-369, 82/08/13, 8208260376
- 8208260336 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/08/16 Document Management Branch. 1p 14575 310 24X Fiche: 50-369, 82/08/16, B208260336

- --8208260340 Forwards public version of revised emergency plan implementing procedures including Procedures EP/G/A/5000/05 re notification of unusual event. EP/O/A/5000/06 re alert & EP/O/A/5000/07 re site emergency TUCKER, H B , GLOVER, H B Duke Power Co 82/08/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 14575 311 24X Fiche 50-369,82/08/16,8208260336
- ---B208260345 Public version of revised emergency plan implementing procedures, including Procedures EP/D/A/5000/05 re notification of unusual event. EP/D/A/5000/05 re alert & EP/D/A/5000/07 re site area emergency GLOVER.M S , ALMOND.J , MCCONNELLT Duke Power Co 82/08/31 175pp 14575 315 24X Fiche 50-349,82/08/16.8208260336

I Financial information

- B20B30032B Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981 TUCKER:H B Duke Power Co B2/0B/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp, 14599 227 24X Fiche 50-000:B2/0B/24.B20B30032B
- --8208300335 Annual Financial Rept 1981 HORN.C Duke Power Co 82/02/15 48pp 14599 004 24) Fiche 50-000,82/08/24-8208300328
- Q Inspection reports. IE Bulletins & correspondence
- 8208030329 Forwards IE Insp Rept 50-370/82-14 on 820615-19 No noncompliance noted DANCE:H C Division of Project & Resident Programs 82/07/08 PARKER:WO Duke Power Co Epp 14154 204 24X Fiche 50-370,82/07/08,8208030329
- --8208030409 IE Insp Rept 50-370/82-14 on 820615-18 No noncompliance noted Major areas inspected licensee identified items & review of as-built drawings OIBBONG, T D , CONLON, T E Division of Engineering & Technical Programs 82/07/02 3pp 14154 206 24X Fiche 50-370,82/07/08,8208030329
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl.
 JORDAM E L Division of Engineering & Guality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 30-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3. Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN.E.L Division of Engineering & Quality Assurance 82/07/19 Michigan. Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp. 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Hater Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp. 14357 276 24X Fiche 50-000.82/07/20.8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures," Svc list encl JGRDAN,E L Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321. 24X Fiche 50-000,82/07/22,8204210398
- B208160326 Forwards IE Insp Repts 50-369/B2-23 & 50-370/82-15 on B20622-25 No noncompliance noted DANCE H C Division of Project & Resident Programs B2/07/22 PARKER, M. O Duke Power Co 2pp 14348 030. 24x Fiche 50-369, 82/07/22, 8208160326
- --8208160396 IE Insp Repts 50-369/82-23 & 50-370/82-15 on 820622-25. No noncompliance noted Major areas inspected compt progress, spent fuel storage racks; safety-related components, reactor vessel installation & licensee action on previous findings KLEINBOROE, W. P. ; ECONOMOS, N. Division of Project & Resident Programs 82/07/16 7pp. 14348 032 24X Fiche, 50-369, 82/07/22, 8208160326.

- 8204210401 IE Info Notace 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23.8204210401
- 8204210402 IE info Notice 82-29, "Control Rod Drive (CRD) guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl, JORDAN,E L Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co of New York 127pp 14194-120 24X Fiche 50-000,82/07/23,8204210402
- 820B160235 Forwards IE Insp Rept 50-370/82-17 on 820706-09 No noncompliance noted DANCE, H. C. Division of Project & Resident Programs 82/07/23 PARKER, W. O. Dute Power Co. 2pp 14342 293 24X Fichs 50-370, 82/07/23, 8208160235
- --B208160244 IR Insp Rept 50-370/82-17 on B20706-07 No nancompliance noted Major areas inspected; preoperational test procedure reviews & preoperational test package reviews JOHNSON A H. JAPE, F Division of Engineering & Technical Programs 82/07/21 4pp 14342,275 24X Fiche 50-370.82/07/23,8208160235
- 8208160256 Forwards IE insp Repts 50-369/82-24 & 50-370/82-16 on 820516-0620 No noncompliance moted.

 DANCE: H C Division of Project & Resident Programs 82/07/23. PARKER. W C Duke Power Co 2pp. 14347 OO1 24X Fiche 50-369
- --8208160262 IE Insp Repts 50-367/82-24 & 50-370/82-16 on 820516-0602 No noncompliance noted Major areas inspected surveillance, plant transient & significant event follows, operational safety verification & maint.

 BEMIS: P. R. HOPKINS: P. BRYANT-J C Division of Project & Resident Programs 82/07/22 itpp. 14347 003 24% Fiche 50-369,82/07/23,8208160256
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PMR Power Plants" Svc list encl.

 JCROAN E L Division of Engineering & Quality Assurance. 82/07/26

 Consolidated Edison Co of New York, 121pp 14357 013 24X

 Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Bturage Pool." Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146. 24X Fiche 50-000. 82/07/28.8204210405.
- B208160201 Ack receipt of IE Insp Repts 50-369/82-16 k 50-370/82-11 No proprietary info PARKER, W U Duke Power Co 82/07/28 O'REILLY, J P Region 2, Office of Director ip 14342 361. 24X Fiche: 50-369, 82/07/28, 8200160201
- 8208160207 Ack receipt of IE Insp Repts 50-369/82-18 & 50-370/82-13 No proprietary info PARKER, # O Duke Power Co 82/07/30. O'REILLY, J.P. Region 2, Office of Director, 1p. 14344 143, 24% Fiche, 50-369, 82/07/30, 8208160207
- 820Bi60379 Ack receipt of 820709 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/82-17 & 50-370/82-12 DANCE.H C. Division of Project & Resident Programs 82/08/02 PARKER.W O Duke Power Go. ip 14349.063, 24X Fiche: 50-369, 82/08/02.8208i60379
- --8208160388 Forwards response to NRC 820611 ltr re violations noted in IE Insp Repts 50-369/82-17 & 50-370/82-12 Corrective actions: Level IV cleanliness sign posted at entrance to lower annulus & program for signs being developed PARKER: W D Duke Power Co 82/07/09. D'REILLY, J P. Region 2, Office of Director. 3pp 14347 064. 24X Fichs 50-369,82/08/02,8208160379
- ---8208160392 Furwards IE Insp Repts 50-369/82-17 & 50-370/82-12 on 820417-0515 & notice of violation DANCE.H.C Division of Project & Resident Programs 82/06/11, PARKER:W U Duke Power Co. 2pp. 14349 067 24% Fiche: 50-369, 82/08/02, 8208160379
- --8208160397 Notice of violation from insp on 820417-0515.

 **pivision of Project Resident Programs. B2/06/11. ip 14449:069. 24% Fichs 50-349,82/08/02.8208160379

- --8205160401 IE Insp Repts 50-369/82-17 & 50-370/82-12 on 820417-0515 203460401 IE Insp Repts 30-367/82-17 & 30-37/82-12 on Seven.
 Noncompliance noted failure to comply w/housekeeping &
 cleanliness requirements
 BEMIS, P.R. HOPKINS, P. HEATHERLY, T. Division of Project &
 Resident Programs 82/06/11 9pp 14349 070 24X
 Piche 50-369,82/08/02.8208160379
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000,82/08/05,8204210407
- 8208160264 Ack receipt on 820714 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-370/82-10 DANCE, H C Division of Project & Resident Programs 82/08/05 TUCKER, H B Duke Power Co 1p 14346 243 24X Piche 50-370,82/08/08.8208160264
- --B20B160270 Responds to NRC B20614 ltr re violations noted in IE Insp Rept 30-370/B2-10 Corrective actions fire detection sys Rept 30-30-102 & Commission of the second of
- --8208160277 Forwards IE insp Rept 50-370/82-10 on 820511-14 & notice of deviation
 DANCE, H C Division of Project & Resident Programs 82/06/14
 PARKER, W O Duke Power Co 2pp 14346 248 24X
 Fishs 30-370, 82/08/05, 8208160264
- --8208160280 Notice of deviation from insp on 820511-14 * Division of Project & Resident Programs 82/06/14 2pp 14346 250 24% Fiche 50-370, 82/08/05,8208160264
- --8208160287 IE Insp Rept 50-370/82-10 on 820511-14 Noncompliance noted failure to install fire detection sys in fuel storage area prior to receipt of fuel & substandard fire protection OA program MILLER.W H Division of Project & Resident Programs 82/06/09 7pp 14346 252 24X Fiche 50-370.82/08/05.8208160264
- CB160499 Forwards Revision 2 to util 791101 response to IE Bulletin 79-14.Revision 1.Suppl 2. "Sersmic Analysis for As-Built Safety-Related Piping Sys "Design & erection of Unit 2 roogressed to near completion u/program similar to Unit 1 [UCKER.H B Dute Power Co 82/08/05 O'REILLY, J P Region 2.] Iffice of Director 9pp 14348 298 24X Fiche 50-369,82/08/05, 1208160499
- 18160481 Ack receipt of IE Insp Rept 50-370/82-14 No proprietory Dro UCKER, H B Dute Power Co 82/08/06 D'REILLY, J P Region 2, iffice of Director 1p 14348 213 24X Fiche 50-370, 82/08/06: ffice of Director 1p 208160481
- A Persodic operating reports & related correspondence
 - 8170159 Forwards first quarter 1982 Yellow Book updates re const PARROS. & L Duke Power Co 82/05/20 LOVELACE. H H Hanagemen formation Branch 5pp 14364 340 24X Fiche 50-000.82/05/20. Manacement iformation Branch 108170157
 - Reportable occurrences. LERs & related correspondence
 - 08030220 Significant Deficiency Rept SD 370/82-04 re cracked & broken OBGOGZZO Bignificant Deficiency Rept SD 370/82-04 re cracked & br switch mechanisms on Roturk Model NA-2 electric motur operators Initially reported on B20623 Actuators will have switch changeaut prior to fuel loading 'ARKER, U O Duke Power Co B2/07/23 O'REILLY, J.P. Region 2, lffice of Director Spp 14198 275 24X Fiche 50-370, B2/07/23, Iffice of Director
 - KET 50-373 LASALLE COUNTY STATION, UNIT 1 Security, medical, emergency & fire protection plans
 - B030096 Releases public version of revised LZP procedures. ELTON, J H Division of Rules and Records 82/07/19 Document Enagement Brench ip 14195 172 24X Fiche, 50~373, 82/07/19, 208030096

- --8208030100 Forwards public version of revised LZP procedures, including Procedures LZP-1200-4 re classification of liquid release & LZP-13030-21 re determination of reactor coolant chloride concentration at high radiation sampling sys HOLYDAK, R H Commonwealth Edison Co 82/06/21 Office of Nuclear Reactor Regulation, Director 1p 14195 173 24X Fiche 50-373,82/07/19,8208030096
- --8208030103 Public version of revised LZP procedures including Procedures LZP-1200-4 re classification of liquid release & LZP-1330-21 re determination of reactor coolant chloride concentration at high radiation sampling sys HDLYOAK,R H Cammonwealth Edison Co 82/06/11 200pp 14195 174 24X Fiche 50-373,82/07/19,8208030096
- 820B1102B6 Releases public version of offsite notification forms FELTON-J M Division of Rules and Records 82/08/03 Docum Management Branch 1p 14332 176 24X Fiche 50-373,82/08/03. B20B1102B6
- --8208110287 Forwards public version of offsite notification forms that have not been returned Verification of manual updates by signing & returning encl forms requosted * Commonwealth Edison Co 82/07/26 NRC No Detailed Affiliation Given 4pp (4332 177 24X Fiche 50-373, 82/08/03), Affiliation Given 4pp 8208110286
- 8208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures" FELTON. J M. Division of Rules and Records 82/08/12 Document Management Branch 1p 14559 354 24X Fiche 50-000.82/09/12.
- --8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 MORREL D Commonwealth Edison Co 82/07/19 DENTON.H R NRC No Detailed Affiliation Civen ip 14559 355 24X
 Fiche 50-000,82/08/12.8208250559
- --8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures " Commonwealth Edison Co 82/06/30 7pp 14559 355 24% Fiche 50-000, 82/08/12, 8208250559
- 8208310054 Forwards IE Safeguards Insp Rept 50-373/82-30 on 820614-17 to notice of violation Notice withheld (ref 10CFR2 790)
 MILLER, J R Division of Engineering & Technical Programs 82/08/24
 REED, C Commonwealth Edison Co 2pp 14689 270 24X
 Fiche 50-373, 82/08/24, 8208310054
- --8208310040 IE Safeguards Insp Rept 50-373/82-30 on 820614-17 Noncompliance noted failure to search hand carried item & failure to pat search visitors Details withheld (ref 10CFR2 790) BELANDER, J L , STAPLETON, B W , CREED, J R Ragion 3, Office of Director 82/08/17 2pp 14689 292 24% Fiche 50-373, 82/08/24, 8208310034
- Q Adjudicatory correspondence
- 8208040556 Responds to 820428 show cause petition on behalf of IL Friends of the Earth Parts of petition pertaining to Unit 1 denied. Decision will be issued upon completion of evaluation prior to decision re OL for Unit 2 OENTON: H R Office of Nuclear Reactor Regulation, Director 82/07/17 ROREM.B L Friends of the Earth 2pp. 14221 170 Fiche 30-373,82/07/19.8208040556 2pp. 14221 190 24X
- --8208040962 Decision DD-82-7 denying petition for show cause proceeding against util for operation of Unit I Decision re Unit 2 will be made upon completion of evaluation DENTON.H R Office of Nurlear Reactor Regulation, Director 82/07/17 7pp 14221 172 24X Fiche 50-373,82/07/19,8208040886
- --8208040567 Notification of issuance of Director's Decision DD-82-9 denying IL Friends of the Earth petition for show cause re Unit I Supplemental decision will be made pertaining to Unit
- 8208040575 Responds to 820324 show cause petition & 820503 amend on behalf of State of IL Parts of petition & amend pertaining to Unit 1 denied Response deferred for Unit 2 Decision will be issued upon completion of evaluation.

 DENTON, HR Office of Nuclear Reactor Regulation, Director 82/07/19 FAHMER, TC Illinois, State of Rep 14228 199 24% Fiche: 50-373, 82/07/19, 8208040375 241

- 8208250451 Declines to suspend OL or withhold amend for full power operation flatters raised in petition will continue to be reviewed Decision under 10CFR2 206 will be issued following independent review of HVAC sys
 DENTON.H R Office of Nuclear Reactor Regulation, Director 82/08/06 00GCL.E M Citizens Against Nuclear Power 4pp
 [4562 286 24X Fiche 50-373,82/08/06,8208250451 g
- ---8208250454 Notice of Citizens Against Nuclear Power 820728 patition to institute show cause proceeding based on allaged safety issues reconst & GA deficiencies DENTON-H R Office of Nuclear Reactor Regulation, Director 82/08/06 3pp 14562 290 24X Fiche 50-373,82/08/06,8208250451
- 8208260487 Releases, for public inspirecord of Dfc of Inspector & Auditor, interview of T Harpster & portion of General Counsel B20726 memorandum concerning Director's decision on petitions re LaBalle PARRISH,R A Office of the General Counsel B2/08/10 DERNABEI,L General Accounting Office 8pp 14595 001 24X Fiche 50-373, 82/08/10.8208260487
- 8208160040 Order extending until 920820 time for Commission to decide whether to review NRR director partial denial of State of IL & B Rorem 820324 request for action under 10CFR2 206 CHILK,S J Office of the Secretary of the Commission 82/08/13 Cammissioners 1p 14344 336 24X Fiche 50-373,82/08/13,820816040
- 8208250345 Informs that Commission declined to review Director's Decision 824 Time within which Commission may act to review expired Decision became final agency action on 820820 CHILK B J Office of the Secretary of the Commission 82/08/23 FAHNER T C Illinois, State of ROREM, B L Friends of the Earth Ip. 14540 264 24X Fiche 50-373,82/08/23,8208250345
- 8208310245 Comments on NRC decisions to authorize facility to operate above 5% power & up to 50% power & require independent review of HVAC sys Comments will be discussed at 820824 meeting w/Region 3 GCODIE; J 8 Illinois, State of 82/08/24 DENYON, H Office of Nuclear Reactor Regulation, Director opp 14694 302 24X Fiche 50-373, 82/08/24, 8208310245

P Operating license stage documents & correspondence

- 8207200060 Ack receipt of 82042B request to institute show cause proceeding to examine allegations of improper const practices & to halt further fuel loading Immediate suspension of activities not warranted DENTON-H R Office of Nuclear Reactor Regulation, Director 82/05/19 ROREM.B L Friends of the Earth 5pp 14194 094. 24X Fiche 50-373, 82/05/19, 8207200060
- --B20720006i Notice of request for action under 10CFR2 206 to halt further fuel loading DENTOIN HR Diffice of Nuclear Reactor Regulation, Director 82/05/19, 3pp 14194 099 24X Fiche 50~373,82/05/19,8207200060.
- 8207200054 Ack receipt of 820503 amend to request for show cause proceeding to suspend operations based on allegations of reinforcing steel damage in const Buspension of activities not warranted DENTON. HR Office of Nuclear Reactor Regulation. Director 82/04/02 FAHNER, T C Illinois, State of 3pp. 14194 091 24X Fichs 50-373, 82/04/02, 8207200054
- E207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR See list encl
 DIRCKS: W J Office of the Executive Director for Operations
 E2/07/02 Consolidated Edison Co of New York. 93pp 14194 001
 24X Fiche 50-000: 82/07/02, 8207080064
- 8208040341 Forwards INEL draft technical evaluation rept based on util response to 801222 generic ltr, "Control of Heavy Loads" Conference call to resolve open items planned in approx 4 wis 4/o encl SCHMENCER: A Licensing Branch 2 82/07/02 DELGEORGE, L O Commonwealth Edison Co 2pp 14978 002 24X Fiche 50-373,82/07/02,8208040341
- 8208040363 Provides authorization to proceed beyond zero power physics testing at reactor core power levels not in excess of 5% full power Allegations submitted by Atty General of IL & Friends of the Earth resolved satifactorily, DENTON-HR Office of Nuclear Reactor Regulation, Director, 82/07/19 REED, C. Commonwealth Edison Co. 2pp. 14221.362, 24% Fiche 50-373,82/07/19,8208040363

- 8208040557 Notification of 820722 meeting w/util in Bethesda.MD to discuss vacuum breaker design pool swell following postulated LOCA BOURNIA:A Licensing Branch 2 82/07/21 SCHWENCER,A Licensing Branch 2 3pp 14221 202 24X Fiche 50-373,82/07/21,8208040557
- 8208070006 Notification of 820723 meeting w/util at site to discuss vacuum breaker design re pool swell following postulated LOCA BOURNIA.A Licensing Branch 2 82/07/23 SCHMENCER, A Licensing Branch 2 3pp 14283 340 24X Fiche 50-373,82/07/23,8208070006
- 8208030265 Advises that results of nonlinear analysis of whip restraint will be provided by conference call on 820730, as agreed upon at 820723 meeting w/NRC STIEDE.W.L. Commonwealth Edison Co. 82/07/26 SCHWENCER, A Licensing Branch 2 1p 14158 134 24X Fiche 50-373, 82/07/26, 8208030255
- 8208040055 Summarizes status of environ qualification requirements for facility & details corrective actions Proprietary draft Amend 61 to F8AR & Bargent & Lundy "Environ Qualification Rept" encl Encl withhold (ref 10CFR2 790)
 SCHROEDER, C W Commonwealth Edison Co 82/07/28 SCHWENCER, A Licensing Branch 2 9pp 14191 210 24X Fiche 50-373, 82/07/28, 8208040055
- 8208040i19 Forwards info re facility compliance w/NUREG-0737, Item II F 2 re inadequate core cooling.per Condition 2 C (30) (1) of License NPF-f1.No addl instrumentation needed to detect inadequate core cooling SCHROEDER, C W Commonwealth Edison Co 92/07/28 SCHMENCER, A Licensing Branch 2 lipp 14187 140 24% Fiche 50-373, 82/07/28, 8208040119
- 8208060248 Forwards "Reactor Containment Bldg Integrated Leak Rate Test," for 820514-19 & related appendices describing Type A test, per 100FR50 App J requirements HOLYDAK, R H Commonwealth Edison Co 82/07/28 Office of Nuclear Reactor Regulation, Director 1p 14241 099 24X Fiche 80-373, 82/07/28, 8208060248
- 8208060199 Discusses proprietary licensing Topical Rept NEDE-21175-3P re method, model & inputs used to evaluate facility BMR fuel assemblies when subjected to scienic & hydrodynamic loads. Amount of fuel bundle gap opening is very small SCHRDEDER. C W Commonwealth Effson Co 82/07/30 SCHWENCER. A Licensing Branch 2 2pp 14239 006. 24X Fiche 50-373,82/07/30,8208060179
- 820B11018B Forwards revised pages to CE-1-A. "Comm Ed QA Program for Nuclear Generating Stations." Revision 21 Ravised pages correct typographical & other minor errors SHARTZ.E Commonwealth Edison Co 82/08/06 HAASS.W P Quality Assurance Branch 1p 14314 077 24X Fichs 50-000.82/08/06.820B110188
- --8208110204 Revised pages to CE-1-A. Revision 21, "Comm Ed GA Program for Nuclear Generating Stations" # Commonwealth Edison Co 82/06/06 (1pp 14314 080 24X Fithe 50-000.82/08/06.8208110188
- 8208300351 Staff requirements memo re 820805 discussion & possible vote on full power OL for facility
 HOYLE,J C. Office of the Secretary of the Commission 82/08/06
 DIRCKS,W J. Office of the Executive Director for Operations 2pp
 14697 149 24X Fiche 50-373,82/08/06,8208300331
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl EIBENRUT.D G Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332, 24% Fiche, 50-000, 82/08/09, 8208090194
- 8208130304 Forwards info re proposed License Condition 2 C (33) (a), discussed during 820802-04 meeting re resolution of Zack Co HVAC documentation deficiencies SCHROEDER, C W Commonwealth Edison Co 82/08/11 SCHHENCER, A Operating Reactors Branch 2, 3pp 14336,042 24X Fiche, 50-373, 82/08/11, 8208130304
- --8208130307 Forwards response to 820729 request for info re HVAC contractor.Zack Co
 DELOGORE, L O Commonwealth Edison Co 82/08/02. GILINSKY, V
 Commissioners. 49pp 14336 045. 24X Fiche, 50-373, 82/08/11, 8208130304

- --8208130311 Submits corrections to typographical errors identified in 820802 ltr Chronology on resolution of Zack Co documentation deficiencies each DELOEORGE.L O Commonwealth Edison Co 82/08/04 OILINSKY, V Commissioners 120pp 14336 098 24% Fithe 50-373,82/08/11.
- --8208130313 "Technical Review of Safety-Related HVAC Sys Installed by Zack Co at LaGalle County Nuclear Generating Station Commonwealth Edison Co 82/08/12 52pp. 14936-213 24X Fiche 50-373,82/08/11,8208130304
- 8208170183 Application to amend License NPF-11.consisting of Tech Spec Change Request NPF-11/82-11 to revise 18-month Surveillance Requirements 4 7 3 c 2 & Bases 3/4 7.3 to account for flow differences between test flow path & normal flow path TRAMM, T R Commonwealth Edison Co 82/08/11 9CHWENCER, A Licensing Branch 2 1p 14365 173 24X Fiche 50-373,82/08/11,8208170183
- --8208170187 Proposed Tech Spec 4 7 3 c 2 % Bases 3/4 7 3, revising 18-month surveyllance requirements to account for flow differences between test flow path % normal flow path % Commonwealth Edison Co 82/08/11 23pp 14365 174 24X Fiche 50-379,82/08/11.8208170183
- 8208270348 Forwards draft ltr to util documenting comments on HVAC sys independent review scoping ltr.per 820817 discussion. Review comments & concurrence requested SPE8SARD.R L. Division of Froject & Resident Programs 82/08/16 E16ENHUT.B.O Division of Licensing App 14565 106 24X Fiche 50-373,82/08/16.6208270348
- 8208240374 Forwards util 820813 ltr to CF Braun & Co.providing special technical requirements for independent contractor review of safety-related & saismic HVAC sys at facility.as required by Amend 4. Condition 2 C (33) (b) to license 8CHROEDER.C W Commonwealth Edison Co 82/08/18 NOVAK,T H Assistant Director for Licensing 10pp 14524 247 24% Fiche 50-373.82/08/18.8208240374
- 8208240224 Application to amend License NPF-11, changing Tech Specs re reactor pressure interlock for LPCI & LPCS injection valves & reactor vessel matl surveillance program withdrawal schedule 8CHROEDER, C W Commonwealth Edison Co 82/08/19 SCHWENCER, A Licensing Branch 2, 2pp 14519 234 24X Fiche 50-373,82/08/19, 8208240224
- -8208240227 Proposed Tech Spec changes modifying opening LPCI & LPCS injection valves in initiation condition & revising reactor vessel math surveillance removal schedule *Commonwealth Edison Co. 82/09/19 18pp. 14519 236 24X Fiche 50-373,82/08/19,8208240224
- t 208240255 Confirms plans for 820824 meeting at Region 3 to discuss current status of independent HVAC review, per 820818 discussion. KEPPLER.J O. Region 3. Office of Director. 82/08/19 REED. C Commonwealth Edison Co 1p 14519.267 24X Piche 50-373.82/08/19,
 - IB240340 Forwards Tech Spec Change Request NPF-11/82-13 Change evises Table 3 3 7.10-1 to include Unit 2 svc water sys filuent line radiation monitor CHROEDER.C W Commonwealth Edison Co 82/08/19 SCHWENCER.A. Accessing Branch 2 1p 14520 296 24X Fiche.50-373, 82/08/19. 3208240340.
- -0208240345 Tech Spec Change Request NFF-11/82-13 revising Table 3.3 7 10-1 to include Unit 2 svc water sys effluent line radiation monitor * Commonwealth Edison Co 02/08/19 tp 14520 297 24X Fiche: 50-373, 62/08/19, 8208240340
- 8208240352 Proposed Tech Spec Page 3/4 3-82, revising Table 3 3 7, 10-1 to include Unit 2 svc water sys effluent line radiation monitor * Commonwealth Edison Co. 82/08/19 ip 14520, 298 24X Fiche, 50-373, 82/08/19, 8208240340
- 18240441 Forwards licensee 820813 ltr to CF Braun & Cp re ndependent HVAC review.in response to 820812 ltr HVAC eview to be discussed at 820824 meeting in Gien Eliyn.IL AVIB.A B. Region 3. Office of Director 82/08/19 VANVRANHEN.J llinois. State of 12pp. 14527.002. 24X Fiche:50-373.82/08/19, 208240441.
 - 60165 Forwards "Comm Ed LaGalle County Station Independent HVAC Technical Proposal "

 OEDER, C. M. Commonwealth Edison Co 62/08/23 NOVAK, T. M. stant Director for Licensing 1p 14556 278 24X e. 50-373, 82/08/23, 8208260165

- --8208260171 "Comm Ed LaSalle County Station Independent HVAC Review Technical Propusal" + C F Braun & Co 82/08/20 25pp 14556 299 24X Fiche 50-373,82/08/23,8208260165
- 8208300182 Forwards info re method used in selection of CF Braum to review installation of safety-related & seismic HVAC sys for facility, per 820820 request SCHROEDER.C W Commonwealth Edison Co 82/08/24 NOVAK,T M Assistant Director for Licensing 3pp 14678 242 24X Fiche 50-373.82/08/24.8208300182
- 8208310241 Discusses conclusions of 820824 telcon re Startup Test Procedure (STP)-14, reactor core isolation cooling startup test Response to FSAR Question 422 28 not accepted & supersaded by util 170803 add response DELQEORGE, L Q Commonwealth Edison Co 82/08/25 SCHWENCER, A Licensing Branch 2 ip 14674 354 24X Fiche 50-373, 82/08/25, 82083/0241
- 8208310301 Informs of 820909 test of wetwell & drywell vacuum breaker valves in Santa Clara, CA, per Condition 2 C (32) of Amend 4 to License NPF-11 SCHROEDER, C W Commonwealth Edison Co 82/08/26 SCHWENCER, A Licensing Branch 2 Ip 14694 293 24X Fiche 50-373, 82/08/26, 8208310304
- O Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (M91V) Leakage " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Montoring Devices for External Radiation " 5vc list encl JURDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24% Fiche 50-000, 82/07/19, 8204210395
- 8208030173 Forwards IE Insp Rept 50-373/82-36 on 820616 No noncompliance noted LITYLE, W 8 Region 3, Office of Director 82/07/17 REED, C Commonwealth Edison Co 2pp 14160 175 24X Fiche 50-373, 82/07/19, 8208030173
- --8208030176 IE Insp Rept 50-373/82-36 on 820616 No noncompliance noted Major areas inspected selective exam of procedures & representative records observations & interviews w/personnel LANDSMAN, R B. WILLIAMS, C C Region 3, Office of Director 82/07/16 3pp 14160 197 24% Fiche 50-373,82/07/19,8208030173
- 8204210396 IE Info Notice 82-23. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp, 14381 001 24X Fiche 50-000.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBD.L I Division of Fuel Facilities, Naterials & Safeguerds 82707/20 Consolidated Edison Co of New York, 7ipp 14357 276 24X Fiche: 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82~26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50~000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list enc! JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche: 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PMRs " Svc list encl. JCRDAN.E L Division of Engineering & Guality Assurance 82/07/23, Consolidated Edison Co. of New York 127pp 14194-120 24X Ficha 50-000, 82/07/23, 8204210402.
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Flants," Svc list encl JORDANS EL Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp. 14357.013, 24X Fiche 50-000, 82/07/26, 8204210403

- 8208170182 Comments on results of investigation into effect of damage to reinforcing steel. IE Investigation Repts 50-373/82-35 & SO-374/82-06 Results of addl analysis requested Full HVAC investigation should be conducted prior to full operation GODDIE. J S Illinois. State of 82/07/27 DENTON, H R Office of Nuclear Reactor Regulation. Director Spp 14364 324 24X Fiche 30-373, 82/07/27.8208170182
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000.62/07/28,8204210405
- 8208130320 Forwards IE Insp Rept 50-373/82-31 on 820609-18 No noncompliance noted LITTLE.W S Division of Engineering & Technical Programs 82/07/28 REED, C Commonwealth Eduson Co 2pp 14336 338 24X Fiche 50-373,82/07/28,8208130320
- --8208130325 IE Insp Rept 50-373/82-31 on 820609-18 No noncompliance noted Major greas inspected Teledyne Engineering Svcs independent design review of RHR Loop C LPCI per piping stress analysis & design of pipo whip restraints YIN. I T , HILLIAMS.C C , DANIELSON.D H , Region 3, Office of Director 82/07/07 opp 14336-337 24% Fiche 50-373,82/07/28,8208130320
- 8208100240 Forwards IG Insp Rept 50-373/62-32 on 820603-0702 No noncompliance noted LITTLE.W S Division of Engineering & Technical Programs 82/07/29 REED,C Commonwealth Edison Co 2pp 14294 302 24X Fiche 50-373,82/07/29,8208100240
- --8208100244 IE Insp Rept 50-373/82-32 on 820403-0702 No noncompliance noted Major areas inspected startup test procedures & results, preoperational test results & previously opened items HAURA,F , LANKSBURY,R , ROBINSON,D Region 3, Office of Director 82/07/14 7pp 14294 304 24X Fiche 50-373,82/07/29,8208100240
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000,82/08/05,8204210407
- 8208160138 Ack receipt of 820728 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/82-25 LITTLE.W 6 Division of Engineering & Technical Programs 82/08/10 REED, C Commonwealth Edison Co 1p 14344 167 24X Fiche 80-373,82/08/10,8208160138
- --8208160140 Responds to NRC 820707 ltr reviolations noted in IE Insp Rept 50-373/82-25 Corrective actions control switch for drywell sump discharge isolation valve IRE 025 placed in auto/close position preventing sump valves from actuating. SCHROEDER.C W Commonwealth Edison Co 82/07/28 KEPPLER.J 0 Region 3. Office of Director 4pp 14344-168 24X Fiche 50-373,82/08/10.8208160138
- E20B170223 Forwards inservice insp rept on 820701-07, describing structural bolt tightness for containment valves Insp program for valves outside containment being devaloped SCHROEDER, C W Commonwealth Edison Co 82/08/10 KEPPLER, J O Region 3, Office of Director 2pp 14361 323 24X Fiche 50-373,82/08/10,8208170223
- --BROB170226 Inservice insp rept on 820701-07, describing structural bolt tightness insp results for containment valves FALB:E E , BHAMBLIN.D L Commonwealth Edison Co 82/08/10 4ipp 14361 325 24X Fithe 50-373,82/08/10,8208170223
- 8208270357 Ack receipt of 820809 ltr informing NRC of steps taken to correct violations nated in IE Insp Rept 50-373/82-28. SPESSARD, R L Division of Project & Resident Programs 82/08/20 REED.C. Commonwealth Edison Co ip 14544 019. 24% Fiche 50-373,82/08/20,8208270359
- --B208270368 Forwards response to NRC B20701 ltr re violations notes in IE Insp Rept 50-373/82-28 Corrective actions, paint cans, rags, cigarette butts & taps removed on 820511 & contractors informed of housekeeping rules.

 DELGEORGE, LO Commonwealth Edison Co. 82/08/09 KEPPLER, J Q. Region 3, Office of Director 4pp 14566 020 24X Fiche 50-373, 82/08/20, 8208270359
- 6208310074 Forwards IE Safeguards Insp Rept 50-373/82-30 on 820614-17 & notice of violation Notice withheld (ref 10CFR2 790)
 MILLER, J R Division of Engineering & Technical Programs 82/08/24,
 REED, C Commonwealth Edison Co 2pp 14687-270 24X
 Fichs 50-373,82/08/24,8208310054

- --8209310060 IE Bafeguards Insp Rept 50-373/82-30 on 820414-17 Noncompliance noted failure to search hand carried item & failure to pat search visitors Details withheld (ref 10CFR2 770) BELANGER, J. L., STAPLETON, B. W., CREED, J. R. Region 3, Office of Director 82/08/17 2pp 14689 292 24X Fiche 50-373, 82/08/24, 8208310054
- R Periodic operating reports & related correspondence
- 8208120288 Forwards monthly operating rept for June 1982 HDLYOAK.R H Commonwealth Edison Co 82/07/08 Office of Resource Management, Director \$1p 14924 314 24X Fiche 50-373, 82/07/08, 8208120288
- --8208120294 Monthly operating rept for June 1982 MANNINO, P F Commonwealth Edison Co 82/07/07 13pp ±4324 315 24X Fiche 50-373.82/07/08.8208120288
- B208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J M Division of Rules and Records 92/07/13 UDELL.R A Critical Mass Energy Project Spp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270359 Forwards "Recorded Annual Whole Body External Exposure for CYB1," per 10CFR20 407(b) W/o Quad Cities, Zion, LaSalle, Byron & Braidwood repts RAUSCH, T. J. Commonwealth Edison Co. 82/03/31 Office of Management and Program Analysis 1p 14680 075 24% Fiche 30-000, 82/07/13, 8208270010
- B Reportable occurrences, LERs & related correspondence
- 8208020117 Forwards NPDES noncompliance rept for facility HOLYOAK.R H Commonwealth Edison Co 82/07/14 KEPPLER.J 9 Region 3. Office of Director 2pp 14141 063 24X Fiche 50-373, 82/07/14, 8208020117
- --B208020179 NPDES noncompliance notification on B20706, line breek from fuel oil storage tank to dissel fire pumps allowed 300 gallons to spill onto Lake Storem House floor Broken line under repair Station personnel notified to cleanup oil # Commonwealth Edison Co B2/07/06 ip 14141.065 24X Fiche 50-373.82/07/14.8208020117
- 8208020176 Forwards NPDES noncompliance rept HOLYOAK,R H Commonwealth Edison Co 82/07/14 KEPPLER,J 9 Region 3, Defice of Director 2pp 14141 041 24X Fiche 30-373, 82/07/14,8298020176
- --8208020178 NPDES noncompliance rept on 820629, excessive amounts of soluble from collected on makeup demineralizers Caused by loss of hydrogen peroxide injection from temporary sys Permanent hydrogen peroxide injection sys will be installed a Commonwealth Edison Co. 82/07/14 ip 14141 043 24X Fiche 50-073,82/07/14-8208020176
- 8208020332 Forwards NPDES noncompliance notification HOLYDAK,R H Commanwealth Edison Co 82/07/14 KEPPLER,J. O Region 3, Office of Director ip 14147 092 24X Fiche 50-373, 82/07/14.8208020332
- --B208020346 NPDES noncompliance notification on B20612.15 t 29.total from from discharges exceeded permitted limits Caused by temporary hydrogen peroxide injection sys becoming airbound Permanent injection sys completion expected by B30101. HDLYOAK,R H Commonwealth Edison Co. B2/07/14 2pp. 14147 093 24X Fiche, 50-373, 82/07/14,8208020332
- 8208020351 Forwards NPDEB Concemptiance notification for Permit IL004B151, per License NPF-11, App B, Section 3 2 HOLYOAK, R H Commonwealth Edison Co. 82/07/14 KEPPLER, J O Region G, Office of Director 2pp 14150 GB2 24X Fiche 30-373, 82/07/14,8248020351
- --8208020357 NPDES noncompliance notification on 820712,18 mg per liter oil & grease released from wastewater treatment facility
 Error in sampling suspected Dil-soak boom placed in outlet chamber to prevent discharge
 # Commonwealth Edison Co 82/07/12 ip 14150 084. 24X
 Fiche 50-373,82/07/14,8208020351
- 8208030437 Forwards NPDES noncompliance rept HOLYOAK,R.H Commonwealth Edison Co 82/07/20 KEPPLER,J 0 Region 3, Office of Director 2pp 14195 345 24X Fiche 50-373, 82/07/20, 8208030437

- --820Bi303ii Submits corrections to typographical errors identified in 820802 ltr Chronology on resolution of Zack Co documentation deficiencies entl DELGEOROE. L O Communication Co 82/08/04 OILINSKY, V Commissioners 120pp 14336 078 24X Fichs 50-373, 82/08/11, 8208130304
- --9208130313 "Technical Review of Bafety-Related HVAC Bys Installed by Zack Co at LaBalle County Nuclear Generating Station • Commonwealth Edison Co 82/08/12 52pp 14336 213 24X Fiche 50-373,82/08/11/8208130304
- 8208170183 Application to smend License NPF~11.consisting of Tech Spec Change Request NPF-11/82-11 to revise 10-month Surveillance Requirements 4 7 3 c 2 & Bases 3/4 7 3 to account for flow differences between test flow path & normal flow path TRAMM, T R Commonwealth Edison Co 82/08/11 SCHWENCER, A Licensing Branch 2 10 14365 173 24X Fiche 50-373,82/08/11,8208170183
- ~~8208170187 Proposed Tech Spec 4 7 3 c 2 & Bases 3/4 7.3, revising 18-month surveillance requirements to account for flow differences between test flow path & normal flow path + Commonwealth Edison Co 82/08/11 23pp 14365 174 24X Fiche 50-373,82/08/11 8208170183
- 8208270348 Forwards draft 1tr to util documenting comments on HVAC sys independent review scaping Itr.per 820817 discussion. Review comments & concurrence requested SPEBSARD, R.L. Division of Project & Resident Programs 82/08/16 EISENHUT, D.O. Division of Licensing App 14565 106 24X Fiche 30-373,82/08/16,8208270348
- 8208240394 Forwards util 820813 ltr to CF Braun & Co, providing special technical requirements for independent contractor review of safety-related & saismic HVAC sys at facility, as required by Amend 4, Condition 2 C (33) (b) to license SCHROEDER, C W Commonwealth Edison Co 82/08/18 NGVAK, T M Assistant Director for Licensing 10pp 14524 247 24X Fichs 50-373, 82/08/18, 8208240394
- 8208240224 Application to amend License NPF-11, changing Tech Spacs re reactor pressure interlock for LPGI & LPGE injection valves & reactor vessel matl surveillance program withdrawal schedule SCHROEDER, C W Commonwealth Edison Co 82/08/19 SCHWENCER, A Licensing Branch 2 2pp 14519, 234 24X Ficha 50-373, 82/08/19, 8208240224
- --8208240227 Proposed Tech Spec changes modifying opening LPCI & LPCS injection valves in initiation condition & revising reactor valvel meti surveillance removal schedule # Commonwealth Edison Co 82/08/19 18pp 14519 236 24X Fiche 50-373,82/08/19.5208240224
- 1208240255 Confirms plans for 820824 meeting at Region 3 to discuss current status of independent HVAC review, per 820818 discussion
 KEPPLER.J. 9 Region 3. Office of Director 82/08/19 REED. C
 Commonwealth Edison Co 1p 14519 267 24X Fiche 50-373.82/08/19, 8208240255
- DS240340 Forwards Tech Spec Change Request NPF-11/82-13, Change revises Table 3 3 7. 10-1 to include Unit 2 syc water sys affluent line radiation monitor SCHROEDER, C W Commonwealth Edison Co B2/08/19 SCHWENCER, A Licensing Branch 2, 1p 14520:292 24X Fiche 50-373, 82/08/19, 8208240340.
- -8208240345 Tech Spec Change Request NPF-11/82-13 revising
 Table 3 3 7 10-1 to include Unit 2 svc water sys effluent
 ine radiation monitor
 * Commonwealth Edison Co 82/08/19 ip 14520 297 24X
 Fiche 50-373.82/08/19,8208240340
- 8208240352 Proposed Tech Spec Page 3/4 3-82 revising Table 3 3 7 10-1 to include Unit 2 svc water sys effluent line radiation monitor
- Commonwealth Edison Co 82/08/19. 1p 14520,298 24X Fiche 30-373,82/08/19,8208240340
- 08240441 Forwards licensee 820813 ltr to CF Braun & Co re independent HVAC review in response to 820812 ltr HVAC review to be discussed at 820824 meeting in Glen Ellyn, IL JAVIS.A B. Region 3. Office of Director 82/08/19 VANVRANHEN, J Illinois, State of. 12pp 14527:002 24X Fiche: 50-373, 82/08/19, 1208240441
 - 1ty Station Independent HVAC
 82/08/23. NOVAK, T M. 14556.298. 24X

- --8208260171 "Comm Ed LaSalle County Station Independent HVAC Review Technical Proposal"

 # C F Braun & Co 82/08/20 25pp 14556 299 24x
 Fiche 50-373,82/08/23,8208260165
- 8208300182 Forwards info re method used in selection of CF Braum to review installation of safety-related & seismic HVAC sys for facility, per 820820 request ECHROEDER, C H Commonwealth Edison Co 82/08/24 NOVAK, T M Assistant Director for Licensing 3pp 14678 242 24X Fiche 50-373, 82/08/24, 8208300182
- 8208310241 Discusses conclusions of 820824 telcon re Startup Test Procedure (STP)-14, reactor core isolation cooling startup test Response to FSAR Question 423 28 not accepted & superseded by util 770803 addi response DELOEDROE, L D Commonwealth Edison Co 82/08/25 SCHWENCER, A Licensing Branch 2. Ip 14694:354 24X Fiche 50-373,82/08/25,8208310241
- 8208310301 Informs of 820707 test of wetwell & drywell vacuum breaker valves in Santa Clara, CA, per Condition 2 C (32) of Amend 4 to License NPF-11 SCHROEDER, C W Commonwealth Edison Co 82/08/26 SCHWENCER, A Licensing Branch 2 ip 14674 273 24X Fiche 50-373, 82/08/26, 8208310301
- Q Inspection reports, IE Bullatins & correspondence
- 8204210393 IE Info Notice 82~23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 62/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000.82/07/16.8204210393
- 8204210395 IE Info Notice 81-26, Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl JORDAN.E L. Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210395
- 8208030173 Forwards IE Insp Rept 50~373/82-36 on 820616 No noncompliance noted LITTLE: WS Region 3, Office of Director 82/07/19 REED, C Commonwealth Edison Co 2pp 14160 195 24X Fiche 50-373,82/07/19, 8208030173
- --8208030176 IE Insp Rept 50-373/82-36 on 820616 No noncompliance noted Major areas inspected selective exam of procedures & representative records observations & interviews w/personnel LANDSMAN, R B , WILLIAMS, C C Region 3, Office of Director 82/07/16 3pp 14160 197 24X Fiche 50-373, 82/07/19,8208030173
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure," Svc list encl
 JORDAN: E L Division of Engineering & Quality Assurance 82/07/20
 Consolidated Edison Co of New York 112pp 14381 001 24X
 Fiche: 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list enc! COBB.L I Division of Fue! Facilities, Materials & Bafeguarda 82/07/20 Consolidated Edison Co of New York 71pp 14357.276 24X Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Byc list enc! JORDANIE L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche: 50-000. 82/07/22,8204210378
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc 11st encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380 115, 24X Fiche 50-000.62/07/23.6204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN.E. L Division of Engineering & Quelity Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 92/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list enc! JORDAN.E L. Division of Engineering & Quality Assurance. 82/07/26 Consolidated Edison Co. of New York 12ipp. 14357 013 24X Fiche. 50-000. 82/07/26. 8204210403

- 8208170182 Comments on results of investigation into effect of damage to reinforcing steel. IE Investigation Repts 80-373/82-35 & 30-374/82-06 Results of addl analysis requested Full HVAC investigation should be conducted prior to full operation GOODIE. J S Illinois. State of 82/07/27 DENTON. H R Office of Nuclear Reactor Regulation. Director 5pp 14364 324 24% Ficha 50-373, 82/07/27.8208170182
- 8204210405 IE Info Notice 82-31, "Overexpasurs of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210409
- 820B130320 Forwards IE Insp Rept 50-373/B2-31 on 820609-19 No noncompliance noted LITTLE, W B Division of Engineering & Technical Programs 82/07/28 REED, C Commonwealth Edison Co 2pp 14334 335 24X Fiche 50-373, 82/07/28, 8208130320
- --8208130325 IE Insp Rept 50-373/82-31 on 820609-18 No noncompliance noted Major areas inspected Teledyne Engineering Sycs independent design review of RHR Loop C LPCI per piping stress analysis & design of pipe whip restraints YIN.IT. WILLIAMS.C C. DANIELSON.D H. Region 3. Office of Director 62/07/07 App 14336 337 24X Fiche 50-373,82/07/28,8208130320
- 8208100240 Forwards IE Insp Rept 50-373/82-32 on 820603-0702 No noncompliance noted LITTLE,W S Division of Engineering & Technical Programs 82/07/29 REED.C Commonwealth Edison Co 2pp 14294 302 24X Fiche 50-373,82/07/29,8208100240
- --8208100244 IE Insp Rept 50-373/82-32 on 820603-0702 No noncompliance noted Major areas inspected startup test procedures & results, preoperational test results & previously opened items MAURALF., LANKSBURY, R. ROBINSBUN, D. Region 3, Office of Director. 82/07/16 7pp 14294 304 24% Fiche 50-373.82/07/27,8208100240
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Hater-Jet Empingement" Svc list and I JORDAN,E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201, 24X Fiche. 50-000, 82/08/05, 8204210407
- 8208160138 Ack receipt of 820728 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-373/82-25 LITTLE:W 5 Division of Engineering & Technical Programs 82/08/10 REED.C Commonwealth Edison Co ip 14344 167 24X Fiche: 30-373, 82/08/10, 8208160138
- --E208160140 Responds to NRC 820707 ltr re violations noted in IE Insp Rept 50-373/82-25 Corrective actions control switch for drywell sump discharge isolation valve IRE 025 placed in auto/close position preventing sump valves from actuating SCHROEDER, C W Commonwealth Edison Co 82/07/28 KEPPLER, J Q Region 3, Office of Director 4pp 14344 168 24X Fiche 50-373,82/08/10,8208160138
- 8208170223 Forwards inservice insp rept on 820701-07, describing structural bolt tightness for containment valves Insp program for valves outside containment being developed SCHROEDER, C W Commonwealth Edison Co 82/08/10 KEPPLER, J. O Region 3, Office of Director. 2pp. 14361 323 24X Fiche 30-373, 82/08/10, 8208170223.
- --BR08170226 Inservice insp rept on 820701-07, describing structural bolt tightness insp results for containment valves. FALB:E E , 8HAMBLIN.D L. Commonwealth Edison Co 82/08/10. Aipp. 14361 328 24X Fiche 50-373.82/08/10,8208170223
- 8208270339 Ack receipt of 820809 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/82-28 SPESSARD.R L. Division of Project & Resident Programs, 82/08/20 REED.C Commonwealth Edison Co. ip 14564 019, 24% Fiche, 50-373, 82/08/20, 8208270359
- --8208270368 Forwards response to NRC 820701 ltr re violations noted in IE Insp Rept 50-373/82-28 Corrective actions.paint cans, rags, cigarette butts & tape removed on 820511 & contractors informed of housekeeping rules.

 DELOCOROE, L. D. Commonwealth Edison Co. 82/09/09 KEPPLER, J. O. Region 3, Office of Director 4pp 14566 020 24X
 Fiche 50-373,82/08/20,8208270359
- 8208310054 Forwards IE Safeguards Insp Rept 50-973/82-30 on 920614-17 & notice of violation Notice withheld (ref 10CFR2 770).

 MILLER, JR Division of Engineering & Technical Programs. 82/08/24
 REED, C Commonwealth Edison Co 2pp 14687:270 24X
 Fiche, 30-373, 82/08/24, 8208310054.

- --8208310060 IE Safeguards Insp Rept 50-373/82-30 on 820614-17 Noncompliance noted failure to search hand carried item & failure to pet search visitors Details withheld (ref 10CFR2 770) BELANGER, J L , STAPLETON, B W , CREED, J R Region 3, Office of Director 82/08/17 2pp 14687 292 24X Fiche 50-373,82/08/24, 8208310034
- R. Periodic operating reports & related correspondence
- 8208120288 Forwards monthly operating rept for June 1982 HOLYDAK,R H. Commonwealth Edison Co. 82/07/08 Office of Resource Management, Director \$1p. 14324-314 24X Fiche 50-373, 82/07/08, 82/8120288
- --8208120294 Monthly operating rept for June 1982 MANNING.P F Commonwealth Edison Co 82/07/07 13pp 14324 315 24X Fiche 50-373,82/07/08,8208120288
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/13 UDELL,R A Critical Mass Energy Project Bpp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- --B208270559 Forwards "Recorded Annual Whole Body External Exposure for CVBI." per 100FR20 407(b) W/o Quad Cities, Zion. LaSalle, Byron & Braidwood repts RAUSCH. T J Commonwealth Edison Co 82/03/31 Office of Hanagement and Program Analysis ip 14680 075 24X Fiche 50-000, 82/07/13, 8208270010
- 8 Reportable occurrences, LERs & related correspondence
- 8208020117 Forwards NPDES noncompliance rept for facility HOLYOAK,R,H Commonwealth Edison Co 82/07/14 REPPLER,J 0 Region 3. Office of Director 2pp 14141 063 24X Fiche: 50-373, 82/07/14, 8208020117
- --8208020179 NPDES noncompliance notification on 820706.line break from fuel oil storage tank to diesel fire pumps allowed 300 gatlons to spill onto Lake Screen House floor Broken line under repair Station personnel notified to cleanup dil * Commonwealth Edison Co 82/07/06 ip 14141.065 24X fiche 30-373.82/07/14,8208020117.
- 8208020176 Forwards NPDES noncompliance rept HOLYDAK,R H Commonwealth Edison Co 82/07/14 KEPPLER,J G Region 3, Office of Director 2pp. 14141 041 24X Fiche 50-373, 82/07/14,8208020176
- --8208020178 NPDEB noncompliance rept on 820629 excessive amounts of soluble iron collected on makeup demineralizers Caused by loss of hydrogen peroxide injection from temporary sys. Permanent hydrogen peroxide injection sys will be installed * Commonwealth Edison Co 82/07/14. Ip 14141 043, 24X Fiche 50-373,82/07/14.8208020176
- 8208020332 Forwards NPBES noncompliance notification HOLYDAX.R H Commonwealth Edison Co 62/07/14 KEPPLER.J C Region 3. Office of Director in 14147.092 24X Fiche.50-373, 82/07/14,8208020332
- ---9208020346 NPDES noncompliance notification on BR0612,15 & 29, total from from discharges exceeded permitted limits Caused by temporary hydrogen peroxide injection sys becoming airbound Permanent injection sys completion expected by B30101. HDLYOAK,R H Commonwealth Edison Co 82/07/14 2pp. 14147 093 24% Fiche.50-373,82/07/14.8208020332
- 8208020351 Forwards NPDEB noncompliance notification for Permit IL0048151, per License NPF-11, App B, Section 3 2, HOLYOAK, R H Commonwealth Edison Co 82/07/14, KEPPLER, J Q Region 3, Office of Director 2pp. 14150 082 24X Fiche 50-373, 82/07/14, 8208020351
- --8208020357 NPDE6 noncompliance notification on 820712.18 mg per liter oil & grease released from wastewater treatment facility Error in sampling suspected Dil-soak boom placed in outlet chamber to prevent discharge.

 **Commonwealth Edison Co 82/07/12 Ip 14150 084 24X Fiche:80-373,82/07/14,8208020351
- 8208030437 Forwards NPDES noncompliance rept HOLYDAK,R.H. Commanwealth Edison Co 82/07/20 KEPPLER,J 9 Region 3, Office of Director 2pp (4155-345 24X Fiche 50-373, 82/07/20.8208030437

- --8208030441 NPDES noncompliance notification on 820703.composite sample initiated on batch discharge 001-82.batch discharge 002-82 commenced w/o stopping composite sample between batches Composite sampler cannot operate automatically ** Commonwealth Edison Co 82/07/06 ip 14159 347 24X Fiche 50-373.82/07/20.8208030437
- 8208100126 PNO-III-82-068 on 820503, allegations from former employee of HVAC contractor received re false or incomplete QA documentation for HVAC work at sites Special insp of Zack Co & facilities initiated MALKER.R D Region 3. Office of Director 82/07/22 ip 14298 183 24X Fiche 50-000,82/07/22,8208100126
- 820B100211 PND-III-82-070 on B20728, Region 3 received copy of 2 206 petition to revoke OL:containing info from affidavits by IL Atty General. Govt Accountability Project & Zack Co re GA problems News media interest expected MALKER.R. KNOP.R. SPESSARD.R. Region 3. Office of Director 82/07/29 1p 14294 246 24X Fiche 50-373,82/07/29,82081002J1
- 8208100280 PNO-III-82-071 on 820729, received Part 21 rept via telcon w/Zack Co re documentation discrepancies for welds made to HVAC components at La Saile & possibily at Clinton & Midland Welder of record may not be actual welder . WALKER:R D Region 3. Office of Director 82/07/30 ip 14294-352 24X Fiche 50-000, 82/07/30, 8208100280
- 820816024B Potential Part 21 rept re weld records Initially reported on 820727 Review of documents indicates possible discrepancy between welder of record & welder completing welds Investigation continuing DE ZUTEL, C Z. Zack Co 82/08/02 KEPPLER, J G. Region 3, Office of Director 10pp 14346 351 24X Fiche 50-000,82/08/02,8208160248
- 8208130030 Advises of steps taken to resolve QA documentation deficiencies of HVAC sys installed by Zack Co Sys can perform designed safety function Rept of independent review will be submitted by 820915
 REED, C Commonwealth Edison Co 82/09/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14335 095 24X
 Fichs 50-373,82/08/04/8208130030
- 8208100233 Forwards LER 82-072/03L-0 HOLYOAK,R H Commonwealth Edison Co 82/08/05 KEPPLER,J 0 Region 3, Office of Director. Ip 14294 331 24X Fiche: 80-373, 82/08/03, 8208100233
- --B208100237 LER 82-072/03L-O on 820724, A & B high steam line tunnel delte T tripped, causing Group I isolation & high pressure reactor scram Caused by double black drain valves left open after MSIV wetting procedure performed Rept reviewed.

 LOCKHOOD. J Commonwealth Edison Co 82/08/02 Region 3, Office of Director 2pp 14294 332 24X Fiche 50-373,82/08/05,8208100233
- 8208100330 Forwards LER 62-057/03L-0 Datailed event analysis entl, MOLYOAK:R H Commonwealth Edison Co 62/08/05 KEPPLER, J O Region 3, Office of Director 2pp 14297; 178 24X Fiche 50-073, 62/08/05, 8208100330
- --8208100336 LER 82-057/03L-0 on 820708, while in Mode 4 cold shutdown. RHR svc water pump found cycling on & off Caused by thermal overload due to motor being rewired at 230-volt configuration instead of 110-volt. Motor rewired CONARD. U. Commonwealth Edison Co. 82/08/05 Region 3. Office of Director ip 14297 200 24% Fiche 50-373,82/08/05,8208100330
- 8209300189 Bubmits NPDES noncompliances, H/Q encl HOLYOAK,R H Commonwealth Edison Co 82/08/05 KEPPLER, J G Region 3, Office of Director ip 14595,358 24X Fiche 50-373,82708/05,8208300189
- 8208200287 RO on B2070? into revealed fire door below 3-h fire rating Hourly fire watch patrol established until door installed w/both 3-h fire rating & bulletproofing HGLYOAK, R H Commonwealth Edison Co B2/08/06. KEPPLER, J G. Region 3. Office of Director 2pp. 14398 351 24X Fiche 50-373, 82/08/06.8208200287
- 8208300061 Forwards LER 82-068/03L-0 HOLYOAK,R.H Commonwealth Edison Co. E2/08/06 KEPPLER,J.O. Region 3. Dffice of Director ip 14598 338 24X Fiche 50-373,82/08/06.8208300061
- -8208300063 LER 82-069/03L-0 on 82072R, position indication lights for BRV-1821-F013H failed, indicating valve did not open on demand. Caused by improper interaction between magnets & lired set of read suitches. Indication repaired LLRICH.J. Commonwealth Edison Co. 82/08/06 Region 3, Office of Director. 2pp. 14598.339. 24X Fichs-50-373.82/08/06, 208300061

- 8208300101 Forwards LER 82-064/03L-0 Detailed event analysis encl HDLYDAK,R H Commonwealth Edison Co 82/08/06 KEPPLER,J 6 Region 3, Dffice of Director 2pp 14596 110 24X Fiche 30-373, 82/08/06,8208300101
- --8208300103 LER 82-064/03L-0 on 820721, position indication lights for automatic depressurization sys valve 1821-F0134 Pailed to operate indicating valve open when observed closed Caused by improper interaction between magnets is reed switches # Commonwealth Edison Co 82/08/06 Region 3, Office of Director 1p 14396 112 24X Fiche 50-373,82/08/06,8208300[0]
- 8208200233 Ferwards LER 82-075/03L-0 HOLYOAK,R H Commonwealth Edison Co 82/08/09 KEPPLER,J O Region 3, Office of Director ip 14399 348 24X Fiche 30-373,82/08/07,8208200235
- --e208200244 LER 82-075/03L-0 on 820726 air hose to automatic dispatch sys valve 1821-F013V ruptured so that IN compressors could not maintain sys pressure Probably caused by hose age, exceeding min bend radius & exposure to high temp VLLRICH-J Commonwealth Eduson Co 62/08/09 Region 3, Office of Director 2pp 14399 349 24X Fiche 50-373,82/08/07.
- 8208230060 Forwards LER 82-060/03L-0 HOLYOAK,R H Commonwealth Edison Co 82/08/10 KEPPLER, J G Region 3, Office of Director ip 14513 359 24X Fiche 50-373, 82/08/10, 8208230060
- --8208230065 LER 82-060/03L-0 on 820717 during operation of B control HVAC train, high ammonia level alarm went off inadvertently Caused by broken tape in detector Tape replaced KLIKA M Commonwealth Edison Co 82/08/06 Region 3, Office of Director 2pp 14513 360 24X Fiche 90-373,82/08/10,8208230060
- B20B240184 Forwards LER B2-074/03L-0 HOLYDAK,R H Commonwealth Edison Co 82/08/10 KEPPLER, J Q Region 5. Office of Director 1p 14519 157 24X Fiche 50-373, 82/08/10, 8208240186
- --8208240189 LER 82-074/03L-0 on 820719, hydregen & oxygen calibr gat instrumentation for post-accident containment monitoring sys did not meet calibr requirements Caused by instrument drift aggravated by foreign particulate matter in lines. GRAY.M. Commonwealth Edison Co. 82/08/10 Region 5, Office of Director 2pp 14519 158 24X Fichs 50-373,82/08/10,8208240[86]
- 0208310289 Forwards LER 82-078/03L-0 HOLYOAK,R H Commonwealth Edison Co 82/08/10 KEPPLER,J 0 Region 3. Office of Director 1p 14688 263 24X Fiche 50-373.02/08/10/8208310289
- --8208310290 LER 82-078/03L-0 on 820726, mgt informed that 820721 analysis revealed snubber RHO4-15208 installed improperly Caused by fillst weld overtooked by production & GC Missing weld discovered by design engineer & repaired within 3D days SPENCER, D A Commonwealth Edison Co 92/08/10 Region 3, Office of Director 2pp 14688 264 24% Fiche 50-373,82/08/10,8208310289
- 8208240200 Forwards LER 02-083/01T-0 HOLVOAK,R H Communusalth Edison Co 82/08/17 KEPPLER, J O, Region 3, Office of Director ip 14544 123 24X Fiche: 50-373, 82/08/17, 8208240200
- --B208240206 LER 82-083/017-0 on B20804.three sections of duct work found having visually unacceptable wolds rendering sys inoperable Caused by porosity & weld profile Welds repaired on 820806 & sys doclared operable on 820807 CQNARD. J Commonwealth Edison Co 82/08/17 Region 3. Office of Director. 2pp 14544 124 24X Fiche 50-373.82/08/17, 8208240200
- 8208300059 Forwards LER 82-063/03L-0 HOLYDAK,R H Commonwealth Eddson Co 82/08/18 KEPPLER,J Q Region 3, Office of Director ip 14598 335 24X Fiche,50-373,82/08/18,8208300059
- --B208300060 LER 82-063/03L-0 on 820720; neutron flux high setdown limit for average power range monitor D found calify to value of 25% rated thermal power Caused by instrument drift All six channels recalify HINTERHOFF, D Commonwealth Edison Cp 82/08/17 Region 3, Office of Director 2pp 14578-336 24% Fiche: 50-373, 82/08/18; 8208300059
- 8208300138 Forwards LER 82-061/03L-0. HDLYDAK,R H Commonweelth Edison Co 82/08/18 KEPPLER, J G. Region 3. Office of Director. ip 14599-182 24X Fichs: 50-373, 82/08/18, 8208300138

- 9209310210 Forwards LER 92-076/03L-0 HOLYDAK,R H Commonwealth Edison Co 92/09/18 KEPPLER,J 0 Region 3. Office of Director ip 14693 127 24X Fiche 50-373,82/08/18,8208310210
- --8208310215 LER 82-076/03L-0 on 820727, during reactor core isolation coaling callbr & functional test for pressure switches IE31-N022 A.B & C. trip setpoints found below Tech Spec limit Caused by setpoint drift Switches will be monitored HOUSTON, R W Commonwealth Edison Co 82/08/18 Region 3, Office of Director 2pp 14693 128 24x Fiche 50-373,82/08/18,8208310210
- 8209310219 Forwards LER 82-066/03L-0 HOLYOAK.R H Commonwealth Edison Co 82/08/18 KEPPLER, J 0 Region 3, Office of Director 1p 14688 356 24X Fiche 50-373,82/08/18.8208310219
- --9208310225 LER 82-066/03L-0 on 820722, reactor core cooling sys declared inoperable due to leaks in reactor core isolation cooling turbine sys & suspected failure of turbine governor Caused by sys being inoperative for 2 yrs Oil leak repaired HCUSTON. R Commonwealth Edison Co 82/08/18 Region 3, Office of Director 2pp 14688 357 24% Fiche 50-373,82/08/18,8208310219
- 8208310243 Forwards LER 82-067/03L-0 HOLYOAK,R H Commonwealth Edison Co 82/08/18 KEPPLER,J Q Region 3, Office of Director 1p 14687 312 24X Fichs 50-373,82/08/18,8208310243
- --8208310250 LER 82-067/03L-0 on 820722 dampers GVE07YA & GVE07YA would not operate manually insp revealed GVE09YA to have blown oil seal Cause not stated Damper activator repaired # Commonwealth Edison Co B2/08/18 Region 3. Office of Director 2pp 14687 313 24X Fiche 50-373,82/08/18,8208310243
- 9208300310 Forwards LER 82-062/03L-0 HOLYDAK,R H Commonwealth Edison Co 82/08/19 KEPPLER,J P Region 3. Office of Director 1p 14599.333 24X Fiche 50-373.62/08/19.8208300310
- --8208300315 LER 82-062/03L-0 on B20720, drywell particulate & gaseous containment atmosphere montoring gave false high reading Caused by sensitivity of sys to electric noise Work request issued to repair sys

 LUETT, W R Commonwealth Edison Co 82/08/19 Region 3, Office of Director 2pp 14599 334 24X Fiche 50-373,82/08/19,8208300310
- 8208310040 Final Deficiency Rept 82-05 re predicted valve stress on drugell/webwell vacuum breaker valves not meeting ASRE code allowable stress initially reported on 820723 Confirmatory test to be canducted by 821101

 8CHROEDER.C W Commanuealth Edison Co 62/08/19 KCPPLER, J G Region 3. Office of Director 2pp 14674 358, 24X

 Fiche 50-373,82/08/19,8208310040
- 8208310234 Forwards LER 82-069/03L-0 HOLYOAK, R H Commonwealth Edison Co 82/08/20 KEPPLER, J Q Region 3. Office of Director Ip 14695 109 24X Fiche 80-373, 82/08/20, 8208310234
- 8208310249 Forwards LER 82-073/03L-0 HOLYOAK, R H Commonwealth Edison Co 82/08/20 KEPPLER, J O Region 3. Office of Director ip 14688 182 24X Fiche 50-373,82/08/20,8208310249
- --B208310263 LER 82-073/03L-O on 820725, during heatup for startup testing, heatup max rate of 100 F/h exceeded Causad by overdependence on CRT ramp rate display Operating personnel reminded to use multiple indications.

 WINTERHOFF, D.R. Commonwealth Edison Co. 82/08/20 Region 3, Office of Director Spp. 14688.183 24X Fiche 50-373,82/08/20,8208310249

- 8208310185 Forwards LER 82-077/03L-0 HOLYOAK,R H Commonwoalth Edison Co 82/08/24 KEPPLER,J 0 Region 3, Office of Director 19 14694 294 24X Fiche 90-373, 62/08/24, 8208310185
- --8208310195 LER 82-077/03L-0 on 820726, reactor core isolation cooling turbine inadvertently rolled Caused by unvented steam in isolated section of steam piping due to closed check valve Limit switches of testable check valves adjusted HOUSTON,R W Commonwealth Edison Co 82/03/24 Region 3, Office of Director 2pp 14694 275 24X Fiche 30-373,82/08/24, B208310195
- T Hearing transcripts on non-antitrust matters
- 8208250404 Transcript of 820805 public meeting re discussion & possible vote on full power OL for LeSalie i in Washington, OC Pp 1-51 Supporting documentation encl * Commissioners 82/08/05 119pp 14562 295. 24X Fiche 50-373, 82/08/05,8208250404.
- DUCKET 50-374 LABALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8207200040 Ack receipt of 820428 request to institute show cause proceeding to examine allogations of improper const practices & to half further fuel loading Immediate suspension of activities not warranted DENTON, H R Office of Nuclear Reactor Regulation, Director, 82/05/19 ROREM, B L Friends of the Earth Spp 14194 094 24X Fiche 50-373, 82/05/19, 8207200040
- --8207200061 Notice of request for action under 100FR2 206 to halt further fuel loading DENTON,H R Office of Nuclear Reactor Regulation, Director 82/05/19 3pp 14194 099 24X Fichs 50-373,82/05/19,8207200060
- 8207200054 Ack receipt of 820503 amend to request for show cause proceeding to suspend operations based on allegations of reinforcing steel damage in const. Suspendion of activities not warranted,
 DENTON, HR Office of Nuclear Reactor Regulation, Director 82/06/02 FAHMER, T C Illinois, State of 3pp 14194, 091, 243 Fiche 30-373, 82/06/02, 8207200054
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list encl
 DIRCKS.W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fiche 50-000,82/07/02.8207080064
- 8208040341 Forwards INEL draft technical evaluation rept based on util response to 801222 generic ltr. "Control of Heavy Loads " Conference call to resolve open items planned in approx 4 bits W/o encl SCHWENCER.A Licensing Branch 2 82/07/02 DELGEORGE.L O Commonwealth Edison Co. 2pp 14978 002 24X Fiche 50-373, 82/07/02, 82/08040341
- 8208040357 Notification of 820722 meeting w/util in Bethesda.MD to discuss vacuum breaker design pool swell following postulated LOCA BOURNIA-A Licensing Branch 2 82/07/21 BCHMENCER.A Licensin Branch 2 3pp. 14221 202 24X Fichs 50-373,82/07/21,8208040557.
- 8208070004 Notification of 820723 meeting w/util at site to discuss vacuum breaker design re pool swell following postulated LOCA.

 BOURNIALA Licensing Branch 2 82/07/23, SCHHENCER.A Licensin Branch 2 3pp 14283:340 24X Fiche. 50-373, 82/07/23, 820807 9004
- 8208030265 Advises that results of nonlinear analysis of whip restraint will be provided by conference call on 820730.as agreed upon at 820723 meeting w/NC STIEDE.W L. Commonwealth Edison Co. 82/07/26. SCHWENCER.A. Licansing Branch 2. 1p. 14158:134. 24X Fiche 50-373.82/07/26. 8208030265

- 8208040055 Summarises status of environ qualification requirements for facility & details corrective actions Proprietary draft Amend 41 to FSAR & Sangent & Lundy "Environ Qualification Rept" encl Encl withheld (ref 10CFR2 790)
 SCHROEDER, C & Commonwealth Edison Co 82/07/28 SCHWENCER, A Licensing Branch 2 9pp 14191 210 24X Fische 50-373,82/07/28,
- 8208040119 Forwards info re facility compliance w/NUREG-0737, Item II F 2 re inadequate core cooling, per Condition 2 C (30) (1) of License NFF-II No add) instrumentation needed to detect inadeguate core cooling. SCHROEDER, C W Commonwealth Edison Co 82/07/28 BCHWENCER, A Licensing Branch 2 lipp 14189 140 24X Fiche 50-373, 82/07/28, 8208040119
- 8208110188 Forwards revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations." Revision 21 Revised pages correct typographical & other minor errors SNARTZE Commonwealth Edison Co 82/08/04 HAASS, W.P. Guality Assurance Branch 1p 14314 079 24X Fiche 50-000.82/08/06.
- --B208110204 Revised pages to CE-1-A.Revision 21, "Comm Ed QA Program for Nuclear Generating Stations" # Commonwealth Edison Co 82/06/06 [1pp 14314 080 24X Fishs 50-000, 82/08/06, 8208110188
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submitted of documents to NRC Summarires 10CFR Chapter I requirements & provides alternatives to requirements Sv list encl EISENNUT.D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24% Fiche 50-000.82/08/09, 8208090194
- 8208130304 Forwards info re proposed License Condition 2 C (33) (a), discussed during 820802-04 meeting re resolution of Zack Co MVAC documentation deficiencies SCHROEDER, C W Commonwealth Edison Co 82/08/11 SCHWENCER, A Operating Reactors Branch 2 3pp 14336 042 24X Fiche 50-373, 82/08/11, 8208130304
 - 8208130307 Forwards response to 820729 request for info re HVAC contractor. Zack Co DELO@CRGE.L O Commonwealth Edison Co 82/08/02 QILINSKY,V Commissioners 49pp 14336 045 24X Fiche 80-373,82/08/11, 8208130304
- -8208130311 Submits corrections to typographical errors identified in 820802 ltr Chronology on resolution of Zeck Co documentation deficiencies enc!

 DELOEGREE, L D Commonwealth Edison Co 02/08/04 GILINSKY, V Commissioners 120pp 14336 098 24x Fiche 50-373, 82/08/11, 8208133304
- --8208130313 "Technical Review of Safety-Related HVAC Sys Installed by Zack Co at LeSalle County Nuclear Generating Station * Commonwealth Edison Co 82/08/12 52pp 14336 213 24X Fiche 50-373, 82/08/11.8208130304
- 8208270348 Forwards draft ltr to util documenting comments on HVAC sys independent review scoping ltr.per 820817 discussion Review comments & concurrence requested SPEBSARD.R L Division of Project & Resident Programs B2/08/16 E18ENHUT.D Q Division of Licensing 4pp 14565 106 24X Fiche 50-373,82/08/16,8208270348
- 9208240441 Forwards licensee 820813 ltr to CF Braun & Co re independent MVAC review in response to 820812 ltr HVAC review to be discussed at 820824 meeting in Olen Ellyn, IL DAVIS, A B Region 3, Office of Director 92/08/19, VANVRANHEN, J Illinois, State of 12pp 14527 002 24X Fiche 50-373, 82/08/19, 8208240441
 - Security, medical, emergency & fire protection plans
- 8208030094 Releases public version of revised LZP procedures FELTON.J.M. Division of Rules and Racords 82/07/19 Document Management Branch 1p 14195 172 24X Fiche.50-373,82/07/19, 8208030074
- --B208030100 Forwards public version of revised LZP procedures, including Procedures LZP-1200-4 re classification of liquid release & LZP-1330-21 re determination of reactor coolant chloride concentration at high radiation sampling sys HOLYDAK.R H Commonwealth Edison Co B2/06/21 Office of Nuclear Reactor Regulation, Director Ip 14195 173, 24X Fiche 50-373, 82/07/19, 8208030096.

- --8208030103 Public version of revised LZP procedures including Procedures LZP-1200-4 re classification of liquid release & LZP-1330-21 re determination of reactor coolant chloride concentration at high radiation sampling sys HOLYDAK, R H Commonwealth Edison Co 82/06/11 200pp 14195 174 24X Fiche 50-373,82/07/19,8208030076
- 8208110286 Releases public version of offsite notification forms FELTON.J M Division of Rules and Records 82/08/03 Document Management Branch 1p 14332 176 24X Fiche 50-373,82/08/03,8208110286
- --B208110289 Forwards public version of offsite notification forms that have not been returned Verification of manual updates by signing & returning encl forms requested

 * Commonwealth Edison Co 82/07/26 NRC No Detailed Affiliation Given 4pp 14332 177 24X Fiche 50-373,82/08/03, 8208110286
- 8208250557 Releases public varsion of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 FELTON.J M Division of Rules and Records 82/08/12 Document Management Branch Ip 14559 354 24% Fiche 50-000, 82/08/12, 8208250559
- --B208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 MODRE, R D Commonwealth Edison Co 82/07/19 DENTON, H R NRC No Detailed Affiliation Olven 1p 14559 355 24x
 Fiche 50-000, 82/08/12, 8208250559
- --8208240047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
 * Commonwealth Edison Co. 82/06/30 7pp. 14559-356. 24X Fiche 50-000.82/08/12.8208250559
- G Adjudicatory correspondence
- 9208040556 Responds to 920428 show cause petition on behalf of IL Friends of the Earth Parts of petition pertaining to Unit 1 denied Decision will be issued upon completion of evaluation prior to decision re OL for Unit 2 DENTON, H R Office of Nuclear Reactor Regulation, Director 92/07/19 ROREM, B L Friends of the Earth 2pp 14221 190 24% Fiche 50-373. 82/07/19, 8208040556
- --8208040562 Decision DD-82-7 denuing petition for show cause proceeding against util for operation of Unit 1 Decision re Unit 2 will be made upon completion of evaluation DENTON.H R Office of Nuclear Reactor Regulation, Director 82/07/19 7pp 14221 172 24X Fiche 50-373,82/07/19,8208040556
- --8208040967 Notification of issuance of Director's Decision DD-82-9 denying IL Friends of the Earth petition for show cause re Unit I Bupplemental decision will be made pertaining to Unit 2 DENTON.H R Office of Nuclear Reactor Regulation, Director 82/07/19 2pp. 14221 200 24% Fische 50-373,82/07/19,8208040556
- 8208040575 Responds to 820324 show cause petition & 820503 amend on behalf of State of IL Parts of petition & amend pertaining to Unit I denied Response deferred for Unit 2 Decision will be issued upon completion of evaluation DENTON, H R Office of Nuclear Reactor Regulation, Director 82/07/19 FAHNER, T C Illinois, State of 2pp 14228 199 24X Fiche 50-373, 82/07/19, 8208040575
- B208290451 Declines to suspend OL or withhold amend for full power operation Matters raised in petition will continue to be reviewed Decision under 10CFR2 206 will be issued following independent review of MVAC sys DENTON.H R Office of Nuclear Reactor Regulation, Director 82/08/04 00001.EM Citizens Against Nuclear Power 4pp 14562 286 24X Fiche 50-373,82/08/06.8208250451
- --8208250454 Notice of Citizons Against Nuclear Power 820728 petition to institute show cause proceeding based on alleged safety issues re const & GA deficiencies

 DENTON.H R Office of Nuclear Reactor Regulation, Director 82/08/06 3pp 14562 290 24X Fiche 50-373,62/08/06,8208290451
- 8208260487 Releases, for public inspirecord of Ofc of Inspector & Auditor, interview of T Harpster & portion of General Counsel 820726 memorandum concerning Director's decision on petitions re Legalle PARRISH, R.A. Office of the General Counsel 82/08/10 BERNABEL, L General Accounting Office 8pp 14595 001 24X Ficher 50-373, 82/08/10, 8208260487

DOCKETED ITEMS

- BROBIA0040 Order extending until B20B20 time for Commission to decide whether to review NRR director partial denial of State of It. & B Rorem B20324 request for action under 10CFR2 204 CHILK.5 J. Office of the Secretary of the Commission B2/08/13 Commissioners 1p 14344 336 24X Fiche 50-373,82/08/13. B208140040
- 8208250345 Informs that Commission declined to review Director's Decision 82-4 Time within which Commission may act to review expired Decision became final agency action on 820820 CHILK, B. J. Office of the Secretary of the Commission 82/08/29 FAHNER, T. C. Illinois, State of ROREM, B.L. Friends of the Earth 1p. 14540 264 24% Fiche 50-373,82/08/23,8208250345
- 8208310245 Comments on NRC decisions to authorize facility to operate above 8% power & up to 50% power & require independent review of HVAC sys Comments will be discussed at B20824 meeting w/Region 3 GOODIE. J S Illinois, State of B2/08/24 DENTON, H Office of Nuclear Reactor Regulation. Director App 14674 302 24% Fiche 50-373.82/08/24.8208310245

P Operating license stage documents & correspondence

8208310301 Informs of 820707 test of wetwell & drywell vacuum breaker valves in Santa Clara, CA, per Condition 2 C (32) of Amend 4 to License NPF-11 SCHROEDER, C W Commonwealth Edison Co 82/08/26 SCHWENGER, A Licensing Branch 2 ip 14674 273 24X Fiche 50-373,82/08/26, 8308/2004

Q Inspection reports, IE Bulletins & correspondence

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV)
 Laatege " Svc list encl
 JGRDAN.E L Division of Engineering & Guality Assurance, 62/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24x
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26,Part 3,Suppl i, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/19, Hithigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradval Loss of Air Pressure " 8vc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210376
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluorida Overpacks " Svc list encl COBB.L.! Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co of New York 7ipp 14387 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp 14194.321 24X Fiche 50-000,82/07/22,8204210398.
- B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115, 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Fa(lures at Westinghouse PWRs " 8vc list encl JORDAN,E. L. Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York. 127pp 14194-120, 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants" Bvc list encl JORDAN, E. L. Division of Engineering & Guality Assurance, 82/07/26, Consolidated Edison Co of New York. 121pp. 14357.013. 24X Fiche: 30-000.82/07/26,8204210403
- 620B170182 Comments on results of investigation into effect of damage to reinforcing steel, IE Investigation Repts 50-373/82-35 & 50-374/82-06. Results of addl analysis requested Full HVAC investigation should be conducted prior to full operation COODIE, J. S. Illinois, State of 82/07/27 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 5pp 14364 324 24X Fiche 50-373, 82/07/27, 8208170182

- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work i Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000. 82/07/28,8204210405
- B204210407 IE Info Notice B2-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Evc list entl JORDAN,E L Division of Engineering & Quality Assurance B2/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fichs 50-000, 82/08/05, 8204210407

R Pariodic operating reports & related correspondence

- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J. M. Division of Rules and Records 82/07/13 UDELL.R.A. Critical Mass Energy Project 8pp 14679 208 24X Fichs 50-000, 82/07/13.8208270010
- ---8208270559 Forwards "Recorded Annual Whole Body External Exposure & CVB1," per 10CFR20 407(b) M/o Guad Cities, Zion, LaBalle, Byron & Braidwood repts
 RAUSCH, T U Commonwealth Edison Co 82/03/31, Office of Management and Program Analysis ip 14680 075 24X
 Fiche. 50-000, 82/07/13, 8208270010

8 Reportable occurrences, LERs & related correspondence

- B20Bi002B0 PNO-III-B2-071 on 820729, received Part 2t rept via telcon w/Zack Co re documentation discrepancies for welds made to HVAC components at La Salle & possibily at Clinton & Hidland Helder of record may not be actual welder HALKER, R. D. Region 3, Office of Director 82/07/30 ip 14294 352 24X Fiche 50-000, B2/07/30, B20B1002B0
- 8208160248 Potential Part 21 rept re weld records Initially reported on 820729 Review of documents indicates possible discrepancy between welder of record & welder completing welds Investigation continuing DE ZUTEL, C Z Zack Co 82/08/02, KEPPLER, J Ø Region 3, Office Director, 10pp 14346-351 24X Fiche 50-000,82/08/02,8208160248
- 8208130030 Advises of steps taken to resolve QA documentation deficiencies of HVAC sys installed by Zack Co Sys can perform designed safety function, Rept of independent review will be submitted by 820915
 RECD. C Commonwealth Edison Co 82/08/04 DENTON, H R, Office of Nuclear Reactor Regulation Director 2pp 14339 095 24X
 Fiche 50-373, 82/08/04, 8208130030
- 8208310040 Final Deficiency Rept 82-05 rs predicted valvs stress on drywell/wetwell vacuum breaker valves not meeting ASME code allowable stress initially reported on 820723 Confirmatory test to be conducted by 821101 SCHROEDER.C.W. Commonwealth Edison Co. 82/08/19 KEPPLER.J Q Region 3. Office of Director 2pp. 14694 358 24X Fiche: 50-373, 82/08/19, 8208310040

DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

- Q Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Charification of Placement of Personnel Monitoring Devices for External Radiation" Syc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ. of 112pp. 14398 001. 24X Fichs 50-000.82/07/18204210395

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

- A Application/construction stage documents & correspondence
- B207080064 Generic itr to all licensees of operating plants, applicant for OL & holders of CP re Commission approved charter for CRGR. Bvc list encl.

 DIRCKS H J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co. of New York. 93pp. 14194,001 24X Fiche: 50-000,82/07/02.8207080064
- 8208040R93 Forwards draft technical evaluation rept, "Control of Heav Loads at Nuclear Power Plants Waterford Generating Station, Unit 3." Comments requested by 820901. MIRAOLIA, F U Licensing Branch 3 82/07/20. MAURIN, L V. Louisia Power & Light Co 2pp. 14225-154 24% Fichs 80-382,82/07/20. 8208040253

- --8208040260 "Control of Heavy Loads at Nuclear Power flants, Waterford Generating Station, Unit 3." draft technical evaluation rept RAMERS, J C EG&O, Inc 82/04/30 NRC - No Detailed Affiliation Oliven 23pp 14225 156 24% Fiche 50-382,82/07/20,8208040283
- 8208020336 Forwards Amend 28 to FSAR, consisting of application to amend OL Amend provides add1 info addressing SER issues resemengency shotdown from autside control room & THI Action 11tems II K 3 30 & II B 2 MCLENDON, 0 D Louisiana Power & Light Co 82/07/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 14147 102 24x Fiche 30-382, 82/07/28, 8208020336
- --B208020343 Application to amend OL.consisting of Amend 28 to FSAR Amend reflects add1 info needed to respond to SER (saues & NRC questions.

 MCLENDON, O D Louisiana Power & Light Co 82/07/28 2pp 14147 103. 24X Fiche 50-382, 82/07/28, 8208020336
- 8208:20068 Confirms 820707 telcon agreement re schedule for equipment audit Audit will start on 820720 MAURIN:L Y Lorisiana Power & Light Co 82/08/06 7EDESCO, R L. Assistant Director for Licensing 1p 14327 164 24X Fiche 50-382, 82/08/06, 8208;20068
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208240266 Responds to questions presented during 820615 meeting re GA program Training of applied physics personnel to GC-4 requirements accomplished MCLENDON, G D Louisians Power & Light Co. 82/08/19 DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp 14521, 362 24X Fiche 50-382,82/08/19,8208240266
- 8208270357 Advises that updated seismic qualification review team summary sheets of selected equipment for audit have been transmitted under separate cover MAURINL V. Louisians Power & Light Co 82/08/19 TEDESCO, R L Assistant Director for Licensing 1p 14565 104. 24X Fiche 50-382, 82/08/19, 8208270357.
- 8208310326 Forwards info re status of nuclear organization as of 820820 & staffing commitment per util 810420 ltr
 MADRIN-L V Louisians Power & Light Co 82/08/23 BLACK, S Office
 of Nuclear Reactor Regulation, Director 3pp 14693-208 24X iche. 50-382, 82/08/23, 8208310326
 - B270446 Forwards 820824 press release issued by applicant announcing eferral in scheduled commercial operation date until an 1984 Fuel loading scheduled for May 1983 Certificate f Svc encl Related correspondence AMLIN.J.B Shaw, Pittman. Potts & Troubridge. HAMLIN.J.B outsidane Power & Light Co. 82/08/24 WOLFE,S.J., FOREMAN,H., JORDAN.W Atomic Safety and Licensing Board Panel 4pp 14566 [16 24% Fichs 50-382,82/08/24,8208270446]
 - 8310154 Informs that response to NRC 820327 questions re rapid epressurfiation & decay heat removal capability of facility esign will be provided by 830815.

 **MAURIN.L V Louisiana Power & Light Co 82/08/25 TEDESCO.R L. Assistant Director for Licensing 2p 14693-197 24X

 Fiche: 50-382, 82/08/25, 8208310134
- 5. NRC Safety Evaluation Report (SER), supple & correspondence
- 8208020336 Forwards Amend 28 to FSAR, consisting of application to amend OL Amend provides addl info addressing BER issues remembered by the student from outside control room & ThJ Action Items II.K 3 30 & II B 2 MCLENDON, 0 D Louisians Power & Light Co 82/07/28 DENTON, H R. Office of Nuclear Reactor Regulation, Director ip 14147 102 24X Fichs: 50-382, 82/07/28, 82/8020336
- --8208020343 Application to amend OL.consisting of Amend 28 to FSAR Amend reflects add1 info needed to respond to SER issues & NRC questions.
 MCLENDON.9 D. Louisiana Power & Light Co. 82/07/28 2pp. 14147:103 24X Fiche 50-382,82/07/28,8208020336.
- F. Security, medical, emergency & fire protection plans
- 3208020196 Releases public version of emergency plan draft implementing procedures, FELTON.J M Division of Rules and Records 82/07/14, Document Management Branch, 1e 14181:059 24X Fiche 50-382,82/07/14,8208020196.

- --8208020197 Forwards public version of emergency plan draft implementing procedures, including Procedures EP-2-010 re notifications & communications & EP-2-020 re contaminated injured/ill personne!

 MAURIN.L V Louisiana Power & Light Co 82/06/28 Office of Nuclear Reactor Regulation, Director ip 14181-062 24X Fiche: 50-382,62/07/14:8208020196
- --8208020198 Public version of emargancy plan draft implementing procedures, including Procedures EP-2-010 re notifications & communications & EP-2-020 re contaminated injured/ill personnel Louisiana Power & Light Co. 82/06/28 900pp 14181-063 24% Fiche 50-382,82/07/14,8208020196

G Adjudicatory correspondence

- 8208110138 Notice of appeal of ASLS 820629 denial of petition to participate as interested state Issue of lack of feed & bleed backup for emergency feedwater sys must be resolved before OL issued Certificate or Svc enc!

 MATKENS, L. B. Louisiana, State of 82/08/06 Atomic Safety and Licensing Appeal Panel Spp 14316 233 24% Fiche 50-302,82/08/06 8208110138
- 8208120127 Response opposing State of LA 820721 petition to intervene No good cause shown for untimely attempt to raise emergency feedwater sys waste disposal issues Certificate of Svc encl CHURCHILL, DW Louisiana Power & Light Co CHURCHILL, BW Shaw. Pittman. Potts & Trowbridge 82/08/09 Atomic Safety and Licensing Board Panel 8pp 14327 066 24X Fiche 50-382,82/08/09,8208120127
- 820Bii0065 Response supporting State of LA B20721 patition to participate as interested state, but opposing admission as intervenor except in Table 5-3/high level waste issue Certificate of Svc encl
 TURK.S E Hearing Branch 1 82/08/10 Atomic Safety and Licensing Board Panel 14pp 14317 013 24X Fiche 50-382.82/08/10, 8208110065
- 8208110163 Notice of ASLAB constitution SF Eilperin, chairman & CN Kohl & RL Gotchy, members SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 82/08/10 1p. 14314 207 24% Ficher 50-382,82/08/10,8208110163
- 8208130170 Order directing will & NRC to file reply briefs to State of LA 820806 appeal from AGLB 820420 order denying State participation by 820823 & 27. respectively SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 62/08/11 Louisiana Power & Light Co 2pp 14339 024 24X Fiche 50-382, 82/08/11, 8208130170
- 8208130136 Memorandum & order requesting full & detailed explanation of acceptability of permit to operate despite incompleteness of staff review of unresolved safety (ssues Affidavít must be filed by 820825 MOLFE.S J Atomic Safety and Licensing Board Panel 82/08/12 Office of the Executive Legal Director 4pp 14335 336 24% Fiche 50-382,82/08/12,8208130136
- 8208190134 Memorandum & order reopening record on emergency planning brackure Schedule for filings on issue listed WOLFERS J Atomic Bafety and Licensing Board Panel 82/08/17 Louisiana Power & Light Co 4pp 14381 132 24X Fiche 50-382, 82/08/17.8208190134
- 8208240350 Forwards public info brochure to be distributed to general public as part of offsite emergency preparedness plan Brochure marked Applicant Exhibit il & sent per ASLB 820817 memorandum & order. Certificate of Svc encl CHURCHILL, B W Shaw, Pittman, Potts & Troubridge CHURCHILL, B H Louisiana Power & Light Co B2/08/17 WOLFE, B J, FOREMAN, M, JORDAN, W H Atomic Safety and Licensing Board Panel App 14321 045 24X Fiche 50-382.62/08/19,8208240350
- 8208240333 Forwards Applicant Exhibit 12 Color sketch to be imposed over public info prochure map to indicate individual color coding for 14 protective action sections within plume smargency planning zone Certificate of Bvc enci Wa sketch CHURCHILL, B W. Shaw, Fittman, Potts & Trowbridge CHURCHILL, B W. Louisiana Power & Light Co 82/08/20 WOLFE, S J., FOREMAN, H, JORDAN, W H. Atomic Safety and Licensing Board Panel. 4pp 14520:322 24x Fiche 50~382,82/08/20,8208240333
- 8208250234 Brief opposing State of LA 820806 notice of appeal from ASLB 820416 order denying LA petition to intervane in OL proceeding Appeal should be dismissed as untimely or ASLB order affirmed Certificate of Svc enci HAMLIN.J B Louisiana Power & Light Co HAMLIN.J B Shaw, Pittman, Potts & Trowbridge. 82/08/23 Atomic Safety and Licensing Appeal Panel 15pp 14542 299 24X Fiche 50-382,82/08/23,8208250234

- 8208270481 Clarification of ASLB 820817 order & conference call Discussion of brochure inadequate w/o discussion of info distribution sys Contention 17/26 (1)(a) not limited to brochure GROESCH.0 L Joint Intervenors-Waterford 82/08/24 2pp 14965 332 24X Fiche 50-382,82/08/26,8208270481
- 8208300102 Confirms 820824 teleon in which NRC request for extension of time until 820827 to file affidavits required by ASLB 820812 memorandum & order was granted Time for other parties to file comments extended until 820910 TURK, S.E. Hearing Branch i 82/09/26 MOLFE, B.J., FOREMAN, H. JORDAN, H. Atomic Safety and Licensing Board Panel ip 14596 151 24X Fiche 50-382,82/08/26,8208300102
- B20B310066 Forwards TY Chang affidavit re Unresolved Generic Bafety
 Issue A-46 on seismic quelification of equipment & CJ
 Anderson & CY Liang affidavit on Unresolved Generic Bafety
 Issue A-45 on shutdown decay heat removal
 TURK.S E Hearing Branch 1 B2/08/27 HOLFE.S J. FUREMAN, H.,
 JURDAN, H. Atomic Safety and Licensing Board Panel 1p
 14690 031 24X Fiche 50-382,82/08/27,8208310066
- --B208310071 Affidavit of TY Chang re Unresolved Ceneric Safety Issue A-46 on seismic qualification of equipment NRC will require resolution of item prior to permitting commencement of operation Prof qualifications encl
 CHANO, TY Equipment Qualification Branch 82/08/27 5pp.
 14670 032 24X Fiche 50-382,82/08/27,8208310046
- ---8208310074 Affidavit of GJ Anderson & CY Liang re Unresolved Generic Safety Issue A-45 on shutdown decay heat removal requirements Plant can be operated prior to resolution of issue Prof qualifications and ANDERSON, CJ Generic Issues Branch, LIANO, C, Y Reactor Bystems Branch & B2/08/27 12pp 14490 037 24X Fiche 50-382,82/08/27, 8208310066
- 8208310070 Brisf opposing Btate of LA 820806 notice of appeal from ASLB denial of LA patition to participate as interested state & ASLB withdrawal of sua sponte issue re feed & bleed capability Certificate of Svc encl TURK.8 E Hearing Branch i 82/08/27 Atomic Safety and Licensing Appeal Panel 12pp 14695 149 24X Fiche 50-382, 82/08/27, 8208310070
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8208020336 Forwards Amend 28 to FBAR, consisting of application to amend CL Amend provides add! info addressing BER issues re emergency shutdown from outside control room & TMI Action Items 11 K 3 30 & II 8 2 MCLENDON, G D Louisiana Power & Light Co 82/07/28 DENTON, H R. Office of Nuclear Reactor Regulation. Director. ip 14147:102 24X Fiche: 50-382, 82/07/28, 8208020336
- --8208020343 Application to amend OL, consisting of Amend 28 to FBAR. Amend reflects add1 info needed to respond to 8ER issues & NRC questions
 MCLEMPON, O D Louisiana Power & Light Co 82/07/28 2pp 14447 103 24X Fiche: 50-382, 82/07/28, 8208020336
- --8208020347 Amend 28 to FSAR

 * Louisiana Power & Light Co. 82/07/31 465pp 14147:105 24%
 Fiche 50-382,82/07/28,8208020336
- 8208030370 Certifies avc of Amend 28 to FBAR on 920730 EDELMAN.L New York, State of 82/07/30 ip 14154 001. 24X Fiche: 50-382, 82/07/30, 8208030370
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8207110046 Certified minutes of ACRS Bubcommittee on Waterford 820303 maeting in Washington DC re OL application FR notice, meeting schedule.list of attendees & selected meeting handouts encl # ACRS Advisory Committee on Reactor Safeguards 82/03/23 ACRS Advisory Committee on Reactor Safeguards 82/03/23 ACRS Advisory Committee on Reactor Safeguards, 39pp 14194.282.24X Fiche 50-382,82/03/23,8207110046.

- G Inspection reports, IE Bulletins & correspondence
- 8208100066 Forwards IE Insp Rept 50-382/82-11 on 820426-30 No noncompliance noted MADSEN, O.L. Division of Resident, Reactor Project & Engineering Programs 82/07/12 MAURIN, L.V. Louisians Power & Light Co. 2pp 14296 183 24X Fiche 50-382,82/07/12,8208100066
- --B208100070 IE Insp Rept 50-382/82-11 on 820426-30 No noncompliance noted Major areas inspected radwaste program & transportation activities including organization, training, waste sys.instrumentation, audits & procedures BAER,R E. MURRAY.B Division of Resident, Reactor Project & Engineering Programs 82/06/21 26pp 14276 185 24X Fichs 50-382,82/07/12,8208100066
- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JURDAN.E L Division of Engineering & Quality Assurance 82/07/16,
 Consolidated Edison Co of New York 87pp 14356 274 24%
 Fiche 50-000.82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl URDAN, E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24% Fiche 50-000, 82/07/19, 8204210395
- 9204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl GOBD,L I Division of Fuel Facilities, Materials & Sefeguards, B2/07/20, Consolidated Edison Co of New York 71pp 14387 276 24X Fiche 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Byc list enci JORDAN,E L Division of Engineering & Quality Assurance, 82/07/22, Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 JE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS "Evo list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/07/23, Consolidated Edison Co. of New York, 127pp 14174*120, 24X Fiche, 50-000. 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCB Piping at Certain Hestinghouse PHR Power Plants " Syc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/07/26. Consolidated Edison Co. of New York. 121pp 14357:013. 24X Fiche. 50-000, 82/07/26. 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JURDAN E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York, 122pp 14357-146, 24X Fiche 50-000-82/07/28,8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " Syc list encl.
 JORDAN: E L Division of Engineering & Quality Assurance. 82/08/05
 Consolifated Edison Co of New York 117pp 14988 201. 24X
 Fiche 50-000, 82/08/05, 8204210407
- 8208180047 Ack receipt of 8207R1 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/82-10 MADBEN, 0 L. Division of Resident, Reactor Project & Engineering Programs. 82/04/12 MAURINLLY Louisina Power & Light Co. ip. 14376,311 24X Fiche: 50-382,82/08/12,8208180047
- --8208180059 Responds to NRC 820615 ltr re violations noted in IE Insp. Rept 50-382/82-10 Corrective actions:craft personnel & supervisors instructed in neef for providing protection of installed equipment & lines.

 MALENDOM G. D. Louisiana Power & Light Co. 82/07/21 MADREN, Q L. Division of Resident, Reactor Project & Engineering Programs. App. 14376-312. 24X Fiche 50-382, 82/08/12, 8206180047.

- 8208240190 Ack receipt of 820806 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/82-06 MADSEN.0 L Division of Resident, Reactor Project & Engineering Programs 62/08/17 MADRIN.L V Louisiana Power & Light Co 1p. 14321 264 24x Fiche 50-382/82/08/17/8208240190
- --8208240193 Responds to NRC 820630 ltr re violations noted in IE Insp Rept 50-382/82-06 Corrective actions reactor vessel head cleaned daily & protective covering used C-E evaluation concluded that coolant piping & weld mat! satisfactory HCLENDON.9 D Louissens Power & Light Co 82/08/06 HADSEN.0 L Division of Resident. Reactor Project & Engineering Programs 3pp 14521 245 24x Fithe 50-382.82/08/17.8208240190
- 8208240205 Ack receipt of 820806 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/82-08 MADSEN.0 L. Division of Resident, Reactor Project & Engineering Programs 82/08/17 MADRIN.L V. Louisiana Power & Light Co. 1p 14519 078 24X Fishe 50-382,82/08/17.8208240208
- --B208240208 Responds to NRC 820617 ltr re-violations noted in IE Insp Rept 30-382/82-08 Corrective actions Candition Work Order Authorization 823607, inadvertently closed, recalled by Ebasco for re-evaluation & disposition MCLENDON. 9 D Louisians Power & Light Co 82/08/06 HADBEN. 9 L Division of Resident. Reactor Project & Engineering Programs App 14519:079 24X Fiche 50-382.82/08/17.8208240205
- R Periodic operating reports & related correspondence
- B20B090043 Forwards monthly rept re recruiting & upgrading of total corporate capability for period ending 820726, per util B10B06 commitment MAURIN, L.V. Louisiana Power & Light Co. B2/07/28 GLACK, B. Office of Nuclear Reactor Regulation, Director 4p. 14270-038 24% Fichs 30-382, 82/07/28, 8208090043
- 8 Reportable occurrences. LERs & related correspondence
- 9208100160 Third interim Significant Const Deficiency 33 re chilled water piping supports Corrective action not completed Final rapt expected by 821001 MCLEMOIN.9 D Louisiana Power & Light Co 82/07/30 COLLING.J T Region 4, Office of Director 1p 14298 035 24X Fiche 50-582,82/07/30.8208100160
- 8208100169 Second interim Bignificant Const Deficiency 47 re GE AKR 30/50 circuit breakers closing spring screw Corrective action not completed Final rept expected by 820813 MCLENDGN, O D Louisiana Power & Light Co 82/07/30 CDLLINS, J T Region 4. Office of Director. 1p (4298 234 24% Fiche 50-382,82/07/30,8208100169
- 6208100313 Advises of delay in submittal of final rept of Bignificant Const Deficiency 49 re Time-Trol. Inc heat trace panel malfunctions, due to extent of work required to complete corrective actions final rept espected by 821120 MCLENDON.0 D Louisiana Power & Light Co 82/07/30 COLLINS, J T. Region 4. Office of Director ip 14297 110 24X Fiche.50-382, 82/07/30.8208100313
- BROBIO0229 Final rept of Significant Const Deficiency 26 re Anchor Darling Valve Co main feedwater isolation valve actuator deficiencies in cold temp Corrective actions involving installation of heaters & thermestats completed on 820728 MCLEMBON, 0. D. Louisiana Power & Light Co. 62/08/02 COLLINS, J T Region 4. Office of Director 3pp. 14294 334 24X Fiche 50-382,82/08/02,6208100229
- 8208100319 Final rept of Significant Const Deficiency 45 re loose mounting screws found in GE AKR 50 relay bell alarm switches Corrective action per GE to prevent mounting screws from backing out completed MCLENBON.0 D Louisiana Power & Light Co. 82/08/02 COLLINS, J T Region 4. Office of Director 3pp 14297 139. 24X Fiche 50-382.82/08/02,8208100319
- 8208140023 Fourth interim deficiency rept re failure of resistive temp detectors final rept on Significant Const Deficiency 37 delayed, pending delivery & installation of replacement detectors. Documentation completed by 82:105 MCLENDON, 0. D. Louisians Power & Light Co. 82/08/05 CGLLINS, J T Region 4. Office of Director ip 14344 312 24% Fiche: 30-382, 82/08/05, 8208140023
- 8208160038 Final Bignificant Const Deficiency Rept 20 re inadequate design/design review of instrumentation seismic & support drawings Rework of 124 supports complete All documentation reviewed & approved by Jul 1982 MCLENDON: 0 D Louisiane Power & Light Co. 82/08/05 CDLLINS, J T Region 4. Office of Director 7pp 14344 344 24X Fiche 50-382,82/08/05,8208160038

- 8208160046 Interim Significant Const Deficiency Rept 38 re startup test control: flooding of smergency diseas generator control & relay panel Final rept expected by 820910 MCLENDON.G D Louisiana Power & Light Co 82/08/05 COLLINS.J Y Region 4, Office of Director ip 14344 303 24X Fiche 30-382, 82/08/05, 8208160046
- 8208160175 Second interim rept of Significant Const Deficiency 55 re holdup & boric acid makeup tanks w/incorrect structural calculations Submittal of final rept delayed until 821215 MCLENDON, O D Louisiana Pawer & Light Co 82/09/05 COLLINS, J T Region 4. Office of Director ip 14344 311 24X Fiche 50-392, 82/08/05, 8208160175
- 8208160283 Interim Significant Const Deficiency 41 rs linear crack in stainless steel tubing Initially reported on 820625 Metallurgical analysis indicates defect due to hot tear traced to tube hollows Final rept expected by 820831 MCLEMPON. 8 D Louisiana Power & Light Co 82/08/05 COLLINS, J T Region 4. Office of Director 4pp 14347 038 24X Fiche 50-382, 82/08/05,8208160283
- 820BiA0076 Third interim deficiency rept re HMA auxiliary relays
 Required insulating tubing for application on relays
 received w/o evidence of certification of compliance to
 spec Bocumentation expected 820B09 Final rept due by 820909
 MCLENDON, O D Louisiana Power & Light Co 82/08/06 CQLLING, J T
 Region 4, Dffice of Director in 14342 121 24X
 Fiche 50-382,82/08/06,820Bi40076
- 8208170122 Interim rept of Bignificant Const Deficiency 58 re 820712 cable tray fire in reactor auxiliary bidg Damaged cables unacceptable for Class IE use will be replaced & repaired as necessary Completion & final rept by 821231 MCLENDON O D Louisiana Power & Light Co 82/08/06 COLLINS, J 7 Region 4, Office of Director 3pp 14365 203 24X fiche 50-382,82/08/06,8208170122
- 8208170341 Interim rept of Significant Const Deficiency 60 re turnover dacomentation & inadequate hanger weld problems Reinsp, Tompkins-Beckwith GA audit & retraining program will be completed by 830215 MCLENDON, 0 D, MILHISER, N J, WILLS, J L Louisiana Power & Light Co 82/08/05 COLLINS, J T Region 4, Office of Director 4pp 14367 014 24X Fiche 50-382.82/08/06.8208170341
- 8208170313 Second interim deficiency rept re low pressure safety injection pump suction valves Initially reported on 820226 Final rept will be delayed until 821217 Current valve shipping date from Anchor-Darling is 820815 HCLENDON 0 D Louisiana Power & Light Co 82/08/10 COLLINS, J T Region 4, Defice of Director ip 14367 038 24X Fiche 50-382, 82/08/10, 8208170313
- 8208200060 Final Significant Const Deficiency Rept 46 re Cooper-Bassemer emergency diesel generator Agastat relays defect.Initially reported on 820611 Control relays, 1480PDC-740, removed & returned to Amarace Corp for repair HCLENDON.0 D Louisiana Power & Light Co 82/08/11 COLLINS, J T Region 4, Office of Director 3pp 14392 357 24X Fiche 50-382, 82/08/11, 8208200060
- 8208200040 Final Bignificant Const Deficiency Rept 46 re
 Cooper-Bessemer emergency diesel generator Agastat relay
 defect.initially reported on 820611 Control relays,
 1480PDC-740.removed & returned to Amarcel Corp for repair
 MCLENDON, 0 D Arkansas Power & Light Co 82/08/15. COLLINS, J T
 Region 4, Office of Director 3pp 14392 357 24X
 Fiche 30-382, 82/08/11, 8208200060
- B20B20009A Final rept of Bignificant Const Deficiency 47 re defect in AKR-90/50 circuit breaker GE circuit breaker failed to recharge closing spring Field inspressed backed out & broken flat screw heads Replacement screw ordered MCLENDON, 0 D Louisiana Power & Light Co B2/08/11 COLLINS, J T Region 4. Office of Director 5pp 14393 254, 24X Fiche 50-382, 82/08/11, 8208200096
- B208200271 Final Deficiency Rept B3 re SCI invertors oscillation deviations Initially reported on B20719 Deficiency determined not reportable under 10CFR50 55e Results of review available at site MCLENDON, 0. D Louisiana Power & Light Co 82/08/11 COLLINS, J 7 Region 4. Office of Director ip 14399 345 24X Fiche 50-382, 82/08/11, 8208200271
- B208240244 Third interim Significant Const Deficiency Rept 41 re unapproved welding Final rept will be submitted by B20917, not B20816. as previously indicated MCLENDON, 0 D Louisiene Power & Light Co 82/08/16 COLLING, J. T Region 4, Office of Director ip 14520 094 24X Fiche 50-382, 82/08/16, 8208240244

- 8208240256 Third interim Significant Const Deficiency Rept 54 re tube steel (HT 16600) laminations final rept will be submitted by 830213 not 820816, as previously indicated MCLENDON.9 D Lauisiana Power & Light Co 82/08/16 COLLING. J T Region 4. Office of Director ip 14527 078 24X Fiche 50-382, 82/08/16, 8208240296
- 8208270168 Interim deficiency rept re instrumentation & control systematical installations not in accordance w/design specs Initially reported on 820714 Crafts reassigned off safety-related sys 5 documented retraining program completed & approved MCLENDON-0 D , MILLIESER.R J , WILLE, J L Louisiana Power & Light Co 82080/17 COLLINS.J T Region 4. Office of Director 4pp 14563 312 24X Ficho 50-382,82/08/17.8208270168
- T Hearing transcripts on non-antitrust matters
- 9208110161 Order granting 920719 & 16 motions to correct hearing transcript HOLFE, BJ Atomic Gafety and Licensing Board Panel 92/08/10 Office of the Executive Legal Director 1p 14314-224 24X Fichs 30-302,82/08/10,8208110161
- DOCKET 50-387 SUBQUEHANNA BIEAM ELECTRIC BIATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8208030737 Requests proposed schedule for submitting program re adequacy of design margins of Mark I & II containment sys. Response within 14 days requested TEDESCO.R.L. Assistant Director for Licensing 82/07/08 CURTIS.N.H. Pennsylvania Power & Light Co. 3pp. 14195.353 Fishe 50-387,82/07/08,8208030737
- E NRC Bafety Evaluation Report (BER), suppls & correspondence
- B20B110066 Advises that fatigue cycling discussed in util B20714 lth has not been completely addressed par B20726 telcon Effects on NSBB equipment should be evaluated Add discussions of item provided in BFR Suppl 3 YOUNDBLOOD D J Licensing Branch 1 B2/07/26 CURTIS, N H Pennsylvania Power & Light Co 2pp 14329 352 24X Fichs 50-387/82/07/26.0208110066
- B20B170027 Forwards NUHLG-07/6, Buppl 3 to BER Rept has been placed in PDR W/d encl.
 YOUNGELEDUS D Licensing Branch I 82/07/26 CURTIB, N W Pennsylvania Power & Light Go 3pp 14506 357 24X Fiche 50-3B7, 82/07/26, U20B170027
- 8208030401 Responds to supplemental BER Item 3 10 1(3) re fatigue effects on NSBS equipment due to safety relief valve loads Electrical & mechanical NSBS equipment analyzed for fatigue cycling All NSBS equipment will perform satisfactorily CURTIS.N & Pennsylvania Power & Light Co 82/07/29 SCHMENCER.A Licensing Branch 2 3pp 14194 013 24X Fiche 50-387,02/07/29,8208030401
- B208030455 Responds to request for results of reassessment of seismic & dynamic qualification of individual NGGS equipment per SER Item 3 10 3 Results of each assessment method on equipment items listed CURTE, N W Pennsylvania Power & Light Co 02/07/29 BCMWENCER, A Licensing Dranch 2 2pp 14155, 272 24X Fiche 50-387, 82/07/29, 8208030455
- 9208040193 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SUSQUEHANNA STEAM CLECTRIC STATION.UNITS 1 AND 2 Docket Nos 50-387 And 50-388 (Pennsylvania Power And Light Company) * Office of Nuclear Reactor Regulation, Director NUREO-0776 803. 82/07/31 173pp Available at NTIG. \$6.50 14233 183 24X Fiche 50-387,82/07/31,8200040193
- 8208240151 Forwards updated preservice insp program info re BER Issue 19 Revision includes preservice exams performed subsequent to util 010519,0616 & 820823 submittals CURTIS,N W Pennsylvania Power & Light Co 82/08/20 BCHWENGER,A Licensing Branch 2. 21pp 14520 130 24% Fiche 50-387,82/08/20,8208240151
- 62083(0125 Provides analysis of wetwell environ & uffect on environ qualification of equipment due to steam bypass per License Condition C(18)(a), Bubmittal satisfies BER Suppl 3, Sections 3 (1, 3 0 & 3 1, 5(2))(c) CURTIS.N W Pennsylvania Power & Light Co 62/08/25 BCHWENCER, A Licensing Branch 2 2pp. 14694 362 24X Fichs 50-387, 62/08/25, 8208310125

- 8208310252 Provides info per SER Suppl 3.Section 3 11 5(2)(#) re submergence due to pool swell Bubmergence caused by pool swell does not affect qualification of equipment in wetwell. CURTIS.N W Pennsylvania Power & Light Co 82/08/25 SCHWENCER.A Licensing Branch 3 2pp 14688 170 24X Fiche 50-387.82/08/25. B208310252
- 820B310343 Forwards draft "Analysis of Scram Discharge Vol Bys Piping Integrity," in response to SER Suppl 3 Item 3 i1 5(2)(e), requiring updated environ qualification of equipment per Section 5 3 of NOREO-OBOS No further action required CURTIS.N N Pennsylvania Power & Light Co 82/08/25 BCHWENCER.A Licensing Branch 2 ip 14692 070 24X Fiche 50-387.82/08/25, 820B310343
- --8208310383 Draft "Analysis of Scram Discharge Vol Bys Piping Integrity " ALEBII.G . HAYEB,F R , STANCAVAGE,P P General Electric Co NEDG-22209 DRFT 82/08/31 28pp 14692 072 24X Fiche 50-387,82/08/25,8208310343
- F Security, medical, emergency & fire protection plans
- 8208050294 Forwards IE Safeguards Insp Rept 50-387/82-22 on 820421-25 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/07/16 CURTIS.N W Pennsylvania Power & Light Co 2pp 14211 185 24X Ficha 50-387, 82/07/16, 8208050294
- --B20B050300 IE Bafeguards Insp Rept 50-3B7/B2-22 on B20621-25 No noncompliance noted Major areas inspected locks, keys & combinations, physical barriers, vital areas, security power supply & detection aids Hithheld (ref 10CFR3 21) DUNLAP, J M, 90DV, J M Region 1, Office of Director, 82/07/08, ip 14211 187 24X Fiche 50-3B7, 82/07/16, 820B050296
- 820B030078 Releases public version of revision to emergency plan implementing procedures manual FELTON, J M Division of Rules and Records, 82/07/19 Documen Management Branch ip 14197 001 24X Fiche 50-387, 82/07/17, 820B030078
- --B20B0300B3 Forwards public version of Ravision 2 to emergency planimplementing procedure.including Procedures EP-IP-CO1 re emergency classification % EP-IP-CO2 re emergency mgt notification * Pennsylvania Power & Light Co 82/06/25 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 14199 002 24% Fiche 50-387,82/07/19,8208030078
- --8208030086 Public version of Revision 2 to emergency plan implementing procedures manual.including Procedures EP-IP-O01 re emergency classification & EP-IP-002 re emergency mgt notification.

 * Pennsylvania Power & Light Co 82/06/28 644pp 14199 004 24X Fichs. 30-387.82/07/19.8208030078
- 8208120047 Forwards IE Insp Rept 50-387/82-20 on 820614-18 No noncompilance noted MARTIN,T T Division of Engineering & Technical Programs 82/07/29 CURTIS,N W Pennsylvania Power & Light Co 2pp 14324,020, 24X Fiche 50-387,82/07/29,8208120047
- --820Bi20094 IE Insp Rept 50-387/B2-20 on 920614-18 No noncompliance noted Major areas inspected emergency, abnormal alarm response & instrument surveillance procedures.

 BLUMDERQ:N. PULLANI:B. CAPHTON:D L. Region I. Office of Director. 82/07/14 19pp 14324 022. 24X Fiche 50-387,82/07/29,8208120047
- B20B120136 Forwards IE Insp Rept 50-387/B2-24 on B20706-09 No noncompliance noted
 BMITH,0 H Division of Emergency Preparedness & Operational Support
 B2/07/29 CURIS.N W Pennsylvania Power & Light Co. 2pp
 14327 122 24X Fiche 50-387.82/07/29.820B120136
- --B20B120140 IE Insp Rept 50-387/82-24 on B20706-09 No noncompliance nobed Major areas inspected emergency preparedness program, selective exam of procedures & representative records, interviews w/personnel & observations by inspector SAKENAB.C. SMITH.R. CROCKER.H W Division of Emergency Preparedness & Operational Support 82/07/22 App 14327-124 24X Ficha-50-387.82/07/29.8208120136
- 8208300285 Forwards "Qualification Fire Test of Protective Envelope Bys," per License Condition 7 Results show adequacy of tested wrapping math of as-installed 1-h cable wrap configuration CURTIB,N W Pennsylvania Power & Light Co 82/08/25 BCHWENCER,A Licensing Branch 2 2pp 14673 359 24X Fiche 90-387,82/08/25, 8208300285

--8208300272 "Qualification Fire Test of Protective Envelope Sys " BEITELIJ J Pennsylvania Power & Light Co 01-7163 82/08/25 300pp 14674 001 24% Fiche 50-387,82/08/25,8208300285

G Adjudicatory correspondence

- 8208110153 Order rendering ASLB 820412 decision authorizing OL issuance effective Full power GL not yet authorized CHILK.S J Office of the Secretary of the Commission 82/08/09 2pp 14314 283 24% Fiche 30-387.82/08/09.8208110153
- 8208160426 Order directing parties to identify person presenting arguments at 820908 hearing in Bethesda.ND Response requested no later than 820831
 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 82/08/13
 Pennsylvania Power & Light Co 2pp 14348 360 24X
 Fiche 50-387, 82/08/13, 8208160426
- 8208230064 Advises that author will represent NRC at 820908 oral argument CUTCHIN, J M Hearing Branch 4 82/08/18 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 1p 14517 221 24X Fiche 50-387, 82/08/18, 8208230064
- 8208240321 Patition for reconsideration of Commission 820809 order rendering ASLB initial decision effective Exceptions to decision require resolution Commission order premature Certificate of Svc encl HALLIGAN.T J Citizens Against Nuclear Dangers 82/08/18 Commissioners 2pp 14521 001 24X Fiche 50-387, 82/08/18, 8208240231
- 8208240179 Order listing questions to be answered at 820708 oral argument SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 82/08/20 4pp. 14517 303 24X Fiche 50~387,82/08/20.8208240199
- 8208270374 Order advising parties to exchange affidavits supporting representations counsel intends to make at 820908 oral argument info needs to be on record Supplemental evidentiary hearings will be held on 820707-10
 SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 82/08/24
 Office of the Executive Legal Director. 4pp 14565 123 24X
 Fiche, 50-387, 82/08/24, 8208270394.
- 8208270460 Advises that JE Silberg will represent applicants at 820908 oral argument Svc list encl Silberg, JE Shaw, Pistmann, Potts & Trowbridge, SILBERG, JE Pennsylvania Power & Light Co 82/08/24 THOMPKINS, B A Atomic Safety and Licensing Appeal Panel 3pp 14565 340 24X Fiche 50-387, 82/08/24, 8208270460
- 8208270376 Order amending B20824 order to provide supplemental avidentiary hearing to be held on 820908 & 10, if hearing necessary SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel, 82/08/25 2pp 14564 235 24X Fiche 30~387,82/08/25,8208270376

J. Insurance & indemnity information

- 3208120105 Forwards Amend 1 to Indemnity Agreement 8-90, per 820717 request CURTIS:N W Pennsylvania Power & Light Co. 82/08/07 EISENHUT, D. O. Division of Licensing Spp 14317 161 24X Fiche: 50-387, 82/08/09, 8208120105.
- 820B170273 Advises that PA Power & Light Co & Allegheng Electric Cooperative have opted to provide surety bond for payment of deferred premiums NELIA Binders EB-84 & XB-84 enci CURTIS:N W. Pennsylvania Power & Light Co 82/08/12 EISENHUT, D Q Bivision of Licensing, 11pp. 14367 215 24X Fiche: 50-387, 82/08/12, 8208170273
- P Operating license stage documents & correspondence
- 9208250305 Farwards "Final Rept. Independent Design Review, Susquehanna Steam Electric Station."

 LANGERS: D F Teledyne Engineering Services 82/05/06. SHOVLIN: R J Pennsylvania Power & Light Co 2pp 14539.001 24X Fiche: 50-387.82/05/06.8208250305.

- 8208060366 Board Notification 82-70 notifies of differing prof opinion regensitization of BMR stainless steel weldments EISENHUT.D 0 Division of Licensing 82/07/20 PALLADING, N J , OLLINSKY, V , AHEARNEJ Commissioners 4pp 14281 361 24X Fiche 50-387, 82/07/20, 8208060366
- 8208090343 Board Notification 82-78 notifies of allegations restress intensification factors % reconciliation of nozzle loads as part of piping analysis & welder qualifications
 TEDESCU.R L. Assistant Director for Licensing 82/07/22 Atomic Safety and Licensing Appeal Panel Spp 14306 306 24%
 Fiche 50-387, 82/07/22, 8208090343
- ---8205i1059i Informs of items which have been ignored by site supervisors in analysis of small bore piping Items should be investigated during next audit # Affiliation Unknown 82/05/03 NRC No Detailed Affiliation Oiven 1p 14306 311 24% Fiche 50-387, 82/07/22, 8208090343
- 8208120326 Forwards Hydrologic Engineering Branch review of proposed UHB test planiper util 820616 itr Plan generally acceptable Suggestions for improvement discussed YOUNGBLOOD, B. J. Licensing Branch 1 82/07/22 CURTIS.N W Pennsylvania Power & Light Co. 5pp 14332 261 24X Fiche 50-387, 82/07/22, 8208120326
- 820B180219 Forwards request for add1 info re emergency diesel engine air starting sys Procedure used to conduct diesel start test per Tech Spec 4 8 1 1 2 d 12 requirement should be provided YOUNGBLOOD B J Licensing Branch 1 82/07/22 CURTIS,N W Pennsylvania Power & Light Co 3pp 14390 350 24X Fiche 50-387, 82/07/22.8208180219
- 8208090936 Advises of Board Notification 82-55 notifying of air pressure leads on drywell-wetwell varuum breakers during pool swell following postulated LOCA EISENHUT.D 0 Division of Licensing 92/07/23 PALLADINO,N J. GLINSKY,V. AHEARNE, J. Commissioners, 5pp 14306 292 24X Fiche: 50-387, 82/07/23, 8208090936
- --8206140404 Board Notification 82-55 notifies of air pressure loads on drywell-wetwell vacuum breakers during pool swell following postulated LOCA
 TEDESCO, R. L. Assistant Director for Licensing 82/06/10
 Atomic Safety and Licensing Appeal Panel 7pp 14306:297 24X
 Fiche 50-387,82/07/23.8208090336
- 8208110066 Advises that fatigue cycling discussed in util 820714 ltr has not been completely addressed per 820726 telcon Effects on NSSS equipment should be evaluated Addl discussions of item provided in SER Suppl 3 YOUNORLOOD, B J Licensing Brench 1 82/07/26 CURTIS, N W Pennsylvania Power & Light Co 2pp 14329 352 24X Fiche 50-387, 82/07/26, 8208110066
- 820Bi10205 Forwards corrected Tech Spec Pages 3/4 3-11,3/4 3-12, 3/4 3-15,3/4 3-32,3/4 3-71,3/4 3-88,3/4 4-6 & 8 3/4 3-8 re isolation actuation instrumentation & ECCS setpoints YOUNGBLOOD, 8 J Licensing Branch ! 82/07/26 CURTIS,N H Pennsylvania Power & Light Co 3pp 14329 060 24X Fiche 50-387,82/07/26,8208110205
- --8208110208 Corrected Tech Spec Pages 3/4 3-11,3/4 3-12,3/4 3-15, 3/4 3-32,3/4 3-71,3/4 3-88,3/4 6-6 & 8 3/4 3-8 re isolation actuation instrumentation & ECCB setpoints # Office of Nuclear Reactor Regulation, Director 82/07/26, 14pp 14329 063 24X Fiche 50-387,82/07/26,8208110205
- 8208020082 Describes steam bypass analysis to be conducted to determine max wetwell temp for aduspment qualification Confirmation of acceptability of analysis requested CURTIS.N.W Pannsylvania Power & Light Co 82/07/27. BCHWENCER A Licensing Branch 2 2pp 14144 100 24X Fiche 50-387,82/07/27. B208020082
- 8208040516 Notification of 820805 meeting w/util in Bethasda,MD to discuss containment purgs & vent valve qualification PERCH,R L Licensing Branch 2 82/07/27 YOUNGBLOOD,B J Licensing Branch 1 3pp 14220 337 24X Fiche.50-387,82/07/27,8208040516
- 8208040142 Forwards qualification repts for M8IV actuators & M8IV leakage control heater sys CURTIS,N W Pennsylvania Fower & Light Co 82/07/28 GCHWENCER,A Licensing Branch 2 11pp 14185,024 24X Fiche 80-387,82/07/28,8208040142
- --8208040166 "Apparent Test Results for Susquehanna 1 & 2 26-inch MSIV Actuator Dynamic Qualification Test." OLIVER, D D, NIEH, C T, ADAMS: T E, Pennsylvania Power & Light Co ATR-DDO-B204, B2/07/20 110pp 14185,035 24X Fichs 50-387,82/07/28,8208040142

- ---8208040190 "Dynamic Gualification Test Rept on MSIV Leakage Control 82/06/21 172nn
- 8208030204 Advises that Bechtel recheck of all calculations used in stick models for containment indicate models acceptable Response satisfies OL requirement to review containment model by B20730 CURTIS.N W Pennsylvania Power & Light Co 82/07/30 SCHWENCER, Licensing Branch 2 lp 14157 337 24X Fichs 50-387, 82/07/30, 8208030204
- 82/07/30 SCHWENCER, A
- 8208040344 TECHNICAL SPECIFICATIONS FOR BUSQUEHANNA STEAM ELECTRIC STATION, UNIT No 1 App A to License NPF-14 Docket No 50-387 (Pennsylvania Power and Light)

 # Office of Nuclear Reactor Regulation, Director NUREG-0931 82/07/31 487pp Available at NTIS \$11 00 14222 001 24X Fiche. 50-387, 82/07/31, 8208040344
- 8208060190 Bubmits info on spraypond Piezometer 2 high groundwater reading Piezometer 2 deletion will be included in next FSAR revision CURTIB.N W Pennsylvenia Power & Light Co 82/08/03 SCHWENCER, A Licensing Branch 2 5pp 14239 035 24X Fiche 50-387,82/08/03, 8208060190
- 8208060278 Forwards results of facility entrainment demonstration program developed to meet requirements of Special Condition C.7art C of NPDES Permit PA 0047325 CURTIS.N W Pennsylvania Power & Light Co. 82/08/03 8CHWENCE, Licensing Branch 2 ip 14237 302 24X Fiche 50-387, 82/08/03, 8208060278 82/08/03 SCHWENCER, A
- --8208060302 "Susquehanna Steam Electric Station 326(b) Entrainment Demonstration Program for NPDES Permit PA 0047325 Special Condition C.Part C " ** Pennsylvania Power & Light Co \$2/07/31 51pp 14239 303 24% Fiche 50-387.62/08/03.8208040298
- 8208070174 Oeneric Ltr 82-14 to all reactor liconsees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT.D 9 Division of Licensing 82/08/07 Consolidated Edison Co of New York ip 14354 332 24X Fiche 30-000.82/08/07, 8208070174
- 8208230478 Responds to 820721 ltr re 820806 submittal addressing NS88 supplier review of emergency operating procedures & startup tests License Condition 28A satisfied YOUNGBLOOD, B. J. Licensing Branch 1 92/08/10 CURTIS, N. W. Pennsylvania Power & Light Co. 2pp. 14328 239 24X Fiche 50-387, 82/08/10, 8208230478
- 820B170248 Forwards results of vacuum breaker performance evaluation providing justification for plant operation beyond Mode 3 Draft NEDE-22178-P, "Mark II Containment Drywell-to-Hetwell Vacuum Breaker Models," withhald (ref 10CFR2, 790) CURTIS,N W Pennsylvania Power & Light Co. B2/08/13, BCHWENCER, A Licensing Branch 2, 2pp 14369, 345 24X Fiche 50-387, B2/08/13, 8208170248
- --8208170252 Forwards "Pool Swell Forcing Functions for Mark II Watwell-to-Drywell Vacuum Breakers " PFEFFERLEN.H C. General Electric Co 82/07/23, SPEIB, T. P. Assistant Director for Reactor Safety Ip 14369-348 24X Fiche 50-387, 82/08/13, 8208170248
- --8208170255 "Pool Bwell Forcing Functions for Mark II Wetwell-to-Drywell Westurm Breakers,"

 * Oeneral Electric Co 82/07/23 7pp 14369 349, 24X Fiche 50-387, 82/08/13, 8208170248.
- --8208170257 "Mark II Primary Containment Vacuum Reilef Valve Test Program.Phase IV.Revision 0 " WILLIAMSON.0 0., TESKE.M E Continum Dynamics. Inc WEBT. J A. Anderson-Greenwood & Co 82-4 ROO 82/08/31 68pp 14369-357 24X Fichs 50-387.82/08/13.8208170248.
- 8208200239 Forwards procedures which comprise revised process control program & supporting lab test program Process control program revised to incorporate provisions for sampling waste batches

 CRT15.N W. Pennsylvania Power & Light Co 82/08/17 8CHWENCER.A.
 Licensing Branch 2 2pp 14398-149 24X Fiche 50-387,82/08/17. Licensing Branch 2 8208200239.
- --8208200245 "Bolid Waste Process Control "

 * Pennsylvania Power & Light Co 82/07/14. 27pp 14398, 151.
 24X Fiche 50-387, 82/08/17, 8208200239.

- --8208200253 "Radwaste Solidification Sys " * Pennsylvania Power & Light Co 82/07/14 52pp 14398 178 24X Fiche 50-387.82/08/17.8208200239
- --8208200257 "Solid Waste Sample Test Solidification & Evaluation "
 # Pennsylvania Power & Light Co 82/07/27 5pp 14398 230
 Fiche 50-387,82/08/17,8208200239 14398 230 24X
- --8208200264 "Solid Radwaste Analysis "
 # Pennsylvania Power & Light Co 82/07/06 14pp 14398 235 24X Fiche 50-387.82/08/17.8208200239
- --8208200274 "Cement Bolidification of Sodium Sulfate Waste Containing Resins & Contaminants "

 Hittman Nuclear & Development Corp (subs Hittman Corp).

 Eli9-1 ROL 82/07/31 44pp 14398 249 24x

 Fichs 50-387,82/08/17,8208200239
- 8208260530 Summary of 820713 meeting w/util & Bechtel & Structural Mechanics Assoc re revisions to horizontal dynamic analysis PERCH.R L. Licensing Branch 2 82/08/17 Licensing Branch 2 4pp 14572 339 24X Fiche 50-387,82/08/17,8208260830
- 8208240397 Application for Amend 1 to License NPF-14, changing App A Tack Specs to allow surveillance requirements for vacuum breakers to be consistent w/manufacturer test procedure Marked-up Teck Specs encl CURTIS.N W Pennsylvania Power & Light Co 82/08/18. BCHWENCER, A Licensing Stanch 2 30pp 14524-217 24X Fichs 50-387,82/08/18,8208240397
- 8208240198 Confirmatory Action Ltr 82-21 re 820810 telcon on small bore pipe action plan Actions util will undertake listed STAROSTECKI.R Division of Project & Resident Programs. 82/08/19 CURTIS.N W Pennsulvania Power & Light Co 2pp. 14519-301. 24X Fiche 50-387.82/08/19.8208240178
- 8208240175 Forwards application for Amend 2 to Item 2 C.(9) of License NFF-14.correcting Amend 48 to 49 on 820709 DL application Fees per 10CFR170 not applicable since license not issued until 820717 CURTIS.N W Pennsylvania Power & Light Co. 82/08/20 SCHWENCER, A Licensing Branch 2 ip 14519 309 24X Fiche 50-387,82/08/20, 8208240195
- --BZ08240202 Application for Amend 2 to Itam 2 C (9) of License NPF-14, correcting Amend 48 to 49 on 820709 DL application CURTIB,N W Pennsylvania Power & Light Co 82/08/20 2pp. 14519 310 24X Fiche 50-387, 82/08/20,8208240195
- 8208260221 Forwards corrected page to B20818 application for Amend 1 to License NPF-14 Date of issuance of license was listed as 780717 instead of 820717 CURTIS.N W Pennsylvania Power & Light Co 82/08/23 SCHWENCER, A Licensing Branch 2 ip 14534-303 24X Fiche-50-387,82/08/23,8208260221.
- --8208260226 Corrected page to 820818 application for Amend 1 to License NPF-14.correcting date of UL issuance. CURTIS,N W Pennsylvania Power & Light Co 82/08/23. ip 14554 304 24X Fiche: 50-387,82/08/23,8208260221.
- 8208270427 Forwards proprietary "Lack of Consequences of Exceedance in High-Frequency Range & General Procedure for High-Frequency Cutoff," per witi 820712 itr. Rept withheld (ref 10CFR2 790) CURTIS.N W Pennsylvania Power & Light Co. 82/08/25 8CHWENCER.A Licensing Branch 2. 1p 14544 212 24X Fiche 50-387,82/08/25, 8208270427
- 8208300124 Advises that License Condition 288 re special low power testing & training satisfied by util 820615 submittal.Loss of ac power test endangers plant equipment & does not achieve NRC test objectives.Alternate testing proposed. CURTIS.N.W. Pennsylvania Power & Light Co 82/08/25. ScHWENCER Licensing Branch 2 2pp 14599 187 24X Ficher 50-387,82/08/25,8208300124. SCHWENCER, A.
- B208300139 Provides interim position re containment purge sys isolation valves prior to exceeding 5% full power Dreakers will be closed & de-energized Atmosphere to be maintained by qualified valves Position meets NOREO-0737, Item II E, 4 2, CURTIS.N.W. Pennsylvania Power & Light Co. 82/08/25, BCHWENCER, A, Licensing Branch 2 2pp 14599, 185, 24% Fiche 50-387, 82/08/25, B208300139
- 8208310078 Summarizes 820811 meeting w/NRC & Bechtel re small piping & equipment nozzle loadings, stress intensification factors for small pipe & penetration grouting & treatment of penetrations in stress analyses.
 KENYON, B. D. Pennsylvania Power & Light Co. 82/08/25. MARTIN, T. Region I. Office of Director. 7pp 14695-139. 24X
 Fiche, 50-387, 82/08/25, 8208310098.

- 9208310180 Advises of recheck/review of diesel generator bldg, reactor/control bldg (vertical model) & ESSM pumphouse Calculations do not contain errors Original design basis adequate Response satisfies conditions to review models by 820825 CURTIS,N W Pennsylvania Power & Light Co 92/08/25 SCHWENCER, A Licensing Branch 2 2ep 14693 112 24X Fiche 50-387, 82/08/25, 8208310180
- 8208310201 Informs that util will modify Startup Test Procedure 8T-28, "Shutdown from Eutside (fain Control Room," verifying that reactor can be scrammed 'MSIV can be closed from outside main control room CURTIB.N W Pennsylvania Power & Light Co 82/08/26 8CHWENCER, A Licensing Branch 2 1p 14693 159 24X Fiche 50-387.82/08/26, 8208210201

O Inspection reports. IE Bulletins & correspondence

- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8208050296 Forwards IE Safeguards Insp Rept 50-387/82-22 on 820421-25 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/07/16 CURTIS.N W Pennsylvania Power & Light Co 2pp 14211 185 24X Ficho 50-387, 82/07/16, 8208050296
- ---8208050300 IE Safeguards Insp Rept 50-387/82-22 on 820621-25 No noncompliance noted Major areas inspected locks, keys & combinations, physical barriers, vital areas, security power supply & detection aids Withheld (ref 100FR3 21)
 DUNLAP, J M, GODY, J M Region 1. Office of Director 82/07/08 ip 14211 187 24X Fiche 30-387, 82/07/16, 8208030296
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Voon Gradual Loss of Air Pressure " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance B2/07/20 Gonsolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 6204210397 IE Info Notice 62-24, "Water Leaking From U Hexafluoride Overpacks "Evc list enc! COBB.L! Division of Fuel Facilities, Materials & Safeguards 62/07/20 Consolidated Edison Co of New York 71gp 14357 27 24X Fiche 50-000,82/07/20,8204210397
- 8204210396 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Vaive Failures " Syc list enc] JORDANIE L. Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174-321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 IE Info Notice 82-28, "Hydragen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 118 24X Fiche 50-000.82/07/23.8204210401
- 6204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JCRDAN.E L Division of Engineering & Quality Assurance 62/07/23 Consolidated Edison Co of New York 127pp 14194-120 24X Fiche 50-000.82/07/23.8204210402
- 6208100094 Forwards IE Insp Rept 50-387/82-26 on 820706-09 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/07/23 CORTIS.N W Pennsylvania Power & Light Co 2pp 14297 338 24X Fiche 50-387.82/07/23.8208100094
- --8208100100 IE Insp Rept 50-387/82-26 on 820706-09 No noncompliance noted Major areas inspected overall startup program review. startup & hot functional test procedures & followup on previous insp findings FULLANI, B U., BETTENHAUSEN, L Division of Engineering & Technical Programs 82/07/22 Bpp 14297 340 24% Fiche 50-387,82/07/23,8208100094
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Cartain Westinghouse PWR Power Plants " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24X Fiche. 50-000. 82/07/26. 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDANIE, L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000,82/07/28.8204210405.

- 6208120047 Forwards IC Insp Rept 50-387/82-20 on 820514-18 No noncompliance noted MARTIN:TT Division of Engineering & Technical Programs 82/07/29 CURTIS,N W Pennsylvania Power & Light Co 2pp 14324 020 24x Fiche 50-387,82/07/29,8208120047
- --820B120054 IE Insp Rept 50-387/B2-20 on B20614-18 No noncompliance noted Major areas inspected emergency, abnormal alarm response & instrument surveillance procedures BLUMBERG, N., PULLANI, S., CAPHTON, D.L. Region i, Office of Director 82/07/14 19pp 14324 022 24X Fiche 50-387,82/07/29, 620B120047
- 8208120134 Forwards IE Insp Rept 50-387/82-24 on 820706-09 No noncompliance noted SMITM.0 H Division of Emergency Preparadness & Operational Support 82/07/29 CURTIS.N W Pennsylvania Fower & Light Co 2pp 14327 122 24X Fichs 50-387.82/07/29.8208120136
- --B20B12O14O IE Insp Rept 50-3B7/82-24 on B20706-07 No noncompliance noted Major areas inspected emergency preparedness program, selective exam of procedures & representative records, interviews w/personnel & observations by inspector SAKENAS.C., SHITH.R., CROCKER.H.W. Division of Emergency Preparedness & Operational Support 82/07/22 6pp 14327 124 24X Fiche 50-387.82/07/29.8208120136
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
 JORDAN.E L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000.82/08/05.8204210407
- 8208230180 Forwards IE Safeguards Insp Repts 50-387/82-21,70-2937/82-01 & 30-16036/82-01 on 820616-17 of activaties under Licenses CPPR-101.5NM-1878 & 37-06554-03, respectively No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/08/04 CURTIS.N W Pennsylvania Power & Light Co 2pp 14510 355 24x Fichs 50-387, 82/08/06,8208230180
- --8208230302 IE Bafeguards Insp Repts 50-387/82-01.70-2937/82-01 & 30-16036/82-01 on 820616-17 No noncompliance noted Major areas inspected facility organization & operation, shipping & receiving & storage & internal control RATTA:AD. GODY:AT Region 1. Office of Director 82/07/28 5pp [4510 357 24X Fiche 50-387, 82/08/04, 8208230180
- 8208230380 Forwards IE Insp Rept 50-387/82-28 on 820706-09 No noncompliance noted HARTIN:T T pivision of Engineering & Technical Programs B2/08/09 CURTES.N W Pennsylvania Power & Light Co 2pp 14508 237 24X Fiche 50-387: 822/08/09.8208230380
- ---8208230396 IE Insp Rept 50-387/B2-28 on B20706-09 No noncompliance noted Major areas inspected selective exams of procedures & representative records interviews w/personnel, observations & previously identified items MEYER, 0 NAPUDA, 0 CAPHTON, D L. Division of Engineering & Technical Programs 8 02/08/04 iipp 14508 239 24x Fiche 50-387, 62/08/09, B208230380
- 8208300254 Forwards IE Insp Repts 50-387/82-19 & 50-388/82-08 on 820616-0727 Np noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 82/08/13 KENYON.B. D Pennsylvania Power & Light Co 2pp 14678, 248 24X Fiche 50-387, 82/08/13, 8208300254
- --8208300258 IE Insp Repts 50-387/82-i9 & 50-388/82-08 on 820616-0727 No noncompliance noted Major areas inspected TMI items, preoperational testing, preoperational test results raview, builetins & circulars & plant startup RHOADB, 0 G, MCCANN.J F, NICHOLAS, H Division of Project & Resident Programs 82/08/12 48pp 14478 250 24X Fiche 50-387,82/08/13,8208300254
- 8208200195 Forwards Preservice Insp Relief Request 14 for exemption from ASME code requirement for volumetric exam of 100% of circumferential weld prior to initial startup List of welds to be scanned encl
 CURTISIN W Pennsylvania Power & Light Co 82/08/17 SCHWENCER, A Licensing Branch 2 10pp 14500 139 24X Fiche 50-387,82/08/17,8208200195
- 8208240151 Forwards updated preservice insp program info re SER Issue 19. Revision includes preservice exams performed subsequent to util 810519,0616 & 820823 submittals CURTISIN W Pennsulvania Power & Light Co 82/09/20 SCHMENCER.A Licensing Branch 2 21pp 14820:130 24X Fiche 50-387,82/08/20, 8208240151

- 8208300079 Ack receipt of \$20715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/80-17 & 50-388/80-11
 STARCSTECKI R Division of Project & Resident Programs 82/08/24
 KENYON B D Pennsylvania Power & Light Co 1p. 14596 132 24X
 Fichs 50-387.82/08/24.8208300079
- --9208300081 Responds to NRC 801203 ltr re violations noted in 1E Insp. Repts 50-387/80-17 & 50-388/80-11 Corrective actions review of records complete & in-record vault will be finished 90 days after fuel load CURTIS,N W Pennsylvania Power & Light Co 82/07/15 STARGSTECKI,R D3viston of Project & Resident Programs 2pp 14594 133 24% Fiche 50-387,82/08/24.8208300079
- 8208310319 Requests relief from augmented inservice inspraquirements of NUREG-0313 for welds identified in util 810915 ltr Util plans to perform induction heating stress improvements on utilds 8upporting documentation encl
 CURTIS.N W Pennsylvania Power & Light Co 82/08/26 SCHWENCER, A
 Licensing Branch 2 2pp 14492 180 24X Fiche 50-388, 82/08/26, 8208310319

S Reportable occurrences. LERs & related correspondence

- 8208050210 RD 50-387/82-01 on 820718, discovered unacceptable linear indication in A-11 weld on reactor recirculation sys riser fraciations detected by radiography KEISER.KW Pennsylvania Power & Light Co. 82/07/19 HAYNES,R C. Region I, Office of Director 2pp 14212 138, 24X Fichs 50-387,82/07/19,8208050210
- 6208020277 LER 82-002/01T-O·confirming 820721 telcon refriction anchers on various sys which will not support axial piping leads as designed KEIBER.H W Pennsylvania Power & Light Co 82/07/22 HAYNES.R C Region 1. Office of Director ip 14152 258 24X Fiche 50-387.82/07/22.8208020277
- 8208050493 Final deficiency mept me design deficiencies in location of vital equipment outside vital area Initially reported on B20715 Also reported per Fart 21 Details withheld (ref 10CFR73 21)
 KENYON B D Pennsylvania Power & Light Co 82/07/29, HAYNES, R C. Region 1, Defice of Director 2pp 14214 103, 24X Fiche 50-387, 82/07/29, 8208050493
- 82080&0143 Forwards LER 82-001/01T-0 KENYON.B D Pennsylvania Power & Light Co 82/08/02 HAYNES.R C Region 1. Office of Director 1p 14241 016 24X Fiche 50-387, 82/08/02, 82080&0143
- --8208060146 LER 82-001/OiT-0 on 820718, unacceptable linear indications found by radiograph of A-11 weld Cause not determined Welds repaired per approved repair program HITCHELL.D O Pennsylvania Power & Light Co 82/08/02. Rogion 1. Office of Director 1p 14241 017 24X Fiche 50-387, 82/08/02, 8208060149
- 8208050202 Final Part 21 rept re AMV Model 8700 back pressure steam isolation dampers Initially reported on 800506 All corrective action concerning wiring deficiencies completed Project cleared of 100FR21 requirement SLOAN.DE American Warming & Ventilating. Inc 82/08/02. Director's Office, Office of Inspection and Enforcement 1p. 54238 360 24X Fiche 50-387.82/08/02.8208060202
- 820810303B Interim deficiency rapt re improper field mounting of Agastat 7000/E7000 series relays Initially reported on 820702 investigation underway Relays will be reworked to ensure conformance. Also reported per Part 21 CORTIS:N W Pennsylvania Fower & Light Co 82/08/03 HAYNES, R. C. Region i, Office of Director 3pp 14276 258 24X Fiche: 50-387, 82/08/03, 8208100038
- 8208130045 Forwards LER 82-002/01T-0 KENYON,8 D Pennsylvania Fower & Light Co 82/08/04 HAYNES,R.C Region 1, Office of Director 1p 14335 073 24X Fiche 50-387,82/08/04,8208130045
- --B208130048 LER B2-002/0iT-O on B2072i, reviewers determined that pipe clamp anchors would not support axial loads as designed Caused by breakdown in transmittal of design into the field & design verification Shims added to ensure 4-point contact.

 MITCHELL D O. Fennsylvania Power & Light Co 82/08/04 Region 1. Office of Director ip. 14335 094. 24x Fichs.50-387.82/08/04, 8208130045.

- 8208230075 Final deficiency rept re error in backpressure calculations for main steam safety relief valve adjusting ring settings initially reported on 820714 GE corrected calculational error Also reported per Part 21 CURTIS.N W Pennsylvania Power & Light Co 82/08/13 HAYNES,R C Region 1, Office of Director Spp 14517, 141 24X Fiche 50-387, 82/08/13, 8208230075
- 8208300054 LER 82-003/01P-0 on 820818.error discovered in fire protection review rapt.Revision 1 & Tech Spec re mislabeled sprintler sys Initially reported on 82088 Condition reportable per License Condition 2 G (a)
 KEIBER.H W Pennsylvania Power & Light Co 82/08/19 HAYNES,R C Region 1. Office of Director ip 14598 307 24X
 Fiche 50-387.82/08/19.8208300054
- DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8208250305 Forwards "Final Rept. Independent Design Review, Susquehanna Steam Electric Station"
 LANDERS, D.F. Teledyne Engineering Services 82/05/06 SHOVLIN, R. J. Pennsylvania Power & Light Co. 2pp. 14537 001 24X
 Fiche 50-387, 82/05/04, 8208250305
- --8208250308 "Final Rept.Independent Design Review Busquehanne Bteam Electric Station " * Teledyne Engineering Bervices TR-5579-3 82/08/23 400pp 14537-003 24X Fiche 50-387.82/05/06.8208250305
- 8208030737 Requests proposed schedule for submitting program re adequacy of design margins of Mark I & II containment sys Response within 14 days requested TEDESCO.R L Assistant Director for Licensing, 82/07/08 CURTIS.N H Pennsylvania Power & Light Co 3pp 14195-353, 24X Fiche 50-387,82/07/08.6208030737
- 8208060366 Board Notification 82-70 notifies of differing prof opinion re sensitization of BMR stainless steel weldments.
 EISENHUT, D G Division of Licensing 82/07/20 PALLADINO, N J .
 GILINBKY, V . AMERINE. J Commissioners 4pp 14281 351 24 X
 Fich 90-387, 82/07/20, 8208060366
- 8208090343 Board Notification 82-78.notifies of allegations re-stress intensification factors & reconciliation of norsie loads as part of piping analysis & welder qualifications TEDESCO.RL Assistant Director for Licensing. 82/07/22. Atomic Safety and Licensing Appeal Fanel 5pp 14306,306 24X Fiche 50-387,82/07/22,8208090343
- --8203110591 Informs of items which have been ignored by site supervisors in analysis of small bore piping Items should be investigated during next audit ### Affiliation Unknown 82/05/03 NRC No Detailed Affiliation Oiven ip. 14306.311 24X Fiche 50-387.82/07/22.8208090343.
- 8208120326 Forwards Rydrologic Engineering Branch review of proposed UHS test plan, per util 820616 ltr Plan generally acceptable 8uggestions for improvement discussed. YOUNOBLOOD B J. Licensing Branch 1 82/07/22 CURTIS, N. W Parmsylvania Power t Light Co. 5pp 14332 261 24X Fiche 50-387.82/07/22,8208120326
- 8208180219 Forwards request for add1 info re emergency diesel engine air starting sys Procedure used to conduct diesel start test per Tech Spec 4 B. i 1 2 d 12 requirement should be provided YOUNGBLOOD. B. J. Licensing Branch 1 82/07/22, CURTIB. N. W. Pennsylvania Power & Light Co. 3pp 14370 350. 24% Fiche: 50-387, 82/07/22, 8208180219
- 8208070336 Advises of Board Notification 82-55 notifying of air pressure loads on drywell-wetwell vacuum breakers during gool swell following postulated LOGA EISENHUT, D.O. Division of Licensing. 82/07/23. PALLADINO, N.J., QILINEKY, V., AHEARNE, J. Commissioners 5pp 14306:272, 24X Fiche 50-387, 82/07/23, 8208070336.
- --8206140404 Board Notification 82-55 notifies of air pressure loads on drywell-wetwell vacuum breakers during pool swell following postulated LOGA
 TEDESCO.R.L. Assistant Director for Licensing. 82/06/10
 Atomic Bafety and Licensing Appeal Panel. 9pp. 14306:297, 24X
 Fichs: 50-387,82/07/23,8200070336.
- 8208020082 Describes steam bypass analysis to be conducted to determine max wetwell tem; for equipment qualification Confirmation of acceptability of analysis requested CURTIS.N W. Pennsylvania Power & Light Co. 82/07/27 SCHWENCER, A. Licensing Branch 2. 2pp 14144 100 24X Fiche: 50-387,82/07/27,82/0802082

- 8208040142 Forwards qualification repts for MSIV actuators & MSIV leatage control heater sqs CURTIS,N & Pennsylvania Power & Light Co 82/07/28 SCHWENGER, A Licensing Branch 2 11pp 14185 024 24X Fichs 50-387, 82/07/28, 8208040142
- --B208040166 "Apparent Test Results for Susquehanna I & 2 24-inch MBIV Actuator Dynamic Qualification Test " OLIVER, D.D., NIEH, C.T., ADAMS.T.E. Pannsylvania Power & Light Co ATR-DDD-8204 B2/07/20 110pp 14185 035 24X Fiche 50-387,82/07/28.8208040142
- --9208040190 "Dynamic Gualification Test Rept on MSIV Leakage Control Sys Heater " * American Environments Co STR-54282-1 82/06/21 172pp 14185 145 24X Fiche 50-387, 82/07/28, 8208040142
- 8208030204 Advises that Bechtel recheck of all calculations used in stick models for containment indicate models acceptable Response satisfies OL requirement to review containment model by 820730 CURTIS.N W Pennsylvania Power & Light Co 82/07/30 SCHMENCER, A Licensing Branch 2 ip 14159 337 24X Fiche 50-387, 82/07/30, 8208030204
- 8208060190 Submits info on spraypond Pierometer 2 high groundwater reading Pierometer 2 deletion will be included in next FSAR revision CURTIS, N W Pennsylvania Power & Light Co 82/08/03 SCHWENCER, A Licensing Branch 2 Spp 14239 035 24X Fiche 50-387, 82/08/03, 8208060190
- 8208060298 Forwards results of facility entrainment demonstration program developed to meet requirements of Special Condition C.Part C of NPDES Permit PA 0047325 CURTIS.N W Pennsylvania Power & Light Co 82/08/03 ECHMENCER.A Licensing Branch 2 ip 14239 302 24X Fiche 50-387,82/08/03,82/08/0298
- --B208060302 "Susquehanna Steam Electric Station 326(b) Entrainment Demonstration Program for NPDES Permit PA 0047325 Special Condition C.Part C "
 Pennsylvania Power & Light Co B2/07/31 51pp 14239 303 24X Fiche 50-387, 82/08/03,8208060298
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarires 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT. D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24% Fiche 50-000,82/08/09,8208090194
- 8208170248 Forwards results of vacuum breaker performance evaluation providing justification for plant operation beyond Mode 3 Draft NEDE-22178-P, "Mark II Containment Drywell-to-Wetwell Vacuum Breaker Models," withheld (ref 10CFR2 790) CURTIS.N W Pennsylvania Power & Light Co 82/08/13 SCHWENCER. A Licensing Branch 2 2pp 14349 345 24X Fiche 50-387,82/08/13.8208170248
- 8208270427 Forwards proprietary "Lack of Consequences of Exceedance in High-Frequency Range & General Procedure for High-Frequency Cutoff," per ucil 820712 let Rept withheld (ref 10CFR2 790). CURTIS.N W Pennsylvania Power & Light Co 82/08/25 BCHWENCER.A Licensing Branch 2 1p 14964 212 24X Fiche 50-387,82/08/25, 8208270427
- 820831007B Gummarises 82081i meeting w/NRC & Bechtel re small piping & equipment notate loadings, stress intensification factors for small pipe & penetration grouting & treatment of penetrations in stress analyses
 KENYON, B. D. Fennsylvania Power & Light Co. 82/08/23. MARTIN, T. Region 1. Defice of Director 7pp. 14673 137 24%
 Fichs 50-387, 82/08/25, 8208310098
- E NRC Bafaty Evaluation Report (SER), suppls & correspondence
- \$208190027 Forwards NUREG-0776, Suppl 3 to SER Rept has been placed in PDR.W/o enc!
 YOUNGELOOD, B J Licensing Branch 1. 82/07/26 CURTIS, N W Pennsylvania Power & Light Co 3pp 14506 357, 24X
 Fiche. 50-387, 82/07/26, 8208190027
- 8208030401 Responds to supplemental SER Item 3 10 1(3) re fatigue effects on NSSS equipment due to mafety relief valve loads Electrical & mechanical NSSS equipment analyzed for fatigue cycling All NSSS equipment will perform satisfactority CURTIS.N W Pennsylvania Power & Light Co 82/07/29, 8CHWENCER.A Licensing Branch 2 3pp 14154 013 24X FicherSO-387,82/07/29,8208030401

- 8208030455 Responds to request for results of reassessment of seaso;c & dynamic qualification of individual NSSS equipment per SER Item 3 10 3 Results of each assessment method on equipment items listed CURTIS,N W Pennsylvania Power & Light Co 82/07/29 SCHWENCER,A Licensing Branch 2 2pp 14155 292 24X Fiche 50-387,82/07/29, 8208030495
- 8208040193 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SUSQUEHANNA STEAM ELECTRIC STATION.UNITS 1 AND 2 Docket Nos 50-387 And 50-388 (Pennsylvania Power And Light Company) * Office of Nuclear Reactor Regulation, Director NUREG-0776 S03 82/07/31 173pp Available at NTIS \$6 50 14233 183 24x Fiche 50-387, 82/07/31, 8208040193
- 8208240151 Forwards updated preservice insp program info re SER Issue 19 Revision includes preservice exams performed subsequent to util 810519,0616 x 820523 submittals CURTIES N W Pennsylvania Power & Light Co 82/08/20 SCHWENKER, A Licensing Branch 2 21pp 14520 130 24X Fiche 50-387,82/08/20, 8208240151
- F Security, medical, emergency & fire protection plans
- 8208030078 Releases public version of revision to emergency plan implementing procedures manual FELTON. J H Division of Rules and Records 82/07/19 Document Hanagement Branch 1p 14199 001 24X Fiche 50-387,82/07/19, 20208/30078
- --B208030083 Forwards public version of Revision 2 to emergency planimplementing procedure.including Procedures EP-IP-001 resembly classification & EP-IP-002 resembly motification when the Procedure of Procedures and Pennsylvania Power & Light Co. B2/06/25 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director 2pp 14199 002 24X Fiche 50-387, 82/07/19, 8208030078
- --8208030086 Public version of Revision 2 to emergency plan implementing procedures manual, including Procedures EP-IP-001 re emergency classification & EP-IP-002 re emergency industrial motification and Pennsylvania Power & Light Co 82/06/28 644pp 14199 004 24% Fiche 50-387,82/07/19.8208030078
- O Adjudicatory correspondence
- 8208110153 Order rendering ARLB 820412 decision authorizing OL issuance effective Full power OL not yet authorized CHILKS J. Office of the Secretary of the Commission 82/08/09 2pp 14314 283 24% Fichs 50-387,82/08/09,8208110153
- 8208160426 Order directing parties to identify person presenting arguments at 820708 fearing in BethesdarMD Response requested no later than 820831 TOMPKINS, 8 A Atomic Safety and Licensing Appeal Panel 82/08/i3 Pennsylvania Power & Light Co 2pp 14348 360 24% Fiche 50-387, 82/08/13, 8208160426
- 8208230064 Advises that author will represent NRC at 820908 oral argument CUTCHIN,J M Hearing Dranck 4 82/08/18 TOMPKINS,B A Atomic Safety and Licensing Appeal Panel 1p 14517 221 24X Fiche 50-387,82/08/18,8208230064
- 8208240321 Petition for reconsideration of Commission 820809 order rendering ASLB initial decision effective Exceptions to decision requira resolution Commission order premature Certificate of Svc encl HALLIGAN, T J Citizens Against Nuclear Dangers 82/08/18 Commissioners 2pp 14521 001 24X Fiche 50-387,82/08/18,8208240321
- 8208240199 Order listing questions to be answered at 820908 oral argument
 SHOENAKER, C. J. Atomic Safety and Licensing Appeal Panel 82/08/20
 4pp 14519 303 24X Fiche; 50-387, 82/08/20, 8208240199
- 6208270374 Order advising parties to exchange affidavits supporting representations counsel intends to make at 820708 oral argument Info meeds to be on record Supplemental evidentiary hearings will be held on 820707-10 SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel, 82/08/24 Office of the Executive Legal Director 4pp 14565 129 24X Fiche. 50-387, 82/08/24, 8208270374
- 8208270440 Advises that JE Silberg will represent applicants at 820908 oral argument 8vt list and SILBERG, JE Shaw, Pittman, Potts & Trombridge SILBERG, JE, Pennsylvania Pomer & Light Co 82/08/24 THOMPKINS, BA Atomic Bafety and Licensing Appeal Panel 3pp 14565 340 24X Fichs 50-387, 82/08/24, 8208270460

- 8208270376 Order amending 820824 order to provide supplemental evidentiary hearing to be held on 820908 & 10. if hearing necessary
 - necessary SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 82/08/25 2pp 14564 235 24% Fiche 50-387,82/08/25,8208270376
- J Insurance & Indemnity information
- B208120105 Forwards Amend 1 to Indemnity Agreement B-90,per 820717
 request
 CURTIS,N W Pennsylvania Power & Light Co 82/08/09 EISENHUT,D 0
 Bivision of Licensing 3pp 14317 161 24X Fiche 50-387,82/08/09,
 8208120105
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list enc!
 JCRDAN,E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24%
 Fiche 50-000,82/07/16,8204210393
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Evc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/20 Graphidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000.82/07/20.8204210396
- 8204210397 IE info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguerds B2/07/20 Constitáated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- B20421039B lE Info Notice B2-26, "RCIC & HPCI Turbing Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fichs 50-000. B2/07/28,820421039B
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl URBANNE L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 113, 24X Fiche 30-000.82/07/23.8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JCRDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120, 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 6204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Bvc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche \$0-000,82/07/28,8204210405
- B204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Bvc list encl.
 JORDAN,E L. Division of Engineering & Quality Assurance 62/08/05
 Consolidated Edison Co of New York 117pp 14388*201 24X
 Fiche 50-000,82/08/05.8204210407
- 8208300254 Forwards IE Insp Repts 50-387/82-19 & 50-388/82-08 en 820616-0727 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 82/08/13 KENYON, B D Pennsylvanta Power & Light Ca 2pp 14678, 248 24X Fiche 50-387, 82/08/13, 8208300254
- --B208300258 IE Insp Repts 50-387/82-19 & 50-388/82-08 on 820616-0727 No noncompliance noted Major areas inspected TMI items, preoperational testing, preoperational test results review, bulletins & circulars & plant startup RHOABS.9 0 , NCCANN.J F , NICKOLAS, H Division of Project & Resident Programs 82/08/12 40pp 14678.250 24X Fichs 50-387,82/08/13,8208300254
- B20B240151 Forwards updated preservice insp program info re BER Issue 19 Revision includes preservice exams performed subsequent to util B10917,0616 & B20523 submittals.

 CVRTIS.N M. Pennsylvania Power & Light Co B2/08/20 SCHWENCER.A Licensing Branch 2 21pp. 14520 130. 24X Fiche 50-387,82/08/20,820840151

- 8208300079 Act receipt of 820715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/80-17 & 50-388/80-11 STAKOSTECKLR Division of Project & Resident Programs 82/08/24. KENYON, B D Pennsylvania Power & Light Co ip 14576 132 24X Fiche 50-387, 82/08/24, 8208300079
- --B2083000B1 Responds to NRC B01203 ltr re violations noted in IE Insp Repts 50-3B7/80-17 & 50-3B8/B0-11 Corrective actions review of records complets & in-record vault will be finished 90 days after fuel load CURTIS.N W Pennsylvania Power & Light Co B2/07/15 BYAROSTECKI.R Division of Project & Resident Programs 2pp 14596 133 24% Fiche 50-387, 82/08/24, 8208300079
- B208310319 Requests relief from augmented inservice insp requirements of NUREO-0313 for welds identified in util B10918 ltr Util plans to perform induction heating stress improvements on welds Supporting documentation encl CURTIS,N W Pennsylvania Power & Light Co B2/08/26 BCHWENCER,A. Licensing Branch 2 2pp 14692 180 24X Fiche 50-388,82/08/26,8208310319
- --8208310325 "Joint BWR Owners Oroup-EPRI Induction Heating Stress Improvement Research Projects," status rapt GIANNUZZI,A.J Electric Power Research Institute 81/06/26 45pp 14692 182 24X Fiche 50-388,82/08/26,8208310319
- --8208310328 "Induction Heating Stress Improvements "
 UMEMOTO, T Ishikawajima Harima Heavy Industries Co , Ltd.
 81/06/25. 68pp 14692 227. 24X Fiche 50-388,82/08/26,8208310319,
- --B208310333 "Induction Heating Stress Improvement Experience in Japan Corresponding to Susquehanna Steam Electric Station,Unit 2." * Ishikabajima - Harima Heavy Industries Co.,Ltd 5504-916-618,K253A B1/11/19. 37pp 14692 295 24X Fiche 50-388,82/08/26,8208310319
- --8208310337 "Rept of Process Evaluation for Induction Heating Stress Improvement at Susquehanna Steam Electric Station. Unit 2 "TBUSHIMA.5 Ishikawajima Harima Heavy Industries Co., Ltd 61KK110 ROO 81/05/27 81pp 14692:340. 24X Fichs 50-388,82/08/26,8208310319
- S Reportable occurrences, LERs & related correspondence
- 8208080493 Final deficiency rept re design deficiencies in location of vital equipment outside vital area Initially reported on 820715 Also reported per Part 21 Details withheld (ref 100FR73 21)

 KENYON, B D Pennsylvania Power & Light Co 82/07/29, HAYNES, R C Region 1, Office of Director 2pp 14214, 103 24X

 Fichs: 50-387, 82/07/29, 8208050493
- 8208060202 Final Part 21 rept re AWV Model 8700 back pressure steam isolation dampers Initially reported on 800306 All corrective action concerning wiring deficiencies completed Project cleared of 100FR21 requirement SLOAN.D E American Warming & Ventilating, Inc. 82/08/02 Director's Office of Inspection and Enforcement. ip 14238-360 24X Fiche 50-387.82/08/02,8208060202
- 820810003B Interim deficiency rept re improper field mounting of Agastat 7000/E7000 series relays Initially reported on 820702. Investigation underway Relays will be reworked to ensure conformance Also reported per Part 21.
 CURTIE,N W Pennsylvania Power & Light Co 82/08/03 HAYNES,R C Region i, Office of Director. 3pp 14276 258 24X Fiche 30-387,82/08/03,8208100038
- 8208230075 Final deficiency rept re error in backgressure calculations for main steam safety relief valve adjusting ring settings Initially reported on 920714 GE corrected calculational error Also reported per Part 21 CURTIS.N.W. Pennsylvania Power & Light Co. 82/08/13 HAYNES,R.C Region 1, Office of Director 5pp 14517 141 24% Fishe 50-387.82/08/13.8208230075
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 820B170320 Trip rept of 820504 site visit re radiological effluent Tech Specs t installation of radwaste mgt sys equipment.

 LEE, J Y Effluent Treatment Systems Branch 82/06/08 QAMMILL, W. R.

 Effluent Treatment Systems Branch 2pp. 14372, 006 24X

 Fiche 50-389, 82/06/08, 8208170320

- 8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl DIRCKS, N J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 OD1 24X Fiche 50-000.82/07/02.8207080064
- 8208030050 Consents to provide FERC w/access to documentation provided by util & required by FERC & PSC of FL to retain, as backup to util record retention sys Util could establish symbiotic relationship to alleviate recordkeeping burden HAASS,W P Quality Assurance Branch 82/07/13 UHRIO.R E Fluids Power & Light Co 2pp 14208 330 24X Fiche 50~000,82/07/13.
- 8208040104 Forwards draft technical rept of util response to 801222 generic itr "Control of Heavy Loads," for review & comment MIRACLIA-F. J Licensing Branch 3 82/07/20 UHRIGAR. Florida Power & Light Co 2pp 14227 301 24X Fiche 50-389.82/07/20,
- ---8208040109 "Control of Heavy Loads at Nuclear Power Plants, St Lucie Plant Unit 2,FL Power & Light Co." draft technical evaluation rept
 SHABER, C. R. E0%0, Inc. 82/05/31 NRC - No Detailed Affiliation
 Oiven 30pp 14229 303 24X Fiche 50-389,82/07/20,8208040104
- 8208040627 Forwards comments on util 820504 list of engineering & constitutes not expected to be complete at core load date Detailed reasoning for finding some dates unacceptable encl PURPLE.R A Assistant Director for Licensing 82/07/26 UHRIG.R E Florida Power & Light Co 9pp 14225 309 24% Fichs 50-389, 82/07/26. 8208040627
- 8208030468 Forwards response to base plate Plexibility action items noted in summary of 820525 meeting in Bethesda, ND UHRIO, RE Florida Power & Light Co 82/07/27 EISENHUT, D 0 Division of Licensing 9pp 14153 276 24X Fiche 50-389, 82/07/27,
- 8208050189 Notification of 820816-19 meetings w/util, #basco.C-E & State of FL in Bethesda, MD to discuss items to be placed in radiological effluent & administrative controls portions of Tach Specs NERSES.V Licensing Branch 3 82/07/27 MIRAGLIA.F J Licensi Branch 3 3pp 14242 121 24X Fiche 50-389.82/07/27.8208050189
- 3208060185 Forwards revised response to Question 410 48 re associated circuits Response will be incorporated into FBAR in future amens UHRIG. R.E. Florida Power & Light Co. 82/07/30 EISENHUT, D.G. Division of Licensing 22pp. 14238-326. 24% Fiche: 50-389, 82/07/30, B2080401B5
- 8208100044 Advises that future correspondence re engineering verification program will be sent directly from Engineering Verification Task Force UHRIO,R E Florida Power & Light Co 82/08/05 EIBENHUT.D 0 Division of Licensing 1p 14276 250 24% Fiche 50-389.82/08/05. Division of Licensing 8208100044
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submitted of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Sev list encl EISENHUT.D 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fichs.50-000.82/08/09, 82/08/90194.
- B20B180051 Forwards Revision 1 to Procedure EVP-ODI/SL-2, "Engineering Verification Program." dtd 820730 BLODGETT, TH Ebasco Services, Inc. (subs. of Enserch Corp.) B2/OB/13 EISENHUT, D. Q. Division of Licensing. 1p. 14379 261. 24X Fiche 50-389.82/08/13.8208180061
- --8208180065 Revision 1 to "Engineering Verification Program"
 4 Florida Power & Light Co 82/07/30, 13pp 14379:262 24X
 Fiche 50-389,82/08/13,8208180061
- 8208200003 Forwards minutes of engineering verification program 820812 206200003 Forwards minutes or engineering versitation program meeting in Windsor, CT BL000ETT.T H Ebasto Services. Inc (subs of Enserch Corp). B2/08/14 EISENHUT, D O. Division of Licensing 2pp 14392. 24X Fiche. 50-389.
- 8208260193 Informs that design of containment isolation actuation signal has been revised based on FSAR review Design change completed & fully implemented in field. URRIOR E Florida Power & Light Co. 82/08/19. EISENHUT, D. Q. Division of Licensing ip 14554:317 24X Fiche 50-389,82/08/19,8208260193

- 8208310265 Forwards Revision 3 to "Environ Qualification Rept & Ouldebook," for safety-related electrical equipment includes update of various component evaluation sheats, definition of plant sys & current generic industry info UHRIGAR E Florida Power & Light Co 82/08/30 EISENHUT, D G Division of Licensing 3pp 14684 001 24X Fiche 50-389,82/0 24X Fiche 50-389, 82/08/3-3
- -- 8208310266 Revision 3 to "Environ Qualification Rept & Guidebook," passety-related electrical equipment Insertion instructions encl enc: 4 Florida Power & Light Co 82/08/30 1,200pp 14684 004 24; Fiche 50-389,82/08/30,8208310265
- F Security, medical, emergency & fire protection plans
- 8207230343 Forwards "Fire Hazard Analysis Equipment & Cables by Fire Area," "Fire Hazard Analysis Cables W/Fire Area Routes" & "Evaluation of Fire Areas in Support of Exemption " #1/42 oversize drawings Aperture cards are in PDR UHRIG, R E Florida Power & Light Co 82/07/14 EISENHUT, D & Division of Licensing ip 13999 062 24X Fiche 50-389,82/07/14,8207230343
- --8207230345 "Fire Hazard Analysis Equipment & Cables by Fire Area"
 Ebasco Services: Inc (subs of Enserch Corp.) 82/04/10
 146pp 13979 063 24X Fithe 50-389,82/07/14,8207230343
- --8207230348 "Fire Hazard Analysis Cables W/Fire Area Routes # Ebasco Bervices, Inc. (subs. of Enserch Corp.) 82/06 133pp 13999 208 24X Fiche 50-389,82/07/14,8207230343 82/04/10
- --8207230349 "Evaluation of Fire Areas in Support of Exemption Requests to Section III-0 of App R to 10CFR50 " # Florida Power & Light Co 82/07/14 122pp 13999-341 Fiche 50-389.82/07/14.8207230343 122pp 13999-341 24x
- 8208040448 Releases public version of Lawnwood Medical Ctr disaster manual. FELTON.J M Division of Rules and Records 82/07/22 Docum Management Branch ip 14220 227 24X Fiche 50-389,82/07/22. 8208040448
- --B208040455 Forwards public version of Lawnwood Medical Ctr disaster manual.in response to concerns raised during 820408 telcon re emergency preparadness C-E ltr of agreement re support sycs during emergencies encl UHR10.R & Florida Power & Light Co 82/07/14 EISENHUT, D 9 Division of Licensing 4pp 14220 228 24% Fiche 50-389, 82/07/22,8208040448.
- --8208040459 Public version of disaster manual # Lawnwood Medical Center FL 81/06/20 20pp 14220 232 24% Fiche 50-389,82/07/22,8208040448
- 8208060185 Forwards revised response to Question 410 48 re associated circuits Response will be incorporated into FSAR in future unerouthRIO.R.E Florida Power & Light Co 82/07/30 EISENHUT.D 0 Division of Licensing 22pp 14238 326 24X Ficha 50-387,82/07/30,8208060185
- 6208110107 Transmits FEMA Interim finding re offsite emergency preparedness, based on draft plans submitted by State of FL & 820210-12 exercise Adequacy of alert & notification sys must be verified in accordance w/NUREO-0554/FEMA REP-1 KRIMM-R W Federal Emergency Management Agency 82/07/30 ORIMES, B Division of Emergency Preparedness 36pp 14316 24x Fiche 50-335.82/07/30.8208110107
- 82081A007i Forwards Revision & to physical security plan.per B20806 discussion Revision withheld (ref 100FR73 21 & Section 147 of Akomic Energy Act of 1954) UHRIG.R E., STEVENS.R.J Florida Power & Light Co 82/08/09 EI8ENHUT.D Q Division of Licensing 1p, 14342 070 24X Fiche-50-335,82/08/09.8208160071
- 8208160058 Forwards bases for using containment high range radiation monitor to estimate offsite doses during emergency in response to Div of Emergency Preparedness request UHRIG.R E Florida Power & Light Co 82/08/10 EISENHUT, D G Division of Licensing 18pp 14344 281 24X Fiche 50-335, 82/08/10, 8208160058.
- 8208190190 Forwards test objectives & results of fire stop test performed by SWRI UKRIO.R E Florida Fower & Light Co 82/08/13 EISENHUT.D 9 Division of Licensing. App 14386 305 24X Fiche: 50-389, 82/08/13.

- 8208300187 Forwards add1 info re emergency action levels.in response to NRC 820624 ltr UHRIG.R E Florida Power & Light Co 82/08/24 EISENHUT.D Q Division of Licensing 12pp 14996 001 24X Fiche 50-389.82/08/24, 8208300187
- x Utility Final Safety Analysis Report (FSAR) & amends
- 8208120019 Forwards Amend II to FBAR
 UHRIG,R E Florida Power % Light Co 82/08/02 EISENHUT,D G
 Division of Licensing 7pp 14320 001 24X Fiche 50-389,82/08/02,8208120019
- --8208120020 Amend 11 to FSAR
 4 Florida Power & Light Co 82/07/31 1350pp 14320 008 24X
 Fiche 50-389,82/08/02.8208120019
- 8208100312 Forwards Amend 12 to FSAR UHR[0,R E Florida Pawer & Light Co 82/08/09 EISENHUT,D G Division of Licensing 3pp 14278 253 24% Fiche 50-389,82/08/09, 8208100312
- --6208100316 Amend 12 to FSAR * Floride Power & Light Co 62/08/31 1,200pp 14248,256 24% Fithe 50-389,82/08/09.8208100312
- H Antitrust correspondence
- 8208170024 Forwards notice of receipt of add1 antitrust info re proposed numerahip transfer HIRAGLIA.F J Licensing Granch 3 82/08/02 UHRIG.R E Florida Power & Light Co 2pp 14373 325 24X Fiche 50-389,82/08/02, 8208170024
- --B208170026 Notice of receipt of add1 antitrust info re proposed add1 ownership participant/FL Power Agency MIRAGLIA/F J Licensing Branch 3 82/08/02 4pp 14373 327, 24% Fiche 30-389, 82/08/02.8208170024
- 8 Operating license stage documents & correspondence
- B208090014 SOCIDECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS BAINT LUCIE CASE STUDY Docket Nos 50-335 And 50-389 (Florida Power And Light Company)
 WEISIGER M L , PIJANKA K D Mountain West Research, Inc * Bocial Impact Research, Inc *FIN B-6268 NUREO/CR-2747 VIO 82/07/31
 Division of Health, Siting & Environment 303pp Available at NIIS 47 00 14303 114 24X Fiche 50-335,82/07/31,8208090014
- 8208190066 Notification of 820817 meeting w/util & Ebasco in Bethesda, MD to discuss emergency operating procedures NERSES.V Licensing Branch 3 82/08/05 MIRAGLIA,F J Licensing Branch 3 4pp 14507 044 24X Fiche 50-389,82/08/05,8208190066.
- G Inspection reports, IE Bulletins & correspondence
- B208030453 Forwards IC Insp Rept 50-389/82-31 on B20630-0702 No noncompliance noted DANCE, H C Region 2, Office of Director 82/07/15, UHRIG, R E Florida Power & Light Co 2pp 14155,274 24X Fiche 50-389,82/07/15,8208030453
- --E208030457 IE Insp Rept 50-387/82-31 on 820430-0702 No noncompliance noted Major areas inspected methods for evaluating plant emergency maint & operating procedures & review of preoperational test program & plant tour TAYLOR,P A , JAPE,F Division of Engineering & Technical Programs 52/07/14 3pp 14155 276 24K Fichs 50-389,82/07/15.8208030453
- B204210393 lE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list enc! JORDAN, E L. Division of Engineering & Quality Assurance B2/07/16 Consolidated Edison Co of New York B7pp. 14354 274 24X Fiche 50-000 82/07/14.8204210393
- 8208160220 Forwards IE Insp Repts 50-335/82-19 & 50-389/82-25 on 820614-18 No noncomplaince noted DANCE,H C Division of Project & Resident Programs 82/07/16 URRIGER E Florida Power & Light Co 2pp 14347.104, 24X Fiche: 50-335, 82/07/16: 8208160220
- --B20B160229 IE Insp Repts 50-335/82-19 & 50-389/82-25 on B20614-18. No noncompliance noted Major areas inspected backfit programs site organization & onsite design activities

 DEBBAGE: A G , WRIGHT.R W , UPRIGHT.C M Division of Engineering & Technical Programs B2/07/13 Spp 14347 106 24X
 Fiche 50-335.82/07/16/820B160220

- 8204210395 IE Info Notice Bi-26, Part 3. Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" 8 vr list encl JORDAN.E L Division of Engineering & Quality Assurance, B2/07/19 Hichigan, Univ of 112pp 14358 001 24% Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Evc list enc! JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Go of New York 71pp 14357, 276 24X Fiche 50-000.82/07/20.8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208140190 Forwards IE Insp Repts 50-333/82-24 & 50-399/82-30 on B20428-0701 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/22 UHRIO, R E Florida Power & Light Co 2pp 14342 324 24X Fichs 50-335, 82/07/22, 8208160190
- --8208160198 IE Bafety Insp Repts 50-335/82-24 & 50-389/82-30 on 820628-0701 No noncompliance noted Major areas inspected licensee action on previous insp findings, training & qualifications of contractor-supplied temporary GC inspectors & records. LENAHAN, J. J., CONLON.T. E. Division of Engineering & Tachnical Programs. 82/07/21 4pp. 14342-326. 24% Fiche.50-335.82/07/22, 8208160190
- 8208160378 Forwards IE Insp Rept 50-389/82-27 on B20622-25 No noncompliance noted DANCE, H C. Division of Project & Resident Programs 82/07/22 UHRIO,R E. Florida Power & Light Co 2pp 14349-052 24X Fiche 50-389,82/07/22,8208160378
- ---B208i60383 IE Insp Rept 50-389/82-27 on B20622-25 No noncompliance noted Major areas inspected preservice inspecteding of internals previous insp finding & IE bulletins CROMLEY, B R. ECONOMOS, N. Division of Engineering & Technical Programs B2/07/21 Bpp 14349 054 24X Fiche 50-389, 82/07/22, 8208i60378
- 6204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDANIE L. Division of Engineering & Quality Assurance Consolidated Edison Co of New York 122pp 14380.115 24X Fiche. 50-000. 62/07/23, 6204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " 8vc list encl JORDANIE L. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co of New York 127pp 14174-120 24X Fiche 50-000, 82/07/23, 8204210402
- 8208040A08 Notification of 820730 meeting w/util.BNL.C-E & EBASCO in New York.NY re IE Bulletin 79-02 & piping analysis open items.
- items.
 NERSES,V Licensing Branch 3 82/07/23 MIRAGLIA,F J, Licensing Branch 3 3pp 14225 294. 24X Fiche: 50-389.82/07/23.8208040408
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Hestinghouse PHR Power Plants " Svc list enci, JRRDAN,E L. Division of Engineering & Guality Assurance, 82/07/26 Consolidated Edison Co. of New York 12ipp 14357 013, 24X Fiche, 50-000, 82/07/26, 8204210403.
- 8208030617 Ack receipt of 820709 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-15 DANCE, H.C. Division of Project & Resident Programs 82/07/26. URRIG.R.E. Florida Power & Light Co
- --8208030631 Forwards IE Insp Repts 50-335/82-15 & 50-389/82-21 on 820411-0514 & notice of violation.

 DANCE, H C Division of Project & Resident Programs 82/06/11, UHR10, R E, Florida Fower & Light Co. 2pp 14162 220, 24X Fichs. 50-335, 82/07/26, 8208030617

- 8208160165 Provides final response to IE Bulletin 79-24, "Frozen Lines "Freeze protection of affected instrument taps & tubing will consist of installing fiberglass insulation on exposed surfaces UHRIGAR E Florida Power & Light Co 82/07/27 D'REILLY, J P Region 2. Office of Director Spp 14345 046 24X Fiche 50-397, 82/07/27, 8208160165
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28 Consolitated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208160334 Ack receipt of 820722 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-789/82-23 LENIB.R C Division of Project & Resident Programs 82/08/02 UNRIG.R E Florida Power & Light Co (p 14348 060 24X Fichs 90-389, 82/08/02, 9208160334
- --0200160343 Responds to NRC 020629 ltr reviolations nated in IE Insp. Rept 50-0097/02-23 Corrective actions draft site quality procedure prepared refire protection systauthining GA controls

 UNRIGHT E Florida Power & Light Co. 82/07/22 O'REILLY, J.P. Region 2, Office of Director 2pp. 14348-061 24X
 Fichs 50-709, 82/08/02, 8200160334
- --B208160336 Forwards IE Insp Rept 50-389/82-23 on 820525-28 % notice of deviation LEWIS R C Division of Project & Resident Programs 82/06/25. UHRIG R E Florida Power & Light Co 2pp 14348 063 24X Fiche 50-387, 82/08/02, 8208160334
- --8208160348 Notice of deviation from insp on 820525-28 * Division of Project & Resident Programs 82/06/25 ip 14348 065 24% Fiche 50-387,82/08/02,8208160334
- --9200160337 IE Insp Rept 50-389/82-23 on 820525-28 Nencompliance noted failure to implement QA requirements fully MILLER, W.H. CONLON, T.C. Division of Project & Resident Programs 82/06/18 3pp 14948 066 24X Fiche 30-389, 82/08/02, 8208160334
- 02042(0407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement" Svc list encl
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co. of New York 117pp 14388 201 24X
 Fiche 50-000, 92/08/05, 8204210407
- R Periodic operating reports & related correspondence
- 8208030276 Forwards weekly status summary of Joint Ebasco & G-E engineering varification task force for 820719-23 BLODGETT Y H Ebasco Sarvices, Inc (subs of Enserch Corp) 82/07/28 EISENFUTTO D O(vision of Licensing 4pp 14156 243 24X Fithe, 50-389, 82/07/28, 8208030296
- 8208030181 Forwards weekly status summary of joint Ebasco & C-E task force for 820726-30 GLODGETT TH Ebasco Services, Inc (subs of Enserch Corp) 82/07/30 EISENHUT.D 0 Division of Licensing 4pp 14160 171 24X Fiche 50-389,82/07/30,8208030181
- 8208120061 Forwards weekly status summary of Joint Ebasco & C-E Task Force for 820802-06 BLODGETT, T H Ebasco Gervices, Inc (subs of Enserch Corp.) 82/08/06 EISENHUT.D Q Division of Licensing 4pp 14324 049 24X Fiche, 80-389, 82/08/06.8208120061
- 6208170173 Forwards weekly status summary of Joint Ebasco & C-E Task
 Force for 620809-13 Romaining design input received Revision
 1 to program Procedure EVP-001/EL-2 issued
 8L000ETT.T H Ebasco Services, Inc. (subs. of Enserch Corp.)
 62/08/13 EISENHUT.D Q Division of Lirensing App. 14367:042
 24% Fiche 50-389, 62/08/13.8208170173
- 8208200085 Forwards const/startup monthly status rept for Jul 1982
 Farget fuel load date is 821028
 UHnib,R E Florida Fower & Light Co. 82/08/16 EISENHUT,D G
 Division of Licensing 2pp 14393 045 24X Fiche 50-389,82/08/16,8208200085

- 8208250111 Forwards weekly status summary of Joint Ebasco & C-E Tail Force engineering verification program for 820816-20 BLODGETTY H Ebasco Services, Inc. (subs. of Enserch Corp.) 82/08/20 EISENNUT. De Division of Licensing App. 14541 298 24X Fiche 50-389,82/08/20,6208250111
- 8208310209 Forwards Joint Ebasco Svcs Inc & C-E task force engineering verification program weakly status summary for 820823-27 BLODGETITH Ebasco Services, Inc (subs of Enserch Corp) 82/08/27 EIGENHUT. 0 Division of Licensing 4pp 14693 153 24X Fiche 50-389,82/08/27,8208310209
- 8 Reportable occurrences, LERs & related correspondence
- 8208030332 Final Deficiency Rept 82-012 re bourdon tubes not rated for currect pressure initially reported on 820623 Bourdon pressure tubes will be replaced & tested to correct man pressure tubes will be replaced & tested to correct man pressure prior to initial core load & startup UHRIG.R E Florida Power & Light Co 82/07/22 0'REJLLY.J P Region 2. Office of Director 2pp 14197 068 24X Fiche 50-389, 82/07/22,8208030332
- 9208030429 Final deficiency rept re incorrect body bonnet buits on valves shipped by Pacific Valve Initially reported on 820417 Currect bolts furnished by vendor Also reportable per Part 21 UNRIO.R & Florida Power & Light Co 82/07/22 O'REILLY, J.P. Region 2. Office of Director 3pp 14154 016 24% Fiche 50-389, 82/07/22,8208030429
- 8208030454 Interim deficiency rept re malfunctioning selector switches In(tially reported on 820623 Investigation continuing Final rept expected by 820823 UHRIG.R E Florida Power? Light Co 82/07/82 O'REILLY, J P Region 2, Office of Director ip 14155 291 24X Fiche 50-389,82/07/22,8208030454
- 8208030638 Interim deficiency rept re installation of rigid conduit where flexible conduit required initially reported on 820623 Froblem still under review Final rept will be submitted by 820823 UHRIO.R E Florida Pawer X Light Co 82/07/22 O'REILLY, J P Region 2, Office of Director is 14162 231 24X Fiche 50-389.82/07/22.8208030638
- 8208090270 Final deficiency rept re failure of charging pump & bypass valve control circuitty initially reported on 820402 Charging pump logics revised to provide automatic & manual pump protection modes UKRIG.R E Florida Power & Light Co 82/07/30 O'REILLY, J F Region 2, Office of Director 3pp 14270 313 24X Fiche 50-389, 82/07/30,8208090270
- 8208090205 Interim deficiency rept re failure of reactor shutdown cooling bypass valves to respond to command signals initially reported on 820630 Final ropt will be submitted by 821008 UHRTO.R E Florida Power & Light Co 82/08/02 O'REILLY, J P Region 2, Office of Director 1p 14272 001 24X Fiche 50-389, 82/08/02, 8208090205
- 8208270119 Final deficiency rept re contacts not reversing position upon operation of switches Initially reported on 820623 Switches returned to vendor for rechecking Portinent documentation maintained at site Not reportable per 10CFRSO. UMRIOR E Florida Power & Light Co 82/08/16 0'REILLY, J P Region 2, Office of Director 2pp 14543 353 24% Fiche 50-389, 82/08/16, 8208270119
- 8208270306 Final deficiency rept re failure of instrument inverters initially reported on 820322 Investigation by Solidstate Controls, Inc found chake & inductor needed tuning to inverter thermal stress requirement Components redesigned, UHRIGAR E Florida Power & Light Co 82/08/16 O'REILLY, J P Region 2. Office of Director Esp (4564 194 24% Fiche. 50-289, 82/08/16, 8208270306
- ROCKET 50-390 WATTS BAR NUCLEAR PLANT. UNIT 1

 A Application/construction stage documents & correspondence
- 8207080054 Generic ltr to all licensees of operating plants, applicants for DL & halders of CP re Commission approved charter for CRGR. Svt list encl
 BIRCKG.W.J. Office of the Executive Director for Operations,
 82/07/02 Consolidated Edison Go of New York 93pp 14194 001
 24X Fiche 50-000, 82/07/02, 8207080064

- 8208020222 Forwards proposed mods to draft radiological effluent Tech Specs Meeting to discuss submittal requested on 820824 HILLS.t. H. Tennessee Valley Authority 82/07/26 ADENBAM, E Licensing Branch 4 68pp 14151 151 24X Fiche 50-390,82/07/26, game202022
- 8208060343 Requests addither places parts monitoring eys Results of ORNL review of 820225 submittel enci ADENSAM, E 0 Licensing Branch 4 82/07/30 PARRIS, H 0 Tempessee Valley Authority 7pp 14281 271 24X Fiche 50-390, 82/07/30, 8208060343
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter i requirements & provides alternatives to requirements Svc list encl EISENHUT.D G Division of Licensing 82/08/09 Consolidated Editor Co of New York ip 14396 332 24X Fiche 50-000,82/08/09,8208090194
- 8208200198 Forwards revised responses to NUREG-0737, Items II B 1, II B 2, II F 1 & II F 2 & Westinghouse application for withholding proprietary summary rept "Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring "MILLS.L M Tennessee Valley Authority 82/08/12 ADENBAM.E Licensing Branch 4 54pp 14399 196 24X Fiche 50-390, 82/08/12, 8208200198
- 8208260318 Notification of 820825 meeting w/Duke Power Co, SC Electric & Oas Co & TVA in Bethesda, MD to review SER for Model D steam generator mods KANE, MF F Licensing Branch 1 82/08/16 YOUNGBLOOD, B Licensing Branch 1 8p 14576 112 24X Fiche 50-000,82/08/16,8208260318
- 8208300125 Advises that schedule for completion of evaluation for control of heavy loads recalculated Info to be provided by 830625
 MILLS.L M Tennessee Valley Authority 82/08/25 ADENBAM.E Licensing Branch 4 ip 14599 214 24X Fiche 50-390.82/08/25, 8208300125
- F Security, medical, emergency & fire protection plans
- 820809007! Forwards revision to physical security plan Revision withheld (ref 10CFR73 21)
 KAMER.D 8 Tennessee Valley Authority 82/07/27 ADENBAM, E A
 Licensing Branch 4 1p 14269 317 24X Fiche 50-390, 82/07/29, 8208090071
- 8208160442 Forwards physical security plan evaluation rept & proposed license condition Encls withhold (ref t0CFR2 790) MCCORMLE.0 W Power Reactor Bafeguards Licensing Branch 82/07/29 8ERNARD.H Standardization & Special Projects Branch 1p 14348 219 24% Fichs 50-390,82/07/29,8208140442

[Financial information

- 820B100C02 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr ending 810630 & "1981 Power Program Summary," for fiscal yr ending 810930, per Section 50 71(b) of 10CFR50 M3LL6.L M Tennesses Valley Authority 82/08/06 DENTON, H R. Office of Nuclear Reactor Regulation, Director 118pp 14294 024, 24X Fiche 30-000,82/08/04,8208100002
- 8208270457 Forwards financial statements for FYBI, power quarterly rept & internal cash flow projection MICLB:L M Tennessee Valley Authority 82/08/23, SALTZMAN, J Assistant Director for State & Licensee Relations 48pp 14566.135 24x Fiche 50-000,82/08/23,8208270457
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180072 Summarizes ACRS 258th meeting on 820812-14 re review of util application for OL OL issuance recommended subj to satisfactory resolution of issus of GA, cement mortar lining thydrogen ignition eys.

 SHEWHON: P ACRS Advisory Committee on Reactor Safeguards 82/03/16 PALLADINO, N. U. Commissioners 3pp 14507 321. 24X Fiche: 50-370, 82/08/16, 8207180072
- O Inspection reports, IE Bulletins & correspondence
- 8208030416 Forwards IE Insp Repts 50-390/82-22 & 50-391/82-18 on 820521-0620 No noncompliance noted LONG, F J Division of Project & Resident Programs 82/07/08, PARRIS.H G Tennesses Vallay Authority, 2pp 14154:172, 241 Fichs 50-390, 82/07/08, 8208030416

- --8208030425 IE Insp Repts 50-390/82-22 & 50-391/82-18 on 820521-0620 No noncompliance noted Major areas inspected design changes & mods.comparison of as-built plant to FSAR description. Licensee event followup & followup on regional requests MCDONALD.J A. HEATHERLY.T L. GUICK.D R. Division of Project & Resident Programs 82/07/08 5pp 14154 174 24X Fiche 50-390,82/07/08 8208030416
- 8204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 92/07/16
 Consolidated Edison Co of New York 87pg 14356.274 24X
 Fiche 50-000.82/07/16,8204210393
- 8304210395 IE Info Notice Bi-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl URDAN, E L Division of Engineering & Guality Assurance B2/07/19. Hichigan, Univ of 112pp 14358 001 24% Fiche 50-000, 82/07/19. B204210395
- 8208160380 Forwards IE insp Repts 50-390/82-23 & 50-391/82-19 on 820629-0702 No noncompliance noted VERRELLI, D.M. Division of Project & Resident Programs 82/07/19, PARRIB, H.G. Tennessee Valley Authority 2pp. 14249 079 24X Fiche 50-390, 82/07/19, 8200160380
- --B208160387 IE Insp Rept 80-390/82-23 & 50-391/82-19 on 820629-0702 No noncompliance noted Major areas inspected licensee action on previous insp findings & followup on licensee identified items
 OIBBONS.T.D., CONLON.T.E. Division of Engineering & Technical Programs 82/07/15 3pp 14349 OB1 24X Fiche 50-390,82/07/19,8208160380
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure" Svc list encl
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20,
 Consolidated Edison Co. of New York 112pp 14391 001, 24X
 Fichs 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluorida Overpacks " Svc list encl CDBB,L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York, 7ipp 14357 276, 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Cherk Valve Failures " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112ep 14194.321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS," Evc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 62/07/23, Consolidated Edison Co. of New York 122pp 14380-115 24X Fichs 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Red Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 62/07/23 Consolidated Edison Co of New York 127pp. 14194 120, 24X Fiche 50-000.82/07/23.8204210402
- 8204210403 TE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance G2/07/26, Consolidated Edison Co of New York 121pp. 14357:013 24X Fiche. 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Fool " Svc list encl URDAN, E L. Division of Engineering & Quality Assurance 82/07/28, Consolidated Edison Co of New York, 122pp 14357 146, 24X Fichs 50-000 82/07/28,8204210405
- 8208030466 Ack receipt of 820713 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-390/82-26 & 30-391/82-20 VERRELLI,D M Division of Project & Resident Progrems 82/07/28 PARTS.H 0 Tennssee Valley Authority. 1p 14154 064, 24X Fiche. 50-390. 82/07/28. 8208030464
- --B208030473 Responds to NRC 1tr re violations noted in IE Insp Repts 50-370/B2-26 & 30-391/B2-20 Corrective actions addiclarification & further revision for upper head injection scope will be provided by B2(O3) DOMER. J A Tempessee Valley Authority, B2/07/13 O'REILLY, J P. Region 2. Office of Director 1p 14134 065, 24X Fiche 50-390, 82/07/28, 8208030466.

- 8208030480 Ack receipt of 820715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-03 & 50-391/82-03
 VERRELLI.D M Division of Project & Resident Programs 82/07/28 PARRIS.H G Tennessee Valley Authority Ip 14154 066 24X Fiche 50-390, 82/07/28, 8208030480
- --8208030492 Responds to NRC 820314 ltr re violations noted in IE Insp Repts 50-390/82-03 & 50-391/82-03 Corrective actions preoperational test manual will be implemented by 820801 MILLS.L M Tennessee Valley Authority 82/07/15 O'REJLLY, J P Region 2. Office of Director 1p 14154 067 24x Fiche 50-390,82/07/28,8208030408
- 8208i60144 Responds to IE Bulletin 81-02 Suppl 1, "Failure of Oate Tupo Valves to Close Against Differentia! Pressure " Util anticipates submittal of final rept by 821028 upon receipt of revised drawings of field change notices KAMMER.D S Tennessee Valley Authority 82/07/29 O'REILLY, J P Region 2, Office of Director | p | 4345 123 24% Fiche 50-000,82/07/29.8208160144
- 8208030202 Forwards info re preservice insp program per NRC 820122 request covering Questions 121 21 & 23 KAMMER.D S Tennessee Valley Authority 82/07/30 ADENSAM.E Licensing Branch 4 Spp 14158 252 24X Fiche 50-390,82/07/30,8208030202
- 8204210407 IE lnfo Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000.82/08/05.8204210407
- 8208160337 Ack receipt of 820720 ltr informing NRC of steps taken to correct violations noted in IE Imsp Repts 50-390/81-19 & 50-391/81-19 WERRELLI.D M Division of Project & Resident Programs 82/08/09 PARRIS.H G Tennessee Valley Authority ip 14349 049 24X Fiche 50-370, 82/08/09, 8208160337
- --8208160346 Responds to NRC 811008 ltr re violations noted in IE Insp Repts 50-370/81-19 & 50-391/81-19 Corrective actions due to general review & upgrading of GC procedures program, insp of locking devices will be issued by 820/28 MILLS.L M Tennessee Valley Auchority 82/07/20 O'REILLY, J P. Region 2. Office of Director ip 14349 050 24x Fiche 50-390,82/08/09,8208160337
- --8208160352 Responds to NRC 811008 ltr re violations noted in IL lnsp Repts 50-391/81-19 & 50-391/81-19 Reytsion of Procedure HBNP-9GP-1 42 or installation of locking devices incomplete Next rept expected by 820630 MILLS.L M Tennessee Valley Authority 82/04/12 O'REILLY, J P Region 2, Office of Director 1p 14349 051 24x Fiche 50-390,82/08/09,8208160337
- S Reportable occurrences, LERs & related correspondence
- 8208020226 Final deficiency rept for Sequeyah, second interim rept for Watts Bar & fifth for Bellefonte, Hartsville, Phipps Bend & Yellow Creek re inconsistent establishment of insp program Next rept for Watts Bar & Bellefonte expected 830103 MILLS.L M Tennessee Valley Authority 82/07/20 D'REILLY, J P Region 2, Office of Director App 14152 344 24X Fiche 50-000, 82/07/20, 8208020226
- 8208020077 Third interim deficiency rept re failure of Limitarque motor operators during valve closure Initially reported on 820126 Westinghouse & Limitorque continuing investigation Next rept expected by 821021 Also reportable per Part 21 MILLS, L. H. Tennessee Valley Authority 82/07/21 O'REILLY, J. P. Region 2, Office of Director ip 14144-105 24X Fiche 50-390, 82/07/21, 8208020077
- 8208020161 Third interim deficiency rept re cable separation in essential raw cooling water intake pumping station Initially reported on 811204 One-hour rated fire barrier protection added Next rept expected by 821122 MILLS, L. M. Tennessee Valley Authority 82/07/21 0'REILLY, J. P. Region 2, Office of Director, 2pp 14145 108 24X Fiche 50-390, 82/07/21,820802016!
- 8208020199 First interim deficiency mept me spacing requirements on saismic pipe supports not in compliance w/criteria Initially reported on 820622 Preliminary changes to 47A053 series drawing notes initiated Next mept expected 821208 MILLS.L M Tennessee Valley Authority 82/07/22 D'REILLY.J P Region 2, Office of Director 2pp 14141 005 24X Fiche 50-390, 82/07/22, 8208020199

- 8208020242 Eighth interim deficiency rept re failure of safety-related Westinghouse gate valves Initially reported on 801031 Final rept will be provided upon receipt of revised drawings from Mestinghouse Also reported per Part 21 MILLS.L M Tennessee Valley Authority 82/07/22 0'REILLY.JP Region 2. Office of Director 1p 14152 057 24x Fiche 30-390.82/07/22.8208020242
- 8208020108 First interim deficiency rept re tornado depressurization go auxiliary bldg Initially reported on 820623 Depressurization calculation revised to determine expected loading on interior wall Next rept by 621116 MILLS, L M Tennessee Valley Authority 82/07/23 O'REILLY, J P Region 2, Office of Director 2pp 14142 115 24X Fiche 50-340, 82/07/23, 8208020108
- 8208030249 Fifth interim deficiency rept re unconservative loads on pipe support design mods Initially reported on 801217 Design reviews for both units will be completed by 821231 & 830430, respectively Addi (nfo will be provided by 830618 MILLS.L.H. Tennessee Valley Authority 82/07/27 0'/REILLY, J P Region 2, Office of Director 2pp 14158 211 24X Fiche 50-390.82/07/27.8208030249
- 8208030161 First interim deficiency rept re alternate analysis prograa breakdown Initially reported on 820628 Complete reverification of alternate analyses will be performed Next rept to be submitted by 821109 MILLS.L M Tennessee Valley Authority 82/07/28 O'REILLY.J P Region 2. Office of Director Epp 14160 116 24X Fiche 50-390.82/07/28.8208030161
- 8208050420 Ninth interim deficiency rapt re installed anchor bolts not in accordance w/spacing specs Initially reported on 810331 Design of enginerad support base plates w/self-drilling expansion shall anchor spacings being reviewed MILLS,L H Tennessee Valley Authority 82/07/28 D'REILLY.JP Region 2. Office of Director 1p 14217 161 24x Fiche 50-390,82/07/28,8208050420
- 8208050347 Fifth interim deficiency rept re insufficient documentation for protective devices initially reported on 820313 Util corrected & documented 90 protective devices & identified 12 which cannot be completed Next rept expected by 821105 HILLS, L. H. Tennesses Valley Authority 82/07/30 D'REILLY, J.P. Region 2. Office of Director ip 14219 333 24X Fiche 50-390, 82/07/30, 8208050347
- 8208090057 Second interim deficiency rept re containment ponetration protection Initially reported on 811207 Penetrations being re-evaluated to determine adequacy of long-time overload protection Next rept will be submitted by 821115 MILLS, L. H. Tennesses Valley Authority 82/07/30 O'REILLY, J.P. Region 2, Office of Director App 14269, 318 24X Fiche 50-390, 82/07/30, 8208090057
- 8208120243 Fourth interim deficiency rept re environ qualification of electrical equipment initially reported on 810727 Components identified as potentially deficient listed on encl Table I Next rept expected by 830225 MILLS. I.M. Tennesses Valley Authority 82/08/03 O'REILLY, J.P. Region 2, Office of Director 33pp 14326, 288 24X Fichs 50-390, 82/08/03, 8208120243
- 8208120161 Third interim deficiency rept re excessive movement of containment penetration bellows Initially reported on 811204 Investigation continuing Next rept expected by 821127 HILLSIL H. Tennessee Valley Authority 82/08/04 O'REILLY, J. P. Region 2, Office of Director ip 14319 277, 24% Fiche 50-390,62/08/04,6208120161
- 8208120102 Sixth interim deficiency rept re retrievable info used in piping analysis Initially reported on 810316 Engineering procedure will be written to define & control use & maint by sys engineers Addi Info will be provided by 830222 MILLS, L M Tennessee Valley Authority 82/08/05 O'REILLY, J P. Region 2, Office of Director, Ip 14319.160. 24X Fiche 50-390,82/08/05.8208120102
- 8208120187 Third interim deficiency rept re HVAC register inoperability Initially reported on 820125 Field-Pabricated balancing devices to replace register Investigation continuing Next rept will be submitted by 820908 MILLS, L M Tennessee Valley Authority 82/08/05 D'REILLY, J P. Region 2, Office of Director ip 14323 276 24X Ficher 50-390, 82/08/05,8208120157
- 8208120306 Third interim deficiency rept rs improper handling & review of engineering change notices Initially reported on 811215 Review of sample notices continuing Next rept will be treasmitted by 830119 MILLS, L M Tennessee Vailey Authority 82/08/05 D'RETLLY, J P Region 2, Office of Director 7pp 14325, 006 24X Fiche 50-000, 82/08/05, 8208120306

- 8208130203 Second interim deficiency rept re Ameron coment mortar lining Initially reported on 820621 Listed corrective actions completed by 820701 w/exception of surface cracks Also reported per Part 21 MILLS, L.M. Tennessee Valley Authority 82/08/06 D'REILLY, J. P Region 2. Defice of Director 4pp 14339 074 24% Fiche 50-370, 82/08/06, 8208130203
- 8208130169 First interim deficiency rept re unistrut clamps loaded in egre than one direction Initially reported on 820708 ASME Section III. Subsection NF 3262 4 indicates all clamps qualified except for 3-inch piping Next rept by 821222 MILLS,L.M Tennessee Valley Authority 82/08/09 0'REILLY, J P Region 2. Office of Director 2pp 14339 022 24X Fiche 50-390,82/08/09,8208130169
- B208530266 Third interim deficiency rept re improper design of HVAC genetrations in containment Initially reported on 811224 Viil rerevaluating nonprocess penetrations using correct load definitions Next rept expected by B21213 MILLS.L M Tennessee Valley Authority 82/08/09 O'REILLY.J P Region 2. Office of Director ip 14333 051 24X Fiche 50-390.82/08/09.8208130266
- 8208160261 Sixth interim deficiency rept re improper weld attachment of shear luge Initially reported on BO1030 Installation of lugs in MYAG chilled water sys 31 in progress Next rept expected by 621025 MILLS,L M Tennessee Valley Authority 82/08/10 O'REILLY,J P Region 2, Office of Director 2pp 14346 361 24X Fiche 90-390.82/08/10.8208140261
- 8208160132 First interim deficiency rept re post-accident readings from containment sump level transmitters Initially reported on 820708 Util reviewing change of capillary fill fluid from water to stificon oil Also reportable per Part 21 MCLEGL M Tennessee Valley Authority 82/08/11 0'REILLY, J P Region 2, Office of Director 2pp 14345 228 24X Fiche 30-370, 82/08/11, 8208160132.
- 8208160477 Seventh interim deficiency rept re improper classification of essential raw cooling water sys piping & components Initially reported on 810324 Evaluation of contract files continuing. Next rept expected by 821019 MILLS.L. M. Temmessee Valley Authority 82/08/11 O'REILLY, J. P. Region 2, Office of Director 3pp 14348, 214 24X Fiche 50-390, 82/08/11, 8208160477
- 8208200014 Second interim deficiency rept re component cooling sys failure to meet pipe support lug criteria Initially reported on 820807 Effects of oversized lugs under review Next rept by 821020 MILLS.L M Tennesses Valley Authority 82/08/12 0'REILLY, J P. Region 2, Office of Director 2pp 14392 244 24X Fiche 30-390,82/08/12.8208200014
- 8208200038 Fourth interim deficiency rept re incorrect modeling of feedwater piging flow control valves 3-236, 237, 242 & 245 Initially reported on BildOF Piping support designs will be modified to qualify piping & equipment Next rept by Billify, HiLLS.L M Tennessee Valley Authority 82/08/12, 0'REILLY, J P. Region 2, Office of Director 2pp 14392 175 24X Fiche 50-390, 82/08/12,8208200038
- 8208200105 First interim deficiency rept re disminilarity of info for frequency criteria for piping supports. Initially reported on 820713 Investigation continuing Next rept expected by 821004 KILLS.L M Tennessee Valley Authority 82/08/12 O'REILLY.J P Region 2. Office of Director 2pp 14393-259 24X Fiche 50-390.82/08/12.6208200105
- 8208270283 Ninth interim deficiency rept re steel containment penetration assemblies initially reported on 801217 All affected piging evaluated & reamalyzed Ouidance will be growided in checklist Final rept expected by 821117 HELLS, L. H. Tennesses Valley Authority 82/08/16 D'REILLY, J. P. Region 2. Office of Director 2p 14564 159 24X Ficher 50-390, 82/08/16, 8208270283
- 8208270128 Fourth interim deficiency rept re foam seals in mechanical pipe eleaves. Initially reported on 811204 Rept corrects inaccuracies stated in 820414 final rept. Design std will be developed to give sleave designers guidance MILLS. L. K. Tennesses Valley Authority 82/08/18 0'RETLLY, J. P. Region 2, Office of Director 2pp 14563; 316 24X Fiche 70-390, 82/08/18, 8208270128.
- 8208270341 Final deficiency rept re pipe supports jeopardizing insulation during thermal movement Initially reported on 820408. Typical support drawings ECN 3341 revised w/note "not to be used w/heat-traced piping."

 HELLS,L N Tennesse Valley Authority, 82/08/18 D'REILLY, J P Region 2, Office of Director 2pp 14565 110 24X

 Fiche 50-390.82/08/18.8208270341

- 8208270342 Supplemental info to 810910 final deficiency rept re improper snubber installation Initially reported on 810811 Corrective action will be completed by 820930 MILLS,L K Tennessee Valley Authority 82/08/18. O'REILLY, J P Region 2, Office of Director ip 14565 113 24X Fiche 50-390, 82/08/18, 8208270342
- 8208270372 Finel deficiency rept re inaccurate work package drawing master status rept Initially reported on 81006 Computer sys reprogrammed to allow for proper merging of new data to ald records Personnel instructed re responsibilities MILLS, L.M. Tennessee Valley Authority 82/08/18 O'REILLY, J.P. Region 2, Office of Director 3pp 14566 013 24X Fiche 50-370, 82/08/18,8208270392
- 8208270275 First interim deficiency rept re washers eliminating axial restraint on essential raw cooling water unistrut supports initially reported on 82072; Drawings revised & washers removed Next rept expected by 82118
 MELG.L K Tennessee Valley Authority 82/08/19 O'REILLY, J P Region 2, Office of Director 2pp 14564 161, 24X
 Fiche 90-390, 82/08/19, 8208270275
- 8208300092 Becond interim deficiency rept re misspec of seismic displacements for steam generators Initially reported on 820430 Coordinate sys transformation relation developed & data sheet filed m/vendor data MILLS, L M Tennesse Valley Authority 82/08/20 0'REILLY, J. P. Region 2, Office of Director 2pp 14598 241, 24X Fiche 30-390, 82/08/20, 8208300092.
- 8208300222 Second interim deficiency rept re incorrect modulus of elasticity used in piping analysis of auxiliary feedwater sys. Initially reported on 820330 Piping analysis Problem N3-3-15A reanalysed Next rept expected by 821118 HILLS.L.H Tennessee Valley Authority 82/08/20 O'REILLY, J. F. Region 2, Office of Director 2pp. 14678 348 24X Fiche 50-390,82/08/20,8208300222
- 8208300338 Revised final rept re deficient Kerotest Y-type globe valves. Initially reported on 800819. Containment spray miniflow valves will be inspected & refurbished before fuel loading MILLS, i.M. Tennessee Valley Authority 82/08/20 D'REILLY, J P Region 2. Office of Director. 3pp 14679 204 24% Fiche. 50-390.82/08/20.8208300338
- 8208300211 Sixth interim deficiency rept re procurement control audits initially reported on 810316 TVA quality engineering branch response to audit deficiencies undergoing review. Next rept due by 821007 MILLS.L M Tennesses Velley Authority 82/08/23 0'REILLY, J P Region 20 Office of Director ip 14679 196. 24X Fiche 50-000:82/08/23.8208300211
- 8208300240 Final deficiency rept re defective welds on seismic i(L) supports to tritiated drain collector tank & floor drain collector tank Initially reported on 810707 Condition could not have adversely affected safe operation of plant HILLS, L. H. Tennesses Valley Authority 82/08/24, 0'REILLY, J. P. Region 2, Office of Director. 2pp 14679-146 24X Fiche 50-390,82/08/24,8208300240
- T Hearing transcripts on non-antitrust matters
- 8208120077 Transcript of ACRE Bubcommittee on Watts Dar 820810 meeting in Hashington. DC. Pp i-332 Supporting documentation encl * ACRE Advisory Committee on Reactor Safeguards. 82/08/10 410pp 14327.259. 24X Fiche. 30-390, 82/08/10.8208120077
- DOCKET 50-391 WATTE BAR NUCLEAR PLANT: UNIT 2
- A Application/construction stage documents & correspondence
- B2070B0064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR. Bvc list encl
 B20770B. Orfice of the Executive Director for Operations.
 B2077702. Consolidated Edison Co of New York 93pp. 14194.00i
 24% Fichs 50-000, B2707702, B2070B0064
- 8208020222 Forwards proposed mods to draft radiological effluent Tech Bacs Meeting to discuss submittal requested on 820824 MILLS.L.M. Tennesses Valley Authority, 82/07/26. ADENSAM.E. Licensing Brench 4. 68pp 14151:151 24X Fiche. 30-390, 82/07/26, 8208020222
- 8208060343 Requests addl info re loose perts monitoring sys.Results of ORNL review of 820225 submittal encl.

 ADENBAM.E. Q. Licensing Branch 4 82/07/30 PARRIS.H.Q. Tennessee Valley Authority. 7pp 14281 271 24X Fiche 50-370.82/07/30.8208060343.

- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT.D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York (p. 14356-332, 24X Fiche 30-000,82/08/09,8208090194
- 8208200198 Forwards revised responses to NUREC-0737. Items [] 8 1, II B 2, II F 1 & II F 2 & Westinghouse application for withholding proprietary summary rept "Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring " HILLS.L M Tennessee Valley Authority 82/08/12 ADENSAM.E Licensing Branch 4 54pp 14397 195 24X Fiche 50-390, 82/08/12, 8208200198
- 8208260318 Notification of 820825 meeting w/Duke Pawer Co.SC Electric & Gas Co & TVA in Bethesda.MD to review SER for Model D steam generator mods RANE.W F Licensing Branch 1 82/08/16 YOUNGELOOD, B Licensing Branch 1 5pp 14576 112 24X Fiche 50-000.82/08/16.8208260318
- 8208300125 Advises that schedule for completion of evaluation for control of heavy loads recelculated info to be provided by 830425 HILLS.L M Tennessee Valley Authority 82/08/25 ADENSAM.E Licensing Branch 4 1p 14599 214 24X Fiche 50-390.82/08/25.8208300125
- F Security, medical, emergency & fire protection plans
- 8208090071 Forwards revision to physical security plan Revision withheld (ref 10CFR73 21)
 KMMER.D S Tennessee Valley Authority 82/07/29 ADENSAM E A
 Licensing Branch 4 lp 14269 317 24X Fiche 50-390,82/07/29,
 8208090071
- 8208160442 Forwards physical security plan evaluation rept & proposed license condition Encls withheld (ref 10CFR2 790) MCCORKLE,0 H Power Reactor Safequards Licensing Branch 82/07/29 BERNARD,H Standardization & Special Projects Branch 1p 14348 219 24X Fiche 50-390,82/07/29,8208160442
- I Financial information
- 8208100002 Forwards "IVA Power Program Summary," Vol. 2, for fiscal yr ending 810630 & "1981 Power Program Summary," for fiscal yr ending 810930.per Section 50 71(b) of 100FR50 MILLS.L M Tennessee Valley Authority 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 118pp 14294 024 24X Fiche 50-000,82/08/06.8208100002
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 9207180072 Summarizes ACRE 268th meeting on 920812-14 re review of util application for OL OL issuance recommended subj to satisfactory resolution of issus of QA.cement mortar lining & hydrogen ignition sys SHEMMON.P ACRE Advisory Committee on Reactor Safeguards 82/09/16 PALLADINO, N J Commissioners 3pp (4509 321 24X Fichs 50-390, 82/09/14, 8207180072
- Q Inspection reports. IE Bulletins & correspondence
- 8208030416 Forwards IE Insp Repts 50-390/82-22 & 50-391/82-18 on 820521-0620 No noncompliance noted CONG.F J Division of Project & Resident Programs 82/07/08 PARRIS,H G Tennessee Valley Authority 2pp 14154 172 24) Fiche 50-390, 82/07/08, 8208030416
- --8208030425 IE Insp Repts 50-390/82-22 & 50-391/82-18 on 820321-0620 No noncompliance noted Major areas inspected design changes & mods.comparison of as-built plant to FSAR description, licensee event follows & follows on regional requests MCDONALD.J A , HEATHERLY, T L , GUICK, D R Division of Project & Resident Programs 82/07/08 Spp 14154 174 24X Fiche 50-390,82/07/08,8208030416
- 8204210393 [E Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl. JORDAN,E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356-274 24X Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Syc list encl JORDAN, E.L. Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ. of 112pp 14358 001 24% Fiche 50-000.82/07/19, 8204210395

- 8208160380 Forwards IE Insp Repts 50-390/82-23 & 50-391/82-19 on 820629-0702 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/07/19 PARRIS.H 0 Tennessee Valley Authority 2pp 14349 079 24X Fiche 50-390, 82/07/19,8208160380
- --B208160387 IE Insp Rept 50-390/02-23 & 50-391/82-19 on 820629-0702 No noncompliance noted Major areas inspected licensee action on previous insp findings & followup on licensee identified items
 OIBBONS, T D , CONLON T E Division of Engineering & Technical Programs B2/07/19 3pp 14349 OBL 24X Fichs 50-390.82/07/19, 8208160380
- B204210376 IE Info Notice B2-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list and I JORDAN,E L Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, B2/07/20, 8204210376
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Herafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/07/20 consolidated Edison Co of New York 71pp 14357 278 24X Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JERDAN, E. L. Division of Engineering & Quality Assurance 62/07/23 Consolidated Edison Co. of New York 122pp (4380) 115 24X Fishe 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 247 Fithe 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PMR Power Plants " Svc list enct JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24% Fiche 50-000, 82/07/26. 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Worl in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance B2/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, B2/07/28, 8204210405
- 8208030466 Ack receipt of 820713 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-390/82-26 & 90-391/82-20 VERRELLI.D M Division of Project & Resident Progrems 82/07/28 PARRIS.H G Tennesse
- --820B030473 Responds to NRC ltr re violations noted in IE Insp Repts 50-390/82-26 & 50-391/82-20 Corrective actions add1 clarification & Further revision for upper head injection scope will be provided by 82:031 DOMER, J A Tennessee Valley Authority 82/07/13 D'REILLY, J P Region 2, Office of Director ip 14154 065 24X Fiche 50-390, 82/07/28, 8208030466
- 8208030480 Ack receipt of 820715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-03 & 50-391/82-03 WERRELLI, D M Division of Project & Resident Programs 62/07/28 PARRIE, H O Tennessee Valley Authority ip 14154 066 24X Fiche 50-390, 82/07/28, 8208030480
- --8208030492 Responds to NRC 820314 itr re violations noted in IE Insp Repts 50-390/82-03 & 50-391/82-03 Corrective actions preoperational test manual will be implemented by 820801 MILLS, L M Tennessee Valley Authority 82/07/18 O'REILLY, J P Region 2: Office of Director ip 14154 067 24X Fiche 50-390,82/07/28,8208030480
- 8208160144 Responds to IE Bulletin 81-02 Suppl 1, "Failure of Gate Type Valves to Close Against Differential Pressure " Util anticipates submittal of final rept by 821028 upon receipt of revised drawings of field change notices KAMMER, D.S. Tennessee Valley Authority 82/07/29 O'REILLY, J.P. Region 2, Office of Director 1p 14345 123 24X Fiche 50-000, 82/07/29, 8208160144

- 8208030202 Forwards info re preservice insp program per NRC 820122 request covering Questions 121 21 & 23 KAMMER.D S Tennessee Valley Authority 82/07/30 ADENSAM.E Licensing Branch 4 5pp 14158 252 24X Fithe 50-390.82/07/30.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl MRDAN.E L Division of Engineering & Guality Assurance 82/08/05 Consoludate Edison Co of New York 117pp 14388 201 24X Fiche 30-000.82/08/05.8204210407
- 820Bi60337 Ack receipt of 820720 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-19 & 50-391/81-19 VERRELLI, D M Division of Project & Resident Programs 82/08/09 PARRISH G Tennessee Valley Authority ip 14349 049 24X Fiche 50-390/82/08/09/8208160337
- --8208160346 Responds to NRC 811008 ltr re violations noted in IE Insp Repts 50-390/81-19 & 50-391/81-19 Corrective actions due to general review & upgrading of GC procedures program, insp of locting devices will be issued by 820728 HILLS.L M Tennessee Valley Authority 82/07/20 O'REILLY.J P Region 2, Dffice of Director ip 14349 050 24X Fiche 50-390,82/08/09,8208160337
- --8203160352 Responds to NRC 811008 ltr re violations noted in IE Insp Repts 50-391/81-19 & 50-391/81-19 Revision of Procedure WBMP-0CP-1 42 or installation of locking devices incomplete West rept expected by 820630 KILLS.L M Tennessee Valley Authority 82/04/12 O'REILLY.J P Region 2. Office of Director ip 14349 051 24X Fishs 50-390,82/08/09.8208160337
- S Reportable occurrences, LERs & related correspondence
- B20B020226 Final deficiency rept for Sequoyah, second interim rept for Matts Bar & fifth for Bellafonto, Hartsville, Phipps Bend & Yellow Creek re inconsistent establishment of insp program Next rept for Watts Bar & Bellafonto expected B30103 MILLS, L.M. Tennessee Valley Authority B2/07/20 O'REILLY, J.P. Region 2, Office of Director App. 14152 344 24X Fiche 50-000, 82/07/20, 8208020226
- 8208020077 Third interim deficiency rept re failure of Limitorque motor operators during valve closure Initially reported on 820126 Mestinghouss & Limitorque continuing investigation Next rept espected by 821021 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 82/07/21 0'REILLY, J P Region 2. Office of Director ip 14144 105 24X Fishe 50-390, 82/07/21, 8208020077
- 8208020161 Third interim deficiency rept re cable separation in essential raw cooling water intake pumping station Initially reported on Bil204 One-hour rated fire barrier protection added Next rapt expected by B21122 MILLS.L M Tennessac Valley Authority 82/07/21 O'REILLY, J P Region 2. Office of Director 2pp 14145 108 24X Fichs 50-390,92/07/21,8208020161
- 8208020199 First interim deficiency rept re spacing requirements on seismic pipe supports not in compliance w/criteria Initially reported on 820822 Preliminary changes to 47A033 series drawing notes initiated Next rept expected 821208 MICLS-L M Tannessee Valley Authority 82/07/22 O'REILLY, J P Region 2. Office of Director 2pp 14141,005 24X Fiche 50-390,62/07/22,8208020199
- E208020242 Eighth interim deficiency ropt re failure of safety-related Mastinghouse gate valves initially reported on 801031 Final rept will be provided upon receipt of revised drawings from Westinghouse Also reported per Part 21 HILLG.L M Tønnessee Valley Authority 82/07/22 D'REILLY, J P Region 2. Office of Director ip 14152 057 24X Facher 50-390, 82/07/22.8208020242
- 8208020108 First interim deficiency rept re tornado depressurization en augiliary bldg Initially reported on 820623 Depressurization calculation revised to determine expected loading on interior wall. Next rept by 821116
 NILLS.L M Tennessee Valley Authority 82/07/23 O'REILLY. J P. Region 2. Office of Director 2pp 14142 115, 24X
 Fiche 50-390.82/07/23.8208020108
- 8208030249 Fifth interim deficiency rept re unconservative loads on pipe support design mods. Initially reported on 801217 Design reviews for both units will be completed by 821231 & 830430, respectively Addi info will be provided by 830615 HKLS.L M Tennessee Valley Authority 82/07/27 0'REILLY, J. P. Region 2. Office of Director 2pp 14158: 211 24X Fiche 50-390, 82/07/27, 8208030249

- 8208030161 First interim deficiency rept re alternate analysis program breakdown initially reported on 820828 Complete reverification of alternate analyses will be performed Next rept to be submitted by 821107 MILLS.L. M. Tennessee Valley Authority 82/07/28 O'REILLY.J.P. Region 2. Office of Director 2pp 14160 116 24X Fiche 50-390.82/07/28.8208030161
- 8208050420 Ninth interim deficiency rept re installed anchor bolts not in accordance w/spacing specs [nitially reported on 810331 Design of engineered support base plates w/self-drilling expansion shell anchor spacings being reviewed MILLS.L. M. Tennessed Valley Authority 82/07/28 O'REILLY, J.P. Region 2. Office of Director ip 14217 161 24X Fiche 50-390.82/07/28.8208050420
- 8208030347 Fifth interim deficiency rept re insufficient documentation for protective devices initially reported on 820313 Util corrected & documented 90 protective devices & identified 12 which cannot be completed Next rept expected by 82105 MILLS,L M Tennessee Valley Authority 82/07/30 O'REILLY, J P Region 2, Office of Director ip 14219 333 24% Fiche 50-390, 82/07/30, 8208050347
- 8208070057 Second interim deficiency rept re containment penetration protection Initially reported on 811207 Penetrations being re-evaluated to debormine adequacy of long-time overload protection Next rept will be submitted by 821115 MICLES.L M. Tennessee Valley Authority 82/07/30 O'REILLY, J.P. Region 2. Office of Director 4pp 14269 318 24X Fiche: 50-390, 82/07/30, 8208070057
- 8208120243 Fourth interim deficiency rept re environ qualification of electrical equipment Initially reported on 810727 Components identified as potentially deficient listed on encl Table I Next rept expected by 830225 MILLS, L M Tennessee Valley Authority 82/08/03 O'REILLY, J P Region 2, Office of Director 33pp 14326 288 24X Fiche 50-390, 82/08/03, 8208120243
- 8208120361 Third interim deficiency rept re excessive movement of containment penetration believe initially reported on 811204 investigation continuing Next rept expected by 821129.

 MILLS.L M Tennesse Valley Authority 82/08/04 D'REILLY, J P Region 2, Office of Director 1p 14319 277 24X Fichs. 50-390, 82/08/04, 8208120161
- 8208120102 Birth interim deficiency rept re retrievable info used in piping analysis Initially reported on 810316 Engineering procedure will be written to define & control use & maint by sys engineers Addl info will be provided by 830222 MICLS, L.M. Tennesses Valley Authority 82/09/05 O'REILLY, J.P. Region 2. Office of Director ip 14319 160 24% Fiche 50-390, 82/08/05, 8208120102
- 8208120157 Third interim deficiency rept re HVAC register inoperability Initially reported on 820125 Field-fabricated balancing devices to replace register Investigation continuing Next rept will be submitted by 820908 MILLS, L M Tennessee Valley Authority 82/08/05. O'REILLY, J P Region 2. Office of Director 1p 14323 276 24X Fiche 50-390, 82/08/05, 8209120157
- 8208120306 Third interim deficiency rept re improper handling & review of engineering change notices Initially reported on 811215 Review of sample notices continuing Next rept will be transmitted by 830119 MILLS.4. M Tennesses Valley Authority. 82/08/05. D'REILLY, J P. Region 2. Office of Director 7pp 14325 006 24X Fiche. 50-000, 82/08/05, 8208120306
- 8208130203 Second interim deficiency rept re Ameron cement mortar lining Initially reported on 820621 Listed corrective actions completed by 820701 w/exception of surface cracks Also reported per Part 21 HILLS.L M Tennesses Valley Authority, 82/08/06, 0'REILLY, J P. Region 2, 06fice of Director 4pp 14339 094 24X Fiche, 50-390, 82/08/06, 8208130203
- 8208130169 First interim deficiency rept re unistrut clamps hosded in more than one direction. Initially reported on 820708 ASME Section III. Subsection NF 3262 4 indicates all clamps qualified except for 3-inch piping Next rept by 821222. HILLERL M Tennesses Valley Authority 82/08/09 0'REILLY, J. P. Region 2. Office of Director 2pp. 14339.022 24X Fiche \$0-390, 82/08/09, 8208130169
- 820B130266 Third interim deficiency rept re improper design of HVAC penetrations in containment Initially reported on 81:224 Util re-evaluating nonprocess penetrations using correct load definitions. Next rept expected by 82:213.
 MILLO, L. M. Tennesse Valley Authority 82/08/09 O'REILLY, J P Region 2. Defice of Director. 1p 14339:051. 24X Fithe: 50-390, 82/08/09.8208130266

- 8208160261 Sirth interio deficiency rept re improper weld attachment of shear lugs Initially reported on 801030 Installation of lugs in HVAC chilled water sys 31 in progress Next rept expected by 821025 MILLS, L.M. Tennessee Valley Authority 82/08/10 G'REILLY, J.P. Region 2, Office of Director 2pp 14346-361 24X Fiche 50-390, 82/08/10.8208160261
- 8208160132 First interim deficiency rept re post-accident readings from containment sump level transmitters initially reported on 820708 Util reviewing change of capillary fill fluid from water to silicon oil Also reportable per Part 21 MILLS, L.M. Tennessee Valley Authority 82/08/11 O'REILLY, J.P. Region 2. Office of Director 2pp 14345 228 24X Fiche 50-390, 82/08/11, 8208160132
- 8208160477 Seventh interim deficiency rept re improper classification of essential raw cooling water sys piping & components initially reported on 810024 Evaluation of contract files continuing Next rept expected by 821019 MILLS,L M Tennessee Valley Authority 82/08/II D'REILLY, J P Ragion 2. Office of Director 3pp 14348 216 24X Fiche 50-390, 82/08/I1,8208160477
- B20B200014 Second interim deficiency rept re component cooling sysfailure to meet pipe support lug criteria Initially reported on B20607 Effects of oversized lugs under review Next rept by B21020 MILLS.L M Tennessee Valley Authority B2/08/12 O'REILLY, J P, Region 2, Office of Director 2pp 14392 244 24X Fiche 80~390,82/08/12.8208200014
- 8208200038 Fourth interim deficiency rept re incorrect modeling of feedwater piging flow control valves 3-234, 239, 242 & 245 Initially reported on 811009 Piging support designs will be modified to qualify giping & equipment Next rept by 82119 MILLS.L.M. Tennessee Valley Authority 62/08/12. D'REILLY, J.P. Region 2, Defice of Director 2pp 14392 195 24X Fiche 50-390, 82/08/12, 8208200038
- 8208200105 First interim deficiency rept re dissimilarity of info for frequency criteria for piping supports Initially reported on 820713 Investigation continuing Next rept expected by 921004 MILLS.L.M. Tennessee Valley Authority 82/08/12 D'REFLLY, J.P. Region 2. Defice of Director 2pp 14393 259 24X Fiche 30-390, 92/08/12, 8208200105
- 8208270283 Ninth interim deficiency rept re steel containment penetration assemblies Initially reported on 801219 All affected piping evaluated & reanalysed Guidance will be provided in checklist Final rept expected by 821117 MILLSL M Tennessee Valley Authority 82/08/16 O'REILLY, J P Region 2, 0ffice of Director 2pp 14564 159 24% Fiche 50-390,82/08/16,8208270283
- 8208270128 Fourth interim deficienty rept re foam seals in mechanical pipe sleeves Initially reported on 011204 Rept corrects inaccuracies stated in 820414 final rept Dasign std will be developed to give sleeve designers guidance MILLS,L M Tennesses Vallay Authority 82/08/18 0'REILLY, J P Region 2. Office of Director 2pp 14563 316 24X Fiche 50-370, 62/08/18, 8208270128
- 8208270341 Final deficiency rept re pipe supports jeopardizing insulation during thermal movement initially reported on 820408 Typical support drawings ECN 3341 revised w/note "not to be used w/heat-traced piping"
 MILLS.L. M. Tennessee Valley Authority 82/08/18, D'REILLY, J.P. Region 2, Office of Director 2pp 14565-110 24X
 Fiche 50-370, 82/08/18, 8208270341
- 8208270342 Supplemental info to 810910 final deficiency rept re improper snubber installation Initially reported on 810811 Corrective action will be completed by 820930 MILLS, LM Tennessee Valley Authority 82/08/18 0'REILLY, J P Region 2, Office of Director ip. 14565 113 24X Fiche: 50-390, 82/08/18,8208270342
- 8208270392 Final deficiency rept re inacturate work package drawing master status rept institutly reported on 81006 Computer sys reprogrammed to allow for proper merging of new data to old records Personnel instructed re responsibilities MILLS.L H Tennessee Valley Authority 82/08/18 0'REILLY.J.P Region 2: 0ffice of Director 3pp 14566 013 24X Fiche 50-390.82/08/18.8208270392
- 8208270275 First interim deficiency rept re washers eliminating exial restraint on essential raw cooling water unistrut supports initially reported on 820721 Brawings revised & washers removed Next rept expected by 821118.

 HILLS.1 M Tennesses Valley Authority 82/08/19 0'REILLY, J P. Region Z. Office of Director 2pp 14564 161 24X Fiche 50-390, 82/08/19, 8208270275.

- 8208300092 Second interim deficiency rept re misspec of seismic displacements for steam generators initially reported on 820830 Coordinate sys transformation relation developed & data sheet filed w/vendor data MILLS.L M Tennesses Valley Authority 82/08/20 O'REILLY.J P Region 2. Office of Director 2pp 14598 241 24X Fiche 50-390,82/08/20,8208300092
- 8208300222 Second interim deficiency rept re incorrect modulus of elasticity used in piping analysis of auxiliary feedwater sys. Initially reported on 82030 Piping analysis Problem NJ-3-15A reanalysed Next rept expected by 821118 MILLS.L. M. Tennessee Valley Authority 82/08/20 0'REILLY, J.P. Region 2. Office of Director 2pp 14678 348 24% Fiche 50-390.82/08/20,8208300222
- 8208300338 Revised final rept re deficient Karotest Y-type global valves Initially reported on 800819 Containment spray miniflow valves will be inspected & refurbished before fuel loading MILLS.L H Tennessee Valley Authority 82/08/20 O'REILLY, J PRegion 2. Office of Director 3pp 14679 204 24X Fiche 50-390.82/08/20.8208300338
- 8208300211 Sixth interim deficiency rept re procurement control audits
 Initially reported on 810316 TVA quality engineering branch
 response to audit deficiencies undergoing review Next
 rept due by 821007
 MILLS.L.M. Tennessee Valley Authority 82/08/23 0'REILLY, J.P.
 Region 2. Office of Director ip 14679 196 24X
 Fiche 50-000, 82/08/23, 8208300211
- 8208300240 Final deficiency rept re defective welds on seismic I(L) supports to tribiated drain collector tank & floor drain collector tank Initially reported on 810707 Condition could not have adversely affected safe operation of plant MILLS.L M Tennessee Valley Authority B2/08/24 O'REILLY, J P Region 2, Office of Director 2pp 14679 146 24% Fiche 50-390.82/08/24.8208300240
- T Hearing transcripts on non-antitrust matters
- 8208120077 Transcript of ACRS Subcommittee on Watts Bar 820810 meeting in Washington, DC Pp 1-332 Supporting documentation enc1 * ACRS Advisory Committee on Reactor Safeguards 82/08/10 410pp 14327 259 24X Fichs 50-390, 82/08/10, 8208120077
- DOCKEY 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for CL & holders of CP re Commission approved charter for CROR Svc list encl DIRCKS, H J Offics of the Executive Director for Operations. 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fichs 50-000, 82/07/02, 8207080064
- 8208040377 Summary of 820721 meeting w/Westinghouse, ANL, Bechtel, TSI, CNASCO & utils in Bethesda, MD re-progress in resolving accelerated tube wear at operating plants w/Westinghouse Model D steam generators KANE, W F Licensing Branch 1 82/07/23 YOUNOBLOOD, B J Licensing Branch 1 5pp 14224 182 24X Fiche, 50-395, 82/07/23, 8208040377
- 8208020142 Summarizes 820716 telcon w/NRC re inadvertent boron dilution High flux at shutdown alarm is physically set each time reactor is shut down by use of general operating & surveillance test procedures
 DIXON-O W South Carolina Electric & Gas Co 82/07/28 DENION-H R
 Office of Nuclear Reactor Regulation, Director 2pp 14142 027
 24X Fiche.50-395,82/07/28.8208020142
- 8R08030R30 Forwards procedures to accomplish special low power physics testing as defined in util 820331 ltr DIXON: D.W. South Carolina Electric & Gas Co 82/07/29, DENTON: HR Office of Nuclear Reactor Regulation, Director 2pp 14158 307 24X Fiche 50-395, 82/07/29, 8208030230
- --820803024: Procedure HBT-7, Revision 1, "Hot Shutdown Tasting, Pressurizer Sprey & Heater Capability & Continuous Spray Flow Settings " HOOLDRIDGE, A Bouth Carolina Electric & Qas Co 82/07/28, 48pp 14158 309 24X Fiche 50-395,82/07/29,8208030230
- --8208030246 Procedure ZPT-9 1, Revision Q, "Zero Power Testing Natural Circulation Demonstration"

 * South Carolina Electric & Gas Co 82/07/06. 34pp 14158 357. 24X Fiche 50-395, 82/07/29.8208030230.

- --8208030251 Procedure ZPT-9 2.Revision 0, "Zero Power Testing, Core Cooling W/Bimulated Loss of Onsite & Offsite AC Power " e South Carolina Electric & Gas Co 92/07/01 17pp 14159 029 24% Fiche 50-395,82/07/29,8208030230
- --8208030257 Procedure POT-11.Revision 1, "Power Operation Testing. Station Electrical Blackout" • South Carolina Electric & Gas Co 82/05/20 16pp 14159 046 24% Ficha 30-095.82/07/29,8208030230
- P208030507 Forwards marked-up revised Tech Spec Page 3/4 5-5 re acceptance criterion for RHR pumps in ECCS DIION.D W South Carolina Electric & Cas Co 82/07/29 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 14163 125 24x Fiche 50-395.82/07/29.8208030507
- 8208030508 Requests exemption from Tech Spec Items 3 & 4 of Table 3 3-1 re reactor trip sys instrumentation, to allow rod drop test w/o reactor trip Proposed license condition encl OlxoN.0 W South Carolina Electric & Gas Co 82/07/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 14161 135 24x Fishs 50-395, 82/07/29, 8208030608
- 8208060183 Forwards performance evaluations for safety valves, power operated relief valves (PORVs) & PORV block valves & pressurier relief sys piping & support svaluation.per NUREG-0737. Item II. D I Item resolved
 DINGN.D W South Carolina Electric & Gas Co 82/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp 14239 104 24X Fichs 50-395, 82/07/30, 8208060183
- --82080&0186 "Pressurizer Rollef Sys Piping & Support Evaluation Rept for VC Summer Nuclear Station.SC Electric & Gas Co in Response to NURSC-0737. Item II D 1 " a Gibert/Commonwealth Cos 82/07/30 3ipp 14239 120 24X Fiche 30-395.82/07/30.8208060183
- B2QB080261 Forwards revised Tech Specs Table 3 3-13 deteting ref to recombiner Spec applies to availability of monitoring instrumentation & not to recombiners
 DIXON G W South Carolina Electric & Gas Co 82/07/30, DENION, if R Office of Nuclear Reactor Regulation, Director ip 14241 293 24x Fiche 30-395, 82/07/30, 8208040241.
- --8208050252 Proposed revised Tech Spec Table 3 3-13 re waste gas monitoring sys. # South Carolina Electric & Gas Co. 82/07/30 ip 14241 274 24X Fiche 50-375.82/07/30.8208050251.
- 8208040051 Advises that facility complies w/NPDES program requirements Perait expired, but SC Administrative Procedures Act extends perait indefinitely until Dept of Health & Environ Control acts on reissuance application GROSS:R 0 Bouth Carolina, State of 82/08/02 DENTON, H R Office of Ruclear Reactor Regulation, Director 1p 14(89 15) 24% Fiche 50-395.82/08/02.8208040051
- 8208:30376 Comments on responses to 820614 itr to HR Denton remonitoring program for svc water pond structures Less frequent insp will not be approved YOUNGELDOB, B. J. Licensing Branch I 82/08/02 DIXON, G. W. Sputh Carclina Electric & Oas Co. 3pp. 14340:265, 24X Fiche 50-393,82/08/02,8208130376
- 6208130427 Forwards revised marked-up pages of App A Tech Specs to reflect responses from NRC on proposed changes YOUNGELOOD B J Licensing Branch [82/08/03 DIXON, D, W South Carolins Electric & Qas Co 33pp 14354 304, 24X Fiche 50-395, 82/08/03, 8208130427
- 820Bi 10126 Forwards proprietary marked-up NUREG-0888 page re change to RdF narrow range resistance temp detactors Formal revision to be issued at later date Affidavit requesting proprietary classification encl Page withheld (ref 100FR2 790) DIXON/O W South Carolina Electric & Oas Co 82/08/04 DENTON, HR Office of Nuclear Reactor Regulation, Director 9pp 14792 208, 24x Fiche. 50-395, 82/08/04, 820Bi 10126
- 8208090194 Oeneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list enci EISENNUT.D.O Division of Licensing 82/08/09, Consolidated Edison Co of New York ip 14356 332 24X Fiche.50-000,82/08/09,8208090194
- E. HRC Gafety Evaluation Report (SER), supple & correspondence
- 8208270486 Forwards Suppl 4 to SER (NUREO-0717) W/o encl YBUNGBLOOD B J. Licensing Branch 1. 82/08/16, DIXON.O.W. South Carolina Electric & Oas Co Ip 14683.069 24X Fiche 50-395.82/08/16, B208270486.

- 8208230411 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE VIRGIL C SUMMER NUCLEAR STATION.UNIT NO 1 Docket No 50-375 (South Caroline Electric & Gas Company) * Office of Nuclear Reactor Regulation, Director NUREG-0717 804 82/08/31 118pp Available at NTIS \$5 50 14528 231 24X Fiche 50-375, 82/08/31, 8208230411
- F Security, medical, emergancy & fire protection plans
- 8208110127 Releases public version of revised radiation emergency plan FELTON.J M Division of Rules and Records 82/08/05 Document Management Branch lp 14328 315 24X Fiche 50-395,82/09/05, 8208110127
- --820Bil0132 Forwards public version of Revision 7 to Radiation Emergency
 Plan EP-100 Instruction sheets enci
 ptxON.0 W South Carolina Ejectric & Oas Co 82/07/30
 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp
 14328 316 24X Fiche 50-395,82/08/05,820Bil0127
- --8208110134 Public version of Revision 7 to Radiation Emergency Plan EP-100 BEALE,K E South Carolina Electric & Oas Co 82/07/20 33pp 14328 318 24% Fishe 50-395,82/08/05,8208110127
- 8208100136 Clarifies util commitment dates for emergency planning items addressed by ASLB 820804 supplemental partial initial decision Dates address areas of min shift manning requirements & emergency response facilities
 DIXON D W South Carolina Electric & Gas Co 82/08/06 DENTON, H R Office of Nuclear Regulation, Director 2pp 14278 131. 24X Fiche 50-375,82/08/06.8208100136
- 8208230005 Forwards Amend 7 to physical security plan Amend withheld (ref 100FR73 71).

 DIXON.O W South Carolina Electric & Gas Co 82/08/13 DENTON.H R Office of Nuclear Reactor Regulation, Director. 2pp 14517 283 24X Fiche 50-395,82/08/13.8208230005
- 8208240375 Requests authority to use roving 1-h fire watches in lieu of continuous fire watch to cover ereas of facility covered by Tech Spec 374 3 7 10 Manning requirements for roving patrols will be increased from five to sight people.

 DIXON O W South Carolina Electric & Oss Co 82/08/18 DENTON, H. R Office of Nuclear Reactor Regulation, Director 2pp 14522 359 24X Fiche 50-395,82/08/18,8208240375
- O Adjudicatory correspondence
- 8208020211 Hotion for reconsideration of portion of ASLB 820720 partial initial decision re NRC 811020 notification to ASLB of peak recorded accelerations associated w/791016 selamic event ASLB misapprehended circumstances Certificate of Svc encl KNOTTS, J B gooth Carolina Electric & Oas Co KNOTTS, J B Booth Carolina Electric & Oas Co KNOTTS, J B Debevois & Liberman 82/07/30 Atomic Safety and Licensing Board Panel 79p 14141 118 24Y Fiche 50-395,82/07/20,8208020211
- 8208030252 Memorandum & order denying Fairfield United Action B20409 petition to intervene & request for hearing & B Bursay 820414 motion for admission of new contentions Different result would not be reached by considering petition mat1 LINEMBERGER.O.. HOUFER, F.F. QRDSSMAN, H. Atomic Safety and Licensing Board Panel 82/08/02 Fairfield United Action opp 14158 213 24X Fiche.50-375,82/08/02,8208030252
- 6208050472 Supplemental partial initial decision authorizing NRR Director to issue full-term DL aubj to listed conditions LINEMBERGER, 0 . HOCFER, F F. . GROSSMAN. H. Atomic Bafety and Licensing Board Panel 82/08/04 68pp. 14216 247 24X Fiche: 50-395, 62/08/04.6206050472
- 820B180013 Hotion to reopen record & conduct further proceedings re GA deficiencies & uncorrected safety-related defects GL should be denied until deficiencies corrected ASLB 820B04 order authorizing operation should be stayed H/Gertificate of Byc BURGEY, B Burssy, B 82/08/10 Atomic Safety and Licansing Board Panel 4pp. 14377 178 24X Fichs 50-395, 82/08/10, 8208180013
- 8208120135 Response joining applicant 820730 request for reconsideration of certain passages of ASLB 820720 partial initial decision Suggestion that accelerameter records not reported on timely basis erroneous. Certificate of Svc encl OCLDEERO, S. C. Hearing Branch 4 82/08/11 Abonic 8afety and Licensing Board Penel. Spp. 14327.117. 24X Fiche 50-395,82/08/11,8208120135
- 8208190117 Hemorandum confirming briefing schedule re allegations of defective welds in containment rebar. Schedule discussed in 820812 telcon GROSSMAN. H. Atomic Safety and Licensing Board Panel 82/08/17 Opp 14382 181 24X Fiche 50-395.82/08/17.8208190117

- 8208240215 Memorandum & order denging applicant 820730 motion for reconsideration of portions of ASLB 820720 partial initial decision on seismic matters Fact of incompleteness of BIO622-24 hearing record cannot be seriously questioned OROSEMAN.H Atomic Gafety and Licensing Board Panel B2/08/20 Bouth Carolina Electrix & Gas Co. Spp. 14519 132 24X Fiche 50-395, 82/08/20, 8208240215
- 8208240278 Informs that NRC will not file exceptions to ASLB 820720 partial initial decision or 820804 supplemental partial initial decisions failure to file exceptions does not imply NRC agreement w/decisions GOLOBERO. S C Hearing Branch 4 62/08/20 SHOEMAKER. C, J Atomic Safety and Licensing Appeal Panel 1p 14527 166 24X Fiche 50-395.82/08/20.8208240278
- 8208240253 Erreta to 820720 partial initial decision making listed corrections & substituting encl corrected Page 67 for original page 98055HAN: H Atomic Safety and Licensing Board Panel. 82/08/20 2pp 14521 051 24X Fiche 50-395.82/08/20.8208240353
- 8208240358 Exceptions to ASLB 820720 partial initial decision & 820804 supplyon seismic issues ASLB erred in concluding that applicant ground motion model unreliable Certificate of Svc encl
 KNOTTB.JB South Carolina Electric & Gas Co KNOTTB.JB
 Debevoise & Liberman 82/08/20 Atomic Safety and Licensing Appeal Panel 8pp 14521 057 24X Fiche 50-395,82/08/20,8208240358
- 8208250263 Erreta to 820804 supplemental partial initial decision GROSSMAN.H Atomic Safety and Licensing Board Panel 82/08/23 2pp. 14543 029 24% Fiche 50-395.82/08/23.8208250263
- 8208270389 Order directing applicants to show cause by 820907 why exceptions should not be dismissed. Exceptions not permitted to defend decision in favor of party submitting exceptions SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 82/08/2 Gouth Carolina Electric & Gas Co. 3pp. 14563 101 24x Fiche 50-395,82/08/24.8208270389
- J insurance & indemnity information
- 8208180029 Advises of increase in coverage under MAELU Policy HF-108 JONES-R. American Nuclear Insurers 82/08/04 DINITZ. I Antitrust & Economic analysis Branch (Utility Finance) 1p. 14376-297 24X Fiche 50-395, 82/08/04, 8208180029
- 820831026B Requests change in annual indemnity fee DINITZ-1. Assistant Director for State & Licensee Relations 82/08/23. PUGLISE.A B Division of Accounting ip 14688 157 24X Fiche 50-375,82/08/23.8208310268
- P Operating license stage documents & correspondence
- 8208260322 Notification of 820701 meeting w/util in Bethesda.MD to review licensee program for responding to License Condition 25 re confirmatory seismic analysis KANE.MF Licensing Branch [82/08/1 YOUNGBLOOD, B Licensing Branch 1 3pp 14576 109 24X Fiche 50-395.82/08/11.8208260322
- 8208160243 Forwards Revision 2 to inservice test program DIXON 0 W Bouth Carolina Electric & Cas Co 82/08/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14347'063 24X Fiche' 50-395, 62/08/12, 8208160243
- --8208160247 General Test Procedure GTP-001.Revision 2. "General Procedure for Inservice Testing of Pumps " * Bouth Carolina Electric & Gas Co 82/08/02 26pp 14347:065 24X Fiche 50-395,82/08/12,8208160243
- 8208240318 Notification of 820825 meeting w/Duke Power Co.BC Electric & Gas Co & TVA in Bethesda.MD to review SER for Model D steam generator mods KANE.W F. Licensing Branch 1 82/08/16 YOUNGBLOOD.B Licensing Branch 1 5pp. 14576.112 24X Fiche 50-000.82/08/16.8208260318
- 8208240423 Application for Tech Specs change re radiation monitor channels monitor setpoints & reactor bidg manipulator crene radiation channels Changes also correct typographical errors
 DIXON, D W South Carolina Electric & Qas Co 82/08/18 DENTON.H R. Office of Nuclear Reactor Regulation, Director. 2pp. 14524:198
 24X Fiche-50-375,82/08/18,8208240423

- --8208240427 Tech Spec Pages 3/4 3-18.3/4 3-26.3/4 3-68.3/4 8-17 1 3/4 9-9 re radiation monitor channels & sotpoints & reactor bldg manipulator crene radiation channels Typographical errors corrected

 * Bouth Carolina Electric & Oss Co 82/08/18 5pp 14524 2% 24X Fiche 80-395.82/08/18.8208240/823
- B20B290192 Application for amend to License NPF-12, requesting reliffrom Tech Spec 3/4 3 7 10
 DIXON.O W South Carolina Electric & Gas Co B2/0B/23 DENTON to
 Office of Nuclear Reactor Regulation, Director 3pp 14540 274
 24X Fiche 50-375.82/0B/23.820B250152
- 8208300228 Application for amond to License NPF-12, proposing Tech Signadministrative changes provided in util 820818 ltr Class II amend fee oncil
 DIXON 0 W South Carolina Electric & Gas Co 82/08/24 DENTON F1
 Office of Nuclear Reactor Regulation, Director 3pp 14678 312
 24X Fichs 50-395,82/08/24,8208300228
- G Inspection reports. IE Bulletins & correspondence
- 8208160156 Submits info to define util approach to phased completion of requirements of IE Builetin 79-14, "Cracking in Feedwater 8us Piping." per 820708 telcon DIXON.O W South Carolina Electric & Qas Co 82/07/09 O'REILLY.J P Region 2. Office of Director 2pp. 14345 144 241 Fichs.50-395,82/07/09,8208160156
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list entl JORDANNE L Division of Engineering & Guality Assurance 82/07/11 Consolidated Edison Co of New York 87pp 14386 274 24X Fiche 50-000
- 8204210395 [E Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance B2/07/13 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/13 B204210375
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " But list ent I JORDAN E L. Division of Engineering & Quality Assurance 82/07/29 Consolidated Edison Co of New York 112pp 14391 001 241 Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Herefluoride Overpacks " 6vc list ent! COPBL I Division of Fuel Facilities, Materials & Gafeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357-278 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Ethaust Cherk Valve Failures " 8vc list enc! JORDAN,C L. Division of Engineering & Quality Assurance 82/07/22. Consolidated Edison Ca of New York 112pp 14194-321 24K Fiche 50-000, 82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orindiry in Vicinity of Drained & Open RCS " Svr list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/27 Consolidated Edison Co of New York 122pp 14380 115 24% Fichs 50-000, 82/07/23,8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Quids Tubs Support Pin Failures at Westinghousa PWRs " Bvc list encl JRDANNE L. Division of Engineering & Quality Assurance 62/07/23 Consolidated Edison Co of New York 127pp 14194.120 24X Fiche 50-000.82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS fights at Certain Westinghouse PWR Power Plants" Bvc list encl JORDAN.E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 121pp 14357-013 24% Fiche 30-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work is Fuel Storage Pool " Syc list encl JORDAN-E L Division of Engineering & Quality Assurance 82/07/28 , Consolidated Edition Co of New York 122pp 14357,146 24x Fiche: 50-000,82/07/28,8204210405
- 8208160207 Forwards IE Insp Rept 50-395/82-42 on 820713-15 No noncompliance moted DANCE: No. Division of Project & Resident Programs, 82/07/28 pIXON, Q W South Carolina Electric & Gas Co 2pp. 14344-155 241 Fichs. 50-395

- --820Bi60214 IE Insp Rept 50-395/82-42 on 820713-15 No noncompliance noted Major areas inspected followup on inspecter identified items PERRY, W W BARR, K P Division of Engineering & Technical Programs 82/07/26 3pp 14344 157 24X Fiche 50-395,82/07/28,8208160209
- 8204210407 IE Info Notice 82-27, "Fuel Rod Dogradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201, 24X Fiche 50-000,82/08/05,8204210407
- 8208230276 Requests removal of requirement for installation of steam generator insp ports from OL Installation of ports to sonitor denting unnecessary DIXON, O W South Carolina Electric & Qas Co 82/08/17 DENTON, H & Office of Nuclear Reactor Regulation, Director 2pp 14512 258 24X Fiche 50-395,82/08/17,8208230276
- 6 Reportable occurrences, LERs & related correspondence
- 8208050079 Final deficiency rept re diesel generator thermostatic control valves Initially reported on 820629 Overrun assembles for thermostatic control valves redesigned to prevent nut from disengaging Also reported per Part 2: DIXON,O W Bouth Carolina Electric & Gas Co 82/07/29 O'REILLY, J.P. Region 2, Office of Director 4pp. 14213-204, 24X Fiche 50-395,82/07/29,8208050079
- 8208240426 PNO-II-82-093 media interest continues in allegations by former facility cadwelder that containment has some defective cadwelds in vertical rebar Investigation continuing. Initial fuel load operations began 820810. 880NHLEE, V L , GLSHINSKI, J A Region 2, Office of Director. 82/08/13 ip 14522 358 24X Fiche 50-395,82/08/13,8208240428
- DOCKET 30-397 WPP88 NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list enci DIRCKS, M. J. Office of the Executive Director for Operations. 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fiche 50-000, 82/07/02, 8207080064
- 8208020227 Advises that updated schedule re pump & valve inservice test program will be submitted by 820701
 80UCHEY. 0 D Washington Public Power Supply System 82/07/08
 SCHWENCER, A Licensing Branch 2 1p 14152 246 24X
 Fich
- 8208020238 Documents 820625 telcon concerning NRC approval for use of ASME Code Case N-316 re alternative rules for fillst weld dimensions for socket welded fittings Case rept encl 8CUCHEY.0 D Washington Public Fower Supply System 82/07/08 SCHMENCER.A Licensing Branch 2 64pp 14151 233 24X Fiche 50-397.82/07/08.8208020238
- 8208030738 Requests proposed schedule for submitting program re adequacy of design mangins of Mark I & II containment sys Response within 14 days requested TEDESCO, R L. Assistant Director for Licensing 82/07/08 FERGUSON, R L. Washington Public Power Supply System 2pp 14195-356 24X Fiche 50-397,82/07/08,8208030738
- 8208020157 Bubmits response to NRC questions arising from review of draft Bierra Geophysics rept. "Paleomagnetism of Pre-Missoula Cravels From Corehole PM-2 on Boutheast Anticline Hanford Bits NA"
 BOUCHEY, G. D. Hashington Public Power Supply System B2/07/13 SCHRENCER, A Licensing Branch 2 2pp 14145 106 24X
 Fiche 50-397, 82/07/13, 8208020157
- 8208040194 Responds to 820611 ltr re-concerns expressed about impact of staff evaluation of geology & seismology for DL review.

 Supplemental SER schaduled in early Aug 1982

 EJBENHUT, D. G. Division of Licensing 82/07/13 BOUCHEY, O.D.

 Washington Public Power Supply System. 1p 14231 314 24X

 Fichs: 50-397, 82/07/13, 8208040194
- --8208040203 Requests timely completion of evaluation of geology & seismology review Excessively re-evaluated siting issues deplate resources; rarely result in plant changes & cause ficensing delays
 BONCHEY, 0 D Mashington Public Power Supply System 82/06/11
 DENION, HR Office of Nuclear Reactor Regulation, Director, 2pp. 14231,319, 24X Fiche 90-397,82/07/13,8208040194

- 8206200020 Opposes unnecessary re-evaluation of siting issues resolved during CP proceedings Reviews deplets both util & NRC financial & manpower resources & are unproductive FERGUBGONR t Washington Public Power Supply System 82/06/11, PALLADINO, N J Commissioners. Spp 14291 314 24X Fiche 50-397, 82/07/13, 8206200020
- 8208040175 Responds to 820611 ltr expressing concerns re review of siting issues resolved during CP proceedings Siting issues will be closed out at CP stage DENTON.HR Office of Nuclear Reactor Regulation: Director 82/07/15 FEROUSON.R L. Washington Public Power Supply System 2pp 14231 312 24X Fiche 50-397.82/07/15.8208040175.
- 8208020130 Responds to NRC 820708 ltr requesting to be advised of schedule for submitting program to address concerns readequacy of design margins of Mark II containment sys Next rept will be provided within 60 days of ltr receipt BOUCHEY. O Washington Public Power Supply System 82/07/23 SCHMENCER: A Licensing Branch 2 Spp 14142 066 24X Fichs 50-397,82/07/23,8208020130
- 8208100072 Confirms 820727 telcon re use of ASME Code Case N-30B, "Documentation of Repairs & Replacement of Components in Nuclear Power Plants " Util will implement code case as written t approved by NRC BOUCHEY, 9 D Washington Public Power Supply System 82/08/04 E18ENHUT, D 0 Division of Licensing ip 14276 180 24X Fiche 50-377, 82/08/04, 8208100072
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re-submittal of documents to NRC Bummarires 18CFR Chapter I requirements & provides alternatives to requirements Byc list encl. EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356-332 24% Fichs. 50-000, 82/08/09, 8208070194
- 8208240101 Forwards request for add1 info re equipment qualification required prior to conducting unsite pump & valve operability review team audit tentatively planned for Sept 1982 8GHENGER.A Licensing Branch 2 62/08/07 FERGUSON,R L. Washington Public Fower Supply System 20pp 14529 262 24X Fiche: 50-397, 62/08/07, 6208240101
- 8208250472 Forwards request for add1 info on fuel rod corrector measures, per Core Performance Brench review of FBAR Notification requested within 7 days if responses cannot be submitted by 820924 SCHWENCER.A. Licensing Branch 2 82/08/09. FERGUSON.R.L. Washington Fuelic Power Supply System 3pp. 14562,266 24X Fiche 50-397,82/08/09,8208250472
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8208020250 Forwards rept on capability of Boutheast Anticline NRC request at 820518-19 meetings Rept should close out open item in SER W/a encl BOUCHEY, O D Washington Public Power Supply System 82/05/28 8CHWENCER, A Licensing Branch 2. Ip. 14152, 336 24X Fiche 50-397, 82/05/28, 8208020250
- 8208020150 Bubmits description of automatic depressurization systematicality for Pacifity in response to outstanding Issue 27 of 8ER NUREO-0892 Issue considered closed BOUCHEY.0 D Washington Public Power Supply System 82/07/01. BCHMENCHR.4 Licensing Branch 2 ip 14145 100 24X Fiche 50-397. 82/07/01. 8208020150
- 8208020151 Comments on NRC 820529 response to 820514 ltr re tormado missile protection for diesel generator exhausts. Backfitting would not justify cost Requests item be deleted from BER open item list BOUCHEY, 0 D Hashington Public Power Bupply Bystem 82/07/23, 8CHWENCER, A Licensing Branch 2 14pp. 14144-138 24X Fichs. 50-397, 82/07/23, 8208020151
- 8208040874 Forwards draft BER Comments & concurrence requested by 820727. Appropriate sections should include statements as to how review conforms to SRF (NUREO-0800). SCHERNGERA Licensing Branch 2. 82/07/27. KNIGHT, J. Assistant Director for Components & Structures Engineering JOHNSTON, M. Assistant Director for Materials & Qualifications Engineering. MULLER, D. Assistant Director for Environmental Technology. 300pp. 14227.001. 24X Fiche 50-377.82/07/27.8208040574
- 8208050141 Advises that findings from Mark III containment program to demonstrate that use of square root of sum of squares rule for combining dynamic responses acceptable for facility, per SER Section 3,9,3.1
 BOUCHEY,0 D Mashington Public Power Supply System, 62/07/28, BCHWENCER,A Licensing Branch 2, 5pp. 14241-246 24X Fiche 50-397,82/07/28,8208050141

- B20B060203 Forwards response to NUREQ-0892.6ER Outstanding Issue 8 repressure interlocks on energency core cooling injection valves Issue considered closed BOUCHEY, G D Hashington Public Power Supply System 82/07/28 SCH
- 8208110136 Forwards add1 info on SER outstanding Issue 10 re standby svc water instrumentation & control design, in response to NRC 820801 ltr Issue 10 considered closed BUUCHEY, G D Washington Public Power Supply System 82/08/02 SCHIENCER, A Licensing Branch 2 23pp 14316 241 24X Fiche 50-377, 82/08/02, 9208110136
- B20B110101 Clarifies diesel generator blög aar antake per discussion re design basis dust storm effect Response closes out BER outstanding concern BOUCHEY.G D Hashington Public Power Supply System 82/08/05 SCHNENCER, A Licensing Branch 2 2pp 14317 176 24X Fiche 50-397, 82/08/05, 8208/10101
- 8208310480 Forwards Suppl 1 to SER (NUREG-0872) in connection w/application for DL W/o encl SCHWENGER, A Licensing Branch 2 82/08/11 FERGUSON, R L Washington Public Fower Supply System 2pp 14705 077 24) Fiche 50-397, 82/08/11, 8208310480
- 6208240332 Forwards marked-up FSAR pages submitting add1 info re internally generated missiles (outside containment).per 820528 commitment Info closes outstanding SER Issue 2, NUREO-0872 BOUCHEV.O D. Hashington Public Power Supply System 62/08/12 SCHWENCER.A. Licensing Branch 2 24pp 14520 326 24X Fiche 50-397.82/08/12.8208240332
- 8208310297 Responds to S Rhow concerns raised during 020430 meeting w/ Burns & Roe in Bethesda MD Util commits to modify control circuitry of standby diesel supply breakers SER outstanding issues closed Marked-up FSAR Page 8 3-13a encl 80UCHEY, 0 D Washington Public Power Supply System 02/08/25 SCHWENCER.A Licensing Branch 2 2pp 14493-096 24X Fiche 50-397,82/08/25,8208310297
- 8208240427 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WPPSS NUCLEAR PROJECT NO 2 Docket No 50-397 (Washington Public Power Supply System) * Office of Nuclear Reactor Regulation, Director NUREG-0892 SOI 82/08/31 2009p Available at NTIS \$7 50 14592;007 24X Ficher 50-397, 82/08/31, 8208240427
- F Security, medical, emergency & fire protection plans
- 8208020205 Advises that util considering adapting Trojan station emergency preparedness plan & operating procedures to establish volcanic ashfall early warning sys & emergency plan protection measures 50UCHEY, 0 D Washington Public Power Supply System 82/07/01 SCHMENGERA Licensing Branch 2 1p, 14151 297 24X Fiche 50-397, 82/07/01,8208020235

H General correspondence

- 8208200070 Forwards corporate organizational changes effective 820810. Changes will be reflected in future revisions to FSAR & operational QA program description 80UCHEV.6 D Hashington Public Power Supply 89stem 82/08/16 NOVAK,T H Assistant Director for Licensing 4pp 14393 241 24X Fiche 30-397,82/08/16,8208200070
- K Utility Final Safety Analysis Report (FSAR) & amends
- 9208020245 Forwards Certificate of Svc for Amend 24 to FBAR Transmittal ltr dtd 820702 to Benton County Commissioners & Energy Facility Site Evaluation Council encl 1000HEV, 6 D Washington Public Fower Supply System 82/07/02 10HWENCER, A Licensing Branch 2 3pp. 14152 231 24X 1che. 50-397, 82/07/02, 8208020245
 - 08020155 Forwards util 820723 transmittel ltr & Certificate of Svc for Amend 25 to FSAR QUCHEY.0 D Washington Public Power Supply System 82/07/23, CHWENCER.A Licensing Brench 2 3pp 14144 135 24X ch# 50-397, 82/07/23, 8208020135

spection reports. IE Bulletins & correspondence

O393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) age: "Svc list enc! AN,E L Division of Engineering & Quality Assurance 82/07/16. hsclidated Edison Co of New York 87pp 14356 274 24X e 50-000,82/07/16.6204210393

- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc 11st entl JORDAN, E.L. Division of Engineering & Quality Assurance 62/07/19 Michigan, Univ. of 112pp 14358-001 24X Fiche, 50-000, 82/07/18204210399
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure ' Svr list encl UPRDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 1/2pp 1438/-001 24X Fiche 50-000.02/07/20.8204210396
- 820A210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list anci COBB.L I Division of Fuel Facilities. Materials & Bafeguards 82/07/20 consolidated Edison Co of New York 7ipp 1435/ 1176 24X Fiche 50-000.82/07/20.8204210397
- 6204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 62/07/22 Consolidated Edison Co of New York 112pp 14174;321 24X Fiche 30-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding is Vicinity of Drained & Open RCS " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance, Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl. JORDAN, E. C. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174-120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Biseves in RCB Figing at Certain Westinghouse PUR Power Plants " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance, 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 82042:0405 IE Info Notice 82-31, "Overexposure of Diver During Hort in Fuel Storage Pool " Evo list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24% Fiche 50-000,82/07/28,82042:0405
- 8208160485 Forwards IE Insp Rept 50-397/82-16 on 820719-22 No noncompliance noted BISHOP:T W Region 5. Office of Director 82/07/30 MAYLOCK:R.Q Washington Public Power Supply System 4pp 14348 269 24X Fiche 50-397:82/07/30:8208160485
- --8208160489 IE Insp Rept 50-397/82-16 on 820719-22, No noncompliance noted Major areas inspected previously identified enforcement & followup items & licenese identified 10CFR30 55s reported items ELIM.J 0. DDDS.R T Division of Resident, Reactor Project & Engineering Programs 82/07/30 5pp 14348 273 24X Fishe 50-397, 82/07/30, 8208160885
- 8208160124 Forwards IE Insp Rept 50-397/82-14 on 820607-0709 % notice of violation BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/08/02 MATLOCK.R 0 Washington Public Power Bupply System 2pp 14345 230 24X Fiche 50-397,82/08/02,8208160124
- --8208160126 Notice of violation from insp on 820607-0709 DODDS,R T Division of Resident, Reactor Project & Engineering Programs 82/08/02 8pp 14345 232 24% Fiche. 50-377, 82/08/02. 8208160124
- --8208160127 IE Insp Rept 50-397/82-14 on B20607-0709 Noncompliance noted pipe bending procedures not properly qualified & approved & prompt measures not initiated to document condition or identify nonconforming matl TOTH.A.D. FEIL.R A. DODDS,R T Division of Resident, Reactor Project & Engineering Programs 82/08/02 12pp 14345-240 24x Fiche 50-397.82/08/02.8208160124
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Syr list encl JORDAN-E L Division of Engineering & Quality Assurance, 62/08/05 Consolidated Edison Co of New York 117pp, 14388.201 24X Fiche 50-000, 82/08/05, 8204210407

S Reportable occurrences. LERs & related correspondence

- B20B240183 Final deficiency rept re defect in 35-130-200 battery thargers supplied by Power Conversion Products Inc Initially reperted on 820716 Replacement of 200 ampere Fi.F2 & F3 fuses w/300 ampere fuses recommended PATLOCK.R 0 Washington Public Power Supply System 82/08/13 EXCELENIER R Region 5. Office of Director 2pp 14517 307 24X Fiche 50-397.82/08/13.8208240183
- 82-08200108 Advises that final Deficiency Repts 22,37,40,43,49,50,53,54,60,64 & 82 re electrical cable routing, termination labeling, power supplies & GC documentation not sufficient Final rept should include GA & field GC programs to resolve items STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/08/17 MATLOCK,R G Washington Public Power Supply System 2pp 14399 165 24X Fiche 50-397,82/08/17,8208200108
- 8208300112 Interim deficiency rept re Johnson Controls design issue
 Thitfelly reported on 820720 Analysis of large bone piping &
 small bore design underway Next rept expected by 821123
 MATLOCK,R 0 Washington Public Power Supply System 82/08/18
 ENGELMEN.R H Region 5, Office of Director 2pp 14596 130 24)
 Fiche 50-397.82/08/18.8208300112
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 2207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS, M. J. Office of the Executive Director for Operations.
 82707702 Consolidated Edison Co of New York 93pp 14194 001.
 24X Fishs 50-000.82/07/02,8207080064
- 8209040085 Forwards Hydrologic & Geotechnical Engineering Branch request for info Response should be in form of amend to FEAR HERACLIA, F. J. Licensing Branch 3 82/07/13 JONES, J. A. Carolina Fower & Light Co. Spp. 14228 322 24% Fishe 50-400, 82/07/13, 8208040083
- 820B040234 Notification of 820728 meeting w/util in Raleigh, NC to 41scuss NRC questions on initial test program LICITRALE A Licensing Branch 3 82/07/22 MIRAOLIA, F. J Licensing Branch 3 3pp 14232 253 24X Fiche 50-400, 82/07/22, 8208040234
- 8208030308 Confirms 820728 & 0816-20 meetings w/NRC Meetings will address util responses to 640 Series safety review questions & discuss NSS8 & balance-of-plant scope safety review questions IFMMERMANS R Carolina Power & Light Co 82/07/29 MIRAOLIA.F. Licensing Branch 3 ip 14156 238 24X Fiche 50-400.82/07/29.8208030308
- 6208050381 Forwards info re Unresolved Safety Issues A-1, A-3, A-11, A-12, A-17, A-40, A-43, A-44, A-45, A-46, A-47 & A-46, per 820216 request Responses provide summary descriptions of programs undertaken to investigate & resolve issues MCDVFIE:M A Carolina Power & Light Co 82/07/30, DENTON, H. R 3ffice of Notlear Reactor Regulation, Director 13pp 14219-304, 24X Fiche 30-400, 82/07/30, 6208030381
- 8208Li0297 Notifies of 820816 site visit to discuss review of instrumentation & control sys Followup meeting will be scheduled.

 HiRACLIA:F.J Licensing Branch 3 82/07/30 JONES.J A. Carolina Power & Light Co ip 14332 181 24X Fichs 50-400.82/07/30.
 8208110297
- 8208170051 Forwards request for add1 info re effluent treatment sys.
 FSAR should be amended to include requested info Info
 requested by 820915 W/d enci
 MIRAQLIA.F J Licensing Branch 3. 82/07/30. JONES.J A. Carolina
 Pawer & Light Co ip. 14373.331 24X Fiche 50-400.82/07/30.
 8208170051
- 8208050284 Forwards responses to FSAR safety review questions Eleven oversite drawings encl Aperture cards are available in PDR. MCDMFFIEM A Carolina Power & Light Co 82/08/02, DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 500pp 14218:057 24X FIche 50-400,82/08/02,8208050284.
- 8208070194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24% Fiche 50-000,82/08/09, E209090194

- C Utility Environmental Report (ER), amends & correspondence
- 8208240157 Forwards responses to environ rept review Questions 240 4-7 Ltr supplis 820603 & 0714 responses Responses to Questions 240 3,291 13 & 291 15 will be submitted in mear future MCDUFFIE.M A Carolina Power & Light Co 82/08/17 DENTON, H R. Office of Nuclear Resoutation, Director 31pp 14527 034. 24X Fishs 50-400,82/08/17,8208240137
- F Security, medical, emergency & fire protection plans
- 920B190010 Summary of 820713 meeting w/util re planned responses to concerns w/fire protection POCC sys design Handauts encl
 STEFANG.JJ Licensing Branch 2 82/07/30 SCHWENCER.A Licensing
 Dranch 2 20pp 14506 320 24X Fiche 50-400.82/07/30.820B190010
- 9 Adjudicatory correspondence
- 8208050535 Brief re spent fuel transshipment supporting admittance of Contentions ? & 4 Individual, not generic, guidaline must be used for compliance w/10CFR20 [(c) Certificate of Byc encl READ, D.F. Affiliation Unknown RUNKLE, J.D. Conservation Council of North Carolina 82/08/04 Atomic Bafety and Licensing Board Panel 15pp 14213 302 24X Fiche 50~400, 82/08/04, \$208050535
- 8208120144 Response to ASLB 820713 t 14 Inquiries 1-4 CHANGE/Environ Law Project 820316 motion for separate hearings should be denied Environ effects of shipping spent fuel to Harrís.
 Brunswick or Robinson lies within ASLB jurisdiction
 BARTH-C A Hearing Branch 1 82/08/10 7pp 14319·179. 24X
 Fiche 50-400.82/08/10.8208120144
- B20Bi30143 Forwards applicant responses to joint contentions & to W Eddiemen amended contentions Also forwards applicant position on svc of documents to intervenors & answer to CHANDE/Environ Law Project Certificate of Bvc only encl DAXTER.T A Bhaw, Pittman, Potts & Troubridge DAXTER.T A Carolina Power & Light Co 82/08/10 KELLEY.J L , BRIGHT, Q O., CARPENTER.J H Atomic Safety and Licensing Board Panel App 14335 327 24X Fiche 50-400, B2/08/10, 820Bi30143
- 8208130160 Answer opposing Chapel Hill Anti-Nuclear Group Effort/ Environ Law Project 820713 renewal & reformation of 820316 motion to postpome or separate proceedings Issues before ABLB common to both units Unit 2 will not be canceled BAXTER: TA Carolina Power & Light Co BAXTER: TA Shaw, Pittman, Potts & Trowbridge 82/08/10, Atomic Safety and Licensing Board Panel 5pp 14339 032 24X Fiche 50-400, 82/08/10.8208130160
- 8208130164 Opposes ABLO 920305 memorandum & order directing applicant to sorve intervenors w/all documents relevant to proceeding Availability of documents in NRC LPDRs sufficient Transmittal letw of FSAR & snyicon rept amends to be sorved. BAXTER T.A. Carolina Power & Light Co. BAXTER T.A. Bhaw, Pittman, Potts & Trowbridge 82/08/10 7pp 14338 309 24X Fiche 30-400.82/08/10.8208130164
- 8208130181 Response in opposition to Chapel Hill Anti-Nuclear Group Effort/Environ Law Project Conservation Council of NG Kudzu Alliance & H Eddleman 820719 Joint Contention II.d re health effects Contention lacks basis
 BAXTER: T A. Carolina Power & Light Co BAXTER: T A. Bhaw, Pittman, Potts & Trowbridge 82/08/10 Atomic Bafety and Licensing Board Panel 1299. 14338 292 24X Fiche 30-400:82/08/10:8208130181
- 8208130200 Response in opposition to W Eddleman 820713 amends to Contentions 1,29,64 & 84 Contentions lack dasis & specificity required by 10cFR2,714(b) BAXFER.T A Carolina Power & Light Co BAXTER.T A Shaw, Pittman, Potts & Troubridge 82/08/10 Atomic 8afety and Licensing Board Panel 20pp 14337-127 24x Fiche 50-400.82/08/10,8208130200.
- 8208170253 Post-hearing submittal re contentions Certificate of Svc encl EDBLEMAN, W Affiliation Unknown 82/08/10 Atomic Bafety and Licensing Board Panel 18pp. 14347.118, 24X Fiche 50-400.82/08/10, 8208170253
- 8208170215 Forwards status rept on proposed contentions to aid ABLE in preparation of prehearing conference order. Certificate of Bvc encl.
 8AXTER.T. A. Shaw, Pittman, Potts & Troubridge BAXTER.T. A. Caroling Power & Light Co. 82/08/13 KELLEY.J. J. BRIGHT.Q.G., CARPENTER.J. H. Atomic Safety and Licensing Board Panel 4pp. 14362.040. 24X Fichs 50-400,82/08/13,8208170215
- --8208170221 Status rept on proposed contentions discussed during 620713-14 prehearing conference.

 BAXTER: T. A. Carolina Power & Light Co. BAXTER: T. A. Bhaw, Pittman: Potts & Traubridge 62/08/13, 13pp. 14362-044, 24X Fiche: 50-400, 82/08/13, 8208170215

- 8208240341 Response opposing applicant 820810 position on svc of documents to intervenors Lack of svc creates time delays not conductive to prompt intervenor responses Certificate of Svc encl
 EDDLEMAN.W Affiliation Unknown 82/08/17 Atomic Safety and Licensing Board Panel 4pp 14520 300 24X Fiche 50-400.82/08/17.8208249341
- 8208250227 Motion to compel applicant to serve intervenors entire filings Applicant presently serving intervenors only cover itrs of certain documents Regulations allow no such svc Certificate of Svc enci SELLS, D.R. Licensing Branch 3 82/08/20 Atomic Safety and Licensing Board Panel 3pp 1454: 358 24X Fiche 50-400,82/08/20,8208250227

Q Inspection reports: IE Bulletins & correspondence

- 8208160479 Submits supplementary response to NRC 820118 ltr reviolations noted in IE Insp Repts 50-400/81-25.50-401/81-25, 50-402/81-25 & 50-403/81-25 Reportability per 10CFR50 55e to be determined by 820702

 BANKS:HR Carolina Power & Light Co 82/06/10 O'REILLY, J P Region 2, Office of Director 2pp 14248 267 24X

 Fiche 50-400, 82/06/10, 8208160479
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSJV) Leakage " Svc list enci JORDAN,E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Syc list encl JURDAN, EL Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8208160202 Forwards IE Insp Repts 50-400/82-20 & 50-401/82-20 on 820622-25 No noncompliance noted VERRELLI.D Division of Project & Resident Programs 82/07/19 JONES J A Carolina Power & Light Co 2pp 14347 123 24X Fiche 50-400, 82/07/19, 8208160232
- --8208160242 IE insp Repts 50-400/82-20 & 50-401/82-20 on 820622-25 No noncompliance noted Major areas inspected licensee identified items. IE builetins & circulars.electrical components & sys & inspector followup items RUFF. A B . CONLOW. T E Division of Engineering & Technical Programs 82/07/13 5pp 14347 125 24X Fiche 50-400,82/07/19,8208160232
- 6208160366 Forwards IE Insp Repts 50-400/82-19 & 50-401/82-19 on 620614-17 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/07/19 JONES, J A Carolina Power & Light Co 2pp 14349 015 24X Fiche 50-400, 82/07/19, 8208160366
- --8208160371 IE Insp Repts 50-400/82-17 & 50-401/82-19 pm 820614-17 No noncompliance noted Najor areas inspected IE bulletins, QA manual & implementing procedures for RCPB & safety-related piping & components & licensee action on previous findings OIRARD, E H , ECONOMIOS N Division of Engineering & Technical Programs 82/07/08 10pp, 14349 017 24% Fiche 50-400,82/07/19,8208160366
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 90-000, 82/07/20, 8204210396
- 1204210377 IE Info Notice 82-24, "Water Leaking From U Herafluoride Overpacks" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- 2042/0398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Gvc list encl. JORDAN E L. Division of Engineering & Guality Assurance 62/07/22 Consolidated Edison Co of New York 112pp 14194,321 24X Fiche 80-000.82/07/22,8204210398
- 1208030694 Ack receipt of 820601 ltr informing NRC of steps taken to correct violations noted in 16 Investigation Repts 50-400/82-03 & 50-401/82-03 VERRELLI, D Division of Project & Resident Programs, 82/07/22 JONES, J A Carolina Power & Light Co. 1p 14194 069 24X Fiche 50-400, 82/07/22, 8208030694

- ---8.208030697 Responds to NRC 820428 ltr re violations noted in lk Investigation Repts 50-400/82-03 & 50-401/82-03 Corrective actions weld insp verified by inspector initials on inspectored by inspector and in the sequent form

 BANKE, HR Carolina Power & Light Co 82/06/01 O'REILLY, J. P. Region 2, Office of Director 5pp 14174 069 24X
 Fichs 50-400.82/07/22.8208030694
- --8208030697 Forwards IE Investigation Repts 50-400/82-03 & 50-401/82-03 on 814211-820226 & notice of violation G'REJLLY, J P Region 2. Office of Director 82/04/28 JONES, J A Carolina Pawer & Light Co. 2pp. 14194 074 24X Fiche 50-400, 82/07/22, 8208030694
- --8208030702 Notice of violation from insp on 811211-820226 * Region 2, Office of Director 82/04/28 lp 14194 076 24% Fiche 50-400.82/07/22.8208030494
- --8208030704 JE Investigation Repts 50-400/82-03 & 50-401/82-03 on 811211-820226 Noncompliance noted inspirecords did not reflect correct identity of individuals who performed weld insp & insps performed by uncertified welders VORSE, JY, ALDERSON, C E. Region Z. Office of Director 82/04/22 13pp 141-94 077 24X Fichs 50-400,62/07/22,8208030694
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grindin; in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York, 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp (4194-120-24X Fiche 50-000, 82/07/23, 8204210402
- B204210403 IE info Notice B2-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse P(WR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list and! JORDANIE L Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN.E L Division of Engineering 5 Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000.82/08/05,8204210407
- 8208160330 Ack receipt of 820722 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-400/82-05 & 50-401/82-05 Extension of commitment dats until 820820 granted

 VERRELLIA DM Division of Project & Resident Programs 82/08/05 JONES JA Carolina Power & Light Co ip 14348 028 24X Fichs 50-400,82/08/05,8208160330
- --820Bi60338 Supple 82042i response to NRC 820322 ltr re violations nated in IE Insp Repts 50-400/82-05 & 50-401/82-05 Extension requested until 820820 to complete corrective actions re Item B 2 PARSONS.R M Caralina Power & Light Co 82/07/22 O'REILLY.J P Region 2. Office of Director ip 14348 029 24% Fiche 50-400.82/08/05.8208160330

S Reportable occurrences. LERs & related correspondence

- 8208020071 Final deficiency rept re walded study on embedded strip plates [nitselly reported on 820418 All embeds an which stud failed returned to vendor for investigation Vendor will provide additinstruction to new production line personnel CHIANGIN J Carolina Power & Light Co 82/07/19 O'REILLY.J P Region 2. Office af Director App 14144 087 24% Fiche 50-400.82/07/19.8208020091
- 8208020217 Interim deficiency rept re bolted connections w/excessive gaps & ASTM A325 nuts on ASTM A490 bolts Initially reported on 820702. Test procedure designed to evaluate mismatched nuts & bolts gaps Next rept expected by 821015. CHIANOI.N J. Carolina Power & Light Co 82/07/19 O'REILLY, J P Region 2. Office of Director 2pp. 14141 081 24X Fiche 50-400, 82/07/19, 8208020217.

- 8208020369 Interim deficiency rept re discovery of ASTM A325 nuts on ASTM A490 boits in two structural connections of turbine bidg Initially reported on 820618 Evaluation continuing & should be complete by 821015 CHIANOI, N J Carolina Power & Light Co 82/07/19 O'REILLY, J.P. Region 2, Office of Director 2pp 14150 098 24X Fiche 50-400, 82/07/19, 8208020369
- R2DBOS0202 Supplemental final deficiency rept re welded studs on embedded strip places initially reported on 820716 Cover sheet w/interim rept; inadvertantly transmitted via 820719 Itr. should be replaced w/encl cover sheet CHIANGI,N J Carolina Power & Light Co. 82/07/23 0'REILLY, J P Region 2. Office of Director 2pp 14212 140 24X Fiche 50-400,82/07/23,8208090202
- 6208200039 Second interim deficiency rept re defective valve springs on diesel engines supplied by Transamerica DeLaval Initially reported on 810828 Valve springs will be replaced Next rept by Oct 1982 Also reported per Part 21 CHIANGI, N J Carolina Power & Light Co 82/07/30 0'REILLY, J P Region 2, Office of Director App 14392 240 24X Fiche 50-400, 82/07/30, 8208200039
- B20B200113 Second interim deficiency rapt re welding of 4 9 kV Class IE switchgear & seismically designed 6 9 kV Nonclass IE switchgear Initially reported on B20331 Also reported per Part 21 Final rept expected by B20B31 CHIANGI,N J Carolina Power & Light Co B2/07/30 O'REILLY, J P Region 2, Office of Director 5pp 14393 313 24X Fiche 50-400, B2/07/30, B206200113
- DOCPET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltv to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CRGR Svc list encl
 DIRCKB.41 J Office of the Executive Director for Operations.
 82/07/02 Consolidated Edison Co of New York 93pp. 14194 001
 24% Fiche 50-000.82/07/02.8207080064
- 620B0400B5 Forwards Hydrologic & Geotechnical Engineering Branch request for info Response should be in form of amend to FSAR HIRAGLIA.F J Licensing Branch 3 82/07/13 JUNES.J A Caroline Power & Light Co 5pp 1422B 322 24X Fiche 50-400,82/07/13,820B0400B5
- 8208040234 Notification of 820728 meeting w/util in Raleigh, NC to discuss NRC questions on initial test program LICITRA.E A Licensing Branch 3 82/07/22 MIRAGLIA.F J Licensing Branch 3 3pp 14232 253 24X Fiche 50-400.82/07/22, 8208040234
- 8208030308 Confirms 820728 & 0816-20 meetings w/NRC Meetings will address util responses to 640 Series safety review questions & discuss NSS8 & balance-of-plant scope safety review questions YIMMERMAN.6 R Carolina Power & Light Co. 62/07/29 MIRAGLIA.F Licensing Branch 3 1p 14136 238 24X Fiche 50-400.82/07/29, 6208030308
- 820B050381 Forwards info re Unresolved Bafety Issues A-1, A-3, A-11, A-12, A-17, A-40, A-43, A-44, A-45, A-46, A-47 & A-48, per 820216 request Responses provide summary descriptions of programs undertaken to investigate & resolve issues HCDUFFIE, M A Carolina Power & Light Co 82/07/30 DENION, H R OFFice of Nuclear Reactor Regulation, Director 13pp 14219, 304 24x Fiche 30-400, 82/07/30, 8208030381
- 8208\$10297 Notifies of 820816 site visit to discuss review of instrumentation & control sys Followup meeting will be scheduled MIRAGLIA, F.J. Licensing Branch 3 82/07/30 JONES, J.A. Carolina Power & Light Co. 1p 14332 181 24X Fiche 50-400,82/07/30, 82/0810297
- 820B170051 Forwards request for add1 info re effluent treatment mys FSAR should be amended to include requested info Info requested by 820915 W/o encl HTRAGLIA.F J Licensing Branch 3 B2/07/30 JONES.J A Carolin Power & Light Co 1p 14373 331 24X Fiche 50-400.82/07/30. B208170051
- 8208050284 Forwards responses to FSAR safety roview questions, Eleven oversize drawings encl Aperture cards are available in PDR. NCDUFFIE.N A Carolina Power & Light Co. 82/08/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director 500pp 14218 05/24X Fishe 50-400, 82/08/02,8208050284

- 8208090194 Openeric Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT.D 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000.82/08/09.8208090194
- C Utility Environmental Report (ER), amends & correspondence
- 8208240157 Forwards responses to environ rept review Questions 240 4-9. Ltr suppls 820603 & 0714 responses Responses to Questions 240 3.291 13 & 291 15 will be submitted in near future HCBUFFIE,M A Carolina Power & Light Co 62/08/17 DENTON,H R Office of Nuclear Reactor Regulation, Director 31pp 14527 034 24X Fiche 50-400,82/08/17,8208240157
- F Security, medical, emergency & fire protection plans
- 8208190010 Summary of 820713 mosting w/util rs planned responses to concerns w/fire protection PGCC sus design Handouts encl STEFANO.J J Licensing Branch 2 82/07/30 SCHWENCER.A Licensing Branch 2 20p 14506 320 24X Fiche 50-400,82207/30.8208190010
- 9 Adjudicatory correspondence
- 8208050535 Brief re spent fuel transshipment supporting admittance of Contentions 7 & 4 Individual, not general, guideline must be used for compliance w/100FR20 1(c) Certificate of Svc encl READ, D F Affiliation Unknown RUNKLE, J D Conservation Council of North Carolina 82/08/04 Atomic Safety and Licensing Board Panel 15pp 14213 302 24X Fishe 50-400, 82/08/04, 8208050535
- 8208120144 Response to ASLB 820713 & 14 Inquiries 1-4 CHANGE/Environ Law Project 820316 motion for separate hearings should be denied Environ effects of shipping spent fuel to Harries Brunswick or Robinson lies within ASLB jurisdiction BARTH-C A Hearing Branch I 82/08/10 7pp 14319 179 24X Fiche 50-400.82/08/10.8208120144
- 820B130143 Forwards applicant responses to joint contentions & to W Eddleman amended contentions Also forwards applicant position an svc of documents to intervenors & answer to CHANOE/Environ Law Project Cprtificate of Bvc only encl BAXTER. T A Shaw, Pittman, Potts & Trowbridge BAXTER. T A Carolina Power & Light Co BZ/08/10 KELLEY, J L . BRIGHT. G G . CARPENTER, J H . Atomic Safety and Licensing Board Panel App 14335 329 24X Fichs 50-400, 82/08/10, 8208130143
- 820Bi30160 Answer opposing Chapel Hill Anti-Nuclear Group Effort/
 Environ Law Project 820713 renewal & reformation of 820316
 motion to postpane or separate proceedings Issues before
 ABLB comman to both units Unit 2 will not be canceled
 BAXTER, T A Carolins Power & Light Co BAXTER, T A Shaw, Pittman,
 Potts & Troubridge 82/09/10, Atomic Safety and Licensing Board
 Panel. 5pp 14339 032 24X Fiche 50-400, 02/08/10, 8208130160
- 8208130164 Opposes ABLB 820305 memorandum & order directing applicant to serve intervenors w/all documents relevant to proceeding Availability of documents in NRC LPDRs sufficient Transmittal ltrs of FSAR & environ rept amonds to be served BAXTER.T.A. Carolina Power & Light Co. BAXTER.T.A. Shaw. Pittman, Potts & Troubsidge 82/08/10 7pp 14338 309 24X Fiche 50-400,82/08/10,6208130164
- 8208130181 Response in opposition to Chapel Hill Anti-Nuclear Group Effort/Environ Law Project Conservation Council of NC, Kudiu Alliance & W Eddieman 820713 Joint Contention II d re health effects Contention lacks basis.

 BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trombridge, 82/08/10 Atomic Safety and Licensing Board Panel 12pp 14338, 272 24X Fiche 50-400, 82/08/10, 82/08/30181
- 8208130200 Response in opposition to W Eddleman 820713 amends to Contentions 1,29,64 & 84 Contentions lack basis & specificity required by 10CFR2 714(b) BAXTER,T A Carolina Power & Light Co DAXTER,T A Shaw, Pittman, Potts & Troubridge 82/08/10 Atomic Safety and Licensing Doard Panel 20pp. 14339 127 24X Fiche. 50-400,82/08/10,8208130200
- 8208170253 Post-hearing submittal re contentions Certificate of Svc enc.1 EDDLEMAN,W Affiliation Unknown 82/08/10 Atomic Bafety and Licensing Board Panel 18pp 14367 118 24X Fiche 50-400.82/08/10, 8208170253

- 8208170215 Forwards status rept on proposed contentions to aid ASLB in preparation of prehearing conference order Certificate of Syc encl
 BAXTER, T A Bhaw, Pittman, Potts & Trowbridge BAXTER, T A
 Carolina Power & Light Co. 82/08/13 KELLEY, J L , BRIGHT O D ,
 CARPENTER, J H Atomic Bafety and Licensing Board Panel 4pp
 14362:040 24X Fichs 50-400.82/08/13.8208170215
- --8208170221 Status rept on proposed contentions discussed during 820713-14 prehearing conference BAXTER.T A Carolina Power & Light Co BAXTER.T A Shaw, Pittman, Potts & Troubridge 82/08/13 13pp 14362 044 24) Fiche: 50-400,82/08/13,8208170215
- 8208240341 Response apposing applicant 620810 position on svc of documents to intervenors lack of svc creates time delays not conductive to prompt intervenor responses Certificate of Svc encl
 EDDLEMAN. W Affiliation Unknown 82/08/17 Atomic Safety and Licensing Board Panel 4pp 14520 300 24X Fiche 50-400, 82/08/17, 8208240341,
- 8208250227 Motion to compel applicant to serve intervenors entire fillings Applicant presently serving intervenors only cover itrs of certain documents Regulations allow no such svc Certificate of 8vc enci SELLS,D E Licensing Branch 3 82/08/20 Atomic Bafety and Licensing Board Panel 3pp. 14541 358 24X Fiche 50-400.82/08/20, 8208250227
- 8208270370 Forwards ALAB-687 NRC position in instant proceeding that contentions should not be conditionally admitted subj to discovery or devalopment of future papers coincides w/ASLAB decision.

 BARTH, C. A. Hearing Branch i 82/08/26 KELLEY, J. L. CARPENTER, J. H., BRIGHT, G. D. Atomic Safety and Licensing Board Panel ip. 14564 260 24X Fiche 50-440,82/08/26,8208270370
- Q. Inspection reports, IE Bulletins & correspondence
- 8208160479 Submits supplementary response to NRC 820118 ltr reviolations noted in IE insp Repts 50-400/81-23, 50-401/81-25, 50-402/81-25 & 50-403/81-25 Reportability per 100FR50 55e to be determined by 820702 SANKSHR. Carolina Power & Light Co. 82/06/10 O'REILLY, J.P. Region 2. Office of Director 2pp 14348 267 24X Fichs. 50-400, 82/06/10, 8208160479
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage." Byc Iist encl.
 JORDAN-E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co. of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for Externel Radiation." Syc list encl JORDAN, E. D. Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ. of 112pp 14358-001, 24X Fiche 50-000, 82/07/19, 8204210395
 - 08160232 Forwards IE Insp Repts 50-400/82-20 & 50-401/82-20 on 820622-25 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 82/07/19 JONES, J. A. Carolina Power & Light Co 2pp 14347 123 24X Fiche: 50-400, 82/07/19, 8208160232
- -8208i60242 IE Insp Repts 50-400/82-20 & 50-401/82-20 on 820622-25 No noncompliance noted. Major areas inspected: licensee identified items. IE bulleting & circulars. selectrical components & says & inspector followup items RUFF, A B . CONLON.T E. Division of Engineering & Technical Programs 82/07/13 5pp. 14347 125 24X Fiche 50-400.82/07/19, 8208i60232.
- 3208160366 Forwards IE Insp Repts 50-400/82-19 & 50-401/82-19 an B20614-17. No noncompliance nated VERRELLI, D. H. Division of Project & Resident Programs 82/07/19, JONES, V.A. Caralina Power & Light Co. 2pg. 14349 015, 24X Fiche: 50-400, 82/07/19, 8208160366
- --8208160371 IE Insp Repts 50-400/82-19 & 50-401/82-19 on 820614-17 No moncompliance noted Major areas inspected IE bulletins, QA manual & implementing procedures for RCPS & safety-related piping & components & licensee action on previous findings OIRARD, E. H., ECONOMOS, N. Division of Engineering & Technical Programs. 82/07/08, 10pp, 14349:017 24% Fiche 50-400-82/07/19, 8208160366.

- B204210376 IE Info Notice B2-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, B2/07/20, B204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list enc! COBB.L ! Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consol/dated Edison Co of New York 71pp 14357 274 24X Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Syr List encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp, 14194-321 24x Fiche 50-000/82/07/22/8204210398
- 8208030694 Ack receipt of 820601 ltr informing NRC of steps taten to correct violations noted in 1E Investigation Repts 50-400/82-03 & 50-401/82-03 VERRELLI, D. Division of Project & Resident Programs 82/07/22 JUNES, J. A. Carojina Power & Light Co. ip. 14194-068. 24X Fiche. 50-400, 82/07/22, 8208030694
- --8208030697 Responds to NRC B20428 ltr re violations noted in IE Investigation Repts 50-400/82-03 & 50-401/82-03 Corrective actions weld insp verified by inspector initials on insp request form

 BANKE: H R Carolina Power & Light Co 82/06/01 O'REILLY, J. Region 2. Office of Director 5pp 14194 069 24X
 Fishe 50-400, 82/07/22.8208030694
- --8208030699 Forwards IE Investigation Repts 50-400/82-03 & 50-401/82-03 on 811211-820226 & natice of violation O'REILLY.J P Region 2. Office of Director 82/04/28 JONES.J A Carolina Power & Light Co. 2pp 14194 074 24X Fiche: 50-400.82/07/22.8208030694
- --8208030706 IE Investigation Repts 50-400/82-03 & 50-401/82-03 on 811211-820226. Noncompliance noted insp records did not reflect correct identity of individuals who performed weld insp & insps performed by uncertified welders VORSE, J Y . ALDERSON.C E Region 2. Diffice of Director, 82/04/22 15pp 14194 077 24X Fiche 50-400.82/07/22,8208030694.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 92/07/23 Consolidated Edison Co. of New York 122pp 14380 113 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sieves in RCG Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24X Fichs 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Natice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl URDAN.E L. Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28,8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl URDANA E L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 9208160330 Ack receipt of 820722 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/82-05 & 50-401/82-05 Extension of commitment date until 820820 granted.

 VERRELLIAD M Division of Project & Resident Programs 82/08/05 JONES, J A Carolina Power & Light Co ip. 14348 028 24X Fiche 50-400, 82/08/05, 8208160330
- --B208160338 Supple 820421 response to NRC 820322 ltr re violations noted in IE Insp Repts 50-400/82-05 & 50-401/82-05 Extension requested until 820820 to complete corrective actions re Item 8 2
 PARSONS: R M Carolina Power & Light Co. 82/07/22, 0'REILLY, J P Regton 2, Office of Director 1p 14948 029 24X Fiche 50-400,82/08/05,8208160330

D-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3 ation/construction stage documents & correspondence

34 Forwards responses to FSAR safety review questions Eleven re drawings encl Aperture cards are available in PDR IE, N A Carolina Power & Light Co 82/08/02 DENTON, H R of Nuclear Reactor Regulation, Director 500pp 14210

tion reports. IE Bulletins & correspondence

'9 Submits supplementary response to NRC 820118 ltr ons noted in IE Insp Repts 50-400/81-25.50-401/81-2 '81-25 & 50-403/81-25 Reportability per 10CFR50 55e Tetermined by 820702 R R Carolina Power & Light Co B2/06/10 O'REILLY, J P 2. Office of Director 2pp 14348 267 24X 10-400, 82/06/10. 8208160479

1-403 BHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4 ation/construction stage documents & correspondence

4 Forwards responses to FSAR safety review questions Eleven p drawings encl Aperture cards are available in PDR E.M A. Carolina Power & Light Co. 82/08/02 DENTON, H R of Nuclear Reactor Regulation. Director 500pp 14218.057 he 50-400.82/08/02.8208050284

tion reports. IE Bulletins & correspondence

P Bubmits supplementary response to NRC 82011B ltr re ons noted in IE Insp Repts 30-400/B1-25.90-401/B1-25, 81-25 & 50-403/B1-25 Reportability per 10CFR50 55e etermined by 820702

R Carolina Power & Light Co 62/06/10 D'REILLY, 2, Office of Director 2pp 1434B 267 24X 0-400.82/06/10.8208160479

D'REILLY, J. P.

-404 NORTH ANNA POWER STATION, UNIT 3 ation/construction stage documents & correspondence

4 Generic 1tr to all licensees of operating plants, applicents & holders of GP re Commission approved charter for C list encl
W J Office of the Executive Director for Operations
Consolidated Edison Co of New York 93pp 14194,001
he 50-000,82/07/02,8207080064

ty, medical, emergency & fire protection plans

3 Forwards IE Insp Repts 50-338/82-15,50-339/82-15 & 82-09 on 820603 No noncompliance noted C Division of Project & Resident Programs 82/07/07 O.R H Vinginia Electric & Power Co 2pp 14154:211 D-338,82/07/07,8208030393 82/07/07

398 IE Insp Repts 50-338/82-15.50-339/82-15 & 50-404/82-09 on 3 No noncompliance noted Major areas inspected ency planning specifically interface between licenses & nding Region 2 organization at smargency facilities, 3.P A Division of Emergency Preparedness & Operational rt 82/07/07 4pp 14154 213 24X Fiche 50-338,82/07/07,20303 rt 82/07/07 30393

tion reports. IE Bulletins & correspondence

3 Forwards IE Insp Repts 50-338/82-15,50-339/82-15 & 32-07 on 820603 No noncompliance noted C Division of Project & Resident Programs 82/07/97. 2.R H Virginia Electric & Power Co. 2pp 14154-211. 24X 3-338,82/07/07,8208030393

398 IE Insp Repts 50-308/82-15.50-339/82-15 & 50-404/82-09 on aro in insp ments oursing/Berloroursin/Berlo & 50-404/82-09

3 No noncompliance noted Major areas inspected:
ency planning specifically interface between licensee &
nding Region 2 organization at emergency facilities.
2.P.A., JENKINE, G.R. Division of Emergency Preparedness &
rional Support 82/07/07 4pp. 14153-213 24X
50-338,82/07/07,8208030393

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage "Svc list enc] JORDAN,E L Division of Engineering & Quality Assurance B2/07/ Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393

8204210395 IE Info Notice 81-26.Part 3.Suppl 1, "Clarification of Placement of Personnol Huntboring Devices for External Radiation" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/19 Hithigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks" Svc list encl COBR.L | Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000.82/07/20,8204210397

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbins Exhaust Check Valve Failures" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321, 24X Fiche 50-000, 82/07/22, 8204210398.

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Brained & Open RCS" Bvc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380.115 24X Fiche 50-000.82/07/23,8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PURS " Svc Jist encl JORDAN E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche: 50-000, 82/07/23, 8204210402

B204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants" Byo list encl JORDAN E L Division of Engineering & Quality Assurance B2/07/26 Consolidated Edison Co of New York IZipp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403

8204210405 IE info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Fool " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405

8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl.

JORDAN,E L. Division of Engineering & Quality Assurance, 82/08/05
Consolidated Edison Co of New York 117pp 14388.201 24X
Fiche 30-000,82/08/05.8204210407

DUCKET SO-406 TUBKEGEE INST RESEARCH REACTOR

@ Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Honitoring Devices for External Radiation " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ of 112pp 14358 001. 24X Fiche 50-000, 82/07/19, paralleles." 8204210375

DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

Q Inspection reports, IE Builetins & correspondence

82080A0147 Ack receipt of 820707 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-407/82-01
8EIDLE-W C Division of Resident Reactor Project & Engineering Programs 82/08/02 JACOBS, H R Utah. Univ of ip 14239 300 24x Fiche: 50-407, 82/08/02, 8208060147.

--8208060180 Responds to NRC 820611 ltr re violations noted in IE Insp. Rept 50-407/62-01 Corrective actions operators cautioned to sign all log book entries & Forms Bi-83 revised to make entries at beginning of checkout procedure JACO86:H R, Utah, Univ of, 82/07/07 SEIDLE,W.C Bivision of Resident, Reactor Project & Engineering Programs ip 14237.301 24X Fiche: 50-407,82/08/02.8208060147

- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

 F Security, medical, energency & fire protection plans
- 8208190252 Submits list of proposed objectives for planned 820803 joint agency emergency preparedness elercise as recommended by FEMA/NRC milestones for exercise & critiques SHIMSHAK,R E Dairyland Power Cooperative 82/05/20 HIND. J A Division of Emergency Preparedness & Operational Support 3pp 14388 171 24X Fiche 50-409.82/05/20.8208190252
- 82080A0306 Releases public version of revised radiological emergency response plan implementing procedure FELTON, J M Bivision of Rules and Records 82/08/03 Document Management Branch 1p 14244 213 24X Fiche 50-409.82/08/03.82080&0306
- --8208060307 Forwards public version of Issue 5 to Radiological Emergency Response Plan Implementing Procedure EPP-2, "Organization & Operations During Emergencies"

 LINDER:F Dairyland Power Cooperative 82/07/22 CRUTCHFIELD.D Operating Reactors Branch 5 1p 14244 216 24X Fiche 50-409.82/08/03.8208060306
- --8208060312 Public version of Issue 5 to Radiological Emergency Response Plan Implementing Procedure EPP-2, "Organization & Operations During Emergencies" 4 Dairyland Power Conperative 82/07/01 64pp 14244 217, 24X Fiche 50-409, 82/08/03, 8208060306

G. Adjudicatory correspondence

- 8208040032 Responds to ABLB 820702 momorandum re NRC calculation of plant 85E magnitude Commission Papers SECY-76-345, SECY-77-539 & BECY-77-361 & related documents showing Commission approval of SEP program encl W/o encl WOODHEAD.C P Hearing Branch 1 82/07/30 BECHHOEFER.C., DECKER.R S. ANDERSON,O C. Atomic Sefety and Licensing Board Panel 3pp. 14189 152 24X Fiche 50-409.82/07/30.8208040032
- 8208040213 Hemorandum & Order LBP-82-58, granting NRC amended motion & util motion for summary disposition of all environ contentions in full-term OL proceeding NRC FES (NUREG-0191) modified as provided.

 8ECHNOEFER C. ANDERSON.O C. DECKER, R. B. Atomic Safety and Licensing Dozef Pansl. 82/08/02 Office of the Executive Legal Director 33pp. 14188 221 24X Fiche.50-409.82/08/02.8208040213
- 820Bii0152 Notice of ASLAS reconstitution SF Ellperin chairman & JH Buck & TS Moore, members BHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 82/08/09 Ip. 14314 285 24X Fiche 50-409.82/08/09.8208110152
- 8208200188 Forwards L Reiter, J Kimball & MT Russell affidavits
 responding to questions in ASLB 820702 memorandum re ASLB
 sua sponts seismic issue
 HDDDH&AD, C P Hearing Branch 1 82/08/18 BECHHOEFER, C .
 DECKER, R. S . ANDERSON, G C Atomic Safety and Licensing Board Panel
 1p. 14377 276. 24% Fiche 30-409.82/08/18.8208200188
- --B208200193 Affidavit of L Reiter & J Kimball, responding to questions in ABLB 820702 memorandum Deterministic study completed by L Reiter Hagnitude of earthquake intensity appropriate to plant discussed REITER, L KIMBALL, J Geosciences Branch 82/08/12 7pp 14999, 227. 24X Fiche 50-409, 82/08/18, 8208200189
- --8208200199 Affidavit of WT Russell that SEP seismic methodology (site specific spectra program) provides acceptable rationale for departure from current licensing criteria RVBSELL, WT Bystematic Evaluation Program Branch 82/08/13 4pp 14399 284 24X Fiche 50-409,82/08/18.8208200188
- 8208240204 Order advising that any party may respond to NRC 820818 affidavits on ABLB seismic questions & matl submitted by NRC 820730 ltr. Fillings due by 820713 BECHHOEFER.C. Atomic Bafety and Licensing Board Panel 1p. 14519 083. 24X Ficher 50-409, 82/08/20, 8208240204
- P Operating license stage documents & correspondence
- B207080064 Generic 1tr to all licenses of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKELW J. dffice of the Executive Director for Operations
 B2/07/02. Consolidated Edison Co of New York 93pp 14194 001
 24% Figher 50-000.B2/07/02.B207080064

- 8208060269 Forwards "Sargent & Lundy Rept Project 6101-32," in response to 790807 request for add1 info re SEP Topic III-7 D. "Design Criteria. Load Combination & Reactor Cavity Design Criteria."

 LINDER, F. Dairyland Power Cooperative 82/07/20 CRUTCHFIELD, D. Derating Reactors Branch 5 ip 14239 358 24X Fiche 50-407, 82/07/20, 8208060269
- --8208060271 "Bargent & Lundy Rept Project 6101-32 " * Sargent & Lundy, Inc 80/06/04 16pp 14239 359 24X Fiche 30-409, 82/07/20, 8208060269
- 8208120218 Forwards "Seismic & Structural Analysis for LACEWR Containment Bldg," Revision O LINDER: F Dairyland Power Cooperative 82/07/22 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 14362 122 24X Fiche 50-409, 82/07/22, 8208120218
- --8208120219 "Seismic & Structural Analysis for LACBWR Containment Bldg," Revision O MORTIEN,T W., FINNIAN.C F., PALENT, V. Nuclear Energy Service. Inc 81A0049 R00 82/07/28 294pp 14362 126 24X Fiche 50-409,82/07/22,8208120218
- --8208170100 "Seismic & Structural Analysis for LaCrosse DWR Turbine Bldg " MORTIEN,T W , FINNIAN,C F , POTENT, V Nuclear Energy Service, Inc 81A0048 R00 82/07/27 150pp 14363 058 24X Fiche 50-409.82/07/22,8208120218
- --B20B170112 "Seismic & Stress Analysis of LACBWR 14-Inch Shutdown Condenser Vent Piping Sys V CAO,N, MORTIEN.T W. FINNIAN.C F Nuclear Energy Service, Inc 81A0051 ROD 82/07/27 56pp 14363 273 24X Fiche 50-409, B2/07/22, 820
- --8208170119 "Seismic & Structural Analysis for LaGrosse BWR 1-9 Diesel Generator Bldg " HUSAIN.J. FINNIAN,C F Nuclear Energy Service, Inc 81A0047 ROO 82/01/22 27pp 14363 329 24% Fiche 50-409,82/07/22, 8208120218
- ---B20B170121 "Beismic & Structural Analysis for LaCrosse DWR Shutdown Condenser Platform " HU5AIN.J. FINNIAN.C F Nuclear Energy Service, Inc. 81A0045 R00 B2/01/20 31pp 14363 356 24X Fiche 50-409, 82/07/22, 820B120218
- --8208170125 "Sgismic & Structural Analysis for LaCrosse BWR Shutdown Condenser," Revision 1, HUSAIN,J, FINNIAN,C F Nuclear Energy Service, Inc. BiA0044 ROI Bi/11/13 89pp 14364 025 24X Fichs 50-409,82/07/22, 8208120218
- --8208170131 "Seismic & Structure1 Analysis of LACBWR Stack Using NRC Site-Specific Oround Response Spectra " HOSTETLER, M., RUMPF.R., FINNIAN.C F. Nuclear Energy Service, Inc B1A0046 ROO B2704/01 27pp 14364 115 24X Fichs 50-407,82/07/22.8208120218
- 8208030234 Forwards request for add1 info re NUREG-0612, "Control of Heavy Loads" Interim Protection Item 1.8WR STS encl CRUTCHFIELD.D Operating Reactors Branch 5 82/07/28 LINDER, F. Dairyland Power Cooperative 3pp 14158 299 24X Fiche 50-409, 82/07/28, 8208030234
- --8208030237 8T8 Pages 3/4 9-8 & 3/4 9-9 re refueling operations. 4 General Electric Co 82/07/28 3pp 14158 302 24X Fiche 50-409,82/07/28,8208030234
- 8208050273 Forwards evaluation of SEP Topic 11-4 F. "Settlement of Foundations & Buried Equipment "Foundations not expected to experience excessive settlements under static or dynamic conditions CRUTCHFIELD, D. Operating Reactors Brench 5 82/07/27 LINDER, F. Dairyland Power Cooperative 12pp 14210 136 24X Fiche. 50-409; 82/07/29, 8208050273
- 8208060270 Forwards Amend 29 to License DPR-45, safety evaluation & notice of issuance & availability Amend changes Tech Specs in response to licensee 810319 & 0924 submittals recontainment integrity & high radiation areas CRUTCHFIELD, D Operating Reactors Branch 5 82/07/30 LINDER, F Dairyland Power Cooperative 4pp 14241 178 24X Fiche 50-409, 82/07/30, 8208060870
- --B208060275 Amend 29 to License DPR-45, chenging Tech Specs recontainment integrity & high reduction areas CRUTCHFIELD, D. Operating Reactors Branch 5 82/07/30. 6pp. 14241 182 24X Ficher 50-409, 82/07/30, 8208060270

- --8208060280 Safety evaluation supporting Amend 27 to License DPR-45
 Office of Nuclear Reactor Regulation, Director 82/07/30 6pp
 14241 188 247 Ficho 50-409,82/07/30,8208060270
- --8208060282 Notice of issuance of Amend 29 to License DPR-45 CRUTCHFIELD.D Operating Reactors Branch 5 82/07/30 2pp 14241 194 24X Fiche 50-409, 82/07/30,8208060270
- 8208100180 Submits corrections to draft evaluation of SEP Topic VI-2 D,
 "Mass & Energy Release for Possible Pipe Break Inside
 Containment" & VI-3, "Containment Pressure & Heat Removal
 Capability "
 LINDER: F Dairyland Power Cooperative 82/08/04 CRUTCHFIELD, D
 Operating Reactors Branch 5 2pp 14278 219 24X
 Fiche 30-407, 82/08/04, 8208100180
- 8208100107 Forwards evaluation of util response to SEP Topic XV-19, "LOCA Resulting From Spectrum of Postulated Piping Breaks Within RCPB " Plant meets current licensing criteria for sys aspects of topics CRUTCHFIELD, D Derating Reactors Branch 5 82/08/06 LINDER, F Dairyland Power Cooperative App 14297 290 24X Fiche 50-407, 82/08/06. 8208100109
- 8208100111 Forwards description of reactor liquid & containment bldg atmospheric sample sys.per NUREG-0737. Item II D 3, "Post-Accident Sampling Sys " Two oversize drawings encl Aperture cards are available in PDR LINDER.F Dairyland Power Cooperative 82/08/06 CRUTCHFIELD, D Operating Reactors Dwanch 5 16pp 14298 237 24% Fiche 50-409,82/08/06.8208100111
- 8208120075 Forwards final evaluation of licensee response to SEP Topic XV-18, "Radiological Consequences of Main Steam Line Failure Outside Containment" Facility design meets acceptance criteria for topic CRUTCHFIELD.D Operating Reactors Branch 5 82/08/06 LINDER, F Dairyland Power Cooperative Bop 14327 177 24X Fichs 50-409,82/08/06,8208120075
- 8208120169 Forwards evaluation of util responses to SEF Topic XV-7.
 "Loss of Forced Coolant Flow Reactor Coolant Pump Rotor
 Seizure, Reactor Coolant Pump Shaft Break LACBUR "
 Assessment acceptable
 CRUTCHFIELD, D. Operating Reactors Branch 5 82/08/06 LINDER, F
 Dairyland Power Cooperative 12pp 14327 001 24X
 Fiche 50-409, 82/08/06, 8208120169
- 8208120205 Forwards safety evaluation for SEP Topic XV-14, "Inadvertent Operation of ECCS That Increases Reactor Coolant Inventory," based on util 810825 topic assessment Licensee conclusions valid CRUTCHFIELD, D. Operating Reactors Branch 5 82/08/06 LINDER, F. Dairyland Power Cooperative 7pp 14324 262 24X Fiche 50-407, 82/08/06, 8208120205
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT.D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 30-000.82/08/09, 8208090194
- 8208200066 Forwards updated LER 82-006/01X-1 LINDER: F Dairyland Power Cooperative 82/08/10 KEPPLER, J. G Region 3. Office of Director 2pp. 14393 026 24X Fiche 30-409.82/08/10.8208200066
- ---820B200083 "LACBUR Cycle 7 Fuel Performance & Finalized Refueling Plan for Cycle 8 " RAFFETY.S.J., BRANDT.M Dairyland Power Cooperative BUCK.P. Nuclear Energy Service, Inc. LAC-TR-112 82/07/31 16pp 14393 029 24x Fiche 50-409,82/08/10.8208200066
- 8208240364 Forwards evaluation of SEP Topic III-5 B. "Pipe Break Outside Containment." per ubil 810629 SER Plant adaquately protected from effects of pipe break subj to clarification of pipe whip damage criteria & jet implingement model CRUTCHFIELD. D. Operating Reactors Branch 5 82/08/12 LINDER, F Dairyland Power Cooperative 15pp 14520 177 24X Fiche 50-409,82/08/12.8208240364
- 8208240421 Forwards avaluation of SEP Topic II-4, E, "Dam Integrity." Failure of US Corps of Engineers Lock & Dam B would not adversely affect safety of facility Response requested within 30 days CRUTCHFIELD, D Operating Reactors Branch 5. 82/08/16, LINDER, F Dairyland Power Cooperative 9pp 14524 022 24X Fichs 50-409.82/08/16,8208240421

- 8208270289 Forwards safety evaluation rept on SEP Topit III-4 A, "Tornado Missiles" Sufficient protection provided to insure plant safety & integrity from effects of tornado missiles LINDER, F Dairyland Power Cooperative 82/08/16 CRUTCHFIELD, D Operating Reactors Branch 5 9pp 14564 183 24X Fiche 50-409, 82/08/16, 8208270289
- 8208200013 Forwards revised safety evaluation for NURED-0737, Item II K 3 19, "Interlock Recirculation Pump Mod" Corrections do not alter 820427 conclusions Facility controls acceptable CRUTCHFIELD, D Operating Reactors Branch S 82/08/17 LINDER, F Dairyland Power Cooperative 7pp 14392 232 24X Fiche 30-409: 82/08/17. 8208200013
- 820B200178 Informs that commitments & exceptions to requirements of Reg Guide 1 38, Revision 1 & Reg Guide 1 146, in response to Deneric Ltr B2-01 acceptable CRUTCHFIELD.D Operating Reactors Branch 5 B2/08/17 LINDER, F Dairyland Power Cooperative 2pp 14500 128 24X Fiche 50-407,82/08/17,8208200178
- 8208270490 Forwards safety evaluation of SEP Topic III-4 D re site proximity missiles including aircraft based on roview of util safety assessment transmitted by 810915 Itr Risk of missile impacts from external explosions extremely remote CRUTCHFIELD.D Operating Reactors Branch 5 82/08/23 LINDER, F Dairyland Power Cooperative 5pp 14565 347 24% Fiche 50-407.82/08/23.8208270480
- 8208270186 Forwards safety evaluation of util 820305 safety easessment for SEP Topic XV-5, "Loss of Normal Feedwater Flow "
 Licensee analysis acceptable Evaluation will be input to integrated assessment for facility CRUTCHFIELD, D Operating Reactors Branch 5 82/08/24 LINDER, F Dairyland Power Cooperative 5pp 14363 201 24X Fiche 50-409, 82/08/24, 8208270186
- 8208310374 Provides info re characteristics & installation of special lifting devices per outlined ANRI stds in response to 820729 request No Tech Spec or NUREG-0612 changes proposed to control heavy loads in FESU program LINDER: F Dairyland Power Cooperative 82/08/25 CRUTCHFIELD, D Operating Reactors Branch 5 7pp 14692 116 24X Fiche 50-409, 82/08/25, 8208310374
- 8208310375 Requests 30-day delay in responding to NRC 820604 requests
 Delay desired due to lack of info supplied Util not in
 possession of NUREC-0606 or NUREC-0649 necessary to complete
 response
 LINDER.F Deiryland Power Cooperative 82/08/25 CRUTCHFIELD.D
 Operating Reactors Branch 5 ip 14692 115 24X
 Fiche 50-407, 82/08/25, 8208310375
- 8208310303 Forwards BEF review of safe shutdown sys & comments on NRC 820307 ltr transmitting safety evaluation of BEP Topics III-1. "Classification of Structures, Components & Sys" & VII-3. "Safety Shutdown Sys" LINDER, F Dairyland Power Cooperative 82/08/26 CRUTCHFIELD, D Operating Reactors Branch 5 44pp 14687 356 24X Fiche 50-407,82/08/26,8208310303
- Q Inspection reports, IE Bulletins & carrespondence
- 8208040033 Ack receipt of 811223 ltr responding to 811022 notice of violation & proposed imposition of civil penalties No adequate reasons Stated why penalties should not be imposed Util has poor record of adherence to procedures DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/05/18. LINDER, F W Datry land Power Cooperative 7pp 14236 036 24% Fithe 50-409.82/05/18.8208040033
- --B208040035 firder imposing civil monetary penalty resulting from 810501-31 insp which revealed mod to pressure sensing line from containment bleg which temporarily disabled automatic actuation signal for three safety-related components DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/05/18 Dairyland Power Cooperative 3pp. 14236 043 24X Fiche 50-409,82/05/16.8208040033.
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (HBIV)
 Leakage " Svc list encl
 JURDAN.E L Division of Engineering & Guality Assurance 82/07/16,
 Consolidated Edison Co of New York 87pp. 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- B204210395 IE Info Notice Bi-26, Part 3. Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, B2/07/19 Michigan: Univ of 112pp 14358 001 24X Fiche 50-000, B2/07/19, B204210395

- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JCRDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fichs 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 71pp 1435/2/ 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN E L Division of Enganeering & Guality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Hestinghouse PWRs " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000.82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Heatinghouse PWR Power Plants" Svc list encl JORDANIE L Division of Engineering & Quality Assurance 620001idated Edison Co of New York. 121pp 14357 013 24X Fiche: 50-000, 82/07/26, 8204210403
- 9208160119 Forwards IE Insp Rept 50-409/81-23 on 811222-820331 & notice of violation KEPPLER. 9 Region 3. Office of Director 82/07/27 LINDER.F W Dairyland Power Cooperative 3pp 14345-205 24X Fichs 50-409.82/07/27.8208160119
- --8208160121 Notice of violation from insp on 811222-920331 KEPPLER, J Q. Region 3. Office of Director 82/07/26 3pp 14945 208 24% Fichs 50-409, 92/07/27, 8208160119
- --8208160125 IE Insp Rept 50-409/01-23 on 811222-820331 Noncompliance noted failure to follow procedures that resulted in unintentional cooldown of 18 forced circulation loop to below limits & to follow procedure during 820316 event BRANCH.N W. FARNEY, N.L., STREETER, J.F. Division of Project & Resident Fragrams 82/07/26 16pp 14345-211 24X Fiche 50-409,82/07/27,8208160119
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357.146 24X Fiche 50-000, 82/07/28, 8204210405
- 204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Ficha 50-000,82/08/05,8204210407
- B208300291 Forwards IE Insp Rept 50-409/82-07 on 820422 & 0601-30 & & notice of violation

 SPESSARD, R L Davision of Project & Resident Programs B2/0B/12

 LINDER, F W Dairyland Fower Cooperative 2pp 14597 283 24X

 Fichs 50-409, 82/08/12, 8208300281
- --8208300284 Notice of violation from insp on 820422 & 0401-30 8PE6SARD.R L Division of Project & Resident Programs 82/08/12 2pp 14597 283 24X Fither 50-407, 82/08/12, 8208300281
- --8208300294 IE Insp Rept 50-409/82-07 on 820422 & 0401-30 Noncompliance noted operational mode changed withigh alpha activity in primary coolant & high & low pressure coolant injection systemoved from syc & door in vital areas unlocked BRANCH W , REYEGL Division of Project & Resident Programs 82/08/11 App 14599 287 24X Fiche.50-409,82/08/12,8208300281
- 8208310003 Responds to appeal re denial of FOIA request for documents concerning IE Insp. Rept 50-358/81-13 Appeal partially granted & partially denied. Forwards CH Weil 810914 memo info partially withheld (ref FOIA Exemption 7).
 DIRCKS-W J. Office of the Executive Director for Operations.
 82/08/12 DEVINE, T Government Accountability Project (p. 14697:220. 24% Fiche 50-000, 82/08/12, 8208310003

- --8208310005 Forwards RT Carlson 810724 memo re allegations reported to Region 1 by anonymous complainant concerning facilities Vendor Insp Branch will conduct insp of Nuclear Engineering Svcs WEIL.C H Region 3. Chicago, Office of the Director (81/03/01) 81/09/14 Region 3. Chicago, Office of the Director (81/03/01) 3pp 14697 221 24V Fiche 50-000,82/08/12,8208310003
- --B20B310009 Forwards RE Shepherd memos re allegations concerning facility (nsp.design controls % accumulation of test data Confidential (info deleted CARLSON,R T Enforcement & Investigation Staff 81/07/24 STREETER, J Enforcement 'Investigation Staff 18pp 14697 224 24X Fiche 50-000,82/08/12,8208310003
- 8208310327 Forwards safety evaluation? Science Applications, Inc technical evaluation rept supporting util 790511,0727, 800124,0714 & 820324 requests for relief from ASME Code Section XI requirements re inservice insp CRUTCHFIELD.D Deparating Reactors Branch 5 82/08/25 LINDER,F Dairyland Power Cooperative 5pp 14690 122 24X Fiche 30-409,82/08/25,8208310327
- --8208310334 Bafety evaluation supporting requests for relief from certain inservice insp exam & test requirements & alternate methods & code requirements

 Operating Reactors Branch 5 82/08/25 5pp 14640 127 24X fiche 50-407,82/08/25,8208310327
- --8206110309 "LaCrosse Nuclear Power Station Inservice Insp Program Technical Evaluation Rept" * Science Applications, Inc NRC-03-82-096 186-028-12 82/06/10 NRC - No Detailed Affiliation Given 22pp 14690 132 24X Fiche 50-409,82/08/25,8208310327
- --8208310464 Nutice of granting of relief from ASME Code Section XI inservice testing (insp) requirements re piping, component pressure boundary & support structural integrity CRUTCHFIELD. D Departing Reactors Branch 5 82/08/25 2pp 14690 154 24X Fiche 50-409, 82/08/25, 8208310327
- R Periodic operating reports & related correspondence
- 8208120305 Forwards revised monthly operating repts for Apr & May 1982 LINDER.F Dairyland Power Copperative 82/07/07 RUSS.P NRC - No Detailed Affiliation Given ip 14324 307 24X Fiche 30-409.82/07/07.8208120305
- --8208120310 Revised monthly operating rept for Apr 1982 QADQH.O R Dairyland Power Cooperative 82/05/05 2pp 14324-308 24X Fiche 50-409,82/07/07.8208120305
- --8208120313 Revised monthly operating rept for May 1982 QOODMAN.L 8 Dairyland Power Cooperative 82/06/04 1 14324 310 24% Fiche 50-409,82/07/07.8208120305
- 820B12029i Forwards monthly operating rept for June 1982 LINDER.F Dairyland Power Cooperative 82/07/08 Office of Resource Management, Director [p 14324 275 24X Fiche 50-409.02/07/08.8208120291
- --8208120293 Monthly operating rept for June 1982 QADDW, Q R Dairyland Power Cooperative 82/07/07 11pp 14324 276 24X Fiche 50~409,82/07/08,8208120291
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp (4679 208 24% Fiche: 50-000, 82/07/13, 8208270010
- --8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81." * NRC - No Detailed Affiliation Olven 82/07/13 48ρρ 14679,214 24X Fiche 50-000,82/07/13.8208270010
- --8208270572 Forwards "Personnel Whole Body Exposures for CY81." per 10CFR20 407 LINDER:F Dairyland Power Cooperative 82/04/02 Office of Management and Program Analysis 1p 14680 077 24X Fiche 50-000:82/07/13:8208270010
- --8208270576 "Personnel Whole Body Exposures for CYB1 "
 4 Dairyland Power Cooperative 82/04/02, 1p 14680 078 24X Fiche 50-000,82/07/13,8208270010

- S Reportable occurrences, LERs & related correspondence
- 8208050471 RO on 820726, internal portion of fire suppression water sys removed from svc in order to replace fire hose cabinets rendering fire suppression water sys inoperable Backup capability provided LINDER, F. Dairyland Power Cooperative 82/07/26 KEPPLER, J G Region 3, Defice of Director 2pp 14213 280 24X Fiche 50-409, 82/07/26, 8208050471
- 8208090247 Forwards LER 82-016/03L-0 Detailed event analysis encl LINDER: F Dairyland Power Cooperative 82/07/29 KEPPLER: J G Region 3. Office of Director 4pp 14271 040 24X Fiche 50-409: 82/07/29: 8208090249
- --820809025; LER 82-016/03L-0 on 820702 during refueling outage 1,200 gallons of water leaked from condensate demineralizer sys Caused by resin addition not closing when turned to close Valve control relay replaced QCDDMAN.L S Dairyland Power Cooperative 82/07/29, Region 3, Dffice of Director 3pp 14271 044 24X Fiche 50-409,82/07/29, 8208090249
- B208200206 Forwards updated LER 81-015/01X-2 Detailed event analysis aubmitted LINDER.F Dairyland Power Cooperative B2/08/06 KEPPLER.J 0 Region 3. Office of Director 3pp 14397 005 24X Fiche 50-409.82/08/06.8208200206
- ---8208200223 Updated LER 81-015/01X-2 on B11224, following reactor scram, 18 forced circulation loap piping temp decreased below Tech Specs Caused by seal problems following scram Operators received add1 training & procedures modified GBODHAN, L.S. Dairyland Power Cooperative 82/08/06 Region 3, Office of Director 20pp 14399 008 24X Fiche 50-409, 82/08/06, 8208200206
- 8208200066 Forwards updated LER 82-006/01X-1 LINDER: F Dairyland Fower Cooperative 82/08/10 KEPPLER: J G Region 3. Office of Director 2pp 14393 026 24X Fiche 50-409: 82/08/10.8208200066
- --8208200076 Updated LER 82-006/01X-1 on 820420, fuel assembly 1-B found w/pin w/5 5-inch long degraded segment Caused by steinless steel cladding cracking due to pellet/clad interaction assisted stress corrossion Assemblies replaced QOODMAN, L. S. Dairyland Power Cooperative 82/08/10 Region 3, Office of Director, 1p 14373 028 24X Fiche 50-407,82/08/10, 8208200066
- --B208200083 "LACSWR Cycle 7 Fuel Performance & Finalized Refueling Plan for Cycle 8 " RAFFETY,8 J , BRANDT,M Dairyland Power Cooperative BUCK,P Nuclear Energy Service, Inc LAC-TR-112 82/07/31 16pp 14393 029 24X Fiche 50-409,82/08/10.8208200066

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for UL & holders of CP re Commission approved charter for CROR Byr list spc.l.

 DIRCKS.W J Office of the Executive Director for Operations
 62/07/02 Consolidated Edison Co of New York 73pp 14174 001
 24X Fiche 50-000:82/07/02.8207080064
- 8208130115 SUCIDECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS NINE MILE PLANT AND FITZPATRICK CASE STUDY Docket Nos 50-220, 50-410 & 50-333 (Ningara Mohawk Fower Corporation And Power Authority Of The State of New York)

 BRANCH.K., MEALE.R. Hountain West Research, Inc. # Bocial Impact Research, Inc FIN B-1268 NUREG/CR-2747 VO6 82/07/31, Division of Health, Siting & Environment 287pp Available at NTIS \$8 00 14341 001 24X Fiche 50-000,82/07/31,8208130115
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes iOCFR Chapter I requirements & provides alternatives to requirements Bvc list encl EISENHUT, D © Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356-332 24X Fiche: 50-000,82/08/09,8208090194
- 8208310346 Advises that schedule for environ qualification testing of equipment supplied by QE will be provided 820831 per 820830 commitment MANNO,8 F Niegera Mohawk Power Corp 82/08/25 EISENHUT,D Q. Division of Licensing, 1p 14693 213 24X Fiche 50-410,82/08/25,8208310346

- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24% Fiche 50-000, 82/07/16, 8204210393
- B204210395 lE Info Notice 81~26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, Et. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14398 001 24X Fiche 50~000, 82/07/19, 8204210395
- 8208030237 Responds to IE Bulletin 82-01, Revision 1, re alteration of radiographs of welds in piping subassemblies No alterations found in radiographs for recirculation sus piping & safer-ends & piping in recirculation pump motor HXS RHODE, O K Niagara Mohauk Power Corp 82/07/19 HAYNES, R C Region 1, Office of Director 2pp 14209 292 24X Fiche 50-410, 82/07/19, 8208050237
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN, E L. Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210376
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Herafluoride Overpacks " Svc list encl COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357-27 24X Fiche 50-000,82/07/20,8204210397
- B20421039B IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN EL, Division of Engineering & Quality Atsurance 82/07/23 Consolidated Edison Co of New York, 122pp 14380*115, 24X Fichs 50-000, 82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rad Drive (CRD) Guide Tuhe Support Pin Failures at Hestinghouse PMRs " Svc list encl JORDANIE L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120. 24X Fiche 50-000, 82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sheeves in RCS Piping at Certain Westinghouse PNR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fichs 50-000.82/07/26.8204210403
- 8204210405 IE Impo Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357:146 24X Fiche 50-000. 82/07/28.8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl JORDAN.E. L. Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co. of New York 117pp 14388 201 24X Fiche 50-600, 82/08/05,8204210407.
- 8208230317 Forwards IE Insp Rept 50-410/82-07 on 820621-0723 % notice of violation STAROBIECKI.R Division of Project & Resident Programs, 82/08/05 RHODE, 0 K Niegara Mohauk Power Corp 2pp 14513 217 24X Fiche 80-410,82/08/05,8208230317
- --8208230318 Notice of viglation from insp on 820621-0723 STARDSTECKI,R Division of Project & Resident Programs 2pp 14513.219 24X Fiche 50-410.82/08/05.8208230317
- --8208230319 IE Insp Rept 50-410/82-07 on 820621-0723 Nancompliance noted failure to establish measures to control piping components & equipment requiring special handling & failure to issue nonconformance rept re jet pump risers SCHULIR D, KISTERH B Division of Project & Resident Programs. 82/08/04. 13pp 14513 221 24X Fiche:50-410.82/08/05.8208230317.

- B20B300276 Forwards IE Insp Rept 50-410/B2-09 on 820713-16 & 20 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs B2/08/13
- MARTIN, T T Division of Engineering & Technical Programs 82/08/13 RHODE, G K Niagara Mohawk Power Corp 2pp 14599 348 24X Fiche 50-410,82/08/13,8208300276
- --8208300280 IE Insp Rept 50-410/82-09 on 820713-16 & 20 No noncompliance noted Major areas inspected mgt control, design reviews & electrical installations PAOLINO.R J. RICHARDS. S. BECKMAN.D A Division of Engineering & Technical Programs B2/08/12 Spp 14599 350 24X Fiche 30-410.82/08/13.8208300276
- S Reportable occurrences, LERs & related correspondence
- 8208050187 Interim 30-day deficiency rept re failed stud on control bldg termination cabinet support silis (nitially reported on 820615 Investigation continuing Final rept will be submitted by 820924 MANNO, 8 F Niggara Mohawk Power Corp 82/07/15 STARDSTECKI, R Division of Project & Resident Programs 2pp 14212 065 24X Fiche 50-410, 82/07/15, 8208050187
- 8208100060 Final deficiency rept re defective Agastat E-7000 Series time delay relays.per IE Info Notice 82-04 Initially reported on 820407 Affected relays corrected by manufacturer & returned to gE Also reported per Part 21 RHODE.0 K Niagara Mohawk Power Corp 82/07/30 STAROBTECKI.R Division of Project & Resident Programs 2pp 14294 221 24X Fichs 50-410.82/07/30.8208100060
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B2070B0064 Generic ltr to all incenses of operating plants, applicants for GL & holders of CP re Commission approved charter for CRQR Byr list enci
 DIRCKS, W J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000, B2/07/02, 82070B0064
- 820B090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes lOCFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT, D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fichs 50-000,82/08/09,8208090194
- 8208250100 Notifies that 820819 meeting rescheduled to 82083i in Bethesda, MD Purpose of meeting is to introduce project mgt personnel & discuss licensing issues impacting util resources & licensing documents submittal Agenda encl MODLEVER.E J Duquesne Light Co 82/08/23 DOOLITTLE, E Division of Licensing 7pp 14540 351 24% Fiche 50-412,82/08/23,8208250100
- Adjudicatory correspondence
- 1208270415 Requests Commonwealth of PA Dept of Environ Resources, Bureau of Radiation Protection be added to distribution list of proceedings Agency will review application & represent PA in proceedings Agency will review application & represent PA in proceedings ORRUSKY.T M Pennsylvania, State of 82/08/20 Docketing & Services Branch 1p 14565 236 24X Fiche 50-412,82/08/20,8208270415
- O Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list enci JORDANE L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000.82/07/16.8204210393
- 8204210395 IE Info Notice 8;-26,Part 3,Suppl 1, "Clarification of Piacement of Personnel Monitoring Devices for External Radiation" Svc list encl
 JORDAN.E L Division of Engineering & Quality Assurance 82/07/19
 Michigen, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JGRDAN.E L Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York 112pp, 14381 001 24X Fiche 50-000, 82/07/20, 8204210396

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks" 8vc iist enci COBB.L I Division of Fuel Facilities, Matorials & Safeguards 82/07/20 Conspitdated Edison Co of New York 71pp 14357 2/6 24X Fiche 50-000.82/07/20.8204210397
- 8208020305 Forwards IE Insp Rept 50-412/82-07 on 820602-0706 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/07/20 MODLEVER, E. J. Duquesne Light Co. 2pp 14151 335 24X Fiche 50-412, 82/07/20, 8208020305
- --0208020308 Notice of violation from insp on 020602-0706 STAROSTECKI,R Division of Project & Resident Programs 82/07/20 ip 14151 337 24X Fiche 50-412/02/07/20/0208020305
- ---8208020316 IE Insp Rept 50-412/82-07 on 820602-0706 Noncompliance noted failure to control & identify nonconforming Category 1 matl & failure to perform insp of containment liner in accordance w/requirements of spec WALTON, 0 Region 1, Office of Director TRIPP, L Division of Project & Resident Programs \$2/07/16 7pp 14151 338 24X Fiche 50-412,82/07/20,8208020305
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Vaive Failures " Svc Iist encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list enci JORDAN, E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23,8204210401
- 8204210402 IE Info Notice 82-27. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list enc! JORDAN.E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche 50-000.92/07/23.8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sigeves in RC9 Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp. 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver Buring Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffie Water-Jet Impingement" Svc 1,st encl
 JORDAN E L Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14368 201 24X
 Fiche 50-000 82/08/05 8204210407
- S Reportable occurrences. LERs & related correspondence
- 8208260329 Interim Bignificant Deficiency Rept 82-03 re potentially defective Robertshaw thermostatic control valves on smergency diesel generator sets Initially reported on 820726 Also reported per Part 21 Next rept by 830110 WOOLEVER, E. J. Duquesme Light Co. 82/08/17 HAYNES, R. C. Region 1, Office of Director App. 14555-356 24X Fiche 50-412,82/08/17,8208260329
- 8208310030 Final Significant Deficiency Rept B2-01 re defective integrated circuits in Brown Boveri overcurrent relays Initially reported on B10616 Relays repaired by vendors & returned for installation MODLEVER, E J Duquesne Light Co 82/08/20 HAYNES, R Region 1, Office of Director 6pp 14695 161 24X Fiche 50-412,82/08/20.8208310030
- DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8207080044 Oeneric ltr to all licenses of operating plants, applicants for UL & holders of CP re Commission approved charter for CRGR 8Vc list encl
 DIRCKS.W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche, 50-000, 82/07/02, 8207080064

- B208030524 Forwards response to Reactor Sys Granch B11207 request for justification for bypassing anticipatory reactor trip on turbine trip at low power levels, Question 440 T 5 Deletion of reactor trip will not increase probability of small LDCA PARKER, N D Duke Power Co B2/07/26 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 3pp 14163 051 24X Fiche 50-413, B2/07/26, B208030524
- --B20B030532 "Catamba Deletion of Reactor Trip on Turbine Trip Below 70% Power " Max dose release analysis encl 4 Westinghouse Electric Corp 18700 1 82/03/31 39pp 14163 054 24% Fiche 50-413, 82/07/26,820B030524
- 8208190300 Forwards response to Section 2 1 3 for auxiliary bldgs & spent fuel pool areas & Sections 2 1 % 2 3 for reactor bidgs of Encl 3 to NRC 801220 generic ltr re NUREG-0612 W/15 oversize drawings Aperture cards are available in PDR TUCKER.H B Duke Power Co 82/08/06 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAME & Licensing Branch 4 105pp 14500 194 24X Fiche 50-413,82/08/06,8208190300
- --B208190304 Revision 1 to "Crenes & Hoists Safety Insp " ANFIN,W L Duke Power Co 80/07/02 11pp 14500 297 24X Fiche 50-413,82/08/06,8208190300
- --8208190311 Revision 1 to "Chain Hoist Safety Insp "

 * Duke Power Co 80/07/02 13pp 14500 316 24X
 Fiche 80-413,82/08/06,8208190300
- --8208190314 Revision i to "Hooks Safety Insp " ANTIN.W L : SMITH,O Duke Power Co 80/07/02 7pp 14500 329 24% Fiche 50-413,82/08/06,8208190300
- --8208190315 "Packaging & Shipping of New Fuel "
 BRADY, M J , LOSS, P J , TUCKMAN, M S Duke Power Co 79/04/03
 10pp 14500 336 24X Fiche 50-413,82/08/06,8208190300
- --8208190316 "Transferring New Fuel to Elevator "
 LOSS.P J , MILLER.N H , GRAVES.C W Duke Power Co 82/05/05
 5pp 14500 346 24X Fiche 50-413.82/08/06.8208190300
- --8208190319 "Primary Neutron Source Handling "
 BRADY, M J. TUCKMAN, M S., GRAVES, C W Duts Power Co. 79/09/13
 17pp 14800 351 24X Fiche 30-413,62/08/06,8208190300
- --8208190321 "Transferring Foel W/Spent Fuel Manipulator Crane "LOSS, P J . MITCHELL.G L . GRAVES.C W Duke Power Co 82/05/19 9pp 14501 006 24% Fiche 50-413 82/08/06 8208190300
- --8208190326 Revision 1 to "Preparation for Refueling "
 CRISP, I . GRAVES.C W Duke Power Co 79/12/04 56pp 14501 015
 24X Fiche 50-413.92/08/06,8208190300
- --8208170328 Marked-up "Transferring Fuel Control Rods & Thimble Plugs W/Reactor Bldg Manipulator Crane " No date + Duke Power Co 82/08/06 20pp 14501 072 24X Fichs 50-413.82/08/06.8208170300
- --8208190332 Marked-up "Fuel Transfer 8ys Operation " No date * Duke Power Co 82/08/06 7pp 14501 092 24X Fiche 50-413,82/08/06,8208190300
- --8208170337 Marked-up "Internal Transfer of Fuel Assemblies" BRADY,M J , CABLER,R , ORAVES,C W Duke Power Co 79/06/12 App 14501 099 24X Fiche 50~413,82/08/06,8208170300
- --8208170340 "B&W Spent Fuel Receipt Btorage & Shipping W/NAC-1 Cask "
 No date

 * Duke Power Co 82/08/06 30pp 14501 103 24X
 Fiche 50-413.82/08/06.8208170300
- --8208190346 "Draining & Filling of Spent Fuel Pool Transfer Canal & Cask Area" BRADY, M J , SKINNER, E H , GRAVES, C W. Duke Power Co 79/04/25, 12pp 14501 133 24X Fiche 50-413,82/08/06,8208170300
- --8208190352 Marked-up "Receipt, Insp & Storage of New Fuel "
 BRADY, M J , LOSS, F J , GRAVES, C W Duke Power Co 79/04/05.
 21pp 14501 145 24X Fiche 50-413,82/08/06,8208190300
- --B208190358 "Overhead Fuel Bldg Cranes " No date. * Duke Power Co 82/08/06 7pp 14501 166 24X Fiche 50-413.82/08/06.8208190300

- --8208190343 "Whiting 12-Ton ER Crames " * Duke Power Co 80/07/01 12pp 14501 175 24X Fiche 50-413, B2/08/06, B208190300
- --8208190367 "EXH Containment Polar Crane" * Duke Power Co 80/07/22 33pp 14501 187 24X Fiche 80-413, 82/08/06.8208190300
- ---8208190375 "EXH Fuel Bldg Bridge Crane "

 * Duke Power Co 80/07/21 46pp 14501 236 24X
 Fiche 80-413.82/08/06.8208190300
- ---8208190379 "81ings Safety Insp "
 # Duke Power Co 81/05/05 App 14901 282 24X
 Fiche 50-413,82/08/06,8208190300
- B20B090194 Qeneric Ltr B2-i4 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Svc list end:
 EISENHUT, D @ Division of Licensing B2/08/09 Consolidated Edison Co of New York Ip 14396 332 24X Fiche 50-000, B2/08/09, B208090194
- 8208170294 Forwards summary of ultimate capacity analysis for containment vessel penetrations per Structural Engineering Branch 820804 request Info on purge penetration isolation valves will be provided by 820831

 TUCKER.H B Duke Power Co 82/08/12 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAH.E O Licensing Branch 4 3pp 14367 115 24X Fiche 50-413.82/08/12.8208170254
- 8208240210 Forwards responses, revised responses or partial responses to listed FSAR questions
 TUCKER.H B Dute Power Co 82/08/17 DENTON, H R Office of Nuclear Reactor Regulation. Director 67pp 14519 167 24X
 Fiche 50-413.82/08/17.8208240210
- 8208260472 Notification of 820907-09 meeting & site visit w/util & Westinghouse to discuss NRC Instrumentation & Control Sys Branch review items
 JABBOURK N Licensing Branch 4 82/08/17 ADENSAM, E.G. Licensing Branch 4 3pp 14369 269 24X Fiche 50-413,82/08/17,8208260472
- 8208260483 Forwards request for add1 info re identification of safety-related structures, sys & components controlled by GA program ADENSAM, E.G. Licensing Branch 4 82/08/17 TUCKER, H.B. Duke Power Co. 5pp. 14594 355 24X Fiche 50-413,82/08/17,8208260483
- 8208250355 Forwards responses to 820707 request for add1 info re containment ultimate capacity & stability analyses Also responds to Dec 1981 structural adequacy audit re FSAR questions & action items Viewgraphs encl TUCKER. H B Duke Power Co 82/08/19 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 67pp 14538 089 24X Fiche 50-413,82/08/19,8208250355.
- --8208250358 "Containment Vessel Stability Analysis " UNBAL.A. MORRIE,N F. HARBTEAD.0 A Harstead Engineering Associates.Inc 8106-2 82/05/27 170pp 14538 293 243 Fiche 80-413.82/08/19.8208250355
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8208270602 Forwards DEB (NUREG-0921) & FR notice of availability
 H/o encis
 NUVAK.T M Assistant Director for Licensing 82/08/16 TUCKER,H I
 Duke Power Co 3pp 14683 208 24% Fiche 50-413.82/08/16,
 8208270602
- --8208270606 Forwards DES (NUREO-0921) & FR notice of availability FES will be prepared after receipt of comments from federal, state & local agencies W/o DES ADENBAM, E G Licensing Branch 4 82/08/16 WILSON, K Environmental Protection Agency 1p 14683 211 24X Fiche 50-413,82/08/16,8208270602
- --8208270610 Forwards DES (NUREO-0921) & FR notice of availability.
 Comments due within 45 days after FR publication of EPA
 listing notifying public of issuance of statement W/o DES
 ADENBAM, E Q. Licensing Branch 4 82/08/16 GRANT. R
 Commerce, Dept of 3pp 14683 212 24X Fiche 50-413, 82/08/16, 8208270402

- --8208270613 Notice of availability of DES (NUREG-0921)
 ADEMSAM, E. Q. Licensing Branch 4 82/08/16 2pp 14683 215 24x
 Fiche 50-413,82/08/16,8208270602
- ~~8208270617 Forwards FR notice of availability of DES (NUREG-0721) H/o encl ADENSAME Q_ Licensing Branch 4 82/08/16 Butzel & Kass. 3pp 14683 217 24X Fiche 50~413,82/08/16,8208270602
- 8208260481 Discusses contentions in DES Further details by way of affidavit k/or written & oral testimony may be needed from responsible NRC members as to contentions finally admitted unconditionally.

 NOVAK.T M. Assistant Director for Licensing 82/08/17

 EISENHUT.D G Division of Licensing 2pp, 14569 267 24X Fiche 50-413, 82/08/17, 8208260481
- 9208240434 Offers no comments on DES
 DAVIS.V W Agriculture.Dept of 82/08/20 ADENSAM.E O Licensing
 Branch 4 ip 14527 001 24% Fiche 50-413.82/08/20,8208240434
- 8208230415 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF CATAMBA NUCLEAR STATION.UNITS 1 AND 2 Docket Nos 50-413 And 50-414 (Duke Power Company)

 * Office of Nuclear Reactor Regulation, Director. NUREQ-0721 82/08/31 173pp Available at NTIS 14518 026 24X Fiche 50-413, 82/08/31, 8208230415
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8208030357 Forwards response to RL Tedesco 820512 request for add1 info re fire protection preliminary draft SER & clarifications on draft & Branch Technical Position CMEB 9 5-1 PARKER, H O Duke Power Co 62/07/29 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E. O Licensing Branch 4 20pp 14157 174 24X Fiche 30-413.82207/29, 8208030357
- F Security, medical, emergency & fire protection plans
- 8208030357 Forwards response to RL Tedesco B20512 request for add1 info re fire protection preliminary draft SER & clarifications on draft & Branch Technical Position CMEB 9 5-1 PARKER, N O. Duke Power Co 82/07/29, DENTGN, H R Office of Nuclear Reactor Regulation, Director ADEMBAN, E Q Licensing Branch 4 20pp 14157.194. 24X Fiche 50-413,82/07/29,8208030357
- B208100191 Advises that final design of public notification sys & schedule for installation will be submitted by 820831, per B10723 request PARKER, W O Duke Power Co B2/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director NEWTON, F Federal Emergency Hanagement Agency ADENSAM, E Q Licensing Branch 4 2pp 14298, 198 24x Fiche 50-413, B2/07/30, B208100191
- 8208260418 Releases public version of revised crisis mgt plan. FELTON.J M. Division of Rules and Records 82/08/11, Document Management Branch ip 14572.098 24% Fichs 50-000,82/08/11, 8208260418
- -8208260430 Forwards public version of Revision 5 to crisis mgt plan Revision involves reorganization of crisis mgt team & updates of Sections D.K & M PARKER.N.O Duke Power Co 82/07/19 DENTON,H R, Office of Nuclear Reactor Regulation, Director. ip 14572 099 24X Fiche: 50-000, 82/08/11,8208260418
- -8208260437 Public version of Revision 5 to crisis mgt plan. TUCKER.H B Duke Power Co. 82/07/09 134pp 14572·100 24X Fiche 50-000.82/08/11.8208260418
- G Adjudicatory correspondence
- 8204070563 Objections to ASLB 820305 order admitting contentions Regulations do not permit admission of defective contentions sub, to later spec JOHNSON, O. E. Hearing Brench 4 82/04/05 Atomic Safety and Licensing Board Panel 16pp. 12576 188 24x Fiche 50-413, 82/04/05, 8204070563
- 8204070570 Response to ASLE 820305 questions re Palmetto Alliance Contentions 8,15 & Id re spent fuel storage & operator qualifications Contention 8 litigable based on NUREQ-0737 Issues re spent fuel storage within scope of proceeding.

 JOHNSON,9 E. Nearing Branch 4 82/04/05 Atomic Sefety and Licensing Board Panel. 22pp. 12576,271. 24X Fiche: 50-419,82/04/05,8204070570

- 8208020230 Comments on litigability of intervenor accident scenarios, per ASLB request Palmetto Alliance Contention 5 properly rejected Contentions 9 & 31 re credibility of hydrogen generation scenarios may be admitted W/Certificate of Svc JOHNSON, 9 E Hearing Branch 4 82/07/30 7pp 14152 239 24X Fichs 50-413, 82/07/30,8208020230
- 8208030358 Response opposing Carolina Environ Study Group & Palmetto Alliance 820331 motion for reconsideration of ASLB 820305 memorandum & order denying admission of serious accident Contentions 5, 7 & 31 Certificate of Svc encl.

 MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 82/07/30 Atomic Safety and Licensing Board Panel 18pp 14137 107 24x Fiche 50-413.82/07/30.8208030358
- 8208030461 Note for parties advising that add1 LPDR established in Columbia, 8G KELLEY, J. Atomic Safety and Licensing Board Panel 82/08/04 ip 14216 333 24X Fiche 50-413,82/08/04,8208030461
- --8208050468 Advises of addl LPDR in Columbia, BC 80UDER, J L Division of Rules and Records 82/07/29 KELLEY, J L Atomic Safety and Licensing Board Panel ip 14216, 334 24X Fiche 50-413, 82/08/04, 8208050461
- 8208(1019) Response apposing interlocutory review sought by applicants & NRC in response to ASLAB 820719 order or alternatively, to affirm ASLB rulings & remand matter to ASLB for further proceedings Certificate of Svc encl GUILD.R Palmetto Alliance GUILD.R Ouild, R 82/08/05 Atomic Seafety and Licensing Appeal Panel 13pp 14313 347, 24X Fiche 50-413,82/08/05,8208110191
- 8208110166 Interrogatories & request to produce re Palmetto Alliance Contentions 16 & 27 Certificate of Svc encl.Related correspondence MCOARRY, J M Duks Power Co MCOARRY, J M Debevoise & Liberman 82/08/09 Atomic Safety and Licensing Board Panel 20pp 14313 255 24X Fiche 50-413.82/08/09.8208110166
- 8208170278 Second set of interrogatories & document production requests re Palmetto Alliance Contentions 8,16 & 27 on operator qualifications, spept fuel storage & real time monitors, respectively Certificate of Byc encl
 JOHNSON, G E Hearing Branch 4, 82/08/13 Palmetto Alliance
 Bpp 14367-070 24X Fiche.30-413.82/08/13,82/08170278
- 8208190140 Interrogatories & requests to produce re Palmetto Alliance Contention & Certificate of Svc encl Related correspondence. CARR, A V Duke Power Co 82/08/16 Pelmetto Alliance 14pp. 14381.022 24x Fiche 50-413.82/08/16,8208190140
- 8208200177 Memorandum & Order ALAB-687 accepting referral by ASLB of three rulings conditionally admitting contentions Cause remanded to ASLB for reconsideration of LBP-82-16 & LBP-82-50 consistent w/views expressed in opinion SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 82/08/19. 19pp 14500 157. 24X Fiche 50-413,82/08/19.8208200177
- I Financial information
- 8208300328 Forwards util & NG Municipal Power Agency Annual Financial Repts for 1981 TUCKER.H B Duke Power Co 82/08/24 DENTON,H R. Office of Nuclear Reactor Regulation, Director ADENBAM.E 0 Licensing Branch 4 2pp 14599 227 24X Fiche 50-000,82/08/24,8208300328
- --8208300335 Annual Financial Rept 1981. HDRN:C., LEE,W. 6 Duke Power Co 82/02/15 48pp. 14579,006 24X Fiche 50-000,82/08/24,8208300328
- --B208300341 Annual Financial Rept 1981 CULLER,R B , SHAW,R,W North Carolina Municipal Power Agencies 82/08/24 26pp 14599 054 24X Fiche, 50-000, 82/08/24, 8208300328
- Q Inspection reports, IE Bulletins & correspondence
- 8208030192 Forwards IE Insp Repts 50-413/82-14 & 50-414/82-11 on 820608-11 No noncompliance noted DANCE/H.C Division of Project & Resident Programs 82/07/08 PARKER.W O Duke Power Co 2pp. 14160,008 24X Fichs.50-413,82/07/08
- --8208030194 IE Insp Repts 50-413/82-14 & 50-414/82-11 on 820408-11 No noncompliance noted Major areas inspected electrical cables & terminations observation of work activities, review of quality records & instrumentation components & sys.

 RUFF, A B: CONLON, T. E. Division of Engineering & Technical Programs 82/07/02 3pp 14160 010. 24X Fiche. 50-413, 82/07/08, 8208030192.

- B20B030320 Forwards IE Insp Repts 50-413/82-19 & 50-414/82-12 on B2060B-11 No noncompliance noted DANCE, H C Division of Project & Resident Programs B2/07/08 PARKER, W D Duke Power Co 2pp 14156 311 24X Fithe 50-413, 82/07/08, 8208030320
- --8208030326 IE Insp Repts 50-413/82-15 & 50-414/82-12 on 820608-11 No noncompliance noted Major areas inspected const progress, safety-related piping, steel structures & supports & licensee identified items per 10CFR50 55(e) KLEINSGRGE, W P , ECGNOMOS. N Division of Engineering & Technical Programs 82/07/05 7pp 14156 313 24X Fiche 50-413.82/07/08, 8208030320
- 8208030185 Forwards IC Insp Repts 50-413/82-16 & 50-414/82-14 on 820326-0625 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/12 PARKER, W O Duke Power Co 2pp 14160 159 24X Fiche 50-413, 82/07/12, 8208030185
- --8208030188 IE Insp Repts 50-413/82-16 & 50-414/82-14 on 820526-0625 No noncompliance noted Major areas inspected nonconforming item repts, RCPB piping & safety-related piping VAN DODAN,P K , BRYANT, J C Division of Project & Resident Programs 82/07/12 5pp 14160 161 24X Fiche 50-413,82/07/12,8208030185
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage "Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 30-000, 822/07/16, 8204210393
- 6204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JDRDAN, E. L. Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 62/07/19, 8204210395
- B204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure" Svc list enci JGRDAN: E L Division of Engineering & Quality Assurance B2/07/20 Consolidated Edison Co of New York 112pp 14381 001 R4X Fiche 50-000: B2/07/20: B204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list onci COBB, L I Division of Fuei Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 27 24X Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list enci JORDANIE L Division of Engineering & Quality Assurance 62/07/22, Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208160328 Forwards 1E Insp Repts 50-413/82-17 & 50-414/82-15 on 820706-09 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/22 PARKER, W O Duke Power Co 2pp 14348 022 24X Fiche 50-413, 82/07/22, 8208160328
- --B208i60384 IE Insp Repts 50-413/82-17 & 50-414/82-15 on 820706-09. No noncompliance noted Major areas inspected instrumentation, components & sys diesel generator storage & sequencer calibr, document control & GC inspector qualifications MILLER, W H. CONLON, T E Division of Project Resident Programs B2/07/20 4pp 14348 024 24X Fiche 50-413,82/07/22,8208160328
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl URDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115, 24X Fiche 50-000, 82/07/23, 8204210401
- B204210402 IE Info Notice B2-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDANIE L. Division of Engineering & Guality Assurance B2/07/23 Consolidated Edison Co of New York 127pp 14194 120, 24X Fiche 50-000.82/07/23,8204210402
- B204210403 IE Info Notice B2-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plents " Byc list encl JORDANIE L Division of Engineering & Guality Assurance B2/07/26 Consolidated Edison Co of New York 121pp 14357,013 24X Fiche,50-000.82/07/26.8204210403

- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list enc! JORDAN E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 144 24X Fiche 50-000, 82/07/28, 8204210405
- 9208160281 Ack receipt of 82061) 1tr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-413/82-10 & 50-414/82-04
 DANCE-H C Division of Project & Resident Programs 82/08/02
 PARKER-W D Duke Power Co 1p 14345 271 24X
 Fiche 50-413, 82/08/02, 8208160281
- --B20Bi60290 Forwards response to NRC ltr re violations noted in IE Insp Repts 50-413/82-10 & 50-414/82-04 Corrective actions all unmarked copies of controlled documents discarded & training given to GC inspectors in requirements,per GAP-G-1 PARKER.W D Duke Power Co B2/06/11 O'REILLY, J P Region 2, Office of Director 2pp 14345 272 24X Fiche 50-413,82/08/02, 820B1602B1
- ---8208160298 Forwards IE Insp Repts 50-413/82-10 & 50-414/82-04 on 820326-0425 & notice of violation DANCE.H C Division of Project & Resident Programs 82/05/14 PARKER.W O Duke Power Co 2pp 14345 274 24X Fiche 50-413,82/08/02:8208160281
- --8208160341 Notice of violation from insp on 820326-0425 # Division of Project & Resident Programs 82/05/14 2pp 14345 276 24X Fiche 50-413,82/08/02,8208160281
- --8208160349 IE Insp Repts 50-413/82-10 & 50-414/82-04 on 820326-0425 Noncompliance noted failure to follow pracedures for dacument control & for corrective action re Class A pressurizer relief valves
 VAN DOORN, P K . DRYANT, J C Division of Project & Resident Programs 82/05/14 6pp 14345 278 24X Fiche 50-413,82/08/02,8208160281
- 8208160206 Ack receipt of IE Insp Repts 50-413/82-15 & 50-414/82-12
 No proprietary info
 TUCKER, H B Duke Power Co 82/08/04 D'REILLY, J P Region 2,
 Office of Director (p 14344 160 24X Fiche 50-413, 82/08/04,
 8208160206
- B208160355 Ack receipt of IE Insp Repts 50-413/82-14 & 50-414/82-11 No proprietary info TUCKER, H B Duke Power Co B2/08/04 O'REILLY, J P Region 2, Office of Director ip 14348 362 24X Fiche 50-413,82/08/04, B208160355
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Syc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/08/05 Consolidated Edison Co of New York 117pp 14388-201 24X Fiche 50-000.82/08/05.8204210407
- R Periodic operating reports & related correspondence
- 8208170159 Forwards first quarter 1982 Yellow Book updates re const status EDMARDS, G.L. Duke Power Co. 82/05/20 LOVELACE, W.H. Management Information Branch 5pp 14364 340 24% Fiche 50-000,82/05/20, 8208170159
- B Reportable occurrences, LERs & related correspondence
- B20B030242 Significant Deficiency Rept BD 413-414/82-14 re capscrews that secure starting air valve & housing assembly to cylinder which may bottom out Initially reported on 820628 Transamerica Delval modified assembly procedures PARKER.W O Duke Power Co 82/07/23 O'REILLY, J.P. Region 2, Office of Director 3pp 14158 224 24X Fiché 50-413, B2/07/23, B208030242
- 8208120036 Final deficiency rept re overtorquing of ITT-Phillips concrete expansion anchors to close excessive plate-to-concrete gaps on pipe supports Initially reported on 820303 Anchors not meeting acceptance criteria replaced TUCKER.H D Duke Power Co 82/08/03 O'REILLY, J P. Region 2, Office of Director 4pp 14323 343 24X Fiche 50-413,82/08/03,82/0812034

- DOCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list encl
 DIRCKS, W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Go of New York 93pp 14194 001
 24X Fiche 50-000.82/07/02.8207080064
- 8208030524 Forwards response to Reactor Sys Branch 811209 request for justification for bypassing anticipatory reactor trip on turbine trip at low power levels, duestion 440 T 3 Deletion of reactor trip will not increase probability of small LOCA PARKER, W O Duke Power Co 82/07/26 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 9 Licensing Branch 4 3pp 14163 051 24X Fiche 50-413,82/07/26,8208030524
- --8208030332 "Catawba Deletion of Reactor Trip on Turbine Trip Below 70% Power " Max dose release analysis enc!
 # Westinghouse Electric Corp 18900 ! 82/03/31 39pp
 14163 034 24% Fiche 30-413,82/07/26,8208030524
- 8208190300 Forward& response to Section 2 i 3 for auxiliary bldgs & spent fuel pool areas & Sections 2 i & 2 3 for reactor bldgs of Encl 3 to NRC 801220 generic ltr re NUREG-0612 W/15 oversize drawings Aperture cards are available in PDR TUCKER.H B Duke Power Co 82/08/06 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSM.E G Licensing Branch 4 105pp 14500 194 24X Fiche 50-413,82/08/06,8208190300
- --8208190304 Revision 1 to "Cranes & Hoists -- Safety Insp " ANFIN,W L Duke Power Co 80/07/02 11pp 14500 297 24X Fiche 50-413.82/08/06.8208190300
- ~-8208190308 "Slings Safety Insp " LAILE W Duke Power Co 79/06/19 Spp 14500.308 24X Fiche 50-413,82/08/06.8208190300
- --8208190311 Revision 1 to "Chain Hoist Safety Insp," * Dute Fouer Co. 80/07/02 13pp 14500 316 24X Fiche 50-413,82/08/04,8208190300
- --8208190314 Revision 1 to "Hooks Safety Insp " AMFIN.W L., BMITH, Q Duke Power Co 80/07/02 7pp 14500 329 24X Fichs 50-413, 62/08/06, 8208190300
- ---B208190315 "Packaging & Shipping of New Fuel " BRADY.M J . LOSS.P J . TUCKMAN.M S Duke Power Co 79 10pp. 14500 336 24X Fiche 50-413.82/08/06.8208190300 79/04/03
- --8208190316 "Transferring New Fuel to Elevator "
 LOSS.P J , MILLER, W H , GRAVES, C W Dute Power Co 8
 5pp 14500 346 24X Fiche 90-413,82/08/06,8208190300 82/05/05
- 8208190319 "Primary Neutron Source Handling " BRADY.H J. TUCKMAN.M S , GRAVES,C W Duke Power Co 17pp 14500,351 24X Fiche 50-413.82/08/06.8208190300 79/09/13
- -8208190321 "Transferring Fuel W/Spent Fuel Manipulator Crane." LOSS.P J. MITCHELL.O L. ORAVES,C W. Dute Power Co. 82/05/19. 7pp 14501 006 24X Fiche 50-413,82/08/06,8208190300
- --8208190326 Revision 1 to "Preparation for Refueling" CRISP.1, GRAVES.C.H Duke Power Co 79/12/04 56pp 14501 015 24% Fiche. 30-413.82/08/06.8208190300
- --8208190328 Harked-up "Transferring Fuel Control Rods & Thimble Plugs W/Reactor Bldg Manipulator Crane " No date * Duke Power Co 82/08/06 20pp 14501 072 24X Fiche 50-413,82/08/06,8208190300
- --8208190332 Marked-up "Fuel Transfer Bys Operation " No date * Dute Power Co 82/08/06 7pp 14501 072. 24X Fiche 50-413.82/08/06.8208190300
- --8208190337 Marked-up "Internal Transfer of Fuel Assemblies"
 BRADY, M. J., CASLER, R., ORAVES, C. W. Duke Power Co., 79/06/12, 4pp
 14501 079 24X Fiche 50-413.82/08/06.8208190300.
- --8208190340 "B&W Spent Fuel Receipt, Storage & Shipping W/NAC-1 Cask " No date * Duke Power Co 82/08/06 30pp 14501 103 24% Fiche 50-413,82/08/06.8208190300

- -- 9208190346 "Draining & Filling of Spent Fuel Pool Transfer Canal & Cask Area " BRADY, M J . SKINNER, E H . ORAVES, C W Duke Power Co 12pp 14501 133 24X Fiche 50-413,82/08/04,8208190300
- --B208190352 Marked-up "Receipt, Insp & Storage of New Fuel "
 BRADY, H J., LOSS, P J., GRAVES, C W Duke Power Co 79/04/05
 Zipp 14501 145 24X Fiche 50-413, B2/08/06, B208190300
- --8208190358 "Overhead Fuel Bldg Cranes " No date * Duke Power Co 82/08/06 9pp 14501 166 24X Fiche 50-413,82/08/06.8208190300
- --8208190363 "Whiting 12-Tun ER Cranes "
 * Duke Power Co 80/07/01 12pp 14501 175
 Fiche 50-413,82/08/06,8208170300
- --8208190372 "Whiting 230/20-Ton Crane (11121 & 11122)

 * Duke Pawer Co 80/07/01 16pp 14501 220 24
 Fiche 50-413,82/08/04.6208190300
- -8208190375 "EXH Fuel Bldg Bridge Crane * Duke Power Co. 80/07/21 46pp 1/ Fiche 50-413,82/08/06,8208190300 14501 236 241
- --8208190379 "Blings Gafety Insp." * Duke Power Co 81/05/05 App Fiche 50-413,82/08/06,8208190300 14501 282 24X 600
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFA Chapter I requirements & provides alternatives to requirements Bvc list enci EISENNUT,D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24% Fiche 50-000,82/08/09,8208090194
- 820B170254 Forwards summary of ultimate capacity analysis for containment vessel penetrations per Structural Engineering Branch 820604 request info on purge penetration isolation valves will be provided by 820B31 TUCKER.H B Duke Power Co 82/08/12 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAM,E Q Licensing Branch 4 3pp 14967 115 24X Fiche 50-413,82/08/12,8208170254
- 8208240210 Forwards responses, revised responses or partial responses to CODE-VOLUME TEACH TOWARDS RESIDENT TO THE PROPERTY OF PARTIES FOR THE PROPERTY OF PARTIES FOR THE PROPERTY OF THE PROPERTY OF
- 8208260472 Notification of 820907-09 meeting & site visit w/util & Westinghouse to discuss NRC Instrumentation & Control Sys Branch review items
 JABBOUR, K N 'Licensing Branch 4 82/08/17 ADENSAM, E. Q Licensing Branch 4 3pp 14569 269 24X Fiche 50-413,82/08/17,8208260472.
- 8208260483 Forwards request for addl info re identification of safety-related structures, sys & components controlled by GA ADENBAM, E G G Licensing Branch 4 82/08/17, TUCKER.H B Duke Pawer 14594 355 24X Fiche 50-413,82/08/17,8208260483
- 8208290395 Forwards responses to 820707 request for additinfore containment ultimate capacity & stability analyses, Also responds to Dec 1781 structural adequacy audit re FSAR questions & action Items Viewgraphs enci TUCKER.H B Duke Power Co. 82/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADEMBAM.E. G Licensing Branch A 69pp. 14538 089 24X Fiche 50-413.82/08/19.8208250355.
- --0208250358 "Containment Vessel Stability Analysis "
 UNSAL.A. MORRIS.N.F. HARBIEAD.O A Harstead Engineering
 Associates.Inc 8106-2 82/05/27 170pp 14338-293 2
 Fichs.50-410,82/08/19.8208250355
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8208270602 Forwards DES (NUREG-0921) & FR notice of availability W/o encis NOVAK,T.M Assistant Director for Licensing 82/08/16 TUC Duke Power Co. 3pp 14683 208 24X Fiche.50-413,82/08/16, 8208270602. TUCKER, H B

- --B208270606 Forwards DES (NUREG-0921) & FR notice of availability FES will be prepared after receipt of comments from federal, state & local agencies M/o DES ADENSAM,E 0 Licensing Branch 4 B2/08/16 WILSON,K Environmental Protection Agency 1p 14683 211 24X Fiche 50-413,82/08/16.8208270602
- --B208270610 Forwards DES (NUREO-0921) & FR notice of availability Comments due within 45 days after FR publication of EPA listing notifying public of issuance of statement W/o DEB ADENSAM.E G Licensing Branch 4 82/08/16 GRANT.R Commerce.Dept of 3pp 14683 212 24X Fiche 50-413,82/08/16.8208270602
- --8208270613 Notice of availability of DES (NUREG-0921)
 ADENSAM E G Licensing Branch 4 82/08/16 2pp 14683 215 24X
 Fiche 50-413,82/08/16,8208270602
- --8208270617 Forwards FR notice of availability of DES (NUREO-0921) W/o encl ADENBAM, E O Licensing Branch 4. 82/08/16 Butsel & Kass 3pp 14683 217 24X Fiche, 50-413, 82/08/16, 8208270602
- 8208260481 Discusses contentions in DES Further details by way of affidavit &/or written & oral testimony may be needed from responsible NRC members as to contentions finally admitted unconditionally.

 NDVAK.T M Assistant Director for Licensing 82/08/17 EIGENHUT, D. 9 Division of Licensing 2pp 14569 267 24X Fiche 50-413, 82/08/17, 8208260481
- 8208240434 Offers no comments on DES.
 DAVIB, V H. Agriculture, Dept of 82/08/20 ADENBAK, E Q. Licensing Branch 4 1p 14527 001 24X Fiche 50-413, 82/08/20, 8208240434
- 8208230415 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF CATAMBA NUCLEAR STATION UNITS I AND 2 Docket Nos 50-413 And 50-414. (Duke Power Company) 4 Office of Nuclear Reactor Regulation, Director NUREG-0921 82/08/31 175pp Available at NTIS 14518 026. 24X Fiche 50-413,82/08/31,8208230415
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8208030357 Forwards response to RL Tedesco 820512 request for add1 info re fire protection praliminary draft 8ER & clarifications on draft & Branch Technical Position CMED 7 5-1 PARKER, W O Duke Power Co 82/07/29 DENTON, H R. Office of Nuclear Reactor Regulation, Director 20pp 14157 174 24X Fiche 50-413, 82/07/29, 8208030357
- F Security, medical, emergency & fire protection plans
- 8208030357 Forwards response to RL Tedesco 820512 request for add1 info re fire protection preliminary draft SER & clarifications on draft & Branch Technical Posttion CHER 7 5-1 PARKER.H O Duke Power Co 82/07/29 DENTON.H R. Office of Nuclear Reactor Regulation, Director ADENSAH,E O Licensing Branch Q 20pp 14157,194 24% Fiche 50-413,82/07/29,8208030357.
- 8208100191 Advises that final design of public notification sys & schedule for installation will be submitted by 820831.per 810723 request PARKER: W.O. Duke Power Co 82/07/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director NEWTON-F. Federal Emergency Hanagement Agency ADENSAM.E.G. Licensing Branch 4. 2pp 14298-198 24X Fiche 50-413.82/07/30.8208100191
- 8208260418 Releases public version of revised crisis mgt plan FELTON, J M Division of Rules and Records. 82/08/11. Document BELTON, J M Division of Rules and Records. 82/08/11. Document BELTON, J M Division of Rules and Records. 82/08/11.
- --B20B260430 Forwards public version of Revision 5 to crisis mgt glan. Revision involves reorganization of crisis mgt team & updates of Sections D.K. & M PARKER, W.O. Duke Fower Co. B2/07/19 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip. 14572 099, 24X Fiche 50-000, B2/0B/ii, B20B26041B.
- --8208260437 Public version of Revision 5 to crisis mgt plan. TUCKER,H. B Duke Power Co. 82/07/09 134pp. 14572 100 24X Fiche, 50-000, 82/08/11, 8208260418

G Adjudicatory correspondence

- 8204070563 Objections to ASLB 820305 order admitting contentions Regulations do not permit admission of defective contentions subj to later spec JOHNSON.0 E Hearing Branch 4 92/04/05 Atomic Safety and Licensing Board Panel 16pp 12576 188 24X Fichs 50~413,82/04/05, B204070363
- B204070570 Response to ASLB B20305 questions re Palmetto Allianca Contentions 8,15 & 16 re spent fuel storage & operator qualifications Contention B litigable based on NUREO-0737 Issues re spent fuel storage within scope of proceeding JOHNSON.0 E Hearing Branch 4 B2/04/05 Atomic Safety and Licensing Board Panel 22pp 12576 271 24X Fiche 50-413,82/04/05, B204070570
- 8208020230 Comments on litigability of intervenor accident scenarios, per ASLB request Palmetto Alliance Contention 5 properly rejected Contentions 9 & 31 re credibility of hydrogen generation scenarios may be admitted W/Certificate of Svc. JOHNSON: 0 E Hearing Branch 4 82/07/30 7pp 14:52 239 24X Fiche 50-413.82/07/30,8208020230
- 820803035B Response opposing Carolina Environ Study Group & Palmetto Alliance 820331 motion for reconsideration of ASLB 820305 memorandum & order denying admission of serious accident Contentions 5.7 & 31 Gertificate of Svc encl MCOARRY, J M Duke Power Co. MCOARRY, J M Debevoise & Liberman. 82/07/30 Atomic Safety and Licensing Board Panel 18pp 14157 107 24X Fiche 50-413,82/07/30,8208030358
- 8208050461 Note for parties advising that add1 LPDR established in Columbia, SC KELLEY, J. L. Atomic Safety and Licensing Board Panel 82/08/04 ip 14216.333 24% Fiche 30-413,82/08/04,8208050461
- --B208050468 Advises of addl LPDR in Columbia:80 SOUDER, J L Division of Rules and Records B2/07/29 KELLEY. J L Atomic 8afety and Licensing Board Panel ip 14216 334 24X Fiche 50-413,82/08/04.8208050461
- 820Bii0171 Response opposing interlocutory review sought by applicants & NRC in response to ASLAB 820717 order or alternatively, to affirm ASLB rulings & remand matter to ASLB for further proceedings. Certificate of Byc enci GUILD: R Palmetto Alliance OUILD: R Guild: R 82/08/05 Atomic Bafety and Licensing Appeal Panel. 13pp 14313.347 24X Fiche 50-413,82/08/05,8208110191
- 8208110166 Interrogatories & request to produce re Palmetto Alliance Contentions 16 & 27 Certificate of Svc entl Related correspondence MCGARRY, J ff Duke Power Co MCGARRY, J ff Debevoise & Liberman 82/08/09 Atomic Safety and Licensing Board Panel 20pp 14313 255, 24X Fichs 50-413, 82/08/09, 8208110166
- 8208170278 Second set of interrogatories & document production requests re Palmetto Alliance Contentions 8:16 & 27 on operator qualifications, spent fuel storage & real time monitors, respectively Certificate of Svc encl JOHNSON, O. E. Hearing Branch 4 82/09/13 Palmetto Alliance. Sp. 14367-090 24X Fichs, 50-413, 82/08/13, 8208170278
- 8208190140 Interrogatories & requests to produce re Palmetto Alliance Contention 8 Certificate of Svc encl Related correspondence, CARR, A V Duke Power Co 82/08/16 Palmetto Alliance 14pp 14381:022 24X Fiche 50-413.82/08/16.8208190140
- 8208200177 Memorandum & Order ALAB-687 accepting referral by ASLB of three rulings conditionally admitting contentions Cause remanded to ASLB for reconsideration of LBP-82-16 to LBP-82-50 consistent w/views expressed in opinion SHOEMAKER; C. J. Atomic Sefety and Licensing Appeal Panel 82/08/19, 19pp. 14500 157 24% Fishe 50-413.82/08/19.8208200177.

I Financial information

- 8208300328 Forwards util & NC Municipal Power Agency Annual Financial Hepts for 1981 TUCKER: H. B. Duke Power Co. 82/08/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4, 2pp. 14599 227 24% Fiche, 50-000, 82/08/24, 8208300328
- --8208300335 Annual Financial Rept 1981 HORN.C., LEE, W. B. Duke Power Co. 82/02/15 48pp. 14599.006 24% Fiche: 50-000, 82/08/24,8208300328
- --B208300341 Annual Financial Rept 1981. CULLER, R B , BHAWAR W North Carolina Municipal Power Agencies 82/08/24 26pp 14599 054 24X Ficha 50-000.82/08/24,8208300328

- Q Inspection reports. IE Bulletins & correspondence
- 8208030192 Forwards 1E Insp Repts 50-413/82-14 & 50-414/82-11 on 820608-11 No noncompliance noted DANCE:HC Division of Project & Resident Programs 82/07/08 PARKER,W O Duke Power Co 2pp 14160 008 24X Fiche 50-413, 82/07/08, 8208030192
- --8208030196 IE Insp Repts 50-413/82-14 & 50-414/82-11 on 820608-11 No noncompliance noted Major areas inspected electrical cables & terminations; observation of work activities; review of quality records & instrumentation; components & sys RUFF.A B . CONLON.T E Division of Engineering & Technical Programs 82/07/02 3pp 14160 010 24X Fiche 50-413,82/07/08,8208030192
- 8208030320 Forwards IE Insp Repts 50-413/82-15 & 50-414/82-12 on 820408-11 No noncompliance noted DANCE:HC Division of Project & Resident Programs 82/07/08 PARKER:HC Duke Power Co 2pp 14156 311 24X Fichs 50-413, 82/07/08,
- --B208030326 IE Insp Repts 50-413/82-15 & 50-414/82-12 on 820608-11 No noncompliance noted Major areas inspected const progress, safety-related piping, steel structures & supports & licensee identified items per 10CFR30 55(e)
 KLEINSURGE, W.P. . ECGNOMOS, N. Davision of Engineering & Technical Programs 82/07/05 7pp 14156 313 24X Fiche 50-413,82/07/08,8208030320
- 8208030185 Forwards 1E Insp Repts 50-413/82-16 & 50-414/82-14 on 820526-0625 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/07/12 PARKER.W O Duke Power Co 2pp 14160 159 24X Fiche 50-413, 82/07/12, 8208030185
- --8208030188 IE Insp Repts 50-413/82-14 & 50-414/82-14 on 820524-0625 No noncompliance noted Major areas inspected honconforming item repts.RCPB piping & safety-related piping VAN DOORN.P K , BRYANT.J C Division of Project & Resident Programs 82/07/12 5pp 14160 161 24% Fiche 50-413,82/07/12,8208030185
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list and!
 JORDAN, E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26,Part 3,Suppl i, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Suc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210395
- Q04210394 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co. of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Gvc list anci COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- 204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN Et. Division of Engineering & Quality Assurance 82/07/22 Consulidate & Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22,8204210398
- 8208160328 Forwards IE Insp Repts 50-413/82-17 & 50-414/82-15 on 820706-09 No noncompliance noted, DANCE,H C Division of Project & Resident Programs 82/07/22 PARKER W O Duke Power Co 2pp 14348 022 24X Fiche 50-413, 82/07/22,8208160328
- --B208160384 IE Insp Repts 50-413/B2-17 & 50-414/82-15 on B20706-09 No noncompliance noted Major areas inspected instrumentation components & sys dissel generator storage & sequencer calibr document control & GC inspector qualifications MILER:N H , CONLON, T E Division of Project & Resident Programs 82/07/20 4pp 14348 024 24X Fiche 50-413,82/07/22,8208160328
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Evc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23,8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 62/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.62/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000.82/07/28.8204210405
- B20Bi602Bi Ack receipt of B206ii ltr informing NRC of steps taken to correct violations nated in IE Insp Repts 80-413/B2-10 & 50-414/B2-04

 DANCE,H C Division of Project & Resident Programs B2/08/02

 PARKER,W C Duke Power Co ip 14345 271 24X

 Fiche 50-413, B2/08/02, B20Bi602Bi
- --8208160290 Forwards response to NRC itr re violations noted in IE Insp Repts 50-413/82-10 & 50-414/82-04 Corrective actions all unmarked copies of controlled documents discarded & training given to GC inspectors in requirements, per GAP-9-1 PARKER.W O. Duke Power Co 82/06/ii 0'REILLY.J P Region 2, Office of Director 2pp 14345 272 24X Fiche 50-413,82/08/02, 8208160281
- --820816029B Forwards IE Insp Repts 50-413/82-10 & 50-414/82-04 on B20326-0425 & notice of violation DANCE.H C Division of Project & Resident Programs 82/05/14 PARKER.H Q Duke Power Co 2pp 14345 274 24X Fiche 50-413,82/08/02,8208160281
- --B208160341 Notice of violation from insp on 920326-0425 ** Division of Project & Resident Programs 82/05/14 2pp 14348 276 24% Fiche 50-413,82/08/02.8208160281
- --B208160349 IE Insp Repts 50-413/BR-10 & 50-414/B2-04 on B20326-0425
 Noncompliance noted failure to foliow procedures for
 document control & for corrective action re Class A
 pressurizer relief valles
 VAN DOORN-P K , BRYANT. J C Division of Project & Resident
 Programs 82/05/14 App 14345 278 24X Fiche 50-413,82/08/02,
 B208160281
- 8208160206 Ack receipt of IE Insp Repts 50-413/82-15 & 50-414/82-12 No proprietary info TUCKER: H B Duke Power Ca 82/08/04 O'REILLY, J P Region 2, Office of Director ip 14344 160 24X Fiche 50-413,82/08/04, 8208160206
- 8208160355 Ack receipt of IE Insp Repts 50-419/82-14 & 50-414/82-11 No proprietary info TUCKER: HE Duke Power Co 82/08/04 O'REILLY, J P Region 2, Office of Director 1p 14348 362 24X Fiche 50-413,82/08/04, 8208160355,
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000.82/08/05.8204210407
- R Periodic operating reports & related correspondence
- B208170159 Forwards first quarter 1982 Yellow Book updates re const status EDMARDS,O L Duke Power Co 82/05/20 LDVELACE,W.H Management Information Branch. 5pp 14364 340 24% Fiche 50-000,82/05/20, 8208170159
- 8 Reportable occurrences, LERs & related correspondence
- 8208030242 Significant Deficiency Rept 8D 413-414/82-14 re capacrews that secure starting air valve & housing assembly to cylinder which may bottom out Initially reported on 820628 Transamerica Delval modified assembly procedures PARKER, W. O. Duke Power Co. 82/07/23 O'REILLY, J. P. Region 2, Office of Director 3pp 14198 224 24x Fiche 50-413, 82/07/23, 8208030242

- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1
- E NRG Bafety Evaluation Report (SER), suppls & correspondence
- B208020410 Forwards results of comparisons between revised independent analysis & McDonald Engineering rept re HPCS ave water pump qualification Based on similar results for stresses on pump shaft, issue as identified in Buppl 2 to SER resolved DALE.L F Mississippi Power & Light Co 82/07/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 14145 120 24X Fiche 50-416,82/07/26,8208020410
- 8208030449 Forwards response to OL Condition 2 C (44 a) & SER Suppl 2 re control room & remote shutdown panel environ survey & labeling review for control room shared panels W/ons oversize drawing Aperture card is available in PDR DALE.L F Mississippi Fower & Light Co 82/07/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 102pp 14160 331 24% Fiche 50-416,62/07/30.8208030449
- 920804013; SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE CRAND QULF NUCLEAR STATION.UNITS I AND 2 Docket Nos 50-416 and 50-417 (Mississippi Power and Light) * Office of Nuclear Reactor Regulation, Director NUREO-0831 803 82/07/31 45pp Available at NTB \$4 75 14236,232 24X Fiche 50-416,82/07/31,8208040131
- 8208120244 Forwards analyses re drywell purge/ventilation isolation valve operability during design basis LOCA in drywell, in response to License Condition 1 11(43) of 8uppl 2 to BER Two oversize drawings encl Aperture cards are in PDR DALE, L.F. Mississipp: Power & Light Co. 82/08/09 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 16pp 14324 095 24X Fiche 30-416,82/08/07,8208120244
- --8208120255 "Isolation/Purge Valve Analysis for 20-Inch 1200 Butterfly Valve " Two oversize drawings encl Aperture cards are available in PDR KAZA,R N. BALLUN,J V. Bechtel Corp. 9645-M-258 ROZ 82/06/22 82pp 14324 113 24X Fiche 50-416.82/08/07.8208120244
- 8208120297 Forwards add1 info in support of util position on long-term operability of deep draft design pumps, in response to NRC request re SER Item i 10(13)

 DALE: L F Mississippi Power & Light Co 82/08/09 DENTON, H. R
 Office of Nuclear Reactor Regulation, Director 4pp 14324:336
 24X Fiche 50-416,82/08/09,8208120297
- --8208120302 CTO Manual.Chapter 5.Bection 4. "Vibration Monitoring," Revision 1 WEBER,H H. SKINNER,P A. Mississippi Power & Light Co. 82/07/11 15pp 14324 340 24X Fiche 50-416,82/08/09.8208120297
- --B20B120314 Surveillance Procedure.06-OP-1P41-M-003, "Btandby Syc Water Loop B Functional Test Safety-Related," Revision 11 EDMGNDS.M L , JOHNBON.0 , HAYES.C Mississippi Power & Light Co 82/06/26 lipp 14324 354. 24X Fiche 50-416.82/08/09.820B120297
- 8208250512 Forwards Buppl 3 to 8ER (NUREQ-0831) W/o encl BCHWENGER, A Licensing Brench 2 82/08/09 MCGAUGHY, J P Mississippi Fower & Light Co 2pp 14562 244 24X Fiche 50-416, 82/08/09, 8208250512
- F Security, medical, emergency & fire protection plans
- 8208030024 Releases public version of revision to emergency plan FELTON, J M Division of Rules and Records 82/07/28 Dacument Management Branch 1p 14197 001 24X Fiche 50-416.82/07/28, 82080300024
- --8208030028 Forwards public version of Revision & to emergency plan.
 Revision addresses items from recent emergency preparedness
 insps & Suppl 1 to SER
 DALE, L.F. Mississippi Power & Light Co. 82/07/20 DENTON, M. R.
 Office of Nuclear Reactor Regulation, Director, 1p. 14197, 002
 24X Fiche 50-416, 82/07/28, 8208030024
- --9208030032 Public version of Revision 6 to emergency plen

 * Mississippi Power & Light Co 82/06/10 145pp 14197 004
 24% Fiche 50-416.82/07/28.8208030024
- 8208110215 Discusses concerns w/use of carbon dioxide sys for fire protection in or adjacent to critical areas & recent event involving actuation of carbon dioxide sys in ECC8 penetration room.

 MICHELSON, C Director's Office 82/07/28 DENTON, H. R Office of Nuclear Reactor Regulation, Director 2pp 14329, 077, 24X Fiche 50-416, 82/07/28, 8208110215

- --8202220663 Advises of concurrence w/conclusion that safety-related sys in areas where fire protection is provided should be re-evaluated in items of ability to function during & following action of fire protection sys MICHELBON.C Director's Office 82/01/28 VOLLMER.R Quality Assurance Branch JORDAN.E Division of Engineering 7pp 14329 079 24X Fiche 50-416, 82/07/28,8208110215
- 8208110118 Responds to 820713 request for add1 info re deficiencies in state & local emergency plans identified in FEMA 820329, "Supplemental Interim Findings " State of MS deficiency resolved LA corrective actions to be completed Sept 1982 KRIMM.R W Federal Emergency Management Agency 82/08/02 ORIMES, B Emergency Preparedness Program Office (after 80119 see 1&E) ip 14314 318 24X Fiche 50-416, 82/08/02, 8208110118
- B20B090067 Forwards Revision 4 to physical security plan Revision withheld (ref 10CFR2 790)
 MCGAUGHY, J.P. Mississippi Power & Light Co. B2/0B/04 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 3pp. 14269 224
 24X Fiche 30-416.82/08/04,8208090067
- 8208090075 Describes testing performed per License Condition 2 C 39(b) to demonstrate adequacy of alerting/notification sys Sirens tested satisfactorily Description of alerting notification sys submitted on B20408 encl
 DALE.L F Mississippi Power & Light Co 82/08/05 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 14270 061
 24X Fiche 30-416.82/08/05.8208090075
- 8208260374 Ack receipt of 820409 % 0513 itrs transmitting Revisions 2 % 3 to facility physical security plan Changes meet requirements of 10CFR73 % are acceptable 8CHMENCER.A Licensing Branch 2 82/08/06 DALE.L F Mississippi Power & Light Co 2pp 14595 064 24X Fiche 50-416.82/08/06.8208260374
- 82082A0102 Releases public version of revised corporate emergency plan procedures FELTON.J M Division of Rules and Records 82/08/13 Document Management Branch. 1p 14572 346 24% Fiche 50-416,82/08/13, 8208260102.
- --8208260109 Forwards public version of revised corporate emergency plan procedures, including Procedures 6 1 re notification of unusual event.6 2 re alert & 6 3 re site emergency DALE.L F Mississippi Power & Light Co 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 14572, 347 24% Fiche 80-416, 82/09/13, 8208260102
- ---B20B2601i3 Public version of revised corporate emergency plan procedures, including Procedures 6 i re notification of unusual event.6 2 re 41ert & 6 3 re 41ere 4 energency Revised table of contents encl 4 Mississippi Power & Light Co 82/07/30 300pp 14572 348 24X Fiche 50-416.82/08/13.8208260102
- O Adjudicatory correspondence
- B208050473 Notice of ABLB constitution JA Laurenson Chairman & QD Bright & J Harbour, members COTTER B P Atomic Safety and Licensing Board Panel 92/08/03 2pp 14216 336 24X Fichs 50-416, B2/08/03, 8208050473
- 8208120011 Opposition to State of LA 820721 untimely petition to intervene No good cause for late filing demonstrated Balance of IOCFR 2714 factors weigh against intervention Notices of appearance & Certificate of 8vc encl MAGNER.M E. RAMSON.R J. Hearing Branch 4 82/08/10 Atomic Sefety and Licensing Board Panel 13pp. 14323 323 24X Fiche 50-416,82/08/10.8208120011
- 8208200127 Notice of appearance in proceeding.

 CONNER.T B Mississippi Power & Light Co CONNER.T B Conner & Wetterhahn 82/08/16 2pp 14397 356 24% Fiche 50-416.82/08/16, 82/0820127
- 8208200134 Notice of appearance in proceeding.
 RADER.R.M Mississippi Power & Light Co RADER.R M Conner & Wetterhahn 82/08/16 ip 14393 347 24X Fiche 50-416,82/08/16,8208200134
- 820820013B Notice of apparance in proceeding WETTERHAHN, M J. Mississippi Power & Light Co. WETTERHAHN, M J. Conner & Wetterhahn 82/08/16 ip 14393 341 24X Fiche 50-416, 82/08/16, 820820013B.

8208200240 Answer opposing State of LA 820721 petition to participate as interested state in DL proceeding ASLN lacks jurisdiction to grant relief re Unit I Requirements for late intervention not satisfied M/Certificate of Svc CONNER, T B Mississippi Power & Light Co CONNER, T B Conner & Wetterhahn 82/08/19 Atomic Safety and Licensing Board Panel 21pp 14399 132 24X Fiche 50-416,82/08/19.8208200240

H General correspondence

8208310286 Informs of appointment of DW Jones to MS Power & Light Safety Review Committee/replacing J Paulk,who resigned because of potential conflict of interest DALE,L F Mississippi Power & Light Co 82/08/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 14688 240 24X Fiche 50-416,82/08/27,8208310286

J Insurance & indemnity information

- 8208100089 Forwards executed Amend 1 to Indemnity Agreement 8-72, changing amount of financial protection DALE, L.F. Mississippi Power & Light Co. 82/08/04 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ... 3pp. 14297 354 24X Fiche 30-416, 82/08/04, 8208100089
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8208230384 Discusses ACRS 268th meeting on 820812-14 re review of util application for OL Unit 1 operation recommended SHEHMON.P ACRS Advisory Committee on Reactor Safeguards 82/08/18 PALLADINO.N J Commissioners 3pp (4513 001 24X Fiche 50-414.82/08/18,8208230384

P. Operating license stage documents & correspondence

- 8208120384 Forwards Amend 1 to License NPF-13 & notice of issuance & availability Amend changes max isolation time for secondary containment isolation Valve Pi1-F02 from 4 to 9 seconds SCHMENCER.A Licensing Branch 2 82/06/30 MCGAUOHY.JP Mississippi Power & Light Co 4pp 14340 281 24X Fiche 50-416.82/06/30.8208120384
- --8208120389 Amend 1 to License NPF-13, changing max isolation time for secondary containment isolation valve P-11F062 from 4 to 9 seconds SCHWENCER, A Licensing Branch 2 82/06/30 App 14340 285 24X Fichs 50-416, 82/06/30, 8208120384
- --B20B130015 Notice of issuance & availability of Amend 1 to License NFF-13
 BCHWENCER, A Licensing Branch 2 82/06/30 4pp 14340'291, 24X
 Fichs 50-414,62/06/30,8208120384
 - '07080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Byc list encl
 DIRCKS, H J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 30-000, 82/07/02.8207080064
- 8208160508 Confirms 820709 telcon re 820716 meeting w/util in Jackson, MS to discuss importance of corporate safety review committee; placing major emphasis on initial operations & assigning nuclear advisor to plant manager O'REILLY, J P Region 2, Office of Director 82/07/16 STAMPLEV, N L Mississippi Power & Light Co 2pp 14348 293 24X Fiche 30-416, 82/07/16, 8208160508
- 8208040212 Expresses appreciation for util cooperation in forwarding INPO mpt rept & util responses to rept when completed SCHMERCER.A Licensing Branch 2 82/07/21 MCOAUGHY.JP Mississippi Power & Light Co 2pp 14232 237 24X Fiche 50-416.82/07/21.8208040212
- 8208040581 Summary of 820714 meeting w/applicant.GE, Bechtel & consultants in Bethesda.MD re Mark III containment concerns of J Humphrey.Details of action plan & schedule & tentative agenda for ACRS 820727-30 meeting encl HOUGTON.D Licensing Branch 2 82/07/26 SCHWENCER.A Licensing Branch 2 24pp 14228 235 24X Fiche 50-416,82/07/26,8208040581.
- 8208030545 Provides response to informal request re adjustment factors for determination of operating limits using ODYN model Two adjustment factor options discussed DALE: L.F. Mississippi Power & Light Co. 82/07/29 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pp. 14162 103 24X Fiche 50-416.82/07/29.8208030545

- 8208030585 Forwards addl info per NUREG-0737, Item II B 3 re post-accident sampling requirements, ref NRC Question 281 9 DALE, L F Mississippi Power & Light Co 82/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14162 142 24X Fiche 50-416,82/07/30,8208030585
- --B20B030596 Revision 0 to "Chemistry Instruction Development & Use of Calibr Curves for Boron Determinations Using Fluoroborate Electrode Safety-Related "
 * Mississippi Power & Light Co 82/06/26 Bpp 14162 144 24x Fiche 50-416, 82/07/30, 8208030585
- --8208030607 Draft Revision 4 to "Chemistry Instruction Development & Use of Calibr Curves for Chloride Determinations Utilizing Chioride Electrodes Safety-Related " No date # Mississippi Power & Light Co 82/07/30 10pp 14162 152 24X Fich# 50-416,82/07/30,8208030585
- --8208030620 Revision 2 to "Chemistry Instruction Operation of Canductivity Bridge Safety-Related"

 MEDOEWORTH: 8 . WILLIAMS, 0 D . STUART, C L Mississippi Power & Light Co 81/01/20 9pp 14162 162 24X Fiche 50-416.82/07/30,8208030585
- --8208030645 Revision 3 to "Chemistry Instruction Operation of pH Meter Safaty-Related" WEDDEMORTH. D Mississippi Power & Light Co 82/06/15 Spp 14162 171 24X Fiche 50-416.82/07/30.8208030383
- --8208030653 Revision 2 to "Chemistry Instruction Sample Preparation for Counting Safety-Related" WEDECHURTH, 8 Mississippi Power & Light Co 82/02/02 12pp 14162 176 24X Fiche 50-416,02/07/30,8208030595
- --8208030660 Revision O to "Chemistry Instruction Germanium Spectroscopy Boftware Safety-Related" * Mississippi Power & Light Co 82/06/29 18pp 14162 188 24x Fiche 50-416,82/07/30,8208030585
- --8208030465 Revision O to "Chemistry Instruction Operation of Orion 701 Ion Analyzer Safety-Related" HEDOEHORTH.8, STUART.C L Mississippi Power & Light Co 82/04/28 lipp 14162 206 24X Fiche 50-416,82/07/30.8208030585
- 8208050428 Forwards "Independent Design Review of Grand Gulf Nuclear Station - Unit I." draft final rept Review resulted in no reportable findings WITTIG.T T Cygna Energy Services 82/07/30 EISENHUT, D G Office of Nuclear Reactor Regulation, Director 2pp 14214 210 24X Fiche 50-416,82/07/30,8208050428
- --8208050432 "Independent Design Review of Grand Gulf Nuclear Station -Unit 1," draft final rept * Cugna Energy Services TR-82026-2 82/07/30 575pp 14214 212 24X fiche 50-416,82/07/30,8208050428
- 8208090092 Provides clarification of drywell purge & post-LOCA vacuum relief sys position indication & 820702 request for amend to OL Min drywell bypass leakage limit will not be exceeded Position indication on check valves unnecessary DALE, L. F. Mississippi Power & Light Co. 82/08/05 DENTON, H. R. Office of Nuclear Reaction Point Co. 1270 237 24X Fiche 50-416.82/08/05,8208090092
- 8208090260 Application to amend License NPF-13 to provide relief from complete compliance w/Reg Guide 1 75 until 1% power & to effect administrative change to Attachment 1 re leek testing of control room envelope Justification provided STAMPLEY.N L Mississippi Power & Light Co 82/08/05 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 14270 341 24% Fiche 50-416.82/08/05.8208090260
- 8208100134 Forwards responses to EO&Q comments on first util heavy load submittal transmitted in 811123 ltr Rescheduling of conference call WEG&Q RNC until wk of 820816 requested DALE/L F Mississippi Power & Light Co 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 24pp 14298 133 24X Fishe 50-416,82/08/06.8208100134
- 8208090194 Oeneric Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements for list enci EISENHUT, D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356.332 24X Fiche 50-000.82/08/09.8208090194

- 8208120149 Forwards evaluation on effects of high water levels in power block area due to PMP event Results indicate that permanent mods necessary for control & diesel generator bldgs & standby svc water basin DALE, L F Mississippi Power & Light Co 82/08/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 19pp 14327 074 24% Fiche 50-4(6,82/08/09,8208120149
- 820B120276 Forwards supplemental info re plant communications & diesal generator reliability.per Conditions 2 C (32) & (33) to License NPF-13 License Condition 2 C (33)(a)(2) not applicable & will be removed when license updated DALE/L F Mississippi Power & Light Co 82/08/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 14324 287 24X Fiche 50-416,82/08/09,8208120276
- 8208120222 Application to amend License NPF-13.delaying control room leak tightness testing until unit exceeds 5% power Technical justification encl MCGAUGHY, JP Mississippi Power & Light Co 82/08/10 DENTDN, H I Deffice of Nuclear Reactor Regulation, Director 4pp 14326 172 24% Fiche 50-414.82/08/10,8208120222
- B2DB180067 Contends that action taken or planned re loose parts monitoring sys meets License NPF-13 intent since completion of sys testing deferred to 5% power milestone (Item 2 b(3), Attachment 1)

 DALE; L F Mississipi Power & Light Co 82/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14377 284 24X Fiche 50-416,82/08/13,8208180067
- 8208230364 Forwards info.including GE proprietary info.in response to NRC design questions re facility containment Submittal provides sufficient info for util to receive full power OL Affidavit encl Info withheld (ref 10CFR2 790)
 DALE, L.F. Mississippi Power 2. Light Co. 82/08/19 DENTON, H.R. Office of Nuclear Resettor Regulation, Director Spp. 14512 321 24X Fiche 50-416.82/08/19.8208230364
- 8208240170 Forwards dotails of cooling tower drift sampling & analytical procedures per environ protection program requirements

 DALE, L.F. Mississippi Power & Light Co. 82/08/20 DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director 4pp 14519 092 24X Fiche 50-416,82/08/20,8208240170
- B208240328 Forwards applicant responses to GE comments on Revision 10 to facility emergency operating procedures GE B20422 ltr providing formal review 2 approval of satisfactory resolution of comments enci
 DALE.L F Mississippi Power & Light Co 82/08/20 DENTON, H R
 Office of Nuclear Reactor Regulation. Director 48pp 14520 225 24X Fiche 50-416.82/08/20,8208240328
- 8208310317 Confirms qualification of 28-inch MSIVs & RHR HX to EGRT criteria: supporting util 820524 commitment Qualification rept cover pages encl DALE.L F Mississippi Power & Light Co 82/08/25 DENYON, H R Dffice of Nuclear Reactor Regulation, Director 4pp 14693 199 24X Fiche 50-416,82/08/25,8208310317
- 8208310445 Requests postponement of Startup Test 1-C91-SU-13-0, "Process Computer" until appropriate time following non-nuclear heatup but prior to exceeding 5% power Approval requested by 820831

 DALE, L.F. Mississippi Power & Light Co. 82/08/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 14890-246-24X Fiche 50-416,82/08/27,8208310445
- Q Inspection reports, IE Bulletins & correspondence
- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " 8vc list encl
 JORDAN, E.L. Division of Engineering & Quality Assurance, 82/07/16
 Consolidated Edison Co. of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210373
- 8204210395 IE Info Notice Bi-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Evc list encl JORDAN.E L Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,
- 8204210396 IE Info Notice 82-29, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Bvc list enci CDBB, L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24% Fiche 50-000.82/07/20.8204210397
- 8208160228 Forwards IE Insp Repts 50-416/82-51 & 50-417/82-10 on 820628-0701 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/07/21 STAMPLEY,N L Mississippi Power & Light Co. 2pp 14346 283 24X Fiche 50-416, 82/07/21, 8208160228
- --8208160236 IE Insp Repts 50-416/82-51 & 50-417/82-10 on 820628-0701
 No noncompliance noted Major areas inspected intervice insp
 & test programs; potential reportable deficiencies & steel
 structures & supports
 BLAKE, J . ECONOMOS, N Division of Engineering & Technical
 Programs 82/07/19 5pp 14346 285 24X Fiche 50-416,82/07/21,
 8208160228
- 820421039B IE info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 820B030400 Ack receipt of 820706 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-32 LEWIS.R C Division of Project & Resident Programs 82/07/22 STAPLEY.N L Mississippi Power & Light Co ip 14154 143 24X Fiche 30-416.82/07/22.8208030400
- --B20B03040B Responds to NRC 820604 itr re violations noted in IE Insp Rept 50-416/82-32 Corrective actions stick file checked to verify that drawings reflect latest revision shown in aperture card file MCOAUGHY, J.P. Mississippi Power & Light Co. B2/07/06 O'REILLY, J.P. Region 2. Office of Director 2pp 14154,144 24X Fiche 50-416,82/07/22,8208030400
- --8208030419 Responds to NRC 820604 ltr re violations noted in IE Insp Rept 50-416/82-32 Corrective action all mati & test aquipment overdue recalled for calibr except equipment lost or replaced MCGAUGHY, J P Mississippi Power & Light Co 82/07/06 O'REILLY, J P Region 2. Office of Director 3pp 14154 146 24X Fiche 50-416,82/07/22,8208030400
- --8208030423 Forwards IE Insp Rept 50-416/82-32 on 820503-07 & notice of violation
 LEWIS.R C Division of Project & Resident Programs 82/06/04
 8TAMPLEY.N L Mississippi Power & Light Co. 2pp 14154 149 24X
 Fiche 50-416,82/07/22.8208030400
- --8208030428 Notice of violation from Insp on 820503-07 * Division of Project & Resident Programs 82/06/04 2pp 14154 151 24X Fiche 50-416, 82/07/22,8208030400
- --B208030434 iE Insp Rept 50-416/82-32 on B20503-07 Noncompliance noted failure to control drawing & failure to calibr measuring & test equipment within required frequency BELISLE, G A , BEMIS.P R , BUTCHER, R C Division of Project & Resident Programs 82/05/28 17pp 14154 153 24% Fiche 50-416,82/07/22,8208030400
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tuba Support Pin Failures at Westinghouse PMRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PHR Power Plants " Evc list encl JORDAN, E L Division of Engineering & Quality Assurance Consolidated Edison Co of New York, 121pp 14357.013, 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc List encl JORDAN,E L. Division of Engineering & Guality Assurance B2/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405

- 820B160234 Informs that no motor operated gate valves have been installed or will be installed in facilities, per IE Bulletin 81-02. Suppl 1
 STAMPLEY, N L Mississippl Power & Light Co 82/08/02
 O'REILLY, J P Region 2. Office of Director 2pp 14347 033
 Fiche 50-416, 82/08/02.8208160234
 - 14347 033 24X
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000.82/08/05,8204210407

R Periodic operating reports & related correspondence

- 8208190274 Forwards monthly operating rept for Jul 1982
 DALE, L.F. Mississippi Rower & Light Co. 82/08/13 DEYOUNG, R.C.
 Dirsctor's Office, Office of Inspection and Enforcement 2pp
 14387 338 24% Fiche 50-416.82/08/13.8208190274
- --B208190277 Monthly operating rept for Jul 1982 RICHARDSON, J D Mississippi Power & Light Co 1 14387 340 24X Fiche 50-416, 82/08/13, 8208190274 82/07/10 9pp

B Reportable occurrences, LERs & related correspondence

- 8208020067 Forwards LER 82-006/01T-0 STAMPLEY, N L Mississippi Power & Light Co 82/07/21
 G'REILLY, J P Region 2, Office of Director 1p 14144 124 24X
 Fiche 50-416,82/07/21,8208020067
- --B20B020070 LER 82-006/01T-0 on B20709, violation of Tech Spec 4 7 B identified re temp monitoring of specific safety-related areas every 12-h Caused by procedural inadequacy & personnel error re operating log requiring recording once every 24-h BYRD.R Mississippi Power & Light Co B2/07/21 Region 2, Office of Director 2pp 14144 125 24X Fiche 50-416, B2/07/21, B20B020067
- 8208020140 Forwards LER 82-005/01T-0 8TAMPLEY,N L Hississippi Power & Light Co 82/07/21 O'REILLY,J P Region 2. Office of Director 1p 14142 029 Fiche 50-416, 82/07/21, 8208020140
- --8208020145 LER 82-005/01T-0 on 820709, while performing refueling interlock check, automatic interlocks failed to stop refueling platform approach to core Caused by malfunction of interlock relay Relay replaced.

 BYRD.R Mississippi Power & Light Co 82/07/21 Region 2, Office of Director 2pp 14142 030 24X Fiche 50-416,82/07/21,8208020140
- 8208030482 Forwards LER 82-007/01T-0 MCGAUGHY, J P Mississippi Power & Light Co 82/07/27, O'REILLY, J P Region 2, Office of Director 1p 14154 0B3 24X Fichs 50-416.82/07/27,8208030482
- --8208030490 LER 82-007/01T-0 on 820715, during special review of fire detection sys by Bechtel AE, smake detectors not found in areas w/divisional cable Sys design did not include fire detectors Design change initiated BYRD.R Mississippi Power & Light Co 82/07/27 Region 2. Office of Director 2pp 14154 084 24X Fiche 50-416, 82/07/27, 8208030482
- 820809004i Final deficiency rept re Div III diesel generator room ventilation sys Initially reported on 820504 Individuals reinstructed on procedural requirements for conduct of maint activities re preparation of work authorization changes MCOAUGHY.J.P Mississippi Power & Light Co 82/07/30 D'REILLY.J.P Region 2. Office of Director 3pp 14270.351. Fiche 50-416.82/07/30.8208090041 14270.351. 24X
- 82080&0191 Forwards LER 82-008/99L-0 STAMPLEY, N.L Hississippi Pawer & Light Co O'REILLY, J.P. Region 2. Office of Director Ficher 50-41& 82/08/02. 82080&0191. 14239 016, 24X
- --8208060196 LER 82-008/99L-0 on 820626.ventilation dampers for Div 1 & 2 switchgear rooms failed to close upon carbon dioxide actuation signal Caused by insufficient power supply needed to melt electro-thermal links connected to damper BYRD.R Mississippi Power & Light Co BZ/OB/OZ Region 2, Office of Director 2pp. 14239-017 24X Fiche, 50-416, 82/OB/OZ, 8208060191
- B208060232 Forwards LER 82-009/03L-0. Detailed event analysis submitted STAMPLEY.N L Hississippi Power & Light Co 82/08/02, O'REILLY, J P Region 2. Office of Director ip, 14241,320 24X Fiche 50-416,82/08/02,8208060232

- Mississipp: Power & Light Co 82/08/02 Region 2. of Director 2pp 14241 321 24X Fiche 50-414,82/08/02. Office of Director
- 82080&0273 Forwards LER 82-010/03L-0 STAMPLEY, N L Mississippi Power & Light Co 82/08/02 D'REILLY, J P Region 2. Office of Director 1p 142-Fiche 50-416.82/08/02.82080&0273 14241 094
- --8208060276 LER 82-010/03L-0 on 820709. Div 2 control room emergency filtration automatic initiation capability declared inoperable Caused by sys isolation under brown tags due to Freen leak in air conditioning compressor BYRD, R Mississippi Power & Light Co 82/08/02 Region 2. Office of Director 2pp 14241 075 24X Fiche 50-416,82/08/02, 2008/0272
- 8208090147 Forwards LER 82-013/03L-0 STAMPLEV.N L Mississippi Power & Light Co O'REILLY.J P Region 2, Office of Director Fiche 30-416, 82/08/04, 8208090147 82/08/04 12 14271 321
- --8208090149 LER 82-013/03L-O on 820702.one 4 16-kV bus undervoltage trip channel setpoint found to be out of Tech Spec value Caused by incorrect calibr procedure Procedure revised ZNKE, G Mississippi Power & Light Co 82/08/04 Region 2, Office of Director ip 14271 322 24% Fiche 50-416,82/08/04,8208090147
- 8208070152 Forwards LER 82-014/03L-0 STAMPLEY,N L Mississippi Power & Light Co O'REILLY,J P Region 2, Office of Director Fichs 50-416,82708/04.8208070152 82/08/04 1p 14270 328 24X
- --8208090210 LER 82-014/03L-0 on 820713, carbon dioxide fire protection sys initiated in electrical penetration room in auxiliary bldg w/o fire Caused by faulty supervisory relay Relay replaced BYRD, R Mississippi Power & Light Co B2/08/04 Region 2, Office of Director 2pp 14270 329 24X Fiche 50-416,82/08/04, 8208090152
- 8208090169 Forwards LER 82-012/01T-0 STAMPLEY,N L Mississippi Power & Light Co 92/08/04 O'REILLY,J F Region 2. Office of Director 1p 142: Fiche 30-416,82/08/04,8208090169 1p 14271 177
- --B208070171 LER B2-012/01T-0 on B20722, radioactive gaseous effluent Sampler flow rates were not being recorded daily per Tech

 Spec 4 3 7 12-1 Operating log did not include sampler
 flow rates Temporary change notice initiated

 NYRD.R Mississippi Power & Light Co 82/08/04 Region 2,

 Office of Director 2pp 14271 178 24X Fiche 30-416.82/08/04. 92090901A9
- 8208070280 Forwards LER 82-011/017-0 STAMPLEY, N L Mississippi Power & Light Co 82/08/04 O'REILLY, J. P. Region 2, Office of Director 1p 142 Fiche 30-416, 82/08/04, 8208070280 14270 304 24X
- --8208070281 LER 82-011/01T-0 on 820722, diesel generator 12 tripped due outlet valve Caused by faulty indicator arrow on Pratt MDT-5 operator Indicator realigned & design modified BYRD,R Mississippi Power & Light Co 82/08/04 Region 2, Office of Director 2pp 14270 305 24X Fiche 50-416,82/08/04.
- B208160075 Second interim deficiency rept re corroded terminal boards on pressure, flow & level transmitters utilized in safety-related applications Initially reported on B20421 Affected transmitters restored to original design criteria MCGAUCHY, J P Mississippi Power & Light Co B2/08/06 O'REILLY, J P Region 2, Office of Director, App 14342, 117 24X Fiche, 50-416, 82/08/06, 8208160075
- 8208160476 Forwards LER 82-015/03L-0 BTAMPLEY.N L Mississippi Power & Light Co 82/08/06 D'REILLY, J P. Region 2. Office of Director 1p 14348 285 Fiche 50-416.82/08/06.8208160476
- --8208160488 LER 82-019/03L-0.on 820714, limiting condition of operation entered due to gasoous effluent sampler being removed from svc for maint Caused by inverted indicator floats in mater tubes due to preoperational testing Floats reinstalled.

 BYRD.R Mississippi Power & Light Co 82/08/06 Region 2, Office of Director 1p 14348 286 24X Fichs 50-416, 82/08/06, 8208160476

- 8208140504 Forwards LER 82-014/03L-0 STAMPLEY, N L Mississipp: Power & Light Co 82/08/06 D'REILLY, J P. Region 2. Office of Director ip 14348 143 24X Fiche 50-414, 82/08/04, 8208140504
- --8208160916 LER 92-016/03L-0 on 820702 during review of completed surveillance, one channel found out of spec Caused by delayed notification to shift supervisor of failure until 820707 when test results identified as unacceptable ZINKE. O Mississippi Power & Light Co 92/09/06 Region 2, Office of Director 2pp 14348 144 24X Fiche 30-416,82/08/06,8208140506
- 8208160339 Final deficiency rept re failure of switching relay in Unit
 1 Division I standby diesel generator Initially reported on
 820326 Relay replaced & design error for both units
 corrected Also reported per Part 2!
 MCGAUGHY, J P Mississippi Power & Light Co B2/08/09
 0'REILLY, J P Region 2. Office of Director 5pp 14348 055 24X
 Fiche 50-416, 82/08/09, 8208160339
- B20B260213 Part 21 rept re HPCS diesel generator air start sys, Initially reported on B20512 Condition unique to Grand Quif plant design EHERWDDD, O O General Electric Co B2/OB/O7 DEYOUNG, R C Director's Office. Uffice of Inspection and Enforcement ip 14554 311 24X Fiche 50-416, B2/OB/O7, B20B260213
- 820B160289 Forwards LER 82-018/01T-0 STAMPLEY, N L Mississippi Fower & Light Co 82/08/10 O'REILLY, J P Region 2, Office of Director ip 14346 272 24X Fiche 50-416, 82/08/10, 8208160289
- --B208160301 LER 82-018/01T-0 on 820728, during special insp, discrepancy between Vol 15.App 9A of FSAR & field condition identified Caused by AE error in not providing fire detectors in plant dasign Necessity for detectors under evaluation BYRD, R Mississippi Power & Light Co 82/08/10 Region 2, Office of Director 2pp 14346 273 24X Fiche 50-416,82/08/10,8208160289
- 8208200020 Forwards LER 82-017/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/08/11 O'REILLY, J P Region 2, Office of Director 2pp 14392 256 24X Fiche 80-416, 82/08/11,8208200020
- --B20B200028 LER B2-017/03L-0 on B20714, during fire door alarms check surveillance test, several doors failed to alarm in secure position Caused by electronic malfunction & equipment out of adjustment Equipment restored to operable status
 BYRD.R Mississippi Power & Light Co B2/08/11 Region 2, Office of Director 2pp 14372 R58 24X Fithe 50-416,82/08/11,820B200020
- 8208200004 Forwards LER 82-020/03L-0 MCGAUGHY, J P Mississippi Pawer & Light Co 82/08/13 D'REILLY, J P Region 2. Office of Director 1p 14392 208 24X Fiche 50-416, 82/08/13, 8208200004
- --B20B200011 LER B2-020/03L-0 on 820718, diesel engine was shutdown prior to completion of HPCB diesel generator 13 functional test due to receipt of high temp alarm Caused by spurious signals as generator was paralleled to bus BYRD.R Mississippi Power & Light Co 82/08/13. Region 2. Office of Director 2pp 14392 209 24X Fiche. 50-416. 82/08/13, 82082000004
- 8208200059 Forwards LCR 82-019/01T-0 MCGAUGHY, J P Mississippi Power & Light Cn 82/08/13 O'REILLY, J P Region 2. Office of Director lp 14393-001 24X Fiche 50-416, 82/08/13, 8208200059.
- --8208200067 LER 82-019/01T-0 on 820801, sampling required on 820729,30 & 31 was not performed Caused by removal of sampler pumps for replacement, due to inoperability of fuel handling area ventilation effluent monitoring sys

 BYRD.R Mississipi Power & Light Co 82/08/13 Region 2,
 Office of Director 2pp 14393 002 24X Fiche 50-416,82/08/13,8208200039
- 8208270227 Supplemental final deficiency rept re 9E Type CR2940 switches installed w/o locking rings, preventing operation of switch Initially reported on 780717 All corrective actions completed 790306 Also reportable per Part 21 MCQAUOHY, J. P. Mississippi Power & Light Co 82/08/16 0'REILLY, J. P. Region 2. Office of Director App 14563 140 24X Fiche 50-416, 82/08/16, 8208270227
- 8208270327 Forwards LER 82-021/03L-0 MCOAUGHY, J.P. Mississippi Power & Light Co. 82/08/17, O'REILLY, J.P. Region 2, Office of Director. 1p. 14564;147 24) Fichs 50-416,82/08/17,8208270327

- --8208270327 LER 82-021/03L-0 on 820720, effluent monitor declared inoperable as gas did not meet requirements of Toch Spec 4 3 7 li for automatic isolation of pathway on down-scale failure Caused by sys design Design change initiated BYRD, R Mississippi Pawer & Light Co 82/08/17 Region 2, Office of Director ip 14564 148 24X Fiche 30-416,82/08/17,8208270327
- 8208270472 Forwards LER 82-022/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/08/17 O'REILLY, J P Region 2. Office of Director 1p 14565 330 24X Fiche 30-416, 82/08/17, 8208270472
- ---8208270483 LER 82-022/03L-0 on 820721, fuel handling area passous effluent monitor inoperable Caused by fuse failure Fuse replaced & monitor re-energized Samples taken during period of inoperability found acceptable

 BYRD.R Mississippi Power & Light Co 82/08/17 Region 2, Office of Director 1p 14565 331 24% Fichs 50-416,82/08/17,8208270472
- 8208270408 Forwards LER 82-024/03L-0 8TAMPLEY, N L Mississippi Power & Light Co., 82/08/19, 0'REILLY, J P. Region 2, Office of Director 19 14965 (91 24X Fiche 50-416, 82/08/19, 8208270400
- --8208270410 LER 82-024/03L-0 on 820723, limiting condition for operation was entered due to inoperability of some 1006 flame detector in HPCS diesel generator east corridor Cause not stated Detector cleaned & texted Fire watch initiated BYRD,R Mississipp: Power & Light Co 82/08/19 Region 2, Office of Director 1p 14565 172 24X Fiche 50-416,82/08/19,8208270408
- 8208270431 Forwards LER 82-023/03L-0 87AMPLEY.N L Mississippi Power & Light Co 82/08/19 0'REILLY,J F Region 2. Office of Director 1p 14965 249 24X Fiche 50-414,82/08/19,8208270431
- ---B20B270434 LER 82-023/03L-0 on B20723, Div 3 Switchgear Room CD2 fire protection sys declared inoperable due to failure of latching mechanism to secure door Caused by failure of striker plate Striker plate adjusted BYRO.R Mississippi Power & Light Co B2/0B/19 Region 2, Office of Director ip 14565 250 24X Fiche 50-416, B2/0B/19, B208270431
- 8208270436 Forwards LER 82-025/03L-0 87AMPLEY.N L Mississippi Power & Light Co 82/08/19 0'REILLY.J P Region 2. Office of Director 1p 14565 251 24) Fiche 50-416, 82/08/19, 8208270436
- --B20B270439 LER 82-025/03L-0 on B20724, fire doors 1A309, 1A109, 1A202 & 1A312 found alarming in closed position Gause not stated fire watch established, magnetic switch components adjusted & operation verified BYRDR Mississippi Power & Light Co B2/0B/19 Region 2, Office of Director 1p 14565 252 24X Fiche: 50-416, B2/0B/19,
- 820B300314 Second interim deficiency rept re corrosion of Dikkers safety relief valve actuators Initially reported on 820521 Analysis of safety implications completed & extent of deficiency determined Next rept provided by 821015 MCOAUOHY, J F Missiusippi Power & Light Co 82/08/20. O'REILLY, J P. Region 2, Office of Director 4pp 14599:327 24X Fiche: 50-416,82/08/20,8208300314
- 8208300105 Forwards LER 82-026/03L-0 MCGAUGHY, J P Mississippi Pawer & Light Ca 82/08/23, O'REILLY, J P Region 2: Office of Director 1p. 14576:113. 24X Fiche 50-416, 82/08/23, 8208300105
- "--8208300107 LER 82-026/03L-0 on 820725, smoke detector above stwam tunnel area zone 2-08 alarmed w/o fire & would not reset. Caused by initiated manual pull station Bys restored & hourly fire watch discontinued BYRD.R Mississippi Pawer & Light Co. 82/08/23. Ragion 2. Office of Director. ip 14576:114 24X Ficha: 50-416, 82/08/23, 8208300105.
- T Hearing transcripts on non-antitrust matters
- 8208130147 Transcript of ACRS Subcommittee on Grand Oulf 820811 meeting in Washington, DC Fp 1-187 Viewgraphs encl # ACRS Advisory Committee on Reactor Safeguards 82/08/11 296pp. 14337.151 24X Fiche 50-416.82/08/11/8208130147

- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS,W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14174 001
 24X Fishe 50-000.82/07/02.8207080064
- 8208040212 Expresses appractation for util cooppration in forwarding INPO mgt rept & util responses to rept when completed SCHWENCER.A Licensing Branch 2 82/07/21 MCGAUGHY, J P Mississippi Fower & Light Co 2pp 14232 239 24X Fiche 50-416,82/07/21,8208040212
- 8208040581 Summary of 820714 meeting w/applicant, 6E, Bechtol & consultants in Bethesda, MD re Mark III containment concerns of J Humphrey Details of action plan & schedule & tentative agenda for ACR8 820727-30 meeting encl JOUSTON D Licensing Branch 2 82707/26 SCHWENCER, A Licensing Branch 2 24pp, 14228 235 24X Fiche 50-416, 82/07/26, 8208040581
- 9208030545 Provides response to informal request re adjustment factors for determination of operating limits using ODYN model Two adjustment factor options discussed
 DALE, L. F. Mississipp: Power & Light Co. B2/07/29 DENTON, H. R. Dffice of Nuclear Reactor Regulation. Director 2pp 14162 103
 24X Fichs 50-416.82/07/29.8208030545
- 8208030585 Forwards add1 info per NUREC-0737, Item II B 3 repost-accident sampling requirements, ref NRC Question 281 9
 BALE.L F Mississippi Fower & Light Co 82/07/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director, 2pp 14142:142
 24X Fiche 50-416.82/07/30,8208030585
- --8208030596 Revision O to "Chemistry Instruction Development & Use of Calibr Curves for Boron Determinations Using Fluoroborate Electrode Safety-Related" * Histosippi Power & Light Co 82/06/26 8pp 14162 144 24x Fiche 50-416,82/07/30,8208030585
- --8208030AO7 Draft Revision 4 to "Chemistry Instruction Development & Use of Calibr Curves for Chloride Determinations Utilizing Chloride Electrodes Safety-Related "No date # Mississippi Power & Light Co 82/07/30 10pp 14162 192 24X Fiche 80-416,82/07/30,8208030585
- --8208030620 Revision 2 to "Chemistry Instruction Operation of Gonductivity Bridge Safety-Related" WEDCHURTH.B , WILLIAMS.G D , STUART.C L Mississippi Power & Light Ca 81/01/20 Spp 14162 162 24X Fiche 50-416.82/07/30. 8208030385
- -8208030648 Revision 3 to "Chemistry Instruction Operation of pH Meter Safety-Related"
 WEDOEWORTH: B Mississippi Power & Light Co 82/06/15 5pp 14162 171 24X Fiche 50-416.82/07/30.8208030585
- -B208030653 Revision 2 to "Chemistry Instruction Sample Preparation for Counting Bafety-Related " WEDGEMORTH, B Hississippi Power & Light Co 82/02/02 12pp 14162 176 24X Fichs 50-416,82/07/30,8208030585
- --8208030660 Revision O to "Chemistry Instruction Germanium Spectroscopy Software Bafety-Related" * Mississippi Power & Light Co 82/06/29 18pp 14162 188. 24X Fiche 50-416.82/07/30.8208030585
- --B20803065 Revision 0 to "Chemistry Instruction Operation of Drion 701 Ion Analyzer Bafaty-Related" HEDGEWORTH. B., STUART.C L Mississippi Pawer & Light Co. B2/04/28 11pp 14162:206 24X Fiche 50-416.B2/07/30.B208030585
- 8208090092 Provides clarification of drywell purge & post-LOCA vacuum relief sus position indication & 820702 request for amend to dL Min drywell bypass loakage limit will not be exceeded Position indication on check valves unnecessary DALE/L F Mississippi Power & Light Co 82/08/05 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pg 14270, 237 24X Fiche 50-416,82/08/05,8208090092
 - **OB100134 Forwards responses to EQ&O comments on first util heavy load submittal transmitted in Bill23 ltr Rescheduling of conference call wifG&O & NRC until Wk of B20816 requested DALELL F. Mississips! Power & Light Co B2/08/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 24pp 14278,133 '4X Fiche: 50-416.82/08/06.8208100134.

- 8208090194 Generic Lti 82-14 to all reactor licensoes, holders of CP & applicants re submitted of documents to NRC Summarizes 10CFR Chapter I requirements % provides alternatives to requirements Svc list encl EISENHUT.D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208120149 Forwards evaluation on effects of high water levels in power block area due to PMP event Results indicate that permanent mods necessary for control & diesel generator bldgs & standby svc water basin DALE, L F Mississippi Power & Light Co 82/08/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 19pp 14327 074 24X Fiche 50-416,82/08/09,8208120149
- 8208230364 Forwards info.including GE proprietary info.in response to NRC design questions re facility containment Submittal provides sufficient info for util to receive full power GL Affidavit encl Info withheld (ref 10CFR2 770)

 DALE, L F Mississippi Fower & Light Co 82/08/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 14512 321 24X Fiche 50-416.82/08/19,8208230364
- B208240170 Forwards details of cooling tower drift sampling & analytical procedures per environ protection program requirements

 DALE.L F Mississippi Power & Light Co 82/08/20 DENTON, H R

 Deffice of Nuclear Reactor Regulation, Director App 14919 092 24X Fichs 50-416.82/08/20.8208240170
- 8208240328 Forwards applicant responses to GE comments on Revision 10 to facility emergency operating procedures GE 820422 ltr providing formal review & approval of satisfactory resolution of comments encl DALE, L F Mississippi Power & Light Co 82/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 48pp 14520 225 24X Fiche 50-416.82/08/20.8208240328
- 0208310317 Confirms qualification of 20-inch MBIVs & RHR HX to EGRT criteria, supporting util 820524 commitment Qualification rept cover pages encl DALE.L F Mississippi Power & Light Co 82/08/25 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 14673 197 24X Fichu 50-416.82/08/25,8208310317
- E NRC Bafoty Evaluation Report (SER), suppls & correspondence
- 8208020410 Forwards results of comparisons between revised independent analysis & McDonald Engineering rept re HPCS svc water pump qualification Based on similar results for stresses on pump shaft, issue as identified in Suppl 2 to SER resolved DALE.L F Mississippi Power & Light Co 82/07/26 DENTON, H R Office of Nuclear Reactor Regulation. Director 13pp 14143 120 24X Fiche 50-416.82/07/26.8208020410
- B208030449 Forwards response to OL Condition 2 C (44 a) & SER Suppl 2 re control room & remote shutdown panel snviron survey & labeling review for control room shared panels H/one oversize drawing Aparture card is available in PDR DALE.L F Mississippi Power & Light Co 82/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 102pp 14160 331 24X Fiche 50-416,82/07/30.8208030449
- 8208040131 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE GRAND GULF NUCLEAR STATION, UNITS 1 AND 2
 Doctet Nos 50-416 and 50-417 (Massissippi Power and Light)
 * Office of Nuclear Reactor Regulation, Director NUREO-0831 803 82/07/31 43pp Available at NT18 \$4 75 14236 232 24X
 Fiche 50-416, 82/07/31, 8208040131
- 820B120244 Forwards analyses re drywell purge/ventilation isolation valve operability during design basis LDCA in drywell, in response to License Condition I 11(43) of Suppl 2 to SER Two oversize drawings encl Aperture cards are in PDR DALE.L F Mississippi Power & Light Co 82/08/07 DENTON, H. R Office of Nuclear Reactor Regulation, Director 16pp 14324.095 24X Fiche 50-416,82/08/09,8208120244
- --B208120295 "Isolation/Purge Valve Analysis for 20-Inch 1200 Butterfly Valve " Two oversize drawings encl Aperture cards are available in FDR KAZA-R N , BALLUN,J V Bechtel Corp 9645-M-258 RO2 B2/06/22 B2pp 14324 113 24X Fiche 50-416,82/08/09,8208120244
- 8208120297 Forwards add1 info in support of util position on long-term operability of deep draft design pumps, in response to NRC request re SER Item 1 10(13)

 DALE: L F Mississippi Power & Light Co 82/08/07 DENTON: H R Office of Nuclear Reactor Regulation. Director 4pp 14324 336 24X Fiche 50-416,82/08/09,8208120297

DOCKETED ITEMS

- --8208120302 CTO Manual, Chapter 5, Section 4, "Vibration Monitoring,"
 - Revision 1
 HEBER, H H . SKINNER, P A Mississippi Pawor & Light Co 82/07/11
 15pp 14324 340 24X Fiche 50-416, 82/08/09, 8208120297
- -B208120314 Surveillance Procedure.06-QP-1P41-M-003, "Standby Svc Water Loop B Functional Test.Bafety-Related," Revision 11 EDMONDS.M L , JOHNSON.G , HAYES.C Mississippi Power & Light Co B2/06/26 11pp 14324 354 24X Fiche 50-416.82/08/09.8208120297
- 1208250512 Forwards Suppl 3 to SER (NUREG-0831) W/o enci SCHMENCER.A Licensing Branch 2 62/08/09 MCGANGHY.JP Mississipp1 Power & Light Co 2pp 14562 244 24X Fiche 50-416.82/08/09.8208250512
- Security, medical, emergency & fire protection plans
- 208030024 Releases public version of revision to emergency plan FELTON, J K Division of Rules and Records 82/07/28 Document Management Branch 1p 14197 001 24% Fiche 50-416,82/07/28, B208030024
- -8208030028 Forwards public version of Revision 6 to emergency plan Revision addresses items from recent emergency proparedness
 - naps & Buppl | to BER
 DALE.L F Hississippi Power & Light Co 82/07/20 DENTON, H R
 Office of Nuclear Reactor Regulation. Director ip 14197 002
 24X Fiche 50-416.82/07/28.8208030024
- -8208030032 Public version of Revision 6 to emergency plan

 * Mississippi Power & Light Co 82/06/10 145pp 14
 24X Fiche 50-416.82/07/28.8208030024. 14197 004.
- 108110118 Responds to 820713 request for add1 info re deficiencies in state & local dmergency plans identified in FEMA 820329, "Bupplamental Interim Findings" State of MS deficiency resolved LA corrective actions to be completed Bept 1982 MRIMM.R W Federal Emergency Management Agency 82/08/02 GRIMES, B Emergency Preparedness Program Office (after 801119 act 186) 1p 14314 318 24% Fiche 30-416.82/08/02.8208110118 B01119 \$60
- '08070067 Forwards Revision 4 to physical security plan Revision withheld (ref locfR2 790)
 HCGAUGHY, J P Mississippi Fower & Light Co 82/08/04 DENTON, H R,
 Dffice of Nuclear Reactor Regulation, Director 3pp 14269 224
 24X Fiche 30-416,82/08/04,8208090067
- OBO90075 Describes testing performed per License Condition 2 C.39(b) to demonstrate adequacy of electing/notification sys Sirens tested satisfactorily Description of electing notification sys sybmitted on 620408 encl
 DALE.L F Mississippi Power & Light Co 82/08/05 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 2pp. 14270:061
 24X Fiche 50-416.82/08/05,8208090075
- O8260374 Ack receipt of 820409 & 0513 ltrs transmitting Revisions 2 & 3 to facility physical security plan Changes meet requirements of 10CFR73 & are acceptable SCHMERCER,A Licensing Branch 2 82708/06 DALE,L F Hississipp: Power & Light Co. 2pp 8208260374 Mississippi
- D82A0102 Releases public version of revised corporate emergency plan procedures
 FELTON, J M Division of Rules and Records 82/08/13. Docum
 Management Branch Ip 14572 346 24X Fiche 50-416, 82/08/13,
- 3208260109 Forwards public version of revised corporate emergency plan procedures, including Procedures 6.1 re notification of unusual event, 6.2 re alert & 6.3 re site emergency DALE, L. F. Mississippi Power & Light Co. 82/08/06 DENTON, H. R. Defice of Nuclear Reactor Regulation, Director ip 14572 247, 247, Fiche 50-416, 82/08/13, 8208260102
- 32082601(3 Public version of revised corporate emergency plan procedures: including Procedures & I re notification of unusual event.6 2 re alert & 6.3 re site emergency Revised table of contents encl * Mississippi Power & Light Co 82/07/30. 300pp 14572 348. 24X Fichs.30-416.82/08/13.8208260102
- Adjudicatory correspondence
- 9050473 Notice of ASLD constitution JA Laurenson, Chairman & GD Tight & J Harbour, members
 OTTER, B P. Atomic Bafety and Licensing Board Panel 82/08/03
 pp 14216-336 24X Fiche, 80-416, 82/08/03, 8208050473

- 8208120011 Opposition to State of LA 820721 untimely petition to intervene No good cause for late filing demanstrated Balance of 10CFR2 714 factors weigh against intervention Notices of appearance & Certificate of Svc encl
 HAONER, M E , RAMSON, R J Hearing Branch 4 B2/08/10 Atom:
 Safety and Licensing Board Panel 13pp 14323 323 24X
 Fiche 50-416, 82/08/10, 8208120011
- 8208200127 Notice of appearance in proceeding CONNER.T B Hississippi Power & Light Co CONNER.T B Conner & Wetterhahn 82/08/16 2pp 14379 356 24% Fiche 50-416.82/08/16.
- B208200134 Notice of appearance in proceeding
 RADER,R M Mississippi Power & Light Co RADER,R M Conner &
 Netterhahn 82/08/16 ip 14393 347, 24X Fiche 50-416,82/08/16
- 8208200138 Notice of appearance in proceeding METTERHAHM.M J Mississippi Power & Light Co WETTERHAHM.M J Conner & Wetterhahn 82/08/16 ip 14393 341 24x Fiche 50-416,82/08/16,8208200138
- 8208200240 Answer opposing State of LA 820721 petition to participate as interested state in CL proceeding ASLB lacks
 jurisdiction to grant relief re Unit 1 Requirements for late intervention not satisfied W/Certificate of Svc
 GONNER.T B Mississippi Power & Light Co CONNER.T B Conner & Wetterhahn 82/08/19 Atomic Safety and Licensing Doard Panel 2ipp 14399 132 24X Fiche 50-416.82/08/19,8208200240
- H General correspondence
- 8208310286 Informs of appointment of DW Jones to MS Power & Light Bafety Review Committee, replacing J Paulk, who resigned because of potential conflict of interest DALE, L.F. Mississippi Power & Light Co. 82/08/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp. 14688-240-24X Fiche 50-416.82/08/27,8208310286
- J Insurance & indemnity information
- 8208100089 Forwards executed Amend 1 to Indemnity Agreement 6-72. changing amount of financial protection

 DALE, L.F. Mississippi Power & Light Co. 82/08/04 DENTON, H.R.

 Office of Nuclear Reactor Regulation, Director 3pp. 14277, 354

 24X Fichs 50-416,82/08/04,8208100087
- Q Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance Consolidates Edison Co of New York B7pp 14356:274 Fiche 30-000-82/07/16.8204210393
- 8204210375 IE Info Notice B1-25.Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19. B204210375
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svt list encl JORDAN.E L Division of Engineering & Quality Assurance, 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks "Bvc list encl COBBL I. Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York, 7ipp. 14357:276 24X Fiche 80-000,82/07/20,8204210397.
- 8208160228 Forwards IE Insp Repts 50-416/82-51 & 50-417/82-10 on 820628-0701 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/07/21 BTAMPLEY, N L Mississippi Power & Light Co 2pp 14346, 283. 2: Fiche 50-416, 82/07/21, 8208160228
- --B208160236 IE Insp Repts 50-416/82-51 & 50-417/82-10 on 820628-0701 No moncompliance noted Major areas inspected inservice insp & test programs potential reportable deficiencies & steel structures & supports.
 BLAKE, J. ECONOMOS, N. Division of Engineering & Technical Programs 82/07/19 Spp 14346-285 24X Fiche 80-416,82/07/21,8208160228

- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JDRDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210378
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E L Division of Englineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23,8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JGRDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000.82/07/23.8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sloeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated & Gison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28,8204210405
- 8208160254 Informs that no motor operated gate valves have been installed or will be installed in facilities.per IE Bulletin 81-02.8 uppl 1
 STAMPLEY.N L Mississippi Power & Light Co 82/08/02
 O'REILLY.J P Region 2. Office of Director 2pp 14347 033 24X Fichs 50-416.82/08/02.8208160254
- 8204210407 lE Info Natice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JRRDANLE L Division of Engineering & Guality Assurance S2/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fichs 50-000, 82/08/05, 8204210407
- 8 Reportable occurrences, LERs & related correspondence
- 8208160337 Final deficiency rept re failure of switching relay in Unit 1 Division I standby diesel generator Initially reported on 820326 Relay replaced & design error for both units corrected Also reported per Part 21 MCGAUCHY, J P Mississippi Power & Light Co 82/08/07 d'REILLY, J P Region 2, Office of Director 5pp 14348 055 24X Fiche 50-416, 82/08/07, 8208160339
- 8208260213 Part 21 rept re HPC8 diesel generator air start sys Initially reported on 820512 Condition unique to Grand Gulf plant design SHERMOOD, 0 0 General Electric Co 82/08/07 DEYGUNG, R C Director's Office, Office of Inspection and Enforcement ip 14554 311 24X Fichs 50-416, 82/08/07, 8208260213
- 8208270227 Supplemental final deficiency rept rs GE Type CR2940 switches installed w/o locking rings, preventing operation of switch Initially reported on 780717 All corrective actions completed 790304 Also reportable per Part 21 MCGAUGHY, J P Mississippi Fower & Light Co 82/08/16 O'REILLY, J P Region 2. Office of Director 4pp 14963 140 24X Fiche 50-416, 82/08/16, 8208270227.
- T Hearing transcripts on non-antitrust matters
- 8208130147 Transcript of ACRS Subcommittee on Grand Gulf 820811 meeting in Washington, DC Pp 1-187 Viewgraphs enct * ACRS Advisory Committee on Reactor Safeguards 82/08/11 296pp 14337:151 24X Fiche 50-416.82/08/11,8208130147.
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 8208020244 Notifies of proposed programmatic change to GA program topical rept. Revision 4A Exception to Paragraph 1 4 of ANSI N45 2 9-1974 re definition of GA records will be added to App F of topical rept. COUNSIL.W 9 Northeast Utilities Bervice Co 82/07/26 HAASS, W. P. Quality Assurance Branch 2pp 14152 234 24X Fiche 50-000, 82/07/26, 8208020244

- 820B100133 Application for amend to CPPR-113 & application for GL Amend provides for addition of purchasers as applicants for all licenses previously requested & for transfers to purchasers of ownership interests Antitrust info encl FERLAND, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) FERLAND, E J Northeast Utilities 82/08/03 YOUNGBLOOD, 8 J Licensing Branch 1 (3pp 14298 157 24X Fiche 30-423,82/08/03,9208100133
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT, D G Division of Licensing 82/09/07 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208240310 Requests review & approval of application for use of ASME Code Case N-310-1 Expedited approval would forego need for costly testing Code case will be used for upgrading commercial mat1 to ASME certified mat1 COUNSIL.W 0. CAGNETA.J P Northeast Utilities 82/08/17 EISENHUT.D & DIVITION of Licensing 2pp 14520 215 24X Fiche 50-423.82/08/17.8208240310

- 8208250135 Notifies of recent changes in util organization reflected in GA program topical rept Revision 4A Details encl COUNSIL,W O Northeast Utilities Service Co 82/08/17 HAASS,W P Guality Assurance Branch 7pp 14541 302 24X Fiche 50-000,82/08/17,8208250135
- M Antitrust correspondence
- 820B100133 Application for amend to CPPR-113 & application for OL Amend provides for addition of purchasers as applicants for all licenses previously requested & for transfers to purchasers of ownership interests Antitrust info encl FERLAND, E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) FERLAND, E.J. Northeast Utilities 82/08/03 YOUN08LOUD, B.J. Licensing Branch i 13pp 14298 157 24X Fiche 50-423, 82/08/03, 8208100133
- Q Inspection reports: IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list enc!
 JRRDAN.E.L. Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14336 274 24X
 Fiche 50-000,82/07/16,8204210393
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list enc! JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks " Svc list encl CORB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 consolidated Edison Co of New York, 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 30-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Evc list encl JRRDAN.E L. Division of Engineering & Quality Assurance B2/07/23 Consolidate Edison Co of New York, 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Fower Plants " Svc list encl. JORDAN.E.L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp, 14357 013 24X Fiche 50-000.82/07/26.8204210403

- 8204210405 IE Info Natice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- S Reportable occurrences, LERs & related correspondence
- 8208090185 Final deficiency rept remissing orifices in sample lines Initially reported on 800225 Field verification found 3 orifices properly installed.5 omitted during fabrication & 11 not fabricated Drawings corrected COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Office) COUNSIL.W O Northeast Utilities 82/07/20 MAYNES.R C Region i. Office of Director 2pp 14272 011 24X Fiche 50-423,82/07/20,8208090185
- DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR SV list encl
 DIRCKS.W J Office of the Executive Director for Operations,
 62/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24% Fiche 50-000:82/07/02.8207080064
- 8208040636 Notification of 820728 meeting w/util & Bechtel in Bethesda, MD to discuss Millett Fault study findings ORANT.J M Licensing Branch I 82/07/23 YOUNOBLOOD, B J Licensing Branch I 3pp 14224 017 24X Fiche 30-424,82/07/23,8208040636
- B20B090174 Generic Ltr 82-14 to all reactor ifcensees, holders of CP & applicants re submittal of documents to NRC Summarises 10CFR Chapter I requirements & provides alternatives to requirements Svc liet enci EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14355 332 24X Fichs 50-00D, 82/08/09, B208090174
- 8208260325 Notification of 820914 meeting w/util. Bouthern Co Bycs. Inc & Bechtel Civil & Minerals. Inc in Bethesda. MD for util presentation of Millett Fault Btudy GRANT. J M Licensing Branch i 82/08/11 YDUNOBLOOD. B Licensing Branch 1 3pp 14576 104 24X Fiche 50-424.82/08/11,8208260325
- [Financial information
- B20B120129 Forwards Annual Financial Rept 1981 Quarterly financial statements for period ending 820630 & projected source of funds statement for Cy83 enci IROWN, M T Georgia Power Co B2/08/09 BALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 7pp 14319 237 24X Fiche 50-000,82/08/09,8208120129
- --8208120134 Annual Financial Rept 1981 BCHERER:R W , MILLER:J H Georgia Power Co 82/02/19 29pp 14319 245 24X Fiche 50-000.82/08/09.8208120129
- Q Inspection reports. IE Bulletins & correspondence
- B204210373 IE Info Notice 82-23, "Main Steam Isolation Volve (MSIV)
 Leakage " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance B2/07/14
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 82042t0375 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Rediation" Syc list encl JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Kichigam, Univ of 112pp 14358 OOI 24X Fichs, 50-000, 82/07/19. 8204210375
- 8204210396 lE info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co of New York 112pp, 14381:001, 24X Fiche 50-000, 82/07/20, 8204210396

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl GDBs.L [Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JRDAN,E L Division of Engineering & Quality Assurance, 82/07/22 Consolidated Edison Co of New York 112pp 14194:321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115. 24X Fiche.50-000,82/07/23.8204210401
- 8204210402 IE Info Natice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Wastinghouse PWRs " Svc list encl JORDAN E L Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Bleeves in RCB Piping at Certain Hestinghouse PHR Power Plants " Svc list enci JORDAN,E L Division of Engineering & Quality Assurance Consolidated Edison Co of New York 121pp 14357 013, 24X Fiche 50-000, 82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list enc! JORDANIE L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- B20B1605i1 Ack receipt of B2072B ltr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-424/82-11 & 50-425/82-11 LEWIS, R.C. Division of Project & Resident Programs. 82/08/04 KELLYR J Georgia Power Co ip 14349 315 24X Fiche 50-424, 82/08/04, 8208160511
- --8208160524 Responds to NRC 820622 itr re-violations noted in IE Insp Repts 50-424/82-11 & 50-425/82-11 Corrective actions contractor directed to be more selective in choosing pige spool storage areas & assign additerioral to monitor area FOSTER.D O Georgia Power Co 82/07/28. LONO,F J Region 2, Office of Director 2pp 14349-316. 24X Fichs 50-424,82/08/04, 8208160511
- --8208160532 Forwards IE Insp Repts 50-424/82-11 & 50-425/82-11 on 820410-0510 & notice of violation LEWIS.R G. Division of Project & Resident Programs 82/06/22. KELLY.R.J Georgia Power Co 2pp 14349 318 24X Fiche 50-424.82/08/04.8208160511
- --8208160834 Notice of violation from insp on 620410-0510 * Division of Project & Resident Programs 82/06/22 ip 14349 320 24X Fiche 50-424,82/08/04,8208160511
- --B208160335 IE Insp Repts 50-424/82-11 & 50-425/82-11 on 820410-0510 Noncompliance noted failure to follow procedures re storage & preservation of matl & failure to have instructions or procedures for survey group SANDERS, W F. BROWNLEE, V. L. Division of Project & Resident Programs 82/06/22 Spp 14349 321 24X Fiche 50-424, 82/08/04, 8208160311
- 8204210407 IE Info Notice 82-27, "Fuel Red Degradation Resulting From Baffle Water-Jet Impingment" Svc list and JRDAN.E L. Division of Engineering & Quality Assurance B2/08/05 Consolidated Edison Co. of New York. 117pp 14388,201 24X Ficher 50-000, 82/08/05, 8204210407
- 8 Reportable occurrences. LERs & related correspondence
- 8208200161 Interim deficiency rept re-starting air valve assembly on standby diesel generators initially reported on 820707.

 Transamerica Delaval will use shortened screws to provide adequate thread engagement Also reportable per Part 21 FOBTER.D O Georgia Power Co. 82708706 O'REILLY.J.P. Region 2. Office of Director 4pp. 14500 115 24X Fiche 50-424,82708706,8208200161
- 8208200005 Beficiency rept re insufficient flow through centrifugal charging pump following secondary side high energy line ruptures Corrective actions to be taken and Also reported per Part 21 FOSTER, D. O. Georgia Power Co., 82/08/10 D'REILLY, J. P. Region 2, Office of Director 7pp 14392-003 24X Fiche 50-424, 82/08/10, 8208200005

- DOCKET 50-425 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS, M J Office of the Executive Director for Operations
 82/07/02 Consolidated Edsson Co of New York 93pp 14194 001
 24X Fiche 50-000,82/07/02.8207080064
- 8208040636 Notification of 820728 meeting w/util & Bechtel in Bethesda, MB to discuss Millett Fault study findings ORANT, J M Licensing Branch 1 82/07/23 YOUNGBLOOD, B J Licensing Branch 1 3pp 14224 017 24X Fische 50-424,82/07/23,
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list enci EISENHUT.D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208260325 Notification of B20914 meeting w/util, Southern Co Svcs. Inc & Bachtel Civil & Minerals. Inc in Bethesda. MD for util presentation of Millett Fault Study GRANTI JM Licensing Branch 1 52/08/11 YQUNOBLOOD, B Licensing Branch 1 5pp 14576 104 24X Fiche 50-424.82/08/11,8208260325

! Financial information

- 8208120127 Forwards Annual Financial Rept 1981 Quarterly financial statements for period ending 820630 & projected source of funds statement for CYB3 encl BROWN.N T Georgia Power Co 82/08/09 SALTZMAN, J Antitrust Economic analysis Branch (Utility Finance) 7pp 14319 237 ALTZMAN, J Antitrust & X42 762 767 Ficha 50-000, 82/08/09, 8208120129
- ~~B208120134 Annual Financial Rept 1981 8CHERER,R W. Georgia Power Co 82/02/19 29pp 14319 245 24X Fiche 50-000,82/08/09.8208120129
- Q Inspection reports, IE Bulletins & correspondence
- B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MBIV)
 Leakage " Svc list enc!
 JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/14
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000.82/07/16.8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN.EL Division of Engineering & Guality Assurance 82/07/19 Michigan Univ. of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204R10396 IE Info Notice 82~25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20. Consolidated Edison Co of New York 112pp 14381.001 24X Fiche.50~000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357:276 24X Fiche 50-000,82/07/20,8204210397
- B204210398 IE Info Notice 82-25, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 TE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consulidated Edison Co of New York 122pp 14380 115 24X Fiche 30-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse FWRs " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York, 127pp 14174 120 24X Fiche: 50-000, 82/07/23, 8204210402

- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JURDAN, E.L. Division of Engineering & Quality Assurance B2/07/26 Consulvated Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000.82/07/28,8204210405
- 8208160511 Ack receipt of 820728 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/82-11 & 50-425/82-11 LEWIS.R C Division of Project & Resident Programs 82/08/04 KELLY.R J Georgia Power Co ip 14349 315 24X Fiche 50-424.82/08/04.8208160511
- --8208160524 Responds to NRC 820622 ltr re violations noted in 1E Insp. Repts 50-424/82-11 & 50-425/82-11 Corrective actions contractor directed to be more selective in choosing pipe spool storage areas & assign addl personnel to monitor area FOSTER.D O Georgia Power Co 82/07/28 LONG.F J Region 2, Office of Director 2pp 14347 316 24X Fiche 50-424,82/08/04,82708/0644 8208140511
- --8208160532 Forwards IE Insp Repts 50-424/82-11 & 50-425/82-11 on 820410-0510 & notice of violation LEWIS,R C Division of Project & Resident Programs 82/06/22 KELLY,R J Georgia Power Co 2pp 14349 318 24X Fiche 50-424,82/08/04.8208160511
- -- B20B160534 Notice of violation from insp on 820410-0510 * Division of Project & Resident Programs 82/14349 320 24X Fiche 50-424, 82/08/04, 8208160511
- --8208160535 IE Insp Repts 50-424/82-11 & 50-425/82-11 on 820410-0510 Noncompliance noted failure to follow procedures re storage & preservation of matl & failure to have instructions or procedures for survey group BANDERS W F , BROWNLEE, V L Division of Project & Resident Programs 82/06/22 5pp 14349 321 24X Fiche 50-424.82/08/04, 8208160511
- 8204210407 JE Info Notice 82-27, "Fuel Rod Dogradation Resulting From Baffle Hater-Jet Impingement " Svc list encl JURDAN, E. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14368 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8 Reportable occurrences, LERs & related correspondence
- 8208200141 Interim deficiency rept re starting air valve assembly on conscious interim dericiency rept re starting air valve assembly o standby diesel generators initially reported on B20707
 Transamerica DeLaval will use shortened screws to provide adequate thread angagement Also reportable per Part 21
 FOSTER DO Georgia Power Co 92/08/06 O'REILLY, J P Region Office of Director 4pp 14500 115 24X Fiche 50-424,82/08/06, FOSTER. D O Georgia Office of Director 8208200161
- 8208200005 Deficiency rept re insufficient flow through centrifugal charging pump following secondary side high energy line ruptures Corrective actions to be taken and Also reported per Part 21 FOSTER, D O Oeorgia Power Co 82/08/10 O'REILLY, J P Region rector 7pp 14392:003 24% Fiche 50-424,82/08/10: Office of Director

DOCKET STN-50-497 FLOATING NUCLEAR PLANT

- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- Q Adjudicatory correspondence
- 8207090111 Errala order furnishing omissions from ASLB 820630 initial decision
 WOLFERB J Atomic Safety and Licensing Board Panel 82/07/07 Ppp
 13791 335 24X Fiche 50-437,82/07/07,8207090111

1

- 8208120138 Memorandum % Order ALAB-686 subsequent to ASLB 820630 decision, LBF-82-49 immediate effectiveness review of mfg licenses not warranted SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 82/08/11 8pp 14327 109 24% Fiche 50-437,82/08/11,8208120138
- 8208270422 Motion for clarification, or in alternative, petition for reconsideration of ASLAB 820811 Memorandum & Order ALAB-686 re application of immediate effectiveness regulation Certificate of Soc encil COWAN.B Z , KENRICK.J R , DAUGHERTY.T M Offshore Power Bystems (subs of Westinghouse Electric Corp) 82/08/23 Atomic Safety and Licensing Board Panel Spp 14566 079 24X Fiche 50-437,82/08/23,8208270422
- @ Inspection reports, IE Bulletins & correspondence
- 8204210393 | E info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list onc! JORDAN,E L Division of Engineering & Guality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14386 274 24X Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN, E L. Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210375
- B204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradval Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance B2/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000.82/07/20,8204210394
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000.82/07/20,8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 90-000,82/07/22,8204210378
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-27, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JCRDAN, E.L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Syr list encl
 JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28
 Consolidated Edison Co. of New York 122pp 14357 146 24X
 Fiche 50-000.82/07/28.8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" 8vc list encl
 JORDAN,E L Division of Engineering & Guality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000,82/08/05,8204210407
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for CL & holders of CP re Commission approved charter for CRGR Svc list encl
 DIRCKS, W J Office of the Executive Director for Operations
 62/07/02 Consolidated Edison Co of New York 93pp 14174.001
 24% Fiche 50-000,82/07/02,8207080064

- B207220192 Advises that info re socondary water chemistry control requested in NRC 790802 & B20709 ltrs will be addressed in response to F9AR Question 282 3 MILLS.L M Tennessee Valley Authority B2/07/19 ADENSAM, E Licensing Branch 4 1p 13977 261 24X Fiche 50-439,82/07/19,820720182
- 8208050138 Advises that response to NRC 820709 ltr re FSAR will be provided by 830202 MILLS.L M Tennessee Valley Authority 82/08/03 ADENSAM, E Licensing Branch 4 ip 14241 297 24% Fiche 50-438, 82/08/03, 8208060138
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP 4 applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT.D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14354 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208170174 Forwards "Verification of Hydraulic Performance of Containment Bumps" Rept describes test results performed on hydraulic model of reactor bldg sumps KAMMER.D 5 Tennessee Valley Authority 82/08/10 ADENBAM, E Licensing Branch 4 2pp 14364 28B 24X Fiche 50-438, 82/08/10, 8208170174
- --8208170180 "Verification of Hydraulic Performance of Containment Sumps, Bellefonte Nuclear Flant " NYSTROM, J B., HECKER, O E. Alden Research Laboratory 82/05/31 54pp 14366 290 24X Fiche 50-438,82/08/10,8208170174

I Financial information

- B20B10D002 Forwards "TVA Power Program Summary," Vol 2.for fiscal yr ending 810630 & "1981 Power Program Summary," for fiscal yr ending 810930,per Bection 50 71(b) of 100FR50 MILLS,L M Tennessee Valley Authority B2/08/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 118pp 14294 024 24X Fiche 50-000.82/08/06.8208100002
- Q Inspection reports, IE Bulletins & correspondence
- 8208030214 Forwards IE Insp Repts 50-438/62-15 % 50-439/62-15 on 820607-10 No noncompliance noted LONG.F J Division of Project & Resident Programs 82/07/02 PARRICS H © Tennessoe Valley Authority 2pp 14159 340 24X Fiche 50-438, 62/07/02, 8206030214
- --B208030214 IE Insp Repts 50-438/82-15 h 50-439/82-15 on B20607-10 No noncompliance noted Major areas inspected structural concrete activities, licensee action on proviously identified insp findings & licensee-identified items HARRIS.JR, CONLON.TE Division of Engineering & Technical Programs 82/07/02 App 14199 342 24X Fichs 50-438.82/07/02.8208030214
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Mentioring Devices for External Radiation " Svc list encl JORDAN, E L Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list onel JORDANIE L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 143B1 001 24X Fiche 50-000. 82/07/20, 8204210394
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14387 2/6 24X Fiche 50-000.82/07/20.8204210397
- 9208030184 Ack receipt of 920617 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-438/81-33 & 50-439/91-33 VERRELLI.0 M Division of Project & Resident Programs 82/07/20 PARRISH 0 Tennessee Valley Authority ip 14160 166 24X Fiche 50-438, 82/07/20, 9208030184
- --8208030191 Responds to NRC 820126 ltr re violations noted in IE Insp Repts 80-438/81-33 & 50-439/81-33 Denies alleged violation re cold springing in General Const Spec 0-43. "Support & Installation of Piping Sys" MILLS.C. M. Tennessee Valley Authority 82/06/17 G'REILLY, J.P. Region 2, Office of Director 3pp 14160 167 24X Fiche 50-438,82/07/20,8208030184

- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Suc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8208030364 Ack receipt of 820708 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-438/82-ii LEMIS.R C Division of Project & Resident Programs 82/07/22 PARRIB.H O Tennessee Valley Authority 1p 14154 222 24X Fiche 50-438.82/Q7/22.8208030364
- --B20B030373 Responds to NRC B20603 ltr reviolations noted in 1E Insp Repts 50-438/82-11 & 50-439/82-11 Add1 info re 10CFR50 55e should be identified as soon as possible HILLS-L M Tennessee Valley Authority B2/07/12 O'REILLY, J P Region 2, Office of Director ip 14154 223 24X Fiche 50-438,82/07/22.8208030366
- --8208030378 Responds to NRC 820603 ltr re violations noted in IE Insp Repts 30-438/82-ii & 50-439/82-ii Corrective action temporary flexible plastic cover placed over valve to minimize entrance of add contaminants to sys HILLS.L M Tennessee Valley Authority 82/07/08 O'REILLY, J P Region 2. Office of Director 3pp 14154 224 24X Fiche 30-438,62/07/22,8208030366
- --8208030381 Forwards IE Insp Rept 50-438/82-11 & 50-439/82-11 on 820426-29 & notice of violation LEUIS.R C Division of Project & Resident Progrems 82/06/03 PARIS.H O Tennesses Valley Authority 2pp 14154 227 24X Fiche 50-438,82/07/22,8208030366
- --B208030384 Notice of violation from insp on 820426-29
 * Division of Project & Resident Programs 82/06/03 ip
 14154 227 24X Fiche 50-438,82/07/22,8208030366
- --B208030394 IE Insp Repts 50-43B/82-i1 % 50-439/B2-i1 on B20426-29 Noncompliance noted valve next to weld iNL0005 was open % uncovered permitting dirt & debris to enter RCPB piping OIRARD, E H , ECDNOHOS, N Division of Engineering & Technical Programs 82/05/20 Bpp 14154 230 24X Fiche 50-43B, B2/07/22, 8208030366
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDANE L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rad Drive (CRD) Guide Tube Bupport Pin Failures at Westinghouse PWRs " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8208160271 Forwards IE Insp Repts 50-438/82-19 & 50-439/82-19 on 820601-30 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/07/23 PARRIB.H 0 Tennessee Valley Authority 2pp 14347 045 24X Fiche 50-438,82/07/23.8208160271
- --8208160282 IE Insp Repts 50-438/82-19 & 50-439/82-19 on 820401-30. No noncompliance noted Major areas inspected const surveillance. QC investigation rept. QA audits & nonconformance rept reviews & unresolved items HILCOX.J D. QUICK, D.R. Division of Project & Resident Programs 62/07/23 9pp 14347 047 24X Fichs 50-438,82/07/23,8208160271
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Hestinghouse PHR Power Plants" Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 62/07/26 Consolidated Edison Co of New York 12ipp 14357 013, 24X Fiche 50-000, 82/07/26, 8204210403
- 8208030594 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-438/82-14 & 50-438/82-14 WERRELLI.D M Division of Project & Resident Programs. B2/07/26 PARRIS.H G Tennessee Valley Authority ip. 14162 108 24X Fichs 50-438.82/07/26.8208030594
- --B20B030400 Responds to NRC 820616 ltr re violations noted in IE Insp. Repts 50-438/82-14 & 50-439/82-14 Corrective actions all work on isolator cabinets completed & documentation closed KAMMER: D 8 Tennessee Valley Authority B2/07/16 O'REILLY, J.P. Region 2, Offica of Director 2pp 14162 109 24X Fiche 50-438,62/07/26,8208030394.

- --B208030605 Forwards IE Insp Repts 50-438/82-14 & 50-439/82-14 on B20511-14 & notice of violation LONG,F J Division of Project & Resident Programs 82/06/16 PARRIS,H O Tennessee Valley Authority 2pp 14162 111 24x Fiche 50-438,82/07/26.6208030594
- --8208030611 Notice of violation from insp on 820511-14

 * Division of Project & Resident Programs 82/06/16 1p
 14162 113 24X Fiche 50-438,82/07/26,8208030574
- --B209030416 IE Insp Repts 50-438/82-14 & 50-439/82-14 on B20511-14 Noncompliance noted failure to document instructions, procedures & drawings & mods to safety-related cabinets communicated verbally RUFF, A B . CONLON. T E Division of Engineering & Technical Programs 82/06/15 5pp 14162 114 24X Fiche 50-438.82/07/26, 8208030594
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208030222 Ack receipt of 820717 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/82-16 & 50-439/82-16 WERRELLI.D M Division of Project & Resident Programs 82/07/28 PARRIS.H 0 Tennessee Valley Authority Ip 14158 258 24X Fiche, 50-438.82207/28.8208030222
- --B208030225 Responds to NRC 820418 ltr re violations noted in IC Insp. Repts 50-439/82-16 & 50-439/82-16 Corrective actions four loose nut ring retainer bolts retourqued, crimped, inspected & documented MILLS,L M Tennessee Valley Authority 82/07/19 O'REILLY, J, P. Region 2, Office of Director 3pp 14158 259 24X Fiche 50-438, 82/07/28, 8208030222
- --B208030R31 Forwards IE Insp Repts 50-438/82-16 & 50-439/82-16 on 820501-31 & notice of violation CDNG:F3 Division of Project & Resident Programs 82/06/18 PARRIS, H 0 Tennessee Valley Authority 2pp 14158 262 24X Fiche 50-438,82/07/28,8208030222
- --B208030236 Notice of violation from insp on B20501-31
 * Region 2, Office of Director 82/06/18 ip 14158 264 24x
 Fiche 30-438,82/07/28,8208030222
- --8208030244 IE Insp Repts 50-438/82-16 & 50-439/82-16 on 820501-31 Noncompliance noted two not ring retainer bolts discovered loose on cantral rod drive mechanisms CRDM 1209 & 1215 WILCOX, J D . CRLENJAK, R V , GUICK, D R Division of Project & Resident Programs 82/06/18 10pp 14158 265 24X Fiche 50-438,82/07/28,8208030222

1

- 820BiA0144 Responds to IE Bulletin 81-02 Suppl 1, "Failure of Gate Type Valves to Close Against Differential Pressure " Util anticipates submittal of final rept by 82102B upon receipt of revised drawings of field change notices KAMHER.D S Tennessee Valley Authority 82/07/29 O'REILLY, J P. Region 2, Office of Director 1p 14345 123 24X Fiche 50-000, 82/07/29, 8208160144
- 8208140215 Forwards summary of 820728 meeting re insp findings concerning misrepresentation of quality documents & subsequent personnel actions.List of attendees encl LEMIB.R C Division of Project & Resident Programs 82/08/02 PARRIS.H Q Tennessee Valley Authority 4pp 14344-144 24% Fiche 50-438,82/08/02.8208140215
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/08/05 Consolidates Edison Co of New York 117pp 14388 201 24% Fiche: 50-000, 82/08/05, 8204210407,
- 8208240004 Responds to FOIA request for info re implementation of amployee protection provision in Baction 210 of Energy Reorganization Act of 1974 Forwards documents listed in app. FELTON. J M Division of Rules and Records 82/08/05 MARCOUX. N C. LeBoeuf, Lamb, Leiby & MacRae 3pp 14568 050 24X Fiche 50-438,82/08/05,8208240004
- --8208260007 Forwards IE Investigation Repts 50-438/81-26 t 50-439/81-26 on 810831-1001 t notice of violation W/o IE investigation rept O'REILLY, J P Region I. Philadelphia, Office of the Director (81/03/01) 82/01/11 PARRIE.H G Tennessee Valley Authority 2pp 14568 058 24X Fiche 50-438,82/08/05.8208260004

- --8208260020 Notice of violation from insp on 810831-1001 Noncompliance noted licensee contractor discharged from employment at plant site on 810904 & hanger inspector name written on support insp checklist by unauthorised person # Region 1. Philadelphia. Office of the Director (81/03/01) 82/01/11 2pp 14568 060 24% Fiche 50-438,82/08/05,8208260004
- 8208160204 Ack receipt of 820621 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-438/82-12 VERRELLI,D M Division of Project & Resident Programs 82/08/09. PARRIS:H G Tennessee Valley Authority ip 14346 330 24% Fiche 50-436,82/08/09.8208160204
- --8209160210 Responds to NRC 820521 ltr re violations noted in IE Insp Repts 50-438/82-12 & 50-439/82-12 Corrective actions sys uill be flushed in accordance u/procedures until ANSI acceptance criteria are satisfied MILLS.L M Tennessee Valley Authority 82/06/21 O'REILLY, J P Region 2. Office of Director 3pp 14346 331 24X Fiche 50-438,82/08/09.8208160204
- --B208160216 Forwards IE Insp Repts 50-439/82-12 & 50-439/82-12 on B20401-30 & notice of violation LONG, F.J. Division of Project & Resident Programs B2/05/21 PARRISH 9 Tennessee Valley Authority 2pp 14346 334 24X Fichs 50-438, 82/08/09, 8208160204
- --8208160218 Notice of violation from insp on 820401~30

 * Division of Project & Resident Programs 82/05/21 2pp
 14346 335 24X Ficho 50~438,82/08/09,8208160204
- --820B160224 TE Insp Repts 50-438/82-12 & 50-439/82-12 on B20401-30 Noncompliance noted tools & matls obtained from inside safety-related sys indicating sys not constructed in clean condition WILCOX, D , GUICK, D R DIVISION of Project & Resident Programs 82/05/21 12pp 14346 338 24% Fiche 50-438.82/08/09,8208160204
- S Reportable occurrences, LERs & related correspondence
- 8208020158 Interim deficiency rept re B&W erroneous design of RCS supports & restraints Initially reported on 820618 Welds & shear bars at interface points potentially undersized & overstressed Also reported per Part 2!

 MILLS.L M Tennessee Valley Authority 82/07/19 0'REILLY, J P Region 2. Office of Director 2pp 14144 130 24X
 Fishe 50-438, 82/07/19, 8208020158
- B208020380 Second interim deficiency rept re nonconforming math utilized by WKM Valve Div of AIF Industries in mfg decay heat removal sys valves Initially reported on B20503. Next rept will be submitted by B20831 MILLS.L M Tennessee Valley Authority B2/07/17 O'REILLY.J P Region 2. Office of Director 2pp 14150 067 24X Fiche 50-438, 82/07/19.8208020380
- 8208020104 Second interim deficiency rept re omissions in auxiliary feedwater pump drawings Instially reported on 820225 Pump vents, drains & turbino bearing cooling water intorconnecting piping designed Drawings will be issued by 820730 MICLS.L M Tennessee Valley Authority 82/07/20 O'REILLY, J. P Region 2, Office of Director 2pp 14142 205 24X Fiche 50-438, 82/07/20, 8208020104
- 8208020226 Final deficiency rept for Sequoyah, second interim rept for Matts Bar & fifth for Bellefonte, Hartsville, Phipps Send & Yellow Creek re inconsistent establishment of insp program Next rept for Matts Bar & Bellefonte expected B30103, MILLELL M Tennessee Valley Authority 82/07/20. O'REILLY, J P Region 2. Office of Director & pp 14152 344 24X Fiche 50-000, 82/07/20, 8208020226
- 8209020361 Second revised final deficiency rept re mislocation of flow characteristic indicators Initially reported on 810109 Addl mods will be completed by 830131 for Unit 1 & 830630 for Unit 2
 MILLS.C. H. Tennessee Valley Authority 82/07/21 O'REILLY, J.P. Region 2. Office of Director 1p 14190 132 24X
 Fiche 50-438.82/07/21.8208020361
- 8208020152 Final deficiency rept re insufficient review of Engineering Change Notice 1268 concerning secondary containment mods Initially reported on 810710 Audit MBI-13 conducted per Engineering Procedure EN DES-EP 4 02 MILLSIL M Tennessee Valley Authority 82/07/22 O'REILLY, J P Region 2. Office of Director 2pp 14145 098 24X Fiche 50-438,82/07/22,8208020152

- 8208020169 Second interim deficiency rept re seismic analysis of auxiliary control bldg Initially reported on 820226 Rept documenting results of revised seismic analysis will be completed by 820801 Next rept expected 820720 MILLSIL M Tennessee Valley Authority 82/07/22 O'REILLY J P Region 2. Office of Director 2pp 14141 021 24X Fiche 50-438,82/07/22,8208020169
- 8208030203 Final deficiency rept re welding of structural steel annulus floor framing Initially reported on 800415 Only two welds found incomplete Event was isolated incident Helds will be repaired by 820801
 MILLS,L M Tennessee Valley Authority 82/07/26 B'REILLY, J P Region 2. Office of Director 2pp 14158 250 24X
 Fichs 50-438,82/07/26,8208030203
- 8208030207 Interim deficiency rept re tolorance for tubular steel cable tray hangers Initially reported on 820716 Evaluation of root cause continuing Next rept expected by 621108 MILLS.L.M. Tennessee Valley Authority 82/07/26 O'REILLY, J.P. Region 2, Office of Director ip 14159 359 24X Fiche 50-438.82/07/26.8208030207
- 8208030238 Second interim deficiency rept re incorrect insp code on hanger drawings by ITT Grinnell Initially reported on 820301 Held documentation & hanger drawings for ASME Section ITI Class 2 under review Also reported per Part 21 MILLS.L M Tennessee Valley Authority 62/07/26 O'REILLY.J P Region 2. Office of Director 2pp 14158 305 24% Fiche 50-438.82/07/26.8208030238
- 8208030319 Fourth interim deficiency ropt re failure to implement design criteria in design drawings Initially reported on 810401 Evaluation continuing Next rept will be submitted by 830117
 MELLS, L M Tennessee Valley Authority 82/07/27 O'REILLY, J P Region 2, Defice of Director ip 14156 308 24X
 Fiche 50-438, 82/07/27, 8208030319
- 8208030189 Second interim deficiency rept re operational defects in MPI nozzles & thermal sleeves Initially reported on 820429 Nonconformance rept forwarded to B&M Investigation to be completed Dec 1982 Next rept 830301 Reported per Part 21 MILLS.L M Tennesses Valley Authority 82/07/28 O'REJLLY, J P Region 2. Offices of Director 3pp 14160 153 24X Fiche 50-438, 82/07/28, 8208030189
- 8208050183 First interim deficiency rept re embedded piping w/crushable insulation Enitially reported on 820629 Analysis continuing Next rept will be submitted by 830114 MILLS.L M Tennesse Valley Authority 82/07/29 O'REILLY, J P Region 2, Office of Director 2pp 14212 067 24X Fiche 50-438,82/07/29,8208030183
- 8208050216 Sixth interim deficiency rept re main feedwater containment isolation valve miscategorization Initially reported on 810106 Atwood & Morrill teismic & stress rept re swing check valves acceptable Next rept expected by 821206 MILLS.L M Tennessee Valley Authority 82/07/29 O'REILLY, J P Region 2, Office of Director 2pp 14212:133 24X Fiche 50-438,82/07/29,8208050216
- 8208050474 Final deficiency rept re pipe hanger supports added to auxiliary feedwater pipe trench initially reported on 820924 Responsible organization instructed to route all pertinent info for review to all groups involved MILLS.L M Tennessee Valley Authority 82/07/29 D'REILLY, J P Region 2. Office of Director 2pp 14216 348 24X Fiche 50-438, 82/07/29, 8208050474
- 8208050332 Bixth interim deficiency rept re-steam pressure regulator malfunction Initially reported on Bi0519 Util in tentative agreement W/DED findings & details of analysis requested. Next rept expected by 821012 Also reported per Part 21 MILLS.L.M. Tennessee Valley Authority 82/07/30. O'RCILLY, J.P. Region 2. Office of Director 2pp 14219 398 24X Ficher 50-438, 82/07/30, 8208050332
- 8208090084 Second revised final deficiency rept re tapes for heat tracing not meeting chemical specs Initially reported on 811224. Corrective action, involving issuance of 8td Spec 88-817 6 01 & Spec 187-4121. completed on 820715 MILLSIL M Tennesses Valley Authority 82/08/02 0'REILLY, J. P. Region 2. Office of Director ip 14270 197 24X Fiche 50-438, 82/08/02, 8208090084
- 8208070215 Third interim deficiency rept re attachment of pipe supports to 6-inch strip plates Initially reported on 811221 Const personnel performed walkdown of reactor bldgs revealing six unacceptable supports MILLES.LM Tennesses Valley Authority. 82/08/02 0'REILLY, J. P. Region 2. Office of Director 2pp 14272 071, 24X Fichs 50-438,82/08/02,8208090215

- 8208090161 Second revised final deficiency rept re Crane Co main stwam atmospheric dump valvas welded w/o required preheat Initially reported on 810220 Valves will be post-weld heat treated & requalified for impact requirements HILLS,L M Tennesses Valley Authority 82/08/03 D'REILLY, J P Region 2. Office of Director 2pp 14271 181 24% Fiche 50-438,82/08/03.8208090161
- 8208120187 Second revised final deficiency rept re 600-volt \$ 8-kV & 15-kV power cables not qualified to IEEE 383-1974 flame test Initially reported on 800819 Cables removed from cable trays in safety-related areas & replaced MILLS.L M Tennessee Valley Authority 82/08/04 O'REILLY.J P Tennessee Valley Authority 82/08/04 O'REILLY.J P Fiche 50-438,82/08/04,8208120187
- 820B120066 Final deficiency rept re solid state ac voltage relays. Initially reported 810402 Vendor currently modifying internal circuitry of Type 27 (2118 series) undervoltage relays Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 82/08/05, O'REILLY, J P. Region 2. Office of Director 2pp 14327 187 24% Fiche 50-438, 82/08/03, 8208120066
- 8208120153 Final deficiency rept re lack of rebar at main steam & feedwater flued heads Initially reported on 810227 Concrete stiffening walls designed to increase capacity of R-line wall in vicinity of ctr main steam pipe anchors MILLS, L M Tennessee Valley Authority 82/08/05 O'REILLY, J P. Region 2. Office of Director 3pp 14323 284 24X Fiche 50-438,82/08/05,8208120153
- 8208120305 Third interim deficiency rept re improper handling & review of engineering change notices Initially reported on 811215 Review of sample notices continuing Next rept will be transmitted by 830119
 MILLS,L H Tennessee Valley Authority 82/08/05 O'REILLY, J P Region 2, Office of Director 7pp 14325 006 24X
 Fiche 50-000, 82/08/05, 8208120306
- 8208130263 Second revised final deficiency rept re excessive vibrations in essential raw cooling water pump/motor assembles for pumps 1A-1A & 1A-2A initially reported on 800819 Addl weight added to pumps Also reportable per Part 21 MILLS, L M Tennessee Vailey Authority 62/08/06 0'REILLY, J. P. Region 2. Office of Director 2pp 14333, 049 24X Fiche 50-438, 82/08/06, 6208130263
- 8208130287 Second revised final deficiency rept re unacceptable replacement for component cooling water pump shaft Initially reported on 820301 Shaft will be returned to Hayward-Tyler TVA will repair original pump shaft Reported per Part 21 MILLS.L H Tennessee Valley Authority 82/08/06 0'REILLY, J P Region 3. Office of Birector 2pp (4333 070 24X Fiche 50-438,82/08/06,8208130287
- 8208130224 Final deficiency rept to improper use of circuit breakers to shed non-Class IE loads initially reported on 820219 FSAR will be revised to reflect exception to Reg Guide 1 75 & results of analysis & configuration by 821201 MILLS, L M Tennessee Valley Authority 82/08/09 O'REILLY, J P Region 2, Office of Director 17pp 14333 125 24X Fiche 50-438, 82/08/09, 8208130224
- 8208160077 Second interim deficiency rept re overpressurization of makeup & purification piping & valves Initially reported on 820528 investigation of damage underway Util awaiting B&W disposition Next rept due by 821012 HILLS.L M Tennessee Valley Authority. 82/08/10 O'REILLY, J P Region 2. Office of Director 2pp 14342 122 24X Fiche 50-438,82/08/10,8208160077
- 820Bi60307 Second interim deficiency rept re defects in reactor protection sys & ESF actuation sys modules supplied by Bailey Mater Co Initially reported on 820414 Util awaiting B&W response Naxt rept will be submitted by 82I029.

 HILLS, L M Tennessee Valley Authority 82/08/10 O'REILLY, J P Region 2. Office of Director 2pp 14345 301 24X

 Fiche: 50-438, 82/08/10, 8209160307
- 8208160313 Bixth interim deficiency rept re B&W nonconservative analysis of neutron flux in reactor protection sys. Institutly reported on 801105 Analystical software fix will be used to correct problem. Next rept due by 821117 MILLS: L M Tennessae Valley Authority 82/08/10, D'REILLY, J.P. Region 2. Office of Director. 2pp 14348,053 24% Fiche. 50-438,82/08/10,8208160313
- 820816036B Revised final deficiency rept re casting defects in four WKM valves. Initially reported on 800226 Valves 2DH-HV3A & 2DH-HV3B returned to MKM for repairs. Grinding of Valves 10H-HV3B completed Also reportable per Part 21.

 MILLB.L M. Tennessee Valley Authority 82/09/11. O'REILLY, J P. Region 2. Office of Director. 2pp. 14349.350 24X

 Fiche: 50-438.82/08/11,8208160368

- 8208160490 Seventh interim deficiency rept re corrosion of carbon steel piping initially reported on 801230 Statistical analysis of meteorological & river temp data demonstrated validity of lowering max emergency raw cooling water temp MILLG.L M Tennessee Valley Authority 82/08/11 O'REILLY, J P Region 2, Office of Director 2pp 14348 316 24X Fiche 50-438, 82/08/11, 8208160490
- 8208160533 Revised final deficiency rept rescore marks on component cooling water pump shaft Initially reported on 811027 Reinstallation of repaired original shaft must await receipt of correct wear rings Also reportable per Part 21 MILLS,L M Tennessee Valley Authority 82/08/11 0'REILLY, J P Region 2. Office of Director 2pp 14356 155 24X Fiche 50-438,82/08/11,8208160533
- B20B200167 Fourth intorim deficiency rept re stainless atoal pipe in area where lugs mfg by BLNF Const are attached which may exhibit burnthrough, exidation or excessive sensitization initially reported on Bil224 Next rept by B21119 HILLS.L M Tennesses Valley Authority B2/08/12 0'REILLY, J.P. Region 2, Office of Director 2pp 14500 [19 24X Fiche 50-438, 82/08/12, 8208200167
- 8208200209 Third interim deficiency rept re temp of nitrogen supply. Initially reported on 820114 Heaters added for nitrogen to meet min temp requirements Epecs issued & installation drawings changed Next rept expected by 830331 MILLS.L. H. Tennesse Valley Authority 82/08/12 O'REILLY, J.P. Region 2. Office of Director. 2pp 14500 155 24X Fiche 50-438, 82/08/12.8208200207
- 8208270326 Final deficiency rept re dimensionally nonconforming anchorage matl Initially reported on 810505 Inryco determined bushings fully engaged w/couplers will not fail No corrective action required Also reportable per Part 21 HILLS.L M Tennessee Valley Authority 82/08/13 O'REILLY, J P Region 2, Office of Director 3pp 14565 007 24% Fiche 50-438,82/08/13,8208270326
- 8208270107 Third interim deficiency rept re environ qualification of safety-related electrical components Entitially reported on 811021 Util establishing qualification program w/RWH & completing corrective actions Next rept expected by 830805 MICLS,L M Tennesse Valley Authority 82/08/16, D'REILLY, J.P. Region 2, Defice of Director 12pp 14563 326, 24% Fiche 50-438,82/08/16,8208270107
- 8208270097 Second interim deficiency rept re valves not qualified to design requirements Initially reported on 820412 Pressure control valves qualified as active & air supply tenk should be qualified by 820823 Next rept expected by 821214 HILLS.L H Tennesse Valley Authority 82/08/18 0'REILLY, J.P Region 2. Office of Director 2pp 14363 199 24X Fiche: 50-438, 82/08/18, 8208270099
- 8208270245 Final deficiency rept re overpressure protection in decay heat removal sys Initially reported on Bit127. Piping design qualified using ASME Section III requirements & calculations Personnel instructed to review code compliance MILLS.L M Tennessee Valley Authority, 82/08/19 O'REILLY, J P. Region 2. Office of Director. 2pp. 14563 113 24X Fiche 50-498. 82/08/19, 82087245.
- 8208270251 Supplemental deficiency rept re intervening hangers restricting access to walding of structural steel annulus floor framing. Initially reported on 800415 Removal of hangers requires extension of completion date to 820901, MILLG,L M Tennessee Valley Authority. 82/08/19 0'REILLY, J.P. Repion 2, Office of Director. Ip 14564,149, 24X Fiche: 50-438, 82/08/19, 8208270251.
- 8208270361 First interim deficiency rept re deficient steam generator support bolts Initially reported on 820723 Loosened sample holts sent to Singleton Lebs for testing & evaluation. Next rept will be sent by 821221 MILLS.L M Tennessae Valley Authority. 82/08/19 O'REILLY, J P Region 2. Office of Director. Ip 14565 038, 24X Fiche: 50-438, 82/08/19, 8208270361

1

1

- 8208300165 Finel deficiency rept re low lockoff pressure readings on 113 FL Häre & Cable Co post-tensioning sys horizontal tendons Initially reported on B10717 Tendons retensioned & stress relaxation tests performed Also reported per Part 21 MILLS.L.M. Tennessee Valley Authority, 82/08/20, 0'REILLY, J.P. Region 2, Office of Director 35pp 14678'168, 24% Fiche: 50-438, 82/08/20, 8208300165
- 8208300202 Final deficiency rept re failure to properly review auxiliary feedwater syst design criteria diagram, Initially reported on 820414 Ongoing review program initiated reapplicable enginearing procedures
 MILLS,L M. Tennessee Valley Authority. 82/08/23. O'REILLY, J P. Region 2. Office of Director 2pp 14678: 235 24X
 Fiche: 80-438, 82/08/23, 8208300202.

DOCKETED ITEMS

- 8208300211 Sixth interim deficiency rept re procurement control audits initially reported on 810316 TVA quality engineering branch response to audit deficiencies undergoing review Naxt rept due by 821007
 MILLG,L M Tennesse Valley Authority 82/08/23 O'REILLY, J P Region 2, Office of Director 1p 14679 176 24X
 Fiche 50-000, 82/08/23, 8208300211
- 8208300324 First interim deficiency rept re undersized fillet welds made before mid-1980 Initially reported on 820722 Inspresults forwarded for angineering evaluation & disposition Next rept will be provided by 830111 MILLS,L H Tennessee Valley Authority 82/08/23 O'REILLY, J P Region 2. Office of Director 2pp 14599 078 24X Fichs 50-438,82/08/23,8208300324
- 8208300334 Fifth interim deficiency rept re unacceptable pipe break interactions Initially reported on 810127 Engineering change notices issued re chilled & demineralized water & fire protection piping Next rept by 830317 HILLS,L H Tennessee Valley Authority 82/08/23 O'REILLY, J P Region 2. Office of Director 2pp 14599 099 24X Fiche 50-438,82/08/23,8208300334
- 8208300226 Fourth interim deficiency rept re improper torque of Borg-Harner bonnet studs on decay heat removal valves Initially reported on 811222 Item remains open Next rept will be submitted by 821104 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 82/08/24 0'REILLY, J. P Region 2, Office of Director 2pp 14679 056 24X Fiche 50-438,82/08/24,8208300226
- 8208300269 First interim deficiency rept re unapproved work releases allouing const to cut reinforcing steel to install anchor bolts for pipe supports in auxiliary feedwater pipe trench initially reported on 830727 Next rept by 821019 MILLS.L M Tennessee Valley Authority 82/08/24 O'REILLY, J P. Region 2. Office of Director. 2pp 14673 001 24X Fiche 50-438.82/08/24.8208300269
- 8208300086 First interim deficiency rept re undervoltage protection during accident Initially reported on 820727 Present design does not comply d/requirements Revision underway Next rept expected by 82:119
 HILLS,L M Tennesses Valley Authority 82/08/25 D'REILLY, J P Region 2, Office of Director 2pp 14378 248 24X
 Fiche, 50-438, 82/08/25, 8208300086
- 8208300252 First interim deficiency rept re failed valve control unit supplied by Air Conditioning, Refrigeration & Combustion, Inc Initially reported on 820727 Vendor notified of deficiency Also reported per Part 21 Next rept due by 821020 MILLS/L M Tennessee Valley Authority 82/08/25 D'REILLY, J. P. Region 2, Office of Director 2pp 14678, 350 24X Fiche 50-438, 82/08/25, 8208300252

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl
 B2/CKS, M J Office of the Executive Director for Operations
 B2/CY/O2 Consolidated Edison Co of New York, 93pp, 14194,001,
 244 Fiche 50-000,82/07/02,8207080064
- 8207220182 Advises that info re secondary water chamistry control requested in NRC 790802 & 820709 ltrs will be addressed in response to FBAR Question 282 3 MILLS.L.M Tennessee Valley Authority 82/07/19. ADENBAN, E Licensing Branch 4 ip 13977 261 24X Fiche 50-438, 82/07/19, 8207220182
- 8208060138 Advises that response to NRC 820709 ltr re F8AR will be provided by 830202.

 MILLS:L M Tennessee Velley Authority 82/08/03. ADENSAM.E. Licensing Branch 4 ip. 14241 257 24% Fiche 50-438.82/08/03, 820806138
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10GFR Chapter I requirements & provides alternatives to requirements Svc list encl EIBENHUT, D. G. Division of Licensing B2/08/09 Consolidated £4ison Co of New York. Ip. 14356-332, 24X Fiche 50-000, B2/08/09, B208090194

- 8208170174 Forwards "Verification of Hydraulic Performance of Containment Bumps" Rept describes test results performed on hydraulic model of reactor bidg sumps KAMMER.D 8 Tennessae Valley Authority 82/08/10 ADENSAM.E Licensing Branch 4 2pp. 14366 288 24X Fiche 50-438.82/08/10, 8208170174
- --8208170180 "Varification of Hydraulic Performance of Containment Sumps, Bellefonte Nuclear Plant " NYSTROM, J B. HECKER, G E. Alden Research Laboratory 82/05/31 54pp 14366 290 24X Fiche. 50-438, 82/08/10, 8208170174

I Financial information

- B20B100002 Forwards "TVA Power Program Bummary," Vol 2, for fiscal yr ending B10S30 & "19B1 Power Program Bummary," for fiscal yr ending B10930,per Bection 50 71(b) of 10CFR50.
 MILLS/L M. Tennessee Valley Authority 92/08/06 DENTON,H R. Office of Nuclear Reactor Regulation, Director 11Bpp 14274:024 24X Fiche 50-000,B2/08/06,820B100002
- Q Inspection reports, IE Bulletins & correspondence
- 8208030214 Forwards IE Insp Repts 50-438/82-15 & 50-439/82-15 on 820607-10 No noncompliance noted LONG, F. J. Division of Project & Resident Programs, 82/07/02 PARRIGH.0 7 Ennesses Valley Authority 2pp 14159 340 24X Fiche 50-438, 82/07/02, 8208030214
- --8208030216 IE Insp Repts 50-438/82-15 & 50-439/82-15 on 820607-10. No noncompliance noted. Major areas inspected: structural concrete activities, licensee action on previously identified insp findings & licensee-identified items HARRIS.JR, CONCON.T E. Division of Engineering & Technical Programs, 82/07/02. 6pp 14159.342 24X Fiche.50-438.82/07/02, 8208030214.
- 8204210395 IE Info Natice 81-26.Part 3. Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance, 82/07/19 Michigam Univ. of. 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210398
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Fressure" Byo list and JURDANE L. Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co of New York 112pp 14381
- 8204210397 IE Info Notice 82-24, "Water Leaking From V Hazafluoride Overparks" Byc list encl. COBB.L. I. Division of Fuel Facilities, Materials & Bafeguards 82/07/20. Consolidated Edison Co of New York 7ipp. 14357:276 24X Fiche: 50-000.82/07/20.8204210397
- 8208030184 Ack receipt of 820617 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/81-33 & 50-439/81-33. VERRELLI.D M. Division of Project & Resident Programs 82/07/20, PARRIS.H Q Tennesses Valley Authority, ip. 14160 166 24% Fiche 50-438,82/07/20.8208030184
- --8208030191 Responds to NRC B20126 ltr re violations noted in IE Insp. Repts 50-438/81-33 & 50-439/81-33 Denies alleged violation re cold springing in General Const Spec 0-43, "Eupport & Installation of Piping Sys"

 MILLS.L. M Tennessee Valley Authority. B2/06/17 O'REILLY, J. P. Region 2, Office of Director 3pp 14160-167. 24X
 Fiche 50-438,82/07/20,8208030184
- 8204210378 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance. B2/07/22, Consolidated Edison Co. of New York 112pp 14174:321, 24X Fiche.50-000.82/07/22.8204210378.
- 8208030366 Ack receipt of 820708 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-438/82-11. LEHIGHR C. Division of Project & Resident Programs. 82/07/22 PARRISHO, Tennesses Valley Authority. 1p. 14154;222. 24% Fiche:50-438,82/07/22,8208030366.
- --8208030373 Responds to NRC 820603 itr re violations noted in IE Insp Rapts 50-408/82-11 & 50-409/82-11.Add1 info re 10cFR50 55e should be identified as soon as possible, MILLB,L.M. Tennessae Valley Authority. 82/07/12, 0'REILLY,J.P. Region 2. Office of Director. ip. 14154 223, 24X Fichs 50-438,82/07/22,820030366.

- --8208030378 Responds to NRC 820603 ltr re violations noted in IE Insp Repts 50-438/82-11 & 50-439/82-11 Corrective action temporary flexible plastic cover placed over valve to minimize entrance of add1 contaminants to sys MILLS,L M Tennessee Valley Authority 82/07/08 D'REILLY, J P Region 2, Office of Director 3pp 14154:224 24X Fiche 50-438,82/07/22,8208030364
- --8208030381 Forwards IE Insp Rept 50-439/82-11 & 50-439/82-11 on 820426-29 & notice of violation LEWIS:R C Division of Project & Resident Programs 82/06/03 PARRIS:H O Tennessee Valley Authority 2pp 14154.227 24) Fiche 50-438,82/07/22.8208030366
- --8208030394 IE Insp Repts 50-438/82-ii & 50-439/82-ii on 820426-29, Noncompliance noted valve next to weld iNL0005 was open & uncovered.permitting dirt & debris to enter RCPB piping QIRARD, E H . ECONOMOS, N Division of Engineering & Technical Programs 82/05/20 8pp 14154 230 24X Fiche 50-438,82/07/22,8208030366
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN-E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000:82/07/23.8204210401
- 8204210402 IE Info Natice 82-29, "Control Rad Drive (CRD) guide Tuber Support Pin Failures at Hestinghouse PHRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York. 127pp 14194,120 24X Fiche 50-000,82/07/23,8204210402
- 8208160271 Forwards LE Insp Repts 50-438/82-19 & 50-439/82-19 on 820601-30 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/07/23 PARRISH 9 Tennessee Valley Authority 2pp 14347 045 24X Fiche 50-438.82/07/23.8208160271
- --8208160282 IE Insp Repts 50-438/82-i9 % 50-439/82-i9 on 820601-30 No noncompliance noted Major areas inspected const surveillance, 80 investigation rept, 6% audits & nonconformence rept reviews & unresolved Items HILCOX,J D, QUICK,D R Division of Project & Resident Programs, 82/07/23 9pp 14347 047 24X Fiche 50-438,82/07/23,8208160271
- 9204210403 IE Info Notice 82-30, "Loss of Thermal Biseves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl URRDAN.E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357.013, 24X Fiche 50-000.82/07/26.8204210403
- 8208030594 Act receipt of 820716 ltr informing NRC of steps teken to correct violations noted in IE Insp Repts 50-438/82-14 & 50-439/82-14
 VERRELLI, B H Division of Project & Resident Programs 82/07/26 PARRIS, H O Tennesses Valley Authority 1p 14162 108 24X Fiche. 50-438, 82/07/26, 8208030394
- --B208030500 Responds to NRC B20515 ltr re violations noted in IE Insp Repts 30-438/82-14 & 50-439/82-14 Corrective actions all work on isolator cabinets completed & documentation closed KAMMER, D.B. Tennessee Valley Authority B2/07/16 D'REILLY, J.P. Region 2, Office of Director 25p 14162 109, 24X Fiche 50-438, 82/07/26, 8208030594
- --8208030605 Forwards IE Insp Repts 50-438/82-14 & 50-439/82-14 on 820511-14 & notice of violation LONO.F J Division of Project & Resident Programs 82/06/16 PARRIB, H Q Tennessee Valley Authority 2pp 14162-111. 24X Fichs-50-438,82/07/26,8208030594
- --8208030611 Notice of violation from insp on 820511-14 * Division of Project & Resident Programs 82/06/16 1; 14162.113 24% Ficher 50-438, 82/07/26, 8208030594
- --8208030616 IE Insp Repts 50-438/82-14 & 50-437/82-14 on 820511-14 Noncompliance noted failure to document instructions, procedures & drawings & mods to safety-related cabinets communicated verbally RMFF.A B . CONLON.T.E Division of Engineering & Technical Progrems. 82/04/15 5pp 14162 114 R4X Fichs.50-438,82/07/26,8208030574
- 8204210405 IE Info Natice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl URDAN: E.L. Division of Engineering & Guality Assurance. 82/07/28 Consolidated Edison Co. of New York 122pp. 14357, 146 24X Fiche 50-000, 82/07/28, 8204210405.

- 8208030222 Ack receipt of 820719 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/82-16 & 50-439/82-16 WERRELLI.D M Division of Project & Resident Programs 82/07/28 PARTIS.H G Tennesse Valley Authority ip 14158 258 24X Fiche 50-438, 82/07/28, 8208030222
- --8208030225 Responds to NRC 820618 ltr re violations noted in IE lnsp Repts 50-438/82-16 & 50-439/82-16 Corrective actions four loose nut ring retainer bolts retourqued, crimped, inspected & documented MILLS,L N Tennessee Valley Authority 82/07/19 O'REILLY, J P Region 2, Office of Director 3pp 14158 259 24X Fitche 50-438,82/07/28,8208030222
- --8208030231 Forwards IE Insp Repts 50-438/82-16 & 50-439/82-16 on 820501-31 & notice of violation LONO,F J Division of Project & Resident Programs 82/04/18 PARRIS.H G Tennesse Valley Authority 2pp 14158 262 24X Fiche 50-438,82/07/28,8208030222
- --B20B030244 IE Insp Repts 50-438/B2-16 & 50-439/B2-16 on 820501-31 Noncompliance noted two nut ring retainer bolts discovered loose on control rod drive mechanisms CRDM 1209 & 1215 WILCOX. J D. CRLENJAK.R V. QUICK.D R Division of Project & Resident Programs 62/06/18 10pp i4158 265 24X Fiche 50-438.B2/07/28.B208030222
- 8208140144 Responds to IE Builetin 8i-02 Suppl 1, "Failure of Gate Type Valves to Close Against Differential Pressure." Util anticipates submittal of final rept by 821028 upon receipt of revised drawings of field change notices KAMMER, D S Tennessee Valley Authority 82/07/29 D'REILLY, J P Region 2, Dffice of Director ip 44345-123 24% Fiche 50-000, 82/07/29, 8208160144
- 8208160215 Forwards summary of 82072B meeting re insp findings concerning misrepresentation of quality documents & subsequent personnel actions List of attendess encl LEWIS, R C. Division of Project & Resident Programs 82/08/02 PARRIS, N G Tennesses Valley Authority 4pp 14344 144 24X Fiche 50-438, 82/08/02, 8208160215
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Evolist encl
 JORDAN,E L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co. of New York 117pp 14388 201 24%
 Fichs 50-000, 82/08/05.8204210407
- 8208260004 Responds to FOIA request for info re implementation of employee protection provision in Section 210 of Energy Reorganization Act of 1974 Forwards documents listed in app FELTON.J M Division of Rules and Records 82/08/05. MARCOUX.W C. LeBourf. Lambs, Leiby & MacRap 3pp. 14568.050 24X Fiche 30-438.82/08/05.8208260004
- --8208260007 Forwards IE Investigation Repts 50-438/81-26 & 50-439/81-26 on 810831-1001 & motice of violation W/o IE investigation rept O'REILLY, J P Region i, Philadelphia, Office of the Director (81/03/01) 82/01/11. PARRIE, H O Tennessee Valley Authority, 2pp 14568 058 24X Fiche 50-438,82/08/05.8208260004
- --8208260020 Notice of violation from insp on 810831-1001. Noncompliance noted licensee contractor discharged from employment at plant site on 810904 & hanger inspector name written on support insp checklist by unauthor(red person.

 * Region 1, Philadelphia. Office of the Director (81/03/01) 82/01/11 2pp 14568-060. 24% Fiche: 50-438,82/08/05,8208260004
- 8208160204 Ack receipt of 820621 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-438/82-12 VERRELLI.D M Division of Project & Resident Programs 82/08/09. PARRIS, M 9. Tennesses Valley Authority ip 14346.330 24X Fiche-50-438.82/08/09.8208160204.
- --B208160210 Responds to NRC B20521 ltr re violations noted in IE Insp. Repts 50-438/82-12 & 50-439/82-12 Corrective actions sys will be flushed in accordance w/procedures until ANSI acceptance criteria are satisfied HILLS, L.M. Tennesses Valley Authority. B2/06/21 O'REILLY, J.P. Region 2, Office of Director 3pp 14346 331 24X Fichs 50-438,82/08/09,8208160204
- --B208160216 Forwards IE Insp Repts 50-438/82-12 & 50-439/82-12 on 820401-30 & notice of violation LONG, F. J. Division of Project & Resident Programs 82/05/21. PARRIEH H. C. Tennessee Valley Authority 2pp 14346.334. 24X Fichs 50-438,82/08/09,8208160204.

- --8208160224 IE Insp Repts 50-438/82-12 & 50-439/82-12 on 820401-30 Noncompliance noted tools & matis obtained from inside safety-related sys indicating sys not constructed in clean condition HILCOK.J D. QUICK.D R Division of Project & Resident Programs. 82/05/21 12pp 14346 338 24X Fiche 50-438.82/08/09.8208160204
- g Reportable occurrences, LERs & related correspondence
- 8208020158 Interim deficiency rept re B&W erroneous design of RC8 supports & restraints Initially reported on 820618 Welds & shear bare at interface points potentially undersized & overstressed Also reported per Part 21 HILLS.L M Tennessee Valley Authority 82/07/19 0'REILLY, J. P. Region 2, Office of Director 2pp 14144 130 24X Fiche 30-438, 82/07/19, 8208020158
- 8208020380 Second interim deficiency rept re nonconforming matlutilised by HKM Valve Div of AIF Industries in mfg decay heat removal sys valves. Initially reported on 820503 Next rept will be submitted by 820831 HILLS.L M Tennessee Valley Authority, 82/07/19 O'REILLY, J. P. Region 2, Office of Director 2pp 14150 067 24X Fiche 80-438, 82/07/19,8208020380
- 8208020104 Second interim deficiency rept re omissions in auxiliary feedwater pump drawings. Initially reported on 820225 Pump vents, drains & turbine bearing cooling water interconnecting plping designed Drawings will be issued by 820730 KFLGL M Tennessee Valley Authority 82/07/20 O'REILLY, J. P. Region 2. Office of Director 2pp 14142 205 24X Fiche 50-438, 82/07/20, 8208020104
- 8208020226 Final deficiency rept for Sequoyah, second interim rept for Watts Sar & fifth for Bellefonte, Hartsville, Phipps Bend & Yellow Creek re inconsistent establishment of insp program Next rept for Watts Bar & Bellefonte expected 830103 MILLS.L M Tennesses Valley Authority, 82/07/20 O'REILLY, J. P. Repion 2, Office of Director App 14152 344, 24% Fiche. 50-000, 82/07/20, 82080202226.
- 8208020361 Becond revised final deficiency rept re mislocation of flow characteristic indicators Initially reported on 610109, Addl mods will be completed by 830131 for Unit 1 & 830630 for Unit 2

 Hitle: M Tennessee Valley Authority 82/07/21 0'REILLY, J P
 Region 2, Office of Director ip 14150 132 24X
 Fich: 50-438, 82/07/21, 8208020361
- 8208020152 Final deficiency rept re insufficient review of Engineering Change Notice 1268 concerning secondary containment mods Instituty reported on 810710 Audit MBI-13 conducted per Engineering Procedure EN DES-EP 4 02 MILLS.L H. Tennessee Valley Authority, 82/07/22 0'REILLY, J. P. Region 2. Office of Director. 2pp 14145 078, 24X Fiche.50-438, 82/07/22, 8208020152
- 8208020169 Second interim deficiency rept re seismic analysis of auxiliary control bidg Initially reported on 820226 Rept documenting results of revised seismic analysis will be completed by 820801 Next rept expected 820920 MILLS,L.M. Tennessee Valley Authority 82/07/22, 0'REILLY, J. P. Region 2, Office of Director, 2pp 14141 021 24X Fiche 30-438, 82/07/22,8208020169
- 8208030203 Final deficiency rept re welding of atructural steel annulus floor framing. Initially reported on 800415, Only two welds found incomplete Event was isolated incident. Welds will be repaired by 820801
 MILLS, L.M. Tennessee Valley Authority. 82/07/26 O'REILLY, J.P. Region 2. Office of Director 2pp. 14188, 230, 24X
 Fiche. 30-438, 82/07/26, 8208030203.
- 8208030207 Interim deficiency rept re tolorance for tubular steal cable tray hangers Initially reported on 820716 Evaluation of root cause continuing. Next rept expected by 821108.

 MILLS,L M. Tennessee Valley Authority 82/07/26 G'REILLY, J. P. Region 2, Office of Director. 1p 14159:359 24X Fiche: 50-438, 82/07/26, 8208030207
- 8208030238 Second interim deficiency rept re incorrect insp cods on hanger drawings by ITT Orinnell Initially reported on 820301. Weld documentation & hanger drawings for ABME Section III class 2 under review Also reported per Part 21. MILLS.L.M Tennessee Valley Authority 82/07/26 O'REILLY, J.P. Region 2: 04/ice of Director 2pp. 14158-305 24X Fiche: 50-438.82/07/26.8208030238.

- 8208030319 Fourth interim deficiency rept re failure to implement design criteria in design drawings Initially reported on 810401 Evaluation continuing Next rept will be submitted by 830117
 HILLS,L M Tennessee Valley Authority 82/07/27 0'REILLY, J P Region 2, Office of Director 1p 14156 308 24X
 Fiche 50-438, 82/07/27, 8208030319
- 8208030189 Second interim deficiency rept re operational defects in HPI notates & thermal sleeves initially reported on 820429 Nonconformance rept forwarded to 84M investigation to be completed Dec 1982 Nett rept 830301 Reported per Part 21. MILLS.L H Tennessee Valley Authority 82/07/28. O'REILLY, J.P., Region 2. Office of Director 3pp 14160 153 24X Fiche 50-438, 82/07/28, 8208030189
- B20B050183 First interim deficiency rept re embedded piping w/crushable insulation initially reported on B20629 Analysis continuing Next rept will be submitted by B30114
 MILLS.L M Tennessee Valley Authority B2/07/29 O'REILLY, J P Region 2, Office of Director 2pp 14212 067 24X
 Fiche. 50-438, B2/07/29, B20B050183.
- 8208050216 Sixth interim deficiency rept re main feedwater containment isolation valve miscategorization Initially reported on Bi0106. Atwood & Morrill Reismic & stress rept re swing check valves acceptable. Next rept expected by 821206 MILLS. L. H. Tennessee Valley Authority, 82/07/29 0'REILLY, J. P. Region 2, Office of Director 2pp. 14212 133 24X Fiche 50-438, 82/07/29.8208050216
- 8208030474 Final deficiency rept re pipe hanger supports added to auxiliary feedwater pipe trench initially reported on 820924 Responsible organization instructed to route all pertinent info for review to all groups involved MILLS.L.M. Tennessee Valley Authority. 82/07/29 O'REILLY, J.P. Region 2. Dffice of Director 2pp 14216, 348 24X Fiche: 50-438, 82/07/29, 8208030474.
- 8208030332 Sirth interim deficiency rept re steam pressure regulator malfunction Initially reported on 810519 Util in tentative agreement w/8&H findings & details of analysis requested. Next rept expected by 921012 Also reported per Part 21. HILLSIL M Tennessee Valley Authority 82/07/30 0'REILLY, J.P. Ragion 2, Office of Director 2pp. 14219 358 24X Fiche 50-438, 82/07/30, 8208050332
- 8208070084 Second revised final deficiency rept re tapes for heat tracing not meeting chemical specs Initially reported on Bi1224. Corrective action, involving issuance of 8td Spec 85-E17 6 01 k Spec PF-4121, completed on 820715 MILLS, L M Tennessee Valley Authority 82/08/02 O'REILLY, J. P Region 2, Office of Director 1p 14270, 187, 24X Fiche: 50-438, 82/08/02, 8208070084
- 8208070215 Third interim deficiency rept re attachment of pipe supports to A-inch strip plates. Initially reported on 811231. Const personnel performed walkdown of reactor bldgs revealing six unacceptable supports MILLS.L M Tennessee Valley Authority 82/08/02. U'REILLY, J.P. Region 2. Office of Director 2pp 14272.071 24X Fiche: 50-438, 82/08/02, 8208090215.
- 8208070161 Second revised final deficiency rept re Crane Co main steam atmospheric dump valves welded w/o required preheat.

 Initially reported on 810220 Valves will be post-weld heat treated & requalified for impact requirements MILLS, L.M Tennessee Valley Authority 82/08/03 O'REILLY, J P Region 2, Office of Director 2pp. 14271 181, 24X Fiche: 50-439, 82/08/03, 8208070161
- 8208120187 Second revised final deficiency rept re 600-volt & 8-kV & 10-kV power cables not qualified to IEEE 383-1974 flame test Initially reported on 800819. Cables removed from cable trays in safety-related areas & replaced.
 MILLBL M Tennessee Valley Authority 82/08/04. 0'REILLY, J P Tennessee Valley Authority 82/08/04. 0'REILLY, J P Tennessee Valley Authority. 2pp. 14326.015 24X Fiche: 50-438, 82/08/04, 8208120187.
- 8208120066 Final deficiency rept re solid state ac voltage relays Initially reported 810102, Vendor currently modifying internal circuitry of Type 27 (2118 series) undervoltage relays, Also reportable per Part 21.
 MILLS,L M. Tennesses Valley Authority, 82/08/05 0'REILLY, J P Region 2, Office of Director, 2pp. 14327, 187, 24X
 Fiche: 50-438, 82/08/05, 8208120064.
- 8208120153 Final deficiency rept re lack of rebar at main steam & feedwater flued heads Initially reported on 810227. Concrete stiffening walls designed to increase capacity of R-line wall in vicinity of cir main steam pipe anchors.
 HILLS.L M Tennesses Valley Authority 82/08/05. O'REILLY, J P Region 2. Office of Director. 3pp. 14323, 284. 24X Fiche: 50-438, 82/08/05, 8208120153

- 8208120306 Third interim deficiency rept re improper handling & roview of engineering change notices Initially reported on 811215 Review of sample notices continuing Next rept will be transmitted by 830119 MILLS, LM Tennessee Valley Authority 82/08/05 0'REILLY, J P. Region 2, Office of Director 7pp 14325 006 24X Fiche 50-000, 82/08/05, 8208120306
- 8208130224 Final deficiency rept to improper use of circuit breakers to shed non-Class IE loads Initially reported on 820219
 FEAR will be revised to reflect exception to Reg Ouide 1 75
 & results of analysis & configuration by 821201
 MILLS.L M Tennesses Valley Authority 82/08/09 O'REILLY, J P
 Region 2. Office of Director 170p 14333 125 24X
 Fiche 50-438, 82/08/09, 8208130224
- 8208160307 Becond interim deficiency rept re defects in reactor protection sys & EBF actuation sys modules supplied by Bailey Meter Co Initially reported on 820414 Util awaiting B&W response Next rept will be submitted by 821029 HILB, L M Tennesses Vailey Authority 82/08/10 O'REILLY, J P Region 2, Office of Director 2pp 14345 301 24X Fiche 50-438, 82/08/10, 8208160307
- 8208160319 Bixth interim deficiency rept re B&W nonconservative analysis of neutron flux in reactor protection sys Initially reported on B01105 Analytical software fir will be used to correct problem Next rept due by 821117 HILLS.L M Tennessee Valley Authority. 82/08/10 0'REILLY, J P Region 2. Dffice of Director 2pp 14348 053 24X Fiche 50-436, 82/08/10,8208160313
- 8208160368 Revised final deficiency rept re casting defects in four WKM valves Initially reported on 800226 Valves 2DM-HV3A & 2DM-HV3B returned to WKM for repairs Orinding of Valves 1DM-HV3B completed. Also reportable per Part 21.

 MILLS.L.M. Tennessee Valley Authority 82/08/11 0'REILLY, J.P. Region 2. Office of Director 2pp 14348 350 24X

 Fiche 50-438, 82/08/11, 8208160368.
- 8208160490 Beventh interim deficiency rept re corrosion of carbon steal piping Initially reported on 801230 Statistical analysis of meteorological & river temp data demonstrated validity of lowering max mergency raw cooling water temp MILLB, L.M. Tennesses Valley Authority 82/08/11 0'REILLY, J. P. Region 2. Office of Director 2pp 14348 316 24X Fiche 50-438, 82/08/11, 8208160490
- 8208200099 Revised final deficiency rept re Atwood & Morrill valve surface discontinuity initiatly reported on 801212 Vendor ground out discontinuity & performed liquid penetrant test Also reportable per Part 21.

 MILLS.L.M Tennessee Valley Authority 82/08/12 0'REILLY, J P Region 2. Office of Director 2pp 14393 261. 24X
 Fiche 50-439, 82/08/12,8208200099
- B20B200167 Fourth interim deficiency rept re steinless steel pipe in area where lugs mfg by BLNP Const are attached, which may exhibit burnthrough, oxidation or excessive sensitization initially reported on 811224 Next rept by 821119.

 MILLS.L.M Tennessee Valley Authority 82/08/12 0'REILLY, J.P. Region 2. Office of Director 2pp 14500 119. 24X

 Fiche. 50-438, 82/08/12, 8208200167.
- 8208200209 Third interim deficiency rept re temp of nitrogen supply. Initially reported on 820114 Heaters added for nitrogen to meet min temp requirements. Specs issued & installation drawings changed. Next rept expected by 830331 HILB.L.M Tennessee Valley Authority 82/09/12 O'REILLY, J P. Region 2, Office of Director. 2pp. 14500 155 24X Fiche: 50-438. 82/08/12, 8208200209
- 8208270326 Final deficiency rept re dimensionally nonconforming anchorage mati. Initially reported on 810505 Inryco determined bushings fully engaged w/coupiers will not fail No corrective action required. Also reportable per Part 21 HILLS,L H Tennesses Valley Authority. 82/08/19 0'REILLY, J P Region 2, Office of Director 3pp 14565,009 24% Fiche: 50-438,82/08/13,82/08/20326
- 8208270107 Third interim deficiency rept re environ qualification of safety-related electrical components Initially reported on Bio21. Util establishing qualification program w/8&H & completing corrective actions. Next rept expected by B30805 MILLS,L.M. Tennessee Valley Authority, B2/08/16 0'REILLY, J P Region 2. Office of Director 12pp, 14563 326, 24X Fiche 50-438, 82/08/16, 8208270107.
- 8208270099 Second interim deficiency rept re valves not qualified to design requirements initially reported on 820412 Pressure control valves qualified as active & air supply tank should be qualified by 820823 Next rept expected by 821814 HILLS.L. M. Tennessee Valley Authority 82/08/18, O'REILLY, J.P. Region 2. Office of Director. 2pp. 14563 199. 24X Fiche. 50-438, 82/08/18, 82/08/2099

- 8208270245 Final deficiency rept re overpressure protection in decay heat removal sys Initially reported on 811127 Piping design qualified using ASME Section III requirements & calculations Personnel instructed to review code compliance MELLS.L M Tennessee Valley Authority 82/08/19 D'REILLY, J P Region 2. Office of Director 2pp 14963 113 24X Fiche 50-438,82/08/19,8208270245
- 8208270251 Supplemental deficiency rept re intervening hangers restricting access to welding of structural steel annulus floor framing. Initially reported on 800415 Removal of hangers requires extension of completion data to 820901 MILLB.L H Tennessee Valley Authority 82/08/19 0'REILLY, J P Region 2, Office of Director ip 14564 149 24X Fichs 50-438, 82/08/19, 8208270251
- 8208270361 First interim deficiency rept re deficient 4team generator support bolts Initially reported on 820723 Loosened sample bolts sent to Singleton Lebs for testing & evaluation Next rept will be sent by 821221 MILLS,L H Tennesses Valley Authority 82/08/19 O'REILLY,J P Region 2. Office of Director 1p 14565 038 24X Fiths: 50-438,82/08/19.8208270361
- 8208300202 Final deficiency rept re failure to properly review auxiliary feedwater sys design criteria diagram Initially reported on 820414.0ngoing review program Initiated re applicable engineering procedures MILLS,L M. Tennessee Valley Authority 82/08/23 O'REILLY, J P Region 2. Office of Director 2pp 14678 235 24X Fiche-50-438,82/08/23,8208300202
- 8208300211 Sixth interim deficiency rept re procurement control audits Initially reported on 810316 TVA quality engineering branch response to audit deficiencies undergoing review Next rept due by 821007.
 MILLS.L M. Tennessee Valley Authority 82/08/23 O'REILLY, J P Region 2, Office of Director 1p 14679 196. 24X Fiche 50-000, 82/08/23, 8208300211
- 8208300324 First interim deficiency rept re undersized fillet welds made before mid-1980 Initially reported on 820722 Insp results forwarded for engineering evaluation & disposition Next rept will be provided by 830111 HILLS.L M Tennesses Valley Authority 82/08/23 O'REILLY.J P Region 2. Defice of Director 2pp 14579 078 24X Fiche 50-438,82/08/23.8208300324
- 8208300334 Fifth interim deficiency rept re unacceptable pipe break interactions Initially reported on 810127 Engineering change notices issued re chilled & demineralized water & fire protection piping Next rept by 830317 MILLS, L M Tennesses Valley Authority 82/08/23 O'REILLY, J P Region 2, Office of Director 2pp. 14599 099 24X Fiche 50-439, 82/08/23, 8208300334
- 8208300226 Fourth interim deficiency rept re improper torque of Borg-Warner bonnet studs on decay hast removal valves Initially reported on 811222 Item remains open Next rept will be submitted by 821104 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 82/08/24. 0'REILLY, J P Region 2, Office of Director 2pp 14679 056 24X Fiche. 50-438, 82/08/24, 8208300226
- 8208300269 First interim deficiency rept re unapproved work releases allowing const to cut reinforcing steel to install anchor bolts for pipe supports in auxiliary feedwater pipe trench. Initially reported on 820727 Next rept by 821019 MILLS. M. Tennessee Valley Authority 82/08/24 O'REILLY, J.P. Region 2. Office of Director 2pp 14473 001 24X Fiche 80-438,82/08/24,8208300269
- 8208300086 First interim deficiency rept re undervoltage protection during accident Initially reported on 820727 Present design does not comply w/requirements Revision underway. Next rept expected by 821119
 MILLB.L M Tennessee Valley Authority 82/08/25 O'REILLY, J P. Region 2, Office of Director 2pp 14598 248 24X
 Fiche 50-438, 82/08/25, 8208300086
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licenses of operating plants, applicants for OL % holders of CP re Commission approved charter for CRGR 8vc list encl.

 DIRCKB.W.J. Office of the Executive Director for Operations 82/07/02 Compolidated Edison Co. of New York 93pp 14194 001 24X Fiche. 50~000, 82/07/02, 8207080064

- 8208950051 Forwards agenda for 820810-13 control room in-progress audit SCHMENCER, A Licensing Branch 2 82/07/30 DAVIDSON, D.R. Cleveland Electric Illuminating Co 3pp 14244 042 24X Fiche 50-440, 82/07/30, 8208050051
- 8208240492 Requests input re addition of personnel w/BHR operating ergerience & evaluation of safe shutdown margins per ACRS committee rept on facilities SCHWENGER. A Licensing Branch 2 82/07/30 DAVIDSON, D R Claveland Electric Illuminating Co 2pp 14544 146 24X Fichs 50-440, 82/07/30, 8208240472
- B208120349 Responds to ACRS B20713 ltr providing comments & recommendations following review of applications for OL Recommendations will be addressed in suppl to SER GOODHIN,E F Office of Nuclear Reactor Regulation, Director 82/08/03 FRALEY,R ACRS Advisory Committee on Reactor Safeguards 3pp 14340 070 24X Fiche 50-440,82/08/03,8208120349
- --8205270049 Bummarizes ACRS 267th meeting on 820708-10 re QL application Util urgently needs add1 personnel w/BUR experience within operating mot If due consideration given to AGRS recommendations, plant can be operated safely SHEHMON.P ACRS Advisory Committee on Reactor Bafeguards 82/07/13 PALLADINO, N J Commissioners 3pp 14340 073 24X Fiche 50-440,82/08/03,8208120349
- 8208100117 Responds to J Humphrey concerns re Mark III containment design Program being established to address each of 23 major concerns raised in Humphrey 620508 ltr to MI Power & Light DAVIDSON, D. R Cleveland Electric Illuminating Co 82/08/05 BCKMENGER, A Licensing Branch 2 2pp 14278 186 24X Fich; 50-440, 82/08/05, 8208100117
- 8208130150 Revision to application for OL, requesting 40-yr QL from date of issuance DAVIDSON,D R. Gleveland Electric Illuminating Go 82/08/05 OENIGN, H.R. Office of Nuclear Reactor Regulation, Director, Spp. 14337 142 24X Fiche 50-440,82/08/05.8208130150
- B20B070174 Ceneric Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list enci EIBENHUT.D O Division of Licensing 82/08/07 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000.82/08/07, 8208070174
- 820825083 Notification of 820813 meeting w/util in Bethesda, MD to discuss safety relief valve hydrodynamic loads Agenda encl BTEFANO, J Licensing Branch 2 82/08/09 GCHMENCER, A Licensing Branch 2 4pp 14559 256 24% Fichs 50-440 82/08/09:8208250083
- 8208190246 Discusses changes to ATMS mitigation design features, per 820720 meeting Safety grade of recirculation pump trip initiation circuit will be upgraded Design details will be submitted as FBAR amend by Jan 1983 DAVIBBON.D.R. Cleveland Electric Illuminating Co 82/08/13 BCHMENCER.A Licensing Branch 2 2pp 14388 188, 24% Fiche 50-440, 82/08/13,8208170246
- 8208240430 Forwards "Containment Annulus Concrete Design.Const & Testing for Perry Nuclear Power Flant "Review or meeting to discuss NRC findings requested by 820901

 pavinson.b.r. Commonwealth Edison Co 82/08/16 BCHWENCER, A Licensing Branch 2 2pp 14526 250 24X Fichs 50-440,82/08/16,8208240430.
- --B208240436 "Containment Annulus Concrete Design:Const & Testing for Perry Nuclear Power Plant." + Gleveland Electric Illuminating Co 82/08/16 49pp 14526 252 24X Fiche 50-440.82/08/16.8208240430
- 8208240323 Buppls 820422 response to 820329 request for info re hydrodynamic loads on control rod drive sys. Bchedule for resolution of overstress conditions extended to B30107 due to contractor expanded scope of work DAVIDEON, D.R. Cleveland Electric Illuminating Co 82/08/18 BCHRACER, A. Licensing Branch 2 2pp 14524 297 24X Fiche 30-440, 82/08/18,8208240323.
- 8208260151 Forwards proprietary, "OE Environ Qualification Program"
 Rept withheld (ref 10CFR2 770) Comments requested by 821015
 Affidavit requesting withholding encl
 DAVIDSON,D R Cleveland Electric Illuminating Co. 82/09/18.
 8CHMENCER,A Licensing Branch 2 4pp 14556:292 24X
 Fichs 50-440, 82/08/18, 8208260151

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8208040003 Forwards add1 info re SER open items on manual initiation & termination of ESF & ADS sys testability.

 DAVIDSON, D R Cleveland Electric Illuminating Co 92/07/20. SCHUENGER, A Licensing Branch 2 27pp 14193 191 24X Fiche 50-440, 82/07/20. 8208040003
- 8208090011 Forwards final draft of supplemental SER Concurrences requested by 820802 Changes L/or additions re resolved open items should be furnished to project manager H/o encl NDVAK.T Assistant Director for Operating Reactors 82/07/28 HOUSTON,R W Assistant Director for Radiation Protection JOINSTON,W V Assistant Director for Materials & Qualifications Engineering KNICKY,J P Assistant Director for Taberials & Gualifications Structures Engineering Gpp 14283 337 24X Fiche 50-440,82/07/28,8208090011
- 8208070306 Requests add1 info re unresolved fire protection issues contained in SER 8CHHENCER.A Licensing Branch 2 82/07/28 DAVIDSON.D R Cleveland Electric Illuminating Co 3pp 14307 108 24X Fiche 50-440.82/07/28.820809030
- 8208120056 Responds to BER Open Item 9 & recent meetings \(\omega/\)Containment

 Bys Branch re pool dynamic loads Commits to meet load

 definitions in App 3B of GESSAR II 23B Nuclear Island

 DAVIDSON,D R Cleveland Elsectric Illuminating Co 82/08/05

 8CHMENCER,A Licensing Branch 2 3pp 14324 008 24X

 Fiche 50-440,82/08/03,8208120056
- ---B204130421 Forwards NRC draft acceptance criteria for LOCA-related Mark III containment pool dynamic loads developed by Containment Bys Branch & BML Recommends that criteria be sent to applicants to address how criteria are met BPEIB.T Assistant Director for Reactor Safety 82/03/08 TEDESCOR Assistant Director for Licensing 9pp 14324.011. 24X Fiche 50-000.82/08/05.8208120054
- 8208240276 Forwards add1 info re feedwater check valves functioning following line break outside containment in response to Rechenical Enjoyeering Branch draft SER Question 3 9-42 DAVIDSON D. R. Cleveland Electric Illuminating Co. 82/08/16 SCH-KENCER, A. Licensing Branch 2 lipp 14528 082 24X Fiche 30-440-82/08/16-8208240276
- 8208270666 Forwards SER Suppl 1 (NUREO-0887) H/o encl 8CHMENGER: A Licensing Branch 2 82/08/18 DAVIDSON, D R Cleveland Electric Illuminating Co 2pp 14683:174 24X Fiche 30-440, 82/08/18, 8208270666
- 8208240299 Forwards response to NRC 820615 ltr & BER Confirmatory Itam 15 re preservice insp program DAVIDBON.D R Cleveland Electric Illuminating Co 82/08/20 BCHHENCER.A Licensing Branch 2 4pp 14528 078 24X Fiche.50-440,82/08/20,8208240299
- 8208310416 Provides info to amend 820608 ltr re SER Confirmatory Item 34 on undervoltage protection Encl sketches clarify logic for typical bus undervoltage protection scheme DAVIDBON.D R Cleveland Electric Illuminating Co 82/08/26 86KHENCER,A Licensing Branch 2 4pp 14693 284 24X Fichs 30-440.82/08/26.8208310416
- 8208230422 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PERRY NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Not 50-440 And 50-441 (Cleveland Electric Illuminating Company) * Office of Nuclear Reactor Regulation, Director NUREQ-0887 801 82/08/31 43pp Available at NTIS 64 75 14518 224 24X Fiche 50-440, 82/08/31, 8208230422
- F Security, medical, amergency & fire protection plans
- 8208070306 Requests add1 info re unresolved fire protection issues contained in BER SCHNENCER, A. Licensing Branch 2 82/07/28 DAVIDSON, D.R. Clevelend Electric Illuminating Co. 3pp 14307 108 24X Fiche 50-440.82/07/28.8208090306
- 9 Adjudicatory correspondence
- 8207080079 FOIA request for Branch Technical Positions APSCB 3-1 & MEB 3-1, ACRS transcripts & tests in Japan re BWR ECCB core spray distributions
 HIATT.B L Ohio Citizens for Responsible Energy. 82/07/04.
 FELTON.J.M Division of Rules and Records ip. 14676:086 24X Fiche. 50-440, 82/07/06, 8207050079.

- 8207140215 Motion for leave to submit addition tention relow level radiation health effects & economic costs based on DE9 (NUREO-0884) & DC Court of Appeals 820427 decision Proof of Svc enci HILT, D. D. Bunflower Alliance HILT, D. D. Hilt, D.D. 82/07/13 Atomic Safety and Licensing Board Panel 3pp 13870 001, 24X Fiche 50-440, 82/07/13, 8207160215
- 8208020208 Answer opposing Sunflower Alliance 820713 motion to submit addl contention Contention untimely & w/o basis DES does not justify filing Certificate of Svc encl. WILLMORE, R. L. Cleveland Electric Illuminating Co. HILLMORE, R. L. Shaw, Pittman, Potts & Trowbridge. 82/07/28 Atomic Safety and Licensing Board Panel 46pp 14141 136 24x Fiche 50-440,82/07/28, 8208020208.
- 8208030372 Emphasizes that Issue i includes OH Citizens for Responsible Energy potassium Iodide issue. Related correspondence HIATT. S L Ohio Citizens for Responsible Energy 82/07/29 BILBERG. J Shaw, Pittman. Potts & Trombridge 2pp 14154 005 24X Fiche 50-440, 82/07/29, 8208030372
- 8208030363 Responds to applicant 820719 & 28 itrs. Intervenors have right to file reply briefs per 810804 order. OH Citizens for Responsible Energy 820706 notice did not imply that criteria for late-filed contentions should be suspended HIATIS L. Did Citizens for Responsible Energy 82/07/31, 8LOCH.P.B., KLINE, J.R., SHON, F.J. Atomic Safety and Licensing Board Panel. 2pp 14237 303 24X Fiche 50-440, 82/07/31, 8208050363,
- 8208040210 Partial answer to second set of interrogetories. WILCOVE, M N , WRIGHT, N A Hearing Branch 2, 82/08/02 Bunflower Alliance. 39pp 14188 254 24X Fiche.50-440, 82/08/02, 8208040210.
- B208040271 Response opposing Sunflower Alliance et al 820713 motion for leave to submit addl contentions Contentions fail to specify basis & fail to specify basis & fail to meet state for late filling Notice of appearance & Certificate of Syc enci.
 MRIOHT.N A. Hearing Branch 2 82/08/02 Atomic Sefety and Licensing Board Panel. 9pp 14183 071 24X Fiche 50-440,82/08/02,8208040271.
- B20B050396 Reply supporting Sunflower Alliance B20721 motion to expand GA contention, Issue should include entire const GA program Any & all violations, regardlass of occurrence dats are relevant Certificate of Svc and HATT.B. L. Ohio Citizens for Responsible Energy, B2/0B/02. Atomic Safety and Licensing Board Panel Spp 14209, 208 24X Fiche: 50-440, 82/08/02, 8208050394
- 208050097 Forwards documents referred to in NRC 820802 response to Interrugatories 66 & 68
 WILCOVE, M N. Hearing Branch 2 82/08/04 WILT, D D Bunflower Alliance. WILT, D D, Wilt, D D 23pp. 14238:150 24X
 Fiche. 50-440. 82/08/04. 8208060097.
- 8208090179 Reply brief supporting ABLB order compaling discovery. Info sought appears reasonably calculated to lead to discovery of admissible evidence Proof of Svc encl.Related correspondence.

 HILT.D.D. Sunflower Alliance HILT.D.D Hilt. D.D 82/08/04 Atomic Bafety and Licensing Spard Panel 2pp 14272;057 24X Fiche-50-440,82/08/04.8208090179.
- 8208090183 Motion for reconsideration of ASLB 820720 decision, dismissing Issue 10 re psychological stress from proceeding, or alternatively for certification to Commission of ALSB jurisdiction over issue. Froof of Bvc enc! HILT, D. D. Sunflower Alliance. WILT, D.D. Hilt, D.D. 82/08/04, Atomic Bafety and Licensing Board Pens! 7pp 14272:049 24X Fichs. 50-440, 82/08/04, 8208090183
- 8208090250 Requests prepared documents including draft emergency plan & std operating procedures as interim discavery measure to assist in assessment of state emergency planning, Related correspondence
 HILT, D. D. Wilt, D. D. WILT, D. D. Bunflower Alliance 82/08/04
 EZZONE, D. T. Lake County, OH 1p. 14271:039 24X
 Fiche: 50-440, 82/08/04/8208090250.
- 8208070005 Advises that NRC will file no response to Bunflower Alliance 820621 motion to compel discovery from applicant, LEMIS.S.H. Hearing Brench 2. 82/08/05, BLOCH-P B, KLINE, J R, BHON, F. J. Atomic 84 fety and Licensing Board Fanel. ip 14270:060, 24X Fiche: 50-440, 82/08/05, 8208090005
- 8208070144 Responds to 820727 ltr re applicant interpretation of Issue 1, ASLB admitted OH Citizens for Responsible Energy potessium iodide contention. Applicants have not changed position on subj contention Byc list encl.

 81LBERG, J.E. Bhaw, Pittman, Potts & Trombridge, SILBERG, J.E. Claveland Electric Illuminating Co. 82/08/05, HIATT, B.L. Ohio Citizens for Responsible Energy 2pp. 14271:315, 24X Fiche: 50-440, 82/08/05, 8208090144

- 8208090146 Confirms 820805 telcon where ASLB informed that Bunflower Alliance agreed to extension until 820810 for applicants to answer Alliance 820721 request for admissions re Issue 4 Svc list encl SILBERO, JE Shaw, Pittman, Potts & Troubridge SILBERO, JE Cleveland Electric Illuminating Co 82/08/05 BLOCH, PB, KLINE, JR, SRUN, FJ Atomic Bafety and Licensing Board Panel 2p, 14271 319. 24% Fiche 50-440, 82/08/05, 8208090146
- 8208090243 Answer opposing Sunflower Alliance, Inc 820721 second motion to expand GA contention. Issue 3 to cover any violation of GA/GC std regardless of date of occurrence No serious programmatic deficiencies identified H/Gertificate of Svc WILLMORE, R L Cleveland Electric Illuminating Co WILLMORE, R L Shaw. Fittman, Potts & Trowbridge 82/08/05 Atomic Safety and Licensing Board Panel 13pp 14271 061 24X Fiche 30-440,82/08/05,8208090243
- 8208110158 Motion to strike Bunflower Alliance 820804 reply brief in support of motion to compel discovery Brief filed in direct contravention of NRC rules of practice Certificate of Bvc encl HILLMORE, R.L. Cleveland Electric Illuminating Co. HILLMORE, R.L. Shaw. Pittman, Potts & Trowbridge 82/08/09, Atomic Safety end Licensing Board Panel 4pp 14314 238 24X Fiche 50-440.82/08/09, 8208110158
- 8208120145 Motion for leave to file Contention 20 re adequacy of consideration of economic consequences of accidents DES (NUMEO-0884) deficient due to failure to include assessment of disruption caused by accident Certificate of Svc encl HIATT, S L Ohio Citizens for Responsible Energy 82/08/09 Atomic Safety and Licensing Board Panel. 23pp 14319 208 24X Fiche 50-440,82/08/09,9208120145
- 8208120123 Answer to Sunflower Alliance. Inc B20721 request for admissions re Issue 4 on ECCS evaluation model. Certificate of Svc encl.

 HILLMORE, R L Cleveland Electric Illuminating Ca HILLMORE, R L Shaur Pittman, Potts & Troubridge 82/08/10 Sunflower Alliance 14pp. 14327-051 24X Fiche 80-440.82/08/10, 8208120123.
- 8208130007 Response opposing Bunflower Alliance, Inc 82072i second motion to expand scope of GA Contention. Issue 3 Alliance failed to extablish bases to provide adequate justification for contention Certificate of 8vc enci.

 HRIOHT, N A Hearing Branch 2, 82/08/1i Atomic Safety and Licensing Board Panel 8pp 14333 190 24X Fiche 50-440.82/08/11, 8208130007
- 8208130165 Answer to second set of interrogatories Certificate of Byc encl Related correspondence WILLMORE, R. L. Cleveland Electric Illuminating Co WILLMORE, R. L. Shaw, Pittman, Potts & Troubridge 82/08/11 Sunflower Alliance, 27pp 14337,038, 24% Fiche. 50-440, 82/08/11, 8208130165,
- 820B170197 Reply supporting Sunflower Alliance 820B04 motion for reconsideration of ABLB 820719 order dismissing Issue 10, or for cartification. Commission B20716 statement of policy repsychological stress illegal W/Certificate of Svc HIATT.B L Ohio Citizens for Responsible Energy 82/08/12 Atomic Safety and Licensing Board Fanel 7pp 14366: 268 24X Fiche: 50-440, 82/08/12, 8208170197
- 8208170271 Answer opposing Sunflower Alliance, Inc et al 820804 motion for reconsideration or, in alternative, certification to Commission of questions re 820719 order dismissing Issue 10 on psychological stress W/Certificate of Svc. WILLMORE, R. L. Cleveland Electric Illuminating Co. WILLMORE, R. L. Shaw, Pittmen, Potts & Trowbridge 82/08/13 Atomic Bafety and Licensing Board Panel 8pp 14367-262 24X Fiche 50-440,82/08/13,8208170271.
- 820B180135 Responses to Sunflower Alliance request for admissions concerning Issue 4 on ECCB evacuation model & Unresolved Safety Issue 4-16 re steam effects on BMR core spray distribution Affidavits & Certificate of Svc encl. WRIGHT-N A. Hearing Branch 2. 82/08/16 Sunflower Alliance. 16pp 14377.053. 24X Fiche.50-440.82/08/16.8208180135.
- 8208180137 Informs of NRC progress on discovery activities during previous 2 months, per ABLB 810909 memorandum & order. Responses submitted to listed documents FEB will be issued in latter half of Aug. VOULER.B H Hearing Branch 2 82/08/16 BLOCH, P.B. 8HON, F.J., KLINE, J.R. Atomic Bafety and Licensing Board Panel. 2pp. 14378.287 24% Fiche: 50-440, 82/08/16, 8208180137.
- 9208200186 Order ruling on Bunflower Alliance 820621 motion to compel.
 Info re emergency response agreements volunteers onsite
 initiating conditions, administrative means, meteorological
 monitoring & communications must be provided,
 BLOCH.P.S. Atomic Bafety and Licensing Board Panel, 82/08/18,
 Cleveland Electric Illuminating Co. 8pp, 14393 333 24X
 Fiche: 50-440, 82/08/18, 8208200186,

- 8208270451 Informs that applicants agreed to add 5 optional extra days to period in which motion to compel discovery may be filed, per ABLB 820713 ruling Motion to compel discovery will be filed by 820907 Related correspondence MIATT.B L Ohio Citizens for Responsible Energy 82/08/18 BLCCH.P B , KLINE.J R , SHON.F J Atomic Safety and Licensing Board Panel 2pp 14566 120 24X Fiche 50-440,82/08/18,8208270451
- 0208270463 Motion for leave to file Contentions 21-26 re turbine missiles, new Mark III containment concerns, seismic evaluation of BMR core thermal hydroulics & in-core thermocouples, W/Certificate of Svc MIAYT.8 L Ohio Citizens for Responsible Energy 82/08/19 Atomic Safety and Licensing Board Panel 21pp 14565 273 24% Ficha 50-440, 82/08/18, 8208270463
- 8208270527 Sixth discovery progress rept per ABLB 810907 Memorandum & Order LBP-81-35 Certificate of 8vc encl Related correspondence HIATIS L Ohio Citizens for Responsible Energy 82/08/18 3pp 14564-128 24X Fiche 50-440,82/08/18,8208270529
- 8208240191 Sixth discovery progress rapt Certificate of Bvc and MILLMORE,R.L. Cleveland Electric Illuminating Co WILLMORE,R.L. Shaw, Pittman, Potts & Troubridge 82/08/20 3pp 14519 330. 24x Fiche 30-440.82/08/20,8208240191
- 8208240235 Answer to second set of interrogetories Certificate of Byc encl HILLMORE.R L Cleveland Electric Illuminating Co HILLMORE.R.L Shaw Pittman, Potts & Trowbridge 82/08/20 Sunflower Alliance, 28pp 14520 021 24X Fiche 50-440,82/08/20,8208240235
- 8208260051 Response opposing Sunflower Alliance, Inc 820804 motion for reconsideration of ASLB 820719 memorandum & order dismissing Issue 10 re psychological stress In alternative, motion should be certified to Commission Certificate of Svc encl, LEMIS H , HRIGHT, N A Hearing Branch 2 82/08/24, Atomic Safety and Licensing Board Panel Spp 14555, 226, 24x Fichs 50-440, 82/08/24, 8208260051
- 8208270506 Add1 answer to first round discovery requests, Certificate of Svc encl Related correspondence
 BILBERG, J. E. Cleveland Electric Illuminating Co. BILBERG, J. E.,
 Bhaw, Pittman, Potts & Troubridge 82/08/24 Sunflower Alliance,
 4pp 14563 357 24X Fiche 50-440, 82/08/24, 8208270506
- B208270370 Forwards ALAB-687 NRC position in instant proceeding that contentions should not be conditionally admitted subj to discovery or development of future papers coincides w/ASLAB decision.

 BARTH:C A Hearing Branch 1, 82/08/26, KELLEY, J. L., CARPENIER, J. H., BRIGHT:O D Atomic Sefety and Licensing Board Panel 19 14564 260 24X Fichs 50-440:82/08/26.8208270370
- 8208300287 Supplemental answer to second set of interrogatories Certificats of Svc encl HILLMORE.R L. Gleveland Electric Illuminating Co WILLMORE.R L. Shaw, Pittnan, Potts & Trowbridge 82/08/26 Ohio Citizens for Responsible Energy 5pp 14679:182. 24X Fiche 30-440.82/08/26, 8208300287
- H Quneral correspondence
- 8208090247 Advises that author will continue to represent clients to best of ability, in response to Willmore 820728 ltr. Related correspondence WILT.D D. Wilt, D.D. WILT.D.D. Bunflower Alliance 82/08/04 BLOCH.P B Atomic Bafety and Licensing Board Panel. ip 14271-047. 24X Fiche: 50-440, 82/08/04.8208090247
- 8208090254 Notice of change of address for DD Wilt WILT-D D Sunflower Alliance, WILT-D.D. Wilt, D D 82/08/04 1p. 14272 019. 24X Fiche 50-440,82/08/04,8208090254.
- M Utility Final Bafety Analysis Report (FBAR) & amends
- 8208260124 Forwards Amend 8 to FBAR. Certificate of 8vc encl. DAVIDBON.D.R. Cleveland Electric Illuminating Co. 82/08/25. DENION.H R. Office of Nuclear Reactor Regulation, Director. 3pp. 14556-333 24X Fiche: 50-440, 82/08/25, 8208260124.
- --8208260129 Amend 8 to FBAR

 * Cleveland Electric Illuminating Co. 82/08/25 800pp.

 [4556:336 24X Fiche:50-440,82/08/25,8208260124

M Antitrust correspondence

- 8208230018 Requests responses to questions re antitrust review of OL application
 TOALBTON.A Antitrust & Economic analysis Branch (Utility Finance)
 82/08/09 DAGGETT, E L Bryan, GH 2pp 14518 001 24X
 Fiche 80-000.82/08/09.82
- 8208230477 Requests responses to questions re antitrust review of DL application
 TOALBTON,A Antitrust & Economic analysis Branch (Utility Finance),
 82/08/09 MIKESSELL,B L Cleveland, CH 2pp 14528,237 24X
 Fiche 50-000,82/08/09,8208230477
- B208240081 Requests responses to questions re antitrust review of DL application
 TOALSTON:A Antitrust & Economic analysis Branch (Utility Finance)
 82/08/09 OREEN.T. Painesville, DH 2gp 14929 313 24X
 Fiche 50-000, 82/08/09, 8208240081.
- G Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list ancl. JORDAN: EL. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co of New York 87pp 14356-274, 24X Fiche.50-000.82/07/16.8204210393
- 8204210395 IE Info Notice 81-26.Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Byc list encl.

 JURDAN.E.L. Division of Engineering & Quality Assurance 82/07/19, Michigan. Univ. of. 112pp 14358-001, 24X Fiche: 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure." Syc list and I JORDANIE L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co. of New York 112pp 14381.001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Herafluoride Overpacks" Syc list encl. COBB.L I. Division of Fuel Facilities, Haterials & Bafeguard # 82/07/20 Consolidated Edison Co. of New York. 71pp. 14357:276, 24X Fiche 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl.

 JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York 112pp. 14194:321, 24x
 Fiche. 50-000, 82/07/22, 8204210398
- 8208100237 Forwards IE Insp Rept 50-440/82-07 on 820706-09 No noncompliance noted MILLER, JR Region 3. Office of Director. 82/07/22. DAVIDSON, DR Cleveland Electric Illuminating Co 2pp. 14294-319. 24X Fiche: 50-440,82/07/22,8208100237.
- --8208i00242 IE Insp Rept 50-440/82-D7 on 820706-09 No noncompliance noted, Major areas inspected radiation protection program, including organization, qualification, procedures, training & facilities, MILLER, D E , OREGER, R Region 3, Office of Director, 82/07/22 Spp 14294-321, 24% Fiche-50-440, 82/07/22, 8208100237.
- 8204210401 IE Info Notice 82-28. "Hudrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN:E L. Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co. of New York 122pp. 14380*115 24% Fiche: 50-000, 82/07/23, 8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRB) Quide Tube Bupport Pin Failures at Westinghouse PNRs." Svc list encl. JCRDAN, E. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co of New York. 127pp. 14194:120, 24X Fiche: 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants." Byc list encl URDAN.E.L. Division of Engineering & Quality Assurance. 82/07/26. Consolidated Edition Co. of New York. 12ipp. 14357:013. 24X Fiche: 50-000.82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool," Svc list encl.
 JORDAN.E.L Division of Engineering & Quality Assurance, 82/07/28, Consolidated Edison Co. of New York, 122pp. 14357

- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " Svc list encl.
 JORDANIE L Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388.201 24X
 Fiche 50-000,82/08/05,8204210407
- 8208310003 Responds to appeal re denial of FOIA request for documents concerning IE Insp Rept 50-358/81-13 Appeal partially granted & partially denied Forwards CH Neil 810914 memo. Info partially withheld (ref FOIA Exemption 7). DIRCKS.N J Office of the Executive Director for Operations 82/08/12 DEVINS.T Government Accountability Project ip 14697 220 24K Fiche 50-000,82/08/12,8208310003
- --B20B310005 Forwards RT Carlson B10724 mamma re allegations reported to Region 1 by anonymous complainant concerning facilities. Vendor Insp Branch will conduct insp of Nuclear Engineering Bycs.

 WEIL.C.H. Region 3, Chicago, Office of the Director (81/03/01) B1/09/14 Region 3, Chicago, Office of the Director (81/03/01) 3pp 14697 221 24X Fiche 50-000, 82/08/12,8208310003.
- --B20B310009 Forwards RE Shepherd memos re allegations concerning facility inspidesign controls & accumulation of test data Confidential info deleted CARLSON, RT Enforcement & Investigation Staff 81/07/24. STREETER, J Enforcement & Investigation Staff. 18pp 14697-224 24X Fiche: 50-000, 82/08/12.8208310003
- 8208240277 Forwards response to NRC 820615 ltr & SER Confirmatory Item 15 re preservice insp program DAVIDBON.D R. Cleveland Electric Illuminating Co 82/08/20 8CHMROER.A Licensing Branch 2. 4pp. 14528 078 24X Fichs 50-440

B. Reportable occurrences. LERs & related correspondence

- 8208130270 Final deficiency rept re potential defects in Pratt Valves & Bettis actuators. Initially reported on 820611 Bite Nonconformance Rept OPGC 258 initiated to tract deficiency Bettis contacted re parts replacement. Maxt rept by 821129 DAVIDSON.D. R. Cleveland Electric Illuminating Co 82/08/05 KEPPLER.J O Region 3, Office of Director 2pp 14333 053 24X Fiche 50-440,82/08/05,8208130270
- Hearing transcripts on non-antitrust matters
- 08170147 Transcript of 820813 telephone conference re OL issuance in Assington, DC Pp 658-759.

 Atomic Safety and Licensing Board Panel. 82/08/13 103pp. 14366:023 24% Fiche: 50-440, 82/08/13, 8208170147
- MOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- · Application/construction stage documents & correspondence
- |2070R0064 Generic itr to all licensees of operating plants,applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl.

 DIRCKS, M J. Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York, 93pp 14194,001, 24X Fiche 50-000,82/07/02,8207080064.
- 8208050051 Forwards agenda for 820810-13 control room in-progress audit SCHMENCER, A Licensing Branch 2. 82/07/30 DAVIDSON, D R Cleveland Electric IIIuminating Co 3pp. 14244:042. 24X Fiche. 50-440, 82/07/30, 8208050051.
- 8208240492 Requests input re-addition of personnel w/BMR operating experience & evaluation of safe shutdown margins per ACRS committee rept on facilities.
 86HHENGER.A. Licensing Branch 2. 82/07/30. DAVIDBON, D.R. Gleveland Electric Illuminating Co. 2pp 14544; 146, 24x Fiche: 80-440, 82/07/30, 8208240492.
- 8208120347 Responds to ACRS 820713 ltr providing comments & recommendations following review of applications for OL. Recommendations will be addressed in suppl to BER GOODHINGEF. Office of Nuclear Reactor Regulation, Director 82/08/03 FRALEY, R. ACRS Advisory Committee on Reactor Bafeguards. 3pp 14340-070. 24X Fichs: 50-440, 82/08/03, 8208120349.
- --8206270049 Summarizes ACRB 267th meeting on 820708-10 re DL application. Util urgently needs addl personnel w/BMR experience within operating mgt. If due consideration given to ACRB recommendations plant can be operated eating SHEWHON.P ACRS Advisory Committee on Reactor Safeguards. 82/07/13. PALLADING.N J. Commissioners Spp. 14340, 073 24X Fiche: 50-440, 82/08/03. 82081202220

- 8208100117 Responds to J Humphrey concerns re Mark III containment design Program being established to address each of 23 major concerns relead in Humphrey 820308 ltr to MI Power & Light DAVIDSON, D R Cleveland Electric Illuminating Co 82/08/05 SCHWENCER, A Licensing Branch 2 2pp 14278 186 24x Fiche 50-440, 82/08/03, 8208100117
- B208130150 Revision to application for OL, requesting 40-yr QL from date of issuance
 DAVIDSON, D. R Claveland Electric Illuminating Co 92/08/05
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp. 14337 142 24X Fiche 50-440,82/08/05,8208130150
- 8208090194 Ceneric Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISCNMUT, D. G Division of Licensing. 82/08/09 Consolidated Edison Co of New York lp 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- 8208250083 Notification of 820813 meeting w/util in Bethesda.MD to discuss safety relief valve hydrodynamic loads Agenda encl BTEFAND, J. J. Licensing Branch 2 82/08/09 SCHWENCER, A Licensing Branch 2, 4pp 14559 256 24X Fiche 50-440,82/08/09,8208250083
- 8208190244 Discusses changes to ATMS mitigation design features, per 820720 meeting. Bafety grade of rectrculation pump trip initiation circuit will be upgraded. Design details will be submitted as FBAR amend by Jan 1983 DAYIDBON.D R Cleveland Electric Illuminating Co 82/08/13 8CHMENGER.A Licensing Branch 2 2pp 14388 188 24X Fiche 30-440, 82/08/13, 8208190244
- B20B240430 Forwards "Containment Annulus Concrete Dasign, Const & Testing for Parry Nuclear Power Plant "Review or meeting to discuss NRC findings requested by 820901 DAVIDBON D R Commonwealth Edison Co B2/08/16 SCHWENCER, A Licensing Branch 2 Zpp 14526 250 24X Fiche 50-440,82/08/16, B20B240430
- --8208240436 "Containment Annulus Concrete Design, Const & Testing for Perry Nuclear Power Plant" « Cleveland Electric Illuminating Co 82/08/16, 49pp 14526-252 24X Fiche: 50-440, 82/08/16, 8208240430
- 8208240323 Supple B20622 response to B20327 request for info re hydrodynamic loads on control rod drive sys Schedule for resolution of overstress conditions extended to B30107, due to contractor expanded scope of work
 DAVIDSON.D R Cleveland Electric Illuminating Co. B2/08/18
 SCHHENGER,A Licensing Branch Z 2pp 14524 277 24X
 Ficha 50-440, 92/08/18,8208240323
- 8208260151 Forwards proprietary, "OE Environ Gualification Program "
 Rept withheld (ref [OCFR2, 790) Comments requested by 821015
 Affidavit requesting withholding enci.
 DAVIDSON,D R Cleveland Electric Illuminating Co 82/08/18
 SCHMENGER.A Licensing Branch 2 4pp. 14556-272. 24X
 Ficher DO-440, 82/08/18, 8208260151
- E NRC Safety Evaluation Report (SER), supple & correspondence
- B20B040003 Forwards add1 info re BER open items on manual initiation & termination of EBF & ADS sys testability DAVIDSON, D. R. Clevaland Electric Illuminating Co 82/07/20 SCHMENCER, A Licensing Branch Z 27pp, 14193 191 24X Fiche 30-440, 82/07/20, 8208040003,
- 820B090011 Forwards final draft of supplemental BER. Concurrences requested by 820B02 Changes &/or additions re resolved open items should be furnished to project manager W/o snc!

 NOVAK, T Assistant Director for Operating Reactors. 82/07/28

 HOUSTON, R W Assistant Director for Radiation Protection JOHNSTON, W Assistant Director for Meterials & Qualifications Engineering. KNIGHT, J P Assistant Director for Components & Structures Engineering Spp. 14283: 337 24X Fiche 50-440,82/07/28,820B090011
- 8208070306 Requests add1 info re unresolved fire protection issues contained in SER SCHWENGER,A. Licensing Branch 2, 82/07/28 DAVIDSON, D, R Cleveland Electric Illuminating Co 3pp 14307 108, 24X Fiche.50-440,82/07/28,8208070306.
- 8208120056 Responds to SER Open Item 9 & recent meetings w/Containment Sys Branch re pool dynamic loads Commits to meet load definitions in App 38 of GESSAR II 238 Nuclear Island DAVIDBON, D R Clevelend Electric Illuminating Co. 82/08/05. 6CHMENCER.A. Licensing Branch 2 3pp. 14324:008, 24X Fiche 50-440, 82/08/05, 8208120056

- --8204130421 Forwards NRC draft acceptance criteria for LOCA-related Mark III containment pool dynamic loads developed by Containment Bys Branch & BNL Recommends that criteria be sent to applicants to address how criteria are met SPEIB.T Assistant Director for Reactor Safety 82/03/09 TEDESCO.R Assistant Director for Licensing 9pp 14324 Oil 24X Fiche 50-000,82/08/05.8208120056
- 8208240296 Forwards add1 info ro feedwater check valves functioning following line break outside containment. In response to Machanical Engineering Branch draft SER Question 3 9-42 DAVIDEON, D R Cleveland Electric Illuminating Co 82/08/16 GCHMENCER, A Licensing Branch 2 11pp 14528 082 24X Fiche 50-440, 82/08/16, 8208240294
- 8208270666 Forwards SER Suppl 1 (NUREQ-OBB7) W/o encl SCHMENCER, A Licensing Branch 2 82/08/18 DAVIDSON, D, R Cleveland Electric Illuminating Co 2pp 14683 174 24x Fiche 30-440.82/08/18.8208270666
- 8208240299 Forwards response to NRC 820615 ltr & 8ER Confirmatory Item 15 re preservice insp program DAVIDSON, D R Cleveland Electric Illuminating Co 82/08/20 8CHMENGER, A. Licensing Branch 2 4pp 14528.078 24x Fichs, 50-440, 82/08/20, 8208240299
- 8208310416 Provides info to amend 820608 ltr re SER Confirmatory Item 34 on undervoltage protection. Encl sketches clarify logic for typical bus undervoltage protection scheme DAVIDEDN, D. R. Cleveland Electric Illuminating Co. 82/08/26 SCHEENCER, A. Licensing Branch 2 4pp 14693-284. 24X Fichs 50-440, 82/08/26, 8208310416,
- B208230422 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PERRY NYCLEAR POWER PLANT. UNITS 1 AND 2 Docket Nos 50-440 And 50-441 (Cleveland Electric Illuminating Company) e Office of Nuclear Reactor Regulation, Director, NUREQ-0887 B01. B2/08/31 43pp, Available at NTIS \$4.75 14518.224 24X Fiche 50-440. B2/08/31, B200230422
- F Security, medical, emergency & fire protection plans
- 8208090306 Requests add1 info re unresolved fire protection issues contained in SER BCHMENCER,A. Licensing Branch 2 82/07/28. DAVIDSON,D R. Cleveland Electric Illuminating Go 3pp 14307,108 24X Fichs. 30-440.82/07/28.8208090306

Adjudicatory correspondence

- 8207050079 FOIA request for Branch Technical Positions APSCB 3-1 & MSB 3-1.ACRB transcripts & tests in Japan re BWR ECCS core spray distributions
 HIATT.S L. Ohio Citizens for Responsible Energy 82/07/06.
 FELION.J M. Division of Rules and Records ip 14696:086. 24X
 Fichs. 50-440.82/07/06.8207050079.
- B207/60215 Motion for leave to submit addl contention re low level radiation health effects & economic costs based on DEB (ANREO-0884) & DC Court of Appeals 820427 decision Proof of Svc encl WILT.D D. Bunflower Alliance. WILT.D D. Wilt. D D. 82/07/13 Atomic Safety and Licensing Board Panel 3pp 13970:001 24X Fiche 80-440, 82/07/13, 8207160215
- 8208020208 Answer opgosing Sunflower Alliance 820713 motion to submit addi contention, Contention untimely & w/o basis DES does not justify filling Certificate of Svc snci.
 WILLMORE,R.L. Cleveland Electric Illuminating Co. WILLMORE,R.L. Shaw, Fitman, Potts & Trowbridge 82/07/28 Atomic Bafety and Licensing Soard Panel 46pp 14141-136. 24X Fiche 50-440,82/07/28,8208020208
- 8208030372 Emphasizes that Issue 1 includes OH Citizens for Responsible Energy potassium iodide issue. Related correspondence HTATT.B.L. Ohio Citizens for Responsible Energy 82/07/29. STLBERQ.J. Shaw. Pittman. Potts & Troubridge 2pp. 14134:005 24X Fiche:50-440.82/07/29.8208030372.
- 8208030363 Responds to applicant 820719 & 28 ltrs. Intervenors have right to file raply briefs per 810804 order. DH Citizens for Responsible Energy 820706 notice did not imply that criteria far late-filed contentions should be suspended, HIATT, S. L. Dhio Citizens for Responsible Energy 82/07/31 8LDCH-P.B. KLINE, J.R., SHON, F. J. Atomic 84fety and Licensing Board Panel. 2pp 14237:303. 24% Fiche. 50-440, 82/07/31.8208050363.
- B208040210 Partial answer to second set of interrogatories.
 WILCOVE, N N . WRIGHT, N A Hearing Branch 2, 82/08/02, Sunflower
 Alliance. 38pp. 14188, 254, 24X Fiche 50-440, 82/08/02, 82080 40210,

- 8208040271 Response opposing Sunflower Alliance et al 820713 motion for leave to submit add1 contentions Contentions fail to specify basis & fail to meet stds for lete filing Notice of appearance & Certificate of Evr uncl
 WRIGHT.N A Hearing Branch 2 82/08/02 Atomic 8efsty and
 Licensing Board Panel 7pp. 14183 071 24X Fiche 50-440,82/08/02,8208040271
- 8208050396 Reply supporting Bunflower Allience 820721 motion to expand GA contention Issue should include entire const dA program. Any & all violations: regardless of occurrence date, are relevant Certificate of Svc enc! HIATT. 8 L Objo Citizens for Responsible Energy 82/08/02 Atomic Rafety and Licensing Board Panel 3pp 14209-208, 24X Fiche 50-440,82/08/02,8208050396
- 8208060097 Forwards documents referred to in NRC 820802 response to Interrogatories 66 & 68
 WILCOVERN N Hearing Branch 2 82/08/04. WILT, D Bunflower Alliance WILT, D Wilt, D D 23pp. 14238 190 24X
 Fiche 50-440.82/08/04.8208060097
- 8208070179 Reply brief supporting ASLB order compelling discovery Info sought appears reasonably calculated to lead to discovery of admissible evidence Proof of Svc encl Related correspondence.

 MILT.D D Sunflower Alliance WILT.D D Wilt, D D 82/08/04, Atomic Bafety and Licensing Board Panel. 2pp 14272 057 24X Fiche: 50-440.02/08/04.8208070179.
- 8208090183 Notion for reconsideration of ASL8 820720 decision, dismissing Issue 10 re psychological stress from proceeding, or alternatively for certification to Commission of ALSB jurisdiction over issue Proof of Bvc encl. WILT.D D Sunflower Alliance. WILT.D.D Wilt, D.D. 82/08/04 Atomic Safety and Licensing Board Penel 7pp. 14272 049, 24X Fiche: 50-440, 82/08/04, 8208090183
- 8208090230 Requests prepared documents including draft emergency plan & std operating procedures as interim discovery measure to assist in assessment of state emergency planning Related correspondence
 HILT.D.D. Wilt, D.D. WILT,D.D. Sunflower Alliance 82/08/04
 EZZONE,D.T. Late County, OH ip. 14271*037. 24X
 Fichs:50-440,82/08/04,8208090250
- 8208070005 Advises that NRC will file no response to Sunflower Alliance 820621 motion to compal discovery from applicant LEWIG.5 H Hearing Branch 2. 82/08/05, BLOCH.P B. KLINE, J.R. 8HON.F J Atomic Sefety and Licensing Board Panel. 1p 14270 060 24X Fichs:50-440,82/08/05,8208070005
- 8208090144 Responds to 820729 ltr re applicant interpretation of Issue 1.88.0 admitted OH Citizens for Responsible Energy potessium iodide contention Applicants have not changed position on subj contention Box list encl.

 81LBERG, J E Shaw, Pittman, Potts & Trowbridge, BllBERG, J, E Cleveland Electric Illuminating Co 82/08/05, HIATT, 8 L Ohio Citizens for Responsible Energy, 2pp 14271-315 24X Fiche 50-440-82/08/05,8208090144
- 8208090144 Confirms 820805 telcon where ABLB informed that Bunflower Alliance agreed to extension until 820810 for applicants to answer Alliance 820721 request for admissions re Issue 4. Bye list encl.

 SILBERO, J.E. Bhaw, Pittman, Potts & Troublidge SILBERO, J.E. Cleveland Electric Illuminating Co. 82/08/05 BLOCH, P.B., KLINE, J.R.: SHON, F.J. Atomic Safety and Licensing Board Panel. 2pp. 14271 319. 24% Fiche: 50-440, 82/08/05. 8208090144
- 8208070243 Answer opposing Sunflower Alliance, Inc 820721 second motion to expand GA contention. Issue 3 to cover any violation of GA/GC std regardless of date of occurrence. No serious programmatic deficiencies identified. H/Certificate of Bvc WILLHORE, R. L. Cleveland Electric Illuminating Co. HILLHORE, R. L. Shaw, Pittman, Potts & Trowbridge. 82/08/05 Atomic Sefety and Licensing Board Panel 13pp. 14271.061 24X Fiche. 50-440, 82/08/05, 82/08/0243
- 8208110158 Mation to strike Sunflower Alliance 820804 reply brief in support of motion to compel discovery. Brief filed in direct contravention of NRG rules of practice. Certificate of Svc enci.

 HILLMORE, R. L. Cleveland Electric Illuminating Co. HILLMORE, R. L. Shaw, Pittmen, Potts & Trowbridge 82/08/09. Atomic Safety and Licensing Board Panel App 14314, 238. 24X Fiche. 50-440, 82/08/09, 82/08/10158
- 8208120145 Motion for leave to file Contention 20 re adequacy of consideration of economic consequences of accidents DES (NUREO-0884) deficient due to failure to include assessment of disruption caused by accident Certificate of 8vc encl. HIATT-8 L. Ohio Citizens for Responsible Energy 82/08/09. Atomic Safety and Licensing Board Panel. 20pp. 14319:208. 24X Fiche: 50-440-82/08/09.8208120145

- 8208120123 Answer to Sunflower Alliance.Inc 820721 request for admissions re Issue 4 on ECCS evaluation model Certificate admitsions religious and cook of Svc enci WILLMORE.R L Cleveland Electric Illuminating Co WILLMORE.R L Bhau. Pittman. Potts & Trombridge 82/08/10 Sunflower Alliance 14pp 14927 051 24X Fiche 50-440.82/08/10.8208120123
- B20Bi30007 Response opposing Sunflower Alliance, Inc B20721 second motion to expand scope of OA Contention, Issue 3 Alliance failed to establish bases to provide adequate justification for contention Certificate of Svc encl NRIGHT, N A Hearing Branch 2 82/08/11 Atomic Safety and Licensing Board Panel 8pp 14333 190 24% Fiche 50-440,82/08/11,8208130007
- 8208130165 Answer to second set of interrogatories Certificate of 8vc encl Related correspondence MILLMORE, R L Cleveland Electric Illuminating Co. WILLMORE, R L 8haw, Pittnam, Potts & Troubridge 82/08/11 Sunflower Alliance 27pp 14339 038 24X Fiche 50-440,82/09/11,8208130165
- 8208170197 Reply supporting Sunflower Alliance 820804 motion for reconsideration of ASLB 820719 order dismissing Issue 10. or for certification Commission 820716 statement of policy repsychological stress illegal W/Certificate of Svc HIATT, S. L. Ohio Citizens for Responsible Energy 82/08/12 Atomic Bafety and Licensing Soard Panel. 7pp. 14364 268 24) Fiche 50-440,82/08/12.8208170197
- B20B170271 Answer opposing Sunflower Alliance. Inc at al 820B04 motion for reconsideration or, in alternative, certification to Commission of questions re 820719 order dismissing Issue 10 on psychological stress H/Certificates of Svc HILLMORE, R. L. Cleveland Electric Illuminating Co HILLMORE, R. L. Shaw, Pittman, Potts & Trowbridge, 82/08/13 Atomic Safety and Licensing Board Panel Bpp 14367-262 24X Fiche 50-440, B2/08/13, 8208170271
- 8208190135 Responses to Sunflower Alliance request for admissions concerning Issue 4 on ECCB evacuation model & Unresolved Safety Issue A-16 re steam affects on BLR core apray distribution Affidavits & Certificate of Svc ancl WRICHT, N A Hearing Branch 2 82/08/16 Sunflower Alliance 16pp 14377 053 24X Fiche 50~440,82/08/16,8208180135
- 8208180137 Informs of NRC progress on discovery activities during previous 2 months.per ASLB 810909 memorandum & order Responses submitted to listed documents FES will be issued in latter half of Aug VOOLER, B, H Hearing Branch 2, 82/08/16 BLOCH, P, B, , SHON, F J , KLINE, J R Atoolc Safeby and Licensing Board Panel 2pp 14378 287 24X Fiche 50~440, 82/08/16, 8208180137
- 8208200186 Order ruling on Sunflower Alliance 820621 motion to compel Info re emergency response agreements, volunteers unsite initiating conditions, administrative means, meteorological monitoring & communications must be provided ELOCH, P.B. Atomic Bafety and Licensing Soard Panel 82/08/18 Cleveland Electric Illuminating Co. 8pp. 14393-353. 24X Fiche: 50-440, 82/08/18, 8208200186
- 8208270451 Informs that applicants agreed to add 5 optional extra COME/OFF INFORMS that applicants agreed to add 5 optional extra
 days to period in which motion to compel discovery may be
 filed.per ASLB 820713 ruling Hotion to compel discovery
 will be filed by 820907 Related correspondence
 HIATTLB L. Ohio Citizens for Responsible Energy 82/08/18
 BLOCH.P B, KLINE, J.R., SHON, F.J. Atomic Safety and Licensing Board
 Panel 2pp 14566 120 24% Ficher 50-440.82/08/18.8208270451
- 8208270463 Motion for leave to file Contentions 21-26 re turbine 208270463 Motion for leave to file Contentions 21-26 re turbine missiles.new Mark III containment concerns, seismic evaluation of BWR core thermal hydraulics & in-core thermocouples H/Gertificate of Evc HIATT, BL Obio Citizens for Responsible Energy 82/08/18, Atomic Safety and Licensing Board Fanel, 21pp. 14565-273 24% Fichs 50-440,82/08/18,8208270463
- 8208270527 Sixth discovery progress rept per ASLB 810707 Memorandum & Order LBP-81-35 Certificate of Syc encl Related Order Confered to 30 confered to 30
- 8208240191 Sixth discovery progress rept Certificate of Bvc encl. WILLMORE, R. L. Clevelend Electric Illuminating Co HILLMORE, R. L. Bhau, Pittman, Potts & Troubridge 82/08/20, 3pp 14519-330 Fiche: 50-440, 82/08/20, 8208240191.
- 8208240235 Answer to second set of interrogatories. Certificate of Syc WillMore, R.L. Cloveland Electric Illuminating Co. HILLMORE, R.L. Bhaw. Pittman, Potts & Trombridge. 82/08/20. Sunflower Alliance, 28pp 14520.021, 24X Fiche 50-440, 82/08/20, 8208240235

- 8208260051 Response apposing Sunflawer Alliance, Inc 820804 motion for reconsideration of ASLB 820719 memorandum & order dismissing Issue 10 re psychological stress In alternative motion should be certified to Commission Certificate of Svc encl LEWIS 8 H , WRIGHT, N A Hearing Dranch 2 82/08/24 Atomic Safety and Licensing Board Panel Spp 14555 226 Fiche 50-440, 82/08/24, 8208260051
- 8208270505 Add1 answer to first round discovery requests Certificate of Svc enci Related correspondence
 SILBERO, J E Cleveland Electric llluminating Co SILBERO, J E Shaw, Pittman, Potts & Trowbridge 82/08/24 Sunflower Alliance 4pp 14563 357 24X Fiche 50-440,82/08/24,8208270506
- 8208300287 Bupplemental answer to second set of interrogatories Certificate of Svc enc! WILLMORE, R L Cleveland Electric Illuminating Co WILLMORE, R L Shaw, Pittman, Potts & Trombridge 82/08/26 Ohio Citizens for Responsible Energy Spp 14679 182 24X Fiche 50-440, 82/08/26, 8208300287

- 8208090247 Advises that author will continue to represent clients to best of ability, in response to Willmore 820728 ltr Related
- correspondence
 WILT, D.D. Wilt, D.D. Will, D.D. Sunflower Alliance 82/08/04
 BLOCH, P.B. Atomic Safety and Licensing Board Panel 1p 1427:
 24X Fiche 50-440, 82/08/04, 8208090247
- 8208090254 Notice of change of address for DD Wilt WILT, D D Sunflower Alliance WILT, D D Wilt, D D 82/08/04 1 14272 019 24% Fiche 50-440.82/08/04.8208090254
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8208260124 Forwards Amend B to FSAR Certificate of Svc encl DAVID8DN.D R Cleveland Electric Illuminating Co 82/08/25 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 14556-333 24X Fiche 50-440, 82/08/25, 8208260124,
- --8208260129 Amend 8 to FSAR * Cleveland Electric Illuminating Co 82/08/25 800pp #4556 336 24% Ficha 50-440, 82/08/25, 8208260124
- M Antitrust correspondence
- 8208230018 Requests responses to questions re antitrust review of OL application.
 TOALBTON: A Antitrust & Economic analysis Branch (Utility Finance)
 82/08/09 DAGOETT.E L. Bryan: OH 2pp 14518 001, 24X
 Fiche 50-000,82/08/09.8208230018
- 8208230477 Requests responses to questions re antitrust review of OL COGESION / New York Control of the Control of Control
- 8208240081 Requests responses to questions re antitrust review of OL application
 TQALBTQN:A Antitrust & Economic analysis Branch (Utility Finance)
 82/08/09 GREEN.T Painesville, GH 2pp 14529 313 24X
 Fiche 50-000, 82/08/09, 8208240081
- O Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl
 JORDAN.E.L Division of Engineering & Quality Assurance. 82/07/16
 Consolidated Edison Co. of New York 87pp 14356 274 24X
 Fiche: 30-000.82/07/16.8204210393.
- 8204210395 IE Info Notice 81-26, Part 3, Suppl i, "Clarification of 204210395 IE info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list oncl JORDAN, E L Division of Engineering & Guality Assurancs, 82/07/19 Michigan, Univ of, 112pp 14358 001, 24X Fichs 50-000, 82/07/19 8204210395,
- 8204210396 IE info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York. 112pp. 14381.001 24X Fiche: 50-000.82/07/20,8204210396

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Dyspacks " Svc list encl C08B.L I Division of Fuel Facilities. Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp. 14357 276 24K Fishe 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York 112pp 14174 321 24X Fiche. 50-000, 82/07/22, 8204210398
- E204210401 IE Info Notice 82-28. "Hydrogen Explosion While Orinding in Vicinity of Dreined & Open RCB " Svc list entl JORDAN E L Division of Engineering & Quality Assurance 92/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fishs 50-000, 82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " 8vc list encl URDAN,E L. Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York 127pp 14194 120, 24X Fishe 50-000, 82/07/23, 8204210402,
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list enci DRDAN,E t. Division of Engineering & Quality Assurance 82/07/26, Consolidated Edison Co of New York, 121pp. 14357:013, 24X Fiche 50-000.82/07/26.8204210403
- B2Q42i0405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Fool " Byc list encl. GRBAN,E L Division of Engineering & Quality Assurance. 82/07/28, Consolidated Edison Co of New York, 122pp 14357:146, 24X Fiche 50-000, 82/07/28, 82042i0405
- B204210407 IE info Notice 82-27, "Fuel Rad Degradation Resulting From Baffis Hater-Jet Impingement," 8vc list encl.

 URBANSE L Division of Engineering & Quality Assurance, 82/08/05 Consolidates Edison Co. of New York 117pp 14388 201, 24X Fichs 50-000, 82/08/05, 8204210407
- B208310003 Responds to appeal re denial of FD1A request for documents concerning IE Insp Rept 50-358/81-13 Appeal partially granted & partially denied Forwards CH Weil 810914 memo. Theo partially withheld (ref FD1A Exemption 7) D1RCAS U Office of the Executive Director for Operations B2/08/12 DEVINE.T Government Accountability Project ip 14697.220 24X Fiche 50-000.82/08/12.8208310003.
- --B208310005 Forwards RT Carlson 810724 memo re allegations reported to Region 1 by anonymous complainant concerning facilities Vandor Insp Branch will conduct insp of Nuclear Engineering Syes.

 WELL: C. H. Region 3, Chicago, Office of the Director (81/03/01).

 81/09/14 Region 3, Chicago, Office of the Director (81/03/01).

 3pp. 14697:221. 24X Fiche:50-000-82/08/12-8208310003
- --B208310009 Forwards RE Shepherd memos re allegations concerning facility insp. design controls & accumulation of test data Confidential info delated. CARLEDN,R T. Enforcement & Investigation Staff 81/07/24. STREETER, J. Enforcement & Investigation Staff. 18pp. 14697 224. 24X Fichs 50-000, 82/08/12, 8208310003
- 8208240299 Forwards response to NRC 820615 ltr & SER Confirmatory [tem 15 re preservice inap program DAVIDBON, B.R. Cleveland Electric Illuminating Co 82/08/20 SCHRENCER, A. Licensing Branch 2 App 14528 078 24X Fiche. 50-440, 82/08/20, 8208240299
- S Reportable occurrences, LERs & related correspondence
- 8208130270 Final deficiency rept re-potential defects in Pratt velves & Bettis actuators Initially reported on 820611.81te Nonconformance Rept UPGC 258 initiated to track deficiency Fattis contacted re-parts replacement Next rept by 821127 DAVIDSDN.D R. Cleveland Electric Illuminating Co. 82708705. KEPPLER.J Q Region 3, Office of Director. 2pp. 14333:053. 24X Fiche 50-440,82708/05,8208130270
- T. Hearing transcripts on non-antitrust matters
- 8208170147 Transcript of 820813 telephone conference re OL issuance in Washington, DC. Pp. 658-759

 Atomic Befety and Licensing Board Panel. 82/08/13, 103pp. 64366 023 24X Fiche: 50-440, 82/08/13, 8208170147

- DOCKET 50-443 BEABROOK NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8208020424 Advises of OL review schedule change SER to be issued on 82108.ACRS meeting to be held on 821210.ASLB decision due in Apr 1984 & Commission decision in May 1994.
 TEDESCO.R.L. Assistant Director for Licensing 82/07/07
 TALLHAN,W.C. Public Service Co. of New Hampshire 2pp. 14181.031
 24X Fiche: 50-443,82/07/07.8208020424.
- 8207300522 Forwards amends to text page tables & figures originally submitted in 820312 ltr.per 241 Series request for addition of the series request for addition DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of Nau Hampshire 82/07/22 MIRAOLIA, F. J. Licensing Branch 3 17pp 14172 260 24X Fiche 50-443,82/07/22,8207300522
- 8208040644 Forwards request for add1 info for safety review of OL application, Response requested within 10 days.
 MIRAOLIA,F J Licensing Branch 3 82/07/27 TALLMAN,H C Public Service Co of New Hampshire 21pp 14224 030 24X
 Fiche 50-443,82/07/27,8208040644
- 820B040565 Notifies of add1 fees due for review of 811216 amend application to transfer ownership shares in facility MILLER,W O License Fee Management Branch. B2/07/28 TALLMAN,W C Public Service Co of New Hampshire 1p 14220,348 24X Fiche 50-443,82/07/28,820B040565
- B20B020071 Forwards R Borcherdt B20721 ltr in response to FDIA request re 820109 Miramichi earthquake in New Brunswick. Canada NRC requested util to investigate earthquake & forward info. Open-file rept describing aftershock data encl.
 KING, J Geosciences Branch B2/07/30 NRC No Detailed Affiliation Given 7pp. 14144.117 24X Fiche: 50-443.82/07/30.820802071
- 8208050408 Forwards revised response to Containment Bys Branch 820301 request for add1 info Comparsion for worst case LOCA of containment pressure & temp response using mass & energy release data provided DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J. Public Service Co of New Hampshire. 82/09/03 MIRAGLIA.F. J. Operating Reactors Branch 3 4pp 14217.345 24X Fiche: 50-443.82/09/03.82/0950408
- 820B090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC SUmmarizes IOCFR Chapter I requirements & provides alternatives to requirements for list encl EIBENHUT.D O Division of Licensing, B2/08/09 Consolidated Edison Co of New York 1p. 14356 332 24X Fiche 50-000, B2/08/09, 8208090194
- 8208110102 Bubmits revised estimate of ennual rediation dose to Unit 2 const personnel during operation of Unit 1 Revised FBAR Section 12 4 3 will be incorporated into Amend 46. DEVINCENTIS. J Vantes Atomic Electric Co DEVINCENTIS. J Public Service Co of New Henrshire. B2/08/07, HIRAGLIS., F J. Licensing Branch 2 2pg. 14317.174 24X Fichs 50-443,82/08/09.8208110102.
- 8208130297 Forwards summary of Instrumentation & Controls 8ys Branch 820715 & 16 review mastings re design conformance w/IMI action plan items
 DEVINCENTIS, J. Yanker Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 82/08/10 MIRAGLIA, J.F. Licensing Branch 3 49pp 14337-092, 24X Fiche 50-443,82/08/10,8208130297
- 8208170323 Forwards followup documentation from Structural Engineering Branch design audit re Action Item 13 Load Combinations used in design are in accordance w/SRP DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 82/08/12 MIRAGLIA, F. J. Licensing Branch 3. 3pp. 14366.339. 24X Fiche. 50-443, 82/08/12. 8209170323.
- 8208190185 Forwards revised FBAR pages re seismic design basis of alectrical raceway cable tray sys Info will be incorporated into Amend 46 to FBAR DEVINCENTIB, J. Yankee Atomic Electric Co. DEVINCENTIB, J. Public Service Co. of New Hampshire 82/08/16 HIRAGLIA, F. J. Licensing Branch 3 5pp. 14382-227. 24X Fichs 50-443,82/08/16,8208190155
- 8208190075 Forwards "Problem 4, Piping Benchmark Problems, NUREO/CR-1677, BNL-NUREO-51267, Vol 1."
 DEVINCENTIB, J Yankee Atomic Electric Co DEVINCENTIB, J. Public Service Co of New Hampshire, 82/08/17 HIRACLIA, F J. Licensing Branch 3 2pp. 14382:249. 24X Fiche. 50-443, 82/08/17, 8208190075

- --8208170080 "Problem 4, Piping Benchmark Problems, NUREO/CR-1677, BNL-NUREO-51267, Vol 1 "

 † United Engineers & Constructors, Inc (subs of Raytheon Co)
 82/05/13 200pp 14382 251, 24X Fiche 50-443,82/08/17,
 8208170075
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8207120047 Offers no comments on BES Resources for which Natl Marine Fisheries Svc bears responsibility & alternatives to reduce adverse impacts on resources addressed satisfactorily in DES REHFUS, R Commerce, Dept of, National Marine Fisheries Service 82/07/01 MIRAGLIA: FJ Licensing Branch 3 ip 13811 147, 24X Fiche 50-443, 82/07/01, 8207120047
- 8208030731 Ack receipt of 820707 comments on facility DES & offer of assistance in responding to comments re NPDES Cooperation & assistance appreciated MIRAOLIA,F.J. Licensing Branch 3 82/07/21. LANDRY, T Environmental Protection Agency ip 14198, 317 24X Fiche: 50-443, 82/07/21, 8208030731
- 8208070323 Forwards comments from federal state & local govt agencies & public on DEB, for review W/o encl MIRAOLIA:F J. Licensing Branch 3 82/07/30 TALLMAN, W C Public Bervice Go of New Hampshire 29p 14307 334, 24X Fiche: 50~443, 82/07/30, 8208070323
- 8208100154 Contests statement in DES that 345 kV transmission lines will have no adverse effect on health of humans or plant & animal life. Research citing negative effects of OH-HV lines noted. Objectivity of DOE & EPRI research questioned GOLDSTEIN.C.H. Affiliation Unknown 82/08/04 Division of Licensing App 14297-211. 24X Ficher 50-443, 82/08/04, 8208100154,
- 0208150036 Requests inclusion of State of NN 820530 comments on DES in record of comments received Comments omitted from NRC 820730 ltr. KINDER, E. T. New Hampshire, State of 82/08/10 HIRAGLIA.F J Licensing Branch 3. 1p 14344 261. 24X Fiche 50-443.82/08/10, 8208160036.
- 1208300142 Forwards response to 820730 ltr re comments on NUREQ-0895, DES for facility. Concentrations of chlorine & bromine residuals will be minimal & should not add to concentrations in sys of marine organisms.

 DEVINCENTIS, J. Public Service Co of New Hampshire 82/08/24 HIRAOLIA, F. J. Licansing Branch 3. 6pp 14678 214 24X

 Fiche: 50-443, 82/08/24, 8208300142
- 3208310187 Forwards response to NRC Jul 1982 comments on DEB repreliminary draft NPDES permit.
 ELLS:8 F. Environmental Protection Agency. 82/08/25 MIRAGLIA.F J Licensing Branch 3 4pp 14687 282 24X Fiche. 50-443, 82/08/25, 8208310189.
- NRC Bafety Evaluation Report (BER), suppls & correspondence
- 8208270608 Forwards partial draft SER.list of open items in SER sections & status of review for remainder of SER. Assignment of authorized representative to participate in resolution of open items requested NOVAK.T.M. Assistant Director for Licensing 82/08/13, TALLMAN, H C Public Service Co of New Hampshire. 300pp 14680 118, 24X Fiche 30-443,82/08/13,8208270608
- F Security, medical, emergency & fire protection plans
- 8208040256 Releases public version of revisions to radiological amorgancy plan FELTON, J. H. Division of Rules and Records. 82/07/20. Document Management Branch. 1p. 14225-001. 24X Fiche 50-443, 82/07/20, 8208040256.
- --8208040261 Forwards public version of detailed radiological emergency plan revisions which ref 820309 request for add1 info & radiological emergency plan annotated pages
 DEVINGENTIBLU. Vankee Atomic Electric Co. DEVINCENTIB.J. Public Bervice Co. of New Hampshire. 82/07/09 MIRACLIA, F. J. Licensing Branch 3 150pp. 14225:002. 24X Fiche.50-449,82/07/20,8208040256.
- 8208060303 Forwards revised pages to fire protection program evaluation submitted 820401. Two redundant automatic deluge sys installed in each fuel oil storage tenk area. DEVINCENTIG.J Public Service Co of New Hampshire. 82/07/28 MIRAGLIA,F.J. Licensing Brench 3, 1p. 14239,353 24X Fichs: 50-443, 82/07/28. 8208060303.

- --8208060305 Revised pages to fire protection program evaluation & comparison to Branch Technical Position APGSB9 5-1 App A, Revision 1

 # Public Service Co of New Hampshire 82/07/28 4pp 14237 354 24% Fiche 50-443,82/07/28,8208060303
- B208040478 Requests response to encl comments on 820628 physical security & guard training & qualification plans Response in form of revised pages requested within 30 days of receipt of ltr MIRROLIA.F J Licensing Branch 3 82/07/30 TALLMAN, W. C Public Service Co of New Hampshire 3pp 14220 306, 24X Fiche 50-443. B2/07/30. B208040478
- 8208130328 Informs that Hampton Falls & Hampton have not been contacted re svacuation planning Suit presently in NH Supreme Court PEVEAR, R C New Hampshire, State of 82/08/07 ROBERTS, T Commissioners. 1p 14378 270 24X Fiche 50-443,82/08/07,8208130328
- Q Adjudicatory correspondence
- 8208060126 Reply to Soc for Protection of Environ of Southeastern NH supplemental patition to intervene Raworded Contention B should be excluded since res judicata prohibits litigation on transmission lines Certificate of Svc encl DIGNAN, T Q . GAD, R K Public Service Co of Naw Hampshire DIGNAN, T Q . Ropes & Gray 82/08/02 Atomic Safety and Licensing Board Panel 8pp 14238 318 24X Fiche 50-443,82/08/02,8208060126
- 8208060135 Motion for leave to reply to Commonwealth of MA brief, New England Coalition on Nuclear Pollution filing on emergency planning & Soc for Protection of Environ supplemental gettion Certificate of Svc encl DIGNAN, T G. GAD, R. K. Public Service Co. of New Hampshire DIGNAN, T G. Ropes & Gray 82/08/02 Atomic Safety and Licensing Board Panel 4pp. 14241 271 24X Fiche 50-443,82/08/02,8208060133
- S208060137 Reply to New England Coalition on Nuclear Pollution supplemental filing on emergency planning contentions Only Contentions 2.6, 11 & 12 meet 10CFR2 714 requirements Certificate of Svc enci DIGNAN, T 9. GAD, R K Public Service Co of New Hampshire DIGNAN, T 9 Ropes & Gray 82/08/02 Atomic Safety and Licensing Board Penel 12pp 14241 258 24X Fichs 50-443,82/08/02,8208060137
- 8208040151 Reply to Commonwealth of MA brief in support of contentions Contentions fail to meet NRC requirements & should be excluded Certificate of Svc encl
 DIGNAN, T G , 9AD, R K Public Benvice Co of New Hampshire
 DIGNAN, T. O Ropes & Gray 82/08/02 Atomic Safety and Licensing
 Board Panel 17pp, 14237 281 24X Fiche 50-443,82/08/02,
- B20B1B0112 Comments on recent tour of facility. Work of Costallo, Lomasney & deNapoli re radiological response planning indequate & incomplete Util optimism on Unit 2 unfounded DAIONEAULT, M Beacoast Anti-Pollution League 82/08/09, ROBERTS, T Commissioners 1p 14379 260 24X Fiche. 50-443, 82/08/09, 82081B0112
- 820Bi60150 Motion for leave to file response to applicant reply to Commonwealth of MA brief supporting Commonwealth contentions Contentions should be consolidated into one emergency planning contention W/Certificate of Svc SHOTWELL, J A Hassachusetts, State of 82/08/10 Atomic Sefety and Licensing Board Panel App. 14345 131 24X Fiche 50-443,82/08/10,8208160150
- 8208160230 Responds to applicant 820802 reply to Commonwealth of MA brief supporting Commonwealth Contentions 2,3 & 4 Contentions state litigable issues firmly based on Commission regulations Certificate of Svc encl.
 SHOTMELL, J.A. Massachusetts, State of S2/08/10 Atomic Safety and Licensing Board Panel 9pp 14347 114 24X Fiche, 80-443, 82/08/10, 8208160220
- 8208120010 Notifies that J Daughty added to svc list in response to 820723 request.
 LESBY, R P Hearings Division 82/08/11 RACKUB, R A Backus, R A 1p 14323 336, 24% Fiche: 50-443,82/08/11,8208120010
- 8208250296 Forwards ALAB-687 due to substantial discussion at second special prehearing conference on admissibility of emergency planning contentions ASLB cannot conditionally admit contentions for any reason
 LESSY.R P. Hearing Branch 3. 82/08/23 HOYT,H . LUEBKE,E,A., PARIS.O.H Atomic Safety and Licensing Board Panel 2pp. 14542 218, 24% Fichs 50-443,82/08/23,8208250296

- 8208230340 Informs that Commission declined review of Director's Decision 82-8 Time within which Commission may act to review expired Decision became final agency action on 820820 CHICK.S.J. Office of the Secretary of the Commission 82/08/23 8408/23,8208250340
- Q Inspection reports. IE Bulletins & correspondence
- 82042(0393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000
- B208020166 Forwards IE Insp Repts 50-443/82-07 & 50-444/82-07 on B20614-17 No noncompliance noted HARTIN.TT Division of Engineering & Technical Programs B2/07/19 TALLHAN,N C Public Service Go of New Hampshire 2pp 14141 009 24x Fiche 50-443,82/07/19,8208020166
- -- 9208020170 IE Insp Repts 50-443/82-07 & 50-444/82-07 on 820614-17. No noncompliance noted Major areas inspected, procedures & work activities re concrete const of primary containment bldg sterior wall & dome & observation of structural fill VARELA.A & DURR.J.P Division of Engineering & Technical Programs 82/07/14 7pp 14141 011 24X Fiche 50-443,82/07/19,8208020166
- B204210396 IE Info Notice 82-29, "Failures of Hiller Actuators Upon Gradual Cass of Air Pressure " Syc list encl JORDAN-E L Division of Engineering & Quality Assurance B2/07/20, Consplidated Edison Co of New York 112pp 14381:001. 24X Fiche: 50-000, 82/07/20, 8204210396
- B2O4210397 IE Info Notice B2-24. "Water Leaking From U Hexafluoride Overpacks" Bvc list encl COBB.L. I Division of Fuel Facilities. Materials & Safeguards. B2/07/20 Consolidated Edison Co of New York 7ipp. 14357.27. 244 Fiche 50-000.82/07/20.8204210397
- 20421037B IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valva Fattures " Svc list encl.

 ARDAN E L Division of Engineering & Quality Assurance 82/07/22
 Consolidated Edison Co of New York 112pp 14174 321. 24X
 Fichs 50-000.82/07/22.8204210378
- 204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding In Vicinity of Drained & Open RCB " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115. 24X Fische 50-000, 82/07/23, 8204210401
- 204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " 8vc list encl JORDMINE L Division of Engineering & Quality Assurance Garsolidated Edison Co of New York 127pp 14194,120 24X Fiche 50-000,82/07/23,8204210402.
- 204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants." Svc list enci JGRDAN,E L Division of Engineering & Guality Assurance Consolidated Edison Co of New York, 12ipp 14357-013 24X Fiche 50-000.82/07/26,8204210403
- *042:0405 IE Info Natice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28 consolidated Edison Co of New York 122pp 14357 146, 24X Fiche 56-000-82/07/28-8204210405
- QBQ20276 Ack receipt of B20717 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/82-04 & 50-444/82-04 BTAROBIECKI.R Division of Project & Resident Programs. 82/07/28 TALLHAN.H C public Service Co of New Hampshire 1p 14152; 259. 24X Fichs 30-443, 82/07/28, 8208020276.
- B208020283 Responds to NRC 820708 ltr re violations noted in IE Insp Repts 50-440/82-04 & 50-444/82-04 Corrective actions: Installation contractor reinspected installed batteries, identified discrepant conditions & performed rework JOHKSON.H P Vankee Atomic Electric Co 82/07/19, STAROSTECKI,R Division of Project & Resident Programs. 2pp 14152.260 24X Fiche, 50-443, 82/07/28, 8208020276.
- 14210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From laftle Water-Jet Impingement," Svc list encl.

 MRDAN, EL Division of Engineering & Guality Assurance, 82/08/05.

 Consolidated Edison Co of New York 117pp 14388,201 24%

 £che-50-000,82/08/05,8204210407

- 8 Reportable occurrences, LERs & related correspondence
- 8208200222 Final deficiency rept re insufficient development length in containment encl bidg horizontal missile shields Initially reported on 820803 Deficiency corrected prior to placement of concrete. As-constructed slabs meet design regularements DEVINCENTIB. J Yankee Atomic Electric Co. DEVINCENTIB. J Public Service Co of New Hampshire 82/08/16 STAROBTECKI, R Division of Project & Resident Programs 2pp 14399.346 24X Fiche 30-443.82/08/16.8208200222
- 8208250281 Final deficiency rept re nonseismically supported conduit Initially reported 820723 Engineering change authorization issued to revise drawings to specify seismically qualified supports for conduits in refueling water storage tank area DEVINCENTIB, J Yantee Atomic Electric Co DEVINCENTIB, J Public Bervice Co of New Hampshire 92/08/19 87ARGHTECKI, R Division of Project & Resident Programs 3pp 14584 272 24% Fiche 50-443, 82/08/19, 8208260281
- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8207300522 Forwards amends to text page tables & figures originally submitted in 820312 ltr.per 241 Series request for addition of DEVINCENTIB, J. Public Strvice Co. DEVINCENTIB, J. Public Strvice Co. of New Hampshire 82/07/22 MIRAGLIA, F. J. Licensing Branch 3 17pp. 14172 260 24X Fiche 50-443,82/07/22,8207300522.
- 8208040644 Forwards request for add1 into for safety raview of DL application Response requested within 10 days MIRAOLIA:F J. Licensing Branch 3 82/07/27 TALLMAN,W C Public Service Co of New Hampshire 21sp 14224 030 24X Fich# 50-443,82/07/27,8208040644
- 8208040565 Notifies of addl fees due for review of 811216 amend application to transfer ownership shares in facility MILLER, W O License Fee Management Branch 82/07/28 TALLMAN, W C, Public Service Co. of New Hampshire. Ip 14220.348 24X Fiche 50-443, 82/07/28, 8208040565
- 8208020071 Forwards R Borcherdt 820721 ltr in response to FOIA request re 820109 Miramichi sarthqueke in New Brunswick, Canada NRC requested util to investigate earthqueke & forward info. Open-file rept describing aftershock data encl
 KINQ, J Geosciences Branch 82/07/30 NRC No Detailed Affiliation Given 7pp 14/44 117 24X Fiche 50-443,82/07/30,8208020071
- 8208050408 Forwards revised response to Containment Sys Branch 820301 request for add1 info Comparsion for worst case LOCA of containment pressure & temp response using mass & snergy release data provided DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/08/03, MIRAGLIAIF, J Operating Reactors Branch 3 4pp 14217.345, 24% Fiche-50-443,82/08/03,8208050408
- B208090174 Generic Ltr B2-i4 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Byc list encl EISENHUT. D O Division of Licensing. 82/08/09 Consolidated Edison Co of New York 1p. 14356 332. 24X Fichs B0-000,82/08/09,82/08/0174
- 8208110102 Submits revised estimate of annual radiation dose to Unit 2 const personnel during operation of Unit 1. Revised FBAR Section 12.4 3 will be incorporated into Amend 45 DEVINCENTIS.J. Yankee Atomic Electric Co DEVINCENTIS.J. Public Service Co of New Hampshire. 82/08/09 MIRAQLIA.F.J. Licensing Branch 2 2pp. 14317 174 24X Fiche 50-443.82/08/09.8208110102
- 8208130297 Forwards summary of Instrumentation & Controls Bys Branch 820715 & 16 review meetings re design conformance w/THI action plan items BEVINCENTIS, J. Yantee Atomic Electric Go. DEVINCENTIS, J. Fublic Service Co. of New Hampshire 82/08/10 MIRAGLIA, J.F. Licensing Branch 3. 49pp. 14337 092. 24X Ficher 50-443,82/08/10,8208130297.
- 8208170323 Forwards followup documentation from Structural Engineering Branch design audit re Action Item 13 Load Combinations used in design are in accordance w/8RP DEVINCENTIS.J. Yankee Atomic Electric Co. DEVINCENTIS.J. Public Service Co. of New Hampshire B2/08/12 MIRAQLIA.F J. Licensing Branch S. 3pp 14366-939. 24X Fichs: 50-443.82/08/12.8208170323.

- 8208190155 Forwards revised FSAR pages re seismic design basis of electrical receway cable tray sys Info will be incorporated into Amend 46 to FSAR DEVINCENTIS. J Yentee Atomic Electric Co DEVINCENTIS. J Public Bervice Co of New Hampshire 82/08/16 HIRAOLIA.F J Licensing Branch 3 3pp 14382 227 24X Fiche 50-443.82/08/16,8208190155.
- 8208190075 Forwards "Problem 4, Piping Benchmark Problems, NUREG/CR-1677, BNL-NUREG-51267, Vol 1 "
 DEVINCENTIS.J Yankse Atomic Electric Co DEVINCENTIS.J Public Bervice Co of New Hampshire 82/08/17 MIRAQLIA, F.J Licensing Branch 3 2pp 14382 249. 24X Fiche. 50-443, 82/08/17, 8208190075
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8207120047 Offers no comments on DEB Resources for which Natl Harine Fisheries Svc bears responsibility & alternatives to reduce adverse impacts on resources addressed satisfactorily in DEB REHFUS, R Commerce, Dept of, National Harine Fisheries Service 82/07/01 MIRAOLIA:F J. Licensing Branch 3 ip. 13811-147. 24X Fiche 50-443, 82/07/01, 8207120047
- 8208030731 Ack receipt of 820707 comments on facility DES & offer of assistance in responding to comments re NPDES. Cooperation & assistance appreciated MIRAOLIA.F.J Licensing Branch 3 82/07/21. LANDRY, T, Environmental Protection Agency 1p 14198 317, 24% Fiche 50-443, 82/07/21, 8208030731
- 8208090323 Forwards comments from federal, state & local govt agencies & public on DEB for review W/o enci MIRAGLIA.F J. Licensing Branch 3 82/07/30 TALLMAN, W C Public Bervice Co. of New Hampshire 2pg 14307:334, 24X Fiche: 50-442, 82/07/30, 8208090323
- 8208100154 Contests statement in DES that 345 kV transmission lines will have no adverse affect on health of humans or plant & animal life Research citing negative affects of OH-HV lines noted Objectivity of ODE & EPRI research questioned.

 GOLDSTEIN,C H. Affiliation Unknown, 82708/04, Division of Licensing App 14297:211 24X Fiche: 50-443, 82/08/04, 8208100154
- 9208160036 Requests inclusion of State of N4 820630 comments on DES in record of comments received Comments unitted from NRC 820730 ltr KINDER, E.T. New Hampshire, State of. 82/08/10 MIRAQLIA, F. U. Licensing Branch S. ip 14344 261 24X Fiche 50-443, 82/08/10, 8208160036.
- 8208300142 Forwards response to 820730 ltr re comments on NUREQ-0895, DEB for facility Concentrations of chloring & browing residuals will be minimal & should not add to concentrations in ays of marine organisms
 DEVINCENTIBL J Public Bervice Co of New Hampshire. 82/08/24
 MIRAOLIA, F J Licensing Branch 3. 6pp 14678, 214, 24X
 Tiche, 50-443, 82/08/24, 8208300142
 - #8310189 Forwards response to NRC Jul 1982 comments on DES re reliminary draft NPDES permit. LLG:8 F. Environmental Protection Agency 82/08/25, MIRAQLIA.F J Licensing Branch 3 App. 14489:282. 24X Fiche:50-443,82/08/25, 8208310189
- NRC Safety Evaluation Report (SER), supple & correspondence
- 8208270608 Forwards partial draft SER.list of open items in SER sections & status of review for remainder of SER.Assignment of authorized representative to participate in resolution of open items requested.

 NOVAK.T M. Assistant Director for Licensing 82/08/13, TALLMAN.H C. Public Service Co of New Hampshire. 300pp. 14680.118. 24X Fiche: 30-443.82/08/13,8208270608
- F Becurity, medical, emergency & fire protection plans
- 8208040256 Releases public version of revisions to radiological amergency plan.
 FELTON, J M Division of Rules and Records. 82/07/20. Document Management Branch. 1p 14225.001 24X Fiche: 50-443, 82/07/20. 8208040256.
- --S208040261 Forwards public version of detailed radiological emergency plan revisions which ref 820309 request for add1 info & radiological emergency plan annotated pages.

 DEVINCENTIB. J. Yankes Atomic Electric Co. DEVINCENTIB, J. Public Service Co. of New Hampshire 82/07/09. MIRAQLIA: F. J. Licensing Branch 3. 130pp. 14225.002 24X Fiche 50-443.82/07/20, 8208040256.

- 8208060303 Forwards revised pages to fire protection program evaluation submitted 820401, Two redundant automatic deluge sys installed in each fuel oil storage tank area DEWINCENTIS. J. Public Service Co. of New Hampshire 82/07/28 MIRACLIA.F. J. Licensing Branch 3 1p 14239 353 24X Fiche. 50-443. 82/07/28. 8208060303
- --8208040305 Revised pages to fire protection program evaluation & comparison to Branch Technical Position APC889 5-1 App A, Revision 1

 * Public Service Co of New Hampshire 82/07/28 4pp 14239 354 24X Fiche 50-443,82/07/28,8208060303
- 8208040478 Requests response to enci comments on 820628 physical security & guard training & qualification plans Response in form of revised pages requested within 30 days of receipt of ltr MIRROLIA, FJ Licensing Branch 3 82/07/30 TALLMAN, H C Public Bervice Co. of New Hampshire 3pp 14220 306 24X Fichs 50-443, 82/07/30, 8208040478
- 8208130328 Informs that Hampton Falls & Hampton have not been contacted re evacuation planning Suit presently in NH Supreme Court PEVZARR C New Hampehire, State of 82/08/07 ROBERTS.T Commissioners. 1p 14378-270 24X Fiche 50-443,82/08/07,8208180328
- O Adjudicatory correspondence
- 8208060126 Reply to Boc for Protection of Environ of Southeastern NH supplemental petition to intervene Reworded Contention B should be excluded since res judicate prohibits litigation on trensmission lines Certificate of Svc encl DIGNAM. T 0 , GAD.R K. Public Bervice Co of New Hampshire DIGNAM.T. Q Ropes & Gray 82/08/02 Atomic Safety and Licensing Board Panel Spp 14238.318 24X Fiche.50-443.82/08/02,8208060126.
- 8208040135 Motion for leave to reply to Commonwealth of MA brief, New England Coalition on Nuclear Pollution filing on emergency planning & Boc for Protection of Environ supplemental petition Certificate of Svc and DIGNAM. T. O. OAD, R. K. Public Service Co. of New Hampshire DIGNAM. T. O. Ropes & Gray. 82/08/02 Abomic Safety and Licensing Board Panel 4pp 14241:271 24X Fiche 50-443, 82/08/02, 8208060135.
- 8208060137 Reply to New England Coelition on Nuclear Pollution supplemental filing on emergency planning contentions Only Contentions 2.6:11 & 12 meet 10CFR2 714 requirements Certificate of Buc encl DIONAN, T O, CAD, R.K. Public Service Co. of New Hampshire DIONAN, T O, Ropes & Oray 82/08/02 Atomic Bafety and Licensing Board Panel. 12pp 1424; 23B 24X Fiche: 50-443, 82/08/02, 8208060137
- 8208060131 Reply to Commonwealth of MA brief in support of contentions Contentions fail to meet NRC requirements & should be excluded Certificate of Bvc encl DIONAN.T.O., OAD.R K Public Service Co of New Hampshire. DIONAN.T O Ropes & Gray. 82/08/02 Abomic Bafety and Licensing Board Pamel. 19pp 14239 281 24X Fiche 50-443,82/08/02,8208060131.
- 8208180112 Comments on recent tour of facility Work of Costello.
 Lomasney & deNapoli re radiological response planning
 inadequate & incomplate. Util optimism on Unit 2 unfounded
 DAIONEAULT, M. Swacoast Anti-Pollution League. 82/08/09 RDBERTS, T
 Commissioners ip. 14379 260 24X Fiche 50-443, 82/08/09.
 8208180112.
- 8208160150 Motion for leave to file response to applicant reply to Commonwealth of MA brief supporting Commonwealth contentions. Contentions should be consolidated into one emergency planning contention W/Certificate of Svc SHOTWELL-U.A Massachusetts, State of 82/08/10 Atomic Safety and Licensing Board Famel 4pp. 14345-131 24X Fiche. 30-443, 82/08/10, 8208160150.
- 8208160230 Responds to applicant 820802 reply to Commonwealth of MA brief supporting Commonwealth Contentions 2.3 & 4. Contentions state litigable issues firmly based on Commission regulations Certificate of Sev encl. SHOTHELL.J A. Massachusetts, State of, 82/08/10, Atomic Safety and Licensing Board Panel 9pp, 14347-114, 24X Fiche-50-443, 82/08/10, 8208160230
- 8208120010 Notifies that J Daughty added to syc list in response to 820723 request.
 LESBY,R.P. Hearings Division 82/08/11 BACKUS,R.A. Backus, R.A. 1p. 14323:336, 24% Fiche. 30-443.82/08/11.8208120010

- 8208250296 Forwards ALAB-687 due to substantial discussion at second special prehearing conference on admissibility of emergency planning contentions ASLB cannot conditionally admit contentions for any reason LESSY, R.P. Hearing Branch 3 82/08/23 HOYT, H. LUEBKE, E.A., PARISO H. Atomic Safety and Licensing Board Panel 2pp 14542 218 24X Fiche 50-443,82/08/23,8208250296.
- 8208250340 Informs that Commission declined review of Director's Decision 82-8 Time within which Commission may act to review expired Decision became final agency action on 820820 CHILK.8 J Office of the Secretary of the Commission 82/08/23 84/08/23, 8208250340
- G Inspection reports. IE Bulletins & correspondence
- B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV)
 Leshags " Svr list enc!
 JORDANIC L Division of Engineering & Quality Assurance B2/07/16
 Consolidated Edison Co of New York B7pp 14356 274 24X
 Fiche 50-000.82/07/16.8204210393
- 8208020166 Forwards IE Insp Repts 50-443/82-07 & 50-444/82-07 on S20614-17 No noncompliance noted HARTIN.T T Division of Engineering & Technical Programs 82/07/19. TALLMAN.H C Public Service Co of New Hampshire 2pp 14141:009. 24X Fiche 50-443,82/07/19.8208020166
- --8208020170 IE insp Repts 50-443/82-07 & 50-444/82-07 on 820614-17 No nancompliance noted Hajor areas inspected procedures & work activities reconcrete const of primary containment bldg exterior wall & dome & observation of structural fill VARELA, A., DURR, J.P. Division of Engineering & Technical Programs. 82/07/14 7pp 14141 011 24X Fiche 50-443,82/07/19,8208020166
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Syc list encl JORDAN: EL Division of Engineering & Quality Assurance 82/07/20 Consolidates Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- B204210397 IE Info Notice 82-24. "Water Leaking From U Herafluoride Byerpacks" Syc list encl COBB.L 1. Division of Fuel Facilities, Materials & Safeguards B2707/20. Consolidated Edison Co of New York 71pp 14357 276 244 Fichs 50-000.82/07/20.8204210397
- B204210398 IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/22 Consolidated Edison Co of New York 112pp 14174 321, 24X Fi
- B20421040: IE Info Notice B2-28. "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN-E L. Division of Engineering & Quality Assurance Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401
- B2042:0402 IE Info Notice B2-29, "Control Rod Drive (CRD) Quide Tube Symport Pin Failures at Westinghouse PMRs " Byo list encl JORDAM: E L. Division of Engineering & Quality Assurance B2/07/23 Consolidate Edison Co of New York 127pp 14194 120 24X Fiche: 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PMR Power Plants " Svc list enci.

 JORDAN, E L. Division of Engineering & Quality Assurance 82/07/26
 Consolidated Edison Co. of New York 121pp 14357:013 24X
 Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl UDRDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidate & Edison Co of New York. 122pp. 14357:146 24X Fichm 30-000,82/07/28.8204210405
- 8208020276 Ack receipt of 820719 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-449/82-04 & 50-444/82-04 Bivision of Project & Resident Programs 82/07/28 TALLMAN, W.C. Public Service Co of New Hampshire 1p. 14152 259 24X Fiche: 50-443,82/07/28,8208020276

- --8208020283 Responds to NRC 820708 ltr re violations noted in IE Insp Repts 50-443/82-04 & 50-444/82-04 Corrective actions installation contractor reinspected installed batteries, identified discrepant conditions & performed rework JOHNSON, W P Yankee Atomic Electric Co 82/07/19 STARDSTECKI, R Division of Project & Resident Programs 2pp 14152 260 24X Fichs 50-443, 82/07/28, 8208020276
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Nater-Jet Impingement" 8vc list encl
 JORDAN, E.L. Division of Engineering & Quality Assurence, 82/08/05
 Contailsdated Edison Co. of New York 117pp 14388 201 24X
 Fiche 50-000, 82/08/05, 8204210407
- 8 Reportable occurrences, LERs & related correspondence
- 8208200222 Final deficiency rept re insufficient development length in containment and bldg horizontal missile shields Initially reported on 820803 Deficiency corrected prior to placement of concrete As-constructed slabs meet design requirements DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 82/08/16 STAROSTECKI, R. Division of Project & Resident Programs 2pp 14399 346 24x Fiche 50-443, 82/08/16, 8208200222
- 8208260281 Final deficiency rept re nonseismically supported conduit.
 Initially reported 820723 Engineering change authorization
 issued to revise drawings to specify seismically qualified
 supports for conduits in refueling water storage tank area
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co. of New Hampshire 82/08/17, 81AROBYECKI, R Division of
 Project & Resident Programs 3pp 14554 272 24X
 Fiche. 50~443, 82/08/17, 8208260281
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA .UNIT 1

 A Application/construction stage documents & correspondence
- B207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of GP re Commission approved charter for CROR. Svc list encl.

 DIRCKS,W J Office of the Essentive Director for Operations

 B207702 Consolidated Edison Co of New York 93pp 14194 GO1

 24X Fiche 50-000.82/07/02,8207080064
- 8208170239 Forwards Amend 2 to application for OL per 10CFR50 33 Amend revises cover ltr, affidavit, Page 2 & Pages 33-35. QARY, R J Teras Utilities Generating Co. 82/07/06 DENTON, H R. Office of Nuclear Reactor Regulation, Director. 2pp 14368 315 24X Fiche 50-445,82/07/06,8208170239
- --8208170244 Amend 2 to application for OL revising cover itraffidavit, Page 2 & Pages 33-35
 H Texas Utilities Generating Co. 82/07/06. 5pp. 14968 317 24X
 Fichs 50-445,82/07/06.8208170237
- 8208090194 Owneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Syc list encl EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York Ip 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- 8208190164 Discusses addl programs implemented to complement QA program in verification of design const & operation of facility.

 QARY.R J Texas Utilities Cenerating Co 82/09/16 DENTON, H R.
 Office of Nuclear Reactor Regulation, Director 4pp 14382:223
 24X Fiche 50-445.82/08/16.8208190164
- 8208240219 Discusses 820612 commitment to gravide flood protection for safety chilled water chiller rooms. Flooding protection described in FSAR Amend 33 & Confirmatory Issue 13 in SER 2 SCHMIDT.H C Texas Utilities Bervices, Inc 82/09/19, BURWELL, 8 Office of Nuclear Reactor Regulation, Director in 14519-096, 24x Fiche, 50-445, 82/08/19, 8208240219
- 8208300119 Agrees to perform special calibr & environ qualification of containment high-range radiation monitors, per NUREG-0737. Item II F i SCHMIDT, H. C Texas Utilities Services, Inc 82/08/25, BURHELL, S B, Office of Nuclean Reactor Regulation, Director ip. 14599: 196. 24X Ficha 50-445.82/08/25,8208300119



G Adjudicatory correspondence

- 8208050463 Order for NRC to show cause why sanctions should not be imposed for NRC refusal to comply w/ASLB orders redisclosure of witness names & statements Identities necessary to evaluate credibility of witnesses MILLER, M & Atomic Safety and Licensing Board Panel 82/08/04 Office of the Executive Legal Director 10pp. 14216 315 24X Fiche 50-445,82/08/04,8208050463
- 8208090148 Order setting forth schedule for remaining hearings on Contention 5 & commencement of hearings on Contention 22 Discovery on Contention 22 to commence immediately MILLER, M E Atomic Bafety and Licensing Board Fanel 82/08/04 2pp 14271 323 24% Fiche 50-445.82/08/04.8208090148.
- 8208110162 Seventh set of interrogetories & request to produce Certificate of Svc and Related correspondence HORIN:W A Texas Utilities Generating Co. HORIN:W A Debevoise & Liberman 62/08/07 Citizens Association for Sound Energy 16pp 14314.208 24X Fiche 50-445.82/08/09.8208110162.
- 8208130142 Thirteenth set of interrogatories & request to produce Certificate of Svc encl Related correspondence ELLIS, J Citizens Association for Sound Energy 82/08/09 Texes Utilities Generating Co 3pp 14335/333 24x Ficher 50-445, 82/08/09, 8208130142
- 8208130212 Forwards twelfth set of interrogatories & request to produce Expedited answer requested Related correspondence ELLIS.J Citizens Association for Sound Energy 92/08/09. REYNOLDS,N S. Debevoise & Liberman. ip 14333 012 24X Fiche, 80-445, 82/08/09, 8208130212
- --B208130216 Twelfth set of interrogatories & request to produce.
 Certificate of Svc enc! Related correspondence
 ELLIS, J Citizens Association for Sound Energy. B2/08/09
 Texas Utilities Generating Co. 10pp 14333.013 24X
 Fiche 50-445,82/08/09,8208130212.
- 8208130173 Application for issuance of subpoena directing J Doyle to appear for B20817 deposition in Dallas.TX re pipe support computer calculations & pipe thermal growth. Certificate of Svc enci Related correspondence
 ELLIB.J Citizens Association for Sound Energy 82/08/10 Atomic Bafety and Licensing Board Panel. 3pp 14339.027. 24X
 Fiche: 50-445, 82/08/10, 8208130173
- 8208170149 Notion for protective order for D Stiner to prevent witness from being fired for testifying in OL proceedings Twelfth & thirteenth sets of interrogatories should be allowed Certificate of Svc encl. Related correspondence ELLIS.J. Citizens Association for Sound Energy 82/08/12 Atomic Safety and Licensing Board Panel 14pp. 14364 195 24X Fiche 50-445,82/08/12,8208170149.
- 8208170144 Answer in opposition to Citizens Assoc for Sound Energy (CASE) 820810 motion to subposes J Doyle CASE failed to show Doyle possesses info not available or presented by witness MA Walsh. Certificate of Svc encl.
 REYNOLOB.N S. HORIN. M. Texas Utilities Generating Co REYNOLOB.N S. Debavoise & Liberman. 82/08/13 Atomic Safety and Licensing Soard Panel 9pp. 14366 135. 24X Fichs 50-445,82/08/13,8208170144
- 8208240185 Notice of J Doyle 820819 deposition in Dallas.TX re Contention 5 on GA/GC during const activities.Related correspondence ELLIS.J. Citizens Association for Sound Energy. 82/08/16 2pp. 14519 320 24X Fiche 50-445
- --8208240187 Subgreen directing J Dayle to appear on 820819 in Dallas,TX for deposition.
 MILLER,M.E Atomic Safety and Licensing Board Panel 82/08/12 DDYLE,J. Affiliation Unknown. Spp. 14519:322 24X Ficher 50-445,82/08/16,8208240185.
- 8208240346 Motion to allow add1 discovery on Contention 5 & request for ASLB order to compel applicant to produce documents, per Citizens Assoc for Bound Energy 820809 twelfth & thirteenth sets of interrogatories W/Certificate of 8vc. ELLIS, J. Citizens Association for Bound Energy 82/08/17 Atomic 8afety and Licensing Beard Panel. 10pp. 14520 306 24X Fiche: 50-445,82/08/17,8208240346,
- 8208240231 Responds to 820804 fourth set of interrogatories & requests to produce Certificate of Syc encl.Related correspondence ELLIB, J Citizens Association for Bound Energy 62/08/18 Texas Utilities Generating Co. Spp. 14519:139, 24X Fiche: 50-445, 82/08/18, 8208240231

- B20B240373 Forwards original certification for Citizens Assoc for Sound Energy answers to applicant B20B04 fourth set of interrogatories & requests to produce Related correspondence ELLIS, J Citizens Association for Sound Energy 82/08/18 Docketing & Bervices Branch ip 14522 334 24X Fiche 50-445, 82/08/18, 8208240373
- --8208240378 Original certification for Citizens Assoc for Bound Energy answers to applicant 820804 fourth set of interrogatories & requests to produce ELLIS, J Citizens Association for Sound Energy 82/08/18 Texas Utilities Generating Co ip 14522 335 24X Fiche 50-445,82/08/18,8208240373
- 8208270441 Notice of GK Krishnen 820820 deposition in Dallas,TX re GA/GC control during facility const activities Certificate of Bvc encl Related correspondence ELLIB, J Citizens Association for Sound Energy 82/08/19 4pp 14566 108 24X Fichs 50-445,82/08/19,8208270441
- 8208270444 Notice of JC Finneran 820820 deposition in Dallas.TX re QA/QC control during facility const activities Certificate of 8vc encl Related correspondence ELLIS.J Citizens Association for Sound Energy 82/08/19 4pp 14556.112 24X Fiche 50-445.82/08/19.8208270444
- 8208270445 Forwards & Echepple, JC Finneran, 0 Krishnan & PSY Chang notices of deposition. Notice of KL Schepple deposition only ancl. Related correspondence ELLIS, J Citizens Association for Bound Energy 82/08/19, MILLER, M E. MCCOLLOM, K A. COLE, R. Atomic Safety and Licensing Board Panel 1p 14565-356 24X Fiche 50-445, 92/08/19, 8208270445,
- --8208270447 Notice of KL Schepple deposition on 820820 in Dallas, TX re Contention 5 on GA/GC control during const activities Certificate of 8vc encl Related correspondence ELLIB.J. Citizens Association for Sound Energy 82/08/19 App. 14365-357 24X Fiche 50-445, 82/08/19,8208270445
- B20B270452 Provides cites re Citizens Assoc for Sound Energy motion for protective order to protect D Stiner from discrimination, haraesment & possible job loss Certificate of Svc encl. Related correspondence ELLIG, J Citizens Association for Bound Energy B2/08/19 MILLER, M E , MCCOLLOM, K A , COLE, R Atomic Safety and Licensing Board Panel 2pp 14565, 263 24X Fiche, 50-445, 82/08/19, 8208270452.
- 8208270624 Notice of SY Chang 820820 deposition in Dallas, TX re GA/00 control during facility const activities Certificate of Svc encl Related correspondence ELLIB, J Citizens Association for Sound Energy 82/08/19 4pp 14366 037 24X Fiche, 50-445, 82/08/19, 8208270624
- 8208240418 Advises of scheduling change Hearings will not be held during wk of 820924 due to unanticipated events. MILLER M E Atomic Bafaty and Licensing Board Panel, 82/09/20, Office of the Executive Legal Director 1p 14523 358, 24X Fiche 50~445,82/08/20,8208240418.
- 8208270419 Notice of RD Bmith 820823 deposition in Dallas,TX re GA/GC control during facility const activities. Certificate of Evc encl. Related correspondence.

 ELLIS, J. Citicens Association for Sound Energy. 82/08/20. 3pp 14565:027. 24X Fiche: 50-445,82/08/20,8208270419
- 8208270435 Notice of RQ Tolson 820823 deposition in Dallas,TX re GA/GC control during const activities Certificate of 8vc encl Related correspondence ELLIB. J. Citizens Association for Bound Energy 82/08/20, 3pp. 14566 0
- B20B270437 Notice of GR Purdy B20B23 deposition in Dallas,TX re GA/GC control during facility const activities Cartificate of Bvc enci Related correspondence ELLIB, J Citizens Association for Bound Energy 92/08/20. 3pp 14566: 102 24X Fiche. 50-445.82/08/20.820B270437
- 8208270440 Notice of CT Brandt 820823 deposition in Dallas,TX re QA/90 control during facility const activities Certificate of 8vc encl Related correspondence.
 ELLIG.J. Citizens Association for Sound Energy. 82/08/20 3pp 14366 105. 24X Fiche 50-445,82/08/20,8208270440
- 8208270449 Motion for subposes directing HA Stiner to appear at 820913 hearings. Certificate of 8vc encl. Related correspondence, ELLIS.J. Citizens Association for Sound Energy. 82708/20 Atomic Safety and Licensing Board Fanel 4pp. 14565-258. 24X Fiche. 50-445, 82/08/20, 8208270443

- 8208250333 Response to 820820 twelfth & thirteenth sats of Interrogatories Certificate of Svc encl ReyNOLDS, N S. MORIN, M A. Texas Utilities Generating Co. REYNOLDS, N S. Debevoise & Liberman 82/08/23 Citizens Association for Sound Energy 8pp 14540 255 24X Fiche 50-445,82/08/23,8208250333
- 8208270453 Forwards answers to util seventh set of interrogatories & requests to produce & original deposition Related correspondence ELLIB.J Citizens Association for Sound Energy 82/08/23 Docketing & Bervices Branch 1p1 14566 122 24X Fiche 50-445, 82/08/23, 8208270453
- --8208270456 Answers to seventh set of interrogatories & requests to produce Certificate of Svc & original deposition encl. Related correspondence ELLIB.J. Gittrens Association for Sound Energy 82/08/23 Years Vtilities Generating Co 12pp 14566 123 24X Fiche 50-445,82/08/23.8208270453
- 8208270464 Forwards original verification for applicant 820823 responses to Citizens Assoc for Sound Energy twelfth & thirteenth sets of interrogatories HORIN.W A Debevoise & Liberman HORIN.W A Texas Utilities Generating Co 82/08/24 STUGKY.S Docketing & Services Branch 1p 14364 035 24X Fiche 50-445.82/08/24.8208270464.
- ~-8209270476 Original verification for 820923 responses to twelfth & thirteenth set of interrogatories

 BCMMIDT.H C Texas Utilities Generating Co 82/08/24 Citizen:
 Association for Sound Energy 1p 14564 036 24X

 Fiche 30-445,82/08/24,8208270464
- 8208310081 Contends that Dept of Labor disclosure of informant statements & entrance of statements into Dept of Labor hearings does not change NRC position that identities should not be disclosed
 TURK, 8 E Hearing Branch i 82/08/27 MILLER, M E., GDLE, R, MCCGLLOM, K A Atomic Safety and Licensing Board Panel 3pp. 14689, 297 24X Fiche 30-445.82/08/27,8208310081
- % Utility Final Bafety Analysis Report (FBAR) & amends
- 8208030271 Forwards Affidavit of 8vc of Amend 33 to F8AR, in accordance w/10CFR2 101(a)
 8CMIDT.H C. Texas Utilities Services, Inc 82/07/26 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 14158 146 24X Fiche: 50-445,82/07/26,8208030271
- 8208310356 Forwards Affidavit of Svc of Amend 34 to FSAR SCHNIDT.H.C Texas Utilities Services, Inc 82/08/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4p 14692 131 24X Fishe 50-445, 82/08/20, 8208310356
- G Inspection reports: IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leatage." Syc list encl. JORDAN,E L. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co. of New York, 87pp. 14356:274, 24X Fiche 50-000, 82/07/16,8204210393
- 8204210395 IE Info Notice 81-26.Pert 3. Suppl 1. "Clarification of Placement of Personnel Honitoring Devices for External Rediation." Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance, 82/07/19, Hichigan, Univ pf. 112pp 14358:001 24X Fiche: 50-000, 82/07/19, 8204210395.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Graduel Loss of Air Freesure " Syc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/20. Consolidated Edison Co. of New York 112pp 14381:001 24X Fiche: 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Syc list encl COBB.L I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co of New York. 7ipp 14357:276. 24X Fiche 50-000.82/07/20.8204210397.
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co of New York, 112pp 14194-321. 24X Fiche: 50-000: 82/07/22: 8204210398.

- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Wastinghouse PWRs " Evo list encl JORDAN; E.L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Luss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8208100022 Forwards IE Insp Rept 50-445/82-12 on 820601-30 No noncompliance noted. MADBEN G L Division of Resident, Reactor Project & Engineering Programs 82/07/26. OARY, R J Texas Utilities Generating Co 2pp. 14294 O16. 24X Fiche 50-449,82/07/26.8208100022
- --8208100028 IE Insp Rept 50-445/82-12 on 820601-30 No noncompliance noted Hajor areas inspected plant tours & praparational test procedure review KELLY, D L. WESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs 82/07/21 4pp 14294-018 24X Fiche 50-445,82/07/26,9208100022
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance. 92/07/28 Consolidated Edison Co of New York. 122pp 14357 146, 24% Fichs 50-000, 82/07/28, 8204210405.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl.
 JORDAN,E L. Division of Engineering & Guality Assurance 82/08/05.
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000,82/08/05.8204210407
- 8208310295 Ack receipt of 820802 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-445/82-11 Further response re other safety-related work performed w/o GC insp requested within 30 days.

 MADSEN.G.L. Division of Resident, Reactor Project & Engineering Programs 82/08/26, GARY,R.J. Texas Utilities Generating Co ip 14693:092 24X Fiche: 50-445, 82/08/26, 8208310295.
- --8208310278 Responds to NRC 820707 ltr re violations noted in IE Insp Rept 50-445/82-11 Corrective actions shims will be replaced w/matl verified & documented by GC & procedures established to assure GC installation interface OARY.R.J Texas Utilities Generating CO 82/08/02. MADBEN.0 L Division of Resident, Reactor Project & Engineering Programs 3pp 14673:073 24X Fiche: 50-445, 82/08/26, 82 08310275.
- 8 Reportable occurrences, LERs & related correspondence
- 8208160269 Interim deficiency rept re diesel generator auxiliary skid Infitially reported on 820709 Evaluation continuing Final rept expected by 821018 GARY, R J Teras Utilities Generating Co. 82/08/04 MADSEN, 9. L Division of Resident, Reactor Project & Engineering Programs ip 14347.042. 24% Ficha 30-445, 82/08/04, 8208160269.
- T Hearing transcripts on non-antitrust matters
- 8208020371 Transcript of 820728 hearing in Fort Worth TX Pp 2, 707-3, 035. • Atomic Safety and Licensing Board Panel 82/07/28 359pp. 14148, 227. 24% Fiche, 30-445, 82/07/28, 8208020371
- 8208020154 Transcript of 820729 hearing in Fort Worth, TX Pp 3, 036-3, 341. • Atomic Safety and Licensing Board Panel. 82/07/29. 307pp. 14144:152. 24X Fiche: 50-445, 82/07/29, 8208020194.
- 8208030555 Transcript of 820730 hearing in Fort Worth, TX. Pp 3.342-3.563 * Atomic Safety and Licensing Board Penel. 82/07/30 223pp. 14161:158 24X Fiche: 50-445, 82/07/30, 8208030555.

- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 2

 A Application/construction stage documents & correspondence
- 9207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR SVC list encl
 DIRCKS:W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 OOt
 24X Fichs 50~000, 82/07/02, 8207080064
- 820B170239 Forwards Amend 2 to application for DL per 10CFRSO 33 Amend revises cover ltr.affidavit.Page 2 & Pages 33-35 ORRY.R J Texas Utilities Concrating Co. 82/07/06 DENTON, H R Office of Nuclear Reaction Regulation
- --8208170244 Amend 2 to application for UL, revising cover ltr. affidavit, Page 2 & Pages 33-35 * Tales Utilities Generating Co 82/07/06 Spp 14368 317 24X Fiche 30-445,82/07/06/8208170239
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants rs submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svo list encl EISENHUT.D 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Ficha 50-000,82/08/09, 8208090194
- 8208190164 Discusses addl programs implemented to complement OA program in verification of design, const & operation of facility GARY.R J Texas Utilities Generating Co 82/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director App 14382 223 24X Fithe 80-445,82/08/16,8708190164
- 8208240219 Discusses B20512 commitment to provide flood protection for safety chilled water chiller rooms Flooding protection described in FSRA Amend 33 & Confirmatory Issue 13 in SER 2 SCHMIDT.H C Texas Utilities Services. Inc 82/08/19 BURWELL, 8 Defice of Nuclear Reactor Regulation. Director Ip 14519 096 24X Fiche 50-445, 82/08/19,8208240219
- B208300117 Agrees to perform special calibr & environ qualification of containment high-range radiation monitors, per NUREO-0737, Item II F I SCHMIDT, H C Teras Utilities Services, Inc 82/08/25 BURWELL. S B Office of Nuclear Reactor Regulation, Director. Ip 14599 196 24X Fichs 50-445,82/08/25,8208300119
-) Adjudicatory correspondence
- 8208050463 Order for NRC to show cause why sanctions should not be imposed for NRC refusal to comply w/ASLB orders redisclosure of witness names a statements identities necessary to evaluate credibility of witnesses MILLER.ME Atomic Safety and Licensing Board Panel 82/08/04 Office of the Executive Legal Director 10pp 14216 315 24X Fiche 50-445, 82/08/04, 8208050463
- \$208090148 Order setting forth schedule for remaining hearings on Contention 5 & commencement of hearings on Contention 22 Oiscovery on Contention 22 to commence immediately MILLER, M E Atomic Safety and Licensing Board Panel 82/08/06 2pp 14271 323 24X Fiche 30-445,82/08/06,8208090148
- #3208110162 Seventh set of interrogatories & request to produce Certificate of Svc encl Related correspondence HORIN: H A Texas Utilities Cenerating Co. HORIN: H A Debevoise & Liberman 82/08/09. Citizens Association for Sound Energy 16p; 14314 208 24X Fiche 50-445.82/08/09.8208110162
- 23/208130142 Thirteenth set of interrogatories & request to produce Certificate of Svc encl Related correspondence ELLIS.J Citizens Association for Sound Energy 82/08/09 Texas Utilities Generating Co 3pp. 14335-333 24X Fichs 50-445, 82/08/09, 8208130142
- 83208130212 forwards twalfth set of interrogatories & request to produce Espedited ansuer requested Related correspondence ELLIS. J Citizens Association for Sound Energy 82/09/09 REYNOLDS, N S Debevoice & Liberman ip 14333.012 24X Fiche 50-445, 82/08/09.8208130212
- ---9208130216 Twelfth set of interrogatories & request to produce.

 Certificate of Svc encl.Related correspondence
 ELLIS.J Citizens Association for Sound Energy.

 Texas Uffilities Generating Co 10pp 14333 013 24x

 Fiche 50-445,82/08/09,8208130212.

- 8208130173 Application for issuance of subposna directing J Doyle to appear for 820819 deposition in Dallas,TX repipe support computer calculations & pipe thermal growth Certificate of Svc encl Related correspondence ELLIS,J Citizens Association for Sound Energy 82/08/10 Atca.-Safety and Licensing Board Panel 3pp 14337 027 24X Fichs 50-445,82/08/10,8208130173
- 8208170149 Motion for protective order for D Stiner to prevent witress from being fired for testifying in OL proceedings Twelfth & thirteenth sets of interrogatories should be allowed Certificate of Suc encl Related correspondence ELLIS. J Citizens Association for Bound Energy 82/08/12 Attaic Safety and Licensing Board Panel 14pp 14364 175 24X Fiche 50-445, 82/08/12, 8208170149
- 8208170144 Answer in apposition to Citizens Assoc for Sound Energy (CASE) 820810 motion to subpoens J Doyle CASE failed to show Doyle possesses info not available or presented by witness MA Galsh Certificate of Syc encl
 REYNOLDS, N B. HORIN, H A Texas Utilities Cenerating Co
 REYNOLDS, N B. Bebevoise & Liberman 82/08/13 Atomic Safety and Licensing Board Panel 9pp 14366 135 24% Fiche SO-445.82/08/13
- 8208240185 Notice of J Doyle 820819 deposition in Dallas, TX re Contention 5 on GA/GC during const activities Related correspondence ELLIEJ Citizens Association for Sound Energy 82/08/16 2pp 14517 320 24X Fichs 50-445,82/08/16.8208240185
- --8208240187 Subpoena directing J Doyle to appear on 820819 in Dallas TI for deposition MILLER,ME Atomic Safety and Licensing Board Panel 82/08/12 DDYLE, J Affiliation Unknown Spp 14519 322 24X Fiche SO-445.82/08/16.8208240185
- 8208240346 Motion to allow additiscovery on Contention 5 & request for ASLS order to compel applicant to produce documents, per Citizens Assoc for Sound Energy 820809 twelfth & thirteenth sets of interrogatories W/Certificate of Svc ELLIG.J Citizens Association for Sound Energy 82/08/17 Atomic Safety and Licensing Board Panel 10pp 14520 306 24X fiche 50-445,82/08/17,8208240346
- 6208240231 Responds to 820804 fourth set of interrogatories & requests to produce Certificate of Svc encl Related correspondence ELLIG. J Citizens Association for Sound Energy 82/08/16 Texas Utilities Generating Co 8pp 14519 139 24X Fiche 50-445, 62/08/18,6208240231
- 8208240373 Forwards original certification for Citizens Assoc for Sound Energy answers to applicant 820804 fourth set of interrogatories & requests to produce Related correspondence ELLIB, J Citizens Association for Sound Energy 82/08/18 Docketing & Services Branch ip 14522 334 24X Fiche 30~445,82/08/18.8208240373
- --8208240378 Original certification for Citizens Assoc for Sound Energy answers to applicant 820804 fourth set of interrogatories & requests to produce ELLIS. J Citizens Association for Sound Energy 82/08/18 Texas Utilities Generating Co ip 14522 335 24% Fiche 50-445.82/08/18.8208240373
- 8208270441 Notice of GK Krishnan 820820 deposition in Dallas,TX re GA/GC control during facility const activities Certificate of Sve encl Related correspondence ELLIS.J Citizens Association for Sound Energy 82/08/19 4pp 14366 108 24X Fiche 50-445,82/08/19.8208270441
- 8208270444 Notice of JC Finneran 820820 deposition in Dallas,TX re QA/QC control during facility const activities Certificate of Svc encl Related correspondence ELLIB.J Cittigens Association for Sound Energy 82/08/19 4pp. 14566 112 24x Fiche 50-445,82/08/19,8208270444.
- B20B270448 Forwards KL Schepple, JC Finneran, O Krishnan & PSY Chang notices of deposition Notice of KL Schepple deposition only encl Related correspondence ELLIB, J Citizens Association for Sound Energy B2/0B/19 MILLER, M E , MCCOLLOM, K A , COLE, R Atomic Bafety and Licensing Board Panel ip 14565, 356 24X Fiche, 50-445, 82/08/19, 8208270445
- --8208270447 Notice of KL Schepple deposition on 820820 in Dalles.TX rg Contention 5 on OA/OC control during const activities Certificate of Svc encl.Related correspondence ELLES.J Gitizens Association for Sound Energy. 82/08/19 4pp 14365-357 24X Fiche 50-445,82/08/19,8208270445

- 8208270452 Provides cites re Citizens Assoc for Bound Energy motion for protective order to protect D Stiner from discrimination, harassment & possible job loss Certificate of Svc encl Related correspondence
 ELLIG.J Citizens Association for Bound Energy 82/08/19
 HILLER.M E . MCCOLLOM.K A . COLE.R Atomic Safety and Licensing Board Panel 2pp 14565 263 24X Fiche 50-445.82/08/19.8208270452
- 8208270624 Notice of 8Y Chang 820820 deposition in Dallas, TX re GA/GC control during facility const activities Certificate of 8vc encl Related correspondence ELLIS, J Citizens Association for Sound Energy 62/08/19 4pp 14566 037 24X Fiche 50~445,82/08/19,8208270624
- 8208240418 Advises of scheduling change Hearings will not be held during wk of 820924 due to unanticipated events HILLER, M E Atomic Bafety and Licensing Board Panel 82/08/20 Office of the Executive Legal Director 1p 14323 358 24X Fiche 50-445,82/08/20,8208240418
- 8208270419 Notice of RD Smith 820823 deposition in Dallas, TX re GA/QC control during facility const activities Certificate of Svc encl Related correspondence ELLIS, J Citizens Association for Sound Energy 82/08/20 3pp 14565 027 24X Fichs 50-445,82/08/20,8208270419
- 8208270435 Notice of RO Tolson 820823 deposition in Dalles, TX re QA/QC control during const activities Certificate of Svc encl.
 Related correspondence
 ELLISJ Citizens Association for Sound Energy. 82/08/20 3pp
 14566 099 24X Fichs 50-445,82/08/20,8208270435
- 8209270437 Notice of GR Purdy 820823 deposition in Dallas, TX re GA/GC control during facility const activities Certificate of Svc antl Related correspondence, ELLIB. J Citizens Association for Bound Energy 82/08/20 3pp 14364 102. 24X Fiche 50-445,82/08/20,8208270437.
- 820B270440 Notice of CT Brendt 820823 deposition in Dallas,TX re QA/QC control during facility const activities Certificate of Svc encl Related correspondence ELLIS,J Citizens Association for Sound Energy. 82/08/20 3pp. 14566 105 24X Fiche 50-445,82/08/20,8208270440.
- 8208270443 Motion for subposes directing HA Stiner to appear at B20913 hearings Certificate of Svc anci Related correspondence ELLIB.J Citizens Association for Sound Energy 82/08/20 Atomic Safety and Licensing Beard Panel 4pp 14545 258 24X Fiche 50-445,82/08/20,8208270443
- B208250333 Response to B20820 twelfth & thirteenth sats of interrogatories Certificate of Svc encl REYNOLDB.N 8., HURIN.W A Texas Utilities Generating Co REYNOLDB.N B Debevoise & Liberman B2/08/23. Citizens Association for Bound Energy Spp 14540 255. 24X Fiche 50-445.82/08/23.8208250333
- 8208270453 Forwards answers to util seventh set of interrogatories & requests to produce & original deposition Related correspondence ELLIS, J Citizens Association for Sound Energy 82/08/23 Bocketing & Services Branch. 1pl. 14566:122 24X Fiche: 50-445, 82/08/23, 8208270453.
- --B208270456 Answers to seventh set of interrogatories & requests to produce. Certificate of Syc & original deposition encl. Related correspondence ELLIS. J Citizens Association for Sound Energy B2/08/23 Texas Utilities Generating Co. 12pp. 14566 123. 24% Fiche. 50-445, 82/08/23, 8208270453
- B20B260022 Response to ABLB B20B04 order to show cause why sanctions should not be imposed for refusal to obey ABLB order redisclosure of informants Requests reconsiderations of order. Previous orders should be vacated.

 TURK B.E. Hearing Brench 1 62/08/24 Atomic Sefsty and Litensing Board Panel 24pp 14555.171. 24X Fiche.50-446.82/08/24, 8208260022
- --B208260030 Affidavit of JT Collins re importance of anonymity in gathering info from confidential sources Disclosure of identifies could cast doubt on Commission commitment to protect individuals who provids info COLLING.J.T Region 4, Office of Director. B2/08/24. App. 14555.195. 24% Fiche 50-444.82/08/24.8208260022.
- --B208260039 Affidavit of DD Driskill & RH Kerr Individuals objected to disclosure or confirmation of identities since disclosure could place present &/or future employment in jeopardy.Prof qualifications & Certificate of Svc encl.

 DRISKILL.D.D. HERRIR.K. Region 4. Office of Director. 82/08/24. 7pp 14555.199. 24X Fiche 30-446, 82/08/24.8208260022

- 8208270464 Forwards original verification for applicant 820823 responses to Citizens Assoc for Bound Energy twelfth & thirteenth sets of interrogatories HORIN, W.A. Debevoise & Liberman HORIN, W.A. Teras Utilities Generating Co. 82/08/24 STUCKY, S. Dockating & Services Branch 1p 14564 055 24X Fiche 50-445, 82/08/24, 8208270464
- --8208270476 Original verification for 820823 responses to twelfth & thirteenth set of interrogatories SCHMIDT-H,C Texas Utilities Generating Co 82/08/24 Citizens Association for Bound Energy 1p 14564 056 24X Fiche 50-445,82/08/24,8208270464
- 8208310081 Contends that Dept of Labor disclosure of informant statements Δ entrance of statements into Dept of Labor hearings does not change NRC position that identities should not be disclosed. TURK S.E. Hearing Branch 1 82/08/27 MILLER M.E., COLE, R., MCCOLLOH, K.A. Atomic Safety and Licensing Board Panel 3pp 14687 297. 24X Fichs 30-445, 82/08/27, 8208310081
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8208030271 Forwards Affidavit of Byc of Amend 33 to FSAR, in accordance w/100FR2 [01(a) SCHMIDT, H C Texas Utilities Services. Inc 82/07/26 DENTON, H R Office of Nuclear Reactor Regulation. Director, 4pp. 14158, 146 24X Fichs 50-445,82/07/26,8208030271
- 8208310356 Forwards Affidavit of Evc of Amend 34 to FSAR SCHMIDT.H.C. Texas Utilities Services, Inc. 82/08/20, DENTON.H R Office of Nuclear Reactor Regulation, Director 4p 14692 131 24X Fiche 30-445.82/08/20.8208310335
- Q. Inspection reports: IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl JORDÁN E. L Dívision of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York. 87pp. 14356 274, 24X Fiche 80-000 82/07/16.8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Parsonnel Monitoring Devices for External Radiation," Svc list encl.

 JORDAN, E. Division of Engineering & Quality Assurance 82/07/19

 Michigan, Univ of 112pp, 14358 001, 24X Fiche 50-000, 82/07/19, 8204210395.
- 8204210396 IE Info Notice 82-25, "Feilures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JURDAN, E L Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York 112pp. 14381 001. 24X Fiche. 90-000, 82/07/20, 8204210396
- 8204210397 IE info Notice 82-24, "Water Leaking From U Herafluoride Overpacks." Syr list enc! COBB.L 1 Division of Fuel Facilities, Materials & Gafeguards 82/07/20 Consolidated Edison Co. of New York. 71pp. 14357.276, 24X Fichs 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Syc list encl JORDAN E. L. Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co. of New York. 112pp 14194 321 24X Fiche: 50-000, 62/07/22, 8204210398.
- B204210401 IE Info Notice B2-28. "Hydrogen Explosion While Grinding in Vicinity of Dreined & Open RCB." Svc list encl, JORDAN, E. L. Division of Engineering & Quality Assurance Consolidated Edison Co. of New York. 122pp. 14380,115. 24X Fiche. 30-000. 82/07/23. 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quids Tube Support Pin Failures at Westinghouse PMRs." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/23 Gonsolidated Edison Co. of New York. 127pp 14194.120, 24X Fichs 50-000,82/07/23,8204210402.
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleaves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York. 121pp 14357:013, 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool." Syc list encl. JORDAN, E. L. Division of Engineering & Guality Assurance, 82/07/28 Consolidated Edison Co. of New York, 122pp, 14357:146 24X Ptche.30-000.82/07/28.8204210405.

- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " Svc list encl JURDAN,E L. Division of Engineering & Guality Assurance 82/08/05 Consolidated Ædison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8 Reportable occurrences, LERs & related correspondence
- 8208030210 Final deficiency rept re void in exterior wall of steam generator compertment Deficiency not reportable under 10CFR50 55e Records supporting determination available for GARY, R J Texas Utilities Generating Co 82/07/23 MADSEN, (Division of Resident, Reactor Project & Engineering Programs 14159 350 24X Fiche 50-446,82/07/23,8208030210 MADSEN, G L
- 8208160269 Interim deficiency rept re diesel generator auxiliary skid Initially reported on 820709 Evaluation continuing Final rept expected by 821018
 OARY, R. J. Teras Utilities Generating Co. 82/08/04 MADSEN, 9 L. Division of Resident, Reactor Project & Engineering Programs in 14347
- T Hearing transcripts on non-antitrust matters
- 8208020371 Transcript of 820728 hearing in Fort Worth,TX Pp 2,707-3,035
 - * Atomic Safety and Licensing Board Panel 82/ 14148 227. 24% Fiche 50-445, 82/07/28, 8208020371 B2/07/28 359ea
- 8208020154 Transcript of 820729 hearing in Fort Worth, TX Pp 3,036-3,341
 - * Atomic Safety and Licensing Board Panel 82/ 14144 152 24x Fiche 50-445,82/07/29,8208020154 82/07/29 307pp.
- 3208030555 Transcript of 820730 hearing in Fort Worth, TX Po 3.342-3,563 * Atomic Safety and Licensing Board Panel 92/9 14161 158 24% Fiche 50-449,82/07/30,8208030555 82/07/30 223pp
- DOCKET 6TN-50-447 GESSAR-238
- Application/construction stage documents & correspondence
- 3207120147 Forwards NEDO-21471-01. "Analytical Model for Estimating Drag Forces on Rigid Submerged Structures Caused by LOCA & Safety Relief Valve Ramshoad Air Discharges, Suppl for Valuestan Air Blockstone."
- 3207120253 "Analytical Model for Estimating Drag Forces of Rigid Submerged Structures Caused by LOCA & Bafety Relief Valve Ramshad Air Discharges, Suppl for X-Ouencher Air Discharges."

 LASHER, L. E., TOWNSEND, H. E., ROGER, A. E. Oeneral Electric Co. NEDO-21471-01 801 79/10/31 11pp 12808 002 24X

 Fiche 50-447,80/06/18.8207120147
- I208030355 Forwards application for Amend 5 to GESSAR II, providing addition to anviron qualification of safety-related aquipment, per NRC 811209 request SHERWOOD, 0 G. General Electric Co. 82/07/30 EISENHUT, D G Division of Licensing 2pp 14157 222 24X Fiche 50-447,82/07/30,8208030355
- -8208030359 Application for Amend 5 to 0E89AR II.providing addition of safety-related equipment, per NRC 811209 request SHERMODD, 0. Oeneral Electric Co 82/07/30 ip 14157 224 24X Fiche: 50-447,82/07/30,8208030355
- 208070174 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Symmatizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISEKNUT, D O Division of Licensing 82/08/07 Consolidated Edison Co. of New York ip 14356.332 24X Fiche 50-000, 82/08/09, 8208070194.
- Adjudicatory correspondence
- 208260022 Response to ASLB 820804 order to show cause why sanctions should not be imposed for refusal to obey ASLB order redisclosure of informants. Requests reconsiderations of order Previous orders should be vacated TURK. B.E. Hearing Branch I 82/08/24 Atomic Safety and Litensing Board Panel 24pp 14555:171. 24X Fiche 50-446,82/08/24,8208260022

- --8208260039 Affidavit of DD Driskill & RH Kerr Individuals objected to disclosure or confirmation of identities since disclosure could place present &/or future employment in jeopardy Prof qualifications & Certificate of Svc encl DRIGKILL, DD, HERR, K Region 4, Office of Director 82/08/24 7pp 14555 199 24X Fiche 50-446,82/08/24,8208260022
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8208030395 Forwards application for Amend 5 to GESSAR II, providing addition of environ qualification of safety-related equipment, per NRC 811207 request SHERHOOD.0 G General Electric Co 82/07/30 EISENHUT.D O Division of Licensing 2pp 14197 222 24X Fiche 50-447.82/07/30, 6208030395
- --8208030359 Application for Amend 5 to GESSAR II, providing addl info re environ qualification of safety-related equipment.per NRC Bil209 request SHERHOOD, O O preval Electric Co 82/07/30 ip 14157 224 24% Fiche 50-447, 82/07/30, 8208030355
- --8208030360 Amend 5 to GESSAR II * General Electric Co 82/07/30 Fiche 50-447,82/07/30,8208030355 82/07/30 239pp 14157 225 24X
- 8208030591 Forwards proprietary portion of Amend 5 to GEBSAR II resolvent qualification of safety-related equipment Affidavit requesting proprietary classification of info encl Amend 5 withheld (ref 100FR2 790)
 SHERMODO, 0 General Electric Co 62/07/30 EISENHUT, D G Division of Licensing 4pp 14162 290 24X Fiche 50-447, 82/07/30, 8208030581
- Q Inspection reports: IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN, Et Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395.
- DOCKET STN-50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licenses of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR 8vc list encl
 pIRCKS, W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000,82/07/02,8207080064
- 9208040484 Notification of 920727 meeting w/Westinghouse in Bethesda, MD to discuss Krsko water hanner event of Jul 1981 & applicability to domestic Westinghouse Type D steam generators CHESNUT.8 Licensing Branch 1 82/07/22 YOUNGBLOOD, B J Licensing Branch 1 3pp 14220 309 24X Fiche 50-454,82/07/22,
- 8208050193 Forwards summary of NRC 820721 meeting w/Westinghouse in Bethesda, MD re progress in resolving accelerated tube wear at operating plants w/Westinghouse Model D steam generators, since facilities will withize Models D-4 & D-5 YOUNOBLOOD, B J Licensing Branch 1 82/07/27 DELGEORGE, L O Commonwealth Edison Co 3pp 14242 124 24X Fiche 50-000, 82/07/8208050193 24X Fiche 30-000, 82/07/27,
- 8208130385 Notifies that criteria for essential svc water pipeline drilling operations as modified by 820723 telcon is acceptable Branch should be informed of drilling schedule in order to observe drilling operations & results.

 YOUNGBLOOD, B J Licensing Branch i 82/07/29 DELOEDROE, L Commonwealth Edison Co 2pp 14340, 269 24X Fiche 50-454, 82/07/29, 200813038
- 820Bi10243 Forwards request for add1 info re water hammer prevention par event at KRSKO reactor in Yugoslavia Test plan to verify that water hammer will not occur should be provided YOUNOBLOOD. B J. Licensing Branch 1 82/07/30 DELGEORGE, L D Commonwealth Edison Co. opp 14331.09E 24X Fiche 50-000,82/07/30,820Bi10243

- 8208(10188 Forwards revised pages to CE-1-A. "Comm Ed QA Program for Nuclear Generating Stations," Revision 21 Revised pages correct typographical & other minor errors SWARTZ-E Commonwealth Edison Co. 82/08/06 HAASS,W.P. Quality Assurance Branch ip (4314-079 24X Fiche 50-000,82/08/06.820810188)
- --8208110204 Revised pages to CE-1-A.Revision 21, "Comm Ed QA Program for Nuclear Generating Stations"

 # Commanusalth Edison Co 82/06/04 11pp 14314 080 24X
 Fishe 50-000, 82/08/06, 8208110168
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Svc list encl EIGENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14336 332 24X Fiche 50-000,82/08/09,8208090194
- 8208/70096 Forwards responses to FSAR questions re flexibility of baseplates for pipe supports Review of response to Questions 130 71 & 110 72 should close outstanding Item 5 of FSAR, TRANH, T R Commonwealth Edison Co 82/08/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 14358 217 24% Fiche 50-000, 82/08/09, 8208170096
- 8208130277 Forwards preliminary revision of Attachment CD & to Section 3 & of FSAR re main steamline break in main steam tunnel Info will be incorporated into next FSAR amend TRANS, TR Commonwealth Edison Co 82/08/10, DENTON, HR Office of Nuclear Reactor Regulation, Director 26pp 14333 077 24X Fiche 50-000,82/08/10,8208130277
- 8208230327 Forwards seismic & dynamic qualification summary & status of equipment important to facility safety, revising 820617 updates Util understands that NRC will examine several listed components during 820630-31 audit TRAMS, T.R. Commonwealth Edison Co. 82/08/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director 150pp 14509.001 24X Fiche 50-454, 82/08/10, 8208230327
- 8208;80026 Requests relief from specific ASME Section XI requirements for automated pressure vessel preservice exam Satis for relief encl NRC action on requests required by 820918 to support field activities TRAMS, TR Commonwealth Edison Co 82/08/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 15pp 14377, 155 24X Fiche 80-454, 82/08/11, 8208180026
- 8208230324 Forwards add1 info re installation of instrumentation for detection of inadequate core cooling Info correlated to Requirements 1-9 for NUREO-0737. Item II F. 2
 TRAPH.TR Commonwealth Edison Co 82/08/13 DENTON. HR Office of Nuclear Reactor Regulation. Director 4pp 14508 328. 24X
 Fiche 50-000.82/08/13.8208230324
- 820823005B Forwards addl info re status of various sys important to Human Factors Engineering Branch review of control rooms Sacond site visit can be scheduled for Feb 1983 or later, which should close out review TRAPH, T R Commonwealth Edison Co 82/08/16 DENTON, H. R Office of Nuclear Reactor Regulation, Director 3pp 14509 324 24x Fiche: 50-000, 82/08/16, 8208230058
- 8208230332 Forwards revised response to FBAR Question 022 54 indicating why power interruption is not practical in case of post-LOCA gurge sys isolation valve (170003) Response will be incorporated into next FBAR amend TRAMM.TR Commonwealth Edison Co 82/08/17. DENTON.H.R Office of Nuclear Reactor Regulation. Director 2pp 14508 258 24x Fiche 50-000.82/08/17.8208230332
- 8208270350 Forwards revised FSAR info re protection against possible turbing missiles at facilities Changes will be incorporated into future FBAR amend. Info closes Outstanding Item 2 of Byron SER TRAMK, T.R. Commonwealth Edison Co. 82/08/18 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 70pp. 14564 300 24X Fithe 30-000.82/08/18.8208270350.
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8208170219 Forwards responses to FSAR Questions 22 23 & 22.24, providing results of reanalysas of ECCS performance w/reduced temp of essential svc water to reactor containment fan cooler units SER Confirmatory Issue 19 closed.
 TRANNIT, R Commonwealth Edison Co. 82/08/06, DENTON, H, R of Nuclear Reactor Regulation, Director, App 14361:317 24% Fiche 50-000, 82/08/06, 8208170219.

- 8208180002 Forwards response to FSAR questions re vol reduction sys Info should close Outstanding Item 15 of Byron SER TRAMM, T R Commonwealth Edison Co 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 19pp 14376 215 24X Fiche 50-000, 82/08/06, 8208180002
- 8208170240 Forwards info to be included in FBAR re analyses of high t moderate energy pipe breaks NRC review of info should close outstanding Item 3 of Byron SER Revised response to Question 10 40 sncl TRAHM.T R Commonwealth Edison GO 82/08/10 DENTON, H R Office of fluctear Reactor Regulation, Director 15pp 14368 322 24X Fichs 50-000, 62/08/10, 8208170240
- 8208180011 Provides info re circuit change which will aid operator during switchover from ECCS injection to recirculation following LUCA Feature will provide control room indication of safety injection 8-Afgnal status
 TRAMMIT R Commonwealth Edison Co 82/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14378 285 24X Fiche 50-000, 82/08/11, 9208180011
- B20B230354 Forwards responses to FSAR Questions 010 59-010 57 re fire protection, requested in NRC 820715 ltr Info will be included in next FSAR amend Responses should close Outstanding Item 13 of Syron SER.

 TRANS, T.R. Commonwealth Edison Co. 82/08/17 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 11pp 14508 285 24X Fiche. 50-000, 82/08/17, B208230354
- 8208270350 Forwards revised FBAR info re protection against possible turbine missiles at facilities Changes will be incorporated into future FBAR amend Info closes Gutstanding Item 2 of Byron SER TRAMM, T R Commonwealth Edison Co 82/08/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 70pp 14564, 300, 24% Ficher 50-000, 82/08/18, 8208270350
- F Security, medical, emergency & fire protection plans
- 8208230559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
 FELTON, J H Division of Rules and Records 82/08/12 Document Management Branch 1p 14559 384 24X Piche 50-000.82/08/12, 8208230359.
- --8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 MDDRE,R D Commonwealth Edison Co. 82/07/19 DENTON,H R. NRC No Detailed Affiliation Given. 16 14559 355 24X Fiche 50-000,82/08/12.8208250359
- --8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
 Commonwealth Edison Co. 82/06/30 7pp 14559 356 24X Fiche 50-000,82/08/12.8208250559
- 8208190014 Forwards revised "Fire Protection Rept in Response to Branch Technical Position CMES 9.5.1." Revision incorporates safe shutdown analysis submitted in util 820614 ltm & updated comparison w/100FRSO App R
 TRANH.TR Commonwealth Edison Co 82/08/16 DENTON.H R
 Of Nuclear Reactor Repulation, Director 2pp 14383 214 24X
 Fichs 50-000, 82/08/16, 8208190014.
- --8208190018 Revised "Fire Protection Rept in Response to Branch Technical Postbion CHER 9 5.1 " • Commonwealth Edison Co 82/08/16, 700pp 14383 219 24X Fiche: 50-000,82/08/16,8208190014
- 8208230334 Forwards responses to FBAR Questions 010,55-010 59 rs fire protection, requested in NRC 820715 ltr Info will be included in next FBAR amend Responses should close Outstanding Item 13 of Byron 886.
 TRAMH.TR Commonwealth Edison Co 82/08/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 11pp 14508 285 24X Fiche 50-000, 82/08/17, 8208230354
- Q Adjudicatory correspondence
- 8208020256 Response opposing Rockford League of Women Voters petitions for waiver of or exception to NRC regulations Petitions fail to set forth justifying special circumstances Certificate of Sve encl.

 BIELAWSKI.A.P. Commonwealth Edison Co. BIELAWSKI.A.P. Isham. Lincoln & Beals 82/07/22. Atomic Sefety and Licensing Board Panel. 158pp 14152:058, 24% Fiche 50-454,82/07/22,8208020256.

- 8208030424 Motion for leave to file response to applicant 820719 answer supporting NRC motion for summary disposition of Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 9c Related correspondence CHAVEZ, D. Sinnissippi Alliance for the Environment (BAFE) 82/07/30 Atomic Safety and Licensing Board Panel 2pp 14154 092 24X Fiche 50-454, 82/07/30, 8208030424
- --8208030430 Response to applicant 820719 answer supporting NRC motion for summary disposition of Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 9c Only Items 1,2,7,11,12,15 & 17 admitted true CRAYEZ.D Sinnissippi Alliance for the Environment (SAFE) 82/07/30 Atomic Sefety and Licensing Board Panel 11pp 14154-094 24X Fiche 50-454,82/07/30.8208030424
- --B208030A35 Affidavit consisting of documents supporting response in apposition to NRC motion for summary disposition of Dekalb Area Alliance for Responsible Energy/Sinniss(ppi Alliance for Environ Contention 9c Certificate of Svc encl BUNCH/R Sinniss(ppi Alliance for the Environment (SAFE) 82/07/30 37pp 14154 105 24x Fiche: 50-454, 82/07/30, 8208030424
- 8208030426 Motion to suppl answer to util & NRC motions for summary disposition of Contentions 2 & 2a New relevant info unavailable when answer filed & only recently available to scientific community Related correspondence CHAVEZ, D DeKalb Area Alliance for Responsible Energy CHAVEZ, D, Sinnissippl Alliance for the Environment (8AFE) 82/07/30 Atomi Safety and Licensing 80ard Panel. 2pp 14163,107 24X Fiche 50-454,82/07/30,8208030426.
- --B2QB030437 Affidavit of EJ Sternglass Cumulative affects of radioactive release from reactors located in northern IL should be re-evaluated EPA min dose of radiation probably cannot be met for some local populations.

 BIERNOLASS, EJ Dekalb Area Alliance for Responsible Energy, BIERNOLASS, EJ Simmissippi Alliance for the Environment (SAFE) 82/07/19 14pp 14163 109 24X Fiche 50-454,82/07/30,8208030426.
- 8208040284 Reply to util & NRC 820722 & 24 responses, respectively, to Rockford League of Homen Voters 820704 petitions for waiver of or exception to regulations, excluding finencial qualifications, need for power & alternative energy issues HHICHER, J M. DeKalb Area Alliance for Responsible Energy HHICHER, J M. Sinnissippi Alliance for the Environment (SAFE) 82/07/30 Atomic Safety and Licensing Board Panel. 15pp 14190.254 R4X Fiche, 50-454, 82/07/30, 8208040284
- --B208040290 Petition for waiver of or exception to financial qualification regulations Special circumstances exists so that purpose of new NRC regulations excluding issue would not be served CASEL.D W DeKelb Area Allience for Responsible Energy CASSEL.D W Binnissippi Alliance for the Environment (SAFE) 82/07/30 Atomic Safety and Licensing Board Panel 14pp 14170 267 247 Fiche 50-454. 82/07/20.8208040284.
- --8208040294 Petition for waiver of or exception to need for power & alternative energy source regulations Special circumstances exist so that purpose of new NRC regulations excluding issues would not be served WHICHER.J. M DeKalb Area Alliance for Responsible Energy, WHICHER.J. M Sinnissippi Alliance for the Environment (BAFE) 82/07/30 Atomic Safety and Licensing Board Panel 9pp. 14190 283. 24X Fiche.50-454.82/07/30.8208040284
- --8208040279 Financial qualifications contention
 CASSEL,D W DeKalb Area Alliance for Responsible Energy
 CASSEL,D W Sinnissippi Alliance for the Environment (SAFE)
 B2/07/30 Atomic Safety and Licensing Board Panel 3pp
 14190:292 24X Fiche 30-454, 82/07/30,8208040284
- --8208040303 Need for power & alternative energy source contention.

 LHICHER.J.H. DeKelb Area Alliance for Responsible Energy
 LHICHER.J.H. Sinnissippi Alliance for the Environment (SAFE)
 82/07/30 Atomic Safety and Licensing Board Panel. 2pp.
 14190.295. 24X Fiche 50-454, 82/07/30,8208040284.
- --8208040308 Response to first request for production of documents refinancial qualifications, need for power & alternative energy sources.
 WHICHER.J M. Dekalb Area Alliance for Responsible Energy.
 HHICHER.J M. Sinnissippi Alliance for the Environment (SAFE).
 82/07/30 Office of the Executive Legal Director. 2pp
 14190.297 24X Fiche 50-454, 82/07/30,8208040284
- --B208040312 Response to first round of interrogatories re financial qualifications, need for power & alternative energy sources CHAVEZ, D Dekalb Area Alliance for Responsible Energy. CHAVEZ, D Sinnisatppi Alliance for the Environment (SAFE) B2/07/30 Commonwealth Edison Ca 4pp 14190 299 24X Fiche 50-454, 92/07/30, B208040284.

- --B208040316 Motion for joint consideration of Rockford League of Homan Voters & Dekalb Area Alliance for Responsible Energy & Binnissippi Alliance for Environ petitions re waiver of regulations Exhibits & Certificate of Svc encl WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Sinnissippi Alliance for Responsible Energy B2/07/30 Atomic Safety and Licensing Board Panel 270pp 14190 303 24X Fiche 50-454,82/07/30,8208040284
- 8208030391 Notice of 820818 prehearing conference in Rockford, IL MARGULIES, M. B. Atomic Safety and Licensing Board Panel 82/08/02 1p 14154 264 24% Fiche 50-454,82/08/02,8208030391
- 8208040223 Memorandum & order denying Rockford League of Women Voters 820706 petition for walver of or exception to regulations eliminating financial qualification from proceedings No prima facie showing of special circumstances made MAROULIES.M. B. Atomic Safety and Licensing Board Panel 82/08/02 League of Homen Voters of Rockford.IL. 9pp 14188 173 24X Fiche 30-454, 82/08/02,8208040223
- 8208050113 Further statement re petitions for waiver or exception.
 Incorporates by ref info in Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820730 petitions Proof of Bvc encl
 CHERRY, M League of Women Voters of Rockford, IL CHERRY, M Cherry, M M./Cherry, Flynn & Kanter 82/08/02 Atomic Safety and Licensing Board Panel. 2pp 14238 255 24X Fiche 50-454,82/08/02,8208040113
- B20B060105 Motion to compel suppl or revision to FEB Grounds set forth in Rockford League of Women Voters & Detailb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ B20706 & 30 petitions: respectively Certificate of Svc encl HHICHER, J. M DeKalb Area Alliance for Responsible Energy HHICHER, J M Sinnissippi Alliance for the Environment (BAFE) B2/08/03 Atomic Safety and Licensing Board Panel App 14238 177. 24% Fiche: 50-454,82/08/03,8208060105
- 8208060133 Motion to compel ASLB order requiring NRC to revise or suppl Feb 1982 SER New circumstances & developments show licenses finencial qualifications to complete const not sufficiently considered WHICHER, J M. DeKalb Area Alliance for Responsible Energy, WHICHER, J M. Binnissippi Alliance for the Environment (BAFE) 82/08/03 Atomic Safety and Licensing Board Panel 2pp 14241 275 24X Fiche 50-454,82/08/03,8208060133
- 8208110068 Memorandum & order denying Rockford League of Women Voters 820706 petition for waiver of or exception to iOCFR51 regulations prohibiting admission of contentions re need for yower or alternative energy sources in OL hearings MAROULIES, M B Atomic Safety and Licensing Board Panel 82/08/05 League of Women Voters of Rockford, IL 12pp 14317 001 24% Fiche 50-454, 82/08/05, 8208110068
- 8208090180 Informs that time for Commission to review ALAB-678 expired Commission declined review Decision became final agency action on 820805
 HOYLE, J.C. Diffice of the Secretary of the Commission 82/08/06
 Atomic Safety and Licensing Board Panel ip 14272:013 24X
 Fiche 50-454, 82/08/06, 8208090180
- 8208100065 Forwards Region 3 820709 ltr to licensee & notice of violation & imposition of civil penalty for Zion facility Proposed fine not indicative of future level of performance of Byron plant mgt YOUNO, M A. Hearing Branch 4 82/08/06 VON ZELLEN, B Northern Illinois Univ. Spp 14296-211 24X Fiche, 50-454, 82/08/06, 8208100658
- 8208100073 Forwards 8 von Zellen 820722 itr NRC elready replied. YOUNO, M. A. Hearing Branch 4 82/08/09. MARGULIES, M B , COLE.R.F., CALLIHAN, A. D. Atomic Sefety and Licensing Board Panel 5pp. 14274:175 24X Fiche 50-454,82/08/09,8208100073.
- 8208160159 Objection to Dakalb Area Alliance for Responsible Energy/
 Sinnissippi Alliance for Environ 820730 motion to suppl snawer to applicant & NRC motions for summary disposition of Alliance Contentions 2 & 2A W/Gertificate of Svc. BIELAWSKI.A.P. Commonwealth Edison Co BIELAWBKI.A.P Isham, Cincoln & Beale. 82/08/10 Atomic Safety and Licensing Board Panel. 6pp. 14345'063, 24x Fiche: 50-454, 82/08/10, 8208160157
- 8208160044 Requests ASLB consider Dekalb Area Alliance for Responsible Energy/Binnissippi Alliance for Environ (DAARE/BAFE) reply to NRC t C-E responses in ruling on DAARE/BAFE 820730 patition for maiver/exception to 10CFRS! WHICHER, J. M. Businessmen for the Public Interest, WHICHER, J M Dekalb Area Alliance for Responsible Energy WHICHER, J. M. Binnissippi Alliance for the Environment (BAFE). 82/08/11. MARQULIEB, M. B., COLE, R F, CALLIHAN, A D, Atomic Safety and Licensing Board Panel, 2pp. 14944 268 24% Fiche 50-454, 82/08/11, 8208160044

- 8208160239 Notifies that Dekalb Area Alliance for Responsible Energy/ Sinnissippi Alliance for Environ 820803 motion to compel NRC to suppl SER & FEB based on Alliance 820730 petition for maiver denied Response will be filed by 820823 GOLDBERG, 8 C Hearing Branch 2 82/09/12 WICHER, J H 8Usingssmen for the Public Interest 1p 14342 287 24X Fiche 80-454,82/08/12, 8208160237
- 8208170275 Responds to Dekalb Area Alliance for Responsible Energy/
 Binnissippi Alliance for Environ 820730 motion to respond to applicant answer to NRC 820604 motion for summary disposition of Contention 9(c) Certificate of Svc encl OCLOBERGS C Hearing Branch 2 82708/13 Atomic Safety and Licensing Board Panel 5pp 14369 178 24% Fiche 50-454, 82708/13, 8208170275
- 8208170277 Response to opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820730 motion to suppl answer to applicent & NRC motion for summary disposition of Contentions 2 & 2A W/Certificate of Evc RAWSON.R J. Hearing Branch 4 82/08/13 Atomic Safety and Licensing Board Panel 6pp 14347 083 24% Fiche 50-454,82/08/13,8208170277
- 8208200276 Response opposing Detaib Area Alliance for Responsible Energy/Binnissipsi Alliance for Environ 820730 petitions for waiver of financial qualifications, need for power & alternative energy regulations W/Certificate of Byc. BIELAWSKI.A P Commonwealth Edison Co 62/08/17 Atomic Safet and Licensing Board Panel 17pp 14394 001 24X Fichs 50-454.82/08/17.8208200276
- 8208230053 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820730 petition for waiver of financial qualification regulations Special circumstances not present YOUNG.M A Hearing Branch 4 82/08/18 Atomic Safety and Licensing Board Fanel 15pp 14517 177 24X Fiche 50~454.82/08/18, 8208230063
- --B20B230067 Affidavit of JC Peterten re waiver of financial qualifications No special circumstances specific to plant erist to justify acception to financial qualification regulations
 PETERSEN.J C Uffice of State Programs, Director 82/08/17 4pp 14317 192 24X Fiche 50-434,82/08/18.8208230063.
- ---B20B2300A9 Affidavit of WL Forney that GA/GC deficiencies were not caused by financially motivated corner cutting.
 FORNEY, W L Division of Project & Resident Programs.
 Bpp 14517 19A 24X Fithe 50-454, 82/08/18. B20B2300A3
- 8208230070 Response apposing Details Area Alliance for Reaponsible Energy/Sinnissippi Alliance for Environ 820730 petition for waiver of need for power & alternative energy source regulations

 RAMSON.R J Hearing Branch 4, 82/08/18 Atomic Safety and Licensing Board Panel 14pp 14517-300 24X Fiche 50-454,82/08/18,8208230070
- ~-8208230098 Affidavit of DA Nash re Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ petition for waiver of need for power & alternative energy source regulations Prof qualifications enc!

 NABH, D.A. Office of State Programs, Director 82/08/13, 5pp. 14517-314 24X Fiche 80-454,82/08/18,8208230070
- 8208230115 Certifies avc of NRC responses to Dekalb Area Alliancs for Responsible Energy/Binnissippi Alliance for Environ petitions for waiver of financial qualifications & need for power & alternative energy source regulations.

 YOUND. M A Hearing Branch 4 82/08/18 2pp 14517;298 24% Fiche 30-454,82/08/18,8208230115
- 8208270459 Advises that util prepared to commence discovery immediately Amended set of interrogatories & production requests limited to admitted contentions to be submitted. Related correspondence
 BIELANBKI.A.P Isham, Lincoln & Beale BIELANBKI.A.P Commonwealth Edison Co 82/08/20 CHERRY.M.M Cherry, M / Cherry, Flynn & Kanter ip 14565 348 24% Fiche 50-454, 82/08/20, 8208270459
- B208300307 Memorandum & order denying Dekaib Arma Alliance for Responsible Energy/Binnissippi Alliance for Environ 820730 petitions for waiver of regulations prohibiting contentions on need for power or alternative energy sources.

 MARGULIES M B. Atomic Safety and Literaing Board Panel 82/08/26 DeKaib Arma Alliance for Responsible Energy 7pp 14599 293, 24X Fiche 50-454,82/08/26,8208300307

8208170130 Requests author be added to svc list.Related correspondence GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co 82708/12 Docksting & Services Branch ip 14365 234 24X

I Financial information

6208310157 Forwards pertial response to Questions 2 & 4 recorrespondence to IL Hunicipal Util Association 4th 320806, FELLMAUERR Geneva, IL 82/08/25 TOALSTON, A Antitrust & Economic analysis Branch (Utility Finance) 3pp 14693-190 24x Fiche 50-454, 82/08/25, 8208310157

M Antitrust correspondence

- 8208230027 Requests antitrust info to aid in OL review Info needed to determine existence of changes in Com Ed activities since CP antitrust review completed in Apr 1974 TOALETON A Antitrust & Economic analysis Branch (Utility Finance). 82208206 CLEVENGER.L T Southern Illinois Power Cooperative. 1p. 14507 319 24X Fichs 50-454,82/08/06.8208230027
- 8208230031 Requests add1 antitrust info for use in OL review Info needed to determine existence of changes in Com Ed activities since CP antitrust review completed in Apr 1974 IOALSTON.A Antitrust Economic analysis Branch (Utility Finance) 82/08/06 Illinois Municipal Utilities Association 2pp. 24X Fithe 50-454, 92/08/06, 8208230031
- 8208230061 Requests antitrust info to aid in OL review info meeded to determine existence of changes in Com Ed activities since OP antitrust review completed in Apr 1974
 TOALSTONA Antitrust & Economic analysis Branch (Utility Finance).
 82/08/06. NEWMAN R 8. Soutand Power Congerative, Inc. 1p. 14507,080
 24X Fichs 50~454,82/08/06.8208230061
- 8208230075 Requests addl antitrust Info for use in CL review Util 790322 submittal must be updated TOALBYON.A Antitrust & Economic analysis Branch (Utility Finance) 82/08/06 NAUQHTON.W F Commonwealth Edison Co 2pp 14518.010 24X Fiche, 50-454, 82/08/06, 8208230075
- 8208230105 Requests antitrust info to sid in QL review Info needed to determine eristence of changes in Com Ed activities since CP antitrust review completed in Apr 1974 TRALSTRIA, A Actitust & Economic analysis Dranch (Utility Finance) 82/08/06. BRINOMAN.D 9 Western Illinois Power Cooperative. Inc. 19. 14517 359 24K Fiche 50-454.82/08/06, \$208230105
- 8208240161 Responds to 820806 request for info re wholesale customers, generating capacity, peak load for 1981, sources of purchased power & miles of transmission lines. Requested info provided BRINONAN, D.B. Wastern Illiands Power Cooperative, inc. 82/08/16 TOALBTON.A. Ancitrost & Economic analysis Branch (Utility Finance) ip 14520 104, 24% Fiche 50-454, 82/08/16, 8208240161
- 9209270495 Provides info re customers to which wholesale power was arovided during 1982; in response to NRC 820806 ltm. CHAPMAN, J.R. Southern Illinois Power Cooperative, 82/08/24, TOALSTON, A. Antitrust & Economic analysis Branch (Utility Finance) is. 14564-046, 24% Fithe 50-454, 82/08/24, 8208270485
- 8208310197 Forwards partial response to Questions 2 & 4 recorrespondence to IL Municipal Util Association dtd 820806 FELLHAUER: R Oeneva. IL 82/08/25 TOALSTON. A Antityust & Economic analysis Branch (Utility Finance) 3pp 14693 190, 24X Fiche: 50-434, 82/08/25, 8208310157.
- Q Inspection reports, IE Bulletina & correspondence
- 8204210393 lE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc List enci. JORDANIE L. Division of Engineering & Guality Assurance. 82/07/16 Constiliated Edison Co. of New York 87pp 14356 274. 24X Fiche 50-000, 82/07/16, 8204210393.
- 8204210373 IE Info Notice 81-26, Part 3, Suppl 1, "Glarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl URRDAN, E.L. Division of Engineering & Quality Assurance, 82/07/19 Hichigan Univ of (12pp. 14358 001 24% Fiche, 50~000, 82/07/19, 8204210395.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressurs." Syc list encl. JOROAN, E. L. Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co. of New York. 112pp 14381 001 24X Fichs 50-000, 82/07/20, 8204210396.

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Mexafluoride Overpacks " Syc list enci GOBB,L I Divisiton of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000, B2/07/20, 8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." 8vc list encl JORDAN, Et Division of Engineering & Quality Assurance 82/07/22, Consolidated & Edison Co. of New York 112pp 14194 321 24X Fiche. 50-600, 82/07/22, 8204210398
- 8204210401 IE Info Natice 82-28. "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, EL Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp. 14380 115 24% Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PMRs " Svc list encl JORDAN.E.L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of Now York 127pp 14194 120 24X Fiche: 50-000. 82/07/23. 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bloeves in RCB Piping at Certain Westinghouse PWR Power Plants" Svc list encl JRDANIE L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013, 24X Fiche 50-000, 82/07/26, 8204210403.
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl URRDAN.E.L. Division of Engineering & Quality Assurance 82/07/28 Comeolidated Edison Co. of New York 122pp 14357:146 24X Fiche: 50-000: 82/07/28: 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Dogradation Resulting From Baffle Water-Jet Impingoment" 8vc list encl URDAN.E L. Division of Engineering & Quality Assurance 82/08/05 Consolidated & Edison Go of New York 117pp 14388 201 24X Fiche: 50-000: 82/08/05,8204210407
- 8208230377 Forwards Revision i to "Byron Nuclear Power Station Unit i Inservice Insp Program Plan for Bnubbars " Relief requests will be added after completion of preservice testing program outline of in util 820319 itr NRC approval requested.

 TRAMM.T.R. Commonwealth Edison Co 82/08/12 DENTON.H.R Office of Nuclear Reactor Regulation. Director 2pp 14908 167. 24X Fichs: 50-454.82/08/12, 9200230377
- --8208230978 Revision I to "Byron Nuclear Power Station Unit I Inservice Insp Program Plan for Shubbers" 57pp 14508-169. 24X Fiche 50-454,62/08/12,6208230377
- ? Periodic operating reports & related correspondence
- 3208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A. FELTON, J H. Division of Rules and Records 82/07/13 UDELL,R.A Critical Mass Energy Project. 8pp. 14679 208 24X Fichs 50-000,82/07/13,8208270010
- -8208270359 Forwards "Rocorded Annual Whole Body External Exposure for CY81." per 10CFR20 407(a) W/o Guad Cities. Zion, LaSalle, Byran & Braidwood repts.
 RAUSCH.T. J Commonwealth Edison Co. 82/03/31 Office of Management and Program Analysis 1p 14680.075. 24X Fiche: 50-000, 82/07/13, 8208270010
- Reportable occurrences, LERs & related correspondence
- 20Bi30223 Interim deficiency rept to emergency diesel generator field relay failure Initially reported on 820702 One contact on relay 14FX found fused closed, Relay replaced Final rept expected by 820902
 TRAMM.T.R. Commonwealth Edison Co. 82/08/02 KEPPLER.J.Q. Region 3, Defice of Director 2pp 14333, 182 24X Fiche-50-000, 82/08/02, 820843023
- 208130027 Interim deficiency rept re potential for fire dampers not to close when fusible link separates Initially reported on 820701. All curtain type fire dampers w/C type fusible links will be reworked prior to fuel load.
 THAMM. T. R. Commonwealth Edison Co. 82/08/03 KEPPLER, J. Q. Region 3, Office of Director. 2pp. 14335:056. 24X Fiche 50-454.82/08/03, 6206130027.

- f Hearing transcripts on non-antitrust matters
- 8208240413 Transcript of 820818 hearing in Rockford, IL Pp 1-165 * Atomic Safety and Licensing Board Panel 82/08/18 167pp 14323-188 24X Fiche 50-434,82/08/18,8208240415
- 8208240301 Transcript of 820819 hearing in Rockford, IL Pp 166-205 * Atomic Bafety and Licensing Board Panel 82/08/19 41pp 14524 299 24X Fiche 50-454,82/08/19,8208240301
- DOCKET STN-50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8207080064 Generic itr to all licenses of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Evc list encl
 DIRCKB.M J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp, 14194.001
 24X Fiche 50~000,82/07/02.8207080064
- B208040484 Notification of 820727 meeting w/Wastinghouse in Bethesda.

 MD to discuss Krsko water hammer event of Jul 1981 & applicability to domestic Westinghouse Type D steam generators

 CHEGNUT. 6 Licensing Branch 1. 82/07/22 YOUNOBLOOD, 8 J

 Licensing Branch 1. 3pp 14220 309 24X Fiche 90-454,82/07/22,8208040484
- 8208050193 Forwards summary of NRC 820721 meeting w/Westinghouse in Bethesda, MD re progress in resolving accelerated tube wear at operating plants w/Westinghouse Model D steam genorators, since facilities will utilize Models D-4 & D-5 YOUNODIODD, B J. Licensing Branch 1 82/07/27 DELGEORGE, L O Commonwealth Edison Co Spp 14242 124. 24X Fiche 50-000,82/07/27, 2200050192
- 8208130385 Notifies that criteria for assential svc water pipeline drilling operations as modified by 820723 telcon is acceptable Branch should be informed of drilling schedule in order to observe drilling operations t results YOUNOBLOOD.B J. Licensing Branch 1 82/07/29 DELGEORGE.L O Commonwealth Edison Co 2pp 14340 269 24X Fiche 50-454.82/07/29, 8208130385
- 8208110243 Forwards request for add1 info re water hommer prevention per event at KRBKD reactor in Yugoslavia Test plan to verify that water hammer will not occur should be provided to Verify YOUNOBLOOD, 8 J Licensing Branch i. 82/07/30 DELGEORGE. C Commonwealth Edison Co 6pp 14331,098 24X Fiche 50-000,82/07/30,820810243
- 8208110188 Forwards revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 21 Revised pages correct typographical & other minor errors SHARTZ, E Commonwealth Edison Co. 82/08/06 HAASS,W.P. Quality Assurance Branch 1p 14314 077. 24% Fiche 50-000,82/08/06.
- ---B20Bii0204 Revised pages to CE-1-A.Revision 21. "Comm Ed GA Program for Nuclear Generating Stations"

 * Commonwealth Edison Co 82/06/06. 11pp 14314 080 24X Ficha 50-000.82/08/06.8208110188
- 9208090194 Owneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re-submitted of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements, 8xc list encl EISENHUT, D. 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip. 14356-332 24X Fiche 50-000,82/08/09, 8208090194
- B20B17009A Forwards responses to FBAR questions re flexibility of baseplates for pipe supports Review of response to Questions 110 71 & 110 72 should close outstanding Item 5 of FBAR. TRAMM.T.R. Commonwealth Edison Co 82/08/09 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 9pp 14358:217 24X Fiche: 50-000, B2/08/09, B2/08170094
- 8208130277 Forwards preliminary revision of Attachment C3.6 to Section 3 6 of FSAR re main steamline break in main steam tunnel Info will be incorporated into next FSAR emend. TRANM.T R Commonwealth Edison Co. 82/08/10. DENTON.H R Office of Nuclear Reactor Regulation, Director. 26pp. 14333.077 24% Fichs: 50-000.82/08/10.8208130277.

- 8208230327 Forwards seismic & dynamic qualification summary & status of equipment important to facility safety, revising 820617 updates Util understands that NRC will examine several listed components during 820830-31 audit TRAHM.T R Commonwealth Edison Co 82/08/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 150pp 14509 001 24X Fiche 50-454,82/08/10,8208230327
- B20B230324 Forwards addl info re installation of instrumentation for detection of inadequate core cooling Info correlated to Requirements 1-9 for NUREG-0737. Item II F, 2
 TRAMM, T R Commonwealth Edison Co B2/08/13, DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 14508/328 24X
 Fiche 50-000.82/08/13,8208230324
- 8208230058 Forwards addl info re status of various sys important to Muman Factors Engineering Branch review of control rooms Second site visit can be schoduled for Feb 1983 or later, which should close out review TRAMM, TR Commonwealth Edison Co 82/08/16 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 14509:324 24X Fiche: 50-000, 82/08/16, 8208230058
- 8208230332 Forwards revised response to FSAR Question 022 54 indicating why power interruption is not practical in case of post-LGCA purge sys isolation valva (1V0003) Response will be incorporated into next FSAR amend TRAMM.T R. Commonwealth Edison Co 82/08/17 DENTON.H.R. Office of Nuclear Reactor Regulation, Director 2pp. 14508-258 24X Fishe 50-000.82/08/17,8208230332.
- 8208270350 Forwards revised FBAR into re protection against possible turbine missiles at facilities Changes will be incorporated into future FBAR amend Into closes Outstanding Item 2 of Byron 8ER
 TRAMM.TR Commonwealth Edison Co 82/08/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 70pp 14564 300 24X
 Fiche 50-000, 82/08/18, 8208270350
- E NRC Sefety Evaluation Report (SER), supple & correspondence
- 8208170219 Forwards responses to F8AR Questions 22 23 & 22 24, providing results of reanalyses of ECCB performance w/reduced temp of essential svc water to reactor containment fan cooler units.

 SER Confirmatory Issue 19 closed TRAMM.TR Commonwealth Edison Co. 82/08/06 DENTON, H.R Office of Nuclear Reactor Regulation, Director App 14361 317 24X Fiche 50-000, 82/08/08/2828170219
- 8208180002 Forwards response to FSAR questions re vol reduction sys Info should close Outstanding Item 15 of Byron SER TRAMM.T.R Commonwealth Edison Co. 82/08/06. DENTON.H R Office of Nuclear Reactor Regulation. Director 19pp. 14376 215 24X Fiche.50-000.82/08/06.B208180002
- 8208170240 Forwards info to be included in FSAR re analyses of high 3: moderate energy pipe broaks NRC review of info should close outstanding Item 3 of Byron 86R Revised response to Question 10 40 encl TRAMM.T.R. Commonwealth Edison Co., 82/08/10, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 15pp 14368-322, 24X Fiche 50-000, 82/08/10, 8208170240
- 820B180011 Provides info re circuit change which will aid operator during switchover from ECCB injection to recirculation following LOCA Feature will provide control room indication of safety injection 8-signal status TRAMMITR. Commonwealth Edison Co. 82/08/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 14376.285, 24X Fiche: 50-000, 82/08/11, 8200180011
- 8208230354 Forwards responses to FBAR Questions 010 55-010 39 re fire protection, requested in NRC 820715 ltr. Info will be included in next FBAR amend, Responses should close Outstanding Item 13 of Byron 8ER.
 TRAMMIT, R Commonwealth Edison Co 82/08/17 DENTON, H.R Office of Nuclear Reactor Regulation, Director tipp 14508 285 24X Fiche 50-000, 82/08/17, 8208230354
- 8208270350 Forwards revised FBAR info re protection against possible turbine missiles at facilities Changes will be incorporated into future FBAR amend Info closes Outstanding Item 2 of Byron 8ER.
 TRAPHITR. Commonwealth Edison Go 82/08/18 DENTON, HR Office of Nuclear Reactor Regulation, Director. 70pp. 14544, 300. 24X Fiche. 50-000, 82/08/18, 8208270350

- F Security, medical, emergency & fire protection plans
- 8208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 FELTON.J M Division of Rules and Records 82/08/12 Document Management Brench 1p 14559 354 24X Fiche 50-000, 82/08/12. 8208250559
- --8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 HODRE,R D Commonwealth Edison Co 82/07/19, DENTON.H R NRC No Datailed Affiliation Coiven. ip. 14559 355 24X Fiche 50-000,82/08/12.8208230557
- --8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."

 # Commonwealth Edison Co 82/06/30 7pp 14559.336 24X Fiche 50-000,82/08/12,8208250559
- 8208190014 Forwards revised "Fire Protection Rept in Response to Branch Technical Position CMEB 9 5 1." Revision incorporates safe shutdown analysis submitted in util 820414 ltr & updated comparison w/10CFR50 App R.
 TRAMM, T R Communuealth Edison Co. 82/08/16 UENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp. 14383 214 24% Fiche 50-000, 82/08/16, 820819014.
- --8208190018 Revised "Fire Protection Rept in Response to Branch Technical Position CMES 9 5.1" * Communecath Edison Co 82/08/16 700pp 14383,219 24X Fiche. 50-000, 82/08/16. 8208190014.
- 8208230354 Forwards responses to FBAR Questions 010 55-010.59 re fire protection requested in NRC 820715 ltr Info will be included in mext FBAR amend Responses should close Dutstanding Item 13 of Byron 8ER TRAMM.T.R. Commonwealth Edison Co. 82/08/17. DENTON, H R Office of Nuclear Reactor Regulation, Director. 11pp 14508-285 24X Fiche: 50-000, 82/08/17, 8208230354
- O Adjudicatory correspondence
- 8208020256 Response opposing Rockford League of Homen Voters petitions for waiver of or exception to NRC regulations. Petitions fail to set forth justifying special discommendes Certificate of Byc encl.

 81ELAWSKI.A.P. Commonwealth Edison Co BIELAWSKI.A.P. Isham, Lincoln & Beale, 82/07/22 Atomic Rafety and Licensing Board Panel 158pp. 14152:05E. 24X Picher 30-434-82/07/22.8208020286
- 8208030424 Motion for leave to file response to applicant 820719 answer supporting NRC motion for summary disposition of Dekalb Area Alliance for Responsible Emergy/Sinnissippi Alliance for Environ Contention 9c. Related correspondence CHAVEZ.D Sinnissippi Alliance for the Environment (8AFE) 82/07/30 Atomic Safety and Licensing Board Panel 2pp. 14154.092 24X Fiche: 50-454.82/07/30.8208030424.
- --8208030430 Response to applicant 820719 answer supporting NRC motion for summary disposition of Detail Area Alliance for Responsible Energy/Binnissippi Alliance for Environ Contention 9c Ornly Items 1.2.7.11.12.15 & 17 admitted true CHAVEZ,D. Binnissippi Alliance for the Environment (BAFE) 82/07/30. Atomic Bafety and Licensing Board Panel 11pp 14154 094 24X Fiche 50-434,82/07/30,8208030424
- --8208030435 Affidavit consisting of documents supporting response in apposition to NRC motion for summary disposition of Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 9c Certificate of Evc encl BUNCH: R Binnissippi Alliance for the Environment (SAFE) 82/07/30. 37pp. 14154.109 24X Fiche.50-454,82/07/30.8208030424.
- 8208030424 Motion to suppl ensuer to util & NRC motions for summary disposition of Contentions 2 & 2a. New relevant info unevailable when answer filed & only recently available to scientific community Related correspondence.
 CHAYEZ, D. DeMaib Area Alliance for Responsible Energy CHAVEZ, D. Sinnissippi Alliance for the Environment (SAFE). 82707/30. Atomic Safety and Licensing Board Panel. 2pp 14163.107 24X Fichs. 50-454, 82707/30, 8208030426
- --8208030437 Affidavit of EJ Sternglass. Cumulative affects of radioactive release from reactors located in northern JL should be re-evaluated. EPA min dose of radiation probably cannot be met for some local populations

 BTERNOLASS. E. J. Dekalb Area Alliance for Responsible Energy.

 STERNOLASS. E. J. Binnissippi Alliance for the Environment (SAFE).

 82/07/19. 14pp. 14163-109. 24X Fiche 50-454,82/07/30.8208030426.

- 8208040284 Reply to util & NRC 820722 & 24 responses, respectively, to Rockford League of Momen Voters 820704 petitions for waiver of or exception to regulations, excluding financial qualifications, need for power & alternative energy issues WHICHER. J M DeXalb Area Alliance for Responsible Energy WHICHER. J M Sinnissippi Alliance for the Environment (SAFE) 82/07/30 Atomic Safety and Licensing Board Panel 15pp 14190:254 24X Fiche 50-454,82/07/30,8208040284
- --B208040290 Petition for waiver of or exception to financial qualification regulations Special circumstances exist so that purpose of new NRC regulations excluding issue would not be served CASSEL, D.W. DeKalb Area Alliance for Responsible Energy CASSEL, D.W. Binnissippi Alliance for the Environment (SAFE) B2/07/30 Atomic Safety and Licensing Soard Panel 14pp 14190;269 24X Fiche 50-454,82/07/30,8208040284
- --8208040294 Patition for waiver of or exception to need for power & alternative energy source regulations Special circumstances exist so that purpose of new NRC regulations excluding issues would not be served.

 MHICHER.J M. DeKalb Area Alliance for Responsible Energy HHICHER.J M. Binnissippi Alliance for the Environment (BAFE) 82/07/30

 Atomic Safety and Licensing Board Panel 9pp 14190 283 24X Fiche 50-454, 82/07/30.8208040284
- --B208040297 Financial qualifications contention
 CASSEL, D. H DeKalb Area Alliance for Responsible Energy
 CASSEL, D. H Sinnissippi Alliance for the Environment (SAFE)
 B2/07/30 Atomic Safety and Licensing Board Panel 3pp
 14170, 292 24X Fiche 50-454, 82/07/30, 8208040284
- --8208040303 Need for power & alternative energy source contention MHICHER.J.M. DeKalb Area Alliance for Responsible Energy MHICHER.J.M Sinnissippi Alliance for the Environment (BAFE) 82/07/30 Atomic Sefety and Licensing Board Panel 2pp 24X Fiche 50-454, 82/07/30.8208040284
- --B20804030B Response to first request for production of documents refinancial qualifications, need for power & alternative energy sources.

 WHICHER, J. M. DeKalb Area Alliance for Responsible Energy WHICHER, J. M. Sinnissippi Alliance for the Environment (SAFE) B2/07/30 Office of the Executive Legal Director 2pp 14190-297. 24X F(che:50-454,82/07/30,8208040284
- --B209040312 Response to first round of interrogatories re financial qualifications, need for power & alternative energy sources CHAVEZ, D. Dakalb Area Alliance for Responsible Energy CHAVEZ, D. Sinnissippi Alliance for the Environment (SAFE) 82/07/30 Gommanwealth Edison Co. 4pp. 14190:299 24X Fiche: 50-454, B2/07/30.8208040284.
- --8208040316 Motion for joint consideration of Rockford League of Homen Voters & Dekaib Area Alliance for Responsible Energy & Sinnissippi Alliance for Environ petitions re waiver of regulations, Exhibits & Certificate of Svc enc.

 WHICHER, J. M Dekaib Area Alliance for Responsible Energy, WHICHER, J. M Sinnissippi Alliance for the Environment (SAFE), 82/07/30 Atomic Bafety and Licensing Board Penel 270pp [4170:303 24% Fishe 50-454, 82/07/30, 8208040284
- B208030391 Notice of B20818 prehearing conference in Rockford. IL MARQULIES. H 8. Atomic Safety and Licensing Board Panel. B2/08/02 1p. 14194-24. 24X Fiche: 80-454.B2/08/02.B208030391
- 8208040223 Hemorandum & order denying Rockford League of Women Voters 820706 petition for waiver of or exception to regulations eliminating financial qualification from proceedings No prime facie showing of special circumstances made HARQUIES.H.B. Atomic Safety and Licensing Board Panel 82/08/02 League of Women Voters of Rockford.IL. 9pp 14188 173 24X Fiche: 50-454, 82/08/02, 8208040223
- 8208050113 Further statement re petitions for waiver or exception, incorporates by ref info in Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820730 pasitions. Proof of Svc encl.

 CHERRY.M. League of Women Voters of Rockford.TL. CHERRY.M. Cherry.M. M. /Cherry. Flynn & Kanter 82/08/02. Atomic Safety and Licensing Board Panel. 2pp. 14238, 255 24% Fiche, 30-454,82/08/02, 8208060113.
- 8208060105 Motion to compel suppl or revision to FES. Grounds set forth in Rockford League of Women Voters & Dakalb Area Alliance for Responsible Energy/Binnissippi Alliance for Environ 820706 & 30 setitions: respectively Certificate of Svc encl WHICHER, J. M. DaKalb Area Alliance for Responsible Energy WHICHER, J. M. Binnissippi Alliance for the Environment (SAFE). 82/08/03, Atomic Safety and Licensing Board Panel App 14238.177 24X Fiche: 50-454,82/08/03,8208040105

- 8208060133 Motion to compel AELB order requiring NRC to revise or supple Feb 1982 SER New circumstances & developments show licensee financial qualifications to complete constitution of the constitution of
- 8208110068 Memorandum & order denying Rockford Lwague of Women Voters 820706 petition for walver of or exception to 10CFR51 regulations prohibiting admission of contentions re need for power or alternative energy sources in CL hearings MARGULIES, H & Atomic Safety and Licensing Board Panel 82/08/05 Lesque of Women Voters of Rockford, IL 12pp 14317 001 24% Fiche 50-454, 82/08/03, 8208110068
- 8208090180 Informs that time for Commission to review ALAB-678 expired Commission declined review Decision became final agency action on 820805 HOYLE.J C Office of the Secretary of the Commission 82/08/06 Atomic Safety and Licensing Board Panel ip 14272 013 24X Fiche 30-454,62/08/06.8208090180
- 8208100065 Forwards Region 3 820709 ltr to licenses & notice of violation & imposition of civil penalty for Zion facility Proposed fine not indicative of future level of performance of Byron plant mgt YOUNO, M A Hearing Branch 4. 82/08/06 VON ZELLEN, B Northern Illinois Univ 8pp 14276 211 24X Fiche 50-454,82/08/06, B208100065
- 8208100073 Forwards B von Zellen 820722 itr NRC already replied YOUNO, M A Hearing Branch 4 82/08/09 MARGULIES, M B , COLE.R F , CALLIHAN, A, D Atomic Safety and Licensing Board Panel 5pp. 14294, 175, 24% Fiche 50-454, 82/08/09, 8208100073.
- 8208160157 Objection to Details Area Alliance for Responsible Energy/
 Sinnissippi Alliance for Environ 820730 motion to suppl
 answer to applicant & NRC motions for summary disposition of
 Alliance Contentions 2 & 2A W/Certificate of Svc.
 BIELAWSKI.A P Commonwealth Edison Co BIELAWSKI.A P Isham,
 Lincoln & Beals 82/08/10 Atomic Safety and Licensing Board
 Panel 6pp 14345 063 24X Fiche 30-454, 82/08/10, 8208160159
- 8208160044 Requests ASLB consider Details Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ (DAARE/SAFE) reply to NRC & C-E responses in ruling on DAARE/SAFE 820730 patition for waiver/exception to 10CFR5; WHICHER, J M Businessmen for the Public Interest, WHICHER, J M DaKails Area Alliance for Responsible Energy WHICHER, J M Signissippi Alliance for the Environment (SAFE) 82/08/11 HARGULIES, M. B., COLE, R. F., CALLIHAN, A. D. Atomic Safety and Licensing Board Panel. 2pp 14344 268 24X Ficher 50-454, 82/08/11, 8208160044
- 820Bi40239 Notifies that Dekalb Area Alliance for Responsible Energy/
 Sinnissippi Alliance for Environ 820B03 motion to compel
 NRC to suppl SER & FES based on Alliance 920730 petition
 for waiver denied Response will be filed by 820B23
 QULDBERO, S C Hearing Branch 2 82/08/12 WICHER, J, M Susinessmen
 for the Public Interest 1p 14342, 287, 24X Fiche 50-454, 82/08/12,
 8208160239.
- 8208170275 Responds to Dekelb Area Alliance for Responsible Energy/
 Sinnissippi Alliance for Environ 820730 motion to respond to applicant answer to NRC 820604 motion for summary disposition of Contention 9(c) Certificate of Svc encl OCLOBERO, 8 C Hearing Branch 2 82/08/13 Atomic 8afety and Licensing Seard Penel 5pp 14369 178 24X Fiche 50-454,82/08/13,8208170275
- 8208170277 Response to opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820730 motion to suppl answer to applicant to NRC motion for summary disposition of Contentions 2 & 2A M/Certificate of Syc. RAWSON.R. J. Hearing Branch 4, 82/08/13 Atomic Safety and Licensing Board Panel 6pp 14367 083, 24X Fiche 50-454,82/08/13,8208170277
- 8208200276 Response opposing Dekalb Area Alliance for Responsible Energy/Binnissippi Alliance for Environ 820730 patitions for waiver of financial qualifications, need for power & alternative energy regulations W/Certificate of Svc.

 BIELAWRKI.A.P. Commonwealth Edison Co. 82/08/17 Atomic Safety and Licensing Board Panel 17pp 14394 001, 24% Fiche, 50-454, 82/08/17, 8208200276
- B20B230Q63 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820730 petition for waiver of financial qualification regulations Special circumstances not present YUUNO, M. A. Hearing Branch 4, 82/08/18 Atomic Safety and Licensing Board Panel 15pp 14517 177 24X Fiche 50-454,82/08/18,8208230063

- --B208230067 Affidavit of JC Petersen re waiver of financial qualifications No special circumstances specific to plant exist to justify exception to financial qualification regulations
 PETERSEN.J C Office of State Programs, Director, 82/08/17 4pp 14517 172 24X Fiche 50-454.82/08/18,8208230063
- --B208230067 Affidavit of WL Forney that GA/OC deficiencies were not caused by financially motivated corner cutting FORNEY, H L Division of Project & Resident Programs 82/08/19, 8pp 14517 176 24X Fiche 50-454, 82/08/18,8208230063
- B208230070 Response opposing Dekalb Area Alliancs for Responsible Energy/Sinnissippi Alliance for Environ 820730 petition for waiver of need for power & alternative energy source regulations RAMBON.R J Hearing Branch 4 82/08/18 Atomic 8afety and Licensing Board Panel 14pp 14517.300 24X Fiche 50-454,82/08/18,8208230070
- --B20B23007B Affidavit of DA Nash re Dekalb Area Alliance for Responsible Energy/Binnissippi Alliance for Environ petition for waiver of nsed for power & alternative energy source regulations Prof qualifications encl
 NASH, D A Office of State Programs, Director B2/0B/13 5pp 14517 314 24% Fiche 50-454, B2/0B/18.B20B230070
- 8208230115 Certifies svc of NRC responses to Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ positions for weiver of financial qualifications & need for power & alternative energy source regulations YQUNO, M A Hearing Branch 4 82/08/18 2pp 14517 298 24X Fiche 50-454, 82/08/18, 82/08230115
- 8208270459 Advises that util prepared to commence discovery immediately Amended set of interrogatoriés & production requests limited to admitted contentions to be submitted Related correspondence BIELAMSKI.A P Isham. Lincoln & Beale BIELAMSKI.A P. Gommonwealth Edison Co 82/08/20 CHERRY, M M Cherry, M M Cherry, Flynn & Kanter ip 14565 348 24X Fiche 50-454,82/08/20,8208270459
- 8208300307 Memorandum & order denying Dekelb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820730 petitions for waiver of regulations prohibiting contentions on need for power or alternative energy sources MAROULIES M B Atomic Safety and Licensing Board Panel, 82/08/26 Dekelb Area Alliance for Responsible Energy 7pp. 14599 273 24X Fiche 50-454,82/08/26,8208300307

- B20B170130 Requeste author be added to svc list Related correspondence GALLG, J Isham, Lincoln & Beale GALLG, J Commonwealth Edison Co. B2/08/12 Docketing & Services Branch ip 14365 234 24X Fiche: 50-454, 82/08/12, 8208170130
- M Antitrust correspondence
- 8208240161 Responds to 820806 request for info re wholesale customers, generating capacity-peak load for 1981, sources of purchased gower & miles of transmission lines Requested info provided BRINGMAN.D B Western Illinois Power Cooperative, Inc 82/08/16 TOALBTON.A Antitrust & Economic analysis Branch (Utility Finance), Ip. 14520 104 24X Fichs 50-454.82/08/16, 8208240161
- 8208270485 Provides info re customers to which wholesale power was provided during 1982; in response to NRC 820806 ltr CHAPMAN, J R Southern Illinois Power Cooperative 82/08/24 TOALSTON. A. Antitrust & Economic analysis Branch (Utility Finance) 1p 14564.046 24X Fiche 50-454.82/08/24,8208270485
- G. Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN.E L. Division of Engineering & Guality Assurance. 82/07/16,
 Consolidated Edison Co. of New York. 87pp 14356 274 24X
 Fiche 50-000, 82/07/16, 8204210393.
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN. E. L. Division of Engineering & Quality Assurance 82/07/19, Michigan, Univ of 112pp 14358 001, 24X Fiche: 50-000, 82/07/19, 8204210395.

- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Evo list enci JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001. 24X Fiche 50-000:82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidate Edison Co of New York 7ipp, 14357-276 24X Fiche 50-000-82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York. 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-29. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Syc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York, 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PMRs " Byc list encl JORDAN.E. L. Division of Engineering & Quality Assurance 82/07/23. Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche 50-000.82/07/23,8204210492
- 8204210403 IE Info Notice B2-30, "Loss of Thermal Bleeves in RGB Piping at Certain Westinghouse PWR Power Plants " Syx list encl JORDAN.E. L. Division of Engineering & Quality Assurance, 82/07/26, Consolidated Edison Co of New York, 12ipp, 14357-013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York, 122pp 14357-146, 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl.
 JORDAN, E.L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co. of New York 117pp. 14388 201, 24X
 Fiche 90-000.82/08/03.8204210407
- R. Periodic operating reports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures, in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A. FELTON, J. H. Division of Rules and Records. 82/07/13 UDELL, R. A Critical Mass Energy Project 8pp. 14679, 208. 24X Fiche. 50-000, 82/07/13, 8208270010.
- --8208270559 Forwards "Recorded Annual Whole Body External Exposure for CVBi," per 10CFR20.407(b) W/o Guad Cities, Zion, LaSalle, Byron & Braidwood repts RAUBCH, T. J. Commonwealth Edison Co. 82/03/31, Office of Management and Program Analysis. 1p 14680.075, 24X Fiche: 50-000, 82/07/13, 8208270010.
- 8. Reportable occurrences. LERs & related correspondence
- 8208i30223 Interim deficiency rept re emergency dissel generator field relay failurs Initially reported on 820702. One contact on relay 14FX found fused closed. Relay replaced. Final rept expected by 820702.

 TRAMM.T.R. Commonwealth Edison Co. 82/08/02 KEPPLER.J.Q. Region 3. Office of Director. 2pp. 14333.182 24X Fiche 50-000.82/08/02.8208130223
- 8208130027 Interim deficiency rept re-potential for fire dampers not to close when fusible link separates Initially reported on B20701 All curtain type fire dampers w/C type fusible links will be reworked prior to fuel load.

 TRAMM.T.R. Commonwealth Edison Co. 82/08/03, KEPPLER, J. Q. Region 3, Office of Director 2pp. 14335;056, 24X Fiche: 50-454,82/08/03, 8208130027
- T Hearing transcripts on non-antitrust metters
- 8208240415 Transcript of 820818 hearing in Rockford, IL Pp 1-165 # Atomic Safety and Licensing Board Panel, 82/08/18, 167pp 14523.198. 24X Fiche 50-454,82/08/18,8208240415,

- 8208240301 Transcript of 820819 hearing in Rockford, IL Pp 166-205 * Atomic Safety and Licensing Board Panel 82/08/19 4ipp 14524 299 24X Fiche 50-454,82/08/19,8208240301
- DOCKET BIN-50-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8208030058 Extends invitation to attend 820721 meeting of senior public officials to discuss regulatory program for nuclear power plants testifent insp program Agenda encl MENCZER, W B Region 3: Office of Director. 82/07/0: MARKETTI, M Illinois. State of 3pp 14208 339 24X Fichs 50-456, B2/07/01, 8208030058
- 8207080064 Generic ltr to all licenses of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS, M J. Diffice of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York, 93pp 14194 001
 24% Fiche 50-000,82/07/02.8207080064
- 8208050193 Forwards summary of NRC 820721 meeting w/Westinghouse in Bethesda, MD re progress in resolving accelerated tube wear at operating plants w/Westinghouse Model D steam generators, since facilities will utilize Models D-4 & D-5 YOUNOSLODD, B, J Licensing Branch 1 82/07/27 DELOEGROE, L C Commonwealth Edison Co 3pp 14242 (24 24X Fiche 50-000, 82/07/27, 8208050193
- 8208:10243 Forwards request for addl info re water hammer prevention per event at KRSKO reactor in Yugoslavia Test plan to verify that water hammer will not occur should be provided YOUNGBLOOD.B J Licensing Branch I 82/07/30 DELEGROE.L O Commonwealth Edison Co App 1433: 098 24X Fiche 50-000.82/07/30.820810243
- 8208160417 Informs of change in arrangements per util 740613 ltr to NRC re fossil hunting at site Storage shed for unprocessed matl no longer needed & will be removed by 820915 unless NRC disagrees
 TRANH.TR Commonwealth Edison Co 82/08/04, DENTON.H R Offic of Nuclear Reactor Regulation, Director ip 14349 288 24X Fiche 30-456, 62/08/04, 8208160417
- 8208110188 Forwards revised pages to CE-1-A. "Comm Ed QA Program for Nuclear Generating Stations." Revision 21 Revised pages correct typographical & other minor errors SHARTZ.E Commonwealth Edison Co 82/08/06 HAASS.N.P. Quality Assurance Branch ip 14314 077. 24X Fiche 50-000.82/08/06.820810188
- --B208110204 Revised pages to CE-1-A,Revision 21, "Comm Ed QA Program for Nuclear Generating Stations" • Commonwealth Edison Co 82/06/06 11pp 14314.080 24X Fiche 50-000.82/08/06.8208110188
- 8208180002 Forwards response to FSAR questions re vol reduction sys Info should close Outstanding Item 15 of Byron SER TRAKKIT R Commonwealth Edison Co 82/08/04 DENTON, H R. Office of Nuclear Reactor Regulation, Director 19pp 14376 215, 24X Fichs 50-000, 82/08/06, 8208180002
- 8208090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Storist encl EIBENHUT.D O Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356-332 24X Fiche 50-000,82/08/09,8208090194
- 8208170094 Forwards responses to FSAR questions re flexibility of baseplates for pipe supports Review of response to Questions 110 71 & 110 72 should close outstanding Item 5 of FBAR.
 TRAMM.T R Commonwealth Edison Co 82/08/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp. 14358 217 24X Fiche 50-000,82/08/09,8208170094.
- 8208130277 Forwards preliminary revision of Attachment C3 & to Section 3 & of FBAR re main steamline break in main steam tunnel Info will be incorporated into next FSAR amend TRAMM.T R Commonwealth Edison Co 82/08/10 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 26pp 14333 077 24X Ficha 50-000, 82/08/10, 8208130277
- 8208180011 Provides info re circuit change which will aid operator during switchover from ECCS injection to recirculation following LOCA Feature will provide control room indication of safety injection S-signal status
 TRAMM.TR. Commonwealth Edison Co. 82/08/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 14378, 265, 24X
 Fiche 50-000, 82/08/11, 8208180011

- 8208230324 Forwards add1 info re installation of instrumentation for detection of inadequate core cooling Info correlated to Requirements 1-9 for NOREG-0737, Item II F 2
 TRANS.T R Commonwealth Edison Co 82/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 14508 328 24X Fichs 50-000, 82/08/13, 8208230324
- 8208230058 Forwards add1 info re status of various sys important to Human Factors Engineering Branch review of control rooms Second site visit can be scheduled for Feb 1983 or later, which should close out review TRAMM.TR Commonwealth Edison Co 82/08/16 DENTON, HR Office of Noclear Reactor Regulation, Director 3pp 14509 324 24X Fiche 50-000, 82/08/16, 8208230058
- 8208230332 Forwards revised response to FBAR Question 022 54 indicating why power interruption is not practical in case of post-LOCA purge sys isolation valve (1V0003) Response will be incorporated into next FBAR amend TRANH, FR Commonwealth Edison Co 82/08/17 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 14508 258 24X Fiche 50-000, 82/08/17, 8208230332
- B20B270350 Forwards revised FSAR info re protection against possible turbine missiles at facilities Changes will be incorporated into future FBAR amend Info closes Outstanding Item 2 of Byron BER TRAMH,TR Commonwealth Edison Co 82/08/18 DENTON,HR Office of Nuclear Reactor Regulation, Director 70pp 14564 300. 24X Fiche 50-000,82/08/18,8208270350
- B20B310293 Confirms 820B31 meeting at Region 3, to discuss potential NRC actions re installation of steam generators, reactor coolant pumps & pressurizers in apparent violation of numerous GA program requirements KEPPLER, J O Region 3, Diffice of Director B2/0B/25, REED, C Commonwealth Edison Co ip 146B 27B 24X Fiche 50-454, B2/0B/25, B20B310293
- E NRC Sefety Evaluation Report (SER), suppls & correspondence
- 8208170219 Forwards responses to FSAR Questions 22 23 & 22,24, providing results of reanalyses of ECCS performance w/reduced temp of essential sec water to reactor containment fan cooler units SER Confirmatory Issue 19 closed
 TRANN, T R Commonwealth Edison Co 82/08/06, DENTON, H R Office of Nuclear Reactor Regulation, Director App 14361 317, 24X Fiche 50-000,82/08/06,8208170219.
- B20B170240 Forwards info to be included in FBAR re analyses of high & moderate energy pipe breaks NRC review of info should close outstanding Item 3 of Byron SER Revised response to Guestion 10 40 encl TRAHM, T R Commonwealth Edison Co 82/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 15pp. 14368 322 24X Fiche 30-000.82/08/10,8208170240
- F Becurity, medical, emergency & fire protection plans
- 8208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
 FELTON, J M Division of Rules and Records 82/08/12 Document Management Branch Ip 14559 354 24X Fiche 50-000.82/08/12, 8208250359.
- --8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"

 MDDREAR D Commonwealth Edison Co 82/07/19, DENTON, H R NRC No Detailed Affiliation Given 1p 14559 355 24X
 Fichs 50-000, 82/08/12, 8208250559
- --8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures" * Commonwealth Edison Co. 82/06/30. 7pp 14559.396 24X Fiche 50-000.82/08/12.8208250559
- 8208190014 Forwards revised "Fire Protection Rept in Response to Branch Technical Position CMEB 9 5 1 " Revision incorporates safe shutdown analysis submitted in util 820614 ltr & updated comparison W/1067850 App R.
 TRAMM, T R Commonwealth Edison Co 82/08/16. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 14383 214 24X
 Fiche 50-000,82/08/16,8208190014
- --8208190018 Revised "Fire Protection Rept in Response to Branch Technical Position CMES 7.5 1 " * Commonwealth Eduson Co 82/08/16 700pp 14383 219, 24X Fichs 50-000, 82/08/16, 8208170014

DOCKETED ITEMS

- B20B230354 Forwards responses to FSAR Questions 010 55-010 59 re fire protection, requested in NRC B20715 ltr Info will be included in next FSAR amend Responses should close Outstanding Item 13 of Byron SER TRAMM, T R Commonwealth Edison Co 82/0B/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp (450B 285 24X Fiche 50-000, 82/0B/17, B20B230354
- Q Inspection reports. IE Bulletins & correspondence
- 8208030058 Extends invitation to attend 820721 meeting of senior public officials to discuss regulatory program for nuclear power plants & resident insp program Agenda encl HENCZER.W B Region 3. Office of Director 82/07/01 MARKETTI.M Illinois. State of 3pp 14208 339 24X Fiche 50-456,82/07/01. 8208030058
- 8204210393 IE Info Notice 82-23, "Main Steem Isolation Valve (MSIV) Leakage " Svc list encl JGRDAN: E.L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14386 274 24X Fiche, 50-000, 82/07/16, 8204210393
- 820B070091 Forwards IE Insp Repts 50-456/82-03 & 50-457/82-03 en 820524-28 & 0601-04 & notice of violation NORELIUS, C E Division of Engineering & Technical Programs 82/07/16 REED, C Commonwealth Edison Co 2pp 14270 240 24X Fiche 50-456/82/07/16/8208070091
- --9208070074 Notice of violation from insp on 820524-28 & 0401-04 NORELIUB, C E Division of Engineering & Technical Programs 82/07/16 2pp 14270 242 24X Fiche 50-456,82/07/16,8208070071
- --B208090097 IE Insp Repts 50-456/B2-03 & 50-457/B2-03 on B20824-28 & O&01-04 Noncompitance noted, failure of site contractors to follow QC procedures & failure to accompitah activities in accordance w/procedures PEBCHELJ H , LOVE, R S , NEISLER, J H, Region 3, Office of Director B2/06/30 & Sopp i4270 244 24X Fiche: 50-456, B2/07/16, B208090091
- 8204210395 IE Info Notice Bi-26, Part 3. Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list and JURDAN, E. L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358.001 24X Fiche 80-000.82/07/19, 8204210395
- 6204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Syc list encl JORDAN E L Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24% Fiche 30-000, 82/07/20.8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Herafluoride Gverpacks " Svc list encl. COBB.L I. Division of Fuel Facilities, Materials & Bafeguards. 82/07/20 Consolidated Edison Co of New York 7ipp 14357-276 24X Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Natice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN E L Division of Engineering & Quality Assurance. D2/07/22 Consolidated Edison Co. of New York 112pp 14194 321 24X Fiche 50-000,82/07/22,8204210378
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS," Evolist encl JORDAN E.L. Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Byc list encl JURDAN,E L. Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co. of New York 127pp 14194 120, 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Lose of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants." Svc list encl. JORDANIE L. Division of Engineering & Quality Assurance. 82/07/26, Consolidated Edison Co. of New York 121pp. 14357:013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool," Svc list encl JORDANIE L. Division of Engineering & Guality Assurance. 82/07/28, Consolidated Edison Co of New York 122pp, 14357:146, 24X Fiche 50-000, 82/07/28,8204210405.

- 8204210407 IE Info Notice 92-27. "Fuel Rod Degradation Resulting Baffle Water-Jet Impingement " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/6 Consolidated Edison Co of New York 117pp 14388 201 243 Fiche 50-000, 82/08/05, 8204210407
- R Periodic operating raports & related correspondence
- 8208270010 Responds to FOIA request for documents detailing colle dose exposures in 1981 for operating nuclear power plants & analyting said info Forwards documents listed in App A FELTON, J M Division of Rules and Records. 82/07/13 UDELL, R Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270559 Forwards "Recorded Annual Whole Body External Exposu
 CY81," per 10CFR20 407(b) W/o Quad Cities, Zion, LaSalte, Byron
 & Braidwood repts
 RAUSCH, T J Commonwealth Edison Co 82/03/31 Office of
 Hanagement and Program Analysis 1p 14680 075 24X
 Fiche. 50-000, 82/07/13, 8208270010
- S Reportable occurrences, LERs & related correspondence
- 8208130223 Interim deficiency rept re emergency diesel generator relay failure Instially reported on 820702 One contact on relay 14FX found fused closed Relay replaced Final rept expected by 820902
 TRAMN.T.R Commonwealth Edison Co 82/08/02 KEPFLER, J 9 Rd Grifte of Director 2pp 14333 182 24X Fiche 50-006,82/088208130223
- DOCKET STN-50-457 DRAIDWOOD STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8208030098 Extends invitation to attend 820721 meeting of senior; officials to discuss regulatory program for nuclear power plants & resident insp program Agenda enci MENCZER. W B Region 3. Office of Director B2/07/01 MARKETT Illinois. State of 3pp 14208 339 24X Fiche 50-456.82/07/08208030088
- 8207080064 Generic ltr to all licensess of operating plants, applic for DL & holders of CP re Commission approved charter for CROR Sev list encl DIRCKS, W J Defite of the Executive Director for Operations 82/07/02 Consplidated Edison Co of New York 93pp 14194 24% Fiche 50-000, 82/07/02, 8207080064
- 8208050193 Forwards summary of NRC 820721 meeting w/Westinghouse Bethesda-MD re progress in resolving accelerated tube wear at operating plants w/Westinghouse Model D steam generators, since facilities will utilize Models p-4 & 0-5 YQUNQRLOOD,B. J. Licensing Branch 1 82/07/27 DELGEORGE,L O Commonwealth Edison Co. Spp. 14242 124 24X Fiche 50-000.82/(8208050193
- B208110243 Forwards request for addl info re water hammer prevent per event at KRSKO reactor in Yugoslavia Test plan to verify that water hammer will not occur should be provided YOUNGELOOD, B. J. Licensing Branch I, 82/07/30 DELOEUROE.L. Commonwealth Edison Co. App. 14331 097, 24% Fiche 50-000,82/(8208110243
- 8208160417 Informs of change in arrangements per util 740613 ltr to NRC re fossil hunting at site Storage shed for unprocessed matino longer needed & will be removed by 820915 unless NRC disagrees.
 TRAMM.T.R. Commonwealth Edison Co. 82/08/04 DENTON.H.R. Of of Nuclear Reactor Regulation, Director. ip 14349,288, 24x Fiche 50-456.82/08/04,8208160417.
- 820811018B Forwards revised pages to CE-1-A, "Comm Ed QA Program Nuclear Generating Stations," Revision 21. Revised pages correct typographical & other minor errors SWARTZ, E Commonwealth Edison Co 82/08/06 MAASS, W.P. Quel Assurance Branch. 1p 14314-079 24X Fiche: 50-000, 82/08/06, 82/081018B.
- ---8208110204 Revised pages to CE-1-A, Revision 21, "Comm Ed QA Proj Nuclear Generating Stations" 4 Commonwealth Edison Co. 82/06/06, 11pp 14314.080, 24X Fiche' 50-000, 82/08/06, 8208110188.
- 8208180002 Forwards response to FSAR questions re vol reduction s Info should close Outstanding Item 15 of Byron SER TRAMH.T R Commonwealth Edison Co. 82/08/06. DENTON.H.R Of of Nuclear Reactor Regulation. Director 19pp. 14376 215 24: Fiche: 50-000.82/08/06.8208180002

DOCKETED ITEMS

- 8090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & pplicants re submittal of documents to NRC Summarizes 10CFR hapter I requirements & provides alternatives to equirement swc list encl 16ENHUT, D 0 Division of Licensing 82/08/07 Consolidated dison Co of New York 1p 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 817009A Forwards responses to FBAR questions re flexibility of assplates for pipe supports Review of response to Guestions 10 71 & 110 72 should close outstanding Item 5 of FBAR RAMM, T.R. Commonwealth Edison Co. 82/08/09 DENTON, H.R. Def f Nuclear Reactor Regulation, Director 9pp 14358 217 24X iche 50-000, 82/08/09, 8208170096 Office
- Bi30277 Forwards preliminary revision of Attachment C3 6 to Section 6 of FSAR re-main steamline break in main steam tunnel nfo will be incorporated into next FSAR amend RAMM.T.R Commonwealth Edison Co 82/08/10 DENTON.H R Office f Nuclear Reactor Regulation, Director 26pp, 14333 077 24X iche 50-000,82/08/10,8208130277
- BIBOOII Provides info re circuit change which will aid operator uring switchover from ECCS injection to recirculation ollowing LOCA Feature will provide control room indication of safety injection S-signal status RAMMITR. Commonwealth Edison Co. 82/08/11 DENTON, H.R. Offi Nuclear Reactor Regulation, Director 2pp. 14378-285. 24X iche 50-000, 82/08/11,8208180011
- 3230324 Forwards add1 info re installation of instrumentation for restion of inadequate core cooling Info correlated to squirements 1-9 for NUREO-0737, item II F 2
 RAMN T R Commonwealth Edison Co 82/08/13 DENYGN.H R Office
 1 Nuclear Reactor Regulation, Director 4pp 14508 328 24X iche: 50-000, 82/08/13, 8208230324.
- 1230058 Forwards add1 info re status of various sys important to man Factors Engineering Branch review of control rooms scond site visit can be scheduled for Feb 1983 or later, sich should close out review (AMM-T.R Commonwealth Edison Co 82/08/16 DENTON, H R Offic Nuclear Reactor Regulation, Director 3pp 14517-324 24X che: 50-000, 82/08/16, 8208230058
- Office
- 1230332 Forwards revised response to FSAR Question 022 54 indicating w power interruption is not practical in case of post-LOCA rge sys isolation valve (1V0003). Response will be corporated into next FSAR amend AMM. T R Commonwealth Edison Co. 62/08/17 DENTON, H.R Dffice Nuclear Reactor Regulation, Director 2pp 14508 258 24% che 50-000, 82/08/17. 6208230332
- 270350 Forwards revised FSAR info re protection against possible rbine missiles at facilities Changes will be incorporated to future FSAR amend. Info class Outstanding Item 2 of
- ren SER.
 AMM.T R. Commonwealth Edison Go 82/08/18 DENTON,H R. Office Nuclear Reactor Regulation, Director 70pg 14564 300. 24X che. 80-000.82/08/18,8208270350
- 310293 Confirms 820831 mesting at Region 3.to discuss potential C actions re installation of steam generators, reactor clant pumps & pressurizers in apparent violation of merous 64 program requirements.

 PPLER.J.O Region 3. Office of Director 82/08/25 REED.C. mesonwealth Edison Co ip 14688:278 24X Fiche:50-456.82/08/25, 08310273
- RC Safety Evaluation Report (BER), supple & correspondence
- 170219 Forwards responses to FBAR Questions 22 23 & 22.24, providing sults of reanalyses of ECCS performance w/reduced temp of sential svc water to reactor containment fan cooler units. Confirmatory Issue 19 closed wft. T R Commonwealth Edison Co 92/08/06, DENTON, H R. Office Nuclear Reactor Regulation, Director. App. 14361:317 24X he.50-000, 82/08/06, 8208170219
- 70240 Forwards info to be included in FBAR re analyses of high inderate energy pipe breaks, NRC review of info should see outstanding Item 3 of Byron SER. Revised response to stion 10 40 enc!

 Mf.T.R. Commonwealth Edison Co 82/08/10 DENION.H R. Office Nuclear Reactor Regulation, Director 15pp, 14368.322 24X he 50-000,82/08/10,8208170240.

- F Becurity, medical, emergency & fire protection plans
- 9208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures" FELTON.J M Division of Rules and Records 82/08/12 Docum Management Branch 1p 14559 354 24X Fiche 50-000.82/08/12.
- --8208260024 Forwards public version of Revision 2 to "Environ Assistant Directory for Environ Director Emergency Plan Implementing Procedures." Procedures."
 MOORE,R D Commonweelth Edison Co
 No Detailed Affiliation Given 1p
 Fiche, 50-000,82/08/12,8208250557 82/07/19 DENTON, H R NRC -14559, 355 24X
- -8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures " + Componeealth Edison Co 82/06/30, 7pp 14559:356 24X Fiche 50-000,82/08/12,8208250559
- 8208190018 Revised "Fire Protection Rept in Response to Branch Technical Position CMEB 9 5 1 " * Gommonwealth Edison Co 82/08/16. 700pp. 14383 219, 24X Fiche 50-000.82/08/16.8208190014
- B20B230354 Forwards responses to FBAR Questions 010 55-010 57 re fire protection requested in NRC B20715 ltr Info will be included in next FSAR amend, Responses should close Outstanding Item 13 of Byron SER TRAMM.TR Commonwealth Edison Co. 82/08/17 DENTON, H.R of Nuclear Reactor Regulation, Director 11pp 14508 285. Fiche: 50-000, 82/08/17, 8208230354 Office
- 8208190014 Forwards revised "Fire Protection Rept in Response to Branch Technical Position CMES 9 5 i," Revision incorporates safe shutdown analysis submitted in util 820614 ltr & updated comparison w/locfR50 App R
 TRAMM-T R Commonwealth Edison Co. 82/08/16 DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp. 14383 214. 24X
 Fiche 50-000,82/08/16,8208190014
- @ Inspection reports, IE Bulletins & correspondence
- 8208030058 Extends invitation to attend 820721 meeting of senior public officials to discuss regulatory program for nuclear power plants & resident insp program Agenda encl MENCZER, M B Region 3. Office of Director 82/07/01 MARKETTI, Illinois, State of 3pp 14208 339, 24X Fichs: 50-456, 82/07/01. MARKETTI.H. 820803005B.
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl. JORDAN E L Division of Engineering & Guality Assurance. 82/07/12 Consolidated Edison Co of New York 87pp. 14356.274. 24X Fiche. 50-000, 82/07/12, 8204210393.
- #208090091 Forwards IE Insp Repts 50-456/82-03 & 50-457/82-03 on 820524-28 & 0601-04 & notice of violation, NORELIUS, C E. Division of Engineering & Technical Programs, 82/07/16 REED, C. Gomeonwealth Edison Co. 2pp. 14270:240. 24X Fichs 50-456,82/07/16,8208090091
- --8208090094 Notice of violation from insp on 820524-28 & 0601-04 NORELIUB, C E Division of Engineering & Technical Programs. 82/07/16. 2pp 14270-242. 24X Fiche. 50-456, 82/07/16, 8208090091.
- --8208090097 IE Insp Repts 50-456/82-03 & 50-457/82-03 on 820524-28 & 0601-04 Noncompliance noted failure of site contractors to follow OC procedures & failure to accomplish activities in accordance w/procedures.
 PESCHELJ H., LOVE, R. B., NEISLER, J. H., Region 3, Office of
 Director 92/06/30. 60pp 14270: 244. 24X Fiche: 50-456, 82/07/16, 8208090091
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clerification of Placement of Personnal Monitoring Devices for External Radiation," 8vc list encl.

 JGRDAN, E.L. Division of Engineering & Quality Assurance, 82/07/19, Michigan, Univ. of, 112pp. 14358-001, 24X Fiche; 80-000, 82/07/19, 8204210395.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure" Svc list encl.
 URDAN.E.L. Division of Engineering & Quality Assurance, 82/07/20.
 Consolidated Edison Co. of New York, 112pp. 14381:001, 24X
 Fiche: 50-000, 82/07/20, 8204210394

04210397 IE Info Notice 82-24, "Water Leaking From U Hetafluoride Overpacks" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safequards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 274 24% Fiche 50-000,82/07/20,8204210397

04210398 IE Info Notice 82-26, "RGIC & HPGI Turbine Exhaust Check Valve Failures " Byc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche:50-000,82/07/22,8204210398

04210401 IE Info Notice B2-28, "Hydragen Explosion While Grinding in Vicinity of Dreined & Open RCS " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche.50-000,82/07/23,8204210401

04210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co. of New York. 127pp 14194 120 24X Fiche: 50-000, 82/07/23, 8204210402

04210403 IE Info Notice 82-30, "Loss of Thermal Sleaves in RCS Piping at Certain Westinghouse PWR Power Plannts" Svc list encl JORDAN,E.L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357.013 24X Fiche 50-000, 82/07/26, 8204210403

04210405 IE Info Notice 82-31, "Overexposure of Diver Buring Work in Fuel Storage Pool," Svc list encl MRDAN,E L. Division of Engineering & Quality Assurance 62/07/28 Consolidated Edison Co. of New York 122pp 14357:146 24X Fichs 50-000, 82/07/28, 8204210405

)4210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement " Syc list encl MRADAN.E L Division of Engineering & Quality Assurance E2/08/05. Consolidated Edison Co of New York 117pp. 14388 201 24X Tiche. 50-000, 82/08/05, 8204210407

Periodic operating reports & related correspondence

18270010 Responds to FOIA request for documents detailing collective lose exposures in 1991 for operating nuclear power plants & malyring seld info. Forwards documents listed in App A ELTON, J M Division of Rules and Records 82/07/13 UDELL, R A ELTON, J M Division of Rules and Records 82 Fritical Mass Energy Project 8p 14679 208 1cha 50-000, 82/07/13, 8208270010

Reportable occurrences. LERs & related correspondence

8130223 Interim deficiency rept re emergency diesel generator field elay failure initially reported on 820702 One contact on elay 14FX found fused closed Relay replaced. Final rept

rpected by 820902 RAMH.T.R. Commonwealth Edison Co. 82/08/02 KEPPLER.J.Q. Region . Office of Director. 2pp 14333 182 24% Fiche 50-000.82/08/02. RAMM, T, R 208130223.

KET 50-458 RIVER BEND STATION, UNIT 1

Application/construction stage documents & correspondence

7080064 Generic 1tr to all licensees of operating plants applicants or GL & holders of CP re Commission approved charter for RGR SIVE list encl.

18CKS.W J Office of the Executive Director for Operations 2/07/02 Consolidated Edison Co of New York, 73pp. 66247,23144 Fiche,50-000,82/07/02,8207080064.

3130029 Forwards request for add1 info re recent Mark []] intainment concerns Submittal schedule should be provided ithin 14 days of receipt of 1tr
:HHENGER, A Licensing Branch 2. 82/07/23. CAHILL.W J. Oulf
tates Utilities Co. 15pp. 14341.349 24X Fiche 50-458.82/07/23. 208130029

- 8208050180 Forwards proposed agenda & list of questions from Instrumentation & Control Sys Branch for upcoming instrumentation & control meetings Proposed schedula for conducting meetings requested within 2 wks SCHWENCER.A Licensing Branch 2 82/07/28 CAMILL.W J States Utilities Co. 22pp 14242 089 24X Fiche 50-458.8 82040304040 24X Fiche 50-458, 82/07/28,
- 8208050048 Forwards request for add1 info re qualification of safety-related equipment for hydrodynamic loads Effects of large number of cycles of dynamic loading fue to suppression pool hydrodynamic loading may not be a
- 8208090194 Generic Ltr B2-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D 0 Division of Licensing B2/08/09 Consolidated Edison Co of New York, 1p 14356.332 24X Fiche 50-000.82/08/09.8208090194
- 8208200031 Forwards results of review of remote shutdown sys & comparison w/Instrumentation Control Bys Branch position Bys masts General Design Criterion 19.App K & App R bys mosts General Design Criterion 19, App K & App R requirements
 BOOKER.JE GULF States Utilities Co. 82/08/13 SCHWENGER, A Licensing Branch 2 3pp 14392 252 24% Fiche 50-458,82/08/13,8208200031
- 8208230295 Advises that responses to 820623 & 0723 ltrs re containment concerns will be combined w/Mark III containment issues owners group siforts BOOKER, J E Oulf States Utilities Co 82/08/13 SCHWENGER, A Licensing Brench 2 ip 14509 358 24X Fiche 50-458,82/08/13,6208230275.

Q Adjudicatory correspondence

8208030570 Hemorandum & order granting Louisianians for State Energy. Inc & GR Rothschild patitions to intervene contingent upon timely filing of one admissible contention Contentions due by 820907 Prehearing conference scheduled for 821017 COTTER.B F. Atomic Safety and Licensing Board Panel 82/07/30, Louisianians for Bafe Energy.Inc. 9pp. 14162 076 24X Fiche 50-458,82/07/30,8208030570,

8208240207 Order amending dates in ASLB 820730 order re filing of contentions Fuel loading dates & dates for issuance of SER & FEB changed, res changes. 1,B.P. Atomic Safety and Licensing Board Panel 82/08/20. 14519.076 24% Fiche.50~458/82/08/20.8208240207 COTTER B. P.

H General correspondence

8208270469 Discusses procedures re syc of relevant documents & changes & clarifications to present syc list Updated syc list encl.
WETTERHAKNIM J Conner & Wetterhalm METTERHAKNIM J Gulf States Utilities Co 82/08/20 COTTER. B P Abomic Safety and Licensing Board Panel 3pp 14565, 327 24% Fiche: 50-458, 82/08/20, 8208270469.

Q Inspection reports. IE Bulletins & correspondence

82042(0393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl, JORDAN.E L. Division of Engineering & Guality Assurance 82/07/9 Consultdated Edison Co. of New York 87pp 14386-274 24X Fiche 50-000,82/07/16,8204210393 82/07/16

8204210375 IE Info Notice 81-26, Part 3, Buppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl, JOROAN, E. L. Dyision of Engineering & Guality Assurance 82/07/19 Michigan, Univ, of 112pp. 14358:001 24X Fiche 50-000,82/07/19,004210

8208030135 Forwards IE Insp Rept 50-458/82-06 on 820614-18, No noncompliance noted.

HADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. 82/07/19. CARLLLH J. Guif States Utilities Co. 2pp. 14213.102 24X Fiche 80-458,82/07/19.8208050135

--8208080107 IE Insp Rept 30-456/82-06 on 820614-18 No noncompliance noted. Major areas inspected: previous insp findings; GA program review & work for erection/installation & welding of safety-related structural starl & supports.

JOHNSON, C. E., ROBERDB, M. J., CROSSMAN, W. A., Division of Resident, Reactor Project & Engineering Programs. S2/07/15 7pp 14213, 104 24% Fiche. 50-458, 82/07/19,8208030135.

- 8204210376 IE info Notice 82-25, "Pailures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN E L Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000 82/07/20 8204210396
- 8204210397 IE Info Notice 82-24, "Mater Leaking From U Hexafluoride Gverpecks" 8vc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/22. Consolidated Edison Co of New York 112pp 14174:321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 JE Info Notice 82-29, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS." Svc list encl JORDAN E. L. Division of Engineering & Guelity Assurance. 82/07/23 Consolidated Edison Co of New York 122pp 14380:115 24X Fiche 50-000, 92/07/23,8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Hestinghouse PHRs " Svc list encl. JORDAN E. L. Division of Engineering & Quality Assurance, 82/07/23, Consolidated Edison Co of New York, 127pp 14194:120, 24X Ficher 50-000, 82/07/23, 8204210402
- 8204210403 IE lnfo Notice 82-30, "Loss of Thermel Bleaves in RCS Piping at Certain Hestinghouse PHR Power Plants " Syc list and URBAN.E. L. Division of Engineering & Quality Assurance 82/07/26 Consplidated Edison Co. of New York 12ipp. 14357-013 24X Fiche 50-000, 82/07/26, 8204210403.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool," Svc list encl JORDAN-E L. Division of Engineering & Quality Assurance 82/07/28 Consolidate Edison Co of New York 122pp. 14357:146 24X Fiche.50-000.82/07/28,8204210405.
- 8208200179 Forwards IE Insp Rept 50-458/82-08 on 820515-0630 No noncompliance noted.

 MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. 82/07/29 CAMILL, N. J. Quif States Utilities Co. 2pp. 14399.156 24x Fiche 50-458/82/07/29,8208200179.
- --B208200195 IE Insp Rept 50-458/82-08 on 820515-0630, No noncompliance noted Major areas inspected reactor coolent pige welding, storage & maint, welding activities & electrical installation activities.

 BROWN:R L r CROSSHAN.W A Division of Resident, Reactor Project & Engineering Programs. 82/07/27, 6pp. 14399:158. 24X Fiche 50-458,82/07/29,8208200179
- 820819023; Forwards IE Insp Rept 50-458/82-07 on B20628-0702.No nuncompliance nated MADSEN:0 L. Division of Resident, Reactor Project & Engineering Programs. 82/08/04, CAHILL:N J Gulf States Utilities Co 2pp 14387 180. 24X Fiche.50-458.82/08/04.8208190231.
- --B208190241 IE Insp Rept 50-458/82-07 on B20628-0702 No noncompliance noted Hajor areas inspected QA program for receipt, storage, installation, identification & separation of electrical cable & associated components.

 REDANGER T. HUNNIGUTT. D.M. Region 4. Office of Director.

 CROSSHAN, H. A. Division of Resident, Reactor Project & Engineering Programs. 82/07/27. 7pp. 14387-182. 24X Fiche: 50-458, 82/08/04, 8208190231.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Syc list encl JORDAN: E.L. Division of Engineering & Quality Assurance. 82/08/05, Consolidate Edison Co of New York. 117pp. 14288-201 24X Fichs: 30-000, 82/08/05, 8204210407
- 8208190211 Ack receipt of 820723 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/82-05, MADSEN 0 L. Division of Resident, Reactor Project & Engineering Programs 82/08/13. CARILL, W. J. Quif 98ates Utilities Co. 1p. 14387.049. 24X Fiche: 50-458, 82/08/13, 8208190211
- --8208170217 Responds to NRC 820623 ltr re violations noted in IE Insp Rept 50-438/82-05 Corrective actions, weld technique sheet H3-N888-54 corrected to reflect min travel speed used & personnel reinstructed re weld orientation & mail control. CAMILL, M. D. Gulf States Utilities Co. 82/07/23. COLLINB, J.T. Resion 4. Office of Director. 3pp. 14387:050. 24X Fiche: 50-458,82/08/13,8208190211.

5 Reportable occurrences, LERs & related correspondence

- 8208030283 Final deficiency rept re arc strikes found on Graver shopfabricated drywell items such as penetrations; beam seate, liner plates & electrical couplings Initially reported on 820430 Condition not reportable under 10CFR50 55(a) 800XER, J E. Quif States Utilities Co. 82/07/26 COLLINS, J T Region 4, Office of Director ip 14156 236 24X Fiche 50-458, 82/07/26, 8208030283.
- 8208090314 Interim deficiency rept re Velan Engineering supplied valve stud metl not recognized under ABME Section III Initially reported on 820629 Investigation of deficiency incomplete Next rept will be provided by 820909 800KER, J E gulf States Utilities Co 82/07/28 COLLINS, J T Region 4, Office of Director ip 14297, 329, 24X Fiche 50-438,82/07/28,8208050316
- 8208050110 Final deficiency rept re documentation of A 500 Grade B steel tubing supplied by Bergen Paterson Evaluation determined only acceptable mati shipped to site therefore condition not reportable per IOCFR50, 35(e) 800MER. J E gulf States Utilities Co 82/07/29 COLLING, J T. Region 4. Office of Director in 14213 027 24X Fiche 50-458, 82/07/29, 8208050110
- 8208100090 Interim daficiency rept re weld defects in Graver shop weld for containment personnel air lock Initially reported on 820702 Investigation incomplete Next rept will be provided by 821006
 BOOKER, JE Oulf States Utilities Co 82/08/02 COLLINS, J. T Region 4, Office of Director ip 14297: 353 24X
 Fiche 50-458, 82/08/02, 8208100090.
- 820B16000B Interim deficiency rept re self-aligning ball bushings that may disengage from Bergen-Paterson snubber & eway strut assemblies initially reported on B20426 StM raview continuing Nezt rapt will be submitted by 820914 BODKER, J E Oulf States Utilities Co 82/08/06 COLLINS, J T Region 4. Office of Director ip 14344, 351 24X Fiche 30-458, 82/08/06, 820816000B
- 820B170137 Interim deficiency rept re unsatisfactory insps performed by former field QC inspector Initially reported on 820329 Re-evaluation of Insps in progress Next rept will be provided by 820930 BOOKER, J E Quif States Utilities Co 82/08/09, COLLINS, J T. Region 4. Office of Director ip 14358 202 24X Fiche: 50-458, 82/08/09, 8208170137
- 8208240047 Interim deficiency rept re HPCS diesel generator radioactive heat loss value, initially reported on 820212. Util awaiting info from OE re cause of deficiency to necessary corrective actions Next rept expected by 821028 800KER. J E Oulf States Utilities Co 82/08/13 COLLINS. J T Ragiom 4. Office of Director. ip 14520 014 24X Fiche: 50-458, 82/08/13, 8208240047
- 8208240063 Final Deficiency Rept DR-31 re loose mounting screws or fasteners used to assemble or mount position switch assembly on Limitorque valve motor operators. Initially reported on 811211 Limits switches to be restored 800KER. J E Quif States Utilities Co 82/08/13 COLLING. J T Region 4. Office of Director 2pp 14519; 357 24X Fichs 50-458, 82/08/13, 82/08240063
- 9208240393 Final Deficiency Repts DR-33 & DR-41 re improperly installed spring nuts & torquing requirements for spring nuts Initially reported on 820211 & 0308, respectively Bafety not adversely effected. Not reportable under 100FR50 55(s) 800KER.J E Oulf States Utilities Co 82/08/13 COLLING.J T. Region 4, Office of Director ip 14522 356. 24X Fiche: 50-458, 82/08/13, 8208240393
- 8208310256 Final deficiency rept re 10 stainless steel forgings delivered from suspect heat lot. Initially reported on 820304 Reinsp uncovered no met! deficiencies Deficiency not reportable per 100FR50 55te).

 800KER. J E Quif States Utilities Co. 82/08/23, COLLING, J. T. Region 4. Defice of Director ip 14689-166, 24X Fiche: 50-458, 82/08/29, 8208310256
- U. Congressional/Executive Correspondence
- 8208070302 Advises that no assessments made in 1982 re plant const schedule & no assessments scheduled to be made in FY82; in response to 820328 request. SCHWENCER.A. Licensing Branch 2 82/07/28, POWELL.T Louisiana; State of. 1p 14307-107, 24X Fichs 50-458,82/07/28,8208070302.

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

- 8207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Byc list encl
 DIRCKB, W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 66247-231
 24X Fiche \$0-000,82/07/02,8207080064
- 8208130029 Forwards request for add1 info re recent Mark III containment concerns Submittal schedule should be provided within 14 days of receipt of itr SCHMENCER,A Licensing Branch 2 82/07/23 CAHILL,H J Gulf States Utilities Co 15pp. 14341 349 24X Fiche 50-459,82/07/23,8208130029
- 8208030180 Forwards proposed agenda & list of questions from Instrumentation & Control Bys Branch for upcoming instrumentation & control meetings Proposed schedule for conducting meetings requested within 2 wks.

 BCIMENCER.A Licensing Branch 2 82/07/28 CAHILL.W J Qulf States Utilities Co 22pp. 14242 089 24X Fiche 50-458,82/07/28,820805080
- 8208030048 Forwards request for add1 info re qualification of safety-related equipment for hydrodynamic loads Effects of large number of tycles of dynamic loading due to suppression pool hydrodynamic loading may not be adequately accounted for SCHHENCER, A Licensing Branch 2 82/07/30 CAHILL, H.J. Qulf States Utilities Co. Spp. 14244 036 24X Fiche 50-458,82/07/30,8208050048
- 8208090174 Owneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT, D G Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14354 332 24X Fiche. 50-000, 82/08/09, 8208090174.
- B208200031 Forwards results of review of remote shutdown sys & comparison w/Instrumentation Control Sys Branch position.

 Sys meets General Design Criterion 19. App K & App R requirements.

 BOOKER. J E Gulf States Utilities Co 82/08/13 SCHWENCER, A. Licensing Branch 2 3pp 14392 252 24X Fiche 50-458,82/08/13.8208200031
- 8208230275 Advises that responses to 820623 & 0723 ltrs re containment concerns will be combined w/Mark III containment issues owners group efforts.

 800KER, J E gulf States Utilities Co 82/08/13 8CHMENCER, A Licensing Branch 2 ip 14507-358 24X Fiche.50-458,82/08/13,8208230275

Q Adjudicatory correspondence

- 8208030570 Memorandum & order granting Louisianians for State Energy, Inc & OR Rothschild patitions to intervene, contingent upon timely filling of one admissible contention Contentions due by 820907 Prehearing conference scheduled for 821019.
 COTTER, B.P. Atomic Safety and Licensing Board Panel. 82/07/30. Louisianians for Safe Energy, Inc. 7pp. 14162:076 24X Fiche 50-458, 82/07/30. 8208030570.
- 8208240207 Order amending dates in ASLB 820730 order refiling of contentions Fuel loading dates & dates for issuance of SER & FEB changed COTTER, B.F. Atomic Bafety and Licensing Board Panel. 82/08/20. 2pp. 14519 076. 24X Fiche: 50-458, 82/08/20, 8208240207

H General correspondence

- 8208270467 Discusses procedures releve of relevant documents & changes & clarifications to present svc list. Updated svc list encl WETTERHAHN, M J. Conner & Wetterhahn. WETTERHAHN, M J. Oulf States Utilities Co. 82/08/20 COTTER: B P. Atomic Bafety and Licensing Board Panel. 3pp. 14565.327. 24X Fiche.50~458,82/08/20,8208270469.
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Mein Steam Isolation Valve (MSIV)
 Leakage " Svc list encl.
 JORDAN,E.L. Division of Engineering & Quality Assurance. 82/07/16.
 Consolidated Edison Co. of New York 87pp 14356:274. 24X
 Fiche 50-000, 82/07/16, 8204210393.

- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnal Monitoring Devices for External Radiation" Syc list encl.

 JORDAN, E.L. Division of Engineering & Quality Assurance, 82/07/19

 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure," Syc list encl JORDAN.E L Division of Engineering & Quality Assurance, 82/07/20, Consolidated Edison Co. of New York 112pp 14381,001 24X Fiche. 50-000, 82/07/20, 8204210396
- B204210377 IE Info Notice B2-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards. 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & IPCI Turbine Exhaust Check Valve Failures " Svc list encl JURDAN,E L Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co of New York. 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210398.
- B204210401 lE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCB " Svc list encl URDAN,E L Division of Engineering & Guality Assurance B2/07/23 Consolidated Edison Co of New York, 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401.
- 8204210402 IE Info Notice 82-27, "Control Rod Drive (CRD) Ouide Tuba Bupport Pin Failures at Westinghouse PHRs." Byo list encl JORDAN, E. Division of Engineering & Quality Assurance B2/07/23, Consolidated Edison Co. of New York 127pp 14174-120, 24% Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sheeves in RGS Piping at Certain Hestinghouse PWR Power Plants." Svc list encl JORDAN E. L. Division of Engineering & Quality Assurance 82/07/26. Consolidated Edison Co of New York 12ipp. 14357,013 24X Fiche 50-000. 82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overesposore of Diver During Work in Fuel Storage Pool," Svc list encl URDAN,E.L. Division of Engineering & Quality Assurance, 82/07/28 Consolidate Edison Co of New York 122pp 14357.146 24X Fiche: 50-000, 82/07/28, 9204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " Bvc list encl JORDANIEL Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York. 117pp 1438R.201. 24X Fiche: 50-000, 82/08/05, 8204210407
- U Congressional/Executive Correspondence
- 8208090302 Advises that no assessments made in 1982 re plant const schedule & no assessments scheduled to be made in FY82, in response to 820528 request 86MHENCER.A Licensing Brench 2 82/07/28 POWELL.T. Louisiana, 8tate of ip 14307 107 24% Fiche 50-458,82/07/28,8208090302
- DOCKET 50-460 WPPBB NUCLEAR PROJECT. UNIT 1
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR 8vc list encl.
 DIRCKS,W J. Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York. 93pp. 14194:001.
 24X Fiche:50-000,82/07/02,8207080064
- 8208040631 Advises that NRC proceeding w/docketing util OL application. Final design will satisfy requirements of any future regulations promulgated between docketing date & resumption of const.

 EISENHUT.D. O Division of Licensing 82/07/16 FERGUSON.R. L. Hashington Public Power Supply System 60pp. 14227-289, 24X Fiche. 30-460, 82/07/16.8208040631.
- 8208110088 Forwards notices of receipt of application for OL, availability of environ rept, consideration of issuance of OL & opportunity for hearing ADENBAM, E.O. Licensing Branch 4 82/07/30, FEROUSON, R L Washington Public Power Supply System. 3pp 14329 336 24X Fiche: 50-440, 82/07/30, 8208110058.

- --8208110061 Notices of receipt of application for OL, availability of environ rept, consideration of issuance of OL & opportunity for hearing Newspaper advertisement notifying public of opportunity to participate in NRC licensing action encl ADENSAME 0 Licensing Branch 4 82/07/30 9pp 14329 339 24% Fiche 50-460, 82/07/30, 8208110038
- 8208100072 Confirms 820727 telcon re use of ASME Code Case N-308, "Documentation of Repairs & Replacement of Components in Nuclear Power Plants " Util uill implement code case as written & approved by NRC BOUCHEY, 0 D Washington Public Power Supply System 82/08/04 EISENMUT, D Q. Division of Licensing is 14276 180 24X Fiche 50-397, 82/08/04, 8208100072
- 8208100290 Submits corrections to design power levels listed in FR notice transmitted w/E9 Adensam 820730 ltr BUUCHEY, 0. D Washington Public Power Supply System 82/08/06 ADENSAM: E 9 Licensing Branch 4 ip 14294 353 24X Fiche 50-460-82/08/06.8208100290
- 8208090194 Qeneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISEMHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208310382 Informs of putential changes to 844 Topical Rept BAM-10082. "Qualification of Safety-Related Instrument & Control Sys." as result of impact of 10CFR50 49 BOUCHEY: 9 D Washington Public Power Supply System 82/08/26 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E O. Licensing Branch 4 ip 14694.330 24X Fiche 50-460.82/08/26.8208310382
- --8208310391 Provides summary of B&W owners group 820720 meeting reculminating dislogue on stope of program for resolution of NUREO-0737. Item II K 3 30, "100FR50 App K Small Breat LOCA Nethods "
 BBUCHEY.0 D Washington Public Power Supply System 82/08/25 DENTON. H R Office of Nuclear Reactor Regulation, Director, ADENSAM, E & Licensing Branch 4 10pp 14694 331 24X fiche 30-460.82/08/26.9208310382
- C Utility Environmental Report (ER), amends & correspondence
- 8208110058 Forwards notices of receipt of application for OLavailability of environ rept, consideration of issuance of OL 4 opportunity for hearing ADENBAM, E. O Licensing Branch 4 82/07/30 FERGUSON, R L Hashington Public Power Supply System 3pp 14329 336 24X Fiche. 50~460, 82/07/30, 8208110058
- --8208110061 Notices of receipt of application for DL, availability of environ rept, consideration of issuance of DL & opportunity for hearing. Newspaper advertisement motifying public of opportunity to participate in NRC licensing action encl ADENBAMIE.O. Licensing Branch 4 82/07/30 9pp 14329 339 24X Fiche 50-440.82/07/30.8208110058.
- 820B100101 Forwards affidavit re distribution of FSAR.environ rept & application & general info.in response to NRC 820716 1tr BOUCHEV.O.D. Washington Public Fower Bupply System 82/08/05 ADENSAM.E G Licensing Branch 4 9pp 14297 319 24X Fiche.50-460.82/08/05.820B100101

ility Final Bafety Analysis Report (FSAR) & amends

O0101 Forwards affidavit re distribution of FBAR, environ rept & lication & general info, in response to NRC 820716 ltr . AUCHEY, O.D. Washington Public Power Bupply System 82/08/05 DENSAM E.O. Licensing Branch 4. Spp. 14297 319 24X Tiche: 50-460, 82/08/05, 8208100101.

- Inspection reports. IE Bulletins & correspondence
- 3207130400 Forwards IE Insp Repts 50-460/82-09 & 50-513/82-05 on 820501-28 & notice of violation 816HOP.T.W Division of Resident, Reactor Project & Engineering Programs 82/06/24 R00T.R.W. Mashington Public Power Supply Bystem 2pp 13851-028 24X Fiche 50-460,82/06/24,8207150400.
- --8207150411 Notice of violation from insp un 820501-28 DDDDS.R T Division of Resident, Reactor Project & Engineering Programs. 82/06/24 2pp. 13851 030 24X Fiche: 50-460,82/06/24, 8207150400

- -8207150421 IE Insp Repts 30-440/82-09 & 50-513/82-05 on 820501-28
 Noncompliance noted electrical contractor subcontracted
 installation of electrical penetration assemblies w/o
 inclusion of appropriate installation procedures
 TOTH, A D , DODDS, R T Division of Resident, Reactor Project &
 Engineering Programs 82/06/23 15pp 13851 032 24X
 fichs 50-440,82/06/24,8207130400
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list enc1 JURDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000.82/07/16.8204210393
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Histoigen, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/17,8204210375
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list and I JORDAN.E L Division of Engineering & Quality Assurance B2/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Ficha: 50-000.82/07/20,8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexefluoride Overpacks " 8vc list enc! COBB-L I Division of Fuel Facilities. Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276. 24X Fichs 50-000,82/07/20,8204210397
- 8208160589 Forwards IE Insp Rept 50-460/82-10 on B20607-18 No noncompliance noted BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 82/07/20 ROOT,R W Washington Public Power Supply System 2pp 14349
- --B20Bi6039B IE Insp Rept 50-460/82-10 on B20607-18 No noncompliance noted Major areas inspected reactor coolant loop piping weld heat treatment, mechanical contractor documentation review & correction activities & previously identified items TOTH.A D . DDDBs.R T Division of Resident, Reactor Project & Engineering Programs 82/07/15 12pp 14349 128 24X Fiche 50-460,82/07/20,820B1603B9
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " 8vc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208160203 Forwards IE Insp Rept 50-460/82-ii on 820628-0702 No noncompliance noted BISHOP:T W Division of Resident, Reactor Project & Engineering Programs 82/07/22 RODT:R W Washington Public Power Supply Bystem 4pp 14342 335 24% Fiche 50-460,82/07/22,8208160203
- --8208160208 IE Insp Rept 50-460/82-11 on 820628-0702. No noncompliance noted Major areas inspected allegation re HVAC contractor. licensee action on previous insp findings & action on IE circulars

 NARBUT.P P. DODDB.R T Division of Resident, Reactor Project & Engineering Programs 82/07/21 12pp 14342-339 24X Fiche 50-460,82/07/22.8208160203
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance \$2/07/23, Consolidated Edison Co of New York. 122pp 14380 115 24X Fiche. 50-000. 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tubs Support Pin Failures at Hestinghouse PHRs " Svc list encl JORDAN.E L. Division of Engineering & Guality Assurance, 82/07/23 Consolidated Edison Co of New York 127pp 14174-120, 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Biseves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26. Consolidated Edison Co. of New York, 121pp 14357.013 24X Fiche 30-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/28 Consolidated Edison Co of New York, 122pp 14357, 146 24X Fichs 50-000, 82/07/28, 8204210405

- 8208100140 Ack receipt of 820702 ltr informing NRC of steps taken to correct items of noncompliance noted in IE Insp Rept 50-460/82-07 pts://proceedings.com/receipts/procedures
 - 50-400/64-07
 BISHOP, T W. Division of Resident, Reactor Project & Engineering Programs 82/08/04 ROOT, R Washington Public Power Supply System. ip. 14298 001 24X Fiche 50-460, 82/08/04, 8208100140
- --8208100150 Responds to NRC 820503 itr re items of noncompliance noted in IE Insp Rept 50-460/82-07 on 820405-09 Corrective actions-procedure qualification re groove bevel w/angle greater than 65 degrees will be performed MAZUR-D. W Washington Public Power Supply System 82/07/02 FAMUKENBERRY, R Region 5, Office of Director 14pp 14298 002 24% Fichs-50-460,82/08/04.8208100140
- 8208100314 Ack receipt of 820702 ltr informing NRC of amend to response re item of noncompliance noted in IE Insp Repts 50-460/82-06 & 50-513/82-04 |
 BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 82/08/04 RUOT, R. W. Washington Public Power Supply System ip 14297.128 24X Fisher 50-460, 82/08/04-8208100314.
- --B20B100323 Responds to NRC 820A0B ltr re violations noted in IE Insp Repts 50-440/82-06 & 50-513/82-04. Corrective actions all welders craft superintendents & GC inspectors have been trained in new weld weave criteria & procedures revised MAZUR, D. H. Hashington Public Power Supply System 82/07/02 FAULKENBERRY, R. Region 5, Office of Director. App 14297 129 24% Fiche. 50-440, 82/08/04, 8208100314
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " 8vc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co. of New York 117pp 14388 201 24X Fichs. 50-000, 82/08/05. 8204210407
- 9208100240 Ack receipt of 820702 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-460/82-04 Request for addl info encl BIGHOP, T W. Division of Resident, Reactor Project & Engineering Programs 62/08/05, ROOT, R W Washington Public Power Supply System. 5pp 14295.183, 24% Ficher 50-440,82/08/05,8208100240
- --8208100273 Responds to NRC 820517 ltr re violations noted in IE Insp Rept 50-460/82-04. Corrective actions MCAR issued on B20115 to address problem of craft preparation of quality documentation & eight assemblies installed w/butt welds MAZUR, D. M. Hashington Public Power Supply System 82/07/02. FALLERNERRY, R. Region 5. Office of Director. App 14295.188 24X Fiche 30-460,82/08/05.8208100260
- B208100226 Ack receipt of B20726 ltr informing NRC of steps taken to correct violations noted in IE insp rept AddI info requested re QA overview controls.

 BISHCP.T.W Division of Resident, Reactor Project & Engineering Programs B2/08/06, RDOT.R W. Washington Public Power Supply System ip. 14297 011 24X Fiche 50-460, 82/08/06, 82/08100226.
- --8208100231 Responds to NRC 820607 ltr re violations noted in IE insprept on 820426-30. Corrective actions, Bechtel is performing in-process surveillance of contractor categorizing activities to ensure acceptability of GA/GC program MAZUR.D M. Washington Public Power Supply System 82/07/26.
 BISHOP.T W. Division of Resident, Reactor Project & Engineering Programs. 3pp. 14297,012. 24X Fiche 80-460,82/08/06,8208100226
- 8 Reportable occurrences, LERs & related correspondence
- B208050343 Interim deficiency rept re undersized fillet welds on skewed tee joints w/obtuse angles. Initially reported on 811106 Potential failure of safety-related items possible. Analysis to be performed during as-built design verification review MAZUR, D. W. Hashington Public Power Supply System 82/07/16. FAULKENBERRY, R. Division of Resident, Reactor Project & Engineering Programs Spp 14219:339. 24X Fiche 50-460.82/07/16.8208050343.
- 8208050448 Interim deficiency rept re deformation of Okonite conductor cable. Initially reported on 820421. Circuite Using suspect cable will be identified & listing sent to engineer Replacement dates forthcoming.

 MATUR.D. W. Washington Public Power Supply System. 82/07/16
 FAULKENBERRY.R. Division of Resident. Reactor Project & Engineering Programs 4pp. 14218 049. 24X Fiche 50-460.82/07/16.8208050448.
- B208050527 Interim deficiency rept re length of capscrew which holds starting eir valva assembly in cylinder head. Initially regorted on 820618, Design configuration revised. Final rept will not be issued due to current const delay on Unit 1. MAZUR, D. H. Washington Public Power Supply System. 82/07/16 FAULKRMBERRY, R. Region 5, Office of Director. 2pp. 14213:282. 24X Fiche: 50-460: 82/07/16, 8208050827.

- 8208160432 Interim deficiency rept re Buffalo Forge fan housing missile protection Initially reported on 810824 Drawings reproposed corrective mode to fan housing reviewed & approved Completion date cannot be established due to const delay MAZUR.D W Washington Public Power Supply System 82/07/27 815HDP.T W Division of Resident, Reactor Project & Engineering Programs 3pp 14347 172 24X Fiche 50-440.82/07/27,8208160432.
- 8208250190 Potential Part 21 rept re defect in containment bldg structural steel framing Results of framing connection flexibility tests will be available by 820830 Status rept on design review will be submitted by 821030 SARSTEN. © E United Engineers & Constructors, Inc (subs. of Raytheon Co) 82/08/13 Director's Office, Office of Inspection and Enforcement 2pp 14340 278 24X Fiche: 50-460.82/08/13, 8208250190

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list enci DIRCKB, M. J. Office of the Executive Director for Operations 82/07/02. Consolidated Edison Co. of New York 93pp. 14194 001, 24X Fiche 50-000,82/07/02,8207080064
- 8208070194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittel of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT.D 0 Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p 14356 332 24X Fiche 50-000,82/08/09,8208070194.
- 8208300162 Forwards "IL Power Quality Program Update," describing quality recovery program discussed w/NRC on 820712 & documented in util 820727 ltm GERSTNER, H. C. Illinois Power Co. 82/08/12 KEPPLER, J Q. Region 0ffice of Director 2pp. 14595.297 24X Fiche 50-461,82/08/12,8208300162.
- --8208300163 "IL Power Quality Program Update "
 # Illinois Power Co 82/08/09 47pp 14595-299 24X
 Fiche: 50-461,82/08/12,8208300162
- 6208260176 Responds to 820623 ltr requesting schedule for addressing Humphrey concerns to Mark III containments Dwners group established program to review generic work by GE for BWR owners group, Rept to be submitted by 821101.

 MULLER, O E Illinois Power Co 82/08/20 BERNARD, H
 Standardization & Special Projects Branch, Fiche, 50-461, 92/08/20, 8208260176
- 8208310379 Forwards revised Page 16 to \$20113 ltr re compliance w/NRC regulations. Pravious transmittal incorrectly referenced addends of ASME Boiler & Pressure Vessel Gode for RCS piping.
 HULLER, 0 E Illinois Power Co 82/08/25. BERNARD, H Standarditation & Special Projects Branch. 2pp. 14692 107. 24X Fiche. 50-461. 82/08/25, 8208310379.
- E NAC Basety Evaluation Report (SER), supple & correspondence
- 820B130470 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CLINTON POWER STATION, UNIT NO. 1. Docket No. 50-461 (Illinois Power Company, et al.)
 # Office of Nuclear Reactor Regulation, Director. NUREO-0853 801. 82/07/31 84pp. Aveilable at NTIS \$5.50. 14351 001. 24X Fiche: 50-461, 82/07/31, 8208130470
- 8208310308 Forwards comments on summarised conclusion reached in recent meeting w/NRC re basis for disposition of SER Outstanding Issue 10A: "Containment Purge." QEIER, J D Illinois Power Co. 82/08/25. WILLIAMS: J H. Standardization & Special Projects Branch 16pp 14687 339. 24X Fiche: 50-461, 82/08/25, 8208310308.
- 8208310226 Forwards response to NRC 820723 request for add1 info result emplification of seismic vibration. Response contains verification of Figures 33.34 & 35 of "Site-Specific Response Spectra," 82R Outstanding Issue 3 resolved. HULLER, G. E. Illinois Power Co. 82/08/25, BERNARD, H Standardization & Special Projects Branch. 8pp. 14695:117, 24X Fiche. 30-461, 82/08/26, 8208310226.

- F Security, medical, emergency & fire protection plans
- 8208060065 Releases public version of applicant commitments to be incorporated in Chapter 13 of FSAR FELTON J M Division of Rules and Records 82/08/02. Document Management Branch 10 14282 174 24X Fighs 50-461.62/08/02. 8208060065
- --8208060070 Submits public version of commitments that will be incorporated into Chapter 13 of FSAR, including commitments re recovery manager duties, public prompt warning sys & dose assessment reporting sys per NVREO-0654

 HULLER, 0 E Illinois Power Co 82/07/22 BERNARD, H
 Standardization & Special Projects Branch 2pp 14282 175

 Fiche 50-461,82/08/02,8208060065
- 24X
- 6 Adjudicatory correspondence
- 8208090174 Response to 820608 suppl to applicant 820422 motion for protective order ASLB ruling on motion should be deferred unless parties disagree on extent of disclosure Proposed protective order encl Certificate of Syc encl WILLMAN.P L Illinois. State of 82/08/02 Commissioners 7pp 14272 059. 24X Fiche, 30-461, 82/08/02, 8208070176
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN, E L Division of Engineering & Guality Assurance. 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000:82/07/16.8204210393
- 82042(0395 IE Info Notice 81-26.Part 3. Suppl 1, "Clarification of Placement of Personnel Manitoring Devices for External Radiation " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/19 Hickigan, Univ of 112pp 14358 ODI 24% Fiche 50-000,82/07/19,
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure" Svc list encl JORDAN.E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210376
- B204210397 IE Info Notice B2-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I. Division of Fuel Facilities, Materials & Safeguards B2/07/20 Consolidated Edison Co of New York 71pp 14357 2: 24X Fiche 50-000, B2/07/20, B204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance. 82/07/22 Consolidated Edison Co of New York 112pp 14194:321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Mydrogen Explosion While Crinding in Vicinity of Drainag & Open RCS " Svc list encl JORDAN E L Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co of New York 122pp 14380 115, 24X Fiche 50-000, 82/07/23, 8204210401
- B204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Fin Fallures at Westinghouse FURs " Svc list encl JORDANIE L Division of Engineering & Quality Assurance, 82/07/29 Consolidated Edison Co. of New York, 127pp 14194*120 24X Fiche: 50-000, 82/07/23, 8204210402
- 3204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Syc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 208160411 Forwards IE Mgt Meeting Rept 50-461/82-12 on 820712. No noncompliance noted KEPPLER: J G Region 3: Office of Director. 82/07/27 KELLEY,W, Q Illinois Power Co. 2pp 14347:146 24X Fiche-50-461,82/07/27, 82/08160411
- -8208160417 IE Mgt Neeting Rept 50-461/82-12 on 820712 No noncompliance noted Major areas discussed existing stop work recovery plans & proposals w/respect to continuing const work activities at facility KEPPLER.J O. Region J. Office of Director KNOP.R C , HALKER.R D. Division of Project & Resident Programs 82/07/26 44pp. 14349 148. 24x Fiche 50-461,82/07/27.8208160411

- 8204210405 IE Info Natice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Syc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDANE L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000,82/08/05,8204210407
- S Reportable occurrences, LERs & related correspondence
- 8208050313 Interim deficiency rept re inadequate quality documentation & records for control room MVAC sys by Zack Co Initially reported on 820621 Stop Work Action 014 issued for all safety-related work by Baldwin Associates GERSTNER,W C Illinois Power Co 82/07/21 KEPPLER,J G Region 3, Diffice of Director 3pp 14237 326 24X Fiche. 50-461.82/07/21.
- 8208100126 PNO-III-82-068 on 820503, allegations from former employee of HVAC contractor received re false or incomplete GA documentation for HVAC work at sites Special insp of Iack Co & facilities initiated MALKER, R D Region 3, Office of Director 82/07/22, ip 14298 183 24% Fichs 50-000,82/07/22,8208100126
- 8208080413 Part 21 deficiancy rept re PGCC termination modules supplied by GE Rewiring of 28 modules completed on Bii215 GERSTNER.W C Illinois Power Co 82/07/23 KEPPLER.J C Regio Office of Director 3pp 14217 342 24X Fiche 50-461,82/07/23. Region 3,
- 8208050477 Interim deficiency rept re failure of GC insp repts for containment bldg structural steel to provide assurance that steel meets design & const requirements Initially reported on 820625 Investigation underway GERBINGE, W C Illinois Power Co 82/07/23 KEPPLER, J G Regio Office of Director 2pp 14216, 245 24X Fiche 50-461, 82/07/23, 200808047 Region 3. Office of Director 8208050477
- 8208100280 PND-III-82-071 on 820729, received Part 21 rept via telcon w/Zack Co re documentation discrepancies for welds made to fivAC components at La Salle & possibily at Clinton & Midland Welder of record may not be actual weider. WALKER B Region 3. Office of Director 92/07/30 ip 14294 352 24% Fiche.50-000.82/07/30.9208100280
- 8208i40248 Potential Part 21 rept re weld records Initially reported on 820729 Review of documents indicates possible discrepancy between welder of record & welder completing welds Investigation continuing DE ZUTEL.C Z Zack Co 82/08/02 KEPPLER.J 0 Region 3, Office of Director 10pp 14346 351 24X Fiche 50-000.82/08/02.8208160248
- 8208100164 PND-III-82-074 on 820803, Baldwin & Associates issued stop work order against Zack Co, HVAC contractor 8top work order involves all noneafety-related HVAC work performed in Category I structures
 LIVERMORE, H. WALKER, R. SPESBARD, R. Region 3, Office of Director 82/08/03 Ip 14278 182 24X Fiche 50-461,82/08/03,8208100164
- 820B170217 Interim deficiency rept re inconsistencies in certification for NVAC matls installed by Zack Co Initially reported on B11002 Evaluation conducted by util QA revealed problems in closure of discrepant documentation packages.

 GERBINER.W C Illinois Power Co B2/0B/03 KEPPLER.J Q Region 3, Office of Director. 2pp 14362.03B 24X Fiche 50-461.82/0B/03, 220212037
- 820B170127 Interim deficiency rept re potential breakdown in const GA program involving ineffective implementation of 10CFR30, App B. Criteria X & XVI. Initially reported on 82070B Investigation of reportability continuing GERSINER. W G Illinois Power Co 82/08/04 KEPPLER, J Q Region 3 Office of Director 3pp 14365 227 24X Fiche 50-441,82/08/04, Region 3, 8208170127
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- \$207080064 Owneric ltr to all licensess of operating plants, applicants for GL & holders of CP re Commission approved charter for CROR. Svc list encl
 DIRCKS, M J Office of the Executive Director for Operations
 62/07/02 Consolidated Edison Co of New York 93pp 14194, OO1
 24X Fiche: 50~000, 82/07/02, 8207080064.

- 8208090194 Generic Ltr 82-i4 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Sv. list encl EISENHUT, D 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14396 332 24X Fiche 50-000,82/08/09,8208090194
- O Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 OO1 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE info Notice 82-25, "Failures of Hiller Actuators Uppn Gradual Loss of Air Pressure " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 62/07/20 Consolidated Edison Co of New York 112pp. 14391 001 24X Fiche 50-000 82/07/20, 8204210394
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB,L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Constituted Edison Co of New York 7ipp 14357 27 24X Fichs 50-000.82/07/20.8204210397
- 8204210398 IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York. 112pg 14194 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svt list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380.115 24X Fiche 50-000.82/07/23.8204210401
- 8204210402 IE Info Notice 82-27, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Hestinghouse PHRs " Svc list encl JORDAM,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche:50-000:82/07/23:8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sieeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl.
 JORDAN E. L. Division of Engineering & Quality Assurance 82/07/26
 Consolidated Edison Co of New York 121pp 14357 013 24X
 Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche: 50-000, 82/07/28, 8204210405
- 8204210407 1E Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" 8vc list encl JORDAN: E.L. Division of Engineering & Guality Assurance 82/08/05. Consolidated Edison Co of New York 117pp. 14388; 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8 Reportable occurrences, LERs & related correspondence
- 8208050313 Interim deficiency rept re inadequate quality documentation & records for control room HVAC sys by Zack Co Initially reported on 820621 Btop Work Action 014 Issued for all safety-related work by Baldwin Associates GERSINER, W C Illinois Power Co 82/07/21 KEPPLER, J Q Region 3, Office of Director 3pp 14237.326 24X Fichs.50-461,82/07/21, 8208050313
- 820816024B Potential Part 21 rept re weld records Initially reported on 820729 Review of documents indicates possible discrepancy between welder of record & welder completing welds Investigation continuing DE ZUTEL, C Z Zack Co. 82/08/02 KEPPLER, J G Region 3, Office of Director 10pp, 14346-351. 24% Fiche.50-000,82/08/02,8208160248

- 8208170217 Interim deficiency rept re inconsistencies in certification for HVAC matls installed by Jack Co Initially reported on 811002 Evaluation conducted by util GA revealed problems in closure of discrepant documentation packages GERSTNER.W C Illinois Power Co 82/08/03 KEPPLER, J G Region 3, Office of Director 2pp 14362 038 24X Fiche 50-461,82/08/03, 8208170217
- 8208i70127 Interim deficiency rept re potential breakdown in const GA program involving ineffective implementation of 10CFR50, App B.Criteria X & XVI Initially reported on 820708 Investigation of reportability continuing OFRBTNER.W C Illinois Power Co 82/08/06 KEPPLER.J O Region 3, Office of Director 3pp 14365 227 24X Fiche 50-461,82/08/06,8208170127
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8208060368 Board Notification 82-70 notifies of differing prof opinion re-sensitization of BMR stainless steel weldments
 TEDESCO.R L Assistant Director for Licensing 82/07/20 Atomic Safety and Licensing Board Panel 4pp 14281 355 24X
 Fiche-50-000.82/07/20.8208060368
- G Adjudicatory correspondence
- 8208i30179 Forwards NRC 8209i1 ltr to util re slippage of CP issuance date, for distribution to parties LAZO,R M Atomic Safety and Licensing Board Panel 82/08/11 STUCKY,S W Docketing & Services Branch 3pp 14339 124 24X Fiche 50-464, 82/08/11, 8208130179
- O Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage "Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York, 87pp 14356 274, 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210376 JE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210376
- 8204210397 IE Info Notice BA-24, "Water Leaking From U Hexafluoride Overpacks" Svc list ancl COBB.L 1 Division of Fuol Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 274 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures" 8vc list encl
 JORDAN.E L Division of Engineering & Quality Assurance 82/07/22,
 Combolidated Edison Co of New York 112pp 14194 321 24X
 Fichs 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAM E L Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche, 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Bupport Pin Failures at Westinghouse PMRs " Svc list encl JORDAN-E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120, 24X Fiche 50-000, 82/07/23, 8204210402
- B204210403 IE Enfo Notice B2-30. "Loss of Thermal Sloeves in RCS Piping at Certain Westinghouse PWR Power Plants " Byo list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/26, Consolidated Edison Co. of New York 121pp 14357 013 24X Fiche 50-000, B2/07/26, 8204210403
- 9204210405 IE info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146. 24X Fiche 50-000,82/07/28,8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
 JORDAN.E.L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York. \$17pp 14388 201. 24X
 Fiche 50-000, 82/08/05,8204210407

S Reportable occurrences, LERs & related correspondence

8208310198 PND-IV-82-033 on 820826.util issued news release informing of cancellation of proposed facility NRC delay on decision on GP & rate treatment of project investment cited as prime factors in final decision
WISNER, C E Region 4. Office of Director 82/08/27 ip
14693 162 24X Fiche 50-466.82/08/27.8208310198

DOCKET STN-50-470 CESSAR SYSTEM SO

- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Stor list encl EIBENHUT, D 0 Division of Licensing 82/08/09. Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000.82/08/09, 8208090194
- 8208240372 Forwards itemized review of compliance of CESSAR FSAR w/10CFR20:30 & 100 Sys 80 NSSE design similar to earlier G-E NSSE which net NRC regulations SCHERER; A E Combustion Engineering, Inc. 82/08/18, BERNARD, H Standardization & Special Projects Branch 11pp 14322 336 24X Fichs. 50-470, 82/08/18,8208240372
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 9208240349 Forwards "Long-Term Iodine Control in Reactor Containment Bldgs Using C-E Iodine Removal Sys." per CESBAR SER Confirmatory Item 12 Rept incorporates 820309 discussion w/ NRC re-containment sampling & radiolysis of hydratine SCHERER.A.E Combustion Engineering, Inc 92/08/19 EISENHUT, D. O Division of Licensing 1p 14521 021. 24% Fiche 30-470.82/08/19, 8208240349
- --8208240354 "Long-Term Iodine Control in Reactor Containment Bldgs Using C-E lodine Removal Sys " * Combustion Engineering, Inc 82/08/31 23pp 14521.022. 24x Fiche 50-470, 82/08/19, 8208240349
- Q Inspection reports. IE Bulletins & correspondence
- 9204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Syc list encl JORDAN: EL Division of Engineering & Quality Assurance 82/07/19 Hickigan

DOCKET STN-50-480 REBAR-41

- A. Application/construction stage documents & correspondence
- B20B090194 Ceneric Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Suc list enc!
 EISENHUT.D.O Division of Licensing B2/08/09 Consolidated Edison Co of New York 1p. 14356 332 24X Fiche 50-000, 82/08/09, 82/88090194
- Inspection reports. IE Bulletins & correspondence
- 204210395 IE Info Notice 81-26.Part 3.Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Rediation." Sec 11st encl.
 JORDAM, E. L. Division of Engineering & Quality Assurance 82/07/19.
 Michigan, Univ. of. 112pp 14358 001 24X Fichs 50-000.82/07/19.
 8204210395

JCKET BTN-50-481 8-8AR-241

- Application/construction stage documents & correspondence
- 'OBO90194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
 EIECHUT.D.9. Division of Licensing 82/08/09, Consolidated Edison Co of New York 1p. 14356.332 24X Fichs 50-000.82/08/09, 8208090194.

- DOCKET STN-50-482 WOLF CREEK GENERATING STATION
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licenses of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR 80× list encl
 DIRCKB,N J Office of the Executive Director for Operations
 82/07/02, Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000:82/07/02.8207080064
- 8208100061 Forwards "SNUPPS Rept on Control of Heavy Loads," final response to 801222 generic ltr PETRICK, N A Standardized Nuclear Unit Power Plant System 82/08/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 14276 001 24X Fiche 50-000,82/08/04,8208100061
- --8208100069 "8NUPPS Rept on Control of Heavy Loads"
 4 Standardized Nuclear Unit Power Plant System 82/08/04 134pp 14276,002 24X Fiche 50-000,82/08/04,8208100061
- 8208100339 Forwards evaluation of effects of higher spectrum in essential svc water piping sys & supports Util commits to adopting Reg Ouide 1 60 as SSE design spectrum for site specific Category I structures RDESTER, O L Kansas Oas & Electric Co 82/08/05 DENTON, H R. Office of Nuclear Reactor Regulation. Director 3pp 14297 090 24X Fiche 50-482,82/08/05,8208100339
- --B208100343 "Seismic Evaluation of Wolf Creek Generating Station Structures Using Livermore Spectrum, Evaluation of Piping Sys & Supports " * Bechtel Corp 82/07/23 5pp 14297 093 24X Fiche 50-482, 82/08/05, 8208100339
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittel of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list enci EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14354 332 24X Fiche 50-000,82/08/09, 9208090194
- 8208310389 Approves 820809 proposed mods to pipe cleanliness program discussed at 820723 meeting, assuming continued constructor & util GC surveillance.

 BEIDLE-H C Division of Resident, Reactor Project & Engineering Programs 82/08/20 KDESTER.O L Kansas Gas & Electric Co 1p 14693 255 24X fiche 50~482.82/08/20.8208310389
- --8208310394 Documents proposed mods to pipe cleanlines program discussed at 820723 meeting Program will be subj to constructor & util GC surveillance. Approval requested MOESTER. O L Kansas Gas & Electric Co 82/08/09. SEIDLE, W C, Division of Resident. Reactor Project & Engineering Programs 2pp 14693 236. 24X Fiche 50-482.82/08/20.8208310389
- 8208270380 Advises that fuel load date has been revised from Dec 1983 to Oct 1984 w/commercial operation planned for Apr 1985, Requests SER suppl be issued in Sept 1982 KOEBTER.O. L. Kansas Gas & Electric Co. 82/08/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 14565 082 24X Fiche; 50-482,82/08/24,8208270380
- B20B310304 Advises that since revised Page 3A-B to Revision 9 of FBAR addendum containing change to commitment to Reg Quide 1 146 found unacceptable util withdraws exception & now fully complies w/recommendations of guide KOESTER.O.L. Kansse Gas & Electric Co. 82/08/26 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 14694 312 24X Fiche 30-482,82/08/26,8208310304
- D. NAC Draft/Final Environmental Statements, supple & correspondence
- 9208060162 Comments on FES re operational environ monitoring, decommissioning, economic risks & nonradiation issues Certain pravious comments on DEB not addressed in FEB. App B does not contain NPDES permit info
 HAJINIAN.C H Environmental Protection Agency 82/08/02
 YDUNOBLOOD.B J Licensing Branch I 2pp 14237, 241. 24X
 Ficha 50-482.82/08/02,8208060162
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8208160265 Forwards "KS Cas & Electric Co.Holf Creek Generating Station Unit 1 Reactor Vessel Rediation Surveillance Program " Rept contains info to resolve Confirmatory Item A-4 in SER (NUREO-0881) re identification of base metal KOESTER. Q.L. Kansas Cas & Electric Co 82/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp 14346: 176 24X Fiche: 50-482,82/08/11,8208160265

- --8208160276 "KS Gas & Electric Co.Wolf Creek Generating Station Unit 1 Reactor Vessel Radiation Surveillance Program " SINGER.L R , MAGER.T R Westinghouse Electric Corp WCAP-10015 82/06/30 47pp 14346 198 24X Fiche 50-482,82/08/11.8208160265
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8208040180 Forwards Revision 9 to FBAR addendum KOESTER, Q L. Kansas Oas & Electric Co. 82/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 14183 088 24/ Fiche 50-482, 82/07/30, 8208040180
- --8208040181 Revisson 9 to FBAR addendum * Kansas Qas & Electric Co 82/07/31 646pp 14183 101 24X Fiche 50-482,82/07/30,8208040180
- Q Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JGRDAN,E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000, 82/07/16,8204210393
- 8204210395 IE Info Notice 8i-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, EL Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ af 112pp 14358 001 24X Fiche 50-000, 82/07/19, 820421039
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Fressure " Syc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001. 24X Fiche 50-000,82/07/20,8204210376
- B204210397 IE Info Notice B2-24. "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Bafeguards B2/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24% Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Bvc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Cartain Westinghouse PWR Power Plants " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000.82/07/28.8204210405
- 8208050190 Ack receipt of 820701 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/82-07 SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs. 82/07/28 KOESTER.O L Kansas Oas & Electric Co. ip 14212 061 24X Fiche 50-482,82/07/28,8208050190
- --8208050194 Responds to NRC 820617 itr reviolations noted in IE Insp. Rept 50-482/82-07 Corrective actions training film will be developed & will define correct application of quality hold tags.

 KOE8TER, O. L. Kansas Gas & Electric Co. 82/07/01 SEIDLE, W. E. Division of Resident, Reactor Project & Engineering Programs 3pp. 14212 062 24% Fiche. 50-482,82/07/28,8208050170

- 8208190287 Forwards IE Insp Rept 50-482/82-08 on 820608-11. No noncompliance noted &EIDLE:NC Division of Resident: Reactor Project & Engineering Programs 82/08/02 KQESTER:G L Kansas Gas & Electric Co 2pp 14387 116 24X Fiche 50-482,82/08/02.8208190287
- --8208190294 IE Insp Rept 50-482/82-08 on 820608-11 No noncompliance noted Hajor areas inspected GA plans, instructions & procedures for electrical cables, terminations & related equipment & independent evaluation of work performance REDANO,R T , HUNNICUTI, D M , NILLIKIN.R P Division of Resident, Reactor Project & Engineering Programs 82/07/26 17pp 14387 118 24X Fiche 50-482,82/08/02,8208190287
- 8204210407 IE Info Notice 82-27, "Fuel Rad Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05,8204210407
- S Reportable occurrences, LERs & related correspondence
- 8208100034 Final deficiency rept re terminal lug crimps in main control panels auxiliary relay racks & local control station Rework Plan RJ-200-A developed & implemented to inspect & replace lug crimps KOESTER.6 L Kansas Oas & Electric Co 82/08/02 SEIDLE, W C. Division of Resident, Reactor Project & Engineering Programs 1p 14294 272, 24% Fiche 50-482,82/08/02,8208100034
- 820Bi70094 Final deficiency rept re nonconforming Rockbestos cable delivered to facility Samples from all suspect cable reels returned to manufacturer for testing against Bechtel specs Deficiency concerns physical properties of Jacket only KOESTER.O L. Kansas Qas & Electric Co. 82/08/09 SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 2pp 14358 214. 24X Fiche 50-482,82/08/09,8208170094
- 8208170067 Final deficiency rept re essential svc water pipe support embedded plate stud failure. Deficiency determined not reportable under 10CFR30 55(e) "Essential Svc Water Sys Pump Restraint Embed Rept" and KOESTER, O. L. Kansas Oas & Electric Co. 82/08/10 SEIDLE, M. C. Division of Resident, Reactor Project & Engineering Programs 19, 14362 085 24X Fiche 50-482, 82/08/10, 8208170067
- --8208170070 "Wolf Creek Generating Station Essential Svc Water Sys Pump Restraint Embed Rept" LABARTA:P Bachtel Corp 82/07/01 16pp 14362 086 24X Fiche 50-482: 82/08/10:8208170067
- 8208200197 Interim deficiency rept re compromised welding inspector exam initially reported on 820712 New exam series developed & security procedures implemented Status rept of investigation will be provided by 821020 MDESTER.W C Kansas 0as & Electric Co 82/08/ii SEIDLE.W C Division of Resident. Reactor Project & Engineering Programs 2pp 14500:135 24X Fiche 50-482,82/08/ii.8208200197
- 8208240069 Final deficiency rept re failure of Colt-Pielstick diesel generator thrust bearing Initially reported on 800513 Crankshaft thrust bearings replaced Also reportable per Part 21 KDESTER, O. L. Kansas Oas & Electric Co. 82/08/16 SEIDLE, H. C. Region 4. Defice of Director App. 14520,001, 24X Fiche 50-482,82/08/16.8208240069
- 8208240196 Final deficiency rept re improprieties in const, installation & documentation of safety-related HVAC duct supports
 Initially reported during Spring of 1981 Nonconformance rept issued to provide 100% reinsp & rework of supports.
 KOESIER: O. L. Kansas Oas & Electric Co. 82/08/16 SEIDLE, W.C. Division of Resident. Reactor Project & Engineering Programs Spp 14519 312 24% Fiche 30-482,82/08/16,8208240196

DUCKET STN-50-483 CALLAWAY PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for CL & holders of CP re Commission approved charter for CROR, 8vc list encl
 DIRCKS, H J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24% Fiche 50-000, 82/07/02, B2070B0064

- 8208090107 Forwards final Systematic Assessment of Licensee Performance Rept 50-483/82-04 for Jul-Sept 1981 Overall regulatory performance satisfactory QA support in electrical area needs strengthening KEPPLER, J O Region 3, Office of Director 82/07/19 SCHNELL.D.F Union Electric Co 22pp 14269 251 24% Fiche 50-483,82/07/19,8208090107
- 8208040507 Notification of 820915 meeting w/util in Mokane:MO & caseload forecast panel 820915 site visit to review const progress for assessing projected fuel load dates Agenda anci EDISON-O E Licensing Branch 1 82/07/22 YOUNOBLOOD, B J Licensing Branch I 7pp 14220 328 24X Fiche 50-483,82/07/22,8208040507.
- 8208050186 Notification of 820817 meeting w/vtils & Nuclear Projects, Inc.in Galthersburg.MD to discuss basis for routing of instrumentation EDISON.9 E. Licensing Branch 1 82/07/22 YOUNGBLOOD, B. J. Licensing Branch 1 4pp 14242 117 24X Fiche 50-483, B2/07/22, 8208050186
- B20B25010B Revised notification of 820915 meeting w/util at Callaway EOF bldg & 820916 caseload forecast panel site visit to review const progress for assessing projected fuel load dates
 EDIBON, G E Licensing Branch 1 B2/07/22 YOUNGBLOOD, B J
 Licensing Branch 1 Ip 14559 239 24X Fiche 50-483, 82/07/22.
 B20B25010B
- 8208260029 FDIA request for all insps made by OSHA of facilities & related documents
 100E.V.M. Affiliation Unknown 82/07/22 KEPPLER, J 0 Region 3, Office of Director 1p 14589 252 24X Fiche 50-483,82/07/22, R208240029
- 8208100061 Forwards "SNUPPS Rept on Control of Heavy Loads," final response to 801222 generic ltr PETRICK.N.A. Standardized Nuclear Unit Power Plant System 82/08/04 DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director. 1p 14296-001 24X Fiche 50-000.82/08/04.8208100061
- --B208100069 "BNUPPB Rept on Control of Heavy Loads"

 * Standardized Nuclear Unit Fower Plant System 82/08/04 134pg
 14276-002 24X Fiche 50-000.82/08/04,8208100061
- 8208260035 Responds to FDIA request for all insps made by OBHA of facilities & related documents NRC has no documents subj to request FELTON, J H Division of Rules and Records 82/08/06 100E, V M Affiliation Unknown ip 14589 253 24X Fiche, 50-483, 82/08/06, 82/08/40035
 - 38070194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Thapter I requirements & provides alternatives to requirements Svc list encl IIEERHUT. D.O Division of Licensing. 82/06/09 Consolidated Idian Co of New York 1p 14356 332 24X Fichs 50-000, 82/08/09, 3208090174
- 208240132 Forwards 820818 press release announcing that completion schedule for facility would be delayed until late 1984 or early 1985 Fuel load date is being delayed from June 1983 to Apr 1984 BCINNELL, D.F. Union Electric Co. 82/08/19, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 14519 336 24X Fisher 50-483, 82/08/19,8208240132
- 208250289 Forwards util 820818 press release announcing change in completion schedule Fuel load date changed from June 1983 to Apr 1984.8vc list encl BAXTER, T.A. Shaw, Pittman, Potts & Trombridge BAXTER T.A. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 82/08/23 GLEASON, J.P., BRIGHT, O.D., KLINE, J.R. Atomic Safety and Licensing Board Panel 4pp 14543:059 24X Fiche 50-483,82/08/23,82/08/2089.
- . Security, medical, emergency & fire protection plans
- '08260364 Releases public version of revision to radiological emergency response plan FELTON.JM Division of Rules and Records 82/08/13 Document Management Branch. Ip 14588-220 24X Fiche 50-483,82/08/13,8208260364.
- --8208260356 Forwards public version of Revision 5 to radiological emergency response plan Encl revision will be incorporated into next FSAR revision BCMNELL, D.F. Union Electric Co 82/08/02 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director 3pp 14588, 221, 24X Fiche; 50-483, 82/08/13, 8208260364

- --8208260369 Public version of Revision 5 to radiological emergency response plan, including revised preliminary evacuation time estimates # Union Electric Co 82/08/31 350pp 14588 224 24X Fiche 50-483, 82/08/13, 8208260364
- --8208260371 Public version of preliminary evacuation time estimates + Planning Research Corp. 81/09/30 97pp 14589 142 24X Fichs 50-483, 82/08/13, 8208260364

Q Adjudicatory correspondence

- 8208030179 Advises that NRC adheres to positions in NRC 820721 ltr to ASLB & will not respond to Judge RO Wright 820707 objections to J Reed motion to compel discovery or Reed 820708 motion to overrule objections PERLIS.R 0 Hearing Branch 3 82/08/02 OLEASON.JP. BRIGHT, 0 D, KLINE, JR Atomic Bafety and Licensing Board Panel 1p 14160 188 24X Fiche 50-483.82/08/02.8208030179
- 8208060106 Response to J Read 820715 application for issuance of subpoense Ruling on application should be deferred Applicant U util should be given opportunity to respond after ABLB rules on Read particularized contentions PERLIB, R 9 Hearing Branch 3 82/08/04 Atomic Safety and Licensing Board Panel 5pp 14238 181, 24% Fiche 50-483,82/08/04,8208060106
- B20Bi10075 Memorandum & hearing schedule order establishing schedule for filing response to discovery requests, summary disposition motions & testimony Prehearing conference will be held on 820902-03 GLEASON J P Atomic Safety and Licensing Board Panel 82/08/06 2pp 14316 350 24X Fiche 50-483, B2/08/06, B208110075
- 8208160162 Forwards ASL8 920806 memorandum & hearing schedule order establishing schedule for filing response to discovery requests, summary disposition motions & testimony, Hearing will commence on last wh in Oct or first wh in Nov. SCINTO. J Deputy Executive Legal Director. 82/08/12, PERRY, 8 Federal Emergency Hanagement Agency 1p 14345.078 24X Fiche: 50-483, 82/08/12, 8208160162
- 8208170204 Motion to amend schedule established in ASLB 820809 order Number & nature of JG Reed contentions require that disputes over admissibility be resolved allowing opportunity to use summary disposition process Certificate of Svc ancl. BAXTER: T A Union Electric Co. BAXTER: T.A. Shaw, Pittman, Potts & Troubridge 82/08/13 Atomic Safety and Licansing Board Panel 7pp 14361 227 24X Fiche 50-483.82/08/13.8208170204
- 9208190135 Forwards revised radiological emergency response plan. W/o encl 8AUSER, D B Shaw, Pittman, Potts & Trombridge. BAUSER, D B Union Electric Co. 82/08/17 REED, J G Read, J. G 3pp, 14381, 076 24X Fiche. 50-483, 92/08/17, 9208190135
- 8208190136 Memorandum & schedule order eliminating existing time requirements for filing & responding to summary disposition motions from schedule on emergency planning contentions. GLEASON, J.P. Atomic Safety and Licensing Board Panel. 82/08/17. 1p. 14381 095 24X Fiche: 50-483,82/08/17,8208190136
- 8208240261 Motion for relief from applicant 820715 excessively burdensome & redundant discovery Applicant using procedural overload to force author into default.Certificate of Svc encl.

 REED J G Reed, J. G 82/08/20 Atomic Sefety and Licensing Board Panel 4pp 14527 135 24x Fiche:50-483.82/08/20,8208240261
- 8208280287 Forwards util 820818 press release announcing change in completion schedule Fuel load date changed from June (983 to Apr 1784 Bvc list encl BAXTER.T.A Bhaw. Pittman, Potts & Troubridge. BAXTER T A Northeast Nuclear Energy Co (subs. of Northeast Utilities). 82/08/23 OLEASON, J P. IRIGHT, G D, KLINE, J R Atomic Bafety and Licensing Board Panel 4pp 14543,037 24X Fiche. 50-483,82/08/23,8208250289.
- 8208250318 Response to interrogatories & requests for production of documents Cartificate of Svc encl SCHUKAIR J Union Electric Co 82/08/23 Reed, J Q, 12pp. 14540 210 24X Fiche, 50-483, 82/08/23, 8208250318
- 8208270426 Response in opposition to JQ Reed 82082i motion for relief from discovery Request w/o merit & untimely. BAXTER: T. A. Union Electric Co BAXTER: T. A. Shew, Pittman, Potts & Troubridge 82/08/25 Atomic Safety and Licensing Board Panel. Spp 14366 087. 24X Ficher 50-483,82/08/25,8208270426

- --8208270428 Mation to compel response to util 820715 request for production of dacuments served on JO Reed Certificate of Svc encl BAXTER.TA Union Electric Co BAXTER.TA Bhaw Fittman. Potts & Troubridge 82/08/25 Atomic Safety and Licensing Board Panel App 14566 075 24X Fiche 50-483.82/08/25,8208270426
- M Antitrust correspondence
- 8208160245 Submits responses to NRC 820513 request for add1 info re CL antitrust review.per util 820623 ltr Related correspondence encl SCHMELL, D.F. Union Electric Co. 82/08/11 TOALBTON, A. Antitrust & Economic analysis Branch (Utility Finance) 174pp 14346 001 24X Fiche 50-483,82/08/11,8208160245
- G Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list enc! JURDAM: L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000.82/07/16.8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc 11st enc! JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 30-000, 82/07/19, 8204210375
- 8204210396 IE Info Notice 82-29, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Syx list encl JDRDAN, E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co. of New York 112pp 14381 001 24X Fiche 50-000.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Byc list encl COBB.L I Division of Fuel Facilities. Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 2: 24X Fiche 50-000.82/07/20.8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp. 14194 321 24X Fiche 50-000.82/07/22.8204210398
- B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Dreined & Open RCB " Evc list encl JORDAN,E L Division of Engineering & Guality Assurance, 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23.8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Wastinghouse PWRs " Syc list encl JORDAN.E.L. Division of Engineering & Quality Assurance G2/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleaves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Guality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14397 013, 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 lE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208170113 Forwards IE Insp Rept 50-483/02-05 on 820712-14 No noncompliance noted. LITTLE:W B. Division of Engineering & Technical Programs 82/08/03 8CHNELL,D F Union Electric Co 2pp 14358 188 24X Fiche 50-483,82/08/03,8208170113
- --8208170118 IE Insp Rept 50-483/82-05 on 820712-14. No noncompliance noted Major areas inspected vendor nondestructive exam activities, review shop & field radiographs, previous insp findings & 10CFR80 55(e) items WARD. K D , DANIELBON, D H Division of Engineering & Technical Programs 82/07/27. 7pp. 14358 190 24X Fichs 50-483, 82/08/03, 8208170113.

- 8208090173 Ack receipt of 820721 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-03 NORELIUS.C E Division of Engineering & Technical Programs 82/08/04 SGMBELL.D F Union Electric Co ip 14271 168 24X Fiche 50-483,82/08/04.8208090173
- --B20B090178 Responds to NRC B20615 ltr re violations noted in IE Insp Rept 50-4B3/B2-03 Corrective actions identified actions to bring open items to current status & developed training program within Delcon for craft/engineering personnel BCHNELL-D F Union Electric Co B2/07/21 NORELIUB, C E Division of Engineering & Technical Programs 8pp 14271 169 24X Fiche 50-4B3, B2/08/04, B20B090173
- 8204210407 IE Info Natice 82-27. "Fuel Rad Degradation Resulting From Baffle Water-Jet Impingement" 8vc list enc! JORDAN, E.L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8208230148 Act receipt of 820721 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-483/82-03 MORELIUS; C E Division of Engineering & Technical Programs 82/08/13 SCHNELL, D F Union Electric Co ip 14514 295 24X Fiche 50-483; 82/08/13; 8208230148
- --8208230198 Responds to NRC 820619 ltr re violations noted in IE Insp Rept 50-483/82-03 Corrective actions util GA will perform surveillance to investigate interface difficulties identified by inspector & results reported to mgt level. SCHNELL.DF Union Electric Co 82/07/21 NORELIUS,C E Division of Engineering & Technical Programs 8pp. 14514 296 24X Fiche.50-483,82/08/13,8208230148
- DOCKET STN-50-485 STERLING POWER NUCLEAR PROJECT, UNIT 1
- G Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage," Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Ficher 50-000, 82/07/16, 8204210393
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York 112pp, 14381 001, 24X Fiche 90-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl COBD.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357:276 24X Fiche 50-000.82/07/20.8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list enci JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp. 14174 321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Bvc list encl JORDAN-E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23,8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rad Drive (CRD) Ouide Tube Support Pin Failures at Wastinghouse PWRs," 8vc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York, 127pp, 14194-120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Mestinghouse PMR Power Plants " Syc list encl JURDAN.E.L. Division of Engineering & Quality Assurance. B2/07/26, Consolidated Edison Co. of New York 121pp 14337 013, 24X Fiche 50-000, 82/07/26, 8204210403.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/28, Consolidated Edison Co. of New York 122pp 14357-146 24X Fiche: 50-000, 62/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JURDAN.E.L Division of Engineering & Quality Assurance. 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche: 50-000, 82/08/05, 8204210407

DOCKET BIN-50-486 CALLAWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

8208260029 FOIA request for all insps made by OSHA of facilities & related documents

Tolery, M Affiliation Unknown 82/07/22 KEPPLER, J 0 Region 3, Office of Director ip 14589 252 24X Fiche 50-483, 82/07/22,

8208260035 Responds to FOIA request for all image made by OSHA of facilities & related documents NRC has no documents subj to

request
FELTON, J M Division of Rules and Records 82/08/06 IQOE, V M
Affiliation Unknown 1p 14589 253 24X Fiche 50-483,82/08/06.

8208240322 Submits status & approx installation & const costs for unit, in response to NRC request, per util 820423 request to

in response to NKC request, per Util 820423 request to resctind CPRR-140 BCHNELL, D F Union Electric Co 82/08/17 DENTON, H R Defice of Nuclear Reactor Regulation, Director 3pp 14520 290 24X Fiche 30-485, 82/08/17, 8208240322

DOCKET STN-50-408 PERKINS NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Syc list encl pircks, HJ. Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001, 24X Fiche 50-000,82/07/02,8207080064

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Eve list encl EISEKHHT. D O Division of Licensing B2/08/09 Consolidated Edison Co. of New York 1p 14356 332 24X Fiche 50-000, 82/08/09, D208090194

I Financial information

8208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981. TUCKER, H B Do

Repris for 1781.
TUCKER, H B Duke Power Co. 82/08/24 DENTON, H R. D.
Nuclear Reactor Regulation, Director 2pp 14599, 227
Fiche: 50-000, 82/08/24, 8208300328

--8208300335 Annual Financial Rept 1981, HORN, C. Duke Power Co 82/02/15 48pp Fiche, 50-000, 82/08/24, 8208300328 14599 OOA 24X

Inspection reports. IE Bulletins & correspondence

04210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV)

Usaking Wor list encl.

Leakage Wor list encl.

JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/16

Consolidated Edison Co. of New York. 87pp 14356 274 24X

Fichs. 80-000. 82/07/16. 8204210393

204210375 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Byo 1614 encl.

JORDAN.E.L Division of Engineering & Guality Assurance 92/07/19

Michigan Univ of. 112pp 14358 001. 24X Fiche 50-000.82/07/19, 8204210395

204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl
JURDAM EL Division of Engineering & Quality Assurance 82/07/20
Consolidated Edison Co of New York 112pp 14381 001 24X
Fiche: 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride

Overpacks " Svc list enci COBB.L I. Division of Fuel Facilities, Materials & Sefeguards 82/07/20. Consolidated Edison Co. of New York 71pp. 1435 24X Fiche: 50-000, 82/07/20, 8204210397.

8204210398 iE Info Notice 82-26. "RGIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl URDAN.E.L Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co. of New York 112pp. 14194 321 24X Fiche: 50-000, 82/07/22, 8204210398,

8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380 i15 24X Fiche 50-000, 82/07/23, 8204210401

B204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance. 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Ficha 50-000,82/07/26,8204210403

8204210405 [E Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000.82/07/28,8204210405

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407

DOCKET BTN-50-489 PERKINS NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for QL & holders of CP re Commission approved charter for CROR, Svc list encl
DIRCKS, W J Dffice of the Executive Director for Operations
82/07/02 Consolidated Edison Co of New York 93pp 14194,001
24X Fichs 50-000,82/07/02,8207080064

820B090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl EIBENHUT. D @ Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000, 82/08/09, 8208090194

I Financial information

8208300328 Forwards util & NC Municipal Power Agency Annual Financial

Repte for 1941. TUCKER, H B Duke Power Co B2/08/24 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 14599 227 24X Fiche 50-000, 82/08/24, 8208300328

--9208300335 Annual Financial Rept 1981 HORN, C Duke Power Co 82/02/15 Fiche 50-000, 82/08/24, 8208300328 48pp 14599 006 24X

Q Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN E L. Division of Engineering & Guality Assurance 82/07/ Consolidated Edison Co of New York 87pp 14386 274, 24X Fiche 50-000,82/07/16.8204210393 82/07/16

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Rediation" Svc 1ist encl JORDAN, Et. Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 112pp 14358.001 24X Fiche 50-000, 82/07/19,

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressurs," Svc list encl JRRDAN,E L Division of Engineering & Quality Assurance, 82/07/20 Consolidated Edison Co. of New York 112pp 14381 001, 24X Fiche 50-000,82/07/20,8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list ancl COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/07/20, Consolidated Edison Co. of New York. 7ipp 14357; 2: 24X Fiche. 50-000, 82/07/20, 8204210397

- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York 122pp 14380,115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Bupport Pin Failures at Westinghouse PWRs " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120, 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Cartain Westinghouse PWR Power Plants" Svc list encl JORDAN.E. L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Hork in Fuel Storage Pool " Svc list encl JURDAN,E L. Division of Engineering & Quality Assurance, 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl, JORDAN.E.L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp. 14388 201 24X Fiche 50-000,82/08/05,8204210407
- DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8207080064 Generic itr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR 8vc list encl
 DIRCKS,W J Office of the Executive Director for Operations
 82/07/02 Consciidated Edison Co of New York. 93pp 14194,001
 24X Fiche 50-000,82/07/02,8207080064
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CF & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bv list encl EISENHUT, D 0 Division of Licensing 82/08/09. Consolidated Edison Co. of New York. 1p. 14356 332 24X Fiche 50-000, 82/08/09, 8208090194
- I Financial information
- 8208300328 Forwards util & NC Municipal Power Agency Annual Financial Rapts for 1981 TUCKER.H B Duke Power Co 82/08/24. DENTON:H R Office of Nuclear Reactor Regulation. Director 2pp 14599:227. 24X Fiche 50-000:82/08/24.8208300328
- --8208300335 Annual Financial Rept 1781. HORN:C Duke Power Co 82/02/15. 48pp 14597 006 24X Fiche. 50-000, 82/08/24, 8208300328
- Q Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list encl.
 JORDAN.E.L Division of Engineering & Quality Assurance, 82/07/16 Consolidated Edison Co. of New York, 87pp 14356,274, 24% Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Davices for External Radiation "Syc list encl.

 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19

 Michigan, Univ. of 112pp. 14358, 001 24X Fiche; 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Feilures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co. of New York 112pp 14381.001. 24X Fiche: 30-000.82/07/20.8204210396

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357, 276 24X Fiche 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L. Division of Englineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp, 14194,321, 24X Fiche,50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Bvc list encl, JORDAN E L. Division of Engineering & Quality Assurance B2/07/23. Consolidated Edison Co of New York 122pp 14380.115, 24X Fiche, 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-27, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Hestinghouse PWRs " Svc list encl. JORDAN E L Division of Engineering & Quality Assurance, 82/07/23, Consolidated Edison Co of New York 127pp 14194-120. 24X Fiche 50-000.82/07/23,8204210402
- 8204210403 IE info Notice 82-30, "Loss of Thermal Sleeves in RGB Piping at Certain Hestinghouse PHR Power Plants " Syc list encl, JORDAN.E L. Division of Engineering & Quality Assurance 62/07/26 Consolidated Edison Co of New York, 12ipp, 14357.013, 24X Fiche. 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Hork in Fuel Storage Pool " Svc list encl. JORDAN-E,L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pg 14357 146. 24X Fiche 50-000,82/07/28,8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Depradation Resulting From Baffle Water-Jet Impingement " Bvc list encl.
 JORDAN,E L. Division of Engineering & Quality Assurance 82/08/05.
 Consolidated Edison Co. of New York 117pp 14388 201, 24X Fiche: 50-000. 82/08/05.8204210407
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8207080064 Ceneric ltr to all licansess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR SVC list encl.
 DIRCKS.W J. Office of the Executive Director for Operations 82/07/02. Consolidated Edison Co. of New York 93pp. 14194-001 24X Fiche-50-000, 82/07/02, 8207080064
- 8208090194 Ceneric Ltr 82-i4 to all reactor licenses, holders of CP 4 applicants re submittel of documents to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list enci.
 EIBENHUT, D 9 Division of Licensing 82/08/09, Consolidated Edison Co. of New York ip. 14354 332 24X Fiche 50-000,82/08/09,8208090194.
- I. Financial information
- 8208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981. TUCKER: H B Duke Power Co. 82/08/24. DENTON: H R Office of Nuclear Reactor Regulation, Director ADENSAM, E. G Licensing Branch 4. 2pp. 14599: 227 24X Fiche: 50-000, 82/08/24, 8208300328.
- --8208300335 Annual Financial Rept 1981 HORN.C., LEE.H.S. Duke Power Co. 82/02/15. 48pp 14599; 006. 24% Fiche: 50-000,82/08/24,8208300328.
- Q. Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage," Svc list ancl. JORDAN.E.L Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co of New York. 87pp. 14356.274 24 X Fiche: 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Byc 11st encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp. 14358:001. 24X Fiche: 50-000, 82/07/19, 8204210395.

- 8204210396 IE Info Notice 82-29, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN:E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210374
- 8204210397 IE Info Notice 82-24, "Hater Leaking From U Hexafluoride Overpacks" Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000.82/07/23.8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Quide Tube Bupport Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche, 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants " 8vc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-3; "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche: 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Bvc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- R Periodic operating reports & related correspondence
- 820B170159 Forwards first quarter 1982 Yellow Book updates re const status. EDMARDS,Q L Dute Power Co 82/05/20 LOVELACC,W H Management Information Branch 5pp 14364-340 24X Fiche 50-000,82/05/20, 8208170189
- DCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2
 - Application/construction stage documents & correspondence
- B207080064 Generic ltr to all licensees of operating plants, applicants for CL & holders of CP re Commission approved charter for CRGR. Svc list encl
 DIRCKB, H J Office of the Executive Director for Operations
 B2/07/02. Consolidated Edison Co of New York 93pp 14194.001
 24X Fiche 50-000, 82/07/02. B207080064
- 3208090194 Deneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list enc! EISENMUT.D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York. ip 14356.332 24X Fiche 50-000.82/08/09, 9208090194
- I. Financial information
- 8208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981 TUCKER, H B Duke Power Co 82/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14599 227 24X Fiche: 50-000, 82/08/24, 8208300328
- --8208300335 Annual Financial Rept 1981 #DRN: C. Duke Power Co 82/02/15 48pp 14599 006 24X Fiche: 50-000, 82/08/24, 8208300328

- @ Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82~23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list enci JORDAN.E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356-274 24X Fiche 50-000
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/19 Michigan. Univ of 112pp, 14358 001 24X Fiche 50-000.82/07/19.8204210395
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list enc! JORDAN.E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co. of New York 112pp 14381 001 24X Fiche 50-000.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 62/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 IE Info Natice B2-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche. 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 62/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche. 50-000, 82/08/05, 8204210407
- R Periodic operating reports & related correspondence
- 8208170159 Forwards first quarter 1982 Yellow Book updates re const status EDWARDS.O L. Duke Power Co 82/05/20 LOVELACE,W H Management Information Branch 5pp 14364 340 24X Fiche 50-000,82/05/20, 8208170159
- DUCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR BVC list encl
 DIRCKB.W J. Diffice of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194-001,
 24X Fiche. 50-000, 82/07/02, 8207080064
- 8208090174 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Syc list enci EISENHUT, D G Division of Licensing 82/08/07 Consolidated Edison Co of New York, 1p 14356 332 24X Fiche. 50-000.82/08/09, 8208090174

I Financial information

- 8208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981
 - Repts for 1961 TUCKER, H B Duke Power Co 82/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14599 227 24X Fiche 50-000, 82/08/24, 8208300328
- --8208300335 Annual Financial Rept 1981 HURN.C Duke Power Co 82/02/15 48pp 14599 006 24X Fiche 50-000,82/08/24,8208300328
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/16, Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Fressure " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list enc! CDBs.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York. 7ipp. 14357-276 24X Fiche 50-000,82/07/20,8204210397
- B204210398 IE Info Notice B2~26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN:E L Division of Engineering & Quality Assurance B2/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50~000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl, JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 II5 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Ouide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants" Bvc list encl.

 JORDAN.E L Division of Engineering & Guality Assurance, 82/07/26,
 Consolidated Edison Co of New York, 121pp 14357:013, 24X
 Fiche, 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edition Co of New York 122pp 14357 146 24X Fiche 50-000.82/07/28:8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingment " Svc list encl.
 JORDAN,E L. Division of Enginesring & Quality Assurance. 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000.82/08/05.8204210407
- R Periodic operating reports & related correspondence
- B208170159 Forwards first quarter 1982 Yellow Book updates re const status EDHARDS, O. L. Duke Power Co 82/05/20 LOVELACE, W. H. Managament Information Branch 5pp 14364 340 24X Fiche: 50-000, 82/05/20, B208170159

- DOCKET STN-50-495 SWESSAR-P1
- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl EISENHUT, D G Division of Licensing B2/08/09, Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000, B2/08/09, B208090194
- Q Inspection reports. IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl i, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl.
 JORDAN, E. L. Division of Engineering & Guelity Assurance 82/07/19
 Michigan, Univ. of 112pp 14358 001 24X Fiche 50-000,82/07/19,8204210395
- DOCKET STN-50-498 BOUTH TEXAS PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8208050447 Forwards revised portion of GA program for design & const phase, Revision 1, dtd 810422 Description of GA/GC program to be implemented upon Bechtel assumption of AE rasponsibilities will be submitted by 811211 OPREA, 0 W Houston Lighting & Power Co. 81/11/24 TEDEBCO, R L. Assistant Director for Licensing 3pp. 14217 359 24X Fiche, 50-498, 81/11/24, 8208030447
- --B208050454 Revised portion of GA program for design & const phase, Revision I. Description of GA/GC program to be implemented upon Bechtel assumption of AE responsibilities will be submitted by B11211 OPREA.O W Houston Lighting & Power Co 81/10/29 12pp 14217.356 24X Fiche 50-498,81/11/24.8208050447.
- 8207080064 Generic ltr to all licenses of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR SVC list encl
 DIRCKS.W J Office of the Executive Director for Operations.
 82/07/02 Consolidated Edison Co of New York 93pp 14194:001.
 24X Fiche 50-000.82/07/02.8207080064
- 8208020419 Confirms conversations re delation of Tech Specs from FSAR NRC has no objection to delation concomitant w/commitment to provide new Tech Specs 18 months prior to scheduled const completion.

 TEDESCO.R L. Assistant Director for Licensing 82/07/07.

 DPREA, O. H. Houston Lighting & Power Co. 2pp. 14179 182 24X Ficher 50-498, 82/07/07, 9208020419.
- 8208030197 Forwards replacement Page 8 to environ protection control programs Revision 2 Encl mck sheet should be completed & returned as indicated BARKER, D G Houston Lighting & Power Co 82/07/29, SELLS, D. E. NRC No Detailed Affiliation Given, 3pp. 14160 003, 24X Fiche, 50-498, 82/07/29, 8208030197
- 8208100083 Advises that responses to Core Performance Branch, Thermal Hydraulics Section 820609 request for add1 info will be submitted in form of amend to FSAR prior to 821231. GOLDBERG, J H Houston Lighting & Power Co 82/08/04 NOVAK, T. M. Assistant Director for Licensing 2pp. 14276
- 8208170282 Advises that util will develop & provide secondary syschemistry control program, in response to Guestion 482.1, per 820607 itr Response to Guestion 482.2 will be consistent w/Wastinghouse technical recommendations GOLDBERG, J H. Houston Lighting & Power Co. 82/08/06 NOVAK, T H. Assistant Director for Licensing. 2pp. 14367, 078. 24X Fichs. 50-498, 82/08/06, 8208170282
- 9208260272 Forwards revised cost estimate & const schedule for project Based upon fuel load dates of Dec 1986 for Unit 1 & Dec 1988 for Unit 2.commercial operation expected to begin in May 1987 & May 1989, respectively.

 GOLDBERG, J H Houston Lighting & Power Co. 82/08/19 DENTON, H R. Office of Nuclear Reactor Regulation, Director. 2pp. 14554:281, 24X Fiche 50-498, 82/08/19, 8208260292.

Q Adjudicatory correspondence

- 820B060092 Advises that util will not respond to Brown & Root B20721 ltr Many statements are inaccurate & are subj of pending litigation or are not matl to any issue before ASLB Certificate of Evc encl NEWHAN, J R Lowenstein, Newman, Reis, Atelrad & Toll NEWHAN, J R. Houston Lighting & Fower Co B2/08/04 BECHWEFER, C Atomic Bafety and Licensing Board Panel 3pp 14238 147 24X Fiche 50-498, 82/08/04, 8208060092
- 8208090272 Joint motion to reopen record for limited purpose of admitting documents referenced in encl stipulation SIRKIN.L Citizens Concerned About Nuclear Power, Inc. NEWMAN, J. R. Houston Lighting & Power Co. GUTIERREZ, J. M. Hearing Branch 3, 82/08/05 About Safety and Licensing Board Panel ip 14271, 124 24X Fiche 50-478, 82/08/05, 8208090272
- --8208090278 Stipulation agreeing that listed exhibits be admitted into evidence w/o formal proof of admissibility, authenticity & truthfulness Exhibits encl QUTIERREZ.J M Hearing Branch 3 NEMMAN.J R, Houston Lighting & Power Co SINKIN.L Citizens Concerned About Nuclear Power, Inc 82/08/05 41pp. 14271 125 24X Fiche 50-498.82/08/05.9208090272.
- 8208170114 Proposed findings of fact & conclusions of law in form of initial decision Certificate of Bvc encl * Houston Lighting & Power Co * Lowenstein, Newman, Reis, Axeirad & Toil 82/08/06 37ipp 14358 241 24X Fiche 50-498, 82/08/06, Conclusions
- 8208170153 Notion to incorporate and transcript corrections Proposed corrections reflect witness best recollection of answers given. Certificate of 8vc encl HUBSON.T B Houston Lighting & Power Co HUBSON.T B. Baker & Botts 82/08/06 Atomic Safety and Licensing Soard Panel. 49pp. 14344 224 24X Fichs 50-498,82/08/06,8208170153.
- 8208170258 Responses opposing Citizens Concerned About Nuclear Power, Inc 820730 motion to adopt Citizens for Equitable Utils Contentions 4-8. No basis provided for delayed interest in contention Certificate of Svc enc!

 AXELRAD, H Houston Lighting & Power Co AXELRAD, H Lowenstein, Newman, Reis, Axelrad & Toll 82/08/13, Atomic Safety and Licensing Board Panel 11pp 14367-104, 24X Ficher 50-498, 82/08/13, 8208170258
- 8208170260 Notice of appearance in OL proceeding Certificate of 8vc encl 81LVERMAN,D,J Houston Lighting & Power Co. 81LVERMAN,D,J, Lowenstein,Neuman,Reis,Axelrad & Toll. 82/08/13 3pp 14367,101 24X Fiche 50-498,82/08/13,8208170260
- 8208200106 Response opposing Citizens Concerned About Nuclear Power Inc 820723 motion to adopt contentions of Citizens for Equitable Utils Citizens failed to address five factors to be considered for untimely admission W/Certificate of 8vc OUTLERREZ.J M Hearing Branch 3 82/08/18 Atomic Safety and Licensing Board Panel 11pp. 14393-200. 24X Fiche.50-498.82/08/18, 8208200106

OB240228 Memorandum & order granting Citizens Concerned About Nuclear Power action for extension of time from 820827 to 820920 to file proposed findings of fact & conclusions of law Dates for other party filings revised.

BECHMOFFER, C Atomic Safety and Licensing Board Panel 62/08/19 Citizens Concerned About Nuclear Fower, Inc 3pp 14519.136. 24X Fichs. 50-498, 82/08/19.8208240226.

- 108250248 Response opposing Citizens Concerned About Nuclear Power 820804 petition to suspend const.Citizens refused to follow Commission review procedures.No legal or factual basis sxists for granting of petition.W/Certificate of Syc AXELRAD.M Houston Lighting & Power Co. AXELRAD.M Lowenstein.Neuman.Reis.Axelrad & Toll 82/08/24. Commissioners 2ipp 14542 349 24% Fiche.50-498.82/08/24,8208250248.
- 8208260133 Response to applicant 820806 motion to incorporate transcript corrections. Joins motion in part. suppls corrections & notes certain corrections which NRC cannot adopt or refute. Certificate of Svc encl.
 OUTIERREZ. J M Hearing Branch 3, 82/08/25 Atomic 8efety and Licensing Board Panel 9pp, 14554-341, 24X Fiche 50-498,82/08/25,8208260133
- G Inspection reports: IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Syc list encl, JORDAN, E.L. Division of Engineering & Quality Assurance, 82/07/16, Consolidated Edison Co. of New York. 87pp. 14356:274, 24X Fiche 50-000,82/07/16,82042(0393.

- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list enci
 JORDAN, E. L. Division of Engineering & Guality Assurance 92/07/19
 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20,8204210396
- 8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks " Svc list encl GOBB.L I. Division of Fuel Facilities, Haterials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194-321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Evc list encl.

 JORDAN, E L. Division of Engineering & Quality Assurance 82/07/23.

 Consolidated Edison Co. of New York 122pp 14380 115 24X

 Fiche, 30-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-27, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs." Syc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194-120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance, 82/07/26 Consolidated Edison Co of New York 121pp 14357:013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/07/28, Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Beffle Water-Jet Impingement " Svc list encl JORDAN.E L. Division of Engineering & Guelity Assurance, 82/08/05, Consolidated Edison Co. of New York, 117pp 14388:201 24X Fiche: 50-000, 82/08/05, 8204210407
- 8208200047 Forwards IE Insp. Repts 50-498/82-10 & 50-499/82-10 during June 1982 No noncompliance noted MADSEN.C L. Division of Resident, Reactor Project & Engineering Programs 82/08/05 OPREA.C.W Houston Lighting & Power Co. 2pp. 14392 325 24X Fiche.50-498/82/08/05/8208200047.
- --8208200054 IE Insp Repts 50-498/82-10 & 50-499/82-10 during June 1982. No noncompliance noted Major areas inspected const activities re transfer of engineering & mot functions from Brown & Root to Bechtel Power Corp HILL: H H , BOARDMAN. J. R : HUBACEK. N O. Region 4, Office of Director. 82/07/29, 16pp 14392 327 24X Fiche 50-498,82/08/05,8208200047
- 8208160312 Discusses IE Investigation Repts 50-498/82-02 & 50-499/82-02 on 820205-12 & 0311-19 & forwards notice of violation MADBEN, G. L. Division of Resident, Reactor Project & Engineering Programs. 82/08/11 OPREA.O.M. Houston Lighting & Power Co 2pp 14345-319 24% Fiche: 50-498.82/08/11.8208160312
- --8208160319 Notice of violation from investigation on 820205-12 & 0311-19 Noncompliance noted NRC not notified of deficiencies per 10GFR50, 55(e) within required 24-h period. # Division of Resident, Reactor Project & Engineering Programs. 82/08/11. 1p. 14345-321 24X Fiche 50-498,82/08/11.8208160312
- S. Reportable occurrences, LERs & related correspondence
- 8208030266 Third interim deficiency rept re potential for failure of certain Rockbestos Co coaxial cables. Initially reported on 81026. Completion of testing & analyses expected by 820930 Next rept expected by 821112.

 OREA, O M. Houston Lighting & Power Co 82/07/28 COLLINS, J. T. Region 4. Office of Director. 200. 14158: 129 24X

 Fiche: 50-498,82/07/28,8208030266

- 8208030542 First interim deficiency rept re incorrect motor operator weights for valves Initially reported on 820629 Bechtel will initiate nonconformance rept covering existing condition of valves identified Next rept will be submitted by 830429 OPREA.0 W Houston Lighting & Power Co 82/07/28 COLLINB.J T Region 4. Dffice of Director 3pp 14162 269 24x Fiche 50-498.82/07/28.8208030342
- 8208030217 Final deficiency rept re unanalyzed release pathway following LOCA Initially reported on 820701 Sys design revised to practude automatic operation of SIS/CSS cubicle sump pumps
 OPREA. G. W Houston Lighting & Power Co 82/07/29 COLLINS, J T Region 4. Office of Director 4pp 14159 327 24x
 Fichs 50-498, 82/07/27, 8208030219
- 8208160460 Fifth interim deficiency rept re use of fail open isolation dampers in HVAC design Initially reported on 820706 Design mod under consideration Next rept by 821018 OPREA, 0 W Houston Lighting & Power Co 82/08/06 COLLINS, J T Region 4, Office of Director Spp 14348 230 24x Fiche 50-498, 82/08/06, 8208160460
- 8208170110 Final deficiency rept re max/min soil density tests on essential cooling water backfill Initially reported on 800820 Requalification of bedding, foundation & backfill performed by Brown & Root 04 program revised OPREA.0 W Houston Lighting & Power Co. 82/08/11 CGLLINS.J T Region 4, Office of Director 5pp 14398 197 24x Fiche 50-498.82/08/11,8208170110
- 8208270423 Final deficiency rept re potential Pailure of leak detection sys to indicate flooding in safety injection/core spray sys pump cubicle train Initially reported on 820701 Structural mods to be performed on cubicles
 OPREA.9 W Houston Lighting & Power Co 82/08/19 COLLINS, J T Region 4. Office of Director 4 pp 14565 245 24X
 Fiche 50-498,82/08/19,8208270423
- 8208270454 First interim deficiency rept re potential malfunctioning of essential cooling water self-cleaning strainer bactwash discharge lines due to non-nuclear safety & non-Selsmic Category I nature Initially reported on 820723 OPREA.O W Houston Lighting & Power Ce 82/08/19 COLLINS, J T Region 4, Office of Director 4pp. 14565 265 24X Fiche 50-498,82/08/19,8208270454
- 8208310063 Interim deficiency rept re design of auxiliary feedwater sys Initially reported on 820727 Sechtel evaluating safety hazard re classification of pump recirculation lines Next rept by 820915
 OPREALO W Houston Lighting & Power Co 82/08/25 COLLINS, J. T Region 4, Office of Director 7pp 14690, 024 24X
 Fiche 50-498, 82/08/25, 8208310063
- DOCKET 6TN-50-499 SOUTH TEXAS PROJECT, UNIT 2

 A Application/construction stage documents & correspondence
- 82080\$0447 Forwards revised portion of QA program for design & const phase. Revision 1. dtd 810422 Description of QA/QC program to be implemented upon Bechtel assumption of AE responsibilities will be submitted by 811211 OPREA. O W Houston Lighting & Power Co 81/11/24 TEDESCO, R L Assistant Director for Licensing 3pp 14217 353 24X Fiche 50-498.81/11/24.8208050447
- --8208050454 Revised portion of QA program for design & const phase, Revision i Description of GA/OC program to be implemented upon Bechtel assumption of AE responsibilities will be submitted by 811211

 OPREA: 0 W Houston Lighting & Power Co 81/10/29 12pp 14217 356 24X Fiche 50-498, Bi/I1/24, B208050447
- 8207080064 Generic ltr to all licensess of operating plants, applicants for DL & holders of CP rs Commission approved charter for CRGR Syc list encl
 DIRCKS WJ Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp, 14194-001, 24X Fiche. 30-000, 82/07/02. 8207080064
- B208020419 Confirms conversations re deletion of Tech Specs from FBAR NRC has no objection to deletion concomitant w/commitment to provide new Tech Specs 18 months prior to scheduled const completion
 TEDESCOR L Assistant Director for Licensing B2/07/07
 DPREA, 0 W Houston Lighting & Power Co 2pp 14179-182, 24X
 Fiche 50-498,82/07/07,8208020419

- 8208030197 Forwards replacement Page B to environ protection control program.Revision 2 Encl ack sheet should be completed & returned as indicated BARKER, D 0 Houston Lighting & Power Co B2/07/29, BELLB, D E NRC No Detailed Affiliation Given 3pp 14160.003 24X Fiche 50-498, 82/07/29, 8208030197
- 8208100083 Advises that responses to Core Performance Branch, Thermal Hydraulics Section 820607 request for addl info will be submitted in form of amend to FSAR prior to 821231 GOLDBERG, J H Houston Lighting & Power Co 82/08/04, NOVAK, T. M Assistant Director for Licensing 2pp 14296:141, 24X Fiche 50-498,82/08/04.8208100083
- B208170282 Advises that util will develop & provide Secondary sys chemistry control program; in response to Question 482 liper B20607 itr Response to Question 482 2 will be consistent w/Westinghouse technical recommendations GDLDBERG.J H. Houston Lighting & Power Co. B2/08/06. NOVAK, T. M Assistant Director for Licensing 2pp 14367 078 24X Fiche 50-498,82/08/06.820B170282
- 8208260292 Forwards revised cost estimate & const schedule for project. Based upon fuel load dates of Dec 1986 for Unit 1 & Dec 1988 for Unit 2, commercial operation expected to begin in May 1987 & Hay 1987 respectively.

 OULDBERG, J H. Houston Lighting & Power Co. 82/08/19 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 2pp 14534 281 24X Fiche 30-498,82/08/19,8208240292
- O Adjudicatory correspondence
- B208060092 Advises that util will not respond to Brown & Root 820721 itr Many statements are inaccurate & are subj of pending litigation or are not mail to any issue before ABLB. Cartificate of Svc enci NEUMAN.JR Lowenstein.Neuman.Reis.Axelrad & Toll. NEUMAN.JR Houston Lighting & Power Co 82/08/04 DECHHOEFER.C Atomic Bafety and Licensing Board Panel 3pp 14238 147. 24X Fiche 50-478,82/08/04.8208060092
- 8208090272 Joint motion to reopen record for limited purpose of admitting documents referenced in encl stipulation SINKIN-L Cititiens Concerned About Nuclear Power, Inc. NEWMAN, J.R. Houston Lighting & Power Co. OUTIERREZ. J.H. Hearing Branch 3 82/08/05 Atomic Safety and Licensing Board Panel 19 14271 124 24X Fiche 50-498,82/08/05,8208090272.
- --B208090278 Stipulation agreeing that listed exhibits be admitted into evidence w/o formal proof of admissibility, authenticity & truthfulness Exhibits encl
 OUTIERREZ.J H Hearing Branch 3 NEHMAN.J R Houston Lighting & Power Co SINKIN-L Citizens Concerned About Nuclear Power, Inc. 82/08/05 41pp. 14271-125. 24X Ficher 50-498, 82/08/05, 8208090272
- 8208170114 Proposed findings of fact & conclusions of law in form of initial decision Certificate of Svc enci * Houston Lighting & Power Co. * Lowenstein, Newman, Reis, Axelrad & Toli 82/08/06 37ipp 14358 241 24X Fiche 50-498, 82/08/06, 8208170114
- 8208170153 Motion to incorporate and transcript corrections Proposed Corrections reflect witness best recollection of answers given Certificate of Syc and.
 HUDSON, T. B. Houston Lighting & Power Co. HUDSON, T. B. Baker & Botts 82/08/06 Atomic Sefety and Licensing Board Panel 67pp. 14364 224 24X Ficha: 30-498,82/08/06, B208170133
- 8208170258 Responses opposing Citizens Concerned About Nuclear Power, Inc 820730 motion to adopt Citizens for Equitable Utils Contentions 4-8 No basis provided for delayed interest in contention. Certificate of 8vc encl.

 AXELRAD. M Houston Lighting & Power Co AXELRAD. M Lowenstein. Newman, Reis, Axelrad & Toll 82/08/13. Atomic 8afety and Licensing Board Panel 11pp 14367.104. 24X Fiche. 50-498, 82/08/13, 8208170258.
- 8208170260 Notice of appearance in OL proceeding Certificate of Sycent.
 SILVERMAN.D.J. Houston Lighting & Power Co. BILVERMAN.D.J.
 Lowenstein Newman. Reis. Axeirad & Toll 82/08/13. 3pp. 14367: 101
 24X Fiche 50-498.82/08/13.8208170260.
- 820820010A Response opposing Citizens Concerned About Nuclear Power, Inc 820723 motion to adopt contentions of Citizens for Equitable Utils Citizens failed to address five factors to be considered for untimely admission, W/Certificate of Suc OUTIERREZ, J. M. Hearing Branch 3 82/08/18, Atomic Safety and Licensing Board Panel, 11pp 14393 200 24X Ficher 50-498,82/08/18,8208200106

- 8208240228 Mamorandum & order granting Citizens Concerned About Nuclear Power motion for extension of time from 820827 to 820920 to file proposed findings of fact & conclusions of law Dates for other party filings revised

 BECHNOEFER.C Atomic Safety and Licensing Board Panel 82/08/19

 Citizens Concerned About Nuclear Power, Inc. 3pp. 14519-136-24X

 Fiche 50-498,82/08/19,8208240228
- 8208250248 Response opposing Citizens Concerned About Nuclear Power 920804 petition to suspend const Citizens refused to follow Commission review procedures No legal or factual basis exists for granting of petition W/Certificate of Svc AXELRAD.M Houston Lighting & Power Co AXELRAD.M Commission.Reis.Azelrad & Toll 82/08/24 Commissioners 21pp. 14542 349 24% Fiche.50-498.82/08/24 9208250248
- 8208250133 Response to applicant 820805 motion to incorporate transcript corrections Joins motion in part supply corrections & notes certain corrections with NRC cannot adopt or refute Certificate of Svc encl CUTTERREZ, J H Hearing Branch 3 82/08/25 Atomic Sefety and Licensing Board Panel 7pp 14954 341 24X Fiche 50-478,82708/25,8208250133
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN EL Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274. 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Into Notice 81-26, Part 3, Suppl 1: "Clarification of Placement of Personnyl Monitoring Devices for External Radiation " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19, Michigan, Univ. of 112pp. 14358 001 24X Fiche. 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-29, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc Iist encl URPDAN.E.L Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche.50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I. Division of Fuel Facilities, Materials & Safeguards 82/07/20. Consolidated Edison Co of New York. 71pp 14357:276 24% Fiche 50-000:82/07/20.8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Vaive Failures " Svc list enc! JORDAN, E. L. Division of Engineering & Quality Assurance. B2/07/22 Consolidated Edison Co. of New York. 112pp 14174 321 24X Fiche 50-000, 82/07/22, 82042(0378
- 8204210401 IE Info Notice 82-29, "Hydrogen Explosion While Grinding in Vicinity of Drainad & Open RGS " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 62/07/29 Consolidated Edison Go of New York 122pp 14380,115 24X Fiche 50-000, 82/07/29, 8204210401.
- 8204210402 [E Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Mestinghouse PMRs " 8vc list encl JORDAN,E L. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co of New York. 127pp 14194-120, 24X Fiche, 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Hestinghouse PHR fower Plants " Svc list enci, JORDAN E L Division of Engineering & Quality Assurance, 82/07/26, Consolidated Edison Co of New York 12/pp. 14357.013 24X Fiche 50-000,82/07/26.8204210403
- 8204210405 IE info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357-146 24X Fiche: 50-000, 82/07/28, 8204210405.
 - od Degradation Resulting From encl 'ity Assurance, 82/08/05, pp 14386:201, 24X
 - O & 50-499/82-10 during Project & Engineering ighting & Power Co. 2pp. 00047.

- --8208200054 IE Insp Repts 50-498/82-10 & 50-497/82-10 during June 1982
 No noncompliance noted Major areas inspected const activities
 re transfer of engineering & mot functions from Brown & Root
 to Bechtel Power Corp
 HILL,W M. BDARDMAN, J R., HUBACEK,W G. Region 4, Office of
 Director 82/07/29 16pp 14392 327 24X Fiche 50-498,82/08/05,
 8208200047
- 8208160312 Discusses IE Investigation Repts 50-498/82-02 & 50-499/82-02 on 820205-12 & 0311-19 & forwards notice of violation MADSEN.0 L Division of Resident. Reactor Project & Engineering Programs 82/08/11 0/PREA.0 W Houston Lighting & Power Co 2pp 14345 319 24X Fiche 50-498/82/08/11.8208160312
- --B20B160319 Notice of violation from investigation on B20205-12 & O311-19 Noncompliance noted NRC not notified of deficiencies per 10CFR80 53(e) within required 24-h period Division of Resident. Reactor Project & Engineering Programs, 62/08/11 p 14345 321 24X Fiche 50-498,82/08/11,8208160312
- S Reportable occurrences. LERs & related correspondence
- 8208030265 Third interim deficiency rept re potential for failure of certain Rockbestos Co coaxial cables Initially reported on 81;026 Completion of testing & analyses expected by 820930 Next rapt expected by 821;12

 OPREA: O W Houston Lighting & Power Co 82/07/28 COLLINS: J T. Region 4. Office of Director. 2pp 14:158 129 24X

 Fiche 50-498: 82/07/28; 8208030266
- 8208030542 First interim deficiency rept re incorrect motor operator weights for valves initially reported on 820827 Bechtel will initiate nonconformance rept covering existing condition of valves identified Next rept will be submitted by 830429 OPREA.9 W Houston Lighting & Power Co 82/07/28, COLLINS, J T Region 4. Office of Director 3pp. 14162 269 24X Fiche: 50-498, 82/07/28, 8208030542
- 9208030219 Final deficiency rept re unanalyzed release pathway following LOCA Initially reported on 820701 Sys design revised to practice automatic operation of 818/CSB cubicle sump pumps.

 OPREA-Q W. Houston Lighting & Power Co B2/07/29 COLLINS, J T Region 4. Office of Director App 14159 327. 24X Fiche 50-498, 82/07/29, 8208030219
- 8208160460 Fifth interim deficiency rept re use of fail open isolation dampers in HVAC design Initially reported on 820706 Design mod under consideration Next rept by 821018 OPREA:0 H Houston Lighting & Power Co 82/08/06 COLLINS, J T, Region 4, Office of Director 5pp 14348 230 24X Fiche 50-498.82/08/06.8208160460
- 8208170110 Final deficiency tept re max/min soil density tests on essential cooling water backfill Initially reported on BOO620 Requalification of bedding foundation & backfill performed by Brown & Root GA program revised OPREA:0 W Houston Lighting & Power Co 82/08/11 COLLINS, J T Region 4. Office of Director Spp 14358.197 24X Fiche 30-498, 82/08/11, 8208170110
- 8208270423 Final deficiency rept re potential failure of leak detection mys to indicate flooding in safety injection/core sprmy eys pump cubicle train. Initially reported on 820701 Structural mods to be performed on cubicles.

 OPREA:0 W Houston Lighting & Power Co 82/09/19 COLLINS, J. T Region 4, Office of Director 4pp 14565 245, 24% Fichs:50-498, 82/08/19, 8208270423
- 8208270454 First interim deficiency rept re potential malfunctioning of essential cooling water self-cleaning strainer backwash discharge lines due to mon-nuclear safety & mon-Beismic Category i nature initially reported on 820723 OPREA.9. W Houston Lighting & Power Co. 82/08/17 COLLINS, J. T. Ragion 4. Office of Director. App. 14365: 265, 24% Fiche: 50-498, 82/08/19,8208270454
- 8208310063 Interim deficiency rept re design of auxiliary feedwater sys Initially reported on 850727, Bechtel evaluating sefety hazard re classification of pump recirculation lines Next rept by 820913.

 OPREA, O. W. Houston Lighting & Power Co 82/08/25 COLLING, J. T Region 4. Office of Director 7pp. 14690, 024, 24X Fiche: 50-498, 82/08/25, 9208310063

- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2
- G Inspection reports. IE Bulletins & correspondence
- 8204210393 IE info Notice 82-23, "Hain Steam Isolation Valve (MBIV) Leakage " Svc list encl JGRDAN,E L Division of Engineering & Guality Assurance. 82/07/16 Consolidated Edison Co of New York 87pp 14356-274 24X Fiche, 50-000, 82/07/16, 8204210393
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Herafluoride Overpacks " Svc list encl. COB8.L.I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000.82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RGIC & HPCI Turbins Exhaust Check Valve Failures " Svc list encl JGRDAN,E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194,321, 24X Fiche:50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York. 122pp 14380 118 24X Fichs 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/07/23 Consolidated Edison Co. of New York 127pp 14174-120, 24X Fiche-50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl, JORDAN: EL Division of Engineering & Guality Assurance 62/07/26. Consolidated Edison Co of New York 121pp 14357.013 24X Fiche. 50-000: 82/07/26. 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, E L Division of Engineering & Guality Assurance, 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche. 50-000, 82/07/28.8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement," Svc list entl JORDAN, E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp, 14388;201, 24X Fiche. 50-000, 82/08/05, 8204210407
- DOCKET 50-501 DAVIS-BEBBE NUCLEAR POWER STATION, UNIT 3

 G. Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (HSIV) Leakage." Syc list enci JORDANIE L Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co of New York. 87pp. 14356-274 24X Fiche: 50-000, 82/07/16, 8204210393.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JORDAN.E.L Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York. 112pp. 14381:001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Hater Leaking From U Hexafluoride Overpacks " Bvc list encl. COBB.L.I. Division of Fuel Facilities, Materials & Bafeguards 82/07/20. Consolidated Edison Go of New York 71pp 14357:276 24X Fiche: 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbins Exhaust Check Valve Failures," Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/22, Consolidated Edison Co of New York 112pp. 14194-321, 24X Fiche: 50-000, 82/07/22, 8204210398.

- 8204210401 IE Info Notice 82-28, "Mydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche. 50-000, 82/07/23, 8204210401.
- 8204210402 IE Info Notice 82-27, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." 8vc list encl JORDAN.E L. Division of Engineering & Guality Assurance. 82/07/23 Consolidated Edison Co of New York 127pp. 14174 120, 24X Fiche: 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Bvc list encl JORDAN.E L. Division of Engineering & Quality Assurance Consolidated Edison Co of New York 12ipp 14957:013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Byo list and JARDAN,E L. Division of Engineering & Quality Assurance. 82/07/28, Consolidated Edison Co of New York. 122pp 14357 146 24X Fiche: 50-000, 82/07/28, 8204210405.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Saffis Water-Jet Impingement" Svc list encl
 JORDAN.E.L. Division of Engineering & Guality Assurance 62/08/05
 Consolidated Edison Co of New York. 117pp 14368.201. 24X
 Fiche: 50-000, 82/08/05, 8204210407.
- DOCKET BIN-50-502 HAVEN NUCLEAR PLANT, UNIT 1
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV)
 Leakage " Svc list enc!
 JORDAN.E L. Division of Engineering & Quality Assurance 62/07/16
 Consolidated Edison Co of New York 87pp. 14336 274. 24X
 Fiche: 50-000, 82/07/16, 8204210393
- 8204210396 IE Info Notice 82-23, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl. JORDAN,E L. Division of Engineering & Quality Assurance. 82/07/20, Consolidated Edison Co of New York 112pp. 143B1 001 24X Fiche: 50-000, 82/07/20, 8204210396.
- 8204210397 IE Info Notice 82-24, "Hater Leaking From U Hexafluoride Overpacks " Svc list encl COB6.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20, Consolidated Edison Co. of New York, 7ipp. 14357:276 24X Fichs 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RGIC & PCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN,E L. Division of Engineering & Quality Assurance. 82/07/22, Consolidated Edison Co of New York 112pp. 14194.321 24X Fiche.50-000,82/07/22,8204210398.
- B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Bvc list encl.

 JORDAN, E. L. Division of Engineering & Guslity Assurance. B2/07/23

 Consolidated Edison Co. of New York 122pp. 14380 115. 24X

 Fiche: 50-000, B2/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23, Consolidated Edison Co of New York, 127pp. 14174.120 24X Fiche: 50-000, 82/07/23, 8204210402.
- 8204210403 IE Info Notice 82-00, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl. JORDAN-E.L. Division of Engineering & Quality Assurance. 82/07/26 Convolidated Edison Co of New York 121pp 14957:013. 24% Fiche: 50-000, 82/07/26, 8204210403.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
 JORDAN E L. Division of Engineering & Quality Assurance. B2/07/28, Consolidated Edison Co of New York, 122pp. 14357:146 24X Fiche: 50-000, 82/07/28, 8204210405.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl.
 JORDAN,E.L. Division of Engineering & Quality Assurance, 82/08/05 Consolidated Edison Co. of New York 117pp. 14388; 201, 24X Fiche: 50-000, 82/08/03, 8204210407.

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

- B2070B0064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR. Svc list encl
 - DIRCKS, W J Office of the Executive Director for Operations 14194 001 82/07/02 Consolidated Edison Co of New York 24% Fiche 50-000,82/07/02,8207080064 9300
- 8208030233 Responds to NRC 820625 questions re use of ITT-Grinnell pipe clamps Several items require testing programs which could not be completed prior to response Commitments re completion
 - of items encl.
 BDUCHEY.O D Hashington Public Power Supply System 92/07/30
 HIRAOLIAF.J Licensing Branch 3 lipp 14158 288 24X
 Fiche 30-508, 82/07/30, 8208030233
- 8208100072 Confirms 820727 telcon re use of ASME Code Case N-308, "Documentation of Repairs & Replacement of Components in Nuclear Power Plants " Util will implement code case as written & approved by NRC BOUCHEY, Q D. Washington Public Power Supply System 82/08/04, EISENHUT, D. Q Division of Licensing ip 14276 180 24X
 - Fiche 50-397, 82/08/04, 8208100072
- 8208270001 Forwards application for OL.consisting of FSAR, environ rept (filed in PDR Category C), emergency preparedness plan (filed in Central Files), fire protection sys info (filed in PDR Category F) & antitrust info (filed in PDR Category M)

 800CHEY, 0 D Washington Public Power Supply System 82/08/20

 DENTON, HR Office of Nuclear Reactor Regulation, Director Spp. 15473 001. 24X Fiche 50-508,82/08/20.8208270001
- --8208270011 Application for DL, consisting of FSAR, environ rept (filed in PDR Category C), emergency preparedness plan (filed in Central Files), fire protection sys info (filed in PDR Category F) & antitrust info (filed in PDR Category M), 30UCHEY, O. D Washington Public Power Bupply System 82/08/20 26pp. 15473 006 24% Fiche 50-508,82/08/20,8208270001.
- C Utility Environmental Report (ER), amends & correspondence
- 9209270001 Forwards environ rept BOUCHEY, 0 D Washington Public Power Supply System 62/09. DENTON, HR Office of Nuclear Reactor Regulation, Director 15473 001. 24% Fichs. 50-508, 62/09/20, 8208270001 82/08/20.
- --8208270017 Environ rept for HPPSS Unit 3

 4 Washington Public Power Supply System 82/08/20 450pp
 Fiche 50-508,82/08/20,8208270001 24X
 - Security, medical, emergency & fire protection plans
 - 08270001 Forwards emergency preparedness plan & fire protection sys info Plan withheld BOUCHEY, Q D Wash BOUCHEY, O D Washington Public Power Supply System 82/08/3 DENTON, H. R Office of Nuclear Reactor Regulation, Director 15473: 001 24X Fiche 50-508, 82/08/20, 8208270001. 82/08/20

1 General correspondence

- 1208200090 Forwards corporate organizational changes effective 820810 Changes will be reflected in future revisions to FBAR & operational QA program description 800UREV,0 D. Washington Public Power Supply System 82/08/16 NOVAK,T H Assistant Director for Licensing. 4pp. 14393,241. 24X Fiche 50-397,82/08/16,8208200090
- . Utility Final Safety Analysis Report (FSAR) & amands
- 8208270001 Forwards application for QL:consisting of FSAR, environ rept (filed in PDR Category C), emergency preparedness plan (filed in Central Files), fire protection sys info (filed in PDR Category F) & antitrust (nfo (filed in PDR Category H) 80UCHEY, O D. Washington Public Power Supply System 82/08/20, DENTON, HR Dffice of Nuclear Reactor Regulation, Director 3pp 15473:001 24X Ficher 50-508, 82/08/20, 8208270001
- -8208270005 FSAR for HPPSS Unit 3 Four oversize maps encl. Aparture cards available in PDR 82/08/20 8,300pp

- --8208270011 Application for OL, consisting of FSAR, environ rept (filed in PDR Category C), emergency preparedness plan (filed in Central Files), fire protection sys info (filed in PDR Category F) & antitrust info (filed in PDR Category M) BDUCHEY, C D Washington Public Power Supply System 02/08/20 26pp 15473 004 24% Fiche 50-508,82/08/20,8208270001
- 8208270020 Chapter 1 to WPPS8 Unit 3 F9AR: "Introduction & Ceneral Description of Plant Site Characteristics "
 * Washington Public Power Supply System 82/08/20 800pp 15476.027 24X Fiche 50-508,82/08/20.8208270020
- B20B270021 Chapter 2 to WPPSS Unit 3 FBAR. "Site Characteristics " Two oversize maps encl Aperture cards available in FDR " Washington Public Power Supply System 82/08/20 1.100pp 15476 296 244 Fiche 50-508.82/08/20.8208270021
- 8208270026 App 2 4A to HPPSS Unit 3 FSAR. "Low Flow Duration & flow Frequency Analysis at Diffuser Site on Chehalis River "
 # Washington Public Power Supply System 82/08/20 7pp
 15478 231 24X Fiche 30-508,82/08/20,8208270026
- 8208270028 App 2 5A to WPP88 Unit 3 FSAR, "Preconst Site Investigation "

 * Washington Public Power Supply System 82/08, 15480 063 24% Fiche 50-508, 82/08/20, 8208270028 82/08/20
- 8208270031 App 2 38 to WPP8S Unit 3 FBAR, "Static Matl Properties * Washington Public Power Supply System 82/08/20 66pp 15480 267 24% Fiche 50-508,82/08/20.8208270031
- 8208270036 App 2 5C to WPP88 Unit 3 FBAR, "Dynamic Matl Properties "
 * Washington Public Power Supply System 82/08/20 38pp 15480 333 24% Fiche 50-508,82/08/20,8208270036
- 8208270039 App 2 5D to NPPSS Unit 3 FBAR. "Site Geophysical Investigations "

 → Washington Public Power Supply System 82/08
 15481 010 24% Fiche 50-508,82/08/20,8208270039 82/08/20
- 8208270043 App 2 SE to MPP88 Unit 3 F8AR. "Remote Sensing * Washington Public Power Supply System 82/08/20 33 15481 041 24% Fiche 50-508.82/08/20,8208270043
- 8208270057 App 2 5F to WPP88 Unit 3 FSAR. "Local Fault Investigation " Washington Public Power Supply System 82/08/20 143pp 1548f 074 24% Fiche 50-508.82/08/20,8208270057.
- 8208270060 App 2 50 to WPP89 Unit 3 FSAR. "Analysis of Linear Trends From Available Gravity & Aeromagnetic Data " * Washington Public Power Supply System 82/08/20 38pp 15481 219 244 Fichs 50-508.82/08/20.8208270060
- 8208270063 App 2 5H to WPPSS Unit 3 F8AR, "Earthquake Catalog "

 * Washington Public Power Supply System 82/08/20 339pp
 15481 263 24X Fiche 50-508,82/08/20,8208270063
- 8208270048 App 2 51 to WPPS8 Unit 3 F8AR, "Lab Qeologic Giudies * Washington Public Power Supply System 82/08/20 55pp 15482:241 24% Fichs.50-508.82/08/20.8208270048
- 8208270073 App 2.5J to WPPS6 Unit 3 FSAR, "Development of 88E & ODE "
 Washington Public Fower Supply System 82/08/20 6Bpp
 15482-276. 24% Fiche 50-508,82/08/20,8208270073
- B208270075 App 2 5K to WPP89 Unit 3 FBAR. "Analysis of Accelerograms Recorded at Dlympia.WA "

 Washington Public Power Supply System B2/08/20. 3ipp. 13493 003 24X Fiche 50-508,82/08/20.0208270076
- 8208270077 App 2 5L to WPPS8 Unit 3 FBAR. "Landslide Investigations "
 ** Washington Public Power Supply System 82/08/20 97pp
 15483 036 24% Fiche 50-508,82/08/20,8208270077
- 8208270079 App 2.8M to WPP88 Unit 3 FBAR, "Volcanic Activity in Bite Region. " * Washington Public Power Supply System 82/08 15483 133. 24X Fiche 50-508,82/08/20,8208270079 82/08/20
- 8208270080 App 2.5N to WPP88 Unit 3 FSAR * Washington Public Power Supply System 24X Fiche 90-508,82/08/20,8208270080 82/08/20 1 p 15493.176
- 8208270031 Apr 2 50 to WPP88 Unit 3 F6AR
 * Washington Public Power Supply System
 24X Fiche 30-508,82/08/20,8208270081 82/08/20 ip. 15403 179

- 8208270084 Chapter 3 to WPPSS Unit 3 FSAR. "Design of Structures "

 * Washington Public Power Supply System 82/08/20 1,200pp
 15483 186 24% Fiche 50-508,82/08/20.8208270084
- 8208270089 App 3 6A to MPP88 Unit 3 FSAR: "Pipe Rupture Analysis "
 * Washington Public Power Supply System 82/08/20 136pp
 15484 061 24X Fiche 50-508,82/08/20,8208270089
- 8208270093 App 3 6B to MPPB8 Unit 3 FBAR, "Computer Programs CALPLOTFI1.PLAST & MKAMMOCII" * Washington Public Power Supply System 82/08/20 29pp. 15484 197 24% Fiche 50-508.82/08/20.8208270093
- 8208270100 App 3 7A to WPP88 Unit 3 F8AR, "Deconvolution of Free-Field Acceleration Time Histories for Rock-Structure Interaction Analysis"

* Washington Public Power Supply System 82/08/20 10pp 24X Fiche 50-308,82/08/20,8208270100

- 8208270104 App 3 10A to WPPSS Unit 3 FBAR. "Criteria for Ssismic Qualification of Non-NSSS Ssismic Catagory I Equipment & Equipment Supplies "

 # Washington Public Power Supply System 82/08/20 Spp. 15486:122 24% Fiche. 50-508. 82/08/20, 8208270104
- 8208270109 Chapter 4 to WPPSS Unit 3 FBAR: "Reactor."

 * Washington Public Power Supply System 82/08/20 8pg
 15486 349 24% Fiche 50-508,82/08/20,8208270109
- 8208270113 App 4A to WPPS8 Unit 3 F8AR.

 * Washington Public Power Supply System 82/08/20. 1p. 15484.357
 24X Ficher 50-508,82/08/20.8208270113
- 8208270117 App 48 to HPP88 Unit 3 F8AR

 * Washington Public Power Supply System 82/08/20. 1p 15486;358

 24% Ficha 50~508,82/08/20.8208270117.
- 8208270121 Chapter 5 to WPP88 Unit 3 FBAR, "RC8 & Connected Sys "

 * Washington Public Power Supply System 82/08/20 210pp
 15486:359 24% Fiche 50-508,82/08/20.8208270121
- 8208270124 Chapter & to WPPS8 Unit 3 F8AR, "ESFe "

 * Mashington Public Power Supply System, 82/08/20 525pp. 15487-247 24% Fiche 50-508, 82/08/20, 8208270124.
- B20B270127 App 6.2A to MPPSB Unit 3 FBAR: "MATEMPT Computer Code to Calculate Shield Bldg Annulus Transfent." * Mashington Public Power Bupply Bystem, 82/08/20 3pp, 15488 349. 24% Fiche 50-808.82/08/20.8208270127
- 8208270130 App 2.48 to WPPSS Unit 3 FBAR, "Ebasco Mode to CONTEMPT-LT Mod 26 Computer Code,"

 * Washington Public Power Supply System, 82/08/20, 11pp. 14588 352 24x Fiche 50-508,82/08/20,8208270130
- 8208270133 Chapter 7 to WPP68 Unit 3 F8AR, "Instrumentation & Control."

 * Washington Public Power Supply System. 82/08/20. 800pp.
 15487 118 24% Fiche 50-508,82/08/20.8208270133.
- B208270136 Chapter 8 to WPP68 Unit 3 F8AR, "Electric Power." Two oversize maps encl Aperture cards available in PDR # Washington Public Power Supply System 82/08/20, 160pp. 15490 325 24% Fiche 30-508.82/08/20.8208270136
- 8208270138 Chapter 9 to WPP88 Unit 3 F8AR, "Auxiliary Sys."
 * Washington Public Power Supply System, 82/08/20, 600pp. 1549; 163 24% Fiche 50-508,82/08/20,8208270138.
- 8208270140 App 9.5A to WPP88 Unit 3 FBAR, "Fire Hazards Analysis." * Washington Public Power Supply System. 82/08/20. 330pp. 15494-049. 24% Fiche: 50-508, 82/08/20, 8208270140
- 8208270144 Chapter 10 to WPPSB Unit 3 FBAR. "Steam & Power Conversion "
 # Washington Public Power Supply Bystem. 82/08/20, 300pp.
 13492-280. 24% Fiche 50-508,82/08/20,8208270144.
- 8208270147 App 10, 4.9A to MPPSS Unit 3 FSAR, "Auxiliary Feedwater Sys Availability Status." * Washington Public Power Supply System 82/08/20, 64pp. 15493 139, 24x Fiche. 50-508.82/08/20, 8208270147.
- 8208270152 Chapter 11 to WPP88 Unit 3 F8AR, "Radwaste Mgt."

 * Washington Public Power Supply System 82/08/20, 180pp, 15493, 204. 24% Fiche, 50-508, 82/08/20, 8208270152.

- 8208270157 Chapter 12 to WPPSS Unit 3 FSAR, "Rediation Protection"

 * Washington Public Power Supply System 82/08/20 180pp
 15495:021 24X Fiche 30-508,82/08/20,8208270157
- 8208270166 App 12A to WPPBS Unit 3 FSAR. "THI Shielding Study NUREO-0578. Item 2 1 66 & NUREO-0737. Item II B 2 Design Review of Plant Shielding for Spaces/Bys Which May Be Used in Post-Accident Operations"

 * Washington Public Power Supply System 82/08/20 57pp 15475-242 24X Fiche 50-508. 82/08/20, 6208270166.
- 8208270173 Chapter 13 to MPP88 Unit 3 F8AR, "Conduct of Operations." * Washington Public Power Supply System 62/08/20 83pp 15495:300 24X Fiche 50-508.82/08/20,8208270173,
- 8208270178 App 13A to MPP88 Unit 3 FSAR, "Qualifications of Technical Bupport Personnel" * Washington Public Power Supply System 82/08/20 19pp 15494.021 24% Fiche 50-508,82/08/20,8208270178
- 8208270183 App 139 to WPP88 Unit 3 FSAR, "Qualifications of Plant Personnel." # Washington Public Power Supply System, 82/08/20 15pp 15494-040 24% Fiche. 50-508, 82/08/20, 8208270183
- 8208270190 Chapter 14 to WPPS8 Unit 3 F8AR, "Initial Test Program "
 # Washington Fublic Power Bupply System. 82/08/20 74pp
 15474-035 24X Fiche-50-508,82/08/20,8208270190
- 8208270196 Chapter 15 to MPP88 Unit 3 F8AR. "Accidental Analysis "
 # Washington Public Power Supply System. 82/08/20 53pp.
 15496 130 24% Fiche: 50-508.82/08/20,8208270196.
- 8208270202 App 151 to MPP88 Unit 3 F8AR, "Containment Leakage & Dose Calculation Models FIRBION 2120 Computer Code"
 # Washington Public Power Supply System. 82/08/20 11pp. 15496-163 24% Fiche: 50-508.82/08/20.8208270202
- 8208270208 Chapter 16 to WPP88 Unit 3 F8AR. "Tech Bpecs." * Washington Public Fower Supply System 82/08/20. 2pp 15496 194 24% Fiche 50-508.82/08/20,8208270208
- 8208270213 Chapter 17 to MPP88 Unit 3 F8AR, "0A "

 * Washington Public Power Supply System 82/08/20. App. 15496:196 24X Fiche: 50-508.82/08/20.8208270213
- M. Antitrust correspondence
- 8208270001 Forwards antitrust info 80UCHEY, 0 D Washington Public Power Supply System, 82/08/20, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp 15473:001. 24X Ficher 50-508,82/08/20,8208270001
- --8208270014 "Info for Antitrust Review of OL Application for WPP88 Nuclear Project 3 " * Washington Public Power Supply System. 82/08/20 15pp 15473:032 24X Fiche. 50-508, 82/08/20, 8208270001.
- Q Inspection reports: IE Bulletins & correspondence
- 8207150428 Forwards IE Insp Rept 50-508/82-12 on 820507-11 k notice of violation.
 BISHOP.T.W. Region 5, Office of Director. 82/05/28. LEDDICK.R.S. Washington Public Power Bupply System. 2pp. 13855:344, 24X Fiche:50-508,82/05/28,8207150428.
- --8207190434 Notice of violation from insp on 620607-11. DODDS:R.T. Region 5: Office of Director. 62/06/28, 2pp. 13656:346 24X Fiche: 50-508, 82/06/28, 8207150428.
- --8207150442 IE Imap Rept 50-508/82-12 on 820607-11 Noncompliance noted. failure to perfore surface exem of containment electrical penetration welds. HATST.D.P., DDDDS.R.T. Region 5, Office of Director. 82/06/25. Spp. 13856:348. 24X Fiche.50-508,82/06/28,8207150428.
- 8208160300 Bubmits add1 clarification of util response to NRC 820415
 1tr re-corrective actions taken per violations noted in
 IE Insp Repts 50-508/81-14/01 & 50-509/81-14/01 Ebasco
 does not agree w/NRC concerns.
 LEDDICKIR S. Washington Public Pawer Supply System. 82/07/02
 815HOP.T.W. Division of Resident: Reactor Project & Engineering
 Programs. 4pp. 14346:279 24% Fiche:50-508,82/07/02.8208160300.

- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000. 82/07/16, 8204210393
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list enci JORDAN, E L. Division of Engineering & Quality Assurance 82/07/19 Hickigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210397 TE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl GDBs.L.I Division of Fuel Facilities, Materials & Safeguards, 82/07/20 Consolidated Edison Co of New York 7ipp 14357 27, 24X Fiche. 50-000, 82/07/20, 8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Yorbine Exhaust Check Valve Failures " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York, 112pp 14174 321 24X Fiche. 50-000, 82/07/22,8204210378.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115. 24X Fiche 50-000, 82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120 24X Fiche 50-000.82/07/23.8204210402
- B208160130 Forwards IE Insp. Repts 50-508/82-13 & 50-509/82-06 on B20601-30 No noncompliance noted BIGHOP, T. W. Division of Resident, Reactor Project & Engineering Programs B2/07/23 LEDDICK.R B. Washington Public Power Supply System 2pp 14345 197 24X Fiche 50-508.62/07/23.6208160130
- --820B160131 IE Insp Repts 50-508/82-13 & 50-509/82-06 on 820601-30 No noncompliance noted Major areas inspected welding for safety-related piping, electrical equipment installation, records for primary loop piping & aquipment maint ALBERT. W O . DUDDB. R T Division of Resident, Reactor Project & Engineering Programs 82/07/22 App 14345 177 24X Fiche 50-508,82/07/23,8208160130
 - 04210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping t Certain Hestinghouse PHR Power Plants" Svc list encl ORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York 121pp 14357,013 24X iche 50-000,82/07/26,8204210403
 - 4210405 IE Info Notice 82-31, "Overexposure of Diver During Work in 'usl Storage Pool " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405.
- 208160259 Forwards IE Insp Rept 50-508/82-14 on 820712-16 No noncompliance noted BISHOP.T.H. Division of Resident, Reactor Project & Engineering Programs 82/08/03 LEDDICK.R.S Washington Public Power Supply System. 1p 14347-023 24X Fiche 50-508, 82/08/03, 8208160259
- --8208160266 iE Insp Rept 50-508/82-14 on 620712-16 No noncompliance noted Major areas inspected mondestructive testing aspects of safety-related pigning installation, installation of safety-related electrical components & 10CFR50 55(a) items HAIST, D.P.; ECKHARDT, J.H.; D'ANGELO, A.J. Division of Resident, Reactor Project & Engineering Programs 62/07/30 8pp 14347:024, 24% Fiche: 50-508/82/08/03/8208160259
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingment " Syc list and I JORDAN,E L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co. of New York. 117pp, 14368.201 24X Fiche 50-600.82/08/05.8204210407

- 8208240163 Advises that response to IE Insp Repts 50-508/81-14 & 50-508/82-04 will be submitted by 820827 & 20, respectively Response to potential deficiency re-structural steel connections will be submitted by 820820 LEDDICK/R S Washington Public Power Supply System 82/08/06 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 2pp 14520 105 24X Fiche 50-508.82/08/06,8208240163
- S Reportable occurrences, LERs & related correspondence
- 8208240163 Advises that response to IE Insp Repts 50-508/81-14 & 30-508/82-04 w(11 be submitted by 820827 & 20, respectively Response to potential deficiency restructural steel connections will be submitted by 820820 LEDDICK, R 8 Washington Public Power Supply System 82/08/06 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 14520 105 24X Fiche 50-508,82/08/06,8208240163
- 8208300321 Revised final deficiency rept re structural steel connections, reflecting additinsp data & detailed design analysis per NRC 820421 request Subsequent insp determined deficiencies not reportable per 10CFR30 55(e) LEDDICK, R B Washington Public Power Supply System 82/08/19 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 76pp 14595 173 24X Fiche 50-508,82/08/19,8208300321
- 8208310224 Forwards final deficiency rept re structural steel connections
 LEDDICK,R 8 Washington Public Power Supply System 82/08/24
 NRC No Detailed Affiliation Given ip 14688 277 24X
 Fiche. 50-508, 82/08/24, 8208310224
- --8208310227 Final deficiency rept re structural steel connections.
 Structural steel erection documentation reviewed for acceptability & conformance to field conditions Hardware deficiencies repaired or reworked
 LEDDICK, R 8 Washington Public Power Supply System 62/08/19,
 SIERNBERG, D M Division of Resident, Reactor Project & Engineering Programs. 59pp 14488 280 24% Fiche 50-508,82/08/24,8208310224
- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- Q Adjudicatory correspondence
- 820802026i Order extending time until 820825 for Commission to decide whether to review NRR Director denial of N Bell.on behalf of Coalition for Bafs Power, petitions per 10CFR2 206 HOYLE.J C Office of the Secretary of the Commission B2/07/29 Commissioners ip 14152 330 24X Fiche 50-509,82/07/29, 820802026i
- 8208250353 Order extending time until 820916 for Commission to decide whether to review NRR director denial of Coalition for Safe Power two 100FR2.206 petitions CHILK-8 J Diffice of the Secretary of the Commission 82/08/23 Commissioners ip 14540 267 24X Fiche, 50-509, 82/08/23, 8208250353
- Q Inspection reports. IE Bulletins & correspondence
- B208160300 Bubmits addl clarification of util response to NRC B20415 ltr re corrective actions taken, per violations noted in IE Insp Repts 50-508/81-14/01 & 50-509/81-14/01 Ebasco does not agree w/NRC concerns
 LEDDICK, R. S Washington Public Power Supply System 82/07/02 BIEHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 14346-279 24% Fiche 80-508/82/07/02,8208160300
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN, E L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393
- B204210396 TE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Fressure " Svc list enc! JORDAN,E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co. of New York 112pp. 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 PE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards, 82/07/20, Consolidated Edison Co. of New York 71pp. 14357,276 24X Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Feilures " Syc list encl JORDAN E L Division of Engineering & Quality Assurance. 82/07/22 Consolidated Edison Co of New York 112pp. 14194 321 24X Fiche 50-000, 82/07/22, 8204210378.

- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN-E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23.8204210401
- B204210402 IE Info Notice 82-27, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174 120 24X Fiche 50-000,82/07/23,8204210402
- 8208160130 Forwards IE Insp Repts 50-508/82-13 & 50-509/82-06 on 820601-30 No noncompliance noted 816HOP,T W Division of Resident, Reactor Project & Engineering Programs 82/07/23 LEDDICK,R B Washington Public Power Supply System 2pp 14345 197 24X Fiche 50-508.82/07/23,8208160130
- --8208160131 IE Insp Repts 50-508/82-13 & 50-509/82-06 on 820601-30 No noncompilance noted Major areas inspected welding for safety-related pipings electrical equipment installation, records for primary loop piping & equipment maint.

 ALBERT, W G , DDDDB, R T Division of Resident, Reactor Project & Engineering Programs 82/07/22 App 14345 199 24X

 Fiche 50-508,82/07/23,8208160130
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN:E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Starage Pool " Svc list encl JORDAN:E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8204210407 IR Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement" Svc list encl JORDAN,E L Division of Engineering & Quality Assurence 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8208240169 Advises that response to IE Insp Repts 50-508/81-14 & 50-508/82-04 will be submitted by 820827 & 20, respectively Response to potential deficiency re structural steel connections will be submitted by 820820 LEDDICK, R S Washington Public Power Bupply 8ystem 82/08/06 STERNBERGO, M Division of Resident, Reactor Project & Engineering Programs 2pp 14520 105. 24X Fiche 50-508,82/08/06,8208240163.
- R Periodic operating reports & related correspondence
- 8208040178 Forwards "Program Director Monthly Status Repts for WNP-4/5
 Termination Program" for Apr.May & June 1982.
 BOUCHEY, 0 D , DE LORENZO, R A Washington Public Power Supply System,
 82/07/28 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 10pp 14189 130 24X Fiche 50-509,82/07/28,8208040178
- S Reportable occurrences, LERs & related correspondence
- 8208240163 Advises that response to IE Insp Repts 50-508/81-14 & 50-508/82-04 will be submitted by 820827 & 20, respectively Response to potential deficiency re structural steel connections will be submitted by 820820 LEDDICK.R.S Washington Public Power Supply System 82/08/06 STERNBERG, b M Division of Resident, Reactor Project & Engineering Programs 2pp 14520:105 24X Fiche 50-508,82/08/06,8208240163.
- 8208300321 Revised final deficiency rept re structural steel connections, reflecting additing data & detailed design analysis per NRC 820421 request, 8ubsequent insp determined deficiencies not reportable per 10CFR50,55(s)
 LEDDICK, R 8 Washington Public Power Supply System 82/08/19 STERNBERGO, D M. Division of Resident, Reactor Project & Engineering Programs 7App 14595-173 24X Fiche.50-508,82/08/19.8208300321
- 8208310224 Forwards final deficiency rept re structural steel connections
 LEDDICK, R 8 Washington Public Power Supply System 82/08/24
 NRC No Detailed Affiliation Given 1p 14688 277 24X
 Fiche 50-508, 82/08/24, 8208310224,
- --B20B310227 Final deficiency rept re structural steel connections.

 Structural steel erection documentation reviewed for acceptability & conformance to field conditions Hardware deficiencies repaired or reworked LEDDICK, R.S. Washington Public Power Supply System B2/08/19.

 STERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs 59pp. 14688 280, 24X Fiche 50-508,82/08/24,8208310224.

- DOCKET 50-513 WPP88 NUCLEAR PROJECT, UNIT 4

 O Adjudicatory correspondence
- 8208020261 Order extending time until 820825 for Commission to decide whether to review NRR Director denial of N Bell, on behalf of Coalition for Safe Power, petitions per 10CFR2 206
 HOYLEJ C Office of the Secretary of the Commission 82/07/29 Commissioners 1p 14152 330 24X Fiche 50-509,82/07/29,8208020261.
- 8208250353 Order extending time until 820916 for Commission to decide whether to review NRR director denial of Coalition for Safe Power two 10CFR2 206 petitions CHILM.5 J. Office of the Secretary of the Commission 82/08/23 Commissioners ip 14540 267 24X Fithe 50-309.82/08/23.
- O Inspection reports. IE Bulletins & correspondence
- 8207150400 Forwards IE Insp Repts 30-460/82-09 & 50-513/82-05 on 820501-28 & notice of violation BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/04/24 R00T, R W Washington Public Power Supply System 2pp. 13851.028 24X Fiche 50-460.82/06/24,8207150400
- --8207150421 IE Insp Repts 50-460/B2-07 & 50-513/B2-05 on 820501-28 Noncompliance mated electrical contractor subcontracted installation of electrical penetration assemblies w/o inclusion of appropriate installation procedures TOTH. A D . DDDDS. R T Division of Resident Reactor Project & Engineering Programs 82/06/23 15pp 13851.032 24X Fiche 50-460,82/06/24-8207150400
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co. of New York 87pp 14356 274 24X Fichs 50-000,82/07/16,8204210393
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York 112pp 14381:001, 24X Fiche: 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards, 82/07/20 Compolidated Edison Go of New York 71sp, 14357 27, 24X Fiche 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list enc!, JORDAN,E L Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York 112pp 14194:321, 24X Fiche 50-000,82/07/22,8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS," Evo list encl. JORDAN, E.L. Division of Engineering & Quality Assurence. 82/07/23, Consolidated Edison Co. of New York 122pp 14380,115 24X Fiche. 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rad Drive (GRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23, Consolidated Edison Co. of New York 127pp. 14194.120 24X Fiche. 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PMR Power Plants." Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance, 82/07/26, Consolidated Edison Co. of New York 12ipp 14357.013 24X Fiche. 50-000, 82/07/26, 8204210403.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool," Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/28, Consolidated Edison Co of New York 122pp 14357,146, 24X Fiche. 50-000, 82/07/28, 8204210405
- 820B100314 Ack receipt of 820702 ltr informing NRC of amend to response re item of noncompliance noted in IE Insp Repts 50-460/82-06 & 50-513/82-04 BI6HDP, T W. Division of Resident, Reactor Project & Engineering Programs 82/08/04, 800T, R. W. Hashington Public Power Bupply System 1p 14297 128, 24X Fichs, 50-460, 82/08/04, 8208100314

- --8208100323 Responds to NRC 820608 ltr re violations noted in IE Insp. Repts 50-450/82-06 & 50-513/82-04 Corrective actions all welders, craft superintendents & GC inspectors have been trained in new weld weave criteria & procedures revised MAZUR, D W Washington Public Power Supply System 82/07/02 FAULKENSERRY, R Region 5, Dffice of Director 6pp 14297 129, 24X Fiche 50-460,82/08/04,8208100314
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN: E L Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388.201 24X Fiche 50-000,82/08/05.8204210407

R Periodic operating reports & related correspondence

8208040178 Forwards "Program Director Monthly Status Repts for UNP-4/5
Termination Program" for Apr.May & June 1982
BOUCHEY.O D , DE LORENZO.R A Washington Public Power Supply System
82/07/28 DENTON,H R Office of Nuclear Reactor Regulation,
Director 10pp 14189 130 24X Fiche 50-509,82/07/28,8208040178

S Reportable occurrences, LERs & related correspondence

8208030343 Interim deficiency rept re undersized fillet welds on skewed tee joints u/obtuse angles Initially reported on 811106 Potential failure of safety-related items possible Analysis to be performed during as-built design verification review MAZUR.D W Washington Public Power Supply System 82/07/16 FAULKENBERRY.R Division of Resident, Reactor Project & Engineering Programs 5pp 14219 339 24X Fiche 50-460.82/07/16.8208050343

8208050448 Interim deficiency rept re deformation of Okonite conductor cable Initially reported on 820421 Circuits using suspect cable will be identified & listing sent to engineer Replacement dates forthcoming MAZUR.D W Washington Public Power Bupply System 82/07/16 FAULKENBERRY.R Division of Resident, Reactor Project & Engineering Programs 4pp 14218'049. 24X Fiche 50-460,82/07/16,8208030448

8208050527 Interim deficiency rept re length of capscrew which holds starting air valve assembly in cylinder head Initially reported on 820618 Design configuration revised. Final rept will not be issued due to current const dalay on Unit 1.
MAZUR.D N Washington Public Power Supply System 82/07/16
FAULKENBERRY R Region 5. Office of Director 2pp 14213 282 24X
Fiche 50-460.82/07/16.8208050527

8208160432 Interim deficiency rept re Buffalo Forge fan housing missile protection Initially reported on 810824 Drawings re proposed corrective mods to fan housing reviewed & approved Completion date cannot be established due to const delay MAZURAD W Washington Public Power Supply System 82/07/27 BISHOPAT W Division of Resident. Reactor Project & Engineering Programs 3pp 14349.192 24X Fiche 50-440.82/07/27.8208160432.

8208250190 Potential Part 21 rept re defect in containment bldg structural steel framing Results of framing connection flexibility tests will be available by 820830 Status rept on design review will be submitted by 82030 Status rept of SARSTEN.9 E United Engineers & Constructors. Inc (subs of Raytheo Co) 82/08/19 Director's Office. Office at Inspection and Enforcement 2pp 14540 278 24X Fiche 50-460,82/08/13,8208250190

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl DIRCKS.N.J Diffice of the Executive Director for Operations 82/07/02. Consolidated Edison Co of New York, 93pp. 14194 001 24X Fiche 50-000.82/07/02.8207080064
- 8208090194 Ceneric Ltr 62-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summerites 10CFR Chapter I requirements & provides alternatives to requirements Byc list enci.
 EISBNHUT.D O Division of Licensing 82/08/09, Consolidated Edison Co of New York ip 14356-332, 24X Fiche 50-000.82/08/09, 8208090194

Q. Inspection reports. IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage "Bvc list encl JURDAN.E L. Division of Engineering & Quality Assurance B2/07/16, Consolidated Edison Go of New York B7pp 14356-274. 24X Fiche 50-000, 82/07/16, 8204210393

- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24% Fiche 50-000,82/07/19,8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Ficha 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBBL I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 272 24% Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " 8vc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " 8vc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
 Consolidated Edison Co. of New York 122pp. 14380 115 24X
 Fiche 30-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl JURDAN,E L. Division of Engineering & Guality Assurance 82/07/26 Gonsolidated Edison Co of New York 12Ipp 14337 013, 24X Fiche 50-000,82/07/26,6204210403
- 8204210405 IE Info Notice 82-31, "Oversxposure of Diver During Hark in Fuel Storage Pool " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche: 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " 8vc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388.201 24X Fiche 50-000,82/08/05,8204210407

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl.

 DIRCKS. M. J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fichs 50-000, 82/07/02, 8207080064
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Svc list enci ETSENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194,

Q Inspection reports, IE Bulletins & correspondence

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list mncl JORDAN E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp. 14356 274. 24X Fichs 50-000,82/07/16,8204210393
- 8204210399 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Sve 11st encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19 Michigam, Univ. of 112pp 14398 001 24X Fiche 30-000, 82/07/19, 8204210395

- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co. of New York 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Constituted Edison Co of New York 7ipp 14357 276 24X Fiche 50-000.82/07/20.8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82~28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 30~000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl. JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of Naw York 127pp 14174-120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants" Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013. 24X Fiche 50-000,82/07/26.8204210403
- 8204210405 IE Info Notice 82-31. "Diversione of Diver During Work in Fuel Storage Pool " Svc list encl JORDANIE L Division of Engineering & Quality Assurance B2/07/28, Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " 8vc list encl JORDAN,E L. Division of Engineering & Quality Assurance. 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000,82/08/05.8204210407

DOCKET STN-50-518 HARTSVILLE MUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for CL & holders of CP re Commission approved charter for CROR SVC list encl
 DIRCKS.N J Deffice of the Executive Director for Operations.
 82/07/02 Consolidated Edison Co of New York. 93pp i4194.001
 24X Fiche 50-000.82/07/02.8207080064
- 8208100166 Forwards info re QA for deferred plants in response to NRC B20524 ltr Possible cancellation of some units will be discussed at future meeting of TVA Board of Directors MILLB, L. M. Tennessee Valley Authority 82/08/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 14274: 013 24X Fiche 50-000, 82/08/06, 8208100166
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Sv list anci EISENHUT, J G Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- I Financial information
- 8208100002 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr ending 810630 & "1981 Power Program Summary," for fiscal yr ending 810930, per Saction 50 71(b) of 100FR30.
 MILLS,L M Tennessee Valley Authority 82/08/06 DENTON,H R Office of Nuclear Resctor Regulation, Director 118pp, 14294.024 24% Fiche 50-000,82/08/06,8208100002
- Q Inspection reports: IE Bulletine & correspondence
- 8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance. 82/07/16,
 Consolidated Edison Co of New York 87pp. 14356.274 24X
 Fiche 50-000, 82/07/16, 8204210393

- 8208160155 Forwards IE Insp Repts 50-518/82-09, 50-519/82-08, 50-520/82-09 & 50-521/82-08 on 820601-04 & 28-30 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/07/16 PARRIS, H O Tennesses Valley Authority 2pp 14345 135 24X Fiche 50-518, 82/07/16, 8208160153
- --8208160161 IE Insp Repts 30-518/82-07.50-519/82-08.50-520/82-07 & 50-521/82-08 on 820601-04 & 28-30 No noncompliance nated Hajor areas inspected Seismic Category 1 concrete,open items & site deferral preparation SCHAPKER, J F., CANTRELL, F. B. Division of Project & Resident Programs 82/07/16 4pp 14345 137 24X Fiche 50-518.82/07/16, 8208160155
- 8204210395 IE Info Notice 81-24, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp. 14398 001 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure," Svc list encl JORDAN, E. L. Division of Engineering & Quelity Assurance. 82/07/20 Consolidated Edison Co. of New York 112pp 14381:001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York, 7ipp, £4357; 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl. JGRDAN,E L Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York, i12pp. 14194.321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN, E L Division of Engineering & Guality Assurance 62/07/23 Consolidated Edison Co of New York 122pp 14380,115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp, 14194.120 24X Fiche 30-000.82/07/23.8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl JGRDAN:E L Division of Engineering & Quality Assurance Consolidated Edison Co of New York 121pp. 14357:013 24K Fiche:50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fusl Storage Pool " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28. Consolidated Edison Co. of New York, 122pp. 14357:146 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement," Svc list anci JORDAN E L Division of Engineering & Quality Assurance. 82/09/05 Consolidated Edison Co of New York. 117pp 14388-201. 24X Fichs.50-000.82/08/05,8204210407
- B. Reportable occurrences, LERs & related correspondence
- 8208020226 Final deficiency rept for Sequoyah, second interim rept for Matts Bar & fifth for Beliefonte, Hartsville, Phipps Bend & Vallow Creek re inconsistent establishment of insp program. Next rept for Watts Bar & Bellefonte expected B30103 MILLS, L. M. Tennessae Vallay Authority B2/07/20 O'REILLY, J. P. Region 2, Office of Director. App 14152; 344 24X Fiche: 50-000, 82/07/20, 8208020226
- 8208300211 Sixth interim deficiency rept re procurement control audits Initially reported on 810316. TVA quality engineering branch response to audit deficiencies undergoing review. Next rept due by 821007
 MILLG.L.M. Tennessee Valley Authority 82/08/23, 0'REILLY, J. P. Region 2, 0ffice of Director. ip. 14679:196. 24X
 Fiche. 50-000, 82/08/23, 8208300211

DOCKET STN-50-519 HARTSVILLE MUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for UL & holders of CP re Commission approved charter for CROR Svc list encl DIRCKS, WJ Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fiche 50-000.82/07/02.8207080064

- 8208100166 Forwards info re OA for deferred plants, in response to NRC 820524 ltr Possible cancellation of some units will be discussed at future meeting of TVA Board of Directors MILLSL M Tennessee Valley Authority 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 14274 013 24X Fiche 50-000,82/08/06,8208100166
- 8208090174 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list enci EISENHUT. J 9. Division of Licensing 82/08/07 Consolidated Edison Co of New York ip 14356 332 24X Fiche 50-000.82/08/07, 8208070194

I. Financial information

- 8208100002 Forwards "TVA Power Program Bummary," Vol 2.for fiscal yr ending 810630 & "1981 Power Program Summary," for fiscal yr ending 810930, per Section 50 71(b) of 10CFR50 HILLS.L M Tennessee Valley Authority. 82/08/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 118pp 14294 024. 24X Fiche 50-000.82/08/06.8208100002 118pp 14294 024.
- G. Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage," 8vc list and JORDAN,E.L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24X Fiche, 50-000, 82/07/16, 8204210393
- 8208160155 Forwards IE Insp Repts 50-518/82-09, 50-519/82-08, 50-520/82-09 & 50-521/82-08 on 820601-04 & 28-30 No purposery & Surgarizards on acception & abrau no noncompliance noted VERRELLI.D.M. Division of Project & Resident Programs. 82/07/1 PARRIS, H Q Tennessee Valley Authority 2pp 14345 135 24X Fiche. 30-518, B2/07/16, 8208160155 82/07/16
- --8208160161 IE Insp Repts 50-518/82-09,50-519/82-08.50-520/82-09 & 50-521/82-08 on 820601-04 & 28-30 No moncompliance noted Hayor areas inapected Seismic Category I concrete open items & site deferral preparation.

 8CHAPKER, J. F. CANTRELL, F. S. Division of Project & Resident Programs 82/07/16 4pp 14345 137. 24X Fiche 50-518,82/07/16,8208160155
- RUMERUSTO IN INFO Notice 81-25.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." But list encl JURDAN.E.L. Division of Engineering & Guality Assurance 82/07/19 Michigan. Univ. of. 112pp 14358 COI. 24X Fiche.50-000.82/07/19, 8204210395 204210395 IE Info Notice 81-25, Part 3, Suppl 1, "Clarification of
- 8204210376 IE Info Notice 82-25, "Feilures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list and I. JORDAN,E.L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001. 24X Fiche: 50-000, 82/07/20, 82042(0376
- 8204210397 IE Info Notice 82-24, "Water Leating From U Hexafluoride Overpacks." Svc list encl COBB:L 1 Division of Fuel Facilities, Materials & Safeguards 62/07/20 Consolidated Edison Co of New York 7ipp, 14357.2 24X Fichs: 50-000,82/07/20,8204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & IPCI Turbine Exhaust Check Valve Failures " Syc list encl.
 JORDANIE L Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co. of New York 112pp. 14194.321. 24X Fiche: 50-000, 82/07/22, 8204210398.
- 9204210401 IE Info Notice 92-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co. of New York 122pp. 14380 115 24% Fiche 30-000,82/07/23.8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JRRDAN:E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice B2-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN:E L Division of Engineering & Guality Assurance B2/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/28 Consolidated Edison Co of New York 122pp, 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list enc!
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York. 117pp 14388 201 24X
 Fiche 50-000, 82/08/09, 8204210407
- & Reportable occurrences, LERs & related correspondence
- 8208020226 Final deficiency rept for Soquoyah, second intorim rept for Matts Dar & fifth for Bellefonte, Martsville, Phipps Bend & Yellow Creek re inconsistent establishment of insp program Next rept for Watts Bar & Bellefonte expected 830103 MILLS, L M Tonnessee Valley Authority 82/07/20 O'REILLY, J P Region 2. Office of Director opp 14182 344 24X Fiche 50-000, 82/07/20, 8208020226
- 8208300211 Sixth interim deficiency rept re procurement control audits Initially reported on 810316 TVA quality engineering branch response to audit deficiencies undergoing review. Next rept due by 821007
 MILLS.L H Tennessee Valley Authority 82/08/23 O'REILLY, J P Region 2, Office of Director ip 14679 176 24X
 Fiche 50-000.82/08/23,8208300211
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKB.M.J. Diffico of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp. 14194 001
 24X Fiche 50-000, 82/07/02, 8207080064
- 8208100166 Forwards info re GA for deferred plants, in response to NRC 820524 it Possible cancellation of some units will be discussed at future meeting of TVA Board of Directors.

 HILLS: LM Tennessee Valley Authority BZ/08/06 DENTON, H R.

 Office of Nuclear Reactor Regulation, Director, 3pp 14294 0: 24% Fiche, 50-000, BZ/08/06, BZ08100166.
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes (OCFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT, D 0 Division of Licensing 82/08/09, Consolidated Edison Co of New York ip 14356 332, 24X Fiche 50-000,82/08/09,8208090194
- I Financial information
- 8208100002 Forwards "TVA Power Program Bummary," Vol 2, for fiscal yr ending 810630 & "1981 Power Program Bummary," for fiscal yr ending 810930, per Section 80 71(b) of 100FR80 MILLB,L.M Tennessee Valley Authority 82/08/06 DENTON,H.R Office of Nuclear Reactor Regulation, Director, 118pp 14274-024 24% Fiche 80-000,82/08/06.8208100002
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Constitute of English and Seem Isolation Valve (MBIV)

 Leakage. "Bvc list encl.

 JORDAN.E L Division of Engineering & Quality Assurance, 82/07/16

 Consolidated Edison Co. of New York. 87pp. 14356 274, 24X

 Fiche. 30-000

- 8208140155 Forwards IE Insp Repts 50-518/62-07.50-517/82-08. 50-520/82-07 & 50-521/82-08 on 820401-04 & 28-30 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/07/16 PARRIB, H O Tennessee Valley Authority 2pp 14345 135 24X Fiche 50-518.82/07/16.8208160155
- --8208160161 IE Insp Repts 50-518/82-09, 50-519/82-08, 50-520/82-09 & 50-521/82-08 on 820601-04 & 28-30 No noncompliance noted Major areas inspected Seismic Category I concrete, open items & site deferral preparation SCHAPKER, JF., CANTRELL.FS Division of Project & Resident Programs 82/07/16 4pp 14345 137 24X Fiche 50-518,82/07/16,8208140155
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ of 112pp 14358, 001 24% Fiche 50-000, 82/07/19, 8204210395
- 8204210376 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance. 82/07/20 Consolidated Edison Co of New York 112pp. 14381 001, 24X Fiche 50-000, 82/07/20, 8204210376
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexefluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafequards 82/07/20 Consolidated Edison Co of New York 7ipp. 14357-276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York (12pp 14194-321 24X Fiche.50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Brained & Open RCB." Svc list encl.

 JORDANE L. Division of Engineering & Quality Assurance. 82/07/23,
 Consolidated Edison Co of New York 122pp 14380·115 24X

 Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Ouide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche: 50-000, 82/07/23, 8204210402
- B204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCB Piping at Cartein Westinghouse PWR Power Plants." Byc list encl JORDAN, E. L. Division of Engineering & Guality Assurance. B2/07/26, Consolidated Edison Co of New York 121pp 14357-013. 24X Fiche 30-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool," Svc list encl, JORDAN E. L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357:146 24X Fiche. 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
 JORDAN.E. L. Division of Engineering & Quality Assurance. 82/08/05
 Consolidated Edison Co. of New York 117pp. 14388; 201 24X
 Ficha. 50-000, 82/08/05, 8204210407
- B. Reportable occurrences: LERs & related correspondence
- 8208020226 Final deficiency rapt for Bequoyah, second interim rept for Matts Bar & fifth for Ballefonte, Hartsville, Phipps Bend & Yallow Creek ra inconsistent establishment of insp program Next rept for Matts Bar & Bellafonte expected 830103.

 MILLBIL M Tannessas Valley Authority 82/07/20 0'REILLY, J P. Region 2. Office of Director App 14152, 344. 24X
 Fiche 30-000, 82/07/20, 8208020226.
- 8208300211 Sixth interim deficiency rept re procurement control audits Initially reported on 810316. TVA quality engineering branch response to audit deficiencies undergoing review Nazt rept due by 821007
 MILLS,L.M. Tennessee Vailey Authority 82/08/23 O'REILLY, J. P Region 2, Office of Director, 1p 14679, 196, 24X Fiche. 50-000, 82/08/23, 8208300211.
- 8208310123 PNO-II-82-098 on 820825, util announced cancellation of listed plants Yellow Creek 1 & 2 indefinitely deferred. CANTRELL,F.8, LEMIS,R.G. Region 2, Office of Director. 82/08/26 ip. 14689 286, 24X Fishe. 50-000, 82/08/26, 8208310123.

- DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8207080054 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Byr list encl
 DIRCKB W J Office of the Executive Director for Operations
 B2/07/02. Consolidated Edison Co. of Nam York 93pp 14194.001,
 24X Fiche 50-000,82/07/02.82070B0064
- 820Bi00166 Forwards info re OA for deferred plants, in response to NRC B20824 ltr Possible cancellation of some units will be discussed at future meeting of TVA Board of Directors MILLS, L. M. Tennesses Valley Authority 82/08/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp. 14294-013 24X Fiche 30-000, 62/08/076, 920B100166
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements by Iist encl EISENHUT.D 0. Division of Licensing. 82/08/07. Consolidated Edison Co. of New York. 1p. 14356 332. 24X Fiche 50-000,82/08/09,8208090194
- I. Financial information
- 8208100002 Forwards "TVA Power Program Summary," Vol 2. for fiscal yr ending 810630 & "1791 Fowar Program Summary," for fiscal yr ending 810930.per Section 50 71(b) of 100FR50 MILLS,L. H. Tennessee Valley Authority 82/08/06 DENTON,H R. Office of Nuclear Reactor Regulation, Director 118pp 14294 024 24X Fiche: 50-000,82/08/06,8208100002.
- Q Inspection reports. IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl.
 JORDAN,E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York. 87pp. 14336*274. 24X
 Fiche,50-000,82/07/16,8204210393
- 8208160155 Forwards IE Insp Repts 50-518/82-09.50-519/82-08. 50-520/82-09 % 50-521/82-08 on 820601-04 % 28-30. No noncompliance noted. VERRELLI, D. H. Division of Project & Resident Programs. 82/07/16 PARRIB, H. G. Tennesses Valley Authority 2pp 14345:135 24X Fichs: 50-518.82/07/16.8208160155
- ---B20B160161 IE Insp Repts 50-518/82-09, 50-519/82-08, 50-520/82-09 & 50-521/82-08 on 820601-04 & 28-30 No noncompliance noted Major areas inspected: Seisaic Category 1 concrete, open items & site deferral preparation.

 SCHAPKER, J. F. Division of Project & Resident Programs B2/07/16, 4pp 14345-137. 24% Fiche 50-516, 82/07/16,8208160135.
- 8204210395 IE Info Notice 81-24, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance. 82/07/19 Michigan, Univ of 112pp 14358, OO1. 24X Fiche 50-000, 82/07/19, 8204210395.
- 8204210396 IE Info Notice 82-25, "Feilures of Hiller Actuators Upon Gradual Loss of Air Fressure." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20, Consolidated Edison Co. of New York. 112pp. 14381:001. 24X Fiche: 50-000, 82/07/20, 8204210396.
- 8204210397 IE info Notice B2-24. "Water Leaking From U Hexafluoride Overpacks " Svc list encl. CO88, L. I. Division of Fuel Facilities, Materials & Bafeguards, 82/07/20 Consolidated Edison Co of New York, 71pp, 14357-276 24X Fiche: 50-000, 82/07/20, 8204210397.
- 8204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Byc list encl. JORDAN,E L. Division of Engineering & Guality Assurance, 82/07/22, Consolidated Edison Co of New York, 112pp, 14194:321, 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydragen Explosion While Orinding in Vicinity of Dreined & Open RCS." Bvc list encl.

 JORDAN, E. L. Division of Engineering & Quality Assurance. 92/07/23,
 Consolidated Edison Co. of New York 122pp. 14380:115, 24X
 Fiche. 50-000, 82/07/23, 8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JURDAN, EL Division of Engineering & Quality Assurance 82/07/23 Consoltdated Edison Co of New York 127pp 14194 120 24X Fiche \$0-000; 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Wastinghouse PWR Power Plants " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000. 82/07/26. 8204210403
- 8204210405 IE Info Notice 82-31, "Dversyposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201. 24X Fiche 50-000, 82/08/05, 8204210407
- S. Reportable occurrences: LERs & related correspondence
- 8208020224 Final deficiency rept for Sequoyah second interim rept for Watts Bar & fifth for Bellefonte. Hartsville. Phipps Bend & Yellow Creek re inconsistent establishment of insp program Next rept for Watts Bar & Bellefonte expected 820103 MILLBIL M Tennessee Valley Authority 82/07/20 O'REILLY, J P Region 2. Office of Director & pp 14152 344 24X Fiche 50-000, 82/07/20, 8208020226
- 820830021i Sixth interim deficiency rept re procurement control audits Initially reported on 810316 TVA quality engineering branch response to audit deficiencies undergoing review Next rept due by 821007 MILB.L.M Tennessee Valley Authority 82/08/23 O'REILLY, J. P Region 2. Office of Director Ip 14679 176 24X Fiche 50-000, 82/08/23, 8208300211
- 82083i0123 PND-11-82-098 on 820825.util announced cancellation of listed plants Yellow Creek 1 & 2 indefinitely deformed CANTRELL.F.S., LEWIS,R C. Region 2. Office of Director, 82/08/26 1p. 14687 284 24% Fiche 50-000.82/08/26,82083i0123
- DOCKEY 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants applicants for OL & holders of CP re Commission approved charter for CRGR. 8vc list encl
 DIRCKS.W J Office of the Executive Director for Operations
 92/07/02 Consolidated Edison Co of New York 93pp 14194,001
 24X Fiche 50-000.82/07/02.8207080064
- 8208050369 Board Notification 82-70 notifies of differing prof opinion resensitization of BUR stainless steel weldments TEDEBCG.R L. Assistant Director for Licensing 82/07/20 Atomic Safety and Licensing Board Panel 4pp 14281,355 24X Fiche 50-000,82/07/20,8208060368
- B208060037 Notification of 820726 meeting w/U608, util & NE8CO in Bethesda. HD to discuss geology investigation program of May Junction monocline MODN.C Licensing Branch 4 B2/07/21 ADENSAM, E 0 Licensing Branch 4 2pp 14280 029, 24X Fiche 50-522, B2/07/21, B208060037.
- 8208020349 Notifies that as result of review of seismic & geologic data for facility, add) work is necessary to evaluate May Junction lineation near site ALGERMISSEN. 8 Interior, Dept of, Geological Survey 82/07/22 JACKBON.R E Geosciences Branch ip. 14147 095 24X Fiche: 50-522, 82/07/22, 8208020349
- 920B110047 PNA-82-005, on 920715, State of MA enacted law, effective 820B01, imposing tax on sales of nuclear fuel assemblies, products mfg for fuel assemblies & on gross income of persons disposing of low level waste LANOAU, M. Assistant Director for State & Licensee Relations KERR, G. U. Office of State Programs, Director, 82/07/23 2pp 14327 251 24X Fiche:50-522,82/07/23,820B10047.

- 8208100216 Discusses resolution of final geology concern re May Junction monocline Investigations yielded no evidence of faults associated w/fold Investigative program discussed at 820721 meeting w/NRC will take approx 8 wks to complete MYERS.R V Puget Sound Power & Light Co 82/08/04 DENTON, H R , ADENSAM,E Office of Nuclear Reactor Regulation, Director 3pp 14294 344 24% Fiche 50-522,82/08/04,8208100216
- B20Bi30327 Forwards request for addl info to confirm presence or absence of potentially hazardous geologic structure within 5 miles of site
 NOVAK.T M Assistant Director for Licensing. B2/08/04 MYERS,R V
 Puget Bound Fower & Light Co 3pp I4340 241 24X
 Fiche 50-522, B2/08/04, 820Bi30327
- 8208090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements &vc list encl EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fiche 80-000,82/08/09,8208990194
- 8208190380 Forwards USOS 820722 ltr recommending add1 drilling in May Junction area & preparation of table showing relationship between lithologic & geophysical logs, Info request of 820804 reflects needs discussed in 820721 meeting ADENSAM.E O Litensing Branch 4 82/08/10 MYERS,V Puget Sound Power & Light Co 2pp 14504 153 24X Fiche 50-522,82/08/10,8208190380
- 8208250191 Summary of 820721 meeting w/util re significance of May Junction monocline in geological/seismological evaluation of Skagit/Hanford sites Not enough info received to confirm hazard HOON.C W Licensing Branch 4 82/08/12 Licensing Branch 4 5pp 14559 234 24X Fiche 50-522.82/08/12,8208250191
- 8208260144 Bummary of B20708 & O9 meetings w/utils.USG8 & Weston Geophysical in Bethesda,MD re seismic refraction data & integrated geology/seismology study MOON,G W Licensing Branch 4 62/08/12, Licensing Branch 4 6pp 14574 313 24X Fiche 50-522,82/08/12,8208260144
- 8208300003 Summary of 82072i meeting w/wtil re response to NRC 820624 ltr.need for power amend. FES & overall project schedule Tentative schedule delayed for last SER suppl due to NRC request for addl geological investigations HOON.C.W. Licensing Branch 4 82/08/23 Licensing Branch 4, 6pp. 14695 001 24% Fichs 50-522.82/08/23/8208300003
- B Utility Preliminary Safety Analysis Report, amends
- B208250213 Forwards Amend 26 to PSAR MYERB.R V Puget Sound Power & Light Co 82/08/16 Office of Nuclear Reactor Regulation. Director 3pp 14542 076 24X Fiche. 50-522. 82/08/16. 8208250213
- --8208250220 Amend 26 to PSAR Seven oversize drawings encl Aperture cards are available in PDR.

 Puget Bound Power & Light Co 82/08/16 56pp 14542 079. 24x Fiche: 50-522.82/08/16,8208250213
- D NRC Draft/Final Environmental Btatements, suppls & correspondence
- 8208040352 Forwards comments received re facilities DES Responses to comments expected by 820811 REGAN, W H Siting Analysis Branch 82/07/22 MYERS, R V. Puget Sound Power & Light Co. 3pp 14221 004 24X Fiche 50-522, 82/07/22, 82/8040552
- O Asjudicatory correspondence
- E209030314 Response opposing Columbia River Inter-Tribal Fish Commission 820716 motion for admission of second suppl to patition to intervent & response to ASLB 820702 order Certificate of 8vc encl
 THOMSEN,F T Puget Sound Power & Light Co THOMSEN,F.T. Perkins, Cole, Stone, Olsen & Williams, 82/07/30 Atomic Safety and Licensing Board Panel 30pp 14156, 278 24X Fiche 50-522,82/07/30, 8208030314
- 8208060112 Response to Columbia River Inter-Tribal Fish Commission 820716 motion for admission of second suppl to petition to intervene Good cause shown for Contention 4 Other factors favor admission of Contention 5. W/Certificate of 8vc.

 BLACK.R. L. Hearing Branch 3. 82/08/05 Atomic Safety and Licensing Board Penel 20pp 14238-235. 24X Fiche. 50-522.82/08/05.8208060112

- 8208240348 Motion for leave to reply to applicant 820730 response opposing Columbia River Inter-Tribal Fish Commission 820714 motion for admission of second suppl to petition to intervene Question of standing raised W/Certificate of 8vc. WAPATO.5 T Columbia River Inter-Tribal Fish Commission 82/08/19 Atomic 8afety and Licensing Board Panel 13pp 14520 155 24X Fiche 50-522,82/08/19,8208240348
- H General correspondence
- B208020352 Advises that distribution lists should be updated by replacing R Lowenstein w/00 Powell POWELL D Covenstein, Newman, Reis, Azelrad & Toll 82/07/27 TEDESCO,R L Assistant Director for Licensing, BLACK,R.L. Office of the Executive Legal Director ip 14150 080 24X Fiche 50-522,82/07/27.8208020352
- G Inspection reports, IE Bulletins & correspondence
- B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/16 Consolidated Edison Co of New York B7pp 14356 274 24X Fiche 50-000, B2/07/16, B204210393
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list entl JORDAN, E L Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ of 112pp 14358:001. 24X Fiche 50-000, 82/07/19, 8204210395.
- 8204210394 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Graduel Loss of Air Pressure " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210394
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl. COBB.L I. Division of Fuel Facilities, Materials & Safeguards 82/07/20. Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82-24, "RGIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN,E. L. Division of Engineering & Guality Assuranca, 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000.82/07/22.8204210378
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York 122pp, 14380.115 24X Fiche.50-000,82/07/23.8204210401.
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Bupport Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York. 127pp 14174 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list enci, JORDAN: E. L. Division of Engineering & Quality Assurance 82/07/26, Consolidated Edison Co. of New York. 121pp 14337, 013. 24X Fiche: 50-000, 82/07/26, 8204210403.
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Fool " Svc list encl. JORDANNEL Division of Engineering & Guality Assurance. 82/07/28 Consolidated Edison Co. of New York 122pp. 14357:146 24X Fiche: 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
 JORDANIE L. Division of Engineering & Quality Assurance. 82/08/05.
 Consolidated Edison Co of New York 117pp. 14388 201. 24X
 Fiche. 50-000. 82/08/05. 8204210407
- DOCKET 50-523 SKAOIT NUCLEAR POWER PROJECT, UNIT 2

 A Application/construction stage documents & correspondence
- 8207080064 Generic 1tr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS, M. J. Office of the Executive Director for Operations.
 82/07/02 Consolidated Edison Co of New York 93pp 14194:001
 24X Ficher 50-000, 82/07/02, 8207080064

- 8208060368 Board Notification 92-70 notifies of differing prof opinion re-sensitization of BWR stainless steel weldments.
 TEDESCO.R L Assistant Director for Licensing 82/07/20 Atomic Safety and Licensing Board Panel 4pp 14281.355 24X
 Fiche 50-000,82/07/20,8208060368
- 8208060037 Notification of 820726 meeting w/U808.util & NEBCO in Bethesda.MD to discuss geology investigation program of May Junction monocline MOON.C Licensing Branch 4. 82/07/21 ADENBAH.E.O Licensing Branch 4 2pp. 14280-029. 24X Fiche 50-522.82/07/21.8208060037
- 820B020349 Notifies that as result of review of ssismic & geologic deta for facility, add1 work is necessary to evaluate May Junction lineation near site. ALGERMISBEN.S Interior. Dept of. Geological Survey 82/07/22. JACKS
- 8208110047 PNA-82-006 on 820716, State of WA enacted law, effective 820801; imposing tax on sales of nuclear fuel assemblies, products mfg for fuel assemblies & on gross income of persons disposing of low level waste.

 LANDAU, M Assistant Director for State & Licensee Relations. KERR.0 U Office of State Programs, Director 82/07/23, 2pp 14329 251. 24X Fiche 50-522.82/07/23.8208110047
- 8208100216 Discusses resolution of final geology concern re May Junction monocline. Investigations yielded no evidence of faults associated w/fold investigative program discussed at 820721 meeting w/NRC will take approx 8 wks to complete. MYERS R V. Puget Bound Power & Light Co. 82/08/04 DENTON, H.R. ADENSAM, E. Office of Nuclear Reactor Regulation, Director 3pp 14294-344 24X Fiche 50-522,82/08/04.8208100216
- 8208130329 Forwards request for add1 info to confirm presence or absence of potentially hazardous geologic structure within 5 inles of site
 NOVAK.T.M Assistant Director for Licensing, 82/08/04, MYERB.R.V. Puget Bound Power & Light Co. 3pp. 14340-241, 24X
 Fiche: 30-522.82/08/04,8208130329.
- 8208090194 Ceneric Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl.
 EIBENHUT.D 0 Division of Licensing, 82/08/09, Consolidated Edison Co. of New York. Ip. 14356/332 24X Fiche:50-000,82/08/09,8208090194
- 8208190380 Forwards USOS 820722 ltr recommending addit drilling in May Junction area & preparation of table showing relationship between lithologic & geophysical logs Info request of 820804 reflects needs discussed in 820721 meeting.

 ADENSAM.E Q. Licensing Branch 4. 82/08/10, MYERS.V Puget Sound Power & Light Co. 2pp. 14504 153. 24X Fiche: 50-522, 82/08/10, 8208190880.
- B20B250191 Bummary of B20721 meeting w/util re significance of May Junction monocline in geological/setsmological evaluation of Skagit/Hanford sites. Not enough info received to confirm hazard MOON.C W Licensing Branch 4. 82/08/12 Licensing Branch 4. 5pp. 14539:234 24X Fiche: 50-522, 82/08/12, 8288250191
- 8208260144 Summary of B20708 & 09 meetings w/utils,USOS & Meston Geophysical in Bethesda,MD re seismic refraction data & integrated geology/seismology study, MOON.C.W Licensing Branch 4 B2/08/12. Licensing Branch 4. 6pp 14574.313 24X Fiche.50-522,82/08/12,8208260144.
- 8208300003 Summary of 820721 meeting w/util re response to NRC 820624 Itr, need for power amend, FES & overall project schedule. Tentative schedule delayed for last SER suppl due to NRC request for addi geological investigations. MOON.C W. Licensing Branch 4. 82708723. Licensing Branch 4. 6pp 14695.001. 24X Fiche:50-522, 82708723, 8208300003.
- B. Utility Preliminary Safety Analysis Report, amends
- 8208250213 Forwards Amend 26 to P8AR, MYERS.R.V. Puget Bound Power & Light Co. 82/08/16. Office of Nuclear Reactor Regulation. Director. Spp 14542:076 24X Fichs. 50-522, 82/08/16, 8208230213.
- --8208250220 Amend 26 to PBAR. Seven oversize drawings encl. Aperture cards are available in PDR.

 + Puget Sound Power & Light Co 82/08/16. 56pp. 14542:077. 24x Fiche: 50-522, 82/08/16. 8208250213.

D NRC Draft/Final Environmental Statements, supple & correspondence

8208040552 Forwards comments received re facilities DES Responses to comments expected by 820811 REGAN, W.H. Siting Analysis Branch 82/07/22 MYERS, R.V. Puget Sound Power & Light Co. 3pp. 14221 004 24X Fiche 50-522,82/07/22,8208040552

6 Adjudicatory correspondence

- 8208030314 Response opposing Columbia River Inter-Tribal Fish Commission 820716 mation for admission of second suppl to petition to intervene & response to ASLB 820702 order Certificate of Svc encl
 THOMSEN.F T Puget Sound Power & Light Co THOMSEN.F T Perkins, Coie, Stone, Olsen & Williams 82/07/30 Atomic Safety and Licensing Board Panel 30pp 14156 278 24X Fiche 50-522,82/07/30,8208030314
- 8208050112 Response to Columbia River Inter-Tribal Fish Commission 820715 motion for admission of second suppl to petition to intervene Good cause shown for Contention 4 Other Partors favor admission of Contention 5. W/Certificate of Svc BLACK-R L Hearing Branch 3 82/08/05 Atomic 8afety and Licensing Board Panel 20pp 14238 235 24X Fiche 50-522.82/08/05. 8208060112
- 8208240369 Motion for leave to reply to applicant 820730 response opposing Columbia River Inter-Tribal Fish Commission 820716 motion for admission of second suppl to petition to intervene Guestion of standing raised W/Certificate of Syc WAPATD.9 T Columbia River Inter-Tribal Fish Commission. 82/06 Atomic Safety and Licensing Doerd Panel. (3pp. 14520.155 ; Fiche 50-522,82/08/19,8208240368

H General correspondence

- 8208020352 Advises that distribution lists should be updated by regizating R Lowenstein w/DB Powell
 PGNELL D 0 Lowenstein Newman, Reis, Arelrad & Toll 82/07/27
 TEDESCO, R L Assistant Director for Licensing BLACK, R L Office
 of the Executive Legal Director ip 14150 080 24X
 Fiche 50-522, 82/07/27, 8208020352
- Q Inspection reports: IE Bulletins & correspondence
- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Lesiage." Svc list and Juneau St. Svc list and Juneau St. Guality Assurance 82/0 Consolidated Edison Co of New York 87pp. 14356 274 24X Ficha 50-000-82/07/16,8204210393.
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation," Bvc list encl JOHDAN E.L. Division of Engineering & Quality Assurance 62/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000,82/07/19,
 - 04210374 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Dradual Loss of Air Pressure " Evc list encl, JURDAN E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381.001, 24X Fiche 50-000, 82/07/20,8204210396,
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list enci COBB. I Division of Fuel Facilities, Materials & Safeguard 82/07/20 Consolidated Edison Co of New York. 7ipp 143 24/ Fiche 50-000,82/07/20.8204210397
- B20421039B IE Info Notice 82-25. "RCIC & IPCI Turbine Exhaust Check Valve Failures." Svc list encl JORDANIE L Division of Engineering & Quality Assurance, 82/07/22, Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000.82/07/22.8204210398
- 9204210401 TE Info Notice 82-23, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp. 14380-115, 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDANEL Division of Engineering & Quality Assurance. B2/07/23 Consolidated Edison Co. of New York. 127pp. 14174 120 24X Fiche 50-000.82/07/23.8204210402

- 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/07/26 Consolidated Edison Co of New York 121pp 14357 013 24X Fiche 50-000.82/07/26,8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JRRDAN.E L Division of Engineering & Quality Assurance 82/08/03 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 50-000.82/08/05.8204210407

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS,W J Office of the Executive Director for Operations
 82/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24X Fiche 50-000,82/07/02,8207080064
- 8208030650 Forwards response to Guestion 231 6 re geologic features identified as possible faults in proximity to facilities. Two oversize drawings encl Aperture cards are available in VAN BRUNT, E E Arizona Public Service Co 82/07/29 TEI Assistant Director for Licensing 13pp 14161 115 24X Ficha 50-528.82/07/29.8208030650 TEDESCO, R L
- 8208160011 Forwards response to NRC 820510 hypothetical questions re postulated loss of essential spray pond spray norries due to tornado missiles Util relied on probabilistic risk assessment as response to SER Section 9 2 5
 VAN BRUNT, E E Arizona Public Service Co 82/08/06 NOVAK, T H Assistant Director for Licensing, lipp 14344 352 24X
 Fiche 50-528,82/08/06,8208160011
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Sec list encl EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison CD of New York ip 14356 332 24% Fiche, 50-000, 82/08/09, 8208090194
- 8208160092 Forwards proposed amended Section 6.2 6 of FBAR responding to NRC 820510 question re-local leak rate testing of certain valves using water in lieu of air or nitrogen Changes will be incorporated in future FSAR amend VAN BRUNT, E.E. Arizona Public Service Co. 82/08/11. NOVAK, T.H. Assistant Director for Licensing. 12pp 14342 054 24X Fiche 50-528,82/08/11,8208160072
- 820B170190 Provides status rept of licensing & pre-fuel load activities Units scheduled for fuel load in Aug 1783 & 1784 & Nov 1985 Application to amend CP to reflect revised inservice dates forthcoming Affidavit encl VAN BRUNT, E E Arizona Public Service Co 82/08/11 NOVAK Assistant Director for Licensing 3pp 14366.285 24X Fiche 80-528,82/08/11,8208170190 NOVAK, T H
- 8208200205 Forwards supplemental info to licensee 820617 ltr re make-up capability to UHS Info includes Ertec Western, Inc feasibility assessment for drilling & const of supplemental water supply well for UHS VAN BRUNT, E.E. Arizona Public Service Co. 82/08/12 NOVAK, T. H. Assistant Director for Licensing 12pp 14397:184 24X Fiche. 50-528, 82/08/12, 8208200205
- 8208230053 Forwards responses to open items re 820803-06 pump & valve operability review team (PVORT) audit VAN BRUNT.E E Arizona Public Service Co. 82/08/19 NOVAK.T H Division of Licensing. 8pp 14517 149 24X Fiche 50-528,82/08/19.8208230053
- F Security, medical, emergency & fire protection plans
- 8208240262 Forwards Proof of Byc for Revision 2 to facility emergency plan VAN BRUNT,E E Arizona Public Service Co 82/08/18. Nuclear Reactor Regulation, Director. App 14527-13 Ficha 50-528.82/08/18,8208240262 Office of 82/08/18. OFFI 14527:131, 24X

6 Adjudicatory correspondence

- 8208020205 Forwards proposed initial decision in form of order, authorizing OL issuance Certificate of Svc encl BISCHOFF, C A Snell & Wilmer BISCHOFF, C A Joint Applicants-Palo Verde 82/07/26 Docketing & Services Branch 97pp 14141 203 24X Fiche 50-528,82/07/26,8208020205
- 8208020236 Repts on NRC investigation of allegations made by unnamed electrical worker Several more interviews remain Rept will be completed by end of Aug DENEY.L 8 Hearing Branch 3 82/07/29 LAZO.R M , COLE.R F , CALLIHAN.D Atomic Safety and Licensing Beard Panel 2pp 14152 082 24% Fiche 50~528,82/07/29,8208020236
- 8208030311 Answer opposing PL Hourihan B20716 motion for reconsideration of ASLB admission into evidence of Joint Applicants Exhibit DD Exhibit authenticated & cannot be excluded under hearsay objection W/Certificate of Svc BISCHOFF, C A Joint Applicants-Palo Verde BISCHOFF, C A C. A B2/07/27 Atomic Safety and Licensing Board Panel 14157 132 24X Fiche 50-528,82/07/27,8208030311
- 8208090003 Response opposing PL Hourihan motion for reconsideration of ASLB admission into evidence of Joint Applicants Exhibit DD Exhibit correctly entered into evidence, meets reliability test & cross-examination was allowed W/Certificate of Svc DENEY, L. S. Hearing Branch 3 82/08/05, Atomic Safety and Licensing Board Panel 12pp 14270 048 24X Fiche 50-528.82/08/05, 820890003
- 920B120131 Requests distribution of encl RM Lazo 820B10 memo to ABLB & parties LAZD,R M Atomic Safety and Licensing Board Panel 82/08/10 STUCKY,B W Docketing & Services Branch ip 14327 130 24X Fiche: 30-528, 82/08/10, 820B120131
- --8208120133 Forwards 820801 ltr containing allegation of faulty welds for appropriate action Investigation rept should be distributed to ASLB & parties W/o encl LAZD,R M Atomic Safety and Licensing Board Panel 82/08/10 FITZGERALD,J A Office of Investigation ip 14327 i31 24X Fiche 50-528,82/08/10,8208120131
- 8208160062 Memorandum & order denying PL Hourihan 820621 patition for directed certification of two evidentiary rulings No reasons given why certification should be granted rather than appealing record to ABLAB LAZU.R.M Atomic Safety and Licensing Board Panel 82/08/12. Hourihan. P 9pp. 14342 027 24X Fiche 50-528,82/08/12,8208160062
- 8208190116 Forwards proposed findings of fact & conclusions of law BERNABELL Harmon & Weiss BERNABELL Hourihan, P 82/08/13 Docketing & Services Branch 1p. 14381 195 24X Fiche 50-528, 82/08/13, 8208190116
- --8208190159 Proposed findings of fect & conclusions of law Certificate of Svc encl + Hourihan, P. 82/08/13 94pp 14381*196 24X Fiche 50-528,82/08/13,8208190114
- 8208200273 Natice of corrections to Joint Applicants 820726 proposed initial decision Certificate of Svc encl BIBCHOFF, C. A. Joint Applicants-Palo Verde BIBCHOFF, C. A. 82/08/16. 30pp 14398 293 24X Fiche 50-528.82/08/16, 8208200273
- 8208240220 Memorandum & order denying PL Hourihan 820716 motion for reconsideration of ASLB admission of Joint Applicants Exhibit DD into evidence Hearsay objection untimally LAZOR K Atomic Safety and Licensing Board Panel 82/09/19 HOURIHAN.P L Hourihan. P 7pp 14521:104. 24X Fiche: 50-328, 82/08/19, 8208240220
- B208260056 Proposed opinion, findings of fact, conclusions of law & order in form of initial decision Certificate of Svc encl. DEWEY, L S. Hearing Branch 3 82/08/23 105pp. 14555-234 24X Fiche, 30-328, 62/08/23, 6208260056

1. Financial information

- 8208270375 Forwards Annual Financial Repts 1981.

 VAN BRUNT, E.E. Arizona Public Service Co 82/08/23 Office of Nuclear Reactor Regulation, Director 1p 14566 186. 24X Fichs. 30-528, 82/08/23, 8208270375.
- --B208270378 Annual Financial Rept 1781. TURLEY, K.L. Arizona Public Service Co. 82/02/25 36pp. 14566-187 24X Fiche 50-528,82/08/23,8208270375.

- --8208270384 Annual Financial Rept 1981 GEIST. J D . SCHREIBER. G A Public Service Co of New Mexico 82/08/23 39pp 14566 223 24X Fiche 50-528,82/08/23,8208270375
- --8208270388 Annual Financial Rept 1981 WALLER El Paso Electric Co 82/08/23 44pp 14566 262 24X Fiche 50-528,82/08/23,8208270375
- --8209270398 Annual Financial Rept 1981 PFISTER.J Salt River Project 82/08/23 32pp 14566 347 24X Fiche 50-528,82/08/23,8208270375
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8208170168 Forwards Amend 9 to FBAR VAN BRUNT, E E, Arizona Public Service Co 82/08/16 Office of Nuclear Reactor Regulation, Director 2pp 14367 274 24X Fiche 50-528,62/08/16,8208170168
- --8208170172 Amend 9 to FSAR Seventeen oversize figures encl Aperture cards are available in PDR * Arizona Public Service Co. 82/08/31 800pp 14367 278. 24X Fiche 50-528,82/08/16,8208170168
- M Antitrust correspondence
- 82080&0102 Forwards draft OL antitrust review finding of no significant change, for review & comment W/o enc! RUTBERG, J Hearing Branch 2 82/07/29 CUTLER, M Justice, Dept. of ip 14238.176 24% Fiche 30-528.82/07/29, 82080&0102
- O Inspection reports: IE Bullatins & correspondence
- 8208270330 Forwards corrected response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Bys Components by Corbicula Sp & Mytilus Sp " Presence of either species not found at facility VAN BRUNT, E E. Arizone Public Service Co 81/06/03 ENGELKEN, R. H Region 5, San Francisco, Office of the Director (81/03/01) 2pp 14368 114 24X Fiche 50-528, 81/06/03, 8208270330
- 8208240383 Bubmits corrected response to IE Bulletin 81-02, "Failure of Oats Tupe Valves to Close Against Differential Pressure." No corrective actions required. Approx 80 manhours expended in review VAN BRUNT, E. E. Arizona Public Service Co. 81/07/07 ENOELKEN, R. H. Region 5, San Francisco, Office of the Director (61/03/01) Spp. 14524 341 24X Fiche 50-528, 81/07/07, 8208240383
- --8208240396 "Flow Interruption Test for Part 77910. Supplied to C-E."
 PATEL, B A , BRALEY, C., RIAZ, M Borg-Warner Corp 1843 RB.
 81/05/18 5pp. 14524.345 24X Fiche 50-528, 81/07/07, 8208240383
- --8208240412 Corrected "Flow Interruption Test on Gate Valve Assembly " HICKOK,N, BAME.D. CLARK,H E Approved Engineering Test Laboratories 548-9142 ERR. 81/05/08 14pp 14524:350 24X Fiche 50-528,81/07/07:8208240383
- 8208240144 Submits corrected copy of response to IE Bulletin Si-O2, "Failure of Oate Type Valves to Close Against Differential Pressure " No subj valves used in design Approx 25 manhours expended in review VAN SRUNT, E.E. Arizona Public Service Co 81/10/01 ENGELKEN, R. F. Region 5. San Francisco, Office of the Director (81/03/01) 2pp 14519 361 24X Fiche 50-528, 81/10/01, 8208240144
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage." Svc list encl JORDANIE L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co. of New York, 87pp. 14336-274, 24X Fiche: 50-000, 82/07/16, 8204210393
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list and JORDAN EL. Division of Engineering & Guality Assurance 82/07/19, Michigan, Univ of, 112pp 14359, 001 24X Fiche: 50-000, 82/07/19, 8204210375.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure," Svc list encl.
 JORDAN,E L. Division of Engineering & Quality Assurance, 82/07/20
 Consolidated Edison Co. of New York 112pp 14381:001. 24X
 Fiche 50-000.82/07/20,8204210396

- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexaflworlde Overpacks" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 24K Fiche 50-000,82/07/20,8204210397
- 8204210378 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York. 112pp 14194 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8208160273 Forwards IE Insp Rept 50-528/82-21 on 820701-16 No noncompliance noted STERNBERG, D H Division of Resident, Reactor Project & Engineering Progress 82/07/22 ANDOGNINI, 9 C Arizona Public Service Co 2pp 14346 181 24X Fiche-50-528,82/07/22,8208160273
- --8208160279 IE Insp Rept 50-528/82-21 on 820701-16 No noncompliance noted Hajor areas inspected startup testing primary syshydrostatic test, document control & preventive maint FIGRELLI.O. JOHNSTON.O. ZWETZIO.O Division of Resident, Reactor Project & Engineering Programs 82/07/22 App 14346 183 24X Fiche.50-528,82/07/22.8208160273
- 8208160318 Forwards IE Insp Rept SO-528/82-20 on 820706-07 No noncompliance noted 800K,H E Division of Radiological Safety & Safeguards Program 82/07/22 ANDOWNINI.O C Arizona Public Service Co 4pp 14348-045 24X Ficha 50-528,82/07/22,8208160318
- --8208160325 IE Insp Rept 50-528/82-20 on 820706-07 No noncompliance noted Major areas inspected current status of chemistry & radiochemistry programs from standpoint of facility. equipment.personnel.04 & procedures HAMADA.0 H , MENBLAMSKI,F , BOOK,H E Division of Radiological Bafety & Safeguards Program 82/07/22 App 14348 049 24% Fiche 50-528.82/07/22.8208160318
- 8204210401 IE Info Natice 82-23, "Hydragen Explosion While Grinding in Vicinity of Dreined & Open RCS " Svc list encl JORDAN:E L Division of Engineering & Quality Assurance, 82/07/23 Consultdated Edison Co. of New York 122pp 14380 115 24X Fiche 50-000.82/07/23.8204210401
- 8204210402 IE Info Notice B2-27, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Hestinghouse PHRs " Byo list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14174,120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357.013 24X Fiche 50-000,82/07/26,8204210403
- 3204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Evo list encl.

 JORDANIE L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 132pp. 14357:146 24X Fiche. 80-000. 82/07/28,8204210405
- 3208240285 Forwards IE Insp Repts 50-528/82-14,50-529/82-07 & 50-530/82-07 on 820503-0625 No noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/08/04. VAN BRUNT,E E Arizona Public Bervice Co 2pp. 14527,150 24X Fichs 50-528-82/08/04,8208240285
- -B20B240291 IE Insp Repts 50-B28/B2-14,50-529/B2-07 & 50-530/B2-07 on B20503-0625, No noncompliance noted, Major areas inspected installation of RCPB & other sefety-related piping in Units 1 & 3 & followorp of 100FR50,5516 bitms.

 VORDERBRUEGOEN, YOUND, T Division of Resident, Reactor Project & Engineering Programs. B2/OB/03 App 14527-152 24X Fiche 50-828,82/08/04,8208240285
- B204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance. B2/08/05 Consolidated Edison Co. of New York. 117pp. 14388 201 24X Fiche.50-000.82/08/05.8204210407
- 8208240277 Ack receipt of 820723 ltr informing NRC of steps taken to correct violations noted in IE insp on 820329-0402
 STERNBERG.D.H Division of Resident, Reactor Project & Engineering Programs. 82/08/16 VAN BRUNTLE Arizons Public Service Co 1; 14327:167. 24X Fiche:50-328,82/08/16,6208240277

- --B208240287 Responds to NRC 820625 itr re violations noted in IE insp on 820329-0402 Corrective actions NCR EA-1944 initiated B20402 to document monconforming anchor bolts & retorque VAN BRUNT, E E Arizona Public Service Co 82/07/23 BISHOP, T W Region 5. Office of Director 10pp 14527 168 24X Fiche 50-528, 82/08/16, 8208240277
- 8208270322 Ack receipt of 820810 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-528/82-12, 50-529/82-06 & 50-530/82-06 STERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs 82/08/20 VAN BRUNT/E E Arizona Public Service Co. 19 14365 073 24% Fiche 50-528,82/08/20,8208270322
- --8208270325 Responds to NRC 820709 notice of violation Corrective actions immediate action taken to inspect uncapped pipe for cleanliness & proper capping VAN BRUNT,E E Arizona Public Service Co 82/08/10 BIBHOP,7 W Division of Resident, Reactor Project & Engineering Programs, 4pp 14565 074 24X Fiche, 50-528, 82/08/20, 8208270322
- R Periodic operating reports & related correspondence
- B20B110130 Forwards "Independent QA Evaluation." biweekly status rept for 820719-30 SIMON.WA Torrey Pines Technology B2/08/03 TURLEY.KL Arizand Public Service Co 1p 14914-353 24X Fiche 50-528,82/08/03, 820B10130.
- --8208110133 "Independent QA Evaluation," biweekly status rept for 820719-30

 * Torrey Pines Technology 82/08/03, 8pp 14314 354, 24X Fiche: 50-528, 82/08/03, 8208110130
- 8208310311 Forwards "Independent QA Evaluation of Palo Verde Nuclear Cenerating Station,Units 1,2 & 3," Biweekly Status Rept 3 for period ending 820813 SIMON,M A. Torrey Pines Technology 82/08/20, TURLEY,K,L Aritans Public Service Co. 12pp 14687 327 24X Fiche 50-528,82/08/20, 8208310311
- 8 Reportable occurrences, LERs & related correspondence
- 8208080245 Final deficiency rept re safety-related instrument tubing clamps installed w/o locking devices on threaded fasteners initially reported on 820303 Design changes issued to have installed clamps corrected to comply w/ASME Code VAN BRUNT.E E Arizona Public Service Co 92/07/23. BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 3pp. 14209, 266 24X Fiche-50-528, 82/07/23, 8208050245
- 820B050437 Interim deficiency rept re possible affect of concrete void below penetretion in main steam supply sys on pipe restraint Initially reported on B20624 Condition not reportable per 10CFR50 55(e) VAN BRUNT, E Arizona Public Service Co. B2/07/23 BISHOP, T W. Region 5, Office of Director 2pp. 14218, 028, 24X Fiche 50-528, 82/07/23, 8208050437
- 8208230358 Final deficiency rept re diesel generator control panel wiring not crimped into terminal lugs mfg by Gosper Energy Initially reported on 820707 Vendor concurred w/removal of lugs & installation of new lugs Also reported per Part 27 VAN BRUNT.E E Arizona Public Service Co 62/08/06. BIBHOP.T W Division of Resident, Reactor Project & Engineering Programs. App 14508 277 24X Fiche: 50-528,82/08/06.8208230358
- 8208230216 Interim deficiency rept re reactor coolant pump 28 discharge pressure tap nozzle weld lesk Initially reported on 820709 Stainless steel portion of nozzle to be replaced w/double socket piece Next rept due by 821104 VAN BRUNT, E E Arizone Public Service Co 82/08/09, BISHOP, T W Division of Resident, Reactor Project & Engineering Programs, 4pp. 14513 342 24X Fiche, 50-528, 82/08/09, 8208230216.
- B20B230301 Fourth interim deficiency rept re mating force of 125-volt dc pull-out fuse block decreasing after several insertions & removals. Initially reported on 810321. Bechtel developing plans to replace fuse block. Finel rept excepted by 821103 VAN BRUNT. E. Arizona Public Service Co 82/08/10. B18HOP.T. W Division of Resident. Reactor Froject & Engineering Programs. App. 14510: 324. 24X Fiche-50-528.82/08/10.8208230301.
- T. Hearing transcripts on non-antitrust matters
- 8208050118 Proposed corrections to 820427-30,0525-28 & 0422-25 transcripts of hearing BISCHOFF, C. A. Joint Applicants-Palo Verde. BISCHOFF, C. A. Bnell & Wilmer. 82/08/03, 15pp. 14238 273. 24X Fiche: 50-528,82/08/03,8208060118

- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8207080064 Generic itr to all licensess of operating plants, applicants for GL & holders of CP re Commission approved charter for CROR Svc list encl
 DIRCKS.W J Diffice of the Executive Diractor for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194 001
 24% Fichs 50-000,82/07/02,8207080064
- 0208030650 Forwards response to Question 231 6 re geologic features identified as possible faults in proximity to facilities
 Two oversize drawings encl Aperture cards are available in
- VAN BRUNT,EE Arizona Public Service Co 82/07/29 TEI Assistant Director for Licensing 13pp 14161 115 24X Fiche.50-528,82/07/29,8208030650 TEDESCO, R. L.
- 8208160011 Forwards response to NRC 820510 hypothetical questions repostulated loss of essential spray pend spray norzles due to ternado missiles Util relied on probabilistic risk assessment as response to BER Section 9 2 5
 VAN BRUNT, E E Arizona Public Service Co. 82/08/06 NOVAK, T H Assistant Director for Licensing 11pp 14344 352 24X
 Ficha 50-528, 82/08/06, 8208160011,
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl EISENHUT.D 0 Division of Licensing 82/08/09 Consolidated Edison Co. of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- 8208160072 Forwards proposed amended Section 6 2 6 of FBAR responding to NRC 820510 question re local leak rate testing of certain valvas using water in lieu of air or nitrogen Changes will be incorporated in future FBAR amend VAN BRUNT. E E Arizona Public Service Co 82/08/11 NOVAK. T H Assistant Director for Licensing 12pp 14342 054 24X Fiche 50-528.82/08/11.8208160092
- 8208170190 Provides status rept of licensing & pre-fuel load 2001/Olfy Provides scatus rept of licensing & pre-tuni load activities Units scheduled for fuel load in Aug 1933 & 1984 & Nov 1985 Application to amend CP to reflect revised inservice dates forthcoming Affidavit encl VAN BRUNT, EE Arizona Public Service Co 82/08/11 NOVAN Assistant Director for Licensing 3pp 14366; 285 24X Fiche 50-528, 82/08/11, 8208170190 NOVAK, T. H
- 820B200205 Forwards supplemental info to licensee 820617 ltr re make-up capability to UHB info includes Erter Western. Inc feasibility assessment for drilling & const of supplemental water supply well for UHB VAN BRUNT, E. E. Arizona Public Service Co. 82/08/12 NOVAK, T H water supply well for UMS
 VAN BRUNT, E. E. Arizona Public Service Co. 82/08/13
 Assistant Director for Licensing. 12pp. 14399,184
 Fiche 50-528,82/08/12,8208200205 82/08/12 NO 4399,184 24X
- 8208230053 Forwards responses to open items re 820803-06 pump & valve considered reviewing responses to open items to \$20803-06 pump & valve openability review team (PVORT) addit VAN BRUNT,E E. Artiona Public Service Co 82/08/19 NOVAK,T.H Division of Licensing 8pp 14517 169 24X Fiche 50-528,82/08/19,8208230053.
- F Security, medical, emergency & fire protection plans
- 8208240262 Forwards Proof of Syc for Revision 2 to facility emergency plan VAN BRUNT,E E Arizona Public Service Co 82/08/18 Nuclear Reactor Regulation. Director 4pp 14527 131 Fiche: 50-528: 82/08/18: 8208240262 Office of 24X
- G Adjudicatory correspondence
- 8208020205 Forwards proposed initial decision in form of order. authorizing OL issuance Certificate of Svc encl BIGCHOFF,C A. Snell & Wilmer BIBCHOFF,C A. Joint Applicants-Palo Verde BZ/07/26 Docketing & Services Branch 99pp 14141 203 24X Fichs. 50-528, 82/07/26, 8208020205
- 8208020236 Repts on NRC investigation of allegations made by unnamed electrical worker Saveral more interviews remain Rept will be completed by end of Aug.

 DEWEY, L. B. Hearing Branch 3 82/07/29 LAZU, R M, COLE, R. F., CALLIMAN. D. Atomic Bafety and Licensing Board Panel 2pp 14152:032 24X Fichs 50-528,82/07/29,8208020236.

- 82080303ii Answer opposing PL Hourshan 820716 motion for reconsideration of ASLB admission into evidence of Joint Applicants Exhibit DD Exhibit authenticated & cannot be excluded under hearsay objection W/Cartificate of Svc BISCHOFF, C A Joint Applicants-Palo Verde BISCHOFF, C A Bischoff, C A 82/07/29 Atomic 88fety and Licensing Board Panel. 14pp 14157 132 24X Fichs 50-528.82/07/29.8208030311.
- 8208090003 Response opposing PL Hourihan motion for reconsideration of ASLB admission into evidence of Joint Applicants Exhibit DD Exhibit correctly entered into evidence meets reliability test & cross-examination was allowed W/Certificate of Svc DEWEY, L S Hearing Branch 3 B2/08/05 Atomic Safety and Licensing Board Penel 12pp 14270 048 24X Fiche 50-528-82/08/05, 82080900003
- 8208120131 Requests distribution of encl RM Laro 820810 mamo to ASLB & parties. LAZO,R M Atomic Safety and Litensing Board Panel 82/08/10 STUCKY,S W Docketing & Services Branch 1p 14327 130, 2: Fiche 50-528,82/08/10,8208120131
- --8208120133 Forwards 820801 itr containing allegation of faulty welds for appropriate action investigation rept should be distributed to ABLO & parties W/o encl LAZO.R M Atomic Sefety and Licensing Board Panel 82/08/10. FITZGERALD.J A. Office of investigation ip 14327 131. 24X Fiche 50-528,62/08/10.8208120131
- 8208160062 Hemorandum & order denying PL Hourihan 82062! petition for directed certification of two evidentiary rulings No reasons given why certification should be granted rather than appealing record to ASLAB.

 LAZO, R M Atomic Safety and Licensing Board Panel 82/08/12 Hourihan, P 9pp 14342.027, 24X Fiche 50-528,82/08/12.8208160062.
- 820B190116 Forwards proposed findings of fact & conclusions of law, BERNABEI.L. Harmon & Weiss BERNABEI.L. Hourihan, P. 82/08/13 Docketing & Services Branch ip 14381:195 24X Fiche 50-520,82/08/13,820B190116.
- -- 8208190159 Proposed findings of fact & conclusions of law Certificate of 8vc enci 4 Haurihan, P 82/08/13 96pp 14381 196 24X Fiche 50-528,82/08/13,8208190116
- 820B200273 Notice of corrections to Joint Applicants 82072A proposed initial decision. Certificate of Svc encl BISCHOFF, C A Joint Applicants-Palo Verde BISCHOFF, C A. Bischoff A B2/08/16 30pp. 14378 293, 24X Fiche 50-528 Bischofe, 8208200273
- 8208240220 Memorandum & order denging PL Hourihan 820716 metion for reconsideration of ASLB admission of Joint Applicants Exhibit DD into evidence Hearsay objection untimely LAZO,R M Atomic Safety and Licensing Board Panel. 82/08/19 HOURIHAN,P L Hourihan, P 7pp 14521; 104 24% Fiche 50-528,82/08/19,8208240220
- 8208260056 Proposed opinion, findings of fact, conclusions of law & order in form of initial decision Certificate of Bvc encl DEWEY, L B Hearing Branch 3 82/08/23 105pp 14555-234. 24X Fiche 50-528, 82/08/23, 8208260056

I Financial information

- 9209270375 Forwards Annual Financial Repts 1981 1082/05/3 Forwards Annual Financial Hope 1701 VAN BRUNT, E.E. Arizona Fublic Service Co. 82/08/23 Nuclear Reactor Regulation, Director 1p. 14566 186 Fiche: 50-528, 82/08/23, 8208270375 Office of
- --8208270378 Annual Financial Rept 1981. TURLEY, K.L. Arizona Public Service Co. 82/02/28 14566 187. 24X Fiche 50-528, 82/08/23, 8208270375 82/02/25, 36pp
- --8208270384 Annual Financial Rept 1981 GEIST, J D : SCHREIBER, G A Public Service Co. of New Hexico. 82/08/23, 39pp 14566-223, 24X Fiche 30-528, 82/08/23, 8208270375
- --8208270388 Annual Financial Rept 1981 WALL: E R. El Paso Electric Co 82/08/23 44pp. 14566:262. 24X Fiche. 50-328, 82/08/23, 8208270375
- --8208270398 Annual Financial Rept 1981. PFISTER, J Salt River Project 82/08/23. 32pp. 14566.347 24X Fiche: 50-526, 82/08/23, 9208270375

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8208170168 Forwards Amend 9 to FSAR VAN BRUNT,E E Arizona Public Service Co 82/08/16 Office of Nuclear Reactor Regulation, Director 2pp 14367 274 24X Fiche 50-528,82/08/16,8208170168
- --B20Bi70172 Amend 9 to FSAR Seventeen oversize figures enci Aperture cards are available in PDR 4 Arizona Public Service Co B2/08/31 800pp 14367 278 24X Fiche 50-528,82/08/16.8208170168
- M Antitrust correspondence
- 8208060102 Forwards draft DL antitrust review finding of no significant change, for review & comment W/o ent! RUTBERG, J Hearing Branch 2 82/07/29 CUTLER, M Justice, Dept of ip. 14238 176 24X Fiche 50-528, 82/07/29, 8208060102
- G Inspection reports. IE Bulletins & correspondence
- 8208270330 Forwards corrected response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corpicula Sp & Mytflus Sp "Presence of either species not found at facility VAN BRUNT.E E Arizone Public Service Co 81/06/03 ENGELKEN,R H Region 5, San Francisco, Office of the Director (81/03/01), 2pp 14565 114 24X Fiche 50-528,81/06/03,8208270330
- 8208240383 Submits corrected response to IE Bulletin 81-02, "Failure of Gate Type Valves to Close Against Differential Pressure "
 No corrective actions required Approx 60 manhours expended in review
 VAN BRUNT.E E Arizona Public Service Co 81/07/07 ENGELKEN.R H Region 5, San Francisco Diffice of the Director (81/03/01) 3pp 14524 341 24X Fiche 50-528,81/07/07.8208240383
- --8208240396 "Flow Interruption Test for Part 77910.8upplied to C-E" PATEL, B A . BRALEY, C . RIAZ, M Borg-Warner Corp 1843 RD 81/05/18 5pp 14524 345 24X Fiche 50-528, 81/07/07, 8208240383
- 8208240144 Submits corrected copy of response to IE Bulletin 81-02, "Fallure of Gats Type Valves to Close Against Differential Pressure " No subj valves used in design. Approx 25 manhours expended in review VAN BRUNT.E E Arizona Public Service Co 81/10/01 ENGELKEN, R H agion 5, San Francisco. Office of the Director (81/03/01) 2pp 14319 361 24% Fiche 50-328,81/10/01,8208240144
 - 04210393 iE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) .eskage " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co of New York 870p 14356-274. 24X Fiche 50-000.82/07/16.8204210393
- 1204210395 IE Info Notice Bi-26,Part 3, Buppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/19, Hichigan, Univ of 112pp 14359 001 24X Fiche: 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list ancl JORDAN E L Division of Engineering & Guality Assurance, 82/07/20, Consolidated Edison Co. of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396,
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list enci COBB,L I. Division of Fuel Facilities, Materials & Gafeguards. 82/07/20 Consolidated Edison Co of New York. 71pp. 14357; 27 24X Fiche 50-000.82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & HFCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN: E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194:321 24X Fiche. 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN: EL Division of Engineering & Quality Assurance 82/07/23. Consolidated Edison Co of New York. 122pp 14380:115 24X Fiche.50-000,82/07/23,8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl JORDAN,E L. Division of Engineering & Guality Assurance. 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Cartain Westinghouse PWR Power Plants" Svc list encl JORDAN,E L Division of Engineering & Guality Assurance B2/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool " Bvc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8208240285 Forwards IE Insp Repts 90-528/82-14, 90-529/82-07 & 30-530/82-07 on 820503-0625 No noncompliance noted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/08/04 VAN BRUNTLE Arizona Public Service Co 2pp 14527 150 24X Fiche 50-528, 82/08/04, 8208240285.
- --8208240271 IE Insp Repts 50-528/82-14.50-529/82-07 & 50-530/82-07 on 820503-0625 No noncompliance noted Major areas inspected installation of RCPB & other safety-related piping in Units 1 & 3 & followsp of 10CFR50 55(a) items VORDERDRUEOGEN, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/08/03 6pp 14527 152 24X Fiche 50-528,82/08/04.8208240285
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388:201 24X
 Fiche 50-000,82/08/05,8204210407
- 8208240277 Ack receipt of 820723 ltr informing NRC of steps taken to correct violations noted in IE insp on 820329-0402 STERNDERO, D H Division of Resident, Reactor Project & Engineering Programs 82/08/16 VAN SRUNT. EE Arizona Public Service Co. 1, 14527 167 24X Fiche 50-528,82/08/16,8208240277
- --8208240287 Responds to NRC 820625 itr re violations noted in IE inspon 820329-0402 Corrective actions NCR EA-1764 initiated 820402 to document nonconforming anchor bolts & retorque VAN BRUNT, E E Arizona Public Borvice Co. 82/07/23 BISHOP, TW Region 5, Office of Director 10pp 14527 168, 24X Fiche 50-528,82/08/16.8208240277
- 8208270322 Ack receipt of 820810 ltr informing NRC of steps taken to correct violations noted in IE Inep Rept 50-528/82-12, 50-527/82-06 & 50-530/82-06
 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/08/20, VAN DRUNT,E E. Arizona Public Benvice Co 1p 14365 073 24X Fiche 50-528,82/08/20,8208270322.
- --8208270325 Responds to NRC 820709 notice of violation Corrective actions immediate action taken to inspect uncapped pipe for cleanliness & proper capping VAN BRUNT,E E Arizona Public Bervice Co. 82/08/10. BIBHOP,T.H Division of Resident, Reactor Project & Engineering Programs, 4pp 14565-074 24X Fiche-50-528,82/08/20,8208270322
- R Periodic operating reports & related correspondence
- 820Bi10130 Forwards "Independent QA Evaluation," biweekly status rept for B20719-30 BIMON.W A Torrey Pines Technology 82/08/03, TURLEY, K.L. Arizons Public Service Co. 1p 14314 353, 24X Fiche 50-528,82/08/03, 820Bi10130
- --8208110133 "Independent QA Evaluation," biweekly status rept for 820719-30.

 * Torrey Pines Technology 82/08/03 8pp 14314.354, 24X Fiche 50-528,82/08/03/8208110130
- 820B310311 Forwards "Independent OA Evaluation of Palo Verde Nuclear Cenerating Station, Units 1.2 & 3." Biweekly Status Rept 3 for period ending 820B13. SIMDN, W A. Torrey Pines Technology. 82/08/20 TURLEY, K.L. Arizon Public Service Co 12pp. 14687:327 24X Fiche: 50-528, 82/08/20.

S Reportable occurrences, LERs & related correspondence

- 8208030245 Final deficiency rept re safety-related instrument tubing clamps installed w/o locking devices on threaded fasteners initially reported on 820303 Design changes issued to have installed clamps corrected to comply w/ASME Code VAN BRUNT, E E Arizona Public Service Co 82/07/23 BIBHOP, T W Division of Readdent, Reactor Project & Engineering Programs 3pp 14209:266 24X Fiche 50-528,82/07/23,8208050245
- 8208160181 Interim deficiency rept re undertorque of low pressure safety injection & containment spray pump casing hold-down bolts. Initially reported on 820707 Analysis of condition continuing Final rept will be submitted by 920930 VAN BRUNT.E E Arizona Public Service Co 82708705 BIEHOP.T W Division of Resident, Reactor Project & Engineering Programs 3pp 14345 097 24X Fiche 50-529,82708/05.8208160181
- 8208230301 Fourth interim deficiency rept re mating force of 125-yolt dc puli-out fuse block decreasing after several insertions & removals Initially reported on 810321 Bechtel developing plans to replace fuse block Final rept excepted by 821103 VAN BRUNT. E Arizona Public Service Co 82/08/10 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs App 14510 324 24% Fiche 50-528,82/08/10,8208230301
- 8208240209 Interim Deficiency Rept DER 82-37 re Class IE wiring terminations crimped w/less pressure than specified due to lack of maint program Initially reported on 820713 Bechtel investigation underway Final rept by 821021.

 VAN BRUNT, E. E. Arizona Public Service Co. 82/08/10 BISHOP, T. H. Division of Resident, Reactor Project & Engineering Programs 3pp 14519,073 24X Fiche 50-529.82/08/10.8208240209

T. Hearing transcripts on non-antitrust matters

- 82080&0118 Proposed corrections to 820427-30,0525-28 & 0422-25 transcripts of hearing BIBCHOFF, C A Joint Applicants-Palo Verde BIBCHOFF, C A 8nell & Wilmer 82/08/03 15pp 14238 273 24X Fiche 50-528,82/08/03,82080&0118
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- B207080064 Generic 1tr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl.

 DIRCKS, H J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York, 93pp 14194:001.

 24x Fiche 50-000,82/07/02,8207080044
- 8208030650 Forwards response to Question 231 & re geologic features identified as possible faults in proximity to facilities. Two oversize drawings encl Aperture cards are available in FDR VAN BRUNT.E. E. Arizona Public Service Co. 82/07/29 TEDESCO.R L. Assistant Director for Licensing. 13pp 14161 119 24X Fiche. 50-528, 82/07/29, 8208030650
- 820B160011 Forwards response to NRC 820510 hypothetical questions repostulated loss of essential spray pond spray nozzles dus to tornado missiles Util ratied on probabilistic risk assessment as response to BER Section 7 2 5
 VAN BRUNT.E.E. Arizona Public Service Co 82/08/06 NGVAK, T. H
 Assistant Director for Licensing 11pp 14344:352 24X
 Fichs 50-528,82/08/06,8208160011
- 8208090194 Generic Ltr 82~14 to all reactor licensess, holders of CP & applicants re submitted of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Bvc list enci EISENHUT, D. O Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Piche 50-000, 82/08/09, 8208090194
- 8208160092 Forwards proposed amended Section 6.2 6 of FBAR responding to NRC 820510 question relocal leak rate testing of certain valves using water in lieu of air or nitrogen Changes will be incorporated in future FBAR amend VAN BRUNTI E.E. Arizone Public Service Co. 82/08/11. NOVAK: T H Assistant Director for Licensing 12pp 14342 054 24% Fiche. 30~528: 82/08/11. 8208160092.
- 8208170190 Provides status rept of licensing & pre-fuel load activities Units acheduled for fuel load in Aug 1983 & 1984 & Nov 1985 Application to amend CP to reflect revised inservice dates forthcoming, Affidavit encl.

 VAN BRUNT, E.E. Aritona Public Service Co. 82/08/11 NQVAK, T H Assistant Director for Licensing. 3pp. 14366,285 24K

 Fiche 50-528,82/08/11.8208170190.

- 8208200205 Forwards supplemental info to licensee 820617 ltr re make-up capability to UHS Info includes Ertsc Western, Inc feasibility assessment for drilling & const of supplemental water supply well for UHS VAN BRUNT, E.E. Arizona Public Service Co. 82/08/12, NOVAK, T. H. Assistant Director for Licensing 12pp 14399 184 24X Fiche 50-528, 82/08/12, 8208200205
- 6208230053 Forwards responses to open items re B20803-06 pump & valve operability review team (PVDRT) audit
 VAN BRUNT.E E Arizona Public Service Co B2/08/19 NOVAK, T H
 Division of Licensing Bpp. 14517 169 24% Fiche 50-528,82/08/19,8208230053
- F Security, medical, emergency & fire protection plans
- 8208240262 Forwards Proof of Svc for Revision 2 to facility amergancy plan VAN URUNT, E Arizona Public Service Co 82/08/18 Office of Nuclear Reactor Regulation, Director 4pp 14527, 131 24X Fiche 50-528, 82/08/18, 8208240262
- G. Adjudicatory correspondence
- 820B020205 Forwards proposed initial decision in form of order, authorizing QL issuance, Certificate of Svc encl.
 BISCHOFF, C. A. Brell & Wilmer BISCHOFF, C. A. Joint Applicants-Palo Varde. 82/07/26 Docksting & Services Brench 99pp 14141 203, 24X Fichs 50-528, 82/07/26, 8208020205
- 820B02023& Repts on NRC investigation of allegations made by unnamed electrical worker. Several more interviews remain Rept will be completed by end of Aug DEWEY,L S Hearing Branch 3 82/07/29 LAZO,R M. COLE,R F. CALLIHAN.D Atomic Safety and Licensing Board Panel 2pp. 14152 052 24X Fiche 50-528,82/07/29,820B020202&
- 820803031i Answer opposing PL Hourihen 820716 motion for reconsideration of ASLB admission into evidence of Joint Applicants Exhibit DB Exhibit authenticated & cannot be excluded under hearsay objection W/Certificate of Bvc.

 818CHOFF, C. A Joint Applicants-Palo Verde BISCHOFF, C. A Bischoff, C A 82/07/27, Atomic Bafety and Licensing Board Panel. 14pp. 14157-192. 24% Fiche 50-528-82/07/27,8208030311
- 8208090003 Response opposing PL Hourihan motion for reconsideration of ABLB admission into evidence of Joint Applicants Exhibit DD Exhibit correctly entered into evidence meets reliability test & cross-examination was allowed W/Certificate of Bvc. DEWEY.L S Hearing Branch 3 82/08/05 Atomic Safety and Licensing Board Panel 12pp. 14270 048 R4X Fiche 50-528,82/08/05,8208090003
- B208120131 Requests distribution of encl RM Lezo B20810 memo to ABLB & parties. LAZO,R.M Atomic Befety and Licensing Board Panel B2/08/10 STUCKY, S. W. Docketing & Services Branch 1p. 14327.130 24X Fiche 50-528, 82/08/10, 8208120131.
- --8208120133 Forwards 820801 ltr containing allegation of faulty welds for appropriate action, investigation rept should be distributed to ASLB & parties 4/o enti LAZO, R M. Atomic Safety and Licensing Board Panel 82/08/10 FTIZOERALD, J A Office of Investigation ip 14327;131 24X Fiche 50-528, 82/08/10, 8208120131,
- 8208160062 Memorandum & order denying PL Hourihan 820621 petition for directed certification of two evidantiary rulings No reasons given why certification should be granted rather than appealing record to ASLAB LAZOR.M. Atomic 8afety and Licensing Board Panel, 82/08/12 Hourihan, P. 9pp 14342:027 24X Fiche 50-528,82/08/12,8208160062.
- 8208190116 Forwards proposed findings of fact & conclusions of law. BERNABEI.L Harmon & Waiss BERNABEI.L Hourthan, P. 82/08/13 Docketing & Services Branch. 1p 14381:195 24X Fiche:30-528.82/08/13,8208190116.
- --B208190159 Proposed findings of fact & conclusions of law.Cartificate of Svc encl.

 * Hourthan, P. 82/08/13 96pp 14381:176. 24X
 Fiche:50-528,82/08/13,8208190116.
- 8208200273 Notice of corrections to Joint Applicants 820726 proposed initial decision Certificate of Svc encl BIBCHOFF.C A. Joint Applicants-Palo Verde. BIBCHOFF.C A. Bischoff, C.A. 82708/16 30pp. 14378 293. 24X Fiche 50-528,82/08/16. 8208200273

- 8208240220 Hemorandum & order denying PL Hourihan 820716 motion for reconsideration of ASLB admission of Joint Applicants Exhibit DD into evidence Hearsay objection untimely LAZD,R M Atomic Safety and Licensing Board Panel 82/08/19 HGURIHAN,P L Hourihan, P 7pp 14521 104 24% Fichs 50-528,82/08/19,8208240220
- 8208260056 Proposed opinion, findings of fact, conclusions of law & order in form of initial decision Certificate of Svc encl DEMEY, L 8 Hearing Branch 3 82/08/23 105pp 14555 234 24X Fiche 50-526, 82/08/23, 8208260056

I Financial information

- 8208270375 Forwards Annual Financial Repts 1981 VAN BRUNT,E E Arizona Public Service Co 82/08/23 Office of Nuclear Reactor Regulation, Director 1p 14866 186 24X Fiche 30-528,82/08/23,8208270375
- --8205270378 Annual Financial Rept 1981 TURLEY.K L Arisona Public Service Co 82/02/25 36pp 14566 187 24% Fiche 50-528,82/08/23,8208270375
- --8208270384 Annual Financial Rept 1981 GEIST, J D , SCHREIBER, G A Public Service Co of New Mexico 82/08/23 39pp 14566 223 24% Fiche 50-528,82/08/23,8208270375
- --8208270388 Annual Financial Rept 1981 WALL, E.R. El Paso Electric Co. 82/08/23 44pp 14566 262 24x Fiche 50-528,82/08/23,8208270375
- --8208270378 Annual Financial Rept 1981 PFISTER.J Salt River Project 82/08/23 32pp 14566 347 24x Fiche 50-528.82/08/23.8208270375
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8208170169 Forwards Amend 9 to FSAR VAN BRUNT,E E Apizona Public Service Co 82/08/16 Office of Nuclear Reactor Regulation. Director 2pp 14367 274 24X Fiche 50-528.82/08/16.82/08/70168
- --8208170172 Amend 9 to FSAR Seventeen oversize Figures encl Aperture cards are available in FDR + Arizona Public Service Co 82/08/31 800pp 14367 278 24X Fiche 50-528.82/08/16.8208170148

Antitrust correspondence

1040102 Forwards draft OL antitrust review finding of no ignificent change for review & comment W/o encl UTBERO.J Hearing Branch 2 82/07/29 CUTLER.M Justice.Dept of p 14238 174 24% Fiche 50-528.82/07/29.8208060102

. Inspection reports, [E Bulletins & correspondence

- 9208270330 Forwards corrected response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp & Mytilus Sp " Presence of either species not found at facility VAN BRUNT.E E Arizona Public Service Co Bi/06/03 ENGELKEN.R Region 5. Ban Francisco. Office of the Director (81/03/01) 2pp 14565 114 24X Fiche 50-528.81/06/03.8208270330
- 3208240383 Bubmits corrected response to 1E Bulletin 81-02, "Failure of Gate Type Valves to Close Against Differential Pressure" No corrective actions required Approx 80 manhours expended in review VAN BRUNT.E E Arizona Public Service Co 81/07/07 ENCELKEN.R H Region 5. San Francisco, Office of the Director (81/03/01). 3pp 14524 341 24X Fiche 50-528.81/07/07.8208240383
- 8208240396 "Flow Interruption Test for Part 77910, Supplied to C-E" PATEL:B A , BRALEY, C , RIAZ, H Borg-Warner Corp 1843 RB 81/05/18 5pp 14524 345 24X Fiche 50-528, B1/07/07, 8208240383
-)8240144 Submits corrected copy of response to IE Bulletin 81-02, "Failure of Oate Type Valves to Close Against Differential "ressure "No sub, valves used in design.Approx 25 manhours typended in review

 N BRUNT.E.E Arizona Public Service Co 81/10/01 ENGELKEN.R gion 5, San Francisco. Office of the Director (81/03/01). 2pp 519 361 24% Fiche 50-528,81/10/01.8208240144

- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN-E L Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000,82/07/16,8204210393
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14398 001 24X Fiche 30-000, 82/07/19, 8204210375
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list encl JERDAN, E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000.82/07/20.8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From V Hexafluoride Overpacks" Svc list encl COBB, L. Division of Fuel Facilities, Materials & Bafeguards 82/07/20 Consolidate Edison Co of New York 7ipp 14357 276 24% Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-24, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14174 321 24X Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion Whils Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN E L Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24x Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " 8vc list encl JURDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RC9 Piping at Certain Westinghouse PWR Power Plants " Svc list encl, JORDAN,E L Division of Engineering & Quality Assurance Consolidated Edison Co. of New York 121pp 14397 013 24X Fiche 50-000, 92/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Syc list encl JORDATAEL Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche 50-000,82/07/28,8204210405
- 8208240285 Forwards IE Insp Repts 50-528/82-14,50-529/82-07 & 50-530/82-07 on 820503-0625 No noncompliance noted BISHOP.TU Division of Resident, Reactor Project & Engineering Programs 82/08/04 VAN SRUNT.E E Arizona Public Bervice Co. 2pp 14527 150 24% Fichs 50-528,82/08/04,8208240285
- --8208240291 IE Insp Repts 50-528/82-14.50-529/82-07 & 50-530/82-07 on 820503-0625 No noncompliance noted Major areas inspected, installation of RCPI & other safety-related piping in Unity I & 3 & followup of IOCFR50,55(e) items VDRDERBRUGOEN, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/08/03 dpp 14527,152 24X Fiche 50-528,82/08/04,8208240285
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl.
 JORDAN.E L Division of Engineering & Guality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388, 201 24X
 Fiche 50-000, 82/08/05, 8204210407
- 8208240277 Ack receipt of 820723 ltr informing NRC of steps taken to correct violations noted in 1E insp on 820329-0402 STERNBERO-D M Division of Resident. Reactor Project & Engineering Programs. 62/08/16 VAN BRUNTS E Arizona Public Service Co 1p. 14527 167 24X Fiche 50-528,82/08/16,8208240277
- --8208240287 Responds to NRC 820625 ltr re violations noted in IE insp on 820329-0402 Corrective actions NCR EA-1964 initiated 820402 to document nonconforming anchor bolts & retorque VAN BRUNT, E.E. Arizona Public Bervice Co 82/07/23 BISHOP, T W Region 5, Office of Director 10pp 14527 168 24X Fiche 50-528,82/08/16.8208240277

1

8208270322 Ack receipt of 820810 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-528/82-12, 30-529/82-06 & 90-530/82-06 BTERNBERO,D H Division of Resident, Reactor Project & Engineering Programs 82/08/20 VAN BRUNTIE Arizona Public Service Co ig 14565 073 24% Fiche 50-528,82/08/20,8208270325

R Periodic operating reports & related correspondence

8208110130 Forwards "Independent GA Evaluation," biweekly status rept for 820719-30 SIMON,W A Torrey Pines Technology 82/08/03 TURLEY,K L Arizona Public Service Co lp 14314 353 24X Fiche 50-528,82/08/03, 8208110130

--8208110133 "Independent GA Evaluation." biweekly status rept for B20719-30 * Torrey Pines Technology 82/08/03 Spp 14314-354 24X Fiche 50-528,82/08/03.8208110130

B20B310311 Forwards "Independent QA Evaluation of Palo Verde Nuclear Cenerating Btation.Units 1.2 & 3," Diweekly Status Rept 3 for period ending 820B13 BIMON.W A Torrey Pines Technology B2/08/20 TURLEY, K L Arizona Public Bervice Co 12pp 146B7 327 E4X Fiche 50-528.82/08/20. B20B310311

8 Reportable occurrences. LERs & related correspondence

8208080245 Final deficiency rept re safety-related instrument tubing clamps installed w/o locking devices on threaded fasteners initially reported on 920303. Design changes issued to have installed clamps corrected to comply w/ASME Code VAN BRUNT, E Arizona Public Service Co 82/07/23 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 3pp 14209-266 24X Fiche 50-528,82/07/23.8208050245

8208030418 Final deficiency rept re undertorquing of Joy éan blade locknuts in fuel bldg AFU by CTI-Nuclear Initially reported on 820602 Condition not reportable under 10CFR50 55(a) based on data provided by Joy Hfg Co VAN BRUNT.E E. Arizona Public Service Co 82/07/23 BISHOP.T U Division of Resident, Reactor Project & Engineering Programs 4p 14217 162 24X Fichs 50-530,82/07/23,8208050418

8208230301 Fourth interim deficiency rept re mating force of 125-volt dc pull-out fuse block decreasing after several insertions & removals Initially reported on 810521 Bechtel developing plans to replace fuse block Final rept excepted by 82103 VAN BRUNT, E E Arizona Public Service Co 82/08/10 BIGHOP, T W Division of Resident, Reactor Project & Engineering Programs. App 14510 324 24% Fiche 50-528,82/08/10,8208230301

8208240192 Interim Deficiency Rept DER 82-38 re Henry Pratt B-inch containment isolation valves w/loose actuator bolts & w/o specified torque Initially reported on 820713 Vendor to review & evaluate deficiency Final rept due on 821105 VAN BRUNT, E E Arizona Public Service Co 82/08/11 BI6HOP, T W Region 5, Office of Director 3pp 14521 261 24X Fiche 50-530,82/08/11.8208240192

T. Hearing transcripts on non-antitrust matters

8208040118 Proposed corrections to 820427-30.0525-28 & 0422-25 transcripts of hearing BISCHOFF, C A. Joint Applicants-Palo Verde BISCHOFF, C A. Snell & Wilmer 82/08/03 15pp 14238.273 24X Fiche.50-528,82/08/03,8208060118

DOCKET STN-50-531 GESSAR-251

A Application/construction stage documents & correspondence

8208070174 Generic Ltr 82-14 to mil reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarites IOCFR Chapter I requirements & provides alternatives to requirements. See list encl EISENHUT. D 0. Division of Licensing 82/08/09 Consolidated Edison Co. of New York ip 14356-332 24X Fiche: 50-000,82/08/09,82/08/0944.

O. Inspection reports. IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" 89c 11st encl JORDAN, E.L. Division of Engineering & Quality Assurance, 82/07/19 Hichigan, Univ. of 112pp 14358, OOI, 24X Fiche 50-000, 82/07/19, 8204210395

DOCKET STN-50-\$32 BRAUNBAR

- O Inspection reports: IE Bullatins & correspondence
- 8204210395 IE Info Notice 81-24, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl UDRDAM, E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358:001 24X Fiche 50-000, 82/07/19, 8204210395

DOCKET STN-50-535 GASSAR-4

- A Application/construction stage documents & correspondence
- 8208090194 Ceneric Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENHUT.D Q Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332, 24X Fiche 90-000.82/08/09, 8208090194
- Q Inspection reports. IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Syc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of. 112pp 14358:001 24X Fiche: 50-000.82/07/19,8204210395

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

- A Application/construction stage documents & correspondence
- 8206200003 FOIA request for five categories of documents re design of HX %/or steam generators for facility
 HATHAHAY. J Congress Watch UDELL.R. Critical Mass Energy Project 82/06/17 FEITON. J Division of Rules and Records. 2pp. 14528 177 24X Fiche 50-537.82/06/17.8206200003.
- 8206300099 Forwards 42 oversize piping fabrication isometric drawings for direct heat removal svc.in response to Question G8760 114 Aperture cands are available in PDR LONGENECKER, J Energy, Dept of 82/06/25 CHECK, P 8. Clinch River Breader Reactor Program Qffice 3pp 13655:293 24% Fiche 50-537,82/06/25,8206300099
- B20B230408 Responds to FOIA request for five categories of documents refacility No documents available subj to request.
 FELTON.J M Division of Rules and Records B2/07/15 HATHAHAY, J Congress Watch 1p 14528 176 24X Fiche. 50-337, B2/07/15, 820B230408
- 8208310485 Notification of contract execution, "Casework CRBR," awarded to 88A Subcontractor Engineering & Economics Research, Inc EDGEMORTH.# Technical Assistance Contracts Branch, FIN B-8601. 82/07/21 CHECK, P. 8 , MORRIS, B Clinch River Bresder Reactor Program Office 1p 14697:298 24X Fiche 50-537,82/07/21, 8208310485
- --820831048B Gontract "Casework -- CRBR," awarded to BBA Bubcontractor, Engineering & Economics Research, Inc. DENNIBTON, S. F. Bmell Business Administration MATTIA, M. J. Division of Contracts. FIN 8-8601 82/07/21, 14pp 14697; 297, 24X Fiche 50-537, 82/07/21, 8208310485
- B208020430 Notification of 820805 meeting w/DDE in Bethesdar ND to discuss CRBR PBAR Chapter 9.9. "Auxiliary Liquid Metal 8ys." Proposed agenda encl. BTARK.R.M Clinch River Breeder Reactor Program Office. 82/07/26. CHECK.P.S Clinch River Breeder Reactor Program Office 5pp. 14180.187. 24X Fichel50-537.82/07/26.8208020430
- 8208040457 Forwards ACRB 820713 rept re application for facility LWA. CHECK-P S Glinch River Breeder Reactor Program Office. 82/07/26 LONGENECKERJ Energy Dept. of, Clinch River Breeder Reactor Plant. 2pp. 14220;283. 24X Fiche 80-537,82/07/26.8208040457.
- --B20B040467 Summarizes ACRS 267th meeting on 82070B-10 rs NUREO-0786.

 "Bits Suitability Rept in Matter of CRBR " CRBR can be designed so as to present to greater risk than LMR Proposed site suitable.

 SHEMMON.P. ACRS Advisory Committee on Reactor Bafeguards B2/07/13. PALLADINO.N.J Commissioners. 2pp. 14220:285. 24X Fichs.50-537.82/07/26.820B040457.

- 8208020097 Application to amend application for CP & OL.consisting of Amend 69 to PSAR LONGENECKER. J Energy, Dept of, Clinch River Broader Reactor Plant HG S 82 072 82/07/30 CHECK, PS Clinch River Breader Reactor Program Office 4pp 14142 212 24X Fiche 50-537, 82/07/30, 820802097
- 8208030540 Forwards reply to Guestions C8 760 23.37,123,168,169,171,172 & 174 in response to 820430.0514 & 0609 requests for add1 info Responses will be incorporated into PSAR Amend 70 scheduled for submittal in late Aug LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant 82/07/30 CHECK, PB Clinch River Breeder Reactor Program Office 28pp [4162 328 24% Fiche 50-537,82/07/30,8208030540
- 8208170303 AN ORIGEN2 MODEL AND RESULTS FOR THE CLINCH RIVER BREEDER REACTOR
 REACTOR
 REGION A GAS Ridge National Laboratory FIN 8-0009
 NUREO/CR-2762 82/07/31 Division of Fuel Cycle & Material
 Safety 128pp Available at NTIS \$6 00 14372 138 24X
 Fiche 50-537,82/07/31.8208170303
- 8208040219 Forwards.for filing, applicant 820802 supplemental answers to Commission questions.
 SILVERBIRGNL Energy, Dept of 82/08/02 Office of the Secretary of the Commission ip 14188 182 24X
 Fiche: 50-537, 82/08/02, 8208040219
- --8208040224 Forwards supplemental responses to Cummission 820701 questions re applicant 10CFR50 12 request CHIPMAN, 0 L Energy, Dept of 82/08/02 PALLADIND, N J , OILLINSKY, V , ROBERTS. T F Commissioners 38pp 14188 183 24X Fiche 50-537,82/08/02.8208040219
- 8208060164 Forwards Revision 4 of CRBRP-3.Vol 2, "Hypothetical Core Disruptive Accident Considerations in CRBRP Assessment of Thermal Margin Beyond Design Base " LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/08/04 CRECK.P S Clinch River Breeder Reactor Program Office ip 14238 001 24X Fiche 50-537,82/08/04.8208060164
- --8208060167 "Hypothetical Core Disruptive Accident Considerations in CRBRP Assessment of Thermal Margin Beyond Design Base," Vol 2, Revision 4 Energy, Dept of, Clinch River Breeder Reactor Plant CRBRP~3 VO2 R04 B2/08/04 97pp 14238 002 24X Fiche 50-537, 82/08/04, 8208806164
- 8208130289 Requests on behalf of TVA.authorization to proceed w/limited const activities for CRBR.per 10CFR50 10(e) Request covers installation of foundation base mat & lower containment rings after completion of site preparation activities LONGENECKER.J Energy, Dept of 82/08/06 CHECK.P S. Clinch River Breeder Reactor Program Office 1p 14340 082 24X Fiche 50-537.82/08/06,6208130287
 - -8208130291 "Limited Canst Activities Rept "

 4 Energy, Dept of 82/08/31 98pp 14340-083 24x

 Fiche 50-537,82/08/06,8208130289
- 8208260435 Staff requirements memo re 820805 discussion & vote on DOE 820701 exemption request for CRBR Commission authorized issuance of order granting applicant request as applied to nonsafety-related site preparation activities.

 HOYLE, J C Office of the Secretary of the Commission 82/08/06 BICKHITL. Office of the Jeneral Counsel to 14579 228 24X Fiche 50-537,82/08/06,8208260435
- 8208090194 Oeneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of Socuments to NRC Bummarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl FISENMUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York Ip 14356.332 24X Fiche 50-000,82/08/09,8208090194
- 8208190371 Notification of 620817 meeting w/DOE in Bethesda, MD to discuss thermal margin design basis Agenda encl.

 STARK, R M Clinch River Breeder Roactor Program Office 62/08/10 CHECK, P S. Clinch River Breeder Reactor Program Office 4pp 14504:147 24X Fiche: 50-537, 82/08/10, 8208190371
- 8208230264 Application for amend to application for CP & GL.consisting of Amend 70 to PBAR
 LONGENECKER, J Energy, Dept of, Clinch River Broader Reactor Plant \$2/08/20 GHECK.PS Clinch River Breader Reactor Program Office 4pp 14518 001 24X Fiche 50-537.82/08/20.8208230264.

- ## 8208310312 Forwards responses to NRC Questions CS 421 24,35 % 52 % C8 760 148.149 % 173.per ## 820409 % 0514 requests Responses will be incorporated into PSAR Amend 71 CONGENECKER, U Energy, Dept of ## 8208126 CHECK, P.S. Clinch River Breeder Reactor Program Office 12pp 14687 315 24X Fiche 50-537.82/08/26,8208310312
- B Utility Preliminary Safety Analysis Report, amends
- 8208020097 Application to amend application for CP & OL, consisting of Amend 69 to PSAR
 LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
 HQ S 82 072 82/07/30 CHECK, P 6 Clinch River Breeder Reactor
 Program Office 4pp 14142 212 24X Fiche 50-537, 82/07/30,
 8208020097
- --8208020101 Amend 69 to PSAR

 4 Energy, Dept of, Clinch River Breeder Reactor Plant 82/07/31
 594pp 14142 216 24X Fiche 50-537,82/07/30,8208020097
- 8208090141 Page replacement guide for Amend 49 to PSAR

 * Energy, Dept of, Clinch River Breeder Reactor Plant
 1p 14271 308 24X Fiche 30-537, 82/07/30, 8208090141
- B208110103 Forwards affidavit confirming distribution of Amend 69 to PSAR LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant B2/08/06 DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp 14314 362 24X Fiche 50-537, B2/08/06, B208110103
- B20B230264 Application for amend to application for CP & DL:consisting of Amend 70 to PBAR LONGENECKER. J Energy. Dept of, Clinch River Breeder Reactor Plant B2/0B/20 CHECK. PB Clinch River Breeder Reactor Program Office 4pp 14511 001 24% Fiche 50-537. B2/0B/20:820B230264
- --8208230267 Amend 70 to PSAR LONGENECKER.J Energy Dept of Clinch River Breeder Reactor Plant 82/08/31 500pp 14511 GO5 24X Fiche 50-537,82/08/20, 8208230264
- B208310208 Forwards affidavit confirming distribution of Amend 70 to CRBR PBAR LONDENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant 82/08/26. DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp 14693 157 24X Fiche 50-937.82/08/26.8208310208
- C Utility Environmental Report (ER), amends & correspondence
- B208080309 Forwards affidavit confirming distribution of environ rept Amend 15 to designated local public officials & representatives of govt agencies LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant B2/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 14211 188 24X Fiche 50-537,82/08/02,8208050309
- D NRG Draft/Final Environmental Statements, supple & correspondence
- 8208030071 Ack receipt of 820621 ltr re changes that have occurred since issuance of 1977 CRBR FES Results of assessment of changes will be documented in rept scheduled for future issuance
 CHECK.P S Clinch River Breeder Reactor Program Office 82/07/18
 ARRHEIN.L. Wisconsin's Environmental Decade 1p 14198 361 2: Fiche 90-537, 82/07/13, 8208030071
- --8208030074 Urges issuance of suppl to 1977 FEB incorporating new info re plant design & recent regulations AMRHEIN.L Wisconsin's Environmental Decade 82/06/21 PALLADING.N Commissioners. ip 14198 362 24X Fithe 50-537, 82/07/15, 8208030071
- 820B030742 Ack receipt of 820611 ltr re recent changes in CRIR FEB (NUREO-0139) issued Feb 1977 Ongoing assessment since Fall 1981 will be documented in rept soon to be issued Rept will be forwarded when available CHECK.P.S. Clinch River Breeder Reactor Program Office 82/07/15 PALMER, C. Audubon Spciety ip 14195 358 24X Fiche 50-537, 82/07/15,820B030742
- --820B030744 Urges NRC meet responsibility under NEPA & issue suppl to 1977 FEB for CRBR Lack of suppl would deny public opportunity to comment on revived project PALMER, C. GROGAN, E M Audubon Society 82/06/11 PALLADINO, N Commissioners, 2pp 14195 359 24X Fiche. 80-537, 82/07/15, 8208030742

1

- 8208030747 Ack receipt of 820612 ltr re recent changes in CRBR FES (NUREO-0139) issued Feb 1977 Ongoing assessment since Fall 1981 will be documented in rept soon to be issued Rept will be forwarded when available CHECK-P S Clinch River Broeder Reactor Program Office 82/07/13 FREY.D 0 Sassefres Audubon Society ip 14195 361 24X Fiche 50-537, 82/07/15, 8208030747
- --8208030748 Requests NRC issue draft suppl to 1977 CRER FES & circulate suppl for public comment FREY,D 0 Sassafras Audubon Society 82/06/12 PALLADING,N Commissioners ip 14195 362 24% Fiche 50-537,82/07/15,8208030747
- 8208030751 Ack receipt of 820614 ltr re recent changes in CRBR FE8 (NVREO-0139) issued Feb 1977 Ongoing assessment since Fall 1981 will be documented in rept soon to be issued Rept will be forwarded when available CHECK.P S Clinch River Breeder Reactor Program Office 82/07/18 FOOTE.V Center for Davelopment Policy 19 14196 352 24X Fiche 50-537,82/07/15,8208030751
- --B208030752 Requests NRC issue draft suppl to FEB for public comment FOOTE.V Center for Development Policy 82/06/14 PALLADINO, N Commissioners 1p 14176 353 24X Fiche 50-537, B2/07/15, B208030751
- 8208040037 Ack recaipt of 820611 ltr re changes in CRBR since FEB issuance in Feb 1977 Assessment of ongoing changes will be documented in rept soon to be issued.
 CHECK.P 8 Clinch River Breeder Reactor Program Office 82/07/15, JENKINS:M Affilation Unknown 2pp 14236 046 24X Fiche 50-537,82/07/15,8208040037
- -B208040041 Requests NRC prepare & issue draft supplied CRBR FEB for public comments
 JENKINS,M Affiliation Unknown 82/06/11 FALLADING,N
 Commissioners 2pp 14236 047 24X Fiche 50-537,82/07/15,8208040037
- 8208040045 Ack receipt of 820614 ltr re changes in CRBR since FEB issuance in Feb 1977 Assessment of ongoing change will be documented in rept soon to be issued CHECK,P S Clinch River Breeder Reactor Program Office 82/07/15 LEVENTHAL,P Nuclear Club, Inc., The. ip. 14232 358 24X Fiche 50-537,82/07/15,8208040045
- --8208040048 Urges NRC to issue revised FE8 on CRBR for public comment LEVENTHAL,P Nuclear Club. Inc., The 82/06/14 PALLADINO,N Commissioners Ip 14232 359 24X Fiche. 50-537,82/07/15,8208040045
- 8208040074 Ack receipt of 820408 ltr re changes occurring since 1977 FES (NUREG-0139) issued Results of assessment of changes to be issued in upcoming rept CHECK.P S. Clinch River Breeder Reactor Program Office 82/07/15 MILLAR.F. Environmental Policy Institute 1p, 14228,289 24% Fiche 50-537,82/07/15,8208040074
- --8208040080 Requests draft suppl to 1977 FES be issued MILLAR.F Environmental Policy Inetitute 82/06/08 PALLADING.N J Commissioners ip 14228 270. 24X Fiche 50-537.82/07/15.8208040074
- 8208040086 Ack receipt of 820511 ltr re changes occurring since 1977 FES (NUREO-0139) issued Results of assessment of changes to be issued soon CHECK.P.B Clinch River Breeder Reactor Program Office 82/07/15. SIMKIN.Y Affiliation Unknown ip 14228.327 24X Fiche 30-537.82/07/15.8208040086
- --8208040089 Urges draft suppl to 1977 FEB be issued SIMKIN.Y, BIMKIN.M. Affiliation Unknown 82/06/11 PALLADING,N.J Commissioners ip 14228 328 24X Fiche 50-537,82/07/15.8208040086
- 8208040092 Ack receipt of 820701 1tr re changes occurring since 1977 FEB (NUREO-0139) issued Results of assessment of changes to be issued toon CHECK-P 8. Clinch River Breeder Reactor Program Office 82/07/15 ADLER, B. Americans for Democratic Action 1p 14228, 331 24X Fiche: 50-537, 82/07/15, 8208040092.
- --B208040095 Urgss 1977 FEB be updated ADLER, B Americans for Democratic Action. 82/07/01 PALLADING, N J Commissioners ip 14228.332 24X Fiche 50-537, 82/07/15, 8208040092

- 8208040102 Responds to 820624 ltr re changes occurring since 1977 FE8 (NUREG-0139) issued Results of assessment of changes since 1977 rept to be issued in rept soon CHECK.P 6 Clinch River Breeder Reactor Program Office 82/07/15. HATHAWAY.J 8 Affiliation Untnown 1p 14229 299 24X Fiche 50-537.82/07/15.8208040102
- --9208040105 Opines that 1977 FES should be updated HATHAWAY. J B Affiliation Unknown 82/05/24 PALLADINO.N J. Commissioners ip 14229 300. 24% Fiche 50-537,82/07/15,8208040102
- 8208040112 Ack receipt of B20607 ltr re changes that have occurred since 1977 FEB (NUREG-0139) issued Changes since rept will be assessed & results documented in soon to be issued rept CHECK.P B Clinch River Breeder Reactor Program Dffice 82/07/15. SEITZ.J Affiliation Unknown ip 14236 310. 24X Fiche 50-537, 82/07/15, 8208040112
- --8208040114 Opposes licensing plant w/o updating 1977 FES SEITZ.J Affiliation Unknown 82/06/09 PALLADINO.N J Commissioners ip 14236 311 24X Fiche 50-537.82/07/15. 8208040112
- 8208040118 Respends to recent itr re changes since 1977 FEB
 (NUREG-0139) issued Changes since rept will be assessed &
 results documented in soon to be issued rept
 CHECK,P 8 Clinch River Breefer Reactor Program Office 82/07/15.
 WARNEKE,B Affiliation Unknown ip. 14236:312 24X
 Fiche 50-537,82/07/15,8208040118
- --8208040122 Expresses concern over NRC failure to suppl 1777 FEB HARNEKE, B Affiliation Unknown 82/04/14. PALLADINO, N J Commissioners. 2pp 14236 313 24X Fiche: 50-537, 82/07/15. 8208040118.
- 8208040127 Ack receipt of 820614 ltr re changes which occurred since FES (NUREG-0139) issued in Feb 1977 Changes since rept will be assessed & results documented in soon to be issued rept CHECK.P 8 Clinch River Breeder Reactor Program Office. 82/07/15 PREBENT.A Affiliation Unknown ip 14236 359 24% Fiche: 30-837.82/07/15,8208040127
- --8208040134 Urges no license be issued until 1977 FEB updated. PRESENT.A Affiliation Untnown 82/06/14. PALLADING.N J Commissioners. 2pp. 14236 360 24X Fiche:50-537.82/07/15.
- 9208040440 Ack receipt of 920618 ltr re changes in CRBR FEB since Feb 1977 issuance Assessment of ongoing changes will be addressed in rept soon to be issued CHECK.P 8 Clinch River Breeder Reactor Program Office. 82/07/15 KEPFORD.C Affiliation Unknown 1p 14220-190 24X Fiche 50-537,82/07/15,8208040440
- --B20B040447 Upposes further development of CRBR as needless extravagance in face of declining demand for electric power Supplemental FEB should be issued for public comment KEPFORD. C. Affiliation Unknown 62/06/18 PALLADING.N J Commissioners 6pp. 14220,171 24X Fiche: 50-537, 82/07/15, 82/07/16
- 8208040494 Ark receipt of 820507 ltr re changes in CRBR FES issued in Feb 1977 Ongoing assessment will be documented in soon to be issued rept.Rept will be forwarded when available CHECK.P.S Clinch River Breader Reactor Program Office 82/07/15 KCLLEY.F Affiliation Unknown ip 14220.281 24X Fiche: 30-537, 82/07/15, 8208040454.
- --B20B040456 Urgss issuance of draft suppl to FES for CRBR for public comment KELLEY, F. Affiliation Unknown. 82/06/07. PALLADIND, N Commissioners ip 14220-282 R20B040454
- 8208040462 Ack receipt of updated ltr re changes in CRBR FEB issued in Feb 1977 Ungoing assessment will be documented in rept scheduled for issue in near future Rept will be forwarded when available CHECK.P 8 Clinch River Breeder Reactor Program Office, 82/07/15, MESERVE.M. Affiliation Unknown 1p 14220*287. 24X Fichs 50-537, 82/07/15.8208040462
- --B208040463 Urges issuance of suppl to FES for CRBR MESERVE,M. Affiliation Unknown. B2/07/27 NRC - No Detailed Affiliation Given. ip. 14220 288 24X Fiche: 50-537, 82/07/15, 8208040462

- B20B090015 Ack receipt of B20612 ltr re recent changes in CRBR FEB (NUREG-0139) issued Feb 1977 Ongoing assessment since Fall 1981 will be documented in rept soon to be issued Rept will be forwarded when available CHECK.P.B Clinch River Breeder Reactor Program Office B2/07/15 KINANCR J Environmental Action.Inc ip 14283 350 24X Fiche 50-537,82/07/15,8208090015
- --8208070018 Requests NRC issue draft suppl to FEB for public comment KINANE.R J., HOZORE.E Environmental Action.Inc 82/04/12 PALLADING.N Commissioners ip 14283 351. 24X Fiche: 50-537, 82/07/15, 820897015
- 8208110043 Ack receipt of 820613 ltr re recent changes in CRBR FE8 (NUREO-0139) issued Feb 1977 (Ingoing assessment since Fall 1981 will be documented in rept soon to be issued Rept will be forwarded when available.

 CMECKLP 8. Clinch River Breeder Reactor Program Office 82/07/15. FORT.M D Affiliation Unknown. Ip 14330 305 24X Fiche. 50-537, 82/07/15, 8208110043.
- --8208110045 Requests NRC issue fraft suppl to FES for public comment. FORT:M D Affiliation Unknown. 82/06/13 PALLADINO.N J Commissioners Ip 14330 306 24X Fiche 50-537.82/07/15, 8208110043.
- 8208110232 Ark receipt of undated ltr re recent changes in CRBR FE8 (NUREO-0139) issued in Feb 1977 Ongoing assessment since Fe11 1981 will be documented in rept soon to be issued, Rept will be forwarded when available CHECK, P. B. Clinch River Breeder Reactor Program Office 82/07/15 KEATING.R. Affilstion Unknown, ip. 14330:313 24X Fiche: 50-537, 82/07/15, 8208110232
- --8208110235 Criticizes nuclear waste, CRBR & nuclear weepons Draft suppl to facility FES should be issued for comment, KEATINO, R. Affiliation Unknown 82/07/02. PALLADING, N J Commissioners ip 14330-314 24X Fiche: 50-537, 82/07/15, 8208110232
- 8208020431 Responds to recent postcard re changes since 1977 FES (NUREO-0139) issued. Results of assessment of changes to be issued shortly CHECK, P.S. Clinch River Breeder Reactor Program Office 82/07/19 EDDLEHAN, H. Affiliation Unknown 1p. 14178.033 24X Fiche 50-537, 82/07/19, 8208020431.
- --8208020434 Urges NRC issue Graft suppl to 1977 FEB EDDLEMAN,W Affiliation Unknown 82/07/02 PALLADING,N J. Commissioners ip 14178 034 24X Fiche 50-537,82/07/19, 8208020431
 - D8040266 Responds to 820707 ltr re NRC environ assessment of site Results of assessment of changes since 1977 FEG issued to be published shortly Director for Operations 32/07/21 HENDON B House of Rep 3pp 14225 356 24% Fiche 50-537, 82/07/21, 8208040266
- -820627003B Forwards constituent R Felk request that NRC issue draft suppl to 1977 FEB Info requested HENDGN, B. House of Rep. 82/07/07 HENDRIE, J. M. Commissioners 2pp. 14225, 339. 24X Fiche, 50-537, 82/07/21, 8208040266
- 1208050065 Ack receipt of ltr concerning changes that have occurred since CRBR FEB (NUREO-0139) was issued Results of assessment of changes documented in draft suppl to NUREO-0139. DIRCKS.N J. Office of the Executive Director for Operations 82/07/27, GREENBURG.P A California, State of. 2pp. 14242-081 24X Fiche: 50-937.82/07/27, 8208050065
- --8207050009 Requests temporary delay to schedule set for licensing of CRBR. Delay necessary to update 1977 EIB OREENSERO.P A. California, State of 82/07/09 DIRCKB.W J. Office of the Executive Director for Operations 2pp 14242-083 24X Fiche: 50-537.82/07/27.8208050065
- 3208050250 Verifies official filing of CRBR EIS, draft suppl (MVREO-0139). FR notice of availability scheduled for publication on 820730 Public review period scheduled to terminate on 820743.

 HILSON, K. L. Environmental Protection Agency, 82/07/28 LEECH, P. H. Glinch River Breeder Reactor Program Office, 1p, 14209, 329, 24% Ficher 50-537, 82/07/28, 8208050250
- 1208100051 Advises of review of draft suppl to FES for CRBR. No comments offered at this time.

 NEELIA H. East Tennessee Development District 82/08/06.

 CHECK.P.B. Clinch River Breeder Reactor Program Diffice ip 14276: 241. 24X Fiche. 50-537, 82/08/06, 8208100051.

- 8208300243 Comments on draft suppl to FES re const & operation of facility NRC should recommend project be canceled due to need & cost considerations
 FREY.D & Sassafras Auduban Society 82/08/17 Office of Nuclear Reactor Regulation. Director. 20p 14679 067 24X
 Fiche 50-537,82/08/17,8208300243
- F Security, medical, emergency & fire protection plans
- 8208030313 Forwards addi info in response to Questions CB 810 1 through 810 16 re emergency planning in NRC 820514 ltr Info will be incorporated in future PSAR amend One oversize drawing encl Aperture card is available in PDR LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/07/28 CHECK, PS Clinch River Breeder Reactor Program Office 41pp 14161 072 24X Fiche 50-537,82/07/28.8208030313
- O Adjudicatory correspondence
- 8208190131 Hemorandum CLI-82-8A holding that author participation in decision on reconsideration of Commission 820316 order denying DGE exemption request will not create appearance of 6 tas or of foregone conclusion ABSEL
- 8208190129 Order CLI-82-8 denying DDE 820314 request for reconsideration of Commission 820316 order denying DDE request for exemption for site preparation activities commissioner Asselstine separate statement encl CHILK, 8 J Office of the Secretary of the Commission 62/05/18 5pp 14381:073 24X Fiche 50-537,82/05/18,8208190129
- 8208070020 Staff requirements memo re 820721 affirmation/discussion assion approving order directing DDE to respond by 820728 to allegations in petition for investigation, filed by NRDC on Sierra Club CHILK.8 J. Office of the Secretary of the Commission 82/07/26 Office of the Secretary of the Commission ip 14283 355 24X Fiche 50-537,82/07/26,8208070020
- 8208020215 Record of decision holding that planned LMFBR program described in FES should be pursued including GRBR plant BREMER, S T Energy, Dept of 82/07/28 12pp 14141 069 24X Fiche: 50-537, 82/07/28, 8208020215
- 8208020249 Advises that pleading that was to be filed on 820728 will be filed on 820729 will be filed on 820729 WEISB.E R: FINAMORE, B A Natural Resources Defense Council WEISB.E R Sierra Club 82/07/28 LINENBERGER, G Atomic Bafety and Licensing Board Panel 2pp 14152, 227 24X Fichs 50-537, 82/07/28, 8208020249
- 8208020300 Confirms 820713 & 28 conversations re intervenor 820628 motion to compel discovery on Interrogatory 27 in 820604 nineteenth set of interrogatories FINAMORE,8 A Natural Resources Defense Council 82/07/28. ED0AR.9 L Horgan, Lewis & Bocklus, 2pp 14151 133 24X Fiche 50-537.82/07/28.8208020300
- 8208030318 Requests to make written limited appearance statement on behalf of Environ Law Project READ,D F. Affiliation Unknown 82/07/28 Office of the Sacretary of the Commission 1p 14157 125 24X Fichs 50-537,82/07/28, 8208030318
- 8208030328 Summarizes 820727 telcon w/NRDC, NRC & Project Mgt Corp re hearing schedule Conference to be held on 820802 in Bathesda, MD to confirm ASLB decision on whether hearing will proceed per schedule set in ASLB 820719 order LINEMBERGER, G. Atomic Sefety and Licensing Board Panel 82/07/28 FINAMORE, B A Natural Resources Defense Council EDGAR, G L Morgan, Lewis & Bockius HAND, C H Atomic Sefety and Licensing Board Panel. 3pp 14156 320 24X Fiche 50-537, 82/07/28, 8208030328
- 8208160001 Forwards revised CRBR rept, initially submitted on 820722 REMICK, F.J. NRC No Detailed Affiliation Given 82/07/28 PALLADINO, N.J., GILINEKY, V., AHEARNE, J. F. Commissioners 58pp 14370:083 24% Fiche: 50-537, 82/07/28, 8208140001
- --8208160002 Order establishing procedures for consideration of merits of applicant 820701 IOGFR50 12 exemption request Request will be considered in informal proceeding involving written comments
 CHILK,8 J Office of the Secretary of the Commission 82/07/09
 4pp 14370 197, 24X Fichs 50-537.82/07/28.8208160001

1

--8208i60003 Transcript of 820729 oral presentation on CRBR. Pp 1-213 ** Commissioners 82/07/29, 215pp 14370 201 24X Fich* 50-537,82/07/28,8208160001

- 8208020052 Forwards NUREG-0139, "Draft Suppl to FES " Copies being provided to parties W/o encl JONES, B W Hearing Branch 1 82/07/29 MILLER, M , LINENBERGER, G., HAND, C H Atomic Safety and Licensing Board Panel 1p 14144 129 24X Fiche 50-537,82/07/29,8208020052
- 8208020207 Motion to reconsider ASLB 820422 rulings on Contentions 1-3 in hight of new additions to NRC case represented by draft FES Intervenors should be permitted to commence discovery & litigate contentions Certificate of Svc encl FINAMORE, B A . WEISB.E R Natural Resources Defense Council FINAMORE, B A Sierra Club 82/07/29 Atomic Bafety and Licensing Board Panel 17pp 14141 182 24X Fiche 50-537.82/07/29, 8208020207
- 8208020296 Outlines administration policy toward cooperation w/foreign countries in breeder R&D & how domestic policies & actions could impinge upon cooperation KENNEDY, R T State, Dept of 82/07/29 DAVIS, W K Energy, Dept of 1p 14152:027 24X Fiche 50-537, 82/07/29, 8208020296
- 8208030321 Confirms 820728 & 29 telcons advising of delivery delays of two pleadings Inappropriate for NRDC to communicate privately w/ABLB member LINENBERGER O Atomic Safety and Licensing Board Panel 82/07/29 FINAMORE, B Natural Resources Defense Council ip 14:56 310 24x Fiche 30-537.82/07/29,8208030321
- 8208030095 Response to applicant 820726 motion to enforce hearing schedule & NRDC 820728 motion to reschedule hearings LWA-1 hearings should continue per schedule in 820211 order for all perties except NRC Certificate of Svc encl JONES, B W Hearing Branch 1 82/07/30 Atomic Bafety and Licensing Board Panel Tipp 14160 061 24X Fiche 50-537.82/07/30, 8208030095
- 8208030362 Informs that Davis-Besse case provides no authority for proceeding today w/project in preconst stage GREENBERG, E.V. Natural Resources Defense Council 82/08/02, PALLADING, N. J., GILINSKY, V., ROBERTS, T.F. Commissioners 4pp. 14157-102-24X Fichs 50-537, 82/08/02, 8208030362
- B20B040219 Forwards for filing applicant 820B02 supplemental enswers to Commission questions
 SELVERSTROML Energy Dept of 82/08/02 Office of the Secretary of the Commission in 14188 182 24X
 Fiche 50-537, 82/08/02, 8208040219
- --8208040224 Forwards supplemental responses to Commission 820701 questions re applicant 10CFR50 12 request CHIPMAN.0 L Energy, Dept. of. 82/08/02 PALLADINO.N J. GILINGKY, V. ROBERTEI, T.F. Commissioners 38pp 14188:183 24X Fiche 50-537.82/08/02,8208040219
- 8208050352 Opines that small increase in CRBR efficiency that might result from granting exemption request does not justify extraordinary relief from NRC licensing process OREENBERO, E V , FINAMORE, B A Natural Resources Defense Council. GREENBERO, E V : GINTER CLUB 62/08/03 PALLADING, N J. , OILINBRY, V , ROBERTS, T F Commissioners 5pp 14237.273, 24X Fiche 50-537,82/08/03,8208050352
- B208110143 Requests to make limited appearance statement at B20823 hearing.
 BATES, A. Affiliation Unknown B2/08/03 CHILK, B. J. Office of the Secretary of the Commission 1p 14314:304 24X Fiche 30-537, 82/08/03, 8208110143.
- 8208050367 Upines that rationals expressed in applicant post-hearing ltr unpersuasive to grant exemption request Applicants confuse total informational benefits to LDP w/marginal benefits of 6-month shift in schedule FADEN.M E Union of Concerned Scientists. 82/08/04, PALLADIND.N J , 0ILINSKY,V , ROBERTB, T F Commissioners. 2pp 14209-140. 24x Fiche 50-537,82/08/04,8208050369
- 8208050378 Demands summary denial of applicant exemption request or alternatively, requests adjudicatory hearing be ruled upon before decision on applicant request made MEISB.E R., FINAMURE, B.A., Natural Resources Defense Council, REISB.E R. Sierra Club 82/08/04 PALLADING, N.J., GILINSKY, V., ROBERTS, T.F. Commissioners. App. 14209-168, 24X Fiche: 50-537, 82/08/04, 8208050378.
- B208060136 Comments on applicability of NEPA to DOE 10CFR50.12 exemption request to conduct site preparation work for CRBR. Consideration of request appropriate despite NRC decision to suppl EIB HILL: A.A. Council on Environmental Quality, 82/08/04. EDWARDS, J.B. Energy, Dept of Ip 14241.270 24X Fiche: 50-537,62/08/04. 8208060136

- 8208060181 Forwards corrected 820722 answer to Commission 820712 Question 5 re site preparation activities LUCK.W D Energy, Dept of 82/08/04 PALLADING.N J , GILINBKY,V , RDBERTS.T F Commissioners 6pp 14239 040 24X Fichs 50-537,82/08/04.8208060181
- 8208130167 Forwards notice of appearance in CRBR proceeding Certificate of 8vc encl LUCK, M D Energy, Dept of 82/08/04 MILLER, M , LINENBERGER, Q , HAND, C H Atomic Bafety and Licensing Board Panel, 5pp. 14338-304 24X Fiche 50-537, 82/08/04, 8208130167
- 8208090262 Order following B20802 conference w/parties in Bethesda.MD Hearing will commence on B20823 in Dak Ridge, TN & will be limited to listed site suitability contentions Bome LMA-1 issues may be heard prior to issuence of final FEB suppl. MILLER.ME Atomic Bafety and Licensing Board Panel 82/08/05 7pp 14270:334 24X Fiche 50-537,82/08/05,8208090262.
- 820B1000B5 Forwards completion of NRC answers to NRDC twenty-sixth set of interrogatories Addl response to Interrogatory IV 23 enc!

 JONES, B W Hearing Branch 1 82/08/05 FINAMORE, B A Natural Resources Defense Council 1p. 14277*252. 24X
 Fiche 50-537, 82/08/05, 820B1000B5
- 8208090153 Application for stay of Commission 820805 decision under IOCFR50 12 authorizing conduct of site preparation activities Issues of first impression will be presented to Court of Appeals Certificate of 8vc encl.

 ORECNBERO.E V , FINAMORE B. A Natural Resources Defense Council ORECNBERO.E V , Sierra Club 82/08/06 Commissioners. 11pp 14271:328 24X Fiche 50-537.82/08/96,82080970153
- 8208110146 Requests to make limited appearance statement at \$20823 hearing
 THOMAS.J Z. Affiliation Unknown
 Secretary of the Commission 19
 Fiche. 50-537, 82/08/06, 8208110146.
- 8208110190 Supplemental responses to eighteenth, nineteenth & first set of interrogatories re listed contentions & to requests for identification of ultnesses Certificate of Svc & affidavits encl Related correspondence EDOAR, O. L. Project Management Corp EDOAR, O. L. Edgar, O. L. EDOAR, O. L. Tennesses Valley Authority 82/08/06 Natural Resources Defense Council 41pp. 14314:038 24X Fiche: 50-537, 82/08/06, 8208110190
- 820Bi30188 Clarifies previous response to ABLB inquiries re computer codes used in review of site suitability.atmospheric transport & diffusion calculations SHANSQN.D.T Hearing Branch 1. 82/08/06. MILLER.H., HAND.C.H., LINENBERGER.O Atomic Safety and Licensing Board Panel 2pp 14338.280 24X Fichs.50-537,82/08/06,8208130188
- 8208110144 Requests to make limited appearance statement at 820823 hearing FORT. M D Affiliation Unknown 82/08/09. Office of the Bacretary of the Commission. Ip 14314 303 24X Fiche 50-537, 82/08/09, 820810144
- 820Bil0159 Petition for directed certification of Commission B20B05 decision to authorize commencement of site preparation Hashing of 10CFR2.761e prohibits commencement of LHA evidentiary hearing prior to FEB issuance.

 WEI8B.E R. FINAMORE.B.A. Natural Resources Defense Council HEI8B.E R. Sierre Club 82/08/09 Atomic Bafety and Licensing Appeal Panel 21pp 14313 275 24X Fiche 50-337.82/08/09, 8208110159
- 820Bi10160 Motion apposing NRDC & Sierra Club request for stay of Commission 820B05 decision authorizing commencement of site preparation activities NRDC remedy must reside in courts not NRC. Cartificate of SVC encl EDOAR, O. L. Project Management Corp. SILVERSTRON, L. Energy, Dept. of EDOAR, Q. L. Edgar, Q. B2/08/09, Commissioners lipp. 14314:227 24X Fiche. 50-537.82/08/09.820B110160.
- 8208120093 Supplemental answers to applicant fourth set of interrogatories Certificate of Svc encl.

 WEISB, E.R. FINAMORE, B.A. Naturel Resources Defense Council.

 WEISB, E.R. Sierra Club 82/08/11. Joint Applicants-Clinch River
 Breeder Reactor, App. 14327:146. 24X Fiche: 50-537, 82/08/11.

- 8208170267 Requests to make limited appearance statement at 820823 meeting in Oak Ridge, TN CLESSCH, E E Affiliation Unknown 82/08/11 Office of the Secretary of the Commission 1p 14367 136 24% Fiche 50-537, 82/08/11,8208170267
- 8208130177 Memorandum & Order CLI-92-22 denying NRDC & Sierra Club 820714 petition for investigation based on applicant 770406 & 0527 memos Serious allegations u/o foundation CHILK-S J Office of the Secretary of the Commission 82/08/12 Natural Resources Defense Council 1ipp. 14333.114 24X Fiche: 50-537.82/08/12,8208130177
- 8208160146 Forwards affidavits of contributors to NRC supplemental answers to NRDC & Sierra Club 820707 twenty-sixth set of interrogatories C Allen 820810 affidavit should replace 820727 version
 - SWANSON: D T. Hearing Branch 1 82/08/12 FINAMORE, B A , WEISS, E R Natural Resources Defense Council, 7pp 14345 124 24X Fiche, 50-537, 82/08/12, 8208160146
- 6208160421 Notice of ASLAB reconstitution SF Ellperin, chairman & MR Johnson & 0J Edlas, members SHOEMAHER: C J Atomic Safety and Licensing Appeal Panel 82/08/12 ip. 14348 166 24% Fiche 50-537,82/08/12.8208160421.
- 8208170327 Forwards statements of qualifications for applicant intended witnesses as identified in supplemental discovery response Centificate of Svc encl.

 EDGAR, O L. Horgan, Lewis & Bockius 82/08/13 FINAMORE, B A Natural Resources Defense Council 16pp. 14366 349 24% Fiche 50-537, 82/08/13, 82/08170327
- 820B18000B Memorandum & Order CLI-82-23 granting joint applicants request for exemption from IOCFR50 12 in part (re nonsafety-related site preparation activities) & denying in part (re safety-related activities). Add commissioner views encl. CHILK, S. J. Office of the Secretary of the Commission. 82/08/17 Joint Applicants-Clinch River Breeder Reactor 57pp 14976-236 24X Fiche 50-537,82/08/17.8208180008
- 8208200283 Response apposing NRDC/Sierra Club 820807 patition for directed certification Patition for review of interlocutory evidentiary ruling improper Patition fails to meet stds required for stay Certificate of Svc encl. EDOAR, Q L Project Hanagement Corp LUCK, H D Energy, Dept. of, 82/08/19 Atomic 8afety and Licensing Appeal Panel 30pp 14399.053. 24X Fiche 50-537,82/08/19,8208200283
 - B240271 Response opposing NRDC/Sierra Club B20807 petition for frected cartification of two questions Intervenors failed o establish irreparable harm or that ASLB order affects rocseding in parvasive manner Certificate of Eve anci. DNES.B W. Hearing Branch | 82/08/20 Atomic Safety and icensing Appeal Panel 149p 14527 183 24X Fiche.50-537, 2/08/20,8208240271
 - DB240411 Advises that R Hiller no longer assigned to proceeding Name should be deleted from svc list, HILLER.H E. Atomic Bafety and Licensing Board Panel 82/08/20 Office of the Erecutive Legal Director 1p. 14822,351 24X Fiche 50-537,82/08/20,8208240411.
- 208270465 Motion to withdraw as party per 10CFR2 714 & to continue participation per 10CFR2 715 Certificate of Svc encl. LANTRIP.M.E. Clak Ridge, TN 82/08/20. Atomic Safety and Licensing Board Panel 4pp. 14565 294. 24X Fiche.50-537.82/08/20, 8208270465.
- 8208240254 Advises that no formal action will be taken until early Sept on 820806 stay request re CRBR exemption decision. No Commission quorum available to act upon request until 820830 CHILK, S. J. Office of the Secretary of the Commission 82/08/23 FINAMORE, B A Natural Resources Defense Council 1p. 14519 264, 24X Fiche 50-537, 82/08/23; 8208240254
- 8208240258 Advises that no formal action will be taken until early Sept on 820806 stay request re CRBR exemption decision No Commission quorum available to act upon request until 820830 CHILK, 8, J. Office of the Secretary of the Commission 82/08/23 OREENSERG, E. V. Tuttle & Taylor. 1p. 14527-077 24X Fiche. 50-537. 82/08/23.8208240258
- 8208240330 Motion to strike portions of applicant testimony & exhibits re-design-specific Info since such info beyond scope of LMA proceeding. Design details are not general characteristics of CRBR design or state of technology MEIBS.E.R.: FINAMORE.B.A. Naturel Resources Defense Council, MEIBS.E.R.: Serra Club. 82/08/23 Atomic Safety and Licensing Board Panel, 16pp 14527:201 24X Fiche.50-537,82/08/23,8208240330

- 8208270400 Memorandum & Order ALAB-688 denying NRDC & Sierra Club petition for directed certification of ALAB 820805 order Neither issue raised is recurring issue of great importance SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel 82/08/25 Natural Resources Defense Council 7pp 14566 001 24X Fiche 50-537,82/08/28.8208270400
- H General correspondance
- B20B02033B Package of 44 comments supporting request by DDE to accelerate site preparation for CRDR

 SCHNELL,D F Union Electric Co MUMAN.R L Affiliation Unknown BRISTOL,D C Carpenter Technology Corp B2/07/22 PALLADING,N J Commissioners 46pp 14150 133 24X Ficher 50-537,82/07/22,8208020358
- 8208020368 Package of 10 comments supporting DDE request to accelerate site preparation for CRBR

 BENSON, L. Southern Boiler & Tank Works, Inc. TESTWUIDDE, R.

 Borg-Warner Corp. STIRRETT, D. D. Derbus Brothers Construction
 82/07/23 PALLADINO, N. J. Commissioners 10pp 14150 089 24x

 Fiche 50-537, 82/07/23, 8208020368
- 8208040285 Comments on DDE request to accelerate site preparation for CRBR Supports request KENNEDY, CF New York State Electric & Gas 82/07/27. PALLADINO, N J Commissioners ip 14183 067 24X Fiche. 50-837, 82/07/27, 8208040285
- 8208050345 Comments on DOE request to accelerate site preparation for CRBR Supports request
 HEMBREE, P P Affiliation Unknown 82/07/27 PALLADING, N. J
 Commissioners ip 14219 338 24X Fiche 50-537, 82/07/27,
 8208050345
- 8208040434 Package of nine comments supporting accelerated site preparation for CRBR
 MCNAMRALJ R Salt River Project MURRILL.P W Oulf Btates
 Utilities Co BTEWART.O C Affiliation Unknown 62/07/28
 PALLADINO, N J Commissioners 7pp 14189 292. 24X
 Fiche 50-537, 82/07/28, B208040434
- 8208040369 Package of two comments supporting accelerated site preparation for CRBR HORTON.A C Jones-Unslow Electric Membership Corp POSTMA, F R Rockbestos Co 82/07/29 PALLADINO, N J Commissioners 2pp 14190 252 24X Fiche 50-537,82/07/29.8208040369
- 8208050399 Comments on DOE request to accelerate site preparation for CRBR Supports request PERSON,R T Public Service Co of Colorado 82/07/29 PALLADINO.N J Commissioners 1p 14209 211 24X Ficha 50-537,82/07/29,8208050399
- 820BC40373 Package of sight comments supporting accelerated site preparation for CRBR RUPERT.R.E. Wyle Laboratories CONLEY.M., ROBAK.D. Affiliation Unknown 82/07/30 PALLADING.N.J. Commissioners 8pp 14190-244 24X Fiche 50-537.82/07/30.8208040373.
- 8208120269 Comments on proposed accelerated site preparation for CRBR Supports proposal.

 MELLS.H.V Clinton Courier News Clinton, TN 82/07/30 PALLADINO, N J Commissioners 1p 14326 331, 24X Fiche 50-537, 82/07/30, 8208120268
- 8208050286 Package of 10 comments supporting accelerated site preparation for CRBR.
 CVICKER, 18. HENLEY, J., GCATEB, R. M. Affiliation Unknown 82/08/02 PALLADINO, N. J. Commissioners 17pp. 14210 168 24X Fiche 50-537, 82/08/02, 8208050286
- 8208120279 Comments on proposed accelerated site preparation for CRBR Supports proposed CUMHINOS, R., CUMHINOS, E., Affiliation Unknown 82/08/02 PALLADINO, N. J., Commissioners, 1p. 14324*278 24X Fichs 50-537.82/08/02,8208120279
- B20B120220 Package of five comments supporting proposed site preparation for CRBR.
 DAVIS:M E. City & County Bank Cak Ridge, TN. BITTABON,F., PATTERBON, T. Affiliation Unknown B2/08/04. PALLADING, N. Commissioners Spp 14319,155 24X Fiche 50-537,82/08/04, processors Spp 14319,155 24X Fiche 50-537,82/08/04,
- 820B120177 Package of ten comments supporting completion of CRBR.

 BIRDHELL, J E First American Bank Clinton, TN,. BMITH, B H
 Carolina Power & Light Co HENRY, O K Affiliation Unknown
 82/08/05 PALLADINO, N J. Commissioners 11pp 14324 073 24X
 Fichs. 50-537, 82/08/05, 820B120177.

- 8208120286 Package of two comments supporting proposed accelerated site preparation for CRBR CLANCY.R C Niagara Mohawk Power Corp SMITH, D L Affiliation Unknown 82/08/06 PALLADINO.N J Commissioners 2pp 14324 299 24X Fiche 50-537.82/08/06,8208120286
- 820B120183 Supports completion of CRBR

 GALMISH, M Affiliation Unknown 82/08/07 PALLADINO, N

 Commissioners ip 14324 229 24 Fiche 50-537, 82/08/07,
- 8208120272 Package of two comments opposing CRIR HAYDEN,P, BLAKELY,H W Affiliation Unknown 82/08/09 PALLADING,N Commissioners 2pp 14324 328 24X Fiche 50-537,82/08/09,8208120272
- 820B120298 Package of three comments supporting CRBR LARBON, D O Steels Wasera Cooperative Electric Miller, M Nolin Rural Electric Cooperative Corp KENNEY, N Affiliation Unknown 82/08/09 PALLADINO, N Commissioners 3pp 14325 003 24X Fiche 50-537,82/08/09,820B120298
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207110047 Certified minutes of ACRS CRBR Subcommittee 820330-31 maeting in Washington, DC re review of NRC principle design criteria for CRBR Viewgraphs enc1

 * ACRS Advisory Committee on Reactor Safeguards, 82/04/24
 ACRS Advisory Committee on Reactor Safeguards 12pp 14194 270
 24% Fiche 50-537,82/04/24,8207110047
- 9206270091 Comments on 920416 meeting re thermal margin beyond design basis rept.CRDR probabilistic risk assessment cannot be used for safety evaluation CATYON, I ACRS Advisory Committee on Reactor Safeguards 82/05/05 GASBER,R Brookhaven National Laboratory 3pp. 14194 115 24X Fiche 50-537,82/05/05.8206270091
- 8208040457 Forwards ACRS 820713 rept re application for facility LWA CMECK-P 8 Clinch River Breeder Reactor Program Defice, 82/07/26 LUNGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 2pp 14220 283. 24X Fiche 50-537, 82/07/26, 8208040457
- --B208040467 Summarizes ACRB 267th meeting on B2070B-10 re NUREG-0786, "Bite Buitability Rept in Matter of CRBR " CRBR can be designed so as to present no greater risk than LWR Proposed designed to the site suitable SHEHMON, P. AGRB - Advisory Committee on Reactor Safeguards 82/07/13 PALLADING, N. J. Commissioners 2pp 14220 283 14220 285 24X
- O Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) JORANGE - Svc list encl JORNAN E.L Division of Engineering & Quality Assurance Consolidated Edison Co of New York 87pp. 14356-274 Fiche 90-000-82/07/16-8204210393
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " 8vc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/20, Consolidated Edison Co of New York, 112pp 14381 001 24X Fiche 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl, CDBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/07/20. Consolidated Edison Co of New York 7ipp 14357 276 24X Fiche 50-000/82/07/20/8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & IPCI Turbine Exhaust Check Valve Failures." Syc list encl JORDAN:E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp. 14194 321 24X Fiche. 50-000. 82/07/22. 8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " 8vc list encl. JORDAN,E L Division of Engineering & Guslity Assurance 82/07/23 Consolidated Edison Co. of New York 122pp. 14380:115, 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 92-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs," Syz list encl. JORDAN, EL Division of Engineering & Quality Assurance, 82/07/29, Consolidated Edison Co. of New York 127pp 14174-120, 24X Fiche 50-000,82/07/29,8204210402.

- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Hestinghouse PMR Power Plants." Svc list encl JORDÁN E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of Flew York 121pp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Natice 92-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JURDAN.E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146. 24X Fiche 50-000, 82/07/28, 8204210403
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co. of New York 117pp 14388 201 24X Fiche 80-000, 82/08/05, 8204210407
- T Hearing transcripts on non-antitrust matters
- 8208020265 Oral comments of MM Todorovich on 820729 in Washington DC supporting DDE examption request
 TODDROVICH, H M Scientists & Engineers for Secure Energy 82/07/29
 13pp 14132 317 24% fiche: 50-337, 82/02/79, 8208020265
- 8208040553 Transcript of 820721 public meeting in Washington. DC re affirmation of CRER order Pp 1-3 Commissioners 82/07/21, 4pp 14221 143 24X Fiche 50-537, 82/07/21, 8208040553
- B20B160001 Forwards revised CRBR rept, initially submitted on B20722 REMICK.F.J. NRC No Detailed Affiliation Given 62/07/28. PALLADING.N.J., GILINBKY,V., AHEARNE,J.F. Commissioners 5Bpp 14370 083 24% Fiche, 50-537, 82/07/28, 8208160001
- --8208160003 Transcript of 820729 oral presentation on CRBR. Pp 1-213 * Commissioners, 82/07/29 215pp, 14370:201 24X Fiche: 50-537, 82/07/28, 8208160001,
- 8208040012 Transcript of 820802 conference in Bethesda, MD Fp 685-875 * Atomic Bafety and Licensing Board Panel. 82/08/02 192pp 14188 298. 24X Fiche 50-537, 82/08/02, 82080 40012
- 8208240025 Transcript of 820805 public meeting re discussion & vote on DDE exemption request in Washington, DC, Pp 1-27 Supporting documentation encl.

 * Commissioners, 82/08/05 118pp 14529, 125, 24X * Commissioners, 82/08/05 11: Fiche. 50-537, 82/08/05, 8208240025
- 820B170109 Testimony of NW Brown, OH Deitrich, VS D'Block & LE Btrawbridge on behalf of joint applicants to NRDC Contentions 1,2 & 3 on adequacy of accident analyses Prof-qualifications & Certificate of Svc enci. BROWN, N W, CLARE, O H, DEITHICHLE W Joint Applicants-Clinch River Breeder Reactor B2/08/16 86pp 14365,235 24X Fiche 50-537, B2/08/16,8208170109.
- 8208170117 Testimony of RD McClelian JW Healy & RC Thompson on behalf of joint epplicants re NRDC Contention Re on calculation of guideline value for radiation doses from postulated release Prof quilifications & Certificate of Svc of encl MCCLELLAN,R O., HEALY,J W , THOMPSON,R C Joint Applicants-Clinch River Breader Reactor. 82/08/16 20pp 14358 166 24X Fiche 50-537,82/08/16,8208170117
- 8208180115 Testimony of TB Cockran on Contentions la.3b & 3d re core disruptive accidents & UBAs & Contentions 2 & 3c re site suitability analysis under 10CFR100 COCHRANT B Natural Resources Defense Council 82/08/16 125pp. 14377'28B 24X Fiche. 50-537; 82/08/16. 8208180115
- --B208180119 Testimony of KZ Morgan on Contentions 1 & 2 Requirements of 10CFR100 not met CROR site not suitable for LMFBR.
 MORGAN: K Z Natural Resources Defense Council. MORGAN: K Z Dak Ridge National Laboratory 82/08/16. 25pp 14378 037. 24X Fiche 50-537.82/08/16.8208180115
- --B20B1B0125 Testimony of F Von Hippel on Contentions 1 & 2 re core disruptive accident probabilities at CRBR VON HIPPEL, F. Natural Resources Defense Council VON HIPPEL, F. Princeton Univ. 82/08/16. 13pp 14378 063 24X Fiche 50-537,82/08/16,82081B0115
- --B20B1B0130 Testimony of JC Cobb on Contention 2 re-proposed stds & guidelines for Pu & other alphe emitting radionuclides.
 Toxicity of Pu underestimated Certificate of Byr encl
 COBB.J.C Natural Resources Defense Council, COBB.J.C, Colorado,
 Univ. of 82/08/12 21pp 14378.075, 24X Fiche 50-537,82/08/16,

- 9208200237 Transcript of ACRS Working Group on Structures & Matls for CRSR 820818 meeting in Washington, DC Pp 1-301 Visugraphs encl ACRE -
 - Advisory Committee on Reactor Safeguards 82/ 14396 345 24X Fiche 50-537,82/08/18,8208200237
- 8208230278 Transcript of ACRS Working Oroup on Structures & Matls for CRSR 820817 meeting in Washington, DC Pp 302-401. Visugraphs encl # ACR8 - Advisory Committee on Reactor Bafeguards, 82/08/19 160pp 24X Fiche 50-537,82/08/19,8208230278
- 8208260245 Transcript of 820823 hearing in Dat Ridge, TN Pp 1, 234-1,626 # Atomic Bafety and Literaing Doard Panel. 82/08/23 394pp 14553 001 24% Fiche: 50-537, 82/08/23, 8208260245
- 8208300033 Transcript of 820824 hearing in Dat Ridge, TN Pp 1,627-1,980 * Atomic Sefety and Licensing Board Panel 82/08/24 335pp 14675:026 24% Fiche. 50-537,82/08/24,8208300033
- 8208300140 Transcript of 820825 meeting in Oak Ridge.TN Pp 1,781-2,585 # Atomic Sefety and Licensing Board Panel 82/08/25 605pp. 14676:020. 24% Fiche:50-537.82/08/25,8208300160
- 8208310161 Transcript of 820826 hearing in Dat Ridge, TN Pp 2, 386-2803, a Atomic Safety and Licensing Board Panel. 82/08/26 219pp. 14689:062 24% Fiche 50-537,82/08/26,8208310161
- 8208310281 Transcript of 820827 hearing in Oak Ridge, TN Pp 2,804-3,217 Supporting documentation encl 4 Atomic Safety and Licensing Board Fanel 82/08/27, 415pp, 14690:198. 24% Fiche 50-537,82/08/27,8208310281
- U Congressional/Executive Correspondence
- S208020268 Requests view on future of CRBR

 BDUGUARD, M L. House of Rep., Science & Technology

 SEITZ, F. Scientists & Engineers for Secure Energy

 24X Fiche. 50-537, Bi/05/27, B208020268 14152-304.
- 8208020354 Opposes CRBR project. FENNICK: H House of Rep 82/07/16 PALLADING, N. C Ip 14:50 11: 24% Fiche 50-337.82/07/16.8208020354 Commissioners.
- 8208020418 Forwards 820224 & 811211 ltrs to NRC in support of CRBR ARC should act w/speed to approve request for accelerated site preparation

 NCMALLY: Tennessee. State of 82/07/20 FALLADING, N J Commissioners ip 14145 112 24X Fiche 50-337. 82/07/20, page 2000.00418
 - 9208020422 Expresses distatisfaction that Governor Alexander & Benator Baker lers supporting CRBR were emitted from NRC rept on roject.Ltrs should be included in suppl to rept.

 ALLY.R. Tennesses, State of 82/02/24 PALLADING, N isstoners ip 14145 113 24X Fiche. 50-537, 92/07/20, inchase.
 - 10425 Supports DOE request to expeditiously authorize site paration for CRBR.

 MALLY.R. Tennessee, State of 81/12/11 PALLADIND.N.J.

 Commissioners, 3pp. 14145 114. 24X Fiche 50-537,82/07/20,8208020418
- DCKET 50-538 MEMPHIS STATE UNIV. RESEARCH REACTOR
- 1 Inspection reports: IE Bulletine & correspondence
- 8204210395 IE Info Notice 81-26, Part G. Suppl i, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.

 JORDAN.E L. Division of Engineering & Quality Assurance. B2/07/19, Hichigan, Univ of, 112pp, 14358:001. 24X Fiche. 50-000, 82/07/19, 8204210395.
- 8. Reportable occurrences: LERs & related correspondence
- 8208270497 Update 2 RO 82-1 on 820811, faulty microswitch discovered in 2082/1497 Update × RU 82-1 on 820811 resulty microswitch discovered shield water level safety channel Caused by corrusion buildup in internal microswitch mechanism, filoroswitch replaced & tested, Normal reactor operations resumed.

 JONES, D H Homphis State Univ 82/08/12, Region 2, Office of Director. Spp. 14564 070, 24X Fiche: 50-538, 82/08/12, 8208270497

DOCKET BTN-50-545 REBAR-35

- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes iOCFR Chapter I requirements & provides alternatives to requirements Bvc list enci EISEMNUT.D O Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24% Fichs 50-000,82/08/09,8208090194
- G Inspection reports. IE Bulletina & correspondence
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External
 Radiation "Svc list and JORDAN EL Division of Engineering & Quality Assurance 82/07/19
 Nichigan Univ of 112pp. 14358 001 24X Fiche 80-000,82/07/19,
- DUCKEY STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8208030272 Discusses meetings to review results of NRC evaluation of util regulatory performance in connection w/NRC systematic Assessment of licensee performance (SALP) Final rept w/minor changes & comments encl KEPPLERJ O Region 3. Office of Director 82/07/20 Public Bervice Co. of Indiana. Inc 10pp 14156 179 Fiche 50-546,82/07/20,8208030272. SHIELDS, S H
- --8208030282 Responds to NRC 820302 systematic assessment of licensee performance (BALF) rept Util takes exception to NRC position that question remains re-project mpt & 0A controls GHIELD8,6 W Public Service Co of Indiana. Inc 82/03/17 HIND.J A Division of Emergency Preparedness & Operational Support 16pp 14136-189 24X Fiche, 50-546,82/07/20,8208030272
- 8208240490 Forwards draft guidance for implementation of iOCFR50 34(g) Outdance undergoing final approval Final form will be sent after publication YOUNOBLOOD, B. J. Licensing Branch i 82/08/05 SHIELDS, B.W. Public Service Co. of Indiana, Inc. 2pp 14544 151 24X Fiche: 50~546, 82/08/05, 8208240490
- 8208090194 Generic Ltr 82-14 to all reactor licensess, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl EISENNUT, D. O. Division of Licensing 82/08/09 Consolidated Edison Co. of New York ip 14356 332 24X Fiche 50-000,82/08/09,8208090194
- G Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl.
 JGRDAN-E L. Division of Engineering & Guality Assurance 82/07/16 Consolidated Edison Co. of New York 87pp. 14356 274, 24X Fichs.50~000.82/07/16.8204210393
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure " Svc list anci JORDAN-E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche. 50-000, 82/07/20, 8204210396.
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Dverpacks " 8vc list encl. CDBp.L I Division of Fuel Facilities, Materials & Bafeguards. 82/07/20. Consolidated Edison Co of New York 71pp 14357,27 24X Fiche.50-000,82/07/20.8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures." Byo list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321, 24X Fichs: 50-000, 82/07/22, 8204210398.
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Dreined & Open RCB " Svc list encl JORDANE L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp. 14380-115 24X Fithe:50-000,82/07/23,8204210401

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl. JORDAN.E L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co. of New York 127pp 14194 120. 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sieeves in RCB Piping at Certain Mestinghouse PWR Power Plants " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357-013, 24X Fiche 50-000, 82/07/26, 8204210403
- 6204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 62/07/28, Consolidated Edison Co of New York 122pp 14357 146, 24X Fiche 50-000, 82/07/28, 8204210405
- 8208090060 Ack receipt of 820720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/82-ii & 50-547/82-ii & 50-547/82-ii & 50-546/82-ii & 51REETER, J.F. Division of Project & Resident Programs 82/07/30 SHIELD8,8 W Public Service Co of Indiana, Inc. ip 14247 233 24X Fiche 50-546,82/07/30,8208090060
- --B208070063 Responds to NRC B20623 ltr re violations noted in IE Insp. Repts 50-546/82-11 & 50-547/82-11 Corrective actions procedure drafted providing adequate instructions for control of combustible matis & potential ignition sources SHIELDS.S.W. Public Bervice Co of Indiana, Inc. 82/07/20. KEPLER, J.O. Region 3, Office of Director 4pp 14267 234 24x Fiche 50-546,82/07/30,8208090060
- 8208170298 Forwards IE Inep Repts 50-546/82-12 & 50-547/82-12 on 820713-16 No noncompliance noted LIVILE.W 9 Division of Engineering & Technical Programs 82/08/03 SHIELDS, 8.W Public Service Co of Indiana, Inc 2pp. 14367 030 24K Fiche 50-546,82/08/03,8208170298
- --B208170302 IE Insp Repts 50-546/82-12 & 50-547/82-12 on 820713-16 No noncompliance noted. Major areas inspected structural concrete work activities & related quality records & concrete repair activities. HAKKINS.F.C., WILLIAMS.C.C. Region 3, Office of Director 82/07/29 4pp. 14367.032, 24% Fiche 50-546, 82/08/03, 8208170298
- 8 Reportable occurrences. LERs & related correspondence
- B20B240283 Interim deficiency rept re spec/design changes left unincorporated in as-built configurations of safety-related equipment or structures Initially reported on 811208 Procedural changes being made. Next rept expected by 821217 BHIELDS.8.W. Public Service Co of Indians. Inc. 82/08/16. KEPPLER.J.O. Region 3. Office of Director 2pp 14527:158 24% Fiche: 50-546: 82/08/16. 8208240283
- 8208300218 Interim deficiency rept re poor implementation of conduit & cable tray insp procedures initially reported on 820721.

 Commonwealth-Lord JV revising insp procedures to clarify documentation requirements Next rept by 821203

 SifiELDS,8 W Public Service Co of Indiana, Inc 82/08/20.

 XEPPLER,J.C. Region 3, Office of Director 2pp 14679 044 24X

 Fiche 50-546, 82/08/20, 8208300218
- DOCKET BIN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 82070B0064 Generic ltr to all licensees of operating plants, applicants for QL & holders of CP re Commission approved charter for CRQR. Svc list enci BIRCKB.W J. Dffice of the Executive Director for Operations 82/07/02 Consolidated Edison Co. of New York 93pp. 14:94 QOI 24X Fiche 50-000,82/07/02,8207080664
- 820B030272 Discusses meetings to review results of NRG evaluation of util resultatory performance in connection w/NRC systematic assessment of licenses performance (SALP) Final rept w/minor changes & comments encl.

 KEPPLER.J O Region 3. Office of Director 82/07/20. SHIELDS, B W Public Service Co of Indians, Inc. 10pp 14156:179 24X Fiche 30-346, 82/07/20, 828030272
- --8208030282 Responds to NRC B20302 systematic assessment of licenses performance (SALP) rept Util takes exception to NRC position that question remains re-project mgt & GA controls.

 SHIELDS, B. W. Public Service Co of Indians. Inc B2/03/17 HIND, J. A. Division of Emergency Preparedness & Operational Support 16pp. 14156.189. 24X Fiche:50-546, B2/07/20, B208030272

- 8208240490 Forwards draft guidance for implementation of 10CFR5Q 34(g). Quidance undergoing final approval Final form will be sent after publication YOUNGBLOOD, B J. Licensing Branch 1 82/08/05 SHIELDS, 8 W Public Service Co of Indiana, Inc. 2pp. 14544 151 24X Ficha 50-546,82/08/05,8208240490
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Byc list encl EISENHUT, D 9 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fichs 50-000, 82/08/09, 8208090194.
- 9 Inspection reports: IE Bulletine & correspondence
- 8204210393 TE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/07/16 Consolidated Edison Co. of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393
- 8204210395 IE Info Notice 81-26.Part 3.Suppl 1, "Clarification of Placement of Parsonnel Honitoring Devices for External Radiation "Syc list encl JURDAN.E L Division of Engineering & Quality Assurance 82/07/19 Hichigan, Univ. of 112pp 14358-001 24X Fiche 50-000.82/07/19.8204210398
- 8204210396 IE Info Notice 82-25, "Feilures of Hiller Actuators Upon Oradual Loss of Air Pressure." Syc list encl, JORDANIE L. Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co. of New York 112pp. 14381 001, 24X Fiche. 50-000. 82/07/20, 8204210394,
- 8204210377 IE Info Notice 82-24. "Hater Leaking From U Hesafluoride Overpacks." Bvc list encl COBD.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co. of New York 7ipp. 14357, 276 24% Fiche: 50-000, 82/07/20, 8204210397
- 8204210398 IE Info Notice 82-26. "RCIC & MPCI Turbine Exhaust Check Valve Failures." Bvc list encl.
 JORDANIE L. Division of Engineering & Quality Assurance. 82/07/22
 Consolidated Edison Co. of New York 112pp 14194 321 24X
 Fiche 50-000.82/07/22.8804210398
- 8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Crinding in Vicinity of Drained & Open RCB " Svc list encl JURDAN.E L. Division of Engineering & Guality Assurance 82/07/23 Cansolidated Edison Co. of New York. 122pp 14380*115. R4X Fiche 50-000.82/07/23.8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PMRs " Svc list encl URDAM.E.L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York. 127ap 14194-120 24X Fiche 50-000, 82/07/23, 8204210402.
- 8204210403 IE Info Notice 82-30; "Loss of Thermal Steeves in RCS Piping at Certain Westinghouse PWR Power Plants " Byc list encl, JURDAN,E L. Division of Engineering & Quality Assurance Consolidated Edison Co of New York 12ipp, 14357 013 24X Fiche: 50-000, 82/07/26, 6204210403
- 8204210405 IE Info Notice 82-31, "Gverexposure of Diver During Work in Fuel Storage Pool," Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357,146, 24X Fiche: 50~000, 82/07/28, 8204210405
- 8208090060 Ack receipt of 820720 itr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-546/82-11 & 50-547/82-11. STREETER.J.F Division of Project & Resident Programs. 82/07/30. SHIELDS.B.W Public Service Co of Indiana, Inc. 1p. 14267, 233, 24X Fiche: 50-546, 82/07/30, 8208090060
- --8208090063 Responds to NRC 820523 ltr re violations noted in IE Insp Repts 50-846/82-11 & 50-547/82-11 Corrective actions' procedure drafted providing adequate instructions for control of combustible matis & patential ignition cources. SHIELDB: B W. Public Service Co of Indiana, Inc 82/07/20 KEPLER, J. G. Region 3. Office of Director 4pp. 14269:234 24X Fichs 50-546,82/07/30,8208090060
- 8208170278 Forwards 1E Inep Repts 50-546/82-12 & 50-547/82-12 on 820713-16 No noncompliance notes.

 LITTLE, N. 8 Division of Engineering & Technical Programs 82/08/03 SHIELDS, 8 N. Public Service Co. of Indiana, Inc 2pp 14367 030 24X Fiche, 50-546, 82/08/03, 8208170278.

- --8208170302 IE Insp Repts 50-546/82-12 & 50-547/82-12 on 920713-16 No noncompliance noted Major areas inspected structural concrete work activities & related quality records & concrete repeir activities HAWKINS.F. C : MILLIAMS.C C Region 3, Office of Director 82/07/29 App 14367 032 24X Fiche 50-546.82/08/03,8208170298
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list enc! JORDAN,E L. Division of Engineering & Quality Assurence 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24% Fiche, 30-000, 82/08/05,8204210407
- S Reportable occurrences, LERs & related correspondence
- 8208240283 Interim deficiency rept re spec/design changes left unincomporated in as-built configurations of safety-related aquipment or structures initially reported on 811208 Procedural changes being ands Next rept expected by 821217 ENTELDS.8 W. Public Bervice Co of Indiana, Inc 82/08/16 KEPPLER.J O Region 3. Office of Director 2pp 14527 158 Fichs 50-546, 82/08/16,8208240283 24X
- 8208300218 Interim deficiency rept re poor implementation of conduit & cable tray intep procedures Initially reported on B20721.

 Commonwealth-Lord JV revising insp procedures to clarify decomentation requirements Next rept by B21203

 BHIRLDS.B.W Public Service Co of Indiana, Inc 82/08/20

 KEPPLER, J O Region 3. Office up Director 2pp 14679 044 24%

 Fichs 30-546, 82/08/20,8208300218
- DOCKET 50-549 OREENE COUNTY NUCLEAR POHER PLANT
- O Adjudicatory correspondence
- 8208040229 Clarification of closing of record in proceeding. Record closed: effective 801022

 9000H00FE, A C Atomic Safety and Licensing Board Panel 82/07/23

 1p 14188 139. 24% Fiche 30-349,82/07/23,8208040229
- DOCKET STN-50-550 GESSAR-238-BOF: INTERFACE
- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of GP & applicants re submittal of documents to NRC Summarires JOCFR Chapter [requirements & provides Alternatives to requirements Sev list encl
 EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York in 14356 332 24% Fiche 50-000,82/08/09, 8208090194
- A Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 81-26.Part 3. Suppl 1: "Clarification of Parsonnet Monitoring Devices for External Marketion." See list encl. JORDAN.EL Division of Engineering & Guality Assurance 82/07/19 Hithigan. Univ of 112pp 14358 001 24% Fiche 50-000,82/07/19.
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B2070B0064 Generic ltr to all licensees of operating plants, applicants for QL & holders of CP re Commission approved charter for CRGR SVx list enci CRGR SVx list enci DIRCKS: W J Office of the Executive Director for Operations B2/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fiche 50-000,82/07/02,82070B0064
- 820B100166 Forwards info re QA for deferred plants, in response to NRC 820324 Itr Fossible cancellation of some units will be discussed at future meeting of IVA Board of Directors MILLS, L. M. Tennessee Valley Authority 82/08/06. DENYGN, H. R. Office of Nuclear Reactor Regulation, Director 3pp 14294; 013. 24X Fiche 50-000,82/08/06.8208/00166
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes JOCFR that the submittal of documents to NRC Summarizes JOCFR requirements & provides afternatives to NRC Summarizes JOCFR that the submittal submittal submitted and submittal submitted submittal subm

- I Financial information
- 8208100002 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr ending 810630 & "1981 Power Program Summary," for fiscal yr ending 810930, per Section 50 7(16) of 10CFR50
 MILLS.L M Tennessee Valley Authority 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 118pp 14294 024
 24% Fiche 50-000, 82/08/06, 8208100002
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list enc1
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/16
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fichs 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice 81-24.Part 3.Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
 JORDAN.E L. Division of Engineering & Guality Assurance 82/07/19
 Nichigan. Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19,
- 8204210396 IE Info Notice 82-28, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl. JORDAN.E L. Division of Engineering & Guality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001, 24X Fiche 30-000, 82/07/20, 8204210396
- 8204210397 [E Info Notice 82-24, "Water Leaking From U Hexafluorids Overpacks " Syc list encl. COBB,L.! Division of Fuel Facilities, Materials & Bafeguards. 82/07/20, Consolidated Edison Co of New York 71pp 14357:27 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE Info Notice 82-26, "RCIC & MPCI Turbine Exhaust Check Valve Failures" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24K Fiche 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RGS " Svc list enc!

 JORDAN, E.L. Division of Engineering & Quality Assurance, 82/07/23

 Consolidated Edison Co. of New York 182pp 14380 115 24X

 Fiche 50-000, 82/07/23, 8204210401,
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." See list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 12700 14194 120 24X Fiche 50-000, 82/07/23, 8204210402 14194 120 DAY
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN, E L Division of Engineering & Guality Assurance 82/07/26 Consolidated Edison Co. of New York (21pp 14357 013 24X fiche.50-000,82/07/26,8204210403
- 8204210405 IE Info Notice 82-81, "Overexposure of Diver During Work in Fuel Storage Pool," Eve list encl JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28 Consolidated Edison Co. of New York 122pp 14357
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Hater-Jet Impingement " Svc list and I. JURDAK, E L. Division of Engineering & Quality Assurance 82/08/05 Convolidated Edison Co of New York 117pp 14388 201, 24X Fiche 50-000, 82/08/05, 8204210407.
- S Reportable occurrences, LERs & related correspondence
- 8208020226 Final deficiency rept for Sequoyen second interim rept for Watts Bar & fifth for Bellefonte, Hartsville, Phipps Bend & Yellow Creek re inconsistent establishment of insp program Next rept for Hetts Bar & Bellefonte expected 830103 MILLS,L M Tennessee Valley Authority, 82/07/20 O'REILLY, J P Region 2. Office of Director. App. 14152, 344 24x Ficher 50-000, 82/07/20, 8208020226
- 8208300211 Bixth interim deficiency rept re-procurement control audita Initially reported on 810316 TVA quality engineering branch response to audit deficiencies undergoing review Next rept due by 821007 MILLS.L.M Tennessee Valley Authority. 82/08/23 0'REILLY, J. P. Region 2, Office of Director. 1p 14679-176. 24X Fiche. 50-000, 82/08/23, 8208300211.

- 8208310123 PNO-II-82-098 on 820825, util announced cancellation of listed plants Yellow Creek 1 & 2 indefinitely deferred CANTRELL.F 8 Region 2, Office of Director 82/08/26 ip 14687 286 24X Fiche 50-000, 82/08/26, 8208310123
- DOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants.applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl DIRCKS. W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194.001 24X Fiche 50-000,82/07/02,8207080064
- 8208100166 Forwards info re QA for deferred plants, in response to NRC 820524 ltr Fossible cancellation of some units will be discussed at future meeting of TVA Board of Directors MILLS.L M Tennessee Valley Authority 82/08/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 14274.013 24% Fiche.50-000,82/08/06,8208100166
- B20B090194 Oeneric Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc 11st encl EISENHUT, D 0 Division of Licensing B2/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fichs 50-000, B2/08/09, B20B090194.
- 1 Financial information
- 8208100002 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr anding 810830 & "1981 Power Program Summary," for fiscal yr ending 810930.per Section 50 71(b) of 10CFR50.
 HILLB.L M Tennessee Valley Authority 82/08/06 DENTON, H R. Diffice of Nuclear Reactor Regulation. Director 118pp 14294:024 24X Fichs.50-000,82/08/06,8208100002
- Q Inspection reports, IE Bulletins & correspondence
- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakaga." Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/ Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000,82/07/16,8204210393 82/07/16
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E. Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ of 112pp 14358:001. 24X Fiche 50-000.82/07/19, page 14358: 8204210395.
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381:001 24X Fiche 50-000.82/07/20.8204210396.
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards, 82/07/20 Consolidated Edison Co. of New York 7ipp 14357-27 24X Fiche 50-000,82/07/20,8204210397.
- 9204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Chack Valva Failures " Syc list encl JORDAN:E L Division of Engineering & Guality Assurance, 82/07/22 Consolidated Edison Co of New York 112pp 14194:321 24X Fiche:50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB " Svc list encl VCRDAN,E L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche: 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Syc list entl JORDANJE L Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York. 127pp 14194:120, 24X Fiche: 50-000, 82/07/23, 8204210402
- 8204210403 IE info Notice 82-30, "Loss of Thermal Sleaves in RCS Piping at Certain Westinghouse PWR Power Plants," Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/26, Consolidated Edison Co. of New York. 121pp 14357-013, 24X Fiche 50-000, 82/07/26, 8204210403

- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAM, E.L. Division of Engineering & Quality Assurence, 82/07/28 Consolidated Edison Co. of New York 122pp 14357 146 24X Fiche 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance B2/08/05 Consolidated Edison Co. of New York 117pp 14388 201 24X Fiche 50-000, 82/08/05, 8204210407
- 8 Reportable occurrences, LERs & related correspondence
- 8208020226 Finel deficiency rept for Sequoyah, second interim rept for Watts Bar & fifth for Sellefonte, Hartsville, Phipps Bend & Yellow Creek re inconsistent establishment of insp program Next rept for Matte Bar & Bellefonte expected 830103 MILLS, L M Tennesses Valley Authority 82/07/20 O'REILLY, J P Region 2, Office of Director App 14132 344 24X Fiche 50-000, 82/07/20, 8208020226
- 8208300211 Bixth interim deficiency rept re procurement control audits. Initially reported on Bi0316,7VA quality engineering branch response to audit deficiencies undergoing review Next rept due by 821007 reps due by Exclus/ MILLS.L M Tennessee Valley Authority 82/08/23 G'REILLY, J P Region 2, Office of Director, ip 14679·196 24X Fiche. 50-000, 82/08/23, 8208300211
- 8208310123 PND-11-82-098 on 820825 util annumeral cancellation of listed plants Yellow Creek 1 & 2 indefinitely deferred. CANTRELL.F 8 Region 2. Office of Director 82/08/26 1p. 14689-286 24X Fiche 50-000,02/08/26,8208310123.
- DOCKET BIN-50-556 BLACK FOX BIATION, UNIT 1
- A Application/construction stage documents & correspondence
- 9207080064 Generic itr to all licensees of operating plants, applicants for GL & holders of GP re Commission approved charter for CROR Byc list and DIRCKS M. J. Office of the Executive Director for Operations 22/07/02 Consolidated Falson Co. of Many York 270n 14 82/07/02. Consolidated Edison Co of New York 24X Fiche: 50-000, 82/07/02, 8207080064. 93pp 14194: 001.
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Ghapter I requirements & provides alternatives to requirements 8 by list enc! EIBENHUT.D 0 Division of Licensing 82/08/09, Consolidated Edison Co of New York | p 14356 332 24X Fiche 50-000,82/08/09,8208090194
- Q Inspection reports: IE Bulletins & correspondence
- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Svc list encl JORDANIE L. Division of Engineering & Quality Assurance. B2/07/16 Consolidated Edison Co. of New York B7pp. 14356; 274. 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Notice Bi-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Homitoring Devices for External Radiation," Syc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/19, Hichigan, Univ of 112pp 14358 001. 24% Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Graduel Loss of Air Pressure " Syc list encl, JORDAN,E L. Division of Engineering & Quality Assurance, 82/07/20, Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 30-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks," 8vt list encl COBB.L.I Division of Fuel Facilities, Haterials & Bafeguards, 82/07/20, Consolidated Effson Co. of New York 7ipp. 14357; 276, 24X Fiche: 50-000: 82/07/20: 6204210397.
- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance. 82/07/22, Consolidated Edison Co of New York 112pp. 14194-321. 24X Fiche. 50-000, 82/07/22, 8204210398.

- 8204210401 IE Info Notice 82-28, "Mydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380:115 24X Fiche 50-000, 82/07/23,8204210401
- 8204210402 IE Info Notice 82-27. "Control Rud Drive (CRD) Quide Tube Support Pin Failures at Hestinghouse PWRs " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- B204210403 IE Info Notice 82-30, "Loss of Thermal Bleaves in RGB Piping at Certain Mestinghouse PMR Power Plants" Svc list encl JORDAN, EL Division of Engineering & Guality Assurance B2/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overesposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York. 1224p 14357:146, 24X Fiche: 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl.
 JURDAN,E L. Division of Engineering & Guality Assurance. 82/08/05
 Consolidated Edison Co. of New York 117pp 14398 201. 24X
 Fiche 50-000,82/08/05,8204210407

DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

- A Application/construction stage documents & correspondence
- B2070B0064 Generic ltr to all licenses of operating plants, applicants for OL & holders of GP re Commission approved charter for CROR Bvc list encl
 DIRCKS, H J Office of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York. 93pp. 14194.001,
 24X Fiche 30-000.82/07/02, B2070B0064
- 8208090194 Ceneric Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements Bvc list encl. EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York ip 14356 332 24X Fichs 50-000,82/08/09, B208090194.
 - Inspection reports, IE Bulletine & correspondence
- 204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leatage " Svc list encl URDAN E L Division of Engineering & Quality Assurance, 82/07/16 Consolidated Edison Co of New York 87pp. 14356 274 24X Fiche 30-000 82/07/16,8204210393
-)204210395 IE Info Notice 81-26, Part 3, Buppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDANIE L. Division of Engineering & Quality Assurance, 82/07/19, Hichigan, Univ of, 112pp. 14358 001, 24X Fiche 50-000, 82/07/19, 8204210395
- 8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Oradual Loss of Air Pressure." Svc list anci. JORDANIE L. Division of Engineering & Quality Assurance, 82/07/20 Consolidated Edison Co of New York 112pp. 14381 001. 24X Fiche: 50-000. 82/07/20. 8204210396
- 9204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357:276 24X Fiche:50-000.82/07/20.8204210397
- 04210401 IE Info Notice 82-28. "Hudrogen Explosion While Grinding in Vicinity of Dreined & Open RCS " Byo list encl. JORDAN.E.L Division of Engineering & Guelity Assurance 82/07/23 Consolidated Edison Co of New York. 122pp 14380 113. 24X Fiche: 50-000, 82/07/23, 8204210401.

- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Bupport Pin Failures at Westinghouse PWRs " Svc list encl JORDAN:E L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Go of New York 127pp 14194 120 24X Fiche 50-000,82/07/23.8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Westinghouse PHR Power Plants " Svc list ancl JORDAN.E L Division of Engineering & Guality Assurance 62/07/26 Consolidated Edison Co. of New York 121pp 14357 013 24X Fiche 30-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Fool " Svc list encl JDRDAN.E L Division of Engineering & Quality Assurance. 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24X Fiche, 50-000, 82/07/28, 8204210405
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffla Water-Jet Impingement " Svc list encl JORDAN: E.L. Division of Engineering & Quality Assurance 82/08/03 Consolidated Edison Co of New York 117pp 14388 201 24X Fichs 50-000.82/08/05,8204210407

DOCKET STN-50-560 BOPSBAR

- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licenees, holders of CP & applicants re submittal of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements. Svc list encl EISENHUT, D.Q. Division of Licensing 82/08/09 Consolidated Edison Co of New York. ip 14356 332 24X Fichs 50-000, 82/08/09, 8208090194.
- G Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice Bi-26, Part 3, Suppl 1, "Clarification of flacement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001, 24X Fiche 50-000, 82/07/19, 8204210395

DOCKET BTN-50-561 B-8AR-205

- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licenses, holders of CP & applicants re submittel of documents to NRC Summarizes IOCFR Chapter I requirements & provides alternatives to requirements, 8xc list encl EISENNUT, D. Q. Division of Licensing 82/08/09 Consolidated Edison Co. of New York 1p 14356 332 24X Fiche. 50-000, 82/08/09, 82/08/09/194.
- Q. Inspection reports: IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 82/07/19 Michigan Univ. of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395.
- DOCKET 50-564 NUCLEAR FUELS RECOVERY & RECYCLE CENTER

 G Inspection reports: IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
 JORDAN, E. Division of Engineering & Guality Assurance 82/07/19
 Michigan, Univ of. 112pp 14358-001 24X Fiche. 50-000, 82/07/19, 8204210395
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8207080064 Generic ltr to all licensees of operating plants, applicants for GL & holders of CP re Commission approved charter for CROR. Svc list encl.
 DIRCKS, H. J. Office of the Executive Director for Operations
 82/07/02. Consolidated Edison Co. of New York 93pp. 14194.001
 24% Fiche. 50-000, 82/07/02, 8207080064

- 620B100164 Forwards info re QA for deferred plants, in response to NRC B20524 ltr Possible cancellation of some units will be discussed at future meeting of TVA Board of Directors HILLS, L.M. Tennessee Valley Authority 82/08/06 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp 14294 013. 24X Fiche 50-000,82/08/06,820B100166
- 6208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8vc list encl EISENNUT D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000, 92/08/09, 8208090194

1 Financial information

- 8208100002 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr anding 810430 t "1981 Power Program Summary," for fiscal yr ending 810930, per Section 50 71(b) of 100FR50 MILLS.L M Tennesses Valley Authority 82/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 118pp 14294 024 24X Fiche 50-000,82/08/06.8208100002
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV) Leakage " Syc list encl JORDAN: E L. Division of Engineering & Guality Assurance 62/07/1. Consolidated Edison Co of New York 87pp 14356 274 24X Fiche 50-000, 82/07/16, 8204210393
- 8204210375 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation "Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/07/19 Hichigen
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressurs " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fische 50-000, 82/07/20, 8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 62/07/20 Consolidated Edison Co of New York 7ips 14357 276 24X Fiche 50-000,82/07/20,8204210397
- 8204210398 IE info Notice 82-26. "RCIC & IPCI Turbine Exhaust Check Valve Failures " Syc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321, 24X Fiche 50-000 82/07/22 8204210398
- B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl JORBAN, E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fische 50-000, 82/07/23, 8204210401
- 8204210402 LE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse PWRs " Bvc list encl JORDAN.E L. Division of Engineering & Quality Assurance, B2/07/23, Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeves in RCS Piping at Certain Hestinghouse PMR Power Plants " Syc list encl JORDAN. E L Division of Engineering & Guality Assurance. 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24% Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 82/07/28 Cansolidated Edison Co of New York. 122pp 14357,144. 24X Fichs 50-000,82/07/28,8204210405
- 8208160144 Responds to IE Bulletin Bi-02 Suppl 1, "Failure of Gate Type Valves to Close Against Differential Pressure " Util anticipates submittel of final rept by 821028 upon receipt of revised drawings of field change notices KAMMER. D. S. Tennessee Valley Authority. 82/07/29 O'REILLY, J.P. Region 2. Office of Director. 1p 14345, 123, 24X Fiche: 50-000, 82/07/27, 8208160144.

- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Mater-Jet Impingement " Svc list encl.

 JORDAN, E. Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche 50-000.82/08/05.8204210407
- S Reportable occurrences, LERs & related correspondence
- 8208020224 Final deficiency rept for Sequoyah, second interim rept for Natts Bar & fifth for Bellefonte, Hartsville, Phipps Bend & Yellow Creek re inconsistent establishment of insp program. Next rept for Hatts Bar & Bellefonte expected 820103 MILLS.L M Tennessee Valley Authority 82/07/20 0'REILLY, J P Region 2, Office of Director App 14152 344 24% Fiche 50-000, 82/07/20, 82/08020226
- 8208300211 Bixth interim deficiency rept re procurement control audits Initially reported on 810316 TVA quality engineering branch response to audit deficiencies Undergoing review Next rept due by 821007
 MILLS.L M Tennesses Valley Authority 82/08/23 O'REILLY, J P Region 2, Office of Director ip 14679 176 24X
 Fiche 50-000,82/08/23,8208300211

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- B2070B0064 Generic ltr to all licensess of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR. Svc list encl.

 DIRCKS, H J. Defice of the Executive Director for Operations
 B2/07/02 Consolidated Edison Co of New York 93pp 14194:001
 24X Fichs 50-000, 82/07/02, B2070B0064.
- 820Bi00166 Forwards info re GA for deferred plants, in response to NRC 820824 ltr Passible cancellation of some units will be discussed at future meeting of TVA Board of Directors HILLS, L. M. Tennessee Valley Authority 82/08/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director Spp. 14294 013 24X Fiche 50-000, 82/08/06, 8208100166
- 8208070174 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants to submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Styr list encl EISENNUT.D © Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356:332 24X Fiche 50-000,82/08/09,8208090194.
- I Financial information
- 820B100002 Forwards "TVA Power Program Summary," Vol 2.for fiscal yr anding 810630 t "1981 Fower Program Summary," for fiscal yr anding 910730.per Section 30 71(b) of 100FR30. HILLB.L M Tennessee Valley Authority 82/08/06 DENTGN.H.R Office of Nuclear Reactor Regulation, Director 118pp 14274:024. 24X Fiche 50-000.82/08/06.820B100002
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MBIV)
 Leakage " Svc list enc!
 JORDAN,E L. Division of Engineering & Quality Assurance 82/07/16,
 Consolidated Edison Co of New York 87pp 14356 274 24X
 Fiche 50-000.82/07/16.8204210393
- 8204210395 IE info Notice 81-26, Part 3, Suppl 1: "Clarification of Placement of Personnal Monitoring Davices for External Radiation" Bvc list encl JORDAN.E.L Division of Engineering & Guality Assurance. 82/07/19 Michigan, Univ. of 112pp 14358 001 24K Fiche 50-000,82/07/19,8204210395.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl JRRDAN,E L. Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co of New York 112pp. 14381.001 24X Fiche 50-000,82/07/20,8204210396.
- 8204210397 IE Info Notice 92-24, "Water Leaking From U Hexafluoride Overpacks" Bvc list encl. C088/L I Division of Fuel Facilities, Materials & Bafaguards. 82/07/20 Compolidated Edison Co of New York 7ipp 14357:274 24X Fichs.50-000.82/07/20,8204210397.

- 8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " 8vc list and JORDAN,E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp. 14174 321 24X Fiche 50-000,82/07/22,8204210398
- 8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl. JORDAN,E L Division of Engineering & Guality Assurance 82/07/23 Consolidate Edison Co. of New York 122pp 14380 115, 24X Fiche 50-000, 82/07/23, 8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Support Pin Failures at Westinghouse FWRs " Svc list encl. JORDAN,E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194,120, 24X Fiche 50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermel Bleeves in RCS Piping at Certain Hestinghouse PHR Power Plants " Svc list enci JORDAN.E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013, 24X Fiche 50-000,82/07/26,8204210403
- B204210405 IE Info Notice B2-31, "Dverexposure of Diver During Work in Fuel Storage Pool," Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance B2/07/28 Consolidated Edison Co. of New York. 122pp. 14357 146 24X Fiche 30-000:82/07/28.8204210405
- 8208160144 Responds to IE Bulletin Bi-O2 Buppl 1, "Failure of Cate Type Valves to Close Against Differential Pressure " Util anticipates submittal of final rept by 821028 upon receipt of revised drawings of field change notices.

 KAMMER.D.8 Tennesses Valley Authority 82/07/29, O'REILLY.JP Region 2, Office of Director ip 14345-123 24X
 Fiche 50-000.82/07/29.8208160144
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Saffle Water-Jet Impingement," Svc list encl.
 JORDAN: E L Division of Engineering & Guality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp. 14388 201 24X
 Fiche 50-000,82/08/05,8204210407
- S Reportable occurrences: LERs & related correspondence
- 8208020226 Final deficiency rept for Sequoyah, second interim rept for Matts Bar & fifth for Sellefonte, Harteville, Phipps Bend & Yellow Creek re inconsistent establishment of Inap program. Next rept for Matts Bar & Bellefonte expected 83003 MILLS, L H Tennesses Valley Authority 82/07/20 O'REILLY, J P Region 2. Office of Director 6pp 14152 344. 24% Fiche 30-000, 82/07/20, 8208020226
 - 08300211 Sixth interim deficiency rept re procurement control audits Initially reported on 810316. TVA quality engineering branch response to audit deficiencies undergoing review Next rept due by 821007.

 HILLE-L H Tennessee Valley Authority 82/08/23 0'REILLY, J P Region 2. Office of Director. 1p. 14679:196 24X Fiche-50-000, 82/08/23, 8208300211
- DOCKET STN-50-572 RESAR-414 WESTINGHOUSE ELECTRIC CORP
- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl EIBENNUT.D.O Division of Licensing. B2/08/09 Consolidated Edison Co of New York. ip 14356;332 24X Fiche: 50-000, 82/08/09, 8208090144
- Q Inspection reports: IE Bulletine & correspondence
- 8204210395 IE Info Notice 81-26, Part 3. Suppl 1: "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl.

 JORDANIE L Division of Engineering & Quality Assurance, 82/07/19

 Hichigan, Univ. of 112pp. 14358 001, 24X Fiche. 90-000, 82/07/19, 8004270398

- DOCKET STN-50-584 GIBBSAR, GIBBS & HILL
- A Application/construction stage documents & correspondence
- 8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements 8v list encl EISENHUT, D 0 Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000,82/08/09,8208090194
- Q Inspection reports. IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-24, Part 3, Suppl 1, "Clarification of EURZIUSYD IE INFO Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list ancl JORDAN.E.L. Division of Engineering & Quality Assurance 82/07/19 Michigan. Univ of 112pp 14358 OOI 24X Fiche 50-000,82/07/19,8204210395
- DOCKET BIN-50-591 ESSAR, EBASCO SERVICES
- A Application/construction stage documents & correspondence
- 820B090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl
 EISENHUT, D 9 Division of Licensing 82/08/07 Consolidated Edison Co of New York 1p 14356 332 24X Fichs 50-000,82/08/09, Edison Co of New York 8208090174
- Q Inspection reports, IE Bulletins & correspondence
- 8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Davices for External Radiation " Svc list encl JORDANA E. Division of Engineering & Guelity Assurance. 82/07/19 Michigan, Univ of. 112pp 14958 001 24% Fiche 80-000, 82/07/19, 8204210395
- DOCKET STN-50-597 NEW HAVEN, UNIT 2
- A Application/construction stage documents & correspondence
- 820B090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Bummarizes IOCFR Chapter I requirements & provides alternatives to requirements. Svc list encl ETBENHUT, D.O Division of Licensing 82/08/09. Consolidated Edison Co. of New York. ip 14356: 332 24X Fiche 50-000, B2/08/09, B208090194
- DOCKET STN-50-599 CARROLL FACILITY I
- Q Adjudicatory correspondence
- 8208030402 Requests hearings be deferred until const plans are more certain in response to ASLB 820707 memorandum & order Deferral would not prejudice rights of parties Related Deferral would not presument to the correspondence
 BIELAWSKI, A.P. Isham, Lincoln & Beale BIELAWSKI, A.P. Commonwealth
 Edison Co. 82/07/28, Atomic Safety and Licensing Board Panel
 2pp 14154, 011 24X Fiche 50-599, 82/07/28, 8208030402
- 8208170263 Memorandum & order allowing case to retain active status provided applicant submits quarterly status repts beginning 821101.

 MOLF, J. F. Atomic Bafety and Licensing Board Panel. 82/08/12, 3pp 14347-098 24X Fiche: 50-599,82/08/12,8208170263.
- G Inspection reports. IE Bulletins & correspondence
- 8204210373 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage " Svc list encl. JORDAN.E L. Division of Engineering & Quality Assurance, Consolidated Edison Co of New York 87pp 14356,274 Fiche.50-000.82/07/16.8204210393 82/07/16, 24X
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradusl Loss of Air Pressure," Syc list encl.
 JORDAN E L. Division of Engineering & Quality Assurance, 82/07/20
 Consolidated Edison Co. of New York 112pp. 14381:001. 24X
 Fichs 50-000.82/07/20,8204210396.

- 8204210397 IE Info Notice 82-24, "Mater Leaking From U Hexafluoride Overpacks " Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 7ipp 14357 276 244 Fiche 50-000.82/07/20.8204210397
- 9204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl UORDAN, E L Division of Engineering & Guality Assurance, 82/07/22, Consolidated Edison Co of New York 112pp 14174,321 24X Fichs 50-000,82/07/22,8204210398
- 82042i0401 IE Info Notice 82-28, "Hydrogen Explosion While Orinding in Vicinity of Drained & Open RCS " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York 122pp, 14380:115 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Syc list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/07/23 Consolidated Edison Co of New York, 127pp 14194 120 24X Fichs.50-000,82/07/23,8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Bleaves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 12ipp 14357 013 24X Fiche: 50-000, 82/07/26, 8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list and I DURDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28 Consolidated Edison Co of New York. 122pp 14357:146 24X Fiche.50-000.82/07/28,8204210403
- 0204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl.

 JORDAN, E.L. Division of Engineering & Guality Assurance 02/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche: 50-000, 82/08/05, 8204210407

DOCKET SIN-50-600 CARROLL FACILITY II

- O Adjudicatory correspondence
- B208030402 Requests hearings be deferred until const plans are more certain in response to ASLB 820707 memorandum & order Deferral would not prajudice rights of parties, Related Deferral would not project the commonwer of the commonwer Communwealth
- B208170269 Memorandum & order allowing case to retain active status provided applicant submits quarterly status repts beginning 821101 821101 WOO.F.J F Atomic Bafety and Licensing Board Panel 82/08/12. 3pp 14367 098 24X Fiche 50-599.82/08/12.8208170263
- Q Inspection reports, IE Bulletins & correspondence
- 8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage," Byo list encl. JORDAN,E L. Division of Engineering & Quality Assurance (2007) Leatage, " Byc list encl.
 JORDAN, E L. Division of Engineering & Quality Assurance 82/07/16
 Consulidated Edison Co. of New York. 87pp 14356 274. 24X
 Fichs. 50-000. 82/07/16. 8204210393.
- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Syc list encl JORDAN, E. L. Division of Engineering & Guality Assurance, 82/07/20 Consolidated Edison Co of New York 112pp 14381;001, 24X Fiche 50-000,82/07/20,8204210396
- B204210397 IE Info Notice B2-24, "Water Leaking From U Hexafluoride Overpacks " Bvc list encl C088:L.1 Division of Fuel Facilities, Materials & Safeguards. B2/07/20 Consolidated Edison Co. of New York, 71pp 14357 2' 24X Fiche: 50-000:82/07/20:8204210397
- B204210398 IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance. B2/07/22 Consolidate Edison Co of New York 112pp. 14194:321. 24X Fiche, 50-000, 82/07/22, 8204210398

- 8204210401 IE info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list entl JORDAN.E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York, 122pp 14380 115 24X Fithe 50-000,82/07/23.8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Quide Tube Bupport Pin Failures at Westinghouse PWRs " Bvc list encl. JORDAN,E L Division of Engineering & Buality Assurance B2/07/23 Consolidated Edison Co of New York. 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402
- 8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Byc list encl. JORDAN.E L Division of Engineering & Quality Assurance Gonsolidated Edison Co of New York. 121pp 14357 013 24X Fiche 50-000.82/07/26,8204210403
- 8204210405 IE Info Natics 82-31, "Overexposure of Diver During Work in Fuel Storage Pool " Svc list encl.
 JORDAN,E L Division of Engineering & Quality Assurance, 82/07/28
 Consolidated Edison Co of New York, 122pp 14357 146 24X
 Fichs 50-000,82/07/28,8204210405.
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list ent!
 JORDAN-E.L Division of Engineering & Quality Assurance 82/08/05
 Consolidated Edison Co of New York 117pp 14388 201 24X
 Fiche-50-000.82/08/05,8204210407.

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP , CANOGA PARK, CA

- 8208130356 Confirms into re Rockwell Intl Hatls License BNM-21 No notice will be published when applying for renswal. Request for intervention status or hearing can be made any time prior to expiration of existing license TEPPER.P.S San Ferhando Valley Alliance for Survival 82/07/6 KETZLACH.N Uranium Fuel Licensing Branch. 1p 14340:254
- 8208270350 Forwards IE Safeguards Insp Rept 70-0025/82-05 on 820712-15 & 19-23 No noncompliance noted.

 NORDERHAUG, L. R Division of Radiological Bafety & Bafeguards Program 82/08/20 FEILER: F N Rockwell International Garp 2pp Program 15574.310
- --8208270363 IE Safeguards Insp Rept 70-0025/82-06 on 920712-16 & 19-23 No noncompliance moted Major areas inspected measurements control plan, shippar-receiver verification, internal control & mgt of matl control. Details withheld (ref 10CFR2 790), MIEDER, A V. NELSUN, 0.3 , NORDERHAUG, L R Division of Radiological Eafety & Safeguards Program 62/08/19 10 15574-312

BOCKET 70-0027 BABCOCK & WILCOX CO , LYNCHBURG, VA

- 8208630012 Advises that Bafeguards Amend MPP-1 to License BNM-42 is revised changing License Condition 2 1 & adding Condition 3.7 re estimates of U content in liquid discharges, per 820317 request EVANS.L J. Fuel Facility Bafeguards Licensing Branch 82/05/05 KELLY.J W Babcock & Wilcox Co 2pp. 14208-346
- 8208030043 Revises Bafeguards Amend MPP-1 to License SNM-42, adding two new license conditions allowing use of shipper values for SKM content of fuel plates & extending requirement for receipt verification to 72-h.

 EVANG.L.J. Fuel Facility Safeguards Licensing Branch 82/05/28 KELLY-J W. Babcock & Milcox Co. 2pp 14208:325
- B20B040134 Advises that addl info is required for B20609 request for exemption from 10CFR70.51(e)(4) & 70 57(b)(9) recomputation of limit of error of inventory difference. EVANSIL J. Fuel Facility Bafeguards Licensing Branch. 82/04/29. KELLY, J W Babcock & Wilcox Co. 2pp 14228.336.
- 8208030342 Forwards IE Safeguards Insp Rept 70-0027/82-12 on 820712-16. CONSISTS PROPERTY AND ANALYSIS OF THE CONTROL OF TH
- --8208030347 IE Safeguards Insp Rept 70-0027/82-12 on 820712-16. No noncompliance noted Major areas inspected; scrap/waste drum measurements & inventory verification Details withheld measurements & savenest y vertical control of Engineering & Technical Programs, 82/07/27, lp. 14155-355,

- 8208160487 Forwards IE Insp Rept 70-0027/82-14 on 820712-16 No noncompliance noted GIBSON, A F Division of Engineering & Technical Programs 82/07/27 ECKERT, J P. Babcock & Wilcox Co 2pp 14348 307
- --B20B160497 IE Insp Rept 70-0027/82-14 on B20712-16 No noncompliance noted. Hajor areas inspected nuclear criticality safety, facility changes & mods, safety committees, operations & training CORYELL.0 P , CLAY.E L , MCALPINE,E J Division of Engineering & Technical Programs 82/07/26 5pp 14248 311
- 9208230326 Forwards IE Bafeguards Insp Rept 70-0027/82-17 on 820802-06 No noncompliance noted GIBSON, A F Division of Engineering & Technical Programs 82/08/18 ECKERT, J P Babcock & Wilcox Co 2pp 14508 264
- --8208230329 IE Safeguards Insp Rept 70-0027/82-17 on 820802-06 No noncompliance noted Major areas inspected review of security plan & implementing procedures records & repts & security program audit Details withheld (ref 100FR73 21) MORE.D E , MCGUIRE.D R Division of Engineering & Technical Programs 82/08/17 1p 14508 266
- DOCKET 70-0033 TEXAS INSTRUMENTS, INC , ATTLEBORO, HA
- 8208060022 Requests assistance in confirmatory survey of TX
 Instruments, Inc property prior to termination of License
 8KM-23
 PAGE:R O Uranium Fuel Licensing Branch 82/07/28 STARGSTECKI.R
 Division of Project & Resident Programs 1p 14244,353
- DOCKET 70-0036 COMBUSTION ENGINEERING, INC., WINDSOR, CT
- 8208020297 Forwards IE Safeguards Insp Rept 70-0036/82-03 on 820829-0702 No noncompliance noted MILLER, J.R. Division of Engineering & Technical Programs 82/07/15 LICHTENBEROER Combustion Engineering, Inc. 2pp 14150 077
- --9208020302 IE Bafeguards Insp Rept 70-0036/82-03 on 820629-0702 No noncompliance noted Major areas inspected inventory & inventory verification Details withheld (ref IOCFRZ 700) FINLEY, A O., BLAYLOCK, J., CREED, J. R. Division of Engineering & Tachnical Programs 82/07/14 ip 14150 079
- 3208310349 Forwards addendum to IE Safeguards Insp Rept 70-0036/82-03 on 820627-0702 No noncompliance noted Addendum withheld (ref 10CFR2 790)
 MILLER-J R Division of Engineering & Technical Programs 82/08/16
 LICHTENBERGER Combustion Engineering, Inc. 2pp. 14693 060
- GCKET 70-0113 PENNSYLVANIA STATE UNIV. , UNIVERSITY PARK, PA
- 8208020364 Discusses IE Insp Rept 70-0113/82-01 conducted on B20428 No noncompliance noted Major areas inspected:outer end-cap usids of Pu/Be sealed sources MARTIN.T. Division of Engineering & Technical Programs 82/07/29 CUNNINOMAN,R Q Pennsylvania State Univ. 2pp £4150 109
- DOCKET 70-0135 BABCOCK & WILCOX CO . APOLLO, PA
- B208050308 Forwards IE Bafeguards Insp Repts 70-0135/82-05 & 70-034/82-04 on B20614-18. No noncompliance noted MARTIN: T T. Division of Engineering & Technical Programs. B2/07/22 CARLSON: R V Babcock & Wilcox Co 2pp 14211-194
- --B208050319 IE: Bafeguards Insp Repts 70-0135/82-05 & 70-0364/82-04 on B20614-18 No noncompliance moted Major areas inspected statistical controls internal controls hisper-receiver, inventory difference & limit of error verification WOLTNER.E., COHEN.I., OODY, A.T. Division of Engineering & Technical Programs 82/07/15 3pp 14211.176
- 8208230463 Informs that Div of Accounting & Finance notified to refund amend fee for 801104 & 820611 applications HILLER, W O License Fee Management Branch 82/08/06 AUSTIN, M A Babcock & Wilcox Co 1p. 14518 360
- 8208300221 Forwards IE Bafeguards Insp Rept 70-0135/82-06 on 820712-16 No noncompliance noted MARTIN, T T. Division of Engineering & Technical Programs. 82/08/11 CARLEON, R.V Babcock & Wilcox Co 2pp 14679-005

- ---8208300227 IE Insp Rept 70-0135/82-06 on 820712-16 No noncompliance noted Major areas inspected measurement & statistical control IIBULERY, H , OUDY, A T Division of Engineering & Technical Programs 82/08/09 3pp 14679 007
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC . ERWIN, TN
- 8208160496 Responds to NRC 820211 comments on IE Insp Rept 70-0143/61-36 re improvements made & evaluation of environ air impinger program since 610211 update No major changes anticipated impinger sys will continue MANSER.W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 82/05/27 O'REILLY, J P Region 2, Office of Director Spp 14348 280
- 8208030034 Revises Amend MPP-1 to License SNM-124, adding license condition granting one-day-only exemption from License Condition 2 19 & Section 1 12 1 1 of plan identified in License Condition 2 1 re SNM shift supervisors EVANS, L J Fuel Facility Safeguards Licensing Branch 82/05/28 HENSLEY, K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 14200 359
- 8208040147 Revises Amend MPP-1 to License SNM-124, granting request for exemption from 10CFR70 51,70 57 & 70 58 re high enriched U bearing const waste drums & incorporating add1 measures, in response to 820521 ltr EVANS.L J Fuel Facility Safeguards Licensing Branch 82/06/21 HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Dil Co) 2pp. 14228 354
- 8208040172 Advises that 820601 request for mod to procedure re search of individuals exiting math access areas acceptable EVANS.L J Fuel Facility Safeguards Licensing Branch 82/07/07 HICHEL,C J Nuclear Fuel Services, Inc (subs of Getty Oil Co) ip 14229 357
- 8207110003 FOIA request for NRC repts re inventory differences at NFS plant in Erwin, TN from 1976-81 & related correspondence between NRC & vendor for same time period BARLETI, D L. Fhiladelphia Inquirer 82/07/14 FELTON, J M Division of Rules and Records 1p 14362 108
- 8208030129 Forwards IE Safeguards Insp Rept 70-0143/82-25 on 820601-14. No noncompliance noted GIBSON. A F Division of Engineering & Technical Programs 62/07/14 MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Dil Co) 2pp 14160.023
- --9208030131 IE Safeguards Insp Rept 70-0143/82-25 on 820601-14 No noncompliance noted Major areas inspected facility operation, criticality safety, radiation protection, environ protection, hypical protection & SNM control LEE.T L , MCALPINE, E. J Division of Engineering & Technical Programs 82/07/13 5pp 14160 025
- 8208140081 Documents 820623 telcon re licensee 820518 ltr & 820527 procedures NRC agrees w/arrangements for providing unescorted access to plant protected areas for inspectors identified in NRC 820412 ltr D'REILLY, J P Region 2, Office of Director 82/07/21 MANSER, M.C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 14342 130
- B20B030656 Ack receipt of B20707 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 70-0143/82-21.
 OIBBON.A F Division of Engineering & Technical Programs 82/07/22 MANSER.W C Nuclear Fuel Services, Inc. (subs of Getty Dil Co) 1p. 14162-124
- --8208030563 Responds to NRC 620616 ltr re violation noted in IE Safeguards Insp Rept 70-0143/82-21 Corrective actions audit plan under development for thorough audit of matl control & accountability MANSER, W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) 82/07/09 LISHINSKI, J A Division of Engineering & Technical Programs 2pp 14162 127
- --8208030669 Forwards IE Safeguards Insp Rept 70-0143/82-21 on 820317-21 to notice of violation. Details & notice of violation withheld (ref 10CFR2 790).

 OLGHINSKI, J. A. Division of Engineering & Technical Programs.

 B2/06/16 MANSER, W.C. Nuclear Fuel Services, Inc. (subs. of Ostty. Oil Co.) 2pp 14162, 127
- ---G208030685 IE Bafeguards Insp Rept 70-0143/82-21 on 820517-21
 Noncompliance noted failure to conduct audit of matl control
 & accounting sys Details withheld (ref 10CFR2.790)
 JONES, D.W., RICHARDS, B.L., MCALPINE, E.J. Division of Engineering &
 Technical Programs 82/06/10 ip 14162 131

DOCKETED ITEMS

- 8208160225 Confirms 820721 telcon agreement re listed corrective actions to be performed to control leakage of U-bearing liquids from underground piping O'REILLY, J.P. Region 2. Office of Director 92/07/23 MANSER, W.C. Ruclear Fuel Services, Inc. (subs. of Oatty Oil Co.) 2pp 14346-322
- 8208190035 Advises of issuance of Amend 17 to License SNM-124, eliminating Amend 14 dtd 820519 Corrected date for completion of decontamination & decommissioning of U-233 facilities is 830101,as stated in Amend 5 FAGE.R 9 Uranium Fuel Licensing Branch 82/07/30 MICHEL, C J. Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) ip 14507 026
- 8208250526 Responds to FOIA request for NRC repts re inventory differences at NFS plant in Erwin.TN from 1976-81 & related correspondence between vendor & NRC Forwards list of insps parformed from 1978-81 FELTON, J M Division of Rules and Records 82/07/30 BARLETT, D L Philadelphis Inquirer 2pp 14562 109
- --8209250531 "Insp Rept Summarization, Hatl Control & Accountability Insp. NFS, Inc." Jan 1978-Dec 1981 4 NRC - No Detailed Affiliation Given 81/12/31 11pp
- B208160205 Ack receipt of 820719 ltr.transmitting rept of investigation re bloassay program Ltr satisfies commitments stated in vendor 820702 ltr.Addl details re QC checks for verification of stock & info re participating labs expected on 820816 QISSON A F Region 2. Office of Director 82/08/03 MANSER,W C Nuclear Fuel Services, Inc (subs of Oetty Qil Co) ip 14344 142
- 8208160478 Ack receipt of IE Insp Rept 70-0143/82-25. No proprietary info HANSER: W.C. Nuclear Fuel Services, Inc. (subs of Getty Oil Co.) 82/08/03. QIBSON, A.F. Division of Engineering & Technical Programs ip 14348-266
- 8208110105 EN-82-027 on 820809 notices of violation & proposed imposition of civil penalties will be issued Action based on violation re inadvertent shipment of low enriched licensed matl in drums supposed to be empty ROSANO.R., LIEBERMAN.J Director's Office, Office of Inspection and Enforcement 82/08/04 ip 14314 327.
- 8208090164 Revised notice of hearing, amending 800121 hearing schedule Issues to be decided at hearing include existence of changed circumstances, amend to License BNM-124 & consequences of revoking license.
 HOYLE, J. C. Office of the Secretary of the Commission 82/08/06, 3pp. 14270 323
- 8208240112 Informs that Div of Accounting & Finance will refund portion of anend fee submitted for Bafeguards Amend MPP-1 of License SMM-124
 MILLER, W O License Fee Management Branch. 82/08/11 HENBLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 1p. 14739-280
- 8208260619 Advises that NRC cannot accept or act on 820420 application for onside burial of contaminated wastes under branch technical position provisions, Position not applicable to request PAGELR G. Uranium Fuel Licensing Branch 82/08/17, MICHEL.C J Nuclear Fuel Barvices, Inc. (subs. of Getty Oil Co.). 19 14367-360
- 8208270424 Informs of Dil, Chemical & Atomic Workers Intl Union participation in hearing on Licenss 8NM-124.
 HIBBRENER, J M. Dil, Chemical & Atomic Workers Intl 82/08/24
 HOYLE, J. C. Diffice of the Secretary of the Commission. 1p 14565-244.
- 8208270450 Notice of plans to file affidavit executed by senior Nevy official re Dept of Navy compelling need for nuclear fuel produced by NFB CORNELIUS.R M. Office of the General Counsel 82/08/26 2pp 14363 256.
- 820830010B Answer to Commission 820806 revised notice of hearing.NRC plans to participate in hearing Certificate of Syc encl. FDNNER,R.L. Regulations Division 82/08/26 5pp 14596-117.
- 8208300322 Answar advising that DOE will participate as party in proceeding Certificate of Svc encl. LEIKEN, L. 8 Energy, Dept of 82/08/27, 4pp 14599:080.

- DOCKET 70-0184 WESTINGHOUSE ELECTRIC CORP , HORSEHEADS, NY
- 8208170073 Forwards IE Bafeguards Insp Rept 70-0184/82-01 on 820630-0702.No noncompliance noted MARTIN.T T. Division of Engineering & Technical Programs 82/08/02 Westinghouse Electric Corp 2pp 14358-123
- --8208170077 IE Safeguards Insp Rept 70-0184/82-01 on 820430-0702 No noncompliance noted Major areas inspected facility organization & operation, internal control, shipper-receiver verification & records & repts RATTA: A D , 000Y; A T Division of Engineering & Technical Programs. 82/07/28 5pp 14358 125
- DOCKET 70-0190 CATHOLIC UNIV OF AMERICA, WASHINGTON, DC
- 8208250256 Discusses IE Insp Rept 70-0190/82-01 conducted on 820729 No noncompliance noted. Major areas inspected activities re Pu/Be sealed source end caps MARTIN.T T Division of Engineering & Technical Programs 62/08/23 KEENE, W Catholic Univ 2pp. 14554 297
- DOCKET 70-0261 SCHLUMBERGER TECHNOLOGY CORP , RIDGEFIELD, CT
- 8209180083 IE Insp Findings & Licenses Ack dtd 820803 of Licenses SMM-239 & 06-00807-01 Insp findings no noncompliance noted FRIEDMANL F Region 1, Office of Director 82/08/03 1p. 14376 347
- DOCKET 70-0273 NATIONAL CARBON CO., FOSTORIA, OH
- 8208230200 Forwards IE insp Rept 70-0279/82-01 on 820628 No nencompliance noted MARTINIT T. Division of Engineering & Technical Programs 82/08/06 KOZAK, P. E. Union Garbide Corp 2pp 14513:267
- --8208230208 IE Insp Rept 70-0273/B2-01 on 820628 No noncompliance noted Major areas inspected:special announced closeout insp of formerly licensed site including review of records & site surveys

 JOHANSEN, J. K., KINNEMAN, J. D. Division of Engineering & Technical Programs KELLY, R. F., New York, State of B2/07/28, lipp 14513-272
- --B208230213 Forwards License 31-02050-01 authorizing use of sealed sources HITCH J W Atomic Energy Commission 57/02/18 STAMBAUGH, R P Union Carbide Corp 15pp 14513 283
- --8208230219 Application for renewal of Matl Byproduct License 31-02080-01 authorizing use of Cs-137 & Co-60 to measure density of carbon. * Union Carbide Corp 58/01/05 36pp 14513 298.
- DUCKET 70-0303 CARNEGIE-MELLON UNIV , PITTSBURCH, PA
- 6208260257 Discusses IE insp of License 6NM-281 on 620722-23 No noncompliance noted. Major areas inspected: PU/Be sealed source end cap welds per DDE recommendation MARTIN T T Division of Engineering & Technical Programs 82/08/23 SHATZ, E Carnegie-Metlon Univ 2pp 14554: 286
- DOCKET 70-0356 NUCLEAR RESEARCH CORP. , DOVER, NJ
- 8208160019 Discusses IE Insp Repts 30-05302/82-02 & 70-0356/82-01 on 82030B; 10 & 11 & forwards notice of violation.

 MARTIMIT T Division of Engineering & Technical Programs. 82/07/30 COOLEY, J. Nuclear Research Corp. 3pp 14344:337.
- --9208140022 Notice of violation from inep on 820308,10 & 11
 Noncompliance noted: surveys not made to assure that licensed mat1 not inadvertently disposed of in unauthorized menner & radioactive mat1 transported w/o proper label HARTIN.T T Division of Engineering & Technical Programs 82/07/30. 4pp 14344:340

DOCKET 70-0359 PITTSBURGH, UNIV OF, PITTEBURGH, PA

- 8208260143 Discusses IE Insp Rept 70-0359/82-01 conducted on 820731 No nancompliance moted. Major areas inspected activities re Pu/Be sealed sources & exam of welds associated w/Pu/Be bources.
 - MARTIN.T T Division of Engineering & Technical Programs 82/08/23 DURKOSH,E D Pittsburgh, Univ of 2pp. 14554-359

DOCKET 70-0364 BABCOCK & WILCOX CO . APOLLO, PA

- 8208050308 Forwards IE Safeguards Insp Repts 70-0135/82-05 & 70-0364/82-04 on 820614-18 No noncompliance noted MARTIN: T. Division of Engineering & Technical Programs 82/07/22 CARLSON: R. V Babcock & Wilcax Co 2pp i4211 194
- --B208050317 IE Safeguards insp Repts 70-0135/82-05 & 70-0364/82-04 on B20614-18 No noncompliance noted Major areas inspected statistical controls internal control, shipper-receiver, inventory difference & limit of error verification WOLTNER.E., COHEN, I., CODY, A.T. Division of Engineering & Technical Programs 82/07/15 3pp 14211 196
- 8208230463 Informs that Div of Accounting & Finance notified to refund amend fee for B01104 & 820611 applications MILLER.W.O License Fee Management Branch 82/08/06 AUSTIN, M A Babcock & Wilcox Co Ip 14518-360

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC . UNCASVILLE, CT

- 820B100245 Forwards IE Insp Rept 70-0371/82-08 on 820713-16 No noncompilance noted STAROSTECKI, R. Division of Project & Resident Programs 82/07/26 AMY, 0, 0 United Nuclear Corp 2pp. 14294 292.
- --820BiO024B IE Insp Rept 70-0371/82-0B on B207i3-16 No nuncompliance noted Major areas inspected organization, facility changes & mods, review of operations & transportation activities, RGTM, J. KEIMIG.R R. Division of Project & Resident Programs B2/07/22 Spp 14274'294
- 8208250450 Informs of partial refund due on fee submitted w/810901 application to amend License SNM-368 MILLER.W O License Fee Management Branch 82/08/17 KIRK, W F United Nuclear Corp ip 14562:292

DOCKET 70-0398 COMMERCE, DEPT OF, WASHINGTON, DC

- 8208300191 Notifies that encl IE Insp Rept 70-0398/82-01 conducted on 820604 assigned incorrect number Rept number should be changed to 70-0398/82-04 MARFLM, T T Division of Engineering & Technical Programs 82/08/23 PEVEY, L E Commerce, Dept of, National Bureau of Standards, 1p
- --8208900193 Discusses IE Insp Rept 70-0398/82-01 conducted on 820804 No noncompliance noted Major areas inspected activities conducted under license re Pu/Be sealed sources MARTIN,T. T. Division of Engineering & Technical Programs. 82/07/09 PE/EY,L E. Commerce.Dept of, National Bureau of Standards. 2pp 14678-240

DOCKET 70-0511 ST. PETER'S COLLEGE, JERSEY CITY, NJ

- B207080350 Discusses IE Insp Rept 70-0511/82-01 conducted on 820601 No noncompliance noted Major areas inspected review of activities conducted under license re Pu/Be sources MARTIN, T T Division of Engineering & Technical Programs 82/07/08 RAPKIN,M 8t Peter's College 2pp 13763 340
- DOCKET 70-0600 SEATTLE UNIV , SEATTLE, WA
- 8208030162 Forwards IE Bafeguards Insp Rept 70-0600/82-01 on 820721 No noncompliance noted NGRDERHAUGL Division of Radiological Safety & Safeguards Program, 82/07/29 IIMMERMAN, O.A. Beattle Univ. 2pp. 14160, 018
- -8208030167 IE Safeguards Insp Rept 70-0600/82-01 on 820721 No noncompliance noted Major areas inspected:SNM protection, security plan & procedures physical barriers detection aids & surveillance Details withheld (ref 10CFR2,790).

 8CHWAN, C A , MCGUEEN, A. , BCHUBTER, M D. Division of Radiological Safety & Safeguards Program 82/07/29 ip 14160,020,

- DOCKET 70-0624 QULF RESEARCH & DEVELOPMENT CO , PITTSBURGH, PA
- 8208120157 Discusses IE insp Rept 70-0624/82-01 conducted on 820715 No noncompliance noted Major areas inspected activities re Pu/Be scaled sources MARTIN.T T Division of Engineering & Technical Programs 82/08/09 LARUE, H A Quif Oil Corp 2pp 14323 263

DOCKET 70-0625 HOWARD UNIV , WASHINGTON, DC

- 8208230300 Discusses IE Insp Rept 70-0625/82-01 conducted on 820729 No noncompliance noted Hajor areas inspected sealed source Pu/Be outer end cap welds per DDE recommendation MARTIN, T T Division of Engineering & Technical Programs 82/08/19 FEROUSON, O Howard Univ 2pp 14509 336
- DOCKET 70-0629 WASHINGTON & JEFFERSON COLLEGE, WASHINGTON, PA
- 8208260265 Discusses IE insp of License SNM-568 on 820721 No noncompliance noted Major areas inspected Pu/De sealed source end cap welds per DDE recommendation MARTIN.T T Division of Engineering & Technical Programs, 82/08/23 BELSKI.A Washington & Jefferson Cullege 2pp 14552 396

DOCKET 70-0687 UNION CARBIDE CORP , TUXEDO, NY

- 8208230182 Forwards IE Insp Rept 70-0687/82-05 on 820628-0702 No noncompliance noted STARRSTECKI.R Division of Project & Resident Programs 82/08/03 MCGOVERN, J J Union Carbide Corp 2pp 14514 340
- --8208230184 IE Insp Rept 70-0687/82-05 on 820628-0702 No noncompliance noted Major areas inspected. Licensed programs including organization, facility changes & mods, internals review & audit & licensee action on previously identified items. ROTH. J. KE INIG.R R Division of Project & Resident Programs 82/08/02 13pp 14514 342
- B20B270966 Issues Amend B to License SNM-639, revising Items 6B & 9 to authorize increase in possession limits of U-235 to 23 kg, in form of irradiated targets & subsequent process & waste forms, in response to B20720 request ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch VOTH, N H Union Carbide Corp 2pp 14683 279.
- --8208270370 Safety evaluation supporting Amend 8 to License GNM-639, authorizing increased possession limits of U-235 TINO-U-W ROUSEL C Advanced Fuel & Spent Fuel Licensing Branch 82/08/18 2pp. 14683 281
- DOCKET 70-0734 GENERAL ATOMIC CO , SAN DIEGO, CA
- B20B020439 Revises License Condition 2 1 of Safeguards Amand MPP-1 to License SKM-696, incorporating revisions to Sections 3 0 & 5 0 of Fundamental Nuclear Matl Control Plan EVANS, L J Fuel Facility Safeguards Licensing Branch B2/05/26 MDWRY, W R. GA Tachnologies, Inc./General Atomic Co ip 14181 033
- 8208040161 Forwards list of items in existing fundamental nuclear math control plan needing revision & areas in Chapters 20 & 21 of revised Category I fixed site facility physical protection plan needing further revisions M/o encls
 EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/06/21
 MCNRY, W. R. OA Technologies, Inc./Oeneral Atomic Co. 2pp. 14237-116
- 8208110010 Advises that invoice for add1 fee will be issued for review of licenses 820608 request for approval of route to be used for shipment of spent fuel.

 MILLER, U.O. License Fee Management Branch 82/07/29 MOWRY, W.R. OA Technologies, Inc./General Atomic Co. ip 14330 293
- 820813000B Forwards comments on 810724 application for renewal of License SNM-696.as supplemented on 820316 Addl info needed Meeting suggested prior to formal submittal of responses KETZLAGN.N. Upantum Fuel Licensing Branch 82/08/02, MOWRY: W. OA Technologies, Inc /General Atomic Co 33pp 14336 241
- 8208270413 Forwards IE Safeguards Insp Rept 70-0734/62-07 on 820810-12 No noncompliance noted. NGRDERHAUG,L., R Division of Radiological Safety & Safeguards Program 82/08/23, PARKER,J W. GA Technologies, Inc /General Atomic Co 2pp. 14566-016

- --8203270425 IE Safeguards Insp Rept 70-0734/82-07 on 820810-12 No noncompliance noted Major areas inspected security plansimplementing procedures organization, mpt & program audit & physical barriers Details withheld (ref 10CFR2 790) MCOUERN A D. SCHUSTER.M D. Division of Radiological Safety & Safeguards Program 82/08/20 ip 14566-018
- DOCKET 70-0754 GENERAL ELECTRIC CO , PLEASANTON, CA
- E208270369 Forwards IE Insp Rept 70-0754/82-02 on 820601-04 No noncempliance noted 800K.H E Division of Radiological Safety & Safeguards Program 82/07/27 DARMITZEL,R W General Electric Co 2pp 14565 018
- DOCKET 70-0820 UNITED NUCLEAR CORP , WOOD RIVER JCT , RI
- E208340039 Forwards comments on revised State of RI draft agreement, submitted May 1982, re decommissioning of United Nuclear Corprescovery sys Apparent goals of State of RI cannot be accomposated within Atomic Energy Act & NRC regulations.
 SHEA, X Lowerstein, Newman, Reis, Azelrad & Toll BHEA, K H United Nuclear Corp 82/07/13 CUNNINGHAM, R C Division of Fuel Cycle & Material Safety 16pp 14237 146
- 82\03100255 Forwards IE Insp Rept 70-0820/82-07 on 820715-16 & notice of vicilation
 6TAROSTECKI, R Division of Project & Resident Programs, 82/07/27
 AMY-0 D United Nuclear Corp 2pp 14294 356
- --8208300259 Notice of violation from insp on 820715-16 STAROSTECKI.R Division of Project & Resident Programs 82/07/27 Ip 14294 358
- --B208100263 IE Insp Rept 70-0820/82-07 on 820719-16 Noncompliance noted, failure to maintain fenced, encl. accessible only to employees area around stored drums in parking lot ROTHLJ. KEINIG.R R Division of Project & Resident Programs 82/07/26 4pp 14294 359
- DOCKET 70-0824 BABCOCK & WILCOX CO , LYNCHDURG, VA
- 8208030330 Forwards IE Insp Rept 70-0824/82-04 on 820414-16 No mancapiliance noted GIGSON A F Division of Engineering & Technical Programs 82/07/14, EI/GELDER.T. C Babcock & Wilcor Co 2pp 14197 061
- --8208030333 IE Insp Rept 70-0824/82-04 on 820614-16 No noncompliance noted Major areas inspected [CCFR21 implementation. organization. safety committees, internal review & audit, facifity changes & mode & nuclear criticality safety TRGUP, 8 L , MCALPINE, E J Division of Engineering & Technical Programs 82/07/13 5pp 14157 063
- DOCKET 70-0925 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY. OK
- 8208100821 Forwards repts of release of SNM in effluents to unrestricted area during first half of 1982, per 10CFR70 59 & Rag Guide 1 21.App B SHELLEY, W J. Kerr-HcOse Corp 82/07/29 KEPPLER, J. G. Region 3, Office of Director 1p 14294 341
- --B208100225 Repts of release of 8NM in effluents to unrestricted area during first half of 1982 + Kerr-McGee Corp B2/07/29 2pp 14294.342
- DOCKET 70-0938 MASSACHUSETTS INSTITUTE OF TECHNOLOGY. CAMBRIDGE, MA
- 8208230344 Ack receipt of 820807 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0938/82-01 STAROSTECKI, R. Division of Project & Resident Programs 82/08/18 CLARK, L. Massachusetts Institute of Technology Ip 14508-281.

- --8208230350 Responds to NRC 820713 ltr reviolations noted in IE Insp Rept 70-0938/82-01 Corrective actions instructions re 12-inch spacing requirement clarified & posted for storage of SMM & source math in vaults CLARK.L Massachusetts Institute of Technology 82/08/09 BTARGSTECKI.R Division of Project & Resident Programs 1p 14508 282
- DOCKET 70-0968 GANNON COLLEGE, ERIE, PA
- 8208120094 Discusses IE Insp Rept 70-0968/82-01 conducted on 820714 No moncompliance noted Major areas inspected Pu/Ba sealed sources, including selective stams of procedures, personnel interviews & inspector measurements & observations MARTIN, T T Division of Engineering & Technical Programs. 82/08/09, ORIESACKER, P D Oannon College ER, Pennsylvania 2pp 14327 152
- DOCKET 70-1068 FLORIDA, UNIV OF, GAINESVILLE, FL
- 8208130274 Forwards IE Safeguards Insp Repts 50-083/82-01 & 70-1068/82-01 on 820629-0701 No noncompliance noted VERRELLI.D Division of Project & Resident Programs 82/07/19 JACOBS.A H Florids. Univ of, Gainesville 2pp. 14336 317 24X Fiche 50-083, 82/07/19, 8208130294
- --8208130299 IE Safeguards insp Repts 50-083/82-01 & 70-1068/82-01 on 820629-0701 No noncompliance noted Major areas inspected: security plan & organization, access controls, records & repts & physical barriers Datails withheld (ref 100FR2 790) MODRE, D.E. MCGUIRE, D.R. Division of Engineering & Technical Programs 82/07/15. 1p 14336-319 24X Fiche, 50-083, 82/07/19, 8208130294
- DOCKET 70-1113 GENERAL ELECTRIC CO . WILMINGTON: NO
- 8208030235 Forwards IE Safeguards Insp Rept 70-1113/82-13 on 820621-25, No noncompilance noted 01860k A F Division of Engineering & Technical Programs 82/07/19 LQNO, J A General Electric Co 2pp 14159 062
- --8208030243 IE Bafeguards insp Rept 70-1113/82-13 on 820621-25 No noncompliance noted Major areas imspected physical inventory varification & production enrichment analyser Details withheld (ref 10CFR2 790) CLAY.E L - MCALPINE.E J Division of Engineering & Technical Programs 82/07/19 ip 14159 064
- 8208270550 Confirms 620719 telcon re 620806 meeting to discuss experimental procedures being implemented for measuring airborne U particle size distributors & solubility characteristics. Comments on sample splitting requested MCLAIN.M. E. Oeneral Electric Co 62/07/19 SHUM.E. NRC No Detailed Affiliation Given 1p 14683 207
- 8208030132 Ack receipt of 820714 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/82-10 01880N.A F Division of Engineering & Technical Programs B2/07/26 LONG J A General Electric Co Ip 14160-074
- --8208030135 Responds to NRC 820615 ltr reviolations noted in IE Insp Rept 70-1113/82-10 Corrective actions auditors to be instructed in proper survey techniques w/emphasis on speed & distance considerations VAUGHAN, G. H. General Electric Co. 82/07/14 GIBSON, A.F. Division of Engineering & Technical Programs, Spp. 14160, 075
- --8208030137 Forwards IE Insp Rept 70-1113/82-10 on 820517-21 & notice of violation of Engineering & Technical Programs. 82/06/15 LONG, J A General Electric Co. 2pp 14160.078.
- --8208030141 Notice of violation from insp on 820517-21 a Region 2, Office of Director 82/05/15. ip 14160:080.
- --8208030145 IE Insp Rept 70-1113/82-10 on 820517-21. Noncompliance notes; on 820520 & 21, individuals exited controlled area w/o performing personal contamination monitoring HOSEY, C. M. BARR, K.P. Division of Engineering & Technical Programs 82/06/15 Spp 14160-081
- 8208030293 Forwards IE Bafeguards Insp Rept 70-1113/82-15 on 820712-16. No noncompliance noted GIBBONA F Division of Engineering & Technical Programs. 82/07/28. LONG.J A Ceneral Electric Co. ip. 14155.350

- --8208030304 IE Safeguards Insp Rept 70-1113/82-15 on 820712-16 No noncompliance noted Major areas inspected measurement control program & verification of export SNM shipment & tampersefing Details withheld (ref 10CFR2 790) 8ATES, J W. MGALPINE, E J Division of Engineering & Technical Programs 82/07/28 ip 14155:352
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGE, PA
- 8208040187 Advises that computer generated forms may be used in lieu of Forms DDE/NRC-742 & 742C for licenses listed in 820406 ltr & future licenses Licenses requiring fundamental nuclear matl control plan will need specific condition EVANB, L, J Fuel Facility Safeguards Licensing Branch 82/06/08 NARDI, A J Westinghouse Electric Corp. 1p 14232 263
- 8208050027 Discusses vendor intent to release 1.875 lb molybdenom scrap after 820721 Release acceptable BIDINGER:0 H Urentium Fuel Licensing Branch 82/07/27. Urentum Fuel Licensing Branch 2pp 14244 340
- 8208110092 Advises that NMBS has no objection to unrestricted release of 1.875 lb of molyddenum scrap which has been decontaminated & surveyed as described in licensee 820621 molybdenum decontamination & surveillance rept. PAOE,R 0. Uranium Fuel Licensing Branch. 82/07/27. REITLER.E K Westinghouse Electric Corp. 1p. 14331 061
- 8208030134 Ack receipt of 820720 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/82-12
 01880N.A F. Division of Engineering & Technical Programs 82/07/28
 D'AMORE,M Westinghouse Electric Corp ip 14160.089
- --8208030137 Responds to NRC 820624 ltr re violations noted in IE Insp Rept 70-1151/82-12 Corrective actions:details of cutting & welding policy reviewed w/non-Hestinghouse cutting & welding operators. D'AMORE.H Hestinghouse Electric Corp 82/07/20 G'REILLY.JP Region 2, Office of Director 3pp. 14160:090
- --8208030144 Forwards IE Insp Rept 70-1151/82-12 on 820602-03 & notice of violation.
 OIBSONA F Division of Engineering & Technical Programs 82/06/24 D'AMORE, M. Heatinghouse Electric Corp. 2pp. 14160.093
- --8208030146 Notice of violation from insp on 820602-03 * Region 2, Office of Director 82/06/24 ip 14160 095
- --B208030148 IE Insp Rept 70-1151/82-12 on B20602-03 Noncompliance noted failure to observe fire prevention procedures for safeguarding welding & cutting operations OIBBONS.T D., MILLER, W.H., CONLOW, T.E. Division of Engineering & Technical Programs. 82/06/23. 7pp 14160 094
- 8208030629 Forwards IE Safeguards Insp Rept 70-1151/82-13 on 820706-09 No noncompliance noted GISSON.AF, Division of Engineering & Technical Programs 82/07/28 D'AMOREM Westinghouse Electric Corp 2pp 14162 123
- --B208030639 IE Safeguards Insp Rept 70-1151/82-13 on 820706-09.
 No noncompliance noted Major areas inspected: MC B3206B measurement control & statistics Details withheld (ref 100FR2.790).
 BABADDS, J.W. Division of Project & Resident Programs MCALPINE. E.J. Division of Engineering & Technical Programs 82/07/28 1p. 14162 125
- DOCKET 70-1173 HERCYHURST COLLEGE, ERIE, PA
- 9208260227 Discusses IE Insp Rept 70-1173/82-01 conducted on 820722. No noncompliance noted Major areas inspected review of activities re Pu/Bs sealed sources & analysis of wipe sample taken from each cap welf area HARTIN.T. Division of Engineering & Technical Programs. 82/08/23 MATHEWS,M Mercyhurst College. 2pp. 14554.301.
- DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8208100221 Forwards repts of release of SNM in effluents to unrestricted area during first half of 1982, per 10CFR70. 59 & Reg Ouide 1.21. App B SHELLEY, H. J. Kerr-McDee Corp. 82/07/27 KEPPLER, J. G. Region 3, Office of Director 1p. 14274:341

- --8208100225 Repts of release of SNM in effluents to unrestricted area during first half of 1982 4 Kerr-McGee Corp 82/07/29 2pp 14294 342
- DOCKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA
- B208160424 Submits addl info re NRC 811101 ltr concerning violations noted in IE Insp Rept 70-1201/81-04 Appropriate changes re sys for detaction of potential diversion can be improved & implemented Detailed data sys discussion encl ALTO,R A Babcock & Wilcox Co 82/04/29 OIBSON,A F Division of Engineering & Technical Programs App 14348 147
- 8208D40163 Advises that page changes to physical security plan, submitted 820407, acceptable for inclusion into plan EVANS.L J Fuel Facility Safeguards Licensing Branch 82/08/20 FORD.J T Babcock & Wilcox Co ip 14237 119
- 8208030039 Revises License Condition 2 i of Bafeguards Amend MPP-2 to License 6NM-1168, incorporating Fundamental Nuclear Matl Control Plan changes dtd 820407 EVANS, L. J. Fuel Facility Bafeguards Licensing Branch 82/05/26 FGRD, J. T. Babcock & Wilcox Co. 1p. 14200 361
- 8208030040 Revises License Condition 2 i of Safeguards Amend MPP-2 to License SNM-1168, incorporating Fundamental Nuclear Matl Control Plan changes dtd 820331 EYANS,L J Fuel Facility Safeguards Licensing Branch 82/05/26 FORD,J T Babcock & Wilcox Co ip 14200 362
- 8208030316 Forwards IE Insp Rept 70-1201/82-08 on 820616-18 No noncompliance noted QIBSON.A F Division of Engineering & Technical Programs 82/07/15 ALTO,R A Babcock & Wilcox Co 2pp 14157-126
- ---8208030324 IE Insp Rept 70-1201/82-08 on 820616-18 No nancompliance noted Hajor areas inspected organization, facility changes & mods, safety committees, operations & previously identified items
 YROUP, 0 L., MCALPINE, E. J. Division of Engineering & Technical Programs 82/07/13 4pp 14157 128
- 8208030505 Forwards 1E Safeguards Insp Rept 70-1201/92-10 on 820628-0701 No noncompliance noted 01880N A F Division of Engineering & Technical Programs 82/07/27, ALTO,R A Babcock & Wilcox Co 2pp 14162 298
- --8208030515 IE Safeguards Insp Rept 70-1201/82-10 on 920628-070f No noncompliance noted Major areas inspected physical inventory observation & records & repts Details withheld (ref 10CFR2 790) TODD, O.A. JUNES, D.W., MCALPINE, E.J. Division of Engineering & Technical Programs 82/07/27 (p. 14162 300)
- DOCKET 70-1230 BLIPPERY ROCK STATE COLLEGE, BLIPPERY ROCK, PA
- 8208120067 Discusses IE insp Rept 70-1230/82-01 conducted on 820714.No noncompliance noted Major areas inspected activities re Pu/Be sealed sources HARTIN.T T Division of Engineering & Technical Programs 82/08/09 REINHARD.H.F 81ipperu Rock State College 2pp 14327 185
- DOCKET 70-1257 EXXON NUCLEAR CO. , INC , RICHLAND, WA
- 8208040195 Advises that Revision 11 to fundamental nuclear math control plans dtd 820217, acceptable except for item identified in encl W/o encl
 EVANS,L J Fuel Facility Safeguards Licensing Branch. 82/04/05
 SCHWEIDER,R A Exxon Nuclear Co., Inc (subs of Exxon Corp) Jp
- 8208260081 Approves const of addition to U oxide bidg per 820602 amend application Introduction of 8NM into new addition requires separate authorization PAGE.R O Uranjum Fuel Licensing Branch 82/08/09, MALOBY, C. W. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) ip 14574-296
- --8208260085 Safety evaluation supporting amend application re addition to U oxide bidg BIDINER, G H , GROW, W T Uranium Fuel Licensing Branch 82/08/09 ip. 14974 297

- DECRET 70-1308 GENERAL ELECTRIC CO , SAN JOSE, CA
- B208250458 Forwards Amend 1 to License SNM-2500 & notice of issuance & availability Amend permits receipt of fuel assemblies having lower enrichment ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 82/08/12 DAMSON.D H General Electric Co 2pp 14562 273
- --B209250463 Amend 1 to License SNM-2500, permitting receipt of fuel sesenblies having lower enrichments
 AQUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/09/12
 App 14562 275
- -- 8208250468 Notice of issuance & availability of Amend 1 to License
 - SIM-2500 RDUSELL C Advanced Fuel & Spent Fuel Licensing Branch 82/08/12 2pp 14562 281
- BE08300111 Forwards IE Insp Rept 72-0001/82-01 on 820720-23 No
 - noncompliance noted
 MILLER, J.R. Division of Engineering & Technical Programs 82/08/12,
 VAN HODMISSEN, J. General Electric Co. 2pp. 14596-124
- --8208300114 IE insp Rept 72-0001/82-01 on 820720-23 No nancompliance substruction in Insp. Kept /2-0001/82-01 on B20720-23 No noncomp noted Major areas inspected fuel receipt & storage, radiation protection, transportation activities, GA, safety committees & surveillance specs PECK, C C GREGERL R Division of Engineering & Technical Programs 82/08/10 4pp 14396-126
- DOCKET 70-1314 NATIONAL AERONAUTICS & SPACE ADMIN . HAMPTON, VA
- B20B030227 IE Insp Findings & Licensee Ack dtd 820713 of License SAM-1288 Insp findings no violations observed FRAMALIN.L C Region 2. Defice of Director 82/07/13 lp 14158 286
- DOCKET 70-18(0 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- B20B0&0367 Forwards renewed License SNM-1306 MACDDNALD.C E Transportation Branch 92/9 Westinghouse Electric Corp 1p 14281 339 U A .1 DRAM ES/70/28
- --B208040370 Renewed License BNM-1504 for Hestinghouse, authorizing possession of math not subj to 10CFR73 for delivery & transportation MACDUNALD.C E Transportation Branch B2/07/23 2pp. 14281:340
- DOCKET 70-2174 SOUTHEAST MISSOURI HOSP , CAPE GIRARDEAU, MO
- 8208070073 Ack receipt of 820722 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses BNM-1593, 24-00128-03 & 24-00128-05 BOOK5 WIEDEMAN, D O Division of Engineering & Technical Programs 82/07/29 NISHDMCER, O D Southeast Missouri Hosp., Cape Ośrardeau, MO Ip 14270 179
- --B208090079 Responds to NRC B20706 ltr re violations noted in IE insport Licenses BNM-1575:24-00128-03 & 24-00128-05 on 820615 Corrective actions all Au-178 seeds surveyed & found below background level HOWER.H W Southeast Missouri Hosp., Cape Girardeau, NO 82/07/22, MILLER,J R Division of Engineering & Technical Programs App. 14270, 140. MILLER, J R 14270 180
- DOCKET 70-2823 DUKE POWER CO . CHARLOTTE, NO
- 8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear youer plants & analyzing said info Forwards documents listed in App A FELTON, J H Division of Rules and Records 82/07/13. UDELL.R. A Critical Mass Energy Project 8pp 14679 208 24X Fiche 80~000,82/07/13.8208270010
- --8208270607 Forwards "Personnel Whole Body Exposures for CY81," per OCERSO 407(a) & (b)

 PARKER, W O Duke Power Co 82/03/09 BASSETT, H, S,

 Management and Program Analysis ip 14680'045 2

 Fiche 50-000,82/07/13,8208270010 Office of 24X
- --B20B270614 "Personnel Whole Rody Exposures for CYB1." LEWIS.L. Duke Power Co. 82/03/07 ip. 14680-046 24X Fiche 50-000.82/07/13.8208270010

- 8208130338 Notifies that Apr 1982 Revision 6 to spent fuel transportation plan meets requirements of 100FR73 37 k is approved Revised plan contains safeguards info which should be withheld (ref 100FR73 21) ba withheld (ref 10CFR73 21) SHERR, T, S Division of Safeguards 82/08/03 PARKER, W D Duk Power Co 1p 14340 240 24X Fiche 50-369, 82/08/03, 8208130338
- DOCKET 70-2625 HENTON MEMORIAL HOSP , NEWTON, NJ
- 8708230270 Act receipt of 820803 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses SNM-1747 & 29-12745-01 on 820422 MARTINITY Division of Engineering & Technical Programs. 82/08/DAILEY.S O Newton Memorial Hosp Newton, NJ. ip 14509, 355 82/08/19
- --8208230294 Responds to NRC 820629 ltr re violations noted in IE insp of Licenses SNH-1747 & 29-12745-01 on 820422 Corrective actions syrings shields to be utilized by technologists during preparation & administration of petient doses DAILEY.8 O Newton Memorial Masp Newton, NJ 82/08/03. MARTIN, T. Division of Engineering & Technical Programs
- DOCKET 70-2884 LONG ISLAND LIGHTING CO . HICKSVILLE. NY
- 8208050175 Advises of issuence of Amend 1 to License SNM-1857, authorizing temporary storage of new fuel onsite, on delivery trucks while awaiting Unloading into reactor bldg for storage PAGE.R O Uranium Fuel Licensing Branch, 82/07/23 POLLOCK.M.B. Long Island Lighting Co ip 14242,086
- --B208050177 Safety evaluation supporting Amend 1 to License SNM-1857 authorizing onsite atorage of new fuel KETZLACH N Uranium Fuel Licensing Branch 82/07/23, 2pp. 14242-087.
- DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP , PRATTVILLE, AL
- 8208:30185 Hemorandum & order granting Westinghouse 820410 request to withdraw application for BMH license w/o prejudice HOLF-J F. Atomic Bafety and Licensing Board Panel 82/08/11 Westinghouse Electric Corp 2pp 14338 283
- DUCKET 70-2936 HISSISSIPPI POWER & LIGHT CO . JACKSON, MS
- 8208020428 Advises of issuance of Amend 4 to License SNM-1882.defining expiration date as 821231 or upon conversion of CPPR-118 to um. PAGE,R Q Uranium Fuel Licensing Branch. 82/06/20. DALE,L F Mississippi Power & Light Co ip 14181 029
- --8208020432 Bafety evaluation supporting issuance of Amend 4 to License 81(H-1882 KETZLACH,N , GROW,W T. Uranium Fuel Licensing Branch 82/05/28 ip. 14181 030.
- DOCKET 70-2937 PENNSYLVANIA POWER & LIGHT, ALLENTOWN, PA
- B208230180 Forwards IE Bafeguards Insp Repts 50-387/82-21,70-2997/82-01 & 30-16036/82-01 on 820616-17 of activities under Licenses CFPR-101,8MM-1878 & 37-06554-03,respectively No CPPM-101, SAM-1878 & 37-0805-05, Instruction of Engineering & Technical Programs 82 (URTIS.N.W Penneylvania Power & Light Co 200 14510:355 Fiche: 50-387, 82/08/06, 8208230180
- --8209230302 IE Bafeguards Insp Repts 50-387/82-01,70-2937/82-01 k 30-16035/82-01 on 820616-17. No noncompliance noted Hajor areas inspected facility organization & operation, shipping & receiving & storage & internal control RATTA: A. D. , GODY: A. T. Region i. Office of Director, 82/07/28. 5pp. 14510.357, 24X Fiche; 50-387, 82/08/06,8208230180. 82/07/28.
- DOCKET 70-2955 EDLOW INTERNATIONAL CO . WASHINGTON, DC
- 8208040162 Requests submittal of separate detailed security plan per 10CFR70, 22(k), to suppl 820311 application for license to store SNM of low strategic significance, Submittal should be marked in eccordance w/proyisions of 10CFR2 790(d), EVANS, L. J. Fuel Factlity Rafeguards Licensing Branch. 82/05/25, EDLOW, J. Edlow International Co. ip 14237 118

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0062 INDUSTRIAL NUCLEAR CO

- 8208040254 Forwards Revision 1 to GA program for design, fabrication, assembly & testing of packaging used in transport of radioactive mati
 GAINES, T M Industrial Nuclear Co 82/07/19 MACDONALD, C E Transportation Branch. 1p 14224 341
- --8208040258 Revision 1 to QA program for design fabrication assembly & testing of packaging used in transport of radioactive mati WILLIAMSON R L Industrial Nuclear Co 82/07/16 14pp

DOCKET 71-0370 AMERSHAM CORP

- B208250090 Forwards GA program for Type B radioactive mat1 transport packages
 BAOBY, L A Amersham Corp 82/07/30 MACDONALD, C Transportation Branch 1p 14559 242
- --8208250095 GA program for Type B radioactive mat1 transport packages
 4 Amersham Corp 82/07/30 13pp 14559 243

DOCKET 71-0478 X-SCAN INSPECTION CO

- 8207070036 Forwards QA program for X-Scan Insp Co.in response to NRC 820413 ltr POTTER.8 8, X-Scan Inspection Co 82/06/17 HACDDNALD.C E NRC -No Detailed Affiliation Given ip 13781 272
- --8207070037 QA program for X-Bcan Insp Co * X-Scan Inspection Co 82/06/17 16pp 13781 273

DOCKET 71-0480 MERCURY METALB, INC

- 8208040063 Forwards facilities list & QA manual re Schlumberger Well Eves Co application for license MELLEY.J.L. Hercury Mobals. Inc. 82/06/30 MACDUNALD.C E Transportation Branch 8pp 14231 266
- --8208040069 GC Manual for Mercury Metals, Inc * Mercury Metals, Inc 80/01/24, 38op 14231 274

DOCKET 71-5097 MODEL 44. ENERGY, DEPT OF

- 8208090331 Forwards request for add1 info needed for review of 771102 applications for approval of Model 44 MACDONALD, C E Transportation Branch 82/07/23. PRICHARD, R P Energy. Dept of 2pp 1/3308 231
- DOCKET 71-5149 MODEL 814A, BADCOCK & WILCOX CO
- 8208040395 Application for amend to Certificate of Compliance 5149.to allow five packages per transport vehicle KELLY.J W Babcock & Wilcox Co 82/07/12 MACBONALD.C E. Transportation Branch 4pp 14224 313
- 6208130419 Forwards Revision 3 to Certificate of Compliance 5149 for Model 814A MACDONALD, C.E. Transportation Branch. 92/07/28 CORDANI, R.A. Babcock & Wilcox Go. 2pp. 14354-396
- --8208130421 Certificate of Compliance 5149, Revision 3. for Hodel 814A MACDONALD.C Transportation Branch 82/07/28 3pp. 14354-358.
- DOCKET 71-5768 MODEL BB-250-2, COMBUSTION ENGINEERING CO., INC
- 8208250423 Forwards revised pages to Jan 1982 application for renewal of Certificate of Compliance 5768 in response to NRC 820527 request for addl info AUSTIN A Babcock & Wilcox Cq 82/08/06 MACDONALD, C E Transportation Branch 4pp. 14862 122
- --8208250430 Revised pages to Jam 1982 application for renewal of Certificate of Compliance 5768. One oversize drawing encl Aperture card is available in PDR # Habcock & Wilcox Co. 82/07/30 73pp 14562:126

- DOCKET 71-5796 MDDEL 181375, 181361, ADVANCED MEDICAL SYSTEMS, INC
- 8208040396 Forwards Revision 7 to Certificate of Compliance 5796 for Hodels 181375 & 181361 HACDONALD,C E Transportation Branch 82/07/22 KELBLEY.N D Advanced Medical Bystems, Inc. 2pp 14224 317
- --8208040399 Cortificate of Compliance 5796, Revision 7, for Models 181275 & 181261 Approval record and MACDONALD, G E Transportation Branch 82/07/22 4pp 14224 319
- DOCKET 71-5805 MODEL VANDENBURGH, CHEM-NUCLEAR SYSTEMS, INC
- B20B130373 Notification of registration as user of Model Vandenburgh in response to B20520 request MACDBNALD.C E Transportation Branch B2/07/29 DAWSON, D. M General Electric Co ip 14340 264
- DOCKET 71-5874 MODEL WAPD-40, ENERGY, DEPT OF
- 8208170395 Forwards request for add1 info re 820420 application for approval of Hodel WAPD-40 MACDONALD, C E Transportation Branch 82/07/30 ENGEL, W P Energy, Dept of 2pp 14372 333
- DOCKET 71-5908 MODEL DOT-6M TYPE B, BABCOCK & WILCOX CO
- 8208050027 Application for revision to Certificate of Compliance 5908, permitting intermixing of U-233 & U-235 fuel matl packaged in Model DDT-6M shipping drums ENGEL. N P Energy, Dept of 82/07/19 MACDONALD, C E Transportation Branch 2pp 14243 128

DECKET 71-5926 MODEL, 0E-100, GENERAL ELECTRIC CO

- 8208040087 Forwards request for addl info re revised drawings transmitted in support of 820622 application to renew Certificate of Compliance 5926 Revised drawings not in complete agreement w/drawings referenced by certificate MACDDNALD, C E. Transportation Branch 82/07/16, CUNNINGHAM, Q E General Electric Co 2pp 14228 329
- 8208130335 Requests extension of expiration date for Certificate of Compliance 5926 pending final review of renewal application CUNNINGHAM.O E General Ejectric Co 82/07/22 MACDONALD.C E Transportation Branch ip 14340 238
- DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CD
- 8208040430 Forwards request for add1 info in response to 820622 ltr transmitting revised drawings in support of application for renewal of Certificate of Compliance 5939 Response should be submitted within 40 days
 MACDONALD. C E Transportation Branch, 82/07/22 CUNNINGHAM, Q E General Electric Co 3pp 14220 178
- 820B130336 Requests extension of expiration data for Certificate of Compliance 5939 pending final review of renewal application CUNNINGHAM.0 E Ceneral Electric Co. 82/07/22 MACDONALD.C E Transportation Branch. 1p 14340 239

DOCKET 71-5957 MODEL BMI-1. DATTELLE COLUMBUS LABORATORY

- 8208260604 Informs that GA Co will submit amend request for slightly modified Certificate of Compliance 5957 to ship TRIGA fuel stements.

 BURIAN.R. J Battelle Memorial Institute, Pacific Northwest Laboratory 82/08/05 MACDONALD, C Transportation Branch 1p 14569:148
- DOCKET 71-6088 HODEL, D-38, OAK RIDGE NATIONAL LAB
- 8208130342 Forwards request for add1 info re effect of normal & Appothetical accident conditions on containment sys & containment criteria for normal form matl for package containment sys MACDONALD, C. E. Transportation Branch 82/07/28, PRICHARD, R P. Energy, Dapt of 2pp 14040 248

IOCAET 71-6115 MODEL R1010-0032, ENERGY, DEPT OF

- 208040435 Requests application for renewal of Certificate of Cowallance dit5 at least 30 days prior to 820930 expiration if continued use of package is desired MACDONALD.C E Transportation Branch 82/07/22 BAUER.R H Energy, Dept of ip 14220 181
- OCKET 78-6574 HODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP.
- 208190111 Requests registration as user of Hodels CNB 8-120, HN-200, CM6-89A, CNS 21-300, CNS 14-195-H, HN-100 Series 1, HN-100 Series 2, HN-1008 & 9080 Series 2, HN-1008 & 9080 SEISER-H W Pennsylvania Power & Light Co 82/07/23 XACDONALD, C E Transportation Branch 2pp 14506 361
- 208240030 Notification of registration as user of Models CNS 14-175-H, (MS 21-300,CNS 8-120,CNS 6-80-2.HN-100 Series 1.HN-100 Series 2.HN-200 & 9080. in response to 820723 request ACCDONALD.C E Transportation Branch. 82/08/10. CURTIS:N W Pennsylvania Pawer & Light Co ip 14529.315
- 208250005 Requests registration as user of Model HN-200 FRICHARD, R.P. Energy, Dept of 82/08/11 HACDONALD, C.E. Transportation Branch 1p 14351 359
- CONET 71-6601 MODEL CNS 8-120, CHEM-NUCLEAR SYSTEMS, INC.
- NOBO40031 Advises of B20617 mag particle test revealing stress marks on bolts on top shield cover of Chem-Nuclear Cask, CNS 8-120 Chem-Nuclear delivered new bolts on B20621 Guestionable bolts returned to vendor for review MAJER, J E Rochester Gas & Electric Corp 82/07/07 Office of Nuclear Material Safety & Safeguards, Director. 1p 14235-352
- 208040267 Requests registration as user of Model CN8 8-120.
 FEWITTLE 0 Argonne National Laboratory 82/07/15 MACDONALD.C E
 Transportation Branch 1p 14224 339
- 208190111 Requests registration as user of Models CNS 8-120, HN-200, CN6-BOA, CNS 21-300, CNS 14-195-H, HN-100 Series 1, HN-100 Series 2, HN-1008 & 9080 KEIEER, H W Pennsylvania Power & Light Co 82/07/23 KACDONALD, C E Transportation Branch 2pp 14506 361
- 208130333 Requests cause of defects & corrective action to be taken re L4 cast lid bolts found defective during insp of Model CNB 8-120 shipping cask Response within 30 days of ltr receipt required KACDURALD.C E Urenium Rocovery Licensing Branch 82/07/27 KARSH.C A Chem-Nuclear Systems. Inc. 4pp 14340 234
- 08240080 Notification of registration as user of Modele CNS 14-195-H, CNS 21-300, CNS 8-120, CNS 6-80-2, HN-100 Series 1, HN-100 Series 2, HN-200 & 9080, in response to 820723 request AACDONALD.C E Transportation Branch 82/08/10 CURTIE, N W Pennsylvania Power & Light Co. 1p 14529 315.
- M8240090 Notification of registration as user of Model CN8 8-120, in response to 820715 request MACDOMALD.C.E Transportation Branch. 82/08/10. CHEEVER.C L Argorne National Laboratory ip 14529.306.
- 10824CO96 Notification of registration as user of Model CNS B-120, in response to 820716 request MAGDONALD.C E Transportation Branch 82/08/10 O'DONNELL, D M Yankwe Atomic Electric Go ip 14529-304.
- CKET 71-6678 MODEL LP-50, ENERGY, DEPT. OF
- 199260596 Requests copy of Savannah River plant renewal request for Certificate of Compliance 6678. SMAM, A Edlaw International Co 82/08/03. MACDONALD, C. E Transportation Branch. ip. 14569-146.
- CKET 71-6698 MODEL, NFS-4, NUCLEAR FUEL SERVICES, INC.
- 07050077 F01A request for documents re NFS-4 shipping casks. KRONZEKi A L. F01 Services 82/07/07. Division of Rules and Records. 1p 14705 133

- 8208240128 Forwards response to 22 requests for add1 info.per 811229 ltr Design & crushable matl of impact limiters changed in Items 1.2 & 3 Design incorporates engineered crushable matl Wisotopic properties UDHNSON,C R Nuclear Assurance Corp 82/07/30 MACDONALD.C E Transportation Branch 2pp 14546 119
- --8208240134 "Bafety Analysis of Modified NAC-1 Spent Fuel Shipping Cask." Vols 1 & 2 • Nuclear Assurance Corp NAC-E-801 RO3 82/06/25 700pp 14546 123
- 8208310426 Responds to FOIA request for documents re NFS-4 shipping casks Forwards Documents 2,5.8.9.11.12.13,29.31.33 & 48
 Listed in App A Remaining documents available in PDR
 FELTON. J K Division of Rules and Records 82/07/30 KRONZEK.A L
 FOI Services 4pp 14705 134 24X Fiche 50-000,82/07/30.
 8208310426
- --8208310432 Requests IE investigate allegations re design deviations of NFS-4. Serial A cask owned by Dute Power Co. per 790329 meeting w/Nuclear Assurance Corp NUSSBAUMER, D. A. Assistant Director for Material Safety & Licensing 79/04/02. HIGOENBOTHAM, L. Division of Fuel Facility & Materials Safety 2pp 14705 138
- --8208310437 Requests IE attend 770417 meeting w/Nuclear Assurance Corp.NPS & Duke Power Co in Bilver Spring.MD to discuss physical measurements of NPS-4 cask cavities to determine if casks meet Certificate of Compliance 6698 package design CURNINOHAM.R E Division of Fuel Cycle & Material Bafety 79/04/12 SHIEZEK, J H Division of Fuel Facility & Materials Bafety 2pp 14705 140
- --B20B310442 Summary of 790417 meeting w/Nuclear Assurance Corp & Duke Power Co re 790406 order to show cause concerning NFB-4 packagings Nuclear Assurance Corp proposed physical measurements of casks acceptable ODEOARDEN.R H Transportation Branch 79/06/04 Transportation Branch 2pp 14705 148
- --8208310448 Summary of 770430 meeting w/Nuclear Assurance Corp & Duke Power Co re 770406 order to show cause concerning NFS-4 packagings Preliminary results of physical measurements of four packages discussed Harked-up drawings encl ODEOAARDEN.R H Transportation Branch 77/06/04 Transportation Branch 10pp 14705:150.
- --820B310453 Summary of 7905ti meeting ω/Nuclear Assurance Corp re 790406 order to show cause concerning NFB-4 packagings Contents of application to demonstrate that packages had been constructed per Certificate of Compliance 6698 discussed DDEOAARDEN. R H Transportation Branch 79/06/04.

 Transportation Branch 1p. 14703 156
- --8208310437 Bummary of 790524 meeting w/NFS re 790404 order to show cause concerning NFB-4 packagings Present status of order discussed Preliminary measurements on packages encl. DDEGARDEM, R H Transportation Branch 79/06/04 Transportation Branch 21pp. 14705 197.
- --8010280028 Discusses Nuclear Assurance Corp shipment made in apparent violation of Certificate of Compliance 6698 Model NFS-4. Dimensions exceed measurements specified in Item 14 of certificate. It instructed to investigate matter ODECOARDEN R ff Transportation Branch 80/09/11 Transportation Dranch 1p 14705 178
- --B208310463 Forwards Revision 3 to "NAC-1 Cask Cavity, Measurements Procedure " Preliminary results indicate that cask does not meet acceptance criteria CRDERS, W T Region 2, Atlanta, Office of the Director, 60/10/30, MACDONALD, G E Transportation Branch ip 14705 179
- --B20B310445 Revision 3 to "NAC-1 Cask Cavity Heasurements Procedure "
 Raw data accumulated on 801022-24 during NFS-4 cask cavity
 integrity verification at Oconee encl
 PANFR: H R. HOFFMAN.C. C. VIEBROCK, J. M. Nuclear Assurance Corp
 80/10/21 21pp. 14705-160
- --8208310467 Forwards NAC-1 cast cavity measurements performed on 801111 at Oconee Cast failed to meet acceptance criteria & will not be employed until package integrity is resolved.
 GREERS H T. Region 2. Atlanta: Office of the Director 80/11/18 MACBUNALD.C.E Transportation Branch 26pp, 14705 201
- --8208310469 Forwards IE Investigation Repts 50-213/80-20 & 50-219/80-38 on 801004-810114 & motice of violation CARLSON, R. T. Enforcement & Investigation Staff 81/12/23 COUNBIL. H. O. Connecticut Yankse Atomic Power Co 2pp 14705.227. 24X Fichs. 50-000,82/07/30,8208310426

- ~~8208310472 Notice of violation from investigation on 801006-810114 CARLBON, R T Enforcement & Investigation Staff 81/12/23 ip 14705 229. 24X Fiche 50-000, 82/07/30, 8208310426
- --8208310476 IE Investigation Repts 50-213/80-20 & 50-219/80-38 on 801006-810114. Noncompliance noted on 800301. Model NFS-4. Serial NAC-IE cask loaded w/failed bundle H07. delivered to carrier w/decay heat generation in excess of 2 5 kH SMITH.R H Enforcement & Investigation Staff 81/10/06 14pp 14705 230 24X Fiche 50-000, 82/07/30, 8208310426
- --8208310481 Informs of intent to ship SNM in form of three irradiated fuel assemblies from Haddam Neck.CT to BMI in Columbus, OH on 800422.28 & 0502 COUNSIL.W 0 , FEE.W F Connecticut Yankee Atomic Power Co 80/04/15 ORIER B H Region i. Philadelphia. Office of the Director ip. 14705 254 24% Fiche 50-000,82/07/30,8208310426
- --8208310483 Informs that first spent fuel assembly shipped from facility to BHI in NAC-1 cask exceeded decay heat limit No adverse effects on health & safety observed, therefore no further action necessary GDUNSIL.N O Connecticut Yankee Atomic Power Co 80/05/21. GRIER.B.H Region 1, Philadelphia, Office of the Director 2pp 14705 274 24% Fiche 50-000, 82/07/30, 8208310424
- --8208310486 Discusses review of licensee mgt of NAC-1E spent fuel shipping container on 800723-0801 (IE Insp Rept 50-219780-25) No noncompliance noted Shipping & receiving survey records encl PLUKLEE,K E. Facility Radiological Protection Section 81/09/17 SHITH.R H Region 1. Philadelphia. Office of the Director (81/03/01) 34pp 14705 276 24X Fiche 50-000,82/07/30,8208310426
- DOCKET 71-6717 MODEL: 6717-B. GAMMA INDUSTRIES
- 8208190141 Requests registration as user of Models 6717-B,C-1 & Spec 2-T HEAD: TO Monroe X-Ray Co., Inc. 82/07/08 HACDONALD,C E Transportation Branch. ip 14506 191
- 8208040272 Requests registration as user of Hodels 6717-8 & 650 MCRLI.8 MSI Yesting Inc. 82/07/19 MCCDNALD.C.E Transportation Branch ip 14224-340
- 8208190128 Requests registration as user of Models 650,6717-8,660 & 660E MORKLI,8 MB: Testing,Inc 82/07/27 MACDONALD,C E Transportation Branch ip 14506 190.
- B20B240100 Notification of registration as user of Models 650 & 6717-Br in response to 820713 request MACDOMALD.C.E Transportation Branch B2/08/10 ORIFFITHS.W B MBI Testing.Inc. ip 14529 301
- DOCKET 71-9004 MODEL 500-8U, AUTOMATION INDUSTRIES, INC.
- B208050023 Application for amond to Certificate of Compliance 9005, incorporating authorization for using drum overpack when Model 500-50 source charger contains two sealed IR-192 sources
 BANTORO, N P Automation Industries, Inc. 82/07/16 MACDDNALD, C E Transportation Brench. 2pp. 14243 104
- DOCKET 71-9032 HODEL 450, TECHNICAL OPERATIONS, INC.
- 8208040272 Requests registration as user of Models 6717-B & 630 MOCKLI, B MSI Testing, Inc 82/07/13 MAGDONALD, C E Transportation Branch. 1p 14224 340
- 8208040262 Requests registration as user of Model 650 EKBERG, E Smith-Emery Co 82/07/22 MACDONALD, C E Transportation Branch ip 14225 153
- 820B19012B Requests registration as user of Hodels 650,6717-B.660 & 660E MCCKLI.B. MSI Testing. Inc. 82/07/27. MACDONALD.C E Transportation Branch. 1p. 14506.190
- 8208130414 Notification of registration as user of Models 650,660,683 & 750 in response to 820618 request.

 MACDOMALD& C. Transportation Branch 82/07/30 FISHER,R 0
 Thayer Inspection Bervice, Inc. 1p 14350 361

- 8208240092 Notification of registration as user of Model 650, in response to 820723 request MACDONALD, C E Transportation Branch 82/08/10 DUNHAM, M 8 Bmith-Emery G ip 14529 305
- 8208240100 Notification of registration as user of Models 650 & 6717-g in response to 820713 request MACDONALD.C.E., Transportation Branch 82/08/10 GRIFFITHS, W.S. MSI Yesting.Tnc 1p 14529 301
- B208230179 Notification of registration as user of Models 650 % 660E, in response to 820608 request MACDUNALD.C E Transportation Branch 82/08/10 WILSON, J C Wilson Inspection Bervices. Inc. ip 14557 233
- DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL DPERATIONS, INC
- 8208190128 Requests registration as user of Models 650,6717-8,660 & 660E 660E MOCKLI.B HSJ Testing, Inc 82/07/27, MAGDONALD, C E Transportation Branch ip 14506 190
- B2OB130414 Notification of registration as user of Models 650,660,683 to 750 in response to B20618 request MACDONALD,C E. Transportation Branch B2/07/30 FIBHER,R Q Thayer Inspection Bervice, Inc ip 14350 361
- B208250179 Notification of registration as user of Models 650 \$ 6605. in response to B20608 request MACDONALD.C E. Transportation Branch 82/08/10 WILSON.J G Wilson Inspection Services.Inc 1p 14559 233
- DOCKET 71-9036 MODEL, C-1, SQURCE PRODUCTION & EQUIPMENT CO
- 8208190141 Requests registration as user of Models 6717-B,C-1 & Bpec 2-T MEAD.T O Monroe X-Ray Co , Inc 82/07/08 MACDONALD.C E Transportation Branch ip 14506 191
- DOCKET 71-9053 MODEL. 683, TECHNICAL OPERATIONS, INC.
- 8208130414 Notification of registration as user of Models 650,660,683 \$2750 in response to 820618 request MACDONALD, C E Transportation Branch 82/07/30. FISHER, R. O. Thayer Inspection Bervice, Inc. ip 14350 361
- DOCKET 71-9056 MODEL SPEC 2-T, BOURCE PRODUCTION & EQUIPMENT CO
- 820B190141 Requests registration as user of Models 6717-B,C-1 & Bpsc 2-T HEAD; T Q Monroe X-Ray Co . Inc. 82/07/08 MACDONALD,C.E Transportation Branch, 1p 14506 191
- DOCKET 71-9074 MODEL. AP-100, ANEFCO, INC
- 8208090036 Requests addl info needed to review 820708 revised consolidated application for renewal of Certificate of Compliance 9074 for Model AP-100 MACDONALD.C E Transportation Branch 82/07/27 MURPHY, J. D Anefco, Inc. Ip 14301.108.
- DOCKET 71-9079 MODEL: HN-100, BERIES 2 & 2A, HITTMAN NUCLEAR
- 8208190111 Requests registration as user of Models CNS 8-120, HN-200, CMS-80A, CNS 21-300, CNS 14-195-H, HN-100 Series 1, HN-100 Series 2, HN-1008 & 9080 KEISER, H W Pennsylvania Power & Light Co. 82/07/23 MACDONALD, C E Transportation Branch 2pp. 14506-361
- 8208240080 Notification of registration as user of Models CNS 14-195-1 CNS 21-300.CNS 8-120.CNS 6-80-2.HN-100 Series 1.HN-100 Series 2.HN-200 & 7080.In response to 820723 request MACDONALD.C E. Transportation Branch 82/08/10 CURTIE,N.W Pennsylvanie Power & Light Co 19 14527.315

- DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 820B190111 Requests registration as user of Models CNB 8-120, HN-200, CN6-80A.CNS 21-300, CNS 14-175-H.HN-100 Series 1, HN-100 Series 2, KH-100B & 7080 KEIBER.H W Pennsylvania Power & Light Co 82/07/23 KAGDONALD, C E Transportation Branch 2pp 14506 361
- 8208240080 Notification of registration as user of Models CNS 14-195-H, CNS 21-300, CNS 8-120, CNS 6-80-2, HN-100 Series 1, HN-100 Series 2, HN-200 & 9080, in response to 820723 request MACDONALD, C E Transportation Branch 82/08/10 CURTIS, N W Pennsylvania Power & Light Co 1p 14527 315
- DOCKET 71-7086 MODEL HN-100, BERIES 1, HITTMAN NUCLEAR & DEV CORP
- 8208190111 Requests registration as user of Hodels CNS 8-120.HN-200. CNG-80A.CNS 21-300.CNS 14-193-H.HN-100 Series 1.HN-100 Series 2.HN-1008 & 9080 KEISER.H W Pennsylvania Power & Light Co 82/07/23 MACDGNALD.C E Transportation Branch 2pp 14506 361
- 8208170014 Advises that encl application & drawings marked proprietary should be placed in PDR MACDONÁLD.C E. Transportation Branch 82/07/28 SCOTT,8 Document Management Branch Ip 14373 342
- --8208170018 Application for renewal of Certificate of Compliance 9086 for HN-100 Series I radioactive matls shipping cask *8AR for HN-100 Series I Radwaste Shipping Cask* encl. HALLORY.C W Hittman Nuclear & Development Corp (subs Hittman Corp.) 82/07/23 MACDONALD.C E Transportation Branch Spp 14073 343
- --820Bi70023 "BAR for HN-100 Series 1 Radwaste Shipping Cask," Revision O Three oversize drawings encl Aperture cards are available in PDR PETTIGREW, Hittman Nuclear & Development Corp. (subs Hittman Corp.) BTD-R-02-006 R00 82/07/23 118pp 14373 351
- 820824080 Notification of registration as user of Models CNS 14-175-H, CNS 21-300, CNS 8-120, CNS 6-80-2, HN-100 Series 1, HN-100 Beries 2, HN-200 & 7080, in response to 820723 request ACCDMALD, C. E. Transportation Branch. 82/08/10 CURTIS, N W Pennsylvania Power & Light Go ip 14529 315
- DOCKET 71-9089 MODEL: HN-1009, HITTMAN NUCLEAR & DEVELOP CORP
- 820B190111 Requests registration as user of Models CNS G-120, HN-200, CNS-80A, CNS 21-300, CNS 14-195-H. HN-100 Series 1, HN-100 Series 2, HN-1008 & 9080 KEIBER. H W Pennsylvania Power & Light Co B2/07/23 MACDQNALD, C E, Transportation Branch 2pp 14506 361,
- DUCKET 71-9094 MODEL: CNS 14-195-H, CHEM-NUCLEAR SYSTEMS, INC.
- B20B190111 Requests registration as user of Hodels CNB B-120, HN-200, CNS-90A, CNB 21-300, CNB 14-193-H. HN-100 Beries 1, HN-100 Beries 2, HN-1008 & 9080 KEIBER, H W Pennsylvania Power & Light Co B2/07/23 MACDONALD, C. E. Transportation Branch. 2pp 14506, 361
- 8208240080 Notification of registration as user of Modele CNS 14-195-K, CNS 21-300, CNS 8-120, CNS 6-80-2, HN-100 Series 1, HN-100 Series 2, HN-200 & 7080 in response to 820723 request MACDONALDIC E. Transportation Branch 82/08/10. CURTIS.N W Pennsylvania Power & Light Co 1p 14527; 315.
- DOCKET 71-9096 MODEL, CNB 21-300, CHEM-NUCLEAR SYSTEMS, INC
- B208240080 Notification of registration as user of Models CNS 14-175-H, CNS 21-300.CNS 8-120.CNS 6-80-2.HN-100 Series 1,HN-100 Series 2,HN-200 & 9080.in response to B20723 request MACDDNALD, C E Transportation Branch. 82/08/10. CURTIG,N W. Pennsylvania Power & Light Co. ip, 14529.315
- DOCKET 71-9098 HODEL, UCC-20MC-2 & RA, UNION CARBIDE CORP.
- 8208040110 Requests consolidated renewal application be submitted at least 30 days before 820930 expiration date of Certificate of Compilance 9098. MACDONALD.C E. Transportation Branch. 82/07/15. VOTH, M. H. Union Carbide Corp. 1p 14228 342.

- DOCKET 71-9111 MODEL CN84-80-2, CHEM-NUCLEAR BYBTEMS, INC
- B208190111 Requests registration as user of Models CNB 8-120, HM-200, CN6-B0A, CNB 21-300, CNS 14-195-H, HM-100 Series 1, HM-100 Series 2, HM-1005 4, 9080 KEIBER, HW Pennsylvania Power & Light Co B2/07/23 MACDDNALD, C E Transportation Branch 2pp 14506 361
- 8208240080 Notification of registration as user of Models CN9 14-195-H, CN8 21-300, CN8 8-120, CN8 4-80-2, HN-100 Series 1, HN-100 Series 2, HK-200 & 9080, in response to 820723 request MACDONALD, C E Transportation Branch 82/08/10 CURTIS, N W Pennsylvania Power & Light Co 1p 14529 315
- DOCKET 71-9128 MODEL: C-8, GAHMA INDUSTRIES
- 8208240486 Requests registration as user of Hodels C-08 & C-10 80ZARTH, B L Industrial Fabricating 82/07/20 MACDUNALD, C E Transportation Branch ip 14544 161
- DOCKET 71-9132 MODEL T-3, ENERGY, DEPT OF
- 8208040073 Forwards request for add1 info re 820616 application to amend Model T-3 packaging MACDONALD.C.E Transportation Branch 82/07/15 HANSEN.L.J. Nuclear Packaging, Inc. 2pp 14228 287
- 820805003B Forwards Revision 9 amends to Model T-3 BAR, per 820715 request Addl calculations show that support base of holddown ring will withstand impact loadings w/o deforming. No addl stress will be induced in containment vessel
 HANSEN, L.J. Nuclear Packaging. Inc. 82/07/23 MACDONALD, C.E. Transportation Branch ip. 14243.150,
- --B208050041 Revision 9 to 8AR for Model T-3 * Nuclear Packaging, Inc 82/07/31 22pp 14243 151
- 8208240033 Forwards Pages 1,2 & 3 of Revision 6 to Drawing H-4-61289 of Model T-3.inadvertently omitted from 820723 transmittal. Pages should be inserted w/previously submitted Page 4 HAELSIQ: R T Nuclear Packaging, Inc. 82/07/26 MACDONALD, C E Transportation Branch 7pp 14329.088.
- DOCKET 71-9135 HODEL. CENTURY B & SA, CEN UNIV. B & SA, CAMMMA IND.
- 8208040028 Advises that no add1 fee required re 770824 application which resulted in 820430 Certificate of Compliance 7135.
 MILLER, W.D. License Fee Management Branch 82/07/15
 RICHARDSON.H D Nuclear System. 1p 14235 353
- 8208130348 Concludes that packages authorized by Certificate of Compliance 9135 meet IAEA requirements for Type B(U) packages MACDONALD.C E. Transportation Branch. 82/08/05 RAWL.R.R Transportation.Dept of ip. 14340-268
- DOCKET 71-9139 HODEL 589, GENERAL ELECTRIC CO.
- 8208040047 Application for amend to Certificate of Compliance 9139, Revision 1, deleting Item 5(b)(1) re secondary container requirement Amend fee not required per 10CFR170, 11(a)3, MICLE, L. M. Tennessee Valley Authority 82/07/07 MAGDONALD, C. E. Transportation Branch 1p 14232; 360.
- 8208040403 Forwards Revision 2 to Certificate of Compliance 9139 for Model 589.

 MACDONALD, C. E. Transportation Branch. 82/07/22 CUNNINGHAM, G. E. General Electric Go. 2pp., 14224-327.
- --8208040405 Certificate of Compliance 9139, Revision 2. for Model 589. Approval record encl McGDUNALD, C.E. Transportation Branch 82/07/22 4pp. 14224:329.
- DOCKET 71-9145 MODEL: NUPAC 50-1, 5L, -2, 5L, -3, 0L & -4 OL, NO USERS
- 8208130345 Notification of registration as user of Model NUPAC 50-1.5t in response to 820616 request. MACDONALD.C. E Transportation Branch 92/07/30 MARSHALL.J.R. Arkansas Power & Light Co 1p. 14340.250.

DOCKETED ITEMS

- --8208310472 Notice of violation from investigation on 801006-810114 CARLSON,R T Enforcement & Investigation Staff 81/12/23 ip 14705 229, 24X Fiche 50-000,82/07/30,8208310426
- --8200310476 IE Investigation Repts 50-213/80-20 & 50-219/80-38 on 801006-810114, Noncompliance noted on 800501. Model NFS-4, Serial NAC-1E cask, loaded u/failed bundle HDz, delivered to carrier u/decay heat generation in excess of 2 5 kM SMITHR H Enforcement & Investigation Staff 81/10/06 14pp 14705 230 24% Fiche 50-000, 82/07/30, 8208310426
- --B20B3104B1 Informs of intent to ship BNM in form of three irradiated fuel assembliss from Haddam Neck.CT to BHI in Columbus.CH on 800422.2B & 0502 COUMBIL.H 0 , FEE.H F Connecticut Yankee Atomic Power Co B0/04/15 ORIER.B H Region 1. Philadelphia, Office of the Director. 1p 14705 256 24% Fiche 50-000.B2/07/30.B20B310426
- --B20B310483 Informs that first spent fuel assembly shipped from facility to BMS in NAC-1 cask exceeded decay heat limit No adverse effects on health & safety observed therefore no further action necessary COUNSIL-V Q. Connecticut Yantee Atomic Power Co B0/05/21 QRIER-B H Region i. Philadelphia. Office of the Director 2pp 14705 274 24X Fiche 50-000, 82/07/30,8208310426
- --8208310486 Discusses review of licensee mgt of NAC-IE spent fuel shipping container on 800723-0801 (IE Insp Rept 50-219780-26) No noncompliance noted Shipping & receiving survey records encl FluHLEE.K E. Facility Radiological Protection Section 81/09/17 SMITH.R H. Region I. Philadelphia. Office of the Director (81/03/01) 34pp 14705 276 24% Fiche 50-000.82/07/30.8308310426
- DOCKET 71-6717 MODEL 6717-B. GAHMA INDUSTRIES
- 8208190141 Requests registration as user of Models 6717-B,C-1 & Spec 2-T
 HEAD,T @ Monroe X-Ray Co , Inc 82/07/08 MACDONALD,C E
 Transportation Branch ip 14506 191
- 8208040272 Requests registration as user of Hodels 6717~8 & 650 MCCKLI, B MBI Testing, Inc 82/07/13 MACDDNALD, C E Transportation Branch 1p 14224 340
- 8208190128 Requests registration as user of Models 630.6717-8.640 & 660E MOCKLI,B MSI Testing, Inc. 82/07/27 MACDONALD,C E Transportation Branch Ip 14506 190
- 8208240100 Notification of registration as user of Models 650 & 6717-Br in response to 820713 request. MACDONALD, C E Trensportation Branch 82/08/10 ORIFFITHS, W 8 MSI Testing, Inc. 19. 14529,301
- DECKET 71-9006 MODEL, 500-8U, AUTOMATION INDUSTRIES, INC.
- B208050023 Application for amend to Certificate of Compliance 9006, incorporating authorization for using drum overpack when Model 900-8U source charger contains two sealed IR-192 sources BANTORO, M.P. Automation Industries, Inc. B2/07/16 MACDONALD, C.E. Transportation Branch 2pp 14243 104,
- DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.
- 8208040272 Requests registration as user of Models 6717-B & 650 MCCKLI.B MSI Testing Inc 82/07/13 MAGDONALD.C E Transportation Branch ip 14224 340.
- 8208040262 Requests registration as user of Model 550 EKBERO, E Smith-Emery Co. 92/07/22 MACDONALD, C E Transportation Branch 1p. 14225-153
- B208190128 Requests registration as user of Hodels 650,6717-8,660 & 660E MCCKLI,B MSI Testing, Inc. 82/07/27. MACDUNALD, C E Transportation Branch. Ip. 14506-190
- 8208130414 Notification of registration as user of Models 650,660,683 & 750 in response to 820618 request MACDONALD,C E. Transportation Branch 82/07/30. FIGHER,R Q Thayer Inspection Service, Inc. ip 14350 361.

- 8208240072 Notification of registration as user of Model 650, in response to 820723 request MACDDNALD, C E Fransportation Branch 82/08/10 DUNHAM, M S 8mith-Emery Co 1p 14327 305
- 8208240100 Notification of registration as user of Models 650 & 6717-8in response to 820713 request MACDONALD,C E Transportation Branch 82/08/10 ORIFFITHS, H 8 MBI Testing, Inc. ip 14527 301
- 8208230179 Notification of registration as user of Models 650 & 660E, in response to 820608 request MACDONALD, C E Transportation Branch 82/08/10 WILSON, J C Wilson Inspection Services. Inc ip 14559 233
- DOCKEY 71-9033 HODEL 660 & 660E, TECHNICAL OPERATIONS, INC
- 9209190128 Requests registration as user of Models 450.6717-B.640 & 660E MCCKLI.B MSI Testing.Inc 82/07/27 MACDONALD.C E Transportation Branch Ip 14506 170
- 8208130414 Notification of registration at user of Models 650,660,683; 750 in response to 820618 request MACDONALD.C E Transportation Branch 82/07/30 FISHER,R Q Thayer Inspection Service, Inc. 1p 14350 361
- 8208230179 Notification of registration as user of Models 650 & 6605. in response to 820608 request MACDONALD, C E. Transportation Branch 82/08/10 WILSON, J C Wilson Inspection Services. Inc 1p 14557 233
- DOCKET 71-9036 MODEL C-1. SOURCE PRODUCTION & EQUIPMENT CO
- 820B190141 Requests registration as user of Models 6717-B,C-1 & Spec 2-T HEAD,T 0 Monroe X-Ray Co. Inc. 82/07/08 MACDONALD,C E Transportation Branch ip 14506 191
- DOCKET 71-9083 MODEL 483, TECHNICAL OPERATIONS, INC.
- 8208130414 Notification of registration at user of Models 650,660,663 p 750 in response to 820618 request MACDONALD.C E Transportation Branch 82/07/30 FIGHER,R 0 Thayer Inspection Service, Inc. ip 14350 361
- DOCKET 71-9056 MODEL SPEC 2-T, BOURCE PRODUCTION & EQUIPMENT CO
- 9209190141 Requests registration as user of Models 6717-8.C-1 & Spec 2-T HEAD.T @ Honrow X-Ray Co , Inc 82/07/08 MACDONALD.C.E Transportation Branch Ip 14506 191
- DOCKET 71-9074 MODEL AP-100, ANEFCO, INC
- B208090036 Requests add1 into needed to review B20708 revised consolidated application for renewal of Certificate of Compliance 9074 for Model AP-100 MACDONALD.C E. Transportation Branch. B2/07/27 MURPHY, J D Anefco.inc ip. 14301 108
- DOCKET 71-9079 MODEL, HN-100, BERIES 2 & 2A, HITTMAN NUCLEAR
- 8208190111 Requests registration as user of Models CN8 8-120,HN-20 CN6-80A,CN8 21-300,CN8 14-195-H,HN-100 Beries 1,HN-100 Beries 2,HN-1008 & 9080 KEIBER:H W Pennsylvania Power & Light Co 82/07/23 HACDONALD,C E. Transportation Branch 2pp 14506-361.
- 8208240080 Natification of repistration as user of Models CNS 14-1 CNS 21-300.CNS 8-120.CNS 6-80-2.HN-100 Beries 1,HN-100 Beries 2,HN-200 & 9080.In response to 820723 request MACDONALD.C E. Transportation Brench 82/08/10. CURTIB.N M. Pennsylvania Power & Light Co ip 14827 315

- DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8208190111 Requests registration as user of Models CNS 9-120, HN-200, CNS-80A, CNS 21-300, CNS 14-195-H, HN-100 Beries 1, HN-100 Series 2, HN-1008 & 7080 KEISER, H W Pennsylvania Power & Light Co 82/07/23 HACDONALD, C E Transportation Branch 2pp 14506 361
- B20B240080 Notification of registration as user of Models CNS 14-195-N, CNS 21-300, CNS 8-120, CNS 6-80-2, HN-100 Series 1, HN-100 Series 2, HN-200 & 9080, in response to 820723 request MACDONALD, C E Transportation Branch 82/08/10 CURTIS, N W Pennsylvania Power & Light Co 1p 14529 315
- DOCKET 71-9086 MODEL HN-100, SERIES 1, HITTMAN NUCLEAR & DEV. CORP.
- B20B170111 Requests registration as user of Models CNS B-120.HN-200, CN6-B0A.CNS 21-300.CNS 14-195-H.HN-100 Beries 1.HN-100 Beries 2.HN-1008 4 9080 KEISER.H W Pennsylvania Power & Light Co B2/07/23 HACDONALD.C E Transportation Branch 2pp 14506:361
- 8208170014 Advises that encl application & drawings marked proprietary should be placed in FDR MACDONALD, C.E. Transportation Branch 82/07/28 SCOTT, B Document Management Branch 1p 14373; 342
- --820B17001B Application for renewal of Certificate of Compliance 9086 for HN-100 Beries 1 radioactive matis shipping cask "SAR for HN-100 Serses 1 Radwaste Shipping Cask" encl MALLORY.C W Hittman Nuclear & Development Corp (subs Hittman Corp) B2/07/23 MACDONALD.C E Transportation Branch. Spp 14373.343
- --8208170023 "SAR for HN-100 Series I Radwaste Shipping Cask," Revision O Three oversize drawings encl Aperture cards are available in PDR PETTIOREW, M Hittman Nuclear & Development Corp. (subs Hittman Corp) STD-R-02-004 ROO 82/07/23 118pp 14373 351.
- 8208240080 Notification of registration as user of Models CNS 14-195-H, CNS 21-300.CNS 8-120.CNS 6-80-2, HN-100 Series 1, HN-100 Series 2, HN-200 & 7080.in response to 820723 request MACDONALD.C.E. Transportation Branch 82/08/10 CURTIS.N W Pennsylvania Power & Light Co 1p 14527 315
- DOCKET 71-9089 MODEL HN-1008, HITTMAN NUCLEAR & DEVELOP CORP
- 820B190111 Requests registration as user of Models CNB B-120, HN-200, CNS-80A:CNB 21-300, CNB 14-195-H, HN-100 Series 1, HN-100 Series 2, HN-100B & 90B0

 RETSER:H W Pennsylvania Power & Light Co B2/07/23, HACDGNALD, C E Transportation Brench 2pp 14506 361.
- DOCKET 71-9094 MODEL CNS 14-195-H, CHEM-NUCLEAR SYSTEMS, INC
- 820B190111 Requests registration as user of Hodels CNS 8-120, HN-200, CNS-80A, CNS 21-300, CNS 14-195-H, HN-100 Series 1, HN-100 Series 2, HN-100B 4 70B0 KEISER, H. # Pennsylvania Power & Light Co 82/07/23, HAGDONALD, C E Transportation Branch. 2pp 14806 361.
- 8208240080 Notification of registration as user of Models CN8 14-195-H, CN8 21-300, CN8 8-120, CN8 6-80-2, HN-100 Series 1, HN-100 Series 2, HN-200 & 9080, in response to 820723 request MACDUNALD.C.E. Transportation Branch 82/08/10 CURTIS, N. H. Pennsylvania Power & Light Co 1p 14529-315
- DOCKET 71-9096 HODEL. CNS 21-300, CHEM-NUCLEAR BYSTEMS, INC.
- B20B2400B0 Notification of registration as user of Models CNB 14-195-H, CNB 21-300, CNB 8-120, CNB 6-80-2, HN-100 Beries 1, HN-100 Beries 1, HN-100 Beries 2, HN-200 & 9080, in response to B20723 request MACDONALD.C E. Transportation Branch. B2/08/10. CURTIE, N W. Pennsylvania Power & Light Co ip 14529, 315
- DOCKET 71-9098 MODEL: UCC-20WG-2 & 2A, UNION CARBIDE CORP
- 8208040110 Requests consolidated renewal application be submitted at least 30 days before 820930 expiration date of Certificate of Compliance 9098 MACBONALD.C.E. Transportation Branch. 82/07/15 VOTH, M.H. Union Carbids Corp. 1p. 14228;342.

- DOCKET 71-9111 HODEL CN96-80-2, CHEM-NUCLEAR SYSTEMS, INC
- B20B190111 Requests registration as user of Hodels CNB B-120, HN-200, CNS-80A, CNS 21-300, CNB 14-195-H, HN-100 Beries 1, HN-100 Beries 2, HN-1008 & 90H0

 KEISER, H W Pennsylvania Power & Light Co B2/07/23, MACDONALD, C E Transportation Branch 2pp 14506 361
- 8208240080 Notification of registration as user of Models CNS 14-195-H. CNS 21-300.CNS B-120.CNS 6-80-2.HN-100 Series 1.HN-100 Series 2.HN-200 & 7080 in response to 820723 request MACDDNALD, C & Transportation Branch 82/08/10 CURTIS, N W Pennsylvania Power & Light Co 1p 14529-315
- DOCKET 71-9128 MODEL C-8, GAMMA INDUSTRIES
- 8208240486 Requests registration as user of Hodels C-08 & C-10 BOZARTH.B L Industrial Fabricating 82/07/20 MACDONALD.C E Transportation Branch 1p 14544 161
- DOCKET 71-9132 HODEL, T-3, ENERGY, DEPT OF
- 8208040073 Forwards request for add1 info re 820616 application to amend Model T-3 packaging.

 #AGDONALD,C E Transportation Branch 82/07/15 HANBEN:L J
 Nuclear Packaging, Inc. 2pp. 14228 287
- 8208050038 Forwards Ravision 9 amends to Model T-3 BAR, per 820715 request Add1 calculations show that support base of holddown ring will withstand impact loadings w/o deforming. No add1 stress will be induced in containment vessel.

 HANSEN, L. J. Nuclear Packaging, Inc. 82/07/23 MACDONALD, C. E. Transportation Brench 1p 14243:130
- --B208050041 Revision 9 to 8AR for Model T-3

 * Nuclear Packaging, Inc. B2/07/31 22pp. 14243-151.
- 8208240033 Forwards Pages 1.2 & 3 of Revision 6 to Drawing H-4-61289 of Model T-3 inadvertently omitted from 820723 transmittal. Pages should be inserted of previously submitted Page 4 HACLBO,RT Nuclear Packaging, Inc. 82/07/26 MACDONALD,C E Transportation Branch. 7pp. 14529.068
- DOCKET 71-9135 HODEL, CENTURY B & SA, CEN UNIV. S & SA, CAMMMA IND.
- 8208040028 Advises that no addl fee required re 770824 application which resulted in 820430 Certificate of Compliance 9135. HILLER W. G. License Fee Management Branch 82/07/15 RICHARDBON,H D. Nuclear System. 19. 14235:353
- 8208130348 Concludes that packages authorized by Certificate of Compliance 9135 meet IAEA requirements for Type B(U) packages. MACDONALD.C.E Transportation Branch. 82/08/05. RAWL,R.R. Transportation,Dept. of. 1p. 14340
- DOCKET 71-9139 HODEL: 589, GENERAL ELECTRIC CO.
- 8208040047 Application for amend to Certificate of Compliance 9139, Revision 1, deleting Item 5(b)(1) re tecondary container requirement Amend fee not required per 10CFR170, 11(a)3, MILLE: L. H. Tennessee Valley Authority 82/07/07, MAGDDNALD, C. E. Transportation Branch. 1p. 14232 360
- 8208040403 Forwards Revision 2 to Certificate of Compliance 9139 for Model 589. MACDONALD.C.E. Transportation Branch, 82/07/22 CUNNINGHAM, G.E. General Electric Co. 2pp 14224-327
- --B20B040405 Cartificate of Compliance 9139, Revision 2, for Hodel 589
 Approval record and MACDONALD, C E Transportation Branch, 82/07/22 4pp. 14224 329
- DOCKET 71-9145 HODEL: NUPAC 50-1 5L, -2 5L, -3 OL & -4. OL, NO USERS
- 8208130345 Notification of registration as user of Model NUPAC 50-1 5L in response to 820616 request MACDONALDIC, & Transportation Branch 82/07/30, MARSHALLIUR Arkanses Power & Light Co. 1p. 14340:230,

- DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP
- 8208030055 Requests registration as user of Model HN-100,8eries 3 EBENHACK,D 0 Chem-Nuclear Systems, Inc 82/07/13 MACDONALD.C E Transportation Branch 1p 14208 338
- B20B170033 Advises that encl application & drawings marked proprietary should be placed in PDR Hittman Nuclear & Development Corp 820726 authorization ltr encl MACDONALD.C E. Transportation Branch 82/07/27 SCOTT.S Document Management Branch ip 14374 320
- --B208170035 Authorizes release to PDR of B20715 application & accompanying documentation in support of certification of HN-100 Series 3A radwaste shipping cask MALLORY,C W Hittman Nuclear & Development Corp (subs Hittman Corp) 82/07/26 Transportation Branch 1p 14374 321
- --8203170038 Application for amend to Certificate of Compliance 7151 to cover both HN-100 Series 3 & HN-100 Series 3A radwaste shipping casks Seven oversize drawings encl Aperture cards are available in PDR MALLORY, C H Hittman Nuclear & Development Corp (subs Hittman Corp.) 82/07/15 MACDONALD, C Transportation Branch 7pp 14374 332
- --B20B170052 "SAR for HN-100 Series 3 Radwaste Shipping Cask." Revision 5
 PETTIOREH.H Hittman Nuclear & Development Corp. (subs Hittman Corp.) STD-R-02-001 R05 B2/07/13 116pp 14374 331
- --8208170053 Revision O to "Addendum to SAR for HN-100 Series 3A Radwaste Shipping Cast " PETTIOREW.M Hittman Nuclear & Development Corp (subs Hittman Corp) 87D-R-02-004 R00 82/07/13 72pg 14375 082
- 8208240078 Notification of registration as user of Model HN-100 Series 3/in response to 820713 request MACDUNALD,C E Transportation Branch 82/08/10 MARSH,C A Chem-Nuclear Systems, Inc. 1p. 14529 279
- DOCKET 71-9158 MODEL. OPU 80, GENERAL PUBLIC UTILITIES
- 8208090033 Forwards request for add1 info needed re review of 820126 application for approval of Model GPU 80 MACDDNALD, C E Transportation Branch 82/07/23 PARKER, P E Ridihalgh, Eggers & Associates opp 14301:102
- 8208170394 Informs of continuing activities re REA casks & request for add1 structural/mechanical personnel to suppl activities, per 820723 commitment Communications between review personnel & NRC staff requested LILIEN.L H Owneral Public Utilities OPU Bervice Corp 82/07/24 MAGDONALD.C E Transportation Branch ip 14372 332
- DOCKET 71-9159 MODEL NUPAC SERIES A. NUCLEAR PACKING. INC
- B208020460 Forwards "SAR for NUPAC Series A Casks to 10CFR71 Type A Packaging Requirements "
 SIMCHUK.J D Nuclear Packaging. Inc 82/06/25 MACDONALD, C. E. Transportation Branch 2pp 14180:079
- --8208020461 "BAR for NUPAC Beries A Casks to 10CFR71 Type A Packaging Requirements " * Nuclear Packaging, Inc. 82/06/29 85pp. 14180 082
- DOCKET 71-9161 MODEL: R. GULF NUCLEAR, INC
- B204190002 Requests agglication fee for review of "Package Evaluation, Model ONM 20. Type B Quantities." submitted in vendor 820302 request for approval of shipping containers. Models R. GNO-20. GNM-20.20-VB & 40-VS

 JACKEON.O License Fee Hanagement Branch. 82/03/25. PAYNE, A E Quif Nuclear, Inc. 2pp 12730 137
- --8204170004 "Package Evaluation Model ONM-20. Type B Guantities " IAEA Certificate of Competent Authority encl. * Quif Nuclear, Inc 82/03/04 20pp. 12730 138.

- DOCKET 71-9162 MODEL ONH-20, GULF NUCLEAR, INC
- B204190002 Requests application fee for review of "Package Evaluation, Model GNM 20. Type B Quantities," submitted in vendor B20302 request for approval of shipping containers, Models R, GNG-20, GNM-20, 20-VS & 40-VB JACKSON, G License Fee Management Branch B2/03/25 PAYNE, A E Gulf Nuclear, Inc. 2pp 12730 137
- DOCKET 71-9143 MODEL GNG-20, QULF NUCLEAR, INC
- 8204190002 Requests application fee for review of "Package Evaluation, Hodel ONM 20, Type B Quantities," submitted in vendor 820302 request for approval of shipping containers, Models R, GNG-20, GNM-20, 20-VS & 40-VG JACKBON, G License Fee Management Branch 82/03/25 PAYNE, A E GUIF Nuclear, Inc. 2pp 12730 137
- DOCKET 71-9146 MODEL 864 TYPE B, TECHNICAL OPERATIONS, INC.
- 8208240038 Application for Certificate of Compliance 9166 for Model 864 Type B package SAR ancl MURRO.J J Tech/Ops (Technical Operations, Inc.) 82/07/15 MAGDONALD.C E. Transportation Branch 2pp 14548 042
- ---8208240042 "SAR Tech/Ops, Inc Model 864 Type B(U) Package "

 * Tech/Ops (Technical Operations, Inc.) 82/07/15 67pp
 14548 044
- DOCKET 71-9186 MODEL 8-6213, ENERGY, DEPT OF
- 8208170391 Application for renewal of listed certificates of compliance ENGEL,W P Energy, Dept of 82/07/27 MACDONALD.C E Transportation Branch 4pp 14372 328
- LICENSING OF INDEPENDENT SPENT FUEL STORAGE
- DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CD
- 8208250458 Forwards Amend 1 to License BNM-2500 & notice of issuance & availability Amend permits receipt of fuel assemblies having lower enrichment ROUSEL C. Advanced Fuel & Spent Fuel Licensing Dranch B2/08/12 DAMBON: D M General Electric Co Zpp 14562 273
- -8208250463 Amend 1 to License SNM-2500, permitting receipt of fuel assemblies having lower enrichments RQUSE.L C Advenced Fuel & Spent Fuel Licensing Branch 82/08/12 opp 14562 275
- --8208250468 Notice of issuance & availability of Amend 1 to License SNM-2500 RDUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/08/12 200 14562 281
- 8208300111 Forwards IE Insp Rept 72-0001/82-01 on 820720-23 No noncompliance noted MILLER, JR Division of Engineering & Technical Programs 82/08/12 VAN HOUHISSEN, J General Electric Co 2pp 14596 124
- --8208300114 IE Insp Rept 72-0001/82-01 on 820720-23 No noncompliance noted Hajor areas inspected fuel receipt & storage, radiation protection, transportation activities, QA, safety committees & surveillance specs PECK, C. C. GREGER, L. R. Division of Engineering & Technical Programs 82/08/10 4pp 14896 126

NONDOCKETED ITEMS

COMMISSION MEETING RECORDS 10CE8

- 8207220007 Unofficial transcript of 820714 public meeting in Hashington, DC re 8ECY-82-204/10CR61 licensing requirements for land disposal of radwasts Pp 1-85 Visugraphs encl © Commissioners 82/07/14 93pp 14028 049
- 8208020028 Staff requirements memo re Commission 820714 briefing in Mashington DC on draft final rule in SECY-82-204.10CFR61, "Licensing Requirements for Land Disposal of Radwaste" CHILK, 8 J Diffice of the Secretary of the Commission MB20714A 82/07/19. Office of the Becretary of the Commission 1p
- 8208020034 Staff requirements memo re Commission 820715 briefing in Washington, DC on status of plans for QA improvements CHIEK-S, J Office of the Secretary of the Commission M820715A 82/07/19, DIRCKS, W J Office of the Executive Director for Operations ip 14181,055
- 8208020421 Staff requirements memo re 820720 discussion of 8ECY-82-183 concerning proposed rulemaking on accreditation of qualiffication testing organizations No Commission requirements or requests made of staff at meeting CHILK, 8 J. Office of the Secretary of the Commission H820720 82/07/20 Office of the Secretary of the Commission, ip
- 8208040248 Staff requirements memo re Commission B20716 affirmation session on SECY-B2-111. "Requirements for Emergency Response Capability " SECY approved w/certain additions CHILK.8. J Office of the Secretary of the Commission MB20716. B2/07/20 DIRCKS.W J Office of the Executive Director for Operations. 7pp. 14232 266
- 8208040505 Btaff requirements memo transmitting NRC Form 3, correcting 820622 staff requirements memo inadvertently dispatched w/incorrect attachment 4 Office of the Secretary of the Commission 82/07/21 2pp 14220 326
- 8208040539 Transcript of 820721 public meeting in Washington.DC re min number of shifts required at operating reactors.Pp 1-43 Visugraphs encl. © Commissioners 82/07/21 58pp 14223:180
- 8208040557 Transcript of 820721 public meeting in Washington, DC re ORNL rept. "Potential Precursers to Severe Core Damage"
 Pp 1-75 Viewgraphs enc1
 * Commissioners 82707/21 98pp 14221, 042
- 8208050043 Transcript of 820723 public meeting in Washington, DC re-budget briefing, Pp 1-173 Commissioners 82/07/23. 181pp 14243 200
- 820805020& Staff requirements memo re 820723 briefing on FY82-85 NRC Budget estimates. Commission requested OMB waiver of FY82 FTE cefling, quarterly reviews of budget activity & breakdown of contract funds between nat1 labs & other contractors CHFLK.8 J Office of the Secretary of the Commission. M820723 82/07/29 DIRCKS, W. J Office of the Executive Director for Operations ip 14242 085
- 9208080016 Staff requirements memo informing of Commission 820714 discussion of safety goals, implementation program & draft proposed policy statement. CHILK.B.J. Office of the Secretary of the Commission M8207141 82/07/16 DIRCKS.W.J. Office of the Executive Director for Operations REMICK.F.J. Office of Policy Evaluations 1p. 14244: 359.

- 8208040018 Staff requirements memo informing of Commission 820622 discussion of amergency response facilities re NUREQ-0496 & SECY-82-111 SECY-82-111 affirmed on 820716 CHILKS J Office of the Secretary of the Commission M820422 SECY-92-16 Office of the Secretary of the Commission ip 14244 359
- 8208060067 Transcript of 820715 affirmation/discussion session re BECY-82-99 & BECY-82-257 in Washington, DC Pp 1-13 * Commissioners 82/07/15 25pp 14282 177
- 8208060069 Transcript of 820716 affirmation/discussion session re SECV-82-111 in Washington,DC Pp 1-3 * Commissioners 82/07/16 7pp. 14282,203
- 8208090326 Commission determination releasing portions of Commission BZO602 meeting in Washington DC re-briefing to improve efforts on IAEA safeguards Pp 1-91 Meeting closed per Exemption 1 Commissioners 82/08/03 96pp 14307, 111
- 820B100377 Transcript of 820720 public meeting re discussion of BECY-82-153 on proposed rulemaking, accreditation of qualification testing organization in Washington, DC Pp 1-99 Viewgraphs encl 82/07/20 124pp 14317-160
- 8208110276 Transcript of budget briefing public meeting in Washington. DC.Pp 1-90 * Commissioners 82/07/27, 100pp 14331 295.
- 8208300004 Informs that Commission approved issuance of proposed rule on applicability of license conditions & Tech Specs in amorgancy on 820723 Ltrs to inform Congressional committees of action & draft FR notice and l
- --8208300019 Staff requirements memo discussing 820715 affirmation session of publication of proposed rule to allow licenses to take reasonable action outside Teck Specs in emergency CHILK-S J Defice of the Servetary of the Commission 82/07/23, BICKWITL Office of the Ceneral Counsel COTTER.P B Atomic Safety and Licensing Board Penel DIRCKH, J Defice of the Executive Director for Operations 13pp. 14695.036
- 8208310504 Staff requirements memo re 820614 discussion on SECY-82-111 COSIONAL STAFF requirements memo re sponse capability

 CHILK: B J Office of the Secretary of the Commission MB20614

 82/07/16. Office of the Secretary of the Commission ip

ACRR ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

- 8206270086 Comments on NRC comments on App E, "Statistical Analysis of LERs. Trial Study, Within NUREO-0572," Underlying model & probabilistic assumptions not explicitly stated BAUNDERS, B C ACRB Advisory Committee un Reactor Safeguards 80/04/17. MOELLER.D. ACRB Advisory Committee on Reactor Safeguards. 2pp. 14194 ii3
- 8206270098 Comments on SECY-82-111. "Requirements for Emergency Response Capability." Task analysis preliminary to implementation of design mods included for safety parameter display sys recommended DESONS.A. ACRS Advisory Committee on Reactor Safeguards. 82/07/19. 4ARD.D. ACRS Advisory Committee on Reactor Safeguards. 2pp. 14194-118

- 8207110049 Bummary of ACRS Subcommittee on Transportation of Radioactive Matis 820414 meeting in Washington.DC re adequacy of procedures used by Transportation Certification Branch in certifying packages * ACRS Advisory Committee on Reactor Safeguards 62/06/04 ACRS Advisory Committee on Reactor Safeguards 68pp
- 8208020409 Forwards corrected TO Theofanous 820415 ltr to ACRB re Mark III pool swell velocity spec Second paragraph MARK III pool swell velocity spec mecono paregraph
 incorrectly typed
 ROBERTS.B ACRS - Advisory Committee on Reactor Safeguards
 B2/07/13 GOODMIN,E Office of Nuclear Reactor Regulation,
 Director REHM.T Office of the Executive Director for Operations
 JONES,P. NRC - No Detailed Affiliation Given 1p 14179 180
- --8208020412 Discusses Mark III pool swell velocity spec Suggests that analysis be made to match as closely as possible full-scale test using actual drywell pressure Corrected copy THEDFANDUS, T Q Purdue Univ THEDFANDUS, T Q ACRB Advisory Committee on Reactor Bafeguerds. 82/04/15 BUEHNERT, P ACRS Advisory Committee on Reactor Bafeguerds. 92/04/15 BUEHNERT, P ACRS Advisory Committee on Reactor Bafeguerds ip 14179,181
- 8208040173 Transcript of ACRB Fluid Dynamic Subcommittee 820729 meeting in Ban Jose, CA Pp 1-235

 * AGRB - Advisory Committee on Reactor Bafsguards 82/07/29.
 371pg 14186 001
- 8208050519 Transcript of ACRS Fluid Dynamics Subcommittee 820730 meeting in Ban Jose CA Pp 236-379 Viewgraphs encl. # ACRS Advisory Committee on Reactor Safeguards 82/07/30. 180pp. 14216:064
- 8208100241 Transcript of ACRS Subcommittee on Class 9 Accidents 820806 meeting in Washington, DC. Pp 1-96 Viewgraphs encl * ACRS Advisory Committee on Reactor Safeguards. 82/08/06 131pp 14295:001
- 8208100254 Transcript of ACRS Subcommittee on Reliability & Probabilistic Assessment 820806 meeting in Weshington, DC Pp I-138 Viewgraphs encl = ACRS Advisory Committee on Reactor Safeguards. 82/08/06 160pp. 14295, 195
- 8208120364 Provides comments on minutes from ACRS 256th meeting & Advanced Reactors Subcommittee 820115 meeting per 820715 GODDNIN, E. F GOODMIN.E.F. Office of Nuclear Reactor Regulation, Director. 82/09/03, BARNARD.E M. ACRS - Advisory Committee on Reactor Bafeguards 2pp. 14340:035
- -8207050006 Forwards minutes from listed ACRS meetings for review & BARNARD,E.M. ACRE - Advisory Committee on Reactor Safeguards B2/07/15, REHM,T.A Office of the Executive Director for Operations 93pp 14339 303
- J208130134 Transcript of ACRS Bubcommittee on Safety Research Program B20811 meeting in Washington, DC Pp 1-130 Supporting documentation encl. ACRS Advisory Committee on Reactor Safeguards 82/08/11 178pp. 14335:149.
- 8208130139 Transcript of ACRB Subcommittee on Extreme External Phenomena 820811 meeting in Machington, DC. Pp 1-55 Supporting documentation encl + ACRB Advisory Committee on Reactor Safeguards 82/08/11. 94pp. 14338:103.
- 8208160052 Transcript of AGRS 268th general meeting on 820812 in Washington, DC, Pp 1-258. Viewgraphs encl. A AGRS Advisory Committee on Reactor Safeguards 82/08/12 400pp. 14343:001
- 8208170007 Franscript of ACRS 268th general mesting on 820813 in Mashington DC. Pp 259-408 Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguerds B2/08/13-200pp 14360:340.
- 8208250154 Transcript of ACRS Subcommittee on Transportation of Radioactive Matls 820824 meeting in Washington, DC Pp 1-284.

 ** ACRB - Advisory Committee on Reactor Safaguards. 82/08/24.
 278pp. 14556.001.
- 3208300096 Transcript of ACRE Subcommittee on Reactor Operations 820825 meeting in Mashington. DC Pp 1-306 Viewgraphs encl e ACRE ~ Advisory Committee on Reactor Safeguards 300pp. 14996:135.

COMMISSION NRC COMMISSIONERS

- 8206200094 Forwards "NRC/FEMA Joint Monthly Rept to Congress on Emergency Preparedness, June 1982 " PALLADIND:N J. Commissioners GlUFFRIDA:L D Federal Emergency Management Agency 82/07/21 SIMPSON, A X Senate, Environment & Public Works 2pp 14506 209
- ---B208190053 "NRC/FEMA Joint Monthly Rept to Congress on Emergency Preparedness, Juns 1982 "

 NRC No Detailed Affiliation Given * Federal Emergency Management Agency 82/07/21 61pp 14506 211
- 8206200095 Requests reconsideration of rejection of Benate provision in NRC FY82 & 83 authorization bill designed to alleviate financial hardships associated w/relocating resident inspectors. Yun-ur program should be funded W/o encl PALLADING,N J Commissioners 82/07/28 UDALL.M K Interior & Insular Affairs 3pp. 14388'341 UDALL, M K House of Rep .
- 8206200098 Urges issuance of proposed EPA stds for mgt & disposal of high level waster-AOCFR191: currently under development PALLADING,N. J Commissioners, 82/07/08 GORBUCH, A M Environmental Protection Agency ip 14306 233
- 8206200099 Forwards comments on 8 B 1662.Natl Nuclear Waste Policy Act of 1982.in response to 820305 request Early enactment of comprehensive waste mgt legislation supported PALLADINO.N.J. Commissioners 82/07/06 PETERSON.R K Office of Management & Budget 4pp 14306-234
- --B20Bi00376 Requests comments on encl bill 8 B i662,Natl Nuclear Haste Policy Act of 1982 OMB will not object to bill if response not received by 820519 PETERBON.R K Office of Management & Budget 82/05/05 NRC -No Detailed Affiliation Given. 54pp 14306-238
- 8206200100 Comments on enrolled bill S B 881, Small Business Innovation Development Act of 1982, in response to 820701 request. Although difficulties may be experienced in meeting requirements of bill, veto not recommended. PALLADINO, N J. Commissioners 82/07/07 FREY, J M. Office of Management & Budget 2pp 14306 225.
- --8208100378 Requests comments on encl S.B 881,8mall Business Innovation Development Act of 1982.Comments requested within 2 days after rateript of ltr. FREY,J M Office of Management & Budget. 82/07/01 BICKHIT,L Office of the General Counsel App 14306.227
- 8208060362 Public version of weekly info rept for wk ending 820723 REHM.T.A Office of the Executive Director for Operations 82/07/29. SOpp. 14281 287.

CONTRACT NRC CONTRACTS AND MODIFICATIONS

- 8208020064 Notification of contract execution "Provide Expert Technical Consulting Byc to Document Control Bye on Task Order Basis, awarded to Dept of Air Force BAZIN. J. Administrative Controcts Branch NRC-10-82-404, 82, MDRRY, F , LUNDY, J. Office of Administration. 1p 14180 350 82/06/21.
- ---8208020066 Contract. "Provide Expert Technical Consulting Svcs to Document Control Sys on Task Order Basis." awarded to Dept of Air Force,

 BALL.C. Q., WYRICH, T. F. Air Force, Dept. of. LEBG, C. D. [
 Contracts NRC-10-82-404 82/06/21, 12pp. 14180 351.
- 8208020068 Notification of contract execution, Mod 4 to "Operation & Maint of NRC Document Control Bys (DCS) " Contractor: Planning Research Corp., HIGGINS, E. Administrative Contracts Branch NRC-10-82-356 82/07/02. NORRY, P. g., LUNDY, J. Office of Administration. 1p 14181: 001.
- --B208020069 Mod 4, providing add1 funds for maint & relocation of terminals, to "Operation & Maint of NRC Document Control Bys (DCB)."

 THANM.E.O. Planning Research Corp. SMITH.P.A. Administrative Corp. SMITH.P.A.
 - SMITH, P. A. / Bys (DGB), "
 THAMM.E.O. Planning Research Corp. SMITH, P.
 Contracts Branch. MRC-10-82-356 82/07/02. Administrative
- 8208020449 Notification of contract execution, Mod 1 to "Intrinsic Germanium Germa-Ray Detector." Contractor, Princeton Qamma-Tech, Inc. PERLMAN.J. Administrative Contracts Branch NRG-28-82-716. 82/07/21. MCOBCAR.J.D., KOTTAN.J Region 1, Office of Director. 14181:027

- --B20B020452 Mod 1.changing type of contract & saying ofc & correcting contract number from NRC-23-B2-716 to NRC-2B-B2-716, to "Intrinsic Germanium Gamma-Ray Detector"

 * Princeton Camma-Tech, Inc SMITH, PA Administrative Contracts
 Branch NRC-28-B2-716 62/07/21 1p 14181 028
- 8208030733 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Callaway County, MD Public Library
 County, MD Public Library
 LITTLE: M Administrative Contracts Branch NRC-10-82-418
 82/07/14 FELTON, J M , SOUDER, J Division of Rules and Records.
 1p 14197-337
- --B208030735 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Callaway County, MO Public Library JUSTICE,L H Callaway County, MO REBELLO, J E Administrative Contracts Branch NRC-10-82-418 B2/07/14 9pp 14197:338
- 9208040022 Notification of contract execution "Geotechnical On-Call Assistance for Case Reviews," awarded to Dept of Army
 EDGEWORTH, P Technical Assistance Contracts Branch FIN B-8032
 NRC-03-82-107 82/07/13 WOLLMER, R H, HELLER, L Division of
 Engineering ip 14232 323
- --820B040023 Ltr Contract NRC-03-82-107 "Geotechnical On-Call Assistance for Case Reviews," awarded to Dept of Army MATTIA:M J Technical Assistance Contracts Branch FIN 8-8032 NRC-03-82-107 82/06/15 FRIEDENWALD,R L Army,Dept of, Corps of Engineers 11pp 14232 324
- B20B040336 Notification of contract execution. Mod 3 to "Assessment of Waste Retrieval Alternatives " Contractor Engineers Intl,
 - Ince Contracts Branch NRC-02-82-031
 FLEEMOR.C Technical Assistance Contracts Branch NRC-02-82-031
 B2/07/21 DAVIS.J. CHABE.L Office of Nuclear Material Safety & Bafeguards.Director 1p 14224 335
- --B208040340 Mod 3, changing NRC project officer, to "Assessment of Waste Retrieval Alternatives" > Engineers International HAGAN, T.F. Technical Assistance Contracts Branch NRC-02-82-031 82/07/21 ip 14224 334
- B2DB040383 Notification of contract execution, Mod 6 to "Review of Tailings Mgt." Contractor CO State Univ FIELDB. J A Tachnical Assistance Contracts Branch NRC-02-80-082 82/07/20 DAVIB.J., FLEMING.T Office of Nuclear Material Safety & Safeguards, Director Ip 14224 307
- --8208040383 Mod 6.adding work requirement & extending expiration date to 820930.to "Review of Tailings Mgt"
 BRDWN.J F. Colorado State Univ HAOAN.T F Technical Assistance Contracts Branch NRC-02-80-082 82/07/20 3pp 14224
- 8208040409 Notification of contract execution. Mod 1 to "Geotechnical On-Call Assistance for Case Reviews " Contractor Dept of MFMW EDQEWORTH,P Technical Assistance Contracts Branch FIN 8-803 NRC-03-82-107 82/07/13 VOLLMER,R H . HELLER,L Division of Engineering. 1p 14224 008 FIN 0-8032
- --8208040477 Ltr Contract NRC-03-82-107, Mod 1, to "Geotechnical On-Call Assistance for Case Review " Renders Task Order 1 effective MATTIA: M. J. Tachnical Assistance Contracts Branch Fin B-8032, NRC-03-82-107 82/06/15 FRIEDENWALD: R Army, Dept of, Corps of Engineers 4pp. 14224 009
- 8208040493 Notification of contract execution, Mod 2 to "NV Test Site (NTB) Visit "Contractor Golder Associates FLEENOR, C Technical Assistance Contracts Branch, NRC-02-82-042 82/07/02 DAVIS, J, JOHNSON, R Office of Nuclear Material Safety & Safeguards, Director ip 14220 324
- -- 8208040498 Mod 2, changing loaded hourly rate of personnel, to "NV Test
- B208040548 Notification of contract execution, Mod 1 to "Photographic Reproduction Bucs, "Contractor Chromocolour Lab.Inc
 PERCHAN, J. Administrative Contracts Branch, NRC-10-82-392
 82/07/22 BESAW, W.J. Division of Technical Information & Document
 Control. 19 14221 001
- --E20B040550 Mod 1, providing administrative changes, to "Photographic Reproduction Sycs" * Chromacolour, Inc BMITH, P.A. Administrative Contracts Branch NRC-10-82-392, 82/07/22 2pp 14221.002

- 6208040637 Notification of contract execution, Mod 1 to "NV Test Bite (NTB) Visit " Contractor Golder Associates FLEENOR.C Technical Assistance Contracts Branch NRC-02-82-042 62/06/18. DAVIS.J., JOHNSON, R Office of Nuclear Material Safety & Bafeguards, Director 19 14224 020
- -8208040643 Mod 1.changing appropriation symbol, revising schedule of meetings & extending period performance to 820702, to "NV Test Bite (NTB) Visit"
 EDEY, A Golder Associates HAGAN, T.F. Technical Assistance Contracts Branch NRC-02-82-042 82/06/18 2pp 14224 021
- 8208040667 Notification of contract execution. Mod 21, to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions " Contractor Franklin Inst HAGAN.T F Technical Assistance Contracts Branch FIN B-6590 NRC-03-79-118 82/07/15 EIBENHUT, D., BAJWA.S Division of Licensing 1p 14225 228
- --8208040671 Mod 21, modifying Section 3.0 re consideration & payment revising Attachment C sward fee determination plan, to "Review & Evaluation of Approx 500 Pending Operating Restors if can in Actions" "Review & Evaluation of Approx 500 Fending Operating Reactors Licensing Actions " BTOVER.JR Franklin Institute/Franklin Research Center MATTIA.H J Technical Assistance Contracts Branch FIN 8-6590 NRC-03-79-118 82/07/15 9pp 14225 229
- 8208040674 Notification of contract execution, Mod 3 to "Technical Assistance for Fire Protection of Contract execution, Mod 3 to "Techn Assistance for Fire Protection Program Review & Evaluation Contractor Cage-Babcock & Associates, Inc FIELDS, J. Technical Assistance Contracts Branch. NRC-03-6 82/06/04 VOLLMER, R., FERGUSON, R. Division of Engineering 14225-292 Division of Engineering
- --8208040480 Mod 3, extending period of performance to 820930 & modifying estimated cost & obligation, to "Technical Assistance for Fire Protection Program Review & Eveluation "

 COHN, B M Oage-Babcock Associates, Inc. HAGAN, T F Technical Assistance Contracts Branch NRC-03-81-140 82/06/04. Ip 14225-293
- 8208040582 Natification of contract execution, Mod & to "Btudy of IN Fault Locations, Displacements, Attitudes & Ages Within 200 Mile Radius of New Madrid, MR Ragion "Contractor: IN Univ SILVIS.R M Research Contracts Branch FIN 8-6262, NRC-04-77-1682/07/27 BATSON, W, BTEVER, N Office of Nuclear Reactor Ragulation, Director ip. 14225-290 NRC-04-77-164
- --8208040485 Ltr contract NRC-04-77-164, Mod & deobligating funds, to "8tudy of IN Fault Locations, Displacements, Attitudes & Ages Hithin 200 Mile Radius of New Madric, MD Region "QUSTAVER P Research Contracts Branch, FIN B-0262 NRC-04-77-164 82/07/09 MULHOLLAND, J Indiana Univ 1p
- 8208080078 Notification of contract execution, Mod 1 to "Freventive Maint for Micrographics Equipment" Contractor Microtech Industries, Inc Industries.inc PAGE.M Administrative Contracts Branch NRC-10-81-397 82/07/08, RIENBTRA.D. SKUCZŁAB.J Offics of Administration ip 14243:038
- --8208050086 Mod 1.extending performance 1 yr.to "Preventive Maint for Micrographics Equipment" * Microtach Industries, Inc. SMITH.P.A Administrative Contracts Branch NRC-10-81-397. B2/07/08 2pp 14243 039
- 8208030140 Notification of contract execution: "Assay of Long-Lived Radionuclides in Low Level Wastes From Power Reactors," awarded to Bolence Applications. Inc EDGEMORTH,P Technical Assistance Contracts Branch FIN 8-7356-1 NRC-02-82-043 82/06/28. DAVIS.U.G. (CLINE, J. Office of Nuclear Material Safety & Safeguards, Director ip 14243 011 FIN B-7354-2 Office of Nuclear
- ---8208050146 Contract "Assay of Long-Lived Radionuclides in Low Level Wastes From Power Reactors," awarded to Bcience Applications, Inc FINDLEY, D.E. Bcience Applications, Inc MATTIA, H. J. Technical Applications, Inc FINDLEY, D.E., Science Applications, Inc. MATTIA, H.J. Technical Assistance Contracts Branch, FIN B-7356-2, NRC-02-82-043 82/06/28 14pp. 14243-012
- 8208060001 Notification of contract execution: "Technical Assistance CONDUCTION REPORT TO THE CONTRACT EXECUTION: "THE ANIEST ASSISTANCE FOR DASIGN Review," awarded to Engineers Intl, Inc.

 EDDEMORTH.P Technical Assistance Contracts Branch FIN 8-7328-2.

 NRC-02-82-030 82/07/19 DAVIS.J., BEAMANS, T. Dffice of Nuclear

 Naterial Safety & Safeguards, Director. 1p 14280 001
- --8208060002 Contract "Technical Assistance for Design Review," awarded to Engineers Inti. Inc SINGH.M H Engineers International MATTIA.M J Technica Assistance Contracts Branch FIN B-7328-2. NRC-02-82-030. 82/07/19 16pp 14280 002

- 8208060023 Notification of contract elecution "Haint & Operation of Local Public Document Rooms (LPDRs)," awarded to Brooks Hemorial Library, VT LITTLE:M Administrative Contracts Branch NRC-10-82-421 82/07/19 FELTON, J M , SOUDER, J Division of Rules and Records ip 14244 343
- --B208060025 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Brooks Memorial Library, VT BRYANTJ Brattleboro, VT REBELLO, JE Administrative Contracts Branch, NRC-10-B2-421 B2/07/19, 9pp 14244 344
- 82080&0351 Notification of contract esecution, Mod 3 to "Presentation of General & Refresher Courses in Helding Technology & Codes " Contractor OH State Univ JACOBS. A Research Contracts Branch FIN X-1173 NRC-05-79-264 82/07/23 ELAMA, J . FOX. E Program Bupport Branch 1p 14281 283.
- --8208060353 Mod 3.adding courses & FY82 funds to, "Presentation of General & Refresher Courses in Welding Technology & Codes." REDHOND, R.F. Ohio State Univ GUSTAVE, R.P. Division of Contracts. FIN X-1173 NRC-05-79-264 82/07/29 ip 14281 284
- 8208060355 Notification of contract execution.Mod 1 to "Establish Computer Support Arrangements for NRC to Use OMB Computer Facility for Trial Period of Three Months " Contractor DMB SHITH,P A. Division of Contracts FIN 8-5051 NRC-07-76-242 82/07/23 CHILK.S J. MCOEE,W Office of the Secretary of the Commission ip 14281,285
- --B208060356 Mod 1.deobligating funds, to "Establish Computer Support Arrangements for NRC to Use DMB Computer Facility for Trial Period of Three Months"

 JONES.D. Office of Hanagement & Budget. SMITH, P. A. Division of Contracts. FIN B-3051 NRC-07-74-242 82/07/23 ip 14281.286
- 8208060364 Notification of contract execution "Courses in C-E Facility Design & Operation," awarded to C-E Power Sys BAIBDENIL, Research Contracts Branch FIN B-1301 NRC-05-82-241. 82/07/22 BLAHA, J. L., FOX.E Program Support Branch 1p. 14281 342
- --8208060365 Contract "Courses in C-E Facility Design & Operation," awarded to C-E Fower Bys awarded to C-E Fower Bys LECLAIR,D E Combustion Engineering, Inc MORTON,K V Division of Contracts, FIN 8-1301 NRC-05-82-241 82/07/22 8pp
- \$208110300 Notification of contract execution, Mod 1 to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents," Contractor.Parameter, Inc BROMBERO, B. Research Contracts Branch FIN B-1302 NRC-05-B2-249, B2/08/03 BLAHA, J. LAUDAN, W. Director's Office, Office of Inspection and Enforcement ip. 14331 139
- -8208110302 Mod 1.changing contractor address to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents " * Persenter, Inc MORTON, K V Research Contracts Branch FIN B-1302. NRC-03-82-247. 82/08/03 1p. 14331 140
- #208120378 Notification of grant execution "Gas Release Mechanisms in U Dioxide," awarded to Purdue Research Foundation.

 BAIBDEN:L Research Contracts Branch FIN G-1031, NRC-0-04-82-005
 82/08/03 BAYBON:N, MARINO,0 Office of Nuclear Regulatory
 Research Director ip 14337 283
- --B208120381 Orant: "Oas Release Mechanisms in U Dioxide," awarded to Purdue Research Foundation OREENKORN, R.A. Purdue Research Foundation. HORTON, K V Research Contracts Branch. FIN 0-1031. NRC-0-04-82-005. 82/08/03 2pp. 14339-284.
- 8208170324 Notification of contract execution: "Technical Assistance to Bupport NRC IE Personnel in Investigations of Incidents," awarded to Parameter, Inc.

 BROMBERO, B. Research Contracts Branch FIN B-1302 NRC-05-82-249, 82/07/22 BLAMA, J., LAUDAN, M. Director's Office, Office of Inspection and Enforcement, ip. 14372 008
- -8208170326 Contract "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents," awarded to Parameter. Inc. LOFTY, R. A. Parameter, Inc. MORTON, K. V. Research Contracta Brench, FIN 8-1302, NRC-05-82-249, 82/07/22, 5pp 14372,009.
- 'OS170413 Notification of contract execution, Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs)."

 Contractor Oresias CD Public Library.

 ITTLE, M. Administrative Contracts Branch. NRC-10-81-706
 12/08/03. FELTON, J. M., BOUDER, J. Division of Rules and Records, p. 14372, 347.

- --8208170420 Mod 1, extending period of performance to 830921 & increasing funding, to "Maint & Operation of Local Public Document Rooms (LPDRs)"
 FROMME Greely.CO REBELLO, J E Administrative Contracts Branch NRC-10-81-706
- 8208180144 Notification of contract execution, Mod 7 to "Definition of Design Performance Criteria for Geologic Radwaste Repository" Contractor Analytic Sciences Corp MCLEAREN, T Technical Assistance Contracts Branch FIN B-6130 NRC-02-77-129 82/07/26 DAVIS, J 0 , KEARNEY, M Office of Nuclear Material Bafety & Safeguards, Director ip 14389 293
- --BEOBIBOIS: Mod 7, establishing final overhead rates, to "Definition of Design Performance Criteria for Geologic Radwaste Repository."

 ** The Analytic Sciences Corp HAGAN, T F Technical Assistance Contracts Branch FIN B-6130 NRC-02-77-129 B2/07/26. 1p 14389 274
- 820B1B0287 Notification of contract execution, Mod 1 to "Training Course 'Safety Aspects of Industrial Radiography for State Regulatory Personnal' " Contractor Gamma Industries Day, Nuclear Sys, Inc.
 MCNULTY, A Purchasing Section FIN B-161B NRC-06-82-293
 B2/09/15 KERR, G W, ABHLEY, E C Office of State Programs, Director ip 143B9 291
- --8208180261 Mod 1.edding one training course & increasing funding to "Training Course" (Safety Aspects of Industrial Radiography for State Regulatory Personnel" RICHARDSON, H D. Nuclear System REBELLO, J E. Purchasing Section FIN 8-1618 NRC-06-82-293 82/08/15 1p 14389 292
- 820B180264 Notification of contract execution, Mod 1 to "Fuel Cycle Analysis Bpain" Contractor Nuclear Assurance Corp MCNULTY. A Purchasing Section FIN B-7374-2 NRC-02-82-048 B2/07/14 BROWN.R S , THOMAS.B H Program Support Branch Ip 14387 313
- --8208180269 Mod 1.deleting provision in Article I, Paragraph C re reporting requirements to "Fuel Cycle Analysis - Spain " THORUP.C B. Nuclear Assurance Corp REBELLO.J E Purchasing Bactton FIN 8-7374-2 NRC-02-62-048 82/07/14 ip 14089.314
- 820B190021 Notification of contract execution.Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 Contractor Rochester NY Public Library
 LITTLE: M Administrative Contracts Branch. NRC~10-81-423
 82/07/29. FELTON,J.M. SOUDER,J. Division of Rules and Records
- --8208170028 Mod 1.extending period of performance for 1 yr & increasing funding to "Maint & Operation of Local Public Document Rooms (LPDRs)"

 BRETZ, L M Rochester, NY. REBELLO, J E Administrative Contracts
 Branch, NRC-10-81-423 82/07/29 ip 14506 350
- 8208170075 Notification of contract execution "CA Offshore Radiological Licensee Burvey," awarded to CA State Dept of Health Svc. HOYLE.A Administrative Contracts Branch. FIN 8-8705 NRC-05-82-254. 82/08/05. BLAHA.J L , YACZKO, Program Support Branch. 1p 14307-029
- --8208190099 Contract "CA Offshore Radiological Licensee Survey," awarded to CA State Dept of Health Svc TODD, J. California, State of REBELLU, J.E. Division of Contracts. FIN 8-8705, NRC-05-82-254, 82/08/05. 5pp 14507
- 8208230021 Notification of contract execution. "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Vespasian Warner Public Library LITLE: M Administrative Contracts Branch NRC-10-82-683. 82708706. FELTON, J M , SOUDER, J Division of Rules and Records ip 14507.320.
- --8208230024 Contract "Haint & Operation of Local Public Document Rooms (LFDRs)," awarded to Vespasian Warner Public Library EVANS.H Clinton, IL REBELLO, J E Administrative Contracts Branch. NRC-10-82-483 82/08/06 7pp. 14507; 321.
- 8208230446 Notification of contract execution "Development of Matl Accounting Data Storage Analysis Sys," awarded to NUSAC, Inc. MILEG E.B. Technical Assistance Contracts Brench FIN 8-7347-2 NRC-02-082-093. B2/08/03. DAVIS, J. R., MEBBENGER, M. Office of Nuclear Material Safety & Safeguards, Director. 19 14529:038.

- --8208230451 Contract "Development of Matl Accounting Data Storage Analysis Bys," awarded to NUSAC, Inc PEVENSTEIN J E NUSAC, Inc MATTIA, M J Administrative Contracts Branch Fin B-7347-2 NRC-03-82-033 82/08/03 36pp 14527:039
- B208230460 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to BF Jones Memorisal Library
 LITTLE,M Administrative Contracts Branch NRC-10-82-689
 82/08/12 FELTON,J M , SOUDER, J Division of Rules and Records ip. 14529 025
- --8208230462 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to BF Jones Memorial Library COLOMBO, ME & Aliquippa,PA REBELLO, J E Administrative Contracts Branch NRC-10-82-669 82/08/12 9pp 14529 026
- 8208240049 Notification of contract execution, Mod 4 to "Executive Devalopment Program " Contractor USDA Graduate School PERLHAN, J Administrative Contracts Branch NRC-10-80-399 82/08/10 DORIE, W , ALLAN, R A Office of Administration ip 14529-358
- --B208240054 Mod 4.extending performance to B31230, providing incremental funding & authorizing advance payment, to "Executive Development Program"

 VARNER, L. 9 Graduate School, Agriculture, Dept of, BMITH, P. A Administrative Contracts Branch NRC-10-80-399 82/08/10 1p 1452:360
- 8208250018 Notification of contract execution, Mod 5 to "Assistance to NMSS in Determining Data Base Requirements & Defining Approach to be Taken for Satisfying Requirement in Support of Advarsary Assessment." Contractor BDM Corp. MCLEAREN, T. Technical Assistance Contracts Branch FIN B-1494-7 MSG-02-77-042 82/07/20 DAVIS, J O. VARDMUMIAN, J Office of Nuclear Material Safety & Safeguards, Director. ip 14951:353.
- --8208250022 Mod 5, incorporating indirect rates & deobligating balance to *Assistance to NMSB in Determining Data Base Requirements & Defining Approach to be Taken for Batisfying Requirement in Support of Adversary Assessment."

 **HALBH, B. O BDM Corp MATTIA: H J Technical Assistance Contracts Branch FIN B~1494-7 NRC-02-77-042, B2/07/20 ip, 14361, 354
- 820825063 Notification of contract execution, Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 Contractor: 9A Dow Memorial Library, Midland, MI
 LITTLE, M. Administrative Contracts Branch NRC-10-81-491
 82/08/03 FELTON, J. M., SOUDER, J. Division of Rules and Records in 14551, 360
- --B208250070 Mod i.extending period of performance to 830716 & increasing funding, to "Maint & Operation of Local Public Document Rooms (LDDRs)."
 PACKARD, A Midland City, MI REBELLO, J E Administrative Contracts Branch. NRC-10-81-691 82/08/03 ip 14551 361
- 820825096 Natification of contract execution.Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 Contractor.Perry.OH Public Library
 LITTLE.M. Administrative Contracts Branch NRC-10-81-703
 82/08/03, FELTON.J M , SOUDER, J. Division of Rules and Records
 ip 14559.240
- ---8208280101 Mod 1, extending period of performance to 830913 & increasing funding, to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 LOCKE, D L. Perry, OH REBELLO, J. E Administrative Contracts Branch. NRC-10-81-703 82/08/03 ip 14559 241.
- 820826007: Notification of contract execution, Mod & to "Programming in Support of Payroll Sys Development" Contractor SBA Subcontractor Technessociates, Inc MATTIA, M. J. Administrative Contracts Branch. NRC-10-79-373. 82/08/06. DDRIE, W.M., FROST, A.R. Office of Administration ip. 14574:293
- --8208240077 Mod 6, deobligating balance remaining Under contract, to "Programming in Support of Payroll Sys Davelopment" OFFORD, J. C. Technassociates, Inc. DENNISTON, S. F. Small Business Administration SMITH, P. A. Division of Contracts. NRC-10-79-373, 82/08/06. 2pp. 14574: 294
- 8208260184 Notification of contract execution, Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 Contractor: Sacramento, CA Public Library
 LITTLE, M Administrative Contracts Branch. NRC-10-81-675.
 82/08/03 FELTON, J M , BOUDER, J. Division of Rules and Records 1p 14587: 275.

- --B208260250 Mod 1, extending period of performance to 830916 & increasing funding to "Maint & Operation of Local Public Document Rooms (LPRs)"
 IBHIDA, H F Secremento, CA REBELLO, J E Administrative Contracts Branch NRC-10-81-695 82/08/03 ip 14589 276
- 8208240341 Notification of contract execution, Mod 15 to "BWR Full Integral Bimulation Tost (FIBT) Program " Contractor 0E/EPRI 0UBTAVE, R Research Contracts Branch FIN 8-3014 NRC-04-76-218 82/08/09 BATBON, W. BECKNER, W Office of Nuclear Regulatory Research Director 19 14575 272
- --8208260335 Mod 15, supplemental agreement adding EPRI funds & incremental funds, to "BWR Full Integral Bimulation Test (FIST) Program "

 KLEFFER.H H General Electric Co RYTKONEN.B.B Electric Power Research Institute HORTON.K V Research Contracts Branch FIN B-3014 NRC-04-76-215 82/08/09. 2pp 14575 273
- 8208260416 Notification of contract execution, Mod 14 to "BWR Full Integral Simulation Test (FIST) Program " Contractor GE/EPRI GUSTAVE, R Research Contracts Branch FIN 8-3014 NRC-04-76-215. 82/08/09 BATSDN.W. BECKNER, W Office of Nuclear Regulatory Research, Director. 1p 14569 274
- --BROBRAGARB Mod 14, modifying property clause, to "DWR Full Integral Simulation Tast (FIST) Program "

 KLEPFER. H General Electric Co RYTKONEN, B B Electric Power Research Institute, MORTON, K. V Research Contracts Branch FIN 8-3014 NRC-04-74-215. 82/08/09 2gp 14549:275
- 8208260436 Notification of contract execution, Mod 1 to "Purchase of Hetal Alloy Analyser " Contractor TX Nuclear 8MITH, P. A Division of Contracts FIN 8-1262 NRC-05-8i-242 82/08/16 DEYGUNG, R C. NATON, 9 A Director's Office, Office of Inspection and Enforcement. 1p 14895 050.
- --8208260445 Mod 1, deobligating balance of funds to closeout contract to "Purchase of Metal Alloy Analyser"

 HART.A P. Texas Nuclear Div (subs. of Ramsay Eng Co.)

 SMITH.P A Division of Contracts PIN 8-1262 NRC-05-81-242.

 82/08/16 ip. 14595:051
- 8208250442 Notification of contract execution. Mod 3 to "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste Repository Performance "Contractor: JFT Agapito & Associ. Inc OUSTAVE. R P Research Contracts Branch FIN 8~1097 NRC~01-80-019 82/08/10 FOREMAND. H, SCHMITT.T Office of Nuclear Regulatory Research, Director 1p 14569 272.
- --8208260459 Mod 3 increasing total funding for contract, to "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste Repository Performance."

 HARDY, H. P. J. F. T. Agaptob & Associates. Inc. MDRTON, K. V. Research Contracts Branch. FIN 8-1099

 19 143569, 273
- 8208240461 Notification of grant execution.Mod 3 to "Bupport of Nuclear Reliability Evaluation Program" Grantse ANE MCDERMOTT.D Research Contracts Branch. FIN 9-1004 NRC-0-004-81-001 82/08/12, BATSON.W., JOHNSON.C. Office of Nuclear Regulatory Research, Director. 1p 14575-054
- --82082&0465 Mod 3, extending period of performance to 821231; to "Support of Nuclear Reliability Evaluation Program"

 DV TEMPLE: O. American Nuclear Society, MORTON, K. V. Research Contracts Branch FIN 9-1004 NRC-9-04-91-001, 82/08/12 1p. 14595:055
- 8208280462 Notification of contract execution. Hod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs), "
 Contractor Madison-Jefferson County, IN Public Library, LITTLE, M. Administrative Contracts Branch NRC-10-81~704, 82/08/03, FELTON, J. M., SDUDER, J. Division of Rules and Records, 1p. 14595:056
- --B208260467 Mod 1, extending pariod of performance to B30913 & increasing funding, to "Maint & Operation of Local Public Document Rooms (LPDRs),"
 BABBITT, D.L. Madison, IN REBELLO, J. E. Administrative Contracts Branch NRC-10-B1-704. B2/08/03 ip. 14595.057,
- 8208260469 Notification of contract execution. Mod 13 to "Maint of Data General Corp C/330 Computers & Associated Peripherals "Contractor. Data Consultants, Inc.
 BMITH.P.A. Division of Contracts FIN 8-1662. NRC-10-77-196
 82/09/16. DORIE.W., JOHNSON.C. Office of Administration. 1p.
 14595:058.

11

-

- --8208260480 Mod 13.deobligating balance remaining under contract, to
 "Maint of Data General Corp C/330 Computer & Associated
 Peripherals "
 BONNES O Data Consultants, Inc SMITH, P A Division of
 Contracts FIN 8-1662 NRC-10-77-176 82/08/16 1p 14595 059
- 8208260492 Notification of contract execution. Nod 3 to "Independent Assessment Destructive Testing & Analysis " Contractor Franklin Inst
 - WOLLETT'S Research Contracts Branch FIN 8-1278 NRC-05-81-247. 82/07/28 BLAHA, J. LAUDAN, H. Program Support Branch 1p 14595 032
- --B208260501 Mod 3.adding labor classifications & rates for contract, to "Independent Assessment Destructive Testing & Analysis "DAVIDLE T Franklin Institute/Franklin Research Center OUSTAVE, Research Contracts Branch FIN 8-1278 NRC-05-81-24 B2/07/26 ip 14595 033 NRC-05-91-247
- 8208260585 Hemorandum of Agreement between NRC & Natl Inst of Kental Health expanding Grant MH35425 to encompass "Reanalysis of Existing Data from Tolephone Burveys Concerning TMT " MATTIA:M Division of Contracts FIN B-8621 RA-NH-82-18 82/07/14 3pp. 14568 046
- 8208300022 Notification of contract execution, Mod 3 to "Working Conference on Legal & Political Effects of Intensified Nuclear Safeguards on Civil Liberties " Contractor Stanford MCLEAREN, T Technical Assistance Contracts Branch FIN 8-9015 NRC-02-76-190 82/07/05 GREBHAM, J Program Support Branch 14683:359.
- --8208300024 Ltr contract Mod 3, deobligating unliquidated balance under contract, to "Working Conference on Legal & Political Effects of Intensified Nuclear Safeguards on Civil Liberties," HAOAN.T F. Technical Assistance Contracts Branch. FIN 8-9015 NRC-02-76-190 82/06/22 RANDALL, W L Stanford Univ 1p
- 8208300197 Notification of contract execution.Mod 2 to "Fuel Cycle Analysis Spain." Contractor Nuclear Assurance Corp MCNULTY, A Administrative Contracts Branch FIN 8-7374-2 NRC-02-82-048 82/08/13 BROWN, R.S., THOMAS, B H Program Support Branch Ip 14683 284
- --8208300204 Mod 2,adding or deleting sentences & paragraphs to ensure proprietary use of info to "Fuel Cycle Analysis Spain " SKITHIR L Nuclear Assurance Corp REBELLO, J E Administrative Contracts Branch FIN A-7374-2 NRC-02-82-048 82/08/13 2pp 14683-295
- 8208310006 Notification of contract execution, Mod 2 to "Study & Review of Issues Concerning Equal Employment Opportunity at NRC "Contractor SBA, Bubscontractor Hero Study Corp PAGE, M. Administrative Contracts Branch FIN 8-1659 NRC-23-82-516 82/08/03. REHM, T. A., WEBTON, M. Office of the Executive Director for Operations ip 14657 132
- --B20B310010 Mod 2.extending period of performance to "Study & Review of Issues Concerning Equal Employment Opportunity at NRC "
 BEVERLYA L Metro Study Corp DENNISTON.B F Bmall Business Administration SHITH.P A Division of Contracts FIN B-1699 NRC-23-82-516. 82/08/03. 2pp 14497.133
- 8208310450 Notification of contract execution. Nod 1 to "ABC Shorthand (Deginning) " Contractor Montgomery County, MD Public Schools COLDMAN, P. J. VAN BANTEN, L. Hanagement Development & Training Staff. 14697.320
- --8208310456 Mod 1, groviding add1 funds for Fall 1982 training course, to "ABC Shorthand (Baginning)"

 * Montsomery County, ND REBELLO, J E Administrative Contracts Branch. NRC-10-82-374 B2/08/12. Ip. 14697 321.
- 8208310462 Notification of contract execution. Mod 1 to "Mat1 Delance Capability of Process Similar to NFS. Erwin. TN " Contractor" NUBAC. Inc OILDENHORN. A J Administrative Contracts Branch. NRC-19-82-491. 82/08/04 REMICK.F J. ONG.C. Office of Policy Evaluations Ip 14697. 317.
- .UMB.R.F. NUBAG.Inc SMITH.PA Administrative Contracts Branch NRC-19-82-491, 82/08/04 ip 14697 318.

- 8208310495 Notification of contract execution Mod 1 to "Expert Opinics on Use of Probabilistic Risk Assessment (PRA) & Bafety Goals." Contractor NVS Corp LITTLE: M Administrative Contracts Branch FIN 8-8178, NRC-19-82-493. 82/09/19 REMICK.F J Office of Management and Program Analysis LEVINE, B NRC No Detailed Affiliation Olyan ip 14697 292
- --B20B31050D Mod 1, extending period of performance to B21231 at no afficest, to "Expert Opinion on Use of Probabilistic Risk Assessment (PRA) & Bafety Goals "
 4 NNB Corp REBELLD, JE Division of Contracts FIN E-8178 NRC-19-82-493 82/08/19 1p 14697 293
- 8208310512 Notification of contract execution, Mod & to "Electrostatic Copying Bycs " Contractor Literature Research Co GILDENHORN A J Administrative Contracts Branch NRC-10-81-369 82/07/27 DDRIE, W Office of Administration BAGGETT, M Publication & Oraphics Branch 1p 14697 275
- -- 8208310515 Mod & increasing ceiling amount, to "Electrostatic Copying Svcs "
 * Literature Research Corp MATTIA, M J Adminis
 Branch. NRC-10-81-369 82/07/27 ip 14697 276 Administrative Contracts
- E20B310517 Notification of contract execution. Mod 5 to "Newspaper Clipping Byc " Contractor Press Intelligence, Inc. OILDENHORN, A J. Administrative Contracts Branch, NRC-10-81-357 82/08/17 DORIE, W , ZUNGOLI, 8 Office of Administration (p. 14697.271.
- 8208310524 Notification of contract execution. Mod 1 to "Gregg Shorther Theory Review " Contractor Montgomery County, MD Public Schools Schools. LITTLE, M Purchasing Section NRC-10-82-375 82/08/12 ODLDMAN.P J , VAN SANTEN, L Management Development & Training Staff 1p 14697-267
- --B208310526 Mod i, providing additions for Fall 1982 training course, to "Gregg Bhorthand Theory Review"

 * Hontgomery County, MD REBELLO, J E
 Branch NRG-10-82-375 82/08/12 Ip 14697-268
- 8208310529 Notification of contract execution, Mod 5 to "Evaluation of Bulk Properties of Radwaste Class & Ceramic Container Matle to Datermine Long-Term Stability " Contractor Catholic Univ of America

 SILVIB,R M Research Contracts Branch FIN B-6330 NRC-04-78-250

 82/08/12 BATBON,W, KIM.K Office of Nuclear Regulatory Research

 Director ip 14705.327
- --8208310531 Ltr Mod 5, deobligating funds for close put, to "Evaluation; Bulk Properties of Radwoste Glass & Ceremic Container Hatis to Determine Long-Term Stability "
 HORTON, K, V Research Contracts Branch HUNTT, T J Catholic Univ FIN B-6330 NRC-04-78-250 82/02/25 BECHTEL, R E, Catholic Univ. 1p 14705:328
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- B20615000B Add1 response to FDIA request for seven categories of documents of Hayward Tyler Pump Co Tenth document contains investigatory records for law enforcement purposes & is withheld (ref FDIA Exemption 7) Listed documents enc1 FELTON-J M Division of Rules and Records B2/05/14 LIEBOLD,N C Affiliation Unknown. 1p 1417B 035
- --8206150017 "Hayward Tyler Pump Co Insp & Investigation Status Sueaby;" NRC No Detailed Affiliation Given 82/02/18 6pp 14178 037.
- --B206150020 Forwards GA Program Investigation Rept 99900345/B2-01 on B20104-29 Bupporting documentation encl BEYFRIT.K V. Region 4. Office of Director B2/02/19, FORTUNAR Division of Fuel Facilities, Materials & Bafeguards. 1p
- --8206150D21 Forwards GA Program Investigation Rapt 99900345/82-01 on 820104-29 Noncompliance noted SEYFRIT.K V Region 4. Office of Director 82/02/19 Hagward Tyler Pump Co 2pp. 14178,044.

- --8206130024 GA Program Investigation Rept 99900345/62-01 on B20104-29
 No toncompliance noted Major areas inspected allegations re
 Hayward Tyler Pump upper mgt failure to support & enforce GA
 program Personnel removed documents from main ofc
 HERR, R K , DRISKILL, D D , ELLERSHAW, L E Division of Vendor &
 Technical Programs 82/02/18 lipp 14178 046
- --B206150027 Forwards GA Program Investigation Rept 97900345/82-02 on B20125-29 & notice of nonconformance COLLINB.J T Region 4. Office of Director 82/02/19 LYONS.B P, Hayward Tyler Pump Co 3pp 14178 077
- --9206150035 GA Program Investigation Rept 99900345/82-02 on 820125-29 Moncompliance noted current & past training schedules not consistent w/training requirements identified in Exhibit I of Engineering 8td 9 0 3/1-1 ELLERSHAW, E., BARNES, I Division of Vendor & Technical Programs, 82/02/16 13pp 14178 088
- --8208020015 Sanitized notification that investigation & insp repts were provided to licensee representatives on 820212 for proprietary review Final rept will be provided upon receipt. BIRCKS, W J Office of the Executive Director for Operations, 82/03/05 PALLADING, N Commissioners ip 14178 148
- B206200004 FOIA request for documents discussing FYB1 NRC Research Order 60-81-195 for Sandia Natl Lab & documents discussing incidents designated 8811,8812,8813 & 8814 SHOLLY,8 C Union of Concerned Scientists B2/06/18 FELTON, J. M Division of Rules and Records Ip 14362,097.
- B206270073 FOIA request for one add1 category of info detailing collective dose exposures in 1981 for operating nuclear power plants & any memo, studies or other documents analyzing said info UDELL, A. Critical Mass Energy Project. 82/06/23 HARRIS, F. Division of Rules and Records ip. 14679 207
- 8206270076 FDIA request for info re implementation of employee protection provision in Section 210 of Energy Reorganization Act of 1974 MARCOUX,W C. LeBosuf, Lamb, Leiby & MacRae 82/06/25 Office of the General Counsel 1p 14568 049
- 8207020007 Addl response to FOIA request for eight categories of documents Forwards documents listed in App A Documents listed in App B completely withheld advice opinions & recommendations (ref FOIA Exemption 5).
 FELTON, J M Division of Rules and Records 82/05/28 MCMURRAY, C, M Kirtpatrick, Lockhart, Hill. Christopher & Phillips. Bpp 13497; 125. 24x Fiche. 50-000, 82/05/28, 8207020007.
- B207050072 FOIA request for quarterly repts of distribution to general licensess provided to NRC by Measurex Corp of Cupertino.CA PRENDEROABT.H LFE Corp B2/07/01 Office of Administration. 1p. 14506:278
- 8207050074 FOIA request for cost & delivery time involved in obtaining copy of IE insp manual.

 8TIBBE.R T Magnetvol International, Inc 82/06/30 Division of Rules and Records. ip. 14528:180
- \$207050084 FOIA request for documents in which NRC has focused on risks associated w/fuel loading & low power operation & has chosen level of mergency preparedness appropriate to assure public safety

 BELAIR R.R. Kirkpatrick, Lockhart, Hill, Christopher & Phillips

 82/07/14. FELTON, J. M. Division of Rules and Records. App. 14568.062
- 8207110006 FOIA request for records re Group VI product mfg by Alpha-Omega Sycs. Inc of Paramount.CA COPPELL.D A. Amersham Corp. 82/07/16 FELTON.J.M Division of Rules and Records. 1p 14562 095
- B207110013 FOIA request for all documents to WR Grace & Co during \$40101-B20720 VAN DYKEN.O. Affiliation Unknown. 82/07/19 Office of Administration 2pp 14506,275
- 9207110014 F01A request for info re W & E Reich & biological experiments.Oranur.Organon & DOR (Deadly Organe Radiation)
 UNREAU.R.C Affiliation Unknown 82/07/22 Division of Rules and Records. 2pp 14568.360.

- 8207110016 FDIA request for documents to Mark III containment issues provided to NRC by JM Humphrey on or about 820628 FIRESTONE,E A. General Electric Co 82/07/22 FELTON.J M Division of Rules and Records ip 14506 272
- 8207110018 FOLA request for list of all known BWR design generic issues still pending resolution & issues considered resolved during past yr & list of interim actions to be initiated until design deficiencies resolved Forwards previous request ltr HAFNER.B Affiliation Unknown. 82/07/20 Division of Rules and Records 2pp 14568 076
- --8208260372 Requests list of all known BMR design generic issues still pending resolution, issues considered resolved during past yr & list of interim actions to be initiated until design deficiencies resolved MAFNER, B Affiliation Unknown 81/11/04 Division of Technical Information & Document Control 1p 14569.078
- 8207110022 Add1 FGIA request for documents re exposure of employers to hazafluoride at K-25 in Oak Ridge. TN STULBERG, D B Hostoller & Stulberg 82/07/20 HENDRIE. J M Committationers 2pp 14528.174
- 8207110024 FDIA request for rept on accident at Idaho Falls nuclear reactor on 610105 LINEHAN.L.J. Affiliation Unknown 82/07/21. NRC - No Detailed Affiliation Olven 1p 14562:092
- 8207110032 FOIA request that all NRC contracts awarded to Science Applications, inc since 790101 be placed in PDR. MEISS, E.R. Harmon & Meiss 82/07/26. FELTON, J.M. Division of Rules and Records. 1p 14568 358.
- 8207110037 FOIA request for records re Wesleyan Univ, its staff, students, political activities, student k/or faculty organizations & relevant background math to aid in preparation of news article TAUSER, A Affiliation Unknown. 82/07/R8 PALLADING, N Cosmissioners ip, 18508; 072
- B2071B0027 FDIA request for repts generated by NRC as result of investigation of allegations made in CJ Mickeal 820316 ltr to J Kinneman.

 EMICH, J F Academy of Pharmacy Practice 82/08/05. Division of Rules and Records ip 14572: 236
- 8208260001 Responds to FOIA request for draft or preliminary versions of NOREG-0904.DES concerning decommissioning of facility.

 Belected records in PDR. Preliminary drafts withheld (ref FOIA Exemption 5).

 FELYON, J H Division of Rules and Records, 82/08/16 RAPKIN, A Illinois, State of, 2pp. 14567 355
- 8208040100 Add1 response to FOIA request for 10 categories of documents JA Martin 810225 memo completely withheld tref FOIA Exemption 53. Specific requested categories addressed Documents listed in App 3 available in PDR. FELTON, J. M. Division of Rules and Records 82/06/22, BHOLLY, S Union of Concerned Scientists, App. 14228:301.
- 8208190032 Responds to FOIA request for quarterly repts of distribution to general licensees provided to NRC by Heasurex Corp of Cupertino. CA Documents revisued for propietary claim. FELTON. J M Division of Rules and Records 82/07/26 PRENDERGABT. W. LFE Corp. 1p. 14506 279
- 820B19003B Responds to FDIA request for all documents re UR Grace & Go during 540101-880720 Documents awailable in FDR FELTON, J. M. Division of Rules and Records 82/07/26. VAN DYKEN, Q. Affiliation Unknown. 1p 14506:277
- 8208190072 Responds to FOIA request for documents re Mark III containment issues by JM Humphrey on or about 820628. Forwards list of documents FELTON.J M Division of Rules and Records. 82/07/26. FIREBTONE, E. A. General Electric Co. 2pp 14506-273
- 8208230396 Responds to FDIA request for documents re exposure of amployees to hexafluoride at K-25 in Oak Ridge.TN. No documents available on requests 6 subj. FELTON.J. H. Division of Rules and Records 82/08/16. STULBERO, D.B. Mostoller & Stulberg. ip. 14528 173
- 8208230403 Responds to FOIA request for cost & delivery time involved in obtaining copy of IE insp manual Manual available in PDR. FELTON.J.M. Division of Rules and Records 82/07/14. STIBBE.R T Magnetvol International. Inc. ip. 14328-179.

- 8208230414 FOIA request for three categories of documents re emergency planning for nuclear actidents & NOAA role in Interagency Radiological Assistance Plan or other participation during accident at nuclear facility Add1 requests encl.

 HIATT, S. L. Affiliation Unknown 82/02/23 Commerce, Dept of, National Oceanographic & Atmospheric Administration 4pp 14529-181
- 8206010033 Recommends that draft plan "Hydro-Meteorological Support for Radiological Emergencies at Commercial Nuclear Power Plants" be published under direction of Federal Coordinator MARKEE.E ff Task Group on Meteorological Plans for Radiological Emergency Response. 82/04/19 DORRE.O B Commerce.Dept of 2pp 14528 220
- ~-8204210308 Comments on draft plan re meteorological support plan at commercial power plants in response to 820307 request Document does not put into perspective overall rolles of various governmental agencies in event of emergency MATTEON.R J Division of Systems Integration (post 811003) 82/03/26 MARKEG.E H Division of Systems Integration (post 811005) 2pp. 66018 151
- --B208230427 Responds to B20309 memo re draft meteorological support plan at commercial nuclear power plants Mateorological & hydrological info needed in event of accident could probably be provided by Nati Weather Buc CUNNINOHAM, R E Division of Fuel Cycle & Material Bafety B2/03/25 MARKEE, E H Accident Evaluation Branch 2pp [4328 224
- --8208230430 Comments on draft meteorological support plan at commercial nuclear power plants in response to 820309 memo Recommenda Memorandum of Understanding or Interagency Agreement to establish level of support svcs warranted GRIMES, B K. Division of Emergency Preparedness 82/04/01 MARKER, E H NRC No Detailed Affiliation Given ip 14528-228
- 8208230473 Nonproprietary version of IE Insp Repts 50-277/81-07 & 50-278/81-09 on 810301-0407 Noncompliance noted: failure to have adequate radwasts collection procedures & to follow administrative procedures for mods CONGILL.C J. MCCABE.E C Reactor Projects Section 28 50-278/81-09 81/06/01. Sipp 14528-142.
- B20B250006 Forwards biweekly rept for LER screening project for period anding B10619. Four of 80 events identified as potentially significant List of LERs screened & identified as nonsignificant encl.
 CASTO.WR Dak Ridge National Laboratory B106/24 COLMAR.B Bafety Program Evaluation Branch 3pp 14559 275
- --820B250009 Forwards biweekly rept for LER screening project for period ending 810702. Fifteen LERs out of 131 identified as potentially significant List of LERs screened & identified as nonsignificant encl
 CABTO.M.R. Oak Ridge National Laboratory 81/07/14 COLMAR, B, Safety Program Evaluation Branch 3pp 14559-279
 - 1208250011 Forwards biweekly rept for LER screening project for period ending B:0717 Six LERs out of 49 identified as potentially significant.List of LERs screened & identified as nonsignificant encl
 CABTO.M.R. Oak Ridge National Laboratory 81/07/23 COLMAR.B.
 Bafety Program Evaluation Branch 4pp 14559 304
- -8208250013 Forwards biweekly rept for LER screening project for period anding 810731, Seven LERs out of 91 identified as potentially significant List of LERs screened & identified as nonsignificant encl CASTO, H.R. Cak Ridge National Laboratury 81/08/05 COLMAR, B Safety Program Evaluation Branch 5pp 14559, 308
- 8208250017 Forwards biweekly rept for LER screening project for period ending 810814 Eighteen LERs out of 100 identified as potentially significant List of LERs screened & identified as nonsignificant encl
 CABTOLWR Oak Ridge National Laboratory 81/08/18 COLMAR, 8, Safety Program Evaluation Branch 5pp 14559; 313
- --820825002i Forwards biwsekly rept for LER acreening project for period ending 810828. Fourteen LERs out of 122 identified as potentially significant List of LERs screened & identified as nonsignificant enci
 CASTO W.R. Oak Ridge National Laboratory 81/09/01. COLMAR.B. Sefety Frogram Evaluation Branch Spp. 14589 318.
 - 8208250027 Submits biweekly rept for LER streening project for period ending 810911 No LERs screened due to other programmatic commitments.

 CABTO, H R Oak Ridge National Leboratory 81/07/21. COLMAR, F Bafety Program Evaluation Branch 1p. 14559,323

- ~-B208250032 Forwards biweekly rept for LER screening project for period ending 810925 Six LERs out of A3 identified as potentially significant List of LERs screened & identified as nonsignificant encl
 CASTO.W R Oak Ridge National Leboratory B1/09/30, COLMAR, B
 Safety Progrem Evaluation Pranch 4pp 14559 324
- --B208250035 Forwards biweekly rept for LER screening project for period ending 811007 Thirteen LERs out of 98 identified as potentially significant list of LERs screened & identified as nonsignificant encl
 CASTD.W R Oak Ridge National Laboratory 81/10/13 CDLMAR.B Gafety Program Evaluation Granch 5pp 14557 328
- ~-820825003B Forwards biweekly rept for LER screening project for period ending 811023 Fifteen LERs out of 90 identified as potentially significant List of LERs screened & identified as nonsignificant & LER goal analysis encl CASTO.W R Oak Ridge National Laboratory 81/10/30 COLMAR, B Safety Program Evaluation Branch 21pp 14509 333
- 8208250055 FDIA request for documents re NRC activities concerning Sheffield Brook & mati re radiation in Wayne,NJ AKBT-D Record, The Hackensack, NJ 82/04/27 ABRAHAM,K Region 1, Office of Director ip 14560 001
- ~~B20825005B Advises that B20427 FOIA request has been forwarded to JM Felton for response BNYDER:0 L Division of Emergency Preparedness & Operational Bupport B2/05/03 AKBT.D Record, The Hackensack, NJ 1p 14560:002
- 8208250081 Advises that monarite sand covered in Philipp Brothers Div of Engelhard Minerals & Chemical Corp import certificate was provided by Davison Chemical Corin response to 671205 request Related info encl RYANA F Atomic Energy Commission 68/02/26, ROEDER, J.R. Atomic Energy Commission 9pp 14560 332
- ~-820825085 Provides guidance re concentration of thorium considered permissible for discharge into stream, in response to 561015 request UDHNSON-L Atomic Energy Commission 56/10/31 RUNION,T C W R Grace & Co 2pp 14560 058
- ~-8208250087 License for Rare Earths, Inc. to export 2,000 lb thorium oxide to Canada
 JOHNSTON, L. E. Atomic Energy Commission 56/11/16 lp
 14560 059
- ~-8208250098 Issues Source Matl License R-196, authorizing receipt & possession of unlimited quantities of thorium-containing matl
 JOHNSON, L Atomic Energy Commission 57/01/24 BARRETT, D P W R Grace & Co ip 14560 063
- ~-8208250099 Forwards AEC regulation entitled "Stds for Protection Against Radiation" effective 570228 JOHNSON:L Atomic Energy Commission 57/02/27 Rare Earths: Inc. 1p 14550 064
- ~-8208250103 Issues Bource Matl License C-3623, authorizing possession of 50 lb refined U-magnesium flouride slag JUHNSON, L. Atomic Energy Commission, 82/06/17 STONE, R. Rare Earths, Inc. 1p 14560 065
- --B20B250121 Application to renew Bource Matl License R-196 to transferd deliver, export or receive 100 tons thorium ores & ore concentrates & 1,000 lb thorium # H R, Grace & Co 59703/24 ip 14560 070
- ~-8209250126 "Health Physics Rept for WR Grace Co. Wayne, N.J." MCCLORKY, M Applied Health Physics, Inc 74/06/18 101pp
- --0208250133 IE insp rapt of License R-176 on B71125 Major areas inspected organization & procedures facilities, instrumentation & radiological procedures & control Related info encl

 * NRC No Detailed Affiliation Given 59/11/25 14pp 14560:075
- ~~8208250164 Advises that enforcement action has not been completed for Davison Chemical Co. in response to 600630 rept * Atomic Energy Commission 60/07/22 DUBINGKI, HAGEMAN, HAYGOCK Atomic Energy Commission. ip 14560:103
- ~-B208250172 "Health Physics Manual " GARIND,P.J W. R. Grace & Co. 60/01/01 33pp 14560.105

- --8209250177 "Procedures for Measurement of Radicactivity "
 ** W R Orace & Co 60/01/01 30pp 14560 138
- --9209250194 Advises of completion of enforcement action for License R-196 WARNER, D E Atomic Energy Commission 61/05/27 KIRKMAN, D E Atomic Energy Commission ip 14960 175
- --8208250254 Forwards info re licensing requirements for persons possessing U or thorium source matl W/o encl KIRKMAN,R W. Atomic Energy Commission 61/07/26 BARRETT,D W R Orace & Co 2pp 14560 203
- --8208250319 Requests identification of owner of property between Black Oak Ridge Road & Pompton River KINNEMAN, J D Haterials Radiological Protection Section 82/02/25 Wayne, NJ 2pp 14561 263
- --B20B250323 Requests copy of Sheets 34 & 25b of tax map.covering area through which Sheffield Brook runs between Black Oak Ridge Road & Pompton River KINNEMAN, J D Region 1, Office of Director 82/03/05 EMOLD, B Hayne, NJ 1p 14561 265
- --B20BR30342 Forwards licensee reply re Form AEC-592 Response adequate W/o form Related info encl KIRKMAN,R W. Atomic Energy Commission 64/07/28 PAGE.R C , DUBINSKI,L Atomic Energy Commission 2pp 14560:241
- --B20B250334 Requests shipment of 100 lb sample of thorium bomb reduction residue to Curtis Bay. MO for processing HANDLE.R M H R Grace & Co 56/O6/27 HANDLE.R M Atomic Energy Commission ip 14561 321
- --B20B250357 Requests amend to License R-132 to permit Rare Earths to receive title to thorium in form of metal scrap, sludges & residues in addition to authorized monazitu ore HANDLE:A M & R Orace & Co. 56/08/02 JOHNSON, L Atomic Energy Commission ip 14561 322
- --E208250360 Requests guidance re specific concentration of thorium permissable for discharge into stream RUNION,T G W R Grace & Co 36/10/15 PRICE,E Atomic Energy Commission ip, 14561 323
- --8208250367 Advises that Pompton Plains,NJ site can be included in DOE utilized sites program,in response to request during 820331 meeting. MOTT.N E Energy, Dept of 82/04/21 PAGE.R O Uranium Recovery Licensing Branch 1p 14560 253
- --B20B250373 Forwards certificate for Philipp Brothers Div of Engelhard Minerals & Chemical Corp re importation of monarite sand Inquiry should be made to determine status & ultimate disposition W/o encl ROEDER, J. R. Atomic Energy Commission 67/12/05, KIRKMAN, R. W. Atomic Energy Commission 1p 14560 265
- --E20B250374 Requests guidance for obtaining sample of U-magnosium fluoride slag for recovery of contained U Related info encl STONE, R. L. Rere Earths, Inc. 56/11/29, JOHNSON, L. Atomic Energy Commission ip 14961 324
- --B20B280377 Forwards process description,waste treatment plant operating description, plot plan indicating location of residues & infore therefore content of sludges stored on property, in response to request.

 MANDLE, R. M. W. R. Grace & Co. 60/01/12 KLEVEN, P. B. Atomic Energy Commission 7pp 14561, 326
- --0200230380 "Process for Breaking Monasite Sands Into Rare Earth & Thorium Compounds "

 W R. Grace & Co 68/02/14 2pp. 14560 327
- ---B208250385 Requests info re radioactive matls used in Wayne, NJ facility during Jul-Aug 1945 MARCUS, B., LEVY, A. E. Monroe & Lemann. 67/03/10, KIRKMAN, R Atomic Energy Commission ip 14561 344
- --B208250388 Forwards US Import Certificates issued to Intl Belling Corp & HR Grace & Co RUTZEN, A C. Commerce. Dept of 67/09/26 Atomic Energy Commission. 4pp. 14561 345
- --8208250394 Requests info re nuclear waste burial sits in Wayne, NJ WAKB.D. Wayne, NJ 81/01/06. Atomic Energy Commission. Spp. 14362.007

- --8208250375 Forwards AEC contracts found in files to aid in study of Pomptons Plains.NJ
 HILLE,A W R Grace & Co 81/12/08 Region 1, Philadelphia, Office of the Director (81/03/01) 74pp 14562 012
- --8208250374 Confirms 820305 telcon re NRC plans for survey of properties west of Pompton Plains, NJ site HDBLEY, B L W & Grace & Co 82/03/05 CAMPBELL, M Region 1, Office of Director 2pp 14562 087
- --8208250397 Forwards view foils & color prints of WR Grace property, in response to request W/o encl.
 MEIBAULR A Energy Engineering Group PG8-92-052 82/04/07
 KINNEMAN.J Region 1. Office of Director 1p 14562 091
- 8208250410 Responds to FOIA request for rept on accident at Idaho Falls nuclear reactor on 610105 Documents listed in App A available in PDR FELTON.J M Division of Rules and Records 62/07/29 LINEHAN.L J Affiliation Unknown 2pp 14562 093
- B20B280340 Responds to FOIA request for records re Group VI product mfg by Alpha-Omega Bycs, Inc of Paramount, CA NRC has no documents subj to request FELTON, J M Division of Rules and Records 82/07/29 COPPELL, D A Amersham Corp ip 14562 096
- 8208250556 Responds to FOTA request for documents discussing FYBI NRC Research Order A0-81-195 & documents discussing incidents designated 88T1,88T2,68T3 & S8T4 Forwards RM Bernero 810414 ltr to DDE & encis, FELTON, J M Division of Rules and Records 82/07/28 SHOLLY,8 C Union of Concerned Scientists 19 14562-098
- 8208260003 Add1 response to FOIA request for seven categories of documents re Hayward Tyler Pump Co Forwards Document 4 Document partially withheld (ref FOIA Exemption 4).W/o NRC 820722 itr to Lodge FELTON.J K Division of Rules and Records 82/07/22 LIEBOLD.W C Affiliation Unknown 2pp 14587 261
- 8208240006 FOIA request for documents made available in response to C McMurray request designated FDIA 82-176 ELLIS:T 8. Harmon & Weiss 82/04/16 FELTON:J M Division of Rules and Records ip 14587.254
- 8208260007 Responds to FOIA request for documents made available in response to C McMurray request designated FOIA 82-176 Bocuments already provided FELTON,J, M Division of Rules and Records 82/07/27 ELLIB,T S Harmon & Weiss ip 14589 255
- 82082&0040 FOIA request for four categories of info re use of radicactive matts as radicactive weapons VON BTACKELBERG Affiliation Unknown 62/06/25 Diffice of Administration 4pp 14589 246
- 8208250041 Responds to FOIA request for documents in which NRC has focused on risks associated w/fuel loading & low power operation Documents lists in App A completely withheld (ref FOIA Exemption 3) FELTON.J M Division of Rules and Records, 82/08/05 BELAIR.R R Kirkpatrick, Lockhart, Hill, Christopher & Phillips 3pp 14588 ORR
- B208260046 Responds to FOIA request for four categories of info re use of radioactive maths as radioactive weepons NRC has no documents subj to request DDE or DDJ may be contacted for info FELTON. J M Division of Rules and Records B2/07/20 VON BTACKELBERG Affiliation Unknown 2pp 14589 250
- 6208260049 Addi response to FBIA request for 19 categories of documents. Documents listed in App A & B withheld commerical info held confidential by INPO (ref FDIA Exemption 4) FELTON.J M Division of Rules and Records 62/08/05, UDELL, R A Critical Hass Energy Project App 14389: 265.
- B20B260107 Responds to FDIA request for records re Wesleyan Univistaff, students, political activities, student &/or faculty organizations & relevent mati NRC has no documents subj to request.

 FELTON, J.M. Division of Rules and Records 62/08/11 TAUBER, A. Affiliation Unknown (p. 14568, 073.
- 8208260116 Responds to FDIA request for rept generated as result of investigation of allegations made by CJ Micheels Rept withheld disclosure will interfere w/enforcement proceeding (ref FDIA Exemption 7) FELYON.J.M Division of Rules and Records. 82/08/12 EMIGH.J.F Academy of Pharmacy Practice ip 14572:237

- 8208260304 Responds to FOIA request for info re W & E Reich & biological experiments, Oranur, Organe, Organon & D O R (Deadly Organe Radiation) No documents located subj to request FELTON-J M Division of Rules and Records 82/08/04 JUNEAU, R C Affiliation Unknown ip 14568 362
- B208260313 Responds to FOIA request that all NRC contracts awarded to Science Applications. Inc since 790101 be placed in PDR Contracts subj to request already available in PDR FELTON.J M Division of Rules and Records B2/08/04 WEISS,E R Harmon & Weiss 1p 14568 339
- B208260361 Appeals denial of FDIA request for documents re Hayward Pump Go LODGE.B Dallas Morning News. 82/05/31 Office of the Secretary of the Commission 1p 14574 169
- 8208260363 Responds to appeal re denial of FOIA request for documents concerning Hayward Pump Co Appeal denied Disclosure of info would interfere w/ongoing enforcement proceeding CORNELLE K Office of the Executive Director for Operations. 82/07/19 LODGE,B Dallas Morning News 2pp 14594 177
- 8208260378 Responds to FOIA request for list of all known BWR design generic issues still pending resolution issues considered resolved during past up & list of interim actions. Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/08/06. HAFNER. B Affiliation Unknown. 2pp 14568 079
- --82082603B1 "TMI Action Plan Tracking Sys," draft

 * NRC No Detailed Affiliation Given 82/01/30 143pp
 14368 090
- 8208260554 Forwards documents requested under FOIA Request 82-145 (Curran) THADANI,A. Division of Safety Technology 82/03/26 WILSON,V H Management Analysis Branch. 3pp 14569 048
- --B20B260561 Forwards D Curran FDIA Request 82-145 for TE Murley 811013 mean to HR Denton Requests action by 820326 HILSON-V H Hanagement Analysis Branch, 82/03/23 THADANI.A Reliability & Risk Assessment Branch 1p 14369 071
- --8208250553 Forwards revised draft ltr rept "Bys Interaction Branch Approach to Sys Interactions in LWRs." CYBUL6KIB.P Battelle Manorial Institute, Columbus Laboratories B1/05/07. COFFMAN.F D Systems Interaction Branch 20pp 14569:120
- 8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A FELTON, J. M. Division of Rules and Records 82/07/13 UDELL, R. A. Critical Mass Energy Project 8pp 14677 208 24X Ficher 50-000, 82/07/13, 8208270010
- -B207160365 Forwards preliminary compilation & analysis of occupational radiation doses reported from 70 LHRs for 1981, Plant mods & inservice inspaceties as contributing causes to increased radiation doses

 CONGEL.F.J Radiological Assessment Branch. B2/06/18
 HOUSTON.R W Assistant Director for Radiation Protection Epp. 14680 103.
- --B208270607 Forwards "Personnel Whole Body Exposures for CYB1," per 10CFR20 407(a) & (b) PARKER, W O Dute Power Co B2/03/09. BASBETT, H S Office of Management and Program Analysis Ip 14680; 045 24X Fiche 50-000, 82/07/13, B208270010
- --B20B270614 "Personnel Whole Body Exposures for CYB1."
 LEMIB.L. Duke Power Co 10CFR 020.407 82/03/09 ip
 14680-046. 24% Fiche.50-000.82/07/13,8208270010
- --8208270629 Forwards whole body range rapt for CY81, per 10cFR20 407. MODDY, D. E. Yankse Atomic Electric Co. FYR-82-32 82/03/12. HALLER, N. M. Office of Managament and Program Analysis. 1p. 14680.050. 24X Fiche 50-000, 82/07/13, 8208270010
- --8208270638 Whole body range rept for CY81. TRIJO, J Yankee Atomic Electric Co 10CFR 020, 407B, 82/03/08, 1p 14680:051 24X Fiche 50-000, 82/07/13, 8208270010
- 8208270619 Forwards rept on number of personnel & man rem by work & job function for 1981, per NUMEG-0737, Item II, K. 3 3. MAYER, L. G. Northern States Power Co. 82/02/26. KEPPLER, J. G. Region 3. Office of Director ip 14679; 342 24X Fiche: 50-000, 82/07/13, 8208270619

- 8208310003 Responds to appeal re denial of FOIA request for documents concerning IE Insp Rept 50-358/81-13 Appeal partially granted & partially denied Forwards CH Weil 810914 memo Info partially withheld (ref FOIA Exemption 7) DIRCKS,W J Office of the Executive Director for Operations 82/08/12 DEVINE,T @overnment Accountability Project ip 14697 220 24X Fiche 50-000,82/08/12,8208310003
- 8208310024 Responds to FUIA request for Branch Technical Positions APBCB 3-1 & MEB 3-1, ACR8 transcripts & tests in Japan re BWR ECC8 core spray distributions Forwards documents listed in App A App B document withheld (ref FUIA Exemption 4) FELTON. J M Division of Rules and Records 82/08/02 HIATT, S L Chio Citizens for Responsible Energy 4pp 14696 087
- ---B208310026 Revision 1 to Branch Technical Position ASB 3-1 (formerly APCSB 3-1), "Protection Against Postulated Piping Failures in Fluid Sys Dutside Containment "

 4 Auxiliary Bystems Branch 81/07/31 20pp 14676 091
- --8208310027 Revision 1 to Branch Technical Position MEB 3-1.
 "Postulated Rupture Locations in Fluid Bys Piping Inside &
 Gutside Containment"
 # Mechanical Engineering Branch 81/07/31 9pp 14696 111
- B208310033 Appeals denial of FOIA request for eight categories of documents we sgs interaction pilot program & interim guidance file, MCMURRAY.C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips. B2/06/07. DIRCKB:W J Office of the Executive Director for Operations. 2pp 14675:167
- 8208310035 Responds to appeal re denial of FOIA request for eight categories of documents. Appeal partially granted Documents from interin guidance files encl Remaining documents withheld (ref FDIA Exemption 5)
 DIRCKS M. J. Office of the Executive Director for Operations. 82/07/13. MCMURRAY, C. M. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 3pp 14695.178
- --B208310062 Comments on 811001 draft of Chapters B & 6 & App A of initial guidance for performance of sys interaction reviews Distinction not made between pilot & ultimate review Quidelines not clear HIDRIO, R D Battelle Memorial Institute, Pacific Northwest Laboratory, 81/11/13, COFFMAN, F D Reliability & Risk Assessment Branch, 3pp. 14675 204.
- --8208310065 Comments on 811001 draft of Chapters 5 & 6 of App A of initial guidance for performance of sys interaction reviews at selected LWRs. Explicit analytic evaluation procedure not used. Marked-up rept summary encl ALESBO. H. P. Lawrence Livermore Laboratory 81/11/16 COFFMAN. F. D. Reliability & Risk Assessment Branch 25pp 14695, 207
- ---8208310048 "Draft Initial Ouidance for Performance Sys Interaction Analyses at Selected LWRs." (guidance for interim use & comment)

 # Reliability & Risk Assessment Branch 82/01/07 44pp 14695, 232,
- --8206290168 Forwards "Initial Quidance on Digraph-Metrix Analysis for Sys Interaction Studies at Selected LHRs," draft rept. ALEBBO, H.P. Lawrence Livermore Laboratory FIN A-0403 NB82-085/03578, 82/06/21, COFFMAN, F.D. Reliability & Risk Assessment Branch 1p. 14475 296
- --8206270171 "Initial Ovidance on Digraph-Matrix Analysis for Bys Interaction Studies at Selected LMRs." draft rapt ALESBO, H. P. Laurence Livermore Laboratory FIN A-0403. 82/06/14, 107pp. 14695-277
- --B20B310075 "Development of Interim Guidance on Sys Interactions " COFFMAN.F. NRC -- No Detailed Affiliation Given ATERI. I. DARI.R. Brookhaven National Laboratory B2/07/13. Spp 14469 332.
- ---B208310078 Notifies that listed documents for project, "Development of Sys Interaction Regulatory Quidance," have been sent HIDRIO, R.D. Battelle Hemorial Institute, Pacific Northwest Laboratory, FIN 8-2337, Bi/1/1/10. COFFMAN.F.D. Division of Systems Integration (post Bi1005). 1p 14695.360
- ---B208310083 Forwards revised draft ltr rept "Bys Interaction Branch Approach to Bys Interaction in LWRs." Revision reflects comments made in continuing discussion w/NRC & observations gathered from meeting w/AIF.
 CYBULMKIS.P. Battslie Memorial Institute, Columbus Laboratories B1/05/07. COFFMAN.F. D Division of Bystems Integration (post 811005). 1p. 14496:047.

--8208310086 "Sys Interaction Branch Approach to Sys Interactions in LMRs," draft staff summary ltr rept * Systems Interaction Branch 81/05/31 18pp 14496 048

GEN TEC 18 GENERIC TECHNICAL ISSUES

- 8208030033 Summary of 820623 meeting w/C-E owners group in Bethesda, MD regressorized thermal shock issue Handouts encl.
 LITTON, F B Generic Issues Branch 82/07/08 Generic Issues
 Branch 27pp 14197 150
- 8208030701 Speech entitled "Containment Emergency Sump Performance" to be presented at 830111-14 Intl Topical Meeting on Nuclear Reactor Thermal Hydraulics SERKIZ, A W Division of Safety Technology WEIGAND, 9 Q Sandia Laboratories 82/07/14 4pp 14196 325
- --8208030704 Speech entitled "Resolution of Unresolved Safety Issue A-1, Water Hammer," to be presented at 830111-14 Intl Topical Meeting on Nuclear Reactor Thermal Hydraylics 8ERNIZ,A W Division of Bafety Technology 82/07/14, 2pp 14176-329
- 8208040530 Notification of 820728 meeting w/E0t0 in Bethesda.MD to review program plan to resolve tasks identified in A-47, "Safety Implications of Control Bys " 8ZUKIEMICZ.A J Generic Issues Branch 82/07/21 KNIEL,K Generic Issues Branch 2pp 14221 040
- 8208040583 Approves request for WCAP-9558.Revision 2 & WCAP-9787 to be withheld from public disclosure, as repts contain proprietary commercial info CRUTCHFIELD, D Operating Reactors Branch 5 82/07/09 WEISSEMANN, R A Westingbouse Electric Corp 2pp 14227:361
- 820B130301 Notifies that inaccurate statement appears in NRC 820623 meeting summary rs pressurited thermal shock Statement in fourth sentence of third paragraph does not reflect C-E owners group evaluations of overcooling events HORRIS,K J C-E Operating Plants Guners Group MORRIS,K J Omeha Public Power District 82/08/06 LITTON,F B Generic Issues Branch ip 14337 141
- 8208190366 Summary of 820730 meeting w/Westinghouse owners group in Bethesda,MD re pressurized thermal shock issue Agenda, attendance list & graphs encl VISSING,O S Operating Reactors Branch 4 82/08/09 Operating Reactors Branch 4 16pp 14504·133
- 8208200021 Requests review of pressurized thermal shock rept prior to formal submittal to Commission ROCHINO.A P Babcock & Wilco. Operating Plants Owners Group ROCHINO.A P. General Public Utilities GPU Bervice Corp. 82/08/17 DENTON,H R Office of Nuclear Reactor Regulation, Director. 1p 14372 237
- 8208230365 Forwards util 820811 ltr to all PWR owners & summary of 820729 meeting w/NRC.EPRI, INPO.AIF-et al in Bethesda.MD re NRC proposed steam generator generic requirements, per O Laines request Participant comments being prepared SCHMIDTAD Steam Generator Guners Oroup, SCHMIDTAD, Florida Power & Light Co 82/08/18. EISENHUT, D Division of Licensing 20pp 14513 064
- B20B260507 Agenda for B20B20 meeting w/BNML re pressurized thermal shock issue LITTON'S B. Generic Issues Branch. B2/0B/16 HANAUER, 8 H. Bivision of Bafety Technology 2pp 14574.360
- B208319443 Responds to B20727 ltr re AIF Reactor Vessel Integrity
 Bubcommittee views on development & implementation of
 regulatory requirements concerning pressurized thermal
 shock Phased approach similar to one under consideration
 BENTON.H R Office of Nuclear Reactor Regulation, Director
 B2708/09 01888.D.C Atomic Industrial Forum, ip 14697.322.
- --8208310451 Submits views of AIF Reactor Vessel Integrity Subcommittee on development & implementation of regulatory requirements re pressurized thermal shock, as followup to 820623 ltr Proposed two phase approach discussed QIBBS.D C Atomic Industrial Forum 82/07/27. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 4pp 14697-323
- B208310528 Notification of B20820 meeting w/BNWL & CRNL in Bethasda, MD to discuss proposed position & recommendations for resolution of pressurized thermal shock issue LITTON.F B. Generic Issues Branch B2/08/13. HANAUER, 8. N Division of Safety Technology 2pp 14697*264

I&E INSPECTION AND ENFORCEMENT

- B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV)
 Leakage " Svc list encl
 JORDAN E. L Division of Engineering & Quality Assurance B2/07/16,
 Consolidated Edison Co of New York B7pp 14386 274 24X
 Fiche 50-000, 82/07/16, 8204210393
- 8204210395 IE Info Nutice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Bvc list encl JORDAN, E. L. Division of Engineering & Quality Assurance, 82/07/19 Michigan, Univ. of 112pp 14358 001, 24X Fiche 50-000,82/07/19, 8204210395,
- 8204210394 IE Info Notice 82~25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl. JORDAN,E L. Division of Engineering & Guslity Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X Fiche 50-000,82/07/20,8204210396
- 8204210397 IE Info Notice 82-24, "Water Leaking From U Hexaftuoride Overpacks " Svc hist encl COSB-L I Division of Fuel Facilities, Materials & Safeguards B2/07/20. Consolidated Edison Co of New York, 7ipp 14357 276 24X Fiche 50-000,82/07/20,8204210397.
- 8204210378 IE Info Notice 82~26, "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl, JORDAN, E L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp, 14174:321 24X Fichs. 50-000, 82/07/22, 8204210398
- 8204210401 IE Info Notice 82~28, "Mydrogen Explosion While Orinding in Vicinity of Drained & Open RCB " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance B2/07/23 Consolidated Edison Co of New York. 122pp. 14380,115, 24X Fiche 50-000,82/07/23,8204210401
- 8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs." Byo list engl. JORDAN.E. L. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co. of New York 127pp 14174-120. 24X Fichs 50-000.82/07/23.8204210402
- 8204210403 IE Info Notice B2-30. "Lose of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl, JORDAN, E L Division of Engineering & Quality Assurance, 82/07/26, Consolidated Edison Co of New York 12ipp. 14357 013 24X Fiche 50-000.82/07/26.8204210403
- 8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in fuel Storage Pool " Bvc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp, 14357,146 24X Fiche 50-000,82/07/28,8204210405.
- B204210407 IE Info Notice BR-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl.

 JORDAN, E L. Division of Engineering & Quality Assurance. B2/08/05
 Consolidated Edison Co of New York 117pp. 14388.201 24X
 Fiche. 30-000, 82/08/05,8204210407
- B20B100037 PNO-11-82-090 on 820730.w/Unit 2 shutdown for scheduled refueling & mods.Units i & 3 failed secondarry containment integrity tests & were shutdown Caused by im-leakage between common refueling zone & three individual reactor zones BUTCHERIR.C Region 2: Office of Director. 82/08/03. 1p 14276: 261
- 8208:00120 PNO-III-82-075 on 820803, briefcase containing three sealed calibr sources was stolen from car of medical consultant.
 Briefcase was not labeled, however, each source contained radioactive meth label State of MD & local police notified HIEDEMAN, D G . SRENIAMSKI, D J. Hegion 3, Diffice of Director 82/08/04 1p. 14278:022.
- B20B100126 PNO-III-B2-06B.on B20503.allegations from former employes of HVAC contractor received re false or incomplete QA documentation for HVAC work at sites. Special insp of Zack Co & facilities initiated.

 MALKER, D. Replan Q. Office of Director 82/07/22. 1p 1429B-183. 24% Fiche 50-000,82/07/22,820B100126.
- 8208160472 PND-III-82-078: on 820809, licensee issued stop work order for ongoing remedial safety-related soils work at site, after NRC determination that work not approved by NRR. Procedures requiring written approval of work will be devaloped, WARNICK, R Region 3, Office of Director 62/09/12. ip. 14348:194.

- 8208170095 PNA-82-007 on 820811, State of LA nuclear energy div notified Region 4 of low level radioactive contamination caused by Ir-192 tagged sand in private homes & in ofc of Hallburton Svcs. Bossier City, LA HEYER, R S. DUDA: R J Region 4. Office of Director 82/08/11 lp, 14388 216
- 8208300225 EN-82-030; on 820827, order modifying license will be issued to Radiodiagnostics Imaging Affiliate of VA.Inc reinadequate mgt control over radiation safety matters FLACK.E., LIEBERMAN.J Director's Office. Office of Inspection and Enforcement 82/08/27 ip 14679 001
- 8208310097 PNO-II-82-097 on 820819, truck transporting low specific radioactive mati from facility to Richland, WA found to have liquid dripping from truck bed On 820821, drum found to have small holes near base COLLINS, T R Region 2, Office of Director 82/08/24 ip 14695 084
- 8208310175 PNO-V-82-037 on 820825, molten steel accidentally poured ever K-ray gauge Model 7060 S containing 200 mCi Cs-157, burning off paint & labels No radioactive matt released & sus restored to original condition HORNER, J W Region 5, Office of Director 82/08/27 ip

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8208020423 Forwards discussion of general scope of fire protection audits & qualifications of auditors, description of min elements that should be incorporated in annual & triennial audits & proposed Tech Spec 6 5 2 S. per 620308 memo EISENHUT.D @ Division of Licensing 82/07/26. OLSHINSKI.J A Division of Engineering & Technical Frograms 6pp 14177 185
- 8208030746 Comments on draft workscope. "Bafety Implications of Auxiliary Bys Biofouling at Nuclear Power Stations" & proposal, "Becond Intl Corbicula Symposium " IMBRO, & V Director's Office. 82/07/14 HAYES, PF Siting & Environment Branch 4pp 14780 034
- B208030750 Forwards status rept of Multi-Plant Action Item A-16.
 "Qualifications of Insp.Exam.Testing & Audit Personnel."
 for B11001-820707
 JAFFE,D H Operating Reactors Branch 3 82/07/09. EISENHUT,D G
 Division of Licensing NOVAK.T M Assistant Director for Operating
 Reactors. 3pp 14176 331
- 8208040014 "Regulatory Development of Waste Repository "
 FEHRINGER,D J., XNAPP,M R High Level Waste Licensing Management
 Branch 82/04/30 4pp 14232-300
- 8208040347 Forwards NRR responses to questions in RL Ottinger 820409 itr re occupational radiation exposure levels, assigned to NRR in HS Bassett 820414 note ENTON. HR Office of Nuclear Reactor Regulation. Director 12/04/22 84888TT. HS. Office of Management and Program Analysis Ion 14221 372
 - 8050012 Advises of NRC status re exports under general licenses to ibye, in light of Executive Branch revocation of Commerce Jept general export licenses for Libya in Apr 1782 Confirmation of State Dept action requested, HORE,RN Office of International Programs, Director 82/07/27. Office of International Programs, Director 19 14244.360
- 10806D020 Forwards request for add1 into re 790420 event at French reactors Bugs 2 & 4 & 790406 event at Gravelines 1 HELTEMES, C J Director's Office B2/07/29 LAFLEUR, J D Office of International Programs, Director. 2pp 14244:336
- 1208090033 Forwards response to 820614 request for assistance in responding to constituent concerns re deaths from radioactive releases
 DIRCKEN J Diffice of the Executive Director for Operations
 82/07/21 ARMSTRONG W L. Senate 9pp 14283, 311
- --8206130015 Requests response to constituent M Hysocki 820417 ltr re deaths occurring from routine radioactive releases ARMSTRONG.H.L Benate. 82/06/14. Office of Congressional Affairs. 5pp. 14283 319
- 8208070327 Bolicits bids for RS-8EC-82-474, "Electrostatic Copying Bycs " Project summary, proposal submission instructions, no-offer response form & solicitation package encl MATTIAN J Administrative Contracts Branch 82/08/03 Affiliation Unknown 100pp. 14307 207

- 8208120189 Forwards responses to questions on EPRI NP-1850-CCM per NRC 820308 itr Proposed technical review meeting for generic review of RETRAN Code would facilitate review process if addl questions generated SCHNATZ. T
- 820Bi20303 Recommends Div of Security conduct seminar for assigned ofc & div security coordinators unabling exchange of ideas & discussion of any problems re security classification guides
 EISENHUT, D G Division of Licensing 62/08/02 BRADY, R J Division of Security ip 14332 255
- --BROBI20307 Requests suggestions re listed security guides developed by NRC Div of Security by 820730 BRADY, R J Division of Security 82/07/14 NORRY, P 0 Office of Administration 10 14332 256
- 820B12O311 Submits procedures to be followed for enforcement actions LIEBERMAN.J Director's Office, Office of Inspection and Enforcement 82/06/23 CARLSDN.R. Region i, Office of Director ALDERSON.C Region 2, Office of Director WARNICK,R Region 3, Office of Director 4pp 14332 257

NUREO NUREO REPORTS AND RELATED CORRESPONDENCE

- 8206270086 Comments on NRC comments on App E, "Statistical Analysis of LERs Trial Study, Within NUREO-0572" Underlying model & probabilistic assumptions not explicitly stated SAUNDERS, S C ACRS - Advisory Committee on Reactor Safeguards BD/04/17 MDELLER, D ACRS - Advisory Committee on Reactor Safeguards 2pp 14194 113
- 8208020043 Forwards comments re proposed severe damage (SFD) program developed by NRC Fuel Testing Force Program premature & should await development of overall LHR safety goals RHELEP Westinghouse Electric Corp BE-LEH-324 B1/09/25 B1LBERBERG.M. Fuel Dehavior Branch 12pp 14180 338
- B208030133 Advises that industry fails to test relief & safety valves under expected flow conditions, as required by NUREO-0737, item II D. I 1 Valves should be tested w/steam containing water droplets of Nuclear Reactor Calibration Lab B2/07/29 DENTON, H Office of Nuclear Reactor Regulation, Director 2pp 14160 103
- 8208030569 Forwards questions for Commission consideration re NRC policy statement on safety goals
 DIRCKB-W J Office of the Executive Director for Operations
 45FR71023 157, 82/07/20 REMICK.F J Office of Policy Evaluations
 4pp 14162, 246
- 8208030577 Comments on NUREG-0880 re NRC policy statement on safety goals Supports statement HILEAN:R Affiliation Unknown 45FR71023 159 82/07/29 Docketing & Bervices Branch 1p 14162 085
- B20B0305B6 Comments on NUREG-0880 re NRC policy statement on safety goals
 DAVIES.R H. Energy: Dept of 45FR71023 158 82/07/22 CHILK.B J
 Office of the Secretary of the Commission 4pp 14162 294
- 8208040116 Comments on draft rept of NRC fuel testing task force Need for info & understanding of how info will be applied should be developed prior to initiating elaborate & expensive experimental program
 TAYLOR.J H Babcock & Wilcox Co 81/09/03 MINOGUE, R B Office of Nuclear Regulatory Research, Director 2pp 14228 349
- 8208040138 Comments on "Dreft Rept of NRC Fuel Testing Task Force " DEHLBERG.R Electric Power Research Institute 81/10/19 BILBERBERG.M Fuel Behavior Branch 3pp 14237 001
- B208040200 NUREO/CR-2530
 CHARCOAL PERFORMANCE UNDER BIMULATED ACCIDENT CONDITIONS,
 Interim Report on Continuing NRL Problem
 DIETZ, V R Navy, Dept of, Naval Research Laboratory 82/07/31
 48pp Available at NTIS 14231,321
- 8208040207 Informs that Bandia Waste Isolation Flow & Transport (BWIFT) computer code is being released for public review & comments Public comments should be received by 830228 MALARO, J C Transportation & Materials Risk Branch. 82/07/08, Transportation & Materials Risk Branch. 2pp. 14232 241

8208040222 NUREO-0920 US NUCLEAR REGULATORY COMMISSION 1981 ANNUAL REPORT October 1980 - January 1982 MAHER, W J , DICKSON, J H Office of Resource Management, Director B2/07/31 220pp Available at NTIS 14234 001

B20B0402B1 NUREO-0B72
BTUDY OF USING LICENSEE EVENT REPORTS FOR A STATISTICAL ASSESSMENT OF THE EFFECT OF QUERTIME AND BHIFT HORK ON OPERATOR ERROR, FINAL REPT DISALVO, R, GERY, A, PITTMAN, J Division of Facility Operations 82/07/31 NRC - No Detailed Affiliation Given 90pp Available at NTIB \$5 50 14229 195

8208050194 Comments on proposed guidance of NUREG-0737 Tech Specs Clarification should be included in draft generic ltrs which address approved Tech Specs BZALAYR Atomic Industrial Forum 82/07/30 EISENHUT, D G Division of Licensing lipp 14212 050

B208060016 Staff requirements memo informing of Commission B20714 discussion of safety goals, implementation program & draft proposed policy statement CHILK-S J Office of the Secretary of the Commission MB20714B 82/07/16 DIRCKS-W J Office of the Executive Director for Operations REMICK-F J Office of Policy Evaluations ip 14244 339

8208060018 Btaff requirements memo informing of Commission 820622 discussion of emergency response facilities re NUREG-0696 & SECY-82-111 affirmed on 820716 CHILK.S J Office of the Secretary of the Commission MB20622A. 82/07/16 Office of the Secretary of the Commission, 1p. 14244 358

8208070004 NUREG-0430 VO2 NO1 LICENSED FUEL FACILITY STATUS REPORT INVENTORY DIFFERENCE Data As Of June 1982 (Grey Book) * Director's Office, Office of Inspection and Enforcement 82/07/31 15pp Available at NTIS 14302 152

8208090012 NUREO-0485 V04 N04 8YSTEMATIC EVALUATION PROORAM STATUS SUMMARY REPORT Data As Of June 30.1982 (Buff Book) * Office of Resource Management, Director 82/07/31 88pp. Available at NTIS 14283 214

8208090016 NUREO/CR-2520
A HYDRODYNAMIC ANALYSIS OF THE ELECTRON BEAM VAPORIZATION
EXPERIMENTS FOR URANIUM DIDXIDE October 1,1979-September 31,
1981.
GANAPOL, B D : CLARK, B A : SMITH, M B Arizona, Univ of FIN A-4065
82/06/30 Division of Accident Evaluation 64pp Available at
NTIS \$5 00 14303 047

8208120362 NUREG/CR-2774 V01
PHYS108 OF REACTOR SAFETY Guarterly Report, January-March
1982
Argonne National Laboratory FIN A-2015 ANL-82-24 V01
82/07/31. Office of Nuclear Regulatory Research, Director. Sipp
Available at NTIB 14340 037

8208120366 NUREG/CR-2842
TRANSPORTATION OF RADIOACTIVE MATERIAL IN SOUTH CAROLINA
October 1980-8eptember 1981
BAPPINGTON: R South Caroline, State of. FIN B-1612, 82/07/3;
Office of State Programs, Director 38pp Available at NTIS
\$4 50 14332 268,

8208120348 NUREO/CR-2281 VO4 NUCLEAR REACTOR SAFETY October 1-December 31,1981 STEVENBON M. 9 Los Alamos Scientific Laboratory. FIN A-7014 LA-9303-PR 82/07/31 Office of Nuclear Regulatory Research, Director. 42pp. Available at NTIS 14339 240

B20B130447 NUREO/CR-2797
EVALUATION OF EVENTB INVOLVING DECAY HEAT REMOVAL SYSTEMS
IN NUCLEAR POWER PLANTB.
HARIED J.A Cak Ridge National Laboratory FIN B-0755,
CRNL/NBIC-209, 82/07/31 Division of Bafety Technology. 106pp.
Available at NTIS, \$5 50 14351 276.

B20B130469 NUREO-0837 VO2 NO1 NRC TLD DIRECT RADIATION MONITORING NETWORK, Progress Report, January-March 1982 COSTELLO,F, THOMPSON.T, COHEN.L Region 1, Office of Director 82/07/31 180pp, Available at NTIS 14355,318,

8208130471 NUREG-0566 VOZ NO3 STANDARDS DEVELOPMENT STATUS SUMMARY REPORT Data As Of June 1982 (Green Book) * Management Information Branch 82/07/31, 250pp. Available at NTIS 14354:059 8208130472 NUREO/CR-2437 VO4
MATERIALS SCIENCE DIVISION LIGHT-WATER-REACTOR BAFETY
RESEARCH PROGRAM Guarterly Progress Report, October-December
1981.

* Argonne National Laboratory FIN A-2016 ANL-81-77 VO4
82/07/31 Office of Nuclear Regulatory Research, Director 108pp
Available at NTIS 14353 078

B20B130473 NUREO/CR-2750
SDCIOECONDMIC IMPACTS OF NUCLEAR GENERATING STATIONS, Bummary
Report On The NRC Post-Licensing Studies
CHALMERS D. PIJANKA.K D. BRANCH K Mountain Heat Research, Inc.
FIN B-6268 B2/07/31 Division of Health, Siting & Environment
245pp Available at NTIS \$7.50 14352 194

8208130474 NUREO/CR-2782 A SUMMARY OF REPOBLITORY SITING MODELB THOMAS, S D , ROSB, S , MERCER, J H Quotrans, Inc FIN 8-6985 82/07/31 Division of Heate Management 247pp Available at NTIB \$7 50 14353 188

8208130475 NUREO/CR-2837
PNL TECHNICAL REVIEW OF PRESBURIZED THERMAL SHOCK ISSUES
TAYLOR: T , PEDERSON, L T , APLEY, W J Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2510 PNL-4207. 62/07/31.
Division of Safety Technology 148pp Available at NTIS #6.50

8208130476 NURE9-0750 VIS NO3 NUCLEAR REGULATORY COMMISSION ISSUANCES March 1982 Pages 359-672 • Division of Technical Information & Document Control, 82/03/31 31999 Available at NTIS 14350 016

8208130477 NUREO-0915 A CRITERION FOR THE ONSET OF QUENCH FOR LOW FLOW REFLOOD. HSU, Y Y., YOUNO, M W Division of Accident Evaluation 82/07/31. Sipp Available at NTIS 94.50 14351:086

8208130478 NURE0/BR-0025 VOB N7
INFORMATION REPORT ON STATE LEGISLATION
LANDAUM B , KERR, G. W Office of State Programs, Director
82/08/01 9pp Available at NTI8 14350, 350.

8208130477 NUREO/CR-2712
ANALYBIS OF TRAINING AND CERTIFICATION OF OPERATIONS
TECHNICIANS AT INDEPENDENT EFENT FUEL STORAGE INSTALLATIONS
HOTTMAN, S B . BATEMAN, R P . BIERS, D W Bandia Laboratorise. FIN
A-1331 BAND82-7051 82/08/31 Office of Nuclear Regulatory
Research, Director. 313pp Available at NTIS 14355:001

8208130480 NUREQ/CR-2383
RADIONUCLIDE DISTRIBUTIONS AND MIGRATION HECHANISMS AT
SHALLOW LAND DURIAL SITES, Annual Report of Research
Investigations On the Distribution Migration and Containment
of Radionuclides At Maxey Flats, Kentucky
KIRBY, L. J. Hatbelle Memorial Institute, Pacific Northwest
Laboratory, FIN 8-2291 FML-4067, 82/07/31 Division of Health,
Siting & Environment, 158pp. Available at NTIS \$6,50, 14392;037

8208130481 NUREO/CR-2798
EVALUATION OF EVENTS INVOLVING UNPLANNED BORON DILUTIONS
IN NUCLEAR POWER PLANTS.
HAGEN, E W. Dak Ridgs National Laboratory. FIN B-0755
DRNL/NBIC-208 82/07/31. Division of Safety Technology, 40pp

8208130483 NUREO/CR-2403 ERR SURVEY OF INBULATION USED IN NUCLEAR POWER PLANTS AND THE POTENTIAL FOR DEBRIS GENERATION # Durns & Ros CD. 82/07/30 Spp Available at NTIS 14350-341

8208160222 Comments on systematic assessment of licenses performance program Assessment, as modified, is vast improvement over process that has existed during past 2 yrs.

MILLER, M. Tennessee Valley Authority 47FR12240 015. 82/08/05, Docketing & Services Branch 3pp. 14344*148.

8208170306 NUREO/CR-2716 V01
REACTOR SAFETY RESEARCH PROGRAMS Quarterly Report; JanuaryMarch 1982
EDLER: B. K. Battella Nemorial Institute, Pacific Northwest
Laboratory FIN B-2101 PNL-4275-1. 82/07/31 Division of
Accident Evaluation 69pp. Available at NTIS. \$5.00. 14371:305

8208170312 NUREQ-0B75
COMMENTS ON THE NRC BAFETY REBEARCH PROGRAM BUDGET FOR
FIBCAL YEARS 1984 AND 1983.
** ACRS - Advisory Committee on Reactor Safeguards 82/07/31 31pp
Available at NTIS \$3.75. 14372:024.

8208170316 NUREQ/CR-2796
COMPRESSED-AIR AND BACKUP NITROGEN SYSTEMS IN NUCLEAR POWER
PLANTS
HAGEN,E W Oak Ridge National Laboratory FIN B-0755
QRNL/NB[C-206 82/07/31 Division of Systems Integration (post
811005) 90pp Available at NTIS \$5 50 14372 032

8208180120 NUREO-0580 VII NO7 REOULATORY LICENSING STATUS SUMMARY REPORT. Data As Of July 10,1982 (Blue Book) # Hanagement Information Branch 82/07/31 72pg Available at NTIS 14391 215

820B180126 NUREQ/CR-2675 VOI
RELEVANCE OF BIOTIC PATHWAYS TO THE LONG-TERM REQULATION
OF NUCLEAR WASTE DISPOSAL A Report On Tasks 1 And 2 Of
Phase I
HCKENZIE, D H , CADHELL, L , CUSHING, L E Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-2377 PNL-4241
62/07/31 Division of Haalth, Sitting & Environment 72pp.
Available at NTIS 45 00 14391 287

8208180212 NUREQ-0871 V01 N03 SUMMARY INFORMATION REPORT Data As Of June 30,1982 (Brown Book) * Office of Resource Management, Director 82/07/31 51pp Available at NTIS 14389 233

8208180217 NUREO/CP-0025
PROCEEDINGS OF A WORKSHOP DN ENVIRONMENTAL ASSESSMENT
WATSON,E C Battelle Hemorial Institute, Pacific Northwest
Laboratory FIN 8-2422 PNL-4235 82/07/31 Office of Nuclear
Regulatory Research, Director 156pp, Available at NTIS \$6.50,
14390 191

8208180222 NUREO/CR-2705
TRAINING COURSE NO 1 THE IMPLEMENTATION OF FEMALTER
(ORM.-5567) COMPUTER PROGRAM
YEH.O.T. Dak Ridge National Laboratory FIN A-7095 DRNL/TM-8327,
82/06/30 Division of Waste Management 174pp Available at
NTIS \$8 00 14389 023

8208180227 NUREQ/CR-2852
TRANSPORTATION OF RADIOACTIVE MATERIAL IN NEVADA September
1980-September 1981
* Nevada, State of FIN 8-1327 82/07/31 Office of State
Programs, Director Zópp Available at NTIS \$3 50 14389-337.

8208180232 NUREO/CR-2224
CHARACTERIZATION HETHODS FOR ULTRASONIC TEST SYSTEMS
BUSBEL J, BECKER,FL, BOWEV,R E Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2269 PNL-4215 82/07/31
Division of Engineering Technology 69pp. Available at NTIS.
\$5.00. 14391.002

108180237 NUREG/CR-1598
EVALUATION OF CATCH-PER-UNIT-EFFORT INDICES USED IN AGUATIC
MONITORINO PROGRAMS AT NUCLEAR POWER PLANT SITES
MCKENZIE, D. H., BKALGKI, J. R., BIMMONS, N. A. Battelle Hemorial
Institute, Pacific Northwest Laboratory FIN B-2160 PNL-3365
82/07/31 Division of Engineering Technology 116pp Available
at NTIS 65. 50 14391 072

OBIBO241 MUREG/CR-2690
THERMAL/HYDRAULEC ANALYBIS RESEARCH PROGRAM Quarterly
Report Cetober-December 1981
THOMPBON, B.L. Bandia Laboratories Fin A-1203 BANDB2-0953,
B2/07/31. Office of Nuclear Regulatory Research, Director, 39pp.
Available at NTIB 14389 192

OSI80245 NUREO-0910 NRG COMPREHENSIVE RECORDS DISPOSITION SCHEDULE * Division of Technical Information & Document Control. 82/07/31, 200pp. Available at NTS 47 50, 14350:001.

8208190016 Responds to 820520 itr re equation used in NUREO/CR-1759, Yol 3, to model wind suspension of dust from low level waste disposal sites. Equation obtained from U mill tailings GEIS & used to estimate bound level of impacts from wind sresion. LOHAUS.P H Low Level Haste Licensing Branch 82/07/26 GULKOWSKI, H. M Commerce. Dept of, National Grandsphic &

8208230001 NUREG-0370 V06 N01 TOPICAL REPORT REVIEW STATUS (Blue Book) * Management Information Branch 82/08/31 201pp Available at NTIS 14507 OB1

8208230002 NUREO-0936 VO1 ND2 NRC REGULATORY AOENDA Quarterly Report April-June 1982 * Division of Rules and Records 82/07/31 167pp Available at NTIS \$7 50. 14507 330

8208230035 NUREO/CR-2612 ERR
VARIABILITY IN DOSE ESTIMATES ASSOCIATED WITH THE FOOD
CHAIN TRANSPORT AND INDESTION OF SELECTED RADIONUCLIDES
* Dak Ridge National Laboratory CRNL/TM-8079 82/08/04
Division of Systems Integration (post 811005) 7pp Available at
NTIS 14507 310

8208230417 NUREO-0525 RO5
SAFEOUARDS SUMMARY EVENT LIST
MACMURDY: P. DAVIDEON: J. LIN. H. Office of Nuclear Material Safety &
Safeguards. Director 82/07/31 59pp Available at NTIS \$4.75

8208240424 NUREO-0020 VO6 NO4 LICENSED OPERATING REACTORS Status Summary Report Data As of March 31,1982 (Orey Book) * Management Information Branch 82/08/31 415pp Available at NTIS 14543 064

8208260002 NUREO/CR-2833 VOI CRITICAL HUMAN FACTORS ISSUES IN NUCLEAR POWER REGULATION & RECOMMENDED COMPREHENSIVE HUMAN FACTORS LONG RANGE PLAN Elecutive Summary HOPKINS.C 0 . SNYDER.H L . PRICE.H E Human Factors Society, Inc FIN 3-7237 B2/08/31 Division of Facility Operations 283pp Available at NTIS \$5 00 14587 007

8208260008 NUREO/CR-2093 ERR
HEAT TRANSFER ANALYBIS OF LWR PRESSURE VESSEL STEEL
IRRADIATION CAPBULES IN THE OAK RIDGE RESEARCH REACTORPRESSURE VESSEL BENCHMARK FACILITY

* Oak Ridge National Laboratory ORNL/NUREO/TM-4 82/08/16
Office of Nuclear Regulatory Research, Director 3pp 14572 343

BROB250017 NUREO/CR-2833 VO3
CRITICAL HUMAN FACTORS ISBUES IN NUCLEAR POWER REQULATION &
RECOMMENDED COMPREHENSIVE HUMAN FACTORS LONG-RANGE PLAN
CRITICAL Discussions of Human Factors Areas of Concern
HDPKINB/C O , SNYDER, H L , PRICE, H E Human Factors Society, Inc
FIN 8-7239, 82/08/31 Division of Facility Operations 28391
Available at NTIS \$8 00 14587 278

8208260027 NUREO/CR-0200 VOI ER

SCALE A MODULAR CODE SYSTEM FOR PERFORMING STANDARDIZED COMPUTER ANALYSIS FOR LICENSING EVALUATION Book I, II And III

* Oak Ridge National Laboratory. ORNL/NUREO/CSD- 82/07/2

Dak Ridge National Laboratory. ORNL/NUREO/CSD- 82/07/23
 Office of Nuclear Material Safety & Safeguards, Director, 28pp Available at NTIS 14575 027

8208260034 NUREO/CR-2403 801 ER
BURVEY OF INSULATION USED IN NUCLEAR POWER PLANTS AND THE
POTENTIAL FOR DEBRIB GENERATION
* Burns & Rop Co * Sandia Laboratorios SANDS2-0927 82/07/30
Division of Safety Technology 2pp 14575 025

B20B260037 NUREO/CR-2793
TECHNIQUEB FOR ELEVATED TEMPERATURE MECHANICAL TESTING
SCHMALE,D T , CROSS,R W Sandia Laboratories 82/08/31 Office
of Nuclear Regulatory Research, Director 35pp Available at NTIB
14576-342

8208260066 NUREG/CR~2851
TRANSPORTATION OF RADIOACTIVE MATERIAL IN ILLINDIS June 1980-June 1981.
MENNEG, M. NORDIN, J. SIMONIN, J. M. Illinois, State of 82/07/31
Office of State Programs, Director 78pp Available at NTIS 45

S208260069 NUREO-0917

NUGLEAR REQULATORY COMMISSION STAFF COMPUTER PROGRAMS FOR
USE WITH METEOROLOGICAL DATA

SNELL, W Q. Division of Systems Integration (post S11005) 82/07/3

115pp Available at NTIS \$6 00 14587.153.

9209260075 NUREG/CR-2407
RADDN AND AEROSOL RELEASE FROM OPEN PIT URANIUM MINING
THOMAS, V W. NIELSON, K K. MAUCH M.L. Battelle Memorial Institute,
Pacific Northwest Laboratory. FIN 8-2279. PNL-4071 82/08/31
Division of Health, Siting & Environment 300pp Available at NTII
49.50 14578-017

B2082600B0 NUREO/CR-2707

ORNL BMALL-BREAK LOCA HEAT TRANSFER TEST SERIES I
COMPARISONS OF EXPERIMENTAL DATA WITH VENDOR MODELS FOR
LOW-FLOW STEAM HEAT TRANSFER
AKKLAN. T M Oak Ridge National Laboratory FIN 8-0123
ORNL/TM-8329 82/07/31 Office of Nuclear Regulatory Research,
Director 61pp Available at NTIS 14577 320

8208250087 NUREG/CR-2525 V04
ORNL ROD BUNDLE HEAT TRANSFER TEST DATA VOL. 4 ORNL SMALL
REAK LOCA HEAT TRANSFER TEST SERIES II Experimental Data
Report
ANKLAM. T M., HUNT, D F., FELDE, D K. Oak Ridge National Laboratory
FIN B-0125 ORNL/NUREG/TM-4 82/07/31 Office of Nuclear
Regulatory Research. Director 133pp Available at NTIS
14574 219

8208260097 NUREQ/CR-2714
ANALYSIS OF FAILURE RATE DATA WITH COMPOUND MODELS
SHULTIS,J K , ECKHOFF,N D , JOHNSON,D E Kansas State Univ FIN
A-6290 E00-2206 82/07/21 Office of Nuclear Regulatory
Research, Director 112pp Available at NTIS 14577 017

#208260112 NUREC/CR-2549

BACKOROUND BTUDY AND PRELIMINARY PLANS FOR A PROGRAM ON THE SAFETY MARGINS OF CONTAINMENTS

BLEJMAS;T E , DENNIS,A W , WOODFIN;R L Bandia Laboratories FII A-1249 SANDS2-0324 \$2/07/31 Office of Nuclear Regulatory Research, Director 58pp Available at NTIS 14577,132

8208260401 NUREQ/CP-0034 V01
PROCEEDINGS OF THE TOPICAL MEETING ON ADVANCES IN REACTOR
PHYBICS AND CORE THERMAL HYDRAULICS
AND CORE THERMAL HY

B208260406 NUREQ/CP-0032
HQRRSHOP ON METEOROLOGICAL ASPECTS OF EMERGENCY RESPONSE
PLANS FOR NUCLEAR POWER PLANTS
SETHURAMAN, B. TICHLER, J. PATRINGS, A. Brockhaven National
Laboratory FIN A-3240 BN_-NUREQ-51552 B2/08/31 Office of
Nuclear Regulatory Research, Director 75pp Available at NTIS
66 50 14590 031.

B20B2A0414 NUREO/CR-2400
TACTICAL IMPROVEMENT PACKAGE
BAEHRID G., HEIDER, J A., ADAMB, K. Q. Sandia Laboratorias FIN
A-1162 SANDS2-0462 82/07/31 Office of Nuclear Material Safety
i Safepuards, Director 103pp Available at NTIS \$5 50
14389 309

8208260420 NUREQ/CP-0034 VO2
PROCEEDINOS OF THE TOPICAL MEETING ON ADVANCES IN REACTOR
PHYSICS AND CORE THERMAL HYDRAULICS.
• NRC - NO Detailed Affiliation Civen 82/08/31 630pp Available
at NTIS \$13 00. 14592 250

8208250429 NUREQ-0883 URANIUM MILL APPRAIBAL PROGRAM EVERETT,R J , CAIN,C L Region 4, Office of Director 82/08/31 33pp Available at NTIS \$4.50 14889:277

#208260433 NUREQ/CR-2784
BEHAVIOR OF WATER SPRAY INJECTED INTO AIR/STEAM
ENVIRONMENT
LEE.8 Y, TANKIN,R 8 Northwestern Univ FIN 0-1000 82/08/31
Division of Accident Evaluation 152pp Available at NTIS \$6 50
14570.028.

©208260434 NUREG/CR-2794 COMPUTER USE IN THE HIGH TEMPERATURE MECHANICAL METALLURGY TESTING LABORATORY. CROSS,R W Sandia Laboratories HUFNAGEL,R EQ&G, Inc. FIN A-1172, SAND82-0799, 82/07/31 Office of Nuclear Regulatory Research, Director. 43pp. Available at NTIB 14568 001

8208260438 NUREO/CR-2752 VOI ADVANCED TWO-PHASE FLOW INSTRUMENTATION PROGRAM Guarterly Progress Report For January-March 1982 HARDY, J. E., ROOERS, 8 C., MILLER, 0 N. Dak Ridge National Laboratory, FIN 8-0401. ORNL/TM-8365. 82/07/31. Office of Nuclear Regulatory Research, Director 17pp Available at NTIS 14567 317

8208260440 NUREQ/CR-2563
RELATIVE STOCK COMPOSITION OF THE ATLANTIC COAST STRIPED
BASS POPULATION FURTHER ANALYSIS.
WINKLE, H. V., KUMAR, K. D. Oak Ridge National Laboratory. FIN B-0165,
ORNL/TH-B217. B2/07/31 Office of Nuclear Regulatory Research,
Director. 41pp Available at NTIS 14570.270

8208260466 NUREO/CR-2616
EVALUATION OF ISOTOPE MIGRATION-LAND BURIAL Water Chemistry
At Commercially Operated Low-Level Radioactive Waste
Disposal Bites Status Report.October 1960-Septamber 1981
PIETRZAK,R. CZYBCINSKI,K.S., WEISB,A.J. Brookhaven National
Laboratory FIN A-3042 BNL-NUREO-51514 82/07/31 Office of
Nuclear Regulatory Research, Director 54pp. Available at NTIS.
14570, 180

8208260473 NUREO/CR-2533
THE EFFECT OF STOCHASTIC VARIATION ON ESTIMATES OF THE PROBABILITY OF ENTRAINMENT MORTALITY Methodology.Results.
And User's Guide
CHRISTENSEN.S. DEANGELIS.D L. Oak Ridge National Laboratory. FIN B-0165 ORRL/TM-7765 82/07/31 Office of Nuclear Regulatory
Research. Director. 84pp Available at NTIS 14570 310

8208260486 NUREO/CR-0169 VI1
LOFT EXPERIMENTAL MEASUREMENTS UNCERTAINTY ANALYSIS,
VOLUME XI,FREE FIELD PRESSURE TRANSDUCER.
0000RICH,L D., LASSAHN, O D EQ&O, Inc. FIN A-6043. EQQ-2037.
82/07/31 19pp Available at NTIS 14367 336

8208260491 NUREO/CR-2649
INFLUENCE OF THE MAGNETOMECHANICAL EFFECT IN TESTING OF
INDUCTIVELY HEARTED FERRITIC STEEL
JONES, H B Bandia Laboratories SANDB2-0752 82/07/31 Office
of Nuclear Regulatory Research, Director 23pp Available at NTIS
14595, OD9

8208240499 NUREQ/CR-2579
THO- AND THREE-DIMENSIONAL DIFFUSION THEORY CALCULATIONS FOR
THE POOL CRITICAL ASSEMBLY PRESSURE VESSEL WALL BENCHMARK
FACILITY.
BALDWIN.C A Dak Ridge National Laboratory FIN 8-0415
ORNL/TM-8118. 82/07/31 Office of Nuclear Regulatory Research,
Director. 57pp Available at NTIS 14572.238

8208260505 NUREO/CR-2869
DIRECTORY AND PROFILE OF LIGENBED UNANIUM-RECOVERY
FACILITIES
HARKENYIEN, J., BUBCH, L. B., DEPUE, J. Argonne National Laboratory,
FIN B-1660 ANL/EB-128. 82/07/31 Office of State Programs,
Director 103pp Available at NTIB \$5.50 14595:066

8208270619 Forwards rept on number of personnel & man rem by work & job function for 1981, per NUREQ-0737, Item II.K. 3 3 MAYER, L. O. Northern States Power Co. 82/02/26. KEPPLER, J. O. Region 3, Office of Director 1p. 14679:342. 24X Fiche: 50-000, 82/07/13, 8208270619

8208310141 Forwards comments on proposed NUREQ-0737 Tech Specs Comments should not be interpreted as formal position of any individual owners group member DENTE.T J. BMR Owners Group BMR00-8255 82/08/26. EISENHUT, D. 9 Division of Licensing 4pp 14693 175

820B310340 Forwards "Analysis of Boram Discharge Vol Bys Piping Integrity " Low probability of core damage initiated by failure of scram discharge piping integrity precludes need to qualify equipment to detect/mitigate consequences DENTE, T. J BHR Owners Oroup. BHR00-B254 B2/08/23. EISENHUT, D. Q. Division of Licensing. Rpp 14493:214.

--8208310347 NEDO-22207

"Analysis of Beram Discharge Vol Sys Piping Integrity "
ALEBII,0 , HAYES,F.R., STANCAVAGE,P P Oeneral Elactric Co.
82NED088 82/08/31 27pp 14693 216

8208310392 Forwards GA Program Insp Rept 99900289/82-02 on 820415-16 No noncompliance noted POTAPUSU Division of Vendor & Technical Programs 82/08/10 RUIKOHBKI,R.J Borg-Warner Corp. 2pp 14693 258.

--B20B310401 GA Program Insp Rept 99900289/B2-02 on B20415-16 No noncompliance noted Major areas inspected: verification that qualification testing of Borg-Harner valve actuator is proceeding in compliance w/NUREG-0588.Revision 1. AGEE, J.R., PHILLIPSH B. Division of Vendor & Technical Programs, 82/07/21. 5pp 14693 260

DRO CORRESPONDENCE WITH OTHER ORGANIZATIONS

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl. JORDAN, E. Diffsion of Engineering & Guality Assurance 82/07/19. Michigan, Univ. of, 112pp 14358.001. 24X Fiche 50-000,82/07/19,8204210395.

- 8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24x Fiche 50-000,82/07/20,8204210396
- B204210398 IE Info Notice B2-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/07/22 Consolidated Edison Co of New York 112pp 14194 321 24X Fiche 50-000,82/07/22.8204210398
- 8204210401 IE Info Notice 82-28, "Mydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl UCROAN, E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp. 14380 115 24X Fiche, 50-000, 82/07/23, 8204210401
- 8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Syc list ent! JURDAN,E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24X Fiche 30-000,82/08/05,8204210407
- 8206200094 Forwards "NRC/FEMA Joint Monthly Rept to Congress on Emergency Preparedness, June 1982"
 PALLADINO,N J Commissioners GIUFFRIDA,L D Federal Emergency Hanagement Agency 82/07/21 SIMPSON,A K Benate, Environment & Public Works 2pp 14506 209
- --8208190053 "NRC/FEMA Joint Monthly Rept to Congress on Emergency Preparedness.June 1982 " + NRC - No Datailed Affiliation Given * Federal Emergency Management Agency 82/07/21 61pp 14506 21
- 8208040207 Informs that Sandia Waste Isolation Flow & Transport (SWIFT) computer code is being released for public review & comments Public comments should be received by 830228 MALARO, J.C. Transportation & Materials Risk Branch 82/07/08 Transportation & Materials Risk Branch 2pp 14232 241
- 8208050196 Comments on proposed guidance of NUREG-0747 Tech Specs Clarification should be included in draft generic itrs which address Approved Tech Specs SZALAY, R Atomic Industrial Forum 82/07/30 EISENHUT, D G Division of Licensing. 11pp 14212 050
- 8208060338 Forwards request for OMB review & supporting statement re survey of radioactive matl shipment date NORRY,P & Office of Administration 82/08/02 SCURRY,N Office of Management & Budget to 14281:116
- 9208100004 Comments on value of SEP Phase III program No current basis exists for justifying initiation of proposed SEP Phase III program. Detailed NRC review of need for program suggested HALSKE, C. Atomic Industrial Forum 82/08/06 EISENHUT, D 0 Division of Licensing 13pp 14294 348
- OB19004: Forwards request for OMB review & supporting statement rereporting & recordiseping requirements contained in proposed 100FR30 7R(c). "Notification of Significant Events" NORRY: P 0 Office of Administration 82/08/:1 SCURRY:N Office of Management & Budget ip 14506 179
- 8208230406 Forwards request for GMB review & supporting statement re reporting & recordsesping requirements for NRC Form 398, "Personnel Qualifications Statement - Licenses " NORRY-P. O Office of Administration 82/08/11 BCURRY, N Office of Management & Budget Ip 14528 229
- 8208240010 Forwards request for OMB review & supporting statement re 10CR350 36(f) proposed rule concerning Tech Specs, NORRY.P G. Office of Administration 82/08/13 SCURRY,, N Office of Management & Budget 1p 14529 264.
- 8208240023 Responds to approval re request for info collection re Equal Access to Justice Act, 10CFR2 Request not approved (withdraum at agency request), SCURRY.N Office of Hanagement & Budget, 82/08/05 SCOTT, S Document Management Branch, 2pg. 14527:262
- 8208240027 Responds to approval request for info collection re survey of radioactive matl shipment data Request approved through 820930 under GMS Number 3150-0089.per Paperwork Reduction Act.

 8CURRY:N Office of Management & Budget. OMB 3150-0089 82/08/09 8COTT.8 Document Management Branch 2pp. 14527 260

- 8208240031 Responds to approval request for info collection re Agreement State program Request approved through 850831 under OMB Number 3150-0029 per Paperwork Reduction Act SCURRY.N Office of Management & Budget OMB 3150-0029 SCOTT, S Document Management Branch 2pp 14529 258
- 8208240039 Forwards request for OMB review & supporting statement re IOCFR40, domestic licensing of source matl NORRY,P O Office of Administration 82/08/09 SCURRY,N Office of Management & Budget Ip 14529 237
- 8208310015 Forwards request for OMB review & supporting statement re 10CFR150, exemptions & continued regulatory authority in Agreement States under Section 274 of Atomic Energy Act NORRY-P @ Office of Administration 82/08/24 SCURRY,N Office of Management & Budget 1p 14697 136
- 8208310443 Responds to 820727 itr re AIF Reactor Vessel Integrity Subcommittee views on development & implementation of regulatory requirements concerning pressurfied thermal shock Phesed approach similar to one under consideration DENTON: H R Office of Nuclear Reactor Regulation, Director 82/08/09 01885,D C Atomic Industrial Forum 1p 14497 322
- --B208310451 Submits views of AIF Reactor Vessel Integrity Subcommittee on development & implementation of regulatory requirements re pressurfized thermal shock, as followup to 820423 ltr Proposed two phase approach discussed 918BB.D C Atomic Industrial Forum 82/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 14697 323

PR PROPOSED RULE

- 8207140177 Comments on proposed rule 10CFR50 re LER sys In instances of operator error, automatic reporting under LER sys should not be required DIXON, 0 W Bouth Carolina Electric & Qas Co 47FR19543 016 82/06/30 CHILK, B J Office of the Secretary of the Commission 2pp 13838,357
- 8208030497 Forwards constituent RW Whalen comments on proposed rule IOCFR35 re training & experience criteria for physicians requesting authorization to use reactor-produced radioactive isotopes
 BROYNILL.J T House of Rep 47FR15798 036 88/07/07 KAMMERER.C Office of Congressional Affairs 3pp 14164 060
- B20B03050B Package of two comments on proposed rule 10CFR50 re LER sys HITTL-R.L. Public Service Electric & Gas Co of New Jersey BECKHAM, J T Georgia Power Co 47FR19543 82/07/26 Docketing & Bervices Branch Jap 14163 250
- 8208030516 Comments on proposed rule 10CFRSO re LER sys MAURIN: L V. Louisiana Power & Light Co 47FR19543 044 82/07/06 Docketing & Services Branch 3pp 14163 127
- 8208030543 Comments on proposed rule 10CFR34 re certification of industrial radiographers Opposes rule Third-party certification is not needed or desirable Addl regulation unwarrented.

 KDVACS. B Foster Wheeler Corp 47FR19132 044 82/07/19 Docketing & Services Branch 3pp 14162 105
- 8208030553 Comments on proposed rule 10CFRBO, "Tech Specs for Nuclear Power Reactors" Bupports need to revise Tech Specs CRANE.P A Pacific Oas & Electric Co 47FR13369 030 82/07/20 Docksting & Services Branch Spp 14162 086
- B208030591 Comments on proposed rule 10CFR34 re licensing of radiographers Recommends ad hoc committee be formed to establish guidelines for licensing companies for possession only & licensing radiographers for utilization of matis DAVIS. J B Davis & Geck, Inc. 47FR19152 046 B2/07/19 JGNES, J A Office of Nuclear Regulatory Research, Director 2pp 14161:155
- 8208030692 Comments on proposed rule 10CFR34 re certification of industrial radiographers Supports separately classifying licensees in categories of fixed facilities & field operations.

 ANNAL-J M Steel Founders' Society of America 47FR19152 045 82/07/22 CHILK, J Office of the Secretary of the Commission. 10pp 14162, 132
- 8208100188 Comments on proposed rule 10CFR34 re third party certification of radiographers Effectiveness of sys would be dependent upon definition of responsibilities of various parties involved & administration of sys ROBIER, O. A. Cherne Contracting Corp. 47FR 19132 047 82/07/30 Docketing & Bervices Branch. 5pp. 14298, 202

- B20B100256 Comments on proposed rule 10CFR71, "General License for Enipment in Packages Approved for Use by Another Person" Recommends that certificates of compliance identify documents & drawings which licensees should have on file HENDRIX.O W Navy.Dept of, Naval Facilities Engineering Command 47FR21269 012 B2/07/30 Docketing & Services Branch ip 14295 194
- 8208100284 Advises recipients of comments on proposed rule 10CFR35, "Physician Use of Radioactive Drugs," that Comment 36 was miscoded Number 36 will not be used again a Docketing & Bervices Branch 47FR15798 82/08/04 Docketing & Bervices Branch 1p 14297 067
- 8208100352 Notifies of 820727 briefing in Germantown, MD. in response to inquiries re status of final technical criteria for disposal of high level radwaste in geologic repositories BELL. M J. High Level Waste Licensing Management Branch 82/07/23 Affiliation Unknown 7pp 14308 324
- 820B100355 Responds to 820704 request for briefing on 10CFR40 Briefing scheduled for 820729 in Germantown, MD BELL, M J High Level Waste Licensing Management Branch 82/07/23 BALLAKD, W. W Energy, Dept of 1p 1430B 273
- 8208160060 Order CLI-82-3 denying KMC & Physical Security Coordinating Group petition for reconsideration & immediate suspension of final rules 10CFR2:50:70 & 73 re protection of unclassified safeguards info No adverse effect shown CHILK:S J Office of the Secretary of the Commission CLI-82-03. 82/03/02. KMC. Inc 4pp 14344 229
- BR08160237 Package of two comments on proposed rule 10CFR34 re third party certification of industrial radiographers
 GAPRID: H. Radiation Protection Service MCGUIRE: R D. Affiliation Unknown 47FR19152 82/08/09 Docketing & Services Branch 5pp 14342 288
- B20B160480 Comments on proposed rule 10CFR50 re LER sys Proposed rule will have adverse effect on present recordkeeping requirements by showing inconsistency w/intent of Paperwork Reduction Act
 AMERINE.T E Nuclear Records Management Association, Inc 47FR19543 047, 82708/05 Docksting & Services Branch ip 14248-318
- B20B170137 Comments on proposed rule 10CFR34 re certification of radiographers Implementation of certification program Will not reduce overexposure incidents Favors hat1 registry to assist licensees in determining qualifications
 DALE.L. F. Mississippi Power & Light Co. 47FR19152 050 B2/08/06
 Docketing & Services Branch 2pp 14366, 234.
- B20B170142 Comments on proposed rule 10CFR50 re mandatory insurance for decontemination of nuclear power plants Opposes rule Exphasis should be on how extensively decontemination can be accomplished LEWIS.H I Lewis, M 47FR27371 001 B2/0B/11 Office of the Becretary of the Commission ip 14366.144
- 8208180032 Comments on proposed rule 10CFR34 re certification of industrial radiographers by third party Proposal would not achieve desired motivation to accomplish reduction in overerposures
 OQUD.H R Affiliation Unknown, 47FR19152 051 82/08/11
 Docketing & Bervices Branch 2pp. 14376.317
- B208180073 Comments on petition for rulemaking PRM-50-32 Geographically localized & time limited studies which would outline ways to assure reactor sefety following high eltitude nuclear explosions suggested TODDROVICH M Brientists & Engineers for Secure Energy, 47FR27371 OO7 82/08/11 CHLK/8 J Office of the Secretary of the Commission ip 14376:316.
- 8208190016 Responds to 820920 ltr re equation used in NUREO/CR-1789, Vol 3, to model wind suspension of dust from low level waste disposal sites Equation obtained from U mill tailings GEIS & used to estimate bound level of impacts from wind erosion LOHAUS, PH Low Level Waste Licensing Branch 82/07/26, CULKOMBRI, WM. Commerce.Dept. of, National Oceanographic & Atmospheric Administration 3pp 14506.341.
- B208300004 Informs that Commission approved issuance of proposed rule on applicability of license conditions & Tech Specs in amergency on B20723.Ltrs to inform Congressional committees of action & deaft FR notice encl
 DENTON.H R. Office of Nuclear Reactor Regulation, Director B2/08/11 FELTON.J M Division of Rules and Records. 11pp. 14695:007.

- ---8208300006 Forwards FR notice re changes to 100FR50 54, "Conditions of Licenses" & 100FR50 72 "Notification of Significant Events " Proposed rule allows licenses to take reasonable action outside Tech Brecs in emergency DENTON, H R Office of Nuclear Reactor Regulation, Director 82/08/11 SIMPSON, A Senats ip 14675 018
- --8208300008 Forwards FR notice re changes to 10CFR50 54, "Conditions of Licenses" & 10CFR50 72 "Notification of Bignificant Events." Proposed rule allows licensee to take reasonable action outside Tach Specs in emergency DENTON.H R Office of Nuclear Reactor Regulation, Director 82/08/11 MOFFETT, T Genate 1p 14675 017
- --B20B3D0010 Forwards FR notice re changes to 10CFR50 54, "Conditions of Licenses" & 10CFR50 72 "Notification of Significant Events," Proposed rule allows licensee to take reasonable action outside Tech Bpecs in emergency DENTON, HR Office of Nuclear Reactor Regulation, Director B2/OB/11 UDALL, MK Senate 1p 14675 020
- --B20B300015 Forwards FR notice re changes to 10CFR50 54, "Conditions of Licenses" & 10CFR50 72 "Notification of Bignificant Events "
 Proposed rule allows licenses to take reasonable action outside Tech Bpecs in emergency
 DENTON,H R Office of Nuclear Reactor Regulation, Director 82/08/11 OTTINGER,R L Senate 14pp 14695 021.
- --8208300019 Staff requirements memo discussing 820715 affirmation session of publication of proposed rule, to allow licenses to take reasonable action outside Tech Epecs in emergency CHILK.8 J Office of the Secretary of the Commission 82/07/23 BICKNIT.L Office of the General Counsel COTTER.P B. Atomic 8afety and Licensing Board Panel DIRCKB.W.J Office of the Executive Director for Operations 13pp 14695.036
- 8208300153 Comments on graposed rule 10CFR30 re codes & stds for nuclear power plants Supports rule WITHERS BD Portland Gameral Electric Co 47FR15801 014. 82/08/17 Doctsting & Services Branch, 1p 14597 218
- 820B300169 Comments on proposed rule lOCFR34 re certification of industrial radiographers Opposes rule
 DEHOFF.H.L. Newport News Industrial Corp (subs of Newport News Shipbuilding & DryDuck Co.) 4.7FR19152 055 82/08/20 Docketing & Bervices Branch 3pp 1467B 220
- 8208300171 Comments on proposed rule 10CFR50 rs insurance for nuclear power plants Recommends quantitative min insurance requirements be established & updated periodically ABHBURN.D.J. Harsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 47FR27371 020 82/08/24. Office of the Secretary of the Commission 3pp 14875.349.
- 820B300172 Comments on proposed rule 10CFR34. "Certification of Industrial Radiographers." Present sys for certification of radiographers preferred GRABHAW, T D Allied Inspection Services, Inc. 47FR19152 054 B2/0B/04 Docketing & Bervices Branch. Spp. 14595-346
- 8208300175 Package of two comments on proposed rule 100FR34 receptification of industrial rediographers Opposes rule MOBERGA J. Newport News Shipbuilding & Bry Dock Co. (subs. of TENNECO Corp.) DOCOART, R. R. Resource Technical Services, Inc 47FR19132 82/08/19 Doctsting & Services Branch. 10pp 14478, 204
- 8208300192 Comments on proposed rule 10CFR50 re LER sys Rewording of specific guidance suggested.
 PDDEETIJA Caroline Power & Light Co 47FR19543 049 82/08/18
 Office of the Berretary of the Commission ip 14596; 014
- 8208300223 Package of two comments opposing proposed rule 10CFR34 re certification of industrial rediographers by third party.

 CARGLL, D. E. Carroll Engineering VORHEES, J. P. Pittsburgh-Des Moines Corp. 47FR19152 82/08/26. Docketing & Bervices Branch 10pp. 14679.046.
- 8208300261 Comments on proposed rule 10CFR50 re drug/alcohol screening for nuclear plant workers Supports rule NORRICK.G. Affiliation Unknown, 47FR33980 001, 82/08/14. Docketing & Services Branch ip 14677 139.
- 8208300264 Package of two comments on proposed rule 10CFR50 re drug & alcohol screening for nuclear plant workers SMITH.H.H. Smith. Sikorski-Smith. KORNNAUSER.M.C Affiliation Unknown. 47FR33980. 82/08/19. Docksting & Services Branch App. 14678:357.

- 8208300268 Comments on proposed rule 10CFR140 re mod of indemnity agreements Opposes rule 2AHLER, R E Shaw, Pittman, Potts & Trowbridge 47FR31887 001 82/08/23 Dacketing & Services Branch. 2pp. 14599 360
- 8208300270 Comments on proposed rule 10CFR50 re fitness for duty of personnel u/unescorted access to protected areas. Proposed rule does not constitute new requirement Revision to 10CFR73 & 10CFR10 would seem more appropriate MCGANN, J D NUMANCO 47FR33980 004 82/09/17. Docketing & Services Branch. 19. 14673 003
- B20B300274 Pactage of two comments opposing proposed rule 10CFR50 re fitness for duty of personnel w/unescorted access to protected areas. JACOX.J W Nuclear Consulting Bervices, Inc HANSON, M B, International Brotherhood of Electrical Workers. 47FR33980, B2/0B/23 pocketing & Services Branch App. 14673, 005
- 8208300277 Comments on proposed rule 10CFR50 re LER sys. Mandatory imposition by universal sys not recommended. RAHELE P. Westinghouse Electric Corp. 47FR19543 048. B2/08/05 CHILK.6 J. Office of the Secretary of the Commission 2pp.
- B20B30027B Comments on proposed rule 10CFR30 re fitness for duty of personnel w/access to protected areas Employee ed program should be instituted for drug/alcohol regulations SCMILLER, V Affiliation Unknown 47FR33980 007 82/06/24 Docketing & Services Branch ip. 14673 004
- 8208310331 Package of two comments supporting proposed rule 100FR50 raphysical fitness for nuclear plant workers ORUPE,C, MEALVE,D Affiliation Unknown 47FR33980 82/08/27 Docketing & Barvices Branch. 2pp. 14693,211

PRM PETITION FOR RULEMAKING

- 8208030522 Package of two comments on petition for rulemaking PRM-50-32 re electromagnetic pulse in nuclear power plants LEWIS.M.I. Affiliation Unknown. 47FR27371 82/07/26 Docketing & Services Branch 5p. 14163:008.
- 8208030352 Comments on petition for rulemaking PRM-50-32 providing electromagnetic pulse-hardening circuitry in all atomic power plants, Supports petition NEMETHY.E Affiliation Unknown 47FR27371 004, 82/07/26, Docketing & Bervices Branch 1p 14162.264
- 1208030556 Comments on petition for rulemaking PRM-50-33 re emergancy plan Opposes patition COLEMAN H I Ilinois, State of 47FR29252 002 62/07/22 Doctating & Services Branch 2pp 14162,262
- 1208030565 Comments on petition for rulemaking PRM-50-33 re emergency plan HOHES, D.R. Kentucky, State of. \$47FR29252 003 82/07/26 CHILK; 8 J. Office of the Secretary of the Commission. 2pp. 14140 103
- 820B1001B3 Comments on petition for rulemaking PRM-50-32 re electromagnetic pulse effects upon safety of nuclear reactors LEWIB.M I Lewis, H 47FR27371 005. 82/08/05. Commissioners. 2pp 14298 216.
- 8208100195 Comments on petition for rulemaking PRM-50-32 re electromagnetic pulse effects upon safety of nuclear reactors. Opposes petition. 80UCHEV. 9.D Washington Public Power Supply System. 47FR27371 006 82/08/03 Docksting & Services Branch 2pp 14298: 208
- 8208180037 Comments on petition for rulemaking PRM-50-33 re frequency of emergency exercises. Opposes petition.
 TEMPLEJ Grundy County, IL. AFRR97852 004 82/08/11. Docketing & Services Branch. 2pp 14378-138.
- 8208300168 Comments on petition for rulemaking PRM-50-32 re electromagnetic pulse Requests CL proceeding for Perry be suspended until petition resolved. KLINE,C. Affilation Unknown. 47FR27371 008. 82/08/12 Docketing & Bervices Branch. ip 14599:243.
- 8208300170 Package of two comments on petition for rulemaking PRM-50-32 rs design protection against electromagnetic pulse, Add1 month to prepare comments requested MARSHALL, M.H. Mapleton Intervenors, Environmental Protection Associates 47FR27371, 82/08/23 Docksting & Services Branch 2pp, 14595-352.

- 8208300183 Package of two comments opposing petition for rulemaking PRM-50-32 re effects of electromagnetic pulsa GEBLER.C W Wisconsin Public Bervice Corp * Dehevoise & Liberman 47FR27371 82/08/25 Office of the Secretary of the Commission 4pp 14595 359
- 8208300198 Comments on petition for rulemaking PRM-50-32 re electromagnetic pulse Design criteria & NRC policy re nuclear attacks should be addressed BALDARINI, J G Ebesco Services, Inc (subs of Enserch Corp) 47FR27371 009 82/08/12 Docketing & Bervices Branch 1p 14996 054
- 8208300201 Comments on petition for rulemaking PRM-30-32 redesign protection against electromagnetic pulse Opposes petition SCHERER, A E Combustion Engineering, Inc. 47FR27371 010, 82/09/20 Office of the Secretary of the Commission 2pp 14678 237
- 8208300205 Notifies that comments on petition for rulemaking PRM-50-32 re design against electromagnetic pulse will be submitted after supiration date, but no later than 820830 HILLMORE,R L. Shaw, Pittman, Potts & Trombridge 47FR27371 82/08/19 CHILK, B J Office of the Secretary of the Commission in 14394 055
- 8208300207 Comments on petition for rulemaking PRM-50-32 re design against electromagnetic pulse, Electromagnetic pulse inappropriate for consideration in licensing of nuclear plants Defense activities should be handled by DOD. BHERNDOD. 0 9 Ceneral Electric Co 47FR27371 015 82/08/23, Docketing & Services Branch. 2pp 14678, 246,
- 8208300216 Comments on petition for rulemaking PRM-50-33 re emergency preparedness exercises Opposes rule Present emergency planning levels should be maintained or increased NRC should focus on devising alternative financial strategies READ, D. F. North Carolina, Univ of 47FR29252 005 82/08/20. Docketing & Bervices Branch ip. 14679 043
- 8208300256 Comments on petition for rulemaking PRM-50-33 re emergency preparedness exercises Frequency of full-scale participation in emergency exercises should not be reduced to once every 2 yrs
 SHEALY:H 9 South Carolina, State of 47FR29252 006 82/08/23 Docteting & Services Branch 2pp 14679 063
- 8208300316 Package of two comments supporting petition for rulemaking PRM-80-32 re design against electromagnetic pulse REED, D. F. PARKER, R. D. Environmental Law Project 47FR27371 82/08/23. CMILK, B. J. Office of the Secretary of the Commission 2pp 14599 325
- 8208310248 Comments on patition for rulemaking PRM-50-32 rs design protection against electromagnetic pulsas Opposes patition.
 8HIELDB.S W Public Service Co of Indiana, Inc. 47FR27371 016 82/08/23, CHILK, B J Office of the Secretary of the Commission.
 5pp 14688 186

PROJ PROJECTS - PREDDCKET LICENSING

- 8208040276 Notifies of acceptability of proposed scheduling of hearing for 820921-22 in San Francisco, CA. Formal notice to be issued at beginning of 88pt
 HAROULIES, H B. Atomic Safety and Licensing Board Panel. ISSUANCES
 A 82/08/02. BTRUMWASSER, M California, State of 19 14183-070.
- B208160057 Order CLI-B5-5 referring matter of PO&E B10918 notice of greaturity & advice of withdrawal back to ASLB for further consideration. Util may unilaterally withdraw from proceeding.

 CHILK: 8 J Office of the Secretary of the Commission CLI-B2-O5. B2/03/17 Spp. 14344 278.
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8208050268 Part 2: rept re defect in installation of HFA relays in control room panels. Affected plants will be informed of defect & corrective actions required SHERHOUD, 0 0. General Electric Co MFN 101-82. 82/07/28. DEYOUNG.R.C Director's Office, Office of Inspection and Enforcement 4pp. 14210 116
- 8208090100 Part 21 rept re corrodable carbon steel lockpins in 10-inch WKM control valves used as decay heat removal/low pressure injection cooler outlet valves Carbon steel pins replaced wistainless steel pins List of affected facilities encl. TAYLOR, J. H. Babcock & Wilcox Co. 82/07/30. DEYQUNG, R.C. Office of International Programs, Director. 3pp. 14269-244.

- 2208100020 Part 21 rept re potential defect in starting air check valve of DSRV standby diesel generator Supplier preparing schedule for valve mod Notification of affected sites projected for 820724
 BOYER.R E Transamerica Delaval. Inc 82/07/28 Director's Office, Office of Inspection and Enforcement 1p 14296 324
- B20Bli0177 Part 21 rept re cracked keyway slot in T-3 yoke Initially reported on 820607 by MI Power & Light New yoke mods will be sent to util LOCABCIO.A T GH Bettis Carp PT21 82-637-000 B2/06/15 DEYOUNO.R C Director's Office. Office of Inspection and Enforcement 3pp 14314 173
- 8208200051 Part 21 rept re sheared pinion keys in Limitorque motor operators which could result in failure of motor operated valves to perform safely All utils should review IE Info Notice 81-08 re sheared pinion keys for guidance RAHE, E P Westinghouse Electric Corp NS-EPR-2637 82/08/06 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 14392 229

GA999 GUALITY ASSURANCE INSPECTIONS

- 820&i50008 Add1 response to FOIA request for seven catagories of documents re Hauward Tuler Pump Co Tenth document contains investigatory records for law enforcement purposes & is withheld (ref FOIA Exemption 7) Listed documents enci FECTON, J H Division of Rules and Records 82/05/14 LIEBOLD, W C. Affiliation Unknown p 14178 035
- --8205150017 "Hayward Tyler Pump Co Insp & Investigation Status Bummary "
 * NRC No Detailed Affiliation Given 82/02/18 App
 14178-037
- --8205150020 Forwards GA Program Investigation Rept 97900345/82-01 on 820104-29, Supporting documentation encl
 SEYFRITIK V. Region 4. Office of Director 82/02/19 FORTUNA, R
 Division of Fuel Facilities, Materials & Safeguards ip 14:878 043
- --8206150021 Forwards GA Program Investigation Rept 97900345/82-01 on B20104-27 Noncompliance noted SEYFRIT.K V Region 4. Office of Director 82/02/19 Hayward Fyler Fump Co 2pp 14178 044
- --B206150024 QA Program Investigation Rept 99900345/82-01 on 820104-29
 No noncompliance noted Major areas inspected allegations re
 Hayward Tyler Pump upper my failure to support & enforce QA
 program Personnel removed documents from main ofc
 HERR.F. K. DRISKILL.D D. F. ELLERSHAW.L. E. Division of Vendor &
 Technical Programs 82/02/18 11pp 14178 046
- --8204150027 Forwards QA Program Investigation Rept 79700345/82-02 on 820123-29 & notice of nonconformance CRLLINS, J T. Region 4, Office of Director 82/02/19 LYQNB, B P. Hayward Tyler Pump Co 3pp 14178 077
- --8206150031 Notice of nonconformance from insp on 820125-29.

 * Director's Office. Office of Inspection and Enforcement 82/05/14 8pp 14178 080
- --8206550035 QA Program Investigation Rept 97900345/82-02 on 820125-29.
 Noncompliance noted current & past training schedules not consistent w/training requirements identified in Exhibit I of Engineering Std 9 O 5/1-1
 ELLERSHAWL E , BARNES I Division of Vendor & Technical Programs, 82/02/16 13pp 14178 Q88.
- --B2GB020015 Sanitized notification that investigation & insp repts were provided to licensee representatives on 820212 for proprietary review Final rept will be provided upon receipt DIRCKS.W J Office of the Executive Director for Operations B2/03/05 PALLADING.N Commissioners. 1p 14178:148
- 8208020075 Ack receipt of 820625 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 9990017/82-01.
 POTAFOVS.U. Division of Vendor & Technical Programs 82/07/28 ANDERSON. K. Dravo Corp. ip 14144 077
- --B20B020099 Responds to NRC 820526 ltr re-nonconformance noted in GA Program Insp Rept 97900017/82-01 Corrective actions shop foremen instructed to fill out weld-joint data cards correctly & nonconformence repts to be reviewed monthly, MOLVIE: W.A. Dravo Corp. 82/06/25 POTAPOVS.U. Division of Vendor & Tachnical Programs. App. 14144,078.

- 8208020125 Ack receipt of 820219,0601 & 04 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp. Rept 99900760/82-01
 POTAPSUE, U Division of Vendor & Technical Programs 82/07/28
 LANOHAM, T Stewart & Stevenson Services 1p 14142 041
- --B208020128 Responds to NRC 82011B & 0505 ltrs re nonconformance noted in GA Program Insp Rept 99900760/82-01 Corrective actions GCs 014 & 010.Revisions C revised & distributed as Revision D & quality vendor list revised

 LANGHAM.T Stewart & Stevenson Bervices 82/04/04 POTAPOVS.U Division of Vendor & Technical Programs 16pp. 14142 042
- --B208020133 Requests extension to complete response to NRC 820506 ltr re nonconformance noted in GA Program Inep Rept 99900760/82-01 Response will be completed by 820608, LANVHAM, T Stewart & Stevenson Services B2/06/04 POTAPOVS, U. Division of Vendor & Technical Programs ip 14142 058
- --8208020136 Ack receipt of 820219 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900760/82-01 Add info required POTAPOV8.U Bivision of Vendor & Technical Programs 82/05/06 LANOHAM.T Stewart & Stevenson Services 2pp 14142 037
- --8208020137 Responds to NRC 820118 ltr re nonconformance noted in GA Program Insg Rept 97900760/82-01 Corrective actions Section 201 of Energy Reorganization Act posted & verification of audit check list for internal audits instituted.

 LANCHAM.T Beawart & Stevenson Services 82/02/17 PDTAPOVB, U. Division of Vendor & Technical Programs 3pp 14142:061
- B208030445 Forwards QA Program Insp Rept 99900519/B2-Q2 on 820517-21 & notice of nonconformance POTAPDVB.U Division of Vendor & Technical Programs 82/07/06. KOMER.J H Bechtel Corp 3pg 14155-303
- --8208030447 Notice of nonconformance from inep on 820517-21 * Division of Vendor & Technical Prog ems 82/07/06 2pp. 14155:306
- --E208030452 GA Program Insp Rept 99900519/82-02 on 820517-21
 Noncompliance noted failure to follow procedures re
 signature identification card completion & failure to
 incorporate drawing change notices within required time.
 COSTELLO.J R. HALE.C J Division of Vendor & Technical Programs,
 82/06/27 lipp 14155 308
- 8208030172 Ack receipt of 820709 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900309/82-01 POTAPUS.U Division of Vendor & Technical Programs, 82/08/02. KELLY.R B Stone & Webster Engineering Corp 1p 14212-071.
- --8208030176 Responds to NRC 820610 ltr re nonconformance noted in GA Program Insp Rept 99700509/82-01 Corrective actions parsonnel reminded that fellure to meet commitment w/o adequate justification warrants close mgs attention, KELLY,R B Stone & Webster Engineering Corp. 82/07/09, POTAPDVS,U, Division of Vendor & Technical Programs Spp 14212-072
- 8208050192 Ack receipt of 820707 1tr informing NRC of steps taken to correct monconformance noted in GA Program Insp Rept 99700217/82-01 POTAPUS.U Division of Vendor & Technical Programs 82/08/02 REING, J.F. Westinghouse Electric Corp 1p 14212.146
- --8208050200 Responds to NRC 820419-22 ltrs re-nonconformance noted in GA Program Insp Rept 99900217/82-01. Corrective actions GA procedure 10.3 written re-qualification of wrap process & personnel. Internal audit of special processes performed HEING, J.F., LEE, R.W., Westinghouse Elsctric Corp. 82/07/07 TILLOU, J.H. Division of Vendor & Technical Programs 4pp. 14212:147
- 8208160189 Forwards QA Program Insp Rept 99700403/82-02 on 820607-11 & notice of nonconformance. POTAPOVS.U Division of Vendor & Technical Programs. 82/07/29. BRUSCHAN, W. H. General Electric Co 2pp. 14342-300
- --8208160195 Notice of nonconformance from insp on 820607-11 # Division of Vendor & Technical Programs. 82/07/29, 2pp 14942 302
- --8208160200 GA Program Insp Rept 99700403/82-02 on 820607-11.

 Noncompliance noted fuel pool HX drawing approved w/HX relief valve setpoint pressure 10% too low

 CHAMBERCAIN.D: HARRELL,P H., HALE,C, J. Division of Vendor & Technical Programs 82/07/23. 20pp 14342:304.

- 8208160217 Forwards QA Program Insp Rept 99900077/82-01 on 820614-18 No noncompliance noted PUTAPOUS, U Division of Vendor & Technical Programs 82/07/29 OMEN.H W Pullman. Inc 2pp. 14346 324.
- --8208160227 QA Program Insp Rept 99900077/82-01 on 820614-18 No noncompliance noted Hajor areas inspected:mfg process control, welding matl control, weld on procedure; spect, joint fitup & nondestructive exam personnel qualification ROBERDS,H W. BARNES,I Region 4. Office of Director 82/07/22 App 14346.326
- 8208160295 Forwards QA Program Insp Rept 99900302/82-01 on 820517-21 & notice of nonconformance POTAPOVS, U Division of Vendor & Technical Programs 82/07/28 FRIEDMAN, K A Mestern Piping & Engineering Co., Inc. 2pp
- --B208160299 Notice of nonconformance from insp un B20517-21

 Division of Vendor & Technical Programs B2/07/28 1
 14345 264
- --8208160304 GA Program Insp Rept 99900302/82-01 on 820517-21
 Noncompliance noted failure to enter measuring instruments
 into insp usage log prior to use by GC inspector for final
 acceptable insp.
 SUTTON.J H , BARNES, I Region 4, Office of Director 82/07/28
 6pp 14345-265
- 8208160359 Forwards QA Program Insp Rept 99900751/82-01 on 820601-03 No noncompliance noted POTAPOVB.U Division of Vendor & Technical Programs 82/07/29 LOUTHAN,F 0 Richmond Engineering Co., Inc. 2pp 14349:100
- --8208160372 QA Program Insp Rept 99900751/82-01 on 820601-03 No noncompliance noted Major areas inspected quality of radiographs of welds for refueling water storage tanks, per 10CFR50.55(e) rept ROBERTS, H. W., BARNEG, I Division of Vendor & Technical Programs 82/07/13 5pp 14349 102.
- B208160385 Forwards GA Program Insp Rept 99900521/82-02 on B20607-11 & notice of nonconformance POTAF0VS,U Division of Vendor & Technical Programs, B2/07/28. MORQH6KI,J V Bechtel Corp, 2pp 14349 112
- --820816039; Notice of nunconformance from insp on 820607-11 * Division of Vendor & Technical Programs. 82/07/28, ig 14349 114.
- --B208140404 QA Program Insp Rept 99900521/82-02 on B20407-11
 Noncompliance noted five deficiency evaluation repts did not
 comply w/procedural requirement that initiator sign & date
 repts
 CD8TELLO.J R , HALE, C J Division of Vendor & Technical Programs,
 82/07/15 11pp. 14349 115.
- '08160403 Forwards QA Program Insp Rept 99900326/82-01 on 820614-17. No noncompilance noted.
 POTAPONS.U. Division of Vendor & Technical Programs. 82/07/29.
 C'BRIEN.D.O. D.O. O'Brien. Inc. 2pp. 14349 153
- -8208i604i3 GA Program Insp Rept 99900326/82-01 on 820614-17. No noncompliance noted Major areas inspected change control, equipment calibr, procurement document control & procurement source selection OLLER, R. E. Division of Yendor & Technical Programs BARNES, Division of Resident, Reactor Project & Engineering Programs 82/07/23 10pp 14348-155
- 3208170177 Ack receipt of 820609 ltr re GA Program Insp Rapt 97900745/82-01.Ltr (GA-3233) is accurate statement PGTAP0V8.U Division of Vandor & Technical Programs 82/08/12. MOSER, O. M. Allied Chemical Corp 1p 14364.331.
- -8208170184 Responds to NRC 820512 ltr & subsequent telcon re GA Program Insp Rept 99900765/82-01 No add1 actions required Corrective action should be verified during future insp. 8RANGA.0, C. Allied Chemical Corp. 82/06/09. POTAPOVS, U. Division of Vendor & Technical Programs 19, 14364.332
- 1208170202 Ack receipt of 820611 & 0729 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Inap Rept 97900514/82-01.
 POTAPOV6.U. Division of Vendor & Technical Programs. 82/08/12.
 BDTTB, W V Energy Incorporated. ip. 14362:026

- --8208170207 Responds to NRC 820526 & 0707 ltrs re nonconformence noted in GA Program Insp Rept 99900514/82-01 Corrective actions change order issued notifying vendor that procurement is safety-related & that 10CFR 21 applies
 LATIN.H L Energy Incorporated C-240-82 82/07/29 POTAPDVB.U. Division of Vendor & Technical Programs 2pp 14362 027
- --820B170210 Ack receipt of 820611 ltr informing NRC of steps taken to correct nonconformance noted in GA Frogram Insp Rept 99900514/82-01 Add1 info requested POTAPOVB.U Division of Vendor & Technical Programs 82/07/OS BDITS.H V Energy Incorporated 1p 14362 027
- --BROBITO213 Responds to NRC 820826 ltr re nonconformance noted in GA Program Insp Rept 97900514/82-01 Corrective actions purchase order form redesigned & will include statement re applicability of iOCFR21 LATIN.H L Energy Incorporated C-165-82 82/06/11 POTAPOVE.U Division of Vendor & Technical Programs 3pp 14362-030
- B20B190100 Forwards QA Program Insp Rept 99900514/B2-01 on B20524-28 & notice of nonconformance POTAPDVB.U Division of Vendor & Technical Programs B2/07/14. QALLAOHER.W J NUS Corp 2pp 14383 146
- --B208190107 GA Program Insp Rept 99700516/B2-01 on 820524-28 Nonconformance noted GA personnel & operations manager in Gaithersburg, MD failed to receive copies of controlled documents, including GA plan CHAMBERLAIN.D., CONNAY.J., HALE.C. J. Division of Vendor & Technical Programs 82/07/02 14pp 14383-150
- B20B190202 Forwards QA Program Insp Rept 99900063/82-01 on 820420-22 & notice of homconformance POTAPOVB, U Division of Vendor & Technical Programs 82/08/02, MOYER D J Pacific Fumpe Div 2pp 14387 053.
- --8208170206 Notice of nonconformance from insp on 820420-22.

 * Region 4, Office of Director 92/08/02 ip 14387 055.
- --B20Bi90209 QA Program Insp Rept 77900063/B2-01 on 820420-22
 Noncompliance noted intermediate cover castings w/visible
 linear indications in excess of 1/16 inch accepted by
 receiving insp.processed & furnished to util
 ELLEMBHAH, L E , BARNES, I Region 4, Office of Director B2/07/22
 Spp 14387 Q56
- B20B190203 Forwards GA Program Insp Rept 99900521/82-03 on 820621-25 & notice of honconformance POTAP0VG.U Division of Vendor & Technical Programs B2/08/02 MORDWBKI, J V Bechtel Corp 2pp 14387 061
- --B208190207 Notice of nonconformance from insp on 820621-25 * Region 4, Office of Director 82/08/02 ip 14387.063
- --B208190214 GA Program Insp Rept 99900521/B2-03 on B20621-25.
 Noncompliance noted monthly audit activity rept not distributed to div GA or project mpt & quality element checklist not signed & dated by lead auditor.
 GCBTELLO.J R., HALE.C J Division of Vendor & Technical Programs 82/07/29 9pp. 14387-064
- 8208190249 Forwards GA Program Insp Rept 99900712/82-01 on 820620-24 & notice of nonconformance POTAPOVG,U. Division of Vendor & Technical Programs. 82/08/06. CAPRALLA Systems Control, Inc. 2pp 14387,329
- --8208170266 Natics of nonconformance from insp on 820620-24, * Region 4, Office of Director, 82/08/06 2pp 14387 331.
- --BROBIFOZZE GA Program Insp Rept 99900712/B2-01 on B20620-24
 Noncompliance noted failure of GC dept to notify project
 engineer of nonconforming conditions & failure to prepare
 documented instructions addressing control of drawings.
 BUTTON, J W. BARNEB, I Region A. Office of Director. B2/08/03,
 5pp. 14387.333.
- 8208190250 Forwards GA Program Insp Rept 99900503/82-02 on 820607-11 & natice of nonconformance POTAPOVS, U Division of Vendor & Technical Programs. 82/08/06, HENDRICKBON, T Burns & Ros Co 2pp 14388:174.
- ---8208190258 Notice of nonconformance from insp on 820607-11 * Region 4, Office of Director. 82/08/06, 4pp. 14388-174

- --8208190272 GA Program Insp Rept 99900503/82-02 on 820607-11
 Honcompliance noted document control program not effectively
 governed by procedure contained in componate operations
 manual & computer program index not prepared as required
 FOX.D F., HALE.C J Division of Vendor & Technical Programs
 82/07/29 App 14388 180 4рр
- 8208190255 Forwards QA Program Insp Rept 99900768/B2-01 on B20129 & O216-18 & notice of violation POTAPOVS.U Division of Vendor & Technical Programs 92/08/06 KCH.8 Hittman Nuclear & Development Corp (subs Hittman Corp) 2pp 14387-302
- --8208190262 Notice of violation from insp on 820127 & 0216-18 * Region 4, Office of Director. 82/08/04 2pp 14387 304.
- 820B190260 Ack receipt of 820B02 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900316/82-01.
 PDTAPOVS.U. Division of Vendor & Technical Programs. 82/08/16 OALLAGHER.W J NUS Corp 1p. 14387 073.
- --8208190271 Responds to NRC 820714 ltr re nonconformance noted in GA Program Insp Rept 99900514/82-01 Corrective actions forms used for transmittal of controlled documents records & receipt logs reviewed & personnel data placed in GA files GALLACHER.W.J. NUS Corp. 82/08/02. POTAPOVS.U Division of Vendor & Technical Programs 4pp. 14387:074
- 8208190281 Forwards GA Program Insp Rept 99900774/82-01 on 820517-21 & notices of nonconformance & violation POTAPOVG/U Division of Vendor & Technical Programs 82/08/06 HEIDELMAIER,J Airco, Inc. 2pp 14387 092
- --B20B1902B4 Notice of violation from insp on B20517-21, * Division of Vendor & Technical Programs B2/08/06 ip 14387.094
- --8208190291 Notice of nonconformance from insp on 820517-21 Bivision of Vandor & Technical Programs. 82/08/06, 414387.095.
- --B20B190295 GA Program Insp Rept 99900774/82-01 on 820517-21 ROBIO273 GA Program Insp Rept 979007492-01 on B20017-21 Moncompliance noted required documentation for procedures not available to provide for evaluation of deviations or for notification of uncorrected deviations CONIANY. J. BARNES, I Division of Vendor & Technical Programs. B2/08/04. 10pp. 14387 099
- B208190282 Forwards GA Program Insp Rept 99900400/82-02 on 820517-21 & notice of nonconformance PCIAPDV8.U Division of Vendor & Technical Programs 62/07/14 QUILBERT, DE Babcock & Wilcox Co 2pp 14387-078
- 14387-080
- --- 8208190289 GA Program Insp Rept 99900400/82-02 on 820517-21. Noncompliance noted nuclear steam core project manager did not originate fuel cycle design requirements & failed to completely fill out CDS form. FOX.D.F., HALE.C J Division of Vendor & Technical Programs 82/07/02 10pp. 14387,083
- B20B190299 Ack receipt of B20722 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900342/82-01, PCTAPOUS,U Division of Vendor & Technical Programs B2/08/16 JONAS.W E. Lakeside Bridge & Steel Co. 1p 14500 G74
- --8208190303 Responds to NRC 820630 ltr re nonconformance noted in GA Program Insp Rept 99700342/82-01. Corrective actions: personnel instructed in proper use of mfg process sheet Sheets will receive final documentation check.

 JANS.D. Lakeside Sridge & Steel Co. 1271. 82/07/22, POTAFOVE,U, Division of Vendor & Technical Programs ip 14500:075.
- 8208200055 Forwards GA Program Insp Rept 99900713/82-01 on 820518-20 No noncompliance noted. PDTAPOVS.U. Division of Vendor & Technical Programs. 82/07/19. ECKERT.D. York Electro-Panel Conrol Co., Inc. 2pp 14373:004.

- --8208200064 GA Program Insp Rept 99900713/82-01 on 820518-20 No noncompliance noted Hajor areas inspected mfg process control, internal audits, nonconformances & corrective action & reporting of defects
 OLLER, R E , BARNES, 1 Region 4, Office of Director 82/07/14.
- 8208240211 Ack receipt of 820804 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept POTAPOVB.U Division of Vendor & Technical Programs 82/08/16.
 KOMES, J. M. Bechtel Corp. 1p. 14519 160.
- --B20B240217 Responds to NRC B20706 ltr re nonconformance noted in GA Program Insp Rept 99900519/82-02. Corrective actions: Engineering Design Procedure 7 5 issued on B2062B, removing longhand requirement on signature cards.

 KONEB, J M Bechtel Corp GAS-B2/245 B2/08/04 PGTAPDVB, U Division of Vandor & Technical Programs. App. 14519 161
- B20B310116 Forwards GA Program Insp Rept 99900404/82-01 on 820621~25 & notice of nonconformance POTAPUS,U. Division of Vendor & Technical Programs B2/08/11 BLEMBER.R J Westinghouse Electric Corp 2pp. 14690 065
- --B208310121 Notice of nonconformance from insp on B20621-25
 * Division of Vendor & Technical Programs 82/08/11
- --8208310127 GA Program Insp Rept 99900404/B2-01 on 820621-25
 Noncompliance noted formal evaluation not conducted every
 yr & Anchor Darling not audited every 3 yrs to maintain
 company as qualified supplier
 BRICKLEY, R. H., HALE, C. J. Division of Vandor & Technical Programs
 82/08/10 12pp 14690 068.
- 8208310119 Forwards GA Program Insp Rept 99900339/82-01 on 820628-0702. PDTAPQVB,U. Division of Vendor & Technical Programs. B2/08/16. HAGSTROM,R W General Electric Co 2pp 14690 049
- --82083]0124 GA Program Insp Rept 99900339/B2-01 on 620628-0702. Major areas inspected, status of previous insp findings, info process control, internal audits, nonconformances & corrective action & iOCFR21.

 OLLER, R E., BARNES, I Division of Vendor & Technical Programs 82/08/10. 14pp 14690 051.
- 8208310128 Forwards QA Program Insp Rept 99900033/82-01 on 620607-11 & notice of nonconformance POTAPOVS,U. Division of Vendor & Technical Programs 82/08/10 BAKES, P R. Westinghouss Electric Corp. 2pp 14690.080
- --B20B310139 GA Program insp Rept 99900033/B2-01 on 820607-11
 Noncompliance noted reactor coolant pump diffuser adaptor
 cap screw failures at Robinson Unit 2 were reported
 but not documented on Form AEGA-1460
 MCNEILL, W M., BARNESI. Division of Vendor & Technical Programs,
 B2/07/30. Bpp. 14690 083
- 8208310133 Forwards QA Program Insp Rept 99900777/82-01 on 820412-15. No noncompliance noted POTAPOVB.U. Division of Vendor & Technical Programs. B2/08/11. NILBON.E. Bergan-Patterson Pipe Support Corp. 3pp. 14670:101.
- --820831013B GA Program Insp Rept 99900777/82-01 on 820412-15. No 20831013B OA Program Insp Rept 797007/7/82-01 ON 820412-15. No noncompliance noted Major areas inspected LAPL rept that stress analysis not performed prior to fabrication of pipssupports furnished to Waterford KELLEY. W.D., BARNEB.I Division of Vendor & Technical Programs. 82/07/23 12pp. 14690.104.
- 8208310237 Forwards GA Program Insp Rept 99900776/82-01 on 820517-19 & notice of monconformence.

 POTAPOVS.U. Division of Vendor & Technical Programs. 8

 JOHNSON.B. Chem-Nuclear Systems, Inc. 2pp. 14695.086.
- --8208310240 Notice of nonconformance from inep on 820517-19 * Division of Vendor & Technical Programs. 82/08/10 ip. 14695:088.
- --8208310246 GA Program Insp Rept 99900776/82-01 on 820517-19.
 Noncompliance noted failure to document nonconforming conditions on Vandenburgh model casks.
 HCMEILLW M. BARNES, I. Region 4. Office of Director, 82/07/30.
 7pp. 14695.089.

- 8208310272 Forwards QA Program Insp Rept 99700779/82-01 on 820621-25 & notices of violation & nonconformance PDTAPQV8,U Division of Vendor & Technical Programs 82/08/11 HANNER,R Nuthern International, Inc. 2pp 14688 247
- --8208310275 Notice of violation from insp on 820621-25 * Division of Vendor & Technical Programs 82/08/11 is (4888-249
- --B208310277 Notice of nanconformance from insp on 820421-25

 Division of Vendor & Technical Programs B2/08/11 3pp 14688 250
- --B20B310280 GA Program Insp Rept 99900779/82-01 on 820621-25
 Noncompliance noted 10CFR21. Section 206 of Energy
 Reorganization Act of 1974 & adopted procedures/appropriate
 notice not posted
 FUSTER. N E . BARNES, J Region 4. Office of Director B2/07/30
 10pp 1448B 253
- 8208310307 Forwards OA Program Insp Rept 99900396/82-01 on 820712-16 & notice of nonconformance POTAPOVS.U Division of Vendor & Technical Programs 82/08/16 SESHAGRI.M CLOW Corp 2pp 14694 314
- --8208310314 Notice of nonconformance from insp on 820712-16 • Division of Vendor & Technical Programs 82/08/16 is 14694 316.
- --B20B310321 DA Program Insp Rept 99700396/82-01 on B20712-16
 Nancompliance noted use of measuring instruments in shop
 machining operations which exceeded callibr dates
 SUTION, J W. BARNES, I Division of Vendor & Tachnical Programs
 82/08/10 6pp 14694 317
- 82083;0337 Forwards GA Program Insp Rept 99700907/82-01 on 820607-10 No noncompliance noted POTAFUGU.U. Division of Vendor & Technical Programs, 82/08/11 EDELSTEIN:A National Testing Systems 2pp 14692 100
- --B20B310341 GA Program Insp Rept 97900907/B2-01 on 820607-10 No noncompliance noted Major areas inspected GA program, test procedure & related thermal analysis for qualification testing of Borg-Marner valve actuator & test facilities AGES.J.R. PHILLIPS.H.S. Region 4. Office of Director B2/08/03 3pp. 14692 102
- 820831034B Ack receipt of 820701 & OB11 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp. Rept 97900310782-02 POYAFOVS, U Division of Vendor & Technical Programs. 82/08/25 CURNANE, R. A United Engineers & Constructors, Inc. (subs. of Raytheon Co.) ip. 14693-246
- --B20B310354 Bupple 820701 response to 82040B ltr re nonconformance noted in GA Program Insp Rept 95900510/B2-02 Corrective actions backfitting accomplished on minor engineering change authorizations.

 CURNANE,R A, United Engineers & Constructors, Inc (subs of Raytheon Co.) B2/08/11 PGTAPUS,U Division of Vendor & Technical Programs 2pp 14693 247.
- --8208910361 Ack receipt of 820701 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900510/82-02 Add1 info re minor engineering change authorizations requested per 820712 telcon PDTAPOV8.U Division of Vendor & Technical Programs 82/08/02 CURNANE, R A United Engineers & Constructors, Inc (subs of Raytheon Co.) 2pp. 14673,247
- ---820B310367 Responds to NRC 82060B Itr re-monconformance noted in GA Program Insp Rept 99900510/02-02 Corrective actions Engineering Change Authorisation 741645B to Administrative Procedure 15, Revision 14, issued 820607 CURNANE, R A United Engineers & Constructors, Inc (subs of Raytheon Co.), B2/07/01 P078P0VB.U Division of Vendor & Technical Programs. 4pp 14493 251
- 3208310392 Forwards QA Program Insp Rept 97900289/82-02 on B20415-16. No noncompliance noted POTAPDVS, U Division of Vendor & Technical Programs 82/08/10. RUTKQWSKI.R.J Borg-Warner Corp 2pp 14493 258
 - 208310401 GA Program Insp Rept 99900289/82-02 on B20415-16 No noncompliance noted Major areas inspected verification that qualification testing of Borg-Harner valve actuator is proceeding in compliance w/NUREG-0588, Revision 1.

 10EE.J R., PHILLIPS, H B Division of Vender & Technical Programs 2/07/21 5pp 14493 240,

- 820B310449 Forwards GA Program Insp Rept 99900052/82-01 on 820308-12 No noncompliance noted POTAPOVB.U Division of Vendor & Technical Programs 82/08/10 TEPLOW.R Crosby Valve & Gage Co 2pp 14690 156
- --B20B310454 GA Program Insp Rept 99900052/02-01 on B2030B-12 No noncompliance noted, Najor areas inspected capability of safety relief valve to demonstrate compliance w/IEEE-323-1974 environ qualification test requirements KELLEY, W D . BARNES, I Division of Vendor & Technical Programs B2/08/04 10pp 14690 158

REGOD REGULATORY GUIDES

- 8207020007 Addl response to FDIA request for eight categories of documents Forwards documents listed in App A Documents listed in App B completely withheld advice opinions & recommendations (ref FDIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/05/28 MCMURHAY, C N Kirkpatrick, Lockhart, Hill, Christopher & Phillips 8pp 13697, 125 24X Fiche 30-000, 82/05/28, 8207020007
- 8208030491 Comments on draft Reg Guido OP 722-4, "Gualifications for Radiation Safety Officer in Large-Scale Non-Fuel-Cycle Radianuclide Program" POTTER, J Affiliation Unknown 82/04/14 BELL, J M Office of Nuclear Regulatory Research, Director 2pp 14163 316
- 8208030533 Package of two comments on draft Reg Guide DP 722-4,
 "Qualifications for Radiation Safety Officer in Large-Scale
 Non-Fuel-Cycle Radionuclide Program "
 GEIOLEIN JE Army, Dept of GILLIN M T Medical College of
 Hisconain 82/07/22 Docketing & Services Branch, 3pp
- 8208030537 Comments on draft Reg Guide OF 722-4, "Qualifications for Radiation Safety Officer in Large-Scale Non-Fuel-Cycle Radionuclide Program " Opposes guide TARAS, D N Army, Dept of 82/07/23 Docketing & Services Branch 3pp 14162 272
- 8208030544 Comments on Revision 4 to Reg Guide 8 8 Submits suggested changes
 LODDE, O M Affiliation Unknown 82/07/20 Office of the Becretary of the Commission 1p 14162 268
- 8208100247 Comments on second proposed Revision 4 to Reg Quide 8 B,
 "Info Re Ensuring That Occupational Radiation Exposures at
 Nuclear Power Stations Will be ALARA "Supports revision
 THORPES JR General Public Utilities GPU Service Corp 82/08/02
 CHILK, B J Office of the Secretary of the Commission 1p
- 8208100251 Comments on draft Reg Quide OP 722-4, "Qualifications for Radiation Safety Officer in Large-Scale Non-Fuel-Cycle Radionuclide Program " Supports reg guide OREENHOUSE,N A American Board of Health Physics 82/07/13 BELL-J M Office of Nuclear Regulatory Research, Director, ip 14295 356
- 820Bi00262 Requests comments on encl correspondence from constituents re Reg Quide 10 8 criteria & experience of physicians using radioactive matl
 BROWHILL, J T House of Rep 47FR3228 228 82/07/07 KAMMEREA, C Office of Congressional Affairs 5pp 14295 178
- 820Bi00311 Comments on draft Reg Guide TM 608-4, "Guide for Preparatio of Applications for Licenses in Médical Teletherapy Programs " Supports rule. MOREN.A E Wheeling Hosp Wheeling.WV 82/07/30 Docketing & Services Branch ip 14297 164
- 8208160253 Comments on Reg Guide 4 17, "Std Format & Content of Site Characterization Repts for High Level Waste Gaologic Repositories " ANSI N170-1976 revised & now designated as ANSI/ANS-2 8-1981 PICHA: K American Nuclear Society 82/08/04 Docketing & Services Branch 1p 14347 032
- B208160293 Comments on draft Reg Quide 10 8 re medical teletherapy programs. Calibr of dosimetry sys at 2-yr interval impractical due to lengthly waiting period for svcs CASTRO, V 0 Abington Memorial Hosp. Abington PA 82/08/06 Doctating & Bervices Branch 1p 14346.271
- 820B170160 Forwards comments on second proposed revision to Reg Guide 8.8 NRC should consider establishing different ALARA concepts for nuclear facilities under const & operating plants.

 OIBSONA F Division of Engineering & Technical Programs 82/08/10 STEPHENS, C R Docketing & Services Branch 3pp, 14364.315

- B2QB170175 Comments on draft Reg Quide OP 722-4, "Qualifications for Radiation Safety Officer in Large-Bcale Non-Fuel-Cycle Radionuclide Program " Requirements consistent w/unwritten Navy requirements & will serve useful purpose for Navy HENDRIX:0 N Navy, Dept of Navel Facilities Engineering Command. 52/08/09 Office of the Secretary of the Commission ip
- 9208170222 Package of two comments on second proposed Revision 4 to Reg Quide 8 8. "Info re Ensuring That Occupational Radiation Exposures at Nuclear Power Stations Will be ALARA " BELOEOROS.L O Commonwealth Edison Co GAPN.A L Bechtel Corp. 82/09/13 Docketing & Services Branch 3pp 14362 033
- B20B180042 Comments on second proposed Revision 4 to Reg Quide 8 B, "Info Relevant to Ensuring That Occupational Radiation Exposures at Nuclear Power Stations Will be ALARA." COOK, J W Consumers Power Co 82/OB/10 Dacketing & Services Branch 2pp 14378 275
- 8208240478 Errata to Reg Quide 3 51, "Calculational Models for Estimating Radiation Doses to Man From Airborne Radioactive Matl Resulting From Milling Operations " * Division of Fuel Quels & Material Safety. 82/08/04 ip
- B20B300231 Comments on draft Reg Quids IC 121-5 re response time testing of protection sys instrument channels.Compliance w/guide will result in increased manpower requirements & radiation exposures due to situ testing requirements HITHERS.B.D. Portland General Electric Co B2/QS/17 Docketing & Services Branch 2pp 14679 180
- 8208300247 Comments on proposed Revision 1 to Reg Quide 5 21.

 "Nondestructive U-235 Enrichment Assay by Qamma Ray
 Spectrometry"
 MALLETTO R General Electric Co 82/08/19 Bocketing & Services
 Branch 2pp 14679 065
- B20B300251 Comments on draft Revision 4 to Reg Ouide B.B, "Info Re Ensuring That Occupational Radiation Exposures at Nuclear Power Stations Will be ALARA " Supports guide ANDOMINI.0 C Arizona Public Service Co. 82/08/16. Backeting & Services Branch 2pp 14679 137
- 8208300260 Comments on proposed revision to Reg Quide 8 B reoccupational radiation overexposure Buggests that Procedure HTH-B0-0004 re underwater diving work associated w/ contaminated water be rewritten HOLLIS.J.L. Affiliation Unknown 82/08/19 Docketing & Services Branch 2pp 14678 355.
- 8208300266 Comments on draft Reg Guide OP 722-4 re qualification of radiation safety officer Required qualifications should be amended to recognize experience as well as ad. RIVKIN. W B Isotope Measurements Laboratories, Inc 82/08/17. Docketing & Bervices Branch ip 14599:362
- 8208300272 Comments on proposed revision to Rag Guide 5.53, "Qualification, Calibr & Error Estimation Methods for Nondestructive Assau" BINNHAM, C.D Energy, Dept of 82/08/18. Docketing & Services Branch 2pp. 14597 358
- B208310255 Comments on draft Revision 1 to Reg Guide 5.34 re nondestructive assay for Pu in scrap mat1 LEMMING.U.F Monsanto Co 82/08/25 Docketing & Services Branch. 3pp 14688, 167
- 8208310267 Comments on draft Reg Ouide TM 608-4. Requirements specifying dosimetry sys be calibr every 2 yrs should be relaxed to accommodate long time required to get instruments calibr by accredited labs.

 WRENN-P C Bt Joseph Hosp, Patterson, NJ. 82/08/23. Dacketing & Services Branch ip 14688: 159
- RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS
- 8207150485 "Analysis of Partial Scram Event in Typical BWR/4," informal rept
 LU, M S., BHIER, W. O., LEVINE, M. M. Brookhaven National Laboratory.
 FIN A-3350 BNL-NUREG-31417 82/01/31. HDDGES, M. W. Division of Bystems Integration (post 811005). 38pp. 14340:180
- B207200345 "Investigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities," ltr rept for May & June 1982, 81MAN-TOVM, Union Carbide Corp. FIN 8-0495-2 82/07/15. 8ERNSTEIN-8, Transportation & Materials Risk Branch Spp. 14237-214

- 8208020060 "Preliminary Assessment of Current Generic Nuclear Power Plant Instrumentation Sys for Use Under Accident Conditions." informal rept NiELSEN.J R. FLITTON.V.E., ROSE.J A E000, Inc. FIN A-6369 E00-EE-5845 82/05/28 FEIT,R Instrumentation & Control Branch. 38pp 14180 192
- 8208020061 "Computer Program to Calculate Thermodynamic Properties of Freon 11," internal technical rept HOHORBIJ K, RAUL, 8 Z EGKo, Inc. WR-CD-82-066 82/05/31. NRC No Detailed Affiliation Given 107pp. 14180 231
- 8208030045 "Matis Properties Models for Severe Core Damage Analysis," interim rept HAGRHAN, D. L. EG&O, Inc. FIN A-6050 EGG-CDD-5801 B2/05/31 HARRING, O P. Office of Nuclear Regulatory Research, Director 252pp 14194;001.
- 8208030048 "Operational Transient Test Scries.Test OPT 1-2, Experiment Operating Spec." informal rept MARTINSON, Z.R. E020, Inc. FIN A-6041 E0G-TFBP-5600. 82/05/31 BILBERBERG.M NRC No Detailed Affiliation Given 59pp 14242:001
- B20B030109 "Operational Transient Test Series.Test DPT 1-2," quick look rept. MARTINBON, Z.R., DBETEK, D.J., WHITE, J.D. EQ&O, Inc. FIN A-6041 E00-TFBP-3900 B2/06/30 SILBERBERG, H. NRC - No Detailed Affiliation Oiven. 44pp 14198.254
- 8208040002 "Thermal Hydraulic LMFBR & LWR Bafety Experiments:" monthly highlight ltr for May 1982 OINSBERO, T., OREENE, O.A. Brookhaven National Laboratory FIN A-3024 82/05/31. CURTIS, R.T. Bevers Accident Assessment Branch 4pp. 14232 319.
- 8208040004 "LDFT Experiment Definition Document (EDD), Anticipated Transients W/Multiple Failures, Test Series L9, Nuclear Test L9-1/L3-3/L8-1A, " interim rept BEELMAN, R J., SQLBRIG, C W., JUNHSON, E. L. EQMO, Inc FIN A-6048 EQG-LOFT-8362, 82/04/13 MCPHERSON, O D Office of Nuclear Regulatory Research, Director. 24pp 14237, 120
- 8208040005 "TRAC-BDI Version 11 Code Assessment Calculations of GE Two Loop Test Apparatus ECC/No ECC Tests 6425 6426," intern rept. HOLCOMB.E. EQ&Q. Inc. FIN A-6047, EOG-CAAD-5857 82/05/31 ODAR.F NRC - No Detailed Affiliation Given 124pp 14236-108.
- 8208040007 "Guick Look Rept For Semiscale Intermediate Break Text B-IB-1," interim rept BTEPHENG.A.O, KULLBERG.C.H., JOHNSEN.OW, EGGO, Inc. FIN A-603B EQQ-BEHI-5839, 82/04/30 LYON,W C Office of Nuclear Regulatory Research, Director 112pp 14237 004
- 8208040010 "Bafety Evaluation Rept.Pump & Valve Inservice Testing Program, Gyster Greek Nuclear Generating Station." interim rept. ROCKHOLD, H. C. E0&0, Inc. FIN A-6258. E00-EA-5844. 82/04/30 PAGE, J. D. Division of Engineering. 27pp. 14236.279
- 8208040018 "Adequacy of Station Electric Distribution Bys Voltages, Beavar Valley Power Station, Unit i." informal interim rept. UDY, A C EQUO, Inc FIN A-6429, EQG-EA-5840 82/05/31. PREVATTE, R.L. Division of Systems Integration (post 611005) 13pp 18202-287
- 8208040024 "Mar 1982 LOFT Progress Rept to Foreign Perticipants," interim rept.
 871LES,J.P. EQ&O, Inc. FIN A-6048. EQQ-LDFT-5861 82/05/31 MCPHERSON,O.D Integral Systems Section TILLER,R E Energy, Dept. of. 17pp 14232:335
- 8208040027 "TRAC-BD1 Calculation & Data Comparison of Intl Std Problem 12," Interim rept DALLMAN.R.J. EQ&O: Inc FIN A-6047. EQQ-CAAD-5860. 82/05/31. CDAR.F. Office of Nuclear Regulatory Research. Director. 60pp. 14236-049
- 8208040036 "LOFT Experiment Operating Spec.Anticipated Transisnt Test Series L9.Test L9-3," interim rept, PETERS.H D., KOBKE.J E. E080, Inc. FIN A-6048 E00-LOFT-5731. 82/03/11 MOPHERSON, D. OPPice of Nuclear Regulatory Research, Director. 35pp. 14236-001.
- 8208040043 "LOFT Experiment Definition Document Anticipated Transient Test Sarias, Nuclear Test L7-3." Interim rept KUAN, P., EGLERIG, C.W., JOHNBON, E.L., EG&O, Inc., FIN A-604B EGO-LOFT-05732, 82/03/11, MCPHERBON, O.D. Office of Nuclear Regulatory Research, Director, 32pp. 14237:162.

- 8208040050 "TMI Resin Solidification Test Program"
 DOUGHERTY, D R , ADAMS, J W , BARLETTA, R E Brookhaven National
 Laboratory BNL-NUREG-31390 82/07/31 JOHNSTON, T C Division of
 Waste Management 5pp 14235 355
- 8208040167 "Proposed Draft Branch Technical Position PSB-3, Licenaing Outdance for Enhancing Reliability of DC Power Sys," interim rept HENDERSON, B. J., UDY, A. C., VANDERBEEK EG&O, Inc. FIN A-6463 EGQ-EA-5721 82/05/31 UNGARD, A. Division of Systems Integration (past 811005) 10pp 14228 270
- 8208040622 "Environ Assessments of Fuel Cycle Facilities." monthly progress rept for May 1982 KELLY,M J Dak Ridge National Laboratory. FIN 8-0279 QRNL/ED/EIS-174 82/05/31. GILLEN,D M Uranium Recovery Licensing Branch. 6pp 14228.300
- 8208040629 "Analysis of Proposed New IAEA Dasis for Transportation Regulatory Bys." Interim rept RANDOLPHIM L., ECKERMAN, K. F. Oak Ridge National Laboratory FIN 8-0810-2 DRNL/HASRD-151 82/06/30 HOPKINS, D. R. Division of Risk Analysis 21pp. 14225-318
- 9208050005 "Noise Diagnostics for Sefety Assessment; Continuous Gn-Line Reactor Surveillance Sys." Interim foreign trip rept of IAEA 820621-25 meeting in Prague, Crechoslovakia THIE. J. A Dax Ridge National Laboratory FIN 8-0191 ORNL/FTR-1330 82/07/01 LEWIS. O 9 Division of Facility Operations 21pp 14243 041
- 8208050009 "Super Sys Code Development, Validation & Application" &
 "Generic Balance-of-Plant Modeling," monthly highlight repts for June 1982
 GUPPY, J & Brookhayen National Laboratory FIN A-3015 82/07/12.
 CURTIS, R T Bevere Accident Assessment Branch 7pp. 14243 062
- 8208050011 "Thermal Hydraulic LMFBR & LWR Bafety Experiments," monthly highlight ltr for June 1982 OINSBERG,T., OREENG,G A Brookhaven National Laboratory FIN A-3024 82/06/30 CURTIS,R T Severe Accident Assessment Branch.
- 8208060039 "May 1982 LDFT Progress Rept to Foreign Participants," interim rept. FELDMAN,E M 20%0, Inc. FIN A-6048 E00-LUFT-5930 82/07/31 MCPHERSDN.G.D Integral Systems Section 19pp 14280 031
- 8208060052 "Effect of Recirculation Pump Trip Following ATW8 at Big Rock Point," interim rept LYDN,R E EQ&0, Inc FIN A-6442 EGG-EA-5533 82/06/30 CHOW,E, Division of Safety Technology HARDIN,W B Division of Systems Integration (past 811005) 12pp 14282.126
- 8208060056 "Anticipated Transients W/Multiple Failures.Test Beries L6-7/L9-2." Interim rept MADDEN.B C EGRO, Inc FIN A-6048 EGO-4.0FT-5360 82/07/27. MCP/HERBON.Q D Office of Nuclear Regulatory Research, Director 18pp. 14282 141
- 8208110008 "Experimental Data Rept for L9-3 Experimental Power Operated Relief Valve Calibr Tests," interim rept OHCA:W A E046 Inc FIN A-6038 E09-8EMI-9919 82/06/30 LANDRY:R R Office of Nuclear Regulatory Research, Director 52pp.
- 8208110241 "Characterization of TMI-Tupe Wastes & Solid Products," quarterly progress rept. Jan-Mar, 1982 SWKLER: K. J. DAYAL: R. Brookhaven National Leboratory FIN A-3236 SNL-NURGO-31413 82706/30 KIM-K Office of Nuclear Regulatory Research, Director 36pp 14331:065
- 8208180158 "Properties of Radwastes & Waste Containers," quarterly progress rept. Apr-June 1982 HGRCOS N , DAYAL, R Brookhaven National Laboratory FIN A-3027. SNL-NUREG-31566 82/07/31 KIM.K Office of Nuclear Regulatory Research, Director. 26pp. 14391 185
- 8208190360 "Accident Aerosol Characterization," progress rept for June. 1982 DWCZARSKI,P.C. Battelle Memorial Institute, Pacific Northwest Leboratory FIN 8-2287, 82/07/16. BERNSTEIN.S. Standards Section 14pp 14506 136
- 8208240045 "June 1982 LOFT Progress Rept to Foreign Participants." interim rept FELDMAN,E M. EQ&O, Inc. FIN A-6048 EQO-LGFT-5969. 82/08/31, MCPHER8DN,G D Integral Systems Section 18pp 14529 339.

- 8208250027 "Container Assassment-Corrosion Study of High Level Waste Container Matls." quarterly progress rept for Apr-June 1982 AHN.T M , SOO.P Brockhaven National Leboratory FIN A-3237 SNL-NUREO-31611 82/07/31 MCNEIL.M Waste Management Branch 30on 14557 180
- 8208250074 "THEF Experiment Operating Spec for Flow Regime & Gritical Flow Studies Experiment 1." interim rept
 SEMMEN.R S EG&G. Inc FIN A-6038 EGG-BENI-5913 82/06/30
 LANDRY.R R Office of Nuclear Regulatory Research, Director 32pp
 14351-304

REVIEW GRP NRC RESEARCH REVIEW GROUPS

- 8207220184 Bummary of CROR 820707 Heeting 15 re proposed guidance to essist applicants in documenting deviations from SRP & NRC perception of ofc staff views of CROR STELLO:V Committee to Review Generic Requirements 82/07/13 DIRCK8/W J Office of the Executive Director for Operations. 3pp 13977-254
- 8208020157 Advises that proposed insider rule has been added to agenda for CRGR Meeting 16 on 820811 Burnett of NM88 will present rule for CRGR review
 STELLD, V Committee to Review Generic Requirements 82/07/29
 EJSENHUT, D O Division of Licensing JORDAN, E L Director's Office, Office of Inspection and Enforcement MAUSSHARDT, D B Dffice of Nuclear Material Safety & Safeguards, Director 1p 14144 132.
- 8208030213 Package of 10 comments on proposed legislation, Nuclear Standardization Act of 1982 CHASE, B 8 Connecticut State of DAVIS,W E New York, State of GERUSKY:T.M Pennsylvania, State of 47FR24044 82/07/27. TOURTELLOTTE, J Regulatory Reform Task Force 37pp 14159: 268
- B20B0302B6 Comments on proposed Nuclear Standardization Act of 19BR BERNERO,R M Division of Risk Analysis 47FR24044 066 B2/07/22 Regulatory Reform Task Forca 4pp 14156 174
- 820803029i Package of two commants opposing proposed legislation, Nuclear Standardization Act of 1982 DOUGHTY, J Beacoast Anti-Pollution League WHITE, J H Affiliation Unknown, 47FR24044 82/07/27 Regulatory Reform Task Force 4pp 1418 123
- 8208030380 Forwards comments on proposed Nuclear Standardization Act of 1982 GRUENEICH, D. California, State of 47FR24044 057 82/07/22 PALLADINO.N J. Commissioners ip 14154 272
- --8208030383 Comments on proposed Nuclear Standardization Act of 1982 VARANINI.E E California, State of 82/07/20 PALLADINO.N J Commissioners Zópp 14154 273
- --8208030385 DOE/EP/10004-1
 "Need for Power & Choice of Technologies State Decisions on Electric Power Facilities"
 # American Law Institute American Bar Association 81/06/30 248pp 14194 299
- --B208030389 800-78-014
 "Power Plant Siting Policy Paper"
 # California, State of 78/11/30 75pp 14155 159
- 8208030301 Comments on Section 185 (b) of Title 1 of proposed legislation, Nuclear Standardization Act of 1982 Certifications would be more appropriately vested in state or local agencies established for such purpose MOORE, C. A. Faderal Energy Regulatory Commission, 47FR24044 054, 82/07/19. Regulatory Reform Task Force, 2pp 14164-056
- B208030511 Comments on draft legislation. Nuclear Standardization Act of 1982 Reform proposals should address regulatory process as applied to both plants in operation or under const as well as new plants
 ROTHSCHILDT NRC No Detailed Affiliation Given 47FR24044 056.
 82/07/26. TOURTELLOTTE. J Regulatory Reform Task Force. 30pp
 14163 285
- 8208030520 Comments on proposed legislation, Nuclear Standardization Act of 1982 SLEMBER, R J Westinghouse Electric Corp 47FR24044 080 82/07/15 CHILK: S J, Office of the Secretary of the Commission 32pp. 14163.212.

- 8208030929 Package of two comments on proposed legislation, Nuclear Standardization Act of 1982 JOHNSON, B Affiliation Unknown BRADBURY, R B Stone & Webster Engineering Corp 47FR24044 82/07/22 Regulatory Reform Task Force 13pp 14163 320
- B208D30536 Comments on proposed Nuclear Standardization Act of 1982 Legislation provides questionable benefits which are outweighed by deficiencies & retrograssions HOLT.J Public Interest Research Group, New York 47FR24044 051 B2/07/16 Regulatory Reform Task Force 3pp 14162 274
- B20B030550 Comments on proposed legislation, Nuclear Standardization Act of 1982 FAY, J M Affiliation Unknown 47FR24044 070 82/07/19 Regulatory Reform Task Force 2pp 14162 094
- 8208030568 Advises that AJ Hazle, State Liaison Officer, will act as coordinator of State of CO comments on proposed legislation. Nuclear Btandardization Act 1982 HAZLE, A J Colorado, State of 47FR24044 059 82/07/19 QALLI
- --8208030576 Forwards FR notice of request for comments on proposed legislation. Nuclear Standardization Act of 1982 Comments due by 820716 KERR. O W Office of State Programs, Director 82/06/22 Office of State Programs, Director 52pp 14162 022
- 8208030549 Forwards questions for Commission consideration re NRC policy statement on safety goals
 DIRCKS:W J Office of the Executive Director for Operations
 45F71023 137 82/07/20 REMICK:F J Office of Policy Evaluations.
 4pp 14162 246
- 9208030577 Comments on NUREQ-0880 re NRC policy statement on safety goals Supports statement MILEAN.R Affiliation Unknown 45FR71023 159, 92/07/29 Docteting & Services Branch ip 14162 085.
- B208030586 Comments on NUREG-0880 re NRC policy statement on safety goals.

 DAVIEB.R.W. Energy, Dept of 45FR71023 158 82/07/22 CHILK, 8 J
 Gefice of the Secretary of the Commission 4pp 14162; 274
- 8208040185 "NRC Reliability Program Plan," interim rept.Vol II apps, NARESKY, J J. ANDERSON, R T. HENRY, D ITT Research Institute 82/06/30 23ipp 14232 007
- B209040547 Notification of Baselt Waste Isolation Project 820714 coordination meeting to discuss site issues, future activities, time commitments & graphics & app for 8CA HRIGHT, R J High Level Waste Technical Development Branch B2/07/13 B0YLE, R, BELL, M, BROOKS, D NRC No Datailed Affiliation Given 1p 14220 360
- 8208040551 Confirms planned times for weekly meetings of Basalt Waste Isolation Project review groups WRIOHTR.J High Level Waste Technical Development Branch 82/07/15 BOYLE.R. COOK.R. GREEVES.J High Level Waste Technical Development Branch 2pp 14220 361
- 8208040421 Requests listed matls be available for exam re boreholes listed in 820707 memo during hydrogeology workshop WRIGHT,R.J High Level Waste Technical Development Brench 82/07/16 OGRANSON.R B Energy, Dapt of 2pp. 14225 278
- 8208050198 Forwards CRGR activities monthly rept for 820703-30 & open items from previous meetings Rept will be included in weekly rept to Commission for wh ending 820730 BCHHINK-W 8 Regional Operations & Generic Requirements. 82/07/30, Committee to Review Generic Requirements 4pp. 14237-358
- 8208100059 Forwards document to replace Encl A of proposed insider rule package forwarded for CRBR review on 820729 Old version of Encl A should be discarded STELLOV. Committee to Review Generic Requirements 82/08/04 EISENHUT, D 0 Division of Licensing JORDAN,E L Director's Office, Office of Inspection and Enforcement HAUSSHARDT, D B. Office of Nuclear Material Safety & Bafeguards, Director, ip. 14/204-203
- B20B100234 Comments on proposed Nuclear Standardization Act of 1982, NRC is incapable of managing comprehensive nat1 safety program for existing nuclear power plants SCHEPP, C.E., Hisconsin's Environmental Decade. 47FR24044 071 82/07/27. Commissioners 3pp 14294 328

- 8208160188 Comments on proposal re one-step licensing for nuclear power plants Opposes proposal HELSLEY, P. Affiliation Unknown 47FR24044 073 82/07/26 NRC No Detailed Affiliation Olven ip 14345, 102
- 8208160199 Comments on proposed legislation, Nuclear Standardization Act of 1982 Opposes legislation DONERTY, J F Affiliation Unknown 47FR24044 072 82/08/06, Docketing & Servicus Branch, 49p 14344:151
- 8208160212 Comments on proposed legislation, Nuclear Standardization Act of 1982 Supports proposal SHIELDS,8 W Public Service Co of Indiana, Inc. 47FR24044 074 82/08/02 Regulatory Reform Task Force 4pp 14342 357
- 8208170097 Requests attendance at CROR Meeting 16 on 820817 in Betheada/ND to continue discussion on proposed insider rule
 8TELLO, V Committee to Review Generic Requirements 82/08/13
 E18ENHUT, D G Office of Nuclear Reactor Regulation, Director JORDAN, E L Director's Office. Office of Inspection and Enforcement, MAUSHARDT, D B. Office of Nuclear Material Safety & Bafeguards, Director. 1p 14258, 230
- 820817017B Forwards comments re proposed Nuclear Btandardization Act of 1982 Standardization may expedite licensing process however, failure of sys in standardized plants may cause extensive industry shutdown, HAZLE: A J Colorado, Stats of, 47FR24044 075 82/08/09, Regulatory Reform Task Force ip 14364, 329.
- B20B17036B Forwards "Basalt Waste Isolation Project Document Review." MILLER, H J. High Level Waste Technical Development Branch. B1/09/30. MARTIN, J B Division of Waste Management. 1p 14371 056.
- --B208170349 "Basalt Waste Isolation Project Document Review "

 * High Level Waste Technical Development Branch 81/09/28 44pp,
 14371 037
- 820B170370 Forwards trip rept of B01202-03 Basalt Weste Isolation Project annual review meeting & B01204 meeting w/Rockwell, PREBTHOLT.P. T. High Level Waste Technical Development Branch B1/01/16 BELL.H J. High Level Waste Technical Development Branch, ip. 14371 101.
- --8208170371 Trip rept of 801202-03 Basalt Waste Isolation Project annual review meeting & 801204 meeting w/Rockwell PRESTHOLT.P.T. LEHMAN.L.L. WRIGHT.R.J. High Level Waste Technical Development Branch 61/01/16. High Level Waste Technical Development Branch 13pp 14371 102.
- 8208170373 Forwards trip rept of 810922-25 site visit to Hanford Basalt Waste Isolation Project re plans for hydrologic investigations MARTIN. B Division of Waste Management 81/12/15 MEYER. B. Energy, Dept of 2pp 14371-117
- 9208170376 Forwards trip rept of 800707-17 visit to assess current siting studies for Henford Baselt Waste Isolation Project, Experience beneficial in developing regulatory & guidance documents & in planning technical programs
 BELL.M.J. High Level Waste Licensing Management Branch 80/09/17.
 HEATH-C. Energy, Dept of 2pp 14375:257
- --8208170378 Trip rept of 800707-17 visit to assess current siting studies for Hanford Basalt Waste Isolation Project HARTUNGAL, LEHMAN, L., 81EFKEN, D. High Level Waste Licensing Management Stranch 80/09/17, NRC No Detailed Affiliation Oliven 46pp, 14371.259.
- 8208180048 Forwards proposed IE circular, "Deficiencies in Primary Contaitment Electrical Penetration Assemblies." Briefing on 820908 suggested. STELLD, V Regional Operations & Generic Requirements. 82/08/17. DEYOUNG.R.C Director's Office, Office of Inspection and Enforcement ip 14375/204.
- ---82081800056 Requests briefing on proposed IE circular, "Deficiencies in Primary Containment Electrical Penetration Assemblies."

 DEYOUNGR C. Director's Office. Office of Inspection and Enforcement. 82/08/11. BTELLO, V. Regional Operations & Generic Requirements 5pp. 14376; 205

B20B20D074 Advises of CROR Meeting 17 on B20T01 in Bethesda, MD to review rule & policy statement on backfitting proposed in BECY-92-326 Off director comments on rule will be transmitted before meeting STELLO.V Regional Operations & Generic Requirements B2/0B/IB EISENHUT, D 9 Division of Licensing JORDAN, E L . MAUSSHARDT. D 9 Director's Office of Inspection and Enforcement ip 14393 214

8208200143 Requests comments re proposed rule & policy statement on backfitting by 820825. CROR review of rule & policy statement also requested DIRCKS, W J Defice of the Executive Director for Operations RODI 82/08/18 STELLO, V Regional Operations & Generic Requirements DENTON-H R Office of Nuclear Reactor Regulation. Director DEYOUNG, R Director's Office, Office of Inspection and Enforcement 1p 14393 265

8208300088 Cancels continuation of CRGR Meeting 16 scheduled for 820817.since Executive Director of Operations requested CRGR terminate review of proposed insider rule. STELLOV Regional Operations & Generic Requirements 82/08/17 EISCHMUT,D & Office of Nuclear Reactor Regulation, Director. JORDAN.E L. Director's Office. Office of Inspection and Enforcement MAUSSHARDT,D & Office of Nuclear Haterial Safety & Safeguards,Director 1p 14679 148

B20B3002B3 Forwards rept "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals " Rept considers proposed Nuclear Standardization Act of 1782 CHARNOFF, C Shaw, Pittman, Potts & Trowbridge 47FR24044 076, 82/08/16 PALLADINO, N J. Commissioners, 1p 14678-278,

--B208300286 "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposeis." CHARNOFF, O , EDGARIO L., LONGIS Ad Hoc Committee for Review of Nuclear Reactor Reform Proposals. 82/08/16 42pp 14678 299.

8208300306 Comments on proposed legislation. Nuclear Standardization Act of 1982. Opposes act TANNER. J. Affiliation Unknown 47FR24044 077 82/08/11 PALLADING.N Commissioners 1p 14599 077

8208310145 Notification of CRGR Meeting 18 on 820908 in Bethesda, ND to discuss proposed circular & status of scheduling reactor specific actions concerning implementation of NRC requirements for power reactor licensees STELLO, V Regional Operations & Generic Requirements 82/08/24 EISENHUT, D @ Division of Licensing JORDAN, E L Director's Office, Office of Inspection and Enforcement MAUSSHARDT, D B Office of Nuclear Material Safety & Bafeguards, Director 2pp 14694 341

820B310206 Informs of CRGR 820915 Meeting 19 to discuss cost/benefit study of design requirements for inadequate core cooling/instrumentation. Presentation responds to CRGR comments on R Mattson briefing at 820324 Meeting 11 rs TMI Item II F.2 STELLO.V Regional Operations & Generic Requirements 82/08/30 EISEMHUT.D 9. Office of Nuclear Reactor Regulation. Director. JORDAN.E L Director's Office, Office of Inspection and Enforcement HAUSSHARDT,D 8. Office of Nuclear Material Safety & Safeguards, Director ip 14689, Oli.

--B20B310214 Forwards "Cost/Benefit Study of Design Requirements for Inedequate Core Cooling Instrumentation." status summary on TMI Action Plan Item II F 2 Proprietary App B of rept withheld (ref 10CFR2.790).

DENTON:H R Office of Nuclear Reactor Regulation, Director B2/0B/19, STELLOV Regional Operations & Generic Reguirements Opp 14689 012

--B20B310221 "Cost/Benefit Bludy of Design Requirements for Inadequate Core Cooling Instrumentation." status summary on TMI Action Plan Item II F 2. B Core Performance Branch B2/06/30. 47pp. 14689.015

BECY POSITION PAPERS BEFORE THE COMMISSION

8204220343 BECY-B2-153
Requests Commission approval to publish notice of proposed rule-making re-accreditation of qualification testing organizations.
DIRCKS, H. J. Office of the Executive Director for Operations, 82/04/08, 133pp. 14317-308

8206100427 SECY-82-204
Recommends Commission approval to publish as final rule, iOCFR61, "Licensing Requirements for Land Disposal of Radwaste." Proposed final rule & draft congressional ltrencl
DIRCKS.W. J. Office of the Executive Director for Operations. 82/05/19 170pp, 14178, 235,

8207220055 SECY-82-204A
Forwards FES for 10CFR61. "Licensing Requirements for Land
Disposal of Radwaste"
DIRCKS.W J Office of the Executive Director for Operations
82/07/06 35pp 14028 328

820B190034 SECY-82-196
Recommends approval of proposed rulemaking requiring fitness for duty for personnel of unescorted access to protected areas
BIRCKB, N J Office of the Executive Director for Operations, 82/05/18 26pp 14507 001

STATE PROG STATE PROGRAMS

8209030568 Advises that AJ Hazle, State Ligison Officer, will act as coordinator of State of CO comments on proposed legislation, Nuclear Standardization Act 1982 HAZLE, A.J. Colorado, State of 47FR24044 059 82/07/19 OALLIGAN, H A Colorado, State of ip 14162 021

8208040564 Ack receipt of 820414 suggestions for implementation of 10CFR60. Subpart C. involving participation by states in high level waste licensing process Meeting to discuss topics requested MILLER. H J High Level Waste Technical Development Branch 82/05/12 SALTZMAN. J D Assistant Director for State & Licensee Relations 2pp 14220 346

8208120364 NUREG/CR-2842
TRANSPORTATION OF RADIOACTIVE MATERIAL IN SOUTH CAROLINA
October 1980-September 1981
SAPPINOTON, R South Carolina, State of FIN 8-1612 92/07/31
Office of State Programs, Director 38pp Available at NTIS,
84 50 14332 286

8208130478 NUREO/BR-0025 VOB N9
INFORMATION REPORT ON STATE LEGISLATION
LANDAU, M S , KERR.O W Office of State Programs, Director
62/08/01 9pp Available at NTIS 14350 330

8208140486 Ack receipt of BG Rutledge 820624 ltr re revised rules & regulations for radioactive metls. Revision of rules necessary before statement of adequacy & competibility could be offered following NRC 1981 review of program O'REILLY, J P Region 2. Office of Director 82/08/04 LEDETTER, J O Georgia, State of, Dept of Human Resources, 2pp 14748 278

820B170075 PNA-82-007 on 820B11, State of LA nuclear energy div notified Region 4 of low level radioactive contamination caused by Ir-192 tagged sand in private homes & in ofc of Haliburton Svcs, Bosaler City, LA HEYER, R. S. ; DODA, R. J. Region 4, Office of Director 82/08/11, 1p 14358 21A.

8208180227 NUREO/CR-2852
TRANSPORTATION OF RADIOACTIVE MATERIAL IN NEVADA September 1980-September 1981
* Nevada, State of FIN 8-1327 82/07/31 Office of State Programs, Director 26pp Available at NTIB \$3 50 14389-337

8208180257 Notification of contract execution: Mod 1 to "Training Course 'Safety Aspects of Industrial Radiography for State Regulatory Personnel' "Contractor: Gamma Industries Div. Nuclear Sys. Inc. MCNULTY: A Purchasing Section FIN 8-1618 NRC-06-82-293 82/08/15 KERR, Q W. ASMLEY, E C Office of State Programs, Director Ip 14389, 291

--8208180261 Mod 1.adding one training course & increasing funding.to
"Training Course 'Safety Aspects of Industrial Radiography
for State Regulatory Personnel' "
RICHARDSON:H D Nuclear System REBELLO, J E Purchasing Section.
FIN B-1618 NRC-06-82-293 82/08/15, 1p 14389 292

8208190341 Forwards response, affirming NRC assistance to State of CO 820616 request for technical assistance in evaluating low level waste disposal facility application SMITH.R D Low Level Wests Licensing Branch. WM-82-488 82/07/30 NUSSBAUMER, D A Assistant Director for State Agreements Programs, 3pp. 14506-150.

8208260046 NUREC/CR-2851
TRANSPORTATION OF RADIGACTIVE MATERIAL IN ILLINOIS June 1980-June 1981.
HENNEG, M., NORDIN, J., SIKONIN, J. M. Illinois, State of 82/07/31.
Office of State Programs, Director 78pp Available at NTIB.
\$5.00 14587-072.

- B20B240505 NUREG/CR-2869
 DIRECTORY AND PROFILE OF LICENSED URANIUM-RECOVERY
 FACILITIES
 HARKENTIEN, J. BUSCH, L. S. DEPUE, J. Argonne National Laboratory,
 FIN B-1660 ANL/ES-128 B2/07/31 Office of State Programs,
 Director 105pp Available at NTIS \$5.50. 14595.066
- 8208310015 Forwards request for OMS review & supporting statement re 10CFR150, exemptions & continued regulatory authority in Agreement States under Section 274 of Atomic Energy Act NDRRY,P 0 Office of Administration 82/08/24 SCURRY,N Office of Kanagement & Budget ip 14697 136

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

- 8207150242 Recommends enclosed issues be transmitted to owners of plants w/Mark I & II containments of overguest that owners discuss how plants will respond Mark II owners will meet 820422 SPEIS.T P Assistant Director for Radiation Protection 82/06/21 LAINAB.O Assistant Director for Safety Assessment NOVAK.T Assistant Director for Operating Reactors TEDESCO.R Assistant Director for Licensing 10pp 14227 001
- 8207280256 Forwards application for withholding proprietary version of MCAP-9863, "Rod Bank Worth Measurements Utilizing Bank Exchange "Nonproprietary version of MCAP-9864, "Rod Bank Horth Measurements Utilizing Bank Exchange enc!"
 RAHE, E P Westinghouse Electric Corp NS-EPR-2612 82/07/15 HILLER, J Standardization & Special Projects Branch, 2pp 14071 001
- --8207280289 Application for withholding proprietary rept,WCAP-9863,
 "Rod Bank Worth Measurements Utilizing Bank Exchange,"
 (ref 10CFR2 790)
 WIEBEMANN:R A Westinghouse Electric Corp AW-82-33 82/07/15.
 MILLER:JR Standardization & Special Projects Branch lipp
- --B207280263 WCAP-7864
 Nonproprietary: "Rod Bank Horth Measurements Utilizing
 Bank Exchange"
 CAMDEN.T M. PALOWITCH.B L., YULEY.C R Westinghouse Electric
 Corp 82/05/31 46pp 14071 015
- B207300360 Forwards proprietary WCAP-10125, "Extended Burnup Evaluation of Westinghouse Fuel" & applications for withholding proprietary info Rept withhold (ref 10CFR2 790) RAHE,E P Westinghouse Electric Corp, NS-EPR-2629, 82/07/28 MILLER,J R Standardization & Special Projects Branch, 2pp 14119 305.
- --8207300365 Requests WCAP-10125, "Extended Burnup Evaluation of Heatinghouse Fuel" be uithheld from public disclosure per previously approved Affidavit AW-78-27 dtd 780322 HIESEHANN-R A Westinghouse Electric Corp AW-82-44, 82/07/28 HILLER JR Btandardization & Special Projects Branch ip 14119 307
- --9207300371 Requests WCAP-9272, "Westinghouse Reload Safety Evaluation Methodology" be withheld from public disclosure per Affidavit AW-76-31 dtd 760727 WIESEMANN,R Westinghouse Electric Corp AW-78-27 78/03/22, STOL2.J F Light Water Reactors Branch 1. ip 14119:308
- --B207300376 Requests reload safety evaluation methodology be withheld from public disclosure (ref 100FR2 790). WIEBEMANN:R Westinghouse Electric Corp AW-76-31 76/07/27 EIBENHUT.D. G Division of Operating Reactors 11pp 14119:309.
- 8207300543 Requests proposed schedule for submitting program to address concerns re adequacy of design margins of Mark I containment sys (dentified from Mark III issues raised by former GE employee Humphrey containment concerns encl.

 EIBENHUT, D O Division of Licensing 82/07/18 LGOUE, R. General Electric Operating Plant Owners Group. 11pp 14194:102
- ©208020063 Forwards comments re proposed severe damage (BFD) program developed by NRC Fuel Testing Force Program premature & should await development of overall LWR safety goals. RAME, E.P. Westinghouse Electric Corp. BE-LEH-524 81/09/25 SILBERBERG.M. Fuel Behavior Branch 12pp. 14180,338.
- 8208030033 Summary of 820623 meeting w/C-E owners group in Bethasda, MD re-pressurized thermal shock issue. Handouts enci LITTON: F. B. Generic Issues Branch 82/07/08. Generic Issues Branch 27pp. 14197:180.

- 8208030177 Confirms scope & process to be employed for second meeting re NRC review of Hestingbouse safety parameter display sys. Review should be akin to topical rept review due to generic preimplementation nature Proposed agenda encl.
 RAHE, E. P. Westinghouse Ejectric Corp. NB-EFR-2620 82/07/15, PAUL60N.W A. Operating Reactors Branch 5. 3pp. 14160:187
- 8208030270 Informs that site tests confirm reliability of Btewart & Stevenson & Morrison-Knudson diesel generators Testing supports GE exceptions to voltage & frequency excursion guideline of Reg Guide 1 9
 SHERMODD, 0 G General Electric Co MFN 100-82 82/07/23.
 DENTON-H R Office of Nuclear Reactor Regulation, Director 2pp 14189-1448
- 8208030443 Forwards revised 820713 itr on resolution of TMI Action Plan Item II.K 3 5 re reactor coolant pump trip during transients Typographical error contained in second paragraph OASPER.J K C-E Operating Plants Owners Group. 82/07/29. MATTSON.R J Division of Systems Integration (post 811005). 1p. 14154:047
- ---B208030474 Bubmits revised summary re appropriate resolution of TMI Action Plan Item II.K 3.5 & comments on influence of third HPGI Recommendation for collant pump operation during degrees unitation most effective method. Visugraphs and I OASPER.J.K C-E Operating Plants Owners Group 82/07/29, MATTEON,R J Division of Bystems Integration (post 811005), 10pp.
- 820B030564 Forwards "Ref Core Rept 17x17 Optimized Fuel Assembly," Vols 1-5. Encl rept & format consistent w/revised guidelines presented in NUREO-0390/Vol 6, Number 1 dtd 820120 RAHE, E.P. Westinghouse Electric Corp. NB-EFR-2624, 92/07/09. MILLER, J. R. Office of Nuclear Reactor Regulation, Director, 1p. 14164:069
- --8208030567 WCAP-9500-A V01

 "Ref Core Rept 17x17 Optimized Fuel Assembly," Vol 1.
 ARLOTTI,M. 9 . RAHE,E P Hestinghouse Electric Corp 82/05/31.
 530pp 14164-070
- --8208030573 WCAP-9500-A VO2
 "Ref Core Rept 17x17 Optimized Fuel Assembly," Vol 2,
 ARLOTTI,M,G., RAHE,E P Westinghouse Electric Corp. 62/03/31,
 500pp. 14165-216
- --8208030578 WCAF-9500-A V03
 "Ref Core Rept 17x17 Optimized Fuel Assembly." Vol 3,
 ARLOTTI,M. G , RAHE,E P Westinghouse Electric Corp. 82/05/31,
 700pp. 14166:211
- --8208030583 WCAP-9500-A V04
 "Ref Core Rept 17x17 Optimized Fuel Assembly," Vol 4.
 ARLOTTI, M. G., RAHE, E.P. Westinghouse Electric Corp. 82/05/31.
 800pp. 14167 326
- --8208030588 HCAP-9500-A V05
 "Ref Core Rept 17x17 Optimized Fuel Assembly," Vol 5
 ARLOTTI, 9, RAHE, E, P Westinghouse Electric Corp. 82/05/31.
 500pp. 14167 039
- 8208030749 Summary of 820623-24 & 29 meetings W/C-E & C-E owners group as C-E emergency operating procedure guidalines program C-E will provide overview of program & discuss validation & implementation of guidalines at next meeting GDDMAN, M. J. Procedures & Test Review Branch 82/07/15 ZIEMANN, D L. Procedures & Test Review Branch 4pp. 14196,306.
- 8208040583 Approves request for MCAP-9558, Revision 2 & MCAP-9767 to be withheld from public disclosure, as repts contain proprietary commercial info CRUTCHFIELD, D. Operating Reactors Branch 5. B2/07/09, WEISSEMANN, R. A. Westinghouse Electric Corp. 2pp. 14227:361.
- 8208050070 Forwards summery description of ref plant & "Emergancy Response Guidelines Low Pressure Version Optimal Recovery Guidelines & Emergancy Contingencies: " Vols 2A & 2B. KINGBLEY, O. D. Hestinghouse Operating Plants Owners Group. KINGBLEY, O. D. Alebama Power Co DG-76. B2/07/21. E18ENHUT, D. Q. Division of Licensing 19pp. 14212:151.
- --- 8208050094 "Emergency Response Guidelines Low Pressure Version, Optimal Recovery Guidelines & Emergency Contingencies." Vols 2A & 2B.
 KINGSLEY. C. D., KING, S. L. Westinghouse Operating Plants Owners Group. 82/07/31. 300pp. 14212:173.

- 8208060031 Notification of 820715 meeting w/Scandpower, Inc in Dethesda, MD to discuss application of radcal gamma thermometer assemblies for core coolant monitoring SCHMENN, 0 A Core Performance Branch 82/06/30 BERLINGER, C H Core Performance Branch 02006/30 BERLINGER, C H
- 8208060033 Notification of 820721 meeting w/BHR owners group in Bethesda,MD to discuss preliminary staff reactions to combostible gas control rept submitted 820621 ROONEY, Deparating Reactors Branch 2 82/07/09 VASSACLO, D 8 Operating Reactors Branch 2 2pp 14280 020
- 8208060041 Informs that util will be billed for review of Revision 11 to Topical Root VOGAP-I-A. "Operational GA," per 10CFR170 21.Category F MILLER.W U License Fee Management Branch 82/08/02 JQHNSQN.W P Vankee Atomic Electric Co 10 14282 042
- B208040145 Requests info re Model B containment annulus structure COOPER.W E. CHIN.S L. Teledyne Engineering Services 82/08/03. SCHIERLINO.H E. Office of Nuclear Reactor Regulation, Director 2pp 14240 120
- B20B0A0233 Notifies of organizational changes within operating unit, effective B20A15 Attached chart will replace Figure 1 of Topical Rept BAH-10096A-Revision 4 in mext revision TAYLORIJH. Babcock & Wilcox Co. B2/07/30 HAASS.W P. Quality Assurance Branch 1p 14241 097
- 8208090189 Responds to 820715 ltr re applicability of NRC-identified Humphrey concerns re Mark III containment to Mark I owners group program Issues have little bearing on program GE response due by 820930 LOOUE, R H Ceneral Electric Operating Plant Owners Group LOOUE, R H Philadelphia Electric Co 82/08/09, EISENHUT, D G Division of Licensing 19 14272 017
- 8208090316 Informs that Div of Accounting & Finance will be billing util for review of Revision 12 to Topical Rept CPC-14, "QA Program"

 MILLER, **ID License Fee Management Branch 82/07/30 COOK, J W Consumers Power Co
- 8208090321 Informs that Div of Accounting & Finance will be billing company for review of Revision 4 to Topical Rept XN-NF-1A, "GA Program,"
- MILLER, W D License Fee Management Branch 92/07/30. VOLHER, C J Erron Nuclear Co. Inc. (subs. of Exron Corp.) 1p. 14307.332.
- 820809-0322 Informs that Div of Accounting & Finance will be billing company for review of Revision 11 to Topical Rept ETR-1001, "QA Program"
- MILLER, H O Licenso Fee Management Branch 82/07/30 TENZER, B. E Ebasco Services, Inc (subs of Enserch Corp.) Ip 14307 333
- 8208100158 Forwards Suppl 2.Addendum 1 to "Exxon Nuclear Power Distribution Control for PMRs Phase II " Rept withheld (ref 100FR2 790)

 OMSLEY.0 F Exxon Nuclear Co , Inc (subs. of Exxon Corp.)

 0F0 052 82 82/08/03 TEDESCO.R L Assistant Director for Licensing 4pp 14297 233
- 8208100285 Forwards response to D Powers questions re Topical Rept XN-75-32, concerning poison rod & assembly bow Response withheld (ref 100FR2 790)

 UMSLEY, Q.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

 OFO 053 83. 82/08/03 TEDESCO, R. L. Assistant Director for Licensing 4pp 14294-142
- 8208110111 Forwards nuclear characteristics tables for 27 new fuel bundle designs, incorporated into GE Reload Licensing Topical Rept NEOE-24011-P-4 in Amend 13 Tables withheld (ref 10CFR2 790)
 CHARNLEY, J.S. General Electric Co. MFN-108-82 82/08/05 BERGGREN, J.S. NRC No Detailed Affiliation Given 2pp. 14314.225
- 820B110112 Forwards Revision 1 to CFC-2A, "OA Program Description for Operational Nuclear Power Plants."

 VANDEWALLE, D. J. Consumers Fower Co. 82/08/04 MAAB, W. Quality Assurance Branch ip 14317 027.
- --8208110114 CPC-2A R01
 Revision 1 to "GA Program Description for Operational Nuclear Power Plants"
 DENITY,R. 8. CODK.J.W. BILBY,C.R Consumers Power Co 82/07/22 BBpp 14317-028

- 820B12003D Forwards proprietary "LOCA-Beismic Structural Response of EXXDN Nuclear Co BWR Jet Pump Fuel Assembly " Encl withheld (ref tQCFR2 790).

 OWSLEY, 0 F Exron Nuclear Co , Inc (subs of Exxon Corp)

 OFO 055-82 82/08/04 BERNARD, H Standardization & Beecial Projects Branch 4pp 14319 041
- 8208120080 Forwards Suppl 3 to XN-NF-82-20, "ECCS Evaluation Model of C-E 2r4 PMR Using EXEM/PMR ECCS Model Large Break Example Problem," Results of analysis for C-E type reactor uses ECCS evaluation model described in Revision 1 DMSLEY, OF Exxon Nuclear Co. Inc. (subs. of Exxon Corp.) 0F0 056 82 82/08/04 BERNARD, H. Standardization & Special Projects Branch. 1p. 14327-200
- --8208120087 XN-NF-82-20 803
 Suppl 3 to "ECCS Evaluation of C-E 2x4 PWR Using EXEM/PWR
 ECCS Model Large Break Example Problem "
 KRAJICEK.J E , JENSON, 9 E., OWSLEY, 0 F Exxon Nuclear Co , Inc.
 (subs of Exxon Corp) 82/07/29 58pp 14327 201
- 8208120078 Forwards proprietary Revision 1 to "XCOBRA-IIIC Computer Code to Determine Distribution of Coolant During Steady-State & Transient Core Operation " Rept withheld (ref 10CFR2 770)
 OMSLEY, Q F Exxon Nuclear Co. Inc. (subs of Exxon Gorp)
 OFO 054 82 82/08/04 BERNARD, H Standardization & Special Projects Branch 4pp 14325 013
- 8208130318 Draft Commission paper reactions taken to resolve make-up nozzle cracking problem in B&W plants Status of repairs at plants noted B&W owners group task force rept & recommendations expected by end of 1982 DIRCKS.W J. Office of the Executive Director for Operations. 82/07/23 4pp 14340 225
- B20B170162 Provides addl info for WCAP-8929, "Benchmark Problem Solutions Employed for Verification of MECAN Computer Code," superseding info provided in 820729 ltr Corrected value of Youngs Modulus in Problem 13 discussed RAHE,E P Mestinghouse Electric Corp. NS-EPR-2633 82/08/04, BDSNAW,R J Mechanical Engineering Branch ip 14366 239
- 8208170233 Forwards requested add1 info re Topical Rept WCAP-B929, "Benchmark Problem Solutions Employed For Verification of MECAN Computer Code " Also transmits topical rapt page revisions W/o enc! RAHE, E P Hestinghouse Electric Corp NB-EPR-2631 82/07/29 BDSNAK.R.J, HARTIMAN, M Mechanical Engineering Branch 2pp
- 8208180017 Forwards corrected Tables 17 2-1 & 17 2-5 for Revision 5 to TVA-TR75-1A, "GA Program Description for Design, Const & Operation of TVA Nuclear Power Plants "MILLSPL H Tennessee Valiey Authority 82/08/13 HAASS, W P Guality Assurance Brench 2pp 14377, 193
- --8208180022 TVA-TR/5-1A ERR
 Corrected Tables 17.2-1 & 17 2-5 for Revision 5 to, "GA
 Program Description for Design, Const & Operation of TVA
 Nuclear Power Plants"

 # Tennessee Valley Authority. 82/08/13 5pp. 14377 195
- B208180027 Forwards NEDD-22155, "Generation & Mitigation of Combustibl Oas Mixtures in Inerted BUR Mark I Containments "DENTE,T J BUR Owners Group BURGO-8252 B2/OS/12 EISENHUT,D G Division of Licensing 2pp 14377 077.
- 8208190017 Notification of 820910 meeting w/BNL.Franklin Research Ctr. GE.Mark I owners group & Structural Mechanics Assoc in Bethesda.MD to discuss items associated w/Mark I long-term program post-implementation review SIGGEL.B L. Operating Reactors Branch R. 92/07/26, VABSALLG.D B Operating Reactors Branch 2 3pp 14506.098
- 8208190307 Forwards "Review of Pressurizer Safety Valve Performance as Observed in EPRI Safety & Relief Valve Test Program," in response to NUREG-0737.Action Item II D 1, "Pressurizer Safety Valve Operability" KINGSLEV.O D Westinghouse Operating Plants Compers Group KINGSLEV.O D Alabams Power Co. 09-77, 82/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director, 1p, 14387 189
- --B20B190310 WCAP-10105

 "Review of Pressuriter Safety Valve Performance as Observed
 in EPRI Bafety & Relief Valve Test Program."

 BURNB: E M . DEEQAN.P. D . HOME, K S Westinghouse Electric Corp
 B2/06/30. 111pp 14387-191

- B208190366 Summary of 820730 meeting w/Westinghouse owners group in Bethssda.MD re pressurized thermal shock issue Agenda, attendance list & graphs encl VISSING.0 S Operating Reactors Branch 4 82/08/09 Operating
 - Osenation 14504 133
- 8208200021 Requests review of pressurized thermal shock rept prior to
 - 208200021 Requests review of pressurized thermal shock rept prior to formal submittal to Commission ROCKIND.A P. Babcock & Wilcox Operating Plants Owners Group ROCKIND.A P. General Public Utilities GPU Service Corp 82/08/17 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 14392-239
- 8208200215 Potential significant deficiency rept re online testing circuits for relays in solid state protection sys & undetectable loss of safeguards sys actuation Initially reported on 820804 Revision to test procedures recommended RAHS.E P Westinghouse Electric Corp 100FR 030 55E 82/08/06 DEYOUND.R Director's Office. Office of Inspection and Enforcement. App 14500 149
- 9208230365 Forwards util 820811 itr to all PHR owners & summary of 820727 mesting w/NRC, EPRI, INPO, AIF, et al in Bethesda, MD re NRC proposed steam generator generic requirements, per G Lainas request Participant commonts being prepared 8CHHIDT, A D Steam Generator Owners Group. ECHHIDT, A.D, Florid Power & Light Co 82/08/18 EISENHUT, D Division of Licensing. 20pp. 14513 064 Florida
- 9208230393 Forwards for review & approval proposed Revision & to UEC-TR-001.QA Program Revision is result of program revision is result of program revision is result of program reliability & QA depts SILVERWOOD.J B United Engineers & Constructors, Inc. (subs of Raytheon Co.) 82/08/16 HAABS,W P Quality Assurance Branch 14513-084
- 820B2400B3 Confirms that affective 820B16, function of Product & GA
 Operation transferred to new component entitled GA &
 Reliability Operation Abridged organization chart enci
 EREEO.A. General Electric Co. 82/08/12 HAASS.W P. Quality
 Assurance Branch 3pp 14524 294
- 820924037: Forwards proprietary & nonpreprietary suppls to WCAP-9500 & WCAP-9401/9402 re NRC SER mixed core compatibility items
 Application for withholding proprietary info encl
 Proprietary Version withheld (ref iOCFR2 790).
 RAME, E. P. Westinghouse Electric Corp NB-EPR-2643 82/08/17
 HILLER J. R Standardization & Special Projects Branch 29p
- --B20B240400 Application for withholding proprietary suppl to WCAP-9500 & WCAP-9401/9402 re NRC SER mixed core compatibility items
 Affidavit encl Nonpropriatary version encl
 WIESEMANN, R A Westinghouse Electric Corp AW-82-48 82/08/17
 MILLER, J R. Btandardization & Special Projects Branch 24pp.
 14522.265.
- S208240381 Forwards proprietary "Review of BHR Reactor Vessel Water Level Measurement Bys," completing first phase of program agreed to at 820127 meeting w/NRC Rept withheld (ref 10CFR2 790)
 DENTE, T. J. BHR Owners Group BHRDG-8253 82/08/13 DENTON, H.R. MATT80N, R. Office of Nuclear Reactor Regulation, Director Spp. 14493:359.
- 8208260295 Forwards nonproprietary & proprietary Revision 1 to "Multiflux 3 O.FORTRAN-IV Computer Program for Analyzing Thermal-Hydraulic-Structural Bus Dynamics (III) Advanced Beam Model." meam numes."
 RAME, E. P. Westinghouse Electric Corp. NB-EPR-2644. 82/08/19.
 MILLER, J. R. Standardization & Special Projects Branch. 3pp
- -- 12208260268 Application for withholding proprietary Revision 1 to "Multiflex 3 O.FDRTRAN-IV Computer Program for Analyzing Thermal-Hydraulic-Structural Bye Dynamics (III) Advanced Beam Model " Rept withheld (ref 105FR2.790) WIESEMANN, R A Westinghouse Electric Corp. AW-82-46 82/08/19. HILLER.J R Standardization & Special Projects Branch 8pp. 14555.004.
- -B209260273 WCAP-9736 R01 208260273 WGAP-Y36 R01
 Nonproprietary Revision 1 to "Multiflex 3.0,FORTRAN-IV
 Computer Program for Analyzing Thermal-Hydraulic-Structural
 Bys Bynamics (III) Advanced Beam Model."
 TAKEUCHI,K , KOMALSKI,D J, BHANDARI,D R Westinghouse Electric
 Corp. 82/07/31 160pp. 14555:012.

- 8208260458 Notification of 820820 meeting w/C-E & C-E owners group in Bethesda, MD to discuss C-E emergency operating procedure guidelines QUIDMAN, M J Procedures & Test Review Branch 82/08/16 Procedures & Test Review Branch 2pp 14 TIEMANNE, IS I LABOR DED
- 8208310111 Forwards matl presented by QE at 820813 stability moeting
- 8208310141 Forwards comments on proposed NURE9-0737 Yech Specs Comments should not be interpreted as formal position of Comments should not be sincerpresed as Total position of any individual owners group member
 DENTE, T J BWR Owners Group BNRDO-8255 82/08/26 EIRENHUT, D Q
 Division of Licensing App 14693-175
- 0200210190 Forwards Endorsement 50 to MAFILL Policy ME-AL & Endorsement 208310190 Formards Endorsement 50 to MARLO Policy RF-61 & Endorsem 67 to NELIA Policy NF-182 LAWBON, T.T. Dute Power Co. 62/08/19. SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance). 3pp. 14693-105
- 8208310302 Asserts that fee for review of Revision 1 to WCAP-9220/9221 inequitable & excessive Exemption from fee requirements of 10CFR170 requested equestes Westinghouse Electric Corp. NB-EFR-2641 82/ J M Division of Accounting 3pp. 14688 054. B2/08/06 RUDATQUEZ J M
- B20B310340 Forwards "Analysis of Scram Discharge Vol Bys Piping Integrity "Low probability of core damage initiated by failure of scram discharge piping integrity precludes need to qualify equipment to detect/mitigate consequences DENTE, T J BWR Owners Group BWROO-8284 82/08/23 EIBENHUT, D. 9 Division of Licensing. 2pp 14493 214.
- --8208310347 NEDG-22207 08310347 NEDD-22207
 "Analysis of Boram Discharge Vol Bys Piping Integrity."
 ALEBII.0 : HAYES, F.R : BTANCAVAGE, P.P. General Electric Co.
 BZNEDDBB 82/08/31 27pp, 14493 216
- 8208310417 Forwards clarification of safety parameter display systemsing verification audit plan Audit III deals w/design or testing of integrated sys at specific plant sites Viewgraphs & technical audit scheduls encl
 RAHE, E P Westinghouse Electric Corp. NB-EFR-2650 82/08/26, BELTRACCHI, L Human Factors Engineering Branch Bpp 14693 2 550 82/08/26. 8pp 1460
- WASTE MOT NUCLEAR WASTE MANAGEMENT
- 8208030113 Lists revisions to draft version of, "Finel Radiological Assessment in Support License Renewal for Dawn U Hill " ONUCNOLI.O N. Urenium Recovery Licensing Branch. 62/05/18. OILLEN.D.H Urenium Recovery Licensing Branch 2pp. 14197: 347
- 8208030114 Forwards "RATRAP Users Manual " SILLING-8.A High Level Waste Licensing Management Branch. 82/07/07 High Level Waste Licensing Management Branch 82/07/07 14197 254.
- --8208030117 "RATRAP Ugers Hanual " BILLING.S A High Level Waste Licensing Management Branch. 82/07/07 83pp 14197:200
- B208030118 Forwards ORNL comments on NRC branch technical position re-waste classification, inadvertently omitted from S20504 ltr. HMITBETT. J B Energy. Dept of B2/06/04. EMITH. D High Lavel Waste Licensing Hanagament Branch 4pp. 14197 349.
- 8208030120 Forwards Part C of draft guide. "Std Format & Content of Site Characterization Repts for High Level Wests Geologic Repositories," in response to 820624 request Wo encl COPLAN, B. H. High Level Waste Technical Development Branch. 82/06/29. NEAL, J. T. Bandia Leboratories, ip. 14197-361
- 8208030163 Forwards confirmation of land ownership exemption granted by NRC in June 1981.per 820618 request W/o encl. SCARANO, R A. Uranium Recovery Licensing Branch. 82/07/06. NUBBRAUMER, D. A. Assistant Director for State Agreements Programs 14200.305
- 8208030166 Affirms NRC exemption of Anaconda Mineral Co Rhode Ranch U Project from UMTRAC land ownership requirements HAMMILL, K. J. Uranium Recovery Licensing Branch. 82/07/06 Uranium Recovery Licensing Branch. 1p. 14200

- 8208030716 Responds to 820618 ltr transmitting 820526 presentation on solidification process Some areas require clarification or correction BROWNINO.R E Division of Waste Management 82/07/15 BETTS.T I Dow Chemical Co 2pp 14196 340
- 8208030723 Responds to 820623 request for info re experiments to be performed by Univ of AZ under contract to NRC to evaluate effectiveness of sealing rock masses & groundwater flow COPLAN.5 M High Level Waste Technical Development Branch 82/07/16 VIETH.D L Energy, Dept of 2pp 14196 342
- 8208030725 Ack receipt of 8206[1 ltm transmitting rept, "Facilities for Natl Waste Terminal Storage Project Plan" NRC requirements for site characterization repts not accurately reflected in project plan MARTIN, J.B. Division of Waste Management 82/07/16 COFFMAN.F.E. Energy, Dept of 2pp 14195 350
- 82080400:3 Forwards revised version of technical position on documentation of computer code models Revision intended to be final position BILLING.8 A. High Level Waste Licensing Management Branch BZ/07/08 KNAPP.H R. High Level Maste Licensing Management Branch 12pp 14332 307
- 820B040016 Forwards list of specific info needs in hydrogeology to be covered during workshop beginning \$20721 WRIOHTRY J High Level Waste Technical Development Branch \$2/07/07 GORANSON.R B Energy, Dept of Jpp 14232 304.
- 8208040034 Forwards rept documenting BNL computer file maint procedures Recommends individual be assigned as key user.
 SILLING.8 A High Level Waste Licensing Management Branch 82/07/12 KNAPP.NR High Level Waste Licensing Management Branch 23pp 14235 329
- 8208040042 Submits comments on papers presented at special session of American Ogophysical Union on rule of Unsaturated zone in disposal of hazardous radwaste SIEFREN, D L , STARMER, F J High Lavel Waste Licensing Management Branch 82/07/06 HAWKINS, E F High Level Waste Licensing Management Stanch 2pp 14232-353
- 8208040313 Forwards listing of all UNTRA mill tailings processing & alternate disposal sites for which DDE Operations Ofc has or intends to execute use agreements.

 CANPBELL/E H Energy, Dept. of 20580 82/07/21 SCARAND, R A NRC No Detailed Affiliation Oiven. 9pp 14223 312
- 8208040325 Forwards comments on NRC Technical Position Paper WK-8201.
 "Hydrologic Design Criteria for Tailings Retention Sys "
 Concept of PMP is entirely subjective & has no meaningful economic consideration
 BROWN.R Union Carbide Corp 20026 B2/06/02 BCARANO.R A
 Uranium Recovery Licensing Branch 7pp. 14223-322
- B20B040333 Forwards comments on draft Technical Position Paper WM-8203, "Hydrogeologic Characterization of U Bolution Mine & Mill Tailings Disposal Site " Methods & techniques do not comprehend site-specific conditions/requirements BHELLEY, W J Kerr-McGee Corp 82/07/14 SCARANO, R A Uranium Recovery Licensing Branch, 4pp, 14223-329
- 8208040339 Expresses appreciation for transmittal of draft position paper, "Hydrogeological Characterization of U Solution Mine to Mill Tailings Disposal Sites " Comments to be sent as soon as possible.

 BUDD.W H Wyoming Mining Association 20584 82/07/14 SCARAND,R A Uranium Recovery Licensing Branch. 1p 14223 333
- B20B040537 Forwards "Analysis of Low Level Radwasts Burial Site Capacity Projections." Refinement of proposed authorative nat1 data bank for generated waste data (IDB sys) at ORNL recommended ODRN-BRAUNJ Licensing Process & Integration Branch. 82/07/28 BURNELER, J J Licensing Process & Integration Branch. 3pp 14221-208.
- --820804054; "Analysis of Low Level Radwaste Burial Site Capacity Projections " GDRN-BRAUN.J. Licensing Process & Integration Branch 82/07/31 12100. 1421:211
- 8208040547 Notification of Basalt Waste Isolation Project 820714 coordination meeting to discuss site issues, future activities, time commitments & graphics & app for BCA MRIGHT, R J. High Level Maste Technical Development Branch 82/07/13 BOYLE:R, BELL, H, BROCKB, D. NRC No Detailed Affiliation Given 1p. 14220 340

- 820804055\$ Confirms planned times for weekly meetings of Basalt Waste Isolation Project review groups WRIGHT,R J High Level Waste Technical Development Branch 82/07/15 BOVLE,R . COOK,R . OREEVEB.J High Level Waste Technical Development Branch 2pp 14220 361
- 8208040564 Ack receipt of 820414 suggestions for implementation of 10CFR60. Subpart C. Involving participation by states in high level waste licensing process Meeting to discuss topics requested MILLER. H. J. High Level Waste Technical Development Branch 82/05/12 BALTZMAN. J.D. Assistant Director for State & Licensee Relations 2pp 14220 346
- 8208040368 Notifies of 820717-21 hydrogeology workshop WRIGHT:R. High Lyvel Waste Technical Development Branch 82/07/19 SQUIRES:D Energy. Dept of 2pp 14220 349
- 8208040572 Trip rept of joint AEG/ASCE 820514 meeting in Baltimore, ND re hazardous waste disposal, site elevation, design & monitoring STARMER, R J . DUNKELMAN, M M Low Lavel Waste Licensing Branch 82/07/20 HAWKINS, E F Low Lavel Waste Licensing Branch 4pp 14225 342
- 8208040576 Forwards siting & design suitability issues for NV Nuclear waste storage investigations, issues complete for transmittal to DOE.

 COPLAN.B.M High Level Waste Technical Development Branch B2/07/14. MILLER, H J High Level Waste Technical Development Branch 14pp 14228 211
- 8208040593 Forwards first draft of "Branch Technical Position on DDE QA Program for Geotschnical Investigations" GREEVES, J T High Level Waste Technical Development Branch 82/07/30 MILLER, H J High Level Waste Technical Development Branch 11pp 14228,259
- B208040621 Requests listed matls be available for exam re boreholes listed in B20707 memo during hydrogeology workshop MRIGHT.R J High Level Waste Technical Development Branch B2/07/16 QORANSON.R B Energy Dept of 2p 14225 298
- B20B050049 Proposes that existing Baselt Waste Isolation Project QA documents should be provided to NRC to fill info gap in site characterization rept WRIGHT.R J High Level Waste Technical Development Branch B2/07/07 OGR
- 820B06012B Forwards "Technical Review Environ Characterization Rept for Paradox Basin Study Region.UT Study Areas " PFLUM.C O. High Level Waste Technical Development Branch 82/07/28 BOYLE.R R High Level Waste Technical Development Branch 1p
- --8208060134 ONWI-144
 "Technical Review Environ Characterization Rept for Paradox Basin Study Region, UT Study Areas"
 PFLUM, C. Q High Level Waste Technical Development Branch 82/05/31 9pp. 14244 203
- 8208060175 Presents actions being taken to ensure satisfactory interface between NRC & DDE during waste repository site investigations DIRCKS-W J Office of the Executive Director for Operations 82/07/07 PALLADING-N J. Commissioners 1p 14244 212
- 8208090001 Forwards May 1982 water quality rept CAIN.8 Cotter Corp 82/06/09 HAZLE, A J Colorado, State of 2pp 14283:343.
- --8208090002 Hay 1982 water quality rept. * Cotter Corp. 20591 82/07/12 5pp. 14283 345
- 820B100352 Notifies of 820729 briefing in Germantown. MD. in response to inquiries re-status of final technical criteria for disposal of high level radwaste in geologic repositories BELL.41 J High Level Waste Licensing Management Branch. 82/07/20 Affiliation Unknown 7pp 14308 324
- 8208100355 Responds to 820706 request for briefing on 10CFR60 Briefing scheduled for 820727 in Germantown MD BELLIM J Nigh Level Waste Licensing Management Branch 82/07/23 BALLARD W. W Energy, Dept of ip, 14308 273
- 820B110011 Comments on May 1982 monthly rept for "Environ Cleanup Btds." No changes to costs or final delivery of contracted products authorized, FLORY.C A Uranium Recovery Licensing Branch FIN B-2216 82/07/28 WOGMAN.N A Battelle Memorial Institute, Pacific Northwest Laboratory. 2pp 14330 294

- 8208110037 Forwards bibliography of documents on health effects from low level radiation & radon in response to request SCARANO, R A Uranium Recovery Licensing Branch 82/07/12 SCOTT, T Piedmont Environmental Council, Warrenton, VA 4pp 14330 299
- 8208/20367 Forwards table prepared in response to request to locate & describe domestic & foreign deep underground mines.
 TIKTINBKY,D High Level Waste Technical Development Branch 82/07/28 MILLER,H J High Level Waste Technical Development Branch 5pp 14332 332
- 8203120373 Forwards first draft of branch technical position on borehole & shaft sealing Copy being sent to J Daeman (Univ of AZ) for technical review OPS Flan 31231281 satisfied OREVES.J T High Level Waste Technical Development Branch 82/07/30 MILLER, H J High Level Waste Technical Development Branch 1p 14332 337
- 820Bi30453 Requests review of environ assessment of waste form selection for high level waste Assessment evaluates environ impact for selection of borosilicate glass as waste form for immobilization of Savannah River waste
 BDYLE,R R. High Level Waste Technical Development Branch 82/07/29
 COOK,F R. High Level Waste Technical Development Branch, KIM,K.,
 MCNEIL,M B. Waste Management Branch 2pp 14354 350
- B20B130455 Trip rept of 820711-18 course on applied rock mechanics held at Univ of CArDavis NATARAJA:M B High Level Waste Technical Development Branch B22/07/23 OREEVEB.J T High Level Waste Technical Development Branch 4pp 14354-352
- 8208170008 Trip rept of attendance at joint chapter symposium of Health Physics Soc in Harrisburg, PA Presentations covered theoretical & experimental findings in internal dosimetry Detailed symmany encl NEUDER, 8 M. DRAGONETTE, K. B. Low Level Waste Licensing Branch. B2/07/27 HAWKINB, E.F. Low Level Waste Licensing Branch 4pp 14373 236
- 820B170065 Forwards description of how confidence interval can be determined for contours in tradeoff plots Analysis indicates probabilities shown on tradeoff plots within 12% of actual probabilities, w/confidence of 70% BILLING. S A High Level Waste Licensing Hanagement Branch B2/07/29 KNAPP.M.R High Level Waste Licensing Management Branch
- 8208170368 Forwards "Basalt Waste Isolation Project Document Review "
 MILLER, H J High Level Waste Technical Development Branch
 B1/09/30 MARTIN, J B Division of Waste Management ip.
 14371 036
- --8208170369 "Basalt Waste Isolation Project Document Revisu "
 * High Level Waste Technical Development Branch 81/09/28, 44pp 14371 057.
- B20B170370 Forwards trip rept of 801202-03 Baselt Waste Isolation Project annual review meeting & 801204 meeting w/Rockwell. PRESTHOLT.P T High Level Waste Technical Development Branch 81/01/16 BELL.M J High Level Waste Technical Development Branch 1p. 14371 101
- 8208170373 Forwards trip rept of 810922-25 site visit to Hanford Baselt Waste Isolation Project re plans for hydrologic investigations MARTIN.8. Division of Waste Management 81/12/15. MEYER.8 Energy. Dapt of. 2pp 14371-117
- --8208170374 Trip rept of 810922-25 site visit to Hanford Basalt Haste Isolation Project re plans for hydrologic investigations BRGDKS, D. J. HARTUNG, L., LEHMAN, L. Division of Waste Management. BI/11/30 NRC No Detailed Affiliation Given 150pp. 14371:119.
- 8208170375 Forwards trip rept of 800707-17 visit to assess current siting studies for Hanford Basalt Waste Isolation Project Experience beneficial in developing regulatory & guidance documents & in planning technical programs.

 BELL, M J High Level Waste Licensing Management Branch. 80/09/17.

 HEATH, C Energy, Dept. of, 2pp 14371;257

- --820Bi7037B Trip rept of 800707-17 visit to assess current siting studies for Hanford Baselt Haste Isolation Project HARTUNG.L., LEHMAN.L., SIEPKEN.D. High Level Waste Licensing Hanagement Branch 80/09/17, NRC No Ostailed Affiliation Given 46pp 14371 239
- 8208180204 Advises that C Harwood should be contacted to establish technical assistance contract number for work re reviewing GA programs for high level waste facilities MILLER. H J High Level Waste Technical Development Branch B2/07/19 HARSB.W.P Quality Assurance Branch. 2pp. 14390 362
- 8208190007 Accepts invitation to participate on interagency review board for chemical waste incinerator ship program TC Johnson will become participating member BROWNING.R E Division of Waste Management 82/07/23 CHAPMAN, 9, D. Environmental Protection Agency ip 14506-317
- 8208190012 Requests loan of documentary film on Biskan Tunnel const for Visuing by interested parties NATARAJA,M S High Level Haste Technical Development Branch 82/07/26 KUMABARA:Y Japan 1p. 14506:340.
- 8208190016 Responds to 820520 ltr re equation used in NUREO/CR-1759, Vol. 3. to model wind suspension of dust from low level waste disposal sites Equation obtained from U mill tailings GEIS & used to stimate bound level of impacts from wind erosion LOHAUS.P H Low Level Waste Licensing Branch. 82/07/26. CULKOMSKI,W.H. Commerce.Pept of, National Disenographic & Atmospheric Administration 3pp 14506:341.
- 820Bi90020 Forwards comments on "NHTB Conceptual Ref Repository Description (CRRD)" prepared by Bechtel Comments also applicable to design efforts underway for baselt & tuff sites.

 CREEVES. T High Level Waste Technical Development Branch 82/07/29. SIEIN.R. Energy, Dept of 3pp 14306 344.
- 8208190091 Summary of L Dressen of Chem-Nuclear Sys. Inc 820618 presentation re proposed waste mgt facility in wastern Hontrose County, CD.
 PANOBURN.O C Low Level Weste Licensing Branch 82/07/08 SHITH.R D Low Level Waste Licensing Branch. 5pp. 14507 035
- 820B190341 Forwards response, affirming NRC assistance to Btate of CD 820516 request for technical assistance in evaluating low level waste disposal facility application SHITH.R D. Low Level Waste Licensing Branch WM-82-488 82/07/30. NUSBBAUMER.D.A Assistant Director for State Agreements Programs Jpp 14506 150
- 8208190345 Trip rept of 820615 visit to State of CO Health Dept to discuss status of announced low level waste disposal facility for western CD.

 SMITHARD, Low Level Weste Licensing Branch 82/07/01 MARTIN. J B.

 Division of Waste Management 37pp. 14506: 193
- 8208230441 Forwards proposed agenda for 820809-12 waste package/ geochemistry workshop WRIOHT, R. J. High Level Waste Technical Development Branch. 82/08/03 BOUINES, D. J. Energy, Dept of 3pp 14529.073.
- 8208260559 Comments on Edgement cleanup action program Hay 1982 monthly rept No changes to costs or final delivery of contracted products authorized FLORY, C.A. Uranium Recovery Licensing Branch FIN 8-2217, 20529. 62/07/30. WOOMAN A Battelle Memorial Institute, Pacific Northwest Laborstory. 2pp. 14572.301
- ---B2082A0564 Forwards 1tr rept, "Edgement Remedial Action Program" for May 1982 W/a encl JACKBON, P.O., PERKINS, R.W., MOGMAN, N.A. Battelle Hemorial Institute, Pacific Northwest Laboratory. FIN B-2217 20529 82/05/14. EADIE, O.O. Uranium Recovery Licensing Branch. 1p. 14572:303
- B20B3i04B7 Forwards summary of B205i7-i9 sits visit & meeting w/DOE at NV test site re scope of siting investigations. List of site & design suitability issues encl Transmittal of issues listed closes one action item listed in meeting summary. COPLAN.B.M. High Level Waste Technical Development Branch, B2/0B/09. VIETH.D L. Energy, Dept. of 42pp 14705:015.
- ---8208310487 "Siting & Design Suitability Issues for NV Nuclear Waste Storage Investigations " # Division of Waste Management 82/08/31. 14pp. 14705:057.

XPORTLIC EXPORT AND IMPORT LICENSES

- 8208020455 License for Nissho Iwa: American Corp to export 4 08 kg U-235, contained in 20 5 kg U, to Japan ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards ODE 31-64 82/07/13 2pp 1488 025
- 8208030044 Requests Executive Branch position re Transnuclear, Inc application for license to export highly enriched U to The Netherlands ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards 82/07/01 STOIBER, C R State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs in 14208 327
- 8208030046 Informs that License XSNM-1954 may be issued No matl changed circumstances since issuance of License XBNM-1940 MODRE,R N Assistant Director for Export/Import & International Safeguards 82/07/19 Assistant Director for Export/Import & International Safeguards 1p 14208 329
- 8208030049 Informs that License XSNM-1955 may be issued No matl changed circumstances since issuance of License XBNM-1940 MODRE, R N Assistant Director for Export/Import & International Safeguards 82/07/19 Assistant Director for Export/Import & International Safeguards 1p 14208 328
- 8208030054 Informs that License XSNM-1944 may be issued No matt changed circumstances since issuance of License XSNM-1940 MODRE.R N Assistant Director for Export/Import & International Bafeguards 82/07/19 Assistant Director for Export/Import & International Safeguards ip 14208 337
- 8208030076 License for Westinghouse to export specially designed & prepared nuclear fuel assembly components to Sweden IMMERHAN.J V Assistant Director for Export/Import & International Safaguards ILS-172 B2/07/20 ip 14200
- 8208030079 Amend 1 to Mitsubish: Intl Corp export license, extending superation date from 820831 to 840831 IMMERMAN.J V. Assistant Director for Export/Import & International Safeguards HSA-5481-10 82/07/21 1p 14200 348
- 8208030082 Submits application to amend import license, increasing quantity to 16 kg U.containing 8 kg U-235
 JOHNEON, C R Nuclear Assurance Corp CRJ/62/155/ETS 82/07/15
 Assistant Director for Export/Import & International Safeguards 1914200 346
- 8208030711 Informs that License XSNM-1959 may be issued No matl changed circumstances since issuance of License XSNM-1932 MORE:R N Assistant Director for Export/Import & International Safeguards 82/07/12 Assistant Director for Export/Import & International Safeguards 1p 14196 301
- 8208030714 Forwards application for license to export 30 075 kg U. containing 28 060 kg U-235, to The Netherlands
 HANNSTT, B A Transmuclear, Inc 82/07/13 MODRE, N Assistant
 Director for Export/Import & International Bafaguards 1p.
 14195 346
- --B208030718 Application for license to export 30 075 kg U, containing 28 060 kg U-235 to The Netherlands
 HANNETT-B A Transnuclear, Inc. NUK-408 82/07/13 3pp
- 8208030722 Application for license to export six compensated ionization chambers to France POCHAL,N.F. Westinghouse Electric Corp. ZE401168-3 82/07/09 3pp. 14196-334
- 8208030726 License for Eberline Instrument Carp to export 0.086 mg PU-239.contained in one PU-239 calibr source to Taiwan ZIMMERHAN.J V Assistant Director for Export/Import & International Bafguards 82/07/16 ip 14196 300
- 8208040078 Amend 1 to Mitsuf Air Intl.Inc export license, increasing total value of equipment ZIMMERMAN.JV. Assistant Director for Export/Import & International Safeguards 82/07/26 ip 14228 293
- B208040082 Amend 1 to Edlow Intl Co export license, adding B&W.
 Lynchburg: VA as alternate location for supplier
 ZIMMERHAN.J V Assistant Director for Export/Import & International
 Safeguards KLK-5.6-8 82/07/29. ip. 14228-300

- B20B040097 Amend i to QA Co export license, changing address of ultimate consignee & increasing quantity of exported math to 6 03 g U-235, contained in 30 19 kg U ZIMMERMAN, J. V Assistant Director for Export/Import & Internationa) Safeguards IEL-1161 82/07/29 ip 14228 337
- 8208040105 License for Teknis.Inc to export 200 mCi tritium as sealed source,to United Kingdom ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards TUK-0843 82/07/29 ip 14228 340
- 8208040107 License for Mitsui Air Intl. Inc to export miscellaneous specially designed parts & components, to Japan ZIMMERNAN. J V Assistant Director for Export/Import & International Bafeguards 82/07/29 ip 14228 341
- 8208040111 License for Westinghouse to export six compensated ionization chambers. Model WL23944, to France 21MMERMAN.J V Assistant Director for Export/Import & International Bafaguards ZE-40116 82/07/30 Ip 14228 343
- 8208040115 Application for license to export 29,032 kg U, contained in U dioxide powder.to Japan w Marubeni America Corp (subs of Marubeni Corp) ZH-0261-DH 82/07/19 2pp 14228 347
- B208040117 Submits application for license to export Zircalay tubing to Normay UDZNIAK.D R Carpenter Technology Corp 82/07/21 HEMBY.E Assistant Director for Export/Import & International Safeguards 3pp 14228 344
- 8208040123 Requests Executive Branch position to Carpenter Yechnology Corp application for license to export Zircalay tubing to Norway ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/07/28 STOIDER, C R State, Dept of, Bureau of Ocean & Internati Environ & Scientific Affairs 1p 14228 331
- 8208040191 Advises of GE plan to transfer ownerthip of remaining SNM exported to NUKER in West Dermany originally exported for mfg into GETR fuel Transfer involves 106 kg U-containing approx 99 kg U-235
 WILSON & D General Electric Co BDM-058-82 B2/06/09
 ZIMMERMAN J V, Assistant Director for Export/Import & International Safeguards 2pp 14232 264
- 8208040214 Submits application to amend export license, extending expiration date from 830831 to 840831
 8HIMA: S Mitsubishi International Corp (subs of Mitsubishi Corp.)
 MSA-4841-10 82/07/15 WRIGHT.8 Assistant Director for Export/Import & International Safeguards 1p 14202 280
- 8208040238 Application for license to export nuclear fuel assembly components to Busden HERBCH. M M Westinghouse Electric Corp. ILS-172 82/07/16 ip-14273-2746
- 820804045i Forwards Reuter-Stokes 820707 itr requesting withdrawal of export license application to export five in-core fission chambers to Malaysia W/o encl
 ZIMMERNAN.J V Assistant Director for Export/Import & International Safeguards 82/07/14 STOIBER,C R State,Dept of, Dureau of Ocean & Internati Environ & Scientific Affairs 1p 14220.262
- 8208060024 Advises that Amend 1 to license to export components to Japan, was issued w/o 15-day waiting period ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/07/26 Assistant Director for Export/Import & International Safeguards, Ip 14244-342
- 8208060043 Submits application to amend export license, increasing tota value of export
 TSUKUDA.T W Mitsul & Co (U S A). Inc (Subs of Mitsul & Co .Ltd) 82/08/03 WRIGHT. B L Assistant Director for Export/Import & International Safeguards ip 14282 083,
- 8208050099 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl IIMMERMAN.J V Assistant Director for Export/Import & International Safeguards. 82/07/23 GRIFFIN.J A Energy, Dept. of ip. 14283.209
- 8208060104 Bubmits application to amend export license, providing alternate location for supplier SHAM. A Ediow International Co 82/07/28. WRIGHT, B Assistant Director for Export/Import & International Bafeguards ip 14283 210

- 8208110227 Forwards 820425 ltr of assurance re 810629 application to export 6 547 kg U.contained in 7 018 kg total U.to Greece DEVINE.J B State.Dept of. Bureau of Oceans & Internati Environ & Scientific Affairs 82/07/08 SHEA.J R Office of International Programs. Director 1p 14330 307
- --B208110227 Ltr of assurance re 810629 application to export 6 547 kg U, contained in 7 018 total U.to Greece MARCHAL, J European Communities, Commission of 82/06/25 GRIFFIN, J A Energy, Dept of ip 14330 308
- 820Bi30019 Application for license to export fission chambers to Canada POCHAL.W F Westinghouse Electric Corp V2A00079. 82/06/28 ip 14341 363
- 8208130035 Executive Branch position re GA Co application to export add1 1,080 g U-235, in 5,430 g U, to Malaysia Amend should be granted
 - be granted

 DEVINE, J 8 State, Dept of, Bureau of Oceans & Internati Environ &
 Scientific Affairs 82/07/21 SHEA, J R Office of International
 Programs, Director 2pp 14340 362
- 8208180116 Executive Branch position re Reactor Experiments, Incapplication to export 0 3661 g Th-232 to Vietnam License should be returned to applicant w/o action
 DEVINE, J B State, Dept of, Bureau of Oceans & Internati Environ 8
 Scientific Affairs 82/07/29 SHEA, J R Office of International
 Programs, Director 1p 14391 001
- 8209180258 Executive Branch position re Saunders-Roe Development. Inc application to export addi 300.000 Ci tritium to United Kingdom Amend should be granted DEVINE. J B State. Dept of Bureau of Oceans & Internati Environ Scientific Affairs 82/07/30 SHEA. J R Office of International Programs, Director ip 14389 290
- 8208180273 Executive Branch position re GA Co application to export instrumentation to Egypt License should be granted DEVINE.J D State.Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 82/07/30 SHEA.J R Office of International Programs, Director 2pp 14389 325
- 820Bi90082 Application for license to export 170 upper tie platus & 170 lower tie plates to Italy DID GUARDIA.J Luigi Serra, Inc 828-528 82/07/22 4pp 14507 040
- 8208230117 Forwards IE Bafeguards Insp Rept 110-02434/82-01 on 820622 of activities under Export License X8NM-1803 No noncompliance noted NORDERRAUG, L. R. Division of Radiological Safety & Safeguards Program 82/08/12 MONDEN, T. Mitsui & Co. (U.S.A.), Inc. (Subs. of Mitsui & Co., Ltd.) 2pp. 14514-336
- --B208230124 IE Bafeguards Insp Rept 110-02434/82-01 on 820720 No noncompliance noted Major areas inspected shipping drum identification & tamper seal numbers, gross drum count & damper seal integrity Details withheld (ref 10CFR2 770) WIEDER, A., IVEY, L., ZURAKOMEKI, P. Division of Radiological Safety & Safeguards Program 82/08/12 1p 14514 338
- B208230473 Requests that 820707 application for license to import Cs-137 from West Garmany be granted at earliest possible date, in order to obtain user license in State of MI VENKAT.C K Wiegand Evaporators, Inc 4834 82/08/06 WRIGHT, B Assistant Director for Export/Import & International Safeguards ip 14528 241
- ---8208230494 Forwards application for license to import two units, each containing 1,000 mCi Cs-137, in form of glass beads, from West Oprmany VENKAT.C K Wiegand Evaporators, Inc. 4731 B2/07/07 MDORE,R N Assistant Director for Export/Import & International Safeguards Bpp 14928 242
- ---B20B230496 Application for license to import two units, each containing 1,000 mCi Cs-137, in form of glass beads, from West Germany VENKATACHAIAM Wiegand Evaporators, Inc. B2/07/07 ip 14828 250
- B208240013 Ltr of assurance re GE application to export 1,358 kg U-235, in 50,329 kg U,to Japan BHIRAKAMA,T Japan 82/08/03 GRIFFIN,J A. Energy, Dept of. 1p 14529 226
- B20B240077 Submits application to amend export license, extending expiration date to 8B010i.revising intermediate consignees to increasing quantity to 3,055 kg U-235 in 126,585 kg U HILBON.B D General Electric Co. BDW-074-82 B2/08/05 WRIGHT.B L Assistant Director for Export/Import & International Bafeguards 2pp 14548 loi

- 8208240082 Submits application to amend export license, extending expiration date to 880101, revising current intermediate consignees & adding intermediate consignees WILSON, B D General Electric Co BDW-073-82 82/08/05 WRIGHT, B L Assistant Director for Export/Import & International Safeguards 2pp 14529 308
- 8208240086 Submits application to amend export license, extending license for add1 6 months
 YAMANA, K Nissha-Iwai American Corp MACPJ 3964KY 82/08/04
 MOGRE, N Assistant Director for Export/Import & International Safeguards tp 14529 307
- 8208240088 Forwards application to export 300 Ci tritium, as elemental gas in glass pellets, to United Kingdom
 WIDMAN, J C KMS Fusion. Inc (Bubs of KMS Industries, Inc.)
 RSG-201-JCW B2/08/04 Assistant Director for Export/Import & International Bafeguards ip 14529 310
- ---B208240074 Application for license to export 300 C1 tritium, as elemental gas contained in hollow glass pellets, to United Kingdom HIDMAN J C KMB Fusion, Inc (Subs of KMB Industries, Inc). KMSF-882-RU B2/08/03 2pp 14527 311
- 6208240097 Forwards application for license to import damaged fuel rods or assemblies, containing U dioxide fuel pellets, from Taiwan License requested to cover return of fuel rods/assemblies for repair & reshipment, as necessary KIEL, O R Exxon Nuclear Co., Inc. (subs of Exxon Corp.) B2/08/04. DEVINE, J B Assistant Director for Export/Import & International Bafeguards 2pp 14827 302
- 8208240104 Application for license to export compounds containing deuterium. w/equivalent of 5 kg deuterium oxide liquid over 2-yr period to India 8 Bigma Chemical Co D-95 82/08/02 1p 14529 281
- 8208250087 License for Rare Earths.Inc to export 2.000 lb thorium oxide to Ganada JOHNETON,L E Atomic Energy Commission 56/11/16 1p 14560 059
- 8208250554 Application for license to export 1 5 kg thorium oxide powder.containing 1 318 kg thorium to Czechoslovakia. COLTON, E Cerac. Inc 82/08/02 1p 14562 205.
- 8208260045 Forwards application for license to export 2 g U.containing 1 79°g U-236 & 0 1858 g U-235, to India HOADLEY, 8 D Homeanto Research Corp 285-81AO 82/08/04 GPLINGER, 0 Assistant Director for Export/Import & International Bafeguards 1p 14575 065
- --B2082&0053 Application for license to export 2 g U.containing 1 79 g U-236 & 0 1858 g U-235 to India HOADLEY, 6 Monsanto Research Corp 285-B1AD 82/08/04 ip 14875 0AA
- 8208260061 Forwards application for license to export 5,030 g U
 Zirconium hydride, contained in TRIGA fuel elements, to
 Yugoslavia
 MOMRY, W R GA Technologies. Inc /General Atomic Co IEL-3094.
 BZ/00/04 ZIMHERMAN.J Assistant Director for Export/Import &
 International Bafeguards lp. 14575 067
- --8208240049 Application for license to export 5,030 g U Zirconium hydride.contained in IRIOA fuel elements to Yuposlavia. MONRY, W R. GA Technologies, Inc /General Atomic Co IEL-3094 82/08/04 ip 14575,068
- 8208260327 Requests that application for license to export Th-232 metal foil to Vietnam be withdrawn HEIMAN.D Reactor Experiments, Inc. 82/08/02. ip 14576 103
- B20B260330 Application to amend export license, extending expiration date for 3 yrs from date of issuance of amend MOMRY.W R OA Technologies. Inc /Qeneval Atomic Co B2/07/28 ZIMMERMAN, J Assistant Director for Export/Import & International Bafeguards 1p 14576 102
- 8208260332 License for Westinghouse to export 2 8 g U-235 contained in 90.1 g U.to Japan.
 ZIMMERMAN, J V. Assistant Director for Export/Import & International Safeguards ILS-150 82/08/13 2pp 14576 099
- 8208260333 Licanse for Transnuclear.Inc to export 35 543 kg U-235, contained in 38 095 kg U, to the Netherlands ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards (NUK-375) 81-16 82/07/30 2pp. 14576 097

NONDOCKETED ITEMS

- 8208260337 Amend 4 to Saunders-Roe Development. Inc export license, extending expiration date from 820915 to 830915 & increasing quantity of mail from 1.000,000 Ci tritium as tritium gas to 1.300,000 Ci tritium as tritium gas ZIMMERMAN.J V Assistant Director for Export/Import & International Bafaguards 82/08/05, 1p 14376 101
- 8208260342 Amend 3 to OA Co export license, extending expiration data from 820901 to 850901. ZIMKERMAN.J V. Assistant Director for Export/Import & International Safeguards 82/08/04 ip. 14375 271
- 9208260347 Application for license to import 44.367 kg U herafluoride, containing 1.050 kg U-235, from France BHAW, A Ediow International Co 92/09/03. ip 14575 270
- 8208270662 Forwards application for license to export 19,749 kg U.
 enriched to 3,2%,to Japan
 # Mitsubishi International Corp (subs of Mitsubishi Corp)
 HBA-5482-05. 82/07/22 Assistant Director for Export/Import &
 International Bafeguards 2pp 14683 198
- --9208270665 Application for license to export 19,769 tg U.enriched ta 3.2% to Japan End use statement encl BHIMA.B Mitsubishi International Corp (subs of Mitsubishi Corp) H8A-5482-05, 82/07/21 2pp 14683 196
- 8208310004 License for Transnuclear, Inc to import 22,900 kg U, enriched to max of 0.91% U-235, from France IIHMERNAN, J V. Assistant Director for Export/Import & International Bafeguards, 82/08/13 1p 14697 131
- 8208310041 Ltr of assurance re OE application to export 280 kg U-235, contained in 10,276 kg U to Japan.

 BHIRAKAWAT. Japan. 82/08/03. GRIFFIN.J A Energy. Dept of. Ip 14697:201.
- 9208310049 Ltr of assurance re Wastinghouse application to export 2.8 g U-235 contained in 90 i g U.to Japan 8HIRAKAMA.T. Japan 92/08/03. GRIFFIN.J A Energy, Dept of. ip 14697-196.

- 8208310056 Executive Branch position re Reactor Experiments, Inc application to export 0 102 microgram U.enriched to 93 15%, to Egypt Litense should be granted DEVINE, J B Btate, Dept of, Bureau of Deeans & Internati Environ, & Scientific Affairs 82/07/30 BHEA, J R Office of International Programs, Director ip 14697 195
- 8208310059 Executive Branch position re Transnuclear, Inc application to smend license, increasing quantity to 94, 513 kg U-235 for export to Canada Amend should be granted DEVINE, J B Btate, Dept of, Bureau of Doeans & Internati Environ & Scientific Affairs 82/07/07 SHEA, J R Office of International Programs. Director 2pp 14697 242
- 8208310490 Amend 3 to Nissho-Twai American Corp export license, extending expiration date from 820901 to 830331 ZIMMERMAN.J V Office of International Programs, Director NIAC-78-003 82/08/13 ip 14697 295
- 8208310493 License for GA Co to export miscellaneous specially designed or prepared parts & components, including multirange picoameter, linear & wide range power channels & flux controller, to Egypt ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards IEL-1053 82/08/06 ip 14697 294
- 8208310496 Forwards application for license to export 7,462 kg U, enriched to 2 8% to Japan SHIMA, B Mitsubishi International Corp (subs of Mitsubishi Corp), HSA-5482-06 82/07/21 Assistant Director for Export/Import & International Bafeguards 3pp 14697 289
- --8208310498 Application for license to export 7,462 kg U, enriched to 2 8% to Japan End use statement encl
 SHIMA.9 Hitsubishi International Corp (subs of Mitsubishi Corp). H8A-5492-06 82/07/21 2pp 14697 287

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this Index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

									**************************************	SUBJE
AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	CATEODR'	Υ	AUTHOR	ACCESSION NUMBER	CATEG
AAMODT, M M	8208090238	50-289	G	ALEXICH, H P	8208020156	50-315	P	AXELRAD, M	8208170258	50-498
AAMODT, M M	8208090240*	50-289	ō.	ALEXICH, H P	8208040173	50-315	P	AXELRAD, M	0208170250	50-478
AAMODT, M M	8208250270	50-289	Q	ALGER, D H	8208310377*	50-186	R	AXELRAD, M	8208250248	50-49E
AAMODT, H H	8208250281	50-289	ō	ALGERMISSEN, S	8208020349	50-522	A	AXELRAD, M	0200250246	50-498
AAMODT, N O	8208110192	50~289	Q	ALKER, P	8208270501	50-352	H	AXELSON.W L	6208090241*	50-275
ABELSON, H	8208110040	50-352	Α	ALMOND, J	8208260345*	50-349	F	AXELBON, W. L	6208130337*	50-344
ABELSON, H	8208120003	50-352	A	ALTER: 8	8208020275	50-247	O	AXELSON. W L	0200200210*	50-255
ABELSON, H	8208230129	50-352	A	ALTO, R A	8208160424	70-1201		AXELSON, W L	8208200228 * 8208270142 *	50-10
ABELSON, H	8208240469	50-352	A	AMERINE, T E	8208160480	PR	_	AXELBON, W L	0208270395*	50-10
ACKERMAN, W C	8208040252	40-277		AMRHEIN, L	8208030074*	50-537	D	AXELBON, W L		
ADAMS, B S	8208020286	50-537	н	ANANDAPPA. A	8208020186*	50-237	S	AXELSON,W L BABBITT,D L	8208270527* 8208260467*	50-254 CONTRA
APAMS.J W	8208040050	HES		ANANDAPPA, A	8208030340# 8208130057#	50-237	\$	DACHMANN R G	8208100031	50-266
ADAMS, K. Q	8208260414	NUREG	_	ANANDAPPA, A	#E908130047#	50-237	8	BACHMANN R Q	8208100076	50-266
ADAMS, T E	8208040166*	50-367	P F	ANANDAPPA, T	8208310074*	20-382	Č	BACHMANN, R Q	8208120009	50-266
L RAYEDA	8208160340	50-245	r	ANDERSON, C J			-			
ADDY, R J	B20B160434	50-213	F	ANDERSON, Q C	8208040213	50-409	G G	Bachmann, R. G Bachmann, R. G	8208130005 8208160219	50-155 50-266
ADENSAM, E 0	8200030021	50-327	P	ANDERSON, P	8208120119	50-266 50-266	Q	BACHMANN, R G	6208170291	50-170
ADENSAM, E O	8508030053*	50~327	P	ANDERSON, P	8208270448 8208020358	50-537	H	BACHMANN, R G	8208180118	50-266
ADENSAM, E Q	8208030029*	50-327	P	ANDERSON, R	8208040185	REVIEW C		BACHMANN, R O	8208180123*	50-266
ADENBAM, E G	8208060343	50-390	A	ANDERSON, R T						
ADENSAM, E G	8208110058	50-460	A	ANDOGNINI, G C	8208300251	RECOD		BACHMANN R O	9208250224 8208250232#	90-155 50-155
ADENSAM, E 9	8208110061*	50-460	A	ANDREWS, D L	8208160406*	50-327	a	BACHMANN, R. O	8208250232*	50-155
ADENBAM, E G	8208170346*	50-329	D	ANDRUB, N. J	8208040295	40-4492		BACHMANNI R. O	8208070264	30-155
ADENBAM, E G	8208170349	50-327	D	ANFIN, W L	8208190304*	50-413 50-413	A	BACHMANN,R J BAEHR,D G.	8208260414	NURED
ADENSAM, E G	8208170352	50-329	D	ANFIN.W L	8208190314*					
ADENSAM, E Q	8208170355	50~327	D	ANO, W P	8208030224*	50-250	Q	BAER, R E	8208100070* 8208250090	50-382 71-370
ADENSAM, E G	8208170380	50-522	A	ANKLAM, T M	8208260080	NUREO		BAGBY, L. A. BAILEY, R. J	6208020293*	50-322
ADENSAM, E O	8208240462	50-329	D	ANSLAM: I D	8208260087 8208030692	PR		BAILEY, R. J.	8208050299*	50-322
ADENSAIT, E G	8208260483 8208270606*	50-413 50-413	A D	ANNAL, J M ANTIO, H A	8208030442	50-29	R	BAIR, O G	8208100054*	50-344
ADENSAM, E Q									B208200296*	50-344
ADENBAM, E 0	8208270610*	50-413	D	ANTIO R H	8208270550*	50-29	R	Bair.0 C. Baisden L.	8208060364	CONTRA
ADENSAM, E G	8208270613*	50-413	D	APLEY, W J	8208130475	NUREQ 50-317	a	BAISDEN, L.	8208120378	CONTRA
ADENSAM, E G	8208270617*	50-413	D	ARCHITZEL, R E	8208050429* 8208060170	50-317	P	BALDWIN, C. A.	8208260479	NUREO
ADENSAM, E G ADENSAM, E. G	8208270683 8208310001	50-329 50-329	A F	ARCHITZEL, R E ARCHITZEL, R E	8208170104*	50-317	à	BALL.C G	8208020066#	CONTRA
			•		8208300203*	50-317	0	BALLINGER. B L	6208120042*	50-298
ADLER, B	8208040095*	50-537	D	ARCHITZEL, R E ARLOTTI, M. O	8208030567*	TOPREP	ч	BALLUN, J Y	8208120255*	50-416
ADLER R_W	8208270470	50-287	o	ARLOTTI, M G	8208030573*	TOPREP		BALLHEO, T. O	8208100097	50-329
AGEE, J. R	8208310341*	0A999 0A999		ARLOTTI, M Q	8208030578*	TOPREP		BAME. D.	8208240412*	50~528
AGEE, J R AHMED, I	8208310401* 8208050042*	50-293	P	ARLOTTI, H G	8208030583*	TOPREP		BANKS, H R	8208030497*	50-400
• • • • • • • • • • • • • • • • • • • •			•		8208030588*	TOPREP		BANKS, H R	8208140479	50~400
AHN, T.H	9209250029	RES		ARLOTTI,M 0 ARMSTRONG,W L	8208030588*	MINE		BARAN, R	820B120038*	50-219
AKST, D.	9209250055	FOIA	a	ARMSTRONG, W L	8208130013	50-317	P	BARBER, G	8208160255	50-344
ALBERT, W G	8208140131*	50-508 50-241	u u	ASHBAUGH, C E	8208190160	50-142	F	BARBER, Q	8208190181	100-331
ALBRICHT R H	8208160437* 8208160526*	50-241	G G	ASHBURN, D J	8208300171	PR		BARIJR	8208310075*	FOIA
ALBRIGHT:R H								BARKER, D G.	8208030197	50-4 7 8
ALDEN, W M	8208190102*	50-277	R	ASPIN, L	8204200038*	50~320 50~\$37	U	BARLETT, D L	8207110003	70-143
ALDERSON, C E	8208030706*	50-400	G .	ASSELSTINE, J K.	8208190131 8208310075*	50-33/ F01A	w .	BARLETTA-R E	8208040050	RES
ALDERSON, C E	8208140370*	50-335	G C	ATEFI. B	8208250423	71-5768		BARNARD, E M	8207050006*	ACRE
ALDERSON, C E	8208160377*	50-261	a	AUSTIN, M A	8208120217*	50-286	R	BARNES: I	8206150035*	FOIA
ALESII. Q	8208310347*	TOPREP		AUTER IND. L						9A779
ALESII. 0	8208310353*	50-397	E	AUTIO: H. A	8208020292	50-29	8	BARNES, I BARNES, I	8208160227* 8208160304*	GA777
ALESSO, H P	820629016B*	FOIA		AUTIO, H A	8208090050	50-29	8	BARNES, I	8208140372*	0A999
ALEGSO, H P	8206290171*	FOIA		AUTIO H A.	6208070118 6208230032	50-27	9	BARNES, I.	8208160413*	0A777
ALESBO, H P	8208310065*	FOIA		AUTIO, H. A	8208230032	50-27	8	BARNES, I.	8208190209*	GA999
ALEXANDERBON, E	8208240147*	50-16	R	AUTIO, H A	0KU0K3001K	20-m.t	₩			

AUTHOR	ACCESSION NUMBER	SUBJE CATE		AUTHOR	ACCESSION NUMBER	CATE		AUTHOR	ACCEBSION NUMBER	SUBJI CATE	
Barnes, I Barnes, I Barnes, I Barnes, I Barnes, I	8208190276 8208190280 8208190295 8208200064 8208310124	• QA999 • QA999 • QA999		BAUSER.D B BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A	8208130143 8208130143 8208130143 8208130149 8208130149	50-400 50-400 50-312) G	BERKOWITZ, L DERLINGER, C H BERNABEI, L BERNABEI, L BERNABEI, L	8207260247 8208170070 8208030331 8208030331 8208030331		9 0 B 0
Barnes, I Barnes, I Barnes, I Barnes, I Barnes, I	8208310138 8208310139 8208310244 8208310280 8208310321	* QA999 * QA999 * QA999		BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A	8208130160 8208130160 8208130164 8208130164 8208130181	50-400 50-400) G	BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L	8208040264 8208090150 8208090150 8208190116 8208190116	50~356 50~356 50~356 50~526 50~526	B 0
BARNEG, I BARNHART, B BARNHART, B BARR, K BARR, K	8208310454 8208040442 8208130448 8208100157 8208030145	* 50-321 * 50-259 50-260	р 5	BAXTER,T A BAXTER.T A BAXTER.T A BAXTER,T A BAXTER,T A	8208130181 8208130200 8208130200 9208100139 9208160139		0	BERNABEI, L BERNABEI, L BERNABEI, L BERNARD, H BERNARD, H	8208240362 8208240362 8208240362 0208260379 82082604044	50-350 50-350 50-350 50-27 50-27	9 0
BARR, K.P. BARR, K.P. BARR, K.P. BARR, K.P. BARR, K.P.	82080306104 82080306354 82080306364 82081602144 82081603114	50~280 50~269 50~395	Q Q Q	BAXTER, T A BAXTER, T A BAXTER, T A BAXTER, T A BAXTER, T A	8208170204 8208170204 8208170215 8208170215 8208170221	50-483 50-483 50-400 50-400	G O	BERNARD, H BERNATH, L BERNERO, R M BERNHOFT, B L BERNHOFT, B L	8208260412* 8208030213 8208030286 8208050477* 8208070214*	REVIEW REVIEW 50-305	ORP B
BARR.K P. BARR.K P BARR.K P BARR.K P BARR.K P	8208160375; 8208160437; 8208160526; 8208160529 8208310097	50-241	9 9 8	BAXTER, T A BAXTER, T A BAXTER, T A BAXTER, T A BAXTER, T A	8208170221: 8208180103 8208280289 8208250289	50-400 50-312 50-312 50-483 50-483		BERNHOFT, 8 L BERNHOFT, 8 L BERNHOFT, 8 L DERNHOFT, 8 L BETTENHAUSEN, L	82081301024 8208170081* 8208230161* 8208230172* 8208100100*	50-305 50-305 50-305	8
BARRIK P BARRETTID P BARRETTID P BARRETTID P BARRETTIL	8208310118 8208250093* 8208250105* 8208250119* 8208130211	40-86	9	BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A	8208270426 8208270426 8208270428* 8208270428* 8208270487		000	BETTENHAUSEN, L BETTENHAUSEN, L BETTINGER, R V BEVAN, R, B BEVAN, R, B	8208120104* 8208160063* 8208030020* 8208060050 8208310010*	50-244 50-317 50-275 50-254 CONTRA	Q Q P
BARRETT, L BARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H	8208130267 8208130462 8208170406 8208250062 8208260474	50-320 50-320 50-320 50-320 50-320	B R R R	BAXTER, T A BAY, J H BAYNARD, P Y BAYNE, J. P BAYNE, J. P	8208270487 8208270418 82081 80021 82080 50449 82081 00246	50-287 50-142 50-302 50-286 50-333	0 P P	BHANDARI, D R BIAN, 8 H BIOD, H E BICKWIT, L BIDINER, G H	6206260273* 6206130475 6206030641* 6206110067 6206260085*	TOPREP NUREO 50-335 50-367 70-125	Q
BARRETT, R O BARTH, C. A BARTH, C. A BARTON, J. J BARTON, J. J	8208040434 8208120144 8208270370 8208050272 8208060177	50-537 50-400 50-440 50-320 50-320	H G S G	BAYNE, J.P. BAYNE, J.P. BAYNE, J.P. BAYNE, J.P. BAYNE, J.P.	8208100300 8208130264 8208190162 8208190196 8208190235	50-284 50-333 50-333 50-286 50-333	4 4 4 4	BIDINGER.G H BIELAWSKI,A P BIELAWSKI,A P BIELAWSKI,A P BIELAWSKI,A P	8208040027 8208020254 8208020256 8208030402 8208030402	70-115 50-454 50-454 80-599 50-599	0000
BARTON, J J BASKIN, K P BASKIN, K. P. BASKIN, K. P. BASKIN, K. P	8208100238 8208020214 8208030201 8208030473 8208040287	50-320 50-206 50-361 50-361 50-361	6 t t t	HAYNE, J P P HAYNE, J P HAYNE, J P HAYNE, J P HAYNE, J P	8208200119 8209250143 8208260290 8208270155 8208300224	50-286 50-333 50-286 50-286 50-333	Р Р Р	BIELAWBKI,A P BIELAWBKI,A P BIELAWBKI,A P BIELAWBKI,A P BIELAWBKI,A P	8208160159 8208160159 8208200276 8208270459 8208270459	50-454 50-454 50-454 50-454 50-454	00000
BASKIN, K P. BASKIN, K P. BASKIN, K P BASKIN, K P BASKIN, K P	8208050171 8208050253 8208050487* 8208060214 8208100088	50-361 50-206 50-206 50-206 50-206	P P P	Bayne, J P Bazin, J Beale, K e Bechhoefer, C Bechhoefer, C	8208310420 8208020064 8208110134* 8208040213 8208110140	50-333 CONTRAC 50-395 50-409 50-329	F 0 0	BIERB, D W BILBY, C, R BINOGELI, B L BINGHAM, C D BIRD, W	8208130479 8208110114* 8208050322* 8208300272 8208120223*	NUREO TOPREP 50-295 REGGD 50-329	g A
BASKIN, K P BASKIN, K P BASKIN, K P BASKIN, K P	8208110117 8208120108 8208130085 8208160013 8208160072	50-361 50-206 50-362 50-362 50-361	P A A Q	Bechhoefer, c Bechhoefer, c Bechhoefer, c Bechhoefer, c Bechhoefer, c	8208180114 8208200171 8208240204 8208240228 8208250274	50-329 50-329 50-409 50-498 50-329	0 0 0	BIRD, W BIRDWELL, J E. DIRKEL, R. A BISCHOFF, C A BISCHOFF, C A	8208120224# 8208120177 8208040438 8208020205 8208020205	50-329 50-537 50-369 50-528 50-528	A H P O
Baskin, K. P Baskin, K. P Baskin, K. P Baskin, K. P	8208160101 8208180113 8208190114 8208190145 8208190205	50-206 50-206 50-206 50-206 50-206	P P P P	BECK.G P BECKHAM.J T BECKHAM.J T BECKHAM.J T BECKHAM.J T	8208230270 8208180232 8208030377* 8208030379* 8208030503	90-356 NURE0 90-321 50-321 50-321	R G G P	BISCHOFF,C A DISCHOFF,C A BISCHOFF,C A BISCHOFF,C A BISCHOFF,C A	8208030311 8208030311 8208040118 8208040118 8208200273	50-528 50-528 50-528 50-528 50-528	0 0 T T
Baskin, K. P.	8208200040 8208200192 8208200225 8208230023 8208250092	50-206 50-206 50-361 50-206 50-361	P P P P	BECKHAN, J T BECKHAN, J T BECKHAN, J T BECKHAN, D BECKHAN, D A	8208030508 8208040192 8208260217 8208100333* 8208300280*	PR 50-321 50-321 50-220 50-410	P G G	BISCHOFF.C.A BISHOP.L.L BISHOP.L.L BISHOP.L.L. BISHOP.L.L.	8208200273 8208200232 8208200232 8208200237 8208200257	50-528 50-329 50-329 50-329 50-329	0 0 0
Babkin, k p. Babkin, k p. Babkin, k p. Babkin, k p. Babkin, k p. Babbo, L. F	8208250169 8208250363 8208260300* 8208270377 8208300234	50-206 50-361 50-361 50-361 50-206	P F P	BEELMAN,R J BEIERLE,C BEITELJ J BELAIR,R R BELANGER,J L	8208040004 8208040305 8208300292* 8207050084 8208160122*	RES 50-275 50-387 FOIA 50-255	0 F	BIGHOP, L L BIGHOP, L L BIGHOP, L L BIGHOP, L L BIGHOP, T W	8208200265 8208200265 8208200275 8208200275 8207150400	50-329 50-329 50-329 50-329 50-460	00000
BASSO, L. F. BASSO, L. F BASSO, L. F BASTRON, A. F. BATEMAN, R. P	8208090045* 8208100057* 8208260225* 8208260244* 8208240482	50-317 50-317 50-317 50-318 40-8781	8 8 8 5	BELANGER, J L BELLEHER, R L BELISLE, G A, BELISLE, G A BELL, H J	8208310040* 8208020138 8208030434* 8208160166* 8208100352	50-373 50-166 50-416 50-261 PR	0 R Q	BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8207150428 8208100140 8208100226 8208100260 8208100260	50-50B 50-460 50-460 50-460 50-460	9
BATEMAN, W H BATEMAN, W, H BATES, A BATES, J W BAUER, E Q	8208130479 8208050214* 8208300085* 8208110143 8208030304*	NUREO 50-354 50-354 50-537 70-1113	Q Q Q	BELL.M J. BELL.M J BEMIS.P R. BEMIS.P R. BEMIS.P R	8208100355 8208170376 8208030434* 8208160262* 8208160401*	PR Waste MQ 50-416 50-369	T G G	BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8208160118 8208160124 8208160128 8208160130 8208160130	50-312 50-397 50-275 50-508 50-460	9 9
BAUMER, D. B. BAUSER, D. B. BAUSER, D. B. BAUSER, D. B	8208310134* 8208250193* 8208130153 8208130153 8208190135		0 0 0	BENSON, L BERGER BERGIN. J BERGHAN, P. A BERGHAN, P. A	8208020348 8208200081* 8208240131* 8208040208 8208040213	50-537 40-84 50-336 50-312 50-302	H 8 P P	DISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T. W	8208140259 8208140389 8208140415 8208140485 8208140485	50-508 50-460 50-362 50-397 50-312	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	BUBJEC T CATEODRY
W T, 40H218 B I AOH218 B I T, 40H218 B I T, 28K218 A M, 3NR3U8	8208240172 8208240285 8208270533 8208300068* 8208170303	50-142 Q 50-528 Q 50-361 Q 50-245 Q 50-537 A	BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E A	8208020288 8208030418 8208070078 8208070177 8208070223	50-358 K 50-358 K 50-358 E 50-358 S 50-358 S	Branca, o c Branch, k Branch, k Branch, k Branch, k Branch, m h	6208170184* 6208070019 6208130115 6208130473 6208160125*	GATTY BO-315 P BO-220 P NUREO BO-407 Q
BLACK,R L BLACK,R L BLACK,R L BLACKHELL,E T BLAKE,J	8208060112 8208240277 8208260044 8208050286 8208160236*	50-522	BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E. A BORGMANN, E A	8208070224 8208070227 8208070243 8208100147 8208140231	50-358 8 50-358 K 50-358 8 50-358 8 50-358 8	BRANCH, M W Brandenburg, B Brandenburg, B Brandt, M Braun, N &	9208300274* 9208170285 9208170123* 9208200083* 9208020348	50-409 Q 50-247 Q 50-247 Q 50-409 8 50-537 H
BLAKELY,H W BLAYLOCK,J BLAZEY,D R BLEJWAS,T E BLOCK,P B	8208120292 8208020302* 8208240449 82082404112 8208110072	50-537 H 70-36 50-289 G NUREQ 50-155 G	BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGT, F J BOUCHEY, G D	8208230110 8208240085 8208310244 8208270592* 8208020130	90-358 8 50-358 8 50-358 Q 50-267 R 50-397 A	BRAUND, C BREAUX, D O BREED, A BRENNER, L BRENNER, L	8208050441* 8208200054* 8208240083 8208110214 8208280258	50-237 Q 50-498 Q TOPREF 50-322 Q 50-352 Q
BLOCH P B BLOCH P B BLOCH P B BLOCH P B BLOCH P B	8208110093 8208130148 8208200184 8208200189 8208240409	50-155	BOUCHEY, O D BOUCHEY, O D BOUCHEY, O D BOUCHEY, O D	8208020150 8208020151 8208020155 8208020159 8208020227	50~397 E 50~397 E 50~397 K 50~397 A 50~397 A	BRENNER, L BRENNER, L BRETZ, L M DREWER, B T BRICKLEY, R H	8208250361 8208270409 8208190026* 8208020215 8208310127*	50-352 0 50-352 0 CONTRACT 50-537 0 QA999
BLODGETT, T H	8208030181 8208030294 8208180041 8208180041 8208190193	50-387 R 50-387 R 50-387 R 50-387 A 50-387 R	BOUCHEY, Q D, BOUCHEY, Q D BOUCHEY, Q D BOUCHEY, Q D BOUCHEY, Q D.	8208020235 8208020238 8208020245 8208020250 8208030213	50-397 F 50-397 A 50-397 K 50-397 E REVIEW GRP	Briden, D Briden, D, Brioge, L, Bringman, D, B. Brinkler, J e	8208030094* 8208040321* 8208300188* 8208240161 8208230194*	50-346 F 50-346 F 50-293 G 50-454 K 50-309 B
BLODGETT, TH BLODGETT, TH BLODGETT, TH BLOWGH, AR BLOWGH, AR	8208200003 8208250111 8208210209 8208230473* 8208300051*	50-389 A 50-389 R 50-389 R 50-277 G 50-277 G	BONCHEA' & D BONCHEA' & D BONCHEA' & D BONCHEA' & D	8208030233 8208040178 8208040203* 8208060141 8208060203	50-508 A 50-509 R 50-397 A 50-397 E 50-397 E	BRINKLER, J.E. BRINKLER, J.E. BRIBTOL, D.C. BRITTIGAN, R.L. BROBBT, G.E.	8208230210* 8208260555* 8208020358 8208240194 8208310036*	50-309 8 50-309 8 50-537 H 60-170 9 80-317 8
BLUBAUGH R E BLUMBERG N BOARDHAN, J R BODINE, J C BODINE, J C	8208120176* 8208120054* 8208200554* 8208020175* 8208060081*	40-3453 50-387 d 50-498 d 50-244 F 50-244 F	BOUCHEY, Q, b BOUCHEY, Q D BOUCHEY, Q D BOUCHEY, Q D BOUCHEY, Q D	8208100072 8208100101 8208100189 8208100290 8208110101	50-397 A 50-460 K PRM 50-460 A 50-397 E	Brock, B. L Broce, R. W Broehl, D. J Brombero, B Brombero, B,	8208270374* 8208260350* 8208030213 8208110300 8208170324	70-754 50-324 F REVIEW ORP CONTRACT CONTRACT
BOGART, D BOGDEN, O BOGDEN, O BOGDEN, O. BOGDEN, O	8208160073* 8207220663 8208070025 8208170373 8208240481	50-302 R 40-1162 40-1162 40-1162 40-1162	BOUCHEY, O. D BOUCHEY, O. D. BOUCHEY, O. D. BOUCHEY, O. D. BOUCHEY, O. D	8208110134 8208200090 8208240332 8208270001 8208270011*	50-397 E 50-397 H 50-397 E 50-508 K 50-508 K	erone, J. C Brone, J. C Brone, J. C Brone, J. C Brone, J. C	8208020381 8208120213 8208130234 8208180078* 8208270432*	50-286 8 50-286 R 50-286 G 50-286 R
BOLLIO, D W BOLON, A E BONNES, O BOOK, H E BOOK, H, E,	8208070027 8208050254 8208260480# 8208030365 8208030367#	40-8743 50-123 H CONTRACT 27-48 27-48	BOUCHEY, O D BOUCHEY, O D BOUCHEY, O D BOUGHAD, M L BOURNIA, A	8208310297 8208310382 8208310391* 8208020268 8208040557	50-397 E 50-460 A 50-460 A 50-537 U 50-373 P	BRONB: J. C RROOKB: D J. BRODKS: E. H BROWN: C Q BROWN: C Q	8208310503* 8208170374* 8208160151* 8208070136* 8208200100*	50~286 F WARTE MOT 50~338 Q 50~302 B 50~302 B
BOOK, H E BOOK, H E BOOK, H E	8208100192 8208100196* 8208160318 8208160325* 8208160466	27-48 27-48 50-528	BOURNIA, A BOUMENB, J O BOWEY, R E. BOYD, D C	8208070006 8208040148* 8208180232 8208100283* 8208160459*	50~373 P 50~329 A NUREO 50~255 G 50~329 G	BROHN, C. Q. Brown, C. Q. Brown, C. Q. Brown, C. H. Brown, Q. D.	8208200172* 8208200227* 8208270358* 8208230174* 8207040189	50~302 B 50~302 B 50~302 B 50~243 Q 40~3453
BOOK, H E BOOK, H E BOOK, H E	8208140475# 8208240197 8208240270 8208240274# 8208240284	50-275 G 50-206 G 50-344 G 50-344 G 50-312 G	BOYER, R E BOYER, V 8 BOYER, V, 8 BOYLE, H L	8208100020 8207070401* 8208250326* 8208270442* 8208170120	PT21 50-352 K 50-352 Q 50-352 Q 50-247 Q	BROWN, O D BROWN, O D, BROWN, O. D BROWN, H H BROWN, H H.	8208120032 8208120173 8208140427 8208030280* 8208030280*	40~8584 40~3453 40~8064 50~275 Q 50~275 Q
BOOK, H. E BOOK, H. E BOOK, H. E	8208240288# 8208240407 8208240410# 8208270369 8208270374#	50-312 Q 27-48 27-48 70-754 70-754	BOYLE, M L BOYLE, R R BOZARTH, B L BRADBURY, R B BRADER, C R	8208260356 8208130453 8208240486 8208030529 8208040148*	50-29 P WASTE MGT 71-9128 REVIEW GRP 50-329 A	BROWN, H H BROWN, H H BROWN, H H BROWN, H. H. BROWN, J. F.	9208040239* 9208040239* <i>9208030538</i> 9208030538 9208040385*	50~322 Q 50~322 Q 50~275 Q 50~275 Q CONTRACT
BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8208030283 8208050110 8208050314 8208100070 8208160008	50-458 8 50-458 8 50-458 8 50-458 8 50-458 8	BRADFORD, L BRADFORD, L BRADFORD, W H BRADLEY, E J BRADLEY, E J	8208240245 8208240417 8208030367* 8207070390 8208020464*	50-289 0 50-289 0 50-348 0 50-352 K 50-352 F	BROWN, M, T BROWN, M, H BROWN, R, BROWN, R, L BROWNING, R E.	8208120129 8208170107 8208040325 8208200185* 8208030716	50-321 1 50-537 T Habte Mot 50-458 Q Habte Mot
BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E, BOOKER, J. E,	8208170137 8208200031 8208230275 8208240047 8208240063	50-45B 8 50-458 A 50-458 A 50-458 B 50-458 B	BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J BRADLEY, E. J BRADLEY, E. J	8208030446 8208030451# 8208050329 8208050439 8208100122	50-352 A 50-352 A 50-352 A 50-352 A	BROWNING; R E. BROWNLEE, V L. BROWNLEE, V. L. BROWNLEE, V L. BROWNLEE, V L.	8208170007 8208030347* 8208030397* 8208160333* 8208160333*	WABTE MOT 50-348 Q 50-321 Q 50-302 Q 50-424 Q
BOOKER, J E BOOKER, J E. BOOS, A BOOS, A. J BORCHERT, R	8208240373 8208310254 8208120224* 8208120223* 8208060212*	50-458 8 50-458 8 50-329 A 50-329 A 50-336 B	BRADLEY, E J BRADLEY, E J BRADLEY, E J, BRADLEY, E J BRADLEY, E J,	8208100284 8208160045 8208240222 8208240226* 8208310112	50-352 A 50-352 C 50-352 A 50-352 A 50-352 A	BROWNLEE, V L. BROYHILL, J T BROYHILL, J. T. BRUCE, M. BRUCH, E	8208240424 8208030499 8208100242 8208120177 8208030425	50-395 8 PR REGOD 50-537 H 50-322 8
Borchert, R. Bordenick, B. M.	8208260254* 8208040020 8208040280 8208200155 8208200163*	20-355 0 20-355 0 20-355 0 20-355 0	BRADLEY, E. J. BRADY, M. J.	0208310136* 0208190315* 0208190319* 0208190337* 0208190346*	50-352 A 50-413 A 50-413 A 50-413 A 50-413 A	BRUNNER, E. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNBON, F. W. BRYAN, D.	8208180044 82082304474 8208230470# 8208020358 8208020358	50-220 8 50-277 Q 50-277 Q 50-537 H 50-537 H
BORDINE, T. C BORDINE, T. C BORDINE, T. C BORDINE, T. C BORES, R. J.	8208130278 8208240324 8208270029* 8208300282 820830034	50-155 8 50-155 P 50-155 R 50-155 8 50-213 P	Brady, M. J. Brady, R. J. Bragar, N. H Braley, C. Bramlett, L B	8208170352* 8208120307* 8208120220 8208240374* 8208120197*	50-413 A MISC 90-537 H 50-528 Q 50-368 R	BRYANT, J. BRYANT, J. BRYANT, J. C. BRYANT, J. C. BRYANT, J. C.	8208060025# 8208160202# 8208030188# 8208030557# 8208160262#	CONTRACT 50-227 0 50-413 0 50-227 0 50-347 0

	ARAMAG	n	·								
AUTHOR BRYANT, J C	112230A R38MUN R360418028	CATE	JECT EOORY 	AUTHOR	ACCESSION NUMBER	LEUB P	GORY	AUTHOR	ACCESSION NUMBER	CATE:	
BRYANT, J C BRYCK, C J BRYCK, C J DUCHANAN BUCHHOLZ, R H	820816040 820831051 820831052 820825013	1 40-82 4 40-82 1 40-82 14* 40-82	19 Q 745 783	CAMDEN, T M CAMPBELL, D R CAMPBELL, E H CAMPBELL, G CAMPBELL, M	8207280283 8208120212 8208040313 8208270524 6208250283	* TOPRE * 50-31 WASTE * 50-25	P 5 R MOT 7 S	CARTWRIGHT, W R CARUSD, R CARUSD, R CARUSD, R CARUSD, R	8208270336 8208270336 8208170332 8208240272 8208240304	* 50-33 50-29 50-29 50-29	17 S
BUCK, P BUCKLES, J BUDD, W H BUNCH, R	820712014 820820008 820804000 820804033 820803043	3* 50-40 6 50-31 9 WASTE 3* 50-45	7 S 5 J MGT	CAMPBELL, M CAMPBELL, M CAMPBELL, M CANTRELL, F S CANTRELL, F S	8208250275 8208250332 8208250327 8208140141 8208140408	* 40-86 * 40-86 * 50-518		CARUSO,R CASHWELL,R J CASHWELL,R J CASELR,R CASSEL,D W	8208270481 8208030484 8208030488 8208190337	* 50-413	q A A B
BURANAPAN, W BURCH, R H BURCHIN, J F BURGER, C W BURGER, C W	820826009 820816037 820816012 820803018 820810016	0* 50-33 9* 50-27 2* 50-32 1 50-32	5 G 5 Q 4 G	CANTRELL.F S CANTRELL.F S CANTRELL.F S CAO.N CAPHION, D L	6208140521 8208160528 6208310123 8208170112 6208020376	* 50-259 50-520 * 50-409	7 Q 0 S 7 P	CASSEL, D W CASSEL, D W CASSEL, D W CASSEL, D W CASTLE, L W CASTO, W R	8208040270; 8208040270; 8208040279; 8208040279; 8208270321;	* 50-454 * 50-454 * 50-454 * 50-316	4 0 4 0 4 0
BURGER, F J BURGESS, B L BURIAN, R J BURKE, T J BURN, R R	820817019 820805052 820826060 8208180056 8208310056	1* 50-28; 71-59; 0* 50-32;	2 Q 57	CAPHTON, D L CAPHTON, D L CAPHTON, D L CAPHTON, D L CAPLE, Q H	8208120034 8208230197 8208230386 8208300068 8208160351	* 50-317 * 50-387 * 50-245	7 G 7 G 7 G	CASTO, W R	8208250006* 8208250007* 8208250013* 8208250017*	FOIA FOIA FOIA	
BURNETT, R F BURNETT, R F. BURNS, E M BURNS, R BURSEY, B	9208030374 9208040171 9208190310 9208020094 9208180013	50-332 TOPREF	? F	CAPRID.M L CAREW.J CAREV.J J CAREV.J J CAREY.J J	8208160237 8208110098 8208020143 8208090087 82080900909	PR 50-304 50-334 50-334	P P	CASTO, W R CASTOR, V O	8208250021* 8208250027* 8208250032* 8208250035* 8208250038*	FOIA FOIA FOIA	
BURSTEIN, S BURSTEIN, S BURSTEIN, S BURSTEIN, S BURSTEIN, S	8208020109 8208100084 8208190188 8208240370 8208260059	50-246 50-266 * 50-266	P G	CAREY, J J CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8208070134 8208100071 8208100281 8208120208 8208120244	50-334 50-334 50-334 50-334 50-334	P P R R	CATTON, I CATTON, I CAVANAUGH, W CAVANAUGH, W	8208160293 8206270091 8208110049 8208020311 8208250379	REGGD 50-537 50-247 50-313 50-348	Ř
Burstein, B Busch, L Buss, R Buss, R Buss, R	8208160446 8208260505 8208090255 8208130218 8208160381	\$ 50-254	9 5 R	CAREY, J J CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8208120250 8208120253* 8208160014 8208170099 8208170169*	50-334 50-334 50-334 50-334 50-334	K P Q F	CAVANAUGH, W CHALMERS, D CHAMBERLAIN, D CHAMBERLAIN, D CHAN, E I	8208310154 8208130473 8208160200* 8208170107* 8208050083	50-313 NUREQ QA799 QA797 50-352	P O
BUSSE,L J BUTCHER,E BUTCHER,E BUTCHER,R C. BUTCHER,R C	6208180232 8208040442: 8208130448: 8208030434: 8208100037	50-259	P G S	CAREY, J J CAREY, J J CARLEON, J D CARLEON, J D	8208240312 8208270400* 8208310075 8207080424* 9208160314*	50-334 50-334 50-235 50-275	P R K Q	CHANLE I CHANDLER, L J CHANDLER, L J CHANG, T Y CHAPLIN, B D	8208310061 8208100008 8208160142 8208310071* 8208050277*	50-352 50-361 50-361 50-382 50-320	9 9 9
BYRD, R BYRD, R BYRD, R BYRD, R,	8208020070: 8208020145: 8208030490: 8208060196: 8208060237:	50-416 50-416 50-416	8 8 8 8	CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, C A	8208310009* 8208310469* 8208310472* 8208310476* 8208020368	50-358 50-213 50-213 50-213 50-537	G G G	CHAPLIN, 6 D CHAPLIN, 8 D CHAPMAN, J R CHARNLEY, J B CHARNOFF, Q	8208180040* 8208180060* 8208270485 8208110111 8208300283	50-320 50-320 50-454 TOPREP REVIEW	8 M GRP
BYRD.R BYRD.R BYRD.R BYRD.R	8208040274* 8208090171* 8208090210* 8208090281* 8208140301*		8 8 8 6 8	CARR, A V CARRIGAN, R W CARROLL, D E CARTER, L J CARTER, L J	8208170140 8208300304* 8208300223 8208110079 8208110085	50~413 50~259 PR 50~247 50~247	0 8	CHARNOFF, G CHARTERINA.J CHASE.J B CHASE.J W CHASE.J W CHASE.J W	8208300284* 8208050091* 8208030213 8208140408* 8208140521*	50-219	S S ORP O
BYRD, R BYRD, R BYRD, R BYRD, R	8208160488* 9208200011* 9208200028* 8208200067* 8208270329*	50-416 50-416 50-416 50-416 50-416	8 8 8 8 8	CARTER, S CARTER, S CARTER, S D. CARTWRIGHT, W CARTWRIGHT, W R	8208050213* 8208050341* 8208270291* 8207230301 8208030240	50-259 50-260 50-260 50-339 50-339	8 8 8	CHASNOFF, D A CHAUDHARY, S CHAVEZ, D CHAVEZ, D	8208160528* 8208060107 8208300258* 8208030424 8208030426	50-259 27-39 50-387 50-454 50-454	a a e
BYRD, R BYRD, R BYRD, R BYRD, R BYRD, R	8208270410* 8208270434* 8208270439* 8208270483* 8208300107*	50-416 50-416 50-416 50-416 50-416	8 8 8 8	CARTWRIGHT, W R CARTWRIGHT, W R. CARTWRIGHT, W R. CARTWRIGHT, W R. CARTWRIGHT, W R	8208030247* 8208050094 8208050103* 8208050235 8208050241*	50-339 50-339 50-339 50-338 50-338	5 5 6 6	CHAVEZ, D CHAVEZ, D CHAVEZ, D CHECK, P, B	8208030424 8208030430* 8208040312* 8208040312* 8208020431	50-454 50-454 50-454 50~454 50-537	0 0 0 0
BYRON, L. CADHELL, L CAGNETTA, J P CAGNETTA, J P CAGNETTA, J P	9208130242* 8208180124 8207210248 8208050143 8208050388	50-295 NUREO 50-213 50-213 50-245	G F F	CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8208050323 8208050330* 8208050355 8208050355 8208050407*	50-339 50-339 50-339 50-369 50-339	9 9 8 6 9	CHECK, P B CHECK, P B, CHECK, P B, CHECK, P B CHECK, P B	8208030071 8208030742 8208030747 8208030751 8208040037	50-537 50-537 50-537 50-537 50-537	D D D
CAGNETTA: J P CAGNETTA: J P CAGNETTA: J P CAGNETTA: J P CAGNETTA: J P	8208040230 8208060230 8208100001 8208100142 8208100142	50-213 50-213 50-245 50-213 50-213	P P G	CARTHRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W, R CARTHRIGHT, W, R	8208050422 8208050431 * 8208050444 82080504452* 82080504524	50-338 50-338 50-339 50-339 50-339	8 6 8	CHECK, P B CHECK, P B CHECK, P, S, CHECK, P, S	8208040045 8208040074 8208040086 8208040072 8208040102	50-537 50-537 50-537 50-537 50-537	D D D D
CAONETTA, J P CAONETTA, J P CAONETTA, J P CAONETTA, J P, CAONETTA, J P	8208140074 8208170218 8208170218 8208240310 8208230135	50-245 50-245 50-245 50-423 50-213	Р Р А Н	CARTURIOHT, W R CARTURIOHT, W R CARTURIOHT, W R CARTURIGHT, W R CARTURIGHT, W R	8208090037* 8208090143 8208090151* 8208090162 8208090164*	50-339 50-339 50-339	8 88 8 8 8	CHECK, P 8 CHECK, P 8 CHECK, P 8 CHECK, P 8	8208040112 8208040118 8208040127 8208040440 8208040454	50-537 50-537 50-537 50-537	D D D D
CAGNETTA, J P CAHILL, P. CAHILL, H. D CAHN, A L CAIN, C. L	8208300075 8208040004 8208190217* 6208170222 8207060192*	50-213 40-2041 50-458 REGGD 40-3453	P Q	CARTHRIGHT, W R	82082000B4 8208200101* 8208200227	50-339 50-339 50-338 50-338	8 8 8 8 8 8	CHECK, P B CHECK, P B CHECK, P B CHECK, P B CHECK, P B	8208040457 8208040462 8208070015 8208110043 8208110232	50-537 50-537 50-537 50-537	A D D D
CAIN, C. L CAIN, B CALLAN, L J CALLAN, L J CALLAN, L J	8208250429 8208090001 8208030225 8208180056* 8208240360	50-313	S Q S	CARTHRIGHT, W R CARTHRIGHT, M, R CARTHRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W R	8208270279* 8208270299* 8208270301 8208270307*	50-339 50-338 50-338 50-338	8 R S S	CHERRY, M. CHERRY, M CHESNUT, S CHIANGI, N CHIANGI, N J CHIANGI, N J	8208060113 8208060113 8208040484 8208020071 8208020217	50-454 50-454 50-454 50-400 50-400	G Q A 8 8
4											

AUTHOR	ACCESSION NUMBER	TOBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
CHIANOI,N J CHIANOI,N J CHIANOI,N J CHILDB,W V CHILDB,W V	8208050202 8208200039 8208200113 8208050516* 8208090088*	50~400 S 50~400 S 50~400 S 50~333 S 50~333 S	CLANCY, R. G CLAPPER, T H CLARDY, L CLARDY, L S CLARE, O H	8208120286 8208040669 8208230313+ 8208300121+ 8208170109	50-537 H 40-8027 50-331 G 50-331 G 50-537 T	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLEBBCH, E E, CLEVELAND, R, B	8208270254 8208270561* 8208300311 8208170267 8208250091*	50-348 50-348 50-364 50-537 40-86
CHILDS, W V CHILDS, W V CHILDS, W V CHILDS, W V	8208160030* 8208160033* 8208230363* 8208260178* 8208260236*	50-333 8 50-333 8 50-333 8 50-333 8	CLARK,B A CLARK,H E, CLARK,L CLARK,L CLARK,L	8208070014 8208240412* 8208230350* 8208240382 8208240382	NUREO 50-528 G 70-938 50-358 G 50-358 O	COBB, J C COBB, J C. COBB, L I COCHRAN, R. COCHRAN, T B.	8208180130# 8208180130# 8204210397 8208130115 8208180115	50-537 50-537 50-3 50-220 50-220
CHILDS,W V CHILDS,W V. CHILK,8 J CHILK,8 J CHILK,8 J	8208260246* 8208260544* 8206300352 8208020028 8208020034	50-333 8 50-333 8 50-275 0 1 OCFR 1 OCFR	CLARK,L CLARK,L, CLARK,P R CLARK,R A CLARK,R A	8208250127 8208260293 8208160168* 8208020054* 8208020062*	50-20 P 50-20 B 50-363 G 50-282 P 50-282 P	COFFMAN, F. COOAN, N. J COHEN, I. COHEN, L. COHN, B, H	6206310075* 6208050065* 6208050319* 6208130469 6208040680*	FOIA 50-245 (70-135 NUREQ CONTRACT
CHILK, S J CHILK, S J, CHILK, S J, CHILK, S J	8208020317 8208020421 8208040248 8208050204 8208060016	50-275 Q 100FR 100FR 100FR 100FR	CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A	8208020444 8208030063* 8208030064 8208030070* 8208030097*	50-282 P 50-309 P 50-335 P 50-309 P 50-348 P	COKINOS, D COLARULLI, P. F COLARULLI, P. F COLARULLI, P. F, COLBURN, T. O,	8208110078 8208190119 8208190119 8208190119 8208040650	50-304 F 50-247 G 50-247 G 50-247 G 50-266 P
CHILK.B J. CHILK.B.J. CHILK.B J CHILK.B J CHILK.B J	8208060018 8208090020 8208110148 8208110149 8208110153	10CFR 50-537	CLARK,R A CLARK,R,A, CLARK,R A CLARK,R A CLARK,R.A	8208030104* 8208040057 8208040066* 8208040071* 8208040083	50-348 P 50-335 P 50-335 P 50-335 P 50-285 P	COLBURN, T. O COLBURN, T. O COLBURN, T. O COLE, L. H. COLE, R. F	8208130128 8208180127* 8208260531 8208260081* 8208130182	50-266 P 50-266 G 50-266 P 40-86 50-352 G
CHILK.S J CHILK.S J CHILK.S J CHILK.S J. CHILK.S J	8208110155 8208120139 8208130133 8208130177 8208160002*	50-298 0 50-289 0 50-155 0 50-537 0 50-537 0	CLARK, R. A. CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A	8208040094 8208040174 8208040221 8208040350 8208040577	50-309 P 50-267 P 50-336 P 50-267 Q 50-317 P	COLE, R. F. COLEMAN, J. K, COLEMAN, R. H COLEY, J. L. COLLING, D, J	8208180110 8208300141 8208030554 8208160169* 8208050243*	50-352 0 50-338 0 PRM 50-247 0 50-293 0
CHILK.B.J CHILK.B.J CHILK.B.J CHILK.B.J CHILK.B.J	8208160040 8208160050 8208160054 8208160057 8208160060	50-373 Q 50-361 Q 50-289 Q PROJ PR	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A.	8208040409 8208040642 8208040658 8208050012 8208070038	50-317 F 50-282 P 50-335 P 50-285 P 50-285 P	COLLINS, J. T COLLINS, J. T. COLLINS, J. T COLLINS, J. T COLLINS, J. T.	820&150027* 8208050374 8208240176 8208260030* 82082703&7	FOIA 50-313 F 50-298 G 50-446 Q 50-285 G
CHILK,8 J CHILK,8 J, CHILK,8 J CHILK,8 J,	8208160223 6208170321 8208180008 6208170129 8208200220	50-247 0 50-293 0 50-537 0 50-537 0 50-361 0	CLARK,R A CLARK,R A. CLARK,R A CLARK,R A CLARK,R A	8208070040 8208070284 8208100359* 8208100365* 8208100369	50-285 G 50-366 G 50-344 P 50-344 P 50-313 P	COLLING, T. R COLLING, T. R. COLLING, T. R COLLING, T. R COLLING, T. R.	8208030636* 8208160311* 8208160375* 8208160375* 8208310097	50-269 0 50-259 0 50-269 0 50-269 0 50-259 8
CHILK,S J CHILK,S J CHILK,S J CHILK,S J	8208240254 8208240258 8208240367 8208250340 8208250345	50-537 0 50-537 0 50-247 0 50-443 0 50-373 0	CLARK, R A CLARK, R A, CLARK, R A CLARK, R A CLARK, R A,	8208110002# 8208110004# 8208110088 8208130100# 8208130121#	50-317 P 50-317 P 50-282 P 50-317 P 50-317 P	Colombo, M E Colombo, R. Colombo, R. W Colombo, R. W Colombo, R. W	8208230462* 8208170270* 8208020202* 8208020262* 82080200130*	CONTRACT 50-312 R 50-312 8 50-312 8 50-312 8
CHILK,S J CHILK,S J CHILK,S J CHILK,S J. CHILLEA,L,K	8208250353 8208250354 8208300019* 8208310504 8208190194*	50-509 Q 50-275 Q PR 10CFR 50-272 P	CLARK,R A CLARK,R A CLARK,R A CLARK,R A CLARK,R A	8208130132* 8208130135* 8208160029 8208170379 8208170001	50-266 P 50-266 P 50-317 P 50-282 F 50-309 Q	COLOMBO, R. W. COLOMBO, R. W. COLTON: E CON, V. N. CONARD: J	82082001&0* 8208200224* 8208250554 82083001&3* 820810033&*	50-312 8 50-312 8 XFORTLIC 50-321 0 50-373 8
CHIN,8 L CHIPMAN,0 L CHOPRA,0 P. CHOULES,N CHRISSOTIMOS,N	8208060145 8208040224# 8208110210# 8208100371# 8208050435#	TOPREP 50-537 0 50-267 0 50-317 0 50-254 0	CLARK, R.A. CLARK, R.A. CLARK, R.A. CLARK, R.A. CLARK, R.A.	8208240037 8208240035 8208240065* 8208240073* 8208240489	50~282 Q 50~338 P 50~338 P 50~338 P 50~335 Q	CONARD, J CONGEL, F, J CONLEY, M, CONLON, T. E, CONLON, T E	8208240206* 8207160365* 8208040373 8208030148* 8208030196*	50~373 B FOIA 50~537 H 70~1151 50~413 Q
CHR I SBOT I MOS, N CHR I BTEL: B. CHR I BTEL: B CHR I STENSEN: S CHR I BTMAN: J. N.	8208050441* 8208230279* 8208310094* 8208260473 8208110168	50-237 Q 50-249 B 50-237 B NUREQ 50-322 Q	CLARK:R A CLARK:R A CLARK:R A. CLARK:R J CLAY:E L.	8208250490 8208250558 8208310376 8208110279 8208030243*	50-344 F 50-317 P 50-265 F 50-257 P 70-1113	CONLON, T. E CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E.	9208030216# 8208030409# 9208030476# 8208030539# 8208030616#	50-438 Q 50-370 Q 50-348 Q 50-302 Q 50-438 Q
CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N	8208110168 8208200270 8208200270 8208250253 8208250253	50-322 0 50-322 0 50-322 0 50-322 0	CLAY, E. L CLAY, E. L. CLAYTON, F. L. CLAYTON, F. L CLAYTON, F. L	6206030347* 8208160497* 6207010228 8208620074 8208020116	70-27 70-27 50-348 6 50-348 8 50-348 8	CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E	8208140198* 8208140242* 8208140357* 8208140384* 8208140387*	50~335 Q 50~400 Q 50~389 Q 50~413 Q 50~390 Q
CHR I STOPHER, W CHR I STOPHER, W CHURCHILL, B, CHURCHILL, B CHURCHILL, B, W	8208200041* 8208270488* 8208270315 8208270315 8208110180	50-296 B 50-296 B 50-266 Q 50-266 Q 50-266 Q	CLAYTON, F, L CLAYTON, F, L CLAYTON, F, L, CLAYTON, F, L, CLAYTON, F, L,	8208020171 8208020243 8208030356* 8208060255 8208060260	50-348 8 50-348 F 50-348 Q 50-364 P 50-348 P	CONNER, E. L. CONNER, T. B. CONNER, T. B. CONNER, Y. B. CONNER, T. B.	8208040240 8208020204 8208020204 8208030368 8208030368	50-336 P 50-358 0 50-358 0 50-352 0 50-352 0
CHURCHILL, B W. CHURCHILL, B W. CHURCHILL, B. W. CHURCHILL, B. W. CHURCHILL, B. W.	8208110180 8208120127 8208120127 6208200293 8208200293	50-266 0 50-382 0 50-266 0 50-266 0	CLAYTON, F. L.	8208040243 8208070181* 8208100172 8208120142 8208120227	50-348 P 50-348 Q 50-348 P 50-348 P 50-348 B	CONNER, T. B.	8208030414 8208030414 8208120101 8208120101 8208170148	50-358 0 50-358 0 50-352 0 50-352 0 50-358 0
CHURCHILL, B. W. CHURCHILL, B. W. CHURCHILL, B. W. CHURCHILL, B. W. CHURCHILL, B. W.	6208240333 8208240333 8208240350 8208240350 8208270319*	50-382 0 50-382 0 50-382 0 50-382 0 50-266 0	CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L.	8208130061 8208130176 8208160020 8208160076 8208160211	50-348 P 50-364 P 50-348 R 50-364 R 50-348 G	CONNER, T. B.	8208190148 8208200127 8208200127 8208200240 8208200240	50-358 Q 50-416 Q 50-416 Q 50-416 Q 50-416 Q
CHURCHILL, B. W. CILIMBERG, R. L CILIMBERG, R. L. CILIMBERG, R. L CILLIS, M.	8208240274# 8208100358 8208190009 8208270622 8208240274#	50-266 0 50-315 Q 50-316 P 50-316 P 50-344 Q	CLAYTON, F. L.	8208200004 8208200164 8208230079 8208230315 8208250309	50-348 P 50-348 B 50-348 F 50-348 P 50-348 P	CONNER, T. B.	8208240236 8208240236 8208250322 8208250322 8208250438	50-352 50-352 50-352 50-352

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CONNER, T. B CONRAN, J H CONROY, B W CONROY, B W CONTE, R	8208270438 8208110206* 8208170372 8208170388 8208020377*	50-352 0 50-289 0 40-8502 40-8502 50-289 0	COTTON. O D COUNSIL. W O COUNSIL. W O COUNSIL. W O	8208240259* 8207210248 8208020076 8208020076 8208020146	50-206 P 50-219 F 50-213 P 50-213 P 50-336 Q	CRAY, M CREED, J R CREED, J R CREED, J R CREED, J R	8208240187* 8208020302* 8208160122* 8208300180* 8208310040*	50-373 8 70-36 50-255 0 50-265 0 50-373 0
CONTE.R CONVERSE.R J CONWAY.J CONWAY.J CONWAY.H F	8208160483* 8208230363* 8208190107* 8208190295* 8208090120*	50-320 G 50-333 B GA999 GA999 50-271 F	COUNSIL. H O COUNSIL. H O COUNSIL. H O	8208020225 8208020244 8208020244 8208050163 8208050179	50-213 P 50-213 P 50-213 P 50-213 F 50-245 P	CREED.J R CRISCIONE.J L CRISP.I CRISP.I CRLENJAK.R V	8208310431* 8208260167* 8208190326* 8208190326* 8208030244*	50-305 Q 50-336 B 50-413 A 50-413 A 50-438 Q
COOK, J W COOK, J W COOK, J W	0208100040* 0208130106* 0207070028 0207070058* 0208040049	50-333 R 50-275 R 50-327 K 50-327 K 50-327 R	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8208050388 8208050388 8208050406 8208060230 8208060230	50-245 F 50-245 F 50-336 F 50-213 P 50-213 P	CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W	8208050225* 8208050304* 8208100017* 8208120140* 8208170141*	50-277 Q 50-286 Q 50-334 Q 50-387 Q 50-293 Q
COQK' A M COQK' A M COQK' A M COQK' A' M	6208040143 6208070055 8208100097 8208100131 8208110114*	50-329 A 50-329 A 50-329 S 50-329 S TOPREP	COUNBIL, W C COUNBIL, W C COUNBIL, W C COUNBIL, W C	8208060231 8208060231 8208060267 8208060267 8208060279	50-213 P 50-213 P 50-213 F 50-213 F 50-213 P	CROFF, A Q CROSS, R W CROSS, R W CROSSMAN, W. A CROSSMAN, W. A	8208170303 8208260037 8208260434 8208050139* 8208190241*	50-537 A NUREO NUREO 50-458 Q 50-458 Q
COOK' A H COOK' A H COOK' A H COOK' A H	8208120221 8208130215 8208160064 8208160308 8208160514	50-327 A 50-329 S 50-329 E 50-327 A 50-329 S	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8208040279 8208090185 8208090185 8208100001 8208100142	50-213 P 50-423 B 50-423 B 50-245 P 50-213 Q	CROSSMAN, W A CROSSMAN, W A CROUSE, R P. CROUSE, R P CROUSE, R P	8208200054* 8208200185* 8208030587 8208050238 8208050242*	50-478 Q 50-458 Q 50-346 P 50-346 P 50-346 P
COOK, J H COOK, J H COOK, J H COOK, J H	8208160042 8208170137 8208240268 8208270246 8208270253*	REGOD 50-329 A 50-329 B 50-329 A 50-329 A	COUNSIL.H O COUNSIL.H O COUNSIL.H O	8208100142 8208160074 8208160074 8208160423 8208160423	50-213 Q 50-245 P 50-249 P 50-213 Q 50-213 Q	CROUSE, R P CROUSE, R. P CROUSE, R P CROUSE, R P CROUSE, R. P	8208050385* 8208070108 8208070112* 8208110104 8208110108*	50~346 P 50~346 P 50~346 P 50~346 P 50~346 P
COOK.J W COOK.R.J COOKE.O C COOKEY.H J	8208310108 8208310276 8208160457* 8208170188* 8208050317	50-329 A 50-329 E 50-329 G 50-244 P 50-277 E	COUMBIL.W O COUMBIL.W O COUMBIL.W O COUMBIL.W O	8208180127* 6208190218 6208190218 8208190279 6208190297	50-336	CROUSE, R P GRQUSE, R, P GROUSE, R P, GROUSE, R P, GRQUSE, R, P	8208110131 9208160024 8208200007 8208200046 8208200116*	50~346 P 50~346 P 50~346 P 50~346 Q 50~346 Q
COGNEY, M J COGNEY, M J. COGNEY, M J COGNEY, M J COGNEY, L J	8208050321* 8208050325* 8208100147 8208190098 8208100277	50-277 S 50-277 S 50-277 S 50-277 R 50-298 S	CONNSIL'H O CONNSIL'H O CONNSIL'H O CONNSIL'H O	8208200072 8208200072 8208240310 8208240384 6208240384	50-245 P 50-245 P 50-423 A 50-213 P 50-213 P	CROUSE, R P. CROUSE, R P CROUSE, R. P CROUSE, R P CROUSE, R P	8208230353 6208240334 8208270244* 6208310147* 8208310192	50-346 P 50-346 Q 50-346 Q 50-346 Q 50-346 P
CODPER, W E COOPER, W E COOPER, W E COOPER, W E COOPER, W E	8208030431 8208040145 8208130049 8208130071* 8208170270	50-275 H TOPREP 50-275 P 50-275 P 50-275 R	CONVAIL'H O CONVAIL'H O CONVAIL'H O CONVAIL'H O	8208240404 8208250135 8208260451* 8208300075 8208300094	50-213 P 50-213 H 50-213 F 50-213 P 50-213 P	CROUSE, R P. CROUSE, R P CROW, W T. CROW, W T. CROW, W T	8208310238* 8208310436 8201140133* 8208020432* 8208020447	50-346 Q 50-346 Q 40-86 70-2936 40-2061
COPELAND, R. A COPELAND, V G COPELAND, V G COPELAND, V, G. COPELAND, V G	8208170206* 8208040227 8208040227 8208040232* 8208240374	50-244 P 50-155 0 50-155 0 50-155 0 50-155 0	COUNSIL, N 0 COUNSIL, N 0 COUNSIL, N, 0 COUNSIL, N, 0 COUPER, N E	8208310304 8208310471* 8208310481* 8208310483* 8208030273	50-245 P 50-245 F 50-213 P 50-213 P 50-275 R	CROW, W T. CROW, W T CROW, W T. CROW, W, T. CROWLEY, B R	8208070275* 8208250275* 8208250315* 8208260085* 8208160383*	40-8027 40-84 40-86 70-1257 50-389 0
COPELAND, V Q COPELAND, V Q COPELAND, V Q COPELAND, V Q COPELAND, V Q	8208240374 8208240377* 8208240377* 8208270328 8208270328	50-155 0 50-155 0 50-155 0 50-155 0 50-155 0	COMAN.B Z. COMAN.F P COMOILL.C J COX.H T COX.H T	8208270422 8208180114 8208230473* 8208050397* 8208070174*	50-437 0 50-329 0 50-277 0 50-261 8 50-261 8	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8208030145 8208030173 8208030234 8208030250 8208030253*	50-29 P 50-29 P 50-409 P 50-244 P 50-244 P
COPELAND, V O COPELAND, V O COPELAND V O COPLAN, B M COPLAN, B M	8208270333* 8208270333* 8208040243* 8208030120 8208030723	50-155 G 50-155 G 50-155 G HABTE MOT WASTE MOT	COX.H.T COX.H T COX.H T, COYLE,F,T COYLE,L,	8208200123# 8208200211# 8208270249# 8208040148 8208070245#	50-261 8 50-261 8 50-261 8 40-6740 50-237 8	CRUTCHFIELD, D CRUTCHFIELD, D, CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8208030240* 8208040583 8208050074 8208050273 8208050534	50-244 P TOPREF 50-213 P 50-409 P 50-155 P
COPLAN, 8 M COPPELL, D A CORCORAN, M J GORMIER, W H	8208040576 8208310487 8207110004 8208230016 8208020289	WASTE MOT WASTE MOT FOIA 40-8801 50-142 0	COYLE, L COYLE, L COYLE, L. M CRANDALL, W E CRANE, C.	8208130272* 8208130324* 8208070230* 8208240273* 8208060170	50-237 8 50-247 8 50-237 8 50-147 Q 50-317 P	CRUTCHFIELD, D CRUTCHFIELD, D, GRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D,	8208060157 8208060270 8208060275* 8208060282* 8208100109	50-206 P 50-407 P 50-407 P 50-407 P
CORMIER, W H CORMIER, W H, CORMIER, W H, CORMIER, W H, CORMIER, W H,	8208070182 8208110137 8208130152 8208130204 8208240249	50-142	CRANE,P A CRANE,P A CRANE,P A CRANE,P A CRANE,P A	8208020241 8208030553 8208060204 8208100218 8208130075	50-133 S PR 50-275 P 50-275 P 50-275 P	CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8208110039 8208110100 8208110119 8208120075 8208120169	50-213 P 50-244 D 50-29 F 50-409 P 50-409 P
CORMIER, W H CORMIER, W H CORNELIUS, R M CORNELL, E X CORYDON, L	8208240337 8208240354 8208270450 8208250343 8208040423	50-142 Q 50-142 Q 70-143 FOIA 40-8027	CRANE, P A CRANE, P A CRANE, P A CRANE, P, A CRANE, P, A	8208130260 8208130261* 8208170157 8208170161 8208170211	50-323 A 50-323 A 50-275 P 50-275 P 50-322 0	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D CRUTCHFIELD, D	8208120205 8208160117 8208170001 8208170143 8208170154	50-409 P 50-213 P 50-155 P 50-206 P 50-255 F
CORYELL, O, P COSTELLO, F COSTELLO, J R. COSTELLO, J R. COSTELLO, J R	8208140477# 8208130449 8208030452* 8208140404* 8208190214*	70-27 NUREG GA999 GA999 GA999	CRANE, P.A. CRANE, P.A. CRANE, P.A. CRANE, P.A. CRANE, P.A.	8208200144 8208200267 8208230019 8208230196 8208230336	50-275 G 50-275 R 50-275 F 50-275 P 50-275 P	GRUTCHFIELD, D CRUTCHFIELD, D, GRUTCHFIELD, D CRUTCHFIELD, D GRUTCHFIELD, D.	8208170158 8208170169 8208170170 8208170171 8208170178	50-213 P 50-213 P 50-206 F 50-155 F 50-155 P
COTTER, B P. COTTER, B P COTTER, B, P COTTER, B, P COTTER, B, P	8208030570 8208050473 8208200087 8208240207 8208250349	50~458	Crane, P. A. Crane, P. A Grane, P. A Grane, P. A. Crane, P. A.	8208250202 8208270611 * 8208300295 8208310144 8208310429	50-275 P 50-133 R 50-341 P 50-275 P 50-275 P	GRUTCHFIELD, D. CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D. GRUTCHFIELD, D.	8208170251 8208170256* 8208170265* 8208190182 8208190199	50-206 P 50-206 P 50-206 P 50-219 P 50-29 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGGRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D	8208200013 8208200017 8208200178 8208240149 8208240247	50-409 P 50-29 P 50-409 P 50-244 P 50-219 P	DALE,L F DALE,L F DALE,L F DALE,L F DALE,L F	8208020410 8208030028* 8208030449 8208030545 8208030585	50-416 E 50-416 F 50-416 E 50-416 P 50-416 P	DAVIDSON, D. R DAVIDSON, D. R DAVIDSON, D. R DAVIDSON, D. R DAVIDSON, D. R	8208190246 8208240296 8208240299 8208240229 8208240323	50-440 A 50-440 E 50-440 G 50-440 A 50-440 A
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8208240251 8208240331 8208240364 8208240421 8208240442	50-213 P 50-244 P 50-409 P 50-409 P 50-155 P	DALE,L F DALE,L F DALE,L F DALE,L F DALE,L F	8208090075 8208090092 8208100089 6208100134 8208120149	50-416 F 50-416 P 50-416 J 50-416 P 50-416 P	DAVIDBON, D R DAVIDBON, D. R DAVIDBON, D R DAVIDBON, J. DAVIES, R W.	8208260124 8208260151 8208310416 8208230417 8208030586	50-440 K 50-440 A 50-440 E Nureo Nureo
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8208250138 8208250494 8208250545 8208260310 8208270186	50-213 P 50-245 F 50-245 P 50-29 P 50-409 P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8208120244 8208120274 8208120297 8208170139 8208180067	50-416 E 50-416 P 50-416 E PR 50-416 P	DAVIS, A DAVIS, A B DAVIS, A B DAVIS, A B DAVIS, J B	8208160472 8208050320 8208050441* 8208240441 8208030591	50-329 8 50-358 9 50-237 0 50-373 P
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8208270480 8208270696 8208310251 8208310254* 8208310262*	50-407 P 50-206 F 50-206 P 50-206 P 50-206 P	DALE,L F DALE,L F DALE,L F DALE,L F DALE,L F	8208170274 8208230364 8208240170 8208240328 8208260107*	50-416 R 50-416 P 50-416 P 50-416 P 50-416 F	DAVIS, M E. DAVIS, B M DAVIS, B M DAVIS, V W	8208120220 8208240491* 8208250171* 8208260504* 8208040429	50-537 H 50-317 B 50-317 B 50-317 B 40-8781
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CULLER, F L CULLER, R B	8208310327 8208310329 8208310464* 8208040434 8208300341*	50-407 G 50-244 P 50-409 G 50-537 H 50-413 I	DALE, L. F DALE, L. F DALE, L. F DALLMAN, R. J DALTROFF, 8. L	9208310286 9208310317 8208310445 8208040027 6208040374#	50-416 H 50-416 P 50-416 P RES 50-277 F	DAVIS, V W DAVIS, W E DAYAL, R DAYAL, R DE LORENZO, R A	8208240434 8208030213 8208110241 8208180158 8208040178	SO-413 D REVIEW ORP RES RES 50-507 R
CULVER, M W. CUMMINOB, J J CUMMINOB, R CUNNINOHAM, A L CUNNINOHAM, A L	8208140093* 8208190065* 8208120279 8208030538* 8208160416*	50-302 R 50-358 Q 50-537 H 50-338 Q 50-250 Q	DALTROFF, 8 L, DALTROFF, 8 L DAMBLY, D C DANCE, H C, DANCE, H C	8208200045 8208310074 8208200077 8208030185 8208030172	50-277 P 50-277 P 50-358 0 50-413 Q 50-413 Q	DE ZUTEL.C Z DEANGELIS.D L DEBBAGE.A G. DEBONS.A DEBRUIN.J.	B20814024B B208240473 B208140229* B206270098 B208170341	50-329 8 NUREO 50-335 9 ACRS 50-382 8
CUNNINGHAM, Q E CUNNINGHAM, Q E CUNNINGHAM, R E CUNNINGHAM, R E CUNNINGHAM, R E	8208130335 8208130336 8208230427* 8208250261* 8208250283*	71-5926 71-5939 FOIA 40-86 40-86	DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C.	8208030320 8208030218 8208030305 8208030305	50-250 Q 50-338 Q 50-280 Q 50-348 Q 50-413 Q	DEBB. B. T. DECKER. R. B. DEEGAN. P. B. DEFFERDING. L. J DEITRICH. L. W	8208160311* 8208040213 8208190310* 8208130475 8208170109	50-257 @ 50-409 9 TOPREP NUREO 50-537 T
CUNNINOHAM,R E CURNANE,R A CURNANE,R A CURTIB,N W CURTIB,N W	8208310437* 8208310354* 8208310367* 8208020082 8208030204	71-6698 GA999 GA999 50-387 P 50-387 P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8208030329 8208030393 8208030404 8208030453 8208030447	50-370 G 50-338 G 50-250 G 50-389 G 50-348 G	DELANEY, J. C DELANEY, J. C DELANEY, J. C DELANEY, J. C.	8208230222* 8208250118* 8208250123* 8208250140* 8208250142*	40-501 40-86 40-86 40-86 40-86
CURTIB, N W CURTIB, N W CURTIB, N W CURTIB, N W CURTIB, N, W	8208030401 8208030455 8208040142 8208040170 8208040298	50-387 E 50-387 E 50-387 P 50-387 P 50-387 P	DANCE, H C. DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C.	8208030528 8208030548 8208030617 8208030418* 8208030431*	50-338	DELBELLO, A B. DELBELLO, A B. DELOEDROE, L D DELOEDROE, L D DELOEDROE, L D	B205040006* B205020270 B205030254 B205070132* B205130307*	50-247 F 50-3 H 50-10 P 50-295 G 50-373 P
CURTIB, N W CURTIB, N W CURTIB, N W CURTIB, N W CURTIB, N W	8208100038 8208120105 8208170248 8208170273 8208200195	50-387 B 50-387 J 50-387 P 50-387 J 50-387 Q	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	9209100187 9208100215 9208100309 9208160147 9208160163	50-366 B 50-338 Q 50-321 Q 50-338 Q 50-269 Q	DELCEDROE: L D DELCEDROE: D	8208130311* 8208170222 8208270368* 8208310241 8208230066*	50-373 P RE00D 50-373 Q 50-373 P 50-314 B
CURTIS, N. W.	8208200239 8208230075 8208240151 8208240175 8208240202*	50-387 P 50-387 B 50-387 Q 50-387 P	DANCE, H C. DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8208140147 8208140190 8208140194 8208140209 8208140220	50-369 Q 50-335 Q 50-269 Q 50-395 Q 50-335 Q	DEMOOR, D. E. DENISON, E. DENISON, E DENISON, E DENISON, E	8208110211* 8208180035 8208270204 8208270212* 8208260112	50-155 Q 50-275 R 50-275 P 50-275 P NUREQ
CURTIB, N W CURTIB, N W CURTIB, N W CURTIB, N. W CURTIB, N W	8208240377 8208240221 8208240226* 8208270427 8208300081*	50-387 P 50-387 P 50-387 P 50-387 P 50-387 Q	DANCE, H. C DANCE, H. C DANCE, H. C DANCE, H. C DANCE, H. C	8208140235 8208140236 8208140257 8208140264 8208140277*	50-370 Q 50-369 Q 50-321 Q 50-370 Q	DENNIBTON, S F DENNIBTON, B F DENNIBTON, B F, DENTE, T, J DENTE, T J	8208260077* 8208310010* 8208310488* 8208180027 8208240381	CONTRACT CONTRACT 50-537 A TOPREP TOPREP
CURTIS, N. W.	8208300124 8208300139 8208300285 8208310125 8208310180	50-387 P 50-387 P 50-387 P 50-387 E 50-387 P	DANCE, H. C.	8208140281 8208140298# 8208140310 8208140317 8208160326	50-413 Q 50-413 Q 50-302 Q 50-250 Q 50-369 Q	DENTE, T J DENTER, T J DENTON, H. R DENTON, H. R. DENTON, H. R.	8208310141 8208310340 8207200054 8207200061*	TDPREP TOPREP 50-373 P 50-373 P 50-373 P
CURTIB, N W GURTIB, N. W. CURTIB, N W CURTIB, N W CUBHINO, L E	8208310201 8208310282 8208310319 8208310343 8208180124	50-387 P 50-387 E 50-388 G 50-387 E NUREO	Dance, H. C Dance, H. C Dance, H. C Dance, H. C Dance, H. C	8208160328 8208160354 8208160364 8208160378 8208160379	50-413 Q 50-250 Q 50-269 Q 50-389 Q 50-369 Q	DENTON, H R. DENTON, H R. DENTON, H R DENTON, H, R DENTON, H, R.	8208020435 8208020444 8208020456 8208040175 8208040347	50-275 P 50-275 P 50-133 H 50-397 A MI8C
B D DICTORUS B CUTCHIN, J. M.	8208260179* 8208110178 8208230059 8208230064 8208230085	50-219 8 50-289 Q 50-289 Q 50-387 Q 50-289 Q	DANCE, H. C. DANCE, H. C. DANCE, H. C. DANIELBON, D. H. DANIELBON, D. H.	8208160392* 8208160505 8208270199 8208070097* 8208130325*	50-349 Q 50-302 Q 50-321 Q 50-456 Q 50-373 Q	DENTON, H. R. DENTON, H. R. DENTON, H. R DENTON, H. R DENTON, H. R	6208040363 6208040488 6208040532 6208040536 82080405562*	50-373 P 50-352 U 50-275 P 50-373 0 50-373 0
CVICKER.J S CYBULGKIB.P CYBULGKIB.P CZYSCINSKI.K S D'ABBRACCI.T	8208050284 8208260543* 8208310083* 8208260464 8208020134	50-537 H F01A F01A NUREG 50-139 H	DANIELSON, D H DANIELSON, D H DANIELSON, D H DAVOHERTY, T M DAVID, L. T.	8208170118* 8208270313* 8208270324* 8208270422 8208260501*	50-483 Q 50-346 Q 50-341 Q 50-437 Q CONTRACT	DENTON, H R	8208040567* 8208040575 8208130217 8208130221* 8208170167	50-373 0 50-373 0 50-352 0 50-352 0 50-206 0
D'AMORE, M D'ANGELO, A, J DABBERT, W F. DAIGNEAULT, M DAILEY, S G.	8208030139* 8208160266* 8208260406 8208180112 8208230294*	70-1151 50-508	DAVIDBON, D.R. DAVIDBON, D.R. DAVIDBON, D.R. DAVIDBON, D.R. DAVIDBON, D.R.	8208040003 8208100117 8208120054 8208120150 8208130270	50-440 £ 50-440 A 50-440 E 50-440 A 50-440 S	DENTON, H. R DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8208170345 8208170348* 8208250451 8208250454* 8208300004	50-206 P 50-206 P 50-373 9 50-373 9 PR

SIDN ER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
2006*	CATEGORY PR PR PR PR REVIEW ORP	DIETZ, C R	820820005B	50-324 8	DODA.R J	8208170095	1&E
2008*		DIETZ, C R.	8208200041	50-324 8	DODDS.R.T.	8207150411*	50-460 Q
2010*		DIETZ, C R.	8208200079	50-325 8	DODDS.R T	8207150421*	50-460 Q
2015*		DIETZ, C R.	8208200254	50-325 8	DODDS.R T	8207150434*	50-508 Q
2214*		DIETZ, C R.	8208200285	50-324 8	DODDS.R.T	8207150442*	50-508 Q
)443	QEN TEC 18	DIETZ, C R	8208270130	50-324	DODDS,R T	8208160126*	50-397 Q
)505	NUREQ	DIETZ, C R	8208270219#		DODDS,R T	8208160127*	50-397 Q
)318*	50-193 R	DIETZ, C R	8208270229#		DODDS,R T	8208160131*	50-508 Q
)098*	50-336 S	DIETZ, C R	8208270258		DODDS,R T	8208160208*	50-460 Q
)522	50-443 A	DIETZ, C, R	8208270381		DODDS,R T	8208160266*	50-508 Q
1522	50-443 A	DIETZ, C R	8208270394	50-325 8	DODDS,R T.	8208160398*	50-460 Q
1261#	50-443 F	DIETZ, C R	8208270404	50-325 8	DODDS,R T	8208160489*	50-397 O
1261#	50-443 F	DIETZ, C, R	8208270412	50-325 8	DOHERTY,J F	8208160199	REVIEW GRP
1408	50-443 A	DIETZ, C R	8208270417	50-324 8	DOLINGER,J R	8208020358	50-537 H
1408	50-443 A	DIETZ, C R	8208270479	50-324 8	DOMER,J A	8208030473*	50-390 Q
303	50-443 F	DIETZ, C R	8208270471	50-324 B	DOUGHERTY, D R DOUGHTY, J DOVER, J L DOVEL, C DOVEL, C	8208030271	RES
102	50-443 A	DIETZ, C R	8208270520	50-325 B		8208030271	REVIEW ORP
102	50-443 A	DIETZ, C, R,	8208300082	50-324 B		8208040434	50-537 H
297	50-443 A	DIETZ, C R	8208300107	50-324 B		8208040452*	50-346 F
297	50-443 A	DIETZ, C R,	8208300144	50-324 B		8208060107*	50-346 F
323	50-443 A	DIETZ.C R.	8208300238	50-325 B	DOYLE, A E	8208120132*	50-307 R
323	50-443 A	DIETZ.C R	8208300333	50-325 B	DOYLE, A E	8208120234*	50-29 R
075	50-443 A	DIETZ.V R	8208040200	NUREO	DRAGONETTE, K 8	8208170008	WASTE MOT
075	50-443 A	DIGOS.R M.	8208030015	50-334 P	DRAPER, D M	8208230256*	50-315 S
155	50-443 A	DIGOS.R M	8208040125	50-335 P	DRAPER, D H	8208310106*	50-315 B
155	50-443 A	Digos, R M	8208250480	50-348 P	DRAYER,D D.	8208260097	NUREO
222	50-443 B	Digos, R M	8208250514	50-27 P	DRISKILL,D D	8206150024*	FOIA
222	50-443 B	Dignan, T G	8208040135	50-443 Q	DRISKILL,D D	8208260039*	50-446 O
281	50-443 B	Dignan, T. O	8208040135	50-443 Q	DU TEMPLE,O	8208260465*	CONTRACT
281	50-443 B	Dignan, T G	8208040124	50-443 Q	DUBINSKI,L	8208250278*	40-86
142	50-443 D	DIGNAN, T C	8208040124	80-443 0	DUFFY, J. F	8208170284	50-247 0
227	XPORTLIC	DIGNAN, T, G	8208040137	50-443 0	DUGSTAD, D	8208130202*	50-202 R
335	XPORTLIC	DIGNAN, T C	8208040137	50-443 0	DUKES, O	8208310372	50-352 H
116	XPORTLIC	DIGNAN, T, C	8208040131	50-443 0	DUNKELMAN, M	8208040572	WASTE MOT
258	XPORTLIC	DIGNAN, T C	8208040151	50-443 0	DUNLAP, J M	8208050300*	50-307 0
173	XPORTLIC	DIIANNI,D C	8208020051	50-282 P	DUNLAP, J M	8208050469*	50-271 0
154	XPORTLIC	DILLARD,F D	8208020088*	50-338 P	DUPONT, B G	8208050435*	50-254 0
189	XPORTLIC	DINITZ,I	8208310248	50-395 J	DUPREE, D	8208120202*	50-327 R
183	50-358 Q	DID GUARDIA,J	8208190082	XPORTLIC	DURR, J P	8208020170*	50-343 0
162	50-358 Q	DIRCKS,W J	8204220343	BECY	DURR, J P,	8208100032*	50-352 0
62 36 03 56 72	50-358 Q 50-528 Q 50-528 Q 50-528 Q 50-255 P	DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J.	8206100427 8207080064 8207200095 8207200110 8207220035	BECY 50-329 H 50-329 P BECY	DURR, J P. DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R	8208230342* 8208050488 8208050488 8208170246 8208170246	50-317 0 50-322 0 50-322 0 50-322 0 50-322 0
14# 23* 33 08 80	TOPREP 50-255 G 50-298 G 50-247 F 50-247 H	DIRCKB, W J. DIRCKB, W J. DIRCKB, W J. DIRCKB, H J. DIRCKB, H. J	8207300503 8208020015* 8208030088 8208030569 8208040266	50-250 H FOIA 50-289 P NUREO ' 50-537 D	DYNNER, A. R DYNNER, A. R DYNNER, A. R DYNNER, A. R DYSON, R. P	8208170249* 8208170249* 8208240390 8208240390 8207050016*	50-322 Q 50-322 Q 50-322 Q 50-322 H
33 35* 56* 31	50-409 G 50-409 Q REVIEW ORP 50-312 F 50-298 Q	Dircks, H J Dircks, H J Dircks, H J Dircks, H J Dircks, H J	8208050065 8208060175 8208070033 8208100350 8208100370	50-537 D Waste Mot Misc 50-247 U 50-271 U	EAPEN, P K. EARLEY, A F EARLEY, A F EARLEY, D F EASLEY, P O.	8208020378* 8208020207 8208020207 8208230183 8208180131*	50-220 G 50-322 G 50-322 G 40-2061 50-266 G
12+	50-298 Q 50-298 Q 30-247 Q 50-537 H NUREQ	Dircke, W. J Dircke, W. J Dircke, H. J Dircke, W. J	8208120351 8208130318 8208170034 8208170356 8208200143	50-289 H TOPREP BECY 50-275 P REVIEW ORP	EAGON, C. F. EAZ ZETTA, B. A EBENHACK, D G ECCLESTON, K, T EGCLESTON, K, T	8208050502 8208160094* 8208030055 8208230038 8208260393*	27-39 50-321 R 71-7151 50-293 P 50-324 P
8 19 9 7	50-361 P 50-361 H 50-361 P 50-361 P 50-206 P	DIRCKB, W J DIRCKB, W J DIRCKB, W. J. DIBALYO, R DIXON, B, W	8208260370 8208310003 8208310035 8208040281 8208270692*	50-206 P 50-358 G 50-322 A NUREO 50-329 A	ECKERMAN, K F ECKES, J, J ECKHARDT, J H, ECKHARDT, J H, ECKHARDT, J, H	8208040629 8208020462 8208160120* 8208160123* 8208160129*	RES 40-2061 50-312 Q 50-312 Q 50-275 Q
9* 7 5 2 5	50-206 P 50-327 S 50-325 S 50-325 S 50-324 S	DIXON, D W. DIXON, D W. DIXON, D W. DIXON, D W.	8207140177 8208020142 8208030230 8208030507 8208030508	PR 50-395 A 50-395 A 50-395 A 50-395 A	ECKHARDT, J H ECKHARDT, J. H ECKHARDT, J H ECKHOFF, N. D. ECONOMOB, N	8208160266* 8208160422* 8208160509* 8208260097 82080302224*	50-50B Q 50-362 Q 50-312 Q NUREG 50-250 Q
2 0 5 8 2	50-325 B 50-325 B 50-325 B 50-324 B 50-325 B	DIXON.O W. DIXON.O W DIXON.O W. DIXON.O.W	8208050079 8208060183 8208060261 8208100136 8208110126	50-395 8 50-395 A 50-395 A 50-395 F 50-395 A	ECONOMOS, N. ECONOMOS, N. ECONOMOS, N. ECONOMOS, N. ECONOMOS, N.	8208030326+ 8208030374+ 8208160167+ 8208160171+ 8208160236+	50-413 Q 50-438 Q 50-269 Q 50-369 Q 50-416 Q
25132	50-324 8 50-324 R 50-325 8 50-325 8 50-324 8	DIXON, O. W. DIXON, O. W. DIXON, O. W. DIXON, O. W. DIXON, O. W.	8208110132* 8208160156 8208160243 8208230005 8208230276	50-395 F 50-395 Q 50-395 F 50-395 F 50-395 Q	ECONOMOS; N. ECONOMOS; N ECONOMOS; N. EDD I NOS; M EDDLEMAN; H	8208160371* 8208160383* 8208160376* 8208120202* 8208020434*	50-400 G 50-387 G 50-369 G 50-327 R 50-537 D
;	50~325 8	DIXON, O W.	8208240375	50-395 F	EDDLEMAN, W	8208170253	50-400 0
	50~325 8	DIXON, O. W.	8208240423	50-395 P	EDDLEMAN, W	8208240341	50-400 0
	50~324 0	DIXON, O. W.	8208250152	50-395 P	EDELMAN, L	8208030370	50-382 K
	50~324 0	DIXON, D W	8208300228	50-395 P	EDEY, A,	8208040643*	CONTRACT
	50~325 8	DOCTOR, B R.	8208180232	NUREO	EDGAR, O, L,	8208110160	50-537 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEORY
EDGAR, Q L EDGAR, Q L EDGAR, Q L EDGAR, Q L EDGAR, Q L	8208110140 8208110190 8208110190 8208110190 8208110190	50-537	ELROD, 8 A ELBABSER, T. ELSON, G EHCH, R EMCH, R	8208030441* 8208300188* 8208180044 8208200278 8208230006	50-335 0 50-293 0 50-247 H 50-155 P 50-155 P	FELTON, J M	8207020007 8207120070 8208020197 8208020190 8208020193	FOIA 50-259 F 50-271 F 50-305 F 50-244 F
EDGAR, Q L	8208170327	50-537 G	EMCH.R	8208230077	50-155 P	FELTON, J M. FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8208020194	50-392 F
EDGAR, Q L	8208200283	50-537 G	EMCH.R	8208250109	50-155 P		8208020443	50-352 F
EDGAR, Q L	8208300286*	REVIEW GRP	EMIGH.J F	8207180027	FOIA		8208030004	50-322 F
EDGEWORTH, P	8208040022	CONTRACT	ENGEL.W P	8208050027	71-5908		8208030013	50-213 F
EDGEWORTH, P	8208040409	CONTRACT	ENGEL.W P	8208170371	71-9184		8208030024	50-416 F
EDGEWORTH, P EDGEWORTH, P EDGEWORTH, P ED180N, Q E ED180N, Q E	8208050140 8208060001 8208310485 8208040507 8208050186	CONTRACT CONTRACT 50-537 A 50-483 A 50-493 A	ENGELKEN, R. H ENGELKEN, R. H ENTWISLE, E. B ENTWISLE, E. B	8208110077* 8208200102 8208310105 8208060117 8208060132	50-361 F 50-344 P 50-275 Q 50-170 O 50-170 Q	FELTON, J M FELTON, J M FELTON, J, M FELTON, J M FELTON, J M	8208030034 8208030038 8208030047 8208030044 8208030078	50-346 F 50-282 F 50-346 F 50-369 F 50-387 F
EDISON, O E	8208250108	50-483 A	EPSTEIN.E	8208250146*	40-84	FELTON, J M FELTON, J M FELTON, J M FELTON, J M. FELTON, J M	8208030076	50-373 F
EDLER, B K	8208170306	NUREO	EPSTEIN.E.	8208250338*	40-86		8208030686	50-3 F
EDLER, B K	8208170306	NUREO	EVANS.C D	8208030413*	50-269 G		8208040100	FDIA
EDMONDS, M L	8208120314*	50-416 E	EVANS.L J	8208020439	70-734		8208040296	50-443 F
EDMUNDS, J	8208020358	50-537 H	EVANS.L J	8208030012	70-27		8208040265	50-289 F
EDWARDS, D W	8208090206	50-27 P	EVANS.L.J	8208030034	70-143	FELTON, J M. FELTON, J M FELTON, J M FELTON, J M. FELTON, J M.	8208040283	50-266 F
EDWARDS, G L	8208170159	50-370 R	EVANS.L.J	8208030039	70-1201		8208040278	50-29 F
EDWARDS, J	8208190270*	50-312 R	EVANS.L.J	8208030040	70-1201		8208040314	50-309 F
EDWARDS, W J	8208110164	50-322 0	EVANS.L.J	8208030043	70-27		8208040326	50-261 F
EDWARDS, W J	8208110164	50-322 0	EVANS.L.J	8208040147	70-143		8208040353	50-10 F
EICH,E F	8208240252*	50-247 R	EYANB.L J	8208040156	70-27	FELTON, J. M. FELTON, J. M FELTON, J. M FELTON, J. M. FELTON, J. M.	8208040371	50-277 F
EICHENHOLZ,H	8208300188*	50-293 G	EVANS.L J	8208040161	70-734		8208040380	50-331 F
EISENHUT,D G	8207300543	TOPREP	EVANB.L J	8208040162	70-2955		8208040444	50-346 F
EISENHUT,D G	8208020384	50-219 P	EVANB.L J	8208040163	70-1201		8208040446	50-389 F
EISENHUT,D G	8208020423	MISC	EVANB.L J	8208040172	70-143		8208040467	50-254 F
EISENHUT, D C EISENHUT, D C EISENHUT, D C EISENHUT, D C	8208040174 8208040197 8208040631 8208040660 8208060366	50-397 A 50-317 F 50-460 A 50-322 H 50-387 P	EVANS, L J. EVANS, L J EVANS, M. EVERETT, R J EVERETT, R J	B208040187 B208040195 B208230024* B207060192* B208160449*	70-1151 70-1257 CONTRACT 40-3453 40-8064	FELTON, J. M.	8208040473 8208040470 8208040512 8208040604 8208050121	50-10 F 50-267 F 50-267 F 50-346 F 50-289 F
EISENHUT, D Q	9208090174	50-3 P	EVERETT.R.J	6208260429	NUREC	FELTON, J. H. FELTON, J. H. FELTON, J. H. FELTON, J. M. FELTON, J. M. FELTON, J. M.	8208040032	50-285 F
EISENHUT, D Q	9208090333	50-275 R	EWING.E	6207270387	50-313 P		8208040040	50-321 F
EISENHUT, D, Q	9208090334	50-387 P	EWING.E	6208050466	50-348 P		8208040051	50-321 F
EISENHUT, D, Q	9208100148	50-206 P	FADEN.M E	6208050369	50-537 0		8208040058	50-320 F
EISENHUT, D Q	9208110097	50-361 F	FAHNER.T C	6208130391	40-2061		8208040055	50-461 F
EISENHUT, D 0	8208110122*	50-29 F	FAIRTILE, M B	8208130041	50-278 F	FELTON, J M	B208040069	50-317 F
EISENHUT, D 0	8208120004	50-79 W	FALE, E E	8208170226*	50-373 Q	FELTON, J M	B208040074	50-244 F
EISENHUT, D G.	8208120095*	50-99 H	FALCONER, D.	8208160202*	50-269 Q	FELTON, J M	B208060094	50-346 F
EISENHUT, D G	8208120303	MISC	FARMER, F. O.	8208170003*	50-185 P	FELTON, J M	B208060127	50-263 F
EISENHUT, D 0	8208170146*	50-204 P	FARNEY, W L	8208160125*	50-409 Q	FELTON, J M.	B208040306	50-409 F
EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	8208170351* 8208170388 8208230071 8208250025 8208250042	50-206 P 50-275 P 50-275 B 50-307 F 50-289 H	FASANO, A FASANO, A FASANO, A FASANO, A FASANO, A	8208020377* 8208130211 8208130267 8208160456* 8208160483*	50-287 Q 50-320 B 50-320 B 50-320 Q 50-320 Q	FELTON, J. M.	8208040313 8208040319 8208040322 8208110127 8208110214	50-346 F 50-346 F 50-305 F 50-395 F 50-320 F
EISENHUT, D G	8208260349	50-247 F	FASAND, A.	8208200044	50-320 B	FELTON, J. M	8208110219	50-259 F
EISENHUT, D G	8208260362	50-275 P	FASCELL, D B	8206200036*	50-250 H	FELTON, J. M.	8208110220	50-331 F
EISENHUT, D G	8208310364	50-275 P	FAY, C W	8208020115*	50-266 B	FELTON, J. M.	8208110230	50-254 F
EKBERG, E	8208040262	71-9032	FAY, C W	8208020273	50-266 G	FELTON, J. M.	8208110240	50-250 F
EL-ASHRY, M T	8208100209	50-327 8	FAY, C W.	8208030440	50-266 P	FELTON, J. M.	8208110246	50-321 F
EL-ABHRY,M T	8208110109	50-327 8	FAY, C. W	8208030472	50-266	FELTON, J M	8208110251	50-346 F
ELIN,J O	8208160487*	50-397 Q	FAY, C W.	8208040140		FELTON, J M.	8208110254	50-275 F
ELLERSHAW,L E	8206150024*	FOIA	FAY, C W	8208040288*		FELTON, J M.	8208110259	50-275 F
ELLERSHAW,L E	8206150035*	FOIA	FAY, C. W	8208130107		FELTON, J M.	8208110264	50-275 F
ELLERSHAW,L E	8208170209*	GA999	FAY, C W.	8208130130		FELTON, J. M	8208110286	50-373 F
ELLIS, J	8208130142	50-445 0	FAY, C. W.	8208160041	50-266 R	FELTON, J M	9209170347	50-344 F
ELLIS, J	8208130173	50-445 0	FAY, C W	8208160043*	50-266 R	FELTON, J M.	9208170354	50-287 F
ELLIS, J	8208130212	50-445 0	FAY, C W	8208160510	50-301 B	FELTON, J, M	9208170362	50-307 F
ELLIS, J	8208130216*	50-445 0	FAY, C W	8208160518*	50-301 B	FELTON, J, M.	9208170032	FOIA
ELLIS, J	8208170149	50-445 0	FAY, C W	8208170066	50-301 P	FELTON, J, M.	9208170038	FOIA
ELLIS, J ELLIS, J ELLIS, J ELLIS, J	6208240165 6208240231 8208240346 8208240373 8208240378*	50-445 0 50-445 0 50-445 0 50-445 0 50-445 0	FAY, C W FAY, C, W FAY, C W. FAY, C, W FAY, C W	8208170248 8208190224 8208200151 8208260240 8208270577*	50-244 P 50-264 F 50-266 G 50-266 G 50-266 R	FELTON, J, M FELTON, J, M, FELTON, J, M, FELTON, J, M FELTON, J M,	8208190055 8208190072 8208190405 8208190404 8208190430	50-358 O FOIA 50-267 F 50-338 F 50-155 F
ELLIS, J.	8208270419	50-445 Q	FAY, C W	6208310171 \\ 6208310264 6208310267 \\ 6208310267 \\ 6208310481 *	50-264 G	FELTON, J. M.	8208230374	FOIA
ELLIS, J.	8208270435	50-445 Q	FAY, C, W		50-301 S	FELTON, J. M.	8208230403	FOIA
ELLIS, J.	8208270437	50-445 Q	FAY, G W.		50-301 B	FELTON, J. M	8208230408	50-537 A
ELLIS, J.	8208270440	50-445 Q	FAY, J M.		REVIEW ORP	FELTON, J. M	8208230418	50-320 P
ELLIS, J	8208270441	50-445 Q	FEE, W. F.		50-213 P	FELTON, J. M.	8208230444	50-277 Q
ELLIS, J ELLIS, J ELLIS, J ELLIS, J	8208270443 6208270444 8208270445 6208270447* 8208270452	50-445 Q 50-445 Q 50-445 Q 50-445 Q	FEHRINGER, D J FEIERABEND, C D FEIL, R. A FEIMAN, B. D FEITKNECHT, C	8208040014 8208050521* 8208160127* 8208130351* 8208030343	M180 50-282 Q 50-397 Q 40-8823 50-334 R	FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M	820825000 1 820825006 1 82082504 1 0 820825052 6 820825054 0	50~241 B 40-86 FOIA 70-143 FOIA
ELLIS, J,	8208270453	50-445 Q	FELDE, D. K	8208240087	NUREO	FELTON: J. M.	8208250554	FDIA
ELLIS, J	8208270456*	50-445 Q	FELDMAN, E. M.	8208040039	RES	FELTON: J. M.	8208250559	50-10 F
ELLIS, J,	8208270624	50-445 Q	FELLMAVER, R.	8208240045	REB	FELTON: J. M.	8208260001	40-2061
ELLIS, T S,	8208260006	FDIA	FELLMAVER, R.	8208310157	50-454 I	FELTON: J. M.	8208260003	FDIA
ELLS, S F	8208310189	50-443 D	FELTON, J. M.	8204150008	FOIA	FELTON: J. M.	8208260004	50-438 G

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
DENTON, H R	9209300004* 9209300009* 9209300015* 9209300015*	PR PR PR PR PR REVIEW ORP	DIETZ, C R DIETZ, C, R DIETZ, C R DIETZ, C R DIETZ, C R	8208200058 8208200061 8208200079 8208200254 8208200285	50-324 8 30-324 6 50-325 8 50-324 8 50-324 8	DODA:R J. DODDS;R T DODDS:R T DODDS:R T DODDS;R,T	8208170095 8207150411* 8207150421* 8207150434* 8207150442*	1&E 50-440 0 50-460 0 50-508 0 50-508 0
DENTON, H R DEPUE, J. DERKB, P S DESLANDES, K D DEVINCENTIB, J	8208310443 8208240505 8208120318+ 8208200078+ 8207300522	OEN TEC IS NUREO 50-133 R 50-336 S 50-443 A	DIETZ, C R DIETZ, C R, DIETZ, C R DIETZ, C R DIETZ, C R	8208270150 8208270219* 8208270229* 8208270256 8208270381	50-324 8 50-324 R 50-324 R 50-325 S 50-325 S	DODDS, R T. DODDS, R, T DODDS, R T DODDS, R T DODDS, R, T	8208160126* 8208160127* 8208160131* 8208160208*	50-397 Q 50-397 Q 50-508 Q 50-460 Q 50-508 Q
DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J,	8207300522 8208040261* 8208040261* 8208050408 8208050408	50-443 A 50-443 F 50-443 F 50-443 A 50-443 A	DIETZ, C R DIETZ, C R DIETZ, C R DIETZ, C R DIETZ, C R	8208270376 8208270404 8208270412 8208270417 8208270479	50-325 S 50-325 S 50-325 S 50-324 S 50-324 S	DODDS,R T. DODDS,R T DOHERTY,J F DOLINGER,J R DOMER,J A	8208160398* 8208160489* 8208160199 8208020358 8208030473*	50-460 Q 50-397 Q REVIEW GRP 50-537 H 50-390 Q
DEVINCENTIB, J. DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J	8208060303 8208110102 8208110102 8208130297 8208130297	50-443 F 50-443 A 50-443 A 50-443 A 50-443 A	DIETZ, C R DIETZ, C R DIETZ, C R. DIETZ, C R DIETZ, C R	8208270491 8208270520 8208300082 8208300109 8208300144	50-324 E 50-325 B 50-324 E 50-324 S 50-324 S	DOUGHERTY, DR DOUGHTY, J DOVER, JL DOYEL, G DOYEL, C,	8208040050 8208030271 8208040434 8208040452* 8208060109*	RES REVIEW GRP 50-537 H 50-346 F 50-346 F
DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J	8208170323 8208170323 8208170075 8208170075 8208170155	50-443 A 50-443 A 50-443 A 50-443 A 50-443 A	DIETZ,C R DIETZ,C R. DIETZ,V,R DIGGS,R M DIGGS,R M	8208300238 8208300333 8208040200 8208030016 8208040125	50-325 8 50-325 8 NUREQ 50-334 P 50-335 P	DOYLE, A E DOYLE, A E DRAGONETTE, K S DRAPER, D M DRAPER, D M	8208120132* 8208120234* 8208170008 8208230256* 8208310106*	50-309 R 50-29 R WASTE MQT 50-315 S 50-315 S
DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J	8208190155 8208200222 8208200222 8208260281 8208260281	50-443 A 50-443 B 50-443 B 50-443 B 50-443 B	DIQOB,R M DIQOB,R M, DIGNAN,T Q DIQNAN,T Q DIQNAN,T Q	8208250480 8208250514 8208040135 8208040135 8208040124	50-348 P 50-29 P 50-443 Q 50-443 Q 50-443 Q	DRAYER,D D. DRIEKILL,D D DRISKILL,D D DU TEMPLE,O. DUBINSKI,L	8208250097 8205150024* 8208250039* 8208250455* 8208250278*	NUREO FOIA 50-446 O CONTRACT 40-86
DEVINCENTIB, J DEVINE, J. B. DEVINE, J. B DEVINE, J. B. DEVINE, J. B.	8208300142 8208110227 8208130035 8208180114 8208180258	50-443 D XPORTLIC XPORTLIC XPORTLIC XPORTLIC	DIONAN, T Q DIONAN, T, Q, DIONAN, T Q DIONAN, T Q DIONAN, T Q,	8208060124 8208060137 8208060137 8208060151 8208060151	50-443 Q 50-443 Q 50-443 Q 50-443 Q 50-443 Q	DUFFY, J F. DUGBTAD, D DUKES, O DUNKELMAN, M. M DUNLAP, J M	8208170284 8208130202* 8208310372 8208040572 8208050300*	50-247 Q 50-282 R 50-352 H WASTE MOT 50-387 Q
DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, T. DEVINE, T.	8208180273 8208310056 8208310059 8207050083 8208240362	XPORTLIC XPORTLIC XPORTLIC 50-358 Q 50-358 O	DIIANNI,D C DILLARD,F D DINITZ,I DIO QUARDIA,J DIRCKE,W J	8208020051 8208020088* 8208310248 8208190082 8204220343	50-282 P 50-338 P 50-395 J XPORTLIC BECY	DUNLAP.J M DUPONT.B 0 DUPREE.D DURR.J P DURR.J P.	8208050469* 8208050435* 8208120202* 8208020170* 8208100032*	50-271 Q 50-254 Q 50-327 R 50-443 Q 50-352 Q
DEVINE,T DEWEY,L.8. DEWEY,L.8. DEWEY,L.8. DEWITT,RB	8208240342 8208020236 8208070003 8208260036 8208050072	50-358 0 50-528 0 50-528 0 50-528 0 50-255 P	DIRCKS, W J. DIRCKS, W J. DIRCKS, W J. DIRCKS, W J.	8206100427 8207080064 8207200095 8207200110 8207220055	8ECY 50-320 U 50-329 H BECY	DURR, J P. DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R	8208230342* 8208050408 8208050488 8208170246 8208170246	50-317 0 50-322 0 50-322 0 50-322 0 50-322 0
DEMITT, R B. DEMITT, R B DEYOUNG, R. DEYOUNG, R. C. DEYOUNG, R C	8208110114* 8208200023* 8208100033 8207300508 8208030080	TOPREP 50-255 G 50-298 Q 50-247 F 50-247 H	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8207300503 8208020015* 8208030088 8208030569 8208040266	50-250 H FDIA 50-289 P NUREQ - 50-537 D	DYNNER, A R DYNNER, A. R. DYNNER, A R DYNNER, A R DYSON, R P	8208170249* 8208170249* 8208240390 8208240390 8207050016*	50-322 Q 50-322 Q 50-322 Q 50-322 Q 50-287 H
DEYOUNG, R. C. DEYOUNG, R. C DEYOUNG, R. C. DEYOUNG, R. C. DEYOUNG, R. C.	8208040033 8208040035* 8208180056* 8208260431 8208310441	50-409 G 50-409 G REVIEW GRP 50-312 F 50-298 G	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8208050065 8208040175 8208090033 8208100350 8208100370	50-537 D WASTE MOT MIBC 50-247 U 50-271 U	EAPEN,P K EARLEY,A F EARLEY,A F EARLEY,D F EABLEY,P O.	8208020378* 8208020209 8208020209 8208230183 8208180131*	50-220 Q 50-322 Q 50-322 Q 40-2061 50-266 Q
DEYOUNG, R. C. DEYOUNG, R. C. DIAMANT, L DICKINSON, R. H DICKSON, J. H	8208310446* 8208310452* 8208270458 8208020358 8208040222	50-298 G 50-298 G 50-247 O 50-537 H NUREO	Dircks, W J. Dircks, W J	8208120351 8208130318 8208170034 8208170354 8208200143	50-289 H TOPREP SECY 50-275 P REVIEW ORP	EABON, C F EAZZETTA, B. A, EBENHACK, D. Q, ECCLESTON, K T ECCLESTON, K, T	8208050502 8208160094* 8208030055 8208230038 8208260373*	27-39 50-321 R 71-9151 50-293 P 50-324 P
DIETCH, R. DIETCH, R DIETCH, R DIETCH, R. DIETCH, R.	8208020248 8208030288 8208030489 8208180049 8208240257	50-361 P 50-361 M 50-361 P 50-361 P 50-206 P	Dircke, W. J. Dircke, W. J. Dircke, W. J. Disalvo, R. Dixon, B. W.	8208240370 8208310003 8208310035 8208040281 8208270492#	50-204 P 50-358 Q 50-322 A NUREO 50-329 A	ECKERMAN, K F ECKES, J. J. ECKHARDT, J H, ECKHARDT, J, H ECKHARDT, J, H	8208040629 8208020462 8208160120* 8208160123* 8208160129*	RES 40-2061 50-312 Q 50-312 Q 50-275 Q
DIETCH, R. DIETRICH, M. A. DIETZ, C. R. DIETZ, C. R. DIETZ, C. R.	8208240259* 8208100097 8208020085 8208020102 8208020105	50-206 P 50-327 9 50-325 8 50-325 9 50-324 8	DIXON, O. W DIXON, O. W DIXON, O. W DIXON, O. W.	8207140177 8208020142 8208030230 8208030507 8208030608	PR 50-395 A 50-395 A 50-395 A 50-395 A	ECKHARDT, J.H. ECKHARDT, J.H ECKHARDT, J.H ECKHOFF, N.D ECONOMOB, N	8208140266* 8208160422* 8208160509* 8208260097 8208030224*	50-50B Q 50-342 Q 50-312 Q NUREO 50-250 Q
DIETZ, C. R. DIETZ, C. R.	8208020382 8208050120 8208070125 8208070148 8208070212	50-325 B 50-325 B 50-325 B 50-324 B 50-324 B	DIXON, O. W. DIXON, O. W. DIXON, O. W. DIXON, O. W.	8208050079 8208060183 8208060261 8208100136 8208110126	50-395 8 50-395 A 50-395 A 50-395 F 50-395 A	ECONDMOS, N ECONDMOS, N, ECONDMOS, N, ECONDMOS, N, ECONDMOS, N	8208030326* 8208030394* 8208160169* 8208160171* 8208160236*	50-413 Q 50-438 Q 50-267 Q 50-367 Q 50-416 Q
	8208120012 8208120015 8208120021 8208120078 8208120142	50-324 B 50-324 R 50-325 S 50-325 S 50-324 S	DIXON, O. W. DIXON, O. W. DIXON, O. W. DIXON, O. W. DIXON, O. W.	8208110132* 8208140154 8208140243 8208230005 8208230276	50-395 F 50-395 Q 50-395 P 50-395 F 50-395 Q	ECONOMOS, N ECONOMOS, N ECONOMOS, N EDD INOS, M, EDDLEMAN, W	8208160371* 8208160383* 8208160396* 8208120202* 8208020434*	50-400 G 50-389 G 50-369 G 50-327 R 50-537 D
	8208130284 8208130314	50-325 B 40-704 B	DIXON, D W. DIXON, D W DIXON, D. W. DIXON, D. W. DOCTOR, B. R.	8208240375 8208240423 8208250152 8208300228 8208180232	50-395 F 50-395 P 50-395 P 50-395 P NUREO	EDDLEMAN, W EDDLEMAN, W. EDELMAN, L. EDEY, A EDGAR, Q. L.	8208170253 8208240341 8208030370 8208040643* 8208110160	50-400 Q 50-400 Q 50-382 K CONTRACT 50-537 Q

ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEOURY
8208110160 8208110190 8208110190 8208110190 8208110190	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	ELROD, B A ELSASSER, T ELSON, O EMCH, R EMCH, R	8208030441* 8208300188* 8208180044 8208200278 8208230004	50-335 G 50-273 G 50-247 H 50-155 P 50-155 P	FELTON: J. M FELTON: J. M FELTON: J. M FELTON: J. M FELTON: J. M	8207020007 8207120070 8208020187 8208020190 8208020193	FDIA 50-259 F 50-271 F 50-305 F 50-244 F
8208170327 8208200283 8208300286* 8208040022 8208040409	50-537 Q 50-537 Q REVIEW GRP CONTRACT CONTRACT	EMCH.R EMCH.R EMIOH.J F ENGEL.W P ENGEL.W P	8208230077 8208250109 8207180027 8208050027 8208170391	50-155 P 50-155 P FOIA 71-5908 71-9186	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J, M	8208020194 8208020463 8208030004 8208030013 8208030024	50-382 F 50-352 F 50-322 F 50-213 F 50-416 F
B208050140 8208040001 8208310485 8208040507 8208050186	CONTRACT CONTRACT 50-537 A 50-483 A 50-483 A	ENGELKEN.R.H ENGELKEN.RH ENGELKEN.RH ENTHIBLE.EB ENTHIBLE.EB	8208110079* 8208200102 8208310105 8208060117 8208060132	50-361 F 50-344 P 50-275 Q 50-170 Q 50-170 Q	FELTON, J M FELTON, J M FELTON, J M. FELTON, J, M FELTON, J M	8208030036 8208030047 8208030047 8208030064 8208030078	50-346 F 50-282 F 50-346 F 50-369 F 50-387 F
8208250108 8208170306 8208170306 8208120314* 8208020358	50-483 A NUREQ NUREQ 50-416 E 50-537 H	EPBTEIN, E. EPBTEIN, E EVANB, C EVANB, L EVANB, L J	8208250166* 8208250338* 8208030613* 8208020439 8208030012	40-86 40-86 50-269 70-734 70-27	FELTON, J M FELTON, J M. FELTON, J, M FELTON, J M FELTON, J M	8208030074 8208030484 8208040100 8208040254 8208040245	50-373 F 50-3 F FOIA 50-443 F 50-289 F
8208070206 8208170157 8208170270* 8208110164 8208110164	50-29 P 50-370 R 50-312 R 50-322 9 50-322 9	EVANS, L. J EVANS, L. J. EVANS, L. J. EVANS, L. J EVANS, L. J	8208030034 8208030037 8208030040 8208030043 8208040147	70-143 70-1201 70-1201 70-27 70-143	FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M	8208040283 8208040278 8208040314 8208040326 8208040353	50-266 F 50-29 F 50-309 F 50-261 F 50-10 F
8208240252* 8208300188* 8207300543 8208020384 8208020423	50-247 R 50-293 G TOPREP 50-219 P MISC	EVANB, L. J EVANB, L. J EVANB, L. J EVANB, L. J EVANB, L. J	8208040156 8208040161 8208040162 8208040163 8208040172	70-27 70-734 70-2955 70-1201 70-143	FELTON J H FELTON J M FELTON J. M. FELTON J. M. FELTON J. M	6208040371 8208040380 8208040444 6208040449 8208040467	50-277 F 50-331 F 50-346 F 50-389 F 50-254 F
8208040174 8208040177 8208040631 8208040660 8208060366	50-397 A 50-317 P 50-460 A 50-322 H 50-387 P	EVANG,L J. EVANG,M. EVANG,M. EVERETT,R J. EVERETT,R.J.	8208040187 8208040195 6208230024* 8207060192* 8208160449*	70-1151 70-1257 CONTRACT 40-3453 40-8064	FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M. FELTON, J. M.	8208040473 8208040490 8208040512 8208040604 8208050121	50-10 F 50-267 F 50-267 F 50-346 F 50-289 F
8208070174 8208070333 8208070336 8208100148 8208110077	50-3 P 50-275 R 50-387 P 50-206 P 50-361 F	EVERETT, R. J. EMING, E EWING, E. FADEN, M E FAHNER, T C	8208260429 8207270387 8208030466 8208050369 8208130371	NUREO 50-313 P 50-368 P 50-537 0 40-2061	FELTON, J. M.	B208040032 B208040040 B208040051 B208040058 B208040045	50-285 F 50-321 F 50-321 F 50-320 F 50-441 F
8208120004 8208120095* 8208120303 8208120303	50-29 F 50-99 W 50-99 H MISC 50-206 P	FAIRTILE,M B FALB,E.E. FALCONER,D. FARMER,F O FARNEY,W.L	8208130041 8208170226* 8208160202* 8208170003* 8208160125*	50-278 P 50-373 G 50-269 G 50-155 P 50-409 G	FELTON, J M. FELTON, J M. FELTON, J M. FELTON, J. M. FELTON, J M.	82080400049 8208040074 8208040074 8208040127 8208040304	50-244 F 50-346 F 50-263 F 50-409 F
8208170351* 8208170388 8208230071 8208250025 8208250042	50-204 P 50-275 P 50-275 8 50-307 F 50-287 H	FABAND, A FABAND, A FABAND, A FABAND, A, FABAND, A,	8208020377* 8208130211 8208130267 8208160458* 8208160483*	50-289 Q 50-320 B 50-320 B 50-320 Q 50-320 Q	FELTON, J M FELTON, J M FELTON, J. M FELTON, J. M. FELTON, J M	8208040313 8208040319 9208040322 8208110127 8208110214	50-346 F 50-305 F 50-395 F 50-320 F
8208260349 8208260362 8208310364 8208040262 8208100209	50-247 F 50-275 P 50-275 P 71-9032 50-327 S	FABANO, A FABCELL, D B FAY, C. H. FAY, C. H FAY, G H.	8208200044 8204200034* 8208020115* 8208020273 8208030440	50-320 8 50-250 H 50-266 B 50-266 Q 50-266 P	FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M. FELTON, J. H.	8208110219 8208110220 8208110230 8208110240 8208110246	50-331 F 50-254 F 50-250 F 50-321 F
8208110109 8208160489* 8206180024* 8206180035* 8208190209*	50-327 8 50-397 G FDIA FOIA GA999	FAY, C, W FAY, C, W. FAY, C, W. FAY, C, W FAY, C, W.	8208030472 8208040140 8208040288* 8208130109 8208130130	50-266 Q 50-266 P 50-266 P 50-266 P 50-266 P	FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M.	8208110251 8208110254 8208110259 8208110266 8208110286	50-346 F 50-295 F 50-295 F 50-275 F 50-373 F
8208130142 8208130173 8208130212 8208130216* 8208170149	50-445 0 50-445 0 50-445 0 50-445 0 50-445 0	FAY, C, W FAY, C, W FAY, C, W FAY, C, W FAY, C, W	B208160041 B208160043* B208160510 B208160518* B208170066	50-266 R 50-266 R 50-301 B 50-301 B 50-301 P	FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8208170347 8208170354 8208170362 8208190032 8208190038	50-269 F 50-309 F FOIA FOIA
8208240185 8208240231 8208240344 8208240373 8208240378*	50-445 0 50-445 0 50-445 0 50-445 0 50-445 0	FAY: C. W. FAY: C. W FAY: C W. FAY: C. W. FAY: C. W	8208170268 8208190224 8208200151 8208260240 8208270577*	50-266 P 50-266 F 50-266 G 50-266 G	FELTON, J. M.	8208190055 8208190072 8208190405 8208190406 8208190430	50-358 FOIA 50-269 F 50-338 F 50-155 F
8208270419 8208270435 8208270437 8208270440 8208270441	50-445 G 50-445 G 50-445 G 50-445 G 50-445 G	FAY, C. H. FAY, C. W. FAY, C W. FAY, J. M. FEE, W. F	6209310171* 8208310264 8208310267* 8208310481*	50-266 G 50-301 B 50-301 S REVIEW QRP 50-213 P	FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M FELTON, J. M	8208230403 8208230408 8208230418 9208230444	FGIA 50-537 A 50-320 P 50-277 G
8208270443 8208270444 8208270445 8208270447* 8208270452	50-445 0 50-445 0 50-445 0 50-445 0 50-445 0	FEHRINGER, D. J FEIERABEND, C. D FEIL, R. A. FEIMAN, B. D. FEITKNECHT, C.	8208040014 8208050521* 8208160127* 8208130351* 8208030343	MIBC 50-282 G 50-397 G 40-8823 50-334 R	FELTON, J. M.	820825000 1 820825006 1 82082504 1 0 820825052 6 820825054 0	40-86 FOIA 70-143 FOIA
8208270453 8208270456* 8208270624 820826006 8208310189	50-445 Q 50-445 Q 50-445 Q FDIA 50-443 D	FELDE, D. W. FELDMAN, E. M FELDMAN, E. M. FELLHAUER, R FELTON, J. M.	8208240087 8208060039 8208240045 8208310157 8206150008	NUREO RES RES 50-454 I FOIA	FELTON, J. M.	8208250556 8208250559 8208260001 8208260003 8208260004	FDIA 50-10 F 40-2061 FDIA 50-438 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUDJECT
FELTON, J M	8208240007 8208240035 8208240041 8208240044 8208240044	F01A 50-483 A F01A F01A F01A	FINAMORE B A	8208050378 8208070153 8208090153 8208110159 8208110159	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8208260141* 8208260261* 8208260323* 8208300233* 8208310153*	50-311 8 50-272 9 50-272 8 50-311 8 50-311 8
FELTON, J M FELTON, J M FELTON, J. M FELTON, J M FELTON, J M	8208260054 8208260058 8208260089 8208260096 8208260102	90-266 F 50-358 H 50-269 F 50-313 F 50-416 F	FINAMORE B A FINAMORE B A FINAMORE B A FINCH O L FINDLEY D E	6208120093 6208120093 6208240330 6208030730* 6208030146*	50-537 0 50-537 0 50-537 0 50-3 F CONTRACT	FRAHM, R FRAHM, R FRAHM, R FRAME, P W FRANCIS, E	8208310274* 8208310318 8208310322* 8208200081* 8208050045	50-311 6 50-311 8 50-311 8 40-86 40-299
FELTON, J M FELTON, J. M FELTON, J M FELTON, J M FELTON, J M	8208260107 8208260110 8208260116 8208260296 8208260304	FOIA 50-324 F FOIA 50-361 F FOIA	FINLEY, A Q. FINLEY, A O FINLEY, A O FINNIAN, C F FINNIAN, C F	8208020302* 8208300180* 8208310431* 8208120219* 8208170100*	70-34 50-265	FRANKLIN, L C FRANKLIN, L C FRAVEL, M T FREDRICKSON, P FRENCH, L	8208030229 8208030232 8208100097 8208140184* 8208090052*	70-1314 40-8546 80-327 8 50-241 0 50-27 8
FELTON, J M	8208260313 8208260336 8208260338 8208260353 8208260364	F01A 50-369 F 50-259 F 50-263 F 50-483 F	FINNIAN.C F FINNIAN,C F FINNIAN.C F FINNIAN.C F FINNIAN.C F	B208170112* B208170117* B208170121* B208170125* B208170131*	50-409 P 50-409 P 50-409 P 50-409 P 50-409 P	FRENCH, L A FREY, D G FREY, D G FREY, J M FRIEDLANDER, M	6208020301* 6208030748* 6208300243 6208100378* 6208020275	50-27 S 50-537 D 50-537 D COMMISSION 50-247 D
FELTON, J M FELTON, J M, FELTON, J, M FELTON, J, M FELTON, J M	8208260376 8208260378 8208260418 8208260447 8208260529	50-369 F FDIA 50-269 F 50-213 F 50-269 F	Fiorelli, o Firestone, e a Figh, r f Figh, r f Fitzgerald, m J	8208160279* 8207110016 8208240288* 8208310113* 8208050460*	50-528	FRIEDMAN, L F FRIEND, H B FROMM, E FROUNFELKER, R FROUNFELKER, R	8208180083 8208190142* 8208170420* 8208040224 8208270494	70-261 50-275 & CONTRACT 50-155 J
ELTON, J M ELTON, J M ELTON, J M ELTON, J M	8208240551 8208270010 8208270563 8208270584 8208270599	50-289 T 50-155 R 50-261 F 50-3 F 50-255 F	FITZGERALD.M J FITZPATRICK.B FITZPATRICK.B FITZPATRICK.B FITZPATRICK.B	8208140033* 8208020232* 8208050220* 8208140005* 8208230347*	50-219 8 50-247 8 50-247 8 50-247 8 50-247 8	FRYE, J FRYE, J H FRYE, J H FRYE, J H	8208180121 8208170246 8208170325 8208270405 8208300293	50-142 0 50-142 0 50-142 0 50-358 0 50-142 0
ELTON, J M ELTON, J. M ELTON, J. M ELTON, J. M ELTON, J. M	8208310024 8208310039 8208310057 8208310087 8208310426	F01A 50-29 F 50-2 F 50-348 F 71-6698	FITZPATRICK, B FITZPATRICK, F FLACK, E FLAHERTY, J R FLAHERTY, J R	8208310186* 8208130236* 8208300225 8208200109* 8208200176*	50-247 8 40-86 14E 50-298 8 50-298 8	FRYE, J H FULLER, B FULLER, C FULLER, C FULLER, G	8208300301 8208040373 8208050379* 8208160027* 8208200124*	50-142
ELTON: J. M ELTON: J. M. ENNICK: M EROUSON: O. A ROUSON: R. L.	8208310468 8208310479 8208020354 8208190121 8206200020	50-245 F 50-286 F 50-537 U 50-70 0 50-397 A	FLEENDR.C. FLEENDR.C. FLEENDR.C. FLEENDR.C M FLEIBCHAKER.D	8208040334 8208040493 8208040437 8208260580 8208030338	CONTRACT CONTRACT CONTRACT 50-289 P 50-275 9	FULLER, G FULLER, G. FULLER, G FURR, B FURSE, R	8208200141# 8208240056# 8208240079# 8208160278 8208020358	50-267 B 50-267 B 50-267 B 50-261 Q 50-537 H
RLANDIE J RLANDIE J RINERIK YIF L. EDLERIF, B	8208100133 8208100133 8206220204* 8208060130* 8208240230	50-423 A 50-423 A 50-29 P 50-263 F 50-219 P	FLE1SCHAKER, D FLE1SHER, Z S FLEMING, T E. FLETCHER, W D. FLETCHER, W D	8208050338 8208160440 8207140406 8208270323* 8208270323*	50-275 0 50-247 0 40-8743 50-266 0 50-266 0	GAD,R K GAD,R K GAD,R K GAD,R K GAD,R K	8208060133 8208060126 8208060126 8208060133 8208060137	50-443 0 50-443 0 50-443 0 50-443 0
EDLER, J EDLER, P. B EDLER, P. B EDLER, P. B EDLER, P. B	8208170074 8208020370 8208050084 8208050126 8208050270	50-321 J 50-219 B 50-219 B 50-219 B 50-219 B	FLITTON, V E FLORY, C FLORY, C A FLORY, C A. FLYNN, C	8208020060 820826051 1 820811001 1 8208260559 8208070010	REB 40-8064 Habte Mot Habte Mot 50-289 P	GAD,R K GAD,R K GAD,R K GADLER,B J GADOH,O R	8208040137 8208040151 8208040151 8208300170 8208300293*	50-443 G 50-443 G 50-443 G PRM 50-409 R
EDLER, P B IDLER, P, B IDLER, P, B IDLER, P B. DLER, P, B,	8208050346 8208050443 8208050453 8208060201 8208060247	50-217 S 50-217 B 50-217 S 50-217 P 50-217 Q	FLYNN, J FLYNN, J, FLYNN, J, FLYNN, J FLYNN, J D	8208040245 8208040311 8208040323 8208130473 8208160170	50-280 P 50-249 P 50-317 P Nureo 50-338 A	Gadow, G R Gaineg, T. M Galazzo, S Galazzo, S Gallagher, W. J	8208120310* 8208040254 8208200112* 8208230304* 8208190271*	50-409 R 71-62 50-220 B 50-220 B 0A999
DLER, P. B. DLER, P. B. DLER, P. B. DLER, P. B DLER, P. B	8208050257 8208100213* 8208120037 8208130295 8208150034	50-219 P 50-219 Q 50-219 R 50-219 8 50-219 8	FLYNN, J. D FOLEY, T FONNER, R. L FOOTE, V FORD, C A	8208140185 8208140010* 8208300108 8208030752* 8208020088*	50~358 A 50~286 G 70~143 50~537 D 50~338 P	OALLO, J. OALLO, J OALLO, J. GALLO, J. GALLO, J.	8208030304 8208030304 8208040232* 8208040232* 8208040243*	50-155 Q 50-155 Q 50-155 Q 50-155 Q
DLER, PB DLER, PB DLER, PB DLER, PB. DLER, P.B	8208160174 8208190157 8208190305 8208260194 8208270103	50-217 S 50-217 P 50-217 Q 50-217 S 50-217 P	FOREMAN, H FORNEY, W L FORREST, B Q FORT, M D FORT, M D	8208170121 8208230067* 8208020267 8208110045* 8208110144	50-70 0 50-484 0 50-338 J 50-537 D 50-537 Q	OALLO, J GALLO, J GALLO, J GALLO, J	8208040243* 8208040111 8208060111 8208110194 8208110194	50-155 0 50-155 0 50-155 0
DLER, P.B. DLER, P.B DLER, P.B DLER, P.B. HER, P.B.	8208270111* 8208270280* 8208270284 8208300055 8208310413	50-217 P 50-217 R 50-217 P 50-217 S 50-217 P	FOSTER, D O FOSTER, D O FOSTER, D. O. FOSTER, H. E FOX, D F.	8208160524* 8208200005 8208200161 8208310280* 8208190272*	50-424 G 50-424 B 50-424 B 0A999 GA999	GALLO, J GALLO, J, GALLO, J GALLO, J GALLO, J	8208170130 8208170130 8208170264 8208170264 8208240377*	50-454 H 50-454 H 50-155 Q 50-155 Q 50-155 G
der, J de, J de, J an, B, D. urn, T	8208170200 8208040674 8208040383 8208130347 8208020153*	50-321 J CONTRACT CONTRACT 40-8823 50-336 S	FOX, D. F FRAHM, R. FRAHM, R FRAHM, R FRAHM, R	8208190289# 8208020327# 8208020353 8208020359# 8208050079#	GA799 50-272	GALLO, J. GALLO, J GALLO, J GALLO, J GALLO, J GALLO, J.	8208240377* 8208270333* 8208270333* 8208270414 8208270414	50-155 0 50-155 0 50-155 0 50-155 0 50-155 0
urn, t. Ldi. L. Hore. B. A. Hore. B. A. Hore. B. A.	8208120280* 8208040401 8208020207 8208020207 8208020249	50-336 B 50-201 P 50-537 G 50-537 G 50-537 G	Frahm, r Frahm, r Frahm, r Frahm, r Frahm, r	8208050380* 8208100018* 8208100086* 8208130219* 8208180080*	50-311 8 50-272 8 50-272 8 50-311 8 50-272 8	GALLD, J GALLD, J GALLD, R. GALLD, R M GALLUP, D R.	8208270518* 8208270518* 8208020285* 8208020273* 820826097	50-155 Q 50-155 Q 50-309 Q 50-322 Q NUREO
(Ore. B. A. fore. B. A fore. B. A fore. B. A. fore. B. A	8208020249 8208020300 8208050352 8208050352 8208050378	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	Frahm, r Frahm, r. Frahm, r Frahm, r Frahm, r.	8208170011* 8208170118* 8208170146* 8208170146* 8208170230*	50-311 8 50-311 8 50-311 8 50-311 8	QALMISH.M. QANAPDL.B.D. QARCIA,F.J. QARCIA,P.J. QARDNER:R.N	8208120183 8208070016 8208040070 8208060348 8208240425*	50-337 H NUREO 40-1162 40-3453 80-329 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT Cateodry	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GARING, P J GARING, P J GARING, P J GARING, P J GARING, P J	8208250074* 8208250172* 8208250187* 8208250237* 8208250244*	40~86 F0IA 40~86 40~86	Glesler, C W Glesler, C W Glesler, C, W Glesler, C W Glesler, C W	8208050276 8208050486 8208060324* 8208070207 8208070253	50-305 P 50-305 8 50-305 F 50-305 B 50-305 F	ODDMAN, L 8 ODDMAN, L 8 ODDMAN, M J ODDMAN, M J ODDDRICH, L. D,	8208200076# 8208200223# 8208030749 8208260458 8208260486	50-409 B 50-409 B TOPREP TOPREP NUREO
GARINO,P J,	8208280364*	40-86	GIESLER,C W	8208100159	50-305 Q	QOODWIN, D C	8208050170#	50-296 B
GARINO,P J	8208250375*	40-86	GIESLER,C W	8208100178	50-305 P	QOODWIN, E F	8208120347	50-440 A
GARINO,P J	8208250376*	40-86	GIESLER,C W	8208120213	50-305 R	QOODWIN, E F	8208120364	ACRB
GARNER,L W	8208250376*	50-324 @	GIESLER,C W	8208130093	50-305 B	QORM-BROWN, J	8208040537	WASTE MOT
GARNIER,P	8208030182*	50-237 8	GIESLER,C W	8208130137	50-305 P	QORM-BROWN, J	8208040541#	WASTE MOT
H C'ALINAS H C'ALINAS H C'ALINAS H C'ALINAS	8208310279* 8208050354 8208050416* 8208100087 8208100222	50-237 8 50-309 P 50-309 Q 50-309 P 50-309 P	GLEBLER,C W OIESLER,C W OIESLER,C W GIESLER,C W GIESLER,C W	8208130235 8208170078 8208230142 8208240181 8208240250	50-305 8 50-305 8 50-305 6 50-305 K 50-305 P	OOULD, 8, 8 ORAESSER, K. L. ORAESSER, K. L. ORAESSER, K. L. ORAESSER, K. L.	8209250087 8208030233 8208030310 8208130103 8208130225	NUREQ 50-295 8 50-295 8 50-295 R 50-304 8
H L,YTIRRAD H L,YTIRRAD H L,YTIRRAD H L,YTIRRAD	8208100304 8208160070 8208160143* 8208170128 8208180045	50-309 P 50-309 P 50-309 Q 50-309 P 50-309 P	GIEBLER,C W GIEBLER,C W GIEBLER,C W GILBERT,L D GILBERT,R A	8208300183 8208310205 8208310305 8208190293* 8208040569	PRM 30-305 P 50-305 P 50-298 Q 50-322 A	GRANT, J M GRANT, J M GRANT, P, GRANT, W, B GRANT, W, B.	8208040636 8208260325 8208200044 8208200210* 8208250368*	50-424 A 50-424 A 50-320 S 50-255 Q 40-86
GARRITY, J. H	8208170283	50-309 Q	OILBERT,R,A OILDENHORN,AJ OILDENHORN,A,J OILDENHORN,A,J OILDENHORN,A,J	8208130004	50-322 A	ORANT, W B.	8208270142*	50-10 G
GARRITY, J. H	8208270524*	50-309 R		8208310462	CONTRACT	ORABHAW, T D	8208300172	PR
GARRITY, J. H	8208310261	50-309 P		8208310512	CONTRACT	ORAVEB, C. W	8208190316*	50-413 A
GARRITY, J	8208310380	50-309 P		8208310517	CONTRACT	ORAVEB, C W	8208190319*	50-413 A
GARY, R J	8208030210	50-446 8		8208030533	REGOD	ORAVEB, C W.	8208190321*	50-413 A
GARY,R.J	8208140269	50-445 8	OILMAN.B.A	8206060022*	50-247 U	ORAVEB, C W	8208170326*	50-413 A
GARY,R.J	8208170239	50-445 A	GIMPEL.J	8208020358	50-537 H	ORAVEB, C. W	8208170337*	50-413 A
GARY,R J	8208190164	50-445 A	GIMBBERG.T	8208040002	RES	ORAVEB, C W	8208170346*	50-413 A
GARY,R J.	8208310298*	50-445 Q	GIMBBERG.T	8208050011	RES	ORAVEB, C W	8208170352*	50-413 A
GABPER,J K	8208030443	TOPREP	GIRARD.E.H	8208030374*	50-438 G	ORAVEB, R. H	8208120238	50-213 R
GASPER, J.K.	8208030474*	TOPREP	GIRARD,E H	8208140371*	50-400 G	Oraveb, R. H.	8208270271#	50-213 R
GAYNDR, R.K.	8208030115	27-39	GIUFFRIDA,L D.	8204200074	COMMISSION	Oraveb, R. H	8208270551*	50-213 R
GAYNDR, R.K.	8208030125	27-39	GLAUBER,J E	8208250383*	50-259 P	Oray, J. R.	8208050058	50-289 0
GAYNDR, R.K	8208130242	27-39	GLAUBER,J E.	8208250371*	50-259 P	Oreen, H. J.	8207150417	50-327 B
GEIER, J.D	8208310308	50-461 E	GLAUBER,J E	8208250402*	50-259 P	Oreen, H. J	8208020080	50-327 B
GEIGLEIN, JE	8208030533	REGOD	GLAUBER, J. E	8208250415*	50-259 P	OREEN. H. J.	8208020074	50-240 8
GEIST, JD	8208270384#	50-52B I	GLAUBER, J. E	8208250426*	50-259 P	OREEN. H. J	8208020111	50-257 8
GERADI, KA,	8208170274	50-247 0	GLAUBER, J. E.	8208250437*	50-259 P	OREEN. H. J	8208020143	50-328 8
GERBER, CA	8208160032	50-220 0	GLAUBER, J. E	8208250443*	50-259 P	OREEN. H. J	8208020317	50-259 8
GERDEMAN, FW	8207200515	40-8674	GLEABON, J. F	8208110075	50-483 0	OREEN. H. J	8208020375	50-328 8
GERNER, L.	8208040475#	50-254 F	GLEABON, J. P	8208170136	50-483 0	CREEN, H. J.	8209030150	50-327 B
GERSHOWITZ, H	8208110125	27-47	GLOVER, J	8208050236*	50-295 8	ORBEN, H. J.	8209030160	50-259 B
GERSTNER, W C	8208050313	50-461 B	GLGVER, M.	8208260385*	50-369 F	ORBEN, H. J	8209030175	50-259 B
GERSTNER, W C	8208050413	50-461 B	OLOVER, M. S	8208260340*	50-369 F	ORBEN, H. J	8209050100	50-328 B
GERSTNER, W C	8208050477	50-461 B	GLOVER, M. S	8208260345*	50-369 F	ORBEN, H. J	8209050108	50-328 B
GERBTNER, W. C.	8208170127	50-461 8	ONUQNOLI, Q N	8208030113	WABTE MQT	OREEN, H. J.	8208050158	30-328 8
GERBTNER, W. C	8208170217	50-461 8	ONUQNOLI, Q N	8208240543	40-8585	OREEN, H. J.	8208050164	50-274 8
GERBTNER, W. C.	8208300162	50-461 A	QODDARD, R. J	8208040025	50-155 Q	OREEN, H. J.	8208050208	50-257 8
GERTECH, A. J	8208120086#	50-313 R	QODDARD, R. J.	8208060070	50-155 Q	OREEN, H. J.	8208050215	50-260 8
GERUEKY, T. M	8208030213	REVIEW ORP	QODDARD, R. J.	8208060073*	50-155 Q	OREEN, H. J	8208050229	50-257 8
GERUBKY,T M.	8208120130	50-289 H	GODDARD,R J	8208060076#	50-155 0	Green, H. J	8208050279	50-259 B
GERUBKY,T M	8208270415	50-412 0	GODDARD,R B.	8208070264	50-155 0	Green, H J	8208050324	50-260 B
GERY,A	8208040281	NUREO	GODY,A T	8208050085#	50-245 G	Green, H J.	8208050327	50-327 B
GETTY,B C.	8208020247*	50-133 8	GODY,A T.	8208050277#	50-322 Q	Green, H J	8208050336	50-327 B
GIANNUZZI,A J	8208310325*	50-388 0	GODY,A T	8208050317#	70-135	Green, H, J	8208050394	50-296 B
GIARDIELLO, P	820830021 4	50-293 8	QODY, A, T	8208050400#	50-217 Q	GREEN, H. J	B208050409	50-327 8
GIARDIELLO, P F	820830021 0	50-293 8	QODY, A, T.	8208050469#	50-271 G	GREEN, H. J.	B208050450	50-259 8
GIARDIELLO, P F.	8208300274*	50-293 8	QODY, A, T	8208170077#	70-184	GREEN, H. J.	B208090191	50-327 8
GIBBONS, T. D	8208030148*	70-1151	QODY, A, T	8208230302#	50-387 G	GREEN, H. J.	B208120113	50-327 8
GIBBONS, T D	8208030409*	50-370 Q	QODY, A, T.	8208300227#	70-135	GREEN, H. J.	B208120184	50-260 8
OIBBONS, T D. OIBBS, D C OIBSON, A F OIBSON, A F. OIBSON, A F	8208160387*	50-390 G	ODDY, J. M	8208050300*	50-387 G	OREEN, H. J.	8208120254	50-326 8
	8208310451*	GEN TEC 18	ODETZ, B	8208030133	NUREQ	OREEN, H. J.	8208120312	50-326 8
	8208030129	70-143	OOLDBERG, D. J.	8208170284	50-352 Q	OREEN, H. J.	8208160332	50-327 8
	8208030132	70-1113	OOLDBERG, D. J	8208170287*	50-352 Q	OREEN, H. J.	8208200002	50-327 8
	8208030134	70-1151	OOLDBERG, J. H.	8208100083	50-498 A	OREEN, H. J.	8208200030	50-294 8
Oibson, A. F	8208030137#	70-1113	QOLDBERG, J H	8208170282	50~478 A	OREEN, H. J.	8208200062	50-257 8
Oibson, A. F	8208030144#	70-1151	QOLDBERG, J H	8208240272	50~478 A	OREEN, H. J.	8208200118	50-260 8
Oibson, A. F	8208030235	70-1113	QOLDBERG, J. R.	8208240260	50~289 Q	OREEN, H. J.	8208270078	50-260 8
Oibson, A. F	8208030273	70-1113	QOLDBERG, J. R.	8208240272	50~289 Q	OREEN, H. J.	8208270086	50-259 8
Oibson, A. F	8208030316	70-1201	QOLDBERG, M. A	8208020358	50~537 H	OREEN, H. J	8208270207	50-327 8
01680N.A.F 01680N.A.F. 01680N.A.F 01880N.A.F 01880N.A.F	8208030330 8208030342 8208030505 8208030629 8208030656	70-824 70-27 70-1201 70-1151 70-143	Goldberg, 9. C. Goldberg, 9. C. Goldberg, 9. C. Goldberg, 8. C. Goldberg, 8. C. Goldberg, 8. C.	8208120135 8208140237 8208170275 8208240278 8208100154	50~395 Q 50~454 Q 50~454 Q 50~395 Q 50~443 D	Green, H. J Green, H. J Green, H. J Green, H. J Green, H. J.	8208270231 8208270282 8208270298 8208270278 8208270474 8208270492	50-259 8 50-260 8 50-328 8 50-296 8 50-259 8
01880N; A. F	8208100197	90-260 8	OOMES, J. R.	8208160083	50~293 Q	OREEN, H. J.	8208270510	50-259 8
01880N; A. F.	8208160205	70-143	OOMES, J. R	8208160087*	50~293 Q	OREEN, H. J.	8208270544	50-259 8
01880N; A. F.	8208160487	70-27	OONZALEZ, A	8207260247*	50~213 P	OREEN, H. J.	8208300270	50-259 8
01880N; A. F.	8208170160	REGOD	OOOD, H. R	8208180032	PR	OREEN, H.	8208040452#	50-346 F
01880N; A. F.	8208230326	70-27	OODDHOPE, A. C.	8208030258	27~39	OREEN, H	8208060109#	50-346 F
OIBSON; J. OIESLER, C. W. OIESLER, C. W OIESLER, C. W.	8208120300# 8208020171# 8208020172# 8208030374 8208030513	50-336 R 50-305 F 50-305 F 50-305 P 50-305 P	OCODHOPE: A C. OCODIE: J B. OCODIE: J. B. OCODHAN: L. B. OCODHAN: L. B.	8208040229 8208170182 8208310245 8208070251* 8208120313*	50~549 0 50~373 0 50~373 0 50~409 8 50~409 R	GREENBERO, E. V. GREENBERO, E. V GREENBERO, E. V GREENBERO, E. V. GREENBERO, E. V.	8208050352 8208050352 8208050352 8208050352	50-537 9 50-537 9 50-537 9 50-537 9 50-537 9

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTVA	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT
REENBERG, E V REENBERG, E V REENBERG, E V REENBERG, P A	8208070153 8208070153 8208070153 8207050007* 8208030213	50-537 G 50-537 G 50-537 G 50-537 D REVIEW GRP	HAIRSTON, W G	8208020122# 8208020131# 8208020174# 8208120231# 8208120236#	50-348	HARSTEAD, G A HART, A P HART, J HART, J HART, J HARTMAN, C J	8208250358* 8208260445* 8208170341 8208270168 8208170435*	50-413 A CONTRACT 50-382 8 50-382 8 50-155 F
REENE, G A	8208040002	RES	Hairston, W G	6208200173*	50-348 8	HARTUNO, L	8208170374*	WASTE MOT
REENE, G A	8208050011	RES	Hairston, W C	6208200183*	50-348 8	HARTUNO, L	8208170378*	WASTE MOT
REENHOUSE, N A	8208100251	REGOD	Hairston, W O	6208200190*	50-348 8	HARTY, R	8208180126	NUREG
REENKORN, R A	8208120381*	CONTRACT	Hairston, W C	8208270261*	50-348 8	HASKINS, J J	8208030589	50-228 R
REENMAN, E G	8208020278*	50-277 G	Hairston, W C	6208270269*	50-348 5	HASKINS, J J	8208030598*	50-228 R
REENMAN, E 0	8208050243*	50-293 0	Hairston, # 0	8208300320*	50-344 8	HASSELL, D F	8208050050	50-247 0
REENMAN, E 0	8208230041*	50-20 0	Haist, D. P	8207180442*	50-508 Q	HASSELL, D F	8208100053	50-247 0
REENMAN, E 0	8208300047*	50-244 0	Haist, D. P	8208160266*	50-508 G	HASSELL, D F	8208250241	50-275 0
REENMAN, E 0	8208300248*	50-293 0	Hajinian, C. H	8208060162	50-482 D	HASSELL, D F	8208310077	50-275 0
REENMAN, E G	8208300250*	50-283 0	Hale, C. J	8208030452*	GA999	HATHAWAY, J.	8204200003	50-537 A
REEVES, J T	8208040593	Haste Mot	HALE.C J.	8208160200*	GA999	HATHAWAY, JS	8208040106*	50-537 D
REEVES, J T	8208120373	Haste Mot	HALE.C J	8208160404*	GA999	HAWKINS, FC	8208130323*	50-329 G
REEVES, J T	8208190020	Waste Mot	HALE.C J	8208190107*	GA999	HAWKINS, FC	8208170302*	50-546 G
REGER, L R	8208050478*	50-155 G	HALE.C J	8208190214*	GA999	HAYDEN, P	8208120272	50-537 H
REGER, L R	8208100299*	50-10 G	HALE.C J	8208190272*	GA999	HAYES, C	8208120314*	50-416 E
REGER, L R REGER, L R REGER, L R. REGER, R REITZER, C	8208300114* 8208300194* 8208310232* 8208100242* 8208020275	70-1308 50-315 G 50-255 G 50-440 G 50-247 G	HALE,C J HALE,C J HALE,C J HALL,B L HALL,B L	8208170269* 8208200054* 8208310127* 8208100224* 8208300167*	GA777 50-478	HAYES, D HAYES, D HAYES, D HAYES, D W HAYES, F R	8208100125 8208100163 8208100317 8208050441* 8208310347*	50-315 8 50-315 8 50-316 8 50-237 0 TOPREP
IIBBLE,R P IIFFINO,E P IIFFINO,E P IIMES,B K 'IMES,B K	8208180232 6208240143 8208240147* 8208030085* 8208230430*	NUREO 50-16 R 50-16 R 50-247 H FOIA	HALL.D N HALL.R A HALL.R E HALL.R E HALLIGAN.T J	8208170274* 8208120177 8208180066* 8208180081* 8208240321	50~482 G 50~537 H 50~313 G 50~285 G 50~387 G	HAYBS, F. R O KAYNEB, J. O HAYNEB, J. O O K. BBAYEH O K. BBAYEH	8208310353* 8208230042 8208230047* 8208230074 8208230086*	50-387 E 50-206 Q 50-206 Q 50-206 Q
DCE,R H	8208120128	50-309 R	HAMADA, CH	8208160325*	50-528 G	HAYNES, J 0	8208230249	50-361 Q
DESCH.G L	8208270481	50-382 Q	HAMBRIGHT, DA	8208020358	50-537 H	HAYNES, J 0	8208230348	50-206 Q
DGAN,E M	8208030744#	50-537 D	HAMLIN, JB	8208250234	50-382 0	HAYNES, R	8208250291*	40-86
DSS,R &	8208040051	50-395 A	HAMLIN, JB	8208250234	50-382 G	HAYNES, R. C	8208060283	50-322 A
DSSMAN,H	8208030252	50-395 Q	HAMLIN, JB	8208250234	50-382 G	HAYNES, R. C	8208100030	50-247 F
OSSMAN, H OSSMAN, H OSSMAN, H OSSMAN, H OSSMAN, H	8208050472 8208190117 8208240215 8208240353 8208250263	50-395	HAMLIN.J B HAMMILL,K J HAMMONO,H J HAMAFORD,T	8208270446 6208030166 8208070078 8208160114 8208120125*	50-382 0 HABTE MOT 50-312 F 50-312 F 50-341 R	HAYNEB,R C HAYNES,R C HAYS,J,C HAZLE,A J HAZLE,A J	8208100143 8208230263 8208110244* 8208030568 8208170178	50-286 F 50-309 8 50-250 F REVIEW GRP REVIEW GRP
OTENHUIS, M	8208040028	50-251 P	HANAUER, S H	8208110050	50~3 P	HEAD, G F	8208040193	50-344 P
UENEICH, D	8208030380	REVIEW ORP	HANCOCK, J A	8208310507	50~302 B	HEAD, S A	8208020358	50-537 H
UPE, C	8208310331	PR	HANNES, P H	8208020293*	50~322 Q	HEAD, T G.	8208190141	71-6717
ILD, R	8208110191	50-413 O	HANNETT, D A	8208030714	XPORTLIC	HEALY, J W	8208170117	50-537 T
ILD, R	8208110171	50-413 G	HANNETT, D A	8208030718*	XPORTLIC	HEATHERLY, T	8208160401*	50-369 @
MBLE, F W	8208020385*	50-286 8	Hannon, J	8208020426	50-247 P	HEATHERLY, T L	8208030425*	50-390 0
PPY, J Q	8208050009	RES	Hansen, L	8208050038	71-9132	HECKER. O E	8208170180*	50-438 A
STAFSGN, P F	8208130327	40-2061	Hanson, M	8208300274	PR	HEDZIK, W A	8208050438	50-358 8
STAVE, R,	8208260341	CONTRACT	Harbour, J	8208180114	50-329 0	HEGGLAND, R W	8208240467	40-8793
STAVE, R	8208260416	CONTRACT	Hardin, A	8208140374#	50-250 0	HEHL, C W	8208100161	50-324 8
STAVE, R	8208260501#	CONTRACT	HARDINO, M R	8207150422#	50-327 8	HEIDEL.C M	8208190221*	50-341 A
STAVE, R P	8208040685#	CONTRACT	HARDINO, M R.	8208020083#	50-327 6	HEIDER.J A	8208260414	NUREG
STAVE, R P	8208060353#	CONTRACT	HARDINO, M R	8208020167#	50-328 8	HEIDER.L H	8208230165	50-271 P
STAVE, R P	8208260442	CONTRACT	HARDINO, M R	8208020379#	50-328 8	HEIMAN.D	8208260327	XPDRTLIC
FIERREZ, J H	8208260442	50-498 Q	HARDINO, M R	8208030154#	50-327 8	HEINS.J F	8208050200*	GA999
FIERREZ, J H FIERREZ, J H FIERREZ, J K (AZDOWSKI, G NSS. W P	6208090278*	50-498 G	HARDING, M R	8208050105#	50-328 8	HEITNER, K.L.	8208040645	50-309 P
	6208200104	50-498 G	HARDING, M R	8208050111#	50-328 8	HELLER, J.K.	8208100283*	50-255 Q
	6208260133	50-498 G	HARDING, M R	8208050141#	50-328 6	HELLER, R.	8208020141*	50-272 E
	8208270257	50-317 F	HARDING, M R	8208050333#	50-327 8	HELLER, R.	8208050344*	50-272 E
	6208030050	50-250 P	HARDING, M R	8208050342#	50-327 6	HELLER, R.	8208050509*	50-272 E
KNEY.C KNEY.C KNEY.C HSIO.R T NER.8	8208050361 8208100081 8208240184* 8208240033 8207110018	50-313 6 50-313 6 50-298 0 71-9132 FOIA	HARDING, M R HARDING, M R HARDING, M R HARDING, M R HARDING, M R	8208050417# 8208070175# 8208120124# 8208120262# 8208120315#	50-327 S 50-327 S 50-327 S 50-328 S 50-328 S	HELLER, R HELLER, R HELLER, R HELLER, R HELLER, R	6208130117* 6208130253* 6208190133* 6208190144* 6208240379*	50-272 8 50-272 6 50-311 8 50-311 8
NER, B.	8208240372*	FOIA	HARDING, M R HARDING, M R HARDING, M R HARDY, J E HARDY, M P.	8208200008*	50-327 8	Heller, r	8208240153*	50-272 S
IAN, Y. F	8208040340*	CONTRACT		8208270218*	50-327 5	Heller, r.	6208310267*	50-272 S
IAN, T. F,	8208040385*	CONTRACT		8208270304*	50-328 6	Heller, r.	6208310400*	50-311 S
IAN, T. F	8208040478*	CONTRACT		8208260438	NUREO	Helsley, p	6208160186	REVIEW GRP
AN, Y. F	8208040643*	CONTRACT		8208260459*	CONTRACT	Heltemes, c J.	6208040020	MISC
AN, T F	8208040667	CONTRACT	HARIED, J A	8208130467	NUREO	HEMBREE, P. P	8208050345	50-537 H
AN, T, F	8208040680*	CONTRACT	HARKLEROAD, R	8208050274*	50-219 8	HENDERSON, D. J	8208040167	RES
AN, T, F	8208110064	40-8743	HARMON, D F	8208250067*	40-84	HENDON, B	8206270038*	50-537 D
AN, T F	8208180151*	CONTRACT	HARMON, D F	8208250313*	40-84	HENDRIX, G, W.	8208170175	REGGD
AN, T, F	8208300024*	CONTRACT	HARMON, D F.	8208250368*	40-84	HENLEY, J	8208050286	50-537 H
AN, T. F	6208300027*	50-320 P	Harmon, D F	8208280371*	40-86	HENRY, D	8208040185	REVIEW GRP
EN, E W	6208130481	NUREØ	Harran, G.	8208120071*	50-245 R	HENRY, O K	8208120177	50-537 H
EN, E W,	8208170316	NUREØ	Harrell, P H	8208160200*	96-279	HERDT, A. R	8208160263*	50-321 G
ER, C,	8208050131*	50-219 8	Harr Ington, P M	8208050539*	50-273 Q	HERINO, R. F	8208100175	50-315 G
RMAN, D L	8208030045	RES	Harr Ington, H D	8208020342*	50-273 Q	HERING, R F	8208100295	50-315 P
rston, C.	8208160021*	50-348 R	Harr Inoton, W. D	8208120060*	50-293 0	HERINO,R F	8208230340	50-315 F
rston, C.	8208160079*	50-364 P	Harr Inoton, W. D	8208230234	50-293 P	HERNAN,R &	6208230094	50-327 E
rston, W. C.	8207010234*	50-348 8	Harr Is, J R	8208030216*	50-438 Q	HERNANDEZ, G	6208160123*	50-312 0
rston, W. O.	8207010251*	50-348 8	Harr Ison, F	8208120016*	50-324 R	HERNANDEZ, G.	6208160422*	50-362 0
rston, W. O.	8208020118*	50-348 6	Harr Ison, W C.	8208240147*	50-14 R	HERNANDEZ, O	6208160509*	50-312 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
HERRIR K HERRIRO, K HERRIRO, K HERSCH, M HERSCH, M HERSLOFF, L W	8204150024* 8208240037* 8208030018 8208040238 8208230116	FOIA 50-446 0 50-275 0 XPORTLIC 40-8452	HOLYOAK, R H HOLYOAK, R H HOLYOAK, R H HOLYOAK, R H HOLYOAK, R H.	8208310210 8208310210 8208310219 8208310234 8208310234	50-373 B 50-373 B 50-373 B 50-373 B 50-373 B	HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8208260201 8208270019* 8208270262 8208270267 8208270649*	50-287 P 50-287 R 50-287 F 50-289 F 50-289 R
HEYER:R B HIATT:B L HIATT:B L HIATT:B L HIATT:B L	8208170095 8207050079 8208030372 8208050363 8208050396	1&E 50-440	HOLYGAK, R H HOLYGAK, R H HOGPER, F. F HOOPER, F F HOOPKING, C O	8208310249 8208310289 8208030252 8208050472 8208260002	50-373 8 50-373 8 50-395 0 50-395 0 NUKEO	HUKILL, H D HUKILLS, C HUMPHREY, G J HUMNICUIT, D, M. HUMNICUIT, D M	8208310177 8208020358 8204200050* 8208050139* 8208160470*	50-289 F 50-537 H 50-271 U 50-458 G 50-298 G
HIATT, S.L. HIATT, S.L. HIATT, S.L. HIATT, S.L. HIATT, S.L. HIATT, S.L.	8208120145 8208170197 8208230414 8208270451 8208270463	50-440 G 50-440 G FUIA 50-440 G 50-440 G	HOPKINS, C O HOPKINS, P HOPKINS, P HORIN, W. A HORIN, W. A	8208260017 8208160262* 8208160401* 8208110162 8208110162	NUREG 50-349 Q 50-349 Q 50-445 Q 50-445 Q	RUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M	8208170241* 8208170273* 8208170274* 8208300122 8208300164	50-458 Q 50-298 CQ 50-482 Q 50-313 8 50-368 8
HIATT, 8 L HICKEY, J P HICKOK, N HIGGINBOTHAM, L HIGGINBOTHAM, L	8208270527 8207110028 8208240412* 8208250231* 8208250236*	50-440 Q 50-358 H 50-529 Q 40-86 40-86	HORIN,W, A HORIN,W A HORIN,W, A HORIN,W A HORIN,W A	8208170144 8208170144 8208250333 8208250333 8208270464	50-445 0 50-445 0 50-445 0 50-445 0 50-445 0	HUNNING, R. HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A. HUNT, D. F.	8208030479* 8208020123* 8208090267* 8208310025* 8208260087	50-367 P 50-282 B 50-306 B 50-306 S NUREO
HIGGINBOTHAM, L HIGGINS, J HIGGINS, J C HILL, A A HILL, K L.	8208250242* 8208050425 8208020293* 8208060136 8208050383*	40-86 50-322 B 50-322 G 50-537 Q 50-331 B	HORIN,W A HORNEC HORNER,J W HORNICK,R.J HORNICK,R.J	8208270464 8208300335* 8208310175 8208260002 8208260017	50-445 0 50-419 I I&E Nureo Nureo	HUNT, P, B. HUNTER, D R HUNTER, R. S, HUNTER, R. S, HUNTER, R. S.	8208020358 8208050324* 8208030527 8208060172 8208070054	50-537 H 50-358 Q 50-315 P 50-315 F 50-315 F
HILL, K L HILL, K L HILL, K L HILL, H M	8208070076* 8208130144* 8208130239* 8208170107* 8208200054*	50~331	HORBMAN, A. HOSEY, C. M HOSEY, C. M HOSEY, C. M. HOSEY, C. M. HOSEY, C. M.	8208120177 8208030145* 8208030635* 8208160527 8208310118	50-537 H 70-1113 50-280 G 50-280 B 50-280 B	HUNTER, R. 8 HUNTER, R. B. HUNTER, R. B HUNTER, R. B. HUNTER, R. B.	8208070054 8208230054 8208240052 8208260276 8208300035	50-315 P 50-315 K 50-315 Q 50-315 P 50-315 F
HILNER, M R HIND, J, A HIND, J, A. HIND, J, A. HIND, J, A	8208240404 8208090231 8208090236* 8208270134 8208310242	50-327 D 50-295 G 50-295 G 50-10 G 50-315 F	HOSTETLER, M. HOTTMAN, B B HOU, 8 HOUSTON, D. HOUSTON, R	8208170131* 8208130479 8208240302* 8208040381 8208310225*	50-409 P NUREQ 50-312 Q 50-416 P 50-373 B	Huntt, T. J Hubain, J. Hubain, J. Hubain, J. Hubeby, D. E.	8208310531* 8208170119* 8208170121* 8208170125* 8208050092*	CONTRACT 50-409 P 50-409 P 50-409 P 50-317 B
HINDS, J. M HIPBHER, W. M HIPBHER, W. M HIRECH, D. HIRSCH, D	8208050441* 8208130158 8208170227 8208110178 8208110179	50-237 G 27-39 27-39 50-142 G 50-142 G	HOUSTON, R W. HOUSTON, R W HOWARD, J E HOWE, K S. HOWE, P. W	8208310176* 8208310215* 8208300215* 8208170310* 8206070827	50-373 6 50-373 9 50-293 Q TUPREP 50-324 P	HUSEBY, D. E HUSEBY, D. E HUSEBY, D. E HUSEBY, D. E	B208050375* B208050392* B208050405* B208130276* B208240235*	50-316 8 50-317 8 50-316 8 50-318 8 50-317 8
HIRBCH, D HIRBCH, D HIRBCH, D HITCH, J. W. HOADLEY, B	8208110175 8208110212 8208200301 8208230213* 8208240053*	50-142 0 50-142 0 50-142 0 70-273 XPORTLIC	HOWE, P W. HOWE, P. W HOYLE, A HOYLE, J C	8208020318 8208040330* 8208110151 8208170075 8208020261	50-324 P 50-261 F 50-261 P CONTRACT 50-509 Q	HUTCHINBON, F. D. Hyman, C. R. Egde, V. M Imbrd, E. V. Irby, B. J.	8208020358 8208260087 8208260029 8208030744 8208030178*	50-537 H NUREQ 50-483 A HISG 50-259 8
HOADLEY, B. D. HOBAUGH, J. L. HODGDON, A. P. HODGDON, A. P. HODGDON, A. P.	8208260045 8208300036* 8208020240 8208050055 8208050083	XPORTLIC 50-213 P 50-352 Q 50-352 Q 50-352 Q	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C	8208020307 8208020312 8208030248 8208030275 8208030275	50-322	irby, B. J. Irby, B. J. Irby, B. J. Irby, D. P. Irbin, D. P.	8208050222* 8208050231* 8208270548* 8208030301 8208030301	50-240 B 50-259 B 50-259 B 50-322 0 50-322 Q
HOELLER, J. P HOFFMAN, C. C HOFFMAN, Q. L. HOFKIN, T. HOFKIN, T	8208100056* 8208310465* 8208040614* 8208170163* 8208240344*	40-8745 50-213 P	HOYLE, J. C. Hoyle, J. C. Hoyle, J. C. Hoyle, J. C Hoyle, J. C	8208030302 8208070142 8208070157 8208070164 8208070165	50-293	irwin, d. p Irwin, d. p. Irwin, r. r Ibhida, h. f. Ibley, t.	8208110150 8208110150 8208270297# 8208260250# 8208300100#	50-322 Q 50-322 Q 50-338 R CONTRACT 50-346 8
HOFKIN, T HOHORST, J K HOLCOMB, E, HOLDEN, C, HOLLIS, J L	8208250548* 8208020061 8208040005 8208100371* 8208300260	REB REB	HOYLE, J. C. HOYLE, J. C. HOYLE, J. C. HOYLE, J. C.	8208070180 8208160047 8208260435 8208270680 8208300351	50-454	IVEY, L. JABBOUR, K. N. JACKIW, I. N. JACKIW, I. N JACKEON, C. W	8208230124* 8208260472 8208100244* 8208100265* 8208260132	XPORTLIC 50-413 A 50-373 G 50-247 G 50-247 B
HOLMES, M. H. HOLT, J HOLYOAK, R. H HOLYOAK, R. H. HOLYOAK, R. H.	8208240221 8208030534 8208020117 8208020176 8208020332	50-267 P REVIEW GRP 50-373 8 50-373 8 50-373 8	HOZORE, E HEU, Y. Y. HUBACEK, H Q. HUDSON, Q HUDSON, T. B.	8208070018* 8208130477 8208200054* 8208260319* 8208170153	50-537 D NUREO 50-498 G 50-263 F 50-498 O	JACKBON, E. W. JACKBON, G JACKBON, J JACKBON, P O JACOBB, A.	8208170174 8204170002 8208170174* 8208260364* 8208060351	50-271 R 71-9161 50-272 P WASTE MGT CONTRACT
HOLYDAK, R. H HOLYDAK, R. H. HOLYDAK, R. H. HOLYDAK, R. H HOLYDAK, R. H	8208020346* 8208020351 8208030100* 8208030103* 8208030437	50-373 8 50-373 F	HUDBON, T B HUETER, L. J. HUFFHAN, G N. HUFFMAN, G N. HUFFMAN, G N.	8208170133 8208300176* 8208030507* 8208030574* 8208160406*	50-498 0 50-315 0 50-338 0 50-280 0 50-327 0	JACOBB, H. R. JACOBB, R. H. JACOX, J. H. JAFFE, D. H. JAFFE, D. H.	6208060150* 8208110200* 8208300274 8208030745 8208030750	50-407 0 50-289 0 PR 50-317 P NISC
HOLYDAK, R. H. HOLYDAK, R. H HOLYDAK, R. H HOLYDAK, R. H HOLYDAK, R. H.	8208040248 8208100233 8208100330 8208120288 8208200235	50-373	HUFFMAN, O N HUFMAN, R L. HUFMAQEL. R. HUQHES, D R. HUQHES, E. M.	8208160513* 8208020358 8208260434 8208030565 8208100097	50-302 0 50-537 H Nureq Prim 50-327 B	JAFFE, D. H JAFFE, D. H JAFFE, D. H. JANB, D. JANUSKA, A G	8208110001 8208130095 8208230101 8208190303* 8208090841*	50-317 P 50-317 P 50-317 F GA999 50-295 Q
HOLYOAK, R. H HOLYOAK, R. H. HOLYOAK, R. H HOLYOAK, R. H HOLYOAK, R. H.	8208200287 8208230040 8208240184 8208240200 8208300059	50-373 8 50-373 8 50-373 8 50-373 8 50-373 8	HUKILL, H. D.	8208050123 8208130013 8208160292 8208170209 8208170074	50-287 P 50-287 Q 50-289 F 50-287 P 50-289 R	JANUBKA, A. O. Jape, F. Jape, F. Jape, F. Jape, F.	8208270142* 8208030459* 8208140151* 8208140244* 8208140243*	50-10 Q 50-389 0 50-338 Q 50-370 Q 50-321 Q
HOLYDAK, R. H. HOLYDAK, R. H. HOLYDAK, R. H. HOLYDAK, R. H. HOLYDAK, R. H.	8208300041 8208300101 8208300138 8208300189 8208300310	50-373 8 50-373 8 50-373 8 50-373 8 50-373 8	HUKILL, H. D.	8208170124 8208170184 8208170200 8208170204* 8208170237*		JAUDON; J. P.	8208030224 8208050361 8208100081 8208160080 8208160157	50-348 8 50-313 8 50-313 8 50-313 8 50-313 8

AUTHOR	ACCESSION NUMBER	CATE	ORY	AUTHOR	ACCESSION NUMBER	SUDJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	
JAUDON, J P JAUDON, J P JAUDON, J P JAUDON, J P JENKINS, G R	8208170223 8208240360 8208270320 8208270478 8208030221	50-313 * 50-285 * 50-296	0 3 S 5 Q	JONES, W C JONES, W C JONES, W C JONES, W C JONES, W C	8208120168* 8208130038 8208130248 8208180089 8208190089	50-285 50-285 50-285 50-285 50-285	F P Q R	KANGA, B K KANGA, B K KANGA, B K KANGA, B K KANGA, B K	8208130184 8208160494 8208180033 8208180054 8208200033	50-320 50-320 50-320 50-320 50-320	0 0 8 8
JENKINS, OR JENKINS, OR JENKINS, OR JENKINS, OR	8208030323 8208030398 8208030509 8208030574 8208160406	* 50-338 * 50-338 * 50-280 * 50-327	Q Q Q	JONES, W C JONES, W C JONES, W C, JONES, W C JONES, W C	8208170172# 8208170247# 8208170264* 8208170276# 8208200135	50-285 50-285 50-285 50-285 50-285	F G G G	KANGA, B K KANGA, B K KANGA, B K KANTOR, F KAUCHER, J	8208250320 8208270290 8208270300 8208030509* 8208050028*	50-320 50-320 50-320 50-336 50-313	P B G P
JENKINB, C. R JENKINB, M JENSEN, H. L JENSON, B. E JEWET, J. R	8208160513 8208040041 8208110203 8208120087 8208270252	50-537 50-289 TOPREP		JONES, W C JONES, W C JONES, W C JONES, W C	8208240165 8208240177 8208240178 8208240278* 8208270362*	50-285 50-285 50-285 50-285 50-285	Р К Р О F	KAUCHER, J E KAY, H B, KAY, J A KAY, J A KAY, J A	0206220204# 0200300034# 020020105 020050533 0200060104	50-29 50-361 50-29 50-29 50-29	6 8 6
JOHASON, J M JOHASON, A H JOHASON, A H JOHASON, B H	82082302084 82082302144 8208040007 82081602444 8208030529	40-501 REB		JONES, W C JONES, W C JORDAN, E L JORDAN, E L JORDAN, E L	8208310159 8208310282* 8204210393 8204210395 8204210394	50-285 50-285 50-3 50-2 50-3	P G G G	KAY, J A KAZA, R N KEATEN, R W, KEATEN, R. W KEATING, R	8208170229 8208120255* 8208270495* 8208270495* 8208110235*	50-29 50-416 50-289 50-289 50-537	P E Q D
JOHNSON, B D JOHNSON, B D JOHNSON, B D JOHNSON, B D	8208050257 8208130028 8208130114 8208180012 8208270234	50-255 50-255 50-255 50-255 50-255	0 8 P P	JORDAN, E. L. JORDAN, E. L. JORDAN, E. L. JORDAN, E. L. JORDAN, E. L.	8204210398 8204210401 8204210402 6204210403 8204210403	50~3 50~3 50~3 50~3 50~3	Q Q Q Q	KEIMIO, R KEIMIO, R R KEIMIO, R R KEIMIO, R R KEIMIO, R R	8208190254 8208100248* 8208100263* 8208230041* 8208230184*	50-219 70-371 70-820 50-20 70-687	s 0
JOHNSON, C. R. JOHNSON, C. R. JOHNSON, D. D.	8208310411* 8208050139* 8208030082 8208240128 8208120317			JORDAN, E. L. JORDAN, H. J., JORGENSEN, B. L. JOYNER, J. H. JOYNER, J. H.	8204210407 8208050403* 8208100283* 8208120241 8208250222*	50-3 50-10 50-255 40-8794 40-86	G G G	KEIMIG,R R KEISER,H W KEISER,H W. KEISER,H W KEISER,H W.	8208300250* 8208020277 8208050210 8208170111 8208300054	50-223 50-387 50-387 71-6574 50-387	0 8 8
JOHNBON, E. H. JOHNBON, E. H. JOHNBON, E. L. JOHNBON, E. L.	8208260097 8208240179* 8208240184* 8208040004 8208040043	NUREO 50-298 50-298 RES RES	g g	JOYNER, J H JULIAN, C JULIAN, C A JULIAN, C. A JUNEAU, R C.	8208250224* 8208030212* 8208030441* 8208310371 8207110014	40-84 50-338 50-335 50-339 FOIA	0 G B	KELLEY, F KELLEY, J L. KELLEY, J L KELLEY, J L KELLEY, W D	8208040456* 8208040063 8208050461 8208110067 8208310138*	50-537 71-480 50-413 50-361 GA999	D G G
JOHNSON, O. E. JOHNSON, O. E. JOHNSON, O. E. JOHNSON, O. E.	8208120314* 8204070563 8204070570 8208020230 8208170278	50-416 50-413 50-413 50-413 50-413	E 0 0	JUNGE, M. A JUNGE, M. A JUNGE, M. A JUNGE, M. A JUNGE, M. A	8208050375* 8208050386* 8208050405* 8208090115* 8208090256*	50-318 50-317 50-318 50-317 50-318	8 8 8 8	KELLEY, W D KELLY, J, P KELLY, J, W KELLY, J, W	8208310454# 8208100028# 8208020368 8208040375 8208040622		G H
JOHNSON, J. JOHNSON, L. JOHNSON, L. JOHNSON, L. JOHNSON, L	8208300188* 8208250066* 8208250072* 8208250077* 8208250080*	50-293 40-86 40-86 40-86 40-86	Q	JUNGE, M A JUNGE, M A JUNGE, M A JUNGE, M A JUNGE, L H	8208100068* 8208130025* 8208230178* 8208250393* 8208030735*	50-317 50-317 50-317 50-317 CONTRACT	8 8 8	KELLY,R B KELLY,R F KEMPER,J 8, KEMPER,J 8 KEMPER,J 8	8208050176* 8208230208* 8208030168 8208120073* 8208130319	50-352	A G B
JOHNSON, L, JOHNSON, L JOHNSON, L JOHNSON, L,	8208250082* 8208250085* 8208250098* 8208250099* 8208250103*	40-86 FOIA FOIA FOIA FOIA		KAEPPEL, F KALIVIANAKIS KALIVIANAKIS, N KALIVIANAKIS, N	8208100174# 8208130210 8208130222 8208050230 8208050290	50-254 50-254 50-255 50-254 50-265	8 8 8	KEMPER, J 8 KENNEDY, C, F KENNEDY, J E KENNEDY, R T KENNEDY, W E	8208200077 8208040285 8208050025* 8208020274 8208180126	50-537 50-322	A H A Q
JOHNSON, L JOHNSON, L JOHNSON, H D. JOHNSON, H D.	8208250146* 8208250158* 8208100092 8208160080 8208160157	40-86 40-86 50-263 50-313 50-313	J 8 9	KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8208090246 8208100049 8208100168 8208100210 8208130240	50-265 50-254 50-254 50-254 50-254	6 6 8 8	KENNEY, N KENNY, T. J KENRICK, J, R KENYON, B D KENYON, D D	8208120278 8208160010* 8208270422 8208050473 8208060143	50-286 50-437 50-387	H 0 0 8
JOHNSON, W. D. JOHNSON, W. D. JOHNSON, W. P. JOHNSTON, O.	8208180066# 8208300122 8208300164 8208020283# 8208160279#	50-313 50-313 50-368 50-443 50-528	G 8 0 0	KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8208160116 8208160374 8208160427 8208200252 8208230335*	50-254 50-254 50-254 50-254 50-254	R R S S F	KENYON, B D, KENYON, B D KEPFORD, C. KEPPLER, J Q KEPPLER, J Q	8208130045 8208310078 8208040447* 8208030272 8208030371	50-387 50-537 50-546	S P D A
JOHNBTON, L. E. JONES, B. W. JONES, B. W. JONES, B. W.	8208250087* 8208020052 8208030075 8208100085 8208100078*	FOIA 50-537 50-537 50-537 50-537	G G G	KALIVIANAKIS, N KALMAN, Q KALMAN, K KAMER, D. S KAMER, D. B	8208270263# 8208130267 8208260511 8208090071 8208160491#	50-254 50-320 40-8064 50-370 50-257	R 8 F Q	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8208050414 8208050441* 8208090107 8208090220 8208140119	50-237 50-483 50-329	G G A A
JONES, B. W. JONES, D. W JONES, D. W JONES, D. H	8208240271 8208060386* 8208030515* 8208030685* 8208270497	50-537 CGNTRACT 70-1201 70-143 50-538	6	KAMMANN,R.W, KAMMER,D.B KAMMER,D.B KAMMER,D.B. KAMMER,D.B.	8208020358 8208030202 8208030339 8208030592* 8208030600*	50-537 50-390 50-327 50-259 50-438	H G R G	KEPPLER, J. O KEPPLER, J. Q. KEPPLER, J. Q KEPPLER, J. G KEPPLER, J. O	8208160121* 8208160393 8208160411 8208160419* 8208190058*	50-327 50-461 50-461	G A G G
JONES, O. T JONES, J. A. JONES, J. L. JONES, J. M.	8208120226 8208120233* 8208310260 8208310079* 8208310520*	50-259 50-259 50-324 50-267 CONTRACT	R R P S	KAMMER, D S KAMMER, D S KAMMER, D S KAMMER, D S KAMMER, D S.	8208070244 8208100078 8208160144 8208160233 8208170174	50-327 50-327 50-390 50-327 50-438	P P G G A	NEPPLER, J G C C C C C C C C C C C C C C C C C C	9208200114 9208200218 9208240255 9208240304 9208240307*	50-373 F	G
JONES, K. R JONES, K. R JONES, B. Z. JONES, V. H	8206200027* 8207070414 8208180027 8208170241* 8208120204*	50-395 40-8102	P J R	Kammer, D. B Kammer, D. B. Kane, W. F Kane, W. F Kane, W. F	6208230351 6206040377 8208260318	50-327 50-259 50-395 50-349 50-395	F A P P	KEPPLER: J. O KEPPLER: J. O KEPPLER: J O KERR: O. W. KERR: O. W.	8208270462 8208310091 8208310293 8208030576* 8208110047	50-331 F 50-255 F 50-456 A REVIEW ORF 50-522 A	4
JONEB, W. B. JONEB, W. C. JONEB, W. C. JONEB, W. C. JONEB, W. C	8208260491 8208030549 8208060034* 8208060216* 8208100003	50-295	K F Q 8	KANGA, B. K. KANGA, B. K. KANGA, B. K. KANGA, B. K. KANGA, B. K	6208100298 6208100302 8208110116	50-320 50-320 50-320	P F P P	KERR, Q, W, KETZLACH, N KETZLACH, N, KETZLACH, N KIANG, R, L	8208130478 8208020432* 8208080177* 8208130008 8208160443*	NUREQ 70-2934 70-2884 70-734 50-312 P	J

ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY
8208240097 8208200193* 8208090018* 8208160034 8208050094*	XPORTLIC 50-409 50-537 50-443 TOPREP	G D D	KOESTER, @ L KOESTER, @ L KOESTER, @ L KOESTER, @ L KOESTER, @ L	8208240069 8208240176 8208270380 8208310304 8208310374*	50-482 50-482 50-482 50-482 50-482	8 8 A A	LARSON, C E LARSON, C E LARSON, D B LASHER, L E LABBAHN, O D	8208260315* 8208260317* 8208120278 8207120253* 8208260486	50-263 F 50-263 F 50-537 H 50-447 A NUREG
8208020071 8207140050 8208050286 8208050070 8208050070	50-443 50-322 50-537 TOPREP TOPREP	A A H	KOESTER, W C KOHLER, J KOHUT, P KOLB, C J KOLTAY, P	8208200197 8208050441* 8208110098 8208240479 8208200046*	50-482 50-237 50-304 50-313 50-247	B Q P P Q	LATIN, H L LATIN, H L LAUERNBON, J A LAURENBON, J A, LAWBON, B	8208170207* 8208170213* 8208270382 8208110070 8208040372	GA999 GA999 50-322 G 50-255 G 40-8745
8208050094 * 8208170225 8208170307 8208190307 8208130227	TOPREP 50-348 TOPREP TOPREP 40-86	P	KOMARA, B.P. KOMES, J.M. KOMOSKY, G.E. KONKLIN, J.E. KONKLIN, J.E.	8208310511* 8208240217* 8208180015* 8208230036* 8208230100*	50-302 0A999 50-336 50-341 50-305	8 G G	LAUSON, B A LAUSON, L T. LAUTON, M D LAYFIELD, L LAZARUS, W	8208040407 8208310190 8208040284 8208230104* 8208030292*	40-8745 TOPREP ' 40-8084 40-86 50-334 G
8208180003 8208230208* 8208230214* 8208250266* 8208250319*	40-86 70-273 40-501 40-86 FOIA		KOOQLE, H Q KORNHAUBER, M C KOSKE, J E KOSLA, B M KOTTAN, J J	8208050286 8208300264 8208040036 8208190040* 8208300248*	50-537 PR RES 40-8724 50-273	e e	LAZO, R. M. LAZO, R. M. LAZO, R. M LAZO, R. M LAZO, R. M.	8208120131 8208120133* 8208130179 8208140062 8208240220	50-528 Q 50-528 Q 50-466 Q 50-528 Q 50-528 Q
6206250323* 8208250344* 8208250348* 8208250392* 8208310421	FOIA 40-86 40-86 40-86 40-672		KOWALSKI, D J KOWACS, B KOWACS, T J KOWACS, T J	8105210393+ 8208040475+ 8208110234+ 8208030543 8208260273+	50-254 50-254 50-254 PR TOPREP	P F F	LEAR, O, LEASBURG, R. H. LEASBURG, R. H LEASBURG, R. H LEASBURG, R. H	B208030122* B208020084 B208030310 B208030444 B208030478*	40-8584 50-338 P 50-338 P 50-280 P 50-338 G
8208230041 * 8208300250 * 8208050182 8208130480 8208020083 *	50-20 50-223 50-341 NUREQ 50-327	Q A B	KRAJICEK, J. E KRAJICEK, J. E KRAMER, C. E KRAUSE, R. W. KRIEGER, R. W.	8208120087* 8208170206* 8208040148* 8208240380* 8208240380*	TOPREP 50-244 50-329 50-298 50-204	P A 8 P	LEASBURG: R. H. LEASBURG: R. H. LEASBURG: R. H. LEASBURG: R. H. LEASBURG: R. H	8208030534* 8208030422* 8208040220 8208070101 8208100071	50-280 G 50-280 G 50-339 P 50-280 P 50-280 8
8208030154* 8208050105* 8208050161* 8208050161* 8208070175* 8208120124*	50-327 50-328 50-328 50-327 50-327	8 6 6 8	KRIEGER, R W. KRIEGER, R. W KRIEGER, R W KRIMM, R W KRIMM, R W.	8208100077 8208100223 8208170184 8208020376 8208110107	50-206 50-206 50-206 50-206 50-335	Р Р Р Г	LEASBURG, R. H LEASBURG, R. H LEASBURG, R. H LEASBURG, R. H LEASBURG, R. H	8208100110 8208120148 8208120203 8208120283 8208160402	50-280 P 50-338 R 50-280 R 50-280 P 50-280 Q
8208120262# 8208250200# 8208250086# 8208250136# 8208250254#	50-928 40-84 40-84 40-86 FOIA	В	KRIHM, R. W. KRIHM, R. W KRIHM, R. W KRONZEK, A. L. KVAN, P	8208110116 8208170081 8208170180 8207050077 8208040043	50-416 50-263 50-206 71-6698 RE8	F F #	LEASBURG, R. H LEASBURG, R. H LEASBURG, R. H, LEASBURG, R. H LEASBURG, R. H	8208170166 8208170173 8208170097 8208170120 8208170175	50-338 q 50-339 P 50-280 F 50-338 P 50-280 P
8208250273* 8208250288* 8208250325* 8208250337* 8208250342*	40-86 40-86 40-86 40-86 FOIA		KULLBERG, C. M KUMAR, K. D KUTZER, J F KUTZER, J F KUTZER, J F	8208040007 8208250440 8208020144* 8208030303* 8208120178*	RES NUREO 50-269 50-287 50-269	6 B 8	LEASBURO, R. H LEASBURO, R. H LEASBURO, R. H LEASBURO, R. H LEASBURO, R. H.	8208190294 8208230280 8208240315 8208250150 8208250344	50-339 P 50-280 P 50-280 F 50-338 P 50-280 P
8208250366* 8208180023 8208160010* 8208180064 8208300046*	40-86 50-361 50-286 50-220 50-247	8 0 8	KUTZER, J F. LABARTA, P LACEY, W B LACEY, W B. LACEY, W, B	8208120275* 8208170070* 8207090216* 8208050129* 8208050451*	50-270 50-482 50-334 50-334 50-334	8 8 8	LEASBURG, R.H. LEASBURG, R.H. LEASBURG, R.H. LEASBURG, R.H. LEASBURG, R.H.	8208270074 8208270293* 8208270303* 8208270364 8208300195	50-280 P 50-338 R 50-280 R 50-338 P 50-280 Q
8208230319* 8208300052* 8208030557* 8208030326* 8208160171*	50-410 50-244 50-269 50-413 50-369	0 0 0 0	LACEY, W. B. LACEY, W. B LACEY, W. B. LACEY, W. B. LACEY, W. B.	8208100029* 8208130070* 8208130073* 8208130245* 8208130259*	50-334 50-334 50-334 50-334 50-334	8 8 8 8	LEBO,C D. LECLAIR,D E LEDDICK,R.B LEDDICK,R.B. LEDDICK,R B	8208020066* 8208060365* 8208160300 8208240163 8208300321	CONTRACT CONTRACT 50-508 Q 50-508 Q 50-508 B
8208140394* 8208240355* 8208240428* 8208250200* 8208250251*	50-369 CONTRACT CONTRACT 40-86 40-86		LACEY,W B. LACEY,W B LAGIEWSKI,J S LAGIEWSKI,J,S LAGIEWSKI,J S	8208260203* 8208300242* 8208050092* 8208130276* 8208240494*	50-334 50-334 50-317 50-318 50-317	8 8 8 8	Leddick, R B. Leddick, R B. Lee, B Lee, B Lee, J. Y.	8208310224 8208310229* 8208130163 8208130262* 8208170320	50-508 8 50-508 8 50-295 0 50-295 0 50-389 A
8208230065# 8208300168 8208040014 8208240300# 8208100125	50-379 PRM MISC 50-312 50-315	S C B	Lagieubki, J, 8 Lai, E, W. Lainab, O. C. Lainab, O. C Lainab, O. C	8208240235* 8208190308* 8208040349 8208240030 8208240320*	50-317 50-413 50-289 50-312 50-312	B A P P	LEE, O A. LEE, R. W. LEE, B Y. LEE, T L. LEE, W B.	8208300220 8208030200* 8208260433 8208030131* 8208300335*	50-267 Q QA979 NUREQ 70-143 50-413 I
8208100163 8208100211 8208050441* 8208100126 8208100271	50-315 50-373 50-237 50-329 50-255	8 9 8 8	LAINAB, OC LAINAB, OC, LAINAB, OC LANDAU, M LANDAU, M. B.	8208270687 8208300002 8208300354 8208110047 8208130478	50-346 50-289 50-133 50-522 NUREO	P G H A	LEHMAN.L LEHMAN.L. LEHMAN.L,L LEHNERT.R.A LEIKEN.L S.	8208170374* 8208170378* 8208170371* 8208200168* 8208300322	HABTE MOT WABTE MOT WABTE MOT 50~341 A 70~143
8208100276* 8208100260 8208160419* 8208160453 8208020211	50-255 50-327 50-461 50-327 50-375	9 9 9 9	LANDERB, D F LANDIB, K. LANDRIEU, P. R H LANDBMAN, R B LANDBMAN, R B	8208250305 8208310371 8208090089 8208030176* 8208240425*	50-387 50-337 50-354 50-373 50-329	P 8 R G	Lempino, J F Lempoes, T E. Lempoes, T. E. Lempoes, T. E. Lempoes, T. E.	8208310255 8208020200 8208050434 8208050470 820805047	REGGD 50-220 F 50-220 Q 50-220 P 50-220 P
8208020211 8208240358 8208240358 8208040180 8208050174#	50-395 50-395 50-395 50-482 50-482	o e e K e	Lange, R. W. Langham, T Langham, T. Langham, T. Lankebury, R	8208040328* 8208020128* 8208020133* 8208020139* 8208100244*	50-305 GA999 GA999 GA999 50-373	F G	Lempoes, T. E. Lempoes, T. E. Lempoes, T. E. Lempoes, T. E. Lempoes, T. E.	8208130193 8208200104 8208230299 8208240051 8208270399	50-220 P 50-220 B 50-220 B 50-220 P 50-220 P
8208100034 8208100339 8208160265 8208170067 8208170094	50-482 50-482 50-482 50-482 50-482	8 E 8 8	LANPHER, L. C, LANPHER, L. G LANTR IP, W. E. LARSON, G. E. LARSON, C. E	8208050271 8208050271 8208270465 8208060127* 8208100080	50-322 50-322 50-537 50-263 50-262	000	Lempgeb, T e Lempgeb, T. e. Lenahan, J J. Lenahan, J, J Lentine, F Q.	8208270476 8208270579* 8208030539* 8208160178* 8208030186	50-220 F 50-220 R 50-302 Q 50-335 Q 50-295 P

AUTHOR	ACCEBBION NUMBER	CATEG		AUTHOR	ACCESSION NUMBER	BUBJECT CATEOOR		AUTHOR	ACCEBSION NUMBER	BUBJECT CATEODRY
TIME.F O TIME.F O TIME.F O TIME.F, O TIME.F O	8208030237 8208030603 8208070103 8208130018 8208130166	50~295 50~295 50~295 50~295 50~295	P P P	Lieberman, J Lieberman, J. Lieberman, J. Lieberman, J Lieberman, J	6208120311 6208160113 6208160255 6208170161 6208250179*	MIBC 50-206 50-344 50-331 40-86	Q 8 Q	LONG, F, J LONG, F J LONG, F J LONG, S LONGENECKER, J	8208160216* 8208160482* 8208160478* 8208300286* 8206300099	50-438 Q 50-327 Q 50-259 Q REVIEW GRP 50-537 A
TINE, F. G TINE, F G TINE, F G NARD, J R BOR, L C	8208180070 8208240305 8208250137 8208200168 8208120040	50-295 50-295 50-295 50-341 50-298	F P A R	Lieberman, J Lieberman, J Liebler, O H Liebb, P. J Lilien, L H	8208260424 8208300225 8208270570* 8208040434 6208170374	50-280 I&E 50-3 50-537 71-9158	Q F H	LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8208020077 8208030313 8208030540 8208050307 8208060164	50-537 B 50-537 F 50-537 A 50-537 C 50-537 A
SOR, L C SOR, L C, SOR, L C SOR, L C SOR, L C	8208160173 8208200103 8208200166 8208240367 8208270182*	50-298 50-298 50-298 50-298 50-298	8 8 8 8 R	LILLYMAN,W J LIN,H LIN,M B LINDER,F LINDER,F	6208100291 6208230417 6208300271* 6208050471 6208060249	50-326 NUREG 50-206 50-409 50-409	H P S P	LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8208110103 8208130287 8208230264 8208230267* 8208310208	50-537 B 50-537 A 50-537 B 50-537 B 50-537 B
SY,RP. SY,RP. SY,R,P. SCHE,K BCHE,KJ	8208120010 8208170335 8208250276 8208200163* 8208170124	50-443 27-39 50-443 50-322 50-322	0 0 0	LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8208040307* 8208070247 8208100111 8208100180 8208120218	50-409 50-409 50-409 50-409 50-409	F 8 P P	LONGENECKER, J LOSS, P. J LOSS, P. J LOSS, P. J LOSS, P. J	8208310312 8208190315* 8208190316* 8208190321* 8208190352*	50-537 A 50-413 A 50-413 A 50-413 A
BCHE, K. J BCHE, K. J BCHE, K. J AN, H. C. AN, H. C.	9208190124 9208190132 9208190132 9208250387* 8208250409*	50-322 50-322 50-322 50-259 50-259	9 9 P P	LINDER, F. LINDER, F LINDER, F LINDER, F LINDER, F	8208120291 8208120305 8208200066 8208200206 8208270289	50-409 50-409 50-409 50-409 50-409	R R S S P	LOTITO, E LOTITO, E M LOVE, R 8 LOVENDALE, P. C LOVENDALE, P. C	8208230373* 8208230371 8208070077* 8208050478* 82080310232*	50-317 R 50-317 R 50-456 Q 50-155 Q 50-255 Q
ANIH C ANIH C ANIH C ANIH C ENTHAL,P	8208250421* 8208250431* 8208250441* 8208250446* 8208040048*	50-259 50-259 50-259 50-259 50-537	P P P D	Linder, F. Linder, F. Linder, F. Linder, F Linehan, J.	8208270572* 8208310303 8208310374 8208310373 8208240511	50~409 50~409 50~409 50~409 40~6064	R P P	LOZITO, E. J LU. H. B. LUCK, H. D LUCK, H. D LUCK, H. D	8208190298* 8207150485 8208060181 8208130167 8208200283	50-939 P RE8 50-537 Q 50-537 Q 50-537 Q
ine, a. H Ine, a. H Ine, a. J In, c	8206200044* 8208040630 8207150485 8208170112 8208250385*	50-329 40-2061 RES 50-5 FOIA	H P	Linehan, J J Linehan, J J Linehan, J J Linehan, L J Linenberoer, G.	8208040362* 8208040542 8208110080 8207110024 8208030252	40-8785 40-8783 40-8786 FOIA 50-395	•	LUDHIO, F. L. LUEBKE, E. A. LUETT, W. R. LUMB, R. F. LUNDVALL, A. E.	9209260406 8209180121 8209300315* 8209310466* 8208060170	NUREQ 50-142 Q 50-373 S CONTRACT 50-317 P
18,4 18,4 18,4 18,4 18,4 1,	8208270612* 8208270614* 8208030522 8208100183 8208160467	50-249 50-369 PRM PRM 50-289	R R	LINENBERGER: O LINENBERGER: O LINENBERGER: G LIPINSKI: D LITTLE: B H	8208030321 8208030328 8208050472 8208300188* 8208230036*	50-537 50-537 50-395 50-293 50-341	0 0 0 0	LUNDVALL; A, E LUNDVALL; A E LUNDVALL; A E LUNDVALL; A, E LUNDVALL; A, E,	8208090049 8208100141 8208100272 8208110124 8208120301	50-317 @ 50-317 P 50-317 P 50-317 P 50-317 P
IB.M I IB.R C IB.R C IB.R C IB.R C	8208170142 8208030353 8208030361* 8208030366 8208030375	PR 50-348 50-348 50-438 50-321	G G G	LITTLE, L W LITTLE, M LITTLE, M LITTLE, M LITTLE, M	8208190125 8208030733 8208060023 8208170413 8208170021	50-297 CONTRACT CONTRACT CONTRACT CONTRACT	•	LUNDVALL, A, E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUTKEHAUS, T C	8208180038 8208180051* 8208230305 8208230323* 8208160468	50-317 P 50-317 Q 50-317 P 50-317 Q 50-302 Q
18, R C 18, R C 18, R C 18, R C 18, R C	8208030381* 8208030382* 8208030400 8208030423* 8208030469	50-438 50-321 50-416 50-416 50-338	a a a a	Little, M. Little, M. Little, M. Little, M Little, M.	8208230021 8208230460 8208250063 8208250076 8208250184	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		LYON, R E MACDONALD, C MACDONALD, C E, MACDONALD, C E MACDONALD, C E	8208050052 8208130421* 8208040073 8208040087 8208040110	RE8 71-5149 71-9132 71-5926 71-9098
IB.R C IB.R C IB.R C IB.R C. IB.R C.	8208030521 8208030531 8208030582 8208030595 8208030597*	50-280 50-302 50-259 50-269 50-259	G G G G	LITTLE, M. CITTLE, M LITTLE, M LITTLE, M LITTLE, W 8	8208260462 8208310450 8208310495 8208310524 8208160138	CONTRACT CONTRACT CONTRACT CONTRACT 50-379	a	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E.	8208040374 8208040379* 8208040403 8208040405* 8208040430	71-5796 71-5796 71-9139 71-9139 71-5939
19. R. C 19. R. C 18. R. C 18. R. C 18. R. C.	8208030579 8208070135 8208070178 8208100228 8208160134*	50-269 50-348 50-348 50-261 50-324	G G G G	LITTLE, W 8 LITTLE, W 8 LITTLE, W 8. LITTLE, W 8 LITTLE, W 8	8208030173 8208100240 8208130320 8208130321 8208170113	50-373 50-373 50-373 50-329 50-483	a a a a	MACDONALD, C. E. MACDONALD, C E MACDONALD, C E MACDONALD, C, E MACDONALD, G E	8209040435 8208060367 8208060370* 8208070035 8208070036	71-6115 70-1810 70-1810 71-9158 71-9074
IB.R.C IB.R.C. IB.R.C IB.R.C. IB.R.C	8208140213 8208140324* 8208140334 8208140334* 8208140382*	50-438 50-302 50-389 50-389 50-250	@ @ @ @ @	LITTLE, H 8 LITTLE, H 8. LITTLE, H 8. LITTLE, H. 8 LITTON, F 8.	8208170298 8208240413 8208240416* 8208270309 8208030033	50-546 50-329 50-329 50-346 Toprep	G G G	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C, E, MACDONALD, C, E,	8208070331 8208130333 8208130342 8208130345 8208130348	71-5097 71-6401 71-6088 71-9145 71-9135
(8, R. C, (6, R. C (8, R. C, (5, R. C (5, R. C	8208160496 8208160493 8208160511 8208160515* 8208160532*	50-327 50-259 50-424 50-259 50-424	G G G G	LITTON, F B. LITTON, F B. LIV, L LIVERMORE, H LOCABCIO, A T.	8208240507 8208310528 8208310279 8208100164 8208110177	OEN TEG : 0EN TEG : 50-331 50-461 PT21		MACDONALD, C. E.	6208130373 6208130414 6208130419 6208170014 6208170033	71-5805 71-9032 71-5149 71-9086 71-9151
.8, R. C .8, S. H .6, 8. H .8, 9. H. .9, C Y	8208310123 8208040021 8208090005 8208260051 8208310074*	50-520 50-352 50-440 50-440 50-362	8 0 0	LOCKE, D. L. LOCKHODD, J. LODDE, B. LOEBL, K.	8208250101* 8208100237* 8208030544 8208260361 8208020358	CONTRACT 50-373 REGOD FOIA 50-537	в	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E	B208170395 B208240080 B208240090 B208240092 B208240092	71-5874 71-6574 71-6601 71-9032 71-6601
TRA, E. A EN, E. A EN, E. A EN, E. A EN, E. A	9208040234 9208020112 9208100162 9208160068 9208190187	50-400 50-272 50-272 50-272 50-272	A G G G P	LOFTY: R A. LOGUE: R. H. LOGUE: R H. LOHAUS: P. H LOHBARDO: J. J	8208170326* 8208070189 8208070189 8208170016 8208260174	CONTRACT TOPREP TOPREP PR 50-219	P	MACDONALD; C, E, MACDONALD; C, E. MACDONALD; C, E MACDONALD; J, MACHON; R. D.	8209240098 8208240100 8208250179 8208020358 8208050264	71-9151 71-6717 71-9032 50-537 H 50-293 B
IN, E. A. IN, E. A. JERMAN, J. JERMAN, J. JERMAN, J	8208250178 8208250178 8208040040 8208100033 8208110105	50-272 50-272 50-255 50-298 70-143	P P G	LONG, F. LONG, F. J. LONG, F. J. LONG, F. J. LONG, F. J.	8208030180 8208030214 8208030231* 8208030416 8208030405*	50-324 50-438 50-438 50-390 50-438	0 0 0 0	Machon, R. D. Machon, R. D. Machon, R. D. Mackie, R. R. Mackie, R. R.	8208120141 8208270620* 8208300289 8208260002 8208260017	50-293 R 50-293 R 50-293 8 NUREQ NUREQ

ACCESSION NUMBER	SUBJECT	ROHTUA	ACCESSION NUMBER	CATEOUR	Y	AUTHOR	ACCESSION NUMBER	SUBJECT
8208040132 8208040132 8208230417 8208040054 8208050400*	50-170 Q 50-170 Q NUREQ RES 50-219 Q	MARDIS.D G MARDIS.D G MARDIS.D G MARDIS.D G MARDIS.D G	82081 60360 82081 60468 82081 80046 8208200093 8208200095	50-302 50-302 50-302 50-302 50-302	G P P 8	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T, T MARTIN, T, T	8208050274 8208050308 8208050370 8208050440 8208050531	50-387 Q 70-135 50-219 Q 50-271 Q 50-293 Q
8208230176* 8208050135 8208060145 8208100022 8208100066	50-243 G 50-458 G 50-247 F 50-445 G 50-382 G	Mardis, D Q Mardis, D Q. Mardis, D Q Marqulies, M B Marqulies, M B	8209200156 8208200219 8208270355 8208030371 8208040223	50-302 50-302 50-302 50-454 50-454	8 8 9 9	MARTIN, T T. MARTIN, T T MARTIN, T T. MARTIN, T T MARTIN, T T	82090&0153 82080&0240 8208100026 8208100094 8208100207	50-311 Q 40-672 50-352 Q 50-387 Q 50-219 Q
8208130209 8208160312 8208160390 8208160444 8208160465	50-274 G 50-498 G 50-267 F 50-267 G 50-298 G	MAROULIES, M 8 MAROULIES, M 8 MAROULIES, M 8 MARKEE, E H MARKEE, E H	8208040276 8208110048 8208300307 8204010033* 8208230420*	PROJ 50-454 50-484 FOIA 50-320	Q Q P	MARTIN.T T. MARTIN.T T. MARTIN.T T. MARTIN.T T. MARTIN.T T. MARTIN.T T	6208100327 6208120047 6208120047 6208120074 6208120100	50-220
8208180047 8208190211 8208190231 8208190292 8208200047	50-382 Q 50-458 Q 50-458 Q 50-298 Q 50-498 Q	MARKT.D Markt.d Markt.d [Marsh.r L Marshall.J r	8208040304* 8208310053* 8208020188* 8208130231* 8208020078*	50-29 50-29 50-271 50-304 50-313	F F 8 8	MARTIN, T T. MARTIN, T. T MARTIN, T T. MARTIN, T. T MARTIN, T. T MARTIN, T T	6208120159 6208140014 6208140017 6208140019 6208140022*	70-624 50-354 B 50-317 G 70-356 70-356
8208200179 8208240184* 8208240190 8208240205 8208240216	50-458 G 50-278 G 50-382 G 50-382 G 50-278 G	MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8208020247* 8208030312 8208030524 8208050179 8208050251*	50-313 50-313 50-313 50-348 50-313	F R 8 Q	MARTIN, T T MARTIN, T T. MARTIN, T. T. MARTIN, T T. MARTIN, T T. MARTIN, T T.	8208170073 8208180043 8208190147 8208230180 8208230189	70-184 50-317 0 50-324 0 50-387 0 50-317 0
8208240223* 8208240437 8208270471 8208310130 8208310275	50-298 G 50-298 F 50-298 G 50-298 G 50-445 G	MARSHALL: J R MARSHALL: J R MARSHALL: J. R MARSHALL: J R MARSHALL: J. R.	8208050262 8208050334 8208060149 8208060174 8208060253	50-368 80-313 50-313 50-313 50-313	8 R F	MARTIN, T T.	8208230200 820823020A 8208230229 820823023A 8208230270	70-273 40-501 40-501 40-501 70-2625
8208160276* 8208300038* 8208040222 8208160148* 8208020174*	50-482 E 50-213 P NUREQ 50-318 B 50-244 F	Marshall, J. R. Marshall, J. R. Marshall, J. R Marshall, J. R Marshall, J. R	8208060266 8208070037 8208100102 8208100116 8208100170	50-368 50-313 50-313 50-313 50-313	ም ያ 8 የ	MARTIN, T T. MARTIN, T F	8208230300 8208230322 8208230333 8208230380 8208240274	70-425 50-317 0 50-317 0 50-387 0 50-29 0
8208020228* 8208020266 8208020313 8208030363 8208030519	50-244 Q 50-244 B 50-244 B 50-244 F 50-244 P	MARBHALL, J. R. MARBHALL, J. R. MARBHALL, J. R. MARBHALL, J. R. MARBHALL, J. R.	8208100201 8208110115 8208110176 8208120085 8208120194	50-313 50-313 50-313 50-313 50-368	P Q P R R	MARTIN, T. T. MARTIN, T T MARTIN, T T. MARTIN, T, T. MARTIN, T, T.	8208240388 8208250310* 8208260143 8208260227 8208260256	50-309 0 40-86 70-359 70-1173 70-190
8208040031 8208040079* 8208070048 8208170144 8208170173*	71-6601 50-244 F 50-244 G 50-244 P 50-244 P	Marshall, J. R Marshall, J. R Marshall, J. R. Marshall, J. R Marshall, J. R	8208140015 8208140079 8208160250 8208160504 8208170129	80-313 80-313 80-313 80-313 50-313	P 8 0 P P	MARTIN, T. T. MARTIN, T T. MARTIN, T T MARTIN, T T. MARTIN, T T. MARTIN, T T.	8208260259 8208260265 8208300044 8208300065 8208300191	70-303 70-429 50-244 0 50-245 0 70-398
8208170214 8208170216+ 8208270346* 8208270549* 8208300249	50-244 P 50-244 P 50-244 R 50-244 R 50-244 P	MARSHALL, J R MARGHALL, J R MARGHALL, J R MARSHALL, J R MARGHALL, J R	8208180001 8208180030 8208180074* 8208190156* 8208200157	50-313 50-313 50-313 50-313 50-313	P P Q F 8	MARTIN, T T MARTIN, T T. MARTIN, T. T MARTIN, T T. MARTINSON, Z. R.	8208300193* 8208300221 8208300245 8208300276 8208030048	70-398 70-135 50-293 @ 50-410 @ REB
8208310335 8208040207 8208250110* 8208180059* 8208300247	50-244 P ORG 40-86 50-382 G REGOD	MARSHALL: J.R MARSHALL: J.R MARSHALL: J.R MARSHALL: J.R MARSHALL: J.R	8208200277 8208230316 8208230356 8208250298 8208260128	50-313 50-313 50-313 50-313 50-368	8 P P P	MARTINSON, Z R MASON, C. C. MATAKAS, R A MATHENY, D. C MATHENY, D C.	9208030109 9208120201 9208240184# 9208100205# 9208310220#	REB 50-327 R 50-278 G 50-346 S 50-346 S
8208170018* 8208170035* 8208170038* 8208240355* 8208250330*	71-9086 71-9151 71-9151 50-344 G 40-86	MARSHALL, J. R. MARSHALL, J. R. MARSHALL, J. R. MARSHALL, J. R. MARSHALL, J. R.	8208270272 8208270275 8208270473* 8208270652* 8208300120	50-313 50-369 50-313 50-313 50-313	8 6 F R P	Matie, J B Matlock, R. G. Matlock, R. G Mateon, W. F. Matthews, D. B.	8208030299 8208240183 8208300112 8208020358 8208100019*	50-289 K 50-397 S 50-397 B 50-537 H 50-361 0
6208250354* 8208250357* 8208250377* 8208030523 8208140448	FOIA FOIA FOIA 50-133 J 50-220 R	Marshall, J. R. Marshall, W. H Marston, R. R Marston, R. R Marston, R. R	8208310099 8208300170 8208030323* 8208030309* 8208030574*	50-313 PRM 50-349 50-339 50-280	B Q Q	HATTIA:M HATTIA:M J. HATTIA:M J. HATTIA:M.J. HATTIA:M J	B208260385* B208040023* B208040477* B208040671* B208030146*	50-289 P CONTRACT CONTRACT CONTRACT CONTRACT
8208200042 8208200049 8208250197 8208190278* 8208120294*	50-220 P 50-220 P 50-220 P 50-339 P 50-373 R	MARSTON, R MARTIN, D MARTIN, D MARTIN, J. B MARTIN, S	8208140404* 8208300350 8208310147 8208030725 8208170373	50-327 40-8681 50-334 WASTE MO		MATTIA:M J. MATTIA:M.J. MATTIA:M J. MATTIA:M J. MATTIA:M J.	8208060002* 8208090329 8208230451* 8208250022* 8208260071	CONTRACT HISC CONTRACT CONTRACT CONTRACT
8208180105 8208050187 8208310346 8208270628* 8208030663*	50-358 Q 50-410 8 50-410 A 50-321 R 70-143	MARTIN,T J MARTIN,T.J MARTIN,T.J MARTIN,T J MARTIN,T T	9209070145 8208100220* 8208140140 8208240223 8207080350	50-354 50-354 50-354 50-354 70-511	9 0 0 8	MATTIA, M. J. MATTIA, M. J. MATTIMOE, J. J. MATTIMOE, J. J. MATTIMOE, J. J.	8208310488* 8208310515* 8208020181 8208020201 8208020257	50-537 A CONTRACT 50-312 P 50-312 S 50-312 S
8209160478 8209160476 8209110229* 8206270076 8208250385*	70-143 70-143 XPORTLIC Foia Foia	MARTIN,T T MARTIN,T T MARTIN,T.T. MARTIN,T T. MARTIN,T T	8208020166 8208020264 8208020270* 8208020338 820802034	50-443 50-277 50-277 50-293 70-113	a a o q	MATTIMOE, J. J.	8208030298 8208030420 8208040001 8208130183 8208160069	50-312 P 50-312 P 50-312 P 50-312 F 50-312 Q
8208030292 8208090133 8208160086 8208160213 8208160316*	50-302 P 50-302 B 50-302 R 50-302 G 50-302 G	MARTIN, T. T MARTIN, T. T. MARTIN, T. T. MARTIN, T. T. MARTIN, T. T	8208020370 8208020383 8208030082 8208030239 8208030273	50-220 50-309 50-245 50-293 50-322	0 0 0 0	MATTIMOE, J. J.	8208160425 8208170166 8208180117 8208200027 8208200122	50-312 P 50-312 P 50-312 F 50-312 P 50-312 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTH O R	ACCESSION NUMBER	BUBJECT CATEGORY
MATTIMOE, J J	8208200134 8208200212 8208230185 8208230244 8208230250	50-312 S 50-312 S 50-312 P 50-312 G 50-312 P	MCGARRY, J M KCGARRY, J M KCGARRY, J M KCGARRY, J M KCGAUGHY, J P	8208030358 8208030358 8208110166 8208110166 8208030408#	50-413 G 50-413 G 50-413 G 50-413 G 50-416 G	MCNALLY, R MCNALLY, R MCNAMARA, A E MCNAMARA, J. R MCNEILL, C A	8208020422* 8208020425* 8208120247* 8208040434 820808050507	50-537 U 50-537 U 50-244 R 50-537 H 50-333 B
L L.BOMITTAM	8208230273	50-312 P	P. C. CHOUADON P. C.	8208030419*	50-416 G	MCNEILL, C. A	8208090044	50-333 8
J. L.BOMITTAM	8208240377	50-312 P		8208030482	50-416 B	MCNEILL, C. A	8208090085	50-333 8
J. L.BOMITTAM	8208250303	50-312 P		8208070041	50-416 B	MCNEILL, C. A	8208100034	50-333 R
J. L.BOMITTAM	8208270221	50-312 Q		8208070067	50-416 F	MCNEILL, C. A	8208140028	50-333 8
J. L.BOMITTAM	8208270226	50-312 Q		8208120222	50-416 P	MCNEILL, C. A	8208140031	50-333 8
MATTIMDE, J J MATTIMDE, J, J MATTIMDE, J J MATTSON, R J MAUCH, M L	8208270338 8208270339 8208300136 8204210308* 8208260075	50-312	T. YHOUADON T. YHOUADON T. YHOUADON T. YHOUADON T. YHOUADON	8208160075 8208160339 8208200004 8208200020 8208200059	50-416 8 50-416 8 50-416 5 50-416 6 50-416 8	MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A	8208230108* 8208230112* 8208230340 8208260161 8208260167	50-333 Q 50-333 Q 50-333 S 50-333 S
MAUCK, J L MAURA, F, MAURA, F MAURIN, L V MAURIN, L V	8208110042 8208100244* 8208100245* 8208020197* 8208030516	50-322 T 50-373 Q 50-249 Q 50-382 F PR	P L.YHOUAGON P L.YHOUAGON P L.YHOUAGON P L.YHOUAGON P L.YHOUAGON	8208270227 8208270327 8208270472 8208300105 8208300314	50-416 8 50-416 8 50-416 5 50-416 8 50-416 8	MCNEILL, C A	8208260208 8208260243 8208260266 8208270193*	50-333 B 50-333 B 50-333 B 50-333 R
MAURIN, L, V	8208070043	50-392 R	MCGILL,PL	8208030213	REVIEW GRP	MCNEILL, C. A	8208270237* 8208190280* 8208310139* 8208310244* 82083180257	50-333 R
MAURIN, L, V	8208120068	50-392 A	MCGIRT,RS	8208230458*	50-261 8	MGNEILL, H M		GA999
MAURIN, L, V	8208270357	50-392 A	MCGREGOR,GL	8208070077*	50-456 G	MGNEILL, H M		GA999
MAURIN, L, V	8208310154	50-392 A	MCGUIRE,DR	8208030417*	50-250 G	MGNEILL, W M		GA999
MAURIN, L, V	8208310326	90-382 A	MCGUIRE,DR,	8208070127*	50-327 G	MGNULTY, A		CONTRACT
MAY, E L.	8208070122*	50-29 8	MCQUIRE, D. R	6208070136*	50-348	MCNULTY, A	8208180264	CONTRACT
MAY, E L.	8208230045*	50-29 B	MCQUIRE, D. R	6208100224*		MCNULTY, A	8208300157	CONTRACT
MAYER, L. O	8208270619	50-282 R	MCQUIRE, D. R	6208100235*		MCQUEEN, A	8208030167*	70-600
MAYER, L. O	8208270644*	50-243 R	MCQUIRE, D. R	6208100274*		MCQUEEN, A D	8208030151*	50-27 G
MAYS, S. E	8208170003*	50-155 F	MCQUIRE, D. R	6208100316*		MCQUEEN, A D	8208030498*	50-139 G
MAZUR, D. W	8208050343	50-460 8	MCGUIRE, D R	8208130297#	50-83 Q	MCQUEEN, A. D	8208270425*	70-734
MAZUR, D. W	8208050448	50-460 8	MCGUIRE, D R	8208140110#	50-261 0	MEALE, R	8208130115	50-220 P
MAZUR, D. W	8208050527	50-460 8	MCGUIRE, D R	8208230329#	70-27	MEALVE, D	8208310331	PR
MAZUR, D. W	8208100150*	50-460 0	MCGUIRE, D R	8208240241	50-261 8	MEDFORD, M. O	8208070051	50-361 P
MAZUR, D. W	8208100231*	50-460 0	MCGUIRE, D R	8208300147#	50-261 Q	MEDFORD, M. O	8208270238	50-361 P
MAZUR, D. H. MAZUR, D. W MAZUR, D. H. MCALPINE, E. J. MCALPINE, E. J.	8208100273* 8208100323* 8208140432 8208030131* 8208030243*	80-440 G 50-460 G 50-460 B 70-143 70-1113	McGuire, R D McGurren, H J McGintosh, M D McKenna, T. J.	8208160237 8208110236 8208180118 8208260392# 8208050269#	PR 50-247	MEDLOCK, R L MEIBAUM, R. A MENCZER, W. B MENDENHALL, E MENDEZ, R	8208110083 8208250397* 8208030058 8208100219* 8208240425*	40-8452 FDIA 50-456 A 50-254 B 50-327 G
MCALPINE.E.J	8208030304*	70-1113	MGKENNA, T. J.	8208170141*	50-293 Q	MENDLIN, J T	8208120177	50~537 H
MCALPINE.E.J	8208030324*	70-1201	MGKENZIE, D. H.	8208180124	NUREQ	MENDONCA, M M	8207080426*	50~275 G
MCALPINE.E J	8208030333*	70-824	MGKENZIE, D. H	8208180237	NUREQ	MENDONCA, M M	8208160314*	50~275 G
MCALPINE.E.J	8208030347*	70-27	MGKIBBEN, J. C	8208310369	50-186 R	MENWEG, M	8208260066	NUREG
MCALPINE.E.J	8208030315*	70-1201	MGKIBBEN, J. C	8208310377*	50-186 R	MERCER, J W	8208130474	NUREG
MCALPINE.E J	8208030639*	70-1151	MCKINNEY, M	8208060062#	50-320 F	MESERVE, M	8208040463*	50-537 D
MCALPINE.E.J	8208030685*	70-143	MCKINNEY, M	8208110217#	50-320 F	MEGLER, R B	8208020362	50-148 R
MCALPINE.E J,	8208160497*	70-27	MCLAIN, M E	8208270650	70-1113	MESSINGER, R L	8208020275	50-247 O
MCBREARTY.R A	8208230342*	50-317 G	MCLAUGHLIN, M, T	8208030271#	50-293 8	METZGER, R M	8208180237	NUREO
MCBRIDE.L.M	8208020252	50-247 P	MCLEAREN, T	8208180144	CONTRACT	MEYER, O.	8208020377*	50-287 Q
MCBRIDE, L M	8208130177*	50-267 R	MCLEAREN, T,	8208250018	CONTRACT	MEYER, Q	8208230384*	50-387 Q
MCBRIDE, M	8208020273*	50-322 Q	MCLEAREN, T	8208300022	CONTRACT	MEYER, Q.	8208300068*	50-245 Q
MCBRIDE, M H	8208300047*	50-244 Q	MCLEAREN, T	8208300025	50-320 P	MEYER, K. A.	8208040381*	50-331 F
MCBRIDE, M H	8208300248*	50-293 Q	MCLENDON, Q, D	8208020334	50-382 K	MICHELB, B.	8208020275	50-247 Q
MCCABE, E. C	8208050427*	50-317 Q	MCLENDON, Q D	8208020343*	50-382 K	MICHELBON, C.	8202220663*	50-416 F
MCCABE, E. C. MCCABE, E. C MCCABE, E. C MCCABE, E. C. MCCABE, E. C.	8208170104* 8208230473* 8208300091* 8208300203* 8208300258*	50-317 Q FOIA 50-277 Q 50-317 Q 50-387 Q	MCLENDON, G. D MCLENDON, G. D. MCLENDON, G. D MCLENDON, G. D MCLENDON, G. D	8208100160 8208100169 8208100229 8208100313 8208100319	50-382 8 50-382 8 50-382 8 50-382 8 50-382 8	MICHELBON, C MICHELBON, C MICHELBON, C MICHELBON, C	8208060030 8208060327 8208110215 8208270684 8208270688*	50-217 8 50-247 8 50-414 F 50-206 P 50-206 P
MCCANN, J D.	8208300270	PR	MCLENDON, G D MCLENDON, G D. MCLENDON, G, D. MCLENDON, G D. MCLENDON, G D.	8208160023	50-382 8	Michelbon, c	8208270471*	50-206 P
MCCANN, J F	8208300258*	50-387 Q		8208160038	50-382 8	Michelbon, c	8208270475*	50-206 P
MCCARTHY, E. L.	8208020358	50-537 H		8208160046	50-382 8	Midura, H. J.	8208020137	50-272 B
MCCLELLAN, R. O.	8208170117	50-537 T		8208160076	50-382 8	Midura, H. J	8208020315	50-272 B
MCCLELLAND, R	8208020368	50-537 H		8208160175	50-382 8	Midura, H. J	8208020353	50-311 B
MCCLEBREY, K E MCCLEBREY, K E MCCLEBRY, E. B MCCLEBRY, E. B MCCLINTOCK, R	8208300305 8208300305 8208250264 8208250264 8208250166*	50-322 Q 50-322 Q 50-322 Q 50-322 Q 40-86	MCLENDON, Q D. MCLENDON, Q D MCLENDON, Q. D. MCLENDON, Q. D. MCLENDON, Q. D. MCLENDON, Q D.	8208160283 8208170122 8208170313 8208170341 8208200060	50-382 8 50-382 8 50-382 8 50-382 8	MIDURA, H. J. MIDURA, H. J. MIDURA, H. J. MIDURA, H. J. MIDURA, H. J.	8208050097 8208050335 8208050348 8208050371 8208050492	50-311 8 50-272 8 50-311 8 50-318 8 50-272 8
MCCLINTOCK, R O.	8208250208*	40-86	MCLENDON; O. D	8208200040	20-385 d	MIDURA: H. J.	8208100010	50-272 8
MCCLOSNY, M	8208250126*	FOIA	MCLENDON; O. D	8208200094	20-385 d	MIDURA: H. J.	8208100079	50-272 8
MCCONNEL, T.	8208260345*	50-347 F	MCLENDON; O. D	8208200271	20-385 8	MIDURA: H. J.	8208130113	50-272 8
MCCORKLE, O H	8208160442	50-390 P	MCLENDON; O. D	8208240193*	20-385 8	MIDURA: H. J.	8208130214	50-311 8
MCCRACKEN, C.	8208040633	50-287 P	MCLENDON; O. D	8208240208*	20-385 8	MIDURA: H. J.	8208130249	50-272 8
MCGRACKEN, C	6208110034	50-289 P	MCLENDON, Q D,	8208240244	50-382 8	MIDURA: H. J.	8208160048	50-272 R
MGGRAGKEN, C,	6208310373	50-289 P	MCLENDON, Q D	8208240256	50-382 8	MIDURA: H. J.	8208160085	50-272 R
MCDERMOTT, D	8208250461	CONTRACT	MCLENDON, Q D	8208240266	50-382 A	MIDURA: H. J.	8208180071	50-272 8
MCDIARMID, R, C	6208180018	50-275 M	MCLENDON, Q D.	8208270168	50-382 8	MIDURA: H. J.	8208190003	50-311 8
MCDIARMID, R, C,	8208180018	50-275 M	MCMURRAY, C. M	8208040233	50-322 Q	MIDURA: H. J.	8208190113	50-311 8
MCDONALD, J A MCDUFFIE, M, A MCDUFFIE, M A, MCDUFFIE, M A MCFARLAND, C R.	8208030425*	50-390 Q	HCMURRAY, C. M.	8208040233	50-322 0	MIDURA: H J.	8208190127	50-311 8
	8208050284	50-400 A	HCMURRAY, C. M.	8208060140	50-322 0	MIDURA: H J	8208190138	50-311 8
	8208050381	50-400 A	HCMURRAY, C. M	8208060140	50-322 0	MIDURA: H J.	8208190143	50-311 8
	8208240157	50-400 C	HCMURRAY, C. M	8208310033	FOIA	MIDURA: H. J.	8208190165	50-311 8
	8208240157	50-280 Q	HCMALLY, R.	8208020418	50-537 U	MIDURA: H. J.	8208190216	50-311 8

AOHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
MIDURA:H J	8208240395	50-311 S	MILLER.W O	8208250124*	40-86	MILLS, L M	8208160502*	50-259 Q
MIDURA:H J	8208260137	50-311 S	MILLER.W O	8208250450	70-371	MILLS, L M	8208160533	50-438 &
MIDURA:H J	8208260148	50-272 S	MILLER.W O	8208270545	50-334 P	MILLS, L M	8208170283	50-259 K
MIDURA:H J	8208260252	50-272 S	MILLER.W O	8208310340	50-361 P	MILLS, L M	8208180017	TOPREP
MIDURA:H J	8208260320	50-272 S	MILLIGAN.M H	8208020337	50-322 8	MILLS, L M	8208190179	50-327 P
MIDURA,H J	9208300056	50-311 8	MILLIGAN, M H	8208050348	50-322 8	MILLB, L M	8208200014	50-390 8
MIDURA,H J	8208300075	50-311 8	MILLIGAN, M H	8208050511	50-322 8	MILLB, L M	8208200038	50-390 8
MIDURA,H J	8208300204	50-311 8	MILLIKEN, G. A	8208260097	NUREO	MILLB, L M	8208200099	50-439 8
MIDURA,H J	8208300208	50-311 8	MILLIKIN, R P	8208190294#	50-482 G	MILLB, L M.	8208200103	50-390 8
MIDURA,H J	8208300229	50-311 8	MILLS, L, M	8207060127	50-259 F	MILLB, L M	8208200167	50-438 8
MIDURA, H J	8208300330	50-311 8	MILLB, L, M	8207120078*	50-257 F	MILLS, L M.	8208200178	50-390 A
MIDURA, H J	8208310150	50-311 5	MILLB, L M	8207220182	50-438 A	MILLS, L, M	8208200207	50-327 P
MIDURA, H J	8208310271	50-311 8	MILLB, L H	8207270454	50-259 P	MILLS, L M	8208200209	50-438 &
MIDURA, H, J	8208310285	50-272 8	MILLB, L, M	8208020077	50-390 B	MILLS, L M.	8208230331	50-259 F
MIDURA, H J	8208310318	50-311 8	MILLB, L M	8208020104	50-438 B	MILLS, L M.	8208230364	90-327 P
Midura, H J	8208310395	90-311 8	MILLB, L, M	8208020108	50-370 8	MILLB, L. M	8208250374	50-259 P
Might, A	8208120212*	50-315 R	MILLB, L M	8208020152	50-438 8	MILLB, L. M.	8208240343*	50-259 F
Might, A.	8208120274*	50-316 R	MILLB, L, M	8208020158	50-438 8	MILLB, L. M	8208270099	50-438 S
Mileb, E B	8208230446	CONTRACT	MILLB, L M	8208020141	50-370 8	MILLB, L. H	8208270107	50-438 S
Milhiber, R J	8208170341	50-382 B	MILLB, L M	8208020149	50-438 8	MILLB, L. M.	8208270128	50-390 S
MILHISER.R J	8208270168	50-382 8	MILLS, L M.	8208020179	50-390 8	MILLB, L H	6208270245	50-438 S
MILLAR.F	8208040080*	50-537 D	MILLS, L M.	8208020221	50-259 P	MILLB, L, H.	6208270251	50-438 S
MILLER.D E	8208100242*	50-440 0	MILLS, L, M.	8208020222	50-390 A	MILLB, L H	8208270275	50-390 S
MILLER.D E	8208310232*	50-255 0	MILLS, L, M	8208020224	50-328 8	MILLB, L H	8208270283	50-390 S
MILLER.D S	8208240263	50-307 9	MILLS, L M	8208020242	50-390 8	MILLB, L, M	8208270326	50-438 S
MILLER, Q E	8208060219	50-326 R	MILLB, L, M	8208020361	50-43B 8	HILLB, L. H.	6208270341	50-370 8
MILLER, Q E	8208060223*	50-326 R	MILLB, L M.	8208020380	50-43B B	HILLB, L. H.	6208270342	50-370 B
MILLER, Q N	8208260438	NUREQ	MILLB, L M	8208030161	50-390 B	HILLB, L. H	8208270361	50-438 B
MILLER, H, J	8208040564	WASTE MOT	MILLB, L, M	8208030189	50-43B B	HILLB, L. H	8208270392	50-370 B
MILLER, H J.	8208170368	WASTE MOT	MILLB, L, M	8208030171*	50-43B G	HILLB, L. H	8208270457	50-257 I
MILLER, H J	8208180204	WASTE MOT	MILLB, L. M	8208030203	50-438 8	MILLS, L. M.	8208270601#	50-259 R
MILLER, J H.	8208120134*	50-321 I	MILLB, L. M	8208030207	50-438 8	MILLS, L. H	8208300086	50-438 B
MILLER, J, R	8208020297	70-36	MILLB, L. M	8208030225*	50-438 9	MILLS, L. M.	8208300072	50-390 B
MILLER, J R	8208050382	50-346 G	MILLB, L. M	8208030238	50-438 8	MILLS, L. M.	8208300125	50-390 A
MILLER, J. R.	8208050462	50-155 G	MILLB, L. M.	8208030249	50-390 8	MILLS, L. M.	8208300165	50-438 B
MILLER, J R	8208050500	50-346 F	MILLB, L. M	8208030319	50-438 8	HILLS, L. M.	8208300202	50-438 8
MILLER, J. R.	8208100237	50-440 G	MILLB, L. M.	8208030378*	50-438 0	HILLS, L. M	8208300211	50-329 8
MILLER, J R	8208100287	50-10 G	MILLB, L. M.	8208030378*	50-438 0	HILLS, L. M	8208300222	50-370 8
MILLER, J R	8208160109	50-255 G	MILLB, L. M	8208030492*	50-370 0	HILLS, L. M.	8208300224	50-438 8
MILLER, J R.	8208300111	70-1308	MILLB, L. M.	8208030562*	50-327 0	HILLS, L. M.	8208300240	50-370 8
MILLER, J. R MILLER, J R MILLER, J R. MILLER, J. R. MILLER, J R	8208300179 8208300194 8208310054 8208310223 8208310227#	50-265 Q 50-315 Q 50-373 Q 50-255 Q 50-255 Q	MILLB, L, M MILLB, L, M. MILLB, L, M. MILLB, L, M. MILLB, L, M.	8208040047 8208050183 8208050216 8208050332 8208050347	71-9139 50-438 B 50-438 B 50-438 B 50-390 B	MILLB, L. M, MILLB, L. H, MILLB, L. M, MILLB, L. M MILLB, L. M,	8208300252 8208300269 8208300324 8208300334 8208300338	50-438 8 50-438 8 50-438 8 50-436 8
MILLER, J. R. MILLER, J. R. MILLER, J. R. MILLER, L. K. MILLER, L. K	8208310349 8208310422 8208310424* 8208160049* 8208160051*	70-36 50-305	MILLB, L, M MILLB, L, M MILLB, L, M MILLB, L, M MILLB, L, M	8208050420 8208050444 8208050474 8208060138 8208090046	50-390 8 50-326 8 50-436 8 50-438 A 50-259 F	MILLS, L. M MINECK, D. L. MINECK, D. L MINECK, D. L MINECK, D. L.	8208310200 8208050376 8208050073 8208050167 8208100045	50-231 B 50-331 B 50-331 B 50-331 B
MILLER, L K MILLER, L K. MILLER, L. K. MILLER, L K. MILLER, L K	8208160053* 8208160055* 8208160056* 8208160087* 8208300217	50-272 R 50-272 R 50-272 R 50-272 R 50-272 R	MILLB, L M MILLB, L M MILLB, L. M MILLB, L. M MILLB, L. M	6208090097 8208090084 6208090161 8208090215 6208100002	80-390 8 50-438 8 50-438 8 50-438 8 50-259 I	Mineck, D.L. Mineck, D.L. Mineck, D.L Mineck, D.L. Mineck, D.L.	8208100128 8208100137 8208130140 8208130233 8208170104	50-331 8 50-331 8 50-331 8
MILLER, L. K	8208300217*	50-272 R	MILLB, L M.	8208100166	50-518 A	MINECK, D. L.	8208230037	50-331 8
MILLER, M	8208120298	50-537 H	MILLB, L M.	8208100315	50-327 P	MINECK, D. L.	8208240135	50-331 8
MILLER, M. E	8208050463	50-445 Q	MILLB, L, M	8208120066	50-438 E	MINECK, D. L.	8208240314	50-331 8
MILLER, M. E	8208070146	50-445 Q	MILLB, L, M.	8208120102	50-390 E	MINECK, D. L.	8208270535*	50-331 R
MILLER, M. E	8208070262	50-537 Q	MILLB, L, M.	8208120153	50-438 B	MINER, B.	8208060108*	50-346 P
MILLER, M. E	8208240187*	50-445 Q	MILLB, L. M	8208120157	50-390 8	Miner, 8,	8208060336*	50-346 Q
MILLER, M. E.	8208240411	50-537 Q	MILLB, L. M	8208120161	50-390 8	Hiner, 8,	8208100375*	50-313 P
MILLER, M. E	8208240418	50-445 Q	MILLB, L. M.	8208120187	50-438 8	Miner, 8,	8208130067*	50-278 P
MILLER, W. H.	8208030148*	70-1151	MILLB, L. H	8208120249	50-390 8	Miraolia, F, J	8208030068	50-361 E
MILLER, W. H	8208030476*	50-348 Q	MILLB, L. H.	8208120306	50-390 8	Miraolia, F, J.	8208030731	50-443 D
MILLER, W. H.	8208160287#	50-370 G	MILL8; L. H.	6208130169	50-390 8	Miraqlia, f. J.	8208040085	50-400 A
MILLER, W. H.	8208160357*	50-389 G	MILL8; L. M.	6208130203	50-390 8	Miraqlia, f. J	8208040104	50-387 A
MILLER, W. H	8208160384*	50-413 G	MILL8; L. M	6208130224	50-438 8	Miraqlia, f. J.	8208040253	50-382 A
MILLER, W. H.	6208190316*	50-413 A	MILL8; L. M.	6208130263	50-438 8	Miraqlia, f. J.	8208040272	50-341 P
MILLER, W. O.	8207140515	50-206 P	MILL8; L. M.	6208130266	50-390 8	Miraqlia, f. J.	8208040277*	50-341 P
MILLER, W. D	8207140517	50-261 P	MILLB, L, M	8208130287	50-438 8	Miraqlia, f. j.	8208040301*	50-361 P
MILLER, W. D	8208020429	50-267 P	MILLB, L, M.	8208140077	50-438 8	Miraqlia, f j.	8208040478	50-443 F
MILLER, W. D.	8208040028	71-9135	MILLB, L, M.	8208140132	50-390 8	Miraqlia, f. j	8208040527	50-275 F
MILLER, W. D.	8208040563	50-302 P	MILLB, L, M.	8208140210#	50-438 0	Miraqlia, f. j.	8208040644	50-443 A
MILLER, W. D	8208040565	50-443 A	MILLB, L, M.	8208140222	NUREO	Miraqlia, f. j.	8208050119	50-361 P
MILLER, W. O.	8208040041	TOPREP	MILLS, L. M	8208160261	50-390 8	Miraqlia; f J,	8208050133*	50-361 P
MILLER, W. O.	8208070312	50-213 F	MILLS, L. M	8208160307	50-438 8	Miraqlia; f, J,	8208050137*	50-361 P
MILLER, W. O.	8208070314	TOPREP	MILLS, L. M.	8208160313	50-438 8	Miraqlia; f J,	8208090323	50-443 D
MILLER, W. O.	8208070321	TOPREP	MILLS, L. M.	8208160346*	50-390 Q	Miraqlia; f J	8208110297	50-400 A
MILLER, W. O	8208070322	TOPREP	MILLS, L. M	8208160352*	50-390 Q	Miraqlia; f, J	8208170024	50-369 M
MILLER, W. O	8208110010	70-734	Mille, L. M.	8208160368	50-438 B	Miraglia, f. J.	8208170026*	50-389 M
MILLER, W. O	8208230463	70-135	Mille, L. M.	6208160447*	50-327 G	Miraglia, f. J.	8208170051	50-400 A
MILLER, W. O	8208230465	50-331 P	Mille, L. M	6208160464*	50-327 G	Miraglia, f. J.	8208260613	50-278 P
MILLER, W. O.	8208240112	70-143	Mille, L. M.	6208160477	50-390 B	Mibak, A.	8208160438*	50-254 B
MILLER, W. O.	8208240465	40-8027	Mille, L. M.	6208160470	50-438 B	Mibbrener, J. M.	8208270424	70-143

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MITCHELL,D G MITCHELL,D G MITCHELL,C L MITTL,R L MOBLEY,B	8208060146# 8208130048# 8208170321# 8208030508 8208200070	50-387 S 50-387 S 50-413 A PR 40-86	MGURY, W R MROCZKA, E J	8208240330 8208020147 8208050114 8208060166 8208060206	XPORTLIC 50-336 8 50-336 0 50-336 8 50-336 8	NARDOCI, P B	8208020084* 8208020090* 8208030215* 8208050203* 8208050402*	50-347 B 50-349 B 50-349 B 50-349 B 50-349 B
MOBLEY, B L MOBLEY, B L MOBLEY, B L MOBLEY, B L	6208250112* 6208250120* 6208250122* 6208250130* 6208250155*	40-86 40-86 40-86 40-86 40-86	MRQCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8208060204 8208120090 8208120090 8208120277 8208120277	50-336	NARDDGI,P B NARDDGI,P B NARDDGI,P B NARDDGI,P B NARESKY,J J	8208070235* 8208140418* 8208200034* 8208200241* 8208040185	50-349 B 50-349 B 50-349 B 50-349 B REVIEW GRP
MOBLEY, B L MOBLEY, B L MOCKLI, B MOCKLI, B.	8208250174* 8208250389* 8208250374* 8208040272 8208170128	40-86 40-86 FOIA 71-6717 71-6717	MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8208120294 8208120294 8208180004 8208180004 8208200091	50-336 R 50-336 R 50-336 S 50-336 S	NASH, B NASH, B NASH, D A NATARAJA, M S NATARAJA, M S	8208040274* 8208050125* 8208230078* 8208130455 8208190012	50-289 F 50-287 F 50-484 G WABTE MGT WASTE MGT
MGEGGENBERG, D	6208050207*	50-348 8	MROCZKA, E J	8208260126	50-336 8	NATHAN, B J	B208260350#	50-324 F
MGEGOENBERG, D	6208200170*	50-313 8	MROCZKA, E J	8208260126	50-336 8	NAVE, E D	B208200129#	50-260 8
MGJTA, M T	6208050249*	50-271 Q	MROCZKA, E J	8208260159	50-336 8	NEEL, A W	B208100051	50-537 D
MGJTA, M T	6208230261*	50-273 F	MROCZKA, E J	8208260246	50-336 6	NEIGHBORG, J D	B208040072	50-272 G
MGLVIE, W A	6208020099*	QA999	MROCZKA, E J	8208260246	50-336 8	NEIGHBORG, J D	B208040342	50-348 P
MOLZAHN, D J MOLZAHN, D J MONTGOMERY, D M MONTGOMERY, D M MONTGOMERY, D M	8208130078* 8208130243* 8208030538* 8208030413* 8208160416*	50-305 E 50-305 E 50-33B Q 50-269 Q	MRDCZKA, E U MUELLER, R MURPO, J J MURPHY, D MURPHY, D	8208270541* 8208200149* 8208240038 8208030144* 8208270507*	50-245 R 50-285 8 71-7166 50-259 6 50-259 8	NEIGHBORB.J D NEIGHBORB.J D NEISLER.J H NELBON.C C NELBON.C C	8208040580 8208050018 8208070097* 8208030040 8208050145	50-295 P 50-348 P 50-456 Q 50-309 P 50-309 P
MOODY, D E	6208100137	50~29 G	MURPHY, D E HURPHY, D E HURPHY, E L HURPHY, H E HURPHY, K E	8208050281*	50-259 S	NELSON, C C	8208070028	50-309 P
MOODY, D, E	8208120232	50~29 R		8208270082*	50-260 B	NELSON, C C	8208230421	50-309 P
MOODY, D E	6208240260*	50~29 G		8208180134*	50-266 Q	NELSON, G B	8208270363*	70-25
MOODY, D E	8208270547*	50~29 R		8208190225*	50-313 Q	NELSON, M A	8208040278*	50-289 F
MOODY, D, E	6208270629*	50~29 R		8208270478*	50-278 Q	NELSON, M A	8208050130*	50-289 F
MODNEY, J MODN, C W MODN, C W MODNEY, J	62080A0037 8208230191 8208240144 8208300003 6208120223*	50-522 A 50-522 A 50-522 A 50-522 A 50-327 A	MURPHY, W P MURPHY, W P MURPHY, W P MURRAY, B MURRAY, B	8208020187* 8208050259 8208050263* 8208100070* 8208240179*	50-271 F 50-271 S 50-271 S 50-382 0 50-298 0	NELSON, M A NELSON, P R NELSON, R L NEMETHY, E NERSES, V	8208170359* 8208250159* 8208230100* 8208030552 8208040608	50-289 F 40-86 50-305 G PRM 50-389 G
MODNEY, J	8208120224*	50-329 A	MURRAY, T	8208040107*	50-346 F	NERSES, V	8208050189	50-389 A
MODNEY, J A	8208240307*	50-329 A	MURRAY, T	6208110253*	50-346 F	NERSES, V	8208190044	50-389 P
MODRE, C A	8208030501	REVIEW ORP	MURRAY, T D	6208050242*	50-346 P	NEUDER, B M	8208170008	WABTE MGT
MODRE, D E,	8208100318*	50-321 G	MURRAY, T D.	8208050435	50-346 S	NEUMANN, M R	8208050031	40-8697
MODRE, D E	8208130277*	50-83 G	MURRAY, T D	8208040321*	50-346 F	NEWACHECK, R L	8208030598*	50-228 R
MODRE, D E	6208230327*	70-27	MURRAY, T D. MURRAY, T D	8208100200	50-346 8	NEWMAN.JR	8208060092	50-498 G
MODRE, O H	6208030020*	50-275 Q		8208130078	50-346 8	NEWMAN.JR	8208060092	50-498 G
MODRE, J E	6208200120	50-247 Q		8208130148	50-346 8	NEWMAN.JR	8208090272	50-498 G
MODRE, R D	6208260024*	50-10 F		8208130281	50-346 8	NEWMAN.JR	8208090278*	50-498 G
MODRE, R N	6208030046	XPURTLIC		8208160450	50-346 8	NEWMAN.RW	8208020358	50-537 H
MOCRE, R N	8208030049	XPORTLIC	MURRAY, T D	8208270621*	50-346 R	NICHOLABIH	8208300258*	50-387 Q
MOCRE, R N	8208030054	XPORTLIC		8208270625*	50-346 R	NICHOLBONIN A	8208270142*	50-10 Q
MOCRE, R N	8208030711	XPORTLIC		6208300097	50-346 8	NICHOLBONIN A	8208270557*	40-7604
MOCRE, R. N.	8208060012	MISC		6208300133	50-346 8	NICHOLBONIN A	8208310351*	50-254 Q
MOCROS, N	8208180158	RES		8208310217	50-346 8	NICHOLABIH	8208040166*	50-387 P
MOREN, A. E	8208100311	REGGD	MURRILL.P W	8208040434	50-537 H	NIELBEN, J R	8208020060	RES
Morgan, C	8208170283	50-247 G	MUSOLF.D	9208020119	50-282 8	NIELBEN, L A	8208170206*	50-244 P
Morgan, C	8208170285	50-247 G	MUSOLF.D	8208020320	50-263 P	NIELBON, K K	8208260075	NUREO
Morgan, C,	8208170123*	50-247 G	MUSOLF.D.	8208030228	50-282 P	NIGHTINGALE, E	8208070097*	50-456 G
Morgan, C	8208170123*	50-247 G	MUSOLF.D.	8208030228	50-306 8	NIMITZ, R L	8208020276*	50-277 G
MORGAN, J N.	8208170188*	50-244 P	HUSOLF, D	8208100055	50-282 P	NIMITZ, R L	8208300248*	50-293 Q
MORGAN, K Z	8208180117*	50-537 T	MUSOLF, D	8208100067	50-263 P	NIX, H G	8208030442	50-321 B
MORGAN, K, Z	8208180117*	50-537 T	MUSOLF, D	8208120181	50-282 P	NIX, H, C	8208060182	50-366 B
MORGAN, H	8208200043*	50-237 S	MUSOLF, D	8208130082	80-263 R	NIX, H C	8208060189	50-366 B
MORGAN, H	8208230401*	50-249 S	MUSOLF, D	8208130198	50-282 R	NIX, H C	8208090271	50-321 B
MORGENSTERN, M MORISI, A. V MORISI, A. V MORRILL, P MORRILL, P. J	8208130475 8208050162 8208100104 8208160105* 8208160525*	NUREQ 50-293 Q 50-293 P 50-142 Q 50-275 Q	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D, MUSOLF, D	8208200084 8208200294 8208200300* 8208260118 8208270294	50-282 P 50-282 P 50-282 P 50-263 P 50-282 P	NIX.H C NIX.H C NIX.H C NIX.H C	8208070276 8208120109 8208120191 8208120199 8208130156	50-321 8 50-366 8 50-366 6 50-321 8 50-366 8
MORRIB, K. J. MORRIB, K. J. MORRIB, N. F. MORTIEN, T. H. MORTIEN, T. H.	8208130301	OEN TEC IS	MUBDLF, D	8208300232	50-263 P	NIX.H C	8208160091	50-321 R
	8208130301	GEN TEC IS	MUBDLF, D	8208300326	50-282 F	NIX.H C	8208160238	50-366 B
	8208250358*	50-413 A	MUBDLF, D	8208310017	50-306 B	NIX.H C	8208160272	50-321 B
	8208120219*	50-409 P	MUSDLF, D. M.	8208020323#	50-263 P	NIX.H C	8208160454	50-321 B
	8208170100*	50-409 P	MUBDLF, D. M	8208030090#	50-282 F	NIX.H C.	8208160495	50-366 B
HORTIEN, T. W	8208170112*	50-409 P	MUSDLF, D M	8208100062*	50-282 P	NIX, H C	8208200045	50-321 8
MORTON, A. C.	8208040367	50-537 H	MUSDLF, D, M	8208100174	50-282 P	NIX, H C,	8208200284	50-366 B
MORTON, K. V.	8208060365*	CONTRACT	MUSDLF, D M	8208170247	50-263 P	NIX, H C	8208270137	50-366 B
MORTON, K. V.	8208110302*	CONTRACT	MUSDLF, D M	8208230338	50-282 P	NIX, H C	8208270228	50-366 B
MORTON, K. V.	8208120381*	CONTRACT	MUSDLF, D M	8208240136	50-282 P	NIX, H C	8208270235	50-321 8
MORTON, K V MORTON, K V. MORTON, K V MORTON, K V MORTON, K, V	8208170324* 8208240355* 8208240428* 8208240459* 8208240445*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MYERS.D O MYERS.R V MYERS.R V MYRABO.A L NAGAI.Y	8208030182* 8208100216 8208250213 8208130087* 8208310440	50-324	NIX, H C NIX, H C NIX, H C. NIX, H C. NIX, H. G.	8208270297 8208270455 8208270534 8208300113 8208300158	50-321 B 50-366 B 50-366 B 50-321 B
MORTON, K V, NOTT, W E OWER, H W OWRY, W, R NWRY, W R	8208310531* 8208250367* 8208070077* 8208260061 8208260069*	CONTRACT FOIA 70-2174 XPORTLIC XPORTLIC	NAPUDA, G Napuda, G Napuda, G. Narbut, P. P. Nardacci, G. A	8208020377* 8208230386* 8208300068* 8208160208* 8208100278*	50-289 G 50-387 G 50-245 G 50-460 G 50-289 R	NIXON'M V NIXON'M V NIX'H C	8208300173 8208300230 8208300344 8208090295* 8208190029	50-321

AUTHOR	ACCEBSION NUMBER	BUBJECT CATEGOR	Įγ	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	ROHTUA	ACCEBSION NUMBER	CATEGO
NORDERHAUG, L NORDERHAUG, L NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R.	8208030143 8208030162 8208030504 8208100267 8208230117	50-27 70-600 50-139 50-267 XPORTLIC	G G G	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8208160078 8208160081 8208160133 8208160166 8208160223	50-324 P 70-143 50-324 Q 50-324 P 70-143	PACE,P L PACE,P L PACE,P L PACE,P L PACE,P L PACE,P L	B208020416* B208030461* B208050252* B208070237* B208160517*	50-335 50-335 50-335 50-335 50-335
NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R	6208230124* 6208230320 8208270360 8208270363* 8208270413	XPDRTLIC 50-326 70-25 70-25 70-734	a	O'REILLY, J P O'REILLY, J P O'REILLY, J P, O'REILLY, J P D'REILLY, J P	8208160286 8208160362 8208160363* 8208160405 8208160473	50-302 P 50-335 G 50-261 G 50-261 G 50-327 F	PACE,P L PACE,P.L PACE,P L PACE,P L PACE,P L	8208200125* 8208200146* 8208200175* 8208300323* 8208300337*	50-250 50-251 50-335 50-335 50-335
NORDIN.J NORELIUB.C E NORELIUB.C E NORELIUB.C E NORELIUB.C E	9208260046 8208070071 9208070074* 8208070130 8208070173	NUREQ 50-454 50-454 50-295 50-483	Q Q Q	D. LOOTE' A D. WEILTA' O D. WEI	8208160486 8208160508 8208160517 8208260007* 8208160004	State Prog 50-416 P 50-324 Q 50-438 G 50-247 S	PACE, P. L. PACKARD, A. PADOVAN, H. L. PAGE, M. PAGE, M.	8208300348* 8208250070* 8208240326* 8208050078 8208310004	50-335 CONTRAC 50-312 CONTRAC CONTRAC
NORELIUB.C E NORELIUB.C E NORELIUB.C E NORELIUB.C E NORELIUB.C E	8208100204 8208100252 8208100257* 8208200107 8208230148	50-155 50-249 50-249 50-346 50-483	G G G	0.100Fe' A D 0.100Fe' A D 0.100Fe' A D 0.100Fe' A D	8208180077 8208020073 8208020229 8208030217 8208030728*	50-247 G 50-3 F 50-247 S 50-3 F	PAGE, R. O PAGE, R. O PAGE, R. O PAGE, R. O. PAGE, R. O	8208020428 8208050175 8208060022 8208070271 8208110072	70-293/ 70-2884 70-33 40-8027 70-1151
NORELIUB, C E NORELIUB, C E NORRHOLM, J NORRICK, O NORRIS, H R	8208270308 8208270311* 8208300317* 8208300261 8208130016*	50-341 50-341 50-272 PR 50-261	G G R	0.100Fe' 7 D 0.100Fe' 7 D 0.100Fe' 7 D 0.100Fe' 7 D 0.100Fe' 7 D	8208050217 8208120237# 8208130276 8208160012 8208160407	50-247 5 50-247 Q 50-247 Q 50-247 P 50-247 P	Page, R. O Page, R. O Page, R. O. Page, R. O Page, R. O	8208190035 8208190037 8208250151* 8208250249* 8208250304*	70-149 40-8724 40-86 40-86 40-86
NORRIE, J F NORRY, P, Q NORRY, P Q NORRY, P Q NORRY, P, Q	8208030445* 8208060338 8208170041 8208230406 8208240010	50-269 Org Org Org Org	8	0'TOOLE, J D 0'TOOLE, J D 0'TOOLE, J D 0'TOOLE, J D 0'TOOLE, J, D	8208200271 8208230232 8208230238* 8208230282 8208230341	50-247 P 50-247 P 50-247 P 50-247 G 50-247 G	Pade, R. O Pade, R. O Pade, R. O Paine, W. J Paine, W. J	8208240081 8208240419 8208270002 8208050337* 8208050524*	70-125; 70-143 40-802; 50-309 50-309
NORRY, P. O NORRY, P. O NORTH, H. S. NORTON, B. NORTON, B.	8208240039 8208310015 8208160475* 8208190139 8208190139	ORG ORG 50-275 50-275 50-275	G G	0'TOOLE, J D 0'TOOLE, J D 0'TOOLE, J D, 0'TOOLE, J D, OBERG, C R.	8208240248 8208270012# 8208270590# 8208310178 8208200054#	50-247 R 50-3 R 50-3 F 50-247 S 50-478 Q	PAINE, W. J PALENT, V. PALLADING, N. J. PALLADING, N. J PALLADING, N. J	8208090074* 8208120219* 8206130070 8206200094 8206200095	50-309 50-409 50-358 COMMISS COMMISS
NOVAK, T NOVAK, T, M NOVAK, T, M NOVAK, T, M NOVAK, T, M	8208070011 8208030072 8208030670 8208030741 8208040052	50-440 50-324 50-324 50-312 50-302	E P P P	DDEGAARDEN, R. H ODEGAARDEN, R. H. ODEGAARDEN, R. H. ODEGAARDEN, R. H. ODEGAARDEN, R. H.	8010280028* 8208310442* 8208310448* 8208310453* 8208310457*	71-6678 71-6678 71-6678 71-6678 71-6678	PALLADING, N. J. PALLADING, N. J. PALLADING, N. J. PALMER, G. PALMER, R. A	8206200098 8206200079 8206200100 8208030744# 8208030362#	COMMISS COMMISS COMMISS 50-537 50-315
NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8209040051 • 8209040078 8209050066 8209070328 8209130327	50-287 50-338 50-254 50-312 50-522	H P O A	CEHLBERG, R. OFFORD, J. C COLE, K M COLEBBY, D. A. OLIVER, D. D	8208040138 8208260077* 8208240022 8208110267* 8208040166*	NUREQ CONTRACT 40-8714 50-275 F 50-367 P	PALMER, R. A. PALMER, R. A PALMER, R. A. PALMER, R. A. PALMER, R. A.	8208100342* 8208100347* 8208160007* 8208230223* 8208270334*	50-315 50-315 50-315 50-315 50-316
NOVAK, T. H NOVAK, T. H. NOVAK, T. H NOVAK, T. H NOVAK, T. H	6209170013 8209170343 8209170076 8209230145 8209240152	50-327 50-329 50-289 50-349 50-327	P P P	OLLER, R E OLLER, R. E OLLER, R. E OLSEN, A. F. OLSHINSKI, J A	8208160413* 8208200064* 8208310124* 8208060217 8208030669*	GA999 GA999 GA999 50-99 J	PALMER, R. A. PALMER, R. A. PALMER, R. A. PALOWITCH, B. L PANO, F	8208270379# 8208270384# 8208310365# 8207280263# 8208230124#	50-315 50-316 50-316 TOPREP XPORTL
NOVAK, T. M NOVAK, T. M. NOVAK, T. M NOVAK, T. M NOVAK, T. M.	8209240394 6208240481 6208240504 6208270594 6208270402	50-361 50-413 50-369 50-369 50-413	P D P P	OLBHINGKI, J. A OPEKA, J F OPEKA, J F OPREA, O W. OPREA, O W	8208240424 8208240384 8208240384 820803021 9 8208030246	50-395 8 50-213 P 50-213 P 50-498 8 50-498 8	Fanoburn, o c Pantell, 8 e Panter, H. R. Paolino, R. Paolino, R. J.	8208190091 8208260536 8208310465* 8208100333* 8208100032*	WARTE 40-840 71-669 50-220 50-352
NOVAK, T. M NOVAK, T. M. NOVAK, T. M NOVAK, T. M NUBBBAUMER, D.	8208270608 8208270682 8208310475 8208310478 8208250321*	50-443 50-329 50-329 50-329 40-84	E A E E	OPREA, O, H. OPREA, O, W OPREA, O, W OPREA, G W OPREA, G, W	8208030542 8208050447 8208050454* 8208160460 8208170110	50-498 8 50-498 A 50-498 A 50-498 B 50-498 S	PAOLINO,R.J PAPAY,L.T. PAPAY,L.T. PAPAY,L.T PAPAY,L.T	8208300280* 8208030204 8208030337 8208050434 8208240203*	50-410 50-362 50-362 50-362 50-266
NUSSEAUMER, D. NUSSEAUMER, D. NUSSEAUMER, D. NUSSEAUMER, D. A. NUSSEAUMER, D. A.	8208250343* 8208250359* 8208250349* 8208250313* 8208250317*	40-86 40-86 40-86 40-86 40-86		OPREA, O. W. OPREA, O. W OPREA, O. W. ORDERB, W. ORDERB, W	8208270423 8208270454 8208310063 8208030557* 8208160202*	50-498 8 50-498 8 50-498 8 50-269 0 50-269 0	PAPAY, L. T PAPERIELLO, C, J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C, J.	8208270536* 8208130334 8208200202 8208200226* 8208230328	50-341 50-346 50-255 50-315 50-254
NUBBBAUMER, D. A. NUTT, W. T. NYBTROM, J. B. O'BLOCK, V. S. O'BRIEN, J.	8208310432* 8208170168* 8208170160* 8208170107 8208240286*	50-438 50-537	P A T G	ORDERB, W. T ORDERB, M. T. ORNSYEIN, H L ORNSYEIN, H L OBETEK, D J.	8208310463# 8208310467# 8208260403# 6208270697# 8208030109	71~6678 71~6678 50~206 P 50~206 P REB	Paperiello, C J Paperiello, C, J, Paperiello, C, J, Paperiello, C, J Paperiello, C, J,	8208270391 8208270523 8208270552 8208310235 8208310336	50-331 50-254 40-760 50-346 50-254
O'CONNER, P. O'CONNOR, B. O'CONNOR, P. O'CONNOR, P. W. O'NEILL, B.	8208270468 8208130086* 8208240398 8208250147 8208160483*	50+346 50-237 50-237	P B P Q	DBOODD, N L OTTO, D. L OWCA, W. A OWCZARBKI, P. G. OWEN, T. B	8208040630 8208020368 8208110008 8208190360 8208190422*	40-2061 50-537 H RES REB 50-269 F	Paperiello, C. J. Pardes, H. Paris, O. H. Paris, C. H Faris, O. H.	8208310405 8208260585* 8208110079 8208110073 8208180121	50-255 50-269 50-247 50-155 50-142
O'REILLY, J. P. O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P. O'REILLY, J. P.	8103250402* 8208030484* 8208030474* 8208030546* 8208030561*	50-338 50-338 50-280	8 G G G	OWSLEY, O.F. OWSLEY, O.F. OWSLEY, O.F OWSLEY, O.F.	8208100158 8208100285 8208120030 8208120080 8208120087*	TOPREP TOPREP TOPREP TOPREP TOPREP	PARKER, R. D PARKER, W. G. PARKER, W. D. PARKER, W. O. PARKER, W. O.	8208300314 8208020075 8208020079 8208020087 8208020121	PRM 50-365 50-265 50-365 50-365
O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P	8208030615 8208030626* 8208030679* 8208060125 8208060139*	50-280 50-400 50-325	0 0 0 0	OWBLEY, O. F PACE, P. PACE, P. PACE, P. L. PACE, P. L.	8208120078 8208120181* 8208120186* 8208020135* 8208020180*	TOPREP 50-250 & 50-250 & 50-250 & 50-251 &	PARKER, H. O PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	8208020144 8208020160 8208020168 8208020303 8208030073*	50-365 50-265 50-265 50-265 50-365

ĺ

AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT
PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8208030211 8208030220 8208030223 8208030242 8208030277	50-369 8 50-370 8 50-269 P 50-413 6 50-287 8	PAVIS.0 S PAVIS.0 S PAVIS.0 S PECK.C C PEDERSON,L T	8208100208* 8208160148* 8208260244* 8208300114* 8208130475	50-318 8 50-318 8 50-316 8	PILANT.J M PILAT.J M PILANT.J M PILANT.J M PILANT.J M	8208140297 6208200088 6208240438* 6208270340 6208310384	50-298 P 50-298 P 50-298 P 50-298 P
PARKER, W O	8208030357	50-413 F	PEDIGO, 8	8208230297*	50-249 9	PITTMAN, J	8208040281	NUREQ
PARKER, W O	8208030458	50-369 P	PEEDLES, T A	8208030367*	50-348 0	PLAYTON, S J	8208040614*	40-8745
PARKER, W O	8208030460	50-269 S	PEERY, W W	8208030610*	50-259 0	PLIML, G	8208110256*	50-275 F
PARKER, W O	8208030524	50-413 A	PEERY, H W	8208160214*	50-395 0	PLIML, G	8208110263*	50-275 F
PARKER, W O	8208030541	50-269 P	PEET, H K	8208020338	50-537 H	PLUMLEE, K E	8208310486*	50-219 Q
PARKER, W O	8208030551*	50-369 P	PELTD, P J	8208130475	NUREQ	POCHAL,W F,	8208030722	XPORTLIC
PARKER, W O	8208030572		PERCH, R L	8208040516	50-387 P	POCHAL,W F	8208130017	XPORTLIC
PARKER, W O	8208030609*		PERCH, R L	8208260530	50-387 P	PODGETT,J A	8208300192	PR
PARKER, W O	8208040169		PEREZ, O	8208160422*	50-362 Q	POHLE,J A	8208030011	40-8684
PARKER, W O	8208050197		PERKINS, R W	8208260564*	WASTE MOT	POINDEXTER.C	8208120272#	50-317 G
PARKER, W O. PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8208050244 8208090232 8208100191 8208120271 8208160196	50-369 S 50-369 S 50-413 F 50-270 S 50-369 Q	PERKINS,T J PERLIS,R G PERLIS,R G PERLMAN,J PERLMAN,J	8208240051 8208030179 8208040104 8208020449 8208040548	50-220 P 50-483 0 50-483 G CONTRACT CONTRACT	POLK, P J POLK, P J POLLOCK, M S POLLOCK, M S POSAKONY, G J	8208030488 8208250012 8208230135# 8208180232	50-220 P 50-333 P 50-322 A 50-322 G NUREG
PARKER, W O	8208160201	50-369 Q	PERLMAN, J	8208240049	CONTRACT	POBNER, P	8208020281	50-247 0
PARKER, W O	8208160207	50-369 Q	PERNY. C	8208100274*	50-324 G	POSNER, P	8208030348	50-247 0
PARKER, W O	8208160270*	50-370 Q	PERNY. C D	8208100235*	50-261 G	POBTMA, F R	8208040369	50-537 H
PARKER, W O	8208160290*	50-413 Q	PERNY, C D	8208240241	50-261 B	POTAPOVB, U	8208020095	GA999
PARKER, W O	8208160291	50-269 Q	PERSON, R T	8208030379	50-537 H	POTAPOVB, U	8208020125	GA999
PARKER, W. D	8208160368*	50-369 Q	PEBCHEL, J. M	8208090097*	50-456 Q	POTAPOVB, U	8208020136*	QA777
PARKER, W. D	8208260430*	50-269 F	PETERB. E	8208040067*	50-287 H	POTAPOVS, U	8208030445	QA777
PARKER, W. O	8208270597*	50-369 R	PETERB. M D	8208040034	RES	POTAPOVS, U	8208050172	QA777
PARKER, W. O	8208270603*	50-269 R	PETERBEN. H E	8208310193	50-285 J	POTAPOVS, U	8208050172	QA777
PARKER, W. O	8208270607*	50-369 R	PETERBEN. J C	8208230067*	50-454 Q	POTAPOVS, U	8208160187	QA777
PARKER,W O	8208310076	50-287 8	PETERSON, D A PETERSON, D A PETERSON, R K PETRICK, N A PETRONE, C, D	8208130273*	50-255 R	POTAPOVB, U	8208160217	QA999
PARRISH,R A	8208260487	50-373 0		8208130274*	50-255 R	POTAPOVB, U	8208160295	QA999
PARSONS,R M	8208140336#	50-400 0		8208100374*	COMMISSION	POTAPOVB, U	8208160359	QA999
PARVIS,G S	8208090083#	50-317 8		8208100061	50-482 A	POTAPOVB, U	8208160385	QA999
PASTERNAK,R J	8208260539	50-333 6		8208120104*	50-244 G	POTAPOVB, U	8208160403	QA999
PATVA,M J	8208020089*	50-325 8	PETRONE,F P	8208100039*	50-247 F	POTAPOVS, U	8208170177	0A777
PATVA,M J	8208020107*	50-325 8	PETRONE,F P	8208100155*	50-286 F	POTAPOVS, U	8208170202	GA777
PATVA,M J	8208020110*	50-324 8	PETTENGILL,H J	8208030121	40-8584	POTAPOVS, U	8208170210*	GA777
PATVA,M J	8208020386*	50-325 8	PETTENGILL,H J	8208040070	40-1162	POTAPOVS, U	8208190100	GA777
PATVA,M J	8208050124*	50-325 8	PETTENGILL,H J	8208040079	40-2259	POTAPOVS, U	8208190202	GA777
PASTVA, H J	8208070128*	50-325 8	PETTENGILL, H J	8208060348	40-3453	POTAPOVB, U,	8208170203	9A777
PASTVA, H J	8208070170*	50-324 8	PETTENGILL, H J	8208110009	40-3453	POTAPOVB, U	8208170247	9A777
PASTVA, M J.	8208070218*	50-325 8	PETTENGILL, H J	8208170241*	40-8102	POTAPOVB, U	8208170250	9A777
PASTVA, H J	8208120013*	50-324 8	PETTENGILL, H J	8208260589	40-8452	POTAPOVB, U	8208170255	9A777
PASTVA, H J	8208120022*	50-325 8	PETTIOREW, H	8208170023*	71-9086	'POTAPOVS, U	8208170260	9A777
PASTVA, H J PASTVA, H J PASTVA, H J PASTVA, H J PASTVA, H J	8208120082* 8208120146* 8208130286* 8208130317* 8208200019*	50-325 6 50-324 8 50-325 8 50-325 8	PETTIONEW, M PETTIONEW, M PETTY, J C PEVEAR, R C PEVENSTEIN, J E	8208170052* 6208170053* 6208270407* 6208130326 6208230451*	71-9151 71-9151 50-270 6 50-443 F CONTRACT	POTAPOVB. U POTAPOVB. U POTAPOVB. U POTAPOVB. U POTAPOVB. U	8208170281 8208170282 8208170277 8208200055 8208240211	0A777 9A777 QA777 QA777 QA777
PASTVA, H. J	8208200068*	50-324 B	PEWITT,E Q	8208040267	71-6601	POTAPOVB, U	8208310114	GA799
PASTVA, H. J	8208200089*	50-325 8	PFEFFERLEN,H C	8208170252*	50-387 P	POTAPOVB, U	8208310119	GA799
PASTVA, M. J	8208200264*	50-324 8	PFEFFERLEN,H C	8208240289	50-271 P	POTAPOVB, U	8208310128	GA799
PASTVA, H. J	8208200288*	50-324 8	PFEFFERLEN,H C	8208310111	TOPREP	POTAPOVB, U	8208310133	GA799
PASTVA, H. J	8208270160*	50-324 8	PFISTER,J	8208270396*	50-528 I	POTAPOVB, U	8208310237	GA799
Pastva, H, J	8208270264*	50-325 8	PFLUM,C.O	8208060128	WASTE MOT	Potapove, u	8208310272	GA777
Pastva, H J	8208270387*	50-325 8	PFLUM,C.O	8208060134*	HASTE MOT	Potapove, u	8208310309	GA777
Pastva, H. J	8208270401*	50-325 8	PHELPS,O B,	8208240414	50-287 Q	Potapove, u	8208310337	GA777
Pastva, H. J	8208270406*	50-325 8	PHILLIP.G A	8208050441*	50-237 Q	Potapove, u	8208310348	GA777
Pastva, H. J	8208270416*	50-325 8	PHILLIPS,B J	8208130400	40-8724	Potapove, u,	8208310361*	GA777
PASTVAIN J	8208270421*	90-324 8	PHILLIPS, H S PHILLIPS, H S PHILLIPS, L E PHILLIPS, M P, PHILPGTTS, D	8208310341#	QA999	POTAPOVB.U	8208310392	QA999
PASTVAIN J,	8208270484*	50-324 8		8208310401#	QA999	POTAPOVB.U	8208310449	QA999
PASTVAIN J	8208270499*	50-324 8		8208110209#	50-289 Q	POTENT.V	8208170100*	50-409 P
PASTVAIN J	8208270542*	50-325 8		8208270395#	50-331 Q	POTTER.A J	8208030491	REGOD
PASTVAIN J	8208300091*	50-324 9		8208060047#	50-321 F	POTTER.S B	8207070036	71-478
PASTVA.H J PATEL.B.A PATRINGS.A PATTERSON.J.P PATTERSON.J.P.	8208300343* 8208240394* 8208260406 8208130337* 8208270142*	50-325 E 50-528 G NUREQ 50-346 Q 50-10 G	PICHA,K, PIEHL,R,H, PIEHL,R,H PIEHL,R,H	8208160253 8208030209* 8208050372* 8208230068* 8208120177	RE00D 50-316 8 50-316 8 50-316 8 50-537 H	POULK,R M POULK,R M POUELL,D G, POWELL,L F	8208300110* 8208300147* 8208300244* 8208020352 8208110169	50-324 B 50-324 B 50-325 B 50-522 H 50-322 Q
PATTERSON, J. P. PATTERSON, J. P. PATTERSON, Y. PAULK, R. PAULK, O. L.	8208270395* 8208270527* 8208120220 8208100299* 8208160408*	50-331 Q 50-254 Q 50-537 H 50-10 Q 50-259 Q	PIETRZAK, R, PIGOTT, D. R PIGOTT, D. R. PIGOTT, D. R. PIGOTT, D. R.	8208260466 8208050482 8208050482 8208110156 8208110156	NUREQ 50-204 Q 50-206 Q 50-361 Q 50-361 Q	POWELL, 1. F PRENDERGABT, W PRESENT, A PRESTHOLT, P T PRESTHOLT, P T	8208110169 8207050072 8208040134* 8208170370 8208170371*	50-322 0 FOIA BO-537 D WABTE MOT WABTE MOT
PAULK, CL	8208160521*	50-259 Q	PIGOTT, D R	8208110154	50-361 Q	PREUBB; M	8208260017	50-254 B
PAULKOL	8208160528*	50-259 Q	PIGOTT, D R	8208110154	50-361 Q	PRICE, A L		40-84
PAULBON, W	8208170005	50-206 P	PIGOTT, D, R	8208110154	50-361 Q	PRICE, H E		NUREQ
PAULBON, H, A	8208310013	50-206 P	PIJAWKA, K D	8208060357	50-277 P	PRICE, H, E		NUREQ
PAULBON, H, A	8208310233	50-206 P	PIJAWKA, K D	8208050014	50-335 P	PRICE, W J		50-317 B
Pavis, 0 s. Pavis, 0. s Pavis, 0. s Pavis, 0. s Pavis, 0. s	8208090045* 8208090068* 8208090227* 8208100057* 8208100105*	50-317 8 50-317 8 50-317 8 50-317 8 50-317 8	PIJAWKA, K D PIJAWKA, K D PIJAWKA, K D PILANT, J, M PILANT, J M	8208070021 8208130473 8208170010 8208020104 8208020124	50-313 P NUREO 50-323 A 50-278 I 50-278 P	PRICE, W J PRICHARD, R. P PROBPECT, W PUCKETT, M PULLANI, S.	8205060412# 8208030557#	50-318 8 71-6574 50-322 H 50-269 0 50-387 0

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PULLANI, B U PURPLE, R A PURPLE, R A PURPLE, R A GUICK, D R	8208100100*	50-387 Q	RAY,H B	8208100050*	50-361 S	REEDY, R F	8208180108	50-275 R
	8208040427	50-389 A	RAY,H B	8208100297	50-361 S	REGAN, W H	8208040552	50-522 D
	8208040324	50-341 A	RAY,H B	8208100303*	50-361 S	REHFUS. R	8207120047	50-443 D
	8208250050*	50-309 F	RAY,H B	8208120122	50-361 R	REHM, T A	8208060362	COMMISSION
	8208030244*	50-438 Q	RAY,H B	8208120147	50-206 R	REIS, H F	8208170381	27-47
GUICK, D R	8208030425*	50-390 Q	RAY,H B	8208120180	50-206 8	REIB.H F	8208170383*	27-47
GUICK, D R	8208160224*	50-438 Q	RAY,H B	8208120182*	50-206 8	REIB.H F	8208170385	27-47
GUICK, D R	8208160282*	50-438 Q	RAY,H B	8208120285	50-361 8	REITER.L	8208200173*	50-409 0
RADER, R M	8208160066	50-352 Q	RAY,H B	8208160149	50-361 8	REMITO.W A	8208160063*	50-317 0
RADER, R M	8208160066	50-352 Q	RAY,H B	8208160153*	50-361 6	REMICK.F J	8208160001	50-537 0
RADER,R M	8208200134	50-416 G	RAY,H B	8208160288	50-205 0	REMICK, F J	8208170125	50-237 Q
RADER,R M	8208200134	50-416 G	RAY,H B	8208170250	50-205 R	REPKA, D. A	8208040017	50-322 Q
RAFFETY,B J	8208200083*	50-409 B	RAY,H B	8208180024	50-361 8	REPKA, D. A	8208250300	50-322 Q
RAFI,A	8208310036*	50-317 B	RAY,H B	8208180031*	50-361 8	REVELEY, T	8208200143*	50-322 Q
RAHE,E P	8207280254	TOPREP	RAY,H B	8208180076	50-206 8	REYES, L.	8208050521*	50-262 Q
RAHE, E, P	8207300360	TOPRCP	RAY,H B	8208200018	50-361 8	REYES, L	8208100123	50-346 B
RAHE, E P	8208020063	TOPREP	RAY,H B	8208200029*	50-361 8	REYES, L	8208230313*	50-331 Q
RAHE, E P	8208030177	TOPREP	RAY,H B	8208200145	50-361 8	REYES, L	8208300274*	50-407 Q
RAHE, E P	8208030564	TOPREP	RAY,H B	8208200152*	50-361 8	REYES, L. A	8208230176*	50-263 Q
RAME, E P	8208030567*	TOPREP	RAY,H B	8208200182	50-361 8	REYES, L. A	8208330121*	50-331 Q
RAHE, E P	8208030573*	TOPREP	RAY,H B	8208200204*	50-341 8	REYROLDS, J R REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R	8208300309*	50-346 G
RAHE, E P	8208030578*	TOPREP	RAY,H B	8208200213*	50-341 8		8208050338	50-275 Q
RAHE, E P	8208030583*	TOPREP	RAY,H B	8208200221*	50-341 8		8208050338	50-275 Q
RAHE, E P	8208030588*	TOPREP	RAY,H B	8208200230*	50-341 8		8208200250	50-275 Q
RAHE, E P	8208170162	TOPREP	RAY,H B	8208200231	50-204 8		8208200250	50-275 Q
RAHE,E P RAHE,E P RAHE,E P RAHE,E P RAHE,E P.	8208170233 8208200051 8208200215 8208240371 8208240255	TOPREP PT21 TOPREP TOPREP TOPREP	RAY,H B RAY,H B RAY,H B RAY,H B	8208200236* 6208200242* 6208200248* 6208200251 8208200256*	50-361 8 50-206 8 50-361 8 50-361 8 50-361 8	REVIOLDE, J. R. REVIOLDE, J. W. REVIOLDE, J. W	8208200262 8208200262 8208020267* 8208020304* 8208020360*	50~275 Q 50~275 Q 50~255 P 50~255 P 50~255 P
RAHE, E P	8208300277	PR	RAY,H B	8208200268*	50-361 8	REYNOLDS, N B	8208170144	50-445 Q
RAHE, E P	8208310302	TOPREP	RAY,H B'	8208200269*	50-361 8		8208170144	50-445 Q
RAHE, E P	8208310417	TOPREP	RAY,H B.	8208200279	50-361 8		8208250333	50-445 Q
RAIDY, T	8208120152*	50-206 R	RAY,H B	8208200270*	50-361 8		8208250333	50-445 Q
RAMOINO, T	8208020358	50-537 H	RAY,H B	8208270582*	50-266 8		8208230473*	50-277 Q
RAMOB, B	8208200228*	50-315 G	RAY.H D	8208300030	50-361 B	RHOADE, Q Q	8208300258*	50-387
RANDAZZA, J B	8208100005	50-309 G	RAY.H B	8208300032*	50-361 B	RHODE, Q. K.	8208050237	
RANDAZZA, J B	8208240392*	50-309 G	RAY.H D	8208300037	50-361 B	RHODE, Q K	8208100040	
RANDOLPH, M L	8208040629	RES	RAY.H B	8208300039*	50-361 B	RIAT, D.	8208160335*	
RANEY, E C	8208100278*	50-289 R	RAY.H B	8208300057	50-206 B	RIAZ, M	8208240376*	
RANBOM, C B	8208170354	50-313 P	RAY,H B	8208300058*	50-204 B	RICE,D A	8208230074*	50-29 6
Rapkin, A	8207180028	40-2041	RAY,H B	8208300071	50-341 B	RICHARDS,B L	8208030485*	70-149
Rapkin, A	8208130332	40-2041	RAY,H B.	8208300072*	50-341 B	RICHARDS,B C	8208100333*	50-220 9
Rapkin, A	8208130391	40-2041	RAY,H B	8208300087	50-204 B	RICHARDS,B	8208300280*	50-410 9
Ratta, A D	8208170077*	70-184	RAY,H B	8208300087*	50-204 B	RICHARDS,B A	8208100032*	50-352 9
RATTA, A D	8208230302*	50-387 @	RAY, HB.	8208300155	50-361 B	RICHARDBON, H. D	8208180261*	CONTRACT
RAUL, S I	8208020061	RES	RAY, HB	8208300156*	50-361 S	RICHARDBON, J D	8208190277*	50-416 R
RAUSCH, T J	8208060268	50-237 P	RAY, HB	8208300189*	50-361 B	RICKER, R M	8208020358	50-537 H
RAUSCH, T J	8208170085	50-249 P	RAYBURN, CL	8208240491*	50-317 S	RIDENGUR, G F.	8208020358	50-537 H
RAUSCH, T J	8208200137	50-254 F	RAYNOR, J	8208090048*	50-317 S	RIDDE, R. H	8208110225*	50-331 F
RAUBCH, T J RAUBCH, T J RAUBCH, T J RAUBCH, T J RAUBCH, T J	8208230107 8208230349 8208230352 8208270250 8208270296	50-237 F 50-237 G 50-237 P 50-254 P 50-249 P	RAYNOR, J RAYNOR, J W RAYNOR, J W RAZLAFF, W J READ, D F	8208090083* 8208230087* 8208230178* 8208110222* 8208030318	50-317 8 50-318 8 50-317 8 50-331 F 50-537 0	RIDOWAY, D.A. RIDOWAY, D.A. RIDOWAY, D.A. RIDOWAY, D.A. RIDOWAY, D.A.	8208110180 8208110180 8208270411 8208270411 8208270486	50-266 0 50-266 0 50-266 0 50-266 0
RAUSCH.T J RAUSCH.T J RAWERS,J C RAWSON,R J RAWSON,R J	8208270559* 8208310230 8208040260* 8208120011 8208170277	50-10 R 50-237 P 90-382 A 50-416 0 50-454 G	READ.D F REAVIS.J A REAVIS.J.A REBELLO.J E	8208050535 8208300214 8208170091* 8208170195* 8208030735*	50-400 C PRM 50-269 R 50-369 R CONTRACT	RIDGWAY, D A. RIDGWAY, D A. RIGGLE, E I RIVKIN, W B. RIZZO, P G.	8208270484 8208270503 8208130258* 8208300246 8208100048*	50-266 0 50-266 0 50-219 9 RECOD 50-317 9
RAWSON,R J RAWSON,R J RAY,H B RAY,H B RAY,H B	8208230070 8208270270 8208020203 8208020206* 8208020212*	50-454	REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	8208060025* 8208170420* 8208180261* 8208180269* 8208190028*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	R1220, P 0 R1220, P 0 R1220, P 0 R1220, P 0 R0BAK, D	6206240474* 6206250373* 6206310026* 6206310502 6206040373	50-317 8 50-317 8 50-318 8 50-318 8 50-337 H
RAY, H D	8208020216*	50-341 8	REBELLO, J. E	8208190099*	CONTRACT	ROBERDS.H W	8208160227*	9A777
RAY, H B	8208020219*	50-361 5	REDELLO, J E	8208230024*	CONTRACT	ROBERDS.M.J	8208050139*	50-458 G
RAY, H B	8208020253	50-341 6	REDELLO, J E	8208230462*	CONTRACT	ROBERBON.D.A.	8208050286	50-537 H
RAY, H B	8208020306	50-341 8	REDELLO, J E.	8208230070*	CONTRACT	ROBERTS.B	8208020409	ACRS
RAY, H B	8208020314*	50-361 8	REDELLO, J E	8208250101*	CONTRACT	ROBERTS.C.H	8208200168*	50-341 A
RAY, H. B RAY, H B RAY, H B RAY, H B RAY, H B	8208020322* 8208020324 8208020329* 8208020334* 8208020339*	50-341 B 50-204 6 50-204 B 50-341 S 50-341 S	REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	8208260250* 8208260467* 8208300204* 8208310456* 8208310500*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	Roderte, H W Roderte, H A Roderte, H. A. Robinson, D. Robinson, D	8208140372* 8208020113* 8208050457* 8208100244* 8208100265*	0A999 50-259 8 50-259 8 50-373 0 50-249 0
RAY, H B.	8208020350	50-341 B	REBELLO, J E	8208310526*	CONTRACT	ROBINSON, L M	8208040373	50-537 H
RAY, H B	8208020366*	50-341 B	REBELOWSKI, T.	8208300046*	50-247 0	ROCHINO, A F.	8208200021	GEN TEC IS
RAY, H B	8208020393	50-341 B	REDANO, R T	8208170241*	50-458 0	ROCHINO, A F.	8208200021	GEN TEC IS
RAY, H B.	8208020395*	50-341 B	REDANO, R T	8208170274*	50-482 0	ROCKHOLD, H C	8208040010	RES
RAY, H, B	8208020414	50-341 B	REDMOND, R. F	8208060353*	CONTRACT	RODRIGUEZ, R. J.	8208190265	50-312 R
RAY,H B	8208020417*	50-341 B	REED.C	8208130030	90-373 8	RDEDER, J. R.	8208250373*	FDIA
RAY,H B	6208070211	50-341 B	REED.D F	8208300314	PRM	ROGERS, D. W	8207120253*	50-447 A
RAY,H B	6208070216*	50-341 B	REED.J Q	8208240261	90-483 0	ROGERS, H. R.	8208310045	50-255 B
RAY,H B	6208070233	50-341 B	REED.M.	8208130229*	90-265 B	ROGERS, H. R.	8207150422*	50-327 B
RAY,H B	6208100043	50-341 B	REEDY.R F	8208030376	90-275 R	ROGERS, H. R	8208020147*	50-328 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT Category
ROGERS, H R ROGERS, H R ROGERS, H R ROGERS, H R ROGERS, P.	8208050111* 8208050333* 8208050342* 8208050417* 8208050265*	50-327 S 50-327 B 50-327 B	RUSBELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	8208070064 8208070074 8208070080 8208070110 8208070221	50-317 8 50-317 8 50-317 8 50-317 8 50-317 8	SCHROEDER, B A SCHROEDER, B A SCHROEDER, B A SCHROEDER, C W SCHROEDER, C W	8208170245* 8208230030* 8208230259* 8208040095	50-10 R 50-237 S 50-237 S 50-373 P 50-373 P
RDOERS, P ROOERS, P ROOERS, P ROOERS, P. ROOERS, P.	8208050334* 8208100121* 8208270284* 8208270305* 8208310102*	50-313 8 50-313 8 50-319 8 50-368 \$ 50-319 8	RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	8208070252 8208100041 8208100064 8208100077 8208100177	50-318 B 50-317 B 50-317 S 50-317 B 50-318 B	SCHROEDER.C W SCHROEDER.C W SCHROEDER.C W SCHROEDER.C W SCHROEDER.C W	8208040199 8208130304 8208140140* 8208170223 8208240224	50-373 P 50-373 P 50-373 Q 50-373 P
RDGERS, R. F	9208030397*	50-321 Q	RUSSELL, L B	8208130020	50-317 8	SCHROEDER, C W	8208240340	50-373 P
RDGERG, S C.	9208240438	NUREQ	RUSSELL, L B	8208130275	50-318 8	SCHROEDER, C W	8208240374	50-373 P
RDGERG, W	9208100123	50-346 8	RUSSELL, L B	8208160145	50-318 8	SCHROEDER, C W	8208260165	50-373 P
ROGERG, W.	8208300309*	50-346 Q	RUSSELL, L B	8208230080	50-318 8	SCHROEDER, C W	8208300182	50-373 P
ROGERS, W. H	8208040057*	50-321 F	RUSSELL, L B	8208230175	50-317 6	SCHROEDER, C W	8208310040	50-373 S
ROGERS, W, H	8208110249*	50-321 F	RUSSELL, L D	8208240488	50-317 B	SCHROEDER.C W	8208310301	50-373 P
ROGOE, J, F	8208100189	50-346 B	RUSSELL, L D	8208240473	50-317 B	SCHUCHART.J A	8208020368	50-537 H
ROMAN, T W	8208160455*	50-220 R	RUSSELL, L, D	8208250160	50-317 B	SCHUELKE.D A	8208030071*	50-282 F
ROMANO, F, R	8208240361	50-352 G	RUSSELL, L B	8208250370	50-317 S	SCHUELKE.D A	8208270207*	50-282 R
ROMANO, F R,	8208270449	50-352 G	RUSSELL, L B	8208250546	50-317 S	SCHUKAI.R J	8208250318	50-483 Q
ROMINE, W.D. ROMINE, W.D. ROMINE, W.D. ROMINE, W.D. ROMINE, W.D.	8208020379*	50-328 8	RV8SELL, L B	8208260218	50-317 8	SCHULZ.R D	8208230319#	50-410 Q
	8208120315*	50-328 8	RV8SELL, L B	8208260229	50-317 8	SCHUMACHER.M C	8208270557#	40-7604
	8208200108*	50-327 8	RV8SELL, L. B	8208260239	50-318 6	SCHUMACHER.M C	8208310351#	50-254 g
	8208270216*	50-327 8	RV8SELL, L B	8208260476	50-317 8	SCHUSTER.M D	8208030151#	50-27 Q
	8208270304*	50-328 8	RV8SELL, L B	8208300084	50-317 8	SCHUSTER.M D	8208030147#	70-600
ROOD, H	8208030075	50-341 P	RUBSELL,L B	8208310023	50-31B B	SCHUBTER, M D	8208030498*	50-137 Q
ROOD, H.	8208260600	50-341 P	RUSSELL,L B	8208310032	50-317 B	SCHUSTER, M D	8208270425*	70-734
ROONEY, V.	8208060033	TOPREP	RUSSELL,W T	8208200199*	50-409 G	SCHUURMAN, A B	8208030020*	50-275 Q
ROONEY, V L	8208230040*	50-293 P	RUTBERG,J	8208060102	50-52B M	SCHUYLER, J D	8208060207*	50-275 P
ROONEY, V L	8208230046*	50-293 P	RUTZEN,A C	8208250386*	FOIA	SCHUYLER, J O	8208130261*	50-323 A
ROONEY, V. L	6208250410*	50-324 P	RYAN, A.F. RYTKONEN, B.B. RYTKONEN, B.B. SABADOS, J. W. SAKENAB, C.	8208250081*	FDIA	SCHUYLER, J D	8208140178	50-275 3
ROOT, L. D,	6208170092	50-331 P		8208260355*	CONTRACT	SCHWAD, F P	8208020358	50-537 N
ROOT, L. D	6208170243	50-331 H		8208260428*	CONTRACT	SCHWAN, C A	8208030151*	50-27 Q
ROOT, L. D	6208230346	50-331 P		8208030639*	70-1151	SCHWAN, C A	8208030147*	70-600
ROOT, L. D.	6208270505	50-331 P		8208120140*	50-387 G	SCHWAN, C A	8208030498*	50-139 0
ROOT, L. D	9209300170	50-331 P	SALDARINI, J C	8208300178	PRM	BCHWENCER, A	8208030025	50-352 C
ROSAND, R.	9209110105	70-143	SALTZMAN, J	8208070032	50-97 J	SCHWENCER, A	8208030030	50-352 A
ROSAND, R	9208160113	50-206 G	BALTZMAN, J	8208310283*	50-324 P	BCHWENCER, A	820803004	50-352 A
ROBE, J A	9209020060	RES	SANDERB, W F	8208160535*	50-424 Q	BCHWENCER, A	8208030081	50-352 A
ROSENFELD, E S.	9209170174*	50-272 P	SANTORO, M, P	8208050023	71-9006	SCHWENCER, A	8208030087	50-352 A
ROBIER, O A	6208100188	PR	Bappinoton, R	B208120366	NUREQ	Schwencer, a	8208030074	50-352 E
ROBB, B	6208130474	NUREQ	Bargent. I	8208040560*	50-239 P	Schwencer, a	8208040204	50-322 A
ROBB, F W	6208040443	40-8781	Bargent. I H	8208170163*	50-213 P	Schwencer, a	8208040212	50-416 P
ROBB, W J.	8208040453	50-272 P	Barbten. O E	8208190177	50-324 8	Schwencer, a,	8208040341	50-373 P
ROBB, W J.	8208060021	80-272 P	Barbten. O E	8208250190	50-460 S	Schwencer, a	8208040374	50-397 E
ROSSIN, J	8208170054	50-311 P	SARSTEN, O, E SAUNDERS, S. C. SCARAND, R. SCARAND, R SCARAND, R A SCARAND, R A	8208270365	50-324 B	SCHWENCER, A	8208050021	50-322 A
ROSSIIC E	8208110042	50-322 T		8206270086	ACRS	SCHWENCER, A	8208050039	50-352 A
ROSZTOCZYIZ R	8208110207*	50-289 0		8208300353	40-8502	SCHWENCER, A	8208050048	50-458 A
ROTHIJ,	8208100248*	70-371		8207140402	40-8681	SCHWENCER, A	8208050051	50-440 A
ROTHIJ,	8208100243*	70-820		8208030123	40-8786	SCHWENCER, A	8208050180	50-458 A
ROTH, J. ROTH, J ROTH, J ROTH, J ROTHSCHILD, T	8208230041# 8208230184# 8208300250# 8208310476# 8208030311	50-20 Q 70-497 50-223 Q 50-213 Q REVIEW ORP	BCARÁND, R A BCARÁND, R. A, BCARÁND, R A BCARÁND, R A BGÁRÁND, R A	8208030163 8208040359 8208040438 8208110037 8208110082	WASTE MOT 40-8786 40-8674 Waste Mot 40-8348	Schwencer, a Bchwencer, a Bchwencer, a, Bchwencer, a Bchwencer, a	8208070023 8208070022	50-352 F 50-352 A 50-352 A 50-352 A 50-458 U
ROUSE, L. C. ROUSE, L. C ROUSE, L. C. ROUSE, L. C. ROUSE, L. C	8208250458 8208250463* 8208250468* 8208270566 8208270570*	70-1308 70-1308 70-1308 70-687 70-687	BCARANO, R. A BCATEB, R. M BCHAPKER, J. F. BCHEPP, C. E BCHERER, A. E	8208170002 8208050284 8208160161* 8208100234 8208240349	40-8102 50-537 H 50-518 G REVIEW GRP 50-470 E	BCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8208120384 8208120389* 8208130015*	50-440 F 50-414 P 50-414 P 50-416 P 50-458 A
Rowe, C. A. Roy, W Rozak, S. Rubinbtein, R Rudlin, D. A.	8208020278* 8208250182* 8208310351* 8208020358 8208110167	50-277 Q 40-86 50-254 Q 50-537 H 50-322 Q	SCHERER, A, E SCHERER, A. E SCHERER, R. W. SCHESSLER, T E SCHILLER, V.	8208240372 8208300201 8208120134* 8208040349 8208300278	50-470 A PRM 50-321 I 40-8781 PR	8CHWENCER, A. 8CHWENCER, A 8CHWENCER, A 8CHWENCER, A 8CHWENCER, A	8208190025 8208240062 8208240101	50-352 A 50-352 A 50-352 A 50-377 A 50-440 A
RUDLIN, D. A. RUFF, A. B. RUFF, A. B. RUFF, A. B. RUFF, R. E.	8208110167 8208030176+ 8208030616+ 8208160242+ 8208260406	50-322 Q 50-413 Q 50-438 Q 50-400 Q NUREG	SCHMALE, D. T SCHMIDT, A. D SCHMIDT, A. D SCHMIDT, H. C SCHMIDT, H. C	8208240037 8208230345 8208230345 8208030271 8208240219	NUREQ TOPREP TOPREP 50-445 K 50-445 A	BCHWENCER, A BCHWENCER, A BCHWENCER, A SCHWENCER, A BCHWENCER, A	8208250472 8208250512 8208260122	50-352 A 50-397 A 50-416 E 50-352 C 50-352 A
RUITER, C. H RUMPF, R RUNION, T. C. RUNKLE, J. D. RUNNER, W. T.	8208120214* 8208170131* 8208250360* 8208050535 8208020358	50-305 R 50-409 P FDIA 50-400 9 50-537 H	BCHMIDT, H C. SCHMIDT, H C SCHMIDT, H C SCHMIDT, H C SCHMITENDORF, Q. SCHMATZ, T. H.	8208270474* 8208300119 8208310354 8208120150* 8208120189	50-445 Q 50-445 A 50-445 K 50-338 R MIEC	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENK, Q A	8208260477 8208270666 8208310480	50-416 F 50-352 A 50-440 E 50-397 E TOPREP
RUPERT, R. E. RUSHMORE: J. W. RUSSELL, L. B RUSSELL, L. B. RUSSELL, L. B.	9208040373 9208130273 9208020387 9208020388 9208020394	50-537 H 50-220 I 50-317 \$ 50-317 B 50-318 B	ECHNELL, D. F BCHNELL, D. F BCHNELL, D. F. BCHNELL, D. F. BCHNELL, D. F	8208020358 8208070175# 8208160245 8208230158# 8208240132	50-537 H 50-483 Q 50-483 M 50-483 G 50-483 A	SCHWENK, H C SCHWINK, N S. SCINTO, J. SCOTT, D J	8208050198 8208130146 8208160162	50~537 H REVIEW GRP 50~361 9 50~483 9 50~237 B
RUSSELL, L. B.	8208050088	50-317 8	SCHNELL, D F	8208240322	50-486 A	80017, D, J	8208030338	50-249 8
RUSSELL, L. B.	8208050359	50-317 8	BCHNELL, D F,	8208260366*	50-483 F	60017, D J		50-237 8
RUSSELL, L. B.	8208050364	50-317 8	BCHREIBER, O, A,	8208270384*	50-528 I	80017, D. J		50-10 F
RUSSELL, L. B.	8208050389	50-318 8	SCHROCK, C, A	8208130078*	50-305 8	80017, D. J.		50-10 F
RUSSELL, L. B.	820805044	50-317 8	SCHROCER, B	8208310052*	50-247 8	80017, D. J		50-249 P

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J	8208070228 8208070242 8208130052 8208130055 8208130267	50-237 S 50-237 S 50-237 S 50-237 S 50-237 S	SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D	9208100371* 9208200249 9208230376 9208240308 9208240309*	50-317	SHOTWELL.JA SHULTIB.JK SIEBER.JD SIEBER.JD SIEBER.JD	8208160230 8208260097 8208030352 8208130034 8208200069	50-443 Q NUREO 50-334 F 50-334 P 50-334 P
9COTT.D J 9COTT.D J 9COTT.D J 9COTT.D J 9COTT.D J	8208130322 8208170242 8208200053 8208230026 8208230029	50-249 S 50-10 R 50-237 S 50-237 S 50-249 S	SHAMBLIN, D L SHANDAKY, M SHANNON, J, B SHANNON, J B SHANNON, J B	8208170224* 8208160458* 8208060005 8208230435* 8208230437	50-373	SIEFKEN, D SIEFKEN, D L SIEGEL, B L SIEGEL, J	8208170378* 8208040042 8208040302 8208170017 8208030487*	WARTE MOT WARTE MOT 27-39 TOPREP 50-369 P
SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J	8208230292 8208230273 8208230272 8208230390 8208300128	50-237 6 50-249 8 50-249 8 50-249 8 50-237 8	SHAPIRO,R SHAPIRO.R SHAUD,E SHAUD,E T SHAUD,E T	8208240229 8208240229 8208300048* 8208230197* 8208120177	50-322	SICMAN, J SICBERO, J E SICBERO, J E SICBERO, J E	8208030495* 8208030502* 8208090144 8208090144	50-369 P 50-369 P 50-440 Q 50-440 Q
SCOTT, D J SCOTT, D J SCOTT, D J SCOTT, B B	8208310048 8208310072 8208310222 8208310270 8208120076*	50-249 \$ 50-237 \$ 50-249 \$ 50-237 \$ 50-237 \$ 50-275 R	Bhau, a Shau, a Shau, a Shau, r Shea, J	8208040104 8208240347 8208240594 8208300341* 8208050480	XPORTLIC XPORTLIC 71-6678 50-413 I 50-245 P	SILBERO, J E SILBERO, J E SILBERO, J E SILBERO, J E SILBERO, J E	8208090146 8209270460 8208270460 8208270506 8208270506	50-440 0 50-367 0 50-367 0 50-440 0 50-440 0
SCOWN, K SCURRY, N SCURRY, N SCURRY, N SCURRY, N	8208310113* 6208240023 8208240027 8208240031 8208240035	50-275 G DRG DRG ORG 50-289 P	SHEA, J F SHEA, J J. SHEA, K H SHEA, K H SHEALY, H O	6208240227 8208200238 8208040039 8208040039 8208300256	50-322 0 50-245 P 70-820 70-820 PRM	Silling. 6 A Silling. 8 A Silling. 8. A Silling. 6 A Billing. 8 A	8208030114 8208030117* 8208040013 8208040034 8208170045	WASTE HOT WASTE HOT WASTE HOT WASTE HOT
SEDKY, C SEDKY, C SEDKY, C	6208060116 6208060116 6208240229 6208240229 6208240240	50-322	SHELLEY, W J SHELLEY, W J SHELLEY, W J	8208040333 8208040407 8208040634 8208100221 8208240038	HABTE HOT 40-8027 40-8768 70-925 40-2061	SILVERMAN, D J SILVERMAN, D J SILVERSTROM, L SILVERSTROM, L SILVERWOOD, J B	8208170260 8208170260 8208040217 8208110160 8208230373	50-498 0 50-498 0 50-537 0 50-537 0 Toprep
SEDKY, C. SEDKY, C. SEIDLE, W. C SEIDLE, W. C	6208240240 6208240243 6208240243 6208180128 6208020072	50-322 0 50-322 0 50-322 0 50-313 0 50-313 P	SHEPHERD, R E SHERR, T S SHERR, T S SHERR, T S SHERWOOD, O O	82081902804 8209130338 8208250483 8208260377 8208030270	GA999 50-369 P 50-280 P 50-155 P TOPREP	SILVIS, R M SILVIS, R M SIMAN-TOV, M SIMCHUK, J. D SIMKIN, Y	8208040682 8208310527 8207200345 8208020460 8208040089*	CONTRACT CONTRACT RES 71-9159 50-537 D
SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8208020259 8208030224 8208030475 8208050190 8208050247	50-313 F 50-368 8 50-285 Q 50-482 Q 50-313 Q	SHERWOOD, 0 0 SHERWOOD, 0 0 SHERWOOD, 0 0 SHERWOOD, 0, 0 SHERWOOD, 0 0	8208030355 8208030357* 8208030581 8208050268 8208260213	50-447 K 50-447 K 50-447 K PT21 50-416 B	SIMONBIO T. A RENOMMIS BIMONDIM A BIMONDIM, A BIMONDIM A BIMONDIM A	8208020458* 8208180124 8208180237 8208110130 8208310311	50-133 H NUREO NUREO 50-526 R 50-526 R
SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8208050361 8208060147 8208060213 8208100081 8208120165	50-313 8 50-407 Q 50-285 Q 50-313 8 50-285 F	SHERWOOD, O O SHEWMON, P SHEWMON, P SHEWMON, P SHEWMON, P	8208300207 8206270047* 8207180072 8208040467* 8208230274	PRM 50-440 A 50-390 D 50-537 A 50-244 D	BIMONEN, F P BIMONIN, J M BIMCHAIR, J II BINCLAIR, J II	9209130475 9209240064 9209020358 9209270353 9209300078*	NUREO NUREO 50-537 H 50-271 P 50-271 G
SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8209160080 8209160452 8208170231 8208180055 8208180070	50-313 B 50-285 Q 50-252 Q 50-313 Q 50-265 Q	SHEWMON, P SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S, W,	8208230384 8208030282* 8208090063* 8208160212 8208240283	50-416 D 50-546 A 50-546 Q REVIEW GRP 50-546 S	Sinclair, M Sinclair, M Sinclair, M P Sinclair, M P Sincer, B.	8208030213 8208110145* 8208040123 8208120124 8208250201*	REVIEW ORP 50-329 0 50-329 0 50-329 0 40-86
Seidle, W C Seidle, W C Seidle, W C Seidle, W C	8208190088 8208190150 8208190170 8208190213 8208190236	50-313 Q 50-313 F 50-285 F 50-313 Q 50-285 Q	Shields, 9 H Shields, 8 W Shier, W O Shima, 6 Shima, 8,	8208300218 8208310248 8207180485 8208040214 8208270665*	50-546 8 PRM REB XPORTLIC XPORTLIC	SINGER, D SINGER, L R SINGH, H H SINKIN, L BINKIN, L	8208250204* 8208160274* 8208060002* 8208090272 8208090278*	40-85 50-482 E CONTRACT 50-478 Q 50-478 O
SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W, C	8208170287 8208240153 8208240274 8208240360 8208270318	50-462 G 50-265 G 50-265 G 50-313 E 50-265 G	Shima, S Shimshak, R Shimshak, R Shirakawa, T Shirakawa, T	8208310494 8208310498* 8208190252 8208240013 8208310041	XPORTLIC XPORTLIC 80-409 F XPORTLIC XPORTLIC	SITTABON, F EKALBKI, J R. SKINNER, E H EKINNER, P A SKINNER, P, H	8208120220 8208180237 8208170346* 8208120302* 8208160501*	50-537 H NUREQ 50-413 A 50-416 E 50-327 Q
SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8208270354 8208270371* 8208270467 8208300117 8208310278	50-285 F 50-285 Q 50-313 F 50-252 Q 50-285 Q	SHIRAKAWA, T. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J.	8208310049 8208030261 8208110091 8208110152 8208110163	XPDRTLIC 50-287	SLATLER, W ELAWINSKI, W J SLAWINSKI, W J, SLEMBER, R. J BLIGER, E K	9208270420 8209100107 8208100113* 9208030520 8208110221*	50-322 H 40-8791 40-8791 REVIEW ORP 50-259 F
SEIDLE, W C SEITZ, J SELAN, J C SELLS, D E BEMKEN, R, S	8208310389 8208040114# 8208030044# 8208230227 8208230074	50-482 A 50-537 D 50-273 P 50-400 G RES	SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J	8208120138 8208130170 8208130421 8208160433 8208160437	50-437 0 50-382 0 50-537 0 50-289 0 50-413 0	BLIGER, E K. SLOAN, D. E. SMILLIE, R J BMITH, B W	8208260343* 8208060202 8208260002 8208260017 8208160333*	50-257 F 50-367 B NUREO NUREO 50-302 Q
SEMMEL, H SEMMEL, H SEMMEL, H SEMMEL, H SEMMEL, H	8208030388 8208030388 8208170124 8208170124 8208270508	50-155 0 50-155 0 50-155 0 50-155 0 50-155 0	SHOEMAKER, C. J SHOEMAKER, C. J SHOEMAKER, C. J SHOEMAKER, C. J SHOEMAKER, C. J	8208240199 8208240232 8208240233 8208270376 8208270389	50-387 0 50-70 0 50-237 0 50-387 0 50-395 0	emith, d. emith, d. L. emith, e. H. emith, q. emith, q.	8208060047* 8208120286 8208100097 8208050400* 8208190314*	50-321 F 50-537 H 50-329 B 50-219 G 50-413 A
SEMMEL.H SERKIZ.A W SERKIZ.A W SERRANO.W SESTAK.F	8208270508 8208030701 8208030704* 8208060054* 8208180025	50-155 Q GEN TEC IS GEN TEC IS 50-313 P 50-275 R	SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOLLY, S. C. SHOLLY, S C	8208270394 8208270400 8208300099 8204200004 8208060100	50-387 0 50-537 0 50-289 0 FOIA 50-247 0	Smith, Q. H Smith, Q. H Smith, Q. H Smith, Q. H.	8208050218 8208050264 8208050275 8208050410 8208050469*	50-277 G 50-271 G 50-286 G 50-307 G 50-271 G
SETHURAMAN, S SEYFRIT, K V SEYFRIT, K V SHABER, C R. SHABER, C R	8208260404 8206150020* 8206150021* 8208040109* 8208230428*	NUREO FOIA FOIA 50-387 A 50-341 A	SHON, F. J SHON, F. J SHOPENN, N M SHORT: R. W SHOTWELL: J. A	9208110079 9208110093 9207060192* 9208190093* 9208160150	50-247 0 50-155 0 40-3453 50-265 R 50-443 0	SMITH, Q H SMITH, Q H, SMITH, Q, H, SMITH, Q, H	8208040246 8208090116 8208100014 8208120058 8208120134	50-309 F 50-271 F 50-334 Q 50-293 Q 50-387 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEQUAY	AUTHOR	ACCESSION NUMBER	SUBJE CATEQ		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SMITH, G H SMITH, G H SMITH, G H SMITH, G H	8208120259 8208160193 8208170140 8208230277 8208300074	50-317 Q 50-271 P 50-273 Q 50-273 F 50-271 Q	SNYDER, H L SNYDER, H L SNYDER, H L SOBEL, C P SOBEL, C P	8208120034 8208260002 8208260017 8208050358 8208160177	NUREG NUREG # 50-219	5 5	STANSBERRY, W W STAPLETON, B W STARK, R M STARK, R M STARKEY, R B	82081601104 8208310060* 8208020430 8208020431 8208050357	50-261
SMITH. O H SMITH. H H SMITH. I W SMITH. I W SMITH. I W SMITH. I W	8208300213 8208300264 8208040259 8208050387 8208110089	50-293 Q PR 50-289 Q 50-289 Q 50-289 Q	SOMINKI, B M SOLBRIG, C W SOLDRIG, C W SOLDAT, J K BOLLENBERGER, D	8208030335 8208040004 8208040043 8208180126 8208040079	50-247 RES RES NUREO 40-2259	G ,	STARKEY,R D STARKEY,R B STARKEY,R D STARKEY,R D STARKEY,R D	8208090172 8208130014 8208160358* 8208200110 8208200203	50-261 S 50-261 R 50-261 0 50-261 S 50-261 S
SMITH.J.C. SMITH.J.L. SMITH.J.L SMITH.J.L	8208240119 8208270556 8208030009* 8208040009 8208040184	50-287 Q 40-6622 50-322 F 50-322 A 50-322 A	SDL1EY, 8 W SOLLEY. 8 W SOO. P SORRELL, E C SORRELL, E C.	B2080504014 B2082000734 B208250029 B2080600444 B2080600554	# 50-259 RE8 # 50-321	ន ទ F	STARKEY.R B STARKEY.R B STARKEY.R B STARKEY.R B STARKEY.R B	8208230456 8208270042* 8208270244 8208300275 8208300279*	50-261 8 50-261 R 50-261 8 50-261 8 50-261 8
HITH, J.L. SHITH, J.L. SHITH, J.L. SHITH, J.L. SHITH, J.L.	8208130191 8208180041 8208200200 8208200246 8208240238	50-322 E 50-322 F 50-322 C 50-322 A	SORRELL.E C SOUDER, J L BOUDER, J L SOUDER, J L SOUTAR, C F	8208110248# 8208040030 8208050448# 8208100364 8208020358	50-289	F P O H H	STARLING, E STARMER, R. J STARMER, R J STAROSTECKI, R STAROSTECKI, R	8208020358 8208040042 8208040572 8208020223 8208020276	50-537 H WASTE MOT WASTE NOT 50-244 O 50-443 Q
SHITH, J L.	8208240293 8208240429 8208240431 8208300137 8208300176	50-322 E 50-322 E 50-322 E 50-322 E	SOWERS, O W SPECTOR, C SPECTOR, B M SPECTOR, B M SPEER, M	8208070016 8206270075 8208020274* 8208020321* 8208170314*	50-244	0 8 8 8	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8208020279 8208020280 8208020284* 8208020305 8208020308*	50-307 Q 50-322 Q 50-322 Q 50-412 Q 50-412 Q
Smith, M J Smith, M B, Smith, P A Smith, P A Smith, P. A	8208270142* 8208070016 8208020047* 8208020452* 8208040550*	50-10 G NUREG CONTRACT CONTRACT CONTRACT	SPEIB, T SPEIB, T P SPELHAN, H J. SPELHAN, H J SPENCER, D A	8204130421* 8207150242 8208300318 8208300318 8208310270*	50-440 TOPREP 40-2061 40-2061 50-373	E 8	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8208020372 8208050205 8208050209* 8208050275 8208050276*	50~289 Q 50~354 Q 50~354 Q 50~219 Q 50~219 Q
SMITH, P A SMITH, P. A SMITH, P. A SMITH, P. A SMITH, P. A	8208050086# 8208060355 8208060356# 8208240054# 8208260077#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	EPESSARD, R SPEBSARD, R SPEBSARD, R SPEBSARD, R SPESSARD, R L	0208100123 8208100164 8208100211 8208050326* 8208050393	50-344 50-461 50-373 50-358 50-10	\$ \$ 0 0	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8208050287 8208050288* 8208050412 8208050423* 8208060286*	50-334 Q 50-334 Q 50-317 Q 50-317 Q 50-322 A
SMITH, P. A SMITH, P. A SMITH, P. A SMITH, P. A. SMITH, P. A	8208260436 8208260445* 820826045* 8208260480* 8208316010*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD, R L. SPESBARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	6208050424 6208050424* 6208100126 6208100280 6208160417*	50-254 50-254 50-327 50-327 50-461	0 8 8 0	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8208100214 8208100245 8208100255 8208100255* 8208120049	50~354 0 70~371 70~820 70~620 50~352 Q
Smith, P. A. Smith, P. A Smith, R. Smith, R. Smith, R. D.	8208310464 8208310520# 8208120140# 8208250117# 8208030159	CONTRACT CONTRACT 90-387 G 40-84 40-8102	SPESSARD, R. L. SPESSARD, R. L SPESSARD, R. L SPESSARD, R. L SPESSARD, R. L SPESSARD, R. L	6208200016 6208200241 6208230088 6208230072* 6208240365	50-255 50-10 50-305 50-305 50-266	G G G G	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8208120230 8208160007 8208160141 8208160445 8208160451#	50-247 Q 50-286 Q 50-309 Q 50-320 Q 50-320 Q
SMITH, R. D. SMITH, R. D. SMITH, R. H SMITH, R. L. SMITH, R. L.	8208190341 8208190345 8208310476* 8208030405 8208270569*	WASTE NOT WASTE NOT 50-213 G 50-271 F 50-271 R	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8208270255 8208270348 8208270359 8208300116 8208300118#	50-344 50-373 50-373 50-331 50-331	Q P Q Q	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	6208160474 6208170078 8208180071 6208180124 6208170227	50-320 G 50-317 G 50-286 G 50-334 G 50-289 G
BMITH, R.L. BKITH, B.H. BMITH, B.W SMITH, W.O. SMITH, W.G.	820830020 4* 8208120177 8208100250* 820803020 5 8208050354	CONTRACT 50-537 H 50-320 S 50-316 S 50-315 S	SPESSARD, R L. SPESSARD, R L SPESSARD, R L SPESSARD, R L. SPITZBERG, D B.	8208300281 8208300284* 8208310143 8208310145 8208140449*	50-409 50-409 50-346 50-266 40-8064	Q Q Q	STAROBTECKI.R STAROBTECKI.R STAROBTECKI.R STAROBTECKI.R STAROBTECKI.R	8208230039 8208230103 8208230125 8208230182 8208230317	50-20 Q 50-333 Q 50-322 Q 70-687 50-410 Q
emith, W. O Thith, H. O Tith, W. O. Iith, W. O. Iith, W. O	8208030347 8208100042 8208100052 8208100338 8208120210	50-316 8 50-316 6 50-315 9 50-315 8 50-315 R	SPIVEY, J M SPIVEY, J H SRENIAWSKI, D J STAFFORD, A H STAHLE, C.	8208110170 8208110170 8208100120 8208270279* 8208040523	50-322 50-322 1&E 50-338 50-315	Q Q R P	STAROSTECKI.R. STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8208230318* 8208230344 8208240178 8208300041 8208300042*	50-410 Q 70-938 50-387 P 50-247 Q 50-247 Q
117H, W O. 117H, W O. 117H, W O. 117H, W O. H17H, W O	8208230062	50-316 R 50-315 8 50-315 8 50-316 8 50-315 8	Btamirib. B Btampley, n l Btampley, n, l Stampley, n, l Stampley, n, l	8208300271 8208020067 8208020140 8208060171 8208060232	50-416	0 8 8 8	STAROBYECKI,R. STAROBYECKI,R STAROBYECKI,R STAROBYECKI,R. STAROBYECKI,R	8208300048 8208300049 8208300050* 8208300079 8208300083	50-244 0 50-277 0 50-244 0 50-387 0 50-354 0
SMITH, W O. SMITH, W O. SMITH, W.O. SMITH, W.O.	8208270314 8208270317 9208270373 8208270643*	50-315 8 50-314 8 50-315 P 50-315 B 50-315 R	STAMPLEY,N L STAMPLEY,N,L STAMPLEY,N L, STAMPLEY,N L STAMPLEY,N L	8208040273 8208090147 8208090152 8208090169 8208090260	50-416 50-416 50-416	8 8 9 8	BTAROBTECKI, R STAROSTECKI, R STAROSTECKI, R, STAROSTECKI, R, STAROSTECKI, R	8208300184 8208300197 8208300236 8208300241* 8208300254	50-293 0 50-317 0 50-223 0 50-223 0 50-387 0
SMITH, W. O SMITH: W O SMOKER, C. S. SMOKER, C. S. SMYRL, S. L.	8208310359 8208130102* 8208230153* 8208020358	90-315 8 90-316 8 50-305 8 50-305 8 50-537 H	STAMPLEY, N L STAMPLEY, N L STAMPLEY, N L, STAMPLEY, N L STAMPLEY, N L	8208070280 8208160254 8208160287 8208160476 8208160506	50-416 50-416 50-416	9 G 8 8	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R. STATON, O. K STEARNS, C. F	8208300300 8208300313* 8208310358 8208230073* 8208250102*	50-272 Q 50-272 Q 50-272 Q 50-275 B 40-86
EMYTH, C. W. BNELL, W. O. BNOW, B. A. BNOW, C. T. BNOW, C. T.	8208240048 8208120245 8208020088* 8208170278*	50-289 R Nureq 50-244 R 50-338 P 50-339 P	STAMPLEY, N I. STAMPLEY, N L STAMPLEY, N L STANCAVAGE, P. P. STANCAVAGE, P P.	8208270408 8208270431 8208270434 8208310347* 8208310353*	50-416 50-416 TOPREP	8 8 8	STEED, L. B STEELE, R L STEELE, R L STEELE, R L STEFAND, J J	8208030345* 8208100046 8208100076 8208200272 8208170010	50-334 R 50-344 B 50-344 B 50-344 B 50-400 F
enyder, B. J. Enyder, B. J. Enyder, B. J. Enyder, G. L. Enyder, G. L.	6208120356* 6208130365 6208160164	50-320 P 50-287 H 50-320 H 60-363 Q FOIA	STANDLEY, L M STANLEY, E STANSBERRY, E, R. STANSBERRY, W W. STANSBERRY, W W.	8208050286 8208020358 8208240401 8208030417# 8208090138*	50-537 50-182 50-250 (H H 9 9	STEFAND, J J STELLO, V STELLO, V. STELLO, V. STELLO, V	8208250083 8207220184 8208020157 8208100059 8208170097	SO-440 A REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STELLO, V	8208180048	REVIEW ORP	STOTZ, J	8208130151*	50-346 B	TAUBER, A	8207110037	FOIA
STELLO, V	8208200074	REVIEW ORP	STOVER, J. R	8208040471*	CONTRACT	TAUBER, H	8208030183	50-341 A
STELLO, V	8208300088	REVIEW ORP	STRAWBRIDGE, L	8208170109	50-537 T	TAUBER, H	8208060148	50-341 A
STELLO, V	8208310145	REVIEW ORP	STREETER, J	8208100317	50-316 B	TAUBER, H	8208170101	50-341 E
STELLO, V	8208310206	REVIEW ORP	STREETER, J F	8208050508	50-282 G	TAUBER, H	8208170106	50-341 E
STEPHENB, A G	8208040007	RES	STREETER, J F	8208090040	50-546 G	TAUBER, H	8208180087	50-341 X
STEPTOE, P	8208240267	50-237 0	STREETER, J F	8208160125*	50-409 Q	TAUBER, H	8208180079	50-341 X
STEPTOE, P	8208240267	50-237 0	STREETER, J F	8208230034	50-341 G	TAUBER, H.	8208200050	50-341 A
STEPTOE, P P	8208020220	50-329 0	STREETER, J F	8208230164	50-263 G	TAUBER, H.	8208200111	50-341 E
STEPTOE, P P	8208020220	50-329 0	STREETER, J F	8208230309	50-331 G	TAUBER, H.	8208200121	50-341 A
STEPTOE, P P	8208040232*	50-155 0	STREETER, J F	8208233310*	50-331 Q	TAUBER, H	8208200162	50-341 A
STEPTOE, P P	8208040232*	50-155 0	STREETER, J F	8208300278	50-346 Q	TAUBER, H	8208200234	50-341 · E
STEPTOE, P P	8208040243*	50-155 0	STREETER, J F	8208300303*	50-346 Q	TAUBER, H.	8208230003	50-341 A
STEPTOE, P P	8208040243*	50-155 0	STUART, C L	8208030620*	50-416 P	TAYLOR, G B	8208020368	50-537 H
STEPTOE, P P	8208110187	50-329 0	STUART, C L	8208030665*	50-416 P	TAYLOR, J. H	8208040116	NUREO
STEPTOE, P P	8208110187	50-329 0	Stulberg, D B	8207110022	FDIA	TAYLOR, J. H TAYLOR, J. H TAYLOR, J. H TAYLOR, P. A TAYLOR, P. A	8208040233	TOPREP
STEPTOE, P P	8208190110	50-329 0	Subramon Ian, N	8206300163*	50-321 0		8208070100	PT21
STEPTOE, P P	8208190110	50-329 0	Sudduth, A	8208030487*	50-369 P		8208100364	50-317 @
STERNBERG, D M	8207080424	50-275 0	Sudduth, A	8208030495*	50-369 P		8208030221#	50-280 @
STERNBERG, D M	8208160100	50-142 0	Sudduth, A	8208030502*	50-369 P		8208030378#	50-338 @
STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M	8208140108 8208160273 8208160309 8208160523 8208160527	50-187 Q 50-528 Q 50-275 Q 50-275 Q 50-312 Q	SUGARHAN, R C SUGARHAN, R C SUGARHAN, R. J SUGARHAN, R J SUGARHAN, R J	6208260002 8208260017 6208110181 6208110181 8208110164*	NUREO NUREO 50-352 O 50-352 O 50-352 O	TAYLOR, P. A TAYLOR, T. T TEDESCO. R L TEDESCO. R L TEDESCO. R L	8208030459* 8208130475 8206140404* 8208020419 8208020424	50-389 @ NUREQ 50-387 P 50-498 A 50-443 A
STERNBERO, D M	8208200108	50-397 8	BUQARMAN, R J	8208110184*	50-352 Q	TEDESCO.R L	8208030737	50-387 A
STERNBERO, D M	8208240269	50-147 Q	SUGARMAN, R J	8208110185	50-352 Q	TEDESCO.R L	8208030738	50-397 A
STERNBERO, D M	8208240277	50-528 G	BUQARMAN, R J	8208110185	50-352 Q	TEDESCO.R L	8208040424	50-322 A
STERNBERO, D M	8208240290	50-133 Q	SUGARMAN, R J	8208110186*	50-352 Q	TEDESCO.R L	8208040427	50-352 A
STERNBERO, D M	8208240348	50-344 Q	BUQARMAN, R J	8208110186*	50-352 Q	TEDESCO.R L	8208060368	50-322 A
STERNBERG, D M	6206270322	50-528 G	Eugarman, R J	8208110167*	50-352 0	TEDEBCO, R L. TEITT, T. R TEMPLE, J TEPPER, P. 8 TERG, N M	8208070343	50-387 P
STERNOLASS, E J	6206030457*	50-454 O	Sugarman, R. J	8208110167*	50-352 0		8208100275	50-289 R
STERNOLASS, E, J	6206030457*	50-454 G	Sugarman, R. J	8208110173	50-352 0		8208180037	PRH
STETKA, T F	6206160333*	50-302 G	Sugarman, R J,	8208110173	50-352 0		8208130356	70-25
STEVENS, D, L	6206130475	NUREO	Sugarman, R. J	8208130157	50-352 0		8208050225#	50-277 Q
STEVENS,R J	8208160071	50-335 F	BUQARMAN, R J	8208130157	50-352 0	TERC, N M TERRELL, C W TESKE, M, E TESTWUIDDE, R THADANI, A	8208050306*	50-286 Q
STEVENSON,M G	8208120368	NUREO	BUQARMAN, R, J	8208180034	50-352 A		8208060197	50-112 P
STEWART,G C,	8208040434	50-537 H	BUQARMAN, R J	8208270432	50-352 0		8208170257*	50-397 P
STEWART,J P	8208160530*	50-312 G	BUQARMAN, R J	8208270432	50-352 0		8208020368	50-537 H
STEWART,N J	8208240410*	27-48	BUQARMAN, R J	8208270489	50-352 0		8208260554*	FOIA
STEWART, P	8208140105#	50-142 @	Sugarman, R. J	6208270487	50-352 0	THAMM, E O THEOFANGUS, T O THEOFANGUS, T O THIE, J A. THIOPEN, R	8208020069*	CONTRACT
STICKLEY, T H	8208040355#	50-267 @	Bugarman, R. J	8208270500	50-352 0		8208020412*	ACRB
STICKLEY, T H	8208270492#	50-327 A	Bugarman, R. J.	8208270500	50-352 0		8208020412*	ACRB
STIEDE, W L	8208030245	50-373 P	Bummerb, R.	8208300317#	50-272 0		8208050005	REB
STILES, J P	8208040024	RE8	Bummer, H. L.	8208120228#	50-321 8		8208020331*	50-259 8
STIRRETT.D D	6208020348	50-537 H	SUMNER, H L	8208160469*	50-321 8	THOM, T	8208120233*	50-239 R
STOOSDILL.P	6208050240*	50-123 H	SUMNER, H L	8208270232*	50-366 B	THOMA, J. O,	8208040511	50-247 P
STOHR.J P	6208140400	50-338 F	SUNDELL, R	8208260905	NUREO	THOMA, J. O	8208040518	50-286 P
STOLZ.F	6208130031	50-289 P	SUNSER, J. J,	8208270230	50-220 F	THOMAS, E. A	8208060251*	50-309 F
STOLZ.J.	6208090013	50-302 F	SUTTON, A. O	8208260087	NUREO	THOMAS, J	8208050285*	50-219 Q
STOLZ, J STOLZ, J STOLZ, J F STOLZ, J, F STOLZ, J, F	8208240148 8208270700 8208020451 8208030743 8208040360	50-302 F 50-302 F 50-277 P 50-321 P 50-302 P	GUTTON, J. W. BUTTON, J. W. BUTTON, J. W. BYENBSON, B. A. BYENBSON, B. A.	8208160304* 8208190278* 8208100058* 8208120212*	GA799 GA799 GA799 50-315 8 50-315 R	THOMAS, J Z THOMAS, L M THOMAS, L M. THOMAS, R D THOMAS, R D	8208110144 8208100035# 8208100151# 8208030349# 8208050534	50-537 Q 50-247 F 50-294 F 27-48 27-48
STOLZ, J F,	8208040378	50-277 P	EWANSON, D G	8208110049	50-247 R	THOMAS, R D THOMAS, B, D	8208100145	27-49
STOLZ, J F	8208040437	50-321 P	SWANSON, D H	8208020358	50-537 H		8208100194*	27-49
STOLZ, J F	8208040446	50-346 P	SWANSON, D T	8208130188	50-537 C		8208240410*	27-49
STOLZ, J F,	8208040450	50-269 F	SWANSON, D T	8208160146	50-537 C		8208270374*	70-754
STOLZ, J F	8208040452	50-289 Q	SWARTZ, E D	8208050470	50-295 Q		8208130474	NUREO
STOLZ.J F STOLZ.J F STOLZ.J F STOLZ.J F	8208050026 8208040071 8208040078* 8208040331 8208100369	50-313 P 50-346 P 50-346 P 50-346 G 50-313 P	EWARTZ, E D EWARTZ, E D. SWARTZ, E D EWARTZ, E. D. EWARTZ, E. D	8208110041 8208110188 8208130044 8208170135 8208310212	50-237 P 50-10 P 50-237 P 50-237 P 50-237 G	THOMAB, V W. THOMPSON: H L. THOMPSON: M S THOMPSON: R. C. THOMPSON: S L	8208260075 8208050053 8208260087 8208170117 8208180241	NUREO 50-220 H NUREO 50-537 T NUREO
STOLZ, J F	8208100372*	50-313 P	SWARTZ, E. D	8208310218	50-10 G	THOMPBON: T	8208130469	NUREG
STOLZ, J F	8208120001	50-344 P	SWARTZ, E. D	8208310402	50-254 P	THOMSEN: F T	8208030314	50-522 G
STOLZ, J F	8208130043*	50-278 P	SWARTZ, J.	8208300135*	50-346 B	THOMSEN: F, T	8208030314	50-522 G
STOLZ, J F	8208170012	50-344 P	SWARTZMAN, Q.	8208180126	NUREG	THONUB: L,	8208160483*	50-320 G
STOLZ, J F.	8208170358	50-289 P	SWEITZER, H J	8208250334*	40-86	THORNBERRY: R C	8208120072	50-275 R
STOLZ, J F. STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8208180270 8208240005 8208250034 8208250471 8208250474	50-344 P 50-312 P 50-312 Q 50-312 P 50-312 P	SWEITZER:H J SWEITZER:H J SWETLAND:P SWYLER:K J SYDNOR:R	8208250370* 8208250372* 8208020285* 8208110241 8208020371*	40-84 40-86 50-309 Q REB 50-317 B	THORNBURG, H D THORNTON, P THORNTON, P. THORNTON, P. THORNTON, P. THORNTON, P	8208250299* 8208270514 8208270514 8208270518* 8208270518*	40-84 50-155 G 50-155 G 50-155 G
STOLZ, J F	8208250500	50-321 P	SZALAY,R.	8208030196	NUREQ	THORPE, J. R	8208100247	REGOD
STOLZ, J, F	8208250504*	50-321 P	SZUKIEWICZ,A J	8208040530	GEN TEC IB	THORUP, C B	8208180269*	CONTRACT
STOLZ, J F,	8208250511*	50-321 P	TABOR,W.H	8208020358	50-537 H	TICHLER, J.	8208260406	NUREO
STOLZ, J, F	8208270689	50-277 P	TAKEUCHI,K	8208260273*	TOPREP	TIERNAN, J. A.	8208270555*	50-317 R
STOLZ, J, F	8208270690	50-321 P	TAM,P B	8208110288	50-334 P	TIERNAN, J. A	8208270568*	50-317 R
STOLZ, J F	8208270693	50-321 P	TANG WEE, D	8208230033*	50-249 B	TIERNAN, J Å.	8208270574*	50-317 R
STOLZ, J F	8208300029	50-321 G	TANKIN.R. B	8208260433	NUREG	TIET, O C.	8208110234*	50-254 F
STONE, R. L	8208250089#	40-86	TANNER, J	8208300306	REVIEW ORP	TIETZ, O.	8208200263*	50-254 B
STONE, R. L.	8208250352#	40-86	TAPIA, J. I	8208160470*	50-298 G	TIKOO, B	8207260247*	50-213 P
STONE, R. L.	8208250374#	FOIA	TARAB, D N.	8208030537	REGOD	TIKTINGKY, D.	8208120367	WASTE MOT

AUTHOR	ACCESSION NUMBER	SUBJECT		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR'		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	
LMAN, A LMAN, A LMAN, A 10, W W PPS, 6 B	8208090127* 8208090138* 8208100274* 8208270570* 8208030450*	50-327 50-348 50-324 70-687 50-321	G G G S	TRIPP, L E	8208050214* 8208050285* 8208050292* 8208190057* 8208300085*	50-354 50-217 50-334 50-358 50-354	9 9 9 9	UHRIO, R E	8208030332 8208030334 8208030429 9208030456 8208030468	50~389 50~335 50~389 50~389 50~389	5 P S S
PB. 8 B PB. 8 B PB. 8. B PB. 8 B PB. 8 B	6208040187* 8208060194* 8208090277* 8208090279* 8208120114*	50-366 50-366 50-321 50-326	20000	TRIPP,L E TROSKOSKI,W M TROUP,O L TROUP,O L TROWBRIDGE,O F	82080300317* 8208050292* 8208030324* 82080303333* 8208090155	50-272 50-334 70-1201 70-824 50-297	9 9	UHRIO,R E UHRIO,R E UHRIO,R E UHRIO,R E UHRIO,R E	8208030624* 8208030638 8208040455* 8208060185 8208060278	50-335 50-389 50-389 50-389 50-335	G S F A P
PS.6 B PS.5 B PS.5 B PS.6 B PS.6 B	8208120178* 8208130157* 8208160503* 8208200052* 8208200289*	50-366 50-366 50-366 50-321 50-366	ច	TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F	8208070155 8208110147 8208110147 8208140338 8208240338	50-289 50-289 50-289 50-289 50-289	0 0 0	UHRIO,R E UHRIO,R E UHRIO,R E UHRIO,R E UHRIO,R E	8208070061 8208070205 8208070270 8208100044 8208100075	50-250 50-389 50-389 50-389 50-250	F 8 8 A P
PS, 8 B PS, 6, 8 PS, 5 B PS, 5, 8 PS, 8 B	8208270145* 8208270241* 8208270302* 8208270461* 8208270539*	50-366 50-321 50-321 50-366 50-366	មាលស្សាធ	TROWBRIDGE. 0 F TROWBRIDGE. 0 F TROWBRIDGE. 0 F TROWBRIDGE. 6 F TROWBRIDGE. 6 F TSUKUDA. T W	8208240342 8208240342 8208240432 8208240432 8208060043	50-289 50-289 50-289 50-289 XPORTLIC	0 0 0	UHRIO,R E UHRIO,R E UHRIO,R E UHRIO,R E UHRIO,R E	8208100095 8208100114 8208100130 8208100187 8208100198	50-335 50-335 50-250 50-335 50-335	P P P P
.pg. 6 B .pg. 6 B .pg. 8 B .pg. 8 B .pg. 6 B	8208300115* 8208300161* 8208300174* 8208300235* 8208300347*	50-3&& 50-321 50-321 50-321 50-3&&	8 8 8 8 8	TBUSHIMA. B TUCKER. H B TUCKER. H B TUCKER. H B TUCKER. H B	8208310339* 8208050254 8208100173 8208100305 8208110182	50-388 50-369 50-269 50-369 50-269	Q Q P F F	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8208100312 8208110242* 8208120019 8208120051 8208130039	50-389 50-250 50-389 50-335 50-250	K F K P
TON, W. J TLAND, L. E ALSTON, A ALSTON, A ALSTON, A	820830003B* 8208240177 820823001B 8208230027 8208230031	50-213 50-317 50-346 50-454 50-454	Р Н М М	TUCKER, H B	8208120028 8208120036 8208120172 8208120216 8208130175	50-269 50-413 50-269 50-269 50-369	P 8 8	UHRIG,R.E UHRIG,R.E UHRIG,R.E UHRIG,R.E UHRIG,R.E UHRIG,R.E	8208140058 8208140071 8208140165 8208140197 8208140247	50-335 50-335 50-389 50-335 50-250	F Q Q Q
LLSTON: A. ALSTON: A ALSTON: A. ALSTON: A ALSTON: A	8208230061 8208230075 8208230105 8208230477 8208240081	50-454 50-454 50-454 50-346 50-346	ក អ អ អ អ	TUCKER, H B	6209130238 8208160136 8208160206 8208160284 8208160355	50-369 50-369 50-413 50-270 50-413	8 0 G 6 0	UHRIO, R E UHRIG, R, E UHRIG, R E UHRIG, R E UHRIG, R, E	8208160276 8208160343* 8208160365* 8208160376* 8208170102	50-251 50-389 50-250 50-250 50-250	0 0 0 0 P
IIN.W DD.O A DD.J J DDROVICH,M DDROVICH,M M.	8208160110* 8208030515* 8208170077* 8208180073 8208020265	50-261 70-1201 CONTRACT PR 50-537	g ·	TUCKER, H B	8208160412 8208160481 8208160499 8208170087 8208170150	50-369 50-370 50-369 50-269 50-369	8 G G R R	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8208170116 8208170123 8208170203 8208190152 8208190190	50-250 50-250 50-335 50-250 50-389	\$ 9 8
IPK.INB.B A IB.R B IGUE, T. IGUE, T. M IGUE, T O	8208160424 8208170307* 8208050441* 8208050403* 8208250137*	50-387 50-219 50-237 50-10 40-86	Q Q Q	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8208170151 8208170854 8208170300 8208170412* 8208200022	50-269 50-413 50-413 50-269 50-369	P A A F 8	UHRIO,R E UHRIO,R E UHRIO,R E UHRIO,R E UHRIO,R E	8208200085 8208200133 8208200194 8208200295 8208230007	50-389 50-250 50-335 50-250 50-250	6 6 6
IGUE, T O IGUE, T O IGUE, T. O IGUE, T D DLE, J D	8208250167* 8208250267* 8208250381* 8208250384* 8208050249*	40-86 40-86 40-86 40-86 50-247	8	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8208200025 8208200247 8208240210 8208240234 8208240242	50-249 50-349 50-413 50-287 50-269	P 8 A P P	UHRIG,R,E UHRIG,R E UHRIG,R E UHRIG,R E UHRIG,R E	8208230370 8208260193 8208270066* 8208270119 8208270306	50-335 50-387 50-250 50-389 50-389	P A A 9 6
DLE, R. J. DLE, R. J. DLE, R. J. TH, A. D. TH, A. D.	8208040278* 8208050130* 8208170359* 8207150421* 8208140127*	50-287 50-287 50-289 50-460 50-397	ቸ F G G	TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B	8208240440 8208250355 8208260136 8208260340* 8208260385*	50-287 50-413 50-349 50-349 50-369	P A P F F	UHRIG,R E UHRIG,R E UHRIG,R E ULLRICH,J ULLRICH,J ULLRICH,J	8208270540* 8208300167 8208310265 8208200244* 8208300063*	50-250 50-387 50-389 50-373 50-373	R F A B
TH, A.D. INSEND, H.E. AMM, T.R. AMM, T.R. AMM, T.R.	8208160378* 8207120253* 8208130027 8208130823 8208130277	30-460 50-447 50-454 50-454 50-454	G A B S A	TUCKER, H B TUCKER, H B, TUCKER, H B TUCKER, H, B TUCKER, H, B	8208260437* 8208260537* 8208260542* 8208270125 8208270403	50-247 50-247 50-249 50-297 50-270	# F \$ 8	UMEMDTO, T. UNSAL, A UPRIGHT, C M UPRIGHT, C M UPRIGHT, C, M,	8208310328* 8208250358* 8208030434* 8208160186* 8208160227*	50-388 50-413 50-416 50-241 50-335	G A G G
ISM, T. R IMM, T. R ISM, T. R IMM, T. R IMM, T. R	8208160417 8208170096 8208170183 8208170219 8208170240	50-456 50-454 50-373 50-454 50-454	A P E E	TUCKER, H B TUCKER, H B TUCKER, H B, TUCKMAN, M S TUCKMAN, M S	8208300328 8208300342 8208310236 8208190315# 8208190319*	50-413 50-269 50-269 50-413 50-413	I I P A A	UPRIGHT, C M URYC, 8 UTLEY, E E UTLEY, E E VAN BRUNT, E E	8209140501* 8208160370* 8208170312 8208250207 8208030650	50-327 50-335 50-324 50-324 50-528	0 9 0 4
М, Т. Я. М, Т. В. М, Т. В. М, Т. В. М, Т. В. М, Т. В.	8208180002 8208180011 8208180026 8208190014 8208230058	50-454 50-454 50-454 50-454 50-454	E A F A	TULEY, CR TURK, BE TURK, BE TURK, BE. TURK, BE	8207280263* 8208110065 8208260022 8208300102 8208310066	TOPREP 50-382 50-446 50-382 50-382	0 0 0	VAN BRUNT, E E VAN BRUNT, E E, VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8208050245 8208050418 8208050437 8208160011 8208160072	50-528 50-530 50-528 50-528 50-928	8 8 A A
MM, T. R. MH; T R. MH; T R. MH; T R. MH; T R. MH; T R.	8208230324 8208230327 8208230332 8208230354 8208230377	50-454 50-454 50-454 50-454 50-454	A A F G	TURK,8 E. TURK,8 E TURLEY,K L TURSKI,F.A UDALL,H K	8208310070 8208310081 8208270378* 8208110179* 8206130005*	50-382 50-445 50-528 50-155 50-358	© 0 1 0 U	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E. E	8208160181 8208170168 8208170170 8208200205 8208230053	50-529 50-528 50-528 50-528 50-528	A K B
MM, T.R. MMELL, C.M, MMELL, C.M GER, J.C JO, J	8208270350 8208030092 8208100354 8208270550* 8208270438*	50-454 50-368 50-344 50-29 50-29	A P P R R	UDALL, M K UDELL, R UDELL, R A. UDELL, R A UDERITZ, R, A	8208070053* 8206200003 8206270073 8207050071 8208060158*	80-358 50-537 FOIA 50-261 50-311	U A 8 Q	VAN BRUNT, E E VAN BRUNT, E E, VAN BRUNT, E, E VAN BRUNT, E, E VAN BRUNT, E E	8208230216 8208230301 8208230358 8208240144 8208240172	50-528 50-528 50-528 50-528 50-530	\$ 5 0 8
MBLE,D.C. MBLE,D.C. MBLE,D.C PP,L PP,L.	8208050429* 8208170104* 8208300203* 8208020314* 8208190254	50-317 50-317 50-317 50-412 50-219	G G G S	UDERITZ,R A UDY,A C. UDY,A C. UDY,A C. UHRIO,R.E UHRIG,R E	8208310366* 8208040018 8208040147 8207230343 8208030170	50-272 RES RES 50-387 50-335	G F P	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8208240209 8208240262 8208240287* 8208240383 8208270325*	50-529 50-528 50-528 50-528 50-528	8 F 0 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VAN BRUNT, E E VAN BRUNT, E E VAN DODRN, P K VAN DODRN, P K VAN DVKEN, G	8208270330 8208270375 8208030188* 8208140349* 8207110013	50-528 Q 50-528 I 50-413 Q 50-413 Q FOIA	VASSALLO, D B	8208050047 8208050057 8208050061 8208060048 8208060060*	50-220 P 50-237 P 50-271 P 50-331 P 50-254 P	VINCENT.R A VISSING.O S VISSING.O S VITO,D J VOQLER.S H	8208250113 8208060042 8208170366 8208060161* 8208180137	50-255 P 50-313 P TOPREP 50-206 P 50-440 0
VANDENBERG, D	8208130271	50-255 R	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8208040064*	50-254 P	VDOT, R J	8208160374*	50-250 G
VANDERBECK, R	8208240446*	50-155 P		8208090024	50-254 P	VDIOT, H. H	8208020213	50-244 G
VANDERBEEK	8208040167	RES		8208110201	50-324 P	VOIOT, H. H	8208020213	50-244 G
VANDEWALLE, D J	8208020081	50-155 P		8208110283*	50-259 P	VDIOT, H. H	8208270477	50-287 G
VANDEWALLE, D J	8208020282	50-255 P		8208110290*	50-259 P	VDIOT, H. H	8208270477	50-287 G
VANDEWALLE, D J	8208020279	50-255 P	VASSALLO, D B	8208120299	50-293 P	VOIOT,H H	8208270532	50-287 0
VANDEWALLE, D J	8208020356	50-255 P		8208120345	50-324 P	VOIOT,H H	8208270532	50-287 0
VANDEWALLE, D J	8208030175	50-255 F		8208120363	50-259 P	VON HIPPEL,F	8208180125*	50-537 T
VANDEWALLE, D J	8208050366	50-155 G		8208130444	50-259 P	VON HIPPEL,F	8208180125*	50-537 T
VANDEWALLE, D J	8208070197	50-155 F		8208180210	50-324 0	VON RIESEMANN	8208260112	NURE0
VANDEWALLE, D J	8208070248	50-155 S	VASSALLO, D B	8208180248	50-263 P	VON STACKELBERO	8208260040	FDIA
VANDEWALLE, D J	8208100212*	50-155 G		8208180254	50-331 P	VDROERBRUEGOEN	8208240291*	50-528 0
VANDEWALLE, D J	8208100217*	50-155 G		8208180262	50-333 P	VDRHEEB, J P	8208300223	PR
VANDEWALLE, D J	8208110112	TOPREP		8208180265	50-293 P	VDRSE, J Y	8208030704*	50-400 0
VANDEWALLE, D J	8208170259	50-155 P		8208180266	50-237 P	VDRSE, J Y	8208160377*	50-261 0
VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J	8208180104 8208190433* 8208230334 8208240329 8208270531*	50-155 Q 50-155 F 50-255 P 50-155 P 50-155 R	VASSALLO, D B	8208190005 8208190004 8208190384 8208190391 8208190399	50-331 P 50-263 P 50-324 P 50-293 P 50-331 P	VOSBURY.F VOBBURY.F VOBBURY.F VUMBACD.F J WADE.P B	8208030169* 8206280418* 8206280525* 8208310423* 8208160082*	50-29 P 50-309 Q 50-289 Q 40-672 50-313 S
VANDEWALLE, D J	8208270604*	50-255 F	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D D	8208230111	50-259 P	WADE, P B.	8208200282*	50-313 8
VANDEWALLE, D J	8208270635*	50-255 R		8208240040	50-254 P	WAGNER, M E.	8208120011	50-416 9
VANDEWALLE, D J	8208310414	50-255 P		8208240046*	50-254 P	WAGNER, P, C.	8208040546	50-267 P
VARANINI, E E	8208030383*	REVIEW GRP		8208240050*	50-254 P	WAGNER, W J	8208160422*	50-362 9
VARELA, A A	8208020170*	50-443 Q		8208240160	50-271 P	WAITE, J A	8208030369*	27-48
VARELA A A	8208100032*	50-352 G	VASSALLO, D B VASSALLO, D B VASSALLO, D B, VASSALLO, D B VASSALLO, D B	8208240164	50-333 P	Waite, J. A	8208100176*	27-48
VARGA B A	8208020059	50-348 F		8208240168	50-254 P	Wake, D.	8208250394*	FOIA
VARGA B A	8208020438	50-261 P		8208240495	50-298 P	Walbridge, W C	8208060163	50-312 P
VARGA B A	8208030101	50-272 P		8208240464	50-237 P	Walbridge, W C	8208100138	50-312 P
VARGA B A	8208040024	50-305 G		8208250002	50-324 P	Walbridge, W C	8208100310	50-312 Q
VARQA: S A	8208040058	50-261 P	VASSALLO, D B	8208250455	50-254 P	WALBRIDGE, W G.	8208120029	50-312 P
VARQA: S A	8208040458*	50-272 P		8208250488	50-333 P	WALCOTT, D L	8208040434	50-537 H
VARQA: S A	8208040464*	50-272 P		8208260367	50-324 P	WALKER, R	8208100144	50-461 B
VARQA: S A	8208050014	50-315 P		8208260380*	50-324 P	WALKER, R	8208100211	50-373 8
VARQA: S A	8208050015	50-334 P		8208260514	50-271 P	WALKER, R. D.	8208030403*	50-10 9
VARGA, B A	8208040045	50-315 P	VABBALLO, D B	8208270498	50-333 F	WALKER, R. D.	8208050435*	50-254 Q
VARGA, B A	8208070273	50-311 P	VAUGHAN, C M	8208030135*	70-1113	WALKER, R. D	8208100126	50-329 B
VARGA, B A	8208110075	50-305 P	VENKAT, C K	8208230493	XPORTLIC	WALKER, R. D	8208100280	50-329 B
VARGA, B A	8208110074	50-272 P	VENKAT, C K	8208230494*	XPORTLIC	WALKER, R. D	8208160419*	50-461 Q
VARGA, B A	8208110213	50-250 P	VENKATAGHAIAH	8208230494*	XPORTLIC	WALL, E. R	8208270388*	50-528 I
VARGA, S. A.	8208110228	50-261 P	VERRELLI.D	8208030694	50-400 G	Walshi B. O	8208250022*	CONTRACT
VARGA, S. A.	8208110231*	50-261 P	VERRELLI.D	8208090124	50-327 G	Walske, C	8208020358	80-537 H
VARGA, S. A.	8208110237*	50-261 P	VERRELLI.D	8208100268	50-324 G	Walske, G	8208100004	DRG
VARGA, S. A.	8208110271*	50-334 P	VERRELLI.D	8208130294	50-83 G	Walton, O	8208020316*	50-412 G
VARGA, B. A.	8208110274*	50-334 P	VERRELLI.D	8208160106	50-261 G	Wambach, T. V	8208190062	50-255 P
VARQA, 8 A VARGA, 5 A VARGA, 8 A VARGA, 8 A VARGA, 8 A	8208130077* 8208130083* 8208130129 8208130430 8208170093	50-295 P 50-295 P 50-348 P 50-334 G 50-334 P	VERRELLI.D VERRELLI.D VERRELLI.D. M VERRELLI.D. M	8208160232 8208160484 8208300166 8208030184 8208030222	50-400 Q 50-259 Q 50-261 Q 50-438 Q 50-438 Q	WAPATO, B T, WARD, E WARD, E. G WARD, K. D WARD, K. D.	8208240348 8208240319# 8208240358# 8208170118# 8208270313#	50-522 0 50-263 F 50-263 F 50-483 G 50-346 G
VARQA, S A	8208170103*	50-334 P	VERRELLI, D. M	8208030446	50-390	WAREMBOURG, D.	8208050349	50-267 8
VARQA, S A	8208170107*	50-334 P	VERRELLI, D. M	8208030480		WAREMBOURG, D.	8208060169*	50-267 F
VARQA, S A	8208170407	50-286 F	VERRELLI, D. M	8208030547		WAREMBOURG, D.	8208100011	50-267 P
VARQA, S A	8208170087	50-315 P	VERRELLI, D. M	8208030594		WAREMBOURG, D.	8208130196	50-267 R
VARQA, S A	8208170092*	50-315 P	VERRELLI, D. M	8208100037		WAREMBOURG, D.	8208130201	50-267 R
VARGA, S, A	8208170381*	50-315 P	VERRELLI, D. M	8208140155	50-518 Q	Warehbourg, D.	8208160025	50-267 B
VARGA, S, A	8208230413	50-247 F	VERRELLI, D M	8208160180	50-261 Q	Warehbourg, D	6208190234	50-267 P
VARGA, S, A	8208240137	50-261 P	VERRELLI, D M	8208160204	50-438 Q	Warehbourg, D	8208200117	50-267 S
VARGA, S, A	8208250538	50-334 P	VERRELLI, D M	8208140228	50-416 Q	Warehbourg, D	8208200126	50-267 S
VARGA, S, A	8208260367	50-348 P	VERRELLI, D M	8208160271	50-438 Q	Warehbourg, D.	8208240053	50-267 S
VARGA, B A	8208260470	50-261 F	VERRELLI, D M	8208160294	50-259 Q	WAREMBOURG, D. W	8208240074	50-267 f
VARNER, D M	8208240139*	50-331 S	VERRELLI, D M	8208160323	50-327 Q	WAREMBOURG, D. W	8208040503*	50-267 f
VARNER, D M	8208240317*	50-331 S	VERRELLI, D M	8208160330	50-400 Q	WAREMBOURG, D. W	8208040198	50-267 f
VARNER, L S	8208240054*	CONTRACT	VERRELLI, D M	8208160337	50-390 Q	WAREMBOURG, D. W	8208140399*	50-267 f
VASSALLO, D, B	8208250003	50-331 P	VERRELLI, D M	8208160344	50-261 Q	WAREMBOURG, D. W	8208140456*	50-267 g
VASSALLO, D	8208040084	50-263 P	VERRELLI.D M	8208160366	50-400 Q	WAREMBDURG, D W	9209170134	50-267 P
VASSALLO, D B	8208020442	50-298 P	VERRELLI.D M	8208160380	50-390 Q	WAREMBDURG, D W	9209310355	50-267 P
VASSALLO, D B	8208030077	50-259 P	VERRELLI.D M.	8208160375	50-259 Q	WARKENTIEN, J,	9209260505	NUREO
VASSALLO, D B	8208030693	50-324 P	VERRELLI.D.M	8208160428	50-241 Q	WARNEKE, B.	9209040122*	50-537 D
VASSALLO, D B.	8208030698	50-259 P	VERRELLI.D M	8208160522	50-261 Q	WARNER, D E.	9209250193*	40-86
VASSALLO, D B	8208040029	50-263 P	VIEBROCK, J. M. VINCENT, R. A. VINCENT, R. A. VINCENT, R. A. VINCENT, R. A.	8208310465*	71-6478	WARNER, D.E.	8208250188*	40-86
VASSALLO, D B	8208040064	50-259 P		8208040176	50-155 P	WARNER, D.E.	8208250194*	FOIA
VASSALLO, D B	8208040077	50-259 P		8208090081	50-155 P	WARNICK, R	8208160472	90-329 8
VASSALLO, D B	8208040216	50-220 P		8208090208	50-155 P	WARNICK, R.F	8208160441*	90-237 0
VASSALLO, D B	8208040220	50-333 P		8208090257	50-155 P	WATKING, L.B.	8208110138	50-382 0
VASSALLO, D B	8208040225	50-333 P	VINCENT, R. A	6208100320	50-155 P	WATSON, E. C	8208180217	NUREO
VASSALLO, D B	8208040555	50-259 P	VINCENT, R. A	8208160258	50-255 G	WATTERS, C R.	8208310447*	50-219 P
VASSALLO, D B	8208040574	50-220 P	VINCENT, R. A,	8208170344	50-255 G	WATTE, K	8208040306	40-4492
VASSALLO, D B	8208040663	50-259 P	VINCENT, R. A	8208230262	50-255 P	WEAVER, L W	8208120211*	50-334 R
VASSALLO, D B	8208050040	50-273 P	VINCENT, R. A	8208230275	50-255 P	WEBER, D. A	8208180267*	50-333 P

AUTHOR	NDI BEBODA RBENUN	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WEBER, H H WEBSTER, C WEDGEWORTH, B WEDGEWORTH, B WEDGEWORTH, B	8208120302* 8208020358 8208030420* 8208030445* 8208030653*	50-416 E 50-537 H 50-416 P 50-416 P 50-416 P	WESTERMAN, T F WETTERMANN, M J	8208270478* 8208020224 8208020224 8208120106 8208120106	50-298 0 27-39 27-39 50-352 0 50-352 0	WILLIAMS.H P WILLIAMS.H P WILLIAMS.H P WILLIAMS.H P WILLIAMS.H P	8208030620* 8207070205 8208050128 8208050445 8208100024	50-416 / 50-334 \$ 50-334 \$ 50-334 \$ 50-334 \$
WEDGEWORTH, B WEEKS, E D WEGST, W F WEGST, W F WEHRING, B W.	8208030665* 8208120316 8208110142* 8208240174* 8208230270	50-416 P 50-133 R 50-142 Q 50-142 Q 50-356 R	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8208120115 8208120115 8208120121 8208120121 8208200138	50-352 0 50-352 0 50-352 0 50-352 0 50-416 0	WILLIAMS, H P WILLIAMS, H P WILLIAMS, H P WILLIAMS, H P	8208130064 8208130066 8208130241 8208130256 8208240167	50-334 \$ 50-334 \$ 50-334 \$ 50-334 \$ 50-334 \$
WEIGAND.O G WEIL.C H WEINFURTER.E WEINFURTER.E WEINKAM.E 3	8208030701 8208310005* 8208050304* 8208160381* 8208170024	GEN TEC IS 50-350 Q 90-245 B 50-254 R 50-322 A	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WHALEN, R WHALEN, R	8208200138 8208270469 8208270469 8208270469 8208020254* 8208310228*	50-416 G 50-458 H 50-458 H 50-247 S 50-249 S	q H.&Maijliu q H.&Maijliu w C.&Maijliu w C.&Maijliu w C.&Maijliu	8208260197 8208300239 8208020127 8208020177 8208020413	50-324 \$ 50-334 \$ 50-335 \$ 50-251 \$ 50-335 \$
Weinkam, e J Weir. p J Weisiger. M L Weisb. a J Weisb. d	8208250314 8208050386* 8208070014 8208260466 8208230432	50-322 A 50-317 & 50-335 P Nureo 40-8102	WHICHER, J # WHICHER, J # WHICHER, J M WHICHER, J M WHICHER, J M	8208040284 8208040284 8208040294* 8208040294* 8208040303*	50-454	M C'SHVITIM M C'SHVITIM M C'SHVITIM M C'SHVITIM M C'SHVITIM	8208030454 8208050248 8208070237 8208110244* 8208120174	50-335 \$ 50-335 \$ 50-335 \$ 50-250 F 50-250 R
WE166, D WE168, E R. WE166, E R. WE166, E R WE166, E R	8208240076* 8207110032 8208020207 8208020207 8208020207	40-8102 FOIA 50-537 0 50-537 0 50-537 0	MHICHEW'N W MHICHEW'N W MHICHEW'N W MHICHEW'N W	8208040303* 8208040308* 8208040308* 8208040314* 8208040316*	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0	WILLIAMO, J W WILLIAMO, J W WILLIAMO, J W WILLIAMO, W W C. SMAILLIAMO	8208140512 8208200115 8208200128 8208200145 8208300317	50-335 8 50-250 5 50-251 5 50-335 8 50-335 8
Weiss, e r Weiss, e r Weiss, e r Weiss, c r Weiss, e r	8208020249 8208020249 8208020249 8208050378 8208050378	50-537	MHICHEW'N W MHICHEW'N W MHICHEW'N W MHICHEW'N W	8208060105 8208060105 8208060133 8208060133 8208160044	50~454	o G GHILLIAMA, J W WILLIAMB, P C WILLIAMB, P C WILLIAMBON, B WILLIAMBON, G G	8208300334 8208300346 8208020358 8208270071* 8208170257*	50-335 8 / 50-335 8 / 50-537 H 50-259 8 50-387 P
Weigs, e r Weigs, e r Weigs, e r Weigs, e r Weigs, e r	8208050378 8208040100 8208040100 8208070258 8208070258	50-537	WHICHER, J M WHICHER, J M WHITE, J. H WHITE, J. H WHITE, J. H	8208160044 8208160044 8208030109 8208030291 8208120143*	50-454 0 50-454 0 REØ REVIEW ORP 50-293 R	WILLIAMBON,R L WILLMAN,P L WILLMORE,R L WILLMORE,R L WILLMORE,R L	8208040258* 8208070176 8208020208 8208020208 8208070243	71-62 50-461 ¢ 50-440 ¢ 50-440 ¢
Weiss.e R Weiss.e R Weiss.e R Weiss.e.R Weiss.e R	8208110157 8208110159 8208110159 8208120093 8208120093	50-537 Q 50-537 Q 50-537 Q 50-537 Q 50-537 Q	WHITNEY, G G WHITNEY, G G WHITNEY, R F WHITNEY, R F WHITNEY, R F,	8208130186 8208260316 8208250383* 8208250371* 8208250402*	50-273 B 50-273 B 50-257 P 50-257 P	WILLMORE, R L	8208090243 8208110158 8208110158 8208120123 8208120123	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0
Weigg, e r Weigg, e r Weigg, e r Weigg, e, r Weigg, e r	8208120093 8208240330 8208240330 8208240330 8208240434	50-537 0 50-537 0 50-537 0 50-537 0 50-289 0	WHITNEY, R F	8208250415* 8208250426* 8208250437* 8208250443* 8208030118	50-259 P 50-259 P 50-259 P 50-259 P Waste Mot	WILLMORE, R L	8208130145 8208130145 8208170271 8208170271 8208240191	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0
Weiss.e R Weiss.e R Weiss.e R Weiss.e.R Welander.c	8208240454 8208240457* 8208240457* 8208250280 8208050286	50-287 0 50-289 0 50-289 0 50-287 0 50-537 H	WHITTEN, J E WIDMAN, J C WIDMAN, J C WIDRIG, R D WIDRIG, R D	8208160449# 8208240088 8208240094# 8208310042# 8208310078#	40-8044 XPORTLIC XPORTLIC FOIA FOIA	WILLMORE,R L WILLMORE,R L WILLMORE,R L WILLMORE,R L WILLMORE,R L	8208240191 8208240235 8208240235 8208300205 8208300287	50-44D 9 50-44D 9 50-44D 9 PRM 50-44D 9
WELLS, C WELLS, D A WELLS, D A WELLS, D A	9208120177 8208020065 8208020132 8208070131 8208070140	50-537 H 50-341 8 50-341 6 50-341 5	WIEBE, J WIEBE, J WIEBEMAN, D O WIEBEMAN, D O WIEBER, A	8208130211 8208200044 8208070073 8208100120 8208230124#	50-320 8 50-320 8 70-2174 I&E XPORTLIC	WILLMORE:R L WILLS,J L WILLS,J L WILSON,B D WILSON,B D	8208300287 8208170341 8208270168 8208040191 8208240077	50-440 9 50-382 8 50-382 8 XPORTLIC XPORTLIC
Wells, D A Wells, D A Wells, D A Wells, D A	8208070154 8208070184 8208170042 8208170134 8208170172	50-341 8 50-341 8 50-341 8 50-341 9 50-341 8	HIEDER, A V HIEBEMANN, R HIEBEMANN, R HIEBEMANN, R HIEBEMANN, R	8208270343* 8207300371* 8207300374* 8207280259* 8207300345*	70-25 TOPREP TOPREP TOPREP TOPREP	MITEON' O C MITEON' O C MITEON' B D	8208240082 8208020358 8208030285 8208030287* 8208030274*	XPORTLIC 50-537 K 50-280 S 50-280 S 50-280 S
WELLS, DA WELLS, HV WELTY, CQ WENDERLICH, R. L WENDERLICH, R. L	8208300080 8208120268 8208250153* 8208050372* 8208070077*	50-341 B 50-537 H 40-86 50-317 S 50-317 S	WIEBEMANN,R,A WIEBEMANN,RA WIEBEMANN,RA WIGGINS,E, WIGGINS,J	8208040146# 8208240400# 8208260268# 8208020068 8208090425	50-266 P TOPREP TOPREP CONTRACT 50-322 B	WILSON, J. L. WILSON, J. L. WILSON, J. L. WILSON, J. L.	8208030463 8208030470* 8208030477* 8208060200 8208060208*	50-281 8 50-281 8 50-281 8 50-280 8 50-280 8
WENDERLICH, R. L WENDERLICH, R. L WENDERLICH, R. L WENDERLICH, R. L WENSLAWSKI, F.	8208230087* 8208260225* 8208310028* 8208310502 8208160325*	50-318 8 50-317 8 50-318 8 50-318 5 50-528 9	WIGGINTON, D WILCOVE, M N WILCOVE, M N WILCOVE, M N	8208130072 8208240179* 8208040210 8208060089 8208060097	50-295 P 50-298 G 50-440 G 50-320 G 50-440 G	MILSON, J L MILSON, J L MILSON, J L MILSON, J L	8208120114* 8208120114* 8208120114*	50~280 \$; 50~280 \$ 50~280 \$ 50~280 \$
HENSLAWSKI, F A HENSLAWSKI, F, A WENSLAWSKI, F A WERNER, R P WEST, A	82081 5047 5# 8208240274 # 820824028# 8208240404 820802021 B	50-275 G 50-344 G 50-312 G 50-213 P 50-327 G	MITCOX' & F MITCOX' & F MITCOX' & D MITCOXE' W W	8208260140 8208040271 8208030244* 8208160224* 8208160282*	50-329	MILSON, J L WILSON, J L WILSON, J L WILSON, J L	8208120170* 8208120175* 8208160268 8208160275* 8208160285*	50-280 8 50-280 8 50-280 8 50-280 8 50-280 8
WEST, A WEST, A. E WEST, J. A WESTBROOK, K. B	8208020218 8208090137 8208090137 8208170257* 8208030124*	50-329 G 50-329 G 50-329 G 50-387 P 40-8784	WILDE, R. M WILEAN, R WILLE, A WILLETT, D J WILLETT, D J	8208250259* 8208030577 8208250395* 8208160115* 8208240295*	40-86 NUREO FOIA 50-187 G 50-133 G	WILBON, J. L. WILBON, J. L. WILBON, J. L. WILBON, J. L.	8208200142 8208200153* 8208200169* 8208270668 8208270674*	20-280 8 20-281 8 20-281 8
WESTEROOK, K B WESTERMAN, T. F WESTERMAN, T. F WESTERMAN, T. F WESTERMAN, T. F	8208040362* 8208160028* 8208160470* 8208170273* 8208240179*	40-8786 50-445	Hilliamb, C C Williamb, C C. Williamb, C. C. Williamb, C C Williamb, C C	8208030176+ 8208130323+ 8208130325+ 8208170302+ 8208240425+	50-373	WILSON, J. L WILSON, J. L WILSON, J. L WILSON, K. L	8208270677* 8208300332 8208300337* 8208300340* 8208040318	50-280 8 50-280 6 50-280 6 50-280 8 40-8781

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WILSON, K L WILSON, R F WILSON, V H WILT, D D WILT, D D	6208050250 6208170084 6208260361* 6207140215 6207140215	50-537 D 50-289 P FOIA 50-440 Q 50-440 Q	WOODHEAD, C P WOODHEAD, C P WOODHEAD, C P WOODS, H W WOODS, H W	8208230078 8208250216 8208250287 8103180387* 8103250395*	50-142 0 50-142 0 50-142 0 50-261 8 50-327 S	YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J	8208110205 8208110243 8208120326 8208130341 8208130376	50-387 P 50-454 A 50-387 P 50-341 Q 50-395 A
WILT, D D	8208070177 8208070177 8208070183 8208070183 8208070247	50-440 G 50-440 G 50-440 G 50-440 H	WOOLDRIDGE, L A WOOLEVER, E J WOOLEVER, E J WOOLEVER, D R	8208030241* 6208250100 8208260329 8208310030 8208040117	50-395 A 50-412 A 50-412 S 50-412 S XPORTLIC	AONOBFOOD' B 7 AONOBFOOD' B 7 AONOBFOOD' B 7 AONOBFOOD' B 7	8208130385 8208130427 8208170011 8208180160 8208180219	50-454 A 50-395 A 50-341 X 50-341 A 50-387 P
WILT, D D WILT, D D WILT, D D WILT, D D WILT, D D	8208070247 8208070250 8208070250 8208070254 8208070254	50-440 H 50-440 G 50-440 G 50-440 H 50-440 H	WRAY, J R WRENN, P C WRIGHT, N A WRIGHT, N A WRIGHT, N A	8208050243* 8208310267 8208040210 8208040271 8208130007	50-293	AONOBFOOD' B ? AONOBFOOD' B ? AONOBFOOD' B ? AONOBFOOD' B ?	8208190023 8208190027 8208230425 8208230478 8208240490	50-358 A 50-387 E 50-341 A 50-387 P 50-546 A
WILVERDING.0 M	8208030263	50-286 P	WRIGHT,N A WRIGHT,N A WRIGHT,N A WRIGHT,R WRIGHT,R WRIGHT,R J	8208180135	50-440 G	YOUNGBLOOD, B J	8208250550	50-341 E
WINKLE,W V	8208260440	NUREO		8208240265	50-237 G	YOUNGBLOOD, B J	8208270486	50-395 E
WINTERHOFF.D	8208300060*	50-373 S		8208260051	50-440 G	YUNDT, C. P	8208100044	50-344 B
WINTERHOFF.D R	8208310253*	50-373 S		8208040568	WASTE MOT	YUNDT, C. P	8208100074	50-344 B
WISNER.C E	8208310178	50-466 S		8208040016	WASTE MOT	YUNDT, C. P	8208100184	50-344 B
WISSINK,R G	8208040673	40-8135	WRICHTIR J	8208040547	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	YUNDT, C P	8208200184	50-344 P
WISSINK,R G	8208040677*	40-8135	WRICHTIR J	8208040551		YUNDT, C P	8208200292	50-344 8
WITHERS,B D	8208030485	50-344 P	WRICHTIR J	8208040621		ZABRISKIE, W L	8208260438	NUREO
WITHERS,B D	8208070070	50-344 P	WRICHTIR J	8208050049		ZAHLER, R E	8208190153	50-289 G
WITHERS,B D	8208100264	50-344 P	WRICHTIR J	8208170371*		ZAHLER, R E	8208190153	50-289 G
WITHERS. 8 D WITHERS, 8 D WITHERS, 8 D WITHERS. 8 D WITHERS. 8 D WITHERS. 8 D	8208170350* 8208230025 8208230294 8208240173 8208240225	50-344 F 50-344 Q 50-344 P 50-344 P 50-344 Q	WRIGHT,R J WRIGHT,R W WRIGHT,W S WRIGHT,W S WRIGHT,W S	8208230441 8208160229# 8208230383# 8208250391# 8208250402#	WASTE MOT 50-335 Q 50-257 P 50-259 P 50-259 P	ZAHLER,R E ZAK,R T ZECH,G Q ZIBULSKY,H ZIELS,B.D	8208300268 8208050331 8208050331 8208300227*	PR 50-537 H 50-309 9 70-135 50-537 H
WITHERS, B D	8208300153	PR	WRIGHT,W 8. WRIGHT,W 8 WRIGHT,W 8 WRIGHT,W 5 WULLER,G E	8208250415#	50-259 P	ZIEMER, P. D.	8208120220	50-537 H
WITHERS, B D	8208300231	REGOD		8208250426#	50-259 P	ZIMMERMAN, J V	8208020455	XFORTLIC
WITTIO, T T	8208050428	50-416 P		8208250497#	50-259 P	ZIMMERMAN, J V	8208030044	XPORTLIC
WIZNER, D G	8208100048*	50-316 S		8208250443#	50-259 P	ZIMMERMAN, J V	8208030076	XPORTLIC
WODEK, D J	8208300005	40-8714		8208060070#	50-461 F	ZIMMERMAN, J V	8208030079	XPORTLIC
WOESBNER,R J	8208100371*	50-317 Q	WULLER, O E	8208260176	50-461 A	ZIMMERHAN, J V	8208030726	XPORTLIC
WOOMAN,N A	8208260564*	WASTE MOT	HULLER, O, E,	8208310226	50-461 E	ZIMMERHAN, J V	8208040078	XPORTLIC
WOOMAS,E J	8208100017*	50-334 Q	WULLER, O E	8208310379	50-461 A	ZIMMERHAN, J V	8208040082	XPORTLIC
WOLF,J F	8208130185	70-2909	HUNDERLICH, J	8208050232*	50-254 8	ZIMMERHAN, J V	8208040077	XPORTLIC
WOLF,J F	8208170263	50-599 Q	WYATT, J. M	8208020358	50-537 H	ZIMMERHAN, J V	8208040105	XPORTLIC
WOLF, J R.	8208170337	50-201 0	WYRICK, T. F.	8208020066#	CONTRACT	ZIMMERHAN, J V	8208040107	XPORTLIC
WOLF, J R	8208300104	50-201 0	YAEGER, W	8208270168	50-302 9	ZIMMERMAN, J V	8208040111	XPORTLIC
WOLFE, J F	8208170125	50-237 0	YAGUINTO, O	8208170010	90-323 A	ZIMMERMAN, J V	8208040123	XPORTLIC
WOLFE, R	8208050458*	50-344 8	YAMANA, K	8208240086	XPORTLIC	ZIMMERMAN, J V	8208040451	XPORTLIC
WOLFE, R	8208130151*	50-346 8	YANDELL, L. A	8208180081#	50-205 Q	ZIMMERHAN, J V	8208060024	XPORTLIC
WOLFE,R	8208130282*	50-346 8	YANDELL,L A.	8208270320*	50-285 Q	ZIMMERMAN, J V	8208060099	XPDRTLIC
WOLFE,S J	8207090111	50-437 0	YEH,O T	8208180222	NUREQ	ZIMMERMAN, J V	8208260332	XPDRTLIC
WOLFE,S J	8208110161	50-382 T	YIN,I.T	8208130325*	50-373 Q	ZIMMERMAN, J V	8208260333	XPDRTLIC
WOLFE,S J	8208130136	50-382 0	YIN,I T	8208270324*	50-341 Q	ZIMMERMAN, J V	8208260337	XPDRTLIC
WOLFE,S J	8208170134	50-382 0	YOSHIHARA,O M,	8208100108*	50-344 B	ZIMMERMAN, J V	8208260342	XPDRTLIC
WOLKEN, M A WOLLETT, B WOLTNER, E WONG, T WOOD, E C	8208160176*	50-298 S	YDUNG, F	8208020377*	50-287 Q	ZIMMERMAN, J V	8208310004	XPORTLIC
	8208260492	CONTRACT	YOUNG, M. A.	8208020231	50-244 G	ZIMMERMAN, J V	8208310470	XPORTLIC
	8208050319*	70-135	YOUNG, M. A.	8208100045	50-454 G	ZIMMERMAN, J V	8208310473	XPORTLIC
	8208040044	40-299	YOUNG, M. A.	8208100073	50-454 G	ZIMMERMAN, R P	8208300052*	50-244 G
	8208020328	50-309 S	YOUNG, M. A.	8208230043	50-454 G	ZIMMERMAN, B R	8208030308	50-400 A
WOOD, E C WOOD, E C WOOD, E C WOOD, E C	8208050315 8208050459 8208090513 8208090072 8208100170	50-309 8 50-309 8 50-309 8 50-309 8 50-309 8	YOUNG, H. A. YOUNG, H. H. YOUNG, T. YOUNG, T. YOUNG, T.	8208230115 8208130477 8207080426* 8208160102* 8208160105*	50-454 C NUREG 50-275 G 50-142 G 50-142 Q	ZIMMERMAN, 8 R ZIMMERMAN, 8 R ZIMMERMAN, 8 R ZIMMERMAN, 8 R ZIMMERMAN, 8 R	8208030309 8208060154 8208100175 8208240166 8208240403	50-324 P 50-261 F 50-324 P 50-261 P 50-324 P
WOOD, E C.	8208230186	50~307 8	YDUNG, T.	8208160111*	50-187	ZIMMERMAN, B R	8208240114*	50-324 F
WOOD, E C	8208230202	50~307 8	YDUNG, T.	8208160115*		ZIMMERMAN, B R	8208270571*	50-261 F
WOOD, E C	8208260271	50~307 8	YDUNG, T	8208160314*		ZINKE, O	8208090149*	50-416 6
WOOD, E C	8208260347	50~307 8	YDUNG, T	8208160525*		ZINKE, O	8208140516*	50-416 6
WOOD, J	8208160462*	50~346 8	YDUNG, T	8208160530*		ZUPKO, J M	8208270176*	50-272 R
WOODFIN, R. L.	8208260112	NUREO	YDUNG, T.	8208240291*	50-528 Q	ZUPKO, J M	8208270594*	80-272 R
WOODHEAD, C. P.	8208040032	50-409 0	YDUNG, T	8208240295*	50-133 Q	ZURAKOWSKI, P	8208230124*	XPDRTLIC
WOODHEAD, C. P.	8208170330	50-142 0	YDUNG, Y A.	8208040542	40-8793	ZWETZIO, O	8208020148	50-361 B
WOODHEAD, C. P.	8208200188	50-409 0	YDUNGBLOOD, B. J	8208050193	50-454 A	ZWETZIO, G	8208160279*	50-520 Q
WOODHEAD, C. P.	8208230052	50-142 0	YOUNGBLOOD, B. J.	8208110064	50-387 P	ZWETZIO, G B	8208240355*	50-344 Q
						ZWDYER: E	8208020358	50-537 H

•			

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Υ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
3M Co , Minnesota Mining & Mfg Co	82080 40673	40-8135			82081 90050	50-348 R	
	8208040677#	40-8135			82081 90051*	50-348 R	
Aamodts, The	82080 90238	50-289	G		82081 60096	50-364 R	
	B2080 90240*	50-289	O		8208160099*	50-364 R	
	82081 10192	50-289	Q		0208140211	50-34B Q	
	82082 50270	50-289	G		9208140211	50-348 0	
	8208250281	50-289	G		8208170225	50-348 P	
Abington Memorial Hosp Abington, PA	82081 60293	REGOD			8208190307	TOPREP	
Academy of Pharmacy Practice	8207180027	FOIA			8208200006	50-348 P 50-348 S	
Ad Hoc Committee for Review of Nuclear	8208300286#	REVIEW G	RP		8208200144	50-348 8	
Reactor Reform Proposals					8208200164	50-348 8	
Aprotest Operations	8208030589	50-228	R		B20B200173*	50-348 8	
Herdren obereasalls	8208030598#	50-228	R		8208200163*	50-348 8	
Agriculture, Dept. of, Forest Service	82080 40349	40-9781			920B200190*	50-348 9	
Agriculture, Dept of	8208020462	40-2061			6206230079	50-348 F	
	B2080 40429	40-8781			8208230079	50-348 F	
	B208240406	50-329	D		8208230315	50-346 P	
	8208240434	50-413	Ď		8208250309	50-348 P	
Air Force, Dept of	8208020066*	CONTRACT			8208250309	50-348 P	
Alabama Power Co	8207010228	50-348	9		8208250314¥	50-34B P	
	8207010228	50-348	8		B20B250314*	50-34B P	
	8207010234*	50-348	g		8208270254	50-348 S	
	8207010234*	50-348	8		8208270254	50-348 B	
	8208020074	50-348	8		8208270261*	50-348 B	
	8208020116	50-348	В		8208270249*	50-348 B	
	8208020118*	50-348	6				
			8		8208270541* 8208270561*	50-348 R 50-348 R	
	8208020122*	50-348 50-348	8		B208270564*	50-348 R	
	8208020131* 8208020171	50-348	8		B208270564*	50-348 R	
	8208020171	50-348	5		8208300311	50-364 8	
	8208020243	50-348	F				
	00400000001 ··	WO 040	g		6208300320* 6208310090*	50-364 B 50-348 F	
	8208030356* 8208050070	50-348 TOPREP	u	Alden Research Laboratory	8208170180#	50-438 A	
	82080 60255	50-344	P	Aliquippa, PA	8208230462*	CONTRACT	
	8208040256*	50-364	p	Allegheny International	B20B130400	40-8724	
	8508090590	50-348	P	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
			_	Allied Chemical Gorp	8208170184*	0A777	
	8208040260	50-348	P	Allied Inspection Services, Inc	8208300172	PR FOT H	
	8208060263	50-348	P	American Association of Engineering	8208020358	50-537 H	
	8208060263 8208060264*	50-349 50-349	P P	Societies, Inc. American Board of Health Physics	0200100251	REGOD	
	8208060264*	30-348	P	American Electric Power Service Corp	8208020156	50-315 P	
					8208060173	50-315 P	
	82080 90181* 82081 00172	50-348 50-348	Q: P	American Environments Co	8208040170*	50-315 P	
	8208120172	50-348	P	American Law Institute - American Bar	8208030385*	REVIEW ORP	
	8208120227	50-348	9	Association			
	8208120227	50-348	8	American Nuclear Insurers	8208180029	50-395 J	
				American Nuclear Society	8208140253	RECOD	
	8208120231* 8208120236*	50-348 50-348	\$ 8		8208260465*	CONTRACT	
	8208130061	50-348	P	American Society of Mechanical Engineer		50-537 H	
	8208130081	50-348	P	American Warming & Ventilating, Inc	8508090505	50-387 9	
	8208130042*	50-348	P	Americans for Democratic Action	B20B040095*	50-537 D	
			_	Amersham Corp	8207110006	FOIA	
	8208130042*	50-348	P		0200250000	71-270	
	8208130174	50-364	P P		8208250090 8208250095*	71-370 71-370	
	8208130180* 8208160015	50-364 50-313	P	Anderson-Greenwood & Co	6208170257*	50-387 P	
	0500100013	20-212		undalabil_alssumded of co	AEGOT LABOLA	20-007 F	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGG	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUDJECT CATEOUR\
Anti-Nuclear Group Representing York Antioch College of Law	8208240414 8208030388 8208170124 8208270508	50-289 50-155 50-155 50-155	9		8208120086* 8208120194 8208120197* 8208160079 8208160082*	50-913 50-968 50-968 50-913 50-913
Applied Health Physics, Inc Applied Science Associates, Inc	8208250126* 8208110049 8208240412*	FOIA 50-247 50-528	R		82081 60250 82081 60504	50-313 50-313
Applied Science needlest Laboratories Approved Engineering Test Laboratory Argonne National Laboratory	8208040267 8208120362 8208130472	71-6601 NUREO NUREO			82081 40504 82081 70127 82081 80601	50-313 50-313
Arzzona Public Service Co	8208260505 8208030650 8208050245 8208050245 8208050245	NUREG 50-528 50-528 50-528 50-528	8 8		82081 80030 82081 80094* 82081 901 54* 82081 901 54* 82082 00040	50-362 50-313 50-313
	8208050418 8208050437 8208160011 8208160011 8208160092	50-530 50-528 50-528 50-528 50-528	8 8 A A		8208200197 8208200170* 8208200277 8208200282* 8208230314	90-313 90-313 90-313 90-313
	82081 60092 82081 60092 82081 60181 82081 70168 82081 70172*	50-528 50-528 50-529 50-528 50-528	A B K		8208230354 8208250298 8208250379 8208250382* 8208260101*	50-313 50-368 50-368 50-368
	8208170190 8208170190 8208170190 8208200205 8208230053	50-528 50-528 50-528 50-528 50-528	AAAA		8208240101* 8208240106* 8208240106* 8208240128 8208270272	50-313 50-313 50-348 50-348
	8208230216 8208230301 8208230301 8208230358 8208240144	50-528 50-528 50-528 50-528 50-528	8 8 8 8		8208270296+ 8208270295 8208270305+ 8208270473+ 8208270452+	50-313 50-368 50-313 50-313
	8208240192 8208240209 8208240262 8208240287* 8208240287*	50-530 50-529 50-528 50-528 50-528	8 6		0208270455# 8208270455# 8208270455# 8208300120 8208300120	20~313 20~313 20~313 20~313 20~313
	8208240287* 8208240383 8208270325* 8208270330 8208270375	50-528 50-528 50-528 50-528 50-528	0 0 0	Armed Forces Radiobiological Research Institute	8208310099 8208310102# 8208310186 8208310172# 8208240194	50-313 50-313 50-313 50-313 50-170
Artions, Univ. of Artions Power & Light Co	6208270376* 6208300251 6208090016 8207270387 6208020078*	50-528 REGOD NUREG 50-313 50-313	I P P	Army, Dept of Atlas Minerals Atomic Industrial Forum	8208030533 8208030537 8208120196* 8208020358	REGOD REGOD 40-3483 50-557
	8208020247* 8208020247* 8208020311 8208030312 8208030312	50-313 50-313 50-313 50-313	F F F F	Auduban Society Automation Industries, Inc 8DM Corp	8208050196 8208100004 8208310451* 8208030744* 8208050023 8208250022*	NUREQ DRO OEN TEC II 50-837 I 71-9006 CONTRACT
	8208030526 8208030530* 8208050199 8208050207* 8208050251*	50-313 50-313 50-368 50-368 50-313	R R S G	BWR Owners Group Beboock & Hilcox Co	6208180027 6208240361 6208310141 6208310340 6208040114	TOPREP TOPREP TOPREP TOPREP NUREQ
	8208050262 8208050265* 8208050334 8208050337* 8208050466	50-368 50-368 50-313 50-313 50-368	8 8		8208040395 8208040168* 8208040217 8208040233 8208090100	71-5149 50-312 F 50-99 L TOPREP PT21
	8208060149 8208060149 8208060155* 8208060174	50-313 50-313 50-313 50-313 50-313	R R R R		82081 60424 82081 60431 * 82081 60435 * 82082 50423 82082 50423	70-120L 50-312 F 50-312 F 71-5768 71-5768
	8208060174 8208060253 8208060266	50-313 50-313 50-368	P P	Babcock & Wilcox Operating Plants Owners Group	8508500051	OEN TEG IE
	8208100102 8208100102 8208100116	50-313 50-313 50-313	P P	Baker & Botts Baltimore Gas & Electric Co.	8208170153 8208020387 8208020368 8208020391*	50-498 C 50-317 E 50-317 E 50-317 E
	8208100121* 8208100190 8208100190	50-313 50-313 50-313 50-313	8 8		8208020374 8208050088 8208050072# 8208050359	50-318 E 50-317 E 50-317 E 60-317 E
	82081 00201 82081 10115 82081 10174 82081 20085 8	50-313 50-313 50-313 50-313 50-313	P G P P R		82080 50364 82080 50371 82080 50375# 82080 50386#	50-317 B 50-317 B 50-318 S 50-318 S 50-317 S

AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT CATEGORY	_	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8208050389 8208050392* 8208050405* 8208040072* 8208040072*	50-317 50-318 50-317	S B S S =		8208240504# 8208270257 8208270257 8208270255 8208270555#	50-317 § 50-317 F 50-317 F 50-317 F 50-317 F
	8208060078* 8208060170 8208060170 8208090044 8208090045*	50-317 50-317 50-317	F P 2 3 3		B20B270555* B20B27055B* B20B27055B* B20B27055B* B20B27055B*	50-317 F 50-317 F 50-317 F 50-317 F 50-317 F
	8208090049 8208090049 8208090064 8208090068* 8208090074	50-317 50-317 50-317	3 3 3 3 3		8208270568* 6208270568* 6208270574* 6208270574* 6208270574*	50-317 F 50-317 F 50-317 F 50-317 F 50-317 F
	82080 90077# 82080 90080 82080 90083# 62080 90110 82080 90115#	50-317 50-317	1 1 3 3 3 3		8208300084 8208310023 8208310028* 8208310032 8208310036*	50-317 { 50-318 { 50-317 { 50-317 {
	8208090221 8208090227#	50-317		Battelle Memorial Institute, Columbus	8208310502 8208240543*	50-318 f FOIA
	8208090252 8208090256# 8208100041	50-318	9 9 9	Laboratories Battelle Hemorial Institute, Pacific	8208310083* 8208130475	FOIA NUREG
	8208100057# 8208100044		3	Northwest Laboratory	8208130480	NUREO
	8208100068* 8208100099 8208100105* 8208100141	50-317 50-317 50-317			8208170306 8208170306 8208180126 8208180217 8208180232	NUREO NUREO NUREO NUREO NUREO
	8208100141 8208100144* 8208100144* 8208100199	50-317 50-317 50-318	1		8208180237 8208190360 8208260075 8208260564*	NUREO REG NUREO WASTE MOT
	82081 00208* 82081 00272 82081 00282* 82081 00282*	50-318 50-317 50-317 50-317 50-317		Bear Creek Uranium Co. Bechtel Corp.	82082 40404 82083 10042 * 82083 10078 * 82081 10053 82081 00097	71-5957 FOIA FOIA 40-8452 50-329
	8208110124 8208110124 8208120272* 8208120301 8208120309*	50-317 i			82081 00343* 82081 20255* 82081 60335* 82081 60342* 82081 70070*	50-482 50-416 50-329 50-329 50-482
•	82081 3002 0 82081 3002 5* 82081 30081 82081 30081 82081 30275	50-317 F	3	Benjamin F. Shaw Co. (subs. of Blount,	82081 70222 82081 70228* 82082 4021 7* 82083 00271* 82080 20358	REGOD 50-348 9A999 50-206 50-537
	8208130276* 8208160145 8208160148*		9 1 1	Inc) Beveridge:Fairbanks: & Diamond	8208300141	50-339
	8208180038 8208180031* 8208230080 8208230087*	50-317 (50-317 (50-318 () }	Bischoff, C A Black River Electric Gooperative Borg-Warner Corp.	8208030311 8208200273 8208050284 8208020348 8208240376#	50-528 50-528 50-537 50-537 50-528
	8208230175 8208230178* 8208230305 8208230305	50-317	3	Boston Edison Co.	8209020342* 8209050162 8208050266 8208050271*	50-293 50-293 50-293 50-293
	8208230323* 8208230323* 8208230371 8208230371	50-317 (50-317 (50-317 (8208050537* 8208100104 8208120141 8208120143*	50-293 50-293 50-293 50-293
	8208230373* 8208230373* 8208240488 8208240491* 8208240493	50-317 (50-317 (8208230234 8208230234 8208270420*	50-273 50-273 50-273
	8208240494* 8208250160 8208250171* 8208250390 8208250393*	50-317 5			9209270620* 9209270620* 9209270623*	50-293 50-293 50-293 50-293
	8208250546 8208250551* 8208250551* 8208260177 8208260218	50-317			8208270623* 8208300210 8208300214 8208300215*	50-273 50-273 50-273 50-273
	8208240225* 8208240229 8208240235*	50-317 E 50-317 E	1 1	Brattleboro, VT Bridgeton, NO Brookhayen National Laboratory	9205300269 9205300276# 9205060025# 9205230016 9207150485	50-293 50-293 CONTRACT 40-8801 REB
	82082	50-318 6 50-318 6 50-317 8		1	8208040002 8208040050	RES RES

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFF ILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	
	8208050009 8208050011 8208110098 8208110241 8208180158	RES RES 50-304 P RES RES		82081 00 195 82081 00 195 82081 10 151 82081 2001 2 82081 2001 3*		Р Р 9
Burns & Roe Ca	8208250029 8208260406 8208260466 8208310075# 8208130483	RES NUREG NUREG FOIA NUREG		82081 20015 82081 20015 82081 2001 6* 82081 20021 82081 20022*	50-324 50-324 50-324 50-325 50-325	A A B B
Bursey, A Businessmen for the Public Interest C-E Operating Plants Owners Group	8208260034 8208160013 8208160044 8208030443 8208030474*	NUREG 50-375 0 50-454 0 TOPREP TOPREP		8208120078 8208120082* 8208120142 8208120146* 8208120177	50-325 50-325 50-324 50-324 50-537	6 6 8 H
G F Braun & Co CONGCO, Inc (Continental Dil Co)	8208130301 8208260171* 8208070027 8208070031* 8208240467	0EN TEC 16 50~373 P 40-8743 40-8743 40-8793		8208130014 8208130016* 8208130143 8208130143 8208130140	50-261 50-261 50-400 50-400 50-400	R C C C
Cabot Corp California, State of	8208040168 8206200027* 8207050009* 8208030213 8208030280*	40-6940 50-275 P 50-537 D REVIEW GRP 50-275 G		8208130140 8208130144 8208130164 8208130181 8208130181	50-400 50-400 50-400 50-400 50-400	0000
	82080 30380 82080 30383* 82080 30389* 82080 50538 82081 70099*	REVIEW ORP REVIEW ORP REVIEW ORP 30-275 G CONTRACT		82081 30200 82081 30200 82081 30284 82081 30286* 82081 30314	50-400 50-400 50-325 50-325 50-325	0 0 8 8
California, Univ of, Irvine	82080-60219 82080-60223# 82081-00291 82080-20289 82080-90182	50-326 R 50-326 R 50-326 H 50-142 0		6208130317* 6208140184 8208140278 8208140320 6208140338*	50-325 50-324 50-241 50-324 50-400	9 0 0
	82081 10139 82081 10142* 82081 30152 82081 30204 82081 90160	30-142 0 50-142 0 50-142 0 50-142 0 50-142 F		82081 60358* 82081 60479 82081 70215 82081 70215 82081 70221*	50-241 50-400 50-400 50-400 50-400	9
Callavey County, MO	8208240174* 8208240249 8208240337 8208240356 8208030735*	50-142 9 50-142 6 50-142 0 50-142 0 CONTRACT		82081 70221 * 82081 70312 82081 70313 * 82081 70313 *	50~400 50~324 50~324 50~324 50~324	6 P P
Carmer & Shapire Carolina Power & Light Co	82082 40227 82060 70827 82080 20085 82080 20087* 82080 20091	50-322 0 50-324 P 50-325 8 50-325 8 50-400 8		8208200012 8208200039 8208200039 8208200058 8208200061	50-325 50-325 80-400 50-324 50-324	8 8 8
	8208020102 8208020105 8208020107* 8208020110* 8208020217	50-325 8 50-324 8 50-325 9 50-324 8 50-400 8		8208200068* 8208200079 8208200089* 8208200110 8208200113	50-324 50-325 50-325 50-261 50-400	8 8
	8208020318 •8208020325* 8208020325* 8208020325*	50-324 P 50-324 P 50-324 P 50-324 P 50-400 8		6208200123* 6208200203 6208200254 8208200264* 6208200285	50-261 50-261 50-324 50-324 50-324	8 8
	6208030362 6208030368 6208030309 6208030309 6208030309	50-325 8 50-325 8 50-400 A 50-324 P 50-324 P		8208200288* 8208230454 8208230458* 8208240157 8208240166	50-324 50-261 50-261 50-400 50-261	8 6 8
	8208030697* 8208040330* 8208040334* 8208050120 8208050124*	50-400		8208240403 8208250207 8208250207 8208270042* 8208270042*	50-324 50-324 50-324 50-261 50-261	G G R R
	8208050202 8208050284 8208050357 8208050381 8208050381	50-400 8 50-400 A 50-261 8 50-400 A 50-400 A		8208270044* 8208270044* 8208270150 8208270160* 8208270219*	50-261 50-261 50-324 50-324 50-324	R R B R
	8208050397* 8208040154 8208090125 8208090128* 8208090148	50-261 8 50-261 F 50-325 9 50-325 8 50-324 8		8208270219# 8208270219# 8208270225# 8208270229# 8208270229#	50-324 50-324 50-324 50-324 50-324	A A B B
	8208090170* 8208090172 8208090174* 8208090212 8208090218*	50-324 8 50-261 8 50-261 8 50-325 8 50-325 8		8208270229* 8208270233* 8208270233* 8208270233* 8208270244	50-324 50-324 50-324 50-324 50-261	R R R

AUTHOR AFF ILIATION	ACCESSION NUMBER	BUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8208270249* 8208270258 8208270266* 8208270381 8208270387*	50-241 50-325 50-325 50-325 50-325	8 8 8		8208240231 8208240231 8208240344 8208240373 8208240373	50-445 50-445 50-445 50-445 50-445	0000
	8208270396 8208270401* 8208270404 8208270406* 8208270412	50-325 50-325 50-325 50-325 50-325	6 8 8 8		8208240378* 8208240378* 8208270419 8208270419 8208270435	50-445 50-445 50-445 50-445 50-445	0
	8208270416* 8208270417 8208270421* 8208270479 8208270484*	50-325 50-324 50-324 50-324 50-324	8 8 8		8208270435 8208270437 8208270437 8208270440 8208270440	50-445 50-445 50-445 50-445 50-445	0000
	8208270491 8208270499* 8208270520 8208270542* 8208270571*	50~324 50~324 50~325 50~325 50~261	8 8 8 F		8208270441 8208270441 8208270443 8208270443 8208270444	50-445 50-445 50-445 50-445 50-445	0 0
	8208270578* 8208300082 8208300091* 8208300109 8208300110*	50~261 50~324 50~324 50~324 50~324	F 8 6 8 9		6208270444 8208270445 8208270445 8208270447* 8208270447*	50-445 50-445 50-445 50-445 50-445	4000
	82083Q0144 82083Q0147* 82083Q0192 82083Q0238 82083Q0244*	50-324 50-324 PR 50-325 50-325	8 8		8208270452 8208270452 8208270453 8208270453 8208270456*	50-445 50-445 50-445 50-445 50-445	00000
	82083 00275 82083 00279* 82083 00333 82083 00343* 82083 10260	50-261 50-261 50-325 50-325 50-324	8 8 9	Citizens Concerned About Nuclear Power, Inc.	8208270456* 8208270624 8208270624 8208090272	50-445 50-445 50-445 50-498	9
Carpentar Technology Corp Carroll Engineering Catholic Univ. Center for Development Policy	8208020358 6208040117 6208300223 6208310531* 6208030752*	50-537 XPORTLIC PR CONTRACT 50-537		Citizens for Nuclear Reactor Bafety, Inc.	8208070278* 8208070278* 8208070278* 8208060119 8208060132 8208120220	50-498 50-498 50-170 50-170	0 0000
Center for Law in the Public Interest	82080 50338 82082 00250 82082 00250 82082 00262 82082 00262	50-275 50-275 50-275 50-275 50-275	90000	City & County Bank Cak Ridge, TN, Cleveland Electric Illuminating Co	8208020208 8208040003 8208070144 8208070144 8208070146	50-537 50-440 50-440 50-440 50-440	H OHOOO
Cerac: Inc. Chamberlin Hanufacturing Corp Chariton Valley Electric Cooperative, Inc. Chem-Nuclear Bustems, Inc Cheme Contracting Corp.	82082 50554 82080 40291 82080 20348 82080 30055 82081 00188	XPORTLIC 40-8211 50-537 71-9151 PR	н		8208090146 8208090243 8208090243 8208100117 8208100117	50-440 50-440 50-440 50-440 50-440	00044
Cherry, M. M./Cherry, Flynn & Kanter Christe-Haria Chromecolour, Inc.	8208040113 8208030388 8208170124 8208270508 8208040550*	50-454 50-155 50-155 50-155 CONTRACT	0000		8208110158 8208120054 8208120054 8208120123 8208130150	50-440 50-440 50-440 50-440 50-440	OEEGA
Cincinnati Oas & Electric Go	8208020204 8208020288 8208020295* 8208030414 8208030418	50-358 50-358 50-358 50-358 50-358	9 K K 9 K		8208130150 8208130165 8208130270 8208130270 8208170271	50-440 50-440 50-440 50-440 50-440	8 8
	82080 90098 82080 90177 82080 90223 82080 90226 82080 90229	50-358 50-358 50-358 50-358 50-358	8 8 8 K		8208170271 8208190246 8208190246 8208240191 8208240191	50-440 50-440 50-440 50-440 50-440	94499
	62080 90263 82081 00149 82081 60170 82081 60185 82081 60231	50-356 50-356 50-356 50-356 50-356	8 8		8208240235 8208240235 8208240296 8208240296 8208240299	50-440 50-440 50-440 50-440 50-440	O O E E O
Citizens Against Nuclear Dangers	8208190148 8208230110 8208240085 8208310244 8208240321	50-358 50-358 50-358 50-358 50-367	0000		8208240279 8208240323 8208240323 8208240436* 8208240436*	50-440 50-440 50-440 50-440 50-440	9 6 8
Citizens Association for Bound Energy	8208130142 8208130142 8208130173 8208130212 8208130212	50-445 50-445 50-445 50-445 50-445	00000		8208260124 8208260124 8208260129* 8208260129* 8208260151	50-440 50-440 50-440 50-440 50-440	K K K
	8208130216# 8208130216# 8208170149 8208240185	50-445 50-445 50-445 50-445	0000		8208260151 8208270506 8208300287 8208300287	50-440 50-440 50-440 50-440	A 0 0 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFF ILIATIO	N	ACCESSION NUMBER	CATEOOR	lY.
Cleveland-Cliffs Iron Co	B208310416 B208310416 B208240022 B208300005 B208300007*		E E			82080 50470 82080 40179 82080 40248 82080 40250 * 82080 40248	50-295 50-373 50-373 50-373 50-237	P P P
Clinton Courier News Clinton, TN Clinton, IL Colorado State Univ Colorado, State of	82081 20248 82082 30024* 82080 40385* 82080 30548 82081 70178	50-537 CONTRACT CONTRACT REVIEW OF REVIEW OF				8208090103 8208090103 8208090132* 8208090228 8208090230*	50-295 50-295 50-295 50-237 50-237	P P 0 8
Colorado, Univ of Columbia River Inter-Tribal Fish Commission Combustion Engineering, Inc	8208180130* 8208240348 8208030213	50-537 50-522 REVIEW 0	T 0			8208090242 8208090245* 8208090246 8208090255*	50-237 50-237 50-245 50-245	8 8 8
	8208050117* 8208060365*	50-336 CONTRACT 50-470	ē.			92081 00049 92081 00056# 82081 00169	50-254 50-254	8
Conmerce Dept of	6208240354* 6208240372 8208300201 6208250388*	50-470 50-470 PRM FOIA	Ā			8208100174* 8208100210 8208100219*	50-254 50-254 50-254	8
Commerce.Dept of, National Marine Fisheries Service Committee to Bridge the Gap	8207120047 8208110178	50-443 50-142	D G			82081 00233 82081 00237# 82081 00330 82081 00334#	50-373 50-373 50-373 50-373	8 8 8 F
	8208110179 8208110195 8208110212	50-142 50-142 50-142	0 6 6			8208110041 8208110041 8208110041 8208110041	50-237 50-237 50-237 50-237	P P
Commonwealth Edison Co	6208200301 6208020117 6208020174 8208020178*	50-142 50-373 50-373 50-373	9 8 8			8208110188 8208110188 8208110188	50-10 50-10 50-10	P P
	8208020179# 8208020184 8208020186* 8208020246	50-373 50-237 50-237 50-247	\$ \$ \$			82081 10188 82081 10188 82081 10188 82081 10188	50-10 50-10 50-10 50-10	P P P
	8208020254* 8208020254 8208020332 8208020344*	50-249 50-454 50-373 50-373	8 6 8			8208110188 8208110188 8208110188 8208110188	50-10 50-10 50-10 50-10	P P P
	8208020351 8208020357* 8208030100*	50-273 50-273 50-273	8 8 F			8208110204* 8208110234* 8208110234*	50-10 50-254 50-254	P F
	9208030103* 9208030184 9208030184 8208030237	50-273 50-275 50-275 50-275	F የ የ			8208110238# 8208110238# 8208110254# 8208110254#	50-254 50-254 50-295 50-295	F F F
	8208030239 8208030245* 8208030245* 8208030254	50-295 50-295 50-295 50-10	P P P			82081 10261* 82081 10261* 82081 10263* 82081 10263*	50-295 50-295 50-295 50-295	F
	8208030245 8208030245 82080303338	50-373 50-373 50-237	P P B			82081 10265# 82081 10265# 82081 10289# 82081 10289#	50-295 50-295 50-373 50-373	F F F
	8208030340# 8208030402 8208030437 8208030441#	50-237 50-579 50-373 50-373	8 9 8			8208120288 8208120294* 8208130018	50-373 50-373 50-373 50-295	R R P
	8208030403 8208030421 * 8208040055 8208040055	50-295 50-295 50-373 50-373	F F P			8208130018 8208130023* 8208130023*	50-295 50-295 50-295	P P P
	8208040119 8208040119 8208040358*	50-373 50-373 50-10	P F			82081 30027 82081 30030 82081 30030 82081 30046	50-454 50-373 50-373 50-237	8 8 8 6 6
	82080 40361 * 82080 40361 * 82080 40361 *		F F			8208130046 8208130046 8208130046 8208130052	50-237 50-237 50-237 50-237	P P
	82080 40475* 62080 40475* 62080 40477* 82080 40481*		는 는 는			8208130055 8208130057* 8208130063*	50-237 50-237 50-237	9 8
	6208040481* 6208040483* 8208040483* 6208050115	50-10 50-10	r F P			8208130103 8208130103 8208130106# 8208130106#	50-295 50-295 50-295 50-295	R R R
,	6208050116* 6208050230 6208050232*	50-249 50-254 50-254	P 8			8208130165 8208130166 8208130166	50-295 50-295 50-295	9 P P
	8208050233 8208050234* 8208050270 8208050304*	50-295 50-295 50-265 50-265	9 6 8			8208130172* 8208130172* 8208130210 8208130218*	50-295 50-295 50-254 50-254	9 9
	8208050310 8208050322* 8208050490		8 8 0			8208130222 8208130223 8208130223	50-254 50-265 50-454 50-454	9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEQUE	RY	AUTHOR AFF I LIAT I	NC	ACCE 9810N NUMBER	SUBJECT CATEGORY	
	82081 30225 82081 30227 * 82081 30231 * 82081 30240 82081 30246 *	50-304 50-265 50-304 50-254 50-254	8 8 8 8			8208200244* 8208200252 8208200263* 8208200276 8208200276	50-254 50-254 50-454	8 8 0 0
	8208130242* 8208130247 8208130272* 8208130277 8208130277	50-295 50-237 50-237 50-454 50-454	Q 8 8 A A			82082300287 8208230026 8208230029 8208230030* 8208230033*	50-373 50-237 50-249 50-237 50-249	6699
	8208130277 8208130277 8208130277 8208130304 8208130304	50~454 50~454 50~454 50~373 50~373	A A A P			9208230058 8208230058 9208230058 8208230058 8208230058	50-454 50-454 50-456 50-454 50-456	A A A A
	8208130307* 8208130311* 8208130311* 8208130313* 8208130322	50~373 50~373 50~373 50~373 50~249	P P P P 8			8208230040 8208230045* 8208230107 8208230107 8208230107	50-373 50-373 50-237 50-237	881
	8208130324* 8208160116 8208160116 8208160140* 8208160157	50~249 50~254 50~254 50~373 50~454	8 R R Q			8208230113* 8208230117* 8208230122* 8208230122* 8208230130*	50-237 50-237 50-237 50-237	1 1 1 1
	8208160159 8208160374 8208160374 8208160381# 8208160417	50~454 50~254 50~254 50~254 50~456	Q R R R			6208230130* 6208230232 6208230236* 6208230242* 8208230252	50-237 50-247 50-247 50-247 50-237	ቸ የ የ የ
	8208140427 8208140438* 8208170085 8208170088* 8208170094	50-254 50-254 50-249 50-249 50-454	8 9 P P			8208230259* 8208230273 8208230277* 8208230292 8208230297*	50-237 50-249 50-249 50-249 50-249	9999
	6208170094 8208170130 8208170130 8208170135 8208170183	50-454 50-454 50-454 50-237 50-373	А Н Н Р			8208230324 8208230324 8208230327 8208230327 8208230332	50-454 50-454 50-454 50-454 50-454	A A A
	8208170187* 8208170219 8208170219 8208170219 8208170219	50-373 50-454 50-454 50-454 50-454	6 6 6 6			8208230332 8208230332 8208230332 8208230332 8208230335*	50-454 50-454 50-454 50-454 50-254	4 4 4 4 F
	8208170219 8208170222 8208170223 8208170226* 8208170240	50-454 REGOD 50-373 50-373 50-454	€ 9 €			8208230335* 8208230349 8208230349 8208230352 8208230354	50-254 50-237 50-237 50-237 50-454	F G G P F
	8208170240 8208170240 8208170240 8208170240 8208170242	50-454 50-454 50-454 50-454 50-10	E E E R			\$2082 30354 82082 30354 82082 30354 82082 30354 82082 30359 *	50-454 50-454 50-454 50-454 50-237	4 4 4 6
	8208170242 8208170242 8208170245* 8208170245* 8208170245*	50-10 50-10 50-10 50-10 50-10	R R R R			8208230359# 8208230377 8208230378# 8208230390 8208230401#	50-237 50-454 50-454 50-247 50-247	0 0 8 8
	8508180005 8508180005 8508180005 8508180005	50-454 50-454 50-454 50-454 50-454	E E			8208240186 8208240189* 8208240200 8208240206* 8208240224	50-3/3 50-3/3 50-3/3 50-3/3 50-3/3	9 9 9
	8208180011 8208180011 8208180011 8208180026 8208180070	50-454 50-454 50-454 50-454 50-295	E E E A F			6208240227* 8208240247 8208240267 8208240267 8208240305	50-373 50-237 50-237 50-237 50-295	P 0 0 0 P
	92081 70014 92081 70014 92081 70014 92081 70014 92081 70014	30-454 50-454 50-454 50-454 50-454	F F F F		4	62082 40340 82082 40345 * 82082 40352 * 82082 4037 4 82082 40430		P P P A
	82081 90018* 82081 90018* 82081 90018* 82081 90018* 82081 90018*	50-454 50-454 50-454 50-454 50-454	F F F F		•	8208250137 8208260024* 8208260024* 8208260047* 8208260047*	50-10 50-10	P F P
	8208200053 8208200063* 8208200137 8208200137 8208200235	50-237 50-237 50-254 50-254 50-373	8 8 F 8			8208240047* 8208240047* 8208240145 8208270250 8208270250		P

AUTHOR AFF'ILIATION	ACCESSION NUMBER	EUDJECT CATEODRY		AUTHOR AFF ILIATION	ACCESSION NUMBER	CATEORY	
	8208270256* 8208270256* 8208270263* 8208270263* 8208270263*	50-254 50-254 50-254 50-254 50-254	Р Р R R		8208060230 8208060230 8208060231 8208060231	50-213 50-213 50-213 50-213	P P P P
	8208270248* 8208270248* 8208270248* 8208270294 8208270294	50-254 50-254 50-254 50-247 50-247	R R R P P		8208040231 8208040247 8208040247 8208040247 8208040247	50-213 50-213 50-213	P F F F
	8208270296 8208270350 8208270350 8208270368* 8208270459	50-247 50-454 50-454 50-373 50-454	P A A G		8208040279 8208040279 8208040279 82081 00142 82081 20238	50-213 50-213 50-213	P P Q Q
	8208270559* 8208270559* 8208270559* 8208270559* 8208270559*	50-249 50-10 50-10 50-10 50-249	R R R R		82081 20297* 82081 60423 82081 60423 82081 60423 82081 60434	50-213 50-213 50-213	R G G F
	8208270567* 8208270567* 8208270567* 8208270567* 8208300039	50-10 50-10 50-247 50-10 50-373	R R R R		82081 90297 8208240384 8208240404 8208260451* 8208260455*	50-213 50-213 50-213 50-213 50-213	P P F F
	8208300060* 8208300063* 8208300101	50-373 50-373 50-373 50-373 50-373	8 8 8 8		8208270271* 8208270271* 8208270276* 8208270276* 8208270351*	50-213 50-213 50-213 50-213 50-213	R R R R
	8208300128 8208300134* 8208300138 8208300140* 8208300182	50-237 50-237 50-373 50-373 50-373	8 8 8 9		8208270551* 8208270554* 8208270554* 8208300075 8208300094	50-213 50-213 50-213 50-213	R R R P P
	8208300189 8208300310 8208300315# 8208310040 8208310048	50-373 50-373 50-373 50-373 50-249	6 6 6 8	Connecticut, State of Conner & Wetterhahn	6206310481* 6206310483* 6206030213 6206020204 6206020224	50-213 50-213 REVIEW 0 50-358 27-39	P P P P P
	8208310052* 8208310092 8208310094* 8208310185 8208310196*	50-249 50-237 50-237 50-273 50-373	8 8 8 8		8208030368 8208030414 8208120101 8208120106 8208120115	50-352 50-358 50-352 50-352 50-352	0000
	8208310218 8208310215 8208310216 8208310216	50-373 50-237 50-373 50-10 50-10	8 0 0		8208120115 8208120121 8208120121 8208120121	50-352 50-352 50-352 50-352 50-352	0000
	8208310218 8208310219 8208310222 9208310225# 8208310228#	50-10 50-373 50-249 50-373 50-247	G 8 8 8		82081 90148 82082 00127 82082 00127 82082 00134 82082 00134	50-358 50-416 50-416 50-416 50-416	0000
	8208310230 8208310234 8208310239* 8208310241 8208310243	50-237 50-373 50-373 50-373 50-373	F 8 8 P 8		8208200138 8208200138 8208200240 8208240236 8208250322	50-414 50-414 50-414 50-352 50-352	99999
	8208310249 8208310250# 8208310253# 8208310279#	50-973 50-979 50-973 50-297 50-297	9 8 8 8	Conservation Council of North Carolina Consolidated Edison Co. of New York	8208270438 8208270469 8208050535 8208020073 8208020229	50-352 50-458 50-400 50-3 50-247	9 4 6 4 8
Computer's Engineering Bervices, Inc.	8208310289 8208310290 * 8208310301 8208310402 8208230285 *	50-373 50-373 50-373 50-254 50-247	8 8 P P Q		8208020232# 8208020368 8208030217 82080303035 8208030728#	50-247 50-537 50-3 50-247 50-3	8 1 0 F
Congress Hatch Connecticut Yankse Atomic Power Co	8208230287* 8205200003 8207210248 8208020076 8208020076	50-247 50-537 50-213 50-213 50-213	Q A F P		8208030730* 8208050217 8208050249* 8208120237* 8208130296	50-3 50-247 50-247 50-247 50-247	F 8 0 0
	#8208020076 8208020076 8208020225 8208020234* 8208020239*	50-213 50-213 50-213 50-213 50-213	P P P P		82081 60004 82081 60005* 82081 60012 82081 60407 82081 70285	50-247 50-247 50-247 50-247 50-247	8 P P
	8208030019* 8208030019* 8208030019* 8208030019* 8208030163	50-213 50-213 50-213 50-213 50-213	e e e e e e e e e e e e e e e e e e e		6208180077 8208180084* 8208190119 8208190119 8208190123*	50-247 50-247 50-247 50-247 50-247	9 9 9 9

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY	AFF II	JTHOR LIATION	ACCESSION NUMBER	EUBJECT CATEODS	RΥ
	9208190123* 9208200291 9208230282 9208230341 9208230347*	50-247 50-247 50-247 50-247 50-247	9 9 9 9 8 8			8208130028 8208130116 8208130118* 8208130215 8208130215	50-255 50-255 50-255 50-329 50-329	6 P P S
	8208240248 8208240252* 8208240132 8208270012* 8208270012*	50-247 50-247 50-247 50-3 50-3	R R S R R			92081 30271 82081 30273* 82081 30274* 82081 30278 82081 30279*	50-255 50-255 50-255 50-155 50-155	R R H B
	8208270012* 8208270016* 8208270016* 8208270016* 8208270590*	50-3 50-3 50-3 50-3 50-3	R R R R			82081 60064 82081 60067 * 82081 60258 82081 60308 82081 60514	50-329 50-329 50-255 50-329 50-329	E Q A B
	8208270590* 6208270593* 8208270593* 8208270637* 8208310178	50-3 50-3 50-3 50-3 50-247	F F F R B			82081 6051 4 82081 70257 82081 70264 82081 70344 82081 8001 2	50-329 50-155 50-155 50-255 50-255	8 0 0 P
Consulting Engineer Consumers Power Co	8208310186* 8208020358 8207070028 8207070028 8207070058*	50-247 50-537 50-329 50-329 50-329	B H K K K			8208180016# 8208180042 8208180046 8208180104 8208190110	50-255 REQUD 50-302 50-155 50-329	P Q Q
	8207070058* 8208020081 8208020218 8208020218 8208020220	50-329 50-155 50-329 50-329 50-329	K P 0 0			8208190110 8208190137 8208190137 8208190146* 8208190146*	50-329 50-329 50-329 50-329 50-329	0 A A 0
	8208020220 8208020282 8208020287* 8208020274* 8208020279	50-327 50-255 50-255 50-255 50-255	9 P P P			8208190433* 8208190434* 8208190435* 8208200023* 8208200211*	50-155 50-155 50-155 50-255 50-261	F G G
	8208020304* 8208020310* 8208020356 8208020340* 8208020345*	50-255 50-255 50-255 50-255 50-255	P P P P			8208230262 8208230275 8208230334 8208240248 8208240309*	50-255 50-255 50-255 50-229 50-329	P P B A
	8208030195 8208030304 8208040049 8208040049 8208040143	50-255 50-155 50-329 50-329 50-329	F O R R A			8208240307* 8208240324 8208240329 8208240374 8208240377*	50-329 50-135 50-135 50-155 50-155	A P P Q
	82080 40148* 82080 40227 82080 40232* 82080 40243* 82080 50072	50-329 50-155 50-155 50-155 50-255	A 0 0 0 0			8208250113 8208260114* 8208270029* 8208270029* 8208270035*	50-255 50-324 50-155 50-155 50-155	P R R R
	82080 50257 82080 50366 82080 60111 82080 60178 82080 60224	50-255 50-155 50-155 50-155 50-155	0 0 0 0			6208270035* 6208270234 6208270246 6208270246 6208270253*	50-155 50-255 50-329 50-329 50-329	R A A
	82080 90055 82080 90055 82080 90081 82080 90137 82080 90197	50-329 50-329 50-155 50-329 50-155	A A P O F			8208270253* 8208270328 8208270333* 8208270337* 8208270414	50-329 50-155 50-155 50-155 50-155	A 0 0 0 0
	82080 90208 82080 90257 82080 90248 82080 90273* 82081 00097	50-155 50-155 50-155 50-155 50-329	8 8 6 6			8208270494 8208270514 8208270518* 8208270531* 8208270531*	50-155 50-155 50-155 50-155 50-155	О С П
	82081 00097 82081 00131 82081 00131 82081 00212* 82081 00217*	50-329 50-329 50-329 50-155 50-155	8 8 9 0			8208270537* 8208270537* 8208270604* 8208270609* 8208270615*	50-155 50-155 50-255 50-255 50-255	R R F F
	82081 00320 82081 10112 82081 10114* 82081 10187 82081 10187	50-155 TOPREP TOPREP 50-329 50-329	P 0 0			8208270635* 8208270638* 8208270639* 8208270639* 8208300282	50-255 50-255 50-255 50-255 50-155	R R R 9
	8208110194 8208110199* 8208110211* 8208120221 8208120223*	50-155 50-155 50-155 50-329 50-329	0 0 0 A			8208300288# 8208310045 8208310108 8208310108 8208310108	50-155 50-255 50-329 50-329 50-329	8 A A E
	92091 20223* 92091 20224* 92091 20224* 92091 20317 92091 20322*	50-329 50-329 50-329 50-255 50-255	A A P P	Continum Dynamics, Control Data Corp	Inc	8208310296 8208310411+ 8208310414 8208310414 8208230073+	50-329 50-255 50-255 50-387 50-275	E G P P B

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC		AFF	AUTHOR FILIATION	ACCESSION NUMBER	GUB. CATE
Contlandt, Town of, NY Cotter Corp Council on Environmental Quality Critical Mass Energy Project	8208170120 6208090001 6208090002# 8208040136 8206200003	50-247 WASTE M WASTE M 50-537 50-537	Q IQT			82081 10184* 82081 10184* 82081 10189* 82081 10189* 82081 10193	50-35 50-35 50-35 50-35 50-35
Culiman Electric Cooperative Cumberland Electric Hambership Corp Cygna Energy Services	8204270073 8207030071 8208020338 8208020358 8208030428	FOIA 50-261 50-537 50-537 50-416	8 H H P			8208130157 8208270432 8208270432 8208270489 8208270489	50-35 50-35 50-35 50-35 50-35
Dairyland Power Cooperative	8208050432* 8208050471 8208060269 8208060307* 8208060312*	50-416 50-409 50-409 50-409 50-409	Р В Р F	Delaware River Ba	esin Commission	8208270500 8208270500 8208170284 8208170284 8208170287*	50-35 50-35 50-35 50-35 50-35
	8208070247 8208070251* 8208100111	50-409 50-409 50-409	9 8 P		esqueces, California,	8208170287* 8207070414	50-35 50-27
	8208100180 8208120218	50-409 50-409	P P	State of, Detroit Edison Co	D.	8208020045 8208020132 8208030183	50-34 50-34 50-34
	8208120291 8208120293* 8208120310* 8208120313*	50-409 50-409 50-409 50-409 50-409	# # # #			8208040148 8208090131 8208090140 8208090184 8208090186	50-34 50-34 50-34 50-34 50-34
	82081 90252 8208200046 8208200076* 8208200083* 8208200206	50-409 50-409 50-409 50-409 50-409	F 6 8 8 8			8208170062 8208170101 8208170106 8208170134 8208170134	50-34 50-34 50-34 50-34 50-34
	8208270223* 8208270289 8208270572* 8208270572* 8208270576*	50-409 50-409 50-409 50-409 50-409	8 R R R			6208180087 8208180099 8208190221* 8208200050 8208200111	50-341 50-341 50-341 50-341
Pallas Horning News	6208270576* 6208310303 6208310374 6208310375 8208260361	50-409 50-409 50-409 50-409 FOIA	R P P			8208200121 8208200162 8208200234 8208230003	50-341 50-341 50-341 50-341 50-341
'ames & Moore 'arte Rural Electric Cooperative. Inc 'ata Consultants Inc. 'avis & Geck, Inc	8208030634 8208030637 8208020358 8208260480* 8208030591	50-285 50-285 50-537 CONTRACT PR	K H T	Dravo Corp		6208240143 6208240147* 6208300080 6208020099* 6208020348	50-16 50-16 50-341 GA999 50-537
DeKalb Area Alliance for Responsible Energy	8208030426	50-454	a -	Duks Power Co.		8208020075 8208020079	50-369 50-269
	6208030426 8208030457* 6208040284 8208040284	50-454 50-454 50-454 50-454	0 0 0			8208020084* 8208020087 8208020090* 8208020121	50-369 50-369 50-369 50-369
	8208040290* 8208040290* 8208040294* 8208040294* 8208040299*	50-454 50-454 50-454 50-454 50-454	0			8208020144 8208020160 8208020164* 8208020168 8208020303	50-361 50-261 50-261 50-261 50-261
	8208040299# 8208040303# 8208040308# 8208040308#	50-454 50-454 50-454 50-454 50-454	0 0 0 0			8208030073* 8208030084* 8208030211* 8208030215*	50-369 50-369 50-369 50-370
	8208040312* 8208040312* 8208040316* 8208040316* 8208060105	50-454 50-454 50-454 50-454 50-454	G G G O			8208030223 8208030242 8208030297 8208030303# 82080303657	50-269 50-413 50-287 50-267 50-413
beyoise & Liberman	8208040105 8208040133 8208040133 8208140044 8208020211	50-454 50-454 50-454 50-454 50-395	0 0 0			8208030358 8208030358 8208030458 8208030456 8208030456	50-413 50-413 50-369 50-369 50-269
	8208030358 8208110162 8208110166 8208170144 8208240358	50-413 80-445 50-413 50-445 90-395	0 0 0			8208030464* 8208030465* 8208030471* 8208030477* 8208030487*	50-349 50-249 50-349 50-369
-Awere Unlimited, Inc	82082 50333 82082 70464 82083 00183 82081 10181 82081 10181	50-445 50-445 PRM 50-352 50-352	0 0			8208030487* 8208030495* 8208030495* 6208030502*	50-349 50-349 50-349 50-349
	8208110184* 8208110184* 8208110185 8208110185	50-352 50-352 50-352 50-352	0			8208030502* 8208030510* 6208030518* 8208030524	50-369 50-369 50-369 50-369 50-413

AUTHOR AFF ILIATION	ACCÆSSION NUMBER	SUBJECT CATEGOR'	,	AUTHOR AFF ILIATIO	ACCESSION NUMBER	SUBJECT	
	8208030541 8208030541 8208030541 8208030541 8208030551*	50-249 50-249 50-249 50-269 50-269	ե Ե Ե		8208190300 8208190300 8208190304* 8208190304* 8208190308*	50-413 50-413 50-413 50-413 50-413	A A A A
	8208030551* 8208030551* 8208030551* 8208030551* 8208030560*	50-269 50-269 50-269 50-269 50-269	P P P P		8208190311* 8208190311* 8208190314* 8208190314* 8208190315*	50-413 50-413 50-413 50-413 50-413	A A A A
	8208030560* 8208030560* 8208030560* 8208030572 8208030579*	50-269 50-269 50-269 50-369 50-369	P P P P		8208190316* 8208190319* 8208190321* 8208190326* 8208190326*	50-413 50-413 50-413 50-413 50-413	AAAA
	8208030609* 8208040169 8208040169 8208050197 8208050203*	50-269 50-369 50-369 50-369 50-369	0 P B 8		82081 70328* 82081 70328* 82081 70332* 82081 70332* 82081 70337*	50-413 50-413 50-413 50-413 50-413	A A A
	8208050244 8208050254 8208050355 8208050402* 8208090232	50-369 50-369 50-369 50-369 50-369	8 0 8 8		82081 70340# 82081 70340# 82081 70346# 82081 70352# 82081 70358#	50-413 50-413 50-413 50-413 50-413	A A A
	#####################################	50-369 50-413 50-413 50-269 50-269	8 F F P P		82081 70358 82081 70363* 82081 70363* 82081 70367* 82081 70372*	50-413 50-413 50-413 50-413 50-413	A A A
	82081 00 193 82081 00 305 82081 00 305 82081 10 164 82081 10 162	50-269 50-369 50-369 50-413 50-269	P F P O F		8208190372* 8208190375* 8208190379* 8208190412* 8208190412*	50-413 50-413 50-413 50-269 50-269	A A F F
	82081 20028 82081 20028 82081 20028 82081 20028	50-269 50-269 50-269 50-269 50-269	F F P P		8208190412* 8208190422* 8208190422* 8208200022 8208200025	50-269 50-269 50-269 50-369 50-269	F F F B P
	8208120034 8208120172 8208120178* 8208120214 8208120214	50-413 50-269 50-269 50-269 50-269	9 8 8 P P		8208200025 8208200025 8208200034* 8208200247 8208200261*	50-269 50-269 50-369 50-369 50-369	6 to 80 to
	8208120216 8208120271 8208120275* 8208130175 8208130238	50-269 50-270 50-270 50-369 50-369	P 33 53 53 53 53 53 53 53 53 53 53 53 53		8208240210 8208240234 8208240237* 8208240237* 8208240242	50-413 50-287 50-287 50-287 50-269	A P P P
	82081 40134 82081 40194 82081 40201 82081 40201 82081 40204	50-369 50-369 50-369 50-369 50-413	0 0 0 0 0		9209240242 9209240242 9209240440 9209250355 9209260136	50-269 50-269 50-267 50-413 50-369	P P A P
	82081 60206 82081 60207 82081 60270 * 82081 60284 82081 60290 *	50-413 50-369 50-370 50-270 50-413	Q Q Q B Q		B20B2&013B* B20B2&0340* B20B2&0340* B20B2&0345* B20B2&03B5*	50-369 50-369 50-369 50-369 50-369	5 5 5 5
	82081 4029 1 82081 4029 1 82081 4035 5 82081 4035 5 82081 40388 *	50-269 50-269 50-413 50-413 50-369	0 0 0 0		8208260385# 8208260392# 8208260430# 8208260437# 8208260437#	50-369 50-369 50-269 50-269 50-269	4 4 4
	8208160388* 8208160412 8208160418* 8208160481 8208160499	50-369 50-369 50-369 50-370 50-369	Q S Q Q		8208260437# 8208260537# 8208260537# 8208260537# 8208260542#	50-269 50-269 50-269 50-269 50-269	F F F F
	8208140499 8208170087 8208170087 8208170087 8208170091#	50-369 50-269 50-269 50-269 50-269	G R R R		8208240542* 8208240542* 8208270125 8208270403 8208270407*	50-269 50-269 50-287 50-270 50-270	F # 8 8 8
	8208170091* 8208170091* 8208170150 8208170151	50-269 50-269 50-369 50-269 50-269	R R R R P P		82082 70597* 82082 70597* 82082 70598* 82082 70598*	50-369 50-369 50-369 50-369 50-269	# # # # #
	8208170151 8208170155* 8208170159 8208170254 8208190140	50-269 50-369 50-370 50-413 50-413	P R R R A Q		8208270503* 8208270503* 8208270503* 8208270507* 8208270507*	50-269 50-269 50-287 50-369 50-369	FI R

AUTHOR AFFILIATION	ACCE SSIGN NUMBER	SUBJEC	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8208270612# 8208270612# 8208270612# 8208270612# 8208270614#	50-287 50-269 50-269 50-269 FOIA	R R		6208310151 6208310152 6208310155 6208310158 6208310160	50-334 50-334 50-334 50-334 50-334	* * * *
	8208270614* 8208270614* 8208300328 8208300328 8208300335*	50-369 50-369 50-413 50-413 50-413	R I I		8208310162 8208310167 8208310168 8208310173 8208310176	50-334 50-334 50-334 50-334 50-334	X X X
	8208300342 8208310074 8208310079* 8208310170 8208310236	50-269 50-287 50-287 TOPREP 50-269	1 9 9		8208310184 8208310187 8208310191 8208310194 8208310197	50-334 50-334 50-334 50-334 50-334	X X X
Duquesne Light Co	8207070205 8207070216* 8208020143 8208030343 8208030343	50-334 50-334 50-334 50-334 50-334	8 9 P R R		8208310199 8208310202 8208310204 8208310207 8208310211	50-334 50-334 50-334 50-334 50-334	K K K
	8208030352 8208050128 8208050129* 8208050445 8208050451*	50-334 50-334 50-334 50-334 50-334	F 8 8 6 8	EDS Nuclear, Inc	8208110222* 8208110225* 8208230266* 8208020060 8208020061	50-331 50-331 50-255 REB RES	F F P
	8208090087 8208090090* 8208090095* 8208090196 8208100024	50-334 50-334 50-334 50-334 50-334	P P P P		8208030045 8208030048 8208030109 8208040004 8208040005	RES RES RES RES RES	
	8208120211* 8208100071 8208100281 8208120208	50-334 50-334 50-334 50-334 50-334	B P P R R		8208040007 8208040010 8208040018 8208040024 8208040027	RES RES RES RES RES	
	8208120244 8208120250 8208120253* 8208120257* 8208120034	50-334 50-334 50-334 50-334 50-334	ቴ ሴ ዩ		8208040036 8208040043 8208040109* 8208040167 8208040260*	REB 50-389 REB 50-382	A A
	8208130064 8208130066 8208130070* 8208130073* 8208130241	50-334 50-334 50-334 50-334 50-334	8 B B B 8 8		8208040355* 8208060039 8208060052 8208060054* 8208060056	50-247 REB REB 50-313 REB	Q P
	8208130245* 8208130256 8208130259* 8208160014 8208170099	50-334 50-334 50-334 50-334 50-334	9 8 8 0 F		8208110008 8208170003* 8208180247* 8208170354 8208230428*	REB 50-155 50-333 50-313 50-341	P P A
	8208190169* 8208200069 8208240167 8208240169* 8208240312	50-334 50-334 50-334 50-334	р Р Р		8208240045 8208240446* 8208250074 8208260097 8208260434	REB 50-155 REB NUREQ NUREQ	P
	8208240313* 8208250100 8208260197 8208260203* 8208260329	50-334 50-412 50-334 50-334 50-412	F A 8 8 8	EM Chemicals	8208260486 8208270692* 8208300038* 8208130347 8208130351*	NUREO 50-329 50-213 40-8623 40-8623	A P
	8208270400 * 8208300239 8208300242* 8208310030	50-334 50-334 50-334 50-412	F 8 8 8	ESCO Corp East Tennessee Development District Ebasco Services. Inc (subs of Enserch Corp.)	9208020358 9208100051 9207230345*	50-537 50-537 50-389	H D F
	8208310095 8208310100* 8208310101	50-334 50-334 80-334	K K		9207230349* 9208030181 8208030296	50-387 50-387 50-389	F R R
	8208310104 8208310107 8208310109 8208310110	50-334 50-334 50-334	K K K		8208120061 8208180061 8208190193 8208200003	50-389 50-389 50-389 50-389	A B A
	8208310114 8208310117 8208310120 8208310122 8208310122	50-934 50-334 50-334 50-334	К К К	Edgar, O L	8208250111 8208300198 8208310209 8208110160 8208110170	50-387 PRM 50-387 50-537 50-537	R R C
	8208310129 8208310131 8208310134 8208310137	50-334 50-334 50-334 50-334	K K K	Ediow International Co. El Paso Electric Co. Electric Power Research Institute	8208060104 8208260347 8208260596 8208270388* 8208040138	XPORTLIC XPORTLIC 71-6678 50-528 NUREO	
	8208310140 8208310142 8208310146 8208310148 8208310149	50-334 50-334 50-334 50-334 50-334	K K K K		8208040434 8208260355* 8208260428* 8208310325*	50-537 CONTRACT CONTRACT 50-388	Ī

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	Y
Electrical Calibration Lab Energy Engineering Oroup	8208030133 8208250397#	NUREG FOIA	-	First American Bank Clinton, TW, Filnt Hills Rural Electric Cooperative	820B120177 820B020358	50-537 50-537	H
Energy Incorporated Energy, Dept of	8208170207* 8208170213* 8206300099	GA979 GA999 50-537	A	Association, Inc Florida Power & Light Co	8207230343 8207230349* 6208020127	50-389 50-389 50-335	F S
	8208020215 8208030118 8208030584 8208040219 8208040224*	WASTE MOT NUREO 50-537	o o		8208020135* 8208020177 8208020180* 8208020413	50-335 50-251 50-251 50-335 50-335	88888
	8208040313 8208050027 8208060181 8208110160 8208110190	50-537	0		8208030170 8208030332 8208030336 8208030429 8208030454	50-335 50-387 50-335 50-389 50-335	P S P S S
	8208130147 8208130289 8208130291# 8208170391 8208200283	50-537 50-537 71-9184	Q A A		8208030456 9208030461* 8208030468 8208030624* 8208030628	50-387 50-335 50-387 50-335 50-387	8 8 A 0
	8208250005 8208250367* 8208300272 8208300322 8208310312	71-6574 FOIA REQQD 70-143 50-537	A		82080 40455* 82080 50248 82080 50252* 82080 60185 82080 60278	50-387 50-335 50-335 50-387 50-335	F 8 8 A P
Energy Dept of, Clinch River Braeder Reactor Plant	8208020097	50-537	B		6208090041 8208090205	50-250 50-369	F B
	8208020101* 8208030313 8208030540 8208050307	50-537 50-537 50-537 50-537	B F A C		82080 70237 82080 70237 82080 70270	50-335 50-335 50-387	8
	8208060164 8208060167* 8208090141 8208110103 8208230264	50-537 50-537 50-537 50-537 50-537	A B B B		8208100044 8208100075 8208100095 8208100114 8208100130	50-397 50-250 50-335 50-335 50-250	P P P
Engineers International Environmental Action Inc	8208230247# 8208310208 8208040340# 8208040002# 8208070018#	50-537 50-537 CONTRACT CONTRACT 50-537	B B		8208100130 8208100187 8208100198 8208100312 820810031&*	50-250 50-335 50-335 50-389 50-389	P P K K
Environmental Law Project Environmental Policy Institute Environmental Protection Agency	8208300314 8208040080* 8208040318 8208050250 8208060004	PRM 50-537 40-8781 50-537 40-2041	D D		82081 10242* 82081 10244* 82081 20019 82081 20020* 82081 20051	50-250 50-250 50-389 50-389 50-335	F K K P
European Communities, Commission of Exelca Developments, Inc Execon Corp.	8208060162 8208310189 8208110229* 8208020358 8208060005	50-482 50-443 XPORTLIC 50-537 40-8044	D D		8208120174 8208120174 8208120174 8208120174 8208120181*	50-250 50-250 50-250 50-250 50-250	R R R R
Exxon Nuclear Co , Inc (subs of Exxon Corp.)	8208100158	TOPREP			8208120181* 9208120181*	50-250 50-250 50-250	R R H
	82081 00285 82081 20030 82081 20080 82081 20087*	TOPREP TOPREP TOPREP TOPREP			8208120181* 8208120186* 8208120186*	50-250 50-250	R R
	8208120078 8208170188* 8208170204* 8208230435*	TOPREP 50-244 50-244 40-8102	p P		9208130039 8208130039 8208130042* 8208130042* 8208160058	50-250 50-250 50-250 50-250 50-335	£ 6
FQI Services	8208230440* 8208230440* 8208240076* 8208240097 8207050077	40-8102 40-8102 40-8102 XPORTLIC 71-6698			82081 60071 82081 60071 82081 60165 82081 60197 82081 60267	50-335 50-335 50-389 50-335 50-250	F 00 00
Farmers Electric Cooperative, Inc. Fauske & Associates, Inc	8208020358 8208170261*	50-537 50-155	H P		82081 60267 82081 60296 82081 60303*	50-250 50-251 50-251	Q Q Q
Federal American Partners Federal Emergency Management Agency	8208040295 8208040306 8206200094 8208020376	40-4492 40-4492 COMMISSI 50-206	ON F		92091 40343+ 92091 40345+ 92091 40345+	50-369 50-250	ā ē
	8208040251* 8208100035* 8208100039* 8208100151*	50-309 50-247 50-247 50-286	FFF		92091 60376* 92091 60512 92091 60519* 92091 70102	50-250 50-335	0 8 8
	82081 00155# 82081 10107 82081 10118 82081 90053# 82081 90081	50-286 50-335 50-416 COMMISSI 50-263	F		8208170102 8208170116 8208170116 8208170123 8208170123	50-250 50-250 50-250 50-250 50-250	P
Federal Energy Regulatory Commission	82081 90084* 82081 90180 82081 90180 82080 30501	20-509 20-509 20-509 20-593	F F F RP		8208170203 8208180065 8208170152 8208170150	50-335 80-389 50-250 50-389	A

AUTHOR AFFILIATION	ND188300A RBMUN	EUDJEC	RY		THOR IATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8208200085 8208200115 8208200125* 8208200128 8208200133	50-389 50-250 50-250 50-251 50-250	R 8 8 9	General Electric Co		9206070868* 9207110016 9207120147 9207120253* 9208030135*	50-324 FOIA 50-447 50-447 70-1113	P A A
	8208200133 8208200144* 8208200145 8208200175* 8208200174	50-250 50-251 50-335 50-335 50-335	P 8 8 8 8			8208030237* 8208030270 8208030355 8208030359* 8208030360*	50-409 TOPREP 50-447 50-447 50-447	P K K
	8208200295 8208200295 8208200299* 8208200299* 8208230007	50-250 50-250 50-250 50-250 50-250	ե ե ե			8208030581 8208040191 8208050248 8208110111 8208130335	50-447 XPORTLIC PT21 TOPREP 71-5926	. ^K
	8208230345 8208230370 8208240193 8208270064* 8208270066*	TOPREP 50~335 50~387 50~250 50~250	P A R R			92081 30334 82081 70252* 82081 70255* 82082 40077 82082 40082	71-5939 50-387 50-387 XPORTLIC XPORTLIC	
	8208270044* 8208270072* 8208270072* 8208270072* 82082700119	50-250 50-250 50-250 50-250 50-389	R R R R S			8208240083 8208240289 8208260213 8208260355* 8208260428*	TOPREP 50-271 50-416 CONTRACT CONTRACT	
	6206270304 6206270540* 6206270540* 6206270540* 6208270540*	50-387 50-250 50-335 50-250 50-250	8 R R R			8208270273* 8208270650 8208300207 8208300247 8208310111	50-254 70-1113 PRM REGOD TOPREP	P
	8208270545* 8208270545* 8208270545* 8208200187 8208300319	50-250 50-250 50-250 50-387 50-335	R R R F 8	General Electric Ope Group General Public Utili		8208310347* 8208310353* 8208090189	TOPREP 50-387 TOPREP 50-219	E
	8208300323*	50-335	8	Corp	Ifids - OLO SHATER			
	6208300334 6208300339* 6208300346 6208300348*	50-335 50-335 50-335 50-335	8 8 8			8208030307# 8208040274# 8208040278# 8208050084 8208050091#	50-289 50-289 50-219 50-219	X FFSS
Florida Power Corp	8208310265 8208310266* 8208030272 8208090133 8208090136*	50-387 50-387 50-302 50-302 50-302	A A P 8 8			8208050123 8208050125* 8208050126 8208050130* 8208050131*	50-289 50-289 50-219 50-289 50-219	P F 5 F 8
	82081 60084 82081 60073* 82081 60213 82081 6031 6* 82081 60360	50-302 50-302 50-302 50-302 50-302	R R Q Q			82080 50270 82080 50272 82080 50274* 82080 50277* 82080 50346	50-219 50-320 50-219 50-320 50-219	8 8 8 8
	82081 60468 82081 80021 8208200093 8208200095 8208200100*	50-302 50-302 50-302 50-302 50-302	Q P 8 8			92080 50358* 92080 50443 92080 50453 92080 50460* 92080 60062*	50-219 50-219 50-219 50-219 50-320	* ***
	8208200154 8208200172* 8208200219 8208200229* 8208270395	50-302 50-302 50-302 50-302 50-302	8 8 9 9			8208060064* 8208060177 8208060201 8208060247	50-320 50-320 50-217 50-217	F Q P
iter Wheeler Corp. anklin Institute/Franklin Research	8208270358* 8208310507 8208310511* 8208030543 8208220204*	50-302 50-302 50-302 PR 50-29	8 8 8			8208040257 8208100177 8208100213# 8208100238 8208100247	50-219 50-320 50-219 50-320 REQQD	P 0 8
entor	8204280418* 8204280528* 8204300143* 8207240247* 8208030149*	50-307 50-287 50-321 50-213 50-29	a a a P P			8208100250* 8208100275 8208100275 8208100278 8208100298 8208100302 8208100307*	50-320 50-289 50-289 50-320 50-320 50-320	8 R F P P
	8208040740# 820804071# 8208050028# 8208050161# 8208170163#	50-259 CONTRAC 50-313 50-206 50-213	Р Р Р			9208110116 9208110123 9208110217* 9208110218* 9208120037 9208120038*	50-320 50-320 50-320 50-320 50-219 50-219	PFFRR
Friends & Family of THI GA Technologies, Inc /Oeneral Atomic Co	8208240344* 8208250546* 8208260501* 8208040047* 8208260061	50-244 50-245 CONTRAC' 50-289 XPORYLIG	H			9208130013 9208130184 9208130255 9208130258* 9208140034	50-289 50-320 50-219 50-219 50-219	
GH Bettim Corp Gage-Babcock Associates, Inc	8208240049* 8208240330 8208110177 8208040480*	XPORTLIC XPORTLIC PT21 CONTRAC	C			8208140035# 8208140174 8208140177#	50-219 50-219 50-219	8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT CATEGOR!	
	82081 40292 82081 60494 82081 70209 82081 70337* 82081 70359*	50-287 50-320 50-289 50-289 50-289	F F F	44 	82080 90271 82080 90274 82080 90277* 82080 90277* 82080 90279* 82081 10248*	50~321 50~321 50~321 50~321 50~321	
	8208170394 8208180033 8208180040* 8208180054 8208180060*	71-9158 50-320 50-320 50-320 50-320	9 8		8208110248* 8208110249* 8208120109 8208120114* 8208120129	50~321 50~321 50~366 50~366 50~321	F S S I
	8208190074 8208190077# 8208190086 8208190124 8208190157	50-289 50-289 50-289 50-289 50-219	R R P F P		8208120191 8208120191 8208120198* 8208120199 8208120228*	50-321 50-366 50-366 50-321 50-321	1 9 8 8
	8208190184 8208190200 8208190204* 8208190210* 8208190237*	50-287 50-287 50-289 50-289 50-287	FPPG		B208130156 B208130159* B208160091 B208160091 B208160094*	50~366 50~321	8 8 8 8 8
	62081 90305 62081 90309* 62082 00021 62082 00033 62082 00036*	50-219 50-219 GEN TEC 50-320 50-320	0 18 P		82081 60094* 82081 60238 82081 60272 82081 60454 82081 60469*	50-321 50-364 50-321 50-321 50-321	R 8 8 8 8
	8208240230 8208250320 8208260174 8208260177* 8208260201	50-219 50-320 50-219 50-219 50-289	P 8 8		8208160503* 8208160503* 8208160524* 8208200005 8208200045	50-424	8999
	8208270019* 8208270019* 8208270019* 8208270023* 8208270023*	50-289 50-289 50-289 50-289 50-289	R R R		8208200052* 8208200161 8208200284 8208200289* 8208260217	50-321 50-424 50-366 50-366 50-321	8888
	8208270023* 8208270103 8208270111* 8208270262 8208270267	50-289 50-219 50-219 50-289 50-289	R P F		8208240217 8208270137 8208270145* 8208270228 8208270232*		6 6 6 6
	8208270267 8208270280* 8208270280* 8208270288* 8208270288*	50-287 50-219 50-219 50-219 50-219	F R R R		8208270235 8208270241* 8208270297 8208270302* 8208270455	50-321 50-321 50-321	8888
	8208270290 8208270300 8208270495* 8208270649* 8208270649*	50-320 50-320 50-289 50-289 50-289	P 8 0 R R		8208270451* 8208270534 8208270539* 8208270628* 8208270628*	50-366 50-366	8 8 8 R
	8208270649* 8208270656* 8208270656* 8208270656* 8208300055	50-289 50-289 50-289 50-289 50-219	R R R S		8208270628* 8208270631* 8208270631* 8208270631* 8208300113	50-321 50-321 50-321 50-321 50-366	R R R R
Ganava, IL	8208310177 8208310413 8208310440 8208310447* 8208310187	50-289 50-219 50-219 50-219 50-454	F P I		8208300115* 8208300158 8208300161* 8208300173 8208300174*	50-346 50-321 50-321 50-321 50-321	****
George M. Eady Co. Georgia Power Co	6208020358 6208030377* 6208030377* 6208030442 6208030450*	50-537 50-321 50-321 50-321 50-321	В В Н	Osotrans, Inc	8208300230 8208300235* 8208300344 8208300347* 8208130474	90-321 50-321 50-364 90-366 Nureo	888
	8208030503 8208030508 8208040192 8208040192 8208040194*	50-321 50-321 50-321	ե Ե	Gerbus Brothers Construction Gibbs & Hill. Inc. (subs. of Dravo Corp.) Gilbert/Commonwaalth Cos. Gimpel Corp Goider Associates	6208020308 8206030299 8208040186# 8208020358 8208040498#	50-537 50-289 50-395 50-537 CONTRACT	HKAH
	8208040176* 8208060044* 8208060044* 8208060047* 8208060047*	50-321 50-321 50-321 50-321	1 1 1 1 1	Government Accountability Project	8208040643* 8207050083 8208030331 8208040264 8208070150	CONTRACT 50-358 50-358 50-358 50-359	9009
	8208060055* 8208060055* 8208060037* 8208060057* 8208060182	50-321 50-321 50-321 50-321 50-366	E I I I I I	Graduate School, Agriculture, Dept of,	8208240362 8208240362 8208240382 8208240385* 8208240354*	50-358 50-358 50-358 50-358 CONTRACT	9999
	8208060187* 8208060189 8208060193 8208060194* 8208060195*	50-366 50-366 50-366 50-366 50-366	8 P 9 P	Gray Panthers Graely.CD Grundy Gounty, IL Guild, R Guild Nuclear, Inc	8208180044 8208170420* 8208180037 8208180191 8204190004*	50-247 CGNTRACT PRM 50-413 71-9161	1 c

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	IRY	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
Gulf States Utilities Co	8208030283 8208040434 8208050110 8208050316 8208100070	50-458 50-537 50-458 50-458 50-458	S H S S S		82080 90278* 82081 00083 82081 00083 82081 60460 82081 60460	50-498 50-498 50-498 50-498 50-498	0 A 8
	8208140008 8208170137 8208170217* 8208200031 8208200031	50-458 50-458 50-458 50-458 50-458	8 8 Q A		8208170110 8208170114 8208170114 8208170153 8208170153	50-498 50-498 50-498 50-498 50-498	9 0 0
	8208230295 8208230295 8208240047 8208240063 8208240393	50-458 50-458 50-458 50-458 50-458	A A B B		82081 70258 82081 70258 82081 70260 82081 70260 82081 70282	50-498 50-498 50-498 50-498 50-498	0000
Harmon & Heiss	8208270469 8208310256 8207110032 8208020207 8208020249	50-458 50-458 FOIA 50-537 50-537	H 6 0 9		8208170282 8208250248 8208250292 8208260292 8208260292	50-498 50-498 50-498 50-498 50-498	A A A B
	8208050378 8208040100 8208070258 8208110157 8208120093	50-537 50-247 50-289 50-537 50-537	0 0 0	Human Factors Society, Inc	8208270423 8208270454 8208270454 8208210063 8208260002	50-498 50-498 50-498 50-498 NUREQ	8 8 8
	8208190116 8208200232 6208200232 8208200257 8208200265	50-528 50-329 50-329 50-329 50-329	0 0 0 0	Hunton & Williams	8208260017 8208020209 8208030301 8208110150 8208110164	NUREG 50-322 50-322 50-322 50-322	0
	6208200265 8208200275 8208240330 8208240454 8208240457*	50-329 50-329 50-537 50-289 50-289	0 0 0 0		8208110167 8208110168 8208110169 8208110170 8208200270	50-322 50-322 50-322 50-322 50-322	000
Harold J. Egelman & Associates Harstead Engineering Associates.Inc Health & Human Bervices, Dept. of.	8208250280 8208260006 8208300318 8208250358# 8208260585#	50-289 FOIA 40-2061 50-413 50-289	A P	Hydro-Engineering ITT Research Institute	8208250253 8208250264 8208300305 8208040614* 8208040185	50-322 50-322 50-322 40-8745 REVIEW G	Q Q Q Q
Henry J Kaiser Co Henry Pratt Co Hull-Christopher & Phillips Hittman Nuclear & Development Corp (subs Hittman Corp)	8208050438 8208040434 8208030280* 8208170018*	50-358 50-537 50-275 71-9086	8 H Q	Ichthyological Associates, Inc Illinois Power Co.	8208100278* 8208050313 8208050413 8208050477 8208060070*	50-287 50-461 50-461 50-461 50-461	8 8 8
	8208170035* 8208170038* 8208170052* 8208170053* 8208200274*	71-9151 71-9151 71-9151 71-9151 50-387	P		8208170127 8208170217 8208240176 8208300142 8208300143*	50-461 50-461 50-461 50-461 50-461	8 6 6 6
Hopper & Associates, Engineers Horry Electric Cooperative, Inc Hourihan, P	8208200243* 8208020358 8208170116 8208170116 8208170116	50-341 50-537 50-528 50-528 50-528	E H G G	Illinois, State of	8208310226 8208310308 8208310379 8207180028 8208030556	50-461 50-461 50-461 40-2061 PRM	¥
use of Rep	8208190159# 8208190159# 8208190159# 8204060022# 8204200036#	50-528 50-528 50-528 50-247 50-250	0 0 U H		8208040107 8208090176 8208130327 8208130332 8208130391	27-39 50-461 40-2061 40-2061 40-2061	•
	8204200039* 8204270038* 8207050016* 8208020354 8208030479	50-320 50-537 50-289 50-537 PR	U D H U	Illinois, Univ of, Urbana-Champaign	8208170182 8208260066 8208310245 8208230270 8208230271*	50-373 NUREO 50-373 50-356 50-356	g R R
use of Rep , Interior & Insular Affairs use of Rep , Science & Technology uston Lighting & Power Co	82081 00242 82061 30005* 82080 70053* 82080 20248 82080 30197	RECOD 50-358 50-358 50-537 50-478	U U U A	Indiana & Michigan Electric Co	8208030527 8208040172 8208040172 8208040179* 8208040179*	50-315 50-315 50-315 50-315 50-315	b b b
	8208030197 8208030219 8208030219 8208030266 8208030266	50-498 50-498 50-498 50-498 50-498	A B B B		8208090054 8208090056 8208090056 8208090059* 8208090059*	50-315 50-315 50-315 50-315 50-315	F P P
	9208030542 9208030542 9208050447 9208050454* 9208060092	50-498 50-498 50-498 50-498 50-498	8 8 A A		8208100052 8208100058# 8208100175 8208100175 8208100295	50-315 50-315 50-315 50-315 50-315	6 6 8
	82080 60092 82080 90272 82080 90272 82080 90278#	50-498 50-498 50-498 50-498	9		8208100338 8208100342* 8208100347* 8208120210 8208120212*	50-315 50-315 50-315 50-315 50-315	9 9 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y	AUTHOR AFFILIATION	ACCEBBION NUMBER	TOBJECT CATEOOR	
	82081 20260 82081 20274* 82081 60006 82081 60007* 82081 60345	50-316 50-316 50-315 50-315	R R S S S	Isham, Lincoln & Beale	8208020218 8208020218 8208020220 8208020220	50-329 50-329 50-329 50-329 50-454	0 0
	8208140351* 8208230054 8208230054 8208230057* 8208230062	50-315 50-315 50-315 50-315 50-316	S K K S		8208030304 8208030402 9208040227 8208040232* 8208040243*	50-155 50-599 50-155 50-155 50-155	0
	8208230066* 8208230212 8208230223* 8208230235	50-316 50-316 50-315 50-315 50-315	\$ \$ \$ \$ \$ \$		82080 60111 82080 90137 82081 10187 82081 10194 82081 60159	50-155 50-329 50-329 50-155 50-454	0 0 0
	8208230254* 8208230340 8208230340 8208240052 8208240052	50-315 50-315 50-315 50-315 50-315	8 F G G		8208170130 8208170264 8208170110 8208240267 8208240374	50-454 50-155 50-329 50-237 50-155	H 0 0 0
	6208240274 6208240274 6208260284* 6208240284* 8208270314	50-315 50-315 50-315 50-315 50-316	6 6 8		8208240377* 8208270328 8208270333* 8208270337* 8208270414	50-155 50-155 50-155 50-155 50-155	0000
	8208270317 8208270317 8208270321* 8208270334* 8208270373	50-315 50-315 50-316 50-316 50-315	P 8 8 8	Ishikawagima - Harima Heavy Industries Co (Ltd	8208270457 8208270514 8208270518* 8208310328*	50-454 50-155 50-155 50-388 50-388	9
	8208270379* 8208270386* 8208270643* 8208300035 8208300035	50-319 50-315 50-315 50-315 50-315	8 R F F	Isotope Measurements Laboratories, Inc J A Jones Construction Co J F T Agapito & Associates, Inc James Valley Electric Cooperative, Inc	8209310339* 8209300266 8209040434 8209260459* 8209050286	50-388 REGGD 50-537 CONTRACT 50-537	Q. H
Indiana & Michigan Power Co	8208310103 8208310106* 8208310359 8208310365* 8208030205	50-315 50-315 50-316 50-316	8 8 8 6 8	Japan Jersey Central Power & Light Co	8208240013 8208310041 8208310049 8208160168* 8208270284	XPORTLIC XPORTLIC XPORTLIC 50-363 50-219	: 1
1	8208030209* 8208050354 8208050342* 8208050347 8208050372*	50-316 50-315 50-315 50-316 50-316	\$ 5 6 6 6	Joint Applicants-Clinch River Breeder Reactor Joint Applicants-Palo Verde	8208170109 8208170117 8208020205 8208030311	50-537 50-528 50-528	T G G
Industrial Fabricating Industrial Nuclear Co	82081 00042 82081 00048* 82082 40484 82080 40254 82080 40258*	50-316 50-316 71-9128 71-62 71-62	8 8	Joint Intervenors-Diable Canyon	8208240118 8208200273 8208050338 8208200250 8208200250	50-528 50-528 50-275 50-275 50-275	T
Institute for Public Representation Interior, Dept of, Geological Gurvey International Brotherhood of Electrical Workers Iowa Electric Light & Power Co	8208040132 8208020349 8208300274 8208040381* 8208040382*	50-170 50-522 PR 50-331 50-331	6 A F F	Joint Intervenors-Waterford Jones-Onslow Electric Hembership Corp. KMS Fusion, Inc. (Subs of KMS Industries,	8208200262 8208200262 8208270481 8208040369 8208240088	50-275 50-275 50-382 50-537 XPORTLIC	g G H
	82080 5037& 62080 50363* 82080 70093 82080 70094* 62080 70147	50-331 50-331 50-331 50-331 50-331	8 8 8	Inc) Names Gas & Electric Co.	62062 40094* 82080 40180 82080 40181* 82080 50194* 82081 00034	XPGRTL 10 50-482 50-482 50-482 50-482	C K G 9
	82081 00045 82081 00128 82081 00139 82081 10225* 82081 30140	50-331 50-331 50-331 50-331	5 8 8 F 8		82081 00339 82081 60265 82081 70067 82081 70074 82082 00197	50-482 50-482 50-482 50-482 50-482	A E 8 8
	9208130144* 9208130233 9208130237* 9208170092 9208170243	50-331 50-331 50-331 50-331 50-331	8 8 8		82082 40196 82082 40196 82082 70380 82083 10304 82083 10394*	50-482 50-482 50-482 50-482	8 A A
	82081 90104 82081 90109* 82082 30037 82082 30346 82082 40135	50-331 50-331 50-331 50-331 50-331	R R S P S	Kansas State Univ Kansas, Univ of Kaya Electric Cooperative Kenturky, State of Kerr-McGee Corp	82082 60097 82080 20362 82080 20358 82080 30565 82080 40333 82080 40407	90-148 50-537 PRM WASTE MO	
	8208240139* 8208240314 8208240317* 8208270505 8208270512*	50-331 50-331 50-331 50-331	8 8 P P		82080 40430 82081 00221 82081 00221 82081 00225* 82081 00225*	40-8027 40-2061 70-925 70-925 70-925 70-925	
faws Pousr & Light Co.	9208270535* 8208300190 8208310299 8208020358	50-331 50-331 50-331 50-537	Я Р Н	Kerr-McGee Nuclear Corp	82082 4005B 82080 40634	40-2061 40-8768	

AUTHOR AFF IL.IATION	ACCESSION NUMBER	BUBJECT CATEGOR		AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y
Kirkpatrick, Lockhart, Hill, Christopher & Phillips	8208040440* 8207050084	40-8769 FOIA			8208100149 8208100229 8208100313 8208100319	50-382 50-382 50-382 50-382	9 9
	8208040233 8208040239* 8208050291 8208050488	50-322 50-322 50-322	000		8208120068 8208120127 8208160023	50-382 50-382 50-362	A 0 8
	8208050538 8208050538 8208060116 8208060140	50-275 50-275 50-322 50-322	0 0 0		82081 60038 82081 60046 82081 60076 82081 60175	50-382 50-382 50-382	8 8 8
	8208170246 8208170249* 8208170126 8208170132 8208170132	50-322 50-322 50-322 50-322 50-322	0000		82081 40283 82081 70122 82081 70313 82081 70341	50-382 50-382 50-382 50-382	9 6 8
	8208240240 8208240243 8208240390 8208310033	50-322 50-322 50-322 FOIA	0		8208180059* 8208200040 8208200074 8208200271 8208240193*	50-382 50-382 50-382 50-382 50-382	0 8 9 0
LFC Corp Lakeside Bridge & Steel Co Lawnwood Medical Genter FL Lawrence Livermore Laboratory	8207050072 8208190303* 8208040459* 8206290168* 8206290171*	FOIA GA999 50-389 FOIA FOIA	F		8208240208* 8208240244 8208240256 8208240266 8208240333	50-382 50-382 50-382 50-382 50-382	S B A Q
LoBoguf, Lamb, Leiby & MacRae	8208040442* 8208050044* 8208130448* 8208310065* 8206270076	50-321 50-293 50-259 FOIA FOIA	P P		8208240350 8208250234 8208270168 8208270357 8208270446	50-382 50-382 50-382 50-382 50-382	0 8 A
League of Homen Voters of Rockford, IL	8208020213 8208190212 8208270477 8208270532 8208060113	50-244 50-341 50-289 50-289 50-454	Q A 0 0 0	Louisiana, State of Lowenstein, Newman, Reis, Axelrad & Toll	8208310154 8208310324 8208110138 8208020352 8208040037	50-362 50-362 50-362 50-522 70-620	A Q R
Leuis, H	8208100183 8208160467 8208170142 8208310515*	PRH 50-289 PR CONTRAC	٩		82080 60092 82081 70114 82081 70258 82081 70258	50-498 50-498 50-498	0000
Literature Research Corp Long Teland Lighting Co	8208020209 8208020337 8208030005* 8208030006*	50-322 50-322	B F F		82081 70260 82081 70260 82081 70381 82081 70383* 82081 70385	50-498 50-498 27-47 27-47 27-47	0
	8208030179 8208030301 8208040009	50-322 50-322 50-322	T Q A	Luigi Berra, Inc MSI Testing Inc	8208250248 8208190082 8208040272	50-498 XPDRTLEC 71-6717	e c
	8208040184 8208040188* 8208050348 8208050511 8208060272*	50-322 50-322 50-322 50-322 50-322	8 8 8	Madison, IN Maine Yankee Atomic Power Co	9208190128 9208260467* 9208020328	71-6717 CONTRACT 50-309	T 8
	8208110150 8208110164 8208110167 8208110168	50-322 50-322 50-322 50-322	9 9 9		8208040317* 8208040319* 8208050315 8208050337* 8208050354	50-309 50-309 50-309 50-309 50-309	6 8 8
	8208110169 8208110170 8208130191 8208180041 8208180050#	50-322 50-322 50-322 50-322 50-322	OEFF		8208050416* 8208050457 8208050513 8208050526* 8208090072	50-309 50-309 50-309 50-309 50-309	9 8 8
	8208180058* 8208200163* 8208200200 8208200246 8208200270	50-322 50-322 50-322 50-322 50-322	FOAEO		92080 90076* 92081 00005 92081 00087 92081 00170 92081 00222	50-309 50-309 50-309 50-309 50-309	8 9 8
	8208230135* 8208240238 8208240293 8208240429 8208240421	50-322 50-322 50-322 50-322 50-322	Q A E E E		82081 00227* 82081 00304 82081 20128 82081 20132* 82081 60070	50-309 50-309 50-309 50-309 50-309	P P R P
	8208250253 8208250264 8208300137 8208300176 8208300305	50-322 50-322 50-322	19 99E9		82081 60143* 82081 70128 82081 70364* 82081 70366* 82081 80045	50-309 50-309 50-309 50-309 50-309	6 6 6
ory	8208120368	NUREO 50-382 50-382 50-382	FFKK		82081 90283 8208230184 8208230194* 8208230202 8208230210*	50-309 50-309 50-309 50-309 50-309	8 8
		50-362	ĸ		8208240392* 8208240271 8208240547 8208240555* 8208270524*	50-309 50-309 50-309 50-309 50-309	0 8 8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC*	4 Y	AUTHOR AFFILIATION	ACCE 681DN NUMBER	SUBJECT CATEOUR	RY
	8208270524* 8208270530* 8208270530* 8208310241 8208310380	50-309 50-309 50-309 50-309 50-309	R R R P		82080 30645# 82080 60191 82080 60196# 82080 60232 82080 60237#	50-416 50-416 50-416 50-416 50-416	P 8 8
Mapleton Intervenors Marsh & McLennan Inc., M & M Nuclear Consultants, Inc. Div	8208300170 8208020269	PRM 50~338	J		8208040273 8208040274* 8208090041 8208090067	50-416 50-416 50-416 50-416	8 8 F
	82080 40006 82081 70074 82081 70074	50-315 50-321 50-321	J J		8208090067 8208090075	50-416 50-416	F F
Merubeni America Corp (subs of Maruben: Corp. }	6208170200 6208170200 6208300171 6208040115	50-321 50-321 PR XPQRTLIC	, ;		8208090075 8208090092 8208090092 8208090147	50-416 50-416 50-416 50-416	F P 8
Manyland, Univ of	8208020138	50-166	R		8208070149# 8208070152	50-416 50-416	8
Massachusetts Institute of Technology Massachusetts, State of	8208230350* 8208250127 8208260293 8208160083	70~938 50~20 50~20 50~293	P B Q		8208090169 8208090171# 8208090210#	50-416 50-416 50-416	8 8 8
	9208140097# 9208140150 8208140150 9208140230	50~293 50~443 50~443	0 0 0		82080 90280 82080 90281 * 82081 00089 82081 00089	50-416 50-416 50-416 50-416	J B
Hecklenburg Electric Cooperative	92081 60230 92080 50286	50-443 50-537	Ф Н		92081 00134 82081 00134	50-416 50-416	P
Medical College of Hisconsin Memphis State Univ Hercury Co. of Norwood, Inc Hercury Metals, Inc.	8208030553 8208270497 8208050286 8208040043	REQUD 50~538 50~537 71~480	8 H		8208120147 8208120147 8208120222	50-416 50-416 50-416	ь ь
Hetro Btudy Corp Metropolitan Edison Co.	8208040047# 8208310010# 8208070155	71~480 CONTRACT 50~289	•		8208 20244 8208 20244 8208 20274 8208 20297	50-416 50-416 50-416	6 E
	82081 10147 82081 30153 82081 60139	50-289 50-289 50-289	0		8208120297 8208120302* 8208120314*	50-416 50-416 50-416	E E
	82081 90153 82082 40338 82082 40342 82082 40432	50-289 50-289 50-289 50-289	0		8208120314+ 8208160075 8208160254 8208160289	50-416 50-416 50-416	0 6 E
Miami Valley Power Project	9208270487 9208270487 9208270495# 9208030331	50-289 50-289 50-289 50-358	0		82081 60301 # 82081 60337 82081 60337 82081 60476	50-416 50-416 50-416 50-416	8 9 9
	8208040264 8208090150 8208240362	50-358 50-358 50-358	9		62081 60488* 62081 60506 62081 6051 6* 82081 70139	50~416 50~416 50~416 PR	6 6
	8208240362 8208240382 8208240385*	50-358 50-358 50-358	9		6208180067	50~416	P
Hichigan, State of, Dept of Public Health Hichigan, Univ of	8208310438 8208310058*	50-329 50-2	D F		82081 90274 82081 90277* 82082 00004 82082 00011* 82082 00020	50-416 50-416 50-416 50-416 50-416	R R B B
Microtech Industries: Inc Hiddle Bouth Services: Inc Midland City. MI Hidwest Environmental Protection Associates	8208050086* 8208120189 8208250070* 8208300170	CONTRACT MISC CONTRACT PRM			82082 00026 * 82082 00059 82082 00067 *	50-416 50-416 50-416	8 8
Hinerals Exploration Co (subs. of Union	B20B1 20034#	40-8584			8208200127 8208200127	50-416 50-416	0
Gil Go, of Galifornia) Hississippi Power & Light Co.	8208020067 8208020070* 8208020140 8208020145*	50-416 50-416 50-416 50-416	8 8 8		8208200134 8208200134 8208200138 8208200138 8208200240	50-416 50-416 50-416 50-416 50-416	00000
	8208020410 8208030028# 8208030032# 8208030408# 8208030419#	50-416 50-416 50-416 50-416 50-416	E F G G		9208200240 8208230364 8208230364 8208240170 8208240170	50-416 50-416 50-416 50-416	9 4 4 6
	8208030449 8208030449 8208030482 8208030490* 8208030345	50-416 50-416 50-416 50-416 50-416	E E E E E E E E E E E E E E E E E E E		8208240328 8208240328 8208260109* 8208260109*	50-416 50-416 50-416 50-416 50-416	b 1 b b b
	8208030585 8208030585 8208030594* 8208030594* 8208030407*	50-416 50-416 50-416 50-416 50-416	P P P		8208260113* 8208260113* 8208270227 8208270227 8208270327 8208270327*	50-416 50-416 50-416 50-416 50-416	
	8208030507* 8208030520* 8208030545* 8208030553* 8208030660*	50-416 50-416 50-416 50-416 50-416	P P P P		820827040B 8208270410* 8208270431 8208270434* 8208270436	50-416 50-416 50-416 50-416 50-416	E E E E E

AUTHOR AFF ILIATIGN	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATECORY
	8208270439* 8208270472 8208270483* 8208300105 8208300107*	50-416 50-416 50-416 50-416 50-416	5 6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8208020129* 8208100277 8208120040 8208120042* 8208160173	50-290 P 50-290 9 50-290 R 50-290 R 50-290 9
	82083 00314 82083 10284 82083 10284 82083 10317 82083 10445	50-416 50-416 50-416 50-416 50-416	6 # P P		82081 60176* 82081 60297 82082 00088 82082 00103 82082 00109*	50-298 6 50-298 P 50-298 P 50-298 8 50-298 8
Missouri, Univ of, Columbia	6208310349 8208310377* 6208310385* 6208050256 8208050260*	50-186 50-186 50-184 50-123 50-123	R R R H		8208200166 8208200176* 8208240369 8208240380* 8208240438*	50-298 8 50-298 8 50-298 8 50-298 8 50-298 F
Mitsubishi International Gorp (subs of Mitsubishi Corp)	8208040214 8208270662 8208270665* 8208310496 8208310496*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			8208270182* 8208270185* 8208270185* 8208270185* 8208270340	50-298 R 50-298 R 50-298 A 50-298 A 50-298 P
Mitsul & Co (U.S.A.), Inc. (Subs. of Mitsul & Co., Ltd.) Monroe & Lemann Monroe X-Ray Co., Inc. Monsanto Co	8208040043 8208250385* 8208190141 8208310255	XPORTLIO FOIA 71-4717 REGOD		Nevada, State of New Hampehire. State of New York State Electric & Gas	82083 10384 82081 80227 82081 30328 82081 40034 82080 40285	50-278 P NUREG 50-443 F 50-443 D 50-537 H
Monsanto Research Corp Montana-Dakota Utilities Co Montgomery County,MD	8208240045 8208240053* 8208020348 8208310454* 8208310524*	XPORTLIC XPORTLIC 50-597 CONTRACT	о н г	New York, Btate of New York, NY Newton Remortal Hosp Newton, NJ	8208030213 8208030370 8208230208* 8208020275 8208230274*	REVIEW ORP 50-382 K 70-273 50-247 Q 70-2625
Morgan Associates	8208170285 8208170117 8208170117 8208170123* 8208170123*	50-247 50-247 50-247 50-247 50-247	0 0 0	Niagara Mohawk Power Corp,	8208020200 8208050187 8208050237 8208050436 8208050470	50-220 F 50-410 B 50-410 0 50-220 Q 50-220 P
Morgan, Lewis & Bockius Mostolier & Stulberg Mountain West Research, Inc	8208170327 8207110022 8208040208 6208040215 8208040245	50-537 FDIA 50-312 50-302 50-200	Ф Р Р		82080 90047 82081 00040 82081 20286 82081 30195 82081 30293	50-220 P 50-410 8 50-537 H 50-220 P 50-220 I
	8208040311 8208040323 8208060357 8208070010 8208070010	50-269 50-317 50-277 50-269 50-289	ե ե ե		82081 60032 82081 60037* 82081 60039* 82081 60042* 82081 60045*	50-220 0 50-220 0 50-220 0 50-220 0 50-220 0
	8208090014 8208090014 8208090019 8208090021 8208090021	50-335 50-335 50-315 50-313 50-313	Р Р Р		82081 60448 82081 60455* 82082 00042 82082 00049 82082 00104	50-220 A 50-220 A 50-220 P 50-220 P 50-220 G
	9209130115 9209130115 9209130115 9209130473 9209170010	50-220 50-220 50-220 NUREG 50-323	P P A		8208200112* 8208230277 8208230304* 8208240051 8208250177	50-220 8 50-220 8 50-220 6 50-220 P 50-220 P
NUMANCO 'US Corp	8208300270 8208190271* 8208260350* 8208310167 8208310500*	PR 0A999 50-324 50-334 CONTRACT	F K		8208270230 8208270379 8208270476 8208270577* 8208270579*	50-220 F 50-220 F 50-220 R 50-220 R
'ISAG, Inc 'UTECH (Nuclear Technology, Inc.) 'ational Society of Professional Engineers	8208230451* 8208310466* 8208200168* 8208050286	CONTRACT CONTRACT 50-341 50-537	Г	Nissho-Iwai American Corp Nolin Rural Electric Cooperative Corp	8208270583* 8208270583* 8208310346 8208240086 8208120278	50-220 R 50-220 R 50-410 A XPORTLIC 50-537 H
atural Resources Defense Council	8208020207 8208020249 8208020300	50-537 50-537 50-537	0	Norman Bragar Co , Inc North Carolina Municipal Power Agencies North Carolina. Univ of North Shore Committee Against Nuclear &	8208120220 8208300341* 8208300216 8208240229	50~537 H 50~413 I PRM 50~322 0
	8208030362 8208050352 8208050378 8208090153	50-537 50-537 50-537 50-537	0 0 0	Thermal Pollution Northeast Nuclear Energy Co (subs of Northeast Utilities)	8208020076	50-213 P
	8208110159 8208120093 8208180115 8208180117* 8208180125*	50-537 50-537 50-537 50-537 50-537	0 0 T T		8208020076 8208020076 8208020146 8208020147 8208020153*	50-213 P 50-213 P 50-334 0 50-334 9 50-336 8
Navy, Dept of, Naval Facilities Engineeri ng Commend	8208180130* 8208240330 8208170175	50-537 50-537 REGGD	7 0		8208030019# 8208030019# 8208030019# 8208050114 8208050179	50-213 F 50-213 F 50-213 F 50-336 0 50-245 P
ng topmenu Navy.Dept of, Naval Research Laboratorg Nebraska Public Power District	8208040200 8208020104 8208020126	NUREO 50-298 50-298	I P		82080 50398 82080 50406 82080 60166	50-245 F 50-336 F 50-336 S
	GEOGUEVIZO	4V~4,70	•		0474481199	ರ∪∾ವರದ ಕ

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT CATEGOR		AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8208040206 8208040212* 8208040230 8208040230 8208040230	50-336 50-336 50-213 50-213 50-213	8 9 P P		82080 20123* 82080 20320 92080 20323* 82080 20320*	50-282 S 50-263 F 50-263 F 50-263 F 50-263 F
	8208040231 8208040231 8208040231 8208040247 8208040247	50-213 50-213 50-213 50-213 50-213	Р Р Р F F		8208030090* 8208030091* 8208030228 8208040129* 8208040130*	50-282 F 50-282 F 50-282 F 50-263 F 50-263 F
	8208040267 8208040279 8208040279 8208040279 8208040279	50-213 50-213 50-213 50-213 50-213	F P P P		8208090259 8208090267* 8208100055 8208100055 8208100055	50-304 6 50-306 6 50-282 7 50-282 7 50-282 7
	82080 90185 82081 00001 82081 00133 82081 00142 82081 20090	50-423 50-245 50-423 50-213 50-245	B P A Q R		82081 00062* 82081 00067 82081 00074* 82081 00074* 82081 00080	50-282 50-263 50-282 50-282 50-282
	82081 20091 * 82081 20277 82081 20280 * 82081 20296 82081 20300 *	50-245 50-336 50-336 50-336 50-336	R 9 R R		82081 00080 82081 00092 82081 00194 82081 20151 82081 30082	50-282 50-263 50-282 50-282 50-263
	82081 60074 82081 60074 82081 60423 82081 60423 82081 60423	50-245 50-245 50-213 50-213 50-213	P P Q Q Q		8208130087* 8208130178 8208130202* 8208170247 8208200084	50-263 50-282 50-282 50-263 50-282
	8208180006 8208180015* 8208180127* 8208190218 8208190279	50-336 50-336 50-336 50-245 50-245	8 0 P P		8208200294 8208200294 8208200297* 8208200297* 8208200297*	50-282 50-282 50-282 50-282 50-282
	8208200072 8208200080* 8208200091 8208200098*	50-245 50-245 50-245 50-336 50-336	P P P S S S		8209200279* 8208200300* 8208200300* 8208230338 8208230338	50-282 50-282 50-282 50-282 50-282
	6208240384 8208250289 8208260126 8208260131* 6208260159	50-213 50-483 50-336 50-336 50-336	P 0 8 6 8		8208240136 8208260118 8208260315* 8208260315* 8208260315*	50-282 50-263 50-263 50-263 50-263
	82082 & 01 & 7 * 82082 & 024 & 82082 & 025 4 * 82082 & 0468 82082 705 41 *	50-336 50-336 50-336 50-245 50-245	8 8 8 8 8		6208240315* 8208240315* 8208240315* 8208240315* 8208240315*	50-263 50-263 50-263 50-263 50-263
	82982 70541 * 82082 70541 * 82082 70543 * 82082 70543 * 82082 70543 *	50-245 50-245 50-245 50-245 50-245	R R R R		82082 60358* 82082 60358* 82082 60358* 82082 60358* 82082 60360*	50-263 50-263 50-263 50-263
	8208310306 8208310310* 8208310310* 8208310471* 8208310471*	50-245 50-245 50-245 50-245 50-245	P ቱ ዩ ዩ		8208240340* 8208240340* 8208250340* 8208270209*	50-243 50-263 50-263 50-282 50-282
Northeast Utilities	8208310473* 8208020244 8208050147* 8208050388 8208050395*	50-245 50-213 50-213 50-245 50-245	E E 6		8208270209# 8208270215# 8208270215# 8208270215# 8208270215#	50-282 50-282 50-282 50-282
	82080 5041 1 * 82080 40204 82080 70185 82081 00133 82081 20070	50-336 50-336 50-423 50-423 50-245	F 8 8 A R		8208270294 8208270419 8208270419 8208270419 8208270626#	50-282 50-282 50-282 50-282
	82081 20277 82081 20294 82081 60074 82081 80004 82082 00072	50-334 50-334 50-245 50-334 50-245	8 R P S P		9209270626* 82092706264 8209270644* 8208270644* 8208270648*	50-263 50-263 50-263
Northeast Utilities Service Co	8208240310 8208240126 8208240244 8208020244 8208140340	50-423 50-336 50-336 50-213 50-245	A 8 8 P F			
Northern California Power Agency, California, State of, Northern States Power Co.	82081 90218 82082 50135 82081 80018 82080 20119	50-245 50-213 50-275 50-282	Р Н Н			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	92081 80269 * 82082 40128 92082 40134 * 82083 60204 * 82083 10465 *	CGNTRACT 71-6698 71-6698 CGNTRACT 71-6698	Oklahoma. Univ of Omaha Public Power District	8208040197 8208030549 8208030554* 8208030558 8208030558	50-112 P 50-285 K 50-285 K 50-285 K 50-285 K
Nuclear Club, Inc , The Nuclear Consulting Services, Inc Nuclear Energy Service, Inc	8208040048* 8208300274 8208120219* 8208170100* 8208170112*	50-537 D PR 50-409 P 50-409 P 50-409 P		8208030564 8208030571 8208030575 8208030580 8208030584	50-285 K 50-285 K 50-285 K 50-285 K
	8208170119* 8208170121* 8208170125* 8208170131* 8208200083*	50-409 P 50-409 P 50-409 P 50-409 P 50-409 B		8208030570 8208030593 8208030601 8208030606 8208030612	50-285 K 50-285 K 50-285 K 50-285 K 50-285 K
Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.)	#E840E0B03B	70-143		8208030614 8208030617	50-295 K 50-285 K
Nuclear Hetals, Inc Nuclear Packaging, Inc	62081 60478 62081 60496 62083 10423# 62080 20460	70-143 70-143 40-472 71-9159		8208030628 8208030628 8208030632	50-285 K 50-285 K
Nuclmar Records Management Association:	82080 20461 * 82080 50041 * 82082 40033 82081 60480	71-9159 71-9132 71-9132 71-9132 PR		8208030434 8208030637 8208030642 8208030647 8208030652	50-285 K 50-285 K 50-285 K 50-285 K
Inc Nuclear System Dak Ridge Associated Univ Dak Ridge National Laboratory	8208180261# 8208200081# 8208040622 8208040629	CONTRACT 40-86 REB RES		8208030657 8208030661 8208030664 8208030668 8208030673	50-285 K 50-285 K 50-285 K 50-285 K 50-285 K
	8208030005 8208130467 8208130481 8208170303	RES NUREO NUREO 50-537 A		8208030675 8208030679 8208060034* 8208060036* 8208060216*	50-285 K 50-285 K 50-285 F 50-285 F 50-285 Q
	8208170316 8208180117* 8208230035 8208230035	NUREG SO-537 T NUREG NUREO FOIA		82081 00003 82081 20168* 82081 30038 82081 30248 82081 30301	50-285 8 50-285 F 50-285 P 50-285 P GEN TEC 18
	8208250007# 8208250011#	FOIA FOIA		8208180089	50-285 Q
	82082 50013* 82082 50017* 82082 50021* 82082 50027*	FOIA FOIA FOIA		82081 90089 82081 90093* 82081 90172* 82081 90247*	50-285 R 50-285 A 50-285 F 50-285 0
	82082 50032* 82082 50035* 82082 50036* 82082 60008 82082 60027	FOIA FOIA NUREO NUREO		8208190264* 8208190276* 8208200135 8208200149* 8208240165	50-285 0 50-285 0 50-285 8 50-285 8 50-285 P
	8208240080 8208240087 8208240112 8208240438 8208240440	NUREG NUREG NUREG NUREG NUREG		8208240177 8208240178 8208240298* 8208270362* 8208310159	50-285 K 50-285 P 50-285 G 50-285 F 50-285 P
Ridge, TN ice of Management & Budget	8208260473 8208260497 8208270465 8208060356* 82081 00376*	NUREO NUREO 50-537 O CONTRACT COMMISSION	Orrick, Herrington & Sutcliffe Pacific Oas & Electric Co	8208310193 8208310282* 8208050482 8208020241 8208020247*	50-285 J 50-285 G 50-206 D 50-133 B 50-133 B
	8208100376* 8208240023 8208240027 8208240031	COMMISSION ORO ORO ORO		9209030020* 8209030523 8209030553 8209040204 8209040207*	50-275 Q 50-133 J FR 50-275 P 50-275 P
Offshore Power Bystems (subs of Westinghouse Electric Corp)	8208240035 8208270422	50-287 P 50-437 G		8208100218 8208110269# 8208110275#	50~275 P 50-275 F 50-275 F
Ogle Petroleum, Inc Ohio Citizans for Responsible Energy	82080 40392 82080 40407 82070 50079 82080 30372 82080 50363	40-8745 40-8745 50-440 G 50-440 G 50-440 G		8208120072 8208120076# 8208120316 8208120318#	50-275 R 50-275 R 50-133 R 50-133 R
	82080 50394 82081 20145 82081 70197	50-440		8208130075 8208130240 8208130241*	50-275 P 50-323 A 50-323 A
	8208270451 8208270451 8208270463	50-440 Q 50-440 Q		8208160178 8208170157 8208170161 8208170161	50-275 P 50-275 P 50-275 P 50-275 P
Ohio State Univ.	8208270463 8208270529 8208270529 8208060353#	50-440 G 50-440 G 50-440 G CONTRACT		8208170211 8208190139 8208190139	50-322 0 50-275 0 50-275 0
Oil Chemical & Atomic Workers Intl. Oklahoma, State of	8208270424 8208040669	70-143 40-8027		82081 90142* 82081 90142* 82082 00144	50-275 0 50-275 0 50-275 0

AUTHOR AFFILIATION	ACCE SSION NUMBER	EUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	,
	8208200148* 8208200150* 8208200154* 8208200158* 8208200267	50-275 50-275 50-275 50-275 50-275			8208270427 8208270440 8208300054 8208300081* 8208300124	50-397 50-397	POSSGP
	8208200272* 8208230019 8208230196 8208230204* 8208230336	50-275 50-275 50-275 50-275 50-275	R F P P		8208300139 8208300285 8208300292* 8208310098 8208310098	50-387 50-387	<u>ው ሱ ቡ ው ው</u>
	8208230334 8208250202 8208270411# 8208270411*	50-275 50-275 50-133 50-133 50-133	P P R R R		8208310125 8208310180 8208310201 8208310252 8208310319	50-387 50-387 50-387 50-387 50-388	E P P G
Pacific Scientific	8208270416* 8208300295 8208310144 8208310429 8208250383*	50-133 50-361 50-275 50-275 50-259	R ₽ ₽ ₽	Pennsylvania State Univ Pennsylvania. State of	9209310343 9208190112 9209030213 9208120130 9208240449	50-387 50-5 REVIEW OF 50-287 50-289	E P P P P P P P P P P P P P P P P P P P
	8208250387* 8208250391* 8208250402* 8208250409* 8208250415*	50-259 50-259 50-259 50-259 50-259	P P P P	Pequannock, Township of, NJ, Perkins, Coie, Stone, Olsen & Williams Perry OH Philadelphia Electric Co	6208270415 8208130236* 8208030314 8208250101* 8207070370	50-412 40-86 50-522 CONTRACT 50-352	κ 0
	8208250421* 8208250424* 8208250431* 8208250437* 8208250441*	50-259 50-259 50-259 50-259 50-259	P P P P		8207070390 8207070401* 8207070406* 8207070406* 8208020464*	50-352 50-352 50-352 50-352 50-352	****
Palmetto Allience Parameter, Inc	82082 50443* 92082 50446* 82081 10191 82081 10302* 82081 70326*	50-259 50-259 50-413 CONTRACT CONTRACT	P P O	•	8208020444* 8208020445* 8208020445* 8208030148 8208030168	50-352 50-352 50-352 50-352 50-352	F F < 4
Parents Concerned About Indian Point Pathfinder Mines Corp. Pachinsy Ugine Kuhlmann Development, Inc Pennsylvania Power & Light Co	8208030348 8208270556 8208040423 8208020082 8208020082	50-247 40-6622 40-8027 50-387 50-387	Q P P		6208030348 8208030348 8208030444 8208030444 8208030451#	50-352 50-352 50-352 50-352 50-352	>>>00
	8208020277 8208030083* 8208030086* 8208030204 8208030401	50-387 50-387 50-387 50-387 50-387	8 F P E		8208030451* 8208040374* 8208040375* 8208050317 8208050321*	50-352 50-277 50-277 50-277 50-277	*****
	8208030401 8208030455 8208030455 8208040142 8208040146	50-387 50-387 50-387 50-387 50-387	E E P P		8208050325* 8208050329 8208050329 8208050439 8208050439	50-277 50-352 50-352 50-352 50-352	8 4 4 4
	8208050210 8208050493 8208050493 8208060143 8208060146*	50-387 50-387 50-387 50-387 50-387	8 9 9 8		8208070187 8208100122 8208100147 8208100286 8208120060#	TOPREP 50-352 50-277 50-352 50-293	A 8 A 0
	8208040190 8208040190 8208040298 8208040298 8208040302*	50-387 50-387 50-387 50-387 50-387	P P P P		8208120073* 8208120101 8208120106 8208120115 8208120115	50-352 50-352 50-352 50-352 50-352	00000
	8208100038 8208100038 8208120105 8208130045 8208130048*	50-387 50-387 50-387 50-387 50-387	88 5 8		8208120116* 8208120121 8208120121 8208130319 8208130319	50-352 50-352 50-352 50-352 50-352	8 6 0 0
	9208170248 9208170248 9208170273 9208170111 9208200175	50-387 50-387 50-387 71-4574 50-387	P J G		62081 60065 62081 60065 62081 60066 62081 60066 62081 90098	50-352 50-352 50-352 50-352 50-277	C C Q G R
	8208200239 8208200245* 8208200253* 8208200259* 8208200246*	50-387 50-387 50-387 50-387 50-387	P P P		8208190102* 8208200045 8208200077 8208240222 8208240222	50-277 50-277 50-352 50-352 50-352	R P A A A
	8208230075 8208230075 8208240151 8208240151 8208240175	50-387 50-387 50-387 50-387 50-387	8 8 0 0		8208240226# 8208240226# 8208240236 6208250322 8208250322	50-352 50-352 50-352 50-352 50-352	6000
	8208240202# 8208240397 8208260221 8208260226# 8208270427	50-387 50-387 50-387 50-387 50-387	P P P P		6208250326# 8208250326# 8208270438 8208270442# 8208270442#	50-352 50-352 50-352 50-352 50-352	00000

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE(CATEG	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC	
	8208310076 8208310112 82083101136* 8208310136*	50-277 50-352 50-352 50-352 50-352	P A A A		8208260544# 8208270155 8208270193# 8208270193# 8208270200#	50-333 50-284 50-333 50-333 50-333	9 R R R
Philadelphia Inquirer Pittsburgh-Des Koines Corp Planning Research Corp Plateau Resources, Ltd	8207110003 8208300223 8208020069* 8208260371* 8207200515	70-143 PR CONTRAC 50-483 40-8674	F		8208270200* 8208270237* 8208270237* 8208270259* 8208270259*	50-333 50-333 50-333 50-333	я я я я
Portland General Electric Co	8207200520* 8208030213 8208030485 8208070070 8208100046	40-8674 REVIEW 50-344 50-344 50-344			8208270532* 8208270632* 8208270640* 8208270640* 8208300224	50-286 50-286 50-286 50-286 50-333	R R R P
	82081 00054* 82081 00076 82081 00108* 82081 00184 82081 00264	50-344 50-344 50-344 50-344 50-344	8 8 9 9	Press Intelligence, Inc Princeton Gamma-Tech, Inc Princeton Univ	8208310420 8208310503* 8208310520* 8208020452* 8208180125*	50-333 50-286 CONTRAC CONTRAC 50-537	
	8208170350* 8208200184 8208200292 8208200296* 8208230025	50-344 50-344 50-344 50-344 50-344	F 9 8	Project Management Corp. Public Interest Research Group, New York Public Service Co. of Colorado	8208110160 8208110170 8208200283 8208030536 8208020252	50-537 50-537 50-537 REVIEW 50-267	Q Q QRP P
	8208230296 8208240173 8208240225 8208300153 8208300231	50-344 50-344 50-344 PR RECOD	Р 0		8208040503* 8208040521* 8208040526* 8208050349 8208050379*	50-267 50-267 50-267 50-267 50-267	F F 9
Power Authority of the State of New York	8208020381 8208020385* 8208030263 8208050447 8208050507	50-286 50-286 50-286 50-286 50-333	8 P P 8		8208050377 8208040147* 8208040178 8208100011 8208100016*	50-537 50-247 50-267 50-267 50-267	H F P P
	8208050514* 6208070044 8208070047* 8208070085 8208070088*	50-333 50-333 50-333 50-333	8 8		8208130194 8208130199* 8208130201 8208160025 8208160027*	50-267 50-267 50-267 50-267 50-267	R R A B
	82081 00034 62081 00040* 82081 00244 82081 00300 82081 20215	50-333 50-333 50-333 50-286 50-286	R P P		8208160397* 8208160456* 8208170136 8208190234 8208200117	50-267 50-267 50-267 50-267 50-267	F 4 P P S
	6206120217* 6206130234 6206130244 6206160028 8206160030*	50-286 50-286 50-333 50-333 50-333	R G P 8		8208200124* 8208200126 8208200141* 8208240053 8208240056*	50-267 50-267 50-267 50-267 50-267	8 8 8
	82081 40031 82081 40033* 82081 70284 82081 70284 82081 70285	50-333 50-933 50-247 50-247 50-247	8 6 9		9208240074 8208240079* 9208240221 9208270592* 8208270592*	50-267 50-267 50-267 50-267 50-267	8 P R
	8208170285 6208180098* 6208190119 6208190119 6208190123*	50-247 50-286 50-247 50-247 50-247	0 0 0	Public Service Co. of Indiana, Inc	8208270595* 8208270595* 8208300220 8208310355 8208030282*	50-267 50-267 50-267 50-267 50-546	R G ₽
	8208190123* 8208190162 8208190196 8208190235 8208200119	50-247 50-333 50-286 50-333 50-286	9 7 7		8208090063* 8208160212 8208240283 8208300218 8208310248	50-546 REVIEW 0 50-546 50-546 PRM	G ORF 8 8
	8208230108* 8208230112* 8208230360 8208230363* 8208230143	50-333 50-333 50-333 50-333 50-333	9 8 8 P	Public Service Co. of New Hampshire	8207300522 8208040261* 8208050408 8208060126 8208060126	50-443 50-443 50-443 50-443 50-443	A F A G G
	8208250144* 8208260161 8208260169 8208260170* 8208260178*	50-333 50-333 50-333 50-333 50-333	8 8 8		8208060135 8208060135 8208060137 8208060137 8208060131	50-443 50-443 50-443 50-443 50-443	00000
	8208240208 8208240216* 8208240230 8208240234* 8208240243	50-333 50-333 50-333 50-333	8 8 8 8		82080 40303 82080 40303 82080 40303 82080 40305* 82080 40305*	50-443 50-443 50-443 50-443 50-443	Q F F F
	8208260248* 8208260246 8208260283* 8208260290 8208260339	50-333 50-333 50-233 50-286 50-333	8 8 8		82081 10102 82081 30297 82081 70323 82081 70075 82081 70155	50-443 50-443 50-443 50-443 50-443	A A A A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	łY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	,
	8208170155 8208200222 8208200222 8208260281 8208300142	50-443 50-443 50-443 50-443 50-443	A 8 9 8	777-7770-770-770-770-770-770-770-770-77	9208270586* 9208270586* 9208270587* 9208270587* 9208270587*	50-272 50-272 50-272	RRRRRR
fublic Service Co of New Mexico fublic Service Electric & Gas Co of New Jersey	8208270384* 8208020112 8208020137	50-528 50-272 50-272	1 G S		8208270701 * 8208270701 * 8208300056 8208300095	50-272 50-311	R R S
	8208020315 8208020327*	50-272 50-272 50-272	9 9		8208300204 8208300208 8208300217	50-311 50-311 50-272	8 8 R
	8208020353 8208020359* 8208030508 8208050097	50-311 50-311 PR 50-311	8 8		8208300217 8208300219* 8208300219*	50-272 50-272	R R R
	8208050059* 8208050335 8208050344* 8208050368 8208050380*	50-311 50-272 50-272 50-311 50-311	9 9 9 8		9208300227 8208300233* 8208300330 8208310150 8208310153*	50-311 50-311 50-311 50-311	9 9 9 9
	8208050472 8208050509* 8208060158* 8208090089 8208090145	50-272 50-272 50-311 50-354 50-354	8 5 9 8		8208310271 8208310274* 8208310285 8208310287* 8208310318	50-311 50-272 50-272	8 8 8 8
	8208100010 8208100018* 8208100079 8208100086* 8208100142	50-272 50-272 50-272 50-272 50-272	8 8 8 0	Puget Sound Power & Light Co	8208310322# 8208310346# 8208310395 8208310400# 8208030314	50-272 50-311 50-311	9 9 9 9
	8208100220* 8208130113 8208130117* 8208130214 8208130217*	50-354 50-272 50-272 50-311 50-311	G 8 8 8		8208100216 6208250213 8208250213 8208250220* 8208250220*	50-522 50-522 50-522	8 8 8
	8208130247 8208130253* 8208140014 8208140048 8208140048	50-272 50-272 50-354 50-272 50-272	\$ 5 5 R R	Purdus Research Foundation Purdus Univ R F Ready. Inc	8208120381* 8208020412* 8208240401 8208030375 8208180108	50-275	P R R
	8208140049* 8208140051* 8208140053* 8208140055* 8208140056*	50-272 50-272 50-272 50-272 50-272	R R R R	Radiation Protection Service Rare Earths: Inc. Reactor Experiments: Inc Record: The Hackentack: NJ	82081 60237 82082 50085* 82082 50374* 82082 60327 82082 50055	PR 40-84 FOIA XPORTLIC POIA	
	8208140048 8208140085 8208140087* 8208140140 8208180071	50-272 50-272 50-272 50-354 50-272	9 R 9 8	Reed, J C. Rio Algam, Ltd Roams-Anderson Economic Council Robert L Cloud Associates, Inc	62082 4028 1 62060 4028 4 62060 5028 4 62061 6003 5 62082 7020 4	40-8084 50-837 50-275	O H R P
	8208180080* 8208170003 8208170011* 8208170113	50-272 50-311 50-311 50-311	8 8 8	Rochester Gas & Electric Corp	8208270212* 8208020194* 8208020195* 8208020213 8208020225*	50-244 50-244 50-244	P F G
	8208170127 8208170133* 8208170138 9208170143 8208170144*	50-311 50-311 50-311 50-311 50-311	8 8 8 8		8208020244 8208020274# 8208020313 8208020321# 8208030363	50-244 50-244 50-244	8 8 8 F
	9208190149* 9208190145 9208190144* 9208190189 9208190194*	50-311 50-311 50-311 50-272 50-272	8 8 8		8208030519 8208040031 8208040079* 8208040081* 8208070048	71-6601 50-244	F G
	8208190216 8208190230* 8208240395 8208240399* 8208250097	50-311 50-311 50-311 50-311 50-272			8208120245 6208120247* 8208170164 8208170173* 9208170181*	50-244 50-244 50-244 50-244 50-244	R P P
	8208250097 8208250198 8208260137 8208260141* 8208260148	50-272 50-272 50-311 50-311 50-272	F P B B B		8208170214 8208170216# 8208170220# 8208270546# 8208270546#	50-244 50-244 50-244 50-244 50-244	P P R R
	8208240148 8208240223 8208240252 8208240241# 8208240320	50-272 50-354 50-272 50-272 50-272	8 9 9	Rochester: NY	8208270549* 8208270549* 8208300249 8208310335 8208190028*	50-244 50-244 50-244 50-244 CONTRACT	R P P
	8208240323* 8208270176* 8208270176* 8208270586*	50-272 50-272 50-272 50-272 50-272	8 R R	Rocky Mountain College Rocky Mountain Energy Co	8208040369 8208130115 8208050031 8208050035* 8208110054*	50-537 50-220 40-8697 40-8697 40-8452	P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	·	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	۱Y
Romano,F Ropes & Oray	8208110057* 8208230116 8208230116 8208270449 8208060126	40-8452 40-8452 50-352 50-352 50-443	G G G	Senate Senation Power Sentry Equipment Corp	82041 3001 5* 82042 0004 4* 82042 000 50* 82082 40243 82080 20358	MISC 50-329 50-271 50-369 50-537	H
	8208060126 8208060135 8208060135 8208060137 8208060137	50-443 50-443 50-443 50-443 50-443	0 0 0	Shaw, Pittman, Potts & Trowbridge	8207110028 8208020208 8208070144 8208070144 8208070146	50-338 50-440 50-440 50-440 50-440	H 0 0 0
Ruscon Construction Co SRI International Sacramento Municipal Utility District	8208060151 8208060151 8208020358 8208160443* 8208020181	50-443 50-443 50-537 50-312 50-312	о 9 Н Р		82080 90146 82080 90155 82080 90243 82080 90243 82081 10147	50-440 50-209 50-440 50-440 50-299	00000
	8208020183* 8208020201 8208020202* 8208020257 8208020262*	50-312 50-312 50-312 50-312	6 8 8 8 8		8208110158 8208110180 8208120123 8208120127 8208130143	50-440 50-266 50-440 50-392 50-400	0000
	8208030278 8208030300* 8208030420 8208040001 8208060163	50-312 50-312 50-312	P P P		8208130143 8208130149 8208130153 8208130160 8208130160	50-400 50-312 50-289 50-400 50-400	0000
	82080 90078 82081 00138 82081 00310 82081 20029 82081 30149	50-312 50-312 50-312	F Q P		8208130164 8208130164 8208130165 8208130181 8208130181	50-400 50-400 50-440 50-400 50-400	0000
	8208130183 8208140047 8208140114 8208140425 8208170165	50-312 50-312 50-312	ե Ե գ		8208130200 8208130200 8208160139 8208170204 8208170215	50-400 50-400 50-289 50-483 50-400	0 0 0
	8208180103 8208180117 8208180122* 8208190245 8208190270*	50-312 50-312 50-312	G F R R		8208170215 8208170221* 8208170221* 8208170271 8208180103	50-400 50-400 50-400 50-440 50-312	0 0 0 0
	8208200027 8208200122 8208200130* 8208200134 8208200160*	50-312 50-312 50-312	, 8 8 8		8208190135 8208190153 8208200293 8208200293 8208240191	50-483 50-289 50-266 50-266 50-440	9000
	8208200212 8208200224+ 8208230185 8208230244 8208230250	50-312 50-312 50-312	8 8 9 9		8208240191 8208240235 8208240235 8208240333 8208240338	50-440 50-440 50-440 50-382 50-289	0000
	8208230293 8208240379 8208250303 8208270221 8208270226	50-312 50-312 50-312	P P G G		8208240342 8208240350 8208240432 8208250234 8208250289	50-289 50-382 50-289 50-382 50-483	0000
scramento, CA alt River Project	6208270339 6208270339 6208300136 6208260250* 6208040434	50-312	g G P		9208270315 9208270315 9208270317* 9208270317* 9208270411	50-266 50-266 50-266 50-266 50-266	00000
an Diego Ges & Electric Co an Fernendo Valley Alliance for Gurvival	6208270398* 6208030213 6208240259* 6208260307* 6208130356	REVIEW OR	t P P		8208270426 8208270426* 8208270446 8208270460 8208270484	50-483 50-483 50-382 50-387 50-286	0000
andia Laboratories	8208030701 8208130479 8208180241 8208240034 8208240037	CEN TEC I NUREO NUREO NUREO NUREO	а		8208270487 8208270504 8208300205 8208300248 8208300283	50-289 50-440 PRM PR REVI€N 9	Q Q Q Q Q
	6208260112 6208260414 6208260434 8208260477 6208260491	NUREO NUREO NUREO 50-313 NUREO	Þ	Shelly & Sands, Inc Shoreham Opponents Caslition Sierra Club	8208300287 8208020368 8208240229 8208020207 8208020249	50-440 50-537 50-322 50-537 50-537	9 H 9 9
Sargent & Lundy, Inc. Sassafras Audubon Society Science Applications, Inc.	8208040271* 8208160102* 8208030748* 8208300243 8204110309*	50-341 50-537 50-537	P X D D G		8208040401 8208050352 8208050378 8208090153 8208110159	50-201 50-537 50-537 50-537 50-537	9 9
Scientists & Engineers for Secure Energy Seaccast Anti-Pollution League	8208050146* 8208020265 8208180093 8208030291 8208180112	PR REVIEW GR	Т Р 0	Sigma Chemical Co Sinclair,M	8208120093 8208240330 8208240104 8208040123 8208040123	50-537 50-537 XPORTLIC 50-327 50-327	00

AUTHOR AFPILIATION	ACCESSION NUMBER	RUBJECT		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEQUA	
	8208110145# 8208110145# 8208120126 8208200232 8208200232	50-329 50-329 50-329 50-329 50-329	0 0 0 0	48- 1300-151-1301-1-14-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	8208240375 6208240423 8208240427* 6208250152 8208300228	50-395 50-395 50-395 50-395 50-395	E P P P P
Simplissippi Alliance for the Environment	8208200265 8208200265 8208200275 8208030424	50-327 50-327 50-327 50-454	G G G	South Carolina, State of South Hississippi Electric Power	8208040051 8208120366 8208300256 8208020368	50-395 NUREO PRM 50-537	A
(SAFE)	8208030424	50-454	o	Association Southeast Missouri Hosp , Cape Girardeau, MO	8208090079#	70-2174	
	8208030426 8208030426 8208030430* 8208030430* 8208030435*	50-454 50-454 50-454 50-454 50-454	0 0 0 0	Southern Boller & Tank Works, Inc Southern California Edison Co	8208020368 8208020203 8208020206* 8208020212* 8208020214	50-537 50-361 50-361 50-361 50-206	H 8 9
	8208030435* 8208030457* 8208040284 8208040284 8208040284	50-454 50-454 50-454 50-454 50-454	e e e e		8208020216* 8208020219* 8208020248 8208020253 8208020306	50-361 50-361 50-361 50-361 50-361	8 8 8 8
	8208040294* 8208040294* 8208040294* 8208040299* 8208040299*	50-454 50-454 50-454 50-454 50-454	0 0 0 0		8208020314* 8208020322* 8208020324 8208020327* 8208020334*	50-361 50-361 50-206 50-206 50-361	9 8 8 8
	8208040303# 8208040308# 8208040308# 8208040308# 8208040312#	50-454 50-454 50-454 50-454 50-454	a o o o		8208020337* 8208020350 8208020346* 8208020373 8208020375*	50-361 50-361 50-361 50-361 50-361	8 8
	8208040312+ 8208040316+ 8208040316+ 8208040105	50-454 50-454 50-454 50-454 50-454	0 0 0		8208020414 8208020417* 8208030201 8208030204 8208030288	50-361 50-361 50-361 50-362 50-361	9888
Gmall Business Administration	8208040133 8208040133 8208140044 8208200257 8208260077*	50-454 50-454 50-454 50-329 CONTRACT	° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° °		82080 30337 82080 30487 82080 30493 82080 30493 82080 40287	50-362 50-361 50-361 50-361 50-361	8 9 9 9
Smith, Sikorsti-Smith Smith-Emery Co Snell & Wilmer	8208310010* 8208310488* 8208300244 8208040242 8208020205	CONTRACT 50-537 PR 71-9032 50-528	r ,		8208040287* 8208050171 8208050171 8208050253 8208050434	50-361 50-361 50-361 50-206 50-362	P P P P P
Social Impact Research, Inc.	8208040118 8208040208 8208040215 8208040245 8208040311	50-528 50-312 50-302 50-280 50-249	T P P P		8208050476 8208050482 8208050487* 8208060214 8208090051	50-206 50-206 50-206 50-206 50-361	P G G P P
	8208040323 8208040357 8208090010 8208090010 8208090014	50-317 50-277 50-289 50-335	P P P P		8208070211 8208070214* 8208070233 8208100043 8208100050*	50-361 50-361 50-361 50-361 50-361	8 8 8
	8208090019 8208130115 8208130115 8208130473 8208170010	30-315 50-220 50-220 NUREO 50-323	P P P		8208100077 8208100088 8208100093* 8208100223 8208100297	50-204 50-204 50-204 50-26 50-361	P P P B
South Caroline Electric & Qas Co	8207140177 6208020142 6208020211 8208030230 6208030241*	PR 50-375 50-375 50-375 50-375	A Q A		8208100303* 8208110117 8208110120* 8208120108 8208120122	50-361 50-361 50-361 50-206 50-361	8 P P R
	8208030246* 8208030251* 8208030257* 8208030507 8208030408	50-375 50-375 50-375 50-375 50-375	A A A		8208120125* 8208120147 8208120152* 8208120180 8208120180	50-341 50-204 50-204 50-204 50-206	RRRB
	8208050079 8208060183 8208060261 8208060262* 8208100136	50-375 50-375 50-375 50-375 50-375	8 A A A F		8208120285 8208130085 8208130086* 8208140013 8208140072	50-361 50-362 50-362 50-362 50-361	8 A A Q
	8208110126 6208110132* 6208110134* 6208160156 6208160243	80-375 50-375 50-375 50-375 50-375	A F G P		8208160072 8208160101 8208160149 8208160153* 8208160288	50-361 50-206 50-361 50-361 50-206	9 P B B G
	82081 60249* 8208230005 8208230276 8208240358	50-395 50-395 50-395 50-395	P F Q O		8208170186 8208170250 8208170314#	50-206 50-206 50-206	P R R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	TOBLEUE
	8208180024 8208180031#	50-341 50-341	9 8	State, Dept of State, Dept. of, Bureau of Oceans & Internati Environ & Scientific Affairs	8208020296 8208110227	50-537 0 XPORTLIC
	9208180049 9208190053* 9208190074	50-361 50-361 50-206	P P B	ATTENTION MINOR WITH THE PROPERTY OF THE PROPE	8208130035 8208180116 8208180258	XPORTLIC XPORTLIC XPORTLIC
	9208180113 9208190114 9208190145	50-204 50-204 50-204	P P P		8208180273 8208310056 8208310059	XPORTLIC XPORTLIC XPORTLIC
	92081 70147+ 82081 70205 92081 70208+	50-204 50-204	P P	Steen Generator Duners Group Steel Founders' Society of America	8208030492 8208230365	TOPREP PR
	62081 70208# 6208200018 6208200027# 6208200040 6208200145	30-204 50-361 50-361 50-204 50-361	6 8 6	Steels Wasera Cooperative Electric Stewart & Stevenson Services	8208120278 8208020128* 8208020133* 8208020137* 8208020358	50~537 H GA999 GA999 GA999
	6208200152* 6208200182	14E-05	8 8	Stock Equipment Co. Stone & Webster Engineering Corp	8208030529	SO-537 H
	8208200192 8208200204* 8208200213*	50-204 50-361	P 8 8	Suffolk County, NY	8208050176* 8208180025 8208200256* 8205060412*	94999 50-275 R 50-322 E 50-322 H
	8208200221* 8208200225 8208200230* 8208200231 8208200236*	50-361 50-361 50-361 50-206 50-361	8 P 8 8		8205060422* 8208040233 8208040237* 8208050271 8208050488	50-322 H 50-322 9 50-322 9 50-322 9
	8208200242* 8208200248* 8208200251 8208200258*	50-206 50-361 50-361 50-361	8 8 8		8208040114 8208040140 8208170244	50-322 0 50-322 0 50-322 0
	8208200268*	50-361 50-361	8		8208170249# 8208190126	20-355 6
	8208200279 8208200290* 8208230023 8208230023	50-361 50-361 50-206 50-206	9 9 F F		82081 90132 8208200163* 82082 40229 82082 40240 82082 40243	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0
	8208230042 8208230047# 8208230074 8208230086# 8208230249	50-206 50-206 50-206 50-206 50-361	0 0 0 0 0	Sugarman, R J.	8208240390 8208110181 8208110181 8208110184* 8208110184*	50-322
	8208230348 8208240203* 8208240257 8208240259* 8208240264*	50-206 50-206 50-206 50-206 50-206	G G P P		8208110185 8208110185 8208110186* 8208110186* 8208110189*	50-352
	82082 50092 82082 50169 82082 50363 82082 60300* 82082 60307*	50-361 50-266 50-361 50-361 50-361	P P F F		9208110189* 9208110193 9208130157 9208180036 9208270432	50-352 9 50-352 9 50-352 A 50-352 A
	8208270236 8208270377 8208270338* 8208270538* 8208270533*	50-361 50-361 50-361 50-361 50-206	P Q Q Q R		8208270432 8208270489 8208270489 8208270500 8208270500	50-352 9 50-352 9 50-352 9 50-352 9 50-352 0
	8208270582* 8208270582* 8208270588* 8208270586* 8208300030	50-204 50-206 50-206 50-266 50-361	R R R R	Sunflower Alliance	8207160215 8208090179 8208090179 8208090183 8208090183	50-440 9 50-440 9 50-440 9 50-440 9 50-440 9
	8208300032* 8208300034* 8208300037 8208300039* 8208300057	50-361 50-361 50-361 50-361 50-206	8 8 8 8 8		8208090247 8208090247 8208090250 8208090250 8208090254	50-440 H 50-440 H 50-440 9 50-440 H
	8208300058* 8208300071 8208300072* 8208300087 8208300089*	50-206 50-361 50-361 50-206 50-206	8 8 8 8	Swisher Electric Cooperative TERA Gorp. Target Rock Gorp. Task Oroup on Meteorological Plans for	8208070254 8208040373 8208050178* 8208250145* 8206010033*	50-440 H 50-537 H 50-361 P 50-333 P FDIA
Southern Illinois Power Cooperative	8208300155 8208300156* 8208300159* 8208300234 8208270485	50-361 50-361 50-361 50-206 50-454	8 8 8 P M	Radiological Emergency Response Tech/Ops (Technical Operations, Inc.) Technessociates, Inc. Technical Analysis Corp	8208240038 8208240042* 8208260077* 8206270075	71-9166 71-9166 CDNTRACT 3 50-277 4
Spiegel, Q. St. Joseph Hosp. Patterson, NJ	8208180018 8208310267	50-275 REGGD	н	Teknekron Research, Inc.	8208130474 8207140050	NUREO 3
Staminis, B. Standardized Nuclear Unit Power Plant System	82081 00061 82081 00061	50-329 50-482 50-482	A A	Teledyne Engineering Services	8207140053* 8208030273 8208030276* 8208030431	50-322 A 50-275 R 50-275 R 50-275 R
	8208100061 8208100069# 8208100069# 8208100069#	50-482 50-482 50-482 50-482	A A A		8208040145 8208130069 8208130071*	TOPREP 50-275 P 50-275 P
						:

9207270454 50-289 P 8208050170* 8207270454 50-289 P 8208050183 8208050183 8208050183	50-259 50-259 50-438 71-9138 50-328 50-328 50-328 50-328 50-328 50-328 50-328 50-328 50-328 50-438 50-438 50-438 50-259 50-259	
\$207120083	50-328 50-328 50-328 50-328 50-276 50-276 50-438 50-438 50-259 50-257	888888888888888888888888888888888888888
8207270454 50-259 P 8208050169 8207270454 50-259 P 8208050163 82087270454 50-259 P 8208050163 820807270454 50-259 P 8208050183	50-296 50-438 50-438 50-259	8 8
		B
82080 20083	50-438 50-438 50-247	8888
8288020108 50-390 8 8208050229 8288020111 50-259 8 82080502219 82880201113 50-288 9	50-260 50-259 50-259 50-259 50-259	8888
8208020158 50-438 8 92080 50327 8208020158 50-438 8 92080 50332 8208020161 50-380 8 92080 50333*	50-260 50-327 50-436 50-327 50-327	8 8 8 8
92080 20147 + 50-328 8 92080 90347 92080 20147 9 92080 20147 9 92080 90347 92080 90347 9 92080 90347	50-260 50-327 50-390 50-390 50-296	80000
8208020221 50-259 P 8208050407 8208050417* 8208020221 50-259 P 8208050420	50-294 50-327 50-327 50-390 50-390	88888
8208020226 50-328 8 82080504574 8208020226 50-328 8 82080504574 8208020226 50-328 8 8208050474	50-328 50-259 50-259 50-438 50-438	8 8 8
8208020142 50-370 8 8208040138 9 8208020319 90-259 8 8208070046 9 8208020314 50-259 8 8208070046	50-438 50-438 50-259 50-259 50-390	A F F 8
8208020379 # 50-328 8 8208090071 9 8208090071 9 8208020380 50-438 8 8208090071 9 82080900071 9 82080900071 9 82080900071 9 82080900071 9 82080900071 9 820809000071 9 8208090000000000000000000000000000000	50-390 50-390 50-390 50-438 50-438	9 F 8 8
8208030164 50-327 8 8208070161 9 8208030164 50-329 8 8208070171 8 8208030164 50-329 8 8208070175 8	50-438 50-438 50-327 50-327 50-438	8 8 8 8
8208030179# 50-239 8 8208090244 9 8208030189 50-438 8 8208090248 9 8208030191# 50-438 8	90-438 90-327 50-327 50-327 50-327	ն 6 10
9208030203 50~439 8 9208100002 9 9208030203 50~438 8 920810002 5 9208030203 50~438 8 920810002 9	30-259 30-259 30-259 30-259 30-259	I I I I
8208030225	50-257 50-259 50-259 50-259 50-259	I I I
8208030379	10-259 10-259 10-259 10-259 10-327	1 1 1 1 p
\$208030362# 50-327 Q \$20810002# 5 \$208030362# 50-327 Q \$208030562# 5 \$208030562# 50-327 Q \$208030562# 5	00-327 00-327 00-327 00-518 00-518	Р Р А А

AUTHOR AFF IL TATION	ACCESSION NUMBER	CATEON	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	82081 00166 82081 00166 82081 00166 82081 00166 82081 00166	50-518 50-518 50-518 50-518 50-518	A A A A		82081 60464* 82081 40477 82081 60477 82081 60470 82081 60490	50-327 50-390 50-390 50-438 50-438	9 9 9
	82081 00164 82081 00164 82081 00209 82081 00315 82081 00315	50-518 50-518 50-327 50-327 50-327	A A B P P		82081 40471 * 82081 40471 * 82081 40502 * 82081 40502 * 82081 40502 *	50-259 50-259 50-259 50-259 50-259	9 9 9
	62081 10107 62081 10190 82081 10221* 62081 10221* 62081 10221*	50-327 50-537 50-259 50-259 50-259	8 G F F		82081 40533 82081 70174 82081 70174 82081 70283 82081 70283	50-438 50-438 50-438 50-259 50-259	B A K K
	82081 10223* 82081 10223* 82081 10223* 82081 20066 82081 20066	50-259 50-259 50-259 50-438 50-438	F F 8 8		8208170283 8208170293* 8208170293* 8208170293* 8208170295	50-259 50-259 50-259 50-259 50-259	K K K K
	8208120102 8208120102 8208120113 8208120124* 8208120153	50-390 50-390 50-327 50-327 50-438	8 9 9		8208170295 8208170295 8208170297 8208170297 8208170297	50-259 50-259 50-259 50-259 50-259	X X X K
	8208120157 8208120157 8208120157 8208120161 8208120184	50-438 50-390 50-390 50-390 50-260	9 8 8 8		8208170299 8208170299 8208170299 8208170301 8208170301	50-259 50-259 50-259 50-259 50-259	K K K K
	8208120197 8208120190* 8208120201 8208120201 8208120202*	50-438 50-260 50-327 50-327 50-327	8 8 R R		82081 70301 82081 70304 82081 70304 82081 70304 82081 70307	50-259 50-259 50-259 50-259 50-259	***************************************
	8208120202* 8208120226 8208120226 8208120226 8208120233*	50-327 50-259 50-259 50-259 50-259	ዩ ዩ ዩ		8208170307 8208170307 8208170308 8208170308 8208170308	50-259 50-259 50-259 50-259 50-259	K K K
	82091 20233* 82091 20233* 82091 20243 82091 20254 82081 20262*	50-259 50-259 50-390 50-328 50-328	R R S S S		8208170310 8208170310 8208170310 8208170311 8208170311	50-259 50-259 50-259 50-259 50-259	K K K
	62061 50307 65081 50307 65081 50307 85081 50307 65081 50307	50-390 50-390 50-390 50-390 50-390	8 8 9 5		8208170311 8208170315 8208170315 8208170315 8208170317	50-259 50-259 50-259 50-259 50-259	K K K
	8208120312 * 6208120303 * 6208130169 8208130169 8208130203	50-328 50-328 50-370 50-370 50-370	8 8 8		8208170317 8208170317 8208170319 8208170319 8208170319	50-259 50-259 50-259 50-259 50-259	* * * * *
	B208130203 8208130224 8208130263 8208130266 8208130266	50-390 50-438 50-438 50-390 50-390	8 8 8		8208170322 8208170322 8208170328 8208170328	50-259 50-259 50-259 50-259 50-259	KKKX
	8208130287 8208160077 8208160132 8208160132 8208160144	50-438 50-438 50-390 50-390 50-390	8 8 0		8208170328 8208170333 8208170333 8208170333 8208170336	50-259 50-259 50-259 50-259 50-259	K K K
	82081 60144 82081 60144 82081 60144 82081 60144 82081 60210#	50-390 50-390 50-390 50-390 50-438	Q Q Q Q		82081 70334 82081 70334 82081 70339 82081 70339 82081 70339	50-259 50-259 50-259 50-259 50-259	K K K
	82081 60222 82081 60233 82081 60261 82081 60367	NUREQ 50-327 50-327 50-390 50-438	G G S S		8208170340 8208170340 8208170340 8208170375 8208170375	50-259 50-259 50-259 50-259 50-259	K K K K
	82081 40307 82081 40313 82081 40313 82081 40332 82081 40344*	50-438 50-438 50-438 50-327 50-390	8 9 8 0		8208170375 8208170377 8208170377 8208170377 8208170379	50-259 50-259 50-259 50-259 50-259	K K K K
	82081 60346* 82081 60352* 82081 60368 82081 60368 82081 60447*	50-390 50-390 50-438 50-438 50-327	Q Q S S Q		82081 70379 82081 70379 82081 70380 82081 70380 82081 70380	50-259 50-259 50-259 50-259 50-257	K K K K

AUTHOR AFF ILIATION	ACCESSION NUMBER	BUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	92081 70382 92081 70382 92081 70382 92081 70384 92081 70384	50-259 50-259 50-259 50-259 50-259	к к к		8208270392 8208270457 8208270457 8208270457 8208270457		1 1 1
	62081 70387 62081 70387 62081 70387 62081 70387 62081 70392	50-259 50-259 50-259 50-259 50-259	K K K		8208270474 8208270488* 8208270492 8208270507* 8208270510		00000
	8208180017 8208180022+ 8208190179 8208200002 8208200008+	TOPREP TOPREP 50-327 50-327 50-327	P 8 8		0209270524* 9208270544 9208270548* 9208270601* 9208270601*	50-259 50-259 50-259 50-259 50-259	23888
	8208200014 8208200014 8208200030 8208200038 8208200038	50-370 50-370 50-276 50-370 50-370	8 8 8 8 8		8208270401* 8208270401* 8208270405* 8208270405* 8208270405*	50-294 50-259 50-259	****
	8208200041* 8208200062 8208200073* 8208200099 8208200105	50-274 50-259 50-259 50-439 50-390	8 8 8 8		8208270405* 8208300084 8208300084 8208300072 8208300092	50-438	8 8 8 8
	9209200105 9209200119 9209200129* 9209200167 9209200167	50-390 50-260 50-260 50-438 50-438	B 8 9		8208300125 8208300145 8208300202 8208300202 8208300211	50-438 50-438 50-438	8888
	8208200198 8208200198 8208200207 8208200207 8208200209	50-390 50-390 50-327 50-327 50-438	A A P P S		8208300211 8208300211 8208300211 8208300211 8208300211	50-326 50-326	8 8 8
	8208200207 8208200214* 8208200214* 8208230004 8208230331	50-438 50-327 50-327 50-327 50-259	8 P F F		8208300222 8208300222 8208300226 8208300226 8208300240		9999
	8208230331 8208230331 8208230351 8208230351	50-259 50-259 50-259 50-259 50-327	F F F F P		8208300252 8208300269 8208300269 8208300270 8208300304*	50-438 50-438 50-438 50-259 50-259	8 8 8
	8208230344 8208230375* 8208230375* 8208250374 8208250374	50-327 50-327 50-327 50-259 50-259	6 6 6 6		8208300324 8208300324 8208300334 8208300334 8208300338	50-438 50-438 50-438 50-438 50-390	8 8 9 8
	82082 50376 82082 50376 82082 50376 82082 60343# 82082 60346#	50-259 50-259 50-259 50-259 50-259	P P P F F	Tennessee, State of	9208300338 9208310200 9208020418 9208020422* 9208020425*	50-370 50-259 50-537 50-537 50-537	9 7 7 7 7
	8208270078 8208270082* 8208270086 8208270071* 8208270079	50-260 50-260 50-259 50-259 50-438	8 8 8	Texas Nuclear Div (subs. of Ramsay Eng Co) Texas Utilities Generating Co	9208260445* 9208030210 9208110162 9208160269 9208170144	50-446 50-445 50-445 50-445	8080
	8208270107 8208270128 8208270128 8208270128 8208270207 8208270218*	50-438 50-390 50-390 50-327 50-327	8 6 9 8		8208170239 8208170239 8208170244+ 8208170244+ 8208170164	50-445 50-445 50-445 50-445 50-445	A A A A
	8208270231 8208270245 8208270245 8208270251 8208270251	50-259 50-438 50-438 50-438 50-438	8 8 8 8		82082 50333 82082 70464 82082 70464 82082 70476* 82082 70476*	50-445 50-445 50-445 50-445 50-445	00000
	6206270252* 6208270275 6206270262 6208270263 6208270291*	50-259 50-390 50-260 50-390 50-260	8 8 8	Taxas Utilities Bervices, Inc	8208310298* 8208030271 8208240219 8208300119 8208310354	50-445 50-445 50-445 50-445 50-445	0 K A K
	8208270298 8208270304* 8208270324 8208270341 8208270341	50-328 50-328 50-438 50-370 50-370	8 8 8	The Analytic Sciences Corp Three Hile Island Alert Tolsdo Edison Co.	8208180151* 8208240245 8208240417 8208030042* 8208030051*	CONTRACT 50-287 50-287 50-346 50-346	0 0 F F
	6208270342 6208270342 6208270361 6208270361 6208270392	50-390 50-390 50-438 50-438 50-390	8 8 8 8		8208030056* 8208030567 8208040449* 8208040452*	50-346 50-346 50-346 50-346	# P F F

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEODRY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	82080 40610* 82080 40616* 82080 50238 82080 50242* 82080 50246*	50-346 50-346 50-346	- F F P		82080 90175# 82081 60245 82081 70204 82081 90135 82082 30158#	50-483 50-483 50-483 50-483 50-483	g H Q g g
	8208050385* 8208050455 9208050458* 8208060101* 8208060107*	50-346 50-346 50-346	0 8 5 F F		8208240132 8208240322 8208250318 8208260366* 8208260368*	50-463 50-466 50-463 50-463 50-463	AGFF
	8208040314* 8208040320* 8208040321* 8208040321*	50-346 50-346 50-346	F F F F F	Union of Concerned Scientists	8208270426 8208270428* 8206200004 8208050367 8208060100	50-463 50-463 FOIA 50-537 50-247	Q Q Q
	8208070112* 8208070113* 8208100200 8208100205* 8208110104	50-346 1 50-346 1	P P B B B	United Engineers & Constructors, Inc (subs of Raytheon Co)	82080 90258 82082 40454 82082 40457* 82081 90080*	50-267 50-267 50-267 50-443	0 0 A 8
	82081 10108* 82081 10110* 62081 10131 62081 10252* 82081 10253*	50-346 F 50-346 F	7 0 0 7 7		82081 90177 82082 30393 82082 30398* 82082 50190 82082 70345	50-324 TOPREP TOPREP 50-460 50-324	8
	8208130078 8208130086* 8208130148 8208130151* 8208130281	50-346 E 50-346 E	8 8 8 8	United Nuclear Corp. Utah, Univ of	8208270365 8208310354* 8208310367* 8208040039 8208060150*	50-324 GA999 GA999 70-820 50-407	9
	82081 30282* 82081 60024 82081 60450 82081 60462* 8208200007	50-346 50-346 50-346 50-346 1	8 H B B	Vermont Yankee Nuclear Power Corp	8208020188* 8208020189* 8208030405 8208050259 8208050263*	50-271 50-271 50-271 50-271 50-271	F F B
	6208200044 6208200114# 6208230353 6208240334 6208270244#	50-346 (50-346 (50-346 (0 9 0 0		82080 90120* 82081 70194 82081 70196* 82082 30165 82082 30170*	50-271 50-271 50-271 50-271 50-271	F 8 8 P
	9209270621# 9209270621# 9209270625# 9209270625# 9209300097	50-346 50-346 50-346 50-346	R R R R R		8208270353 8208270569* 8208270569* 8208270573* 8208270573*	50-271 50-271 50-271 50-271 50-271	P R R
	8208300100* 8208300133 8208300135* 8208310147* 8208310192	50-346 50-346 50-346 50-346	8 8 8 8 0 9	Virgania Electric & Power Co.	8208300078* 8207230301 8208020084 8208020088* 8208030240	50-271 50-339 50-338 50-339 50-339	9 P P
rrey Pines Technology	8209310217 8209310220* 8209310238* 8209310436 8208110130	50-346 50-346 50-346 50-528	8 8 9 9 9 8		8208030247# 8208030285 8208030289* 8208030294* 8208030310	50-339 50-260 50-260 50-260 50-338	9 5 6
	8208110130 8208110133# 8208110133# 8208110133#	50-528 50-528 50-528 50-528	R R R R R		8208030444 8208030444 8208030448* 8208030448* 8208030448	50-260 50-260 50-260 50-260 50-261	6 6 6
fransamerica Delaval, Inc fransnuclear, Inc futtle & Taylor	8208310311 8208100020 8208030714 8208030716* 8208030362	PT21 XPORTLIC XPORTLIC 50-537	e o		8208030470# 8208030477# 8208030478# 8208030478# 8208030534#	50-281 50-336 50-336 50-336	8 0 0
US Ecology, Inc (Formerly Nuclear Engineering)	92080 50352 92080 70153 92080 20224 92080 30117		0		8208030622* 8208050096 8208050103* 8208050235	50-280 50-339 50-339 50-338	8 00 00
	8208030128 8208030127* 8208050502 8208130158 8208130161* 8208130242	27-39 27-39 27-39 27-39 27-39 27-39			82080 50241* 82080 50323 82080 50330* 82080 50353 82080 50407* 82080 50422	50-338 50-339 50-339 50-339 50-338	* *******
Uniformed Services Univ. of the Health Sciences	8208170227 8208170234* 8208300027*		P		8208050431 # 8208050444 8208050452# 8208060200	50-338 50-339 50-339 50-280	# # # E
Union Carbide Corp.	8207200345 8208040044 8208040325 8208230219=	RE8 40-299 WABTE MOT 70-273			82080 60200 82080 60208* 82080 60220	50-280 50-280 50-339	£ 6 P
Union Electric Co	8208020358	50-537	н		8208090034	50-339	E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	Y	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	82080 90037* 82080 90101 82080 90101 82080 90105* 82080 90105*	50-339 50-280 50-280 50-280 50-280	 Տ P P P		9209270307* B20B270312* B20B270312* B20B270312* B20B270331	50-280 50-280 50-260	8 R R 9
	82080 90143 82080 90151* 82080 90162 82080 90166* 82081 00071	50-337 50-337 50-337 50-337 50-260	8 8 8 8 8 8 8		8208270336* 8208270366 8208270366 8208270668 8208270674*	50-338 50-338	8 P B
	8208100071 8208100110 8208100110 8208120110 8208120112*	50-280 50-280 50-280 50-280 50-280	8 P 9 8		8208270677* 8208300195 8208300195 8208300332 8208300332	50-280 50-280 50-280 50-280 50-280	8 0 0 8
	8208120116* 8208120148 8208120150* 8208120166 8208120166	50-280 50-338 50-338 50-280 50-280	8 R R G S	Volunteer Electric Cooperative N R Grace & Co	8208300337* 8208300340* 8208040434 8208200070 8208250093*	50-280 50-280 50-537 40-84 40-86	B B
	8208120170* 8208120175* 8208120203 8208120204* 8208120283	50-280 50-280 50-280 50-280 50-280	8 8 8 8 8		8208250074* 8208250105* 8208250112* 8208250114* 8208250117*	40-86 40-86 40-86 40-86 40-86	
	82081 20283 82081 20287* 82081 20287* 82081 60268 82081 60268	50-280 50-280 50-280 50-280 50-280	P P P B B		8208250120* 8208250121* 8208250122* 8208250125* 8208250130*	40-86 FDIA 40-86 40-86 40-86	
	82081 40275* 82081 40285* 82081 40402 82081 70144 82081 70173	50-280 50-280 50-280 50-338 50-339	8 9 0 0 P		8208250139* 8208250155* 8208250167* 8208250172* 8208250174*	40-86 40-86 40-86 FOIA 40-86	
	82081 90097 82081 90097 82081 90120 82081 90122 82081 90122*	50-280 50-280 50-338 50-338 50-338	ፑ ፑ የ የ		8208250177± 8208250237* 8208250244* 8208250247* 8208250330*	FOIA 40-86 40-86 40-86 40-86	
	82081 90122* 82081 90195 82081 90195 82081 90294 82081 90298*	50-338 50-280 50-280 50-337 50-339	ኮ ቦ ቦ		8208250334* 8208250347* 8208250352* 8208250354* 8208250357*	40-85 40-86 40-86 FOIA FOIA	
	8208170413* 8208170413* 8208170426* 8208170426* 8208200086	50-338 50-338 50-338 50-338 50-337	ድ መ ት		9208250364* 9208250370* 9208250370* 9208250372* 9208250375*	FOIA 40-86 40-86 40-86 40-86	
	8208200101* 8208200142 8208200153* 8208200169* 8208200227	50-339 50-281 50-281 50-281 50-338	8 8 8		8208250377* 6208250376* 8208250380* 8208250381* 8208250384*	FOIA 40-86 FOIA 40-86 40-86	
	8208200233* 8208230280 8208230280 8208230284* 8208230284*	50-338 50-280 50-280 50-280 50-280	8 P P P	Washington Public Power Bupply Bystem	82082 50389* 82082 50395* 82082 50396* 82082 50396* 82080 20130	40-86 FOIA FOIA 50-397 50-397	A A
	8208240315 8208240315 8208240315 8208240315 8208250150	50-260 50-260 50-260 50-280 50-280 50-338	F F F P		82080 20150 82080 20151 82080 20155 82080 20159 82080 20227	50-397 50-397 50-397 50-397 50-397	EKAA
	8208250154 8208250154* 8208250154* 8208250162* 8208250346	50-338 50-338 50-338 50-338 50-280	ե ե ե ե		9208020235 8208020238 8208020245 8208020250 8208030213		A X E ORP
	8208250344 8208270076 8208270076 8208270274 8208270279#	50-280 50-280 50-280 50-339 50-339	8 8 6 6		9208030233 9208040178 9208040203* 9208050343 9208050343	50-460 50-460	R A SI B
	8208270293# 6208270293# 8208270293# 8206270299# 8208270299#	50-338 50-338 50-338 50-338 50-336	A		8208050448 8208050448 8208050527 8208050527 8208040141	50-460 50-460 50-460 50-460 50-377	8 8 8 6
	8208270297* 8208270301 8208270303* 8208270303* 8208270303*	50-338 50-338 50-280 50-280 50-280	R R		8208040203 8208100072 8208100101 8208100150 8208100185	50-397 50-397 50-460 50-460 PRM	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE		AUTHOR AFFILIATION	ACCE8810N NUMBER	SUBJECT CATEODRY
	8208100231* 6209018028 6209102323* 8208100323*	50-460 50-460 50-460 50-460 50-460	а А а а	Westinghouse Electric Corp	6208090026* 6208170393 6208170393 6208240481 6207280256 6207280259*	40-1162 40-1162 40-1162 TOPREP TOPREP
	82081 10101 82081 10134 82081 40300 82081 40432 8208200090	50-397 50-397 50-508 50-460 50-397	8 8 8 8		8207280263* 8207300360 8207300365* 8207300371* 8207300376*	TOPREP TOPREP TOPREP TOPREP TOPREP
	8208240163 8208240183 8208240332 8208270001 8208270005*	50-50B 50-397 50-397 50-508 50-508	6 E K K		8208020063 8208020358 8208030139* 8208030177 8208030520	TOPREP 50-537 H 70-1151 TOPREP REVIEW ORP
	8208270011* 8208270014* 8208270017* 8208270020 8208270021	50-508 50-508 50-508 50-508 50-508	K M C K K		8208030532* 8208030564 8208030567* 8208030573* 8208030576*	50-413 A TOPREP TOPREP TOPREP TOPREP
	8208270026 8208270028 8208270031 8208270036 8208270039	50-508 50-508 50-508 50-508 50-508	K K K K		8208030583* 8208030588* 8208030722 8208040146* 8208040238	TOPREP TOPREP XPORTLIC 50-266 P XPORTLIC
	8208270043 8208270057 8208270060 8208270063 8208270068	50-508 50-508 50-508 50-508 50-508	K K K K		82080 50200* 62080 40224* 82081 3001 9 82081 40274* 82081 70142	QA999 50-339 P XPORTLIG 50-482 E TOPREP
	8208270073 8208270075 8208270077 8208270077 8208270080	50-508 50-508 50-508 50-508 50-508	K K K		8208170233 8208170310* 8208200051 8208200215 8208240371	TOPREP TOPREP PT21 TOPREP TOPREP
	8208270081 8208270084 8208270087 8208270073 8208270100	50-508 50-508 50-508 50-508 50-508	K K K K		8208240400* 8208260255 8208260248* 8208260273* 8208270323*	TOPREP TOPREP TOPREP TOPREP 50-265 0
	9208270104 9209270109 9208270113 8208270117 9208270121	50-508 50-508 50-508 50-508 50-508	K K K	Westinghouse Operating Plants Owners Group	8208300277 8208310302 8208310417 8208050090	PR TOPREP TOPREP TOPREP
	8208270124 8208270127 8208270130 8208270133 8208270136	50-508 50-508 50-508 50-508 50-508	K K K	Wheeling Hosp Wheeling, WV Wiegand Evaporators, Inc	82080 50094* 82081 70307 82081 00311 82082 30493 82082 30494*	TOPREP TOPREP REGGD XPORTLIC XPORTLIC
	8208270138 8208270140 8208270144 8208270147 8208270152	50-508 50-508 50-508 50-508 50-508	K K K	Wilbur Bmith & Associates Wilt, D.D	8208230496* 8208240309* 8207160215 8208090179 8208090179	XPDRTLIC 50-361 F 50-440 G 50-440 G
	8208270157 8208270166 8208270173 8208270178 8208270183	50-508 50-508 50-508 50-508 50-508	K K K		82080 90183 82080 90183 82080 90247 82080 90247 82080 90250	50-440 0 50-440 H 50-440 H 50-440 O
	8208270190 8208270196 8208270202 8208270208 8208270213	50-508 50-508 50-508 50-508 50-508	KKK	Wisconsin Electric Power Co.	82080 90250 82080 90254 82080 90254 82080 2010 9 82080 20115*	50-440 H 50-440 H 50-266 B 50-266 B
	8208300112 8208300321 8208300321 8208310224 8208310227*	50-397 50-508 50-508 50-508 50-508	8 8 8		8208020273 8208030440 8208030440 8208030472 8208030472 8208040140	50-266 @ 50-266 P 50-266 P 50-266 0 50-266 0
te Management, Inc.	82083 10229* 82083 10297 82083 10382 82083 10391 * 62081 10125	50-508 50-397 50-460 50-460 27-47	8 6		8208040140 8208040140 8208040288* 8208040293* 8208100084 8208110180	50-266 P 50-266 F 50-266 F 50-266 F 50-266 P 50-266 0
ne, NJ Branch Conservation Association Chicago, IL Chester County,NY	8208230374* 6208160440 8208300318 8206060006* 8208020270	FOIA 50-247 40-2061 50-247 50-3	e F H		8208130109 8208130109 8208130130 8208130130 8208130130	50-266 F 50-266 P 50-266 P 50-266 P
ern Illinois Power Cooperative, Inc. ern Nuclear, Inc. (subs. of Phelps ge Corp.)	8208240161 8207220663 8207220673* 8208090025	50-454 40-1162 40-1162 40-1162	н		82081 60041 82081 60043* 82081 60043* 82081 60446	50-266 R 50-266 R 50-266 R 50-266 R 50-266 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	<u>.</u>	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	
	92081 40510 92091 40518* 92091 70046 92091 70048* 92091 70268	50-301 50-301 50-301 50-301 50-266	8 8 P P		8208230153+ 8208230141+ 8208230172+ 8208240181 8208240250	50-305 S 50-305 S 50-305 S 50-305 K 50-305 P	
	82081 70248 82081 70188 82081 70188 82081 70224 82081 70224	50-266 50-266 50-266 50-266 50-266	P F F F	Wisconsin's Environmental Decade	8208240253* 8208300183 8208310205 8208310305 8208030074*	50-305 P PRM 50-305 P 50-305 P 50-537 D	
	8208200151 8208200151 8208200293 8208240370* 8208240370*	50-266 50-266 50-266 50-266 30-266	Q Q Q Q	Wisconsin, Univ of, Madison	82081 00234 82081 20117 8208270448 8208030484 8208030488=	REVIEW GRP 50-266 0 50-266 0 50-156 R 50-156 R	
	8208240057* 8208240047* 8208240047* 8208240240 8208270315	50-246 50-266 50-266 50-266 50-266	F F G Q	Hood-Leaver & Associates, Inc Hoodward-Clyde Consultants, Inc Hyle Laboratories Hyoming Mineral Corp.	8208170261* 8208120111* 8208040373 8208170372 8208170388	50-155 P 50-206 P 50-537 H 40-8502 40-8502	
	8208270315 8208270319* 8208270319* 8208270323* 8208270411	50-246 50-246 50-266 50-266 50-266	0 0 0 0	Hyoming Mining Association Hyoming, State of X-Scan Inspection Co	8208040339 8208040252 8208050045 8208240482 8207070036	WASTE MOT 40-299 40-299 40-8781 71-478	
	8208270486 8208270503 8208270577* 8208270577* 8208270577*	50-266 50-266 50-266 50-266 50-266	G G R R	Yankes Atomic Electric Co	8207070037* 8207300522 8208020185 8208020283* 8208020292	71-478 50-443 A 50-29 P 50-443 G 50-29 8	
	8208270581* 8208270581* 8208270581* 8208310171* 8208310171*	50-266 50-266 50-266 50-266 50-266	R R R Q Q		8208020301* 8208040261* 8208040304* 8208040309* 8208050408	50-29 8 50-443 F 50-29 F 50-29 F 50-443 A	
Wisconsin Public Bervice Corp	8208310264 8208310269* 8208020191* 8208020192* 8208030396	50-301 50-301 50-305 50-305 50-305	۵ 8		8208050533 9208050537* 9208060184 920806050 920806052*	50-29 P 50-29 P 50-29 P 50-29 S 50-29 S	
	8208030513 8208030517# 8208050276 8208050486 8208050499#	50-305 50-305 50-305 50-305 50-305	P P 8 8		8208070118 8208070122* 8208070206 8208100137 8208110102	50-29 8 50-29 8 50-29 P 50-29 0 50-443 A	
	82080 40324 # 82080 40328 # 82080 9020 9 82080 9021 4 # 82080 90253	50-305 50-305 50-305 50-305 50-305	F F 8 9 F		92081 20232 92081 20234* 92081 20297 92081 70229 92081 70323	50-29 R 50-29 R 50-443 A 50-29 P 50-443 A	
	8208100159 8208100178 8208100181* 8208120213 8208120214*	50-305 50-305 50-305 50-305 50-305	G P P R R		82081 90075 82081 90155 82082 90222 82082 90222	50-443 A 50-443 A 50-443 S 50-443 S	
	8208120220 8208130093 8208130098* 8208130102* 8208130137	50-537 50-305 50-305 50-305 50-305	H 8 9 9 4		62082 30032 62082 30045 * 82082 30072 82082 30074 * 82082 40280 *	50-29 8 50-29 8 50-29 8 50-29 8 50-29 0	
	8208130235 8208130243* 8208170078 8208170081* 8208230142	50-305 50-305 50-305 50-305 50-305	& 8 8 9		8208240281 8208270547# 8208270550* 8208270629# 8208270638#	50-27 R 50-27 R	
				Yuba Heat Transfer Corp Zack Co	8208310053* 8208310055* 8208020358 8208140248		: {

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	6UBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION HUMBER	SUBJECT CATEOGRY	OTHER REPORT NUMBER
9209250029 9209250074 9645-H-259 R02	8208250029 8208250074 8208120255* 8208110049	RE9 RE9 50-416 E 50-247 F	BNL-NUREO-31611 E00-BEMI-5913	01-7163 02-0540-1108 RB 12-1132517	8208300292* 8208330266* 8208160435*	50-387 F 50-255 P 50-312 P	
ABAI-81-001 ATR-9DD-8204	8208040166*	50-387 F		1934 1843 RB	8208250145* 8208240396*	50-333 P 50-528 G	
B-82-273 BAW-1732 BR-5853-C-4 CFC-2A RO1	8208080178* 8208040148* 8208300271* 8208110114*	50-361 F 50-312 F 50-206 F TOPREP	1	186-028-12 18700: 1 26160 1 548-9142 ERR	8206110309* 8208030532* 8208060226* 8208240412*	50-409 Q 50-413 A 50-339 P 50-528 Q	
CABRP-3 VOR RO4	8208060167*	50-537		5504-816-611K255A	8208310333*		FLA-1125
DOE/EP/10004-1 DPC-RD-2001 R01 E119-1 R01 EF-128 E00-1183-1827	8208030385* 8208240239* 8208200274* 8208240147* 8208300038*	REVIEW QRI 50-287 I 50-387 I 50-16 I 50-213 I		611K110 R00 800-78-014 8104-2 81A0044 R01 81A0045 R00	8208310339* 8208030389* 8208250358* 8209170125* 8209170121*	50-388 G REVIEW GRP 50-413 A 50-409 P	PLA-1125
EGG-1183-4212 EGG-EA-5340 EGG-EA-5931 EGG-EA-5961 [R-191-010	8105210393* 8208180247* 8208170003* 8208240444* 8208050117*	50-333 50-155 50-155	•	81A0045 R00 81A0047 R00 81A0048 R00 81A0049 R00 81A0031 R00	8208170131* 6208170119* 8208170100* 8208120217* 8208170112*	50-409 P 50-409 P 50-409 P 50-409 P	
LAC-TR-112 NPGP-1 RO3 NPGP-2 RO0 NAC-E-B01 RO3 NEDO-21471-01 801	8208200083* 6208120223* 6208120224* 6208240134* 6207120253*	71-6698		62~4 ROO 6207180465 6207200365 6208020060 6208020061	8208170257* 8207150485 8207200345 8208020060 8208020061	50-387 P RES RES RES RES	BNL-NUREQ-31417 EQQ-EE-5845 HR-CD-82-066
NEDO-22209 NEDO-22209 DRFT NEDO-22434A ERR 07 NEDO-24344 NUREO-0020 V06 N04	8208310347* 8208310353* 8208270273* 8206070868* 8208240424	TOPREP 50-387 50-254	82NED088 6 82NED088 7 79NED273 9 81NED277	8208030045 8208030048 8208030109 8208040002 8208040004	8208030045 8208030048 8208030107 8208040002 8208040004	RES RES RES RES	E00-CDD-5801 E00-TF8P-5600 E00-TF8P-5700
NUREO-0390 VO6 NO1 MUREO-0430 VO2 NO1 NUREO-0485 VO4 NO6 NUREO-0325 RO5 NUREO-0325 RO5	8208230001 8208070004 8208070012 8208230417 8208170006	NUREG NUREG NUREG NUREG 50-329	3	8208040005 8208040007 8208040010 820804001B 8208040024	8209040005 8208040007 8208040010 8208040018 8208040024	REB REB REB REB	E00-caad-5857 E00-8emi - 5859 E00-ea-5844 E00-ea-5840 E00-luft-5861
NUREO-0546 VOZ NOS NUREO-0580 VII NO7 NUREO-0717 804 NUREO-0750 VIS NOS NUREO-0776 803	8208130471 8208180120 8208230411 8208130476 8208040173	NUREO	Ξ £	8208040027 8208040036 8208040030 8208040030 8208040167	9208040027 8208040036 8208040043 8208040050 8208040147	REO REO REO REO REO	E00-CAAD-5860 E00-LOFT-5731 E00-LOFT-5732 BNL-NUREQ-31390 E00-EA-5721
MUREQ-0831 803 MUREQ-0837 VO2 NO1 MUREQ-0833 801 MUREQ-0871 VOI NO3 MUREQ-0872	8208040131 8208130449 8208130470 8208180212 8208040281	NUREO	E	8208040622 8208040627 8208036005 8208036007 8208050011	8208040622 8208040629 8208030005 8208030009 8208030011	RE8 RE8 RE8 RE8 RE8 RE8	ORNL/ED/E18-174 ORNL/HABRD-151 ORNL/FTR-1330
MUREO-0875 MUREO-0883 MUREO-0887 801 MUREO-0892 801 MUREO-0910	8208170312 8208260429 8208230422 8208260427 8208180245		E E	8208040037 8208040052 8208040054 8208110008 8208110098	8208040039 8208040052 8208040054 8208110008 8208110078	REB REB REB REB 50-304 P	E00-L0FT-5930 E00-E4-5533 E00-L0FT-5340 E00-BEMI-5919 BML-NUREO-31290
MUREO-0915 MUREO-0917 MUREO-0920 MUREO-0921 MUREO-0931	8208130477 8208260068 8208040222 8208230415 8208040344		D P	82081 1024 1 82081 801 58 82081 90354 82081 90360 8208240045	8208110241 8208180158 8208170354 8208170360 8208240045	REB REG 50~313 P REB REB	BNL-NUREG-31413 BNL-NUREG-31566 EGG-EA-5742 EGG-LOFT-5769

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATE GORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER
NUREQ-0936 V01 NO2 NUREQ/BR-0025 V08 N9 NUREQ/CP-0025 NUREQ/CP-0032 NUREQ/CP-0034 V01	8208230002 8208130478 8208180217 8208260406 8208260401	NUREO NUREO NUREO NUREO NUREO	PNL-4235 BNL-NUREG-51552	NUREG/CR-2833 VO3 NUREG/CR-2837 NUREG/CR-2842 NUREG/CR-2851 NUREG/CR-2852	9209260017 8208130475 8208120366 8208260066 8208180227	NUREG NUREG NUREG NUREG NUREG	PNL-4327
NUREO/CP-0034 V02 NUREO/CR-0169 V11 NUREO/CR-0200 V01 ER NUREO/CR-1598 NUREO/CR-2053 ERR	8208240420 8208240484 8208240027 8208180237 8208240008	NUREG NUREG NUREG NUREG NUREG	EGG-2037 DRNL/NUREO/CSD- PNL-3369 DRNL/NUREO/TM-4	NUREO/CR-2669 NUS-4148 NUS-958 ROO UNWI-144 P 109-4-839-005 ROO	8208260505 8208260350* 8208310167 8208060134* 8208270212*	NUREG 50-324 F 50-334 K WASTE MOT 50-275 P	ANL/ES-128
NUREO/CR-2264 NUREO/CR-2281 VO4 NUREO/CR-2383 NUREO/CR-2400 NUREO/CR-2403 ERR	8208180232 8208120368 8208130480 8208260414 8208130483	NUREO NUREO NUREO NUREO NUREO	PNL-4215 LA-9305-PR PNL-4067 \$AND82-0462	R547 01 8ECY-82-153 8ECY-82-194 8ECY-82-204 EECY-82-204A	8208230285* 8204220343 8208190034 8206100427 8207220055	50-247 Q SECY SECY SECY SECY	IEB-80-11
NUREG/CR-2403 BO1 ER NUREG/CR-2407 NUREG/CR-2437 VO4 NUREG/CR-2520 NUREG/CR-2525 VO4	8208260034 8208260075 8208130472 8208090016 8208260087	NUREO NUREO NUREO NUREO NUREO	BANDB2-0927 PNL-4071 ANL-81-77 VO4 ORNL/NUREQ/TM-4	STD-R-02-001 R05 STD-R-02-004 R00 STD-R-02-006 R00 STR-54282-1 TER-C5257-181	8208170052# 8208170053# 8208170023# 8208040190# 8208040560#	71-9151 71-9151 71-9084 50-387 P 50-259 P	21020 21020
NUREO/CR-2533 NUREO/CR-2549 NUREO/CR-2550 NUREO/CR-2563 NUREO/CR-2579	8208260473 8208260112 8208040200 8208260440 8208260499	NUREO NUREO NUREO NUREO NUREO	ORNL/TH-7945 9AND02-0324 ORNL/TH-0217 ORNL/TH-0118	TER-C5297-289 TER-C5297-304 TER-C5297-435 TER-C5297-444 DRF T TER-C5257-445	8206220204* 8208050028* 8207260247* 8208240344* 8208170163*	50-27 P 50-313 P 50-213 P 50-244 P 50-213 P	
NUREO/CR-2612 ERR NUREO/CR-2614 NUREO/CR-2649 NUREO/CR-2675 VO1 NUREO/CR-2690	8208230035 8208260466 8208260471 8208180126 8208180241	NUREG NUREG NUREG NUREG NUREG	ORM_/TM-B099 BNL-NUREG-51514 BANDB2-0752 PNL-4241 BANDB2-0953	TER-C5287-451 DRFT TER-C5287-529 TER-C5506-132 TER-C5506-141 TER-C5506-145	8208250548* 8208060161* 8206280418* 8206280525* 8206300163*	50-289 G	1EB-80-04 IEB-80-04 IEB-80-11
NUREO/CR-2705 NUREO/CR-2707 NUREO/CR-2712 NUREO/CR-2714 NUREO/CR-2716 VO1	8208180222 8208260080 8208130479 8208260097 8208170306	NUREG NUREG NUREG NUREG NUREG	ORNL/TM-8327 ORNL/TM-8329 8AND82-7051 ECO-2206 PNL-4275-1	TER-C5506-303 TR 839 RA TR 840 TR 841 RA TR 842	8208030167* 6208250383* 6208250371* 6208250402* 6208250415*	50-29 P 50-259 P 50-259 P 50-259 P	
NUREG/CR-2749 VO1 NUREG/CR-2749 VO2 NUREG/CR-2749 VO3 NUREG/CR-2749 VO4 NUREG/CR-2749 VO5	8208070021 8208040323 8208040215 8208070019 8208170010	50-313 P 50-317 P 50-302 P 50-315 P 50-323 A		TR 843 TR 845 RA TR 846 TR-5599-3 TR-5633-2	8208250426* 8208250437* 8208250443* 8208250308* 8207140053*	50-259 P 50-259 P 50-259 P 50-387 P 50-322 A	
NUREG/CR-2749 V06 NUREG/CR-2749 V07 NUREG/CR-2749 V08 NUREG/CR-2749 V09 NUREG/CR-2749 V10	8208130115 8208040311 8208060357 8208040208 8208090014	50-220 P 50-269 P 50-277 P 50-312 P 50-335 P		TR-82026-2 TVA-TR75-1A ERR UEC-TR-001 R06 VEP-FRD-49 VEP-FRD-50	8208050432* 8208180022* 8208230398* 82081902988*	50-416 P TOPREP TOPREP 50-339 P 50-338 P	
NUREQ/CR-2749 V11 NUREQ/CR-2749 V12 NUREQ/CR-2750 NUREQ/CR-2752 V01 NUREQ/CR-2762	8208040245 8208090010 8208130473 8208240438 8208170303	50-280 P 50-289 P NUREO NUREO A	ORM_/TM-8365 ORM5884	WCAP-10015 WCAP-10105 WCAP-9500-A VOI WCAP-9500-A VOZ WCAP-9500-A VO3	8208160276* 8208190310* 8208030567* 8208030573* 8208030578*	50-482 E TOPREP TOPREP TOPREP	
NUREO/CR-2774 VO1 "EQ/CR-2782 G/CR-2784 J/CR-2787 VO1 J/CR-2793	8208120362 8208130474 8208260433 8208260479 8208260037	NUREO NUREO NUREO 50-313 P NUREO	ANL-82-24 V01 SAND82-0978	HCAP-9500-A V04 HCAP-9500-A V05 HCAP-9736 R01 HCAP-9864 WLA-1-R-82-05	8208030583* 8208030588* 8208260273* 8207280263* 8208170261*	TOPREP TOPREP TOPREP TOPREP 50-155 P	
)/CR-2794)/CR-2796)/CR-2798)/CR-2799)/CR-2833 VO1	8208260434 8208170316 8208130481 8208130467 8208260002	NUREO NUREO NUREO NUREO NUREO	BANDB2-0799 ORNL/NBIC-206 ORNL/NBIC-208 ORNL/NBIC-209	XN-NF-82-20 903 XN-NF-82-45 R01 XN-NF-82-57	8208120087* 8208170188* 8208170206*	TOPREP 50-244 P 50-244 P	

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

ENCLOBURE	PRINCIPAL DOCUMENT	DATE	BUBJECT	
8010280028	8208310426	82/07/30	71-6698	
8103180387	8208250001	82/07/26	50~261	9
8103250375	8208250001	82/07/26	50-327	8
8103250402	8208250001	82/07/26	50-327	a
8105210393	8208050066	82/07/28	50~254	P
0201140133	8208250061	82/06/17	40-86	
6202220663	8208110215	82/07/28	50-416	F
6204130421	B208120056	82/08/05	50-440	E
8204170004	8204190002	82/03/25	71-9161	
8204210308	8208230418	82/07/29	FOIA	
8205060412	8208040660	82/07/14	60-322	Н
8205060422	8208040660	82/07/14	50-322	н
8205110591	8208090343	82/07/22	50~387	P
8204010033	8208230418	82/07/29	FOIA	
8509090009	8207300508	82/07/07	50-247	F
8204040022	8208100350	82/07/09	50-247	U
6206070868	8206070829	82/05/03	50-324	P
8204110309	8208310327	82/08/25	50-409	a
8206130005	8204130070	82/07/15	50-35B	Ü
6206130015	8208070033	82/07/21	MISC	-
8206140404	8208070336	82/07/23	50-387	'P
8206150017	B20415000B	82/05/14	FOIA	-
8206150020	8204150008	82/05/14	FOIA	
8206150021	8206150008	92/05/14	FOIA	
8206150024	8204150008	82/05/14	FOIA	
B206150027	8206150008	82/05/14	FOIA	
8206150031	8206150008	82/05/14	FOIA	
8206150035	B204150008	82/05/14	FOIA	
8206200027	B208040532	82/07/21	50-275	₽
8206200036	8207300503	82/07/09	50-250	Н
8206200038	8207200095	82/07/08	50-320	v
8205200044	8207200110	62/07/09	50-329	Ä
8206200050	B20B100370	82/07/19	50-271	Ü
B204220204	B20B190199	82/08/16	50-29	p
8206270038	8208040266	82/07/21	50-537	D
8206270049	8208120349	82/08/03	50-440	A
8204280418	8208190001	82/07/25	50-307	G
6206280525	8208040452	82/07/21	50-289	Ğ
6205290168	8208310035	82/07/13	FOIA	
8206270171	8208310035	82/07/13	FOIA	
8206300163	8208300029	82/08/16	50-321	a
8207010234	8207010228	82/04/25	50-34B	ē
0207010251	8207010228	82/04/25	50~34B	8
9207050006	8208120364	82/08/03	ACRE	-
8207050009	8208050065	82/07/27	50-537	D
	9208120351	55 (AD /c -	50-289	н
0207050016		82/08/04		п
9207060191	9207060189	82/06/23	40-3453	
0207060192	8207060189	82/06/23	40-3453	
0207070037	8207070036	82/06/17	71-478	
Ø20707005B	8207070028	82/06/25	50-329	K

NGGEWAY PI	- HOUNEM			
	PRINCIPAL	DATE	BUBJECT	
ENCLOSURE	DOCUMENT	THEVED	CATEGOR	Y
			p	
8207070401	8207070390	85/06/30	50-352	K
6207070406	8207070390	82/06/30	50-352	ĸ
8207080426	8207080424	82/06/10	50-275	Q.
8207090216	8207090205	82/06/27	50-334	19
8207120078	8207120070	82/07/06	50-259	F
8207120083	8207 120070	92/07/06	50-259	F
B207120253	B207120147	80/06/18	50-447	Ą
B207140053	8207140050	82/07/09	50-322	A
8207150411	8207150400	82/06/24	50-460	Ģ
8207150421	8207150400	82/06/24	50-460	G.
E207180477	0007180417	82/07/12	50-327	8
8207150422	8207150417	82/06/28	50-508	ã
8207150434	8207150428			a
8207150442	8207150426	82/06/28	50-508 FOIA	u
8207160365	8208270010	82/07/13		P
8207200061	8207 200060	82/05/19	50-973	r
9207200520	8207 200515	82/05/30	40~B674	
8207220673	8207220663	B2/04/30	40-1162	
	8207 230343	82/07/14	50-389	F
8207230345	8207 230343	B2/07/14	50-389	F
8207230348	8207 230343	82/07/14	50-389	F
8207230349	8501 \$30343	82/0//14	30-367	г
8207260247	6208240251	82/08/12	50-213	p
8207280259	8207280256	82/07/15	TOPREP	•
8207280263	8207280254	82/07/15	TOPREP	
8207300365	8207300360	82/07/28	TOPREP	
8207300371	8207300360	82/07/28	TOPREP	
DEG/OGGI1	0207 300000	02.0,,20		
9207300376	8207300360	92/07/28	TOPREP	
8208020018	8204150008	82/05/14	FOIA	
8208020054	8208020051	82/07/16	50-2B2	P
820B020054	8209020051	82/07/16	50-282	р
8208020062	6208020051	82/07/16	50~282	p
8208020044	8208 020064	82/05/21	CONTRACT	•
B208020069	8208020068	82/07/02	CONTRACT	•
8208020070	8208 020067	82/07/21	50-416	8
8208020078	8208020072	82/07/27	50-313	P
8208020083	8208020080	82/07/21	50-327	8
8208020084	6208020075	82/07/20	50-369	8
6208020088	8208020086	82/07/26	50-338	P
8208020089	8208020085	82/07/21	50-325	8
8208020090	8208020097	62/07/20	50-369	8
8208020096	8208020094	82/07/22	50-260	8
		DO 107 100	21000	
8208020099	8208020095	82/07/28	0A999	
8208020101	8208020097	82/07/30	50-537	B
8208020107	8208020102	82/07/23	50-325 50-324	8
8208020110	6208020105	82/07/21		8
8208020113	8208020111	82/07/22	50-259	2
0000000115	0200020100	82/07/21	50-266	8
8208020115	8208020109	82/07/21	50-348	8
8208020118	8208020116 8208020116	82/07/22	50-348	8
8206020122		82/07/20	50-292	8
8208020123	8208020119	82/07/28	QA977	4
8208020128	8208020125	45101150	am 777	

	N NUMBER					IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSVED	BUBJEC CATEGD		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 168UED	SUBJECT CATEGORY	
8208020129 8208020131 8208020133 8208020135 8208020136	9208020126 9208020116 9208020125 9208020127 9208020127	82/07/28 82/07/22 82/07/28 82/07/21 82/07/28	50-298 50-348 GA999 50-335 GA999	р 9	8208020379 8208020385 8208020386 8208020391 8208020391	8208020375 8208020381 8208020382 8208020388 8208020393	62/07/23 82/07/26 82/07/27 82/07/22 82/07/23	50-32B B 50-286 8 50-325 B 50-317 8 50-361 8	1
8208020139 8208020141 8208020145 8208020153 8208020164	8208020125 8208020137 8208020140 8208020147 8208020160	82/07/28 82/07/21 82/07/21 82/07/23 82/07/21	0A777 50-272 50-416 50-336 50-267	888	8208020412 8208020416 8208020417 9208020412 8208020422	8208020407 8208020413 8208020414 8208020418 8208020418	82/07/13 82/07/22 82/07/22 82/07/20 82/07/20	ACR8 50-335 8 50-341 8 50-537 U 50-937 U	•
9208020167 9208020170 9209020174 9209020178 9209020179	8208020163 8208020166 8208020171 8208020176 8208020117	82/07/23 82/07/19 82/07/20 82/07/14 82/07/14	50-328 50-443 50-348 50-373 50-373	8 8 8 8	8208020432 8208020434 8208020432 8208020454 8208020454	8208020428 8208020431 8208020449 8208020451 8208020456	82/06/28 82/07/19 82/07/21 82/07/07 82/07/07	70-2936 50-537 D CONTRACT 50-277 P 50-133 H	
8208020180 8208020183 8208020186 8208020188 8208020189	8208020177 8208020181 8208020184 8208020187 8208020187	82/07/23 82/07/16 82/07/20 82/07/13 82/07/13	50-251 50-312 50-237 50-271 50-271	84844	8208020461 8208020464 8208020469 8208030005 8208030006	8208020460 8208020463 8208020463 8208030004 8208030004	82/06/25 82/07/14 82/07/14 82/07/19 82/07/19	71-9159 50-352 F 50-352 F 50-322 F 50-322 F	
6208020191 6208020192 6208020194 6208020195 6208020197	8208020190 8208020190 8208020193 8208020193 8208020194	82/07/13 82/07/13 82/07/13 82/07/13 82/07/14	50-305 50-305 50-244 50-382	111111	8208030019 8208030020 8208030023 8208030026 8208030028	8208030013 8208030018 8208030021 8208030021 8208030024	82/07/20 82/07/21 82/07/07 82/07/07 82/07/28	50-213 F 50-275 Q 50-327 P 50-327 P 50-416 F	!
8208020178 8208020202 8208020204 8208020212 8208020214	8208020196 8208020201 8208020203 8208020203 8208020203	82/07/14 82/07/14 82/07/20 82/07/20 82/07/20	50-382 50-312 50-361 50-361 50-361	F 8 8 8 8	8208030029 8208030032 8208030042 8208030051 8208030056	8208030021 8208030024 8208030036 8208030047 8208030047	82/07/07 82/07/28 82/07/28 82/07/28 82/07/28	50-327 P 50-416 F 50-346 F 50-346 F	
8208020219 8208020228 8208020232 8208020234 8208020239	8208020203 8208020223 8208020229 8208020225 8208020225	62/07/20 62/07/29 62/07/21 62/07/23 62/07/23	50-361 50-244 50-247 50-213 50-213	8 9 P	8208030063 8208030045 8208030070 8208030073 8208030074	0400E080SB 0400E080SB 0400E080SB 6400E080SB 1700E080SB	82/07/14 82/07/14 82/07/14 82/07/19 82/07/15	50-309 P 50-309 P 50-309 P 50-369 F 50-537 D	
8208020247 8208020254 8208020262 8208020267 8208020270	8208020246 8208020257 8208020257 8208020259 8208020264	82/07/23 82/07/22 82/07/19 82/07/27 82/07/19	50-133 50-249 50-312 50-313 50-277	8 8 F	8208030083 8208030084 8208030085 8208030086 8208030090	8208030078 8208030046 8208030080 8208030078 8208030038	62/07/19 62/07/19 62/07/04 62/07/19 62/07/19	50-387 F 50-369 F 50-247 H 50-387 F 50-282 F	
8208020274 8208020278 8208020283 8208020284 8208020285	8208020266 8208020264 8208020276 8208020280 8208020279	82/07/22 82/07/19 82/07/28 82/07/14 82/07/19	50-244 50-277 50-443 50-322 50-309	9	8208030091 8208030099 8208030100 8208030103 8208030103	8208030038 8208030072 8208030074 8208030072 8208030074	82/07/19 82/07/21 82/07/19 82/07/21 82/07/19	50-282 F 50-348 P 50-373 F 50-348 P 50-373 F	
8208020286 8208020287 8208020293 8208020294 8208020295	8208020288 8208020282 8208020282 8208020282	82/07/14 82/07/29 82/07/14 82/07/29 82/07/30	50-322 50-255 50-322 50-255 50-358	Q Q P K	8208030104 8208030117 8208030122 8208030124 8208030127	8208030092 8208030114 8208030121 8208030123 8208030125	82/07/21 82/07/07 82/05/28 82/06/16 82/06/07	50-348 P WABTE MOT 40-8584 40-8786 27-39	
9208020301 9208020302 9208020304 8208020308 9208020310	8208020292 8208020297 8208020299 8208020305 8208020299	82/07/23 82/07/15 82/07/29 82/07/20 62/07/29	50-29 70-36 50-255 50-412 50-255	B G P	8208030131 8208030135 8208030137 8208030139 8208030139	8208030127 8208030132 8208030132 8208030134 8208030132	82/07/14 82/07/26 82/07/26 82/07/28 82/07/26	70-143 70-1113 70-1113 70-1151 70-1113	
8208020314 8208020316 8208020321 8208020322 8208020323	6208020305 6208020313 6208020306 6208020320	82/07/23 82/07/20 82/07/24 82/07/23 82/07/23	50-361 50-412 50-244 50-361 50-263	8 8 8	8208030144 8208030145 8208030146 8208030148 8208030151	8208030134 8208030132 8208030134 8208030134 8208030143	82/07/28 82/07/26 82/07/28 82/07/28 82/07/28	70-1151 70-1113 70-1151 70-1151 50-27 Q	
8208020325 8208020326 8208020327 8208020329 8208020330	8208020318 8208020320 8208020315 8208020324 8208020320	82/07/29 82/07/23 82/07/21 82/07/21 82/07/23	50-324 50-263 50-272 50-206 50-263	P 8 8	8208030154 8208030144 8208030167 8208030169 8208030176	8208 0301 50 8208 0301 60 8208 0301 62 8208 0301 65 8208 0301 73	82/07/27 82/07/27 82/07/29 82/07/29 82/07/19	50-327 8 50-259 8 70-600 50-29 P 50-373 Q	
8208020331 8208020334 8208020339 8208020342 8208020343	8208020319 820802030A 8208020338 8208020334	82/07/22 82/07/23 82/07/23 82/07/28 82/07/28	50-259 50-341 50-341 50-293 50-382	8 8 8	8208030178 8208030182 8208030183 8208030191 8208030194	8208030175 8208030180 8208030185 8208030184 8208030172	82/07/28 82/07/13 82/07/12 82/07/20 82/07/08	50-257 B 50-324 G 50-413 G 50-43B G 50-413 G	
9208020346 9208020347 9208020357 9208020359 9208020360	8208020332 8208020334 8208020351 8208020353 8208020355	82/07/14 82/07/29 82/07/14 92/07/21 82/07/29	50-373 50-382 50-373 50-311 50-255	8 8 8	8208030207 8208030212 8208030215 8208030216 8208030221	8209030205 8208030208 8208030211 8208030214 8208030218	82/07/27 82/07/13 82/07/23 82/07/02 82/07/07	50-314 B 50-338 Q 50-349 B 50-438 Q 50-280 Q	
8208020345 8208020346 8208020377 8208020377 8208020378	8208020354 8208020350 8208020370 8208020372 8208020370	82/07/29 82/07/23 82/07/19 82/07/20 82/07/19	50-255 50-361 50-220 50-289 50-220	P 8 0 0	8208030224 8208030225 8208030231 8208030234 8208030237	8208030200 8208030222 8208030222 8208030222 8208030234	82/07/06 82/07/28 82/07/28 82/07/28 82/07/28	50-250 G 50-438 G 50-438 G 50-438 G 50-409 P	

ACCE8910				AC	CEEBION	HUMBER		
ENCLOSURE	PRINCIPAL DUCUMENT	DATE DBUBBI	SUBJECT CATEGORY	and an		PRINCIPAL	DATE	SUBJECT
8208030241	6208030230	82/07/29	50-395 A	82080: ENCLO:		DOCUMENT	188UED	CATEGORY
8208030243 8208030244	8208030235 8208030222	82/07/19 82/07/28	70-1113 50-438 G	82080	3048B	820803045B 8208030484	82/07/27	50-369 P 50-156 R
8208030245 8208030246	8208030239 8208030239	82/07/29 82/07/29	50-295 P 50-395 A	B5080:	30492	8208030482 8208030480	82/07/27 82/07/28	50~416 9 50~390 0
8208030247	8208030240	82/07/23	50-337 8	82080		8208030469	82/07/27	50-338 0
8208030251 8208030253	8208030230 8208030230	82/07/29 82/07/29	50-395 A 50-244 P	82080 82080	30498	8208030458 8208030504	82/07/26 82/07/29	50-369 P 50-139 0
8208030257 8208030259	6208030230 6208030250	82/07/29 82/07/29	50-395 A 50-244 P	82080: 82080:	30509	8208030458 8208030469	82/07/26 82/07/27	50-349 P 50-338 Q
8208030240	8208030250	82/07/29	50-244 P	920803		0208030458	82/07/26	50-369 P
8208030274 8208030280	0208030273 0208030275	82/07/29 82/07/30	50-275 R 50-275 Q	82080: 82080: 82080:	30517	8208030505 8208030513	82/07/27 82/07/22	70-1201 50-305 P
9208030292 9208030297	8208030272 8208030285	82/07/20 82/07/26	50-546 A 50-280 8	82080: 82080:	30530	8208030458 8208030526 8208030524	82/07/26 82/07/26	50-369 P 50-313 R
8208030294	8208030285	82/07/26	50-280 B	82090;		B20B030521	82/07/26	50-413 A
8208030300 8208030303	8208030298 8208030297	82/07/28 82/07/23	50-312 P 50-287 B	92090: 82090:	30538	8208030528 8208030531	82/07/27 82/07/14	50-280 G 50-338 G
8208030304 8208030307	8208030293 8208030299	82/07/28 82/07/28	70-1113 50-289 K	82090; 82090;	30546	8208030521 8208030541	82/07/14 82/07/27 82/07/30	50~302 Q 50~280 Q
8208030323	8208030305	82/07/09	50-348 g	82050;		8208030549	82/07/22	50-269 P 50-265 K
8208030324 8208030324	B208030316	82/07/15 82/07/08	70-1201 50-413 q	92080: 82080:	30557	820803034B 8208030541	82/07/14 82/07/30	50-269 K 50-269 P
8208030333 8208030340	8208030330 8208030338	82/07/14 82/07/21	70~824 50~237 8	82080; 82080;	30541	8208030521 8208030547	82/07/27 82/07/26	50-280 0
8208030345	8208030343	92/07/30	50-334 R	82080		8208030564	82/07/09	50-327 G
8208030347 8208030356	9208030342 9208030353	82/07/27 82/07/23	70-27 50-34B G	92080: 92080:	30573	8208030564 8208030521	82/07/09 82/07/27	TOPREP 50-280 Q
9208030359 8208030360	8208030355 8208030355	82/07/30 82/07/30	50-447 K 50-447 K	92080: 92080:		8208030568 8208030564	82/07/19 82/07/09	REVIEW ORP
9209030361 9209030364	8208030353 8208030353	82/07/23 82/07/23	50-348 Q 50-348 Q	82080:	30579	8208030572	82/07/30	50-369 P
9208030367 8208030367	8208030353 8208030355	82/07/23 82/07/29	50-348 Q 50-348 Q 27-48	920803 920803		8208030564 8208030564	82/07/09 82/07/09	TOPREP TOPREP
8208030373	8208030366	82/07/22	50-438 Q	92080: 92080:		8208030582 8208030585	82/07/26 82/07/30	50-259 Q 50-416 P
8208030374 8208030377	8208030371 8208030375	82/07/27 82/07/23	50-263 F 50-321 G	920803		8208030592	B2/07/26	50-259 q
8208030376 8208030379	8208030366 8208030375	82/07/22 82/07/23	50-438 G 50-321 G	82080: 82080:	30600	82080305B9 8208030594	82/07/21	50-228 R 50-438 G
8208030381	8208030366	82/07/22	50-438 Q	85080: 85080:		8208030582 8208030594	82/07/26 82/07/26	50-259 0 50-438 0
8208030382	8208030375 8208030380	82/07/23 82/07/22	50-321 Q REVIEW ORP	92080		9208030565	82/07/30	50-416 P
8208030384 8208030385	820803036A 8208030388	82/07/22 82/07/22	50-438 Q REVIEW ORP	820803 820803	30610	B208030595 B208030582	82/07/27 82/07/26	50-269 Q 50-259 Q
8208030387	8208030375	82/07/23	50-321 Q	820803 820803		8208030594 8208030599	82/07/26 82/07/09	50-438 Q 50-269 Q
8208030389 8208030390	8208030380 8208030375	82/07/22 82/07/23	REVIEW ORP	820800 820800		9208030594 9208030595	92/07/26 92/07/27	50-438 0 50-267 0
8208030394 8208030397	8208030366 8208030375	82/07/22 82/07/23	50-438 Q 50-321 Q	82,0803 82,0803	30620	8208030585 8208030403	82/07/30 82/07/30	50-414 P 50-295 F
8208030398	8208030393	82/07/07	50-338 Q	820803		8208030615	82/07/28	50-290 Q
8208030408 8208030409	8208030400 8208030327	82/07/22 82/07/08	50-416 G 50-370 G	820803 920803		8208030617 8208030595	82/07/26 82/07/27	50-335 Q 50-269 Q
8208030417 8208030417	8208030404 8208030400	82/07/29 82/07/22	50-250 Q 50-416 Q	820803 820803	30626	8208030615 8208030615	82/07/28 82/07/28	50-280 Q 50-280 Q
6208030423 6208030425	8208030400	82/07/22 82/07/08	50~416 G	820803		9208030617	82/07/26	50-335 G
62080304RB	8208030414 8208030400	82/07/22	30-416 G	820803 820803		8208030617 8208030615	82/07/26 82/07/28	50-335 Q 50-290 G
8208030430 8208030434 8208030435	8208030400 8208030400	82/07/30 82/07/22	50-454 Q	820803 820803	30639	8208030595 8208030629	82/07/27 82/07/28	50-269 G 70-1151
8208030433	8208030424	82/07/30 82/07/20	50-454 Q 50-373 8	8208 03		B20B030417	82/07/26	50-335 G
8208030447 8208030448	8208030445 8208030444	82/07/06 82/07/29	50-373 8 0A979 50-280 P	820803 820803	30453	8208030585 8208030585	92/07/30 92/07/30	50-416 P 50-416 P
8208030450 8208030451	8208030442 8208030446	82/07/21 82/07/30	50-260 P 50-321 8 50-352 A	820803 820803	E990E	8508030929 8508030285	82/07/30 82/07/22	50-416 P 70-143
8208030452	8208030445	B2/07/04	GA999	820803		8208030585	02/07/30	50-416 P
8208030457 8208030459	8208030424 8208030453	82/07/30 82/07/15	50-454 Q 50-389 Q	620803 620803	30685	8208030454 8208030454	82/07/22 82/07/22	70-143 70-143
8208030461 8208030464	8208030454 8208030458	82/07/26 82/07/26	50-335 8 50-349 P	820803 820803	30699	8208030694 8208030694	92/07/22 92/07/22	50-400 Q 50-400 Q
8208030465	8208030440	82/07/23	50-269 8	820803 820803		8208030694 8208030701	82/07/22	50-400 Q
8208030470 8208030471	8208030463 8208030458	82/07/26 82/07/26	50-281 B 50-369 P	820803 820803	30706	8208030701 8208030694 8208030714	82/07/14 82/07/22 82/07/13	GEN TEC 18 50-400 O XPORTLIC
8208030473 8208030474	6208030466 6208030443	82/07/28 82/07/29	50-390 Q TOPREP	820803 820803	30728	8208030684 8208030714	82/07/20 82/07/20	50-3 F 50-3 F
8208030476	8208030467	82/07/09	50~34B Q	B20803		8208030733	82/07/14	CONTRACT
8208030477 8208030478	8208030463 8208030469	82/07/26 82/07/27	50-281 8 50-338 0	820803 820803	30744	8208030742 8208030747	82/07/15 82/07/15	50-537 D 50-537 D
8208030479 8208030486	8208030458 8208030469	82/07/26 82/07/27	50-369 P 50-338 G	920803 820804	30752	8208030751 8208040022	82/07/13 82/07/13	50-537 D CONTRACT

ACCESSID.					ACCESS I O	N NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBBUED	BUB JECT CATEOOR	
8208040035 8206040041 8208040048 8208040066 8208040067	8208040033 8208040037 8208040045 8208040057 8208040061	82/05/18 82/07/15 82/07/15 82/07/29 82/07/13	50-409 50-537 50-537 50-335 50-269	D D P H	8208040481 8208040483 8208040499 8208040553 8208040551	8208040469 8208040493 8208040493 8208040490 8208040512	82/07/23 82/07/22 82/07/02 82/07/22 82/07/22	50-254 50-10 CONTRACT 50-267	F F F
8208040069 8208040071 8208040080 8208040089 8208040095	8208 040043 8208 040057 8208 040074 8208 040086 8208 040092	82/04/30 82/07/29 82/07/15 82/07/15 82/07/15	71-480 50-335 50-537 50-537 50-537	P D D	8208040526 820804054 1 8208040550 8208040550 8208040552	8208040512 8208040537 8208040548 8208040555 8208040556	82/07/22 82/07/28 82/07/22 82/07/22 82/07/19	50~247 WASTE MO CONTRACT 50~259 50~373	F T P Q
8208040106 8208040107 8208040114 8208040122 8208040134	8208040102 8208040104 8208040112 8208040118 8208040127	82/07/15 82/07/20 82/07/15 82/07/15 62/07/15	50-537 50-389 50-537 50-537 50-537	A D D	8208040547 8208040610 8208040614 8208040615 8208040640	8208040556 8208040604 8208040607 8208040604 8208040634	82/07/19 82/07/30 82/06/25 82/07/30 82/05/28	50~373 50~346 40~8745 50~346 40~8768	P
9208040146 9208040149 9208040166 9208040181 9208040188	8208040140 8208040143 8208040142 8208040180 8208040184	82/07/28 82/07/21 82/07/28 82/07/30 82/05/17	50-266 50-329 50-387 50-482 50-322	PAPKA	8208040643 8208040646 8208040651 8208040657 8208040471	8208040637 8208040642 8208040642 8208040632 8208040667	82/06/18 82/07/22 82/07/22 82/07/21 82/07/15	CONTRACT 50-282 50-282 50-289 CONTRACT	P P Q
6208040170 6208040176 6208040203 6208040224 6208040232	8208040142 8208040172 8208040174 8208040217 8208040227	82/07/28 82/07/28 82/07/13 82/08/02 82/07/30	50-387 50-321 50-397 50-537 50-155	PFAGG	8208040477 8208040480 8208040685 8208050013 8208050025	8208040473 8208040474 8208040482 8208050012 8208050021	82/07/14 82/06/04 82/07/29 82/07/23 82/07/22	40-8135 CONTRACT CONTRACT 50-285 50-322	P A
8208040239 8208040243 8208040246 8208040258 8208040260	8208040233 8208040227 8208040240 8208040254 8208040253	82/07/20 82/07/16 82/07/16 82/07/19	50-322 50-155 50-336 71-62 50-382	400	8208050028 8208050035 8208050041 9208050042 8208050044	8208050026 8208050031 8208050038 8208050040 8208050040	82/07/26 82/07/16 82/07/23 82/07/28 82/07/28	50-313 40-8497 71-9132 50-293 50-293	P P
8208040261 8208040274 8208040278 8208040288 8208040289	8208040255 8208040265 8208040265 8208040283 8208040287	62/07/20 82/07/20 82/07/20 82/07/20	50~443 50~289 50~289 50~266 50~361	क्रमसम	8208050080 8208050085 8208050086 8208050091 8208050092	8208050065 8208050082 8208050078 8208050084 8208050088	82/07/28 82/07/21 82/07/08 82/07/23 82/07/19	50-254 50-245 CONTRACT 50-219 50-317	P G S
8208040270 8208040273 8208040274 8208040277 8208040277	8208040284 8208040283 8208040284 8208040292 8208040284	82/07/30 82/07/30 82/07/30 82/07/30	50-454 50-266 50-454 50-361 50-454	P C	8208050074 8208050079 8208050103 8208050105 8208050111	8208050070 8208050097 8208050076 8208050100 8208050108	92/07/21 92/07/21 92/07/29 92/07/29 92/07/29	TOPREP 50-311 50-337 50-328 50-328	8 8 8
8208040300 8208040301 8208040303 8208040304 8208040308	8208040272 8208040272 8208040284 8208040278 8208040284	82/07/30 82/07/30 82/07/30 82/07/20 82/07/30	50-361 50-361 50-454 50-29 50-454	PPOFG	8208050117 8208050118 8208050124 8208050125 8208050125	8208050114 8208050115 8208050120 8208050121 8208050128	82/07/16 82/07/09 82/07/28 82/08/02 82/07/23	50-336 50-247 50-325 50-287 50-334	9 8 8
8208040309 8208040312 8208040316 8208040317 8208040319	0208040278 8208040284 8208040284 8208040314 8208040314	82/07/20 82/07/30 82/07/30 82/07/20	50-29 50-454 50-454 50-309 50-309	FOOFF	8208050130 8208050131 8208050133 8208050137 8208050137	8208050121 8208050124 8208050119 8208050119 8208050135	82/08/02 82/07/16 82/07/16 82/07/16 82/07/19	50-289 50-219 50-361 50-361 50-458	FBPPO
8208040330 8208040334 8208040340 8208040355 8208040358	8208040326 8208040326 8208040336 8208040350 8208040353	82/07/23 82/07/23 82/07/21 82/07/21 82/07/13	50-261 50-261 Contract 50-267 50-10	F G F	8208050146 8208050161 8208050167 8208050170 9208050176	8208050140 8208050158 8208050163 8208050164 8208050172	92/06/28 92/07/30 92/07/16 92/07/29 92/08/02	CDNTRACT 50~328 50~213 50~276 GA777	8 F 8
8208040341 8208040342 8208040374 8208040375 8208040379	8208040353 8208040359 8208040371 8208040371 8208040378	82/07/13 82/07/22 82/07/13 82/07/13 92/07/19	50-10 40-8786 50-277 50-277 50-277	F F F	6208050177 8208050178 8208050194 8208050200 8208050200	9209050175 8208050171 8208050190 8208050192 8208050197	\$2/07/23 \$2/08/03 \$2/07/28 \$2/08/02 \$2/07/26	70-2684 50-361 50-482 0A979 50-369	P 01
8208040391 8208040392 8208040393 8208040399 8208040405	8208040380 8208040383 8208040383 8208040396 8208040403	82/07/28 82/07/28 82/07/20 82/07/22 82/07/22	50-331 50-331 CONTRACT 71-5796 71-9139	F F	6208050207 8208050209 8208050213 8208050214 8208050220	8208050199 8208050205 8208050206 8208050205 8208050217	92/07/28 92/07/22 92/07/29 92/07/22 92/07/16	50-368 50-354 50-257 50-354 50-247	8000
9209040442 9209040447 9209040449 9209040452 9209040455	8208040437 8208040440 8208040444 8208040444 8208040448	82/07/22 82/07/15 82/07/28 82/07/28 82/07/22	50-321 50-537 50-346 50-346 50-389	P D F F	6208050222 6208050221 6208050231 6208050234	8208050215 8208050218 8208050229 8208050230 8208050233	82/07/29 82/07/21 82/07/29 82/07/22 82/07/28	50~240 50~277 50~259 50~254 50~295	8000
8208040456 8208040458 8208040459 8208040461 8208040463	8208040453 8208040448 8208040448 8208040453 8208040462	82/07/15 82/07/23 82/07/22 82/07/23 82/07/15	50-537 50-272 50-389 50-272 50-537	D F F D	6208050241 8208050242 8208050243 8208050245 8208050249	8208050235 8208050238 8208050239 8208050238 8208050171	82/07/26 82/07/30 82/07/21 82/07/30 82/07/23	50~339 50~346 50~293 50~346 50~247	# P O P B
8208040464 8208040467 8208040475 8208040477 8208040477	8208 040453 8208 040457 8208 040469 8208 040409 8208 040473	82/07/23 82/07/26 82/07/23 82/07/13 82/07/22	50-272 50-337 50-254 CONTRACT 50-10	P A F	9209050251 8208050252 8208050265 9208050263 8208050265	8208050247 8208050248 8208050256 8208050259 8208050262	82/07/23 82/07/29 82/07/20 82/07/22 82/07/27	50-313 50-335 50-123 50-271 50-368	0 8 H 9 8

ACCESSION					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGORY	_	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT	_
6208050249 8208050271 8208050274 8208050277 8208050278	8208050264 8208050266 8208050270 8208050272 8208050275	82/07/22 82/07/21 82/07/26 82/07/26 82/07/22	50-271 50-293 50-219 50-320	0 8 8 8 8	8208040040 8208040042 8208040043 8208040044 8208040044	8208060050 8208060059 8208060050 8208060050 8208060058	82/05/27 82/08/02 82/05/27 82/05/27 82/05/27	50-254 50-320 50-254 50-254	P F P F
8208050281 8208050285 8208050288 8208050292 8208050299	8208050279 8208050275 8208050287 8208050287 8208050287	82/07/29 82/07/22 82/07/21 82/07/21 82/07/16	50-217 50-334 50-334	8 9 9 9	8208050070 8208050072 8208050078 8208050079 8208050081	8298060065 8298060067 8298060047 8298060074 8298060074	82/08/02 82/08/02 82/08/02 82/08/02	50-317 50-317 50-244	F F F
8208050300 8208050304 8208050306 8208050317 8208050321	8208050276 8208050270 8208050275 8208050308 8208050317	82/07/16 82/07/19 82/07/22 82/07/22 82/07/16	50-265	6 6 6	8208040093 6208040096 6208040101 6208040101	8208060090 8208060090 8208060091 8208060094 8208060091	82/07/30 82/07/30 82/07/28 82/08/02 82/07/28	50-155 50-346 50-346	0 P F P
8208050322 8208050325 8208050326 8208050330 8208050333	8208050310 8208050317 8208050320 8208050323 8208050327	82/07/28 82/07/16 82/07/20 82/07/28 82/07/30	50-295 50-277 50-358 50-337 50-327	6 9 0 8	8208040108 8208040109 8208040129 8208040130 8208040134	8208060091 8208060094 8208060127 8208060127 8208060128	82/07/28 82/08/02 82/08/03 82/08/03 82/07/28	50-346 50-263	P F F
8208050337 8208050337 8208050341 8208050342 8208050344	8208050315 8208050334 8208050324 8208050336 8208050335	82/07/20 82/07/24 82/07/30 82/07/30 82/07/21	50-309 50-313 50-260 50-327 50-272	8 8 8	82080&0139 82080&014& 92080&0150 82080&0155 82080&0158	8208060125 8208060143 8208060147 8208060149 8208060153	82/07/16 82/08/02 82/08/02 82/07/29 82/07/30	50-325 50-387 50-407 50-313 50-311	0 9 0 R 0
9208050358 9208050342 9208050372 9208050375 9208050377	8208050346 8208050354 8208050367 8208050371 8208050349	82/07/19 82/07/28 82/07/28 82/07/19 82/07/30	50-219 50-315 50-316 50-318 50-267	8 8 8 8	8208040141 8208040147 8208040148 8208040149 8208040149	8208040157 8208040164 8208040163 8208040165 8208060172	82/08/03 82/08/04 82/08/03 82/08/02 82/08/02	50-206 50-537 50-312 50-267 50-315	P A P F P
8208050380 8208050383 8208050385 8208050386 8208050392	8208050368 8208050376 8208050382 8208050364 8208050359	82/07/21 82/07/26 82/07/30 82/07/21 82/07/19	50-311 50-331 50-346 50-317 50-317	8 0 8	8208050185 9208060187 8208060195 8208060195 9208060196	8208060183 8208060182 8208060187 8208060193 8208060191	82/07/30 82/07/27 82/07/27 82/07/29 82/08/02	50-395 50-3&6 50-3&6 50-3&6 50-416	A 8 8 8
8208050395 8208050397 8208050398 8208050400 8208050401	8208050388 8208050357 8208050373 8208050370 8208050374	82/07/16 82/07/28 82/07/19 82/07/21 82/07/29	50-245 50-261 50-10 50-219 50-296	F 8 0 8	8208050207 9208050208 9208050212 8208050216 9208050218	8208040204 8208040200 8208040204 8208040213 8208060200	82/08/03 82/07/26 82/07/30 82/08/02 82/07/26	50-275 50-280 50-336 50-285 50-280	P 8 0 8
8208080402 8208080403 8208050405 8208050407 8208050411	8208050355 8208050373 8208050387 8208050353 8208050406	82/07/27 82/07/19 82/07/19 82/07/28 82/07/16	50-369 50-10 50-318 50-339 50-336	8 8 8	6209060223 6209050226 6209050237 6209060230 6208060231	8208060219 8208060220 8208060232 8208060248 8208060246	82/07/30 82/08/04 82/08/02 82/07/28 82/08/03	50-326 50-337 50-416 50-373 50-309	A & & & & & & & & & & & & & & & & & & &
8208050416 8208050417 8208050423 8208050426 8208050429	8208Q50410 8208050409 8208050412 8208050424 8208050412	82/07/29 82/07/29 82/07/16 82/07/19 82/07/16	50-309 50-327 50-317 50-254 50-317	0 0 0	8209060236 8208060262 8208060264 8208060271 8208060271	8208040255 8208040241 8208040243 8208040257 8208040270	92/08/02 92/07/30 92/08/03 92/07/20 92/07/30	50-364 50-395 50-348 50-409 50-409	P P P P
6208050431 6208050432 6208050435 6208050441 6208050451	8208050422 8208050428 8208050424 8208050414 8208050445	82/07/28 82/07/30 82/07/19 82/07/12 82/07/23	50-338 50-416 50-254 50-237 50-334	8 9 0 9	9209060274 8209060280 8209060284 8209060284 8209060272	8208040273 8208040270 8208040270 8208040283 8208040283	82/08/02 82/07/30 82/07/30 82/07/22 82/07/22	50-416 50-409 50-409 50-322 50-322	8 P A A
8208050452 8208050454 8208050457 8208050458 8208050460	8208050444 8208050447 8208050450 8208050455 8208050455	82/07/28 81/11/24 82/07/29 82/07/23 82/07/14	50-339 50-478 50-259 50-346 50-219	8 8 8	8209060302 8209060305 8209060312 8209060312 8209080318	8208040278 8208040304 8208040304 8208040304	82/08/03 82/07/28 82/08/03 82/08/03 82/08/03	50-397 50-443 50-409 50-409 50-346	p f f f
8208050468 8208050469 8208050478 8208050487 8208050499	8208050441 8208050440 8208050462 8208050482 8208050486	82/08/04 82/07/16 82/07/21 82/08/03 82/07/28	50-413 50-271 50-155 50-206 50-305	9 9 9	82080A0318 82080A0320 82080A0324 82080A0324 82080A0328		82/08/02 82/08/02 82/08/02 82/08/02 82/08/02	50-346 50-346 50-346 50-305 50-305	F F F F
8208050507 8208050516 8208050521 8208050526 8208050537	8208050492 8208050507 8208050508 8208050513 8208050533	82/07/21 82/07/27 82/07/19 82/07/23 82/07/30	50-272 50-333 50-282 50-309 50-27	8 8 8	02.000.0032 02.000.0036 02.000.0036 02.000.0036 02.000.0036	8208040331 8208040331	82/07/29 82/07/29 82/07/23 82/07/23 82/07/22	50-346 50-346 CONTRACT CONTRACT	τ
8208050537 8208060002 8208060025 8208060034 8208060036	9208050531 9208060001 9208060023 9208060032	82/07/30 82/07/19 82/07/19 82/08/02 82/08/02	50-293 CONTRAC CONTRAC 50-285 50-285		82080400376 8208040003 8208040003 8208040035 8208040035	8208090001 8208090015 8208090025	82/07/23 82/06/09 82/07/15 82/06/30 82/07/21	70-1810 WASTE N 50-537 40-1162 50-309	D
9208040044 9208040047 9208040054 9208040055 9208040057	9208060040 9208060040 9208060042 9208060051 9208060051	82/08/02 82/08/02 82/07/15 82/08/02 82/08/02	50-321 50-313 50-321	FFFF	820804003: 820804004: 820804004: 820804004: 820804005:	8208090034 8208090040 8208090044	82/08/02 82/07/22 82/07/30	40-8743 50-339 50-265 50-317 50-29	8 0 8

ACCESSION NUMBER		ACCEBBIO	N NUMBER	
PRINCIPAL DATE	D CATEGORY	ENCLOSURE	PRINCIPAL DATE DOCUMENT ISSUE	
8208090053 8206130070 82/07 8208090054 8208090054 82/08 8208090060 82/08 82/07 8208090064 82/07 82/07 8208090064 82/07 82/07	702 50-315 F 730 50-546 0 730 50-317 B	8208100082 8208100086 8208100093 8208100099 8208100100	8208100076 82/08/ 6208100077 82/07/ 6208100088 82/08/ 6208100085 82/08/ 8208100074 82/07/	28 50-272 8 05 50-206 P 05 50-537 0
8208090074 8208090072 82/07, 8208090074 82/07, 8208090074 82/07, 8208090073 82/07, 8208090083 82/07, 8208090085 82/07,	30 50-317 8 27 70-2174 30 50-317 8	6208100105 8208100108 8208100113 6208100121 8208100144	8208100099 82/07/ 8208100096 82/07/ 8208100107 82/08/ 8208100116 82/07/ 8208100141 82/07/	30 50-344 B 05 40-8791 29 50-313 B
8208090090 8208090087 82/07. 8208090094 8208090091 82/07. 8208090095 8208090097 82/07. 8208090096 8208090093 92/07. 8208090097 8208090091 82/07.	16 50~456 G 20 50~334 P 29 50~331 B	8208100150 8208100151 8208100155 8208100155 8208100174	8208100140 82/08/ 8208100143 82/08/ 8208100143 82/08/ 8208100148 82/08/ 8208100148 82/08/	03 50-286 F 03 50-286 F 03 50-206 P
8208090103 E208090101 82/08. 8208090112 8208090108 82/08. 8208090113 8208090108 82/08. 8208090115 8208090110 82/07. 8208090120 8208090116 82/07.	03 50-346 P 03 50-346 P 30 50-317 B	8208100181 8208100196 8208100205 8208100208 8208100212	8208100178 82/08/ 8208100192 82/08/ 8208100200 82/07/ 8208100199 82/07/ 8208100204 82/08/	06 27~4B 28 50-346 8 30 50-318 8
8208090122 8208090118 82/07. 8208090127 8208090124 82/08. 8208090128 8208090125 82/08. 8208090132 8208090130 82/08. 8208090134 8208090133 82/08.	05 50-327 Q 30 50-325 B 04 50-295 Q	8208100213 8208100217 8208100219 8208100220 8208100220	8208100207 82/07/3 8208100204 82/08/0 8208100210 82/07/3 8208100214 82/08/4 8208100215 82/08/6	04 50-155 Q 30 50-254 B 02 50-354 Q
8208090138 8208090135 82/06, 8208090149 8208090147 82/08, 8208090151 8208090143 82/08, 8208090166 8208090162 82/08, 8208090166 82/08/08/08/08/08/08/08/08/08/08/08/08/08/	04 50-416 8 02 50-337 8 02 50-337 5	8208100225 8208100227 8208100231 8208100235 8208100237	8208100221 82/07/3 8208100222 82/08/0 8208100224 82/08/0 8208100228 82/06/0 8208100233 82/08/0	05 50-309 P 06 50-460 G 09 50-261 G
8208090171 8208090149 82/08, 8208090173 8208090173 82/07, 8208090173 82/08, 8208090173 82/08, 8208090181 8208090174 82/08,	31 50-261 8 04 50-483 G 05 50-346 G	8208100242 8208100244 8208100248 8208100280 8208100280 8208100287	8208100237 82/07/2 8208100240 82/07/2 8208100245 82/07/2 6208100238 82/07/2 8208100252 82/07/2	27 50~373 0 26 70~371 27 50~320 8
8208090210 8208090152 82/08/ 8208090214 8208090219 82/07/ 8208090216 8208090211 82/08/ 9208090218 8208090212 82/07/ 8208090227 8208090221 82/07/	30 50-305 8 02 50-361 8 30 50-325 8	8208100259 8208100243 8208100245 8208100274 8208100274	8208100255 82/07/3 8208100255 82/07/3 8208100252 82/07/3 8208100250 82/08/0 8208100268 82/08/0	27 70-820 29 50-249 Q 35 50-460 Q
8208090230 8208090228 82/07/ 6208090235 8208090232 82/07/ 8208090234 8208090231 82/07/ 8208090239 8208090237 82/08/ 8208090240 8208090238 82/08/	27 50-367 8 22 50-275 0 02 50-335 B	82081 00274 82081 00278 82081 00282 82081 00283 82081 00289	8208100271 82/07/3 8208100275 82/08/6 8208100272 82/08/6 8208100271 82/07/3 8208100289 82/07/3	05 50-289 R 02 50-317 P 02 50-255 0
8208u70241 8208u70231 82/07/ 8208090245 8208u90244 82/07/ 8208090248 8208u90244 82/07/ 8208090231 8208u90247 82/07/ 8208090255 8208u90246 82/07/	20 50-237 8 29 50-327 P 29 50-409 8	8208100303 8208100307 8208100316 8208100318 8208100323	8208100297 82/07/2 8208100302 82/08/6 8208100312 82/08/6 8208100308 82/08/6 8208100314 82/08/6	06 50-320 P 07 * 50-387 K 05 50-321 Q
\$208090254 8208090259 82/07/ \$208090247 8208090259 82/07/ \$208090273 8208090248 82/07/ \$208090277 8208090271 82/07/ \$208090278 8208090272 82/08/	30 50-304 8 30 50-155 8 27 50-321 8	8208100327 8208100333 8208100334 8208100342 8208100343	8208100327 82/07/2 8208100327 82/07/2 8208100330 82/08/0 8208100338 82/07/2 8208100339 82/08/0	23 50-220 0 25 50-373 8 30 50-315 8
8208090279 8208090275 82/07/ 8208090281 8208090286 82/08/ 9208090289 8208090286 82/07/ 8208090293 8208090291 82/07/ 8208100016 8208100011 82/07/	04 50-416 8 28 50-368 0 28 40-8027	9208100347 <i>9208100357</i> 8208100362 8208100363 8208100371	820810033B 82/07/5 8208100354 82/07/5 8208100354 82/07/5 8208100354 82/07/6 8208100366 82/04/5	27 50-344 P 27 50-344 P 27 50-344 P
9208100017 8208100014 82/07/ 8208100018 8208100010 82/07/ 8208100019 8208100008 82/08/ 8208100028 8208100022 82/07/ 8208100029 8208100024 82/07/	28 50-272 8 06 50-361 0 26 50-445 0	8208100372 8208100375 8208100374 8208100374 8208110002	8208100369 82/07/2 8208100369 82/07/2 8206200099 82/07/2 8206200100 82/07/2 8208110001 82/07/2	29 50-313 F 26 COMMISSION 27 COMMISSION
0208100032 8208100026 82/07/ 8208100035 8208100030 82/08/ 8208100039 8208100030 82/08/ 8208100040 8208100036 82/08/ 8208100042 82/08/ 82/08/	09 50-247 F 09 50-247 F 06 50-333 R	8208110003 8208110004 8208110045 8208110037	8208110001 82/07/3 8208110001 82/07/3 8208110043 82/07/3 8208110053 82/07/3	90 50-317 P 15 50-337 P 08 40-8452
8208100050 8208100043 82/07/ 8208100054 8208100046 82/07/ 8208100055 8208100049 82/07/ 8208100057 8208100041 82/07/ 8208100058 8208100052 82/08/	26 50-344 8 21 50-254 8 29 50-317 8	8208110061 8208110077 8208110108 8208110110 8208110111	8208110058 82/07/5 8208110077 82/08/6 8208110106 82/08/6 8208110106 82/08/6 8208110112 82/08/6	72 30-341 F 73 50-346 P 73 30-346 P
8208100062 8208100055 82/07/ 8208100068 8208100064 82/07/ 8208100070 8208100066 82/07/ 8208100074 8208100055 82/08/	90 50-317 8 04 50-482 A 12 50-392 0	8208110120 8208110122 8208110132 8208110133 8208110134	8208110117 82/08/0 8208110119 82/08/0 8208110127 82/08/0 8208110130 82/08/0 8208110127 82/08/0	05 50-29 F 05 50-396 F 03 50-528 R

ACCESSION	NUMBER				ACCESSIO	IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	BUDJECT CATEGOR	٧	ENCLOSURE	PRINCIPAL	DATE	SUBJECT	
8208110142 8208110145 8208110184 8208110186 8208110189	8208110139 8208110140 8208110181 8208110181 8208110185	82/08/05 82/08/07 82/08/07 82/08/09 82/08/09	50-142 50-329 50-352 50-352 50-352	00000	8298120150 8298120150 8298120152 8208120175 8208120175	BOGUMENT 8208120148 8208120147 8208120165 8208120164 8208120166	188VED 	50-338 50-204 50-285 50-280 50-280	RRFBB
8208110199 8208110200 8208110202 8208110203 8208110204	8208110174 8208110178 8208110201 8208110178 8208110178	82/08/04 92/08/09 92/07/28 92/08/09 92/08/06	50-155 50-287 50-324 50-289 50-10	0 0 0 P	8208120178 8208120181 8208120182 8208120186 6208120190	8208120172 8208120174 8208120180 8208120174 8208120184	82/08/03 82/07/15 82/08/02 82/07/15 82/08/05	50-249 50-250 50-204 50-250 50-260	8 R B R
8208110204 8208110207 8208110208 8208110209 8208110210	8208110178 8208110178 8208110205 8208110178 8208110178	82/08/09 82/08/09 82/08/09 82/08/09 82/08/09	50-289 50-289 50-387 50-289 50-209	0000	8208120195 8208120197 8208120198 8208120202 8208120204	8208120193 8208120194 8208120191 8208120201 8208120203	62/08/05 62/07/14 62/07/29 62/07/12 82/07/15	40-3453 50-368 50-366 50-327 50-280	R R R
8208110211 8208110217 8208110218 8208110221 8208110222	8208110194 8208110216 8208110216 8208110219 8208110220	82/08/06 82/07/30 82/07/30 82/08/04 82/07/29	50-155 50-320 50-320 50-259 50-331	9 4 4 4 6	9209120211 8208120212 8208120214 9209120217 8208120217	8208120208 8208120210 8208120213 8208120215	82/07/12 82/07/14 82/07/12 82/08/04 82/07/22	50-334 50-315 50-305 50-286 50-409	RRRR
8208110223 8208110225 8208110227 8208110231 8208110233	8208 10219 8208 10220 8208 10227 8208 10228 8208 10228	92/08/04 92/07/29 92/07/08 92/07/23 92/07/23	50-259 50-331 XPORTLIC 50-261 50-261	F F P	\$208120223 8208120224 8208120228 8208120231 8208120233	8208 2022 8208 2022 8208 20199 8208 20227 8208 20226	82/08/09 82/08/09 82/08/03 82/07/30 82/07/14	50-329 50-329 50-321 50-349 50-259	AABBR
8208110234 8208110235 8208110237 8208110238 8208110242	8208 10230 8208 10232 8208 10228 8208 10230 8208 10240	62/08/05 62/07/15 62/07/23 62/08/05 62/08/05	50-254 50-537 50-241 50-254 50-250	F D F F	8209120204 8208120205 8208120207 8208120207 8208120207	8208120232 8208120227 8208120230 8208120238 8208120245	82/07/09 82/07/30 82/08/05 82/07/13 82/07/09	50-29 50-348 50-247 50-213 50-244	R G R
8208110244 8208110248 8208110249 8208110252 8208110253	8208110240 8208110246 8208110246 8208110251 8208110251	82/08/05 82/08/05 82/08/05 82/08/05	50-250 50-321 50-346 50-346	4 4 4 4	6206120253 6206120255 6206120257 9208120262 6208120262	6208120245 8208120244 8208120246 8208120254 8208120257	82/08/09 82/08/09 82/08/03 92/08/04 82/08/04	50-334 50-416 50-334 50-328 50-317	P E P 6
9208110256 9208110261 9208110263 9208110265 9208110267	9208110254 8208110254 8208110257 8208110259 8208110266	02/08/05 02/08/05 02/08/05 02/08/05 02/08/05	50-295 50-295 50-295 50-295 50-275	****	8208120274 8208120275 8208120280 8208120280 8208120283	8208 20260 8208 2027 8208 2027 7 8208 2028 3 8208 2027 1	82/07/14 82/07/30 82/08/02 82/08/09 82/07/08	50-316 50-270 50-336 50-280 50-409	R B B P R
8208110275 8208110283 8208110287 8208110287 8208110270	8208 10264 8208 10279 8208 10279 8208 10286 8208 10279	62/08/05 82/07/22 82/07/22 82/08/03 82/07/22	50-275 50-259 50-259 50-373 50-259	ななななな	8208120294 8208120300 8208120300 8208120307 8208120307	8208 120288 8208 120294 8208 120297 8209 120303 8208 120301	82/07/08 82/07/14 82/08/09 82/08/02 82/08/06	50-373 50-336 50-416 HIBC 50-317	R R E
8208110291 8208110292 8208110294 8208110302 8208120013	8208110288 8208110288 8208110288 8208110300 8208120012	82/07/27 82/07/27 82/07/27 82/08/03 82/08/03	50-334 50-334 50-334 CONTRACT 50-324	9 9 1	8208120310 82001120313 82001120315 8201120315	9209120305 8208120305 8208120297 8208120312 8208120314	82/07/07 82/07/07 82/08/09 82/08/04 82/07/19	50-409 50-409 50-416 50-328 50-133	R E B R
8208120016 8208120020 8208120022 8208120034 8208120038	8208120015 8208120019 8208120021 8208120032 8208120037	82/08/04 82/08/02 92/08/04 82/08/05 82/07/14	50-324 50-389 50-325 40-8584 50-219	R R	6208120322 8208120324 6208120374 8208120389 8208120389	9208120317 8208120351 8208120373 8208120378 8208120384	82/08/10 82/08/04 82/07/30 82/08/03 92/06/30	50-255 50-289 WASTE MO CONTRACT 50-416	
8208120049 8208120054 8208120050 8208120073 9208120076	8208120040 8208120047 8208120088 8208120069 820812007R	82/06/27 82/07/29 82/08/04 82/08/06 82/07/06	50-298 50-307 50-293 50-352 50-275	R Q Q R	8208130015 8208130016 8208130025 8208130025 8208130042	8208 20384 8208 30014 8208 30018 8208 30020 8208 30037	82/06/30 82/08/09 82/08/05 82/08/05 82/08/06	50-416 50-261 50-295 50-317 50-250	P P B
8208120082 8208120086 8208120087 8208120071 8208120078	8208120078 8208120085 8208120080 8208120090 8208120004	82/07/30 82/07/14 82/08/04 82/07/12 82/07/20	50-325 50-313 TOPREP 50-245 50-79	B R R	8208130043 8208130047 8208130046 8208130052 8208130052	8208 3004 8208 3004 8208 3004 8208 3005 2 8208 3004	82/07/29 82/07/29 82/08/04 92/07/08 82/08/10	50-276 50-276 50-387 50-237 50-346	P = B = P
8208120077 8208120104 8208120111 8208120112 8208120114	8208120004 8208120100 8208120108 8208120110 8208120109	62/07/20 62/07/27 62/06/07 62/06/03 62/06/03	50-79 50-244 50-266 50-280 50-366	H G P B	8208130063 8208130067 8208130073 8208130073 8208130073	8208130055 8208130041 8208130066 8208130069 8208130064	82/07/07 82/07/29 82/07/30 82/08/05 82/08/02	50-237 50-278 50-334 50-275 50-334	84848
8208120116 8208120118 8208120124 8208120125 8208120132	9209120110 9209120113 9209120122 9209122122 9209120122	82/08/03 82/08/09 82/08/04 82/07/15 82/07/09	50-280 50-352 50-327 50-341 50-309	8 8 8 R	8208130077 8208130079 8208130083 8208130084 8208130084	8208 130072 8208 130072 8208 130072 8208 130078 8208 130082	99/07/30 82/07/30 82/07/30 82/08/05 82/08/10	50-295 50-295 50-295 50-346 50-263	P P B R
8208120133 8208120134 8208120140 8208120143 8208120146	8208120131 8208120129 8208120136 8208120141 8208120142	82/08/10 82/08/09 82/07/29 82/07/14 82/08/04	50-528 50-321 50-387 50-293 50-324	Q R B	8208130088 8208130078 8208130100 8208130104 8208130104	8208130093	92/08/11 82/08/06 82/07/29 82/08/06 82/07/29	50-362 50-305 50-317 50-305 50-317	A B P B P

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGOR	Υ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUB JECT CATEGOR	
8208130104 8208130117 8208130118 8208130121 8208130132	8208130103 8208130113 8208130116 8208130095 8208130128	82/08/06 82/07/28 82/08/06 82/07/29 82/07/27	50-275 50-272 50-255 50-317 50-266	4 4 8	8208160099 8208160102 8208160105 820816010 8208160111	82081601096 8208160100 8208160106 8208160106	82/08/11 82/07/22 82/07/22 82/08/11 82/07/27	50-344 50-142 50-142 50-261 50-167	R Q Q
8208130135 8208130144 8208130151 8208130157 8208130161	8208130128 8208130140 8208130148 8208130154 8208130158	82/07/27 62/08/05 62/08/04 62/06/03 62/07/12	50-246 50-331 50-346 50-366 27-39	P 8 8	0208160115 0208360120 18160180 02081601122 0208160123	8208160108 8208160118 8208160119 8208160109 8208160118	82/07/27 82/07/29 82/07/27 82/08/10 82/07/29	50-187 50-312 50-409 50-255 50-312	0 0 0 0
6209130172 8208130180 8208130177 8208130202 8208130216	8208130166 8208130176 8208130196 8208130198 8208130212	82/08/05 82/08/06 82/08/10 82/08/10 82/08/09	50-295 50-364 50-267 50-282 50-445	P R R	\$208160125 \$208160126 \$208160127 \$208160129 \$208160131	8208160119 8208160124 8208160124 8208160128 8208160130	82/07/27 82/08/02 82/08/02 82/07/27 82/07/23	50~409 50~397 50~397 50~275 50~808	0 0 0 0
8208130218 8208130219 8208130221 8208130227 8208130231	8208130210 8208130214 8208130217 8208130222 8208130225	82/07/14 82/08/04 82/08/04 82/08/02 82/08/02	50-254 50-311 50-352 50-245 50-304	B & Q B &	8208160134 8208160140 8208160143 8208160148 8208160151	8208140133 8208140138 8208140141 8208140145 8208140147	82/08/04 82/08/10 82/08/11 82/08/03 82/07/23	50-324 50-373 50-309 50-318 50-338	0000
8208130236 8208130239 8208130243 8208130245 8208130246	6206130227 6206130233 6206130235 6206130241 6206130240	82/08/09 82/08/05 82/08/05 82/08/04 82/08/02	40-84 50-331 50-305 50-334 50-254	8 8 8	8208140153 8208140141 8208140148 8208140169 8208140171	8208160149 8208160155 8208160164 8208160163 8208160167	82/08/05 82/07/16 82/08/09 82/07/22 82/07/26	50-361 50-518 50-363 50-269 50-369	0 0 6
8208130253 8208130258 8208130259 8208130261 8208130262	8208130247 8208130255 8208130254 8208130240	62/07/28 62/08/03 62/08/03 82/08/09 62/08/09	50-272 50-219 50-334 50-323 50-295	8 8 8 A	B208140176 B208140177 B208140186 B208140175 B208140175	8208140173 8208140174 8208140180 8208140189 8208140189	82/08/05 82/08/02 82/07/26 82/07/29 82/07/22	50-298 50-219 50-241 60-979 50-335	8 8 0
8208130272 8208130273 8208130274 8208130274 8208130279	8208130247 8208130271 8208130271 8208130275 8208130278	62/08/03 82/08/09 82/08/09 82/08/03 82/08/03	50-237 50-255 50-255 50-318 50-155	6 R R 8	8208160200 8208160202 8208160208 8208160210 8208160210	8208160189 8208160194 8208160203 8208160204 8208160209	62/07/29 82/07/26 62/07/22 82/08/09 82/07/28	GA999 50-269 50-460 50-438 50-395	0 G G
8208130282 8208130286 8208130271 8208130277 8208130307	8208 130281 8208 130284 8208 130289 8208 130294 8208 130304	82/08/05 82/08/06 82/08/06 82/07/19 82/08/11	50-346 50-325 50-537 50-83 50-373	8 8 9 9	8208160216 8208160218 8208160224 8208160227 8208160227	8208160204 8208160204 8208160204 8208160217 8208160220	82/08/09 82/08/09 82/08/09 82/07/29 82/07/16	50-438 50-438 50-436 GA999 50-335	0 0 0
8208130311 8208130313 8208130317 8208130323 8208130324	8208 130304 8208 130304 8208 130314 8208 130321 8208 130322	82/08/11 82/08/11 82/08/06 82/07/28 82/08/05	50-373 50-373 50-325 50-329 50-249	P B G S	82081 60236 82081 60242 82081 60244 82081 60249 82081 60262	8208160228 8208160232 8208160235 8208160243 8208160256	82/07/21 82/07/19 82/07/23 82/08/12 82/07/23	50-416 50-400 50-370 50-395 50-369	0 0 P
8208130325 8208130337 8208130351 8208130421 8208130436	8208130320 8208130334 8208130347 8208130419 8208130430	82/07/28 82/07/28 82/07/12 82/07/28 82/08/04	50-373 50-346 40-8923 71-5149 50-334	a a	8208160263 8208160266 8208160270 8208160275 8208160276	8208 1 60257 8208 1 60259 8208 1 60264 8208 1 60268 8208 1 60265	82/07/19 82/08/03 82/08/05 82/08/06 82/08/11	50-321 50-508 50-370 50-280 50-482	0 0 0 11 E
8208130448 8208160002 8208160003 8208160005 8208160007	8208130444 8208160001 8208160004 8208160006	82/08/02 82/07/28 82/07/28 82/07/30 82/08/06	50-259 50-537 50-537 50-247 50-315	P Q Q S B	9208160277 9208160279 9208160280 9208160280 9208160282	6208160264 6206160273 6208160264 6208160271 6208160268	82/08/05 82/07/22 82/08/05 82/07/23 82/08/06	50-370 50-528 50-370 50-438 50-280	Q Q Q Q Q
8208160010 8208160021 8208160022 8208160022	8208160009 8208160017 8208160020 8208160019 8208160025	82/07/30 82/07/30 82/08/11 82/07/30 82/08/06	50-286 50-317 50-348 70-356 50-267	G R R	92081 60297 82081 60290 82081 60298 82081 60299 82081 60299	8208 60264 8208 60281 8208 60281 8208 60275 8208 60287	82/08/03 82/08/02 82/08/02 82/07/28 82/08/10	50-370 50-413 50-413 9499 50-416	@ @ @
8208160030 8208160035 8208160037 8208160037	8208160028 8208160031 8208160034 8208160032 8208160032	82/07/30 82/07/30 82/08/02 81/04/17 81/04/17	50-333 50-333 50-219 50-220 50-220	8 8 9 0	8208160303 8208160304 8208160311 8208160316 8208160316	8208160296 8208160295 8208160294 8208160309 8208160310	82/08/09 82/07/28 82/07/28 82/07/22 82/07/30	50-251 GA999 50-259 50-275 50-302	a a a
8208160042 8208160043 8208160045 8208160049 8208160051	8208140032 8208140041 8208160032 8208160048 8208160048	81/04/17 82/08/10 81/04/17 82/08/10 82/08/10	50-220 50-266 50-220 50-272 50-272	R G R	8208160319 8208160324 8208160325 8208160327 8208160333	8208160310 8208160318 8208160310 8208160310	92/08/11 92/07/30 92/07/22 92/07/30 92/07/30	50-302 50-302 50-302 50-302	9 9 9
8208160053 8208160055 8208160056 8208160063 8208160067	8208160048 8208160048 8208160048 8208160017 8208160064	82/08/10 82/08/10 82/08/10 82/07/30 82/08/11	50-272 50-272 50-272 50-317 50-329	R R G E	8208160335 8208160336 8208160338 8208160341 8208160342	8208140308 8208140334 8208140330 8208140308	82/08/05 82/08/02 82/08/05 82/08/05	50-329 50-399 50-400 50-413 50-329	A Q Q A
8208160082 8208160087 8208160089 8208160093 8208160094	8208160079 8208160083 8208160085 8208160094 8208160091	62/07/29 82/08/10 82/08/10 82/08/09 82/08/10	50-313 50-293 50-272 50-302 50-321	S R R	8208160343 8208160346 8208160349 8208160349 8208160351	8208160334 8208160337 8208160334 8208160281 8208160345	82/08/02 82/08/09 82/08/02 82/08/02 82/08/06	50~389 50~390 50~389 50~413 50~315	0 0 0 8

	N NUMBER				ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	188UED DATE	BUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE	BUB JECT CATEODA	
8208160352 8208160357 8208160358 8208160363 8208160365	8208160337 8208160334 8208160344 8208160344 8208160354	82/08/09 82/08/02 82/07/29 82/07/29 82/08/03	50~390 50~389 50~241 50~251 50~250	0 0 0	8208160532 8208160534 8208160535 8208170003 8208170018	8208160511 8208160511 8208160511 8208170001 8208170014	82/08/04 82/08/04 82/08/04 82/08/12 82/07/28	50-424 50-424 50-424 50-155 71-9086	0 0 0
8208140347 8208140370 8208140371 8208140372 8208140375	6208160344 6208160362 6208160366 6208160357 6208160364	82/07/29 82/07/20 82/07/19 82/07/29 82/07/27	50-241 50-335 50-400 0A999 50-269	G G G	8208170023 6208170025 8208170035 8208170038 8208170032	8208170014 8208170024 8208170033 8208170033	82/07/28 82/08/02 82/07/27 82/07/27 82/07/27	71-9086 50-389 71-9151 71-9151 71-9151	н
8208160375 8208160375 8208160376 8208160377 8208160381	8208160364 8208160364 8208160354 8208160344 8208160374	82/07/27 82/07/27 82/08/03 82/07/29 82/08/02	50-269 50-269 50-250 50-261 50-254	0 0 0 R	9208170053 8208170059 8208170059 8208170070 8208170077	8208170033 8208170056 8208170066 8208170067 8208170073	82/07/27 82/07/23 82/08/11 82/08/10 82/08/02	71-7151 50-311 50-301 50-482 70-184	P B
8208160382 8208160383 8208160384 8208160386 8208160387	9209 140354 9209 140378 9209 140328 9209 140354 9208 140380	82/08/03 82/07/22 82/07/22 82/08/03 82/07/19	50-250 50-389 50-413 50-250 50-370	0 0 0	8209170091 8208170089 8208170090 8208170091 8208170100	8208170078 8208170085 8208170087 8208170087 8208120218	82/08/10 82/08/10 82/08/11 82/08/13 82/07/22	50-305 50-249 50-314 50-249 50-409	8 P P R
8208160388 8208160391 8208160392 8208160394 8208160396	8208160379 8208160385 8208160379 8208160354 8208160326	82/08/02 82/07/28 82/08/02 82/08/03 82/07/22	50-369 0A999 50-369 50-250 50-369	0	8209170103 8209170104 8209170107 8209170119 8209170119	8208170093 8208170098 8208170093 8208120218 8208170113	82/08/02 82/08/02 82/08/02 82/07/22 82/08/03	50-334 50-317 50-334 50-409 50-483	4 4 6
8208160397 8208160398 8208160399 8208160401 8208160404	8208140379 8208140389 8208140390 8208140379 8208140385	82/08/02 82/07/20 82/08/10 82/08/02 82/07/28	50-367 50-460 50-267 50-369 GA979	9 9 9	8208170119 8208170121 8208170125 8208170131 8208170141	8208120218 9208120218 8208120218 8208120218 8208170140	82/07/22 82/07/22 82/07/22 82/07/22 82/06/22	50-409 50-409 50-409 50-409 50-293	P P P
8208160406 8208160408 8208160413 8208160416 8208160418	8208160323 8208160395 8208160403 8208160317 8208160412	82/07/27 82/07/24 82/07/29 82/07/28 82/08/03	50-327 50-259 GA999 50-250 50-369	() () () ()	8208170146 8208170155 8208170155 8208170172 8208170173	8208170143 8208170150 8208170158 8208170148 8208170144	82/08/13 82/08/13 82/08/12 82/08/16 82/08/09	50-204 50-347 50-213 50-528 50-244	PRFKP
8208160419 8208160422 8208160431 8208160435 8208160437	8208160411 8208160415 8208160425 8208160425 8208160428	82/07/27 82/07/27 82/08/12 82/08/12 82/07/19	50-461 50-362 50-312 50-312 50-241	0 P P	6208170180 8208170181 8208170184 6208170184 9208170188	8208170174 8208170164 8208170177 8208170163 8208170164	82/08/10 82/08/09 82/08/12 82/08/11 82/08/09	50-438 50-244 GA999 50-373 50-244	A P P
8208160438 8208160441 8208160443 8208160447 8208160449	8208160427 8208160427 8208160425 8208160436 8208160429	82/08/02 82/07/28 82/08/12 82/08/09 82/07/28	50-254 40-8064 50-312 50-327 40-8064	8 P Q	8208170196 8208170206 8208170207 8208170210 8208170213	8208170194 8208170164 8208170202 8208170202 8208170202	82/08/13 82/08/09 82/08/12 82/08/12 82/08/12	50-271 50-244 0A999 0A999	P P
8208160451 8208160455 8208160456 8208160458 8208160459	8208160445 8208160444 8208160444 8208160445 8208160453	82/07/30 82/08/09 82/08/11 82/07/30 82/07/26	50-320 50-220 50-247 50-320 50-329	0 R 0 0	6206170216 6208170220 6206170226 8208170226 6208170228	8208170214 8208170214 8208170215 8208170223 8208170225	62/08/12 92/08/12 82/08/13 82/08/10 82/08/11	50-244 50-244 50-400 50-373 50-348	P P Q P
8208160462 8208160464 8208160469 8208160470 8208160475	8208140450 8208140436 8208140454 8208140465 8208140466	82/08/06 82/08/09 82/08/06 82/07/23 82/07/30	50-346 50-327 50-321 50-298 50-275	9 9 9 9	8208170234 6208170241 8208170244 8208170245 8208170245	8208170227 9208170002 9208170239 8208170242 8208170246	82/06/11 82/07/27 82/07/06 82/08/01 82/08/13	27-39 40-8102 50-445 50-10 50-322	A R Q
8208160482 8208160483 8208160488 8208160489 8208160491	8208 1 60436 8208 1 60474 8208 1 60476 8208 1 60488 8208 1 60484	82/08/09 82/07/30 82/08/04 82/07/30 82/08/03	50-327 50-320 50-416 50-397 50-259	() () ()	8208170252 8208170255 8208170256 8208170257 8208170261	8208170248 8208170248 8208170251 8208170248 8208170259	82/08/13 82/08/13 82/08/11 82/08/13 82/08/10	50-397 50-387 50-206 50-387 50-155	4444
8208140492 8208160497 8208160498 8208160501 8208160502	B208160436 6208160487 6208160484 8208160436 8208160493	82/08/09 82/07/27 82/08/03 82/08/09 82/08/04	\$0-327 70-27 50-259 50-327 50-259	G G G	8208170242 8208170245 8208170297 8208170297 8208170293	8208170251 8208170251 8208170286 8208170290 8208170283	82/08/11 82/08/10 82/08/10 82/08/13 82/08/12	50~206 50~206 50~352 50~275 50~259	P P P R K
8209160503 8208160507 8208160509 8208160513 8208160515	8208160495 6208160484 6208160500 8208160505 8208160493	82/08/05 82/08/03 82/08/03 82/07/26 82/08/04	50-346 50-259 50-312 50-302 50-259	0 0 0	8208170302 8208170314 8208170326 8208170346 8208170348	8208170298 8208170250 8208170324 8208170343 8208170345	82/08/03 82/08/11 82/07/22 82/07/30 82/08/11	50-546 50-206 CONTRACT 50-329 50-206	Q R D
8208160516 8208160518 8208160519 8208160520 8208160521	8208160506 8208160510 8208160512 8208160493 8208160484	82/08/05 82/08/10 82/08/09 82/08/04 82/08/03	50-416 50-301 50-335 50-259 50-259	8 8	8209170350 8209170351 8209170357 8209170359 8208170364	9209170347 9208170345 9209170354 9208170354 9208170362	82/08/10 82/08/11 82/08/10 82/08/10 82/08/10	50-344 50-206 50-289 50-289 50-309	FPFFF
8208160524 8208160525 8208160526 8208160528 8208160530	8208160511 8208160523 8208160522 8208160473 8208160473	82/08/02 82/08/02 82/07/26 82/08/04 82/08/02	50-424 50-275 50-261 50-289 50-312	G G G G	8208170366 8208170367 8208170371 8208170374	8208170342 8208170348 8208170370 8208170373	82/08/10 81/09/30 81/01/16 81/12/15	50-309 HASTE HO HASTE HO HASTE HO	T

	ON NUMBER					ION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1980ED	SUBJEC	
8208170383 8208170420 8208180015 8208180016 8208180022	8208170381 8208170413 8208180004 8208180012	82/08/03 82/08/10 82/08/11	CONTRAC 50-336 50-255	T S P	8208170214 8208170215 8208170217 8208170217 8208170221	8208190213 9208190211 9208190213	82/08/02 82/08/06 82/08/13 82/08/06 82/08/13	90-313 50-458 50-313 50-313 50-341	Q Q Q A
8208180031 8208180040 8208180050 8208180051 8208180053	8208180033 8208180041 8208180043	82/08/06	50-320 50-322 50-317	8 9 9 9	8208190225 8208190233 8208190233 8208190241 8208190247	8208190216 8208190227 8208190231	82/08/04 82/08/04 82/08/12 82/08/04 82/08/13	50-313 50-311 50-289 50-458 50-285	0 5 0 0
8208180056 8208180057 8208180058 8208180059 8208180060	8208180048 8208180055 8208180041 8208180047 8208180054		REVIEW 50-313 50-322 50-382 50-380	GRP G F G S	8208190258 8208190242 8208190344 8208190346 8208190260	8208190255 8208190236 8208190249	82/08/06 82/08/06 82/08/13 82/08/06 82/08/05	QA999 QA999 50-285 QA999 50-312	Q
8208180045 8208180046 8208180074 8208180080 8208180081	8208180061 8208180055 8208180070 8208180070	82/08/13 82/07/27 82/07/28 82/08/06 82/07/28	50-369 50-313 50-285 50-272 50-285	A G B	8208190271 8208190272 8208190272 8208190277 8208190278	8208190236 8208190274	82/08/16 82/08/13 82/08/13 82/08/13	QA999 GA999 50-285 50-416 GA999	Q R
8208180084 8208180076 8208180078 8208180102 8208180117	9208180077 6206180088 6208180091 9208180099 6208180115	82/08/12 82/08/13 82/08/14 82/08/16	50-247 50-313 50-286 50-341 50-537	Q Q X T	8208190280 9208190284 9208190285 9208190287 9208190291	6206190255 6206190261 6206190262 8206190262 6206190261	82/08/06 82/08/06 82/07/14 82/07/14 82/08/06	0A999 0A999 0A999 0A999 0A999	
8208180122 8208180123 8208180125 8208180127 8208180127	8208180117 8208180118 8208180118 8208180118 8208180124	82/08/13 82/08/16 82/08/16 82/08/16 82/08/13	50-312 50-266 50-537 50-266 50-336	F Q T Q	8208170273 8208170274 8208170275 8208170278 8208170303	8208 170292 8208 170287 8208 170281 8208 170276 8208 170277	82/08/02 82/08/02 82/08/04 82/08/12 82/08/16	50~298 50~462 GA999 50~339 GA999	01 01 P
8208180130 8208180131 8208180133 8208180134 8208180131	8208180115 8208180119 8208180128 8208180118 8208180144	82/08/16 82/08/16 82/06/14 82/08/16 82/07/26	50-537 50-266 50-313 50-266 CONTRACT	T G G	8208170304 8208170308 8208170310 8208190310 8208170311	8208 190300 8208 190300 8208 190305 8208 190307 8208 190300	82/08/04 82/08/04 82/08/12 82/07/27 82/08/04	50-413 50-413 50-219 TOPREP 50-413	A Q A
8208180261 8208180267 8208180267 8208180271 8208190004	8208180257 8208180262 8208180264 8208180266 8208190001	82/08/15 82/08/02 82/07/14 82/07/28 82/07/26	CONTRACT 50-33 CONTRACT 50-237 50-309	Р Р О	8208190313 8208190314 8208190315 8208190316 8208190319	8208190312 8208190300 8208190300 8208190300 8208190300	82/08/16 82/08/06 82/08/06 82/08/06 82/08/06	50~324 50~413 50~413 50~413 50~413	P A A A
8208190008 8208190011 8208190018 8208190028 8208190040	8208190006 8208190003 8208190014 8208190021 8208190027	82/07/28 82/08/04 82/08/14 82/07/29 82/07/30	50-263 50-311 50-454 CONTRACT 40-8724	P 8 F	8208190321 8208190326 8208190328 8208190337 8208190337	8208190300 8208190300 8208190300 8208190300	82/08/06 82/08/06 82/08/06 82/08/06	50-413 50-413 50-413 50-413 50-413	Λ Α Α Α
8208190053 8208190057 8208190058 8208190065 8208190077	8206200094 8208190055 8208190055 8208190055 8208190074	62/07/21 62/06/23 62/06/23 62/06/23 62/08/13	COMMISSI 50-358 50-358 50-358 50-299	ON G G G R	8208190340 8208190346 8208190358 8208190358 8208190363	6208 1 70300 6208 1 70300 6208 1 70300 6208 1 70300	82/08/06 82/08/06 82/08/06 82/08/06	50-413 50-413 50-413 50-413 50-413	A A A A
8208190080 8208190084 8208190092 8208190093 8208190099	8208190075 8208190081 8208190087 8208190089 8208190095	82/08/17 82/08/05 82/07/23 82/08/10 82/08/05	50-443 50-263 50-315 50-285 CONTRACT	A F P R	8208190367 8208190372 8208190375 8208190377 8208190379	8208190300 8208190300 8208190300 8208190087 8208190300	82/08/06 82/08/06 82/08/06 82/07/23 82/08/04	50-413 50-413 50-413 50-315 50-413	A A P A
8208190102 8208190103 8208190107 8208190109 8208190118	8208170078 8208170100 8208170100 8208170106 8208170113	82/08/13 82/07/14 82/07/14 82/08/13 82/08/04	50-277 0A979 0A999 50-331 50-311	R R S	8208190381 8208190412 8208190413 8208190422 8208190422	8208 190087 8208 190405 8208 190404 8208 190405 8208 190406	82/07/23 82/08/10 82/08/09 82/08/10 82/08/09	50-315 50-267 50-338 50-269 50-338	P # F F F
8208190122 8208190123 8208190133 8208190142 8208190144	8208190120 8208190127 8208190127 8208190139 8208190138	82/08/14 82/08/17 82/08/04 82/08/16 82/08/04	50-247 50-311 50-275	P 0 9 0 8	82081 90433 82081 90434 82081 90433 8208200008 8208200011	8208 1 90430 8208 1 90430 8208 1 90430 8208 200002 8208 200004	82/08/10 82/08/10 82/08/10 82/08/10 82/08/13	50-155 50-155 50-155 50-327 50-416	F F 6 8
8208190146 8208190147 8208190149 8208190156 8208190159	8208190110 8208190145 8208190143 8208190150 8208190116	82/08/15 62/08/17 62/08/04 62/08/16 62/08/13	50-206 50-311 50-313	e P S F O	8208200019 820820023 820820023 820820028 820820029 820820034	8208200022 8208200018 8208200016 8208200018	82/08/13 82/08/13 82/08/11 82/08/13 82/08/06	50-325 50-255 50-416 50-361 50-369	9 6 8 B
8208190166 8208190169 8208190172 8208190194 8208190204	8208190165 8208190167 8208190170 8208190189 8208190200	82/08/04 82/08/13 82/08/16 82/08/03 82/08/13	50-334 50-265 50-272	S Q F P	8208200036 8208200041 8208200034 8208200034 8208200063	8208200033 8208200030 8208200045 8208200047 8208200053	82/08/16 82/08/12 82/08/12 82/08/05 82/08/09	50-320 50-276 50-321 50-498 50-237	P 8 8 6 8
8208190205 8208190207 8208190208 8208190209 8208190210	8208190202 8208190203 8208190205 8208190200	82/08/02 82/08/02 82/08/17 82/08/02 82/08/13	QA999 QA999 50-206 QA999 50-269	3	\$208200064 \$208200067 \$208200068 \$208200073 \$208200076	8208200055 8208200058 8208200058 8208200062	82/07/19 82/08/13 82/08/13 82/08/10 82/08/10	GA797 50-416 50-324 50-259 50-409	8 8

PRINCIPAL	DATE			NUMBER			
ENCLOSURE DOCUMENT	IBSUED	SUBJECT		PRINCIPAL	DATE	SUB JECT	
8208200080 8208200072 8208200081 8208200070 8208200083 8208200066 8208200089 8208200077 8208200099 8208200091	82/08/12 82/08/14 82/08/10 82/08/13 82/08/11	50-245 40-86 50-409 50-325 50-336	ENCLOSURE 5208230036 6208230040 8208230041 6208230043 6208230045	8208230034 8208230038 8208230039 8208230039 8208230038	188VED 82/08/05 92/08/05 82/08/06 82/08/05 82/08/11	50-341 50-273 50-20 50-29 50-29	Y
8208200100 8208200095 8208200101 8208200086 8208200109 820820103 8208200112 8208200104 8208200114 8208200107	82/08/11 82/08/09 82/08/10 82/08/09 82/08/16	50~302 80~337 50~278 50~220 50~346	8208230046 8208230047 8208230057 8208230065 8208230066	8208230038 8208230042 8208230054 8208230060 8208230062	82/08/05 82/08/12 82/08/18 82/08/10 82/08/13	50-293 50-206 50-315 50-373 50-316	P Q K S
8208200123 8208200110 8208200124 8208200117 8208200125 8208200115 8208200127 8208200118 8208200120 8208200122	82/08/13 82/08/11 82/08/12 82/08/13 82/08/16	50-241 50-247 50-250 50-240 50-312	8208230067 8208230068 8208230069 8208230073 8208230074	B208 230063 B208 230062 B208 230063 B208 230071 B208 230072	82/08/18 82/08/13 82/08/18 82/08/17 82/08/12	50-454 50-316 50-454 50-275 50-29	9 6 6 6 8
9208200141 8208200126 9208200146 8208200128 9208200148 8208200144 8208200147 8208200135 9208200150 8208200144	82/08/11 82/08/12 82/08/12 82/08/10 82/08/12	50-267 50-251 50-275 50-285 50-275	8208230085 8208230087 8208230092 8208230098 8208230100	8208 230074 B208 230080 B208 230088 B208 230070 B208 230088	82/08/12 82/08/13 82/08/18 82/08/02	50-206 50-318 50-305 50-454 50-305	0 8 0 0
8208200153 8208200145 8208200153 8208200142 8208200154 8208200144 8208200158 9208200144 8208200160 8208200136	82/08/12 82/08/13 82/08/12 82/08/12 82/08/04	50-361 50-281 50-275 50-275 50-312	8208230108 8208230112 8208230113 8208230117 8208230122	8208230103 8208230103 8208230107 8208230107 8208230107	82/08/17 82/08/17 82/08/13 82/08/13 82/08/13	50-333 50-333 50-237 50-237 50-237	G F F
8208200143 8208200143 8208200145 8208200142 8208200147 8208200142 8208200170 8208200157 9208200172 8208200156	82/08/19 82/08/18 82/08/13 82/07/28 82/08/13	50-322 50-341 50-281 50-313 50-302	8208230124 6208230130 8208230133 8208230153 8208230158	8208230117 8208230107 8208230125 8208230142 8208230148	92/08/12 82/08/13 82/08/09 82/08/13 82/08/13	XPDRTLIC 50-237 50-322 50-305 50-483	F G G
8208200173 8208200164 8208200175 8208200165 8208200176 9208200164 8208200183 8208200164 8208200185 8208200177	82/08/11 82/08/13 82/08/10 82/08/11 82/07/29	50-348 50-335 50-298 50-346 50-458	8208230161 8208230170 8208230172 8208230174 8208230178	8208230142 8208230165 8208230142 8208230164 8208230175	82/08/13 82/08/19 82/08/13 82/08/05 82/08/12	50-305 50-271 50-305 50-263 50-317	8 9 8 8
B208200170 B208200164 B208200173 B208200188 B208200179 B208200188 B208200204 B208200182 B208200210 B208200202	82/08/18 82/08/18 82/08/18 82/08/13	50-348 50-409 50-409 50-341 50-255	8208230184 6208230174 8208230177 8208230204 8208230208	8208230182 8208230184 8208230187 8208230176 8208230200	82/08/03 82/08/13 82/08/03 82/08/18 82/08/05	70-697 50-309 50-317 50-275 70-273	8 G P
8208200211 8208200203 8208200213 8208200182 8208200216 8208200207 8208200221 8208200206 8208200223 8208200206	82/08/07 82/08/13 82/08/12 82/08/13 82/08/06	50-261 50-361 50-327 50-361 50-409	9208230210 8208230213 8208230214 8208230219 8208230222	B208 230206 B208 230200 B208 230200 B208 230202	82/08/11 82/08/06 82/08/06 82/08/06 82/08/06	50-309 70-273 40-501 70-273 40-501	8
8208200224 8208200212 8208200228 8208200219 8208200229 8208200219 8208200230 8208200182 8208200233 8208200227	82/08/03 82/08/02 82/08/13 82/08/13 82/08/09	90-312 50-315 50-302 50-341 50-338	8208230223 8208230238 8208230242 8208230256 8208230259	8208230212 8208230232 8208230235 8208230235 8208230252	82/08/13 82/08/18 82/08/18 82/08/13 82/08/10	50-315 50-247 50-247 50-315 50-237	8 P 6 8
8208200236 8208200182 8208200242 8208200231 8208200243 8208200234 8208200244 8208200235 8208200245 8208200239	82/08/13 82/08/06 82/08/18 82/08/09 82/08/17	50-361 50-206 50-341 50-373 50-387	8208230266 8208230267 8208230271 8208230279 8208230281	8208230262 8208230264 8208230270 8208230273 8208230277	82/08/16 82/08/20 82/08/23 82/07/27 82/08/17	50-255 50-537 50-356 50-249 50-293	P R B
8208200248 8208200182 8208200253 8208200234 820820025 8208200244 8208200288 8208200182 8208200257 8208200239	82/08/13 82/08/17 82/08/13 82/08/13 82/08/17	50-361 50-387 60-322 50-361 50-387	8208230284 6208230285 6208230287 6208230294 6208230297	8208230282 8208230282 8208230282 8208230270 8208230272	82/08/17 82/08/16 82/08/16 82/08/19 82/08/06	50-280 50-247 50-247 70-2625 50-249	р 0
8208200261 8208200247 8208200263 8208200252 8208200264 8208200254 8208200266 8208200239 8208200268 8208200182	82/08/10 82/08/06 82/08/13 82/08/17 82/08/13	50-369 50-254 50-324 50-387 50-361	8208230302 8208230304 8208230310 8208230313 8208230318	8208230180 8208230277 8208230307 8208230307 8208230317	82/08/03 82/08/03 82/08/03 82/08/03	50-387 50-220 50-331 50-331 50-410	8999
8208200249 8208200251 8208200272 8208200247 8208200274 8208200239 8208200282 8208200277 8208200288 8208200285	82/08/12 82/08/13 82/08/17 82/07/29 82/08/13	50-361 50-275 50-387 50-313 50-324	6208230317 8208230323 8208230327 8208230335 8208230342	8208230317 8208230322 8208230326 8208230328 8208230333	82/08/05 82/08/19 82/08/18 82/08/18 82/08/03	50-410 50-317 70-27 50-254 50-317	Q Q F Q
8208200289 8208200284 8208200290 8208200279 8208200296 8208200292 8208200297 8208200294 8208200298 8208200294	82/08/12 82/08/13 82/07/30 82/08/13 82/08/13	50-344 50-344 50-262 50-262	8208230347 8208230350 8208230359 8208230363 8208230373	9208230341 9208230344 9208230349 9208230360 9208230371	82/08/09 82/08/18 82/08/16 82/08/09 82/08/17	50-247 70-936 50-237 50-333 50-317	B Q B R
8208200299 8208200300 8208200294 8208230024 8208230021 8208230030 8208230025 8208230039 8208230029	82/08/12 82/08/13 82/08/06 82/08/10 82/08/06	50-250 50-282 CONTRACT 50-237 50-249	8208230375 8208230378 8208230384 8208230378 8208230401	8208230366 8208230377 8208230380 8208230393 8208230390	82/09/16 82/08/12 82/08/09 B2/08/16 B2/08/06	50-327 50-454 50-387 TOPREP 50-249	9 0 8

ACCESSION N					ACCESSION	NUMBER			
ENCLOSURE P	RINCIPAL DOCUMENT	185UED	CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT	
8208230427 8 8208230428 8 8208230430 8	2208230418 2208230418 2208230425 3208230418 3208230418	82/07/29 82/07/29 82/07/30 82/07/29 82/05/14	50-320 FOIA 50-341 FOIA 40-8102	P A	B20B240412 B20B240416 B20B240419 B20B240425 B20B240427	8208240383 8208240413 8208240413 8208240413 8208240423	81/07/07 82/08/09 82/08/09 82/08/09 82/08/18	50-528 50-329 50-329 50-329 50-395	0 0 0 0
8208230451 8 8208230458 8 8208230462 8	1208230437 1208230446 1208230456 1208230460 1208230444	82/05/26 82/05/03 81/03/27 82/08/12 82/07/19	40-8102 CONTRACT 50-241 CONTRACT 50-277	5	8208240436 8208240438 8208240446 8208240457 8208240491	8208240430 8208240437 8208240442 8208240454 8208240468	82/08/13 82/08/20 82/08/20 81/03/26	50-440 50-298 50-155 50-289 50-317	A P D 8
8208230473 6 8208230494 8 8208230496 8 8208240042 6	3208230444 3208230444 3208230493 3208230493 3208230493	82/07/19 82/07/19 82/08/06 82/08/06 82/07/15	50-277 50-277 XPORTLIC XPORTLIC 71-9166		8208240494 8208250006 8208250009 8208250011 8208250013	8208240493 8208250001 8208250001 8208250001 8208250001	81/03/27 82/07/26 82/07/26 82/07/26 82/07/26	50-317 FOIA FOIA FOIA FOIA	Б
8208240050 8 8208240054 8 8208240056 8 8208240065 8	3203240040 3208240040 3208240049 3208240053 3208240055	82/08/06 82/08/06 82/08/10 82/08/17 82/08/04	50-254 50-254 CONTRACT 50-267 50-338	5 P	8208250017 8208250021 8208250022 8208250027 8208250032	8208250001 8208250001 8208250001 8208250001	82/07/26 82/07/26 82/07/20 82/07/26 82/07/26	FOIA FOIA CONTRACT FOIA FOIA	T
8208240073 8 8208240076 8 8208240077 8 8208240094 8	3208240055 3208240055 3208230432 3208240074 3208240088	82/08/04 82/08/04 82/05/14 82/08/17 82/08/04	50~338 50~338 40~8102 50~267 XPORTLIC	P P S S S S S S S S S S S S S S S S S S	8208250035 8208250038 8208250050 8208250058 8208250044	8208250001 8208250005 8208250025 8208250025	82/07/26 62/07/26 82/08/11 82/04/27 82/06/17	FOIA FOIA 50~309 FOIA 40~84	F
8208240137 8 8208240147 8 8208240149 8 8208240174 8	0208240128 0208240135 0208240143 0208240147 0208240147	82/07/30 82/08/13 82/07/29 82/08/19 82/08/16	71~6698 50~331 50~16 50~334 50~142	8 R P Q	6209250047 8208250070 8208250072 8208250073 8208250077	8208250061 8208250063 8208250061 8208250061 8208250061	82/06/17 82/08/03 82/06/17 82/06/17 82/06/17	40~86 CONTRACT 40~86 40~86 40~86	г
8208240184 8 8208240187 8 8208240189 8	0208240174 0208240176 0208240185 0208240186 0208240190	82/08/09 82/08/09 82/08/16 82/08/10 82/08/17	50-298 50-298 50-445 50-373 50-382	ପ ପ ପ	8208250080 8208250081 8208250082 8208250084 8208250085	8208250061 8208250061 8208250061 8208250061 8208250061	82/06/17 82/06/17 82/06/17 82/06/17 82/06/17	40-86 FDIA 40-86 40-86 FDIA	
8208240203 B 8208240206 B 8208240208 B	208240195 208240197 208240200 208240205 208240211	82/08/20 82/08/18 82/08/17 82/08/17 82/08/16	50-387 50-206 50-373 50-382 0A999	о в о	8208250086 8206250087 8208250089 8208250091 8208250093	8208250041 8208250041 8208250041 8208250041	82/06/17 82/06/17 82/06/17 82/06/17 82/06/17	40-86 FOIA 40-86 40-86 40-86	
8208240227 8 8208240227 8 8208240237 8	208240216 208240222 208240224 208240234 208240234	82/08/19 82/08/20 82/08/19 82/08/11 82/08/11	50-298 50-352 50-373 50-287 90-287	Q A P P P	8208250094 8208250075 8208250098 8208250099 8208250101	8208250061 8208250070 8208250061 8208250061	82/05/17 82/07/30 82/06/17 82/06/17 82/08/03	40-86 71-370 FOIA FOIA CONTRACT	r
8208240257 8 8208240257 8 8208240264 8	208240248 208240250 208240257 208240257 208240257	92/08/14 62/08/18 82/08/11 62/08/11 62/08/14	50-247 50-305 50-206 50-206 50-147	R P P P C	8208250102 8208250103 8208250105 8208250104 8208250110	1400828084 1400828084 1400828084 1400828084 1400828084	82/06/17 82/06/17 82/06/17 82/06/17 82/06/17	40-86 F01A 40-86 40-86 40-86	
8208240287 8 8208240287 8	208240270 1208240276 1208240277 1208240284 1208240284	62/07/26 62/08/19 82/08/16 82/08/03 82/08/04	50-344 50-29 50-528 50-312 50-528	Q Q Q Q	8208250112 8208250114 8208250117 8208250118 8208250119	8208250061 8208250061 8208250061 8208250061	82/06/17 82/06/17 82/06/17 82/06/17 82/06/17	40-86 40-86 40-86 40-86 40-86	
8208240298 B 8208240300 B 8208240302 B	208240270 208240274 208240277 208240297 208240306	82/08/03 82/08/18 82/08/18 82/08/13	50-133 50-265 50-312 50-312 50-331	Q Q Q Q	8208250120 8208250121 8208250122 8208250123 8208250124	8208230061 8208230061 8208230061 8208230061	82/06/17 82/06/17 82/06/17 82/06/17 82/06/17	40-86 40-86 40-86 40-86	
9208240313 8: 9208240317 8: 9208240320 8:	208240308 208240312 208240314 208240297 208240297	82/08/14 82/08/18 82/08/13 82/08/18 82/08/16	50~329 50~334 50~331 50~312 50~312	A P B G G G G G G G G G G G G G G G G G G	8208250125 8208250126 8208250130 8208250133 8208250134	8208250061 8208250061 8208250061 8208250061	82/06/17 82/06/17 82/06/17 82/06/17 82/06/17	40-86 FOIA 40-86 FOIA 40-86	
8208240352 B 8208240352 B 8208240354 8	208240331 208240340 208240340 208240349 208240348	82/08/19 82/08/19 82/08/19 82/08/19 82/07/15	50-244 50-379 50-373 50-470 50-344	P P E O	8208250134 8208250139 8208250140 8208250142 8208250144	8208250061 8208250061 8208250061 8208250061 8208250143	82/06/17 82/06/17 82/06/17 82/06/17 82/08/12	40-84 40-86 40-86 40-86 50-333	P
8208240377 8: 8208240378 8: 8208240380 8:	208240365 208240374 208240373 208240369 208240369	82/08/16 82/08/19 82/08/18 82/08/13 82/08/20	50-266 50-155 50-445 50-298 50-358	Q 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	8208250145 8208250146 8208250151 8208250153 8208250154	8208250143 8208250061 8208250061 8208250061 8208250150	82/08/12 82/06/17 82/06/17 82/06/17 82/08/20	50-333 40-86 40-86 40-86 50-338	q q
8208240376 8: 8208240377 8: 8208240400 8:	208240388 208240383 208240395 208240371 208240407	82/08/20 81/07/07 82/08/12 82/08/17 82/08/17	50-309 50-528 50-311 TOPREP 27-48	Q Q В	8208230135 8208230158 8208230159 8208230162 8208230164	8208250061 8208250061 8208250061 8208250150 8208250061	82/06/17 82/06/17 82/06/17 82/08/20 82/06/17	40-84 40-84 40-86 50-338 FOLA	P

ACCE8810	N NUMBER				ACCEPTION	N. Annana			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJEC		WF-5911	N NUMBER 	DATE	CUR ICO	
8208250166	8208280091	82/04/17	CATEGO 40-86	H Y	ENCLOSURE	DOCUMENT	ISSUED	CATEGO	
8208250167 8208250171	8208250061	82/06/17 81/06/16	40-86 50-317	8	8208250371 8208250372	9209250061 9208250061	82/06/17 82/06/17	40-86 40-86	
8208250172 8208250174	8208250061 8208250061	82/06/17 82/06/17	FOIA 40-86		8208250373 8208250374	8208250061 8208250061	82/06/17 82/06/17	FOIA FOIA	
8208250177	B208250061	82/06/17	FOIA		8208250375	8208 250061	82/05/17	40-B6	
8208250182 8208250183	8208250061 8208250061	82/06/17 82/06/17	40-86		8208250377 8208250378	8208250041 8208250041	82/06/17 82/06/17	FOIA 40-86	
8208250187 8208250188	8208250061	82/06/17 82/06/17	40-86 40-86		8208250380 8208250381	B208250061 B208250061	82/06/17 82/06/17	FO1A 40-86	
8208250193	8208250061	82/06/17	40-86		8208250382	8208250379	85/08/23	50-368	P
0208250194 8208250199	8208250061 8208250061	82/06/17 82/06/17	FD1A 40-86		6209250383 9208250384	8208250374 8208250061	82/08/18 82/06/17	50~259 40-86	P
8208250200 8208250201	8208250061 8208250061	82/06/17 82/06/17	40-86 40-86		9209250385 8208250387	8208250041 8208250376	82/06/17 82/09/18	FOIA 50-259	Р
8208250204	8208250061	82/06/17	40-B6		8208250388	8208250061	82/06/17	FOIA	
820825020B 8208250220	8208250061 8208250213	85/09/17	40-86 50-522	D	6208250389 9208250391	8208250061 8208250376	82/06/17 82/08/18	40-86 50-259	P
8508520559 8508520555	8208250061	82/06/17	40-86 40-86	D	8208250392 8208250393	8208250061 8208250390	81/07/06	40-84 50-317	5
6208250531	B20B250061	82/06/17	40-B6		8208250394	8208250061	82/06/17	FOIA	-
0200250232 0200250234	0208250224 0208250061	82/08/23	50-155 40-86	G	8208250395 8208250396	8208250061 8208250061	82/06/17	FOIA FOIA	
8208250237 8208250238	8208250061 8208250224	82/06/17 82/08/23	40-84 50-155	G	8208250397 8208250402	8208250376	82/06/17 82/08/18	FOIA 50-259	Р
0208250242	8208250041	82/06/17	40-86	· ·	B20B250409	8208250376	85/08/18	\$0~259	P
8208250244 8208250249	8208250061 8208250061	82/06/17 82/06/17	40-86 40-86		8206250415 8208250421	8208250376 8208250376	82/08/18	30-259 30-259	P
8208250251 8208250254	8208250061 8208250061	82/06/17 82/06/17	40-86 FOIA		6208250426 6208250430	8208250376 8208250423	82/08/18	30-259 71-5748	P
8208250259	8208250061	82/04/17	40-86		8208250431	8208 250374	85/08/18	50-259	P
6208250261 8208250266	8208250061 8208250061	82/06/17 82/06/17	40-84 40-84		6209250437 9208250441	8208250376 8208250376	85/08/18	50-259 50-259	P P
8208250267 8208250273	8208250041 8208250041	82/06/17 82/06/17	40-86 40-86		8208250443 8208250446	8208250376 8208250376	85/08/18 85/08/18	50-259 50-259	P
8208250275	8208250041	82/06/17	40-86		B208250454	8208250451	85/08/09	50-373	0
8208250278 8208250283	B208250041 B208250041	82/06/17 82/06/17	40-86 40-86		8208250463 8208250468	8208250458 8208250458	85/08/15 85/08/15	70-1308 70-1308	
6206250265 6206250266	8208250041 8208250041	82/06/17 82/06/17	40-86 40-86		8208250508 8208250508	8208250500 8208250500	82/08/10 82/08/10	50-321 50-321	P
420B250291	B208250061	82/06/17	40-84		6208250511 CONDESSES	8208250500	92/08/10	50-321	Р
0200250275 0200250275	8208250061 8208250061	82/06/17 82/06/17	40-86 40-86		920925053k 920925054B	6208250526 6208250545	82/07/30 82/08/04	70-143 50-245	P
<i>9208250306</i> 8208250308	8208250041 8208250305	82/06/17	40-86 50-387	₽	8208250551 8208260007	8208250546 8208260004	82/06/10	50-317 50-438	G.
0200250310	0208250061	02/06/17	40-86		8208240020 8208240024	8208250559	82/08/05	50-438 50-10	G F
8208250313 8208250314	8208250061 8208250309	82/06/17 82/08/20	40-84 50-349	ρ	\$208260030 \$208260039	8508590055 8508590055	82/08/24 82/08/24	50-446 50-446	6
8208250315 8208250317	8208250061	92/06/17 92/06/17	40-86 40-86		8208240047 8208240053	8208250557 8208260045	82/08/12 82/08/04	50-10 XPORTLIC	F
8208250317	8208250061	92/06/17	FOIA		9209260059	8208260054	82/08/13	50-266	F
8208250321 8208250323	8208250041 8208250041	82/06/17 82/06/17	40-86 FDIA		5205240047 5206240049	8208260054 8208260061	82/08/13 82/08/04	50-246 XPORTLIC	F
8208250325 8208250326	8208250061 8208250322	82/06/17 82/08/20	40-86 50-352	0	9209250077 9209250085	8208260071 8208260081	82/08/04 82/08/09	CONTRACT	
8208250327	0208250061	92/04/17	40-86		8208260101	8208260076	82/08/11	50-313	F
8208250327 8208250330	8208250061 8208250061	82/06/17 82/06/17	40-86 40-86		8208260104 8208260107	8208260096 8208260102	82/08/11 82/08/13	50-313 50-416	F F
8208250332 8208250334	8208250061 8208250061	82/06/17 82/06/17	40-86 40-86		6208260113 8208260114	8208260102 8208260110	82/08/13 82/08/11	50-416 50-324	F
9208250337	8208280091	62/06/17	40-B6		8208260129	B20B260124	92/09/25	50-440	К
8208250338 8208250342	8208520091	82/06/17 82/06/17	40-86 FOIA		8208260131 8208240138	8208260126 8208260136	82/08/18 82/08/17	50-334 50-369	s P
8208250343 8208250344	8208250041 8208250041	82/06/17 82/06/17	40-86 40-86		8208260141 8208260153	8208240137 8208240148	82/08/12	50-311 50-272	8 8
6208250347	8208250061	82/05/17	40-84		8208260167	8209240159	82/08/19	48E-08	9
8208250348 8208250352	8208250041 8208250041	82/06/17 82/06/17	40-86 40-86		9208260170 9208260171	B20B260161 B20B260165	82/08/23	50-333 50-373	81 P
0208250354 8208250357	8208250041	82/06/17 82/06/17	FOIA FOIA		920526017B 8208260199	8208260169 8208260194	82/08/17 82/08/16	50-333 50-219	6 8
8209250356	6206250355	82/08/19	50-413	A	6306340503	8208240197	82/08/12	50-334	B
8208250359 8208250360	8208250041 8208250041	82/06/17 82/06/17	40-84 FOIA		8208590552 8208590519	8208 590518 8208 590508	62/08/20 62/09/16	50-333 50-317	8
8208250364 8208250365	8208250061 8208250061	82/06/17 82/06/17	40-86 40-86		8208260235 8208260226	8208260221 8208260227	85\08\50 85\08\53	50-387 50-317	Р 6
6208250366	8208250061 8208250061	92/06/17 B2/06/17	40-86		8208260234	8208260230	82/08/14 82/08/18	50-333 50-318	S
6206250367 6206250366 6206250367	8508520091 8508520091	82/06/17 82/06/17 82/06/17	FOIA 40-86 40-86		8208260244 8208260248 8208260250	8208260237 8208260243 8208260184	82/08/16 82/08/03	50-333 CONTRACT	8
8208250367	8208250041	82/06/17	40~86		8208260250 8208260254	8208260184 8208260246	82/08/18		В

ACCESSIO.				ACCESSIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBBUED	BUB JECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8208240241 8208240246 8208240273 8208240283 8208240284	8208260255 8208260255 8208260255 8208260266 8208260276	82/08/12 82/08/19 82/08/19 82/08/20 82/08/20	50-272 E TOPREP TOPREP 50-333 E 50-315 F	8208270207 8208270212 8208270215 8208270218 8208270219	8208270010 8208270204 8208270010 8208270207 8208270010	62/07/13 82/08/19 82/07/13 62/08/18 82/07/13	50-282 50-275 50-282 50-327 50-324	R P R B
8208260300 8208260307 8208260309 8208260319	6208240294 6208240294 6208240294 6208240089	82/08/20 82/08/20 82/08/20 82/08/13 82/08/13	50-341 F 50-341 F 50-341 F 50-243 F 50-243 F	8208270225 8208270227 8208270232 8208270233 8208270237	8208270010 8208270010 8208270228 8208270010 8208260010	82/07/13 82/07/13 82/08/13 82/07/13 82/07/13	50-324 50-324 50-266 50-324 50-333	R B R R
8208260323 8208260340 8208260343 8208260345 8208260346	8208260338 8208260336 8208260336 8208260336	82/08/12 82/08/14 82/08/13 82/08/14 82/08/13	50-272 E 50-369 F 50-259 F 50-369 F 50-259 F	8208270241 8208270247 8208270252 8208270253 8208270256	8208270235 8208270244 8208270231 8208270236 8208270250	82/08/10 82/08/17 82/08/19 82/08/24 82/08/19	50-321 50-261 50-259 50-329 50-254	8 8 8 A P
8208260350 8208260355 8208260358 8208260360 8208260366	8208 2601 10 8208 260341 8208 260353 8208 260353 8208 260364	82/08/11 82/08/09 82/08/13 82/08/13 82/08/13	50-324 F CONTRACT 50-263 F 50-263 F 50-483 F	8208270259 8208270261 8208270263 8208270264 8208270266	8208270010 8208270254 8208270010 8208270255 8208270258	82/07/13 82/08/17 92/07/13 82/08/20 82/08/20	50-333 50-348 50-254 50-346 50-325	R R Q 8
8208260368 8208260371 8208260372 8208260380 8208260381	8208 260364 8208 260364 8207 110018 8208 260367 8208 260378	82/08/13 82/09/13 82/07/20 62/08/05 62/08/06	50-483 F 50-483 F FOIA 50-324 F FOIA	8208270269 8208270269 8208270271 8208270273 8208270276	8208270010 8208270254 8208270010 8208270250 8208270010	82/07/13 82/08/17 82/07/13 82/08/19 82/07/13	50-254 50-348 50-213 50-254 50-213	R B R P R
8208260385 8208260372 8208260393 8208260403 8208260404	8208260376 8208260376 8208260367 8208260390 8208260399	82/08/13 82/08/13 82/08/05 82/08/16 62/08/11	50-369 F 50-369 F 50-324 F 50-206 F 50-27 F	8208270279 8208270280 8208270286 8208270288 8208270291	8208270274 8208270010 8208270272 8208270010 8208270282	82/08/18 82/07/13 82/08/05 82/07/13 82/08/12	50-339 50-219 50-313 50-219 50-240	8 8 8
8208240407 8208240410 8208240412 8208240428 8208240430	8208260399 8208260367 8208260399 8208260416 8208260416	82/08/11 82/08/05 82/08/11 82/08/09 82/08/11	50-27 F 50-324 F 50-27 F CONTRACT 50-269 F	8208270293 8208270299 8208270302 8208270303 8208270304	8208270010 8208270010 8208270297 8208270010 8208270298	82/07/13 82/07/13 82/08/10 82/07/13 82/08/18	50-338 50-338 50-321 50-280 50-328	R R B R
8208260437 8208260445 8208260451 8208260455 8208260457	8208260418 8208260436 8208260447 8208260447 8208260442	82/08/11 82/08/16 82/08/09 82/08/09 82/08/10	50-269 F CONTRACT 50-213 F 50-213 F CONTRACT	8208270305 8208270307 8208270311 8208270312 8208270313	8208270295 8208270301 8208270308 8208270010 8208270309	82/08/13 82/08/18 82/08/10 82/07/13 82/08/11	50-368 50-336 50-341 50-280 50-346	8 9 8 9
8208260465 8208260467 8208260480 8208260501 8208260504	8208260461 8208260462 8208260469 8208260492 8208260496	82/08/12 82/08/03 82/08/16 82/07/26 81/05/04	CONTRACT CONTRACT CONTRACT CONTRACT 50-317 E	8208270319 8208270320 8208270321 8208270323 8208270324	8208270318 8208270318 8208270314 8208270315 8208270308	82/08/09 82/08/13 82/08/18 82/08/09 82/08/10	50-266 50-285 50-316 50-266 50-341	0 B 0 0
8208260537 8208260542 8208260544 8208260554 8208260555	8208240529 8208240529 8208240539 8208240551 8208240547	82/08/13 82/08/13 81/04/16 82/07/15 81/04/14	50-249 F 50-249 F 50-333 E FOIA 50-309 E	8208270325 8208270329 8208270333 8208270334 8208270336	8208270322 8208270327 8208270328 8208270314 8208270331	82/08/20 82/08/17 82/08/23 82/08/18 82/08/17	50-528 50-414 50-155 50-314 50-339	9 9 8
8208260361 8208260363 8208260364 8208260383 8208270005	8208240551 8208240551 8208240559 8208240580 8208270001	82/07/15 82/07/15 82/07/30 82/07/21 82/08/20	FOIA FOIA HASTE HOT 50-269 F	9208270337 9208270358 9208270362 9208270363 9208270368	8208270328 8208270355 8208270354 8208270360 8208270359	82/08/23 82/08/16 82/08/20 82/08/20 82/08/20	50-155 50-302 50-285 70-25 50-373	,0 8 F
6208270011 6208270012 6208270014 6208270016 9208270017	8208270001 8208270010 8208270001 8208270010 8208270001	92/08/20 92/07/13 92/08/20 92/07/13 82/08/20	50-508 X 50-3 R 50-508 P 50-3 R 50-508 0	8208270371 8208270374 8208270378 8208270379 8208270384	8208270367 8208270369 8208270375 8208270373 8208270375	82/08/20 82/07/29 82/08/23 82/08/18 82/08/23	50-285 70-754 50-528 50-315 50-528	Q 1 8 1
8208270019 8208270023 8208270029 8208270035 8208270042	8208270010 8208270010 8208270010 8208270010 8208270010	82/07/13 82/07/13 82/07/13 82/07/13 82/07/13	50-289 R 50-289 R 50-155 R 50-155 R 50-261 R	8208270386 8208270387 8208270398 8208270395 8208270398	8208270373 8208270361 8208270375 8208270391 8208270375	82/08/18 82/08/20 82/08/23 82/08/13 82/08/23	50-315 50-325 50-528 50-331 50-528	1 0 8 8
8208270044 8208270046 8208270072 8208270082 8208270091	8208270010 8208270010 8208270010 8208270076 8208270086	82/07/13 82/07/13 82/07/13 82/08/17 82/08/19	50-241 R 50-250 R 50-250 R 50-260 S 50-267 S	9209270401 9209270406 9209270407 9209270410 9208270416	8208270396 8208270404 8208270403 8208270408 8208270412	82/08/18 82/08/17 82/08/13 82/08/19 82/08/18	50-325 50-325 50-270 50-416 50-325	8 8 8
6208270098 8208270111 8208270142 8208270145 8208270160	8208270010 8208270103 8208270134 8208270137 8208270150	82/07/13 82/08/20 82/08/03 82/07/27 82/08/13	50~155 R 50~219 P 50~10 G 50~366 £ 50~324 E	8208270421 8208270425 8208270428 8208270434 8208270439	8208270417 8208270413 8208270426 8208270431 8208270436	82/08/20 82/08/23 82/08/25 82/08/19 82/08/19	50-324 70-734 50-483 50-416 50-416	B 8
8208270174 8208270182 8208270185 8208270193 8208270200	8208270010 8208270010 8208270010 8208270010 8208270010	82/07/13 82/07/13 82/07/13 82/07/13 82/07/13	50~272 R 50~278 R 50~278 R 50~333 R 50~333 R	8208270442 8208270447 8208270456 8208270461 8208270473	8208270438 8208270445 8208270453 8208270455 8208270467	82/08/24 82/08/19 82/08/23 82/08/12 82/08/20	50-352 50-445 50-445 50-366 50-313	000BF

ACCESSION	I NUMBER				ACCES810N	I NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUB JECT CATEGOR	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBBUED	SUBJECT	
8208270476 8208270478 8208270483 8208270484 8208270488	8208270464 8208270471 8208270472 8208270479 8208270474	82/08/24 82/08/10 82/08/17 82/08/20 82/08/12	50-445 50-298 50-416 50-324 50-296	0 0 8 8	9208270623 8208270625 8208270625 8208270628 8208270628 9208270629	8208270010 8208270010 8208270010 8208270010 8208270010	82/07/13 82/07/13 82/07/13 82/07/13 82/07/13	50-293 50-346 50-282 50-321 50-29	RRRRR
8208270495 8208270477 8208270507 8208270512 8208270518	6208270467 8208270491 8208270492 8208270505 8208270514	82/08/25 82/08/17 82/08/13 82/08/20 82/08/23	50-287 50-324 50-257 50-331 50-155	8 8 P 0	8208270631 8208270635 8208270635 8208270637 8208270638	8208270010 8208270010 8208270010 8208270010	82/07/13 82/07/13 82/07/13 82/07/13 82/07/13	50-321 50-286 50-255 50-3 50-27	R R R R
8208270524 8208270526 8208270527 8208270530 8208270531	8208270510 8208270010 8208270523 8208270523 8208270010	82/08/13 82/07/13 82/08/13 82/07/13 82/07/13	50-259 50-309 50-254 50-309 50-155	8 R G R	9208270639 8208270640 8208270643 9208270644 8209270648	8208270010 8208270010 8208270010 8208270010	82/07/13 82/07/13 82/07/13 82/07/13 82/07/13	50-255 50-286 50-315 50-263 50-263	R R R R
8208270535 8208270537 8208270538 8208270539 8208270540	8208270010 8208270010 8208270533 8208270534 8208270010	82/07/13 82/07/13 82/08/20 82/08/12 82/07/13	50-331 50-155 50-361 50-366 50-250	R Q S R	9209270649 820827055 820827055 9208270656 8208270665	8208270010 8208270010 8208270010 8208270010	82/07/13 82/07/13 82/07/13 82/07/13 82/07/22	50-287 50-313 50-313 50-287 XPORTLIC	R R R R
8208270541 8208270542 8208270543 8208270543 8208270546	6208270010 6208270520 6208270010 6208270010	82/07/13 82/08/13 82/07/13 82/07/13 82/07/13	50-245 50-325 50-245 50-250 50-244	R R R	8208270674 8208270677 8208270698 8208270691 8208270692	8208270668 8208270668 8208270684 8208270684 8208270682	81/03/30 81/03/30 82/08/12 82/08/16	50-280 50-280 50-206 50-206 50-329	8 P P A
8208270547 8208270548 8208270549 8208270550 8208270551	8208270010 8208270544 8208270010 8208270010 8208270010	82/07/13 82/08/13 82/07/13 82/07/13 82/07/13	50-29 50-259 50-244 50-29 50-213	R B R R	8208270495 8208270497 8208270701 8208300004 8208300007	9208270684 8208270684 820827 010 8208300004 8208300005	82/08/12 82/08/12 82/07/13 82/08/11 82/07/21	50-206 50-206 50-272 PR 40-8714	PPR
8208270553 8208270554 8208270555 8208270557 8208270558	8208270010 8208270010 8208270010 8208270552 8208270010	82/07/13 82/07/13 82/07/13 82/08/11 82/07/13	50-206 50-213 50-317 40-7604 50-317	R R R	8208300008 8208300010 8208300015 8208300019 8208300024	8208300004 8208300004 8208300004 8208300004 8208300022	82/08/11 82/08/11 82/08/11 82/08/11 82/07/05	PR PR PR PR CONTRACT	r
8208270559 8208270341 8208270544 8208270547 8208270548	8209270010 8208270010 8208270010 8208270010 8208270010	62/07/13 62/07/13 62/07/13 62/07/13 62/07/13	50-10 50-348 50-348 50-10 50-317	R R R R	8208300027 8208300032 8208300038 8208300038 8208300039	8208300025 8208300030 8208300030 8208300036 8208300037	82/08/16 82/08/18 82/08/18 82/08/25 82/08/20	50-320 50-361 50-361 50-213 50-361	9 8 9
8208270569 8208270570 8208270571 8208270572 8208270573	8208270010 8208270546 8208270543 8208270010 8208270010	82/07/13 82/08/18 82/08/11 82/07/13 82/07/13	50-271 70-687 50-261 50-409 50-271	R F R	6208300042 8208300045 8208300046 8208300047 8208300050	8208300041 8208300044 8208300041 8208300044 8208300048	82/08/16 82/08/13 82/08/16 82/08/13 82/08/16	50-247 50-244 50-247 50-244 50-244	0 0 0 0
8208270574 8208270574 8208270577 8208270578 8208270579	8208270010 8208270010 8208270010 8208270543 8208270010	82/07/13 82/07/13 82/07/13 82/08/11 82/07/13	50-317 50-409 50-266 50-261 50-220	R R R F	8208300051 820830058 820830050 820830060 820830060	8208300049 8208300048 8208300057 8208300059 8208300061	82/09/10 82/09/14 82/08/17 82/08/18 82/08/06	50-277 50-244 50-204 50-373 50-373	0 8 8
8208270581 8208270582 8208270583 8208270586 8208270588	8208270010 8208270010 8208270010 8208270010 8208270010	82/07/13 82/07/13 82/07/13 82/07/13 82/07/13	50-266 50-206 50-220 50-272 50-206	R R R R	8208300067 8208300068 8208300078 820830078 9208300081	8208300045 6208300045 6208300071 8208300074 6208300079	82/08/13 82/08/13 82/08/18 82/08/25 82/08/24	50-245 50-245 50-361 50-271 50-387	0 5 0 0
8208270889 8208270590 8208270592 8208270593 8208270595	8208270010 8208270584 8208270010 8208270584 8208270584	82/07/13 82/08/12 82/07/13 82/08/12 82/07/13	50-272 50-3 50-267 50-3 50-267	R F R	B20B3000B5 B20B3000B7 B20B300091 B20B300100 B20B300103	8208300083 8208300087 8208300082 8208300097 8208300101	82/08/13 82/08/20 82/08/24 82/08/18 82/08/06	50-354 50-206 50-324 50-346 50-373	9 8 8
9208270597 8208270598 9208270400 8208270401 8208270403	6208270010 6208270010 6208270010 6208270010 6208270010	62/07/13 62/07/13 62/07/13 62/07/13 82/07/13	50-369 50-369 50-334 50-259 50-269	R R R R	8208300107 8208300110 8208300114 8208300118	8208300105 8208300107 8208300111 8208300113 8208300116	82/08/23 82/08/23 82/08/12 82/08/19 82/08/10	30-416 50-324 70-1308 50-366 50-331	8 8
8208270604 8208270605 8208270606 8208270607 8208270607	8208270599 8208270010 8208270402 8208270010 8208270599	82/08/16 82/07/13 82/08/16 82/07/13 82/08/16	50-255 50-259 50-413 50-369 50-255	F R D R F	8208300121 8208300134 8208300135 8208300140 8208300147	8208300116 8208300128 8208300133 8208300138 8208300144	82/08/10 82/08/20 82/08/18 82/08/18 82/08/23	50-331 50-237 50-346 50-373 50-324	8 8 8
8208270610 8208270611 8208270612 8208270613 8208270613	8208270402 8208270010 8208270402 8208270402 8208270010	82/08/16 82/07/13 82/07/13 82/08/16 82/07/13	50-413 50-133 50-269 50-413 50-369	D R R D	8208300156 8208300159 8208300161 8208300163 8208300167	8208300155 8208300158 8208300162	82/08/18 82/08/19 82/08/19 82/08/12 82/08/25	50-361 50-361 50-321 50-461 50-261	8 8 8 A 0
8208270615 8208270616 8208270617 8208270627 8208270621	8208270599 820827050 8208270602 8208270010 8208270010	82/08/16 82/07/13 82/07/13 92/07/13	50-255 50-133 50-413 50-293 50-346	F R P R	8208300174 8208300180 8208300185 9208300186 8208300186	8208300177 8208300184 8208300184	82/08/10 82/08/05 82/08/16 82/08/16 82/08/16	50-321 50-265 50-293 50-293 50-293	9 0 0 0

ACCESSIO	N NUMBER				ACCE8910			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 168UED	BUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8208300193 8208300194 8208300200 8208300203 8208300204	8208300191 8208300194 8208300197 8208300197 8208300157	92/09/23 92/08/12 92/08/16 92/08/16	70-398 50-315 50-317 50-317 CONTRACT	•	8208310172 8208310184 8208310194 8208310214 8208310215	8208310154 8208310178 8208310185 8208310204 8208310210	82/08/24 82/08/19 82/08/24 82/08/30 82/08/18	50-313 P 50-247 B 50-373 B REVIEW GRP 50-373 S
8208300215 8208300219 8208300227 8208300233 8208300235	8208300213 8208300217 8208300221 8208300229 8208300230	82/09/24 82/09/18 82/08/11 82/08/18 82/08/17	50-293 50-272 70-135 50-311 50-321		820B310220 820B310221 820B310225 820B310227 820B31022B	8208310217 8208310204 8208310219 8208310223 8208310222	82/08/19 82/08/30 82/08/18 82/08/13 82/07/12	50-346 8 REVIEW GRP 50-373 8 50-255 G 50-249 B
8208300241 8208300242 8208300244 8208300248 8208300250	8208300234 8208300237 8208300238 8208300245 8208300236	82/08/11 82/08/19 82/08/24 82/08/13 82/08/11			8208310229 8208310232 8208310238 8208310239 8208310240	8208310224 8208310223 8208310235 8208310234 8208310237	82/08/24 82/08/13 82/08/25 82/08/20 82/08/10	50-508 B 50-255 G 50-346 G 50-373 B GA999
8208300258 8208300271 8208300279 8208300280 8208300284	8208300254 8208300234 8208300275 8208300276 8208300281	82/08/13 82/08/26 82/08/13 82/08/13	50-387 50-204 50-261 50-410 50-409		8208310244 8208310250 8208310253 8208310254 8208310257	8208310237 8208310243 8208310249 8208310251 8208310251	82/08/10 82/08/18 82/08/20 82/08/25 82/08/25	GA999 50-373 8 50-373 8 50-206 P 50-206 P
8208300286 8208300288 8208300292 8208300294 8208300276	8208300283 8208300282 8208300285 8208300281 8208300287	82/08/14 82/08/19 82/08/25 82/08/12 82/08/19	REVIEW ORI 50-155 50-387 50-409 50-293		8208310262 8208310266 8208310269 8208310274 8208310275	8208310251 8208310265 8208310264 8208310271 8208310272	82/08/25 82/08/30 82/08/20 82/08/18 82/08/11	50-206 P 50-389 A 50-301 S 50-311 S GA999
8208300304 8208300307 8208300313 8208300313 8208300315	8208300298 8208300290 8208300298 8208300300 8208300310	82/08/10 82/08/23 82/08/10 82/08/12 82/08/19	50-346 50-259 50-346 50-272 50-373		8208310277 8208310279 8208310280 8208310282 8208310283	8208310272 8208310270 8208310272 8208310278 8208310240	82/08/11 82/08/23 82/08/11 82/08/23 82/08/25	GA999 50-237 B GA999 50-285 Q 50-324 P
6208300317 6208300320 6208300323 6208300335 6208300337	9208300300 8208300311 8208300328 8208300332	82/08/12 82/08/19 82/08/23 82/08/24 82/08/20	50-272 50-364 50-335 50-413 50-280		8208310287 8208310290 8208310298 8208310310 8208310314	9208310285 9208310287 9208310275 9208310304 9208310307	82/08/12 82/08/20 82/08/26 82/08/16	50-272 8 50-373 8 50-445 0 50-245 P GA797
8208300339 8208300240 8208300341 8208300343 8208300347	8208300336 8208300332 8208300328 8208300333 8208300344	82/08/23 82/08/20 82/08/24 82/08/20 82/08/19	50-335 (50-280 (50-413 50-325 (50-366 (8208310321 8208310323 8208310328 8208310333	8208310309 8208310319 8208310319 8208310319	82/08/16 82/08/18 82/08/26 82/08/26	GA799 50-311 B 50-388 G 50-388 G
8209300348 8209310005 8208310009 8208310010 8208310025	82083100346 8208310003 8208310003 8208310006 8208310017	62/08/20 62/08/12 62/08/03 62/08/18	50-335 (50-358 (50-358 (CONTRACT 50-304 (8208310334 6208310339 8208310341 8208310347 8208310351	8208310327 8208310319 8208310337 8208310340 8208310334	82/08/25 62/08/24 62/08/11 82/08/23 82/08/17	50-407 G 50-388 G GA979 TOPREP 50-254 G
8208310026 8208310029 8208310036 8208310036	8208310024 8208310023 8208310024 8208310032 8208310048	82/08/02 81/05/29 82/08/02 81/06/09 82/08/17	FDIA 50-318 (FDIA 50-317 (50-249 (8208310353 8208310354 8208310361 8208310365 8208310366	8208310343 8208310348 8208310348 8208310359 8208310358	82/08/25 82/08/25 82/08/25 82/08/23 82/08/26	50-387 E QA999 QA999 50-316 & 50-272 Q
8208310053 8208310058 8208310058 8208310060 8208310062	8208310039 8208310039 8208310057 8208310054 8208310035	82/08/11 82/08/11 82/08/11 82/08/24 82/07/13	50-29 1 50-29 1 50-2 1 50-373 (8208310347 8208310377 8208310385 8208310391 8208310394	8208310348 8208310349 8208310369 8208310382 8208310387	92/08/25 82/08/27 82/08/27 82/08/26 92/08/20	GA999 50-186 R 50-186 R 50-460 A 50-462 A
8208310045 8208310048 8208310071 8208310074 8208310075	8208310035 8208310046 8208310066 8208310066 8208310035	82/07/13 82/07/13 82/08/27 82/08/27 82/07/13	FDIA 50-382 (50-382 (FDIA		8208310400 8208310401 8208310411 8208310423 8208310424	8208310395 8208310392 8208310405 8208310421 8208310422	92/08/19 92/08/10 92/08/25 92/08/26 92/08/24	50-311 B GA999 50-255 Q 40-672 50-305 Q
8208310078 8208310079 8208310083 8208310086 8208310090	8208310035 8208310076 8208310035 8208310035 8208310087	82/07/13 81/04/22 82/07/13 82/07/13 82/08/11	FOIA 50-287 6 FOIA FOIA 50-348 6		8208310431 8208310432 8208310437 8208310442 8208310446	8208310422 8208310426 8208310426 8208310426 8208310441	82/08/24 82/07/30 82/07/30 82/07/30 82/08/09	50-305 Q 71-4698 71-4698 71-6698 50-298 Q
8208310094 8208310100 8208310102 8208310106 8208310113	8208310092 8208310095 8208310099 8208310103 8208310105	92/08/23 92/08/31 92/08/19 92/08/20 92/07/08	50-237 5 50-334 5 50-313 5 50-315 5 50-275 6		8208310447 8208310448 8208310451 8208310452 8208310453	8208310440 8208310426 8208310443 8208310441 8208310426	82/08/24 82/07/30 82/08/09 82/08/09 82/07/30	50-217 P 71-6698 GEN TEC IS 50-298 G 71-6698
8208310121 8208310124 8208310127 8208310132 8208310134	8208310115 8208310117 8208310116 8208310112 8208310112	82/08/11 82/08/16 82/08/11 82/08/10 82/08/30	GA999 GA999 GA999 GA999 50-352		8208310454 8208310456 8208310457 8208310463 8208310464	8208310449 8208310450 8208310426 8208310426 8208310327	82/08/10 82/08/12 82/07/30 82/07/30 82/08/25	GA777 CONTRACT 71-6678 71-6678 50-407 Q
8208310138 8208310139 8208310147 8208310153 8208310171	6208310133 6208310128 6208310143 6208310150 6208310165	82/08/11 82/08/10 82/08/24 82/08/16 82/08/24	0A999 0A999 50-346 50-311 50-266		8208310465 8208310467 8208310467 8208310469	8208310426 8208310462 8208310426 8208310426	82/07/30 82/08/04 82/07/30 82/07/30	71-6698 CONTRACT 71-6698 50-213 G

ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE DAUED	BUB JECT CATEOD	
B20B310472	8208310426	82/07/30	50-213	Q
8208310473	8208310468	82/0B/11	50-245	Ē
8206310476	8208310426	82/07/30	50-213	a
8209310481	8208310426	82/07/30	50-213	P
8208310483	8208310426	82/07/30	50-213	P
8208310486	8208310426	62/07/30	50-219	Q.
8208310488	8208310485	82/07/21	50-537	Ā
8208310489	8208310487	82/08/09	WASTE M	
8208310498	8208310496	82/07/21	XPORTLE	
8208310500	8208310495	82/08/19	CONTRAC	

ACCESSION	NUMBER		
ENCLOSURE	PRINCIPAL BDC UMENT	DATE	CATEGORY
8208310503 8208310511 8208310515 8208310520 8208310526	8208310477 8208310507 8208310512 8208310517 8208310524	82/08/13 81/03/31 82/07/27 82/08/17 82/08/12	50-266 F 50-302 8 CONTRACT CONTRACT CONTRACT
8208310531	8208310529	82/09/12	CONTRACT

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8 Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWAs.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks.

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER s) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB)
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

l

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.
- NOTE For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

l. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the OA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

B-9

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

(NDO OOF		
NRC FORM 335 U.S. NUCLEAR REGULATORY COMMISSION		1. REPORT NUMBER (Assigned by DDC) NUREG-0540
BIBLIOGRAPHIC DATA SHEET		Vol. 4, No. 8
4 TITLE AND SUBTITLE (Add Valume No., if appropriate)		2. (Leave blank)
Title List of Documents Made Publicly Availab	le	3 RECIPIENT'S ACCESSION NO
August 1-31, 1982		S RECIFICIAL S ACCESSION NO
7 AUTHOR(S)	***************************************	5. DATE REPORT COMPLETED
		MONTH YEAR
9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include		DATE REPORT ISSUED
Division of Technical Information and Documen	t Control	December 1982
Office of Administration U.S. Nuclear Regulatory Commission		6 (Leave blank)
Washington, DC 20555		
12 SDANGODING ORGANIZATION NAME AND MALLING ADDRESS (I.e.	7	8 (Leave blank)
12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include	e Zip Codê)	10. PROJECT/TASK/WORK UNIT NO
Same as 9, above.		11. FIN NO
13 TYPE OF REPORT	PERIOD COVERE	ED (Inclusive dates)
Monthly	(Aug	ust 1-31, 1982
15 SUPPLEMENTARY NOTES		14. (Leave plank)
16. ABSTRACT (200 words or less)		
This document is a monthly publication contains received and generated by the U.S. NRC. This material associated with civilian nuclear power active materials, and (2) nondocketed material pertinent to its role as a regulatory agency. Personal Author Index, Corporate Source Index, Reference to Principal Documents Index.	information er plants and received a The follow Report Num	includes (1) docketed d other uses of radio- nd generated by NRC ing indexes are included: ber Index, and Cross
17. KEY WORDS AND DOCUMENT ANALYSIS	17a DESCRIPTORS	3
17b IDENTIFIERS/OPEN-ENDED TERMS		
	T.a	Tal van an a
18 AVAILABILITY STATEMENT	Unclas	ssified 21 NO OF PAGES
Unlimited		CLASS (This page) 22 PRICE SSIFIED S